

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	B	S02	Stairwell to Basement next to Fan Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S02	Stairwell to Basement next to Fan Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S02	Stairwell to Basement next to Fan Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S02	Stairwell to Basement next to Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S02	Stairwell to Basement next to Fan Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S02	Stairwell to Basement next to Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	010B	Pump Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	010B	Pump Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	010B	Pump Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	010B	Pump Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	010B	Pump Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	010B	Pump Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	EMR	Elevator Machine Room inside Pump Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	EMR	Elevator Machine Room inside Pump Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	EMR	Elevator Machine Room inside Pump Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	EMR	Elevator Machine Room inside Pump Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	EMR	Elevator Machine Room inside Pump Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	EMR	Elevator Machine Room inside Pump Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	001B	Fan Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	001B	Fan Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	001B	Fan Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	001B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	001B	Fan Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	001B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	3	Classroom 3	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	3	Classroom 3	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	3	Classroom 3	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	3	Classroom 3	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	3	Classroom 3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	3	Classroom 3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	003B	Electrical Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	003B	Electrical Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	003B	Electrical Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	003B	Electrical Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	003B	Electrical Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	003B	Electrical Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1B	Hallway outside of Electrical Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1B	Hallway outside of Electrical Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1B	Hallway outside of Electrical Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1B	Hallway outside of Electrical Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1B	Hallway outside of Electrical Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1B	Hallway outside of Electrical Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	B12	Boiler Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	B12	Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	B12	Boiler Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	B12	Boiler Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	B12	Boiler Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	B12	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	101B	Mechanical Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	101B	Mechanical Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	B	101B	Mechanical Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	101B	Mechanical Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	101B	Mechanical Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	101B	Mechanical Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	005B	Locker Room across from Building Engineer's Office	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	005B	Locker Room across from Building Engineer's Office	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	005B	Locker Room across from Building Engineer's Office	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	005B	Locker Room across from Building Engineer's Office	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	005B	Locker Room across from Building Engineer's Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	005B	Locker Room across from Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	004B	Locker Room Restroom	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	004B	Locker Room Restroom	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	004B	Locker Room Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	004B	Locker Room Restroom	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	004B	Locker Room Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	004B	Locker Room Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1	Hallway outside of Building Engineer's Office	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1	Hallway outside of Building Engineer's Office	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1	Hallway outside of Building Engineer's Office	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1	Hallway outside of Building Engineer's Office	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1	Hallway outside of Building Engineer's Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1	Hallway outside of Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1-J	Custodial Closet in Hallway outside of Building Engineer's Office	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1-J	Custodial Closet in Hallway outside of Building Engineer's Office	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1-J	Custodial Closet in Hallway outside of Building Engineer's Office	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1-J	Custodial Closet in Hallway outside of Building Engineer's Office	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1-J	Custodial Closet in Hallway outside of Building Engineer's Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	H1-J	Custodial Closet in Hallway outside of Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	009B	Building Engineer's Office	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	009B	Building Engineer's Office	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	009B	Building Engineer's Office	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	009B	Building Engineer's Office	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	009B	Building Engineer's Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	009B	Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B	Building Engineer's Office Restroom	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B	Building Engineer's Office Restroom	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B	Building Engineer's Office Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B	Building Engineer's Office Restroom	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B	Building Engineer's Office Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B	Building Engineer's Office Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B1	Building Engineer's Office Restroom Shower	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B1	Building Engineer's Office Restroom Shower	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B1	Building Engineer's Office Restroom Shower	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B1	Building Engineer's Office Restroom Shower	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	007B1	Building Engineer's Office Restroom Shower	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	B	007B1	Building Engineer's Office Restroom Shower	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S01	Stairwell next to Boiler Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S01	Stairwell next to Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S01	Stairwell next to Boiler Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S01	Stairwell next to Boiler Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S01	Stairwell next to Boiler Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	S01	Stairwell next to Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	100	Classroom 100	yes	W1	CMU	Red	None	0	0	Negative
1380	1	1	100	Classroom 100	yes	W2	CMU	Blue	None	0	0	Negative
1380	1	1	100	Classroom 100	yes	W3	CMU	Green	None	0	0	Negative
1380	1	1	100	Classroom 100	yes	W4	CMU	Yellow	None	0	0	Negative
1380	1	1	100	Classroom 100	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	100	Classroom 100	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	100	Classroom 100	yes	DOOR CASING 1	METAL	TAN	None	0	0.07	Negative
1380	1	1	100	Classroom 100	yes	DOOR CASING 4	METAL	TAN	None	0	0.01	Negative
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	DOOR CASING 1	METAL	TAN	None	0	1.7	Positive
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	DOOR CASING 2	METAL	TAN	None	0	1.4	Positive
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	DOOR CASING 3	METAL	TAN	None	0	0.08	Negative
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	DOOR CASING 4	METAL	TAN	None	0	0.01	Negative
1380	1	1	100A	Small Rear Hallway between Classrooms 100 & 101	yes	DOOR 1	METAL	TAN	None	0	0	Negative
1380	1	B	100C	Closet in Small Rear Hallway between Classrooms 100 & 101	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	100C	Closet in Small Rear Hallway between Classrooms 100 & 101	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	100C	Closet in Small Rear Hallway between Classrooms 100 & 101	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	100C	Closet in Small Rear Hallway between Classrooms 100 & 101	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	100C	Closet in Small Rear Hallway between Classrooms 100 & 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	B	100C	Closet in Small Rear Hallway between Classrooms 100 & 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	100B	Classroom 100 Restroom	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	100B	Classroom 100 Restroom	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	100B	Classroom 100 Restroom	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	100B	Classroom 100 Restroom	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	100B	Classroom 100 Restroom	yes	Ceiling	PLASTER	BEIGE	None	0	0	Negative
1380	1	1	100B	Classroom 100 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	100B	Classroom 100 Restroom	yes	DOOR CASING	METAL	TAN	None	16	1	Positive
1380	1	1	101	Classroom 101	yes	W1	CMU	BEIGE	None	0	0	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	1	101	Classroom 101	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	101	Classroom 101	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	101	Classroom 101	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	101	Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	101	Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	101	Classroom 101	yes	DOOR CASING	METAL	TAN	None	5	2	Positive
1380	1	1	101	Classroom 101	yes	DOOR CASING	METAL	TAN	None	5	1.6	Positive
1380	1	1	101B	Classroom 101 Restroom	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	101B	Classroom 101 Restroom	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	101B	Classroom 101 Restroom	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	101B	Classroom 101 Restroom	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	101B	Classroom 101 Restroom	yes	Ceiling	PLASTER	BEIGE	None	0	0	Negative
1380	1	1	101B	Classroom 101 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	101B	Classroom 101 Restroom	yes	DOOR CASING	METAL	TAN	None	5	1.6	Positive
1380	1	1	101B	Classroom 101 Restroom	yes	PIPE CHASE DOOR	METAL	BEIGE	None	0	0	Negative
1380	1	1	101C	Small Storage Room in Classroom 101 by Main Entry Door	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	Small Storage Room in Classroom 101 by Main Entry Door	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	Small Storage Room in Classroom 101 by Main Entry Door	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	Small Storage Room in Classroom 101 by Main Entry Door	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	Small Storage Room in Classroom 101 by Main Entry Door	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	Small Storage Room in Classroom 101 by Main Entry Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	101C : Small Storage Room in Classroom 101 by Main Entry Door	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	101C : Small Storage Room in Classroom 101 by Main Entry Door	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	101C : Small Storage Room in Classroom 101 by Main Entry Door	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	101C : Small Storage Room in Classroom 101 by Main Entry Door	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	101C : Small Storage Room in Classroom 101 by Main Entry Door	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	101C	101C : Small Storage Room in Classroom 101 by Main Entry Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	101A	Hallway at Classroom 101	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101A	Hallway at Classroom 101	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101A	Hallway at Classroom 101	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101A	Hallway at Classroom 101	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	101A	Hallway at Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	101A	Hallway at Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	S13	Stairwell next to Classroom 101	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	W4	CMU	BEIGE	None	0	1.8	Positive
1380	1	1	S13	Stairwell next to Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	S13	Stairwell next to Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	1	S13	Stairwell next to Classroom 101	yes	DOOR 1	METAL	ORANGE	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	DOOR CASING 1	METAL	ORANGE	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	DOOR CASING 3	METAL	ORANGE	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	DOOR 3	METAL	ORANGE	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	DOOR CENTER POST 3	METAL	ORANGE	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	STAIR STRINGER	METAL	GRAY	None	0	0.08	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	STAIR TREAD	CONCRETE	GRAY	None	0	0	Negative
1380	1	1	S13	Stairwell next to Classroom 101	yes	STAIR RAILING	METAL	BROWN	None	0	0.09	Negative
1380	1	1	102/102A	Classroom 102	yes	W1	CMU	RED	None	0	0	Negative
1380	1	1	102/102A	Classroom 102	yes	W2	CMU	BLUE	None	0	0	Negative
1380	1	1	102/102A	Classroom 102	yes	W3	CMU	RED	None	0	0	Negative
1380	1	1	102/102A	Classroom 102	yes	W4	CMU	YELLOW	None	0	0	Negative
1380	1	1	102/102A	Classroom 102	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	102/102A	Classroom 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	102/102A	Classroom 102	yes	DOOR CASING 1	METAL	TAN	None	0	0.01	Negative
1380	1	1	102/102A	Classroom 102	yes	DOOR CASING 2	METAL	TAN	None	0	0.01	Negative
1380	1	1	102/102A	Classroom 102	yes	DOOR 1	METAL	TAN	None	0	0.03	Negative
1380	1	1	102/102A	Classroom 102	yes	DOOR 2	METAL	TAN	None	0	0	Negative
1380	1	1	102B	Classroom 102 Restroom	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	102B	Classroom 102 Restroom	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	102B	Classroom 102 Restroom	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	102B	Classroom 102 Restroom	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	102B	Classroom 102 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	102B	Classroom 102 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	102B	Classroom 102 Restroom	yes	DOOR CASING	METAL	TAN	None	0	0	Negative
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	W4	CMU	BEIGE	None	0	0.01	Negative
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	DOOR CASING 3	DRYWALL	GRAY	None	0	0	Negative
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	DOOR CASING 1	DRYWALL	BLUE	None	0	0	Negative
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	DOOR 1	METAL	BLUE	None	0	0.01	Negative
1380	1	1	H09	Hallway at Classroom 102 to Gym	yes	DOOR 3	METAL	BLUE	None	0	0.3	Negative
1380	1	1	H13	Hallway at from Classroom 101 to Auditorium	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	H13	Hallway at from Classroom 101 to Auditorium	yes	W2	CMU	Green	None	0	0.5	Negative
1380	1	1	H13	Hallway at from Classroom 101 to Auditorium	yes	W3	CMU	Tan	None	0	1.5	Positive
1380	1	1	H13	Hallway at from Classroom 101 to Auditorium	yes	W4	CMU	Red	None	0	0	Negative
1380	1	1	H13	Hallway at from Classroom 101 to Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H13	Hallway at from Classroom 101 to Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	116	Auditorium	yes	W1	CMU	BLUE	None	0	0	Negative
1380	1	1	116	Auditorium	yes	W2	CMU	BLUE	None	0	0	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	1	116	Auditorium	yes	W3	CMU	BLUE	None	0	0	Negative
1380	1	1	116	Auditorium	yes	W4	CMU	WHITE	None	0	0	Negative
1380	1	1	116	Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	116	Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	116	Auditorium	yes	DOOR CASING 1	METAL	BLUE	None	0	1.2	Positive
1380	1	1	116	Auditorium	yes	DOOR 1	METAL	BLUE	None	0	0.01	Negative
1380	1	1	116	Auditorium	yes	DOOR CENTER POST 1	METAL	BLUE	None	0	0	Negative
1380	1	1	116	Auditorium	yes	DOOR CASING 3	METAL	TAN	None	0	0	Negative
1380	1	1	116	Auditorium	yes	DOOR 3	METAL	TAN	None	0	0	Negative
1380	1	1	116	Auditorium	yes	DOOR CENTER POST 3	METAL	TAN	None	0	0	Negative
1380	1	1	116	Auditorium	yes	RAILING 4	METAL	TAN	None	0	0.03	Negative
1380	1	1	116A	Auditorium Stage	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	116A	Auditorium Stage	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	116A	Auditorium Stage	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	116A	Auditorium Stage	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	116A	Auditorium Stage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	116A	Auditorium Stage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	116A	Auditorium Stage	yes	DUCT	METAL	BEIGE	None	0	0	Negative
1380	1	1	104	Main Office	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	1	104	Main Office	yes	W2	CMU	Tan	None	0	0.4	Negative
1380	1	1	104	Main Office	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	1	104	Main Office	yes	W4	CMU	Tan	None	0	0.5	Negative
1380	1	1	104	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	104	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	104	Main Office	yes	Door	Metal	Beige	None	0	0.5	Negative
1380	1	1	104	Main Office	yes	Door Casing 1	Metal	Beige	None	0	0	Negative
1380	1	1	104	Main Office	yes	Door Casing 3	Metal	Beige	None	0	1.5	Positive
1380	1	1	104	Main Office	yes	Door Casing 4	Metal	Beige	None	0	0.5	Negative
1380	1	1	104	Main Office	yes	Window Casing	Metal	Beige	None	0	0.4	Negative
1380	1	1	104AA	Copier Room in the Main Office closest to Classroom 101	yes	W1	CMU	Tan	None	N/A	0	Negative
1380	1	1	104AA	Copier Room in the Main Office closest to Classroom 101	yes	W2	CMU	Tan	None	N/A	0	Negative
1380	1	1	104AA	Copier Room in the Main Office closest to Classroom 101	yes	W3	CMU	Drywall	Flaking	5	0.1	Negative
1380	1	1	104AA	Copier Room in the Main Office closest to Classroom 101	yes	W4	CMU	Tan	None	N/A	0	Negative
1380	1	1	104AA	Copier Room in the Main Office closest to Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	104AA	Copier Room in the Main Office closest to Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	104AA	Copier Room in the Main Office closest to Classroom 101	yes	Door Casing 1	Metal	Beige	None	0	0.5	Negative
1380	1	1	104AA	Copier Room in the Main Office closest to Classroom 101	yes	Door Casing 3	Metal	Black	None	0	0.1	Negative
1380	1	1	104AB	IDF Room next to the Copier Room	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	1	104AB	IDF Room next to the Copier Room	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	104AB	IDF Room next to the Copier Room	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	104AB	IDF Room next to the Copier Room	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	104AB	IDF Room next to the Copier Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	104AB	IDF Room next to the Copier Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	104B	Office in Main Office behind Principal's Office	yes	W1	CMU	Tan	None	0	0.2	Negative
1380	1	1	104B	Office in Main Office behind Principal's Office	yes	W2	CMU	Tan	None	0	0.4	Negative
1380	1	1	104B	Office in Main Office behind Principal's Office	yes	W3	CMU	Tan	None	0	0.4	Negative
1380	1	1	104B	Office in Main Office behind Principal's Office	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	1	104B	Office in Main Office behind Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	104B	Office in Main Office behind Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	104B	Office in Main Office behind Principal's Office	yes	Door Casing	Metal	Beige	None	0	0.3	Negative
1380	1	1	105	Principal's Office	yes	W1	CMU	Orange	None	0	0	Negative
1380	1	1	105	Principal's Office	yes	W2	CMU	Orange	None	0	0	Negative
1380	1	1	105	Principal's Office	yes	W3	CMU	Orange	None	0	0	Negative
1380	1	1	105	Principal's Office	yes	W4	CMU	Orange	None	0	0.1	Negative
1380	1	1	105	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	105	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	105	Principal's Office	yes	Door Casing 1	Metal	Beige	None	0	0.5	Negative
1380	1	1	105	Principal's Office	yes	Door Casing 3	Metal	Beige	None	0	1.7	Positive
1380	1	1	105	Principal's Office	yes	Door Casing 4	Metal	Beige	None	0	2.2	Positive
1380	1	1	105C	Principal's Office Restroom	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	105C	Principal's Office Restroom	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	105C	Principal's Office Restroom	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	105C	Principal's Office Restroom	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	105C	Principal's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	105C	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	W1	CMU	BEIGE	None	6	0.5	Negative
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	W2	CMU	BEIGE	None	0	0.1	Negative
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	W3	CMU	BEIGE	None	0	0.5	Negative
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	W4	CMU	BEIGE	None	0	0.4	Negative
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	Ceiling	PLASTER	BEIGE	None	0	0	Negative
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	DOOR CASING 1	Metal	Beige	None	0	1.2	Positive
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	DOOR CASING 3	METAL	TAN	None	0	0.09	Negative
1380	1	1	105A	Men's Staff Restroom at Auditorium	yes	PIPE CHASE DOOR	METAL	TAN	None	0	0	Negative
1380	1	1	105B	Women's Staff Restroom at Auditorium	yes	W1	CMU	BEIGE	None	5	0	Negative
1380	1	1	105B	Women's Staff Restroom at Auditorium	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	105B	Women's Staff Restroom at Auditorium	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	105B	Women's Staff Restroom at Auditorium	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	105B	Women's Staff Restroom at Auditorium	yes	Ceiling	PLASTER	BEIGE	None	0	0	Negative
1380	1	1	105B	Women's Staff Restroom at Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	105B	Women's Staff Restroom at Auditorium	yes	DOOR CASING	METAL	TAN	None	0	0.21	Negative
1380	1	1	106	Conference Room next to Principal's Office	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	106	Conference Room next to Principal's Office	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	106	Conference Room next to Principal's Office	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	106	Conference Room next to Principal's Office	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	106	Conference Room next to Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	1	106	Conference Room next to Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	106	Conference Room next to Principal's Office	yes	DOOR CASING 1	METAL	TAN	None	0	3.3	Positive
1380	1	1	106	Conference Room next to Principal's Office	yes	DOOR CASING 4	METAL	TAN	None	0	0.04	Negative
1380	1	1	106	Conference Room next to Principal's Office	yes	DOOR CASING 1	METAL	TAN	None	0	3.1	Positive
1380	1	1	107	Office across from Conference Room	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	107	Office across from Conference Room	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	107	Office across from Conference Room	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	107	Office across from Conference Room	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	107	Office across from Conference Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	107	Office across from Conference Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108	Hallway at Nurse's Office	yes	W1	CMU	BEIGE	None	0	0.01	Negative
1380	1	1	108	Hallway at Nurse's Office	yes	W2	CMU	BEIGE	None	0	0.01	Negative
1380	1	1	108	Hallway at Nurse's Office	yes	W3	CMU	BEIGE	None	0	0.02	Negative
1380	1	1	108	Hallway at Nurse's Office	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	108	Hallway at Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108	Hallway at Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108	Hallway at Nurse's Office	yes	DOOR CASING 2	METAL	TAN	None	0	0	Negative
1380	1	1	108	Hallway at Nurse's Office	yes	DOOR CASING 1	METAL	TAN	None	0	2.2	Positive
1380	1	1	108A	Office next to Nurse's Office	yes	W1	CMU	WHITE	None	0	0	Negative
1380	1	1	108A	Office next to Nurse's Office	yes	W2	CMU	WHITE	None	0	0	Negative
1380	1	1	108A	Office next to Nurse's Office	yes	W3	CMU	WHITE	None	0	0	Negative
1380	1	1	108A	Office next to Nurse's Office	yes	W4	CMU	WHITE	None	0	0	Negative
1380	1	1	108A	Office next to Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108A	Office next to Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108A	Office next to Nurse's Office	yes	DOOR CASING	METAL	TAN	None	0	0	Negative
1380	1	1	108A	Office next to Nurse's Office	yes	WINDOW CASING	METAL	TAN	None	0	0.01	Negative
1380	1	1	108B	Nurse's Office Room 108B	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	108B	Nurse's Office Room 108B	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	108B	Nurse's Office Room 108B	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	108B	Nurse's Office Room 108B	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	108B	Nurse's Office Room 108B	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108B	Nurse's Office Room 108B	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108C	Nurse's Office Room 108C	yes	W1	CMU	WHITE	None	0	0	Negative
1380	1	1	108C	Nurse's Office Room 108C	yes	W2	CMU	WHITE	None	0	0	Negative
1380	1	1	108C	Nurse's Office Room 108C	yes	W3	CMU	WHITE	None	0	0	Negative
1380	1	1	108C	Nurse's Office Room 108C	yes	W4	CMU	WHITE	None	0	0	Negative
1380	1	1	108C	Nurse's Office Room 108C	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108C	Nurse's Office Room 108C	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	108C	Nurse's Office Room 108C	yes	DOOR CASING	METAL	TAN	None	0	0.4	Negative
1380	1	1	108TR	Nurse's Office Restroom	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	108TR	Nurse's Office Restroom	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	108TR	Nurse's Office Restroom	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	108TR	Nurse's Office Restroom	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	108TR	Nurse's Office Restroom	yes	Ceiling	PLASTER	BEIGE	None	0	0	Negative
1380	1	1	108TR	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	1	108TR	Nurse's Office Restroom	yes	DOOR CASING	METAL	TAN	None	0	0.12	Negative
1380	1	1	109A	Nurse's Office 1	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	109A	Nurse's Office 1	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	109A	Nurse's Office 1	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	109A	Nurse's Office 1	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	109A	Nurse's Office 1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	109A	Nurse's Office 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	109A	Nurse's Office 1	yes	DOOR CASING	METAL	TAN	None	0	0.01	Negative
1380	1	1	109A	Nurse's Office 1	yes	DOOR CASING	METAL	TAN	None	0	0	Negative
1380	1	1	109B	Nurse's Office 2	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	109B	Nurse's Office 2	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	109B	Nurse's Office 2	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	109B	Nurse's Office 2	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	109B	Nurse's Office 2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	109B	Nurse's Office 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	109B	Nurse's Office 2	yes	DOOR CASING	METAL	TAN	None	0	0.6	Negative
1380	1	1	109C	Nurse's Office 3	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	109C	Nurse's Office 3	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	109C	Nurse's Office 3	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	109C	Nurse's Office 3	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	109C	Nurse's Office 3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	109C	Nurse's Office 3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	109C	Nurse's Office 3	yes	DOOR CASING	METAL	TAN	None	0	0.07	Negative
1380	1	1	106A	Boy's Restroom	yes	W1	CMU	BEIGE	None	3	0	Negative
1380	1	1	106A	Boy's Restroom	yes	W2	CMU	BEIGE	None	3	0	Negative
1380	1	1	106A	Boy's Restroom	yes	W3	CMU	BEIGE	None	3	0	Negative
1380	1	1	106A	Boy's Restroom	yes	W4	CMU	BEIGE	None	3	0	Negative
1380	1	1	106A	Boy's Restroom	yes	Ceiling	PLASTER	BEIGE	None	0	0	Negative
1380	1	1	106A	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	106A	Boy's Restroom	yes	PIPE CHASE DOOR	METAL	BEIGE	None	0	0	Negative
1380	1	1	106A	Boy's Restroom	yes	DOOR CASING	METAL	TAN	None	0	0.5	Negative
1380	1	1	106B	Girl's Restroom	yes	W1	CMU	BEIGE	None	6	0	Negative
1380	1	1	106B	Girl's Restroom	yes	W2	CMU	BEIGE	None	0	0.01	Negative
1380	1	1	106B	Girl's Restroom	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	106B	Girl's Restroom	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	106B	Girl's Restroom	yes	Ceiling	PLASTER	BEIGE	None	0	0	Negative
1380	1	1	106B	Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	106B	Girl's Restroom	yes	DOOR CASING	METAL	TAN	None	0	0	Negative
1380	1	1	115	Cafeteria	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	115	Cafeteria	yes	W2	CMU	BEIGE	None	0	0.7	Positive
1380	1	1	115	Cafeteria	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	115	Cafeteria	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115	Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	115	Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	115	Cafeteria	yes	WALL BASEBOARD	CMU	TAN	None	0	1.3	Positive
1380	1	1	115	Cafeteria	yes	DIVIDER WALL	WOOD	BLUE	None	0	0	Negative
1380	1	1	115B	Cafeteria Serving Line	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115B	Cafeteria Serving Line	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	1	115B	Cafeteria Serving Line	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115B	Cafeteria Serving Line	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115B	Cafeteria Serving Line	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	115B	Cafeteria Serving Line	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	115C	Loading Dock	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115C	Loading Dock	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115C	Loading Dock	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115C	Loading Dock	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115C	Loading Dock	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	115C	Loading Dock	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	113	Ramp inside of Loading Dock	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	113	Ramp inside of Loading Dock	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	113	Ramp inside of Loading Dock	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	113	Ramp inside of Loading Dock	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	113	Ramp inside of Loading Dock	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	113	Ramp inside of Loading Dock	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	115D	Storage Room inside of Loading Dock	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115D	Storage Room inside of Loading Dock	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115D	Storage Room inside of Loading Dock	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115D	Storage Room inside of Loading Dock	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	115D	Storage Room inside of Loading Dock	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	115D	Storage Room inside of Loading Dock	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	114	Kitchen	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	114	Kitchen	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	114	Kitchen	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	114	Kitchen	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	114	Kitchen	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	114	Kitchen	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	114B	Kitchen Storage	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	114B	Kitchen Storage	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	114B	Kitchen Storage	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	114B	Kitchen Storage	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	114B	Kitchen Storage	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	114B	Kitchen Storage	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H12	Hallway from Classroom 100 to 110	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	1	H12	Hallway from Classroom 100 to 110	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	H12	Hallway from Classroom 100 to 110	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	1	H12	Hallway from Classroom 100 to 110	yes	W4	CMU	Tan	None	0	0.5	Negative
1380	1	1	H12	Hallway from Classroom 100 to 110	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H12	Hallway from Classroom 100 to 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	110	Music Room	yes	W1	CMU	WHITE	None	0	0	Negative
1380	1	1	110	Music Room	yes	W2	CMU	WHITE	None	0	0	Negative
1380	1	1	110	Music Room	yes	W3	CMU	WHITE	None	0	0	Negative
1380	1	1	110	Music Room	yes	W4	CMU	WHITE	None	0	0	Negative
1380	1	1	110	Music Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	110	Music Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	110	Music Room	yes	DOOR CASING 1	METAL	TAN	None	0	1.7	Positive
1380	1	1	110	Music Room	yes	DOOR CASING 2	METAL	TAN	None	0	0.5	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	1	111	Office Next to Music Room	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	111	Office Next to Music Room	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	111	Office Next to Music Room	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	111	Office Next to Music Room	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	111	Office Next to Music Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	111	Office Next to Music Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	111	Office Next to Music Room	yes	DOOR CASING 4	METAL	TAN	None	0	0.04	Negative
1380	1	1	111	Office Next to Music Room	yes	DOOR CASING 2	METAL	TAN	None	0	0	Negative
1380	1	1	111	Office Next to Music Room	yes	DOOR CASING 1	METAL	TAN	None	0	1.5	Positive
1380	1	1	112	Lounge at Music Room	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	112	Lounge at Music Room	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	112	Lounge at Music Room	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	112	Lounge at Music Room	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	112	Lounge at Music Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	112	Lounge at Music Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	112	Lounge at Music Room	yes	DOOR CASING 4	METAL	TAN	None	0	2.3	Positive
1380	1	1	112	Lounge at Music Room	yes	DOOR CASING 2	METAL	TAN	None	0	0.6	Negative
1380	1	1	H11	Hallway from Teacher's Lounge to Cafeteria	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	H11	Hallway from Teacher's Lounge to Cafeteria	yes	W2	CMU	BEIGE	None	0	0.1	Negative
1380	1	1	H11	Hallway from Teacher's Lounge to Cafeteria	yes	W3	CMU	BEIGE	None	0	0.5	Negative
1380	1	1	H11	Hallway from Teacher's Lounge to Cafeteria	yes	W4	CMU	BEIGE	None	0	0.1	Negative
1380	1	1	H11	Hallway from Teacher's Lounge to Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H11	Hallway from Teacher's Lounge to Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H11	Hallway from Teacher's Lounge to Cafeteria	yes	Door Casing	Metal	Blue	None	0	0.4	Negative
1380	1	1	H11	Hallway from Teacher's Lounge to Cafeteria	yes	Door	Metal	Blue	None	0	0	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	DOOR 1	METAL	BLUE	None	0	0.6	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	DOOR 2	METAL	TAN	None	0	0.4	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	DOOR 3	METAL	TAN	None	0	0.5	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	DOOR CASING 1	METAL	BLUE	None	0	0.01	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	DOOR CASING 2	METAL	TAN	None	0	0.03	Negative
1380	1	1	H10	Hallway from Classroom 110 to Gym	yes	DOOR CASING 3	METAL	TAN	None	0	0.04	Negative
1380	1	1	103	Gym	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	103	Gym	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	103	Gym	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	103	Gym	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	103	Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	103	Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	1	103	Gym	yes	DOOR CASING 2	METAL	TAN	None	0	0.01	Negative
1380	1	1	103	Gym	yes	DOOR CASING 3	METAL	TAN	None	0	0	Negative
1380	1	1	103	Gym	yes	DOOR CASING 4	METAL	TAN	None	0	0.05	Negative
1380	1	1	103A	Gym Office	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	103A	Gym Office	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	103A	Gym Office	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	103A	Gym Office	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	103A	Gym Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	103A	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	103A	Gym Office	yes	DOOR CASING 1	METAL	BEIGE	None	0	0.03	Negative
1380	1	1	103A	Gym Office	yes	DOOR CASING 3	METAL	BEIGE	None	0	0.01	Negative
1380	1	1	103B	Gym Storage next to Gym Office	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	103B	Gym Storage next to Gym Office	yes	W2	CMU	BEIGE	None	0	0	Negative
1380	1	1	103B	Gym Storage next to Gym Office	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	103B	Gym Storage next to Gym Office	yes	W4	CMU	BEIGE	None	0	0	Negative
1380	1	1	103B	Gym Storage next to Gym Office	yes	Ceiling	PLASTER	BEIGE	None	0	0	Negative
1380	1	1	103B	Gym Storage next to Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	103B	Gym Storage next to Gym Office	yes	DOOR CASING	METAL	TAN	None	0	0.01	Negative
1380	1	1	103C	Gym Storage in Corner	yes	W1	CMU	Tan	Flaking	4	0.2	Negative
1380	1	1	103C	Gym Storage in Corner	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103C	Gym Storage in Corner	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103C	Gym Storage in Corner	yes	W4	CMU	Tan	None	0	0.4	Negative
1380	1	1	103C	Gym Storage in Corner	yes	Ceiling	Plaster	TAN	Cracking	2	0.1	Negative
1380	1	1	103C	Gym Storage in Corner	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	103C	Gym Storage in Corner	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	1	103C	Gym Storage in Corner	yes	Pipe Shaft Door	Metal	Tan	None	0	0.1	Negative
1380	1	1	103CP	103PC : Pipe Chase in Corner of Gym Storage	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103CP	103PC : Pipe Chase in Corner of Gym Storage	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103CP	103PC : Pipe Chase in Corner of Gym Storage	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103CP	103PC : Pipe Chase in Corner of Gym Storage	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103CP	103PC : Pipe Chase in Corner of Gym Storage	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	103CP	103PC : Pipe Chase in Corner of Gym Storage	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	103D	Gym Storage across from 103C	Yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103D	Gym Storage across from 103C	Yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103D	Gym Storage across from 103C	Yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103D	Gym Storage across from 103C	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	1	103D	Gym Storage across from 103C	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	103D	Gym Storage across from 103C	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	W1	CMU	BEIGE	None	0	0	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	W2	CMU	BEIGE	None	0	0.01	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	W3	CMU	BEIGE	None	0	0	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	W4	CMU	BEIGE	None	0	0.04	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	Ceiling	PLASTER	BEIGE	None	0	0.2	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	Floor	CONCRETE	GRAY	None	0	0	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	STAIR STRINGER	METAL	BROWN	None	0	0.04	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	STAIR RAILING	METAL	BROWN	None	0	0.12	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	STAIR TREAD	METAL	GRAY	None	0	0	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	STAIR RISER	METAL	GRAY	None	0	0.12	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	DOOR CASING 1	METAL	BLUE	None	0	0	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	DOOR 1	METAL	BLUE	None	0	0	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	DOOR 3	METAL	BEIGE	None	0	0	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	DOOR CASING 3	METAL	BEIGE	None	0	0	Negative
1380	1	1	S11	Stairwell next to Teacher's Lounge	yes	DOOR CENTER POST 3	METAL	BEIGE	None	0	0.01	Negative
1380	1	1	S12	Stairwell to Basement next to Loading Dock	yes	W1	CMU	N/A	N/A	5		
1380	1	1	S12	Stairwell to Basement next to Loading Dock	yes	W2	CMU	N/A	N/A	5		
1380	1	1	S12	Stairwell to Basement next to Loading Dock	yes	W3	CMU	N/A	N/A	5		
1380	1	1	S12	Stairwell to Basement next to Loading Dock	yes	W4	CMU	N/A	N/A	5		
1380	1	1	S12	Stairwell to Basement next to Loading Dock	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	S12	Stairwell to Basement next to Loading Dock	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	W1	CMU	BEIGE	None	10	0	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	W2	CMU	BEIGE	None	0	2.7	Positive
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	W3	CMU	BEIGE	None	0	0.3	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	W4	CMU	BEIGE	None	0	3	Positive
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	Ceiling	Metal	White	Flaking	40	0.5	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	Ceiling	I-Beam	White	None	0	2.1	Positive
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	Floor	CONCRETE	GRAY	None	0	0	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	Floor	CONCRETE	GRAY	Flaking	3	0.1	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	STAIR STRINGER	METAL	BEIGE	None	0	1.5	Positive
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	STAIR RISER	METAL	GRAY	None	0	0.12	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	STAIR TREAD	METAL	GRAY	None	0	0	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	STAIR RAILING	METAL	BLACK	None	0	0.11	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	DOOR 1	METAL	TAN	None	0	0	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	DOOR 4	METAL	YELLOW	None	0	3.5	Positive
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	DOOR CASING 1	METAL	TAN	None	0	0	Negative
1380	1	1	S14	Stairwell behind Cafeteria/Auditorium	yes	DOOR CASING 4	METAL	YELLOW	None	0	4	Positive
1380	1	2	200	Classroom 200	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	200	Classroom 200	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	2	200	Classroom 200	yes	W3	CMU	Blue	None	0	0.5	Negative
1380	1	2	200	Classroom 200	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	2	200	Classroom 200	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	200	Classroom 200	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	200	Classroom 200	yes	Window Sill	Metal	Beige	None	0	0	Negative
1380	1	2	200	Classroom 200	yes	Door Casing 1	Metal	Beige	None	0	0.5	Negative
1380	1	2	200	Classroom 200	yes	Door Casing 4	Metal	Beige	None	0	1.5	Positive
1380	1	2	NP-2	Classroom 200 Storage Closet	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-2	Classroom 200 Storage Closet	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-2	Classroom 200 Storage Closet	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-2	Classroom 200 Storage Closet	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-2	Classroom 200 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	2	NP-2	Classroom 200 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	200A	Vestibule in Classroom 200 to Outdoor Roof Play Deck	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	200A	Vestibule in Classroom 200 to Outdoor Roof Play Deck	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	200A	Vestibule in Classroom 200 to Outdoor Roof Play Deck	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	200A	Vestibule in Classroom 200 to Outdoor Roof Play Deck	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	200A	Vestibule in Classroom 200 to Outdoor Roof Play Deck	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	200A	Vestibule in Classroom 200 to Outdoor Roof Play Deck	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-3	Classroom 200 Restroom	yes	W1	CMU	Blue	Flaking	2	0.1	Negative
1380	1	2	NP-3	Classroom 200 Restroom	yes	W2	CMU	Blue	Flaking	1	0.1	Negative
1380	1	2	NP-3	Classroom 200 Restroom	yes	W3	CMU	Blue	Flaking	7	0	Negative
1380	1	2	NP-3	Classroom 200 Restroom	yes	W4	CMU	Blue	Flaking	15	0	Negative
1380	1	2	NP-3	Classroom 200 Restroom	yes	Ceiling	Plaster	Tan	None	0	0.2	Negative
1380	1	2	NP-3	Classroom 200 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-3	Classroom 200 Restroom	yes	Pipe Chase Cover	Metal	Blue	Flaking	1	0.1	Negative
1380	1	2	NP-3	Classroom 200 Restroom	yes	Door Casing	Metal	Beige	None	0	1.7	Positive
1380	1	2	200B	Hallway Storage Closet across from Classroom 202	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	200B	Hallway Storage Closet across from Classroom 202	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	200B	Hallway Storage Closet across from Classroom 202	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	200B	Hallway Storage Closet across from Classroom 202	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	200B	Hallway Storage Closet across from Classroom 202	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	200B	Hallway Storage Closet across from Classroom 202	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	S23	Stairwell by Classroom 200	yes	W1	CMU	N/A	None	N/A	0	Negative
1380	1	2	S23	Stairwell by Classroom 200	yes	W2	CMU	N/A	None	N/A	0	Negative
1380	1	2	S23	Stairwell by Classroom 200	yes	W3	CMU	Beige	Peeling	5	0	Negative
1380	1	2	S23	Stairwell by Classroom 200	yes	W4	CMU	N/A	None	N/A	1.8	Positive
1380	1	2	S23	Stairwell by Classroom 200	yes	Ceiling	Metal	White	Flaking	70	0.5	Negative
1380	1	2	S23	Stairwell by Classroom 200	yes	Ceiling	I-Beam	White	None	0	1.3	Positive
1380	1	2	S23	Stairwell by Classroom 200	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	S23	Stairwell by Classroom 200	yes	Window Sill	Metal	Beige	Peeling	2	0.2	Negative
1380	1	2	201A	Staff Restroom at Classroom 201	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	201A	Staff Restroom at Classroom 201	yes	W2	CMU	Tan	Flaking	2	0.4	Negative
1380	1	2	201A	Staff Restroom at Classroom 201	yes	W3	CMU	Tan	Flaking	4	0.5	Negative
1380	1	2	201A	Staff Restroom at Classroom 201	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	2	201A	Staff Restroom at Classroom 201	yes	Ceiling	Drywall	Tan	None	0	0.1	Negative
1380	1	2	201A	Staff Restroom at Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	201A	Staff Restroom at Classroom 201	yes	Pipe Shaft Door	Metal	Beige	None	0	0.1	Negative
1380	1	2	201A	Staff Restroom at Classroom 201	yes	Door Casing	Metal	Beige	None	0	1	Positive
1380	1	2	201B	Custodial Closet next to Classroom 201	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	201B	Custodial Closet next to Classroom 201	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	2	201	Classroom 201	yes	W1	CMU	CMU	Tan	N/A	0.1	Negative
1380	1	2	201	Classroom 201	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	201	Classroom 201	yes	W3	CMU	CMU	Tan	N/A	0	Negative
1380	1	2	201	Classroom 201	yes	W4	CMU	CMU	Tan	N/A	0	Negative
1380	1	2	201	Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	201	Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	201	Classroom 201	yes	Window Sill	Metal	Beige	Flaking	2	0	Negative
1380	1	2	201	Classroom 201	yes	Door Casing	Metal	Beige	None	0	1.4	Positive
1380	1	2	202	Classroom 202	yes	W1	CMU	CMU	Tan	N/A	0	Negative
1380	1	2	202	Classroom 202	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202	Classroom 202	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	2	202	Classroom 202	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202	Classroom 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202	Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202	Classroom 202	yes	Window Sill	Metal	Beige	Flaking	2	0.2	Negative
1380	1	2	202	Classroom 202	yes	Door Casing	Metal	Beige	None	0	1.1	Positive
1380	1	2	200A	Storage Room beside Girl's Restroom	yes	W1	CMU	Tan	None	0	0.5	Negative
1380	1	2	200A	Storage Room beside Girl's Restroom	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	2	200A	Storage Room beside Girl's Restroom	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	2	200A	Storage Room beside Girl's Restroom	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	2	200A	Storage Room beside Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1380	1	2	200A	Storage Room beside Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202A	Girl's Restroom across from Classroom 202	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202A	Girl's Restroom across from Classroom 202	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202A	Girl's Restroom across from Classroom 202	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202A	Girl's Restroom across from Classroom 202	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202A	Girl's Restroom across from Classroom 202	yes	Ceiling	Plaster	Tan	Flaking	80	0.1	Negative
1380	1	2	202A	Girl's Restroom across from Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202A	Girl's Restroom across from Classroom 202	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	2	202A	Girl's Restroom across from Classroom 202	yes	Convactor	Metal	Beige	None	0	0	Negative
1380	1	2	202C	Boy's Restroom across from Classroom 202	yes	W1	CMU	Tan	None	5	0.4	Negative
1380	1	2	202C	Boy's Restroom across from Classroom 202	yes	W2	CMU	Tan	None	5	0	Negative
1380	1	2	202C	Boy's Restroom across from Classroom 202	yes	W3	CMU	Tan	None	5	0.1	Negative
1380	1	2	202C	Boy's Restroom across from Classroom 202	yes	W4	CMU	Tan	None	5	0.5	Negative
1380	1	2	202C	Boy's Restroom across from Classroom 202	yes	Ceiling	Plaster	Tan	Flaking	4	0.2	Negative
1380	1	2	202C	Boy's Restroom across from Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202C	Boy's Restroom across from Classroom 202	yes	Door Casing	Metal	Beige	None	0	0.3	Negative
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	202PC	Pipe Chase across from Boys Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	203	Classroom 203	yes	W1	CMU	Green	None	0	0.1	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	2	203	Classroom 203	yes	W2	CMU	Green	None	0	0.3	Negative
1380	1	2	203	Classroom 203	yes	W3	CMU	Green	None	0	0	Negative
1380	1	2	203	Classroom 203	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	203	Classroom 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	203	Classroom 203	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	203	Classroom 203	yes	Window Sill	Metal	Black	Flaking	3	0	Negative
1380	1	2	203	Classroom 203	yes	Door Casing	Metal	Beige	None	0	1.4	Positive
1380	1	2	204	Classroom 204	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	204	Classroom 204	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	2	204	Classroom 204	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	2	204	Classroom 204	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	2	204	Classroom 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	204	Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	204	Classroom 204	yes	Window Sill 3	Metal	Beige	Flaking	2	0	Negative
1380	1	2	204	Classroom 204	yes	Window Sill 4	Metal	Beige	Flaking	2	0.4	Negative
1380	1	2	204	Classroom 204	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	2	204A	Storage Room next to Classroom 204	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	204A	Storage Room next to Classroom 204	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	204A	Storage Room next to Classroom 204	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	204A	Storage Room next to Classroom 204	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	204A	Storage Room next to Classroom 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	204A	Storage Room next to Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H23	Hallway from Classrooms 200 to 204	yes	W1	CMU	Purple	None	0	0.1	Negative
1380	1	2	H23	Hallway from Classrooms 200 to 204	yes	W2	CMU	Purple	None	0	0.5	Negative
1380	1	2	H23	Hallway from Classrooms 200 to 204	yes	W3	CMU	Purple	None	0	1.5	Positive
1380	1	2	H23	Hallway from Classrooms 200 to 204	yes	W4	CMU	Purple	None	0	0.5	Negative
1380	1	2	H23	Hallway from Classrooms 200 to 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H23	Hallway from Classrooms 200 to 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H23	Hallway from Classrooms 200 to 204	yes	Door	Metal	Orange	None	0	1.1	Positive
1380	1	2	H23	Hallway from Classrooms 200 to 204	yes	Door Casing	Metal	Orange	None	0	1.9	Positive
1380	1	2	205	Classroom 205	yes	W1	CMU	Green	Flaking	2	0.1	Negative
1380	1	2	205	Classroom 205	yes	W2	CMU	Green	Flaking	15	0.1	Negative
1380	1	2	205	Classroom 205	yes	W3	CMU	Green	Flaking	10	0.1	Negative
1380	1	2	205	Classroom 205	yes	W4	CMU	Green	Flaking	12	0	Negative
1380	1	2	205	Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	205	Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	205	Classroom 205	yes	Window Sill	Metal	Beige	Flaking	7	0.2	Negative
1380	1	2	205	Classroom 205	yes	Door Casing 1	Metal	Beige	None	0	1.1	Positive
1380	1	2	205	Classroom 205	yes	Door Casing 2	Metal	Beige	None	0	1.6	Negative
1380	1	2	205A	Classroom 205 Closet	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	205A	Classroom 205 Closet	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	205A	Classroom 205 Closet	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	205A	Classroom 205 Closet	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	205A	Classroom 205 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	205A	Classroom 205 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-6	Classroom 205 Restroom	yes	W1	CMU	Tan	Flaking	10	0.5	Negative
1380	1	2	NP-6	Classroom 205 Restroom	yes	W2	CMU	Tan	Flaking	5	0.5	Negative
1380	1	2	NP-6	Classroom 205 Restroom	yes	W3	CMU	Tan	Flaking	20	0.1	Negative
1380	1	2	NP-6	Classroom 205 Restroom	yes	W4	CMU	Tan	Flaking	10	0.6	Negative
1380	1	2	NP-6	Classroom 205 Restroom	yes	Ceiling	Drywall	Tan	None	0	0.1	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	2	NP-6	Classroom 205 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-6	Classroom 205 Restroom	yes	Pipe Shaft Door	Metal	Tan	Flaking	2	0	Negative
1380	1	2	NP-6	Classroom 205 Restroom	yes	Door Casing	Metal	Beige	None	0	0.5	Negative
1380	1	2	206	Classroom 206	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	206	Classroom 206	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	2	206	Classroom 206	yes	W3	CMU	Tan	None	0	0.5	Negative
1380	1	2	206	Classroom 206	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	2	206	Classroom 206	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	206	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	206	Classroom 206	yes	Window Sill	Metal	Tan	Flaking	2	0	Negative
1380	1	2	206	Classroom 206	yes	Door Casing 1	Metal	Tan	None	0	1.7	Positive
1380	1	2	206	Classroom 206	yes	Door Casing 3	Metal	Tan	None	0	0.5	Negative
1380	1	2	206	Classroom 206	yes	Door Casing 4	Metal	Tan	None	0	1.8	Positive
1380	1	2	206A	Classroom 206 Restroom - along hallway wall	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	206A	Classroom 206 Restroom - along hallway wall	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	206A	Classroom 206 Restroom - along hallway wall	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	206A	Classroom 206 Restroom - along hallway wall	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	206A	Classroom 206 Restroom - along hallway wall	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	206A	Classroom 206 Restroom - along hallway wall	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	206A	Classroom 206 Restroom - along hallway wall	yes	Door Casing	Metal	Tan	None	0	0.4	Negative
1380	1	2	NP-8	Classroom 206 Storage Closet	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-8	Classroom 206 Storage Closet	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-8	Classroom 206 Storage Closet	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-8	Classroom 206 Storage Closet	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-8	Classroom 206 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-8	Classroom 206 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-7	Classroom 206 Restroom - along exterior wall	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	2	NP-7	Classroom 206 Restroom - along exterior wall	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	2	NP-7	Classroom 206 Restroom - along exterior wall	yes	W3	CMU	Tan	Flaking	8	0.4	Negative
1380	1	2	NP-7	Classroom 206 Restroom - along exterior wall	yes	W4	CMU	Tan	Flaking	3	0.5	Negative
1380	1	2	NP-7	Classroom 206 Restroom - along exterior wall	yes	Ceiling	Drywall	Tan	None	0	0.1	Negative
1380	1	2	NP-7	Classroom 206 Restroom - along exterior wall	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-7	Classroom 206 Restroom - along exterior wall	yes	Door Casing	Metal	Tan	None	0	0.4	Negative
1380	1	2	H24	Hallway at Classroom 206	yes	W1	CMU	Purple	None	0	4	Positive
1380	1	2	H24	Hallway at Classroom 206	yes	W2	CMU	Purple	None	0	0.1	Negative
1380	1	2	H24	Hallway at Classroom 206	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H24	Hallway at Classroom 206	yes	W4	CMU	Purple	Flaking	4	0	Negative
1380	1	2	H24	Hallway at Classroom 206	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H24	Hallway at Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	S24	Stairwell between Classrooms 206 and 207	yes	W1	CMU	N/A	None	N/A	0	Negative
1380	1	2	S24	Stairwell between Classrooms 206 and 207	yes	W2	CMU	N/A	None	N/A	2.7	Positive
1380	1	2	S24	Stairwell between Classrooms 206 and 207	yes	W3	CMU	N/A	None	N/A	0.3	Negative
1380	1	2	S24	Stairwell between Classrooms 206 and 207	yes	W4	CMU	Beige	Peeling	5	3	Positive
1380	1	2	S24	Stairwell between Classrooms 206 and 207	yes	Ceiling	Metal	White	Flaking	30	0.5	Negative
1380	1	2	S24	Stairwell between Classrooms 206 and 207	yes	Ceiling	I-Beam	White	None	0	2.3	Positive
1380	1	2	S24	Stairwell between Classrooms 206 and 207	yes	Floor	Concrete	GRAY	None	0	0.1	Negative
1380	1	2	S24	Stairwell between Classrooms 206 and 207	yes	Window Sill	Metal	Beige	Flaking	2	0.1	Negative
1380	1	2	215	Outdoor Roof Play Deck	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	215	Outdoor Roof Play Deck	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	215	Outdoor Roof Play Deck	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	2	215	Outdoor Roof Play Deck	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	215	Outdoor Roof Play Deck	yes	Ceiling	Concrete	Beige	None	0	0	Negative
1380	1	2	215	Outdoor Roof Play Deck	yes	Floor	Concrete	Beige	None	0	0.2	Negative
1380	1	2	215	Outdoor Roof Play Deck	yes	Door Casing 1	Metal	Beige	None	0	0.3	Negative
1380	1	2	215	Outdoor Roof Play Deck	yes	Door 1	Metal	Beige	None	0	0	Negative
1380	1	2	215	Outdoor Roof Play Deck	yes	Door 2	Metal	Beige	None	0	0.1	Negative
1380	1	2	215	Outdoor Roof Play Deck	yes	Door Casing 2	Metal	Beige	None	0	0.4	Negative
1380	1	2	215	Outdoor Roof Play Deck	yes	Door Casing 3	Metal	Beige	None	0	0.3	Negative
1380	1	2	215	Outdoor Roof Play Deck	yes	Door 3	Metal	Beige	None	0	0	Negative
1380	1	2	207	Classroom 207	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	2	207	Classroom 207	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	2	207	Classroom 207	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	2	207	Classroom 207	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	2	207	Classroom 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	207	Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	207	Classroom 207	yes	Window Sill	Metal	Tan	Flaking	4	0.1	Negative
1380	1	2	207	Classroom 207	yes	Door Casing 1	Metal	Beige	None	0	1.1	Positive
1380	1	2	207	Classroom 207	yes	Door Casing 2	Metal	Beige	None	0	1.4	Positive
1380	1	2	207	Classroom 207	yes	Door Casing 3	Metal	Beige	None	0	0.3	Negative
1380	1	2	NP-10	Classroom 207 Restroom	yes	W1	CMU	Tan	None	0	0.4	Negative
1380	1	2	NP-10	Classroom 207 Restroom	yes	W2	CMU	Tan	Flaking	2	0.1	Negative
1380	1	2	NP-10	Classroom 207 Restroom	yes	W3	CMU	Tan	Flaking	6	0	Negative
1380	1	2	NP-10	Classroom 207 Restroom	yes	W4	CMU	Tan	None	0	0.5	Negative
1380	1	2	NP-10	Classroom 207 Restroom	yes	Ceiling	Drywall	Tan	None	0	0.2	Negative
1380	1	2	NP-10	Classroom 207 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-10	Classroom 207 Restroom	yes	Pipe Chase Cover	Metal	Tan	Flaking	2	0.1	Negative
1380	1	2	NP-10	Classroom 207 Restroom	yes	Door Casing	Metal	Beige	None	0	0.5	Negative
1380	1	2	NP-9	Classroom 207 Storage Closet	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-9	Classroom 207 Storage Closet	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-9	Classroom 207 Storage Closet	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-9	Classroom 207 Storage Closet	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-9	Classroom 207 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-9	Classroom 207 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-9	Classroom 207 Storage Closet	yes	Door Casing	Metal	Beige	None	0	0.7	Positive
1380	1	2	208	Classroom 208	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	2	208	Classroom 208	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	2	208	Classroom 208	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	2	208	Classroom 208	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	2	208	Classroom 208	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	208	Classroom 208	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	208	Classroom 208	yes	Window Sill	Metal	Beige	Flaking	2	0	Negative
1380	1	2	208	Classroom 208	yes	Door Casing	Metal	Beige	None	0	1.2	Positive
1380	1	2	208A	Classroom 208 Restroom	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	2	208A	Classroom 208 Restroom	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	2	208A	Classroom 208 Restroom	yes	W3	CMU	Tan	Flaking	4	0.5	Negative
1380	1	2	208A	Classroom 208 Restroom	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	2	208A	Classroom 208 Restroom	yes	Ceiling	Plaster	Tan	None	0	0.2	Negative
1380	1	2	208A	Classroom 208 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	208A	Classroom 208 Restroom	yes	Door Casing	Metal	Beige	None	0	1.1	Positive

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	2	H22	Center Hallway outside Classroom 215	yes	W1	CMU	Purple	None	0	0.1	Negative
1380	1	2	H22	Center Hallway outside Classroom 215	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H22	Center Hallway outside Classroom 215	yes	W3	CMU	Purple	None	0	0.1	Negative
1380	1	2	H22	Center Hallway outside Classroom 215	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H22	Center Hallway outside Classroom 215	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H22	Center Hallway outside Classroom 215	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H22	Center Hallway outside Classroom 215	yes	Door	Metal	Yellow	None	0	3.4	Positive
1380	1	2	H22	Center Hallway outside Classroom 215	yes	Door Casing	Metal	Yellow	None	0	3.5	Positive
1380	1	2	H22	Center Hallway outside Classroom 215	yes	Door Casing	Metal	Beige	None	0	0.2	Negative
1380	1	2	H22	Center Hallway outside Classroom 215	yes	Door	Metal	Beige	None	0	0.1	Negative
1380	1	2	209	Classroom 209	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	209	Classroom 209	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	2	209	Classroom 209	yes	W3	CMU	Tan	None	0	0.5	Negative
1380	1	2	209	Classroom 209	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	2	209	Classroom 209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	209	Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	209	Classroom 209	yes	Window Sill 3	Metal	Beige	Flaking	1	0.1	Negative
1380	1	2	209	Classroom 209	yes	Door Casing	Metal	Beige	None	0	1.6	Negative
1380	1	2	209A	Storage Room next to Classroom 209	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	209A	Storage Room next to Classroom 209	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	209A	Storage Room next to Classroom 209	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	209A	Storage Room next to Classroom 209	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	209A	Storage Room next to Classroom 209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	209A	Storage Room next to Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	210	Classroom 210	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	210	Classroom 210	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	210	Classroom 210	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	2	210	Classroom 210	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	2	210	Classroom 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	210	Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	210	Classroom 210	yes	Window Sill	Metal	Beige	Flaking	2	0.4	Negative
1380	1	2	210	Classroom 210	yes	Door Casing	Metal	Beige	None	0	1.5	Positive
1380	1	2	210A	Janitor's Closet beside Classroom 210	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	210A	Janitor's Closet beside Classroom 210	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	210A	Janitor's Closet beside Classroom 210	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	210A	Janitor's Closet beside Classroom 210	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	210A	Janitor's Closet beside Classroom 210	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	210A	Janitor's Closet beside Classroom 210	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	211	Classroom 211	yes	W1	CMU	Tan	None	0	0.4	Negative
1380	1	2	211	Classroom 211	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	2	211	Classroom 211	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	2	211	Classroom 211	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	211	Classroom 211	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	211	Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	211	Classroom 211	yes	Window Sill	Metal	Tan	None	0	0.1	Negative
1380	1	2	211	Classroom 211	yes	Door Casing	Metal	GRAY	None	0	1.4	Positive
1380	1	2	211	Classroom 211	yes	Door	Metal	GRAY	Peeling	4	0	Negative
1380	1	2	E01	Elevator next to Girl's Restroom across from Classroom 211	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	2	E01	Elevator next to Girl's Restroom across from Classroom 211	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	E01	Elevator next to Girl's Restroom across from Classroom 211	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	E01	Elevator next to Girl's Restroom across from Classroom 211	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	E01	Elevator next to Girl's Restroom across from Classroom 211	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	E01	Elevator next to Girl's Restroom across from Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	E01	Elevator next to Girl's Restroom across from Classroom 211	yes	Door	Metal	Beige	Peeling	2	0.1	Negative
1380	1	2	E01	Elevator next to Girl's Restroom across from Classroom 211	yes	Door Casing	Metal	Beige	None	0	0.5	Negative
1380	1	2	211A	Girl's Restroom across from Classroom 211	yes	W1	CMU	Yellow	None	5	0.5	Negative
1380	1	2	211A	Girl's Restroom across from Classroom 211	yes	W2	CMU	Yellow	None	0	0	Negative
1380	1	2	211A	Girl's Restroom across from Classroom 211	yes	W3	CMU	Yellow	None	0	0.6	Negative
1380	1	2	211A	Girl's Restroom across from Classroom 211	yes	W4	CMU	Yellow	None	0	0.5	Negative
1380	1	2	211A	Girl's Restroom across from Classroom 211	yes	Ceiling	Drywall	Yellow	None	0	0.1	Negative
1380	1	2	211A	Girl's Restroom across from Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	211A	Girl's Restroom across from Classroom 211	yes	Door	Metal	Beige	None	0	0.7	Positive
1380	1	2	211A	Girl's Restroom across from Classroom 211	yes	Convectector	Metal	Beige	None	0	0	Negative
1380	1	2	211B	Boy's Restroom across from Classroom 211	yes	W1	CMU	Yellow	None	0	0.5	Negative
1380	1	2	211B	Boy's Restroom across from Classroom 211	yes	W2	CMU	Yellow	None	0	0	Negative
1380	1	2	211B	Boy's Restroom across from Classroom 211	yes	W3	CMU	Yellow	None	0	0.5	Negative
1380	1	2	211B	Boy's Restroom across from Classroom 211	yes	W4	CMU	Yellow	None	0	0	Negative
1380	1	2	211B	Boy's Restroom across from Classroom 211	yes	Ceiling	Drywall	Yellow	None	0	0	Negative
1380	1	2	211B	Boy's Restroom across from Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	211B	Boy's Restroom across from Classroom 211	yes	Pipe Shaft Door	Metal	Yellow	Flaking	2	0.1	Negative
1380	1	2	211B	Boy's Restroom across from Classroom 211	yes	Door Casing	Metal	Tan	None	0	0.4	Negative
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	Ceiling	Plaster	Tan	None	0	0.2	Negative
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	Floor	Concrete	GRAY	None	0	0.1	Negative
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	Door Casing	Metal	Tan	None	0	0.3	Negative
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	Data Panel	Wood	White	None	0	0.1	Negative
1380	1	2	213B	Classroom 213 Storage Room/Electrical Closet	yes	Door	Metal	Yellow	None	0	0.1	Negative
1380	1	2	213	Classroom 213	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	213	Classroom 213	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	2	213	Classroom 213	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	2	213	Classroom 213	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	2	213	Classroom 213	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	213	Classroom 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	213	Classroom 213	yes	Door Casing 1	Metal	Tan	None	0	0.4	Negative
1380	1	2	213	Classroom 213	yes	Door Casing 2	Metal	Tan	None	0	0.6	Negative
1380	1	2	213	Classroom 213	yes	Door	Metal	Tan	None	0	0.1	Negative
1380	1	2	213A	Storage between 214 and 213	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	2	213A	Storage between 214 and 213	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	Door Casing	Metal	Beige	None	0	0.5	Negative
1380	1	2	213A	Storage between 214 and 213	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	Storage between 214 and 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	214A: Storage between 214 and 213	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	214A: Storage between 214 and 213	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	214A: Storage between 214 and 213	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	214A: Storage between 214 and 213	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	214A: Storage between 214 and 213	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	213A	214A: Storage between 214 and 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	212	Classroom 212	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	212	Classroom 212	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	2	212	Classroom 212	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	2	212	Classroom 212	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	2	212	Classroom 212	yes	Ceiling	N/A	Tan	N/A	N/A	N/A	N/A
1380	1	2	212	Classroom 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	212	Classroom 212	yes	Window Sill	Metal	Beige	Flaking	4	0.1	Negative
1380	1	2	212	Classroom 212	yes	Door Casing	Metal	Beige	None	0	1.3	Positive
1380	1	2	212	Classroom 212	yes	Door	Wood	Blue	None	0	0	Negative
1380	1	2	212A	Classroom 212 Restroom	yes	W1	CMU	Tan	None	0	0.2	Negative
1380	1	2	212A	Classroom 212 Restroom	yes	W2	CMU	Tan	Flaking	2	0.2	Negative
1380	1	2	212A	Classroom 212 Restroom	yes	W3	CMU	Tan	Flaking	4	0.1	Negative
1380	1	2	212A	Classroom 212 Restroom	yes	W4	CMU	Tan	Flaking	3	0.6	Negative
1380	1	2	212A	Classroom 212 Restroom	yes	Ceiling	Drywall	Tan	None	0	0.1	Negative
1380	1	2	212A	Classroom 212 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	212A	Classroom 212 Restroom	yes	Pipe Shaft Door	Metal	Tan	None	0	0.1	Negative
1380	1	2	212A	Classroom 212 Restroom	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	2	214	Classroom 214	yes	W1	CMU	Blue	Flaking	4	0.5	Negative
1380	1	2	214	Classroom 214	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	2	214	Classroom 214	yes	W3	CMU	Tan	Flaking	10	0.5	Negative
1380	1	2	214	Classroom 214	yes	W4	CMU	Tan	Flaking	5	0.1	Negative
1380	1	2	214	Classroom 214	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	214	Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	214	Classroom 214	yes	Window Casing	Metal	Tan	None	0	0.5	Negative
1380	1	2	214	Classroom 214	yes	Door Casing 1	Metal	Tan	None	0	0.5	Negative
1380	1	2	214	Classroom 214	yes	Door Casing 2	Metal	Tan	None	0	0.6	Negative
1380	1	2	214A	Hallway between Classroom 214 and Office Beside Classroom 214	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	Hallway between Classroom 214 and Office Beside Classroom 214	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	Hallway between Classroom 214 and Office Beside Classroom 214	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	Hallway between Classroom 214 and Office Beside Classroom 214	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	2	214A	Hallway between Classroom 214 and Office Beside Classroom 214	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	Hallway between Classroom 214 and Office Beside Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	214A: Hallway between Classroom 214 and Office Beside Classroom 214	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	214A: Hallway between Classroom 214 and Office Beside Classroom 214	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	214A: Hallway between Classroom 214 and Office Beside Classroom 214	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	214A: Hallway between Classroom 214 and Office Beside Classroom 214	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	214A: Hallway between Classroom 214 and Office Beside Classroom 214	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	214A	214A: Hallway between Classroom 214 and Office Beside Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-1	Office beside Classroom 214	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	2	NP-1	Office beside Classroom 214	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	2	NP-1	Office beside Classroom 214	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	2	NP-1	Office beside Classroom 214	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	2	NP-1	Office beside Classroom 214	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-1	Office beside Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	NP-1	Office beside Classroom 214	yes	Door Casing	Metal	Tan	None	0	1.4	Positive
1380	1	2	H21	Hallway from Classrooms 209 to 214	yes	W1	CMU	Purple	None	0	0.5	Negative
1380	1	2	H21	Hallway from Classrooms 209 to 214	yes	W2	CMU	Purple	None	0	0	Negative
1380	1	2	H21	Hallway from Classrooms 209 to 214	yes	W3	CMU	Blue	None	0	0	Negative
1380	1	2	H21	Hallway from Classrooms 209 to 214	yes	W4	CMU	Purple	None	0	0.1	Negative
1380	1	2	H21	Hallway from Classrooms 209 to 214	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H21	Hallway from Classrooms 209 to 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	H21	Hallway from Classrooms 209 to 214	yes	Door Casing	Metal	Blue	None	0	1	Positive
1380	1	2	H21	Hallway from Classrooms 209 to 214	yes	Door	Metal	Blue	None	0	0	Negative
1380	1	2	S21	Stairwell by Classroom 214	yes	W1	CMU	N/A	None	N/A	0	Negative
1380	1	2	S21	Stairwell by Classroom 214	yes	W2	CMU	Beige	Flaking	3	0.01	Negative
1380	1	2	S21	Stairwell by Classroom 214	yes	W3	CMU	N/A	None	N/A	0	Negative
1380	1	2	S21	Stairwell by Classroom 214	yes	W4	CMU	N/A	None	N/A	0.04	Negative
1380	1	2	S21	Stairwell by Classroom 214	yes	Ceiling	Metal	White	Flaking	90	0.4	Negative
1380	1	2	S21	Stairwell by Classroom 214	yes	Ceiling	I-Beam	White	Flaking	1	2.7	Positive
1380	1	2	S21	Stairwell by Classroom 214	yes	Floor	Concrete	Grey	Flaking	5	0.02	Negative
1380	1	2	S21	Stairwell by Classroom 214	yes	Window Sill	Metal	Beige	Peeling	2	0.5	Negative
1380	1	2	J2	Custodial Closet next to Classroom 212	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	J2	Custodial Closet next to Classroom 212	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	J2	Custodial Closet next to Classroom 212	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	J2	Custodial Closet next to Classroom 212	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	2	J2	Custodial Closet next to Classroom 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	2	J2	Custodial Closet next to Classroom 212	yes	Floor	Concrete	GRAY	None	0	0.1	Negative
1380	1	2	J2	Custodial Closet next to Classroom 212	yes	Door Casing	Metal	Tan	None	0	0.5	Negative
1380	1	3	300	Classroom 300	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	300	Classroom 300	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	3	300	Classroom 300	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	300	Classroom 300	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	3	300	Classroom 300	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	300	Classroom 300	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	3	300	Classroom 300	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	3	300	Classroom 300	yes	Window Sill	Metal	Beige	None	0	0.1	Negative
1380	1	3	S33	Stairwell outside Classroom 300	yes	W1	CMU	Beige	Peeling	3	0	Negative
1380	1	3	S33	Stairwell outside Classroom 300	yes	W2	Drywall	Beige	None	0	0.1	Negative
1380	1	3	S33	Stairwell outside Classroom 300	yes	W3	CMU	N/A	None	N/A	0	Negative
1380	1	3	S33	Stairwell outside Classroom 300	yes	W4	CMU	N/A	None	N/A	1.8	Positive
1380	1	3	S33	Stairwell outside Classroom 300	yes	Door	Wood	Beige	Peeling	2	0.1	Negative
1380	1	3	S33	Stairwell outside Classroom 300	yes	Door Casing	Metal	Beige	None	0	0	Negative
1380	1	3	S33	Stairwell outside Classroom 300	yes	Ceiling	Metal	White	Flaking	120	0.5	Negative
1380	1	3	S33	Stairwell outside Classroom 300	yes	Ceiling	I-Beam	White	Flaking	5	2.5	Positive
1380	1	3	S33	Stairwell outside Classroom 300	yes	Floor	Concrete	GRAY	None	0	0.1	Negative
1380	1	3	S33	Stairwell outside Classroom 300	yes	Window Sill	Metal	Beige	Peeling	2	0.1	Negative
1380	1	3	NP-2	Custodial Closet next to Classroom 301	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-2	Custodial Closet next to Classroom 301	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-2	Custodial Closet next to Classroom 301	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-2	Custodial Closet next to Classroom 301	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-2	Custodial Closet next to Classroom 301	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-2	Custodial Closet next to Classroom 301	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	301	Classroom 301	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	301	Classroom 301	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	301	Classroom 301	yes	W3	CMU	Tan	None	0	0.4	Negative
1380	1	3	301	Classroom 301	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	3	301	Classroom 301	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	301	Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	301	Classroom 301	yes	Door Casing	Metal	Beige	None	0	0.5	Negative
1380	1	3	301	Classroom 301	yes	Cabinet Door	Metal	White	None	0	0.1	Negative
1380	1	3	301	Classroom 301	yes	Window Sill	Metal	Beige	None	0	0.4	Negative
1380	1	3	301A	Staff Restroom next to Classroom 301	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	301A	Staff Restroom next to Classroom 301	yes	W2	CMU	Tan	None	0	0.4	Negative
1380	1	3	301A	Staff Restroom next to Classroom 301	yes	W3	CMU	Tan	Flaking	2	0.4	Negative
1380	1	3	301A	Staff Restroom next to Classroom 301	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	3	301A	Staff Restroom next to Classroom 301	yes	Ceiling	Plaster	Tan	None	0	0	Negative
1380	1	3	301A	Staff Restroom next to Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	301A	Staff Restroom next to Classroom 301	yes	Door Casing	Metal	Beige	None	0	0.5	Negative
1380	1	3	301A	Staff Restroom next to Classroom 301	yes	Pipe Shaft Door	Metal	Beige	None	0	0	Negative
1380	1	3	302	Office 302	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	302	Office 302	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	302	Office 302	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	302	Office 302	yes	W4	CMU	Tan	None	0	0.4	Negative
1380	1	3	302	Office 302	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	302	Office 302	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	302	Office 302	yes	Door Casing	Metal	Beige	None	0	0.5	Negative
1380	1	3	303	Classroom 303	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	303	Classroom 303	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	303	Classroom 303	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	303	Classroom 303	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	303	Classroom 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	303	Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	303	Classroom 303	yes	Door Casing	Metal	Beige	None	0	0.5	Negative
1380	1	3	303	Classroom 303	yes	Window Sill	Metal	Beige	None	0	0.1	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	3	303A	Boy's Restroom across from Classroom 303	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	303A	Boy's Restroom across from Classroom 303	yes	W2	CMU	Tan	Flaking	7	0.1	Negative
1380	1	3	303A	Boy's Restroom across from Classroom 303	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	303A	Boy's Restroom across from Classroom 303	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	3	303A	Boy's Restroom across from Classroom 303	yes	Ceiling	Plaster	Tan	None	0	0.1	Negative
1380	1	3	303A	Boy's Restroom across from Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	303A	Boy's Restroom across from Classroom 303	yes	Door Casing	Metal	Beige	None	0	0.1	Negative
1380	1	3	303B	Girl's Restroom across from Classroom 303	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	303B	Girl's Restroom across from Classroom 303	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	3	303B	Girl's Restroom across from Classroom 303	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	303B	Girl's Restroom across from Classroom 303	yes	W4	CMU	Tan	None	0	0.5	Negative
1380	1	3	303B	Girl's Restroom across from Classroom 303	yes	Ceiling	Plaster	Tan	None	0	0.1	Negative
1380	1	3	303B	Girl's Restroom across from Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	303B	Girl's Restroom across from Classroom 303	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	3	303B	Girl's Restroom across from Classroom 303	yes	Convector	Metal	Beige	None	0	0	Negative
1380	1	3	303C	Storage next to Girl's Restroom across from Classroom 303	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	303C	Storage next to Girl's Restroom across from Classroom 303	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	303C	Storage next to Girl's Restroom across from Classroom 303	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	303C	Storage next to Girl's Restroom across from Classroom 303	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	303C	Storage next to Girl's Restroom across from Classroom 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	303C	Storage next to Girl's Restroom across from Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	304	Classroom 304	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	304	Classroom 304	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	3	304	Classroom 304	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	304	Classroom 304	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	304	Classroom 304	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	304	Classroom 304	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	304	Classroom 304	yes	Door	Metal	Beige	None	0	0.3	Negative
1380	1	3	304	Classroom 304	yes	Window Sill	Metal	Beige	None	0	0.1	Negative
1380	1	3	305	Classroom 305	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	305	Classroom 305	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	305	Classroom 305	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	3	305	Classroom 305	yes	W4	CMU	Tan	Flaking	1	0	Negative
1380	1	3	305	Classroom 305	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	305	Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	305	Classroom 305	yes	Window Sill 2	Metal	Beige	None	0	0	Negative
1380	1	3	305	Classroom 305	yes	Window Sill 3	Metal	Beige	None	0	0.5	Negative
1380	1	3	NP-3	Storage Room next to Classroom 305	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-3	Storage Room next to Classroom 305	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-3	Storage Room next to Classroom 305	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-3	Storage Room next to Classroom 305	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-3	Storage Room next to Classroom 305	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-3	Storage Room next to Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	306	Classroom 306	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	306	Classroom 306	yes	W2	Drywall	Tan	Peeling	3	0.1	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	3	306	Classroom 306	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	3	306	Classroom 306	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	3	306	Classroom 306	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	306	Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	306	Classroom 306	yes	Door Casing	Metal	Beige	None	0	0.8	Positive
1380	1	3	306	Classroom 306	yes	Window Sill	Metal	Beige	None	0	0	Negative
1380	1	3	307	Classroom 307	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	307	Classroom 307	yes	W2	CMU	Tan	Peeling	3	0.5	Negative
1380	1	3	307	Classroom 307	yes	W3	CMU	Tan	None	0	0.2	Negative
1380	1	3	307	Classroom 307	yes	W4	Drywall	Tan	None	0	0.1	Negative
1380	1	3	307	Classroom 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	307	Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	307	Classroom 307	yes	Window Sill	Metal	Beige	Flaking	2	0.1	Negative
1380	1	3	307	Classroom 307	yes	Door Casing 1	Metal	Beige	None	0	0.4	Negative
1380	1	3	307	Classroom 307	yes	Door Casing 4	Metal	Beige	None	0	0.1	Negative
1380	1	3	H33	Hallway from Classrooms 300 to 306	yes	W1	CMU	Green	None	0	0.4	Negative
1380	1	3	H33	Hallway from Classrooms 300 to 306	yes	W2	CMU	Green	None	0	0.5	Negative
1380	1	3	H33	Hallway from Classrooms 300 to 306	yes	W3	CMU	Green	None	0	1	Positive
1380	1	3	H33	Hallway from Classrooms 300 to 306	yes	W4	CMU	Green	None	0	0.5	Negative
1380	1	3	H33	Hallway from Classrooms 300 to 306	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H33	Hallway from Classrooms 300 to 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H33	Hallway from Classrooms 300 to 306	yes	Door	Metal	Orange	Flaking	2	0	Negative
1380	1	3	H33	Hallway from Classrooms 300 to 306	yes	Door Casing	Metal	Orange	None	0	1.7	Positive
1380	1	3	308	IMC (Library)	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	308	IMC (Library)	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	308	IMC (Library)	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	308	IMC (Library)	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	3	308	IMC (Library)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	308	IMC (Library)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	308	IMC (Library)	yes	Door Casing 1	Metal	Beige	None	0	0.4	Negative
1380	1	3	308	IMC (Library)	yes	Door Casing 2	Metal	Beige	None	0	0.2	Negative
1380	1	3	308	IMC (Library)	yes	Window Sill 3	Metal	Beige	None	0	0.1	Negative
1380	1	3	308	IMC (Library)	yes	Door Casing 4	Metal	Beige	None	0	0.1	Negative
1380	1	3	308A	Classroom 308A in IMC	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	308A	Classroom 308A in IMC	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	308A	Classroom 308A in IMC	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	308A	Classroom 308A in IMC	yes	W4	CMU	Tan	None	0	0.4	Negative
1380	1	3	308A	Classroom 308A in IMC	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	308A	Classroom 308A in IMC	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	308A	Classroom 308A in IMC	yes	Door Casing	Metal	Beige	None	0	0.3	Negative
1380	1	3	308B	Office 308B in IMC	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	308B	Office 308B in IMC	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	308B	Office 308B in IMC	yes	W3	CMU	Tan	None	0	0.5	Negative
1380	1	3	308B	Office 308B in IMC	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	3	308B	Office 308B in IMC	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	308B	Office 308B in IMC	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	308B	Office 308B in IMC	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	3	308B	Office 308B in IMC	yes	Window Sill	Metal	Beige	None	0	1.2	Positive
1380	1	3	H32	Hallway outside of IMC	yes	W1	CMU	Green	None	0	0.1	Negative
1380	1	3	H32	Hallway outside of IMC	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	3	H32	Hallway outside of IMC	yes	W3	CMU	Green	None	0	0.5	Negative
1380	1	3	H32	Hallway outside of IMC	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H32	Hallway outside of IMC	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H32	Hallway outside of IMC	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H32	Hallway outside of IMC	yes	Window Sill	Metal	Beige	None	0	0.5	Negative
1380	1	3	309	Classroom 309	yes	W1	CMU	Blue	None	0	0	Negative
1380	1	3	309	Classroom 309	yes	W2	Drywall	Blue	Flaking	10	0.1	Negative
1380	1	3	309	Classroom 309	yes	W2	CMU	Blue	None	0	0.1	Negative
1380	1	3	309	Classroom 309	yes	W3	CMU	Blue	None	0	0.5	Negative
1380	1	3	309	Classroom 309	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	309	Classroom 309	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	309	Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	309	Classroom 309	yes	Door Casing	Metal	Beige	None	0	1.4	Positive
1380	1	3	309	Classroom 309	yes	Window Sill	Metal	Beige	None	0	0.1	Negative
1380	1	3	310	Classroom 310	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	310	Classroom 310	yes	W2	CMU	Tan	None	0	0.1	Negative
1380	1	3	310	Classroom 310	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	310	Classroom 310	yes	W4	Drywall	Tan	Flaking	5	0.1	Negative
1380	1	3	310	Classroom 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	310	Classroom 310	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	310	Classroom 310	yes	Window Sill	Metal	Beige	Flaking	3	0.1	Negative
1380	1	3	310	Classroom 310	yes	Door Casing 1	Metal	Beige	None	0	0.7	Positive
1380	1	3	310	Classroom 310	yes	Door Casing 3	Metal	Beige	None	0	0.2	Negative
1380	1	3	311	Classroom 311	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	311	Classroom 311	yes	W2	Drywall	Blue	Flaking	10	0.1	Negative
1380	1	3	311	Classroom 311	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	311	Classroom 311	yes	W4	CMU	Blue	None	0	0	Negative
1380	1	3	311	Classroom 311	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	311	Classroom 311	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	311	Classroom 311	yes	Door Casing 1	Metal	Beige	None	0	0.9	Positive
1380	1	3	311	Classroom 311	yes	Door Casing 2	Metal	Beige	None	0	0.1	Negative
1380	1	3	311	Classroom 311	yes	Door Casing 3	Metal	Beige	None	0	0.4	Negative
1380	1	3	311	Classroom 311	yes	Window Sill 4	Metal	Beige	None	0	0.1	Negative
1380	1	3	312	Classroom 312	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	312	Classroom 312	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	312	Classroom 312	yes	W3	CMU	Tan	Flaking	10	0	Negative
1380	1	3	312	Classroom 312	yes	W4	Drywall	Blue	None	0	0	Negative
1380	1	3	312	Classroom 312	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	312	Classroom 312	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	312	Classroom 312	yes	Window Sill	Metal	Beige	Flaking	1	0.1	Negative
1380	1	3	312	Classroom 312	yes	Door Casing 1	Metal	Beige	None	0	1.3	Positive
1380	1	3	312	Classroom 312	yes	Door Casing 4	Metal	Beige	None	0	0	Negative
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	W1	CMU	Green	None	0	4.2	Positive
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	W2	CMU	Green	None	0	0.2	Negative
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	Window Sill	Metal	Beige	Flaking	2	0.4	Negative
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	Door Casing	Metal	Yellow	None	0	3.5	Positive

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	Door	Metal	Yellow	None	0	3.8	Positive
1380	1	3	H34	Hallway from IMC to Classroom 310	yes	Window Sill	Metal	Beige	None	0	0.3	Negative
1380	1	3	S34	Stairwell by Classroom 310	yes	W1	CMU	Beige	Peeling	1	0	Negative
1380	1	3	S34	Stairwell by Classroom 310	yes	W2	Drywall	Beige	None	0	0.1	Negative
1380	1	3	S34	Stairwell by Classroom 310	yes	W3	CMU	N/A	None	N/A	0.3	Negative
1380	1	3	S34	Stairwell by Classroom 310	yes	W4	CMU	Beige	Peeling	6	3	Positive
1380	1	3	S34	Stairwell by Classroom 310	yes	Ceiling	Metal	White	Flaking	18	0.5	Negative
1380	1	3	S34	Stairwell by Classroom 310	yes	Ceiling	I-Beam	White	Flaking	8	1.1	Positive
1380	1	3	S34	Stairwell by Classroom 310	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	S34	Stairwell by Classroom 310	yes	Window Sill	Metal	Beige	N/A	2	0.1	Negative
1380	1	3	314	314: Storage Closet	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	314	314: Storage Closet	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	314	314: Storage Closet	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	314	314: Storage Closet	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	314	314: Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	314	314: Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	S31	Stairwell next to Classroom 315	yes	W1	CMU	Beige	Peeling	1	0	Negative
1380	1	3	S31	Stairwell next to Classroom 315	yes	W2	CMU	N/A	None	N/A	0.01	Negative
1380	1	3	S31	Stairwell next to Classroom 315	yes	W3	CMU	N/A	None	N/A	0	Negative
1380	1	3	S31	Stairwell next to Classroom 315	yes	W4	Drywall	Beige	Flaking	1	0.1	Negative
1380	1	3	S31	Stairwell next to Classroom 315	yes	Ceiling	Metal	White	Flaking	120	0.6	Negative
1380	1	3	S31	Stairwell next to Classroom 315	yes	Ceiling	I-Beam	White	Flaking	1	2.7	Positive
1380	1	3	S31	Stairwell next to Classroom 315	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	S31	Stairwell next to Classroom 315	yes	Window Sill	Metal	Beige	Peeling	2	0.1	Negative
1380	1	3	314A	Staff Restroom next to Classroom 315	yes	W1	CMU	Tan	None	0	0.5	Negative
1380	1	3	314A	Staff Restroom next to Classroom 315	yes	W2	CMU	Tan	None	0	0.5	Negative
1380	1	3	314A	Staff Restroom next to Classroom 315	yes	W3	CMU	Tan	Flaking	5	0.4	Negative
1380	1	3	314A	Staff Restroom next to Classroom 315	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	3	314A	Staff Restroom next to Classroom 315	yes	Ceiling	Plaster	Tan	Flaking	1	0.1	Negative
1380	1	3	314A	Staff Restroom next to Classroom 315	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	314A	Staff Restroom next to Classroom 315	yes	Door Casing	Metal	Beige	None	0	1.7	Positive
1380	1	3	314A	Staff Restroom next to Classroom 315	yes	Pipe Shaft Door	Metal	Tan	None	0	0	Negative
1380	1	3	NP-1	Custodial Closet next to Classroom 315	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-1	Custodial Closet next to Classroom 315	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-1	Custodial Closet next to Classroom 315	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-1	Custodial Closet next to Classroom 315	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-1	Custodial Closet next to Classroom 315	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-1	Custodial Closet next to Classroom 315	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	313	Classroom 313	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	313	Classroom 313	yes	W2	CMU	Tan	Flaking	20	0	Negative
1380	1	3	313	Classroom 313	yes	W3	CMU	Tan	None	0	0.5	Negative
1380	1	3	313	Classroom 313	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	3	313	Classroom 313	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	313	Classroom 313	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	313	Classroom 313	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	3	315	Classroom 315	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	315	Classroom 315	yes	W2	CMU	Tan	None	0	0.4	Negative
1380	1	3	315	Classroom 315	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	3	315	Classroom 315	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	3	315	Classroom 315	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1380	1	3	315	Classroom 315	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	315	Classroom 315	yes	Door Casing	Metal	Beige	None	0	1.8	Positive
1380	1	3	315	Classroom 315	yes	Window Sill	Metal	White	None	0	0	Negative
1380	1	3	316	Classroom 316	yes	W1	CMU	Tan	None	0	0.1	Negative
1380	1	3	316	Classroom 316	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	316	Classroom 316	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	316	Classroom 316	yes	W4	Divider	N/A	N/A	N/A	N/A	N/A
1380	1	3	316	Classroom 316	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	316	Classroom 316	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	316	Classroom 316	yes	Door Casing	Metal	Beige	None	0	2.2	Positive
1380	1	3	316	Classroom 316	yes	Window Sill	Metal	Beige	None	0	0.1	Negative
1380	1	3	NP-4	Storage Room/Electrical Closet next to Elevator	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-4	Storage Room/Electrical Closet next to Elevator	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-4	Storage Room/Electrical Closet next to Elevator	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-4	Storage Room/Electrical Closet next to Elevator	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-4	Storage Room/Electrical Closet next to Elevator	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	NP-4	Storage Room/Electrical Closet next to Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	316A	Boy's Restroom across from Classroom 316	yes	W1	CMU	Tan	None	0	0.5	Negative
1380	1	3	316A	Boy's Restroom across from Classroom 316	yes	W2	CMU	Tan	Flaking	15	0.1	Negative
1380	1	3	316A	Boy's Restroom across from Classroom 316	yes	W3	CMU	Tan	Flaking	1	0.5	Negative
1380	1	3	316A	Boy's Restroom across from Classroom 316	yes	W4	CMU	Tan	None	0	0	Negative
1380	1	3	316A	Boy's Restroom across from Classroom 316	yes	Pipe Chase Cover	Metal	Tan	Flaking	1	0.1	Negative
1380	1	3	316A	Boy's Restroom across from Classroom 316	yes	Ceiling	Plaster	Tan	None	0	0.4	Negative
1380	1	3	316A	Boy's Restroom across from Classroom 316	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	316A	Boy's Restroom across from Classroom 316	yes	Door Casing	Metal	Beige	None	0	0.2	Negative
1380	1	3	316B	Girl's Restroom across from Classroom 316	yes	W1	CMU	Tan	Flaking	2	0.1	Negative
1380	1	3	316B	Girl's Restroom across from Classroom 316	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	316B	Girl's Restroom across from Classroom 316	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	316B	Girl's Restroom across from Classroom 316	yes	W4	CMU	Tan	Flaking	1	0.1	Negative
1380	1	3	316B	Girl's Restroom across from Classroom 316	yes	Ceiling	Plaster	Tan	None	0	0	Negative
1380	1	3	316B	Girl's Restroom across from Classroom 316	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	316B	Girl's Restroom across from Classroom 316	yes	Door Casing	Metal	Beige	None	0	0.4	Negative
1380	1	3	317	Classroom 317	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	317	Classroom 317	yes	W2	Divider	N/A	N/A	N/A	N/A	N/A
1380	1	3	317	Classroom 317	yes	W3	CMU	Tan	None	0	0	Negative
1380	1	3	317	Classroom 317	yes	W4	CMU	Tan	None	0	0.4	Negative
1380	1	3	317	Classroom 317	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	317	Classroom 317	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	317	Classroom 317	yes	Door Casing	Metal	Beige	None	0	2.1	Positive
1380	1	3	317	Classroom 317	yes	Window Sill	Metal	Beige	None	0	0	Negative
1380	1	3	318	Classroom 318	yes	W1	CMU	Tan	None	0	0	Negative
1380	1	3	318	Classroom 318	yes	W2	CMU	Tan	None	0	0	Negative
1380	1	3	318	Classroom 318	yes	W3	CMU	Tan	None	0	0.1	Negative
1380	1	3	318	Classroom 318	yes	W4	CMU	Tan	None	0	0.1	Negative
1380	1	3	318	Classroom 318	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	318	Classroom 318	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	318	Classroom 318	yes	Door Casing	Metal	Beige	None	0	1.5	Positive
1380	1	3	318	Classroom 318	yes	Window Sill 3	Metal	Beige	None	0	0.4	Negative
1380	1	3	318	Classroom 318	yes	Window Sill 4	Metal	Beige	None	0	0.1	Negative

				Inspection Dates: 10/8/21 - 10/15/21		School District of Philadelphia						
				Name of Inspector: K. Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report						
				Inspection Company: Acer Associates		Morton Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1380	1	3	318A	Storage Room next to Classroom 318	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	318A	Storage Room next to Classroom 318	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	318A	Storage Room next to Classroom 318	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	318A	Storage Room next to Classroom 318	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A
1380	1	3	318A	Storage Room next to Classroom 318	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	318A	Storage Room next to Classroom 318	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	319	Classroom 319	yes	W1	CMU	Blue	None	0	0.5	Negative
1380	1	3	319	Classroom 319	yes	W2	CMU	Blue	Flaking	2	0	Negative
1380	1	3	319	Classroom 319	yes	W3	CMU	Blue	None	0	0.1	Negative
1380	1	3	319	Classroom 319	yes	W4	Drywall	Blue	None	0	0.1	Negative
1380	1	3	319	Classroom 319	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	319	Classroom 319	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	319	Classroom 319	yes	Door Casing	Metal	Beige	Flaking	3	0.1	Negative
1380	1	3	319	Classroom 319	yes	Door Casing	Metal	Beige	Flaking	1	0.1	Negative
1380	1	3	319	Classroom 319	yes	Window Sill	Metal	Beige	Flaking	2	0.4	Negative
1380	1	3	319	Classroom 319	yes	Door Casing	Metal	Beige	None	0	1.6	Positive
1380	1	3	320	Classroom 320	yes	W1	CMU	Beige	None	0	0.1	Negative
1380	1	3	320	Classroom 320	yes	W2	Divider	N/A	N/A	N/A	N/A	N/A
1380	1	3	320	Classroom 320	yes	W3	CMU	Beige	None	0	0.1	Negative
1380	1	3	320	Classroom 320	yes	W3	Drywall	Black	None	0	0	Negative
1380	1	3	320	Classroom 320	yes	W4	CMU	Beige	None	0	0.1	Negative
1380	1	3	320	Classroom 320	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	320	Classroom 320	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	320	Classroom 320	yes	Window Sill	Metal	Beige	Flaking	2	0	Negative
1380	1	3	320	Classroom 320	yes	Door Casing 1	Metal	Beige	None	0	2	Positive
1380	1	3	320	Classroom 320	yes	Door Casing 2	Metal	Beige	None	0	0	Negative
1380	1	3	H31	Hallway from Classrooms 314 to 318	yes	W1	CMU	Green	None	0	0.4	Negative
1380	1	3	H31	Hallway from Classrooms 314 to 318	yes	W2	CMU	Green	None	0	0.1	Negative
1380	1	3	H31	Hallway from Classrooms 314 to 318	yes	W3	CMU	Green	None	0	0.5	Negative
1380	1	3	H31	Hallway from Classrooms 314 to 318	yes	W4	CMU	Green	None	0	0.6	Negative
1380	1	3	H31	Hallway from Classrooms 314 to 318	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H31	Hallway from Classrooms 314 to 318	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	3	H31	Hallway from Classrooms 314 to 318	yes	Door Casing	Metal	Blue	None	0	1.3	Positive
1380	1	3	H31	Hallway from Classrooms 314 to 318	yes	Door	Metal	Blue	None	0	0.1	Negative
1380	1	AT	A	Attic	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	AT	A	Attic	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	AT	A	Attic	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	AT	A	Attic	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	AT	A	Attic	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	AT	A	Attic	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	CS	C	Crawlspace	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	CS	C	Crawlspace	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	CS	C	Crawlspace	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	CS	C	Crawlspace	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	CS	C	Crawlspace	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1380	1	CS	C	Crawlspace	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A