

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	G	009A	Storage Room across Hallway from Classroom 9	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	009A	Storage Room across Hallway from Classroom 9	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	009A	Storage Room across Hallway from Classroom 9	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	009A	Storage Room across Hallway from Classroom 9	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	009A	Storage Room across Hallway from Classroom 9	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	009A	Storage Room across Hallway from Classroom 9	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	S04C	Ground Floor Stairwell Q	W1	Concrete	White	None	0	N/A	N/A
8020	1	G	S04C	Ground Floor Stairwell Q	W2	Concrete	White	None	0	N/A	N/A
8020	1	G	S04C	Ground Floor Stairwell Q	W3	Glass	N/A	None	0	N/A	N/A
8020	1	G	S04C	Ground Floor Stairwell Q	W4	Concrete	White	None	0	N/A	N/A
8020	1	G	S04C	Ground Floor Stairwell Q	Ceiling	Concrete	White	None	0	0	Negative
8020	1	G	S04C	Ground Floor Stairwell Q	Floor	Concrete	Black	None	0	0	Negative
8020	1	G	S04C	Ground Floor Stairwell Q	Railing	Metal	Black	None	0	0.16	Negative
8020	1	G	S04C	Ground Floor Stairwell Q	Staircase	Metal	Black	None	0	0.07	Negative
8020	1	G	9	Classroom 9	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	G	9	Classroom 9	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	9	Classroom 9	W3	Concrete	Peach & White	Cracking	1	0	Negative
8020	1	G	9	Classroom 9	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	9	Classroom 9	Ceiling	Concrete	White	None	0	0	Negative
8020	1	G	9	Classroom 9	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	10	Classroom 10	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	10	Classroom 10	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	10	Classroom 10	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	10	Classroom 10	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	10	Classroom 10	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	10	Classroom 10	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	11	Classroom 11	W1	Concrete	Peach	None	0	0	Negative
8020	1	G	11	Classroom 11	W2	Concrete	Peach	None	0	0	Negative
8020	1	G	11	Classroom 11	W3	Concrete	Peach	None	0	0	Negative
8020	1	G	11	Classroom 11	W4	Concrete	Peach	None	0	0	Negative
8020	1	G	11	Classroom 11	Ceiling	Concrete	White	None	0	0	Negative
8020	1	G	11	Classroom 11	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	11	Classroom 11	Door Frame	Metal	White	Peeling	1	0.12	Negative
8020	1	G	011A	Drying Room	W1	Concrete	Green	None	0	N/A	N/A
8020	1	G	011A	Drying Room	W2	Concrete	Green	None	0	N/A	N/A
8020	1	G	011A	Drying Room	W3	Concrete	Green	None	0	0	Negative
8020	1	G	011A	Drying Room	W4	Concrete	Green	None	0	N/A	N/A
8020	1	G	011A	Drying Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	011A	Drying Room	Floor	Concrete	N/A				
8020	1	G	H04	Hallway between Appreciate Avenue and Elevator	W1	Concrete	Beige & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	H04	Hallway between Appreciate Avenue and Elevator	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H04	Hallway between Appreciate Avenue and Elevator	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	G	H04	Hallway between Appreciate Avenue and Elevator	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H04	Hallway between Appreciate Avenue and Elevator	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H04	Hallway between Appreciate Avenue and Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H04	Hallway between Appreciate Avenue and Elevator	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	H04	Hallway between Appreciate Avenue and Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H03	Hallway from Boiler Room to Loading Dock	W1	Concrete	Tan	None	0	0	Negative
8020	1	G	H03	Hallway from Boiler Room to Loading Dock	W2	Concrete	Tan	None	0	N/A	Negative
8020	1	G	H03	Hallway from Boiler Room to Loading Dock	W3	Concrete	Tan	None	0	N/A	Negative
8020	1	G	H03	Hallway from Boiler Room to Loading Dock	W4	Concrete	Tan	None	0	N/A	Negative
8020	1	G	H03	Hallway from Boiler Room to Loading Dock	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H03	Hallway from Boiler Room to Loading Dock	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H01B	Hallway in Wing D adjacent to Loading Dock	W1	Concrete	Tan	Chipping	1	0	Negative
8020	1	G	H01B	Hallway in Wing D adjacent to Loading Dock	W2	Concrete	Tan	Chipping	1	0	Negative
8020	1	G	H01B	Hallway in Wing D adjacent to Loading Dock	W3	Concrete	Tan	Chipping	1	0	Negative
8020	1	G	H01B	Hallway in Wing D adjacent to Loading Dock	W4	Concrete	Tan	Chipping	1	0	Negative
8020	1	G	H01B	Hallway in Wing D adjacent to Loading Dock	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H01B	Hallway in Wing D adjacent to Loading Dock	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	12	Classroom 12 Wing D	W1	Concrete	Peach	None	0	0	Negative
8020	1	G	12	Classroom 12 Wing D	W2	Concrete	Peach	None	0	0	Negative
8020	1	G	12	Classroom 12 Wing D	W3	Concrete	Peach	None	0	0	Negative
8020	1	G	12	Classroom 12 Wing D	W4	Concrete	Peach	None	0	0	Negative
8020	1	G	12	Classroom 12 Wing D	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	12	Classroom 12 Wing D	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	012A	Storage Room inside Classroom 12 at Front Entrance	W1	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	012A	Storage Room inside Classroom 12 at Front Entrance	W2	Wood	Beige	None	0	N/A	N/A
8020	1	G	012A	Storage Room inside Classroom 12 at Front Entrance	W3	Wood	Beige	None	0	N/A	N/A
8020	1	G	012A	Storage Room inside Classroom 12 at Front Entrance	W4	Wood	Beige	None	0	N/A	N/A
8020	1	G	012A	Storage Room inside Classroom 12 at Front Entrance	Ceiling	Drop ceiling	White	None	0	N/A	N/A
8020	1	G	012A	Storage Room inside Classroom 12 at Front Entrance	Floor	Concrete	Brown	None	0	0	Negative
8020	1	G	012C	Storage Room inside Classroom 12 at Back of Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	012C	Storage Room inside Classroom 12 at Back of Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	012C	Storage Room inside Classroom 12 at Back of Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	012C	Storage Room inside Classroom 12 at Back of Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	012C	Storage Room inside Classroom 12 at Back of Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	G	012C	Storage Room inside Classroom 12 at Back of Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	13	Classroom 13	W1	Concrete	Beige	None	0	0	Negative
8020	1	G	13	Classroom 13	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	G	13	Classroom 13	W3	Concrete	Beige/Dark Grey	None	0	0	Negative
8020	1	G	13	Classroom 13	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	G	13	Classroom 13	Ceiling	Drop ceiling.-	White	None	0	N/A	N/A
8020	1	G	13	Classroom 13	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	013D	Storage Room in Classroom 13	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013D	Storage Room in Classroom 13	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013D	Storage Room in Classroom 13	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013D	Storage Room in Classroom 13	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013D	Storage Room in Classroom 13	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013D	Storage Room in Classroom 13	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013F	Teacher's Office in Classroom 13	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	013F	Teacher's Office in Classroom 13	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	013F	Teacher's Office in Classroom 13	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	013F	Teacher's Office in Classroom 13	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	013F	Teacher's Office in Classroom 13	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	013F	Teacher's Office in Classroom 13	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	013B	Audio Room at Front Back of Classroom 13	W1	Sheetrock	Dark grey	Chipping	1	0	Negative
8020	1	G	013B	Audio Room at Front Back of Classroom 13	W2	Sheetrock	Dark grey	Chipping	1	N/A	Negative
8020	1	G	013B	Audio Room at Front Back of Classroom 13	W3	Sheetrock	Dark grey	Chipping	1	N/A	Negative
8020	1	G	013B	Audio Room at Front Back of Classroom 13	W4	Sheetrock	Dark grey	Chipping	1	N/A	Negative
8020	1	G	013B	Audio Room at Front Back of Classroom 13	Ceiling	Drop ceilings	N/A	N/A	N/A	N/A	N/A
8020	1	G	013B	Audio Room at Front Back of Classroom 13	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	013B	Audio Room at Left Front Back of Classroom 13	W1	Sheetrock	No Access	No Access	No Access	No Access	No Access
8020	1	G	013B	Audio Room at Left Front Back of Classroom 13	W2	Sheetrock	No Access	No Access	No Access	No Access	No Access
8020	1	G	013B	Audio Room at Left Front Back of Classroom 13	W3	Sheetrock	No Access	No Access	No Access	No Access	No Access
8020	1	G	013B	Audio Room at Left Front Back of Classroom 13	W4	Sheetrock	No Access	No Access	No Access	No Access	No Access
8020	1	G	013B	Audio Room at Left Front Back of Classroom 13	Ceiling	Drop ceiling	No Access	No Access	No Access	No Access	No Access
8020	1	G	013B	Audio Room at Left Front Back of Classroom 13	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	013A	Photography Room at Back Center of Classroom 13	W1	Sheetrock	No Access	No Access	No access	No Access	No Access
8020	1	G	013A	Photography Room at Back Center of Classroom 13	W2	Sheetrock	No Access	No Access	No access	No Access	No Access
8020	1	G	013A	Photography Room at Back Center of Classroom 13	W3	Sheetrock	No Access	No Access	No access	No Access	No Access
8020	1	G	013A	Photography Room at Back Center of Classroom 13	W4	Sheetrock	No Access	No Access	No access	No Access	No Access
8020	1	G	013A	Photography Room at Back Center of Classroom 13	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013A	Photography Room at Back Center of Classroom 13	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013C	Storage Room at Right Back of Classroom 13	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	013C	Storage Room at Right Back of Classroom 13	W2	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021								
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.		North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
8020	1	G	013C	Storage Room at Right Back of Classroom 13	W3	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	013C	Storage Room at Right Back of Classroom 13	W4	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	013C	Storage Room at Right Back of Classroom 13	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	013C	Storage Room at Right Back of Classroom 13	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	14	Classroom 14	W1	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	G	14	Classroom 14	W2	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	G	14	Classroom 14	W3	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	G	14	Classroom 14	W4	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	G	14	Classroom 14	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	G	14	Classroom 14	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	G	014B	Room 14A	W1	Concrete	Beige	None	0	N/A	N/A	
8020	1	G	014B	Room 14A	W2	Concrete	Beige	None	0	N/A	N/A	
8020	1	G	014B	Room 14A	W3	Concrete	Beige	None	0	N/A	N/A	
8020	1	G	014B	Room 14A	W4	Concrete	Beige	None	0	N/A	N/A	
8020	1	G	014B	Room 14A	Ceiling	Drop ceiling	White	None	0	N/A	N/A	
8020	1	G	014B	Room 14A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	G	15	Classroom 15	W1	Concrete	Peach/White	Chipping	1	0	Negative	
8020	1	G	15	Classroom 15	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	G	15	Classroom 15	W3	Concrete	Peach	Chipping	1	0	Negative	
8020	1	G	15	Classroom 15	W4	Concrete	Peach	None	0	N/A	N/A	
8020	1	G	15	Classroom 15	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	G	15	Classroom 15	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	G	015A	Storage Room in Classroom 15	W1	Concrete	Light blue/White	None	0	N/A	N/A	
8020	1	G	015A	Storage Room in Classroom 15	W2	Concrete	Light blue/White	Chipping	1	0	Negative	
8020	1	G	015A	Storage Room in Classroom 15	W3	Concrete	Light blue/White	None	0	N/A	N/A	
8020	1	G	015A	Storage Room in Classroom 15	W4	Concrete	Light blue/White	Chipping	1	0	Negative	
8020	1	G	015A	Storage Room in Classroom 15	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	G	015A	Storage Room in Classroom 15	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	G	H02	Hallway in Wing D between Loading Dock Hallway and Classroom 016	W1	Concrete	Beige & White	None	0	0	Negative	
8020	1	G	H02	Hallway in Wing D between Loading Dock Hallway and Classroom 016	W2	Concrete	Beige & White	None	0	0	Negative	
8020	1	G	H02	Hallway in Wing D between Loading Dock Hallway and Classroom 016	W3	Concrete	Beige & White	None	0	0	Negative	
8020	1	G	H02	Hallway in Wing D between Loading Dock Hallway and Classroom 016	W4	Concrete	Beige & White	Cracking	1	0	Negative	
8020	1	G	H02	Hallway in Wing D between Loading Dock Hallway and Classroom 016	Ceiling	Concrete	White	None	0	N/A	N/A	

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	H02	Hallway in Wing D between Loading Dock Hallway and Classroom 016	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	015B	Girl's Restroom across the Hallway from Classroom 16B	W1	Concrete	Peach/White	Chipping	1	0	Negative
8020	1	G	015B	Girl's Restroom across the Hallway from Classroom 16B	W2	Concrete	Peach/White	None	0	N/A	N/A
8020	1	G	015B	Girl's Restroom across the Hallway from Classroom 16B	W3	Concrete	Peach/White	None	0	N/A	N/A
8020	1	G	015B	Girl's Restroom across the Hallway from Classroom 16B	W4	Concrete	Peach/White	None	0	N/A	N/A
8020	1	G	015B	Girl's Restroom across the Hallway from Classroom 16B	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	015B	Girl's Restroom across the Hallway from Classroom 16B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	015C	Girl's Restroom across the Hallway from Classroom 16B Pipe Chase	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	015C	Girl's Restroom across the Hallway from Classroom 16B Pipe Chase	W2	Concrete	Peach & White	None	0	0	Negative
8020	1	G	015C	Girl's Restroom across the Hallway from Classroom 16B Pipe Chase	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	015C	Girl's Restroom across the Hallway from Classroom 16B Pipe Chase	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	015C	Girl's Restroom across the Hallway from Classroom 16B Pipe Chase	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	015C	Girl's Restroom across the Hallway from Classroom 16B Pipe Chase	Floor	Concrete	Brown	None	0	0	Negative
8020	1	G	016B	Classroom 16B	W1	Concrete	Beige & White	Chipping	1	0.02	Negative
8020	1	G	016B	Classroom 16B	W2	Sheetrock	Beige	Chipping	1	0	Negative
8020	1	G	016B	Classroom 16B	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	016B	Classroom 16B	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	016B	Classroom 16B	Ceiling	Concrete	Beige	None	0	N/A	N/A
8020	1	G	016B	Classroom 16B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	016A	Classroom 16A	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	G	016A	Classroom 16A	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	G	016A	Classroom 16A	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	G	016A	Classroom 16A	W4	Sheetrock	Purple	None	0	0	Negative
8020	1	G	016A	Classroom 16A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	016A	Classroom 16A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	016C	Storage Room in Classroom 16A	W1	Concrete	Blue	None	0	0.01	Negative
8020	1	G	016C	Storage Room in Classroom 16A	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	G	016C	Storage Room in Classroom 16A	W3	Concrete	Grey	None	0	N/A	N/A
8020	1	G	016C	Storage Room in Classroom 16A	W4	Concrete	Grey	None	0	0.01	Negative
8020	1	G	016C	Storage Room in Classroom 16A	Ceiling	Concrete	White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	016C	Storage Room in Classroom 16A	Floor	Concrete	N/A				
8020	1	G	016D	Storage Room in Classroom 16A in Back of Room	W1	Concrete	Yellow & white	None	0	N/A	N/A
8020	1	G	016D	Storage Room in Classroom 16A in Back of Room	W2	Concrete	Yellow & white	None	0	N/A	N/A
8020	1	G	016D	Storage Room in Classroom 16A in Back of Room	W3	Concrete	Yellow & white	None	0	N/A	N/A
8020	1	G	016D	Storage Room in Classroom 16A in Back of Room	W4	Concrete	Yellow, white, & black	None	0	0	Negative
8020	1	G	016D	Storage Room in Classroom 16A in Back of Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	016D	Storage Room in Classroom 16A in Back of Room	Floor	Concrete	N/A				
8020	1	G	017C	Classroom 17C	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	017C	Classroom 17C	W2	Sheetrock	Peach & White	None	0	N/A	N/A
8020	1	G	017C	Classroom 17C	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	017C	Classroom 17C	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	017C	Classroom 17C	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	017C	Classroom 17C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	017D	Office inside Classroom 017C	W1	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	017D	Office inside Classroom 017C	W2	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	017D	Office inside Classroom 017C	W3	Sheetrock	Peach	None	0	0	Negative
8020	1	G	017D	Office inside Classroom 017C	W4	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	017D	Office inside Classroom 017C	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	017D	Office inside Classroom 017C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	017E	Storage Room at Front of Classroom 17C	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	017E	Storage Room at Front of Classroom 17C	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	017E	Storage Room at Front of Classroom 17C	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	017E	Storage Room at Front of Classroom 17C	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	017E	Storage Room at Front of Classroom 17C	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	017E	Storage Room at Front of Classroom 17C	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	021J	Boy's Restroom across the Hallway from Classroom 17C	W1	Concrete	Peach & White	None	0	0.05	Negative
8020	1	G	021J	Boy's Restroom across the Hallway from Classroom 17C	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	021J	Boy's Restroom across the Hallway from Classroom 17C	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	G	021J	Boy's Restroom across the Hallway from Classroom 17C	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	021J	Boy's Restroom across the Hallway from Classroom 17C	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	021J	Boy's Restroom across the Hallway from Classroom 17C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	018A	Office 18A	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	018A	Office 18A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	018A	Office 18A	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	018A	Office 18A	W4	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	018A	Office 18A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	018A	Office 18A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	018E	Office 18A Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	018E	Office 18A Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	018E	Office 18A Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	018E	Office 18A Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	018E	Office 18A Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	018E	Office 18A Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	018B	Classroom 18B	W1	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	018B	Classroom 18B	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	G	018B	Classroom 18B	W3	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	018B	Classroom 18B	W4	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	018B	Classroom 18B	Ceiling	Concrete	White	None	0	0	Negative
8020	1	G	018B	Classroom 18B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	018C	Classroom 18C	W1	Sheetrock	Peach & White	Cracking	1	0	Negative
8020	1	G	018C	Classroom 18C	W2	Sheetrock	Peach & White	Cracking	1	0	Negative
8020	1	G	018C	Classroom 18C	W3	Sheetrock	Peach & White	Cracking	1	0	Negative
8020	1	G	018C	Classroom 18C	W4	Sheetrock	Peach & White	Cracking	1	0	Negative
8020	1	G	018C	Classroom 18C	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	018C	Classroom 18C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	018D	Classroom 18D	W1	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	018D	Classroom 18D	W2	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	018D	Classroom 18D	W3	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	018D	Classroom 18D	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	G	018D	Classroom 18D	Ceiling	Concrete	White	Moisture Damage	4	0	Negative
8020	1	G	018D	Classroom 18D	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	018F	Classroom 18D Bathroom	W1	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	018F	Classroom 18D Bathroom	W2	Sheetrock	White	None	0	N/A	N/A
8020	1	G	018F	Classroom 18D Bathroom	W3	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	018F	Classroom 18D Bathroom	W4	Sheetrock	White	Moisture Damage	1	0	Negative
8020	1	G	018F	Classroom 18D Bathroom	Ceiling	Sheetrock	White	None	0	N/A	N/A
8020	1	G	018F	Classroom 18D Bathroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	019A	Room 19A	W1	Concrete	Peach	None	0	0	Negative
8020	1	G	019A	Room 19A	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	G	019A	Room 19A	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	G	019A	Room 19A	W4	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	019A	Room 19A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	019A	Room 19A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	019B	Classroom 19B	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	G	019B	Classroom 19B	W2	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	019B	Classroom 19B	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	G	019B	Classroom 19B	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	019B	Classroom 19B	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	019B	Classroom 19B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	019C	Classroom 19A Bathroom	W1	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	019C	Classroom 19A Bathroom	W2	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	019C	Classroom 19A Bathroom	W3	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	019C	Classroom 19A Bathroom	W4	Sheetrock	Peach	None	0	N/A	N/A
8020	1	G	019C	Classroom 19A Bathroom	Ceiling	Drop tile	White	N/A	N/A	N/A	N/A
8020	1	G	019C	Classroom 19A Bathroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	017A	Classroom 17A	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	017A	Classroom 17A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	017A	Classroom 17A	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	017A	Classroom 17A	W4	Sheetrock	Peach & White	None	0	N/A	N/A
8020	1	G	017A	Classroom 17A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	017A	Classroom 17A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	017B	Classroom 17B	W1	Sheetrock	Peach & White	None	0	0	Negative
8020	1	G	017B	Classroom 17B	W2	Sheetrock	Peach & White	None	0	0	Negative
8020	1	G	017B	Classroom 17B	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	G	017B	Classroom 17B	W4	Concrete	Peach & White	None	0	0	Negative
8020	1	G	017B	Classroom 17B	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	017B	Classroom 17B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H03G	Hallway between Classroom 17C and Room 19A	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H03G	Hallway between Classroom 17C and Room 19A	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H03G	Hallway between Classroom 17C and Room 19A	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H03G	Hallway between Classroom 17C and Room 19A	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	G	H03G	Hallway between Classroom 17C and Room 19A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H03G	Hallway between Classroom 17C and Room 19A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	8	Classroom 8	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	8	Classroom 8	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	8	Classroom 8	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	8	Classroom 8	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	8	Classroom 8	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	8	Classroom 8	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	7	Classroom 7	W1	Concrete	Peach & White	Chipping	1	0	Negative
8020	1	G	7	Classroom 7	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	7	Classroom 7	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	G	7	Classroom 7	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	7	Classroom 7	Ceiling	Concrete	White	None	0	0	Negative
8020	1	G	7	Classroom 7	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	G	6	Classroom 6	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	6	Classroom 6	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	6	Classroom 6	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	6	Classroom 6	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	6	Classroom 6	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	6	Classroom 6	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	006A	Storage Room adjacent to Classroom 6	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	G	006A	Storage Room adjacent to Classroom 6	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	G	006A	Storage Room adjacent to Classroom 6	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	G	006A	Storage Room adjacent to Classroom 6	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	G	006A	Storage Room adjacent to Classroom 6	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	006A	Storage Room adjacent to Classroom 6	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	55	Girl's Restroom adjacent to Classroom 6	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	55	Girl's Restroom adjacent to Classroom 6	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	55	Girl's Restroom adjacent to Classroom 6	W3	Concrete	Beige & White	None	0	0.01	Negative
8020	1	G	55	Girl's Restroom adjacent to Classroom 6	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	55	Girl's Restroom adjacent to Classroom 6	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	55	Girl's Restroom adjacent to Classroom 6	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H01M	Hallway between Classroom 8 and Classroom 6	W1	Concrete	Beige & White	None	0	0.06	Negative
8020	1	G	H01M	Hallway between Classroom 8 and Classroom 6	W2	Concrete	Beige & White	None	0	0	Negative
8020	1	G	H01M	Hallway between Classroom 8 and Classroom 6	W3	Concrete	Beige & White	None	0	0.03	Negative
8020	1	G	H01M	Hallway between Classroom 8 and Classroom 6	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	G	H01M	Hallway between Classroom 8 and Classroom 6	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	G	H01M	Hallway between Classroom 8 and Classroom 6	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell D	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell D	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell D	W3	Glass	Peach	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell D	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell D	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell D	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell D	Railings	Metal	Black	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell D	Staircase	Metal	Black	None	0	N/A	N/A
8020	1	G	5	Classroom 5	W1	Concrete	Peach & White	Chipping	1	0	Negative
8020	1	G	5	Classroom 5	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	5	Classroom 5	W3	Concrete	Peach & White	Chipping	1	0	Negative
8020	1	G	5	Classroom 5	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	5	Classroom 5	Ceiling	Concrete	White	Cracking		0	Negative
8020	1	G	5	Classroom 5	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	4	Classroom 4	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	4	Classroom 4	W2	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	G	4	Classroom 4	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	4	Classroom 4	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	4	Classroom 4	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	4	Classroom 4	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	3	Classroom 3	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	G	3	Classroom 3	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	3	Classroom 3	W3	Concrete	Peach & White	Cracking	1	0	Negative
8020	1	G	3	Classroom 3	W4	Concrete	Peach & White	None	0	0	Negative
8020	1	G	3	Classroom 3	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	3	Classroom 3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	2	Classroom 2	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	G	2	Classroom 2	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	2	Classroom 2	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	G	2	Classroom 2	W4	Sheetrock	Peach & White	None	0	0	Negative
8020	1	G	2	Classroom 2	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	2	Classroom 2	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	1	Classroom 1	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	1	Classroom 1	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	1	Classroom 1	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	1	Classroom 1	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	1	Classroom 1	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	1	Classroom 1	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H01M	Hallway between Classroom 8 and Classroom 6	Door Frame	Metal	Yellow	Peeling	1	0.04	Negative
8020	1	G	H01N	Hallway between Classroom 1 and Classroom 5	W1	Concrete	Beige & White	None	0	0.01	Negative
8020	1	G	H01N	Hallway between Classroom 1 and Classroom 5	W2	Concrete	Beige & White	None	0	0.03	Negative
8020	1	G	H01N	Hallway between Classroom 1 and Classroom 5	W3	Concrete	Beige & White	Cracking	2	0.03	Negative
8020	1	G	H01N	Hallway between Classroom 1 and Classroom 5	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	G	H01N	Hallway between Classroom 1 and Classroom 5	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H01N	Hallway between Classroom 1 and Classroom 5	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	S04	Ground Floor Stairwell A	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S04	Ground Floor Stairwell A	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S04	Ground Floor Stairwell A	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S04	Ground Floor Stairwell A	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S04	Ground Floor Stairwell A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	S04	Ground Floor Stairwell A	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	G	S04	Ground Floor Stairwell A	Railing	Metal	Grey	Friction	30	N/A	N/A
8020	1	G	S04	Ground Floor Stairwell A	Stairway	Metal	Grey	Chipping	1	N/A	N/A
8020	1	G	25	Office 25	W1	Concrete	Peach/White	Cracking	1	0	Negative
8020	1	G	25	Office 25	W2	Concrete	Peach/White	None	0	N/A	N/A
8020	1	G	25	Office 25	W3	Concrete	Peach/White	None	0	0	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	25	Office 25	W4	Concrete	Peach/White	None	0	N/A	N/A
8020	1	G	25	Office 25	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	25	Office 25	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	24	Classroom 24	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	G	24	Classroom 24	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	24	Classroom 24	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	G	24	Classroom 24	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	24	Classroom 24	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	24	Classroom 24	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	23	Classroom 23	W1	Concrete	Peach/White	None	0	0	Negative
8020	1	G	23	Classroom 23	W2	Concrete	Peach/White	None	0	N/A	N/A
8020	1	G	23	Classroom 23	W3	Concrete	Peach/White	Alligatoring	1	0	Negative
8020	1	G	23	Classroom 23	W4	Concrete	Peach/White	None	0	N/A	N/A
8020	1	G	23	Classroom 23	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	23	Classroom 23	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	23A	Boy's Restroom adjacent to Cafeteria	W1	Concrete	Yellow	Cracking	2	0	Negative
8020	1	G	23A	Boy's Restroom adjacent to Cafeteria	W1	Concrete	White	None	0	0.07	Negative
8020	1	G	23A	Boy's Restroom adjacent to Cafeteria	W2	Concrete	Blue & White	None	0	N/A	N/A
8020	1	G	23A	Boy's Restroom adjacent to Cafeteria	W3	Concrete	Blue & White	None	0	N/A	N/A
8020	1	G	23A	Boy's Restroom adjacent to Cafeteria	W4	Concrete	Blue & White	None	0	N/A	N/A
8020	1	G	23A	Boy's Restroom adjacent to Cafeteria	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	23A	Boy's Restroom adjacent to Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H02A	Hallway between Stairwell M and Office 25	W1	Concrete	Beige/White	None	0	0.09	Negative
8020	1	G	H02A	Hallway between Stairwell M and Office 25	W2	Concrete	Beige/White	None	0	0.03	Negative
8020	1	G	H02A	Hallway between Stairwell M and Office 25	W3	Concrete	White	None	0	N/A	N/A
8020	1	G	H02A	Hallway between Stairwell M and Office 25	W3	Concrete	Beige/White	None	0	0	Negative
8020	1	G	H02A	Hallway between Stairwell M and Office 25	W4	Concrete	Beige/White	None	0	0.01	Negative
8020	1	G	H02A	Hallway between Stairwell M and Office 25	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H02A	Hallway between Stairwell M and Office 25	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell M	W1	Concrete	White	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell M	W2	Concrete	White	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell M	W3	Glass	N/A	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell M	W4	Concrete	White	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell M	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell M	Floor	Concrete	Black	None	0	N/A	N/A
8020	1	G	S06	Ground Floor Stairwell M	Railing	Metal	Grey	Chipping	1	0.07	Negative
8020	1	G	S06	Ground Floor Stairwell M	Staircase	Metal	Grey	None	0	0.11	Negative
8020	1	G	44	Cafeteria	W1	Ceramic Tile	Gray	Cracking	6	>1	Positive
8020	1	G	44	Cafeteria	W2	Concrete	Beige	None	0	0	Negative
8020	1	G	44	Cafeteria	W3	Ceramic Tile	Blue	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	44	Cafeteria	W4	Concrete	Beige	None	0	0	Negative
8020	1	G	44	Cafeteria	Ceiling	Acoustic Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	44	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	44	Cafeteria	Column	Concrete	Beige	None	0	0	Negative
8020	1	G	044A	Cafeteria Store in Cafeteria	W1	Wood	Grey	None	0	0	Negative
8020	1	G	044A	Cafeteria Store in Cafeteria	W2	Concrete	Grey	None	0	N/A	N/A
8020	1	G	044A	Cafeteria Store in Cafeteria	W3	Ceramic	Grey	None	0	N/A	N/A
8020	1	G	044A	Cafeteria Store in Cafeteria	W4	Wood	Grey	None	0	N/A	N/A
8020	1	G	044A	Cafeteria Store in Cafeteria	Ceiling	Acoustic Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	044A	Cafeteria Store in Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	044B	School Security Office in Corner of Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	044B	School Security Office in Corner of Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	044B	School Security Office in Corner of Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	044B	School Security Office in Corner of Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	044B	School Security Office in Corner of Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	044B	School Security Office in Corner of Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	S03	Ground Floor Stairwell next to Music Practice Rooms	W1	Concrete	Beige	Flaking	1	N/A	N/A
8020	1	G	S03	Ground Floor Stairwell next to Music Practice Rooms	W2	Concrete	Beige	Flaking	1	0	Negative
8020	1	G	S03	Ground Floor Stairwell next to Music Practice Rooms	W3	Glass	N/A	N/A	N/A	N/A	N/A
8020	1	G	S03	Ground Floor Stairwell next to Music Practice Rooms	W4	Concrete	Beige	Flaking	1	N/A	N/A
8020	1	G	S03	Ground Floor Stairwell next to Music Practice Rooms	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	S03	Ground Floor Stairwell next to Music Practice Rooms	Floor	N/A	N/A	N/A	N/A	0	Negative
8020	1	G	S03	Ground Floor Stairwell next to Music Practice Rooms	Railings	Metal	Grey	Chipping	5	0.18	Negative
8020	1	G	S03	Ground Floor Stairwell next to Music Practice Rooms	Staircase	Metal	Grey	Chipping	5	0.44	Negative
8020	1	G	24C	Teachers Lounge in Main Cafeteria	W1	Ceramic	Grey	None	0	N/A	N/A
8020	1	G	24C	Teachers Lounge in Main Cafeteria	W2	Ceramic	Grey	None	0	N/A	N/A
8020	1	G	24C	Teachers Lounge in Main Cafeteria	W3	Ceramic	Grey	None	0	N/A	N/A
8020	1	G	24C	Teachers Lounge in Main Cafeteria	W4	Ceramic	Grey	None	0	N/A	N/A
8020	1	G	24C	Teachers Lounge in Main Cafeteria	Ceiling	Acoustic Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	24C	Teachers Lounge in Main Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H02	Hallway associated with Glendale Avenue Exit	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H02	Hallway associated with Glendale Avenue Exit	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H02	Hallway associated with Glendale Avenue Exit	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H02	Hallway associated with Glendale Avenue Exit	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	G	H02	Hallway associated with Glendale Avenue Exit	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H02	Hallway associated with Glendale Avenue Exit	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H02	Hallway associated with Glendale Avenue Exit	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	H02	Hallway associated with Glendale Avenue Exit	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	020B	9th Grade Counselors Office	W1	Concrete	White	None	0	N/A	N/A
8020	1	G	020B	9th Grade Counselors Office	W2	Concrete	White	None	0	N/A	N/A
8020	1	G	020B	9th Grade Counselors Office	W3	Concrete	White	None	0	N/A	N/A
8020	1	G	020B	9th Grade Counselors Office	W4	Concrete	White	None	0	N/A	N/A
8020	1	G	020B	9th Grade Counselors Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	020B	9th Grade Counselors Office	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	G	021A	Classroom 021A	W1	Ceramic & Concrete	Peach & Beige	None	0	N/A	N/A
8020	1	G	021A	Classroom 021A	W2	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	021A	Classroom 021A	W3	Ceramic & Concrete	Peach & Beige	None	0	N/A	N/A
8020	1	G	021A	Classroom 021A	W4	Ceramic & Concrete	Peach & Beige	None	0	N/A	N/A
8020	1	G	021A	Classroom 021A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	021A	Classroom 021A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	021A	Classroom 021A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	21	Room 21 Deans Office	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	G	21	Room 21 Deans Office	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	G	21	Room 21 Deans Office	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	G	21	Room 21 Deans Office	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	G	21	Room 21 Deans Office	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	21	Room 21 Deans Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	020A	Office adjacent to Exit to Glendale Avenue	W1	Sheetrock	Multi	Friction	1	0.01	Negative
8020	1	G	020A	Office adjacent to Exit to Glendale Avenue	W2	Sheetrock	Multi	None	0	N/A	N/A
8020	1	G	020A	Office adjacent to Exit to Glendale Avenue	W3	Ceramic	Grey	None	0	N/A	N/A
8020	1	G	020A	Office adjacent to Exit to Glendale Avenue	W4	Ceramic	Grey	None	0	N/A	N/A
8020	1	G	020A	Office adjacent to Exit to Glendale Avenue	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	020A	Office adjacent to Exit to Glendale Avenue	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	020C	Boy's Restroom at Appreciate Ave and J Stairwell	W1	Concrete	Yellow/White	Cracking	4	0	Negative
8020	1	G	020C	Boy's Restroom at Appreciate Ave and J Stairwell	W2	Concrete	Yellow/White	None	0	N/A	N/A
8020	1	G	020C	Boy's Restroom at Appreciate Ave and J Stairwell	W3	Concrete	Yellow/White	None	0	0	Negative
8020	1	G	020C	Boy's Restroom at Appreciate Ave and J Stairwell	W4	Concrete	Yellow/White	None	0	N/A	N/A
8020	1	G	020C	Boy's Restroom at Appreciate Ave and J Stairwell	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	020C	Boy's Restroom at Appreciate Ave and J Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	S01	Ground Floor Stairwell J	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S01	Ground Floor Stairwell J	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S01	Ground Floor Stairwell J	W3	Glass	N/A	None	0	N/A	N/A
8020	1	G	S01	Ground Floor Stairwell J	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S01	Ground Floor Stairwell J	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	S01	Ground Floor Stairwell J	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	G	S01	Ground Floor Stairwell J	Railing	Metal	Black	None	0		
8020	1	G	S01	Ground Floor Stairwell J	Staircase	Metal	Black	None	0		
8020	1	G	H01A	Hallway to Aironoutics Building	W1	Concrete	Beige & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	H01A	Hallway to Aironautics Building	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H01A	Hallway to Aironautics Building	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H01A	Hallway to Aironautics Building	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	G	H01A	Hallway to Aironautics Building	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H01A	Hallway to Aironautics Building	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H01A	Hallway to Aironautics Building	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	H01A	Hallway to Aironautics Building	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	21C	Health Resource Center next to Aironautics Bldg	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21C	Health Resource Center next to Aironautics Bldg	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21C	Health Resource Center next to Aironautics Bldg	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21C	Health Resource Center next to Aironautics Bldg	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21C	Health Resource Center next to Aironautics Bldg	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21C	Health Resource Center next to Aironautics Bldg	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21D	Health Resource Center next to Aironautics Bldg Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21D	Health Resource Center next to Aironautics Bldg Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21D	Health Resource Center next to Aironautics Bldg Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21D	Health Resource Center next to Aironautics Bldg Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21D	Health Resource Center next to Aironautics Bldg Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	21D	Health Resource Center next to Aironautics Bldg Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	H01	Hallway between Room 21C and Cafeteria	W1	Concrete	Beige/White	None	0	0	Negative
8020	1	G	H01	Hallway between Room 21C and Cafeteria	W2	Concrete	Beige/White	None	0	0	Negative
8020	1	G	H01	Hallway between Room 21C and Cafeteria	W3	Concrete	Beige/White	None	0	0.01	Negative
8020	1	G	H01	Hallway between Room 21C and Cafeteria	W4	Concrete	Beige/White	None	0	0.01	Negative
8020	1	G	H01	Hallway between Room 21C and Cafeteria	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H01	Hallway between Room 21C and Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	S02	Ground Floor Stairwell K	W1	Concrete	Beige	Chipping	3	0	Negative
8020	1	G	S02	Ground Floor Stairwell K	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S02	Ground Floor Stairwell K	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S02	Ground Floor Stairwell K	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S02	Ground Floor Stairwell K	Ceiling	Concrete	Beige	None	0	N/A	N/A
8020	1	G	S02	Ground Floor Stairwell K	Floor	Concrete	N/A	None	0	N/A	N/A
8020	1	G	S02	Ground Floor Stairwell K	Railing	Metal	Grey	Chipping	5	0.15	Negative
8020	1	G	S02	Ground Floor Stairwell K	Stairway	Metal	Grey	Chipping	3	0.09	Negative
8020	1	G	22	Girl's Restroom adjacent to Cafeteria Kitchen	W1	Concrete	White	None	0	0	Negative
8020	1	G	22	Girl's Restroom adjacent to Cafeteria Kitchen	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	G	22	Girl's Restroom adjacent to Cafeteria Kitchen	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	22	Girl's Restroom adjacent to Cafeteria Kitchen	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	G	22	Girl's Restroom adjacent to Cafeteria Kitchen	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	22	Girl's Restroom adjacent to Cafeteria Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	021A/021B	Room 21A - SLC Hub	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	021A/021B	Room 21A - SLC Hub	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	021A/021B	Room 21A - SLC Hub	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	021A/021B	Room 21A - SLC Hub	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	021A/021B	Room 21A - SLC Hub	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	021A/021B	Room 21A - SLC Hub	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	H01	SPARC Building Main Hallway	W1	Concrete	Grey	None	0	N/A	N/A
8020	1	G	H01	SPARC Building Main Hallway	W2	Concrete	Multi	None	0	N/A	N/A
8020	1	G	H01	SPARC Building Main Hallway	W3	Concrete	Red	None	0	N/A	N/A
8020	1	G	H01	SPARC Building Main Hallway	W4	Concrete	Multi	None	0	N/A	N/A
8020	1	G	H01	SPARC Building Main Hallway	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	H01	SPARC Building Main Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	H01	SPARC Building Main Hallway	Ceiling	Drop Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	H01	SPARC Building Main Hallway	Floor	N/A	N/A	None	0	N/A	N/A
8020	1	G	31	Science Lab Room 31	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31	Science Lab Room 31	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31	Science Lab Room 31	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31	Science Lab Room 31	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31	Science Lab Room 31	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31	Science Lab Room 31	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31A	Science Lab Room 31 Chemical Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31A	Science Lab Room 31 Chemical Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31A	Science Lab Room 31 Chemical Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31A	Science Lab Room 31 Chemical Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31A	Science Lab Room 31 Chemical Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	31A	Science Lab Room 31 Chemical Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	33	Classroom 33	W1	Concrete	Peach	None	0	0	Negative
8020	1	G	33	Classroom 33	W2	Sheetrock	Peach	Friction	2	0	Negative
8020	1	G	33	Classroom 33	W3	Concrete	Peach	None	0	0	Negative
8020	1	G	33	Classroom 33	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	G	33	Classroom 33	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	33	Classroom 33	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	35	Office 35	W1	Concrete	Peach	None	0	0	Negative
8020	1	G	35	Office 35	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	G	35	Office 35	W3	Concrete	Peach	None	0	0	Negative
8020	1	G	35	Office 35	W4	Concrete	Peach	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	G	35	Office 35	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	G	35	Office 35	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	35A	Small Office 35 by Hallway	W1	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	35A	Small Office 35 by Hallway	W2	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	35A	Small Office 35 by Hallway	W3	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	35A	Small Office 35 by Hallway	W4	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	35A	Small Office 35 by Hallway	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	35A	Small Office 35 by Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	35B	Small Office 35 by Windows	W1	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	35B	Small Office 35 by Windows	W2	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	35B	Small Office 35 by Windows	W3	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	35B	Small Office 35 by Windows	W4	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	35B	Small Office 35 by Windows	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	35B	Small Office 35 by Windows	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	34	Classroom 34	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	G	34	Classroom 34	W2	Sheetrock	Peach & White	None	0	0	Negative
8020	1	G	34	Classroom 34	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	G	34	Classroom 34	W4	Sheetrock	Peach & White	None	0	0	Negative
8020	1	G	34	Classroom 34	Ceiling	Spline ceiling	White	N/A	N/A	N/A	N/A
8020	1	G	34	Classroom 34	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	34A	Classroom 34 Storage Room by Hallway	W1	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	34A	Classroom 34 Storage Room by Hallway	W2	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	34A	Classroom 34 Storage Room by Hallway	W3	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	34A	Classroom 34 Storage Room by Hallway	W4	Sheetrock	Beige	None	0	N/A	N/A
8020	1	G	34A	Classroom 34 Storage Room by Hallway	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	34A	Classroom 34 Storage Room by Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	34B	Classroom 34 Storage Room by Windows	W1	Sheetrock	N/A	N/A	N/A	N/A	N/A
8020	1	G	34B	Classroom 34 Storage Room by Windows	W2	Sheetrock	N/A	N/A	N/A	N/A	N/A
8020	1	G	34B	Classroom 34 Storage Room by Windows	W3	Sheetrock	N/A	N/A	N/A	N/A	N/A
8020	1	G	34B	Classroom 34 Storage Room by Windows	W4	Sheetrock	N/A	N/A	N/A	N/A	N/A
8020	1	G	34B	Classroom 34 Storage Room by Windows	Ceiling	Drop Ceiling Tiles	White	N/A	N/A	N/A	N/A
8020	1	G	34B	Classroom 34 Storage Room by Windows	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	G	32B	Women's Restroom across from Classroom 33	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	32B	Women's Restroom across from Classroom 33	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	32B	Women's Restroom across from Classroom 33	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	32B	Women's Restroom across from Classroom 33	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	32B	Women's Restroom across from Classroom 33	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	32B	Women's Restroom across from Classroom 33	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	32C	Men's Restroom across from Classroom 33	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	G	32C	Men's Restroom across from Classroom 33	W2	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021								
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.		North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
8020	1	G	32C	Men's Restroom across from Classroom 33	W3	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32C	Men's Restroom across from Classroom 33	W4	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32C	Men's Restroom across from Classroom 33	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32C	Men's Restroom across from Classroom 33	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32D	Shower Room in Men's Bathroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32D	Shower Room in Men's Bathroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32D	Shower Room in Men's Bathroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32D	Shower Room in Men's Bathroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32D	Shower Room in Men's Bathroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32D	Shower Room in Men's Bathroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	G	32	Classroom 32	W1	Sheetrock	Black & Beige	None	0	0	Negative	
8020	1	G	32	Classroom 32	W2	Concrete	Black	None	0	0	Negative	
8020	1	G	32	Classroom 32	W3	Sheetrock	Black	None	0	N/A	N/A	
8020	1	G	32	Classroom 32	W4	Sheetrock	Black	None	0	N/A	N/A	
8020	1	G	32	Classroom 32	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A	
8020	1	G	32	Classroom 32	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	G	32	Classroom 32	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	G	32A	SPARC Module Room in Classroom 32	W1	Sheetrock	Blue	None	0	N/A	N/A	
8020	1	G	32A	SPARC Module Room in Classroom 32	W2	Sheetrock	Blue	None	0	0	Negative	
8020	1	G	32A	SPARC Module Room in Classroom 32	W3	Sheetrock	Purple	None	0	0	Negative	
8020	1	G	32A	SPARC Module Room in Classroom 32	W4	Sheetrock	Blue	None	0	N/A	N/A	
8020	1	G	32A	SPARC Module Room in Classroom 32	Ceiling	Sheetrock	White	None	0	N/A	N/A	
8020	1	G	32A	SPARC Module Room in Classroom 32	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	G	32A	SPARC Module Room in Classroom 32	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	176/178	Boy's Gymnasium	W1	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	176/178	Boy's Gymnasium	W2	Concrete	Beige	None	0	0	Negative	
8020	1	1	176/178	Boy's Gymnasium	W3	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	176/178	Boy's Gymnasium	W4	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	176/178	Boy's Gymnasium	Ceiling	Metal	Beige	None	0	N/A	N/A	
8020	1	1	176/178	Boy's Gymnasium	Floor	Wood	N/A	None	0	N/A	N/A	
8020	1	1	176/178	Boy's Gymnasium	Baseboards	Metal	Black	N/A	N/A	0.12	Negative	
8020	1	1	176K	Boy's Gymnasium Coaches Office	W1	Concrete	Beige & White	None	0	N/A	N/A	
8020	1	1	176K	Boy's Gymnasium Coaches Office	W2	Concrete	Beige & White	None	0	N/A	N/A	
8020	1	1	176K	Boy's Gymnasium Coaches Office	W3	Concrete	Beige & White	None	0	N/A	N/A	
8020	1	1	176K	Boy's Gymnasium Coaches Office	W4	Concrete	Beige & White	None	0	N/A	N/A	
8020	1	1	176K	Boy's Gymnasium Coaches Office	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	176K	Boy's Gymnasium Coaches Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	179B	Storage Room adjacent to Boy's Gymnasium	W1	Concrete	Beige & White	None	0	N/A	N/A	
8020	1	1	179B	Storage Room adjacent to Boy's Gymnasium	W2	Concrete	Beige & White	None	0	N/A	N/A	

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	179B	Storage Room adjacent to Boy's Gymnasium	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	179B	Storage Room adjacent to Boy's Gymnasium	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	179B	Storage Room adjacent to Boy's Gymnasium	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	179B	Storage Room adjacent to Boy's Gymnasium	Floor	Wood	N/A	N/A	N/A	N/A	N/A
8020	1	1	179B	Storage Room adjacent to Boy's Gymnasium	Baseboard	Metal	Grey	Chipping	1	0.52	Negative
8020	1	1	177/179	Girl's Gymnasium	W1	Concrete	Beige	None	0	0	Negative
8020	1	1	177/179	Girl's Gymnasium	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	177/179	Girl's Gymnasium	W3	Concrete	Beige	None	0	0	Negative
8020	1	1	177/179	Girl's Gymnasium	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	177/179	Girl's Gymnasium	Ceiling	Metal	Beige	None	0	N/A	N/A
8020	1	1	177/179	Girl's Gymnasium	Floor	Wood	N/A	N/A	N/A	N/A	N/A
8020	1	1	177/179	Girl's Gymnasium	Baseboards	Metal	Red	N/A	N/A	0.13	Negative
8020	1	1	177/179	Girl's Gymnasium	Baseboards	Metal	Black	N/A	N/A	1	Positive
8020	1	1	179H	Girl's Gymnasium Coaches Office	W1	Concrete	Beige & Tan	Moisture Damage	3	0	Negative
8020	1	1	179H	Girl's Gymnasium Coaches Office	W2	Concrete	Beige & Tan	None	0	N/A	N/A
8020	1	1	179H	Girl's Gymnasium Coaches Office	W3	Concrete	Beige & Tan	None	0	N/A	N/A
8020	1	1	179H	Girl's Gymnasium Coaches Office	W4	Concrete	Beige & Tan	None	0	N/A	N/A
8020	1	1	179H	Girl's Gymnasium Coaches Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	179H	Girl's Gymnasium Coaches Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	179H	Girl's Gymnasium Coaches Office	Baseboard	Metal	Grey	Chipping	1	0.34	Negative
8020	1	1	179D	Storage Room adjacent to Girls Gymnasium	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	179D	Storage Room adjacent to Girls Gymnasium	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	179D	Storage Room adjacent to Girls Gymnasium	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	179D	Storage Room adjacent to Girls Gymnasium	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	179D	Storage Room adjacent to Girls Gymnasium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	179D	Storage Room adjacent to Girls Gymnasium	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	177/179A	Boy's Locker Room	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	177/179A	Boy's Locker Room	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	177/179A	Boy's Locker Room	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	177/179A	Boy's Locker Room	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	177/179A	Boy's Locker Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	177/179A	Boy's Locker Room	Floor	Concrete	Tan	Friction	1		
8020	1	1	177G	Girl's Locker Room	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	177G	Girl's Locker Room	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	177G	Girl's Locker Room	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	177G	Girl's Locker Room	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	177G	Girl's Locker Room	Ceiling	Concrete	White	Moisture Damage	2		

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021								
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.		North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
8020	1	1	177G	Girl's Locker Room	Floor	Concrete	Tan	None	0	N/A	N/A	
8020	1	1	171A	Room 177 Athletic Department Office Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	171A	Room 177 Athletic Department Office Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	171A	Room 177 Athletic Department Office Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	171A	Room 177 Athletic Department Office Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	171A	Room 177 Athletic Department Office Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	171A	Room 177 Athletic Department Office Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	171B	Room 177 Athletic Department Office Copy Room	W1	Concrete	Peach & White	None	0	0	Negative	
8020	1	1	171B	Room 177 Athletic Department Office Copy Room	W2	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	171B	Room 177 Athletic Department Office Copy Room	W3	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	171B	Room 177 Athletic Department Office Copy Room	W4	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	171B	Room 177 Athletic Department Office Copy Room	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	171B	Room 177 Athletic Department Office Copy Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	171C	Room 177 Athletic Department Office	W1	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	171C	Room 177 Athletic Department Office	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	171C	Room 177 Athletic Department Office	W3	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	171C	Room 177 Athletic Department Office	W4	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	171C	Room 177 Athletic Department Office	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	171C	Room 177 Athletic Department Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	171D	Room 177 Athletic Department Office Lounge	W1	Concrete	Beige	None	0	0	Negative	
8020	1	1	171D	Room 177 Athletic Department Office Lounge	W2	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	171D	Room 177 Athletic Department Office Lounge	W3	Concrete & Ceramic	Beige & Blue	None	0	N/A	N/A	
8020	1	1	171D	Room 177 Athletic Department Office Lounge	W4	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	171D	Room 177 Athletic Department Office Lounge	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	171D	Room 177 Athletic Department Office Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	171E	Room 177 Athletic Department Office Bathroom	W1	Concrete & Ceramic	Red & Beige	None	0	N/A	N/A	
8020	1	1	171E	Room 177 Athletic Department Office Bathroom	W2	Concrete & Ceramic	Red & Beige	None	0	N/A	N/A	
8020	1	1	171E	Room 177 Athletic Department Office Bathroom	W3	Concrete & Ceramic	Red & Beige	None	0	N/A	N/A	
8020	1	1	171E	Room 177 Athletic Department Office Bathroom	W4	Concrete & Ceramic	Red & Beige	None	0	N/A	N/A	
8020	1	1	171E	Room 177 Athletic Department Office Bathroom	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	171E	Room 177 Athletic Department Office Bathroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	166A	Away Team Locker Room	W1	Concrete & Ceramic	Biege	None	0	0	Negative	
8020	1	1	166A	Away Team Locker Room	W2	Concrete & Ceramic	Biege	None	0	N/A	N/A	
8020	1	1	166A	Away Team Locker Room	W3	Concrete & Ceramic	Biege	None	0	N/A	N/A	
8020	1	1	166A	Away Team Locker Room	W4	Concrete & Ceramic	Biege	None	0	N/A	N/A	
8020	1	1	166A	Away Team Locker Room	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	166A	Away Team Locker Room	Floor	Concrete	Tan	Friction		0	Negative	
8020	1	1	166	Athletic Trainer	W1	Concrete	Peach	Flaking	1	0	Negative	
8020	1	1	166	Athletic Trainer	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	166	Athletic Trainer	W3	Concrete	Peach	None	0	N/A	N/A	

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021								
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.		North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
8020	1	1	166	Athletic Trainer	W4	Wood	N/A	N/A	N/A	N/A	N/A	
8020	1	1	166	Athletic Trainer	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	166	Athletic Trainer	Floor	Concrete	Tan	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office	W1	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office	W2	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office	W3	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office	W4	Concrete	Peach & White	None	0	0	Negative	
8020	1	1	164A	Room 164A Physical Education Office	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office Lockerrom	W1	Concrete	Biege	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office Lockerrom	W2	Concrete	Biege	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office Lockerrom	W3	Concrete	Biege	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office Lockerrom	W4	Concrete	Biege	None	0	N/A	N/A	
8020	1	1	164A	Room 164A Physical Education Office Lockerrom	Ceiling	Concrete	White	Moisture Damage	5	0.05	Negative	
8020	1	1	164A	Room 164A Physical Education Office Lockerrom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	164	Athletic Directors Office	W1	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	164	Athletic Directors Office	W2	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	164	Athletic Directors Office	W3	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	164	Athletic Directors Office	W4	Concrete	Beige	None	0	N/A	N/A	
8020	1	1	164	Athletic Directors Office	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	164	Athletic Directors Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	173B	Storage Room adjacent to Room 162	W1	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	173B	Storage Room adjacent to Room 162	W2	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	173B	Storage Room adjacent to Room 162	W3	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	173B	Storage Room adjacent to Room 162	W4	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	173B	Storage Room adjacent to Room 162	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	173B	Storage Room adjacent to Room 162	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	162	Classroom 162	W1	Concrete	Tan	None	0	N/A	N/A	
8020	1	1	162	Classroom 162	W2	Concrete	Tan	None	0	N/A	N/A	
8020	1	1	162	Classroom 162	W3	Concrete	Tan	None	0	N/A	N/A	
8020	1	1	162	Classroom 162	W4	Concrete	Tan	None	0	N/A	N/A	
8020	1	1	162	Classroom 162	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	162	Classroom 162	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	H18	Hallway next to Boy's Gymnasium and Boy's Locker Room	W1	Concrete	Beige & White	None	0	N/A	N/A	
8020	1	1	H18	Hallway next to Boy's Gymnasium and Boy's Locker Room	W2	Concrete	Beige & White	None	0	0.06	Negative	
8020	1	1	H18	Hallway next to Boy's Gymnasium and Boy's Locker Room	W3	Concrete	Beige & White	None	0	N/A	N/A	
8020	1	1	H18	Hallway next to Boy's Gymnasium and Boy's Locker Room	W4	Concrete	Beige & White	None	0	0	Negative	

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	H18	Hallway next to Boy's Gymnasium and Boy's Locker Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H18	Hallway next to Boy's Gymnasium and Boy's Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	109	Classroom 109	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	109	Classroom 109	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	109	Classroom 109	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	109	Classroom 109	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	109	Classroom 109	Ceiling	Concrete	Peach	None	0	0.1	Negative
8020	1	1	109	Classroom 109	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	111	Classroom 111	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	111	Classroom 111	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	111	Classroom 111	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	111	Classroom 111	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	111	Classroom 111	Ceiling	Concrete	Peach	None	0	0.01	Negative
8020	1	1	111	Classroom 111	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	111A	Science Prep Room between Classrooms 111 and 109	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	111A	Science Prep Room between Classrooms 111 and 109	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	111A	Science Prep Room between Classrooms 111 and 109	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	111A	Science Prep Room between Classrooms 111 and 109	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	111A	Science Prep Room between Classrooms 111 and 109	Ceiling	Concrete	White	Chipping	2	0.03	Negative
8020	1	1	111A	Science Prep Room between Classrooms 111 and 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H17	Hallway between Classroom 109 and Classroom 111	W1	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H17	Hallway between Classroom 109 and Classroom 111	W2	Concrete	Beige & White	None	0	0.03	Negative
8020	1	1	H17	Hallway between Classroom 109 and Classroom 111	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H17	Hallway between Classroom 109 and Classroom 111	W4	Concrete	Beige & White	None	0	1	Positive
8020	1	1	H17	Hallway between Classroom 109 and Classroom 111	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H17	Hallway between Classroom 109 and Classroom 111	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	107	Room 107 Mail Room	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	107	Room 107 Mail Room	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	107	Room 107 Mail Room	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	107	Room 107 Mail Room	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	107	Room 107 Mail Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	107	Room 107 Mail Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	105	Room 105	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	105	Room 105	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	105	Room 105	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	105	Room 105	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	105	Room 105	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	105	Room 105	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	105A	Room 105 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021								
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.		North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
8020	1	1	105A	Room 105 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	105A	Room 105 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	105A	Room 105 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	105A	Room 105 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	105A	Room 105 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103A	Room 103A Assistant Principal's Office Mr Picardi	W1	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103A	Room 103A Assistant Principal's Office Mr Picardi	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103A	Room 103A Assistant Principal's Office Mr Picardi	W3	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103A	Room 103A Assistant Principal's Office Mr Picardi	W4	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103A	Room 103A Assistant Principal's Office Mr Picardi	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	103A	Room 103A Assistant Principal's Office Mr Picardi	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	103B	Room 103B Ms Morton Office School Counselor	W1	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103B	Room 103B Ms Morton Office School Counselor	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103B	Room 103B Ms Morton Office School Counselor	W3	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103B	Room 103B Ms Morton Office School Counselor	W4	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103B	Room 103B Ms Morton Office School Counselor	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	103B	Room 103B Ms Morton Office School Counselor	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	103C	Room 103C Ms Kinning Office School Counselor	W1	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103C	Room 103C Ms Kinning Office School Counselor	W2	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103C	Room 103C Ms Kinning Office School Counselor	W3	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103C	Room 103C Ms Kinning Office School Counselor	W4	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103C	Room 103C Ms Kinning Office School Counselor	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103C	Room 103C Ms Kinning Office School Counselor	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103D	Room 103D Mr Dunakin's Office School Counselor	W1	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103D	Room 103D Mr Dunakin's Office School Counselor	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103D	Room 103D Mr Dunakin's Office School Counselor	W3	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103D	Room 103D Mr Dunakin's Office School Counselor	W4	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	103D	Room 103D Mr Dunakin's Office School Counselor	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	103D	Room 103D Mr Dunakin's Office School Counselor	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	103E	Room 103E Mr Belz Office School Counselor	W1	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103E	Room 103E Mr Belz Office School Counselor	W2	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103E	Room 103E Mr Belz Office School Counselor	W3	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103E	Room 103E Mr Belz Office School Counselor	W4	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103E	Room 103E Mr Belz Office School Counselor	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103E	Room 103E Mr Belz Office School Counselor	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
8020	1	1	103	Room 103 Counselor's Office Lobby	W1	Concrete	Peach & White	None	0	0	Negative	
8020	1	1	103	Room 103 Counselor's Office Lobby	W2	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	103	Room 103 Counselor's Office Lobby	W3	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	103	Room 103 Counselor's Office Lobby	W4	Concrete	Peach & White	None	0	N/A	N/A	
8020	1	1	103	Room 103 Counselor's Office Lobby	Ceiling	Concrete	White	None	0	N/A	N/A	

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	103	Room 103 Counselor's Office Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H103	Hallway between 103C and 103E	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H103	Hallway between 103C and 103E	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H103	Hallway between 103C and 103E	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H103	Hallway between 103C and 103E	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H103	Hallway between 103C and 103E	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H103	Hallway between 103C and 103E	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	101	Main Office Open Area	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	1	101	Main Office Open Area	W2	Concrete	Peach & White	None	0	0	Negative
8020	1	1	101	Main Office Open Area	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	1	101	Main Office Open Area	W4	Concrete	Peach & White	None	0	0	Negative
8020	1	1	101	Main Office Open Area	Ceiling	Concrete	White	None	0	0.03	Negative
8020	1	1	101	Main Office Open Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	101A	Principal's Office	W1	Concrete	Blue	None	0	N/A	N/A
8020	1	1	101A	Principal's Office	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	101A	Principal's Office	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	101A	Principal's Office	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	101A	Principal's Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	101A	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	101E	Restroom in Principal's Office	W1	Ceramic & Concrete	Red & Beige	None	0	N/A	N/A
8020	1	1	101E	Restroom in Principal's Office	W2	Ceramic & Concrete	Red & Beige	None	0	N/A	N/A
8020	1	1	101E	Restroom in Principal's Office	W3	Ceramic & Concrete	Red & Beige	None	0	N/A	N/A
8020	1	1	101E	Restroom in Principal's Office	W4	Ceramic & Concrete	Red & Beige	None	0	N/A	N/A
8020	1	1	101E	Restroom in Principal's Office	Ceiling	Concrete	Beige	None	0	N/A	N/A
8020	1	1	101E	Restroom in Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	101F	Principal's Office Closet	W1	Concrete	Blue	None	0	N/A	N/A
8020	1	1	101F	Principal's Office Closet	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	101F	Principal's Office Closet	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	101F	Principal's Office Closet	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	101F	Principal's Office Closet	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	101F	Principal's Office Closet	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	101B	Assitant Principal's Office Ms. Mecca	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101B	Assitant Principal's Office Ms. Mecca	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101B	Assitant Principal's Office Ms. Mecca	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101B	Assitant Principal's Office Ms. Mecca	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101B	Assitant Principal's Office Ms. Mecca	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	101B	Assitant Principal's Office Ms. Mecca	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	101C	Assistant Principal's Office Mrs DeNaples	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101C	Assistant Principal's Office Mrs DeNaples	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101C	Assistant Principal's Office Mrs DeNaples	W3	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	101C	Assistant Principal's Office Mrs DeNaples	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101C	Assistant Principal's Office Mrs DeNaples	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	101C	Assistant Principal's Office Mrs DeNaples	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	101D	Assistant Principal's Office Mr Greaves	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101D	Assistant Principal's Office Mr Greaves	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101D	Assistant Principal's Office Mr Greaves	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101D	Assistant Principal's Office Mr Greaves	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	101D	Assistant Principal's Office Mr Greaves	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	101D	Assistant Principal's Office Mr Greaves	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H13A	Hallway between Main Office and Counselor's 103 Suites	W1	Concrete	Beige & White	None	0	1.07	Positive
8020	1	1	H13A	Hallway between Main Office and Counselor's 103 Suites	W2	Concrete	Beige & White	None	0	1	Positive
8020	1	1	H13A	Hallway between Main Office and Counselor's 103 Suites	W3	Concrete	Beige & White	Chipping	1	1.25	Positive
8020	1	1	H13A	Hallway between Main Office and Counselor's 103 Suites	W4	Concrete	Beige & White	None	0	1	Positive
8020	1	1	H13A	Hallway between Main Office and Counselor's 103 Suites	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	H13A	Hallway between Main Office and Counselor's 103 Suites	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	136	Classroom 136	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	136	Classroom 136	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	136	Classroom 136	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	136	Classroom 136	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	136	Classroom 136	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	136	Classroom 136	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	136A	Classroom 136 Storage next to Window	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	136A	Classroom 136 Storage next to Window	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	136A	Classroom 136 Storage next to Window	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	136A	Classroom 136 Storage next to Window	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	136A	Classroom 136 Storage next to Window	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	136A	Classroom 136 Storage next to Window	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	136B	Classroom 136 Storage next to Hallway	W1	Concrete	Tan	None	0	N/A	N/A
8020	1	1	136B	Classroom 136 Storage next to Hallway	W2	Concrete	Tan	None	0	N/A	N/A
8020	1	1	136B	Classroom 136 Storage next to Hallway	W3	Concrete	Tan	None	0	N/A	N/A
8020	1	1	136B	Classroom 136 Storage next to Hallway	W4	Concrete	Tan	None	0	N/A	N/A
8020	1	1	136B	Classroom 136 Storage next to Hallway	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	136B	Classroom 136 Storage next to Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	138	Classroom 138	W1	Concrete	Blue & Yellow	None	0	N/A	N/A
8020	1	1	138	Classroom 138	W2	Concrete	Blue	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	138	Classroom 138	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	138	Classroom 138	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	138	Classroom 138	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	138	Classroom 138	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	S12B	First Floor Stairwell A	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12B	First Floor Stairwell A	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12B	First Floor Stairwell A	W3	Glass	N/A	None	0	N/A	N/A
8020	1	1	S12B	First Floor Stairwell A	W4	Concrete	Beige	None	0	0.01	Negative
8020	1	1	S12B	First Floor Stairwell A	Ceiling	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12B	First Floor Stairwell A	Floor	Concrete	N/A	None	0	N/A	N/A
8020	1	1	138A	Girl's Restroom near Main Entrance	W1	Concrete & Ceramic	White	None	0	N/A	N/A
8020	1	1	138A	Girl's Restroom near Main Entrance	W2	Concrete	Peach & White	None	0	0	Negative
8020	1	1	138A	Girl's Restroom near Main Entrance	W3	Concrete & Ceramic	White	None	0	N/A	N/A
8020	1	1	138A	Girl's Restroom near Main Entrance	W4	Concrete & Ceramic	White	None	0	N/A	N/A
8020	1	1	138A	Girl's Restroom near Main Entrance	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	138A	Girl's Restroom near Main Entrance	Floor	Concrete	Grey	Chipping	2	0	Negative
8020	1	1	134A	Men's Staffroom adjacent to Classroom 138	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	134A	Men's Staffroom adjacent to Classroom 138	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	134A	Men's Staffroom adjacent to Classroom 138	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	134A	Men's Staffroom adjacent to Classroom 138	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	134A	Men's Staffroom adjacent to Classroom 138	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	134A	Men's Staffroom adjacent to Classroom 138	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	134G	Men's Staffroom adjacent to Classroom 138 Restroom	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134G	Men's Staffroom adjacent to Classroom 138 Restroom	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134G	Men's Staffroom adjacent to Classroom 138 Restroom	W3	Ceramic & Concrete	Peach & White	Moisture Damage	3	0.04	Negative
8020	1	1	134G	Men's Staffroom adjacent to Classroom 138 Restroom	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134G	Men's Staffroom adjacent to Classroom 138 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	134G	Men's Staffroom adjacent to Classroom 138 Restroom	Floor	Concrete	Brown	Friction	1	0	Negative
8020	1	1	134B	Men's Staff Restroom across the Hallway from Main Office	W1	Concrete & Ceramic	Blue & White	None	0	N/A	N/A
8020	1	1	134B	Men's Staff Restroom across the Hallway from Main Office	W2	Concrete & Ceramic	Blue & White	None	0	N/A	N/A
8020	1	1	134B	Men's Staff Restroom across the Hallway from Main Office	W3	Concrete & Ceramic	Blue & White	None	0	N/A	N/A
8020	1	1	134B	Men's Staff Restroom across the Hallway from Main Office	W4	Concrete & Ceramic	Blue & White	None	0	N/A	N/A
8020	1	1	134B	Men's Staff Restroom across the Hallway from Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	134B	Men's Staff Restroom across the Hallway from Main Office	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	1	134C	Women's Staff Restroom across the Hallway from Main Office	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	134C	Women's Staff Restroom across the Hallway from Main Office	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134C	Women's Staff Restroom across the Hallway from Main Office	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134C	Women's Staff Restroom across the Hallway from Main Office	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134C	Women's Staff Restroom across the Hallway from Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	134C	Women's Staff Restroom across the Hallway from Main Office	Floor	Concrete	Brown	None	0	0	Negative
8020	1	1	134D	Women's Staff Locker Room across from Main Office	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134D	Women's Staff Locker Room across from Main Office	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134D	Women's Staff Locker Room across from Main Office	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134D	Women's Staff Locker Room across from Main Office	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	134D	Women's Staff Locker Room across from Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	134D	Women's Staff Locker Room across from Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	134E	Women's Staff Locker Room Restroom across from Main Office	W1	Concrete & Ceramic	Peach & White	None	0	N/A	N/A
8020	1	1	134E	Women's Staff Locker Room Restroom across from Main Office	W2	Concrete & Ceramic	Peach & White	None	0	N/A	N/A
8020	1	1	134E	Women's Staff Locker Room Restroom across from Main Office	W3	Concrete & Ceramic	Peach & White	None	0	N/A	N/A
8020	1	1	134E	Women's Staff Locker Room Restroom across from Main Office	W4	Concrete & Ceramic	Peach & White	None	0	N/A	N/A
8020	1	1	134E	Women's Staff Locker Room Restroom across from Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	134E	Women's Staff Locker Room Restroom across from Main Office	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	1	134H	Boy's Restroom across from Main Office	W1	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	134H	Boy's Restroom across from Main Office	W2	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	134H	Boy's Restroom across from Main Office	W3	Ceramic & Concrete	Blue & White & Beige	None	0	N/A	N/A
8020	1	1	134H	Boy's Restroom across from Main Office	W4	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	134H	Boy's Restroom across from Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	134H	Boy's Restroom across from Main Office	Floor	Concrete	Grey	Chipping	1	N/A	N/A
8020	1	1	100	School Services Room 100	W1	Concrete	Blue	None	0	0	Negative
8020	1	1	100	School Services Room 100	W2	Sheetrock	Blue	None	0	N/A	N/A
8020	1	1	100	School Services Room 100	W3	Sheetrock	Blue	None	0	N/A	N/A
8020	1	1	100	School Services Room 100	W4	Concrete	Blue	None	0	0	Negative
8020	1	1	100	School Services Room 100	Ceiling	Spline Ceilings	White	None	0	N/A	N/A
8020	1	1	100	School Services Room 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	100A	School Services Office 100A	W1	Concrete	Blue	None	0	N/A	N/A
8020	1	1	100A	School Services Office 100A	W2	Sheetrock	Blue	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	100A	School Services Office 100A	W3	Sheetrock	Blue	None	0	N/A	N/A
8020	1	1	100A	School Services Office 100A	W4	Sheetrock	Blue	None	0	N/A	N/A
8020	1	1	100A	School Services Office 100A	Ceiling	Spline Ceilings	White	None	0	N/A	N/A
8020	1	1	100A	School Services Office 100A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	100B	School Services Office 100B	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	100B	School Services Office 100B	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	100B	School Services Office 100B	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	100B	School Services Office 100B	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	100B	School Services Office 100B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	100B	School Services Office 100B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	100C	School Services Office 100C	W1	Sheetrock	Blue	None	0	N/A	N/A
8020	1	1	100C	School Services Office 100C	W2	Sheetrock	White	None	0	N/A	N/A
8020	1	1	100C	School Services Office 100C	W3	Concrete	White	None	0	N/A	N/A
8020	1	1	100C	School Services Office 100C	W4	Sheetrock	Blue	None	0	N/A	N/A
8020	1	1	100C	School Services Office 100C	Ceiling	Spline Ceilings	White	None	0	N/A	N/A
8020	1	1	100C	School Services Office 100C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	100D	School Services Office 100D	W1	Sheetrock	Blue	None	0	N/A	N/A
8020	1	1	100D	School Services Office 100D	W2	Sheetrock	Blue	None	0	N/A	N/A
8020	1	1	100D	School Services Office 100D	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	100D	School Services Office 100D	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	100D	School Services Office 100D	Ceiling	Spline Ceilings	White	None	0	N/A	N/A
8020	1	1	100D	School Services Office 100D	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	102	Room 102 Roster Office	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	1	102	Room 102 Roster Office	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	102	Room 102 Roster Office	W3	Concrete	Peach & White	None	0	0	None
8020	1	1	102	Room 102 Roster Office	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	102	Room 102 Roster Office	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	1	102	Room 102 Roster Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	104	College and Career Room 104	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	104	College and Career Room 104	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	104	College and Career Room 104	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	104	College and Career Room 104	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	104	College and Career Room 104	Ceiling	Concrete	White	None	0	0.09	Negative
8020	1	1	104	College and Career Room 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	104A	Girl's Restroom next to Room 104	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	104A	Girl's Restroom next to Room 104	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	104A	Girl's Restroom next to Room 104	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	104A	Girl's Restroom next to Room 104	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	104A	Girl's Restroom next to Room 104	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	104A	Girl's Restroom next to Room 104	Floor	Concrete	Grey	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	106A	Room 106A Storage Room (Chemical Storage)	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	106A	Room 106A Storage Room (Chemical Storage)	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	106A	Room 106A Storage Room (Chemical Storage)	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	106A	Room 106A Storage Room (Chemical Storage)	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	106A	Room 106A Storage Room (Chemical Storage)	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	106A	Room 106A Storage Room (Chemical Storage)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	S12B	First Floor Stairwell A	Railing	Metal	Grey	Friction	30	0.09	Negative
8020	1	1	S12B	First Floor Stairwell A	Stairway	Metal	Grey	Chipping	1	0.1	Negative
8020	1	1	S11	First Floor Stairwell D	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell D	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell D	W3	Glass	Peach	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell D	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell D	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell D	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	108A	Physics Storage Room	W1	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	108A	Physics Storage Room	W2	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	108A	Physics Storage Room	W3	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	108A	Physics Storage Room	W4	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	108A	Physics Storage Room	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	1	108A	Physics Storage Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	108	Classroom 108	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	1	108	Classroom 108	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	108	Classroom 108	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	1	108	Classroom 108	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	108	Classroom 108	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	1	108	Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	108A	Physics Storage Room	Wall Ventilator	Metal	Beige	Chipping	2	0.02	Negative
8020	1	1	112A	Science Prep Room between Classrooms 108 and 112	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	112A	Science Prep Room between Classrooms 108 and 112	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	112A	Science Prep Room between Classrooms 108 and 112	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	112A	Science Prep Room between Classrooms 108 and 112	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	112A	Science Prep Room between Classrooms 108 and 112	Ceiling	Concrete	White	Moisture Damage	2	N/A	N/A
8020	1	1	112A	Science Prep Room between Classrooms 108 and 112	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	112	Classroom 112	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	112	Classroom 112	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	112	Classroom 112	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	112	Classroom 112	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	112	Classroom 112	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	112	Classroom 112	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	106	Classroom 106	W1	Concrete	Peach & White	None	0	0	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	106	Classroom 106	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	106	Classroom 106	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	1	106	Classroom 106	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	106	Classroom 106	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	1	106	Classroom 106	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	110A	Science Prep Room between Classrooms 106 and 110	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	110A	Science Prep Room between Classrooms 106 and 110	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	110A	Science Prep Room between Classrooms 106 and 110	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	110A	Science Prep Room between Classrooms 106 and 110	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	110A	Science Prep Room between Classrooms 106 and 110	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	110A	Science Prep Room between Classrooms 106 and 110	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	110	Classroom 110	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	1	110	Classroom 110	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	110	Classroom 110	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	1	110	Classroom 110	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	110	Classroom 110	Ceiling	Concrete	White	None	0	0.01	Negative
8020	1	1	110	Classroom 110	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	114	Classroom 114	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	114	Classroom 114	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	114	Classroom 114	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	114	Classroom 114	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	114	Classroom 114	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	114	Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	116	Classroom 116	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	116	Classroom 116	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	116	Classroom 116	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	116	Classroom 116	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	116	Classroom 116	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	116	Classroom 116	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	118	Classroom 118	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	118	Classroom 118	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	118	Classroom 118	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	118	Classroom 118	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	118	Classroom 118	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	118	Classroom 118	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	S17	First Floor Stairwell C	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S17	First Floor Stairwell C	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S17	First Floor Stairwell C	W3	Glass	N/A	N/A	N/A	N/A	N/A
8020	1	1	S17	First Floor Stairwell C	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S17	First Floor Stairwell C	Ceiling	Concrete	White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	S17	First Floor Stairwell C	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	120A	Room 120A	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	120A	Room 120A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	120A	Room 120A	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	120A	Room 120A	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	120A	Room 120A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	120A	Room 120A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	120	Classroom 120	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	120	Classroom 120	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	120	Classroom 120	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	120	Classroom 120	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	120	Classroom 120	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	120	Classroom 120	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	122	Classroom 122	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	1	122	Classroom 122	W2	Concrete	Peach & White	None	0	0	Negative
8020	1	1	122	Classroom 122	W2	Concrete	Multi (Paint Splatters)	None	0	1	Positive
8020	1	1	122	Classroom 122	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	1	122	Classroom 122	W4	Concrete	Peach & White	None	0	0	Negative
8020	1	1	122	Classroom 122	Ceiling	Concrete	White	None	0	0.8	Positive
8020	1	1	122	Classroom 122	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	S17	First Floor Stairwell C	Railing	Metal	Black	None	0	N/A	N/A
8020	1	1	S17	First Floor Stairwell C	Staircase	Metal	Black	None	0	N/A	N/A
8020	1	1	122A	Storage Closet in Classroom 122	W1	Concrete	Blue	None	0	0	Negative
8020	1	1	122A	Storage Closet in Classroom 122	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	122A	Storage Closet in Classroom 122	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	122A	Storage Closet in Classroom 122	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	122A	Storage Closet in Classroom 122	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	122A	Storage Closet in Classroom 122	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	134	SLC Coordinator Room	W1	Concrete	Blue	None	0	0	Negative
8020	1	1	134	SLC Coordinator Room	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	134	SLC Coordinator Room	W3	Concrete	Blue	None	0	0	Negative
8020	1	1	134	SLC Coordinator Room	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	134	SLC Coordinator Room	Ceiling	Concrete	White	None	0	0.13	Negative
8020	1	1	134	SLC Coordinator Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	134F	Room 134 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	134F	Room 134 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	134F	Room 134 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	134F	Room 134 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	134F	Room 134 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	134F	Room 134 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	130	Classroom 130	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	130	Classroom 130	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	130	Classroom 130	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	130	Classroom 130	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	130	Classroom 130	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	130	Classroom 130	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	140	Classroom 140	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	140	Classroom 140	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	140	Classroom 140	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	140	Classroom 140	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	140	Classroom 140	Ceiling	Concrete	White	None	0	0.06	Negative
8020	1	1	140	Classroom 140	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	128C	Classroom 140 Restroom	W1	Concrete & Ceramic	Peach & White	None	0	N/A	N/A
8020	1	1	128C	Classroom 140 Restroom	W2	Concrete & Ceramic	Peach & White	None	0	N/A	N/A
8020	1	1	128C	Classroom 140 Restroom	W3	Concrete & Ceramic	Peach & White	None	0	N/A	N/A
8020	1	1	128C	Classroom 140 Restroom	W4	Concrete & Ceramic	Peach & White	None	0	N/A	N/A
8020	1	1	128C	Classroom 140 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	128C	Classroom 140 Restroom	Floor	Concrete	Brown	Friction	1	0	Negative
8020	1	1	132	Classroom 132	W1	Concrete	Blue	None	0	0	Negative
8020	1	1	132	Classroom 132	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	132	Classroom 132	W3	Concrete	Blue	None	0	0	Negative
8020	1	1	132	Classroom 132	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	132	Classroom 132	Ceiling	Concrete	White	None	0	0.03	Negative
8020	1	1	132	Classroom 132	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	128D	Classroom 132 Kitchen	W1	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128D	Classroom 132 Kitchen	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128D	Classroom 132 Kitchen	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128D	Classroom 132 Kitchen	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128D	Classroom 132 Kitchen	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	128D	Classroom 132 Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	128E	Classroom 132 Kitchen Food Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128E	Classroom 132 Kitchen Food Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128E	Classroom 132 Kitchen Food Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128E	Classroom 132 Kitchen Food Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128E	Classroom 132 Kitchen Food Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128E	Classroom 132 Kitchen Food Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128B	Classroom 132 Game Room	W1	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128B	Classroom 132 Game Room	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128B	Classroom 132 Game Room	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128B	Classroom 132 Game Room	W4	Concrete	Blue	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	128B	Classroom 132 Game Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	128B	Classroom 132 Game Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	128A	Classroom 132 Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128A	Classroom 132 Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128A	Classroom 132 Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128A	Classroom 132 Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128A	Classroom 132 Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	128A	Classroom 132 Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	S18	First Floor Stairwell B	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S18	First Floor Stairwell B	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S18	First Floor Stairwell B	W3	Glass	N/A	None	0	N/A	N/A
8020	1	1	S18	First Floor Stairwell B	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S18	First Floor Stairwell B	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	S18	First Floor Stairwell B	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	1	S18	First Floor Stairwell B	Railing	Metal	Grey	Flaking	20	N/A	N/A
8020	1	1	S18	First Floor Stairwell B	Stairway	Metal	Grey	Friction	1	N/A	N/A
8020	1	1	128	Teachers Lounge 128	W1	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128	Teachers Lounge 128	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128	Teachers Lounge 128	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	128	Teachers Lounge 128	W4	Concrete	Blue	None	0	0	Negative
8020	1	1	128	Teachers Lounge 128	Ceiling	Concrete	Tan	Moisture Damage	4	0.01	Negative
8020	1	1	128	Teachers Lounge 128	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	126	Classroom 126	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	126	Classroom 126	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	126	Classroom 126	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	126	Classroom 126	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	126	Classroom 126	Ceiling	Concrete	White	None	0	0.07	Negative
8020	1	1	126	Classroom 126	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	124	Classroom 124	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	124	Classroom 124	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	124	Classroom 124	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	124	Classroom 124	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	124	Classroom 124	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	124	Classroom 124	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	122B	Storage Closet in Classroom 122	W1	Concrete	Green	None	0	N/A	N/A
8020	1	1	122B	Storage Closet in Classroom 122	W2	Concrete	Green	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	122B	Storage Closet in Classroom 122	W3	Concrete	Green	None	0	N/A	N/A
8020	1	1	122B	Storage Closet in Classroom 122	W4	Concrete	Green	None	0	N/A	N/A
8020	1	1	122B	Storage Closet in Classroom 122	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	122B	Storage Closet in Classroom 122	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell D	Railings	Metal	Black	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell D	Staircase	Metal	Black	None	0	N/A	N/A
8020	1	1	124A	Classroom 124 Storage Room	W1	Concrete	Green	None	0	N/A	N/A
8020	1	1	124A	Classroom 124 Storage Room	W2	Concrete	Green	None	0	N/A	N/A
8020	1	1	124A	Classroom 124 Storage Room	W3	Concrete	Green	None	0	N/A	N/A
8020	1	1	124A	Classroom 124 Storage Room	W4	Concrete	Green	None	0	N/A	N/A
8020	1	1	124A	Classroom 124 Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	124A	Classroom 124 Storage Room	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	124B	Classroom 124 Storage Room	W1	Concrete	Green	None	0	N/A	N/A
8020	1	1	124B	Classroom 124 Storage Room	W2	Concrete	Green	None	0	N/A	N/A
8020	1	1	124B	Classroom 124 Storage Room	W3	Concrete	Green	None	0	N/A	N/A
8020	1	1	124B	Classroom 124 Storage Room	W4	Concrete	Green	None	0	N/A	N/A
8020	1	1	124B	Classroom 124 Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	124B	Classroom 124 Storage Room	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	H12K	Hallway across from Gymnasium Entering G Wing	W1	Concrete	Beige & White	None	0	0.06	Negative
8020	1	1	H12K	Hallway across from Gymnasium Entering G Wing	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H12K	Hallway across from Gymnasium Entering G Wing	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H12K	Hallway across from Gymnasium Entering G Wing	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H12K	Hallway across from Gymnasium Entering G Wing	Ceiling	Concrete	White	None			
8020	1	1	H12K	Hallway across from Gymnasium Entering G Wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	150	Classroom 150	W1	Concrete	Peach	None	0	0.01	Negative
8020	1	1	150	Classroom 150	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	150	Classroom 150	W3	Concrete	Peach	Mold growth	1	0.02	Negative
8020	1	1	150	Classroom 150	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	150	Classroom 150	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	150	Classroom 150	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	152A	Classroom 152A	W1	Concrete	Peach	None	0	0	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	152A	Classroom 152A	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	152A	Classroom 152A	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	152A	Classroom 152A	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	152A	Classroom 152A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	152A	Classroom 152A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	154	Classroom 154	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	154	Classroom 154	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	154	Classroom 154	W3	Concrete	Peach	None	0	0.02	Negative
8020	1	1	154	Classroom 154	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	154	Classroom 154	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	154	Classroom 154	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	156	Classroom 156	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	156	Classroom 156	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	156	Classroom 156	W3	Concrete	Peach	None	0	0.02	Negative
8020	1	1	156	Classroom 156	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	156	Classroom 156	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	156	Classroom 156	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	158	Classroom 158	W1	Concrete	Blue	None	0	0	Negative
8020	1	1	158	Classroom 158	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	158	Classroom 158	W3	Concrete	Blue	None	0	0.01	Negative
8020	1	1	158	Classroom 158	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	158	Classroom 158	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	158	Classroom 158	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H12K	Hallway across from Gymnasium Entering G Wing	Ceiling	Spline Ceiling Tiles	White	N/A	N/A	N/A	N/A
8020	1	1	H12K	Hallway across from Gymnasium Entering G Wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	158A	Classroom 158 Restroom	W1	Concrete	Blue	None	0	N/A	N/A
8020	1	1	158A	Classroom 158 Restroom	W2	Concrete	Blue	None	0	N/A	N/A
8020	1	1	158A	Classroom 158 Restroom	W3	Concrete	Blue	None	0	N/A	N/A
8020	1	1	158A	Classroom 158 Restroom	W4	Concrete	Blue	None	0	N/A	N/A
8020	1	1	158A	Classroom 158 Restroom	Ceiling	Drop Ceiling Tiles	N/A	N/A			
8020	1	1	158A	Classroom 158 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	160	Classroom 160	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	160	Classroom 160	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	160	Classroom 160	W3	Concrete	Peach	None	0	0.1	Negative
8020	1	1	160	Classroom 160	W4	Concrete	Peach	None	0	0	Negative
8020	1	1	160	Classroom 160	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	160	Classroom 160	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	158A	Classroom 158 Restroom	Floor	Ceramic	Tan	N/A			
8020	1	G	H03	Hallway from Boiler Room to Loading Dock	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	G	H03	Hallway from Boiler Room to Loading Dock	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	160A	Classroom 160 Restroom	W1	Ceramic	Cream	None	0	N/A	N/A
8020	1	1	160A	Classroom 160 Restroom	W2	Ceramic	Cream	None	0	N/A	N/A
8020	1	1	160A	Classroom 160 Restroom	W3	Ceramic	Cream	None	0	N/A	N/A
8020	1	1	160A	Classroom 160 Restroom	W4	Ceramic	Cream	None	0	N/A	N/A
8020	1	1	160A	Classroom 160 Restroom	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	1	160A	Classroom 160 Restroom	Floor	Ceramic	Red	None	0	N/A	N/A
8020	1	1	186	Woman's Staff Restroom adjacent to Classroom 160	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	186	Woman's Staff Restroom adjacent to Classroom 160	W2	Concrete	Beige	Flaking	N/A	N/A	N/A
8020	1	1	186	Woman's Staff Restroom adjacent to Classroom 160	W3	Concrete	Beige	Flaking	2	0	Negative
8020	1	1	186	Woman's Staff Restroom adjacent to Classroom 160	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	186	Woman's Staff Restroom adjacent to Classroom 160	Ceiling	Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	186	Woman's Staff Restroom adjacent to Classroom 160	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	182	Men's Staff Restroom adjacent to Classroom 160	W1	Concrete	Beige	Flaking	1	N/A	N/A
8020	1	1	182	Men's Staff Restroom adjacent to Classroom 160	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	182	Men's Staff Restroom adjacent to Classroom 160	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	182	Men's Staff Restroom adjacent to Classroom 160	W4	Concrete	Beige	Flaking	4	0	Negative
8020	1	1	182	Men's Staff Restroom adjacent to Classroom 160	Ceiling	Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	182	Men's Staff Restroom adjacent to Classroom 160	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
8020	1	1	184	Storage Room adjacent to Classroom 158	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	184	Storage Room adjacent to Classroom 158	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	184	Storage Room adjacent to Classroom 158	W3	Concrete	N/A	None	0	N/A	N/A
8020	1	1	184	Storage Room adjacent to Classroom 158	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	184	Storage Room adjacent to Classroom 158	Ceiling	Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	184	Storage Room adjacent to Classroom 158	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
8020	1	1	H12J	Hallway between Classroom 160 and Classroom 152A	W1	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H12J	Hallway between Classroom 160 and Classroom 152A	W2	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H12J	Hallway between Classroom 160 and Classroom 152A	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H12J	Hallway between Classroom 160 and Classroom 152A	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H12J	Hallway between Classroom 160 and Classroom 152A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H12J	Hallway between Classroom 160 and Classroom 152A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H19	Hallway between Classroom 108 and Classroom 118	W1	Concrete	Beige & White	None	0	0.01	Negative
8020	1	1	H19	Hallway between Classroom 108 and Classroom 118	W2	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H19	Hallway between Classroom 108 and Classroom 118	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H19	Hallway between Classroom 108 and Classroom 118	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H19	Hallway between Classroom 108 and Classroom 118	Ceiling	Concrete	W	None	0	N/A	N/A
8020	1	1	H19	Hallway between Classroom 108 and Classroom 118	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H19A	Hallway between Classroom 120 and Room 120A	W1	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H19A	Hallway between Classroom 120 and Room 120A	W2	Concrete	Beige & White	None	0	0.1	Negative
8020	1	1	H19A	Hallway between Classroom 120 and Room 120A	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H19A	Hallway between Classroom 120 and Room 120A	W4	Concrete	Beige & White	None	0	0	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	H19A	Hallway between Classroom 120 and Room 120A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H19A	Hallway between Classroom 120 and Room 120A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H11	Hallway between Classroom 138 and Classroom 130	W1	Concrete	Beige & White	None	0	0.02	Negative
8020	1	1	H11	Hallway between Classroom 138 and Classroom 130	W2	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H11	Hallway between Classroom 138 and Classroom 130	W3	Concrete	Beige & White	None	0	0.01	Negative
8020	1	1	H11	Hallway between Classroom 138 and Classroom 130	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H11	Hallway between Classroom 138 and Classroom 130	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H11	Hallway between Classroom 138 and Classroom 130	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H11A	Hallway between Classroom 126 and Room 126A	W1	Concrete	Beige & White	None	0	0.01	Negative
8020	1	1	H11A	Hallway between Classroom 126 and Room 126A	W2	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H11A	Hallway between Classroom 126 and Room 126A	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H11A	Hallway between Classroom 126 and Room 126A	W4	Concrete	Beige & White	None	0	0.02	Negative
8020	1	1	H11A	Hallway between Classroom 126 and Room 126A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H11A	Hallway between Classroom 126 and Room 126A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	S12G	First Floor Stairwell Q	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12G	First Floor Stairwell Q	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12G	First Floor Stairwell Q	W3	Glass	N/A	None	0	N/A	N/A
8020	1	1	S12G	First Floor Stairwell Q	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12G	First Floor Stairwell Q	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	S12G	First Floor Stairwell Q	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	1	S12G	First Floor Stairwell Q	Railings	Metal	Grey	Friction	15	N/A	N/A
8020	1	1	S12G	First Floor Stairwell Q	Staircase	Metal	Black	None	0	N/A	N/A
8020	1	1	113	Classroom 113	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	113	Classroom 113	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	113	Classroom 113	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	113	Classroom 113	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	113	Classroom 113	Ceiling	Concrete	Peach	None	0	0.04	Negative
8020	1	1	113	Classroom 113	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	113A	Office 113A	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	1	113A	Office 113A	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	113A	Office 113A	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	1	113A	Office 113A	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	113A	Office 113A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	113A	Office 113A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	115	Classroom 115	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	115	Classroom 115	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	115	Classroom 115	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	115	Classroom 115	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	115	Classroom 115	Ceiling	Concrete	Peach	None	0	0.01	Negative
8020	1	1	115	Classroom 115	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	S11C	First Floor Stairwell J	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S11C	First Floor Stairwell J	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S11C	First Floor Stairwell J	W3	Glass	N/A	None	0	N/A	N/A
8020	1	1	S11C	First Floor Stairwell J	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S11C	First Floor Stairwell J	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	S11C	First Floor Stairwell J	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	1	H14C	Hallway from Classroom 115 to Stairwell Q	W1	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H14C	Hallway from Classroom 115 to Stairwell Q	W2	Concrete	Beige & White	None	0	0.03	Negative
8020	1	1	H14C	Hallway from Classroom 115 to Stairwell Q	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H14C	Hallway from Classroom 115 to Stairwell Q	W4	Concrete	Beige & White	None	0	1	Positive
8020	1	1	H14C	Hallway from Classroom 115 to Stairwell Q	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H14C	Hallway from Classroom 115 to Stairwell Q	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H15	Hallway from Fitness Center to Athletic Department's Office	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H15	Hallway from Fitness Center to Athletic Department's Office	W2	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H15	Hallway from Fitness Center to Athletic Department's Office	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H15	Hallway from Fitness Center to Athletic Department's Office	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H15	Hallway from Fitness Center to Athletic Department's Office	Ceiling	Concrete	White				
8020	1	1	H15	Hallway from Fitness Center to Athletic Department's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H15	Hallway from Fitness Center to Athletic Department's Office	Ceiling	Concrete	White	Spline Ceiling Tiles	N/A	N/A	N/A
8020	1	1	H15	Hallway from Fitness Center to Athletic Department's Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8020	1	1	H16	Hallway from Athletic Department Office to Boy's Gymnasium	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H16	Hallway from Athletic Department Office to Boy's Gymnasium	W2	Concrete	Beige & White	None	0	0.01	Negative
8020	1	1	H16	Hallway from Athletic Department Office to Boy's Gymnasium	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H16	Hallway from Athletic Department Office to Boy's Gymnasium	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H16	Hallway from Athletic Department Office to Boy's Gymnasium	Ceiling	Concrete	White				
8020	1	1	H16	Hallway from Athletic Department Office to Boy's Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H14	Hallway from Classroom 117 to Classroom 131	W1	Concrete	Beige & White	None	0	0.03	Negative
8020	1	1	H14	Hallway from Classroom 117 to Classroom 131	W2	Concrete	Beige & White	None	0	0.01	Negative
8020	1	1	H14	Hallway from Classroom 117 to Classroom 131	W3	Concrete	Beige & White	None	0	0.02	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	H14	Hallway from Classroom 117 to Classroom 131	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H14	Hallway from Classroom 117 to Classroom 131	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H14	Hallway from Classroom 117 to Classroom 131	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	173	Fitness Center	W1	Concrete	White & Peach	Flaking	1	0.03	Negative
8020	1	1	173	Fitness Center	W2	Concrete	White & Peach	Flaking	1	N/A	N/A
8020	1	1	173	Fitness Center	W3	Concrete	White & Peach	Flaking	1	N/A	N/A
8020	1	1	173	Fitness Center	W4	Concrete	White & Peach	Flaking	1	N/A	N/A
8020	1	1	173	Fitness Center	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	173	Fitness Center	Floor	Wood	N/A	N/A			
8020	1	1	173	Fitness Center	Baseboard	Metal	Black	Chipping	1	0.06	Negative
8020	1	1	173A	Fitness Center Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	173A	Fitness Center Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	173A	Fitness Center Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	173A	Fitness Center Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	173A	Fitness Center Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	173A	Fitness Center Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	H16	Hallway from Athletic Department Office to Boy's Gymnasium	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H16	Hallway from Athletic Department Office to Boy's Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	175C	Fitness Center Storage Room Bathroom	W1	Ceramic & Concrete	Peach & Beige	None	0	N/A	N/A
8020	1	1	175C	Fitness Center Storage Room Bathroom	W2	Ceramic & Concrete	Peach & Beige	None	0	N/A	N/A
8020	1	1	175C	Fitness Center Storage Room Bathroom	W3	Ceramic & Concrete	Peach & Beige	None	0	N/A	N/A
8020	1	1	175C	Fitness Center Storage Room Bathroom	W4	Ceramic & Concrete	Peach & Beige	None	0	N/A	N/A
8020	1	1	175C	Fitness Center Storage Room Bathroom	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	175C	Fitness Center Storage Room Bathroom	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	175	Dance Studio	W1	Concrete	White & Peach	Flaking	10	0.03	Negative
8020	1	1	175	Dance Studio	W2	Concrete	White & Peach	Flaking	3	N/A	N/A
8020	1	1	175	Dance Studio	W3	Concrete	White & Peach	Flaking	6	0.01	Negative
8020	1	1	175	Dance Studio	W4	Concrete	White & Peach	Flaking	3	N/A	N/A
8020	1	1	175	Dance Studio	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	175	Dance Studio	Floor	Wood	N/A	N/A	N/A	N/A	N/A
8020	1	1	175A	Dance Studio Storage Room	W1	Concrete & drywall	Beige & Tan	None	0	N/A	N/A
8020	1	1	175A	Dance Studio Storage Room	W2	Concrete	Beige & Tan	None	0	N/A	N/A
8020	1	1	175A	Dance Studio Storage Room	W3	Concrete	Beige & Tan	None	0	N/A	N/A
8020	1	1	175A	Dance Studio Storage Room	W4	Concrete	Beige & Tan	None	0	N/A	N/A
8020	1	1	175A	Dance Studio Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	175A	Dance Studio Storage Room	Floor	Concrete	Tan	None	0	0	Negative
8020	1	1	175B	Dance Studio Storage Room Bathroom	W1	Concrete & Ceramic	White & Peach	None	0	N/A	N/A
8020	1	1	175B	Dance Studio Storage Room Bathroom	W2	Concrete & Ceramic	White & Peach	None	0	N/A	N/A
8020	1	1	175B	Dance Studio Storage Room Bathroom	W3	Concrete & Ceramic	White & Peach	None	0	0	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	175B	Dance Studio Storage Room Bathroom	W4	Concrete & Ceramic	White & Peach	None	0	N/A	N/A
8020	1	1	175B	Dance Studio Storage Room Bathroom	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	175B	Dance Studio Storage Room Bathroom	Floor	Concrete	Tan	None	0	N/A	N/A
8020	1	1	169A	Boy's Restroom adjacent to Classroom 117	W1	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	169A	Boy's Restroom adjacent to Classroom 117	W2	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	169A	Boy's Restroom adjacent to Classroom 117	W3	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	169A	Boy's Restroom adjacent to Classroom 117	W4	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	169A	Boy's Restroom adjacent to Classroom 117	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	169A	Boy's Restroom adjacent to Classroom 117	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	117	Classroom 117	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	117	Classroom 117	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	117	Classroom 117	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	117	Classroom 117	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	117	Classroom 117	Ceiling	Concrete	White	None	0	0.24	Negative
8020	1	1	117	Classroom 117	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	115A	Student ID Office 117A	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	115A	Student ID Office 117A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	115A	Student ID Office 117A	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	115A	Student ID Office 117A	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	115A	Student ID Office 117A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	115A	Student ID Office 117A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	119	Classroom 119	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	119	Classroom 119	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	119	Classroom 119	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	119	Classroom 119	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	119	Classroom 119	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	1	119	Classroom 119	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	121	Classroom 121	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	1	121	Classroom 121	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	121	Classroom 121	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	1	121	Classroom 121	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	121	Classroom 121	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	121	Classroom 121	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	123	Classroom 123	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	1	123	Classroom 123	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	123	Classroom 123	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	1	123	Classroom 123	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	123	Classroom 123	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	123	Classroom 123	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	123A	Health SLC Room 123A	W1	Concrete	Beige	None	0	0	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	123A	Health SLC Room 123A	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	123A	Health SLC Room 123A	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	123A	Health SLC Room 123A	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	123A	Health SLC Room 123A	Ceiling	Concrete	White	Moisture Damage	2	0.06	Negative
8020	1	1	123A	Health SLC Room 123A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	123B	Counseling Office 123B	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	123B	Counseling Office 123B	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	123B	Counseling Office 123B	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	123B	Counseling Office 123B	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	123B	Counseling Office 123B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	123B	Counseling Office 123B	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	S11C	First Floor Stairwell J	Railing	Metal	Black	None	0	N/A	N/A
8020	1	1	S11C	First Floor Stairwell J	Stairway	Metal	Black	None	0	N/A	N/A
8020	1	1	S12E	First Floor Stairwell K	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12E	First Floor Stairwell K	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12E	First Floor Stairwell K	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12E	First Floor Stairwell K	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S12E	First Floor Stairwell K	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	S12E	First Floor Stairwell K	Floor	Concrete	Brown	None	0	0	Negative
8020	1	1	125	Classroom 125	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	125	Classroom 125	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	125	Classroom 125	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	125	Classroom 125	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	125	Classroom 125	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	1	125	Classroom 125	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	127	Classroom 127	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	1	127	Classroom 127	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	127	Classroom 127	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	1	127	Classroom 127	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	127	Classroom 127	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	127	Classroom 127	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	S12E	First Floor Stairwell K	Door	Metal	Tan	Friction	2	0	Negative
8020	1	1	S12E	First Floor Stairwell K	Railings	Metal	Black	None	0	0.08	Negative
8020	1	1	S12E	First Floor Stairwell K	Staircase	Metal	Black	None	0	0.79	Positive
8020	1	1	129	Office 129	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	129	Office 129	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	129	Office 129	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	129	Office 129	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	129	Office 129	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	129	Office 129	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	131	Classroom 131	W1	Concrete	White & Peach	None	0	N/A	N/A
8020	1	1	131	Classroom 131	W2	Concrete	White & Peach	None	0	N/A	N/A
8020	1	1	131	Classroom 131	W3	Concrete	White & Peach	None	0	N/A	N/A
8020	1	1	131	Classroom 131	W4	Concrete	White & Peach	None	0	N/A	N/A
8020	1	1	131	Classroom 131	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	131	Classroom 131	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	133A	Music Office 131A	W1	Concrete	Blue & Green	None	0	0	Negative
8020	1	1	133A	Music Office 131A	W2	Concrete	Blue & Green	None	0	N/A	N/A
8020	1	1	133A	Music Office 131A	W3	Concrete	Blue & Green	None	0	N/A	N/A
8020	1	1	133A	Music Office 131A	W4	Concrete	Blue & Green	None	0	N/A	N/A
8020	1	1	133A	Music Office 131A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	133A	Music Office 131A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	133	Chorus Room 133	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	133	Chorus Room 133	W2	Concrete	Peach	None	0	0	Negative
8020	1	1	133	Chorus Room 133	W3	Concrete	Peach	Cracking	1	0	Negative
8020	1	1	133	Chorus Room 133	W4	Concrete	Peach	Chipping	1	0	Negative
8020	1	1	133	Chorus Room 133	Ceiling	Spline Ceilings	White	None	0	N/A	N/A
8020	1	1	133	Chorus Room 133	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	135	Band Room 135	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	135	Band Room 135	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	135	Band Room 135	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	135	Band Room 135	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	135	Band Room 135	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	1	135	Band Room 135	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	131A	Band Room 135 Office	W1	Concrete	Green	None	0	N/A	N/A
8020	1	1	131A	Band Room 135 Office	W2	Concrete	Green	None	0	N/A	N/A
8020	1	1	131A	Band Room 135 Office	W3	Concrete	Green	Moisture Damage	3	N/A	N/A
8020	1	1	131A	Band Room 135 Office	W4	Concrete	Green	Moisture Damage	3	0	Negative
8020	1	1	131A	Band Room 135 Office	Ceiling	Concrete	White	Moisture Damage	5	0.02	Negative
8020	1	1	131A	Band Room 135 Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	131B	Band Practice Room 4	W1	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131B	Band Practice Room 4	W2	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131B	Band Practice Room 4	W3	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131B	Band Practice Room 4	W4	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131B	Band Practice Room 4	Ceiling	2' x 4' Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	131B	Band Practice Room 4	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	131C	Band Practice Room 3	W1	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131C	Band Practice Room 3	W2	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131C	Band Practice Room 3	W3	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131C	Band Practice Room 3	W4	Sheetrock	Beige & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	131C	Band Practice Room 3	Ceiling	2' x 4' Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	131C	Band Practice Room 3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	131D	Band Practice Room 5	W1	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131D	Band Practice Room 5	W2	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131D	Band Practice Room 5	W3	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131D	Band Practice Room 5	W4	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131D	Band Practice Room 5	Ceiling	2' x 4' Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	131D	Band Practice Room 5	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	131E	Band Practice Room 6	W1	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131E	Band Practice Room 6	W2	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131E	Band Practice Room 6	W3	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131E	Band Practice Room 6	W4	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131E	Band Practice Room 6	Ceiling	2' x 4' Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	131E	Band Practice Room 6	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	131F	Band Practice Room 2	W1	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131F	Band Practice Room 2	W2	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131F	Band Practice Room 2	W3	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131F	Band Practice Room 2	W4	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131F	Band Practice Room 2	Ceiling	2' x 4' Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	131F	Band Practice Room 2	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	131G	Band Practice Room 1	W1	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131G	Band Practice Room 1	W2	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131G	Band Practice Room 1	W3	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131G	Band Practice Room 1	W4	Sheetrock	Beige & White	None	0	N/A	N/A
8020	1	1	131G	Band Practice Room 1	Ceiling	2' x 4' Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	131G	Band Practice Room 1	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H32	Hallway from Band Room 135 to Stairs	W1	0	Beige & White	None	0	N/A	N/A
8020	1	1	H32	Hallway from Band Room 135 to Stairs	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H32	Hallway from Band Room 135 to Stairs	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H32	Hallway from Band Room 135 to Stairs	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H32	Hallway from Band Room 135 to Stairs	Ceiling	Concrete	White				
8020	1	1	H32	Hallway from Band Room 135 to Stairs	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H32	Hallway from Band Room 135 to Stairs	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H32	Hallway from Band Room 135 to Stairs	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	S13	First Floor Stairs next to Music Practice Rooms	W1	Concrete	Beige & White	Chipping	5	N/A	N/A
8020	1	1	S13	First Floor Stairs next to Music Practice Rooms	W2	Concrete	Beige & White	Chipping	30	0.04	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	S13	First Floor Stairs next to Music Practice Rooms	W3	Glass	N/A	N/A	N/A	N/A	N/A
8020	1	1	S13	First Floor Stairs next to Music Practice Rooms	W4	Concrete	Beige & White	Chipping	20	N/A	N/A
8020	1	1	S13	First Floor Stairs next to Music Practice Rooms	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	S13	First Floor Stairs next to Music Practice Rooms	Floor	Concrete	Brown	Friction	10	0	Negative
8020	1	1	S13	First Floor Stairs next to Music Practice Rooms	Railings	Metal	Grey	Friction	20	0.18	Negative
8020	1	1	S13	First Floor Stairs next to Music Practice Rooms	Staircase	Metal	Grey	Chipping	5	0.44	Negative
8020	1	1	H31	Hallway from Band Room 135 to Hallway	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H31	Hallway from Band Room 135 to Hallway	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H31	Hallway from Band Room 135 to Hallway	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H31	Hallway from Band Room 135 to Hallway	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H31	Hallway from Band Room 135 to Hallway	Ceiling	Concrete	White				
8020	1	1	H31	Hallway from Band Room 135 to Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H13	Hallway from Chorus Room 133 to Classroom 131	W1	Concrete	Beige & White	None	0	0.03	Negative
8020	1	1	H13	Hallway from Chorus Room 133 to Classroom 131	W2	Concrete	Beige & White	None	0	0.01	Negative
8020	1	1	H13	Hallway from Chorus Room 133 to Classroom 131	W3	Concrete	Beige & White	None	0	0.02	Negative
8020	1	1	H13	Hallway from Chorus Room 133 to Classroom 131	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H13	Hallway from Chorus Room 133 to Classroom 131	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H13	Hallway from Chorus Room 133 to Classroom 131	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H31	Hallway from Band Room 135 to Hallway	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	H31	Hallway from Band Room 135 to Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	135A	Staff Rest Room across from Classroom 125	W1	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	135A	Staff Rest Room across from Classroom 125	W2	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	135A	Staff Rest Room across from Classroom 125	W3	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	135A	Staff Rest Room across from Classroom 125	W4	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	1	135A	Staff Rest Room across from Classroom 125	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	135A	Staff Rest Room across from Classroom 125	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	135B	Storage Room adjacent to Staff Room	W1	Concrete	Pink	None	0	0	Negative
8020	1	1	135B	Storage Room adjacent to Staff Room	W2	Concrete	Pink	None	0	N/A	N/A
8020	1	1	135B	Storage Room adjacent to Staff Room	W3	Concrete	Pink	None	0	N/A	N/A
8020	1	1	135B	Storage Room adjacent to Staff Room	W4	Concrete	Pink	None	0	N/A	N/A
8020	1	1	135B	Storage Room adjacent to Staff Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	135B	Storage Room adjacent to Staff Room	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	137	Classroom 137	W1	Concrete	Peach	None	0	0	Negative
8020	1	1	137	Classroom 137	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	137	Classroom 137	W3	Concrete	Peach	None	0	0	Negative
8020	1	1	137	Classroom 137	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	137	Classroom 137	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	1	137	Classroom 137	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	139	Classroom 139	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	139	Classroom 139	W2	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	139	Classroom 139	W3	Concrete	Peach & White	Chipping	3	0	Negative
8020	1	1	139	Classroom 139	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	139	Classroom 139	Ceiling	Concrete	White	None	0	0.03	Negative
8020	1	1	139	Classroom 139	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H12A	Hallway from Classrooms 137 and 139 to Stairwell K	W1	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H12A	Hallway from Classrooms 137 and 139 to Stairwell K	W2	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H12A	Hallway from Classrooms 137 and 139 to Stairwell K	W3	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H12A	Hallway from Classrooms 137 and 139 to Stairwell K	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	1	H12A	Hallway from Classrooms 137 and 139 to Stairwell K	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	1	H12A	Hallway from Classrooms 137 and 139 to Stairwell K	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H12A	Hallway from Classrooms 137 and 139 to Stairwell K	Ceiling	Concrete	White				
8020	1	1	H12A	Hallway from Classrooms 137 and 139 to Stairwell K	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	S11	First Floor Stairwell M	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell M	W2	Concrete	Beige	None	0	0.02	Negative
8020	1	1	S11	First Floor Stairwell M	W3	Glass	N/A	N/A	N/A	N/A	N/A
8020	1	1	S11	First Floor Stairwell M	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell M	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	S11	First Floor Stairwell M	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	141	Classroom 141	W1	Concrete	Tan	None	0	0	Negative
8020	1	1	141	Classroom 141	W2	Concrete	Tan	None	0	N/A	N/A
8020	1	1	141	Classroom 141	W3	Concrete	Tan	None	0	0	Negative
8020	1	1	141	Classroom 141	W4	Concrete	Tan	None	0	N/A	N/A
8020	1	1	141	Classroom 141	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	1	141	Classroom 141	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	141A	Speech and Hearing Room	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	141A	Speech and Hearing Room	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	141A	Speech and Hearing Room	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	141A	Speech and Hearing Room	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	141A	Speech and Hearing Room	Ceiling	Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	141A	Speech and Hearing Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	141B	Nurse's Office Restroom	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	1	141B	Nurse's Office Restroom	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	141B	Nurse's Office Restroom	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	1	141B	Nurse's Office Restroom	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	1	141B	Nurse's Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	141B	Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	141C	Nurse's Office 145	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	1	141C	Nurse's Office 145	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	1	141C	Nurse's Office 145	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	1	141C	Nurse's Office 145	W4	Concrete	Peach	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021								
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.		North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
8020	1	1	141C	Nurse's Office 145	Ceiling	No Access	White	None	No Access	No Access	No Access	
8020	1	1	141C	Nurse's Office 145	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	141D	Testing Room	W1	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141D	Testing Room	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141D	Testing Room	W3	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141D	Testing Room	W4	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141D	Testing Room	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	141D	Testing Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	141E	Nurse's Office Closet	W1	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141E	Nurse's Office Closet	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141E	Nurse's Office Closet	W3	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141E	Nurse's Office Closet	W4	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141E	Nurse's Office Closet	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	141E	Nurse's Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	141F	Nurse's Office Exam Room	W1	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141F	Nurse's Office Exam Room	W2	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141F	Nurse's Office Exam Room	W3	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141F	Nurse's Office Exam Room	W4	Concrete	Peach	None	0	N/A	N/A	
8020	1	1	141F	Nurse's Office Exam Room	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	141F	Nurse's Office Exam Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	141G	Hallway from Nurse's Office to Copy Room	W1	Concrete	Beige & White	None	0	0	Negative	
8020	1	1	141G	Hallway from Nurse's Office to Copy Room	W2	Concrete	Beige & White	None	0	0	Negative	
8020	1	1	141G	Hallway from Nurse's Office to Copy Room	W3	Concrete	Beige & White	None	0	0	Negative	
8020	1	1	141G	Hallway from Nurse's Office to Copy Room	W4	Concrete	Beige & White	None	0	0	Negative	
8020	1	1	141G	Hallway from Nurse's Office to Copy Room	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	141G	Hallway from Nurse's Office to Copy Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	141H	Hallway from Nurse's Office to Speech and Hearing Room	W1	Concrete	Beige & White	None	0	0	Negative	
8020	1	1	141H	Hallway from Nurse's Office to Speech and Hearing Room	W2	Concrete	Beige & White	None	0	0	Negative	
8020	1	1	141H	Hallway from Nurse's Office to Speech and Hearing Room	W3	Concrete	Beige & White	None	0	0	Negative	
8020	1	1	141H	Hallway from Nurse's Office to Speech and Hearing Room	W4	Concrete	Beige & White	None	0	0	Negative	
8020	1	1	141H	Hallway from Nurse's Office to Speech and Hearing Room	Ceiling	Concrete	White	None	0	N/A	N/A	
8020	1	1	141H	Hallway from Nurse's Office to Speech and Hearing Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
8020	1	1	S11	First Floor Stairwell M	Railings	Metal	Grey	Friction	20	0.09	Negative	
8020	1	1	S11	First Floor Stairwell M	Staircase	Metal	Grey	Chipping	5	0.12	Negative	
8020	1	1	141I	Assistant Nurse's Office	W1	Concrete	Beige	None	0	N/A	N/A	

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	1411	Assistant Nurse's Office	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	1411	Assistant Nurse's Office	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	1411	Assistant Nurse's Office	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	1411	Assistant Nurse's Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	1411	Assistant Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	H12	Hallway from Classroom 137 to Main Office	W1	Concrete	Beige & White	Cracking	1	0	Negative
8020	1	1	H12	Hallway from Classroom 137 to Main Office	W2	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H12	Hallway from Classroom 137 to Main Office	W3	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H12	Hallway from Classroom 137 to Main Office	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	1	H12	Hallway from Classroom 137 to Main Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	H12	Hallway from Classroom 137 to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	153	Storage Room across from Office 143	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	153	Storage Room across from Office 143	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	153	Storage Room across from Office 143	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	153	Storage Room across from Office 143	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	153	Storage Room across from Office 143	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	153	Storage Room across from Office 143	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	159	Storage Room across from Nurse's Office 145	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	159	Storage Room across from Nurse's Office 145	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	159	Storage Room across from Nurse's Office 145	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	159	Storage Room across from Nurse's Office 145	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	159	Storage Room across from Nurse's Office 145	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	159	Storage Room across from Nurse's Office 145	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	H11	Main Entrance Hallway	W1	Marble	Tan	None	0	N/A	N/A
8020	1	1	H11	Main Entrance Hallway	W2	Marble	Tan	None	0	N/A	N/A
8020	1	1	H11	Main Entrance Hallway	W3	Marble	Tan	None	0	N/A	N/A
8020	1	1	H11	Main Entrance Hallway	W4	Marble	Tan	None	0	N/A	N/A
8020	1	1	H11	Main Entrance Hallway	Ceiling	Spline Ceiling	White	None	0	N/A	N/A
8020	1	1	H11	Main Entrance Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	143	Alumni Office 143	W1	Concrete	Tan	None	0	0	Negative
8020	1	1	143	Alumni Office 143	W2	Concrete	Tan	None	0	0	Negative
8020	1	1	143	Alumni Office 143	W3	Concrete	Tan	None	0	0	Negative
8020	1	1	143	Alumni Office 143	W4	Concrete	Tan	None	0	0	Negative
8020	1	1	143	Alumni Office 143	Ceiling	Concrete	White	None	0	0	Negative
8020	1	1	143	Alumni Office 143	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	145	Auditorium	W1	Wood Panels on Concrete	Beige	None	0	N/A	N/A
8020	1	1	145	Auditorium	W2	Wood Panels on Concrete	Beige	None	0	N/A	N/A
8020	1	1	145	Auditorium	W3	Stage	Beige	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	1	145	Auditorium	W4	Wood Panels on Concrete	Beige	None	0	N/A	N/A
8020	1	1	145	Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	145	Auditorium	Ceiling	Spline ceiling	Tan	None	0	N/A	N/A
8020	1	1	145	Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	145A	Auditorium Exit	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	1	145A	Auditorium Exit	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	145A	Auditorium Exit	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	145A	Auditorium Exit	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	145A	Auditorium Exit	Ceiling	2' x 4' Drop Ceiling Tiles	N/A	N/A	N/A	N/A	N/A
8020	1	1	145A	Auditorium Exit	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	147	Auditorium Stage	W1	Concrete	Beige	None	0	0	Negative
8020	1	1	147	Auditorium Stage	W2	Concrete	Beige	None	0	0	Negative
8020	1	1	147	Auditorium Stage	W3	Concrete	Beige	None	0	0	Negative
8020	1	1	147	Auditorium Stage	W4	Concrete	Beige	None	0	0	Negative
8020	1	1	147	Auditorium Stage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147	Auditorium Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	147B	Auditorium Stage Hallway	W1	Concrete	Beige & White	None	0	0.03	Negative
8020	1	1	147B	Auditorium Stage Hallway	W2	Concrete	Beige & White	None	0	0.01	Negative
8020	1	1	147B	Auditorium Stage Hallway	W3	Concrete	Beige & White	None	0	0.02	Negative
8020	1	1	147B	Auditorium Stage Hallway	W4	Concrete	Beige & White	None	0	0	Negative
8020	1	1	147B	Auditorium Stage Hallway	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	147B	Auditorium Stage Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	147C	Auditorium Stage Girl's Dressing Room	W1	Concrete	Beige	Chipping	1	0	Negative
8020	1	1	147C	Auditorium Stage Girl's Dressing Room	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	1	147C	Auditorium Stage Girl's Dressing Room	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	1	147C	Auditorium Stage Girl's Dressing Room	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	1	147C	Auditorium Stage Girl's Dressing Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	147C	Auditorium Stage Girl's Dressing Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	1	147E	Auditorium Stage Girl's Dressing Room Bathroom	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	147E	Auditorium Stage Girl's Dressing Room Bathroom	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	147E	Auditorium Stage Girl's Dressing Room Bathroom	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	147E	Auditorium Stage Girl's Dressing Room Bathroom	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	1	147E	Auditorium Stage Girl's Dressing Room Bathroom	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	1	147E	Auditorium Stage Girl's Dressing Room Bathroom	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	1	147D	Auditorium Stage Boy's Dressing Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147D	Auditorium Stage Boy's Dressing Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147D	Auditorium Stage Boy's Dressing Room	W3	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	1	147D	Auditorium Stage Boy's Dressing Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147D	Auditorium Stage Boy's Dressing Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147D	Auditorium Stage Boy's Dressing Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147F	Auditorium Stage Boy's Dressing Room Bathroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147F	Auditorium Stage Boy's Dressing Room Bathroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147F	Auditorium Stage Boy's Dressing Room Bathroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147F	Auditorium Stage Boy's Dressing Room Bathroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147F	Auditorium Stage Boy's Dressing Room Bathroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	1	147F	Auditorium Stage Boy's Dressing Room Bathroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	219E	Boy's Restroom adjacent to Office 219C	W1	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	219E	Boy's Restroom adjacent to Office 219C	W2	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	219E	Boy's Restroom adjacent to Office 219C	W3	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	219E	Boy's Restroom adjacent to Office 219C	W4	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	219E	Boy's Restroom adjacent to Office 219C	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	219E	Boy's Restroom adjacent to Office 219C	Floor	Concrete	Grey	Friction	1	0	Negative
8020	1	2	219C	Office 219C	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219C	Office 219C	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219C	Office 219C	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219C	Office 219C	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219C	Office 219C	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	219C	Office 219C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	219B	Classroom 219B	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219B	Classroom 219B	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219B	Classroom 219B	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219B	Classroom 219B	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219B	Classroom 219B	Ceiling	Concrete	White				
8020	1	2	219B	Classroom 219B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	219A	Classroom 219A	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	219A	Classroom 219A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219A	Classroom 219A	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	219A	Classroom 219A	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	219A	Classroom 219A	Ceiling	Concrete	White	None	0	0.07	Negative
8020	1	2	219A	Classroom 219A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	221A	Classroom 221A	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	221A	Classroom 221A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	221A	Classroom 221A	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	221A	Classroom 221A	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	221A	Classroom 221A	Ceiling	Concrete	White				
8020	1	2	221A	Classroom 221A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	221B	Classroom 221B	W1	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	2	221B	Classroom 221B	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	221B	Classroom 221B	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	221B	Classroom 221B	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	221B	Classroom 221B	Ceiling	Concrete	White				
8020	1	2	221B	Classroom 221B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	223C	Classroom 223C	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	223C	Classroom 223C	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	223C	Classroom 223C	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	223C	Classroom 223C	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	223C	Classroom 223C	Ceiling	Concrete	White	None	0	0.06	Negative
8020	1	2	223C	Classroom 223C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	223A	Classroom 223A	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	223A	Classroom 223A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	223A	Classroom 223A	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	223A	Classroom 223A	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	223A	Classroom 223A	Ceiling	Concrete	White	None	0	0.23	Negative
8020	1	2	223A	Classroom 223A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	223T	Girl's Restroom adjacent to Classroom 223A	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	223T	Girl's Restroom adjacent to Classroom 223A	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	223T	Girl's Restroom adjacent to Classroom 223A	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	223T	Girl's Restroom adjacent to Classroom 223A	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	223T	Girl's Restroom adjacent to Classroom 223A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	223T	Girl's Restroom adjacent to Classroom 223A	Floor	Concrete	Grey	Friction	1	0	Negative
8020	1	2	225	Tutoring Center	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	225	Tutoring Center	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	225	Tutoring Center	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	225	Tutoring Center	W4	Sheetrock	Peach & White	None	0	N/A	N/A
8020	1	2	225	Tutoring Center	Ceiling	Concrete	White	None	0	0.06	Negative
8020	1	2	225	Tutoring Center	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	225A	Tutoring Center Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	225A	Tutoring Center Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	225A	Tutoring Center Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	225A	Tutoring Center Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	225A	Tutoring Center Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	225A	Tutoring Center Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	227A	Classroom 227A	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	227A	Classroom 227A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	227A	Classroom 227A	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	227A	Classroom 227A	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	227A	Classroom 227A	Ceiling	Concrete	White				

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	227A	Classroom 227A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	227B	Classroom 227B	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	227B	Classroom 227B	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	227B	Classroom 227B	W3	Concrete	Peach & White	Cracking	1		
8020	1	2	227B	Classroom 227B	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	227B	Classroom 227B	Ceiling	Concrete	White				
8020	1	2	227B	Classroom 227B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H27B	Second Floor Hallway from Stairwell J to Stairwell K	W1	Concrete	Grey-Cream and White	None	0	0.1	Negative
8020	1	2	H27B	Second Floor Hallway from Stairwell J to Stairwell K	W2	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H27B	Second Floor Hallway from Stairwell J to Stairwell K	W3	Concrete	Grey-Cream and White	None	0	0.01	Negative
8020	1	2	H27B	Second Floor Hallway from Stairwell J to Stairwell K	W4	Concrete	Grey-Cream and White	None	0	0.02	Negative
8020	1	2	H27B	Second Floor Hallway from Stairwell J to Stairwell K	Ceiling	Spline ceiling	White	N/A	N/A	0	Negative
8020	1	2	H27B	Second Floor Hallway from Stairwell J to Stairwell K	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H27A	Second Floor Hallway from Stairwell K to Classroom 227A	W1	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H27A	Second Floor Hallway from Stairwell K to Classroom 227A	W2	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H27A	Second Floor Hallway from Stairwell K to Classroom 227A	W3	Concrete	Grey-Cream and White	None	0	0.01	Negative
8020	1	2	H27A	Second Floor Hallway from Stairwell K to Classroom 227A	W4	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H27A	Second Floor Hallway from Stairwell K to Classroom 227A	Ceiling	Spline ceiling	White	N/A	N/A	0	Negative
8020	1	2	H27A	Second Floor Hallway from Stairwell K to Classroom 227A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	229C	Classroom 229C	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	229C	Classroom 229C	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	229C	Classroom 229C	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	229C	Classroom 229C	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	229C	Classroom 229C	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	2	229C	Classroom 229C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	229B	Classroom 229B	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	229B	Classroom 229B	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	229B	Classroom 229B	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	229B	Classroom 229B	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	229B	Classroom 229B	Ceiling	Concrete	White	None	0	0.08	Negative
8020	1	2	229B	Classroom 229B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	229A	Viking Cafe Office	W1	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8020	1	2	229A	Viking Cafe Office	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	229A	Viking Cafe Office	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	229A	Viking Cafe Office	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	229A	Viking Cafe Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	229A	Viking Cafe Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	229D	Storage Room across from Stairwell M	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	2	229D	Storage Room across from Stairwell M	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	2	229D	Storage Room across from Stairwell M	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	2	229D	Storage Room across from Stairwell M	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	2	229D	Storage Room across from Stairwell M	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	229D	Storage Room across from Stairwell M	Floor	Concrete	Tan	None	0	N/A	N/A
8020	1	2	231	Classroom 231	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	231	Classroom 231	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	231	Classroom 231	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	231	Classroom 231	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	231	Classroom 231	Ceiling	Concrete	White				
8020	1	2	231	Classroom 231	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	233	Classroom 233	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	233	Classroom 233	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	233	Classroom 233	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	233	Classroom 233	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	233	Classroom 233	Ceiling	Concrete	White				
8020	1	2	233	Classroom 233	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	233C	Storage Room across from Classroom 233	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	233C	Storage Room across from Classroom 233	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	233C	Storage Room across from Classroom 233	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	233C	Storage Room across from Classroom 233	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	233C	Storage Room across from Classroom 233	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	233C	Storage Room across from Classroom 233	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	235	Classroom 235	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	235	Classroom 235	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	235	Classroom 235	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	235	Classroom 235	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	235	Classroom 235	Ceiling	Concrete	White	None	0	0.04	Negative
8020	1	2	235	Classroom 235	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	235C	Storage Room across from Classroom 235	W1	Concrete	Yellow	None	0	N/A	N/A
8020	1	2	235C	Storage Room across from Classroom 235	W2	Concrete	Yellow	None	0	N/A	N/A
8020	1	2	235C	Storage Room across from Classroom 235	W3	Concrete	Yellow	None	0	0	Negative
8020	1	2	235C	Storage Room across from Classroom 235	W4	Concrete	Yellow	None	0	N/A	N/A
8020	1	2	235C	Storage Room across from Classroom 235	Ceiling	Concrete	White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	235C	Storage Room across from Classroom 235	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	235C	Storage Room across from Classroom 235	Pipe Chase	Metal	Yellow	Chipping	9	0.12	Negative
8020	1	2	235D	Storage Room across from Classroom 237	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	235D	Storage Room across from Classroom 237	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	235D	Storage Room across from Classroom 237	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	235D	Storage Room across from Classroom 237	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	235D	Storage Room across from Classroom 237	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	235D	Storage Room across from Classroom 237	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	235E	Storage Room adjacent to Classroom 237	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	235E	Storage Room adjacent to Classroom 237	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	235E	Storage Room adjacent to Classroom 237	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	235E	Storage Room adjacent to Classroom 237	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	235E	Storage Room adjacent to Classroom 237	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	235E	Storage Room adjacent to Classroom 237	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	237	Bilingual Counselors Office	W1	Concrete	Peach	None	0	N/A	N/A
8020	1	2	237	Bilingual Counselors Office	W2	Concrete	Peach	None	0	N/A	N/A
8020	1	2	237	Bilingual Counselors Office	W3	Concrete	Peach	None	0	N/A	N/A
8020	1	2	237	Bilingual Counselors Office	W4	Concrete	Peach	None	0	N/A	N/A
8020	1	2	237	Bilingual Counselors Office	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	237	Bilingual Counselors Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H27A	Second Floor Hallway Classroom 227A to Teacher's Lounge	W1	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27A	Second Floor Hallway Classroom 227A to Teacher's Lounge	W2	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27A	Second Floor Hallway Classroom 227A to Teacher's Lounge	W3	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27A	Second Floor Hallway Classroom 227A to Teacher's Lounge	W4	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27A	Second Floor Hallway Classroom 227A to Teacher's Lounge	Ceiling	Spline ceiling	White	N/A	N/A	N/A	N/A
8020	1	2	H27A	Second Floor Hallway Classroom 227A to Teacher's Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	214	Classroom 214	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	214	Classroom 214	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	214	Classroom 214	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	214	Classroom 214	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	214	Classroom 214	Ceiling	Concrete	White				
8020	1	2	214	Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H29	Second Floor Hallway from Stairwell C to Classroom 214	W1	Concrete	Grey-Cream and White	None	0	0.01	Negative
8020	1	2	H29	Second Floor Hallway from Stairwell C to Classroom 214	W2	Concrete	Grey-Cream and White	None	0	0.05	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	H29	Second Floor Hallway from Stairwell C to Classroom 214	W3	Concrete	Grey-Cream and White	None	0	0.04	Negative
8020	1	2	H29	Second Floor Hallway from Stairwell C to Classroom 214	W4	Concrete	Grey-Cream and White	None	0	0.02	Negative
8020	1	2	H29	Second Floor Hallway from Stairwell C to Classroom 214	Ceiling	Spline	White	N/A	N/A	0	Negative
8020	1	2	H29	Second Floor Hallway from Stairwell C to Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	216	Classroom 216	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	216	Classroom 216	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	216	Classroom 216	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	216	Classroom 216	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	216	Classroom 216	Ceiling	Concrete	White	None	0	0.1	Negative
8020	1	2	216	Classroom 216	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	218	Classroom 218	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	218	Classroom 218	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	218	Classroom 218	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	218	Classroom 218	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	218	Classroom 218	Ceiling	Concrete	White	None	0	0.07	Negative
8020	1	2	218	Classroom 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	220	Classroom 220	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	220	Classroom 220	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	220	Classroom 220	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	220	Classroom 220	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	220	Classroom 220	Ceiling	Concrete	White				
8020	1	2	220	Classroom 220	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	222	Classroom 222	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	222	Classroom 222	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	222	Classroom 222	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	222	Classroom 222	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	222	Classroom 222	Ceiling	Concrete	White				
8020	1	2	222	Classroom 222	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	222A	Office 222A	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	222A	Office 222A	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	222A	Office 222A	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	222A	Office 222A	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	222A	Office 222A	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	2	222A	Office 222A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	224A	Large Library Office	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224A	Large Library Office	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224A	Large Library Office	W3	Concrete	Beige	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	224A	Large Library Office	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224A	Large Library Office	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	2	224A	Large Library Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	224B	Small Library Office	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224B	Small Library Office	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224B	Small Library Office	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224B	Small Library Office	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224B	Small Library Office	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	2	224B	Small Library Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	224C	Library Office Storage Room	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224C	Library Office Storage Room	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224C	Library Office Storage Room	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224C	Library Office Storage Room	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	224C	Library Office Storage Room	Ceiling	Spline Ceiling Tiles	White	None	0	N/A	N/A
8020	1	2	224C	Library Office Storage Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	224D	Library Faculty/Staff Restroom	W1	Ceramic & Concrete	Red & Beige	None	0	N/A	N/A
8020	1	2	224D	Library Faculty/Staff Restroom	W2	Ceramic & Concrete	Red & Beige	None	0	N/A	N/A
8020	1	2	224D	Library Faculty/Staff Restroom	W3	Ceramic & Concrete	Red & Beige	None	0	N/A	N/A
8020	1	2	224D	Library Faculty/Staff Restroom	W4	Ceramic & Concrete	Red & Beige	None	0	N/A	N/A
8020	1	2	224D	Library Faculty/Staff Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	224D	Library Faculty/Staff Restroom	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	226	Library	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	226	Library	W2	Concrete	Peach & White	None	0	0	Negative
8020	1	2	226	Library	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	226	Library	W4	Concrete	Peach & White	None	0	0	Negative
8020	1	2	226	Library	Ceiling	Drop ceiling tiles	White	None	0	N/A	N/A
8020	1	2	226	Library	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	226D	Library Storage Room	W1	Concrete	Green	None	0	N/A	N/A
8020	1	2	226D	Library Storage Room	W2	Concrete	Green	None	0	N/A	N/A
8020	1	2	226D	Library Storage Room	W3	Concrete	Green	None	0	N/A	N/A
8020	1	2	226D	Library Storage Room	W4	Concrete	Green	None	0	N/A	N/A
8020	1	2	226D	Library Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	226D	Library Storage Room	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	H26	Second Floor Hallway from Stairwell B to Library	W1	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H26	Second Floor Hallway from Stairwell B to Library	W2	Concrete	Grey-Cream and White	None	0	1	Positive
8020	1	2	H26	Second Floor Hallway from Stairwell B to Library	W3	Concrete	Grey-Cream and White	None	0	1	Positive
8020	1	2	H26	Second Floor Hallway from Stairwell B to Library	W4	Concrete	Grey-Cream and White	None	0	0	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	H26	Second Floor Hallway from Stairwell B to Library	Ceiling	Spline celing	White	N/A	N/A	0	Negative
8020	1	2	H26	Second Floor Hallway from Stairwell B to Library	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H28	Second Floor Hallway from Stairwell C to Library	W1	Concrete	Grey-Cream and White	None	0	0.02	Negative
8020	1	2	H28	Second Floor Hallway from Stairwell C to Library	W2	Concrete	Grey-Cream and White	None	0	0.02	Negative
8020	1	2	H28	Second Floor Hallway from Stairwell C to Library	W3	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H28	Second Floor Hallway from Stairwell C to Library	W4	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H28	Second Floor Hallway from Stairwell C to Library	Ceiling	Spline	White	N/A	N/A	0	Negative
8020	1	2	H28	Second Floor Hallway from Stairwell C to Library	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	226A	Teating Center and Office adjacent to Library Entrance and Stairwell B	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	226A	Teating Center and Office adjacent to Library Entrance and Stairwell B	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	226A	Teating Center and Office adjacent to Library Entrance and Stairwell B	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	226A	Teating Center and Office adjacent to Library Entrance and Stairwell B	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	226A	Teating Center and Office adjacent to Library Entrance and Stairwell B	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	226A	Teating Center and Office adjacent to Library Entrance and Stairwell B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	226B	Storage Closet adjacent to Stairwell B	W1	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	226B	Storage Closet adjacent to Stairwell B	W2	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	226B	Storage Closet adjacent to Stairwell B	W3	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	226B	Storage Closet adjacent to Stairwell B	W4	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	226B	Storage Closet adjacent to Stairwell B	Ceiling	Spline Ceiling Tiles	White	Moisture Damage	9	0	Negative
8020	1	2	226B	Storage Closet adjacent to Stairwell B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	228	Classroom 228	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	228	Classroom 228	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	228	Classroom 228	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	228	Classroom 228	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	228	Classroom 228	Ceiling	Concrete	White	None	0	0.06	Negative
8020	1	2	228	Classroom 228	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	230	Classroom 230	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	230	Classroom 230	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	230	Classroom 230	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	230	Classroom 230	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	230	Classroom 230	Ceiling	Concrete	White				
8020	1	2	230	Classroom 230	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	232	Classroom 232	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	232	Classroom 232	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	232	Classroom 232	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	232	Classroom 232	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	232	Classroom 232	Ceiling	Concrete	White				
8020	1	2	232	Classroom 232	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	236	Classroom 236	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	236	Classroom 236	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	236	Classroom 236	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	236	Classroom 236	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	236	Classroom 236	Ceiling	Concrete	White				
8020	1	2	236	Classroom 236	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H27C	Second Floor Hallway from Stairwell B to Classroom 236	W1	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H27C	Second Floor Hallway from Stairwell B to Classroom 236	W2	Concrete	Grey-Cream and White	None	0	0.01	Negative
8020	1	2	H27C	Second Floor Hallway from Stairwell B to Classroom 236	W3	Concrete	Grey-Cream and White	None	0	1	Positive
8020	1	2	H27C	Second Floor Hallway from Stairwell B to Classroom 236	W4	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H27C	Second Floor Hallway from Stairwell B to Classroom 236	Ceiling	Spline ceiling	White	N/A	N/A	0	Negative
8020	1	2	H27C	Second Floor Hallway from Stairwell B to Classroom 236	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	234	Classroom 234	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	234	Classroom 234	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	234	Classroom 234	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	234	Classroom 234	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	234	Classroom 234	Ceiling	Concrete	White	None	0	0.05	Negative
8020	1	2	234	Classroom 234	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	238	Classroom 238	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	238	Classroom 238	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	238	Classroom 238	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	238	Classroom 238	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	238	Classroom 238	Ceiling	Concrete	White				
8020	1	2	238	Classroom 238	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	240	Classroom 240	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	240	Classroom 240	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	240	Classroom 240	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	240	Classroom 240	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	240	Classroom 240	Ceiling	Concrete	White	None	0	0.03	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	240	Classroom 240	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H27	Second Floor Hallway from Classroom 240 to Middle Hallway	W1	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27	Second Floor Hallway from Classroom 240 to Middle Hallway	W2	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27	Second Floor Hallway from Classroom 240 to Middle Hallway	W3	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27	Second Floor Hallway from Classroom 240 to Middle Hallway	W4	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27	Second Floor Hallway from Classroom 240 to Middle Hallway	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	H27	Second Floor Hallway from Classroom 240 to Middle Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	242	Classroom 242	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	242	Classroom 242	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	242	Classroom 242	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	242	Classroom 242	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	242	Classroom 242	Ceiling	Concrete	White				
8020	1	2	242	Classroom 242	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	244	Classroom 244	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	244	Classroom 244	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	244	Classroom 244	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	244	Classroom 244	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	244	Classroom 244	Ceiling	Concrete	White				
8020	1	2	244	Classroom 244	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	246	Women's Staff/Faculty Restroom adjacent to Classroom 242	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	246	Women's Staff/Faculty Restroom adjacent to Classroom 242	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	246	Women's Staff/Faculty Restroom adjacent to Classroom 242	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	246	Women's Staff/Faculty Restroom adjacent to Classroom 242	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	246	Women's Staff/Faculty Restroom adjacent to Classroom 242	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	246	Women's Staff/Faculty Restroom adjacent to Classroom 242	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	246C	Women's Staff/Faculty Locker Room adjacent to Classroom 242	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	246C	Women's Staff/Faculty Locker Room adjacent to Classroom 242	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	246C	Women's Staff/Faculty Locker Room adjacent to Classroom 242	W3	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	246C	Women's Staff/Faculty Locker Room adjacent to Classroom 242	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	246C	Women's Staff/Faculty Locker Room adjacent to Classroom 242	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	246C	Women's Staff/Faculty Locker Room adjacent to Classroom 242	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	242A	Storage Closet adjacent to Women's Restroom by Classroom 242	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	242A	Storage Closet adjacent to Women's Restroom by Classroom 242	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	242A	Storage Closet adjacent to Women's Restroom by Classroom 242	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	242A	Storage Closet adjacent to Women's Restroom by Classroom 242	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	242A	Storage Closet adjacent to Women's Restroom by Classroom 242	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	242A	Storage Closet adjacent to Women's Restroom by Classroom 242	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	242B	Storage Closet adjacent to Men's Restroom by Classroom 201	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	242B	Storage Closet adjacent to Men's Restroom by Classroom 201	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	242B	Storage Closet adjacent to Men's Restroom by Classroom 201	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	242B	Storage Closet adjacent to Men's Restroom by Classroom 201	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	242B	Storage Closet adjacent to Men's Restroom by Classroom 201	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	242B	Storage Closet adjacent to Men's Restroom by Classroom 201	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	246A	Men's Staff/Faculty Restroom across from Classroom 201	W1	Concrete	Yellow/Tan	None	0	N/A	N/A
8020	1	2	246A	Men's Staff/Faculty Restroom across from Classroom 201	W2	Concrete	Yellow/Tan	None	0	N/A	N/A
8020	1	2	246A	Men's Staff/Faculty Restroom across from Classroom 201	W3	Concrete	Yellow/Tan	None	0	N/A	N/A
8020	1	2	246A	Men's Staff/Faculty Restroom across from Classroom 201	W4	Concrete	Yellow/Tan	None	0	N/A	N/A
8020	1	2	246A	Men's Staff/Faculty Restroom across from Classroom 201	Ceiling	Concrete	Yellow/Tan	None	0	N/A	N/A
8020	1	2	246A	Men's Staff/Faculty Restroom across from Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	246B	Men's Bathroom within Faculty area across from Classroom 201	W1	Concrete	Beige/Tan	None	0	0	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	246B	Men's Bathroom within Faculty area across from Classroom 201	W2	Concrete	Beige/Tan	None	0	N/A	N/A
8020	1	2	246B	Men's Bathroom within Faculty area across from Classroom 201	W3	Concrete	Beige/Tan	None	0	0	Negative
8020	1	2	246B	Men's Bathroom within Faculty area across from Classroom 201	W4	Concrete	Beige/Tan	None	0	0	Negative
8020	1	2	246B	Men's Bathroom within Faculty area across from Classroom 201	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	246B	Men's Bathroom within Faculty area across from Classroom 201	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	201C	Boy's Restroom adjacent to Classroom 200	W1	Concrete	Beige & White	None	0	1.11	Positive
8020	1	2	201C	Boy's Restroom adjacent to Classroom 200	W2	Concrete	Beige & White	None	0	1.21	Positive
8020	1	2	201C	Boy's Restroom adjacent to Classroom 200	W3	Concrete	Beige & White	None	0	1.04	Positive
8020	1	2	201C	Boy's Restroom adjacent to Classroom 200	W4	Concrete	Beige & White	None	0	N/A	N/A
8020	1	2	201C	Boy's Restroom adjacent to Classroom 200	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	201C	Boy's Restroom adjacent to Classroom 200	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	201	Classroom 201	W1	Concrete	Peach & White w/Green	None	0	0	Negative
8020	1	2	201	Classroom 201	W2	Concrete	Peach & White w/Green	None	0	0	Negative
8020	1	2	201	Classroom 201	W3	Concrete	Peach & White w/Green	None	0	N/A	N/A
8020	1	2	201	Classroom 201	W4	Concrete	Peach & White w/Green	None	0	N/A	N/A
8020	1	2	201	Classroom 201	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	201	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	203	Classroom 203	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	203	Classroom 203	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	203	Classroom 203	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	203	Classroom 203	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	203	Classroom 203	Ceiling	Concrete	White				
8020	1	2	203	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	203A	Classroom 203A	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	203A	Classroom 203A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	203A	Classroom 203A	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	203A	Classroom 203A	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	203A	Classroom 203A	Ceiling	Concrete	White				
8020	1	2	203A	Classroom 203A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	200	Classroom 200	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	200	Classroom 200	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	200	Classroom 200	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	200	Classroom 200	W4	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021		Lead Safe Certification Assessment Report North East High School					
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,							
				Inspection Company: REPSG, Inc.							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	200	Classroom 200	Ceiling	Concrete	White				
8020	1	2	200	Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	202	Classroom 202	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	202	Classroom 202	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	202	Classroom 202	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	202	Classroom 202	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	202	Classroom 202	Ceiling	Concrete	White	None	0	0.05	Negative
8020	1	2	202	Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	205	Classroom 205	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	205	Classroom 205	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	205	Classroom 205	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	205	Classroom 205	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	205	Classroom 205	Ceiling	Concrete	White				
8020	1	2	205	Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	204	Classroom 204	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	204	Classroom 204	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	204	Classroom 204	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	204	Classroom 204	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	204	Classroom 204	Ceiling	Concrete	White	None	0	0.04	Negative
8020	1	2	204	Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H25	Second Floor Middle Hallway from Classroom 201 to Classroom 205	W1	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H25	Second Floor Middle Hallway from Classroom 201 to Classroom 205	W2	Concrete	Grey-Cream and White	None	0	0.03	Negative
8020	1	2	H25	Second Floor Middle Hallway from Classroom 201 to Classroom 205	W3	Concrete	Grey-Cream and White	None	0	0.02	Negative
8020	1	2	H25	Second Floor Middle Hallway from Classroom 201 to Classroom 205	W4	Concrete	Grey-Cream and White	None	0	0.06	Negative
8020	1	2	H25	Second Floor Middle Hallway from Classroom 201 to Classroom 205	Ceiling	Spline	White	N/A	N/A	0	Negative
8020	1	2	H25	Second Floor Middle Hallway from Classroom 201 to Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	204D	Girl's Restroom adjacent to Classroom 204	W1	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	204D	Girl's Restroom adjacent to Classroom 204	W2	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	204D	Girl's Restroom adjacent to Classroom 204	W3	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	204D	Girl's Restroom adjacent to Classroom 204	W4	Ceramic & Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	204D	Girl's Restroom adjacent to Classroom 204	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	204D	Girl's Restroom adjacent to Classroom 204	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	204C	Storage Closet adjacent to Girl's Restroom by Classroom 204	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	204C	Storage Closet adjacent to Girl's Restroom by Classroom 204	W2	Concrete	Beige	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	204C	Storage Closet adjacent to Girl's Restroom by Classroom 204	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	204C	Storage Closet adjacent to Girl's Restroom by Classroom 204	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	204C	Storage Closet adjacent to Girl's Restroom by Classroom 204	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	204C	Storage Closet adjacent to Girl's Restroom by Classroom 204	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	206B	Storage Closet across from Stairwell D	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	206B	Storage Closet across from Stairwell D	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	206B	Storage Closet across from Stairwell D	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	206B	Storage Closet across from Stairwell D	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	206B	Storage Closet across from Stairwell D	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	206B	Storage Closet across from Stairwell D	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	206C	Boy's Restroom adjacent to Classroom 206	W1	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	206C	Boy's Restroom adjacent to Classroom 206	W2	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	206C	Boy's Restroom adjacent to Classroom 206	W3	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	206C	Boy's Restroom adjacent to Classroom 206	W4	Ceramic & Concrete	Blue & White	None	0	N/A	N/A
8020	1	2	206C	Boy's Restroom adjacent to Classroom 206	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	206C	Boy's Restroom adjacent to Classroom 206	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	206	Classroom 206	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	206	Classroom 206	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	206	Classroom 206	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	206	Classroom 206	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	206	Classroom 206	Ceiling	Concrete	White				
8020	1	2	206	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H25	Second Floor Hallway from Classroom 210 to Middle Hallway	W1	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H25	Second Floor Hallway from Classroom 210 to Middle Hallway	W2	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H25	Second Floor Hallway from Classroom 210 to Middle Hallway	W3	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H25	Second Floor Hallway from Classroom 210 to Middle Hallway	W4	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H25	Second Floor Hallway from Classroom 210 to Middle Hallway	Ceiling	Spline	White	N/A	N/A	N/A	N/A
8020	1	2	H25	Second Floor Hallway from Classroom 210 to Middle Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	206A	Office 206A	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	206A	Office 206A	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	206A	Office 206A	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	206A	Office 206A	W4	Concrete	Peach & White	None	0	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	206A	Office 206A	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	206A	Office 206A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	208	Classroom 208	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	208	Classroom 208	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	208	Classroom 208	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	208	Classroom 208	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	208	Classroom 208	Ceiling	Concrete	White				
8020	1	2	208	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	210	Classroom 210	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	210	Classroom 210	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	210	Classroom 210	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	210	Classroom 210	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	210	Classroom 210	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	2	210	Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	212	Classroom 212	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	212	Classroom 212	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	212	Classroom 212	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	212	Classroom 212	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	212	Classroom 212	Ceiling	Concrete	White				
8020	1	2	212	Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	211	Classroom 211	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	211	Classroom 211	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	211	Classroom 211	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	211	Classroom 211	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	211	Classroom 211	Ceiling	Spline ceiling	White	None	0	N/A	N/A
8020	1	2	211	Classroom 211	Ceiling	Concrete	White	None	0	0.02	Negative
8020	1	2	211	Classroom 211	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	213	Classroom 213	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	213	Classroom 213	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	213	Classroom 213	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	213	Classroom 213	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	213	Classroom 213	Ceiling	Spline ceiling	White	None	0	N/A	N/A
8020	1	2	213	Classroom 213	Ceiling	Concrete	White	None	0	0.05	Negative
8020	1	2	213	Classroom 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	215A	Office 215A	W1	Sheetrock	Beige	None	0	0	Negative
8020	1	2	215A	Office 215A	W2	Sheetrock	Beige	None	0	N/A	N/A
8020	1	2	215A	Office 215A	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215A	Office 215A	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215A	Office 215A	Ceiling	Spline ceiling tiles	White	None	0	N/A	N/A
8020	1	2	215A	Office 215A	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	215B	Office 215B	W1	Sheetrock	Peach & White	None	0	0	Negative
8020	1	2	215B	Office 215B	W2	Sheetrock	Peach & White	None	0	N/A	N/A
8020	1	2	215B	Office 215B	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	215B	Office 215B	W4	Sheetrock	Peach & White	None	0	N/A	N/A
8020	1	2	215B	Office 215B	Ceiling	Spline ceiling	White	None	0	N/A	N/A
8020	1	2	215B	Office 215B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	215C	Office 215C	W1	Sheetrock	Beige	None	0	N/A	N/A
8020	1	2	215C	Office 215C	W2	Sheetrock	Beige	None	0	N/A	N/A
8020	1	2	215C	Office 215C	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215C	Office 215C	W4	Sheetrock	Beige	None	0	N/A	N/A
8020	1	2	215C	Office 215C	Ceiling	Spline ceiling tiles	White	None	0	N/A	N/A
8020	1	2	215C	Office 215C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	215D	Office 215D	W1	Sheetrock	Beige	None	0	N/A	N/A
8020	1	2	215D	Office 215D	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215D	Office 215D	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215D	Office 215D	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215D	Office 215D	Ceiling	2x4' drop ceiling tile system	Cream	None	0	N/A	N/A
8020	1	2	215D	Office 215D	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	215E	Office across from Offices 215A and 215B	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215E	Office across from Offices 215A and 215B	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215E	Office across from Offices 215A and 215B	W3	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215E	Office across from Offices 215A and 215B	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215E	Office across from Offices 215A and 215B	Ceiling	Concrete	Beige	None	0	N/A	N/A
8020	1	2	215E	Office across from Offices 215A and 215B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	215F	Storage Closet across from Offices 215A and 215B	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	215F	Storage Closet across from Offices 215A and 215B	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	215F	Storage Closet across from Offices 215A and 215B	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	215F	Storage Closet across from Offices 215A and 215B	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	215F	Storage Closet across from Offices 215A and 215B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	215F	Storage Closet across from Offices 215A and 215B	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	H215	Office 215 Hallway	W1	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H215	Office 215 Hallway	W2	Sheetrock	Grey-Cream and White	None	0	0	Negative
8020	1	2	H215	Office 215 Hallway	W3	Sheetrock	Grey-Cream and White	None	0	0	Negative
8020	1	2	H215	Office 215 Hallway	W4	Sheetrock	Grey-Cream and White	None	0	0	Negative
8020	1	2	H215	Office 215 Hallway	Ceiling	Spline ceiling	White	N/A	N/A	N/A	N/A
8020	1	2	H215	Office 215 Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	217	Classroom 217	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	217	Classroom 217	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	217	Classroom 217	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	217	Classroom 217	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	217	Classroom 217	Ceiling	Concrete	White				
8020	1	2	217	Classroom 217	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H27C	Second Floor Hallway from Stairwell J to Office 215	W1	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27C	Second Floor Hallway from Stairwell J to Office 215	W2	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27C	Second Floor Hallway from Stairwell J to Office 215	W3	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27C	Second Floor Hallway from Stairwell J to Office 215	W4	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H27C	Second Floor Hallway from Stairwell J to Office 215	Ceiling	Spline ceiling	White	None	0	N/A	N/A
8020	1	2	H27C	Second Floor Hallway from Stairwell J to Office 215	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H27	Second Floor Hallway from Stairwell J to Stairwell Q	W1	Concrete	Grey-Cream and White	None	0	0.05	Negative
8020	1	2	H27	Second Floor Hallway from Stairwell J to Stairwell Q	W2	Concrete	Grey-Cream and White	None	0	0.05	Negative
8020	1	2	H27	Second Floor Hallway from Stairwell J to Stairwell Q	W3	Concrete	Grey-Cream and White	None	0	0.03	Negative
8020	1	2	H27	Second Floor Hallway from Stairwell J to Stairwell Q	W4	Concrete	Grey-Cream and White	None	0	0.04	Negative
8020	1	2	H27	Second Floor Hallway from Stairwell J to Stairwell Q	Ceiling	Spline ceiling	White	N/A	N/A	0	Negative
8020	1	2	H27	Second Floor Hallway from Stairwell J to Stairwell Q	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	209	Classroom 209	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	209	Classroom 209	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	209	Classroom 209	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	209	Classroom 209	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	209	Classroom 209	Ceiling	Concrete	White				
8020	1	2	209	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H211	Second Floor Hallway from Storage Room 207A to Classroom 209	W1	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H211	Second Floor Hallway from Storage Room 207A to Classroom 209	W2	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H211	Second Floor Hallway from Storage Room 207A to Classroom 209	W3	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H211	Second Floor Hallway from Storage Room 207A to Classroom 209	W4	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H211	Second Floor Hallway from Storage Room 207A to Classroom 209	Ceiling	Spline ceiling	White	N/A	N/A	N/A	N/A

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,	Lead Safe Certification Assessment Report						
				Inspection Company: REPSG, Inc.	North East High School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	H211	Second Floor Hallway from Storage Room 207A to Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	H213	Second Floor Hallway from Storage Room 207A to Classroom 201	W1	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H213	Second Floor Hallway from Storage Room 207A to Classroom 201	W2	Concrete	Grey-Cream and White	None	0	0	Negative
8020	1	2	H213	Second Floor Hallway from Storage Room 207A to Classroom 201	W3	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H213	Second Floor Hallway from Storage Room 207A to Classroom 201	W4	Concrete	Grey-Cream and White	None	0	N/A	N/A
8020	1	2	H213	Second Floor Hallway from Storage Room 207A to Classroom 201	Ceiling	Spline	White	N/A	N/A	N/A	N/A
8020	1	2	H213	Second Floor Hallway from Storage Room 207A to Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	207	Classroom 207	W1	Concrete	Peach & White	None	0	0	Negative
8020	1	2	207	Classroom 207	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	207	Classroom 207	W3	Concrete	Peach & White	None	0	0	Negative
8020	1	2	207	Classroom 207	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	207	Classroom 207	Ceiling	Concrete	White	None	0	0.13	Negative
8020	1	2	207	Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8020	1	2	207A	Storage Room 207A	W1	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	207A	Storage Room 207A	W2	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	207A	Storage Room 207A	W3	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	207A	Storage Room 207A	W4	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	207A	Storage Room 207A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	207A	Storage Room 207A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8020	1	2	S29	Second Floor Stairwell A	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S29	Second Floor Stairwell A	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S29	Second Floor Stairwell A	W3	Glass	N/A	None	0	N/A	N/A
8020	1	2	S29	Second Floor Stairwell A	W4	Concrete	Beige	None	0	0.01	Negative
8020	1	2	S29	Second Floor Stairwell A	Ceiling	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S29	Second Floor Stairwell A	Floor	Concrete	N/A	None	0	N/A	N/A
8020	1	2	S29	Second Floor Stairwell A	Railing	Metal	Grey	Friction	20	0.09	Negative
8020	1	2	S29	Second Floor Stairwell A	Stairway	Metal	Grey	Chipping	3	0.1	Negative
8020	1	2	S28	Second Floor Stairwell B	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S28	Second Floor Stairwell B	W2	Concrete	Beige	None	0	0.06	Negative
8020	1	2	S28	Second Floor Stairwell B	W3	Glass	N/A	None	0	N/A	N/A
8020	1	2	S28	Second Floor Stairwell B	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S28	Second Floor Stairwell B	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	S28	Second Floor Stairwell B	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	S28	Second Floor Stairwell B	Railing	Metal	Grey	Flaking	20	0.1	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gourdine, Sherif Mohamed, James Arbuckle,		Lead Safe Certification Assessment Report					
				Inspection Company: REPSG, Inc.		North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	S28	Second Floor Stairwell B	Stairway	Metal	Grey	Friction	1	N/A	N/A
8020	1	2	S27	Second Floor Stairwell C	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S27	Second Floor Stairwell C	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S27	Second Floor Stairwell C	W3	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S27	Second Floor Stairwell C	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S27	Second Floor Stairwell C	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	S27	Second Floor Stairwell C	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	S27	Second Floor Stairwell C	Railing	Metal	Black	None	0	N/A	N/A
8020	1	2	S27	Second Floor Stairwell C	Stairway	Metal	Black	None	0	N/A	N/A
8020	1	2	S20	Second Floor Stairwell D	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S20	Second Floor Stairwell D	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S20	Second Floor Stairwell D	W3	Glass	Peach & White	None	0	N/A	N/A
8020	1	2	S20	Second Floor Stairwell D	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S20	Second Floor Stairwell D	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	S20	Second Floor Stairwell D	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	S20	Second Floor Stairwell D	Railing	Metal	Black	None	0	N/A	N/A
8020	1	2	S20	Second Floor Stairwell D	Stairway	Metal	Black	None	0	N/A	N/A
8020	1	2	S24	Second Floor Stairwell J	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S24	Second Floor Stairwell J	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S24	Second Floor Stairwell J	W3	Glass	N/A	None	0	N/A	N/A
8020	1	2	S24	Second Floor Stairwell J	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S24	Second Floor Stairwell J	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	S24	Second Floor Stairwell J	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	S24	Second Floor Stairwell J	Railing	Metal	Black	None	0	N/A	N/A
8020	1	2	S24	Second Floor Stairwell J	Stairway	Metal	Black	None	0	N/A	N/A
8020	1	2	S22	Second Floor Stairwell K	W1	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S22	Second Floor Stairwell K	W2	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S22	Second Floor Stairwell K	W3	Glass	N/A	None	0	N/A	N/A
8020	1	2	S22	Second Floor Stairwell K	W4	Concrete	Peach & White	None	0	N/A	N/A
8020	1	2	S22	Second Floor Stairwell K	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	S22	Second Floor Stairwell K	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	S22	Second Floor Stairwell K	Railing	Metal	Black	None	0	N/A	N/A
8020	1	2	S22	Second Floor Stairwell K	Stairway	Metal	Black	None	0	N/A	N/A
8020	1	2	S21	Second Floor Stairwell M	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S21	Second Floor Stairwell M	W2	Concrete	Beige	None	0	0.05	Negative
8020	1	2	S21	Second Floor Stairwell M	W3	Glass	N/A	None	0	N/A	N/A
8020	1	2	S21	Second Floor Stairwell M	W4	Concrete	Beige	None	0	0	Negative
8020	1	2	S21	Second Floor Stairwell M	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	S21	Second Floor Stairwell M	Floor	Concrete	Brown	None	0	N/A	N/A
8020	1	2	S21	Second Floor Stairwell M	Railing	Metal	Grey	Chipping	24	0.04	Negative

				Inspection Dates: 5/3/2021, 5/11-12/2021, 5/18-19/2021							
				Name of Inspector: Suzanne Shourds, Shaluanda Gouridine, Sherif Mohamed, James Arbuckle,							
				Inspection Company: REPSG, Inc.		Lead Safe Certification Assessment Report					
						North East High School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8020	1	2	S21	Second Floor Stairwell M	Stairway	Metal	Grey	Friction	3	0.08	Negative
8020	1	2	S25A	Second Floor Stairwell Q	W1	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S25A	Second Floor Stairwell Q	W2	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S25A	Second Floor Stairwell Q	W3	Glass	N/A	None	0	N/A	N/A
8020	1	2	S25A	Second Floor Stairwell Q	W4	Concrete	Beige	None	0	N/A	N/A
8020	1	2	S25A	Second Floor Stairwell Q	Ceiling	Concrete	White	None	0	N/A	N/A
8020	1	2	S25A	Second Floor Stairwell Q	Floor	Concrete	Grey	None	0	N/A	N/A
8020	1	2	S25A	Second Floor Stairwell Q	Railing	Metal	Grey	Friction	5	0.06	Negative
8020	1	2	S25A	Second Floor Stairwell Q	Stairway	Metal	Grey	None	0	N/A	N/A