

				Inspection Dates: 2/17/20-2/24/20			School District of Philadelphia					
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs, Inc.			Patterson Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	1	100	Main Office	yes	W1	Plaster	Blue	Cracking	5	5.4	Positive
1400	1	1	100	Main Office	yes	W2	Plaster	Blue	Flaking	3	3.2	Positive
1400	1	1	100	Main Office	yes	W3	Plaster	Blue	Flaking	10	1.6	Positive
1400	1	1	100	Main Office	yes	W4	Plaster	Blue	Cracking	1	4.1	Positive
1400	1	1	100	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	100	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	100A	Principal's Office	yes	W1	Plaster	Tan	Cracking	5	7.7	Positive
1400	1	1	100A	Principal's Office	yes	W2	Plaster	Tan	Chipping	1	5.4	Positive
1400	1	1	100A	Principal's Office	yes	W3	Plaster	Tan	Cracking	10	8.8	Positive
1400	1	1	100A	Principal's Office	yes	Radiator (W3)	Metal	Grey	Chipping	1	0.3	Negative
1400	1	1	100A	Principal's Office	yes	W4	Plaster	Tan	Cracking	10	3.5	Negative
1400	1	1	100A	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	100A	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	100B	Principal's Office Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	1	100B	Principal's Office Restroom	yes	W2	Plaster	Tan	Cracking	5	4.1	Positive
1400	1	1	100B	Principal's Office Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	1	100B	Principal's Office Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	1	100B	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	100B	Principal's Office Restroom	yes	Ceiling	Plaster	Tan	Flaking	20	0.9	Positive
1400	1	1	100C	Principal's Conference Room	yes	W1	Plaster	Blue	Chipping	1	2.1	Positive
1400	1	1	100C	Principal's Conference Room	yes	W2	Plaster	Blue	Cracking	5	3.3	Positive
1400	1	1	100C	Principal's Conference Room	yes	W3	Plaster	Blue	Cracking	1	6.1	Positive
1400	1	1	100C	Principal's Conference Room	yes	W4	Plaster	Blue	Chipping	5	5.4	Positive
1400	1	1	100C	Principal's Conference Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	100C	Principal's Conference Room	yes	Ceiling	Plaster	White	Flaking	1	8.8	Positive
1400	1	1	101	Classroom 101	yes	W1	Plaster	Tan	Flaking	5	11.1	Positive
1400	1	1	101	Classroom 101	yes	W2	Plaster	Tan	Flaking	5	5.7	Positive
1400	1	1	101	Classroom 101	yes	W3	Plaster	Tan	Cracking	10	9.8	Positive
1400	1	1	101	Classroom 101	yes	W4	Plaster	Tan	Cracking	5	6.7	Positive
1400	1	1	101	Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	101	Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	101A	Classroom 101 Storage	yes	W1	Plaster	Tan	Cracking	1	5.5	Positive
1400	1	1	101A	Classroom 101 Storage	yes	W2	Plaster	Tan	Cracking	1	8.1	Positive
1400	1	1	101A	Classroom 101 Storage	yes	W2	Wood	Tan	None	0	N/A	N/A
1400	1	1	101A	Classroom 101 Storage	yes	W3	Plaster	Tan	Partially Inaccessible	N/A	N/A	N/A
1400	1	1	101A	Classroom 101 Storage	yes	W4	Plaster	Tan	Cracking	1	4.4	Positive
1400	1	1	101A	Classroom 101 Storage	yes	W4	Wood	Tan	None	0	N/A	N/A
1400	1	1	101A	Classroom 101 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	101A	Classroom 101 Storage	yes	Ceiling	Plaster	Tan	Cracking	10	6.7	Positive
1400	1	1	101B	Classroom 101 Restroom	yes	W1	Plaster	Tan	Cracking	10	4.1	Positive
1400	1	1	101B	Classroom 101 Restroom	yes	W2	Plaster	Tan	Partially Inaccessible	0	N/A	N/A
1400	1	1	101B	Classroom 101 Restroom	yes	W3	Plaster	Tan	Cracking	10	6.9	Positive
1400	1	1	101B	Classroom 101 Restroom	yes	W4	Plaster	Tan	Cracking	1	6.7	Positive
1400	1	1	101B	Classroom 101 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20				School District of Philadelphia				
				Name of Inspector: Michael Barth				Lead Safe Certification Assessment Report				
				Inspection Company: Criterion Labs, Inc.				Patterson Elementary School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	1	101B	Classroom 101 Restroom	yes	Ceiling	Plaster	Tan	Flaking	10	3.2	Positive
1400	1	1	101C	Staff Restroom outside Classroom 101	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	101C	Staff Restroom outside Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	101C	Staff Restroom outside Classroom 101	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	101C	Staff Restroom outside Classroom 101	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	101C	Staff Restroom outside Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	101C	Staff Restroom outside Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	102	Classroom 102	yes	W1	Plaster	Tan	Cracking	20	4.1	Positive
1400	1	1	102	Classroom 102	yes	W2	Plaster	Tan	Cracking	10	8.7	Positive
1400	1	1	102	Classroom 102	yes	W3	Plaster	Tan	Flaking	20	6.1	Positive
1400	1	1	102	Classroom 102	yes	W4	Plaster	Tan	Flaking	5	3.2	Positive
1400	1	1	102	Classroom 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	102	Classroom 102	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	102A	Classroom 102 Restroom	yes	W1	Plaster	Tan	Chipping	1	6.7	Positive
1400	1	1	102A	Classroom 102 Restroom	yes	W2	Plaster	Tan	Flaking	1	4.1	Positive
1400	1	1	102A	Classroom 102 Restroom	yes	W3	Plaster	Tan	Cracking	1	5.2	Positive
1400	1	1	102A	Classroom 102 Restroom	yes	W4	Plaster	Tan	Chipping	1	2.6	Positive
1400	1	1	102A	Classroom 102 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	102A	Classroom 102 Restroom	yes	Ceiling	Plaster	Tan	Cracking	3	9.8	Positive
1400	1	1	102B	Classroom 102 Storage	yes	W1	Plaster	Tan	Chipping	2	5.4	Positive
1400	1	1	102B	Classroom 102 Storage	yes	W2	Plaster	Tan	Chipping	5	7.8	Positive
1400	1	1	102B	Classroom 102 Storage	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	1	102B	Classroom 102 Storage	yes	W4	Plaster	Tan	Chipping	1	4.1	Positive
1400	1	1	102B	Classroom 102 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	102B	Classroom 102 Storage	yes	Ceiling	Plaster	Tan	Flaking	3	6.7	Positive
1400	1	1	103	Classroom 103	yes	W1	Plaster	White	Chipping	5	2.1	Positive
1400	1	1	103	Classroom 103	yes	W2	Wood	Brown	Friction	5	0.03	Negative
1400	1	1	103	Classroom 103	yes	W2	Plaster	White	Cracking	3	3.2	Positive
1400	1	1	103	Classroom 103	yes	W2	Wood	Brown	Friction	5	0.1	Negative
1400	1	1	103	Classroom 103	yes	W3	Plaster	White	Chipping	10	1.2	Positive
1400	1	1	103	Classroom 103	yes	W3	Wood	Brown	None	0	N/A	N/A
1400	1	1	103	Classroom 103	yes	W4	Plaster	White	Chipping	1	4.1	Positive
1400	1	1	103	Classroom 103	yes	W4	Wood	Brown	Friction	1	0.1	Negative
1400	1	1	103	Classroom 103	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	103	Classroom 103	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	103A	Classroom 103 Storage	yes	W1	Plaster	Tan	Flaking	1	8.8	Positive
1400	1	1	103A	Classroom 103 Storage	yes	W2	Plaster	Tan	Chipping	3	7.4	Positive
1400	1	1	103A	Classroom 103 Storage	yes	W3	Plaster	Tan	Chipping	3	6.5	Positive
1400	1	1	103A	Classroom 103 Storage	yes	W4	Plaster	Tan	Flaking	6	8.4	Positive
1400	1	1	103A	Classroom 103 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	103A	Classroom 103 Storage	yes	Ceiling	Plaster	Tan	Flaking	1	9.8	Positive
1400	1	1	103B	Classroom 103 Restroom	yes	W1	Plaster	Tan	Alligating	6	10.1	Positive
1400	1	1	103B	Classroom 103 Restroom	yes	W2	Plaster	Tan	Cracking	1	5.4	Positive
1400	1	1	103B	Classroom 103 Restroom	yes	Radiator (W2)	Metal	Tan	Flaking	1	0.02	Negative
1400	1	1	103B	Classroom 103 Restroom	yes	W3	Plaster	Tan	Alligating	6	8.7	Positive

				Inspection Dates: 2/17/20-2/24/20				School District of Philadelphia					
				Name of Inspector: Michael Barth				Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs, Inc.				Patterson Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1400	1	1	103B	Classroom 103 Restroom	yes	W4	Plaster	Tan	Flaking	3	6.6	Positive	
					yes	W4	Wood	Black	None	0	N/A	N/A	
1400	1	1	103B	Classroom 103 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	1	103B	Classroom 103 Restroom	yes	Ceiling	Plaster	Tan	Flaking	1	1.2	Positive	
1400	1	1	H11	Hallway at Main Office	yes	W1	Metal	Grey	Chipping	1	0.01	Negative	
1400	1	1	H11	Hallway at Main Office	yes	W2	Plaster	Tan	Cracking	5	4.1	Positive	
1400	1	1	H11	Hallway at Main Office	yes	W3	Plaster	Tan	Cracking	3	5.5	Positive	
1400	1	1	H11	Hallway at Main Office	yes	W4	Plaster	Tan	Cracking	5	3.2	Positive	
1400	1	1	H11	Hallway at Main Office	yes	Floor	Concrete	Black	Friction	10	0.3	Negative	
1400	1	1	H11	Hallway at Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	1	104	Classroom 104	yes	W1	Plaster	Tan	Cracking	20	12.1	Positive	
1400	1	1	104	Classroom 104	yes	Door Frame (W1)	Wood	Tan	Flaking	5	3.4	Positive	
1400	1	1	104	Classroom 104	yes	W2	Plaster	Tan	Cracking	3	10.9	Positive	
1400	1	1	104	Classroom 104	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A	
1400	1	1	104	Classroom 104	yes	W3	Plaster	Tan	Cracking	20	11.4	Positive	
1400	1	1	104	Classroom 104	yes	W3	Plaster	White	Chipping	1	5.5	Positive	
1400	1	1	104	Classroom 104	yes	Radiator (W3)	Metal	Grey	Chipping	1	0.3	Negative	
1400	1	1	104	Classroom 104	yes	Vertical Fiberglass Pipe (W3)	Plastic	Tan	None	0	N/A	N/A	
1400	1	1	104	Classroom 104	yes	W4	Plaster	Tan	Chipping	10	6.9	Positive	
1400	1	1	104	Classroom 104	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	1	104	Classroom 104	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	1	104B	Classroom 104 Storage	yes	W1	Plaster	Tan	Cracking	1	10.1	Positive	
1400	1	1	104B	Classroom 104 Storage	yes	W2	Plaster	Tan	Chipping	1	5.5	Positive	
1400	1	1	104B	Classroom 104 Storage	yes	W3	Plaster	Tan	None	0	N/A	N/A	
1400	1	1	104B	Classroom 104 Storage	yes	W4	Plaster	Tan	Cracking	1	6.7	Positive	
1400	1	1	104B	Classroom 104 Storage	yes	Floor	Wood	N/A	N/A	0	N/A	N/A	
1400	1	1	104B	Classroom 104 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A	
1400	1	1	104A	Girl's Restroom next to Classroom 104	yes	W1	Plaster	Tan	None	0	N/A	N/A	
1400	1	1	104A	Girl's Restroom next to Classroom 104	yes	W2	Plaster	Tan	Chipping	2	4.1	Positive	
1400	1	1	104A	Girl's Restroom next to Classroom 104	yes	W3	Plaster	Tan	Moisture Damage	3	6.7	Positive	
1400	1	1	104A	Girl's Restroom next to Classroom 104	yes	Radiator (W3)	Metal	Black	None	0	0.2	Negative	
1400	1	1	104A	Girl's Restroom next to Classroom 104	yes	W4	Plaster	Tan	Spalling	1	5.1	Positive	
1400	1	1	104A	Girl's Restroom next to Classroom 104	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	1	104A	Girl's Restroom next to Classroom 104	yes	Ceiling	Plaster	Tan	Moisture Damage	6	3.7	Positive	
1400	1	1	104A	Girl's Restroom next to Classroom 104	yes	Horizontal Pipe (Ceiling)	Metal	Tan	Chipping	2	0.9	Positive	
1400	1	1	105	Classroom 105	yes	W1	Plaster	Tan	Cracking/Flaking	25	15.1	Positive	
1400	1	1	105	Classroom 105	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A	
1400	1	1	105	Classroom 105	yes	W2	Plaster	Tan	Cracking	5	9.8	Positive	
1400	1	1	105	Classroom 105	yes	W3	Plaster	Tan	Cracking	25	11.2	Positive	
1400	1	1	105	Classroom 105	yes	Radiator (W3)	Metal	Grey	Chipping	3	0.4	Negative	
1400	1	1	105	Classroom 105	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	1	105	Classroom 105	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	105	Classroom 105	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	105A	Classroom 105 Storage	yes	W1	Plaster	Tan	Cracking	1	5.5	Positive
1400	1	1	105A	Classroom 105 Storage	yes	W2	Plaster	Tan	Cracking	2	10.1	Positive
1400	1	1	105A	Classroom 105 Storage	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	1	105A	Classroom 105 Storage	yes	W4	Plaster	Tan	Cracking	5	8.9	Positive
1400	1	1	105A	Classroom 105 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	1	105A	Classroom 105 Storage	yes	Ceiling	Plaster	Tan	Flaking	1	15.4	Positive
1400	1	1	106	Classroom 106	yes	W1	Plaster	Tan	Cracking	25	13.4	Positive
1400	1	1	106	Classroom 106	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	1	106	Classroom 106	yes	W3	Plaster	Tan	Cracking	15	14.1	Positive
1400	1	1	106	Classroom 106	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	1	106	Classroom 106	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	1	106	Classroom 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	106A	Classroom 106 Storage	yes	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	1	106A	Classroom 106 Storage	yes	W2	Plaster	Tan	None	0	N/A	N/A
1400	1	1	106A	Classroom 106 Storage	yes	W3	Plaster	Tan	Chipping	1	5.4	Positive
1400	1	1	106A	Classroom 106 Storage	yes	W4	Plaster	Tan	Chipping	3	3.6	Positive
1400	1	1	106A	Classroom 106 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	1	106A	Classroom 106 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	1	107	Classroom 107	yes	W1	Plaster	Blue	Cracking	3	3.1	Positive
1400	1	1	107	Classroom 107	yes	W2	Plaster	Blue	Chipping	3	2.2	Positive
1400	1	1	107	Classroom 107	yes	W2	Wood	Blue	None	N/A	N/A	N/A
1400	1	1	107	Classroom 107	yes	W3	Plaster	Blue	Chipping	5	5.5	Positive
1400	1	1	107	Classroom 107	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	1	107	Classroom 107	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	1	107	Classroom 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	107B	Classroom 107 Storage	yes	W1	Plaster	Tan	Chipping	1	4.7	Positive
1400	1	1	107B	Classroom 107 Storage	yes	W2	Plaster	Tan	Chipping	1	8.8	Positive
1400	1	1	107B	Classroom 107 Storage	yes	W3	Plaster	Tan	Partially Inaccessible	N/A	N/A	N/A
1400	1	1	107B	Classroom 107 Storage	yes	W4	Plaster	Tan	Chipping	1	10.1	Positive
1400	1	1	107B	Classroom 107 Storage	yes	Floor	Wood	N/A	None	N/A	N/A	N/A
1400	1	1	107B	Classroom 107 Storage	yes	Ceiling	Plaster	Tan	Flaking	1	8.9	Positive
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	W2	Plaster	Tan	Chipping	1	10.1	Positive
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	W2	Metal	Black	None	0	N/A	N/A
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	W3	Plaster	Tan	Cracking	1	5.4	Positive
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	Vertical Pipe (W3)	Metal	White	Chipping	1	0.2	Negative
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	W4	Plaster	Tan	Chipping	5	1.3	Positive
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	Vertical Pipe (W4)	Metal	White	Chipping	3	0.3	Negative
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	107A	Boy's Restroom next to Classroom 107	yes	Ceiling	Plaster	Tan	Moisture Damage	10	5.6	Positive
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	W1	Plaster	Tan	Cracking	10	8.9	Positive

				Inspection Dates: 2/17/20-2/24/20				School District of Philadelphia				
				Name of Inspector: Michael Barth				Lead Safe Certification Assessment Report				
				Inspection Company: Criterion Labs, Inc.				Patterson Elementary School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	W3	Plaster	Tan	Chipping	5	10.5	Positive
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	W3	Plaster	White	Cracking	15	12.4	Positive
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	W3	Plaster	Blue	Cracking	1	4.5	Positive
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	Door (W3)	Wood	Purple	Chipping	6	8.4	Positive
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	Floor	Concrete	Black	Friction	10	0.2	Negative
1400	1	1	H12	Hallway at Classrooms 105 to 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Door (W1)	Wood	Purple	Chipping	3	2.1	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Moulding (W1)	Wood	Tan	Chipping	1	6.4	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	W1	Plaster	Tan	Moisture Damage	6	10.1	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Stair Riser (W2)	Wood	Purple	Chipping	1	2.3	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Moulding (W2)	Wood	Tan	Cracking	2	4.1	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	W2	Plaster	Tan	Moisture Damage	15	12.2	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Door (W3)	Wood	Purple	Flaking	6	3.2	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Moulding (W3)	Wood	Tan	None	0	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Near 105	yes	W3	Plaster	Tan	Moisture Damage	5	11.2	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Stair Riser (W4)	Wood	Purple	Chipping	1	3.1	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Moulding (W4)	Wood	Tan	None	0	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Near 105	yes	W4	Plaster	Tan	Cracking	1	13.2	Positive
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Near 105	yes	Ceiling	Plaster	White	Moisture Damage	5	10.1	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W1	Wood	Purple	Chipping	3	2.1	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W1	Wood	Tan	Chipping	1	3.2	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W2	Wood	Purple	Chipping	1	1.2	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W2	Wood	Tan	Cracking	1	3.4	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W2	Plaster	Tan	Cracking	1	8.9	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W3	Wood	Purple	Flaking	10	5.4	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W3	Wood	Tan	Chipping	1	1.3	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W4	Wood	Purple	None	0	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W4	Wood	Tan	Cracking	1	1.4	Positive
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12A	Auditorium Foyer Between 106-109	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	1	H12C	Storage in Hallway by Auditorium Entrance	no	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H12C	Storage in Hallway by Auditorium Entrance	no	W2	Plaster	Tan	Cracking	1	3.2	Positive
1400	1	1	H12C	Storage in Hallway by Auditorium Entrance	no	W3	Plaster	Tan	Cracking	1	4.6	Positive
1400	1	1	H12C	Storage in Hallway by Auditorium Entrance	no	W4	Plaster	Tan	Cracking	1	7.6	Positive
1400	1	1	H12C	Storage in Hallway by Auditorium Entrance	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12C	Storage in Hallway by Auditorium Entrance	no	Ceiling	Plaster	Tan	Cracking	10	5.4	Positive
1400	1	1	H12D	Custodial Closet in Hallway by Auditorium Entrance	no	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H12D	Custodial Closet in Hallway by Auditorium Entrance	no	W2	Plaster	Tan	Cracking	1	4.7	Positive
1400	1	1	H12D	Custodial Closet in Hallway by Auditorium Entrance	no	W3	Plaster	Tan	Cracking	1	6.6	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	1	H12D	Custodial Closet in Hallway by Auditorium Entrance	no	W4	Plaster	Tan	Cracking	1	6.7	Positive
1400	1	1	H12D	Custodial Closet in Hallway by Auditorium Entrance	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12D	Custodial Closet in Hallway by Auditorium Entrance	no	Ceiling	Plaster	Tan	Cracking	5	8.9	Positive
1400	1	1	108	Classroom 108	yes	W1	Plaster	Tan	Chipping	15	12.1	Positive
1400	1	1	108	Classroom 108	yes	Vertical Pipe (W1)	Metal	Tan	None	N/A	N/A	N/A
1400	1	1	108	Classroom 108	yes	W2	Plaster	Tan	Chipping	5	10.3	Positive
1400	1	1	108	Classroom 108	yes	W3	Plaster	Tan	Cracking	10	10.1	Positive
1400	1	1	108	Classroom 108	yes	Radiator (W3)	Metal	Grey	Chipping	1	0.4	Negative
1400	1	1	108	Classroom 108	yes	W4	Plaster	Tan	Cracking	15	14.7	Positive
1400	1	1	108	Classroom 108	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	108	Classroom 108	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	108B	Classroom 108 Storage	yes	W1	Plaster	Tan	Flaking	1	3.4	Positive
1400	1	1	108B	Classroom 108 Storage	yes	W2	Plaster	Tan	Chipping	3	4.5	Positive
1400	1	1	108B	Classroom 108 Storage	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	1	108B	Classroom 108 Storage	yes	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	1	108B	Classroom 108 Storage	yes	Vertical Pipe (W4)	Metal	White	Chipping	2	0.9	Positive
1400	1	1	108B	Classroom 108 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	108B	Classroom 108 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	1	108A	Classroom 108 Restroom	yes	W1	Plaster	Tan	Cracking	1	7.8	Positive
1400	1	1	108A	Classroom 108 Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1400	1	1	108A	Classroom 108 Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	1	108A	Classroom 108 Restroom	yes	W3	Metal	Black	None	0	N/A	N/A
1400	1	1	108A	Classroom 108 Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	1	108A	Classroom 108 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	108A	Classroom 108 Restroom	yes	Ceiling	Plaster	Tan	Cracking	10	6.7	Positive
1400	1	1	109	Classroom 109	yes	W1	Plaster	Tan	Flaking	15	11.1	Positive
1400	1	1	109	Classroom 109	yes	W2	Plaster	Tan	Cracking	10	5.4	Positive
1400	1	1	109	Classroom 109	yes	W3	Plaster	Tan	Cracking	5	3.2	Positive
1400	1	1	109	Classroom 109	yes	W4	Plaster	Tan	Cracking	15	5.5	Positive
1400	1	1	109	Classroom 109	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	109	Classroom 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	109B	Classroom 109 Storage	yes	W1	Plaster	White	Chipping	3	4.3	Positive
1400	1	1	109B	Classroom 109 Storage	yes	W2	Plaster	White	Chipping	10	2.1	Positive
1400	1	1	109B	Classroom 109 Storage	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A
1400	1	1	109B	Classroom 109 Storage	yes	W4	Plaster	White	Chipping	10	5.5	Positive
						W4	Wood	White	None	0	N/A	N/A
1400	1	1	109B	Classroom 109 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	109B	Classroom 109 Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	1	109A	Classroom 109 Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	1	109A	Classroom 109 Restroom	yes	W2	Plaster	Tan	Cracking	1	10.2	Positive
1400	1	1	109A	Classroom 109 Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	1	109A	Classroom 109 Restroom	yes	W4	Plaster	Tan	Cracking	1	15.4	Positive
1400	1	1	109A	Classroom 109 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20			School District of Philadelphia					
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs, Inc.			Patterson Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	1	109A	Classroom 109 Restroom	yes	Ceiling	Plaster	Tan	Flaking	5	9.8	Positive
1400	1	1	110	Classroom 110	yes	W1	Plaster	Yellow	Cracking	3	5.6	Positive
1400	1	1	110	Classroom 110	yes	W1	Plaster	White	Chipping	1	4.9	
1400	1	1	110	Classroom 110	yes	W2	Plaster	Yellow	Chipping	5	7.6	Positive
1400	1	1	110	Classroom 110	yes	W3	Plaster	Yellow	Chipping	5	8.8	Positive
1400	1	1	110	Classroom 110	yes	W4	Plaster	Yellow	Chipping	5	10.3	Positive
1400	1	1	110	Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	110	Classroom 110	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	110B	Classroom 110 Storage	yes	W1	Plaster	Tan	Cracking	1	9.6	Positive
1400	1	1	110B	Classroom 110 Storage	yes	W2	Plaster	Tan	Flaking	5	8.6	Positive
1400	1	1	110B	Classroom 110 Storage	yes	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A
1400	1	1	110B	Classroom 110 Storage	yes	W4	Plaster	Tan	Flaking	5	16.3	Positive
1400	1	1	110B	Classroom 110 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	110B	Classroom 110 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	1	110A	Classroom 110 Restroom	yes	W1	Plaster	Tan	Cracking	1	11.5	Positive
1400	1	1	110A	Classroom 110 Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1400	1	1	110A	Classroom 110 Restroom	yes	W3	Plaster	Tan	Cracking	3	10.3	Positive
1400	1	1	110A	Classroom 110 Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	1	110A	Classroom 110 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	110A	Classroom 110 Restroom	yes	Ceiling	Plaster	Tan	Flaking	5	5.7	Positive
1400	1	1	111	Classroom 111	yes	W1	Plaster	Tan	Cracking	3	8.8	Positive
1400	1	1	111	Classroom 111	yes	W2	Plaster	Tan	Cracking	1	6.7	Positive
1400	1	1	111	Classroom 111	yes	Moulding (W2)	Wood	Tan	Alligating	3	14.1	Positive
1400	1	1	111	Classroom 111	yes	W3	Plaster	Tan	Cracking	5	3.4	Positive
1400	1	1	111	Classroom 111	yes	W4	Plaster	Tan	Cracking	5	6.4	Positive
1400	1	1	111	Classroom 111	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	111	Classroom 111	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	111F	Classroom 111 Storage	No Access	W1	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	1	111F	Classroom 111 Storage	No Access	W2	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	1	111F	Classroom 111 Storage	No Access	W3	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	1	111F	Classroom 111 Storage	No Access	W4	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	1	111F	Classroom 111 Storage	No Access	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	1	111F	Classroom 111 Storage	No Access	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	1	111A	Auditorium	yes	W1	Plaster	Tan	Flaking	20	8.9	Positive
1400	1	1	111A	Auditorium	yes	W1	Wood	Tan	Chipping	1	0.4	Negative
1400	1	1	111A	Auditorium	yes	W1	Wood	Purple	Flaking	15	5.2	Positive
1400	1	1	111A	Auditorium	yes	W1	Wood	White	None	0	N/A	N/A
1400	1	1	111A	Auditorium	yes	W2	Plaster	Tan	Moisture Damage	20	6.9	Positive
1400	1	1	111A	Auditorium	yes	W2	Wood	Tan	Cracking	5	0.3	Negative
1400	1	1	111A	Auditorium	yes	W2	Wood	Purple	Flaking	15	1.4	Positive
1400	1	1	111A	Auditorium	yes	W2	Wood	White	None	0	N/A	N/A
1400	1	1	111A	Auditorium	yes	W2	Metal	Purple	None	0	N/A	N/A
1400	1	1	111A	Auditorium	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	111A	Auditorium	yes	W4	Plaster	Tan	Cracking	10	15.4	Positive
1400	1	1	111A	Auditorium	yes	W4	Wood	Tan	Chipping	5	0.4	Negative

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	1	111A	Auditorium	yes	W4	Wood	Purple	Chipping	5	1.5	Positive
1400	1	1	111A	Auditorium	yes	W4	Wood	White	None	0	N/A	N/A
1400	1	1	111A	Auditorium	yes	W4	Metal	Purple	None	0	N/A	N/A
1400	1	1	111A	Auditorium	yes	Floor	Wood	N/A	N/A	0	N/A	N/A
1400	1	1	111A	Auditorium	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	Door (W1)	Metal	Grey	Friction	3	0.2	Negative
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	Door Frame (W1)	Metal	Green	None	0	N/A	N/A
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	W2	Plaster	Tan	Chipping	5	10.1	Positive
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	W2	Brick	N/A	None	0	N/A	N/A
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	Cove Base (W2)	Brick	Black	None	0	N/A	N/A
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	W3	Plaster	Tan	Cracking	1	14.3	Positive
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	W3	Brick	N/A	None	0	N/A	N/A
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	Cove Base (W3)	Brick	Black	Chipping	1	3.2	Positive
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	W4	Plaster	Tan	Cracking	10	6.9	Positive
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	W4	Brick	N/A	None	0	N/A	N/A
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	W4	Brick	Black	Chipping	1	3.4	Positive
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	Floor	Concrete	Black	Friction	10	0.2	Negative
1400	1	1	H13	Hallway at Classrooms 108 to 111	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12D	Utility Closet in Hallway to the left of Auditorium Entrance	no	W1	Plaster	White	Moisture Damage	2	12.4	Positive
1400	1	1	H12D	Utility Closet in Hallway to the left of Auditorium Entrance	no	W2	Plaster	White	Cracking	2	9.3	Positive
1400	1	1	H12D	Utility Closet in Hallway to the left of Auditorium Entrance	no	W3	Plaster	White	Chipping	1	10.5	Positive
1400	1	1	H12D	Utility Closet in Hallway to the left of Auditorium Entrance	no	W4	Plaster	White	Moisture Damage	10	10.3	Positive
1400	1	1	H12D	Utility Closet in Hallway to the left of Auditorium Entrance	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12D	Utility Closet in Hallway to the left of Auditorium Entrance	no	Ceiling	Plaster	White	Moisture Damage	5	16.8	Positive
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	W1	Plaster	Tan	Moisture Damage	5	15.4	Positive
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	Door Frame (W1)	Metal	Red	Chipping	1	3.2	Positive
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	W2	Plaster	Tan	Moisture Damage/Cracking	10	9.8	Positive
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	Door Frame (W2)	Metal	Red	Chipping	2	4.4	Positive
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	W3	Plaster	Tan	Moisture Damage	5	10.1	Positive
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	Door Frame (W4)	Metal	Red	Chipping	3	1.2	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	111B	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	no	Ceiling	Plaster	Tan	Moisture Damage	5	8.4	Positive
1400	1	1	H12C	Wardrobe Room in the Hallway to the right of Auditorium Entrance	no	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H12C	Wardrobe Room in the Hallway to the right of Auditorium Entrance	no	W2	Plaster	Tan	Cracking	1	11.5	Positive
1400	1	1	H12C	Wardrobe Room in the Hallway to the right of Auditorium Entrance	no	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H12C	Wardrobe Room in the Hallway to the right of Auditorium Entrance	no	Electrical Box (W3)	Metal	Grey	None	0	N/A	N/A
1400	1	1	H12C	Wardrobe Room in the Hallway to the right of Auditorium Entrance	no	Electrical Conduit (W3)	Metal	White	None	0	N/A	N/A
1400	1	1	H12C	Wardrobe Room in the Hallway to the right of Auditorium Entrance	no	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	1	H12C	Wardrobe Room in the Hallway to the right of Auditorium Entrance	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	H12C	Wardrobe Room in the Hallway to the right of Auditorium Entrance	no	Ceiling	Plaster	Tan	Cracking	3	10.2	Positive
1400	1	1	111C	Stage	yes	Stage (W1)	Wood	Purple	Chipping	10	2.1	Positive
1400	1	1	111C	Stage	yes	Moulding (W1)	Wood	Tan	Chipping	15	0.3	Negative
1400	1	1	111C	Stage	yes	Radiator (W1)	Metal	Purple	Chipping	1	0.1	Negative
1400	1	1	111C	Stage	yes	Radiator (W1)	Metal	Tan	Chipping	5	0.2	Negative
1400	1	1	111C	Stage	yes	W2	Plaster	White	Moisture Damage	2	10.1	Positive
1400	1	1	111C	Stage	yes	W2	Wood	Tan	Chipping	1	0.2	Negative
1400	1	1	111C	Stage	yes	W2	Wood	Purple	Chipping	1	0.4	Negative
1400	1	1	111C	Stage	yes	W2	Metal	Tan	Chipping	1	0.01	Negative
1400	1	1	111C	Stage	yes	W3	Plaster	White	Chipping	1	5.7	Positive
1400	1	1	111C	Stage	yes	W3	Plaster	Black	None	0	N/A	N/A
1400	1	1	111C	Stage	yes	W3	Wood	Purple	Friction	5	0.3	Negative
1400	1	1	111C	Stage	yes	W4	Plaster	White	Cracking	2	10.1	Positive
1400	1	1	111C	Stage	yes	W4	Wood	Tan	Chipping	1	0.4	Negative
1400	1	1	111C	Stage	yes	W4	Wood	Purple	Cracking	1	0.03	Negative
1400	1	1	111C	Stage	yes	W4	Metal	Tan	Chipping	1	0.1	Negative
1400	1	1	111C	Stage	yes	Floor	Wood	N/A	N/A	0	N/A	N/A
1400	1	1	111C	Stage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	1	111D	Storage to the Right of Stage	no	W1	Plaster	Tan	Cracking	1	10.3	Positive
1400	1	1	111D	Storage to the Right of Stage	no	W1	Wood	Tan	Chipping	5	0.2	Negative
1400	1	1	111D	Storage to the Right of Stage	no	W1	Metal	Tan	Chipping	5	0.41	Negative
1400	1	1	111D	Storage to the Right of Stage	no	W2	Plaster	Tan	Cracking	2	8.8	Positive
1400	1	1	111D	Storage to the Right of Stage	no	W2	Metal	Grey	Chipping	3	0.5	Negative
1400	1	1	111D	Storage to the Right of Stage	no	W3	Plaster	Tan	Chipping	15	6.7	Positive
1400	1	1	111D	Storage to the Right of Stage	no	W3	Wood	Brown	Chipping	3	0.2	Negative
1400	1	1	111D	Storage to the Right of Stage	no	W4	Plaster	Tan	Cracking	5	4.1	Positive
1400	1	1	111D	Storage to the Right of Stage	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	111D	Storage to the Right of Stage	no	Ceiling	Plaster	Tan	Moisture Damage	10	8.8	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	1	111D	Storage to the Right of Stage	no	Ceiling	Metal	Brown	Chipping	3	0.1	Negative
1400	1	1	111E	Storage to the Left of Stage	no	W1	Plaster	Tan	Cracking	1	14.1	Positive
1400	1	1	111E	Storage to the Left of Stage	no	W1	Wood	Tan	Cracking	3	0.2	Negative
1400	1	1	111E	Storage to the Left of Stage	no	W2	Plaster	Tan	None	0	N/A	N/A
1400	1	1	111E	Storage to the Left of Stage	no	W3	Plaster	Tan	Cracking	1	12.1	Positive
1400	1	1	111E	Storage to the Left of Stage	no	W4	Plaster	Tan	Cracking	1	8.9	Positive
1400	1	1	111E	Storage to the Left of Stage	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	1	111E	Storage to the Left of Stage	no	Ceiling	Plaster	Tan	Flaking	10	6.7	Positive
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	Door (W1)	Metal	Grey	Friction	1	0.2	Negative
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	W1	Plaster	White	Cracking	1	5.4	Positive
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	Stairs (W1)	Concrete	Grey	Friction	5	4.8	Positive
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	W2	Plaster	Tan	None	0	N/A	N/A
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	W3	Metal	Grey	Friction	1	0.4	Negative
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	Stairs (W3)	Concrete	Grey	Friction	5	3.5	Positive
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	W4	Plaster	Tan	Cracking	5	10.4	Positive
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	Floor	Concrete	Grey	Friction	3	0.2	Negative
1400	1	1	S11	Stairwell on the Girl's Restroom Side	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	Door (W1)	Metal	Grey	Friction	1	0.2	Negative
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	W1	Plaster	Tan	Cracking	1	5.6	Positive
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	Stairs (W1)	Concrete	Grey	Friction	5	2.1	Positive
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	W2	Plaster	Tan	Cracking	3	6.9	Positive
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	Door (W3)	Metal	Grey	Friction	1	0.3	Negative
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	Stairs (W3)	Concrete	Grey	Friction	5	3.2	Negative
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	W4	Plaster	Tan	Chipping	1	10.1	Positive
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	Floor	Concrete	Black	Friction	10	0.1	Negative
1400	1	1	S12	Stairwell on the Boy's Restroom Side	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	2	200	Classroom 200	yes	W1	Plaster	Yellow	Chipping	5	11.3	Positive
1400	1	2	200	Classroom 200	yes	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	2	200	Classroom 200	yes	Vertical Pipe (W1)	Metal	White	Chipping	2	0.03	Positive
1400	1	2	200	Classroom 200	yes	W2	Plaster	Yellow	Chipping	5	5.4	Positive
1400	1	2	200	Classroom 200	yes	W2	Plaster	Tan	Chipping	2	7.6	Positive
1400	1	2	200	Classroom 200	yes	W3	Plaster	Yellow	Cracking	10	2.5	Positive
1400	1	2	200	Classroom 200	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	2	200	Classroom 200	yes	W3	Plaster	White	Cracking	3	8.9	Positive
1400	1	2	200	Classroom 200	yes	Radiator (W3)	Metal	Grey	Chipping	2	0.2	Positive
1400	1	2	200	Classroom 200	yes	W4	Plaster	Yellow	Chipping	5	1.9	Positive
1400	1	2	200	Classroom 200	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	200	Classroom 200	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	2	200B	Classroom 200 Storage	yes	W1	Plaster	Yellow	Chipping	1	14.3	Positive
1400	1	2	200B	Classroom 200 Storage	yes	W1	Plaster	Tan	Cracking	3	9.8	Positive
1400	1	2	200B	Classroom 200 Storage	yes	Vertical Pipe (W1)	Metal	White	Chipping	3	0.4	Positive
1400	1	2	200B	Classroom 200 Storage	yes	W2	Plaster	Tan	Cracking	5	10.1	Positive
1400	1	2	200B	Classroom 200 Storage	yes	W3	Plaster	Tan	Flaking/Cracking	5	5.4	Positive
1400	1	2	200B	Classroom 200 Storage	yes	W4	Plaster	Tan	Partially Inaccessible	0	3.1	Positive
1400	1	2	200B	Classroom 200 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	200B	Classroom 200 Storage	yes	Ceiling	Plaster	Tan	Flaking	5	10.5	Positive
1400	1	2	200B	Classroom 200 Storage	yes	Piping (Ceiling)	Metal	Tan	None	0	N/A	N/A
1400	1	2	200A	Office at the end of the Hallway by Classroom 200	yes	W1	Plaster	Tan	Cracking	3	4.1	Positive
1400	1	2	200A	Office at the end of the Hallway by Classroom 200	yes	W2	Plaster	Tan	Cracking	10	5.5	Positive
1400	1	2	200A	Office at the end of the Hallway by Classroom 200	yes	W3	Plaster	Tan	Flaking	5	3.7	Positive
1400	1	2	200A	Office at the end of the Hallway by Classroom 200	yes	W4	Plaster	Tan	Flaking	3	6.5	Positive
1400	1	2	200A	Office at the end of the Hallway by Classroom 200	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	200A	Office at the end of the Hallway by Classroom 200	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	201	Classroom 201	yes	W1	Plaster	Blue	Chipping	1	4.1	Positive
1400	1	2	201	Classroom 201	yes	W1	Plaster	Tan	Cracking	3	8.7	Positive
1400	1	2	201	Classroom 201	yes	W2	Plaster	Blue	Chipping	1	9.8	Positive
1400	1	2	201	Classroom 201	yes	W3	Plaster	Blue	Chipping	3	5.4	Positive
1400	1	2	201	Classroom 201	yes	W3	Plaster	Tan	Cracking	10	6.4	Positive
1400	1	2	201	Classroom 201	yes	Radiator (W3)	Metal	Grey	Chipping	3	0.1	Negative
1400	1	2	201	Classroom 201	yes	W4	Plaster	Blue	Chipping	3	2.4	Positive
1400	1	2	201	Classroom 201	yes	Radiator (W4)	Metal	Grey	Chipping	5	0.2	Negative
1400	1	2	201	Classroom 201	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	201	Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	201A	Classroom 201 Storage	yes	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	2	201A	Classroom 201 Storage	yes	W2	Plaster	Tan	Chipping	10	4.1	Positive
1400	1	2	201A	Classroom 201 Storage	yes	W3	Plaster	Tan	Cracking	5	6.7	Positive
1400	1	2	201A	Classroom 201 Storage	yes	W4	Plaster	Tan	Cracking	5	5.5	Positive
1400	1	2	201A	Classroom 201 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	201A	Classroom 201 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	2	202	Classroom 202	yes	W1	Plaster	Yellow	Cracking	5	4.1	Positive
1400	1	2	202	Classroom 202	yes	W1	Plaster	Tan	Chipping	1	2.2	Positive
1400	1	2	202	Classroom 202	yes	W2	Plaster	Yellow	Cracking	1	3.4	Positive
1400	1	2	202	Classroom 202	yes	W2	Plaster	Tan	Chipping	1	5.7	Positive
1400	1	2	202	Classroom 202	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1400	1	2	202	Classroom 202	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	2	202	Classroom 202	yes	Radiator (W3)	Metal	Grey	Chipping	2	0.3	Negative
1400	1	2	202	Classroom 202	yes	W4	Plaster	Yellow	Cracking	1	1.9	Positive
1400	1	2	202	Classroom 202	yes	W4	Plaster	Tan	Chipping	1	3.2	Positive
1400	1	2	202	Classroom 202	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	202	Classroom 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	202A	Classroom 202 Storage	yes	W1	Plaster	Tan	Cracking	1	4.4	Positive
1400	1	2	202A	Classroom 202 Storage	yes	W2	Plaster	Tan	Cracking	3	5.6	Positive

				Inspection Dates: 2/17/20-2/24/20				School District of Philadelphia				
				Name of Inspector: Michael Barth				Lead Safe Certification Assessment Report				
				Inspection Company: Criterion Labs, Inc.				Patterson Elementary School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	2	202A	Classroom 202 Storage	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	2	202A	Classroom 202 Storage	yes	W4	Plaster	Tan	Cracking	1	7.7	Positive
1400	1	2	202A	Classroom 202 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	202A	Classroom 202 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	2	203	Classroom 203	yes	W1	Plaster	Tan	Spalling	4	8.7	Positive
1400	1	2	203	Classroom 203	yes	W2	Plaster	Tan	Cracking	10	5.4	Positive
1400	1	2	203	Classroom 203	yes	Radiator (W2)	Metal	Grey	Chipping	2	0.4	Negative
1400	1	2	203	Classroom 203	yes	W3	Plaster	Tan	Cracking	10	6.8	Positive
1400	1	2	203	Classroom 203	yes	Radiator (W3)	Metal	Tan	Chipping	2	0.3	Negative
1400	1	2	203	Classroom 203	yes	Radiator (W3)	Metal	Grey	Chipping	2	0.2	Negative
1400	1	2	203	Classroom 203	yes	W4	Plaster	Tan	Chipping	1	4.7	Positive
1400	1	2	203	Classroom 203	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	203	Classroom 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	203A	Classroom 203 Storage	yes	W1	Plaster	Tan	Cracking	1	8.7	Positive
1400	1	2	203A	Classroom 203 Storage	yes	W2	Plaster	Tan	Chipping	1	4.4	Positive
1400	1	2	203A	Classroom 203 Storage	yes	W3	Plaster	Tan	Cracking	3	9.7	Positive
1400	1	2	203A	Classroom 203 Storage	yes	Vertical Pipe (W3)	Metal	White	Chipping	1	0.1	Negative
1400	1	2	203A	Classroom 203 Storage	yes	W4	Plaster	Tan	Cracking	1	2.4	Positive
1400	1	2	203A	Classroom 203 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	203A	Classroom 203 Storage	yes	Ceiling	Plaster	Tan	Cracking	5	5.4	Positive
1400	1	2	204	Classroom 204	yes	W1	Plaster	Tan	Flaking	20	6.7	Positive
1400	1	2	204	Classroom 204	yes	W1	Wood	Black	Friction	5	0.1	Negative
1400	1	2	204	Classroom 204	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	204	Classroom 204	yes	W3	Plaster	Tan	Flaking	20	7.7	Positive
1400	1	2	204	Classroom 204	yes	W3	Wood	Black	Chipping	5	0.2	Negative
1400	1	2	204	Classroom 204	yes	W4	Plaster	Tan	Flaking	30	5.4	Positive
1400	1	2	204	Classroom 204	yes	W4	Wood	Black	Chipping	5	0	Negative
1400	1	2	204	Classroom 204	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	204	Classroom 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	204B	Classroom 204 Storage	yes	W1	Plaster	Tan	Alligatoring	3	7.4	Positive
1400	1	2	204B	Classroom 204 Storage	yes	W2	Plaster	Tan	Flaking	5	10.1	Positive
1400	1	2	204B	Classroom 204 Storage	yes	W3	Plaster	Tan	Flaking	5	6.5	Positive
1400	1	2	204B	Classroom 204 Storage	yes	Vertical Pipe (W3)	Metal	Tan	None	N/A	N/A	N/A
1400	1	2	204B	Classroom 204 Storage	yes	W4	Plaster	Tan	Flaking	5	4.4	Positive
1400	1	2	204B	Classroom 204 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	204B	Classroom 204 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	2	204A	Girl's Restroom next to Classroom 204	yes	W1	Plaster	Tan	Cracking	5	12.1	Positive
1400	1	2	204A	Girl's Restroom next to Classroom 204	yes	W2	Plaster	Tan	Cracking	3	11.3	Positive
1400	1	2	204A	Girl's Restroom next to Classroom 204	yes	W3	Plaster	Tan	Flaking	10	14.3	Positive
1400	1	2	204A	Girl's Restroom next to Classroom 204	yes	Vertical Pipe (W3)	Metal	White	Chipping	2	0.5	Negative
1400	1	2	204A	Girl's Restroom next to Classroom 204	yes	W4	Plaster	Tan	Flaking	5	13.1	Positive
1400	1	2	204A	Girl's Restroom next to Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	2	204A	Girl's Restroom next to Classroom 204	yes	Ceiling	Plaster	Tan	Flaking	15	11.5	Positive
1400	1	2	205	Classroom 205	yes	W1	Plaster	Tan	Chipping	10	5.4	Positive
1400	1	2	205	Classroom 205	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	205	Classroom 205	yes	W3	Plaster	Tan	Chipping	10	7.8	Positive
1400	1	2	205	Classroom 205	yes	Radiator (W3)	Metal	Grey	Chipping	2	0.2	Negative
1400	1	2	205	Classroom 205	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	205	Classroom 205	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	205	Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	205A	Classroom 205 Storage	yes	W1	Plaster	Tan	Chipping	1	6.7	Positive
1400	1	2	205A	Classroom 205 Storage	yes	Door Frame (W1)	Wood	Brown	None	0	N/A	N/A
1400	1	2	205A	Classroom 205 Storage	yes	W2	Plaster	Tan	Chipping	5	10.1	Positive
1400	1	2	205A	Classroom 205 Storage	yes	W3	Plaster	Tan	Cracking	1	14.1	Positive
1400	1	2	205A	Classroom 205 Storage	yes	W4	Plaster	Tan	Chipping	5	5.4	Positive
1400	1	2	205A	Classroom 205 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	205A	Classroom 205 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	2	206	Classroom 206	yes	W1	Plaster	Tan	Cracking	2	4.1	Positive
1400	1	2	206	Classroom 206	yes	W2	Plaster	Tan	Cracking	5	3.2	Positive
1400	1	2	206	Classroom 206	yes	W3	Plaster	Tan	Cracking	5	4.4	Positive
1400	1	2	206	Classroom 206	yes	Radiator (W3)	Metal	Grey	Chipping	1	0.3	Negative
1400	1	2	206	Classroom 206	yes	W4	Plaster	Tan	Cracking	2	5.7	Positive
1400	1	2	206	Classroom 206	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	206	Classroom 206	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	206A	Classroom 206 Storage	yes	W1	Plaster	Tan	Cracking	1	6.5	Positive
1400	1	2	206A	Classroom 206 Storage	yes	W2	Plaster	Tan	Chipping	1	4.8	Positive
1400	1	2	206A	Classroom 206 Storage	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	2	206A	Classroom 206 Storage	yes	W4	Plaster	Tan	Cracking	1	5.4	Positive
1400	1	2	206A	Classroom 206 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	206A	Classroom 206 Storage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	1	2	207	Classroom 207	yes	W1	Plaster	Tan	Cracking	15	4.8	Positive
1400	1	2	207	Classroom 207	yes	W2	Plaster	Tan	Flaking/Cracking	15	8.8	Positive
1400	1	2	207	Classroom 207	yes	W3	Plaster	Tan	Cracking/Moisture Damage	13	10.1	Positive
1400	1	2	207	Classroom 207	yes	Radiator (W3)	Metal	Grey	Chipping	2	0.3	Negative
1400	1	2	207	Classroom 207	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	207	Classroom 207	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	207	Classroom 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	207B	Classroom 207 Storage	yes	W1	Plaster	Tan	Cracking	1	9.1	Positive
1400	1	2	207B	Classroom 207 Storage	yes	W2	Plaster	Tan	Cracking	4	11.3	Positive
1400	1	2	207B	Classroom 207 Storage	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	2	207B	Classroom 207 Storage	yes	W4	Plaster	Tan	Cracking	5	8.4	Positive
1400	1	2	207B	Classroom 207 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	2	207B	Classroom 207 Storage	yes	Ceiling	Plaster	Tan	Cracking	1	13.1	Positive
1400	1	2	207A	Boy's Restroom next to Classroom 207	yes	W1	Plaster	Tan	None	0	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20			School District of Philadelphia						
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.			Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1400	1	2	207A	Boy's Restroom next to Classroom 207	yes	W2	Plaster	Tan	Spalling	1	10.2	Positive	
1400	1	2	207A	Boy's Restroom next to Classroom 207	yes	W3	Plaster	Tan	Cracking	3	8.5	Positive	
1400	1	2	207A	Boy's Restroom next to Classroom 207	yes	Vertical Pipe (W3)	Metal	White	Chipping	5	0.1	Negative	
1400	1	2	207A	Boy's Restroom next to Classroom 207	yes	W4	Plaster	Tan	None	0	N/A	N/A	
1400	1	2	207A	Boy's Restroom next to Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	2	207A	Boy's Restroom next to Classroom 207	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A	
1400	1	2	208	Classroom 208	yes	W1	Plaster	Tan	Cracking	5	5.4	Positive	
1400	1	2	208	Classroom 208	yes	W1	Plaster	White	Cracking	15	10.2	Positive	
1400	1	2	208	Classroom 208	yes	W2	Plaster	Tan	Flaking	1	6.5	Positive	
1400	1	2	208	Classroom 208	yes	W3	Plaster	Tan	Cracking	20	5.4	Positive	
1400	1	2	208	Classroom 208	yes	W4	Plaster	Tan	Cracking	15	3.2	Positive	
1400	1	2	208	Classroom 208	yes	Floor	Wood	N/A	None	0	N/A	N/A	
1400	1	2	208	Classroom 208	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	2	208A	Classroom 208A Storage	yes	W1	Plaster	Tan	None	0	N/A	N/A	
1400	1	2	208A	Classroom 208A Storage	yes	W2	Plaster	Tan	Cracking	10	3.3	Positive	
1400	1	2	208A	Classroom 208A Storage	yes	W3	Plaster	Tan	Moisture Damage	10	5.6	Positive	
1400	1	2	208A	Classroom 208A Storage	yes	W3	Wood	Black	Chipping	5	0.03	Negative	
1400	1	2	208A	Classroom 208A Storage	yes	W4	Plaster	Tan	Flaking	1	8.6	Positive	
1400	1	2	208A	Classroom 208A Storage	yes	Floor	Wood	N/A	N/A	0	N/A	N/A	
1400	1	2	208A	Classroom 208A Storage	yes	Ceiling	Plaster	Tan	Cracking	5	5.4	Positive	
1400	1	2	209	Classroom 209	yes	W1	Plaster	Tan	Chipping	10	8.9	Positive	
1400	1	2	209	Classroom 209	yes	W2	Plaster	Tan	Flaking	10	10.2	Positive	
1400	1	2	209	Classroom 209	yes	W3	Plaster	Tan	Flaking	10	6.7	Positive	
1400	1	2	209	Classroom 209	yes	W4	Plaster	Tan	Cracking	10	9.9	Positive	
1400	1	2	209	Classroom 209	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1400	1	2	209	Classroom 209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	2	209A	Classroom 209A Storage	yes	W1	Plaster	Tan	Cracking	3	13.1	Positive	
1400	1	2	209A	Classroom 209A Storage	yes	W2	Plaster	Tan	Chipping	1	10.2	Positive	
1400	1	2	209A	Classroom 209A Storage	yes	W2	Plaster	White	Chipping	3	9.8	Positive	
1400	1	2	209A	Classroom 209A Storage	yes	W3	Plaster	Tan	Cracking	3	6.8	Positive	
1400	1	2	209A	Classroom 209A Storage	yes	W3	Metal	Tan	None	N/A	N/A	N/A	
1400	1	2	209A	Classroom 209A Storage	yes	W4	Plaster	Tan	Cracking	5	11.7	Positive	
1400	1	2	209A	Classroom 209A Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1400	1	2	209A	Classroom 209A Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	2	210	Faculty Lounge	yes	W1	Plaster	Tan	Cracking	15	8.8	Positive	
1400	1	2	210	Faculty Lounge	yes	W1	Plaster	White	Cracking	3	15.1	Positive	
1400	1	2	210	Faculty Lounge	yes	W1	Metal	Brown	None	0	N/A	N/A	
1400	1	2	210	Faculty Lounge	yes	W2	Plaster	Tan	Cracking	5	12.1	Positive	
1400	1	2	210	Faculty Lounge	yes	W3	Plaster	Tan	Cracking	15	10.2	Positive	
1400	1	2	210	Faculty Lounge	yes	W4	Plaster	Tan	Cracking	15	9.8	Positive	
1400	1	2	210	Faculty Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	2	210	Faculty Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1400	1	2	210A	Faculty Lounge Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A	

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	2	210A	Faculty Lounge Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1400	1	2	210A	Faculty Lounge Restroom	yes	W3	Plaster	Tan	Cracking	3	8.7	Positive
1400	1	2	210A	Faculty Lounge Restroom	yes	W4	Plaster	Tan	Cracking	3	6.5	Positive
1400	1	2	210A	Faculty Lounge Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	210A	Faculty Lounge Restroom	yes	Ceiling	Plaster	Tan	Flaking	5	10.1	Positive
1400	1	2	211	Nurse's Office next to Classroom 210	yes	Door Frame (W1)	Metal	Brown	Chipping	3	0.2	Negative
1400	1	2	211	Nurse's Office next to Classroom 210	yes	Cove Base (W1)	Wood	Black	Chipping	5	0.1	Negative
1400	1	2	211	Nurse's Office next to Classroom 210	yes	Window Frame (W2)	Wood	Black	Chipping	5	0.03	Negative
1400	1	2	211	Nurse's Office next to Classroom 210	yes	Window Frame (W3)	Wood	Blue	Chipping	5	0.4	Negative
1400	1	2	211	Nurse's Office next to Classroom 210	yes	Door Frame (W4)	Metal	Brown	Chipping	5	0.1	Negative
1400	1	2	211	Nurse's Office next to Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	211	Nurse's Office next to Classroom 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	211A	Nurse's Office Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1400	1	2	211A	Nurse's Office Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1400	1	2	211A	Nurse's Office Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	2	211A	Nurse's Office Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	2	211A	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	211A	Nurse's Office Restroom	yes	Ceiling	Plaster	Tan	Cracking	3	11.2	Positive
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	Door Frame (W1)	Metal	Grey	Chipping	1	0.1	Negative
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	W2	Plaster	Tan	Cracking	10	5.4	Positive
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	W2	Brick	N/A	None	0	N/A	N/A
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	Cove Base (W2)	Brick	Black	Chipping	3	1.2	Positive
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	W3	Plaster	Tan	Chipping	1	4.6	Positive
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	W3	Brick	N/A	None	0	N/A	N/A
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	Cove Base (W3)	Brick	Black	Chipping	3	2.1	Positive
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	W4	Plaster	Tan	Chipping	5	8.8	Positive
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	W4	Brick	N/A	None	0	N/A	N/A
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	Cove Base (W4)	Brick	Black	Chipping	3	3.4	Positive
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	Floor	Concrete	Black	Friction	10	0.3	Negative
1400	1	2	H21	Hallway at Classrooms 200 to 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	W1	Plaster	Tan	Cracking	10	4.7	Positive
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	W1	Plaster	White	Chipping	1	8.9	Positive
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	Cove Base (W1)	Brick	Black	Chipping	5	2.4	Positive
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	Door Frame (W1)	Metal	Grey	Chipping	1	0.2	Positive
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20				School District of Philadelphia				
				Name of Inspector: Michael Barth				Lead Safe Certification Assessment Report				
				Inspection Company: Criterion Labs, Inc.				Patterson Elementary School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	W3	Plaster	Tan	Cracking	10	9.9	Positive
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	W3	Plaster	White	Moisture Damage	15	6.8	Positive
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	Cove Base (W3)	Brick	Black	Chipping	5	4.1	Positive
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	Door Frame (W3)	Metal	Grey	Chipping	3	0.1	Negative
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	Floor	Concrete	Grey	Friction	1	0.2	Negative
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	Floor	Concrete	Black	Friction	1	0.3	Negative
1400	1	2	H22	Hallway at Classrooms 204 to 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	Door Frame (W1)	Metal	Grey	Chipping	1	0.2	Negative
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	Door (W1)	Metal	Brown	None	0	N/A	N/A
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	W2	Plaster	Tan	Cracking	5	7.8	Positive
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	W2	Brick	N/A	None	0	N/A	N/A
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	Cove Base (W2)	Brick	Black	Chipping	5	1.3	Positive
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	W3	Plaster	Tan	Chipping	3	5.6	Positive
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	W3	Brick	N/A	None	0	N/A	N/A
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	Cove Base (W3)	Brick	Black	Chipping	1	0.9	Positive
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	W4	Plaster	Tan	Chipping	3	5.6	Positive
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	W4	Brick	N/A	None	0	N/A	N/A
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	W4	Brick	Black	None	0	N/A	N/A
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	Floor	Concrete	Black	Friction	20	0.4	Negative
1400	1	2	H23	Hallway at Classrooms 208 to 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300	Classroom 300	yes	W1	Plaster	Blue	Chipping	20	5.8	Positive
1400	1	3	300	Classroom 300	yes	W2	Plaster	Blue	Chipping	15	6.3	Positive
1400	1	3	300	Classroom 300	yes	Radiator (W2)	Metal	Blue	Flaking	1	0.3	Negative
1400	1	3	300	Classroom 300	yes	W3	Plaster	Blue	Chipping	20	10.2	Positive
1400	1	3	300	Classroom 300	yes	W4	Plaster	Blue	Flaking	10	9.8	Positive
1400	1	3	300	Classroom 300	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	300	Classroom 300	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300C	Classroom 300 Storage	yes	W1	Plaster	Blue	Chipping	10	5.9	Positive
1400	1	3	300C	Classroom 300 Storage	yes	W2	Plaster	Blue	Moisture Damage	1	6.7	Positive
1400	1	3	300C	Classroom 300 Storage	yes	W3	Plaster	Blue	Cracking	15	8.5	Positive
1400	1	3	300C	Classroom 300 Storage	yes	W4	Plaster	Blue	Cracking	5	6.9	Positive
1400	1	3	300C	Classroom 300 Storage	yes	W4	Plaster	White	Chipping	1	3.2	Positive
1400	1	3	300C	Classroom 300 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300C	Classroom 300 Storage	yes	Ceiling	Plaster	Blue	Flaking	5	4.2	Positive
1400	1	3	300C	Classroom 300 Storage	yes	Ceiling	Plaster	White	Chipping	10	6.5	Positive
1400	1	3	300A	Classroom 300 Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300A	Classroom 300 Restroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300A	Classroom 300 Restroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300A	Classroom 300 Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	3	300A	Classroom 300 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300A	Classroom 300 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300B	Staff Restroom outside Classroom 300	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300B	Staff Restroom outside Classroom 300	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300B	Staff Restroom outside Classroom 300	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300B	Staff Restroom outside Classroom 300	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300B	Staff Restroom outside Classroom 300	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	300B	Staff Restroom outside Classroom 300	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	301	Classroom 301	yes	W1	Plaster	Blue	Cracking	15	12.1	Positive
1400	1	3	301	Classroom 301	yes	W2	Plaster	Blue	Cracking	20	6.8	Positive
1400	1	3	301	Classroom 301	yes	W3	Plaster	Blue	Cracking	20	9.6	Positive
1400	1	3	301	Classroom 301	yes	Radiator (W3)	Metal	Grey	Chipping	3	0.2	Negative
1400	1	3	301	Classroom 301	yes	W4	Plaster	Blue	Cracking	20	11.2	Positive
1400	1	3	301	Classroom 301	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	301	Classroom 301	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	301A	Classroom 301 Storage	yes	W1	Plaster	Blue	Cracking	1	4.5	Positive
1400	1	3	301A	Classroom 301 Storage	yes	W2	Plaster	Blue	Chipping	4	6.2	Positive
1400	1	3	301A	Classroom 301 Storage	yes	W3	Plaster	Blue	Cracking	3	3.9	Positive
1400	1	3	301A	Classroom 301 Storage	yes	Vertical Pipe (W3)	Metal	White	Chipping	3	0.3	Negative
1400	1	3	301A	Classroom 301 Storage	yes	W4	Plaster	Blue	Chipping	5	5.4	Positive
1400	1	3	301A	Classroom 301 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	301A	Classroom 301 Storage	yes	Ceiling	Plaster	White	Cracking	3	8.4	Positive
1400	1	3	302	Classroom 302	yes	W1	Plaster	White	Chipping	15	5.3	Positive
1400	1	3	302	Classroom 302	yes	W1	Plaster	Green	Chipping	10	6.8	Positive
1400	1	3	302	Classroom 302	yes	W2	Plaster	White	Chipping	15	9.4	Positive
1400	1	3	302	Classroom 302	yes	W3	Plaster	Green	Chipping	15	10.2	Positive
1400	1	3	302	Classroom 302	yes	Radiator (W3)	Metal	Grey	Chipping	3	0.2	Negative
1400	1	3	302	Classroom 302	yes	W3	Plaster	White	Flaking	10	6.5	Positive
1400	1	3	302	Classroom 302	yes	W4	Plaster	White	Flaking	15	3.9	Positive
1400	1	3	302	Classroom 302	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1400	1	3	302	Classroom 302	yes	W4	Plaster	Black	Chipping	1	4.1	Positive
1400	1	3	302	Classroom 302	yes	W4	Plaster	Pink	Chipping	1	5.2	Positive
1400	1	3	302	Classroom 302	yes	W4	Plaster	Blue	None	0	N/A	N/A
1400	1	3	302	Classroom 302	yes	Vertical Pipe (W4)	Metal	White	Chipping	1	0.4	Negative
1400	1	3	302	Classroom 302	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	302	Classroom 302	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	302A	Classroom 302 Storage Entrance Near Hallway	yes	W1	Plaster	Blue	None	0	N/A	N/A
1400	1	3	302A	Classroom 302 Storage Entrance Near Hallway	yes	W2	Plaster	Blue	Partially Inaccessible	N/A	N/A	N/A
1400	1	3	302A	Classroom 302 Storage Entrance Near Hallway	yes	W3	Plaster	Blue	Partially Inaccessible	N/A	N/A	N/A
1400	1	3	302A	Classroom 302 Storage Entrance Near Hallway	yes	W4	Plaster	Blue	Cracking	3	8.5	Positive
1400	1	3	302A	Classroom 302 Storage Entrance Near Hallway	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	302A	Classroom 302 Storage Entrance Near Hallway	yes	Ceiling	Plaster	Blue	None	0	N/A	N/A
1400	1	3	302A	Classroom 302 Storage Entrance Near W3 of 302	yes	W1	Plaster	Blue	Cracking	3	3.5	Positive

				Inspection Dates: 2/17/20-2/24/20				School District of Philadelphia				
				Name of Inspector: Michael Barth				Lead Safe Certification Assessment Report				
				Inspection Company: Criterion Labs, Inc.				Patterson Elementary School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	3	302A	Classroom 302 Storage Entrance Near W3 of 302	yes	W2	Plaster	Blue	Partially Inaccessible	N/A	N/A	N/A
1400	1	3	302A	Classroom 302 Storage Entrance Near W3 of 302	yes	W2	Metal	Blue	Flaking	1	0.1	Negative
1400	1	3	302A	Classroom 302 Storage Entrance Near W3 of 302	yes	W3	Plaster	Blue	Flaking	3	2.4	Positive
1400	1	3	302A	Classroom 302 Storage Entrance Near W3 of 302	yes	W4	Plaster	Blue	Flaking	3	5.4	Positive
1400	1	3	302A	Classroom 302 Storage Entrance Near W3 of 302	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	302A	Classroom 302 Storage Entrance Near W3 of 302	yes	Ceiling	Plaster	Blue	None	N/A	N/A	N/A
1400	1	3	303	Classroom 303	yes	W1	Plaster	Blue	Cracking	3	4.7	Positive
1400	1	3	303	Classroom 303	yes	W1	Plaster	Tan	Moisture Damage	15	5.2	Positive
1400	1	3	303	Classroom 303	yes	W2	Plaster	Blue	Cracking	3	3.5	Positive
1400	1	3	303	Classroom 303	yes	W2	Plaster	White	Chipping	10	6.8	Positive
1400	1	3	303	Classroom 303	yes	W2	Plaster	Green	Chipping	1	8.6	Positive
1400	1	3	303	Classroom 303	yes	W3	Plaster	Blue	Flaking	25	4.3	Positive
1400	1	3	303	Classroom 303	yes	W4	Plaster	Blue	Chipping	3	8.8	Positive
1400	1	3	303	Classroom 303	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	303	Classroom 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	303A	Classroom 303 Storage	yes	W1	Plaster	White	Partially Inaccessible	N/A	2.5	Positive
1400	1	3	303A	Classroom 303 Storage	yes	W2	Plaster	White	Partially Inaccessible	N/A	3.6	Positive
1400	1	3	303A	Classroom 303 Storage	yes	W3	Plaster	White	Moisture Damage	15	5.5	Positive
1400	1	3	303A	Classroom 303 Storage	yes	W3	Plaster	Blue	Cracking	5	4.2	Positive
1400	1	3	303A	Classroom 303 Storage	yes	W4	Plaster	White	None	0	N/A	N/A
1400	1	3	303A	Classroom 303 Storage	yes	W4	Plaster	Blue	Cracking	3	6.5	Positive
1400	1	3	303A	Classroom 303 Storage	yes	Floor	Wood	N/A	N/A	0	N/A	N/A
1400	1	3	303A	Classroom 303 Storage	yes	Ceiling	Plaster	White	Cracking	1	3.3	Positive
1400	1	3	303A	Classroom 303 Storage	yes	Ceiling	Plaster	Blue	Cracking	3	1.2	Positive
1400	1	3	304	Classroom 304	yes	W1	Plaster	Blue	Cracking	15	5.8	Positive
1400	1	3	304	Classroom 304	yes	W2	Plaster	Blue	Cracking	3	3.4	Positive
1400	1	3	304	Classroom 304	yes	Plastic Room Divider (W2)	Plastic	N/A	N/A	N/A	N/A	N/A
1400	1	3	304	Classroom 304	yes	W3	Plaster	Blue	Cracking	5	8.4	Positive
1400	1	3	304	Classroom 304	yes	W3	Plaster	Orange	Moisture Damage	15	6.6	Positive
1400	1	3	304	Classroom 304	yes	Radiator (W3)	Metal	Grey	Chipping	3	0.1	Negative
1400	1	3	304	Classroom 304	yes	W4	Plaster	Blue	Cracking	5	8.4	Positive
1400	1	3	304	Classroom 304	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	304	Classroom 304	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	304B	Classroom 304 Storage	yes	W1	Plaster	Blue	Chipping	1	12.3	Positive
1400	1	3	304B	Classroom 304 Storage	yes	W2	Plaster	Blue	Cracking	5	14.2	Positive
1400	1	3	304B	Classroom 304 Storage	yes	W3	Plaster	Blue	Chipping	3	8.9	Positive
1400	1	3	304B	Classroom 304 Storage	yes	W4	Plaster	Blue	Cracking	5	11.3	Positive
1400	1	3	304B	Classroom 304 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	304B	Classroom 304 Storage	yes	Ceiling	Plaster	Blue	Flaking	3	14.1	Positive
1400	1	3	304A	Girl's Restroom next to Classroom 304	yes	W1	Plaster	White	Cracking	1	11.4	Positive
1400	1	3	304A	Girl's Restroom next to Classroom 304	yes	W2	Plaster	White	Cracking	1	13.1	Positive
1400	1	3	304A	Girl's Restroom next to Classroom 304	yes	W3	Plaster	White	Cracking	1	16.4	Positive
1400	1	3	304A	Girl's Restroom next to Classroom 304	yes	W4	Plaster	White	Cracking	1	14.3	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	3	304A	Girl's Restroom next to Classroom 304	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	304A	Girl's Restroom next to Classroom 304	yes	Ceiling	Plaster	White	Flaking	10	15.9	Positive
1400	1	3	305	Classroom 305	yes	W1	Plaster	Green	Chipping	20	11.2	Positive
1400	1	3	305	Classroom 305	yes	W2	Plaster	Green	Chipping	3	13.1	Positive
1400	1	3	305	Classroom 305	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	305	Classroom 305	yes	W3	Plaster	Green	Chipping	10	6.4	Positive
1400	1	3	305	Classroom 305	yes	W3	Plaster	Blue	Flaking	10	13.3	Positive
1400	1	3	305	Classroom 305	yes	Radiator (W3)	Metal	Grey	Chipping	3	0.3	Negative
1400	1	3	305	Classroom 305	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	305	Classroom 305	yes	Plastic Divider (W4)	Plastic	Green	N/A	N/A	N/A	N/A
1400	1	3	305	Classroom 305	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	305	Classroom 305	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	305A	Classroom 305 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A
1400	1	3	305A	Classroom 305 Storage	yes	W2	Plaster	Blue	None	0	N/A	N/A
1400	1	3	305A	Classroom 305 Storage	yes	W3	Plaster	Blue	None	0	N/A	N/A
1400	1	3	305A	Classroom 305 Storage	yes	W4	Plaster	Blue	Cracking	3	4.5	Positive
1400	1	3	305A	Classroom 305 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	305A	Classroom 305 Storage	yes	Ceiling	Plaster	White	Cracking	1	2.6	Positive
1400	1	3	306	Classroom 306	yes	W1	Plaster	Green	Cracking	10	10.2	Positive
1400	1	3	306	Classroom 306	yes	W1	Plaster	Orange	Chipping	2	11.6	Positive
1400	1	3	306	Classroom 306	yes	W2	Plaster	Orange	None	0	N/A	N/A
1400	1	3	306	Classroom 306	yes	Plastic Divider (W3)	Plastic	Green	N/A	N/A	N/A	N/A
1400	1	3	306	Classroom 306	yes	W3	Plaster	Orange	Chipping	15	12.1	Positive
1400	1	3	306	Classroom 306	yes	W3	Plaster	Blue	Cracking	3	14.2	Positive
1400	1	3	306	Classroom 306	yes	Radiator (W3)	Metal	Grey	Chipping	1	0.4	Negative
1400	1	3	306	Classroom 306	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	306	Classroom 306	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	306	Classroom 306	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	306A	Classroom 306 Storage	yes	W1	Plaster	Blue	Chipping	1	5.4	Positive
1400	1	3	306A	Classroom 306 Storage	yes	W2	Plaster	Blue	Chipping	2	6.7	Positive
1400	1	3	306A	Classroom 306 Storage	yes	W3	Plaster	Blue	Cracking	1	8.9	Positive
1400	1	3	306A	Classroom 306 Storage	yes	W4	Plaster	Blue	Cracking	2	5.9	Positive
1400	1	3	306A	Classroom 306 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	306A	Classroom 306 Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	3	307	Classroom 307	yes	W1	Plaster	Blue	Cracking	5	11.5	Positive
1400	1	3	307	Classroom 307	yes	W2	Plaster	Blue	Cracking	10	9.8	Positive
1400	1	3	307	Classroom 307	yes	W3	Plaster	Blue	Chipping	20	6.7	Positive
1400	1	3	307	Classroom 307	yes	Radiator (W3)	Metal	Grey	Chipping	2	0.2	Negative
1400	1	3	307	Classroom 307	yes	W4	Plastic	Blue	None	0	N/A	N/A
1400	1	3	307	Classroom 307	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	307	Classroom 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	307B	Classroom 307 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20			School District of Philadelphia					
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs, Inc.			Patterson Elementary School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1400	1	3	307B	Classroom 307 Storage	yes	W2	Plaster	Blue	Cracking	1	13.4	Positive
1400	1	3	307B	Classroom 307 Storage	yes	W3	Plaster	Blue	None	0	N/A	N/A
1400	1	3	307B	Classroom 307 Storage	yes	W4	Plaster	Blue	Cracking	10	12.1	Positive
1400	1	3	307B	Classroom 307 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	307B	Classroom 307 Storage	yes	Ceiling	Plaster	White	Cracking	1	9.8	Positive
1400	1	3	307A	Boy's Restroom next to Classroom 307	yes	W1	Plaster	Tan	Cracking	5	10.2	Positive
1400	1	3	307A	Boy's Restroom next to Classroom 307	yes	Radiator (W1)	Metal	Black	None	0	N/A	N/A
1400	1	3	307A	Boy's Restroom next to Classroom 307	yes	W2	Plaster	Tan	Cracking	5	6.5	Positive
1400	1	3	307A	Boy's Restroom next to Classroom 307	yes	W3	Plaster	Tan	Cracking	3	7.8	Positive
1400	1	3	307A	Boy's Restroom next to Classroom 307	yes	Vertical Pipe (W3)	Metal	White	Chipping	3	0.3	Negative
1400	1	3	307A	Boy's Restroom next to Classroom 307	yes	W4	Plaster	Tan	None	0	N/A	N/A
1400	1	3	307A	Boy's Restroom next to Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	307A	Boy's Restroom next to Classroom 307	yes	Ceiling	Plaster	Tan	Flaking	10	11.5	Positive
1400	1	3	307C	Custodial Closet in Hallway outside Boy's Restroom	no	W1	Plaster	Tan	Cracking	1	10.2	Positive
1400	1	3	307C	Custodial Closet in Hallway outside Boy's Restroom	no	W2	Plaster	Tan	Cracking	1	3.5	Positive
1400	1	3	307C	Custodial Closet in Hallway outside Boy's Restroom	no	W3	Plaster	Tan	None	0	N/A	N/A
						Metal Door (W3)	Metal	White	Chipping	1	0.3	Negative
1400	1	3	307C	Custodial Closet in Hallway outside Boy's Restroom	no	W4	Plaster	Tan	Cracking	1	9.9	Positive
1400	1	3	307C	Custodial Closet in Hallway outside Boy's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	307C	Custodial Closet in Hallway outside Boy's Restroom	no	Ceiling	Plaster	Tan	Flaking	3	10.1	Positive
1400	1	3	308	Classroom 308	yes	W1	Plaster	Tan	Chipping	5	4.7	Positive
1400	1	3	308	Classroom 308	yes	W2	Plaster	Tan	Chipping	2	8.9	Positive
1400	1	3	308	Classroom 308	yes	Vertical Pipe (W2)	Metal	White	Chipping	1	0.2	Negative
1400	1	3	308	Classroom 308	yes	W3	Plaster	Tan	Flaking	5	10.1	Positive
1400	1	3	308	Classroom 308	yes	Radiator (W3)	Metal	Grey	Chipping	1	0.3	Negative
1400	1	3	308	Classroom 308	yes	W4	Plaster	Tan	Moisture Damage	5	12.1	Positive
1400	1	3	308	Classroom 308	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	308	Classroom 308	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	308A	Classroom 308 Storage	yes	W1	Plaster	Tan	Cracking	1	14.2	Positive
1400	1	3	308A	Classroom 308 Storage	yes	W2	Plaster	Tan	Cracking	6	6.9	Positive
1400	1	3	308A	Classroom 308 Storage	yes	W3	Plaster	Tan	Cracking	5	10.5	Positive
1400	1	3	308A	Classroom 308 Storage	yes	W4	Plaster	Tan	Cracking	1	12.3	Positive
1400	1	3	308A	Classroom 308 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	308A	Classroom 308 Storage	yes	Ceiling	Plaster	Tan	Cracking	5	11.3	Positive
1400	1	3	309	Classroom 309	yes	W1	Plaster	Purple	Cracking	2	14.3	Positive
1400	1	3	309	Classroom 309	yes	W1	Plaster	Orange	None	0	N/A	N/A
1400	1	3	309	Classroom 309	yes	W2	Plaster	Purple	None	0	N/A	N/A
1400	1	3	309	Classroom 309	yes	W3	Plaster	Orange	Flaking	5	13.2	Positive
1400	1	3	309	Classroom 309	yes	W3	Plaster	Blue	Flaking	15	9.8	Positive
1400	1	3	309	Classroom 309	yes	Radiator (W3)	Metal	Grey	Chipping	2	0.2	Negative

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	3	309	Classroom 309	yes	W4	Plaster	Purple	Chipping	3	8.7	Positive
1400	1	3	309	Classroom 309	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	309	Classroom 309	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	309A	Classroom 309 Storage	yes	W1	Plaster	Blue	Cracking	1	11.4	Positive
1400	1	3	309A	Classroom 309 Storage	yes	W2	Plaster	Blue	Cracking	1	12.5	Positive
1400	1	3	309A	Classroom 309 Storage	yes	W3	Plaster	Blue	Chipping	1	9.8	Positive
1400	1	3	309A	Classroom 309 Storage	yes	Vertical Pipe (W3)	Metal	Blue	Chipping	1	0.1	Negative
1400	1	3	309A	Classroom 309 Storage	yes	W4	Plaster	Blue	Cracking	5	8.8	Positive
1400	1	3	309A	Classroom 309 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	309A	Classroom 309 Storage	yes	Ceiling	Plaster	Blue	Moisture Damage	1	4.3	Positive
1400	1	3	310	Classroom 310	yes	W1	Plaster	Yellow	Cracking	5	5.4	Positive
1400	1	3	310	Classroom 310	yes	W1	Plaster	Pink	Cracking	5	6.7	Positive
1400	1	3	310	Classroom 310	yes	W2	Plaster	Yellow	Chipping	1	10.1	Positive
1400	1	3	310	Classroom 310	yes	W2	Plaster	White	Chipping	10	5.4	Positive
1400	1	3	310	Classroom 310	yes	W2	Plaster	Grey	Cracking	5	9.8	Positive
1400	1	3	310	Classroom 310	yes	Radiator (W2)	Metal	Grey	Chipping	1	0.1	Positive
1400	1	3	310	Classroom 310	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1400	1	3	310	Classroom 310	yes	W3	Plaster	White	Cracking	10	11.4	Positive
1400	1	3	310	Classroom 310	yes	W3	Plaster	Pink	Chipping	1	12.3	Positive
1400	1	3	310	Classroom 310	yes	W3	Plaster	Blue	Chipping	1	15.4	Positive
1400	1	3	310	Classroom 310	yes	Radiator (W3)	Metal	Grey	Chipping	1	0.2	Positive
1400	1	3	310	Classroom 310	yes	W4	Plaster	Yellow	Chipping	1	9.9	Positive
1400	1	3	310	Classroom 310	yes	W4	Plaster	Blue	Cracking	2	14.3	Positive
1400	1	3	310	Classroom 310	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	310	Classroom 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	310A	Classroom 310 Storage	yes	W1	Plaster	Blue	Chipping	1	10.2	Positive
1400	1	3	310A	Classroom 310 Storage	yes	W2	Plaster	Blue	Chipping	2	11.5	Positive
1400	1	3	310A	Classroom 310 Storage	yes	W2	Plaster	Purple	Cracking	1	13.2	Positive
1400	1	3	310A	Classroom 310 Storage	yes	W3	Plaster	Blue	Cracking	10	14.1	Positive
1400	1	3	310A	Classroom 310 Storage	yes	Vertical Pipe (W3)	Metal	White	Chipping	5	0.1	Negative
1400	1	3	310A	Classroom 310 Storage	yes	W4	Plaster	Blue	Flaking/Cracking	5	10.5	Positive
1400	1	3	310A	Classroom 310 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1400	1	3	310A	Classroom 310 Storage	yes	Ceiling	Plaster	White	Cracking	2	11.5	Positive
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	W1	Plaster	Blue	Flaking	5	12.1	Positive
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	W1	Plaster	Brown	None	N/A	N/A	N/A
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	W2	Plaster	Blue	Flaking	10	15.4	Positive
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	W2	Plaster	White	Chipping	3	12.3	Positive
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	W3	Plaster	Blue	Moisture Damage	15	9.8	Positive
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	W3	Plaster	White	Chipping	3	13.1	Positive
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	W4	Plaster	Blue	Flaking	10	10.5	Positive
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	311	Office next to Classroom 310 (used as Book Room)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	Door (W1)	Metal	Grey	Friction	1	0.3	Negative

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W2	Plaster	Tan	Cracking	3	12.1	Positive
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W2	Brick	Black	None	N/A	N/A	N/A
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W3	Plaster	Tan	Cracking	1	13.3	Positive
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W3	Brick	Black	N/A	N/A	N/A	N/A
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W4	Plaster	Tan	Cracking	1	9.9	Positive
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	W4	Brick	Black	Friction	3	3.2	Positive
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	Floor	Concrete	Black	Friction	10	0.2	Negative
1400	1	3	H31	Hallway at Classrooms 300 to 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	W1	Plaster	Tan	Cracking	5	12.3	Positive
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	Cove Base (W1)	Brick	Black	Friction	5	3.2	Negative
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	Electrical Box Panel (W1)	Metal	Grey	Chipping	1	0.3	Negative
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	Door (W1)	Metal	Grey	Chipping	1	0.1	Negative
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	W3	Plaster	Tan	Cracking	10	5.4	Positive
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	Cove Base (W3)	Brick	Black	Friction	5	3.4	Positive
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	Radiator (W3)	Metal	Grey	Chipping	5	0.1	Negative
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	Floor	Concrete	Black	Friction	3	0.1	Negative
1400	1	3	H32	Hallway at Classrooms 304 to 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	Door Frame (W1)	Metal	Grey	Chipping	1	0.1	Negative
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	Door (W1)	Metal	Brown	None	0	N/A	N/A
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	W2	Plaster	Tan	Chipping	3	10.1	Positive
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	W2	Plaster	White	Chipping	1	12.3	Positive
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	Cove Base (W2)	Brick	Black	Chipping	1	1.3	Positive
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	Door Frame (W2)	Metal	Grey	Chipping	1	0.2	Negative
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	W3	Plaster	Tan	Cracking	3	5.4	Positive
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	W3	Plaster	White	None	0	N/A	N/A
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	Cove Base (W3)	Brick	Black	Chipping	1	3.1	Positive
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	W4	Plaster	White	Chipping	3	10.2	Positive
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	Cove Base (W4)	Brick	Black	Chipping	1	1.4	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	Floor	Concrete	Black	Friction	10	0.2	Negative
1400	1	3	H33	Hallway at Classrooms 308 to 311	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	001B	Boiler Room	no	W1	Brick	White	Chipping	10	10.4	Positive
1400	1	B	001B	Boiler Room	no	W1	Brick	Grey	Chipping	10	12.3	Positive
1400	1	B	001B	Boiler Room	no	W2	Brick	White	None	0	N/A	N/A
1400	1	B	001B	Boiler Room	no	W2	Brick	Grey	Chipping	10	15.4	Positive
1400	1	B	001B	Boiler Room	no	W3	Brick	White	Chipping	10	13.1	Positive
1400	1	B	001B	Boiler Room	no	W3	Brick	Grey	Chipping	10	12.2	Positive
1400	1	B	001B	Boiler Room	no	W3	Plaster	White	Chipping	3	11.1	Positive
1400	1	B	001B	Boiler Room	no	W3	Plaster	Grey	Chipping	3	9.9	Positive
1400	1	B	001B	Boiler Room	no	W4	Brick	White	Chipping	10	5.4	Positive
1400	1	B	001B	Boiler Room	no	W4	Brick	Grey	Chipping	10	9.8	Positive
1400	1	B	001B	Boiler Room	no	Sliding Door (W4)	Metal	Grey	Chipping	5	0.3	Negative
1400	1	B	001B	Boiler Room	no	Sliding Door Frame (W4)	Metal	Black	Chipping	3	0.4	Negative
1400	1	B	001B	Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	001B	Boiler Room	no	Ceiling	Plaster	White	Partially Inaccessible	N/A	N/A	N/A
1400	1	B	001C	Fan Room	no	W1	Brick	White	Flaking	10	10.1	Positive
1400	1	B	001C	Fan Room	no	W1	Brick	Grey	None	0	N/A	N/A
1400	1	B	001C	Fan Room	no	Door Frame (W1)	Metal	Black	None	0	N/A	N/A
1400	1	B	001C	Fan Room	no	W2	Concrete	White	Flaking	10	5.4	Positive
1400	1	B	001C	Fan Room	no	W2	Concrete	Grey	Flaking	2	6.9	Positive
1400	1	B	001C	Fan Room	no	W3	Brick	White	Chipping	3	7.8	Positive
1400	1	B	001C	Fan Room	no	W3	Brick	Grey	Chipping	1	10.2	Positive
1400	1	B	001C	Fan Room	no	Door (W3)	Metal	Grey	None	0	N/A	N/A
1400	1	B	001C	Fan Room	no	W4	Brick	White	Chipping	5	12.1	Positive
1400	1	B	001C	Fan Room	no	W4	Brick	Grey	Chipping	5	14.2	Positive
1400	1	B	001C	Fan Room	no	Electrical Box (W4)	Metal	Grey	Flaking	3	0.5	Negative
1400	1	B	001C	Fan Room	no	Window Frame (W4)	Wood	Grey	Cracking	3	3.1	Positive
1400	1	B	001C	Fan Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	001C	Fan Room	no	Ceiling	Plaster	White	Flaking	10	9.9	Positive
1400	1	B	001D	Hallway next to Fan Room	no	W1	Brick	White	Flaking	10	6.5	Positive
1400	1	B	001D	Hallway next to Fan Room	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	001D	Hallway next to Fan Room	no	Door (W1)	Metal	Grey	Chipping	1	8.6	Positive
1400	1	B	001D	Hallway next to Fan Room	no	W2	Brick	White	Chipping	3	10.4	Positive
1400	1	B	001D	Hallway next to Fan Room	no	W2	Brick	Grey	Chipping	3	8.7	Positive
1400	1	B	001D	Hallway next to Fan Room	no	Door Frame (W2)	Metal	Black	Friction	1	0.4	Negative
1400	1	B	001D	Hallway next to Fan Room	no	W3	Brick	White	Chipping	3	6.3	Positive
1400	1	B	001D	Hallway next to Fan Room	no	W3	Brick	Grey	Chipping	3	7.4	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	B	001D	Hallway next to Fan Room	no	Door Frame (W3)	Metal	Black	Friction	1	0.1	Negative
1400	1	B	001D	Hallway next to Fan Room	no	W4	Brick	White	Chipping	3	10.2	Positive
1400	1	B	001D	Hallway next to Fan Room	no	W4	Brick	Grey	Chipping	3	11.1	Positive
1400	1	B	001D	Hallway next to Fan Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	001D	Hallway next to Fan Room	no	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	B	001D	Hallway next to Fan Room	no	HVAC Unit (Ceiling)	Metal	White	Flaking	10	0.4	Negative
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W1	Brick	White	Moisture Damage	10	11.2	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W1	Brick	Grey	Moisture Damage	1	3.9	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	Door Frame (W1)	Metal	Black	Friction	1	0.1	Negative
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W2	Brick	White	Moisture Damage	25	9.8	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W2	Concrete	Grey	Moisture Damage	5	10.1	N/A
1400	1	B	003B	Custodial storage room next to Fan Room	yes	Horizontal Pipe (W2)	Metal	White	Chipping	5	1.2	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W3	Brick	White	Moisture Damage	10	5.4	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W3	Concrete	Grey	Moisture Damage	10	6.7	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	Horizontal Pipe (W3)	Metal	White	Chipping	5	6.8	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W4	Brick	White	Moisture Damage	5	8.9	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	W4	Brick	Grey	Moisture Damage	5	4.9	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	003B	Custodial storage room next to Fan Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	B	003B	Custodial storage room next to Fan Room	yes	HVAC System (Ceiling)	Metal	White	Moisture Damage	15	0.2	Negative
1400	1	B	003B	Custodial storage room next to Fan Room	yes	Concrete Support Beams	Concrete	White	Cracking	3	3.5	Positive
1400	1	B	003B	Custodial storage room next to Fan Room	yes	Concrete Support Beams	Concrete	Grey	Cracking	3	4.4	Positive
1400	1	B	004B	Boiler Room Storage	yes	W1	Brick	White	Chipping	5	5.4	Positive
1400	1	B	004B	Boiler Room Storage	yes	W1	Brick	Grey	Chipping	5	6.3	Positive
1400	1	B	004B	Boiler Room Storage	yes	Door (W1)	Metal	Black	Friction	1	0.3	Negative
1400	1	B	004B	Boiler Room Storage	yes	W2	Brick	White	Chipping	15	11.4	Positive
1400	1	B	004B	Boiler Room Storage	yes	W2	Brick	Grey	Chipping	15	12.3	Positive
1400	1	B	004B	Boiler Room Storage	yes	Vertical Pipe (W2)	Metal	White	Cracking	1	0.4	Negative
1400	1	B	004B	Boiler Room Storage	yes	W3	Brick	White	Chipping	5	14.3	Positive
1400	1	B	004B	Boiler Room Storage	yes	W3	Brick	Grey	Chipping	5	13.1	Positive
1400	1	B	004B	Boiler Room Storage	yes	Wooden Stairs (W3)	Wood	Grey	Friction	1	0.5	Negative

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	B	004B	Boiler Room Storage	yes	Vertical Pipe (W3)	Metal	White	Cracking	1	0.1	Negative
1400	1	B	004B	Boiler Room Storage	yes	W4	Brick	White	Chipping	15	6.3	Positive
1400	1	B	004B	Boiler Room Storage	yes	W4	Brick	Grey	Chipping	15	7.8	Positive
1400	1	B	004B	Boiler Room Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	004B	Boiler Room Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	B	004B	Boiler Room Storage	yes	Boiler Breeching (Ceiling)	Metal	White	Flaking	10	0.3	Negative
1400	1	B	004B	Boiler Room Storage	yes	Metal Piping (Ceiling)	Metal	White	Chipping	1	0.4	Negative
1400	1	B	012B	Gym	yes	W1	Brick	White	Chipping	3	18.1	Positive
1400	1	B	012B	Gym	yes	W1	Metal	White	Chipping	2	0.3	Negative
1400	1	B	012B	Gym	yes	W1	Metal	Brown	Chipping	2	2.5	Positive
1400	1	B	012B	Gym	yes	W1	Metal	Brown	Friction	1	0	Negative
1400	1	B	012B	Gym	yes	W2	Brick	White	Flaking	10	15.6	Positive
1400	1	B	012B	Gym	yes	W2	Wood	White	None	0	N/A	N/A
1400	1	B	012B	Gym	yes	W2	Wood	Brown	Chipping	2	0.12	Negative
1400	1	B	012B	Gym	yes	W2	Metal	Brown	Friction	10	0	Negative
1400	1	B	012B	Gym	yes	W3	Brick	White	Flaking	5	14.2	Positive
1400	1	B	012B	Gym	yes	W3	Metal	Brown	Friction	5	0	Negative
1400	1	B	012B	Gym	yes	W3	Metal	White	Chipping	2	5.4	Positive
1400	1	B	012B	Gym	yes	W3	Metal	Brown	Chipping	2	7.8	Positive
1400	1	B	012B	Gym	yes	W4	Brick	White	Cracking	5	12.1	Positive
1400	1	B	012B	Gym	yes	W4	Metal	Brown	Friction	1	0	Negative
1400	1	B	012B	Gym	yes	Vertical Pipe (W4)	Metal	White	Chipping	1	5.4	Positive
1400	1	B	012B	Gym	yes	Vertical Pipe (W4)	Metal	Brown	Flaking	15	4.6	Positive
1400	1	B	012B	Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	012B	Gym	yes	Ceiling	Plaster	White	Moisture Damage/Cracking	15	11.3	Positive
1400	1	B	012B	Gym	yes	Ceiling	Metal	White	Flaking	10	13.8	Positive
1400	1	B	009B	Gym Office	yes	W1	Brick	White	None	0	N/A	N/A
1400	1	B	009B	Gym Office	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	009B	Gym Office	yes	Cove Base (W1)	Brick	Black	Friction	1	3.2	Positive
1400	1	B	009B	Gym Office	yes	Electrical Conduit (W1)	Metal	White	Flaking	1	0.3	Negative
1400	1	B	009B	Gym Office	yes	W2	Brick	White	Partially Inaccessible	N/A	N/A	N/A
1400	1	B	009B	Gym Office	yes	W3	Brick	White	Partially Inaccessible	N/A	N/A	N/A
1400	1	B	009B	Gym Office	yes	W4	Brick	White	None	0	N/A	N/A
1400	1	B	009B	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	009B	Gym Office	yes	Ceiling	Plaster	White	Partially Inaccessible	10	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1400	1	B	009B	Gym Office	yes	Boiler Breeching (Ceiling)	Metal	White	Flaking	3	0.2	Negative
1400	1	B	010B	Gym Storage	yes	W1	Brick	White	Chipping	1	6.9	Positive
1400	1	B	010B	Gym Storage	yes	W2	Brick	White	Chipping	1	7.2	Positive
1400	1	B	010B	Gym Storage	yes	W3	Brick	White	Cracking	1	9.8	Positive
1400	1	B	010B	Gym Storage	yes	W4	Brick	White	Cracking	1	5.4	Positive
1400	1	B	010B	Gym Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	010B	Gym Storage	yes	Ceiling	Plaster	White	Flaking	10	10.1	Positive
1400	1	B	010B	Gym Storage	yes	Boiler Breeching (Ceiling)	Metal	White	Flaking	5	0.5	Negative
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	Door (W1)	Metal	Grey	Friction	1	0.1	Negative
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	W2	Brick	White	Cracking	2	1.9	Positive
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	Cove Base (W2)	Brick	Black	Friction	3	3.2	Positive
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	W3	Brick	White	None	0	N/A	N/A
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	Cove Base (W3)	Brick	Black	Friction	3	4.1	Positive
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	W4	Brick	White	Cracking	1	11	Positive
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	Cove Base (W4)	Brick	Black	Friction	3	3.4	Positive
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	Wooden Frame (W4)	Wood	Tan	Chipping	1	6.7	Positive
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	Floor	Concrete	Black	Friction	5	0.3	Negative
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	Ceiling	Plaster	White	Chipping	5	6.9	Positive
1400	1	B	H1	Hallway by Cafeteria and Girl's Restroom	yes	Boiler Breeching (Ceiling)	Metal	White	Chipping	3	0.4	Negative
1400	1	B	012C	Gym Closet	yes	W1	Brick	Tan	Flaking	3	5.4	Positive
1400	1	B	012C	Gym Closet	yes	Door Frame (W1)	Metal	Brown	Friction	1	0.3	Negative
1400	1	B	012C	Gym Closet	yes	W2	Brick	Tan	Cracking	3	3.2	Positive
1400	1	B	012C	Gym Closet	yes	W3	Brick	Tan	Cracking	3	10.4	Positive
1400	1	B	012C	Gym Closet	yes	W4	Brick	Tan	None	0	N/A	N/A
1400	1	B	012C	Gym Closet	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	012C	Gym Closet	yes	Ceiling	Plaster	Tan	Flaking	10	5.6	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W1	Brick	White	Chipping	1	13.1	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W1	Brick	N/A	N/A	0	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Door Frame (W1)	Metal	Black	Friction	1	0	Negative
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Cove Base (W1)	Brick	Black	Chipping	1	3.7	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W2	Brick	White	Cracking	1	15.3	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W2	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Cove Base (W2)	Brick	Black	Chipping	20	5.4	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W2	Metal	Black	Friction	1	0	Negative
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Vertical Pipe (W2)	Metal	Black	Chipping	1	0.1	Negative
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Vertical Pipe (W2)	Metal	White	Chipping	1	0.5	Negative
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W3	Brick	White	N/A	0	N/A	N/A
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W3	Brick	N/A	None	0	N/A	N/A
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Cove Base (W3)	Brick	Black	Chipping	5	4.4	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W3	Metal	Black	Chipping	1	0	Negative
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W3	Concrete	Black	Chipping	1	6.5	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W3	Concrete	Black	Friction	5	0.3	Negative
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W4	Concrete	Black	Friction	5	16.1	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W4	Brick	White	Chipping	5	11.3	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W4	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Cove Base (W4)	Brick	Black	Chipping	20	4.6	Positive
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	W4	Metal	Black	Friction	5	0	Negative
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
1400	1	B	H03	Hallway by Music Room and Boy's Restroom	yes	Ceiling	Plaster	White	Chipping	5	18.5	Positive
					yes	Boiler Breeching (Ceiling)	Metal	White	Flaking	10	4.3	Positive
1400	1	B	06B	Music Room	yes	W1	Plaster	Blue	None	0	N/A	N/A
1400	1	B	06B	Music Room	yes	W1	Brick	N/A	None	0	N/A	N/A
1400	1	B	06B	Music Room	yes	W1	Metal	Black	Chipping	1	0	Negative
1400	1	B	06B	Music Room	yes	W2	Plaster	Blue	Chipping	5	27.7	Positive
1400	1	B	06B	Music Room	yes	W2	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	06B	Music Room	yes	W2	Wood	Black	Chipping	1	0.02	Negative
1400	1	B	06B	Music Room	yes	W2	Metal	Black	Flaking	1	0.35	Negative
1400	1	B	06B	Music Room	yes	W2	Sheetrock	Tan	Chipping	1	0	Negative
1400	1	B	06B	Music Room	yes	W3	Plaster	Blue	Moisture Damage	10	23.4	Positive
1400	1	B	06B	Music Room	yes	W3	Plaster	White	Moisture Damage	5	20.1	Positive
1400	1	B	06B	Music Room	yes	W3	Brick	N/A	N/A	0	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20			School District of Philadelphia					
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs, Inc.			Patterson Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	B	06B	Music Room	yes	W3	Wood	Black	None	0	N/A	N/A
1400	1	B	06B	Music Room	yes	W4	Plaster	White	Moisture Damage	1	21.2	Positive
1400	1	B	06B	Music Room	yes	W4	Plaster	Blue	Moisture Damage	5	22.3	Positive
1400	1	B	06B	Music Room	yes	W4	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	06B	Music Room	yes	W4	Wood	Black	None	0	N/A	N/A
1400	1	B	06B	Music Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	06B	Music Room	yes	Ceiling	Metal	Blue	Chipping	5	18.8	Positive
1400	1	B	06B	Music Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	06B-A	Music Room Storage	yes	W1	Brick	White	Flaking	1	10.2	Positive
1400	1	B	06B-A	Music Room Storage	yes	W2	Brick	White	Flaking	1	15.4	Positive
1400	1	B	06B-A	Music Room Storage	yes	W2	Plaster	White	Flaking	3	13.2	Positive
1400	1	B	06B-A	Music Room Storage	yes	W3	Brick	White	None	0	N/A	N/A
1400	1	B	06B-A	Music Room Storage	yes	W4	Brick	White	Flaking	1	11.1	Positive
1400	1	B	06B-A	Music Room Storage	yes	Vertical Pipe (W4)	Metal	White	Chipping	3	0.3	Negative
1400	1	B	06B-A	Music Room Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	06B-A	Music Room Storage	yes	Ceiling	Plaster	White	Chipping	1	8.9	Positive
1400	1	B	06B-A	Music Room Storage	yes	Boiler Breeching (Ceiling)	Metal	White	Chipping	1	0.4	Negative
1400	1	B	07B	Art Room	yes	W1	Plaster	Blue	None	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W1	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W1	Plaster	White	Chipping	1	12.5	Positive
1400	1	B	07B	Art Room	yes	W2	Plaster	Blue	Chipping	1	17.8	Positive
1400	1	B	07B	Art Room	yes	W2	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W1	Plaster	White	None	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W3	Plaster	Blue	Moisture Damage	5	13.4	Positive
1400	1	B	07B	Art Room	yes	W3	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W3	Plaster	White	None	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W4	Plaster	Blue	Spalling	1	14.4	Positive
1400	1	B	07B	Art Room	yes	W4	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W4	Plaster	White	None	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W4	Wood	Black	None	0	N/A	N/A
1400	1	B	07B	Art Room	yes	W4	Sheetrock	White	None	0	N/A	N/A
1400	1	B	07B	Art Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	07B	Art Room	yes	Ceiling	Plaster	White	Flaking	2	7.9	Positive
1400	1	B	07B-A	Art Room Storage	yes	W1	Brick	White	Chipping	1	10.2	Positive
1400	1	B	07B-A	Art Room Storage	yes	W2	Brick	White	None	0	N/A	N/A
1400	1	B	07B-A	Art Room Storage	yes	W2	Plaster	White	Cracking	1	7.8	Positive
1400	1	B	07B-A	Art Room Storage	yes	W3	Brick	White	None	0	N/A	N/A
1400	1	B	07B-A	Art Room Storage	yes	W4	Brick	White	Chipping	1	12.4	Positive
1400	1	B	07B-A	Art Room Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	07B-A	Art Room Storage	yes	Ceiling	Plaster	White	Cracking	1	9.9	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1400	1	B	07B-A	Art Room Storage	yes	Boiler Breeching (Ceiling)	Metal	White	Chipping	1	0.3	Negative
1400	1	B	05B	Boy's Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1400	1	B	05B	Boy's Restroom	yes	W2	Brick	White	None	0	N/A	N/A
1400	1	B	05B	Boy's Restroom	yes	W2	Plaster	White	Chipping	1	5.4	Positive
1400	1	B	05B	Boy's Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1400	1	B	05B	Boy's Restroom	yes	W4	Plaster	White	Spalling	1	8.6	Positive
1400	1	B	05B	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	05B	Boy's Restroom	yes	Ceiling	Plaster	White	Flaking	5	7.5	Positive
1400	1	B	S01A	Stairwell	yes	W1	Metal	Grey	Friction	1	0.2	Negative
1400	1	B	S01A	Stairwell	yes	W2	Brick	Tan	None	0	N/A	N/A
1400	1	B	S01A	Stairwell	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	S01A	Stairwell	yes	W4	Brick	Tan	None	0	N/A	N/A
1400	1	B	S01A	Stairwell	yes	Floor	Concrete	Grey	Friction	5	2.3	Positive
1400	1	B	S01A	Stairwell	yes	Ceiling	Plaster	Tan	Chipping	1	4.3	Positive
1400	1	B	020B	Storage next to Boy's Restroom	no	W1	Plaster	White	Cracking	1	8.8	Positive
1400	1	B	020B	Storage next to Boy's Restroom	no	W1	Brick	White	Flaking	5	10.2	Positive
1400	1	B	020B	Storage next to Boy's Restroom	no	Door Frame (W1)	Metal	Grey	None	0	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	Door (W1)	Metal	Grey	None	0	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	Vertical Pipe (W1)	Metal	White	None	0	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	W2	Brick	White	Flaking	5	10.9	Positive
1400	1	B	020B	Storage next to Boy's Restroom	no	W3	Brick	White	Chipping	3	11.2	Positive
1400	1	B	020B	Storage next to Boy's Restroom	no	W3	Brick	Tan	None	0	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	W3	Plaster	White	None	0	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	W3	Plaster	Tan	None	0	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	Vertical Pipe (W3)	Metal	White	Chipping	1	0.3	Negative
1400	1	B	020B	Storage next to Boy's Restroom	no	Vertical Pipe (W3)	Metal	Tan	Chipping	1	0.4	Negative
1400	1	B	020B	Storage next to Boy's Restroom	no	W4	Plaster	White	None	0	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	B	020B	Storage next to Boy's Restroom	no	Boiler Breeching (Ceiling)	Metal	White	None	0	N/A	N/A
1400	1	B	H02	Hallway outside Kitchen	yes	W1	Brick	White	Cracking	1	13.3	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W1	Brick	N/A	None	0	N/A	N/A
1400	1	B	H02	Hallway outside Kitchen	yes	Cove Base (W1)	Brick	Grey	Chipping	1	4.5	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	Door (W1)	Metal	Black	None	0	N/A	N/A
1400	1	B	H02	Hallway outside Kitchen	yes	W2	Brick	White	Chipping	1	15.5	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W2	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	H02	Hallway outside Kitchen	yes	Cove Base (W2)	Brick	Grey	Chipping	10	3.4	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	B	H02	Hallway outside Kitchen	yes	Door (W2)	Metal	Black	Chipping	1	0	Negative
1400	1	B	H02	Hallway outside Kitchen	yes	W2	Metal	Grey	Chipping	1	0.03	Negative
1400	1	B	H02	Hallway outside Kitchen	yes	W2	Brick	Black	Flaking	1	2.4	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W3	Brick	White	Flaking	5	14.4	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W3	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	H02	Hallway outside Kitchen	yes	W3	Brick	Black	Chipping	1	3.4	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W3	Plaster	White	Cracking	1	12.3	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W3	Metal	Black	Chipping	1	0	Negative
1400	1	B	H02	Hallway outside Kitchen	yes	W3	Concrete	Black	Chipping	10	17.2	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W3	Concrete	Black	Chipping	10	2.8	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W3	Concrete	Black	Chipping	5	5.4	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W4	Brick	White	Cracking	5	11.4	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W4	Brick	N/A	N/A	0	N/A	N/A
1400	1	B	H02	Hallway outside Kitchen	yes	W4	Brick	Grey	Chipping	15	3.2	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	W4	Wood	White	Chipping	5	5.3	Positive
1400	1	B	H02	Hallway outside Kitchen	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1400	1	B	H02	Hallway outside Kitchen	yes	Ceiling	Plaster	White	Flaking	5	14.1	Positive
1400	1	B	014B	Kitchen	no	W1	Plaster	Pink	Flaking	10	13.1	Positive
1400	1	B	014B	Kitchen	no	W1	Plaster	White	Flaking	5	1.3	Positive
1400	1	B	014B	Kitchen	no	W1	Brick	Pink	Cracking	2	8.8	Positive
1400	1	B	014B	Kitchen	no	W1	Brick	White	Cracking	1	7.9	Positive
1400	1	B	014B	Kitchen	no	W1	Wood	Brown	Friction	5	0	Negative
1400	1	B	014B	Kitchen	no	W1	Metal	Brown	Friction	2	0.08	Negative
1400	1	B	014B	Kitchen	no	W2	Plaster	Pink	Flaking	5	10.1	Positive
1400	1	B	014B	Kitchen	no	W2	Plaster	White	Cracking	2	7.8	Positive
1400	1	B	014B	Kitchen	no	W2	Brick	White	Cracking	5	5.7	Positive
1400	1	B	014B	Kitchen	no	W3	Plaster	Pink	Flaking	20	13.8	Positive
1400	1	B	014B	Kitchen	no	W3	Plaster	White	Cracking	5	7.6	Positive
1400	1	B	014B	Kitchen	no	W3	Brick	White	Cracking	5	10.2	Positive
1400	1	B	014B	Kitchen	no	W3	Metal	Pink	Flaking	5	10.8	Positive
1400	1	B	014B	Kitchen	no	W4	Plaster	Pink	Flaking	10	12.5	Positive
1400	1	B	014B	Kitchen	no	W4	Plaster	White	Flaking	5	10.9	Positive
1400	1	B	014B	Kitchen	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	014B	Kitchen	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	014C	Kitchen Storage	no	W1	Plaster	Tan	Flaking	10	10.2	Positive
1400	1	B	014C	Kitchen Storage	no	Door Frame (W1)	Metal	Brown	Friction	1	0.2	Negative
1400	1	B	014C	Kitchen Storage	no	W2	Plaster	Tan	None	0	N/A	N/A
1400	1	B	014C	Kitchen Storage	no	Shelving (W2)	Wood	Red	Friction	5	1.3	Positive
1400	1	B	014C	Kitchen Storage	no	W3	Plaster	Tan	Cracking	1	8.5	Positive
1400	1	B	014C	Kitchen Storage	no	Shelving (W3)	Wood	Red	Friction	2	3.2	Positive
1400	1	B	014C	Kitchen Storage	no	W4	Plaster	Tan	Cracking	3	5.4	Positive
1400	1	B	014C	Kitchen Storage	no	Shelving (W4)	Wood	Red	Friction	5	4.4	Positive
1400	1	B	014C	Kitchen Storage	no	Floor	Wood	Red	None	0	N/A	N/A
1400	1	B	014C	Kitchen Storage	no	Ceiling	Plaster	Tan	Cracking	5	6.8	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	B	014C	Kitchen Storage	no	Boiler Breeching (Ceiling)	Metal	Tan	None		0.2	Negative
1400	1	B	H01	Hallway behind Gym	yes	W1	Brick	White	Chipping	1	17.4	Positive
1400	1	B	H01	Hallway behind Gym	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	H01	Hallway behind Gym	yes	W1	Brick	Black	Chipping	5	1.7	Positive
1400	1	B	H01	Hallway behind Gym	yes	W1	Metal	Black	Friction	1	0	Negative
1400	1	B	H01	Hallway behind Gym	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	H01	Hallway behind Gym	yes	W3	Brick	White	Chipping	1	11.4	Positive
1400	1	B	H01	Hallway behind Gym	yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	H01	Hallway behind Gym	yes	W3	Brick	Black	Chipping	5	2.5	Positive
1400	1	B	H01	Hallway behind Gym	yes	W3	Wood	White	Chipping	1	8.4	Positive
1400	1	B	H01	Hallway behind Gym	yes	W3	Wood	Grey	Chipping	2	19	Positive
1400	1	B	H01	Hallway behind Gym	yes	W3	Metal	White	Chipping	5	0.03	Negative
1400	1	B	H01	Hallway behind Gym	yes	W4	Brick	White	Flaking	1	15.4	Positive
1400	1	B	H01	Hallway behind Gym	yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	H01	Hallway behind Gym	yes	W4	Brick	Black	Chipping	1	1.8	Positive
1400	1	B	H01	Hallway behind Gym	yes	W4	Metal	Black	Friction	1	0	Negative
1400	1	B	H01	Hallway behind Gym	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1400	1	B	H01	Hallway behind Gym	yes	Ceiling	Plaster	White	Flaking	15	19.4	Positive
1400	1	B	H01	Hallway behind Gym	yes	Ceiling	Metal	White	Flaking	1	16.4	Positive
1400	1	B	015B	Cafeteria	yes	W1	Plaster	Tan	Flaking	30	16.5	Positive
1400	1	B	015B	Cafeteria	yes	Door Frame (W1)	Metal	Green	Friction	1	0	Negative
1400	1	B	015B	Cafeteria	yes	W2	Plaster	Tan	Flaking	6	21	Positive
1400	1	B	015B	Cafeteria	yes	W3	Plaster	Tan	Cracking	6	18.6	Positive
1400	1	B	015B	Cafeteria	yes	W4	Plaster	Tan	Flaking	6	19.1	Positive
1400	1	B	015B	Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	015B	Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	015B-B	Restroom in Cafeteria	yes	W1	Plaster	Tan	Cracking	1	16.4	Positive
1400	1	B	015B-B	Restroom in Cafeteria	yes	W2	Plaster	Tan	Flaking	10	12.3	Positive
1400	1	B	015B-B	Restroom in Cafeteria	yes	Radiator (W2)	Metal	Tan	Chipping	1	0.3	Negative
1400	1	B	015B-B	Restroom in Cafeteria	yes	W3	Plaster	Tan	Flaking	10	15.4	Positive
1400	1	B	015B-B	Restroom in Cafeteria	yes	Radiator (W3)	Metal	Tan	None	0	N/A	N/A
1400	1	B	015B-B	Restroom in Cafeteria	yes	W4	Plaster	Tan	Flaking	5	13.3	Positive
1400	1	B	015B-B	Restroom in Cafeteria	yes	Radiator (W4)	Metal	Tan	Chipping	1	0.2	Negative
1400	1	B	015B-B	Restroom in Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	015B-B	Restroom in Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	016B	Cafeteria Storage	no	W1	Plaster	Tan	Cracking	1	3.4	Positive
1400	1	B	016B	Cafeteria Storage	no	W2	Plaster	Tan	Chipping	1	5.5	Positive
1400	1	B	016B	Cafeteria Storage	no	W3	Plaster	Tan	Cracking	1	12.2	Positive
1400	1	B	016B	Cafeteria Storage	no	W4	Plaster	Tan	Cracking	1	6.7	Positive
1400	1	B	016B	Cafeteria Storage	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	016B	Cafeteria Storage	no	Ceiling	Plaster	Tan	Flaking	2	10.9	Positive
1400	1	B	017B	Building Engineer's Office	no	W1	Plaster	Blue	Flaking	5	10.1	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	1	B	017B	Building Engineer's Office	no	Door Frame (W1)	Metal	Brown	Chipping	1	0	Negative
1400	1	B	017B	Building Engineer's Office	no	W2	Plaster	Blue	Cracking	1	15.2	Positive
1400	1	B	017B	Building Engineer's Office	no	W3	Plaster	Blue	Chipping	1	16.1	Positive
1400	1	B	017B	Building Engineer's Office	no	Vertical Pipe (W3)	Metal	Blue	Flaking	1	0.3	Negative
1400	1	B	017B	Building Engineer's Office	no	W4	Plaster	Blue	None	0	N/A	N/A
1400	1	B	017B	Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	017B	Building Engineer's Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	W1	Brick	White	Chipping	1	10.2	Positive
1400	1	B	018B	Girl's Restroom	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	Door Frame (W1)	Metal	Black	None	0	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	W2	Brick	White	None	0	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	W2	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	Vertical Pipe (W2)	Metal	White	None	0	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	W3	Brick	White	None	0	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	W3	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	W4	Brick	White	None	0	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	W4	Brick	N/A	N/A	N/A	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	B	018B	Girl's Restroom	no	Horizontal Pipe (Ceiling)	Metal	White	Cracking	15	0.4	Negative
1400	1	B	019B	Storage outside of Girl's Restroom	no	W1	Brick	White	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W1	Brick	Grey	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	Door Frame (W1)	Metal	Black	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W2	Brick	White	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W2	Brick	Grey	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W2	Plaster	White	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W2	Plaster	Grey	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W3	Brick	White	Chipping	1	12.1	Positive
1400	1	B	019B	Storage outside of Girl's Restroom	no	W3	Brick	Grey	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W3	Plaster	White	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W3	Plaster	Grey	Chipping	1	10.5	Positive
1400	1	B	019B	Storage outside of Girl's Restroom	no	Vertical Pipe (W3)	Metal	White	Chipping	1	0.3	Negative
1400	1	B	019B	Storage outside of Girl's Restroom	no	Vertical Pipe (W3)	Metal	Grey	Chipping	1	0.4	Negative
1400	1	B	019B	Storage outside of Girl's Restroom	no	W4	Brick	White	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	W4	Brick	Grey	Chipping	2	10.1	Positive
1400	1	B	019B	Storage outside of Girl's Restroom	no	Vertical Pipe (W4)	Metal	White	Chipping	1	0.4	Negative
1400	1	B	019B	Storage outside of Girl's Restroom	no	Vertical Pipe (W4)	Metal	Grey	Chipping	1	0.3	Negative

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
					no	Bathroom Door (W4)	Metal	Brown	Friction	3	0.1	Negative
1400	1	B	019B	Storage outside of Girl's Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	Ceiling	Plaster	White	None	0	N/A	N/A
1400	1	B	019B	Storage outside of Girl's Restroom	no	Boiler Breeching (Ceiling)	Metal	White	None	0	N/A	N/A
1400	1	B	S04A	Stairwell outside of Girl's Restroom	no	Door Frame (W1)	Metal	Grey	Friction	1	0.5	Negative
1400	1	B	S04A	Stairwell outside of Girl's Restroom	no	W2	Brick	Tan	None	0	N/A	N/A
1400	1	B	S04A	Stairwell outside of Girl's Restroom	no	W3	Brick	Tan	None	0	N/A	N/A
1400	1	B	S04A	Stairwell outside of Girl's Restroom	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1400	1	B	S04A	Stairwell outside of Girl's Restroom	no	Stairs (Floor)	Concrete	Grey	Friction	5	3.2	Positive
1400	1	B	S04A	Stairwell outside of Girl's Restroom	no	Ceiling	Plaster	Tan	None	0	N/A	N/A
1400	2	1	A1	Classroom A1	yes	W1	Sheetrock	Tan	Chipping	3	0.03	Negative
1400	2	1	A1	Classroom A1	yes	Shelving (W1)	Wood	White	Friction	5	0.9	Positive
1400	2	1	A1	Classroom A1	yes	Door Frame (W1)	Metal	Blue	Chipping	1	0.01	Negative
1400	2	1	A1	Classroom A1	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	A1	Classroom A1	yes	W3	Brick	White	Flaking	1	1.4	Positive
1400	2	1	A1	Classroom A1	yes	Window Stool (W3)	Wood	White	Cracking	1	0.3	Negative
1400	2	1	A1	Classroom A1	yes	Radiator (W3)	Metal	Grey	Chipping	1	0.4	Negative
1400	2	1	A1	Classroom A1	yes	Radiator (W3)	Metal	Tan	None	0	N/A	N/A
1400	2	1	A1	Classroom A1	yes	W4	Sheetrock	Tan	Chipping	2		
1400	2	1	A1	Classroom A1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	A1	Classroom A1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	A2	Classroom A2	yes	W1	Sheetrock	Tan	Chipping	3	0.1	Negative
1400	2	1	A2	Classroom A2	yes	Shelving (W1)	Wood	White	None	0	N/A	N/A
1400	2	1	A2	Classroom A2	yes	Door Frame (W1)	Metal	Blue	Friction	2	0.01	Negative
1400	2	1	A2	Classroom A2	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	A2	Classroom A2	yes	W3	Brick	White	None	0	N/A	N/A
1400	2	1	A2	Classroom A2	yes	Window Stool (W3)	Wood	White	Cracking	1	0.5	Negative
1400	2	1	A2	Classroom A2	yes	Radiator (W3)	Metal	Tan	None	0	N/A	N/A
1400	2	1	A2	Classroom A2	yes	W4	Sheetrock	Tan	Chipping	3	0.2	Negative
1400	2	1	A2	Classroom A2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	A2	Classroom A2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	A3	Classroom A3	yes	W1	Sheetrock	Tan	Chipping	1	0.1	Negative
1400	2	1	A3	Classroom A3	yes	Door Frame (W1)	Metal	Black	Chipping	1	0.03	Negative
1400	2	1	A3	Classroom A3	yes	Door Frame (W1)	Metal	White	Friction	1	0.01	Negative
1400	2	1	A3	Classroom A3	yes	Shelving (W1)	Wood	White	None	0	N/A	N/A
1400	2	1	A3	Classroom A3	yes	W2	Sheetrock	Tan	None	0	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	2	1	A3	Classroom A3	yes	W3	Brick	White	None	0	N/A	N/A
1400	2	1	A3	Classroom A3	yes	Window Stool (W3)	Wood	White	None	0	N/A	N/A
1400	2	1	A3	Classroom A3	yes	Radiator (W3)	Metal	White	None	0	N/A	N/A
1400	2	1	A3	Classroom A3	yes	W4	Sheetrock	Tan	Chipping	1	0.2	Negative
1400	2	1	A3	Classroom A3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	A3	Classroom A3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	A4	Classroom A4	yes	W1	Sheetrock	Tan	Chipping	1	0.02	Negative
1400	2	1	A4	Classroom A4	yes	Door Frame (W1)	Metal	Blue	Cracking	1	0.01	Negative
1400	2	1	A4	Classroom A4	yes	Shelving (W1)	Wood	White	None	0	N/A	N/A
1400	2	1	A4	Classroom A4	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	A4	Classroom A4	yes	W3	Brick	White	None	0	N/A	N/A
1400	2	1	A4	Classroom A4	yes	Window Stool (W3)	Wood	White	None	0	N/A	N/A
1400	2	1	A4	Classroom A4	yes	Radiator (W3)	Metal	Tan	None	0	N/A	N/A
1400	2	1	A4	Classroom A4	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	A4	Classroom A4	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	A4	Classroom A4	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	1	Storage Room in Rear Corridor	no	W1	Sheetrock	White	None	0	N/A	N/A
1400	2	1	1	Storage Room in Rear Corridor	no	Door Frame (W1)	Metal	Blue	Chipping	1	0.01	Negative
1400	2	1	1	Storage Room in Rear Corridor	no	W2	Sheetrock	White	Chipping	1	0	Negative
1400	2	1	1	Storage Room in Rear Corridor	no	W3	Brick	White	Flaking	5	4.7	Positive
1400	2	1	1	Storage Room in Rear Corridor	no	W3	Brick	Grey	Chipping	1	5.5	Positive
1400	2	1	1	Storage Room in Rear Corridor	no	W4	Brick	White	Alligating	20	3.4	Positive
1400	2	1	1	Storage Room in Rear Corridor	no	Window Stool (W4)	Wood	White	Chipping	3	1.4	Positive
1400	2	1	1	Storage Room in Rear Corridor	no	Vertical Pipe (W4)	Fiberglass	White	Flaking	5	0.03	Negative
1400	2	1	1	Storage Room in Rear Corridor	no	Radiator (W4)	Metal	White	Chipping	1	2.3	Positive
1400	2	1	1	Storage Room in Rear Corridor	no	W4	Brick	Grey	Chipping	3	0.44	Negative
1400	2	1	1	Storage Room in Rear Corridor	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	1	Storage Room in Rear Corridor	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	W1	Sheetrock	White	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	Moulding (W1)	Wood	Tan	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	W2	Sheetrock	White	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	Door Frame (W2)	Metal	Blue	Chipping	1	0.03	Negative
1400	2	1	H1	Hallway Rear Corridor	yes	W3	Brick	Tan	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	W3	Brick	White	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	Window Stool (W3)	Wood	White	Cracking	2	0.9	Positive

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	2	1	H1	Hallway Rear Corridor	yes	Radiator (W3)	Metal	Tan	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	W4	Brick	Tan	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	W4	Brick	White	None	0	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H1	Hallway Rear Corridor	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	W1	Sheetrock	White	None	0	N/A	N/A
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	Moulding (W1)	Wood	Tan	None	0	N/A	N/A
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	Door Frame (W1)	Metal	Blue	Friction	1	0.02	Negative
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	W2	Sheetrock	Tan	Chipping	15	0	Negative
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	W2	Sheetrock	White	Chipping	2	0.01	Negative
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	Moulding (W1)	Wood	Tan	Chipping	10	0.1	Negative
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	Door Frame (W1)	Metal	Blue	Friction	1	0	Negative
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	W4	Brick	White	Flaking	5	3.3	Positive
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	Window Stool (W4)	Wood	White	Flaking	5	6.4	Positive
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	Radiator (W4)	Metal	Tan	None	0	N/A	N/A
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H2	Hallway between Classrooms A1 & A4	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H3	Hallway in front of Boys Restroom	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	H3	Hallway in front of Boys Restroom	yes	W1	Sheetrock	White	Chipping			
1400	2	1	H3	Hallway in front of Boys Restroom	yes	Moulding (W1)	Wood	Tan	None	0	N/A	N/A
1400	2	1	H3	Hallway in front of Boys Restroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H3	Hallway in front of Boys Restroom	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	H3	Hallway in front of Boys Restroom	yes	W3	Sheetrock	White	Chipping			
1400	2	1	H3	Hallway in front of Boys Restroom	yes	Moulding (W3)	Wood	Tan	None	0	N/A	N/A
1400	2	1	H3	Hallway in front of Boys Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H3	Hallway in front of Boys Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H3	Hallway in front of Boys Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	W1	Brick	White	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	W1	Brick	Tan	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	Double Doors (W1)	Metal	Brown	Chipping	1	0	Negative
1400	2	1	H4	Hallway near Administrative Office	yes	Door Frame (W1)	Metal	Grey	Friction	3	0.1	Negative
1400	2	1	H4	Hallway near Administrative Office	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	W2	Sheetrock	White	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	Door Frame (W2)	Metal	Blue	Chipping	3	0.01	Negative

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	2	1	H4	Hallway near Administrative Office	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	W3	Sheetrock	White	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	Moulding (W3)	Wood	Tan	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	W4	Sheetrock	White	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	Moulding (W4)	Wood	Tan	None	0	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	H4	Hallway near Administrative Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	W1	Sheetrock	White	Flaking	1	0.02	Negative
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Door Frame (W1)	Metal	Blue	Friction	1	0.1	Negative
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	W2	Brick	White	Cracking	3	3.4	Positive
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Electrical Conduits (W2)	Metal	White	None	0	N/A	N/A
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Panel Box (W2)	Metal	Grey	None	0	N/A	N/A
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	W3	Brick	White	Flaking	5	5.5	Positive
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Vertical Pipe (W3)	Metal	White	Flaking	5	1.3	Positive
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Radiator (W3)	Metal	White	None	0	N/A	N/A
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Window Stool (W3)	Wood	White	Cracking	1	3.2	Positive
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	W4	Sheetrock	White	Moisture Damage	1	0.4	Negative
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Sink (W4)	Metal	White	None	0	N/A	N/A
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1400	2	1	2	Slop Sink Room at the End of the Hallway	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	6	Office	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	6	Office	yes	Door Frame (W1)	Metal	Blue	Friction	1	0.03	Negative
1400	2	1	6	Office	yes	W2	Brick	White	Cracking	3	1.3	Positive
1400	2	1	6	Office	yes	Radiator (W2)	Metal	White	None	0	N/A	N/A
1400	2	1	6	Office	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	6	Office	yes	Door Frame (W3)	Metal	Blue	Friction	1	0.01	Negative
1400	2	1	6	Office	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	6	Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	6	Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	7	Staff Restroom next to Office	yes	W1	Sheetrock	Tan	Cracking	2	0.1	Negative
1400	2	1	7	Staff Restroom next to Office	yes	Door Frame (W1)	Metal	Black	Friction	3	0	Negative
1400	2	1	7	Staff Restroom next to Office	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	7	Staff Restroom next to Office	yes	W2	Sheetrock	Purple	None	0	N/A	N/A
1400	2	1	7	Staff Restroom next to Office	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	7	Staff Restroom next to Office	yes	W3	Sheetrock	Purple	None	0	N/A	N/A
1400	2	1	7	Staff Restroom next to Office	yes	W4	Sheetrock	Tan	None	0	N/A	N/A

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1400	2	1	7	Staff Restroom next to Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	7	Staff Restroom next to Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	8	Mechanical Room behind Office	no	W1	Sheetrock	White	None	0	N/A	N/A
1400	2	1	8	Mechanical Room behind Office	no	Door Frame (W1)	Metal	Blue	None	0	N/A	N/A
1400	2	1	8	Mechanical Room behind Office	no	W2	Sheetrock	White	None	0	N/A	N/A
1400	2	1	8	Mechanical Room behind Office	no	W3	Sheetrock	White	None	0	N/A	N/A
1400	2	1	8	Mechanical Room behind Office	no	W4	Sheetrock	White	None	0	N/A	N/A
1400	2	1	8	Mechanical Room behind Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	8	Mechanical Room behind Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	W1	Sheetrock	Tan	Chipping	3	0.1	Negative
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	W1	Sheetrock	Purple	None	0	N/A	N/A
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	Door Frame (W1)	Metal	Blue	Friction	1	0.03	Negative
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	W2	Sheetrock	Tan	Chipping	1	0.01	Negative
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	W3	Brick	Tan	Cracking	5	0.9	Positive
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	Window Stool (W3)	Wood	Tan	Chipping	3	0.3	Negative
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	Radiator (W3)	Metal	Tan	Friction	1	0.5	Negative
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	Vertical Pipe (W3)	Plastic	Tan	Flaking	3	0.1	Negative
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	W4	Sheetrock	Tan	None	0	N/A	N/A
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	N/A	Kitchen Next to Staff Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1400	2	1	A	Attic- 3rd - near SE Stairs/Rm 304	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1400	2	1	A	Attic- 3rd - near SE Stairs/Rm 304	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1400	2	1	A	Attic- 3rd - near SE Stairs/Rm 304	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	AT	A	Attic- 3rd - near SE Stairs/Rm 304	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	AT	A	Attic- 3rd - near SE Stairs/Rm 304	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	AT	A	Attic- 3rd - near SE Stairs/Rm 304	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	CS	C	Crawl Space	No Access	W1	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	CS	C	Crawl Space	No Access	W2	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	CS	C	Crawl Space	No Access	W3	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 2/17/20-2/24/20		School District of Philadelphia						
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs, Inc.		Patterson Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1400	1	CS	C	Crawl Space	No Access	W4	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	CS	C	Crawl Space	No Access	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1400	1	CS	C	Crawl Space	No Access	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access