

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	B	1	Girl's Restroom by Classroom 003	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	1	Girl's Restroom by Classroom 003	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	1	Girl's Restroom by Classroom 003	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	1	Girl's Restroom by Classroom 003	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	1	Girl's Restroom by Classroom 003	yes	Ceiling	Concrete	Beige	Flaking	100	12.5	Positive
6350	1	B	1	Girl's Restroom by Classroom 003	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	13	Storage Room outside of Girl's Restroom - South Hallway	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	B	13	Storage Room outside of Girl's Restroom - South Hallway	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	B	13	Storage Room outside of Girl's Restroom - South Hallway	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	B	13	Storage Room outside of Girl's Restroom - South Hallway	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	B	13	Storage Room outside of Girl's Restroom - South Hallway	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	13	Storage Room outside of Girl's Restroom - South Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	2	Teacher's Lounge/Food Service Room next to Classroom 003	yes	W1	Concrete	Beige	None	0	N/A	N/A
6350	1	B	2	Teacher's Lounge/Food Service Room next to Classroom 003	yes	W2	Drywall/CMU	Beige	None	0	N/A	N/A
6350	1	B	2	Teacher's Lounge/Food Service Room next to Classroom 003	yes	W3	Plaster	Beige	Moisture	40	0.04	Negative
6350	1	B	2	Teacher's Lounge/Food Service Room next to Classroom 003	yes	W4	CMU	Beige	None	0	N/A	N/A
6350	1	B	2	Teacher's Lounge/Food Service Room next to Classroom 003	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	2	Teacher's Lounge/Food Service Room next to Classroom 003	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	002A	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	002A	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	002A	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	002A	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	002A	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
6350	1	B	002A	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	3	Pre-Kindergarten Classroom 003	yes	W1	Concrete	Beige	Chipping	10	0.05	Negative
6350	1	B	3	Pre-Kindergarten Classroom 003	yes	W2	Concrete	Beige	Cracking	25	0	Negative
6350	1	B	3	Pre-Kindergarten Classroom 003	yes	W3	Concrete/CMU	Beige	None	0	N/A	N/A
6350	1	B	3	Pre-Kindergarten Classroom 003	yes	W4	CMU	Beige	None	0	N/A	N/A
6350	1	B	3	Pre-Kindergarten Classroom 003	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	3	Pre-Kindergarten Classroom 003	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	003A	Pre-Kindergarten Classroom 003 Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	003A	Pre-Kindergarten Classroom 003 Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	003A	Pre-Kindergarten Classroom 003 Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	003A	Pre-Kindergarten Classroom 003 Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	003A	Pre-Kindergarten Classroom 003 Restroom	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
6350	1	B	003A	Pre-Kindergarten Classroom 003 Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	003B	Pre-Kindergarten Classroom 003 Storage Closet	yes	W1	Plaster	Beige	Efflorescenc/Cracking	30	0.12	Negative
6350	1	B	003B	Pre-Kindergarten Classroom 003 Storage Closet	yes	W2	Plaster	Beige	Cracking	15	0.12	Negative

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	B	003B	Pre-Kindergarten Classroom 003 Storage Closet	yes	W3	Plaster	Beige	Cracking	20	0.24	Negative
6350	1	B	003B	Pre-Kindergarten Classroom 003 Storage Closet	yes	W4	Plaster	Beige	Cracking	20	0.24	Negative
6350	1	B	003B	Pre-Kindergarten Classroom 003 Storage Closet	yes	Ceiling	Plaster	NA	N/A	N/A	N/A	N/A
6350	1	B	003B	Pre-Kindergarten Classroom 003 Storage Closet	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	H03	Hallway from Girl's Restroom to Classroom 003	yes	W1	Brick	Beige	None	0	11.2	Positive
6350	1	B	H03	Hallway from Girl's Restroom to Classroom 003	yes	W2	Brick	Beige	None	0	10.9	Positive
6350	1	B	H03	Hallway from Girl's Restroom to Classroom 003	yes	W3	Brick	Beige	None	0	9.9	Positive
6350	1	B	H03	Hallway from Girl's Restroom to Classroom 003	yes	W4	Brick	Beige	None	0	7	Positive
6350	1	B	H03	Hallway from Girl's Restroom to Classroom 003	yes	Ceiling	Concrete	Beige	Holes	5	11.7	Positive
6350	1	B	H03	Hallway from Girl's Restroom to Classroom 003	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	S02	Stairwell outside Classroom 003	yes	W1	Plaster	Beige	None	0	11.5	Positive
6350	1	B	S02	Stairwell outside Classroom 003	yes	W2	Plaster	Beige	None	0	15.4	Positive
6350	1	B	S02	Stairwell outside Classroom 003	yes	W3	Plaster	Beige	None	0	11	Positive
6350	1	B	S02	Stairwell outside Classroom 003	yes	W4	Plaster	Beige	None	0	9.5	Positive
6350	1	B	S02	Stairwell outside Classroom 003	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	B	S02	Stairwell outside Classroom 003	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	Stair Stringer	Metal	Blue	Friction	25	0	Negative
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	Stair Tred	Metal	Blue	Friction	25	0.01	Negative
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	Stair Riser	Metal	Blue	Friction	25	0.25	Negative
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	Stair Ballast	Metal	Blue	Friction	20	2.3	Positive
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	Stair Newel Post	Metal	Blue	Friction	25	1.7	Positive
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	Ceiling	Concrete	Beige	Flaking/Moisture	200	23.4	Positive
6350	1	B	S03	Stairwell outside Girl's Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	H02	Center Hallway outside Classroom 004	yes	W1	Brick	Beige	None	0	N/A	N/A
6350	1	B	H02	Center Hallway outside Classroom 004	yes	W2	Brick	Beige	None	0	N/A	N/A
6350	1	B	H02	Center Hallway outside Classroom 004	yes	W3	Brick	Beige	None	0	N/A	N/A
6350	1	B	H02	Center Hallway outside Classroom 004	yes	W4	Brick	Beige	None	0	N/A	N/A
6350	1	B	H02	Center Hallway outside Classroom 004	yes	Ceiling	Concrete	Beige	Holes	5	11.7	Positive
6350	1	B	H02	Center Hallway outside Classroom 004	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	4	Classroom 004	yes	W1	Brick	Beige	Moisture/Flaking	40	12.8	Positive
6350	1	B	4	Classroom 004	yes	W2	Brick	Beige	None	0	13.8	Positive
6350	1	B	4	Classroom 004	yes	W3	Brick	Beige	None	0	11.8	Positive
6350	1	B	4	Classroom 004	yes	W4	Brick	Beige	None	0	10.1	Positive
6350	1	B	4	Classroom 004	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	B	4	Classroom 004	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	004A	Classroom 004 Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	004A	Classroom 004 Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	004A	Classroom 004 Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	004A	Classroom 004 Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	004A	Classroom 004 Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	B	004A	Classroom 004 Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	12	Boiler Room	no	W1	Concrete	Pink/Whire	Flaking/Moistuer	500	0.8	Positive

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	B	12	Boiler Room	no	W2	Concrete	Pink/Whire	Flaking/Moistuer	500	0.9	Positive
6350	1	B	12	Boiler Room	no	W3	Concrete	Pink/Whire	Flaking/Moistuer	500	1	Positive
6350	1	B	12	Boiler Room	no	W4	Concrete	Pink/Whire	Flaking/Moistuer	1,000	1.1	Positive
6350	1	B	12	Boiler Room	no	Ceiling	Concrete	Metal/Concrete	Flaking/Chipping	450	2.2	Positive
6350	1	B	12	Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	012A	Fan Room	no	W1	Concrete	White	Flaking/Chipping	550	12.5	Positive
6350	1	B	012A	Fan Room	no	W2	Concrete	White	Flaking/Chipping	400	21.5	Positive
6350	1	B	012A	Fan Room	no	W3	Concrete	White	Flaking/Chipping	400	16.8	Positive
6350	1	B	012A	Fan Room	no	W4	Concrete	White	Flaking/Chipping	350	19	Positive
6350	1	B	012A	Fan Room	no	Ceiling	Concrete	White	Flaking/Chipping	250	N/A	N/A
6350	1	B	012A	Fan Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	012B	Old Ash Room/Storage Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	012B	Old Ash Room/Storage Room	no	W1	Concrete	Black	Flaking	100	23	Positive
6350	1	B	012B	Old Ash Room/Storage Room	no	W2	Concrete	Black	Flaking	100	29.4	Positive
6350	1	B	012B	Old Ash Room/Storage Room	no	W3	Concrete	Black	Flaking	100	19.5	Positive
6350	1	B	012B	Old Ash Room/Storage Room	no	W4	Concrete	Black	Flaking	100	30	Positive
6350	1	B	012B	Old Ash Room/Storage Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	012C	Old Coal Storage Room/Storage Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	012C	Old Coal Storage Room/Storage Room	no	W1	Concrete	White	Flaking	100	22.6	Positive
6350	1	B	012C	Old Coal Storage Room/Storage Room	no	W2	Concrete	White	Flaking	100	21.5	Positive
6350	1	B	012C	Old Coal Storage Room/Storage Room	no	W3	Concrete	White	Flaking	100	27	Positive
6350	1	B	012C	Old Coal Storage Room/Storage Room	no	W4	Concrete	White	Flaking	100	27.6	Positive
6350	1	B	012C	Old Coal Storage Room/Storage Room	no	Ceiling	Concrete	White	Flaking	100	17	Positive
6350	1	B	012D	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	yes	W1	Brick	Beige	None	0	N/A	N/A
6350	1	B	012D	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	yes	W2	Brick	Beige	None	0	N/A	N/A
6350	1	B	012D	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	yes	W3	Brick	Beige	Chipping	5	1.7	Positive
6350	1	B	012D	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	yes	W4	Brick	Beige	None	0	N/A	N/A
6350	1	B	012D	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	yes	Ceiling	Concrete	Beige	acking/Flaking/Moisture	20	10.9	Positive
6350	1	B	012D	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	5	Gym/Cafeteria	yes	W1	Brick	White	None	0	N/A	N/A
6350	1	B	5	Gym/Cafeteria	yes	W2	Brick	White	None	0	N/A	N/A
6350	1	B	5	Gym/Cafeteria	yes	Stair Handrail (W2)	Metal	Black	Friction	10	2.5	Positive
6350	1	B	5	Gym/Cafeteria	yes	Stair Tred (W2)	Concrete	Red	Frictin/Chipping	25	0.8	Negative
6350	1	B	5	Gym/Cafeteria	yes	Stair Riser (W2)	Concrete	Red	Frictin/Chipping	25	0.9	Negative
6350	1	B	5	Gym/Cafeteria	yes	W3	Brick	White	None	0	N/A	N/A
6350	1	B	5	Gym/Cafeteria	yes	W4	Brick	White	None	0	N/A	N/A
6350	1	B	5	Gym/Cafeteria	yes	Ceiling	Concrete	White	ence/Flaking/Moisture	200	3.5	Positive
6350	1	B	5	Gym/Cafeteria	yes	Duct Work (Ceiling)	Metal	White	Flaking	100	5.6	Positive
6350	1	B	5	Gym/Cafeteria	yes	Pipe (Ceiling)	Metal	White	Flaking	80	9.4	Positive
6350	1	B	5	Gym/Cafeteria	yes	Radiator (Ceiling)	Metal	White	Flaking	80	2.5	Positive
6350	1	B	5	Gym/Cafeteria	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	005A	Kitchen inside Gym/Cafeteria	yes	W1	Brick	Beige	None	0	2.3	Positive

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	B	005A	Kitchen inside Gym/Cafeteria	yes	W2	Brick	Beige	None	0	2.9	Positive
6350	1	B	005A	Kitchen inside Gym/Cafeteria	yes	W3	Brick	Beige	None	0	1.7	Positive
6350	1	B	005A	Kitchen inside Gym/Cafeteria	yes	W4	Brick	Beige	None	0	5	Positive
6350	1	B	005A	Kitchen inside Gym/Cafeteria	yes	Door Window Frame (W	Metal	Red	Friction	10	0.01	Negative
6350	1	B	005A	Kitchen inside Gym/Cafeteria	yes	Door Frame (W4)	Metal	Red	Friction	15	0.19	Negative
6350	1	B	005A	Kitchen inside Gym/Cafeteria	yes	Ceiling	Concrete	N/A	None	0	N/A	N/A
6350	1	B	005A	Kitchen inside Gym/Cafeteria	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	005B	Gym Storage Room	yes	W1	Brick	Beige	Flaking	20	1.8	Positive
6350	1	B	005B	Gym Storage Room	yes	W2	Brick	Beige	None	0	2.9	Positive
6350	1	B	005B	Gym Storage Room	yes	W3	Brick	Beige	Moisture	150	2.3	Positive
6350	1	B	005B	Gym Storage Room	yes	W4	Beick	Beige	None	0	1.7	Positive
6350	1	B	005B	Gym Storage Room	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A
6350	1	B	005B	Gym Storage Room	yes	Floor	Concrete	N/A	None	0	N/A	N/A
6350	1	B	005C	Gym Vestibule to School Yard	yes	W1	Brick	Beige	Flaking/Cracking	20	5.3	Positive
6350	1	B	005C	Gym Vestibule to School Yard	yes	W2	Brick	Beige	Flaking/Cracking	50	7.8	Positive
6350	1	B	005C	Gym Vestibule to School Yard	yes	W3	Brick	Beige	Flaking/Cracking	50	9	Positive
6350	1	B	005C	Gym Vestibule to School Yard	yes	W4	Brick	Beige	Flaking/Cracking	25	4.6	Positive
6350	1	B	005C	Gym Vestibule to School Yard	yes	Ceiling	Plaster	Beige	Efflorescence/Flaking	100	4.4	Positive
6350	1	B	005C	Gym Vestibule to School Yard	yes	Pipe (Ceiling/W3)	Metal	Beige	Flaking	20	1.5	Positive
6350	1	B	005C	Gym Vestibule to School Yard	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	H01	Hallway from Boy's Restroom to Classroom 008	yes	W1	Brick	Beige	Flaking	5	14.8	Positive
6350	1	B	H01	Hallway from Boy's Restroom to Classroom 008	yes	W2	Brick	Beige	Chipping	8	7.8	Positive
6350	1	B	H01	Hallway from Boy's Restroom to Classroom 008	yes	Pipe (W2)	Metal	Beige	Chipping	8	1.6	Positive
6350	1	B	H01	Hallway from Boy's Restroom to Classroom 008	yes	W3	Brick	Beige	Chipping	8	7.8	Positive
6350	1	B	H01	Hallway from Boy's Restroom to Classroom 008	yes	W4	Brick	Beige	Flaking/Chipping	100	5.4	Positive
6350	1	B	H01	Hallway from Boy's Restroom to Classroom 008	yes	Pipe (W4)	Metal	Beige/Grey	Chipping	40	0.01	Negative
6350	1	B	H01	Hallway from Boy's Restroom to Classroom 008	yes	Ceiling	Plaster	Beige	Holes/Flaking/Cracking	150	11.9	Positive
6350	1	B	H01	Hallway from Boy's Restroom to Classroom 008	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	7	Boy's Restroom next to Classroom 009	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	7	Boy's Restroom next to Classroom 009	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	7	Boy's Restroom next to Classroom 009	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	7	Boy's Restroom next to Classroom 009	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	7	Boy's Restroom next to Classroom 009	yes	Ceiling	Plaster	Beige	Flaking	60	13.5	Positive
6350	1	B	7	Boy's Restroom next to Classroom 009	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	W1	Brick	Beige	Flaking	20	2.2	Positive
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	W2	Brick	Beige	None	0	N/A	N/A
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	W3	Brick	Beige	Holes	2	2.4	Positive
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	W4	Brick	Beige	None	0	N/A	N/A
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	Ceiling	Plaster	Beige	Holes	5	13.2	Positive
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	Stair Handrail	Metal	Red	Friction/Chipping	20	0.02	Negative
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	Stair Tred	Metal	Red	Friction/Chipping	20	0.1	Negative
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	Stair Stringer	Metal	Red	Friction/Chipping	20	0.14	Negative
6350	1	B	S04	Stairwell outside Boy's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	B	9	Classroom 009	yes	W1	Concrete	Beige	Cracking/Flaking	2	9.8	Positive
6350	1	B	9	Classroom 009	yes	W2	Concrete	Beige	None	0	N/A	N/A
6350	1	B	9	Classroom 009	yes	W3	Concrete	Beige	Alligating	40	8.9	Positive

				Inspection Dates: 11/6/19			School District of Philadelphia						
				Name of Inspector: Jessica Sewell			Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX			Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
6350	1	B	9	Classroom 009	yes	W4	CMU	Beige	None	0	N/A	N/A	
6350	1	B	9	Classroom 009	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
6350	1	B	9	Classroom 009	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	
6350	1	B	009A	Classroom 009 Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	B	009A	Classroom 009 Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	B	009A	Classroom 009 Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	B	009A	Classroom 009 Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	B	009A	Classroom 009 Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	B	009A	Classroom 009 Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	B	10	Classroom 010	yes	W1	Concrete	Beige	N/A	N/A	N/A	N/A	
6350	1	B	10	Classroom 010	yes	W2	CMU	Beige	N/A	N/A	N/A	N/A	
6350	1	B	10	Classroom 010	yes	W3	Concrete	Beige	N/A	N/A	N/A	N/A	
6350	1	B	10	Classroom 010	yes	W4	Concrete	Beige	N/A	N/A	N/A	N/A	
6350	1	B	10	Classroom 010	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
6350	1	B	10	Classroom 010	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	
6350	1	B	8	Classroom 008	yes	W1	Concrete	Beige	Cracking	4	1.6	Positive	
6350	1	B	8	Classroom 008	yes	W2	CMU	Beige	None	0	N/A	N/A	
6350	1	B	8	Classroom 008	yes	W3	Concrete	Beige	None	0	N/A	N/A	
6350	1	B	8	Classroom 008	yes	W4	Concrete	Beige	None	0	N/A	N/A	
6350	1	B	8	Classroom 008	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
6350	1	B	8	Classroom 008	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	
6350	1	B	008A	Classroom 008 Storage Closet	yes	W1	Plaster	Green	Flaking/Chipping	40	1.7	Positive	
6350	1	B	008A	Classroom 008 Storage Closet	yes	W2	Plaster	Green	Moisture Damage	30	9.5	Positive	
6350	1	B	008A	Classroom 008 Storage Closet	yes	W3	Plaster	Green	flaking/Moisture/Chipping	100	3.3	Positive	
6350	1	B	008A	Classroom 008 Storage Closet	yes	W4	Plaster	Green	Flaking	20	6	Positive	
6350	1	B	008A	Classroom 008 Storage Closet	yes	Ceiling	Plaster	White	Chipping/Flaking	20	10.1	Positive	
6350	1	B	008A	Classroom 008 Storage Closet	yes	Floor	Wood	Silver	None	0	N/A	N/A	
6350	1	B	S01	Stairwell outside Classroom 008	yes	W1	Plaster	Beige	None	0	N/A	N/A	
6350	1	B	S01	Stairwell outside Classroom 008	yes	W2	Plaster	Beige	Flaking	30	13.8	Positive	
6350	1	B	S01	Stairwell outside Classroom 008	yes	W3	Plaster	Beige	None	0	N/A	N/A	
6350	1	B	S01	Stairwell outside Classroom 008	yes	W4	Plaster	Beige	Cracking/Flaking	45	15	Positive	
6350	1	B	S01	Stairwell outside Classroom 008	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A	
6350	1	B	S01	Stairwell outside Classroom 008	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
6350	1	1	101	Classroom 101	yes	W1	Plaster	Beige	Chipping/Holes/Cracking/Flaking	50	11.5	Positive	
6350	1	1	101	Classroom 101	yes	W2	Plaster	Beige	Chipping/Holes	10	10	Positive	
6350	1	1	101	Classroom 101	yes	W3	Plaster	Beige	Chipping/Holes	50	9	Positive	
6350	1	1	101	Classroom 101	yes	W4	Plaster	Beige	flaking/Moisture Damage	25	5.6	Positive	
6350	1	1	101	Classroom 101	yes	Ceiling	Plaster	Beige	Moisture Damage/Efflorescence	60	14	Positive	
6350	1	1	101	Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
6350	1	1	101A	Classroom 101 Boy's Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	1	101A	Classroom 101 Boy's Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	1	101A	Classroom 101 Boy's Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	1	101A	Classroom 101 Boy's Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	1	101A	Classroom 101 Boy's Restroom	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A	
6350	1	1	101A	Classroom 101 Boy's Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	1	101B	Classroom 101 Girl's Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	1	101B	Classroom 101 Girl's Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	101B	Classroom 101 Girl's Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	101B	Classroom 101 Girl's Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	101B	Classroom 101 Girl's Restroom	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
6350	1	1	101B	Classroom 101 Girl's Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	101C	Classroom 101 Storage Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	1	101C	Classroom 101 Storage Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	1	101C	Classroom 101 Storage Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	1	101C	Classroom 101 Storage Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	1	101C	Classroom 101 Storage Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	101C	Classroom 101 Storage Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	114	Women's Restroom next to Classroom 101	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	114	Women's Restroom next to Classroom 101	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	114	Women's Restroom next to Classroom 101	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	114	Women's Restroom next to Classroom 101	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	114	Women's Restroom next to Classroom 101	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	114	Women's Restroom next to Classroom 101	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	S13	Stairwell outside Classroom 101	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S13	Stairwell outside Classroom 101	yes	W2	Plaster	Beige	Flaking	10	14	Positive
6350	1	1	S13	Stairwell outside Classroom 101	yes	W3	Plaster	Beige	Cracking/Chipping	25	16.7	Positive
6350	1	1	S13	Stairwell outside Classroom 101	yes	W4	Plaster	Beige	Damage/Efflorescence	150	3.7	Positive
6350	1	1	S13	Stairwell outside Classroom 101	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	S13	Stairwell outside Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	102	Classroom 102	yes	W1	Plaster	Beige	Cracking	30	10.5	Positive
6350	1	1	102	Classroom 102	yes	W2	Plaster	Beige	Holes	5	9.5	Positive
6350	1	1	102	Classroom 102	yes	W3	Plaster	Beige	Flaking/Cracking	50	11	Positive
6350	1	1	102	Classroom 102	yes	W4	Plaster	Beige	Holes	10	14.3	Positive
6350	1	1	102	Classroom 102	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	102	Classroom 102	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	102A	Classroom 102 Coat Closet	yes	W1	Plaster	Beige	Cracking	30	8.9	Positive
6350	1	1	102A	Classroom 102 Coat Closet	yes	W2	Plaster	Beige	Cracking	30	9.1	Positive
6350	1	1	102A	Classroom 102 Coat Closet	yes	W3	Plaster	Beige	Cracking	30	15.7	Positive
6350	1	1	102A	Classroom 102 Coat Closet	yes	W4	Plaster	Beige	Cracking	30	7	Positive
6350	1	1	102A	Classroom 102 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	102A	Classroom 102 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	103	Room 103: School Police Office	yes	W1	Plaster	Beige	Cracking/Chipping	30	8.2	Positive
6350	1	1	103	Room 103: School Police Office	yes	W2	Plaster	Beige	Holes/Flaking	30	9.9	Positive
6350	1	1	103	Room 103: School Police Office	yes	W3	Plaster	Beige	Peeling/Flaking/Holes	25	11.3	Positive
6350	1	1	103	Room 103: School Police Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
6350	1	1	103	Room 103: School Police Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	103	Room 103: School Police Office	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	103A	Room 103 Restroom	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	103A	Room 103 Restroom	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	103A	Room 103 Restroom	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	103A	Room 103 Restroom	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	103A	Room 103 Restroom	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 11/6/19			School District of Philadelphia					
				Name of Inspector: Jessica Sewell			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			Pennypacker Elementary School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	1	103A	Room 103 Restroom	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	103B	Room 103 Coat Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	103B	Room 103 Coat Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	1	103B	Room 103 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	1	103B	Room 103 Coat Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	1	103B	Room 103 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	103B	Room 103 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	H16	Hallway from Classrooms 101 to 103	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	H16	Hallway from Classrooms 101 to 103	yes	Door (W1)	Metal	Blue	Friction	20	8.6	Positive
6350	1	1	H16	Hallway from Classrooms 101 to 103	yes	Door Frame (W1)	Metal	Blue	Friction	20	9.1	Positive
6350	1	1	H16	Hallway from Classrooms 101 to 103	yes	W2	Plaster	Beige	Holes/Cracking	15	6.3	Positive
6350	1	1	H16	Hallway from Classrooms 101 to 103	yes	W3	Plaster	Beige	None	0	N/A	N/A
6350	1	1	H16	Hallway from Classrooms 101 to 103	yes	W4	Plaster	Beige	Holes/Cracking	25	17	Positive
6350	1	1	H16	Hallway from Classrooms 101 to 103	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	H16	Hallway from Classrooms 101 to 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	S12	Stairwell outside Classroom 103	yes	W1	Plaster	Beige	Cracking/Moisture/Chipping	20	10	Positive
6350	1	1	S12	Stairwell outside Classroom 103	yes	W2	Plaster	Beige	Flaking/Cracking/Holes	50	9.8	Positive
6350	1	1	S12	Stairwell outside Classroom 103	yes	W3	Plaster	Beige	Cracking/Flaking	20	11	Positive
6350	1	1	S12	Stairwell outside Classroom 103	yes	W4	Plaster	Beige	Cracking/Flaking	100	14	Positive
6350	1	1	S12	Stairwell outside Classroom 103	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S12	Stairwell outside Classroom 103	yes	Crown Molding (Ceiling)	Plaster	Beige	Efflorescence	15	9.8	Positive
6350	1	1	S12	Stairwell outside Classroom 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	113	Girl's Restroom next to Classroom 104	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	113	Girl's Restroom next to Classroom 104	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	113	Girl's Restroom next to Classroom 104	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	113	Girl's Restroom next to Classroom 104	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	113	Girl's Restroom next to Classroom 104	yes	Pipe (W2)	Metal	Beige/Red	Chipping	12	11.4	Positive
6350	1	1	113	Girl's Restroom next to Classroom 104	yes	Ceiling	Plaster	Beige	Efflorescence/Flaking/Falling t	200	14.5	Positive
6350	1	1	113	Girl's Restroom next to Classroom 104	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	104	Classroom 104	yes	W1	Plaster	Beige	Cracking/Flaking/Chipping	50	11.9	Positive
6350	1	1	104	Classroom 104	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
6350	1	1	104	Classroom 104	yes	W3	Plaster	Beige	Cracking/Holes/Heat Damage	20	10	Positive
6350	1	1	104	Classroom 104	yes	W4	Plaster	Beige	Flaking/Chipping	40	9.9	Positive
6350	1	1	104	Classroom 104	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	104	Classroom 104	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	104A	Classroom 104 Coat Closet	yes	W1	Plaster	Beige	Chipping	100	7.9	Positive
6350	1	1	104A	Classroom 104 Coat Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	1	104A	Classroom 104 Coat Closet	yes	W3	Plaster	Beige	Chipping	100	8.8	Positive
6350	1	1	104A	Classroom 104 Coat Closet	yes	W4	Plaster	Beige	Peeling	15	7	Positive
6350	1	1	104A	Classroom 104 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	104A	Classroom 104 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	100	Main Office	yes	W1	Plaster	Beige	Hole	5	20	Positive
6350	1	1	100	Main Office	yes	W2	Plaster	Beige	Partially Inaccessible	0	22.8	Positive
6350	1	1	100	Main Office	yes	W3	Plaster	Beige	Partially Inaccessible	0	21	Positive
6350	1	1	100	Main Office	yes	W4	Plaster	Beige	Partially Inaccessible	0	19.9	Positive
6350	1	1	100	Main Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	1	100	Main Office	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	100D	Main Office Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100D	Main Office Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100D	Main Office Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100D	Main Office Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100D	Main Office Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100D	Main Office Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100A	Principal's Office	yes	W1	Plaster	Beige	Hole	16	27	Positive
6350	1	1	100A	Principal's Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	1	100A	Principal's Office	yes	W3	Plaster	Beige	Partially Inaccessible	0	22	Positive
6350	1	1	100A	Principal's Office	yes	W4	Plaster	Beige	Partially Inaccessible	0	19.8	Positive
6350	1	1	100A	Principal's Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	100A	Principal's Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
6350	1	1	100C	Principal's Office Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	100C	Principal's Office Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	100C	Principal's Office Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	100C	Principal's Office Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	100C	Principal's Office Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	100C	Principal's Office Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	100B	Principal's Office Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100B	Principal's Office Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100B	Principal's Office Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100B	Principal's Office Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100B	Principal's Office Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	100B	Principal's Office Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	105	Classroom 105	yes	W1	Plaster	Beige	Chipping	5	13.2	Positive
6350	1	1	105	Classroom 105	yes	W2	Plaster	Beige	Partition Wall	N/A	N/A	N/A
6350	1	1	105	Classroom 105	yes	W3	Plaster	Beige	Chipping	15	11.4	Positive
6350	1	1	105	Classroom 105	yes	W4	Sheetrock	Beige	Peeling	30	17.8	Positive
6350	1	1	105	Classroom 105	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	105	Classroom 105	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	105A	Classroom 105 Coat Closet	yes	W1	Plaster	Beige	Cracking	10	7.6	Positive
6350	1	1	105A	Classroom 105 Coat Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	1	105A	Classroom 105 Coat Closet	yes	W3	Plaster	Beige	Peeling	20	11	Positive
6350	1	1	105A	Classroom 105 Coat Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	10.8	Positive
6350	1	1	105A	Classroom 105 Coat Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
6350	1	1	105A	Classroom 105 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	S14	Stairs from Center Hallway to Auditorium across from Classroom 105	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S14	Stairs from Center Hallway to Auditorium across from Classroom 105	yes	W2	Plaster	Beige	Flaking	10	9	Positive
6350	1	1	S14	Stairs from Center Hallway to Auditorium across from Classroom 105	yes	W3	Plaster	Beige	Flaking	10	4.5	Positive

				Inspection Dates: 11/6/19	School District of Philadelphia							
				Name of Inspector: Jessica Sewell	Lead Safe Certification Assessment Report							
				Inspection Company: VERTEX	Pennypacker Elementary School							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	1	S14	Stairs from Center Hallway to Auditorium across from Classroom 105	yes	W4	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S14	Stairs from Center Hallway to Auditorium across from Classroom 105	yes	Ceiling	Plaster	White	Flaking/Efflorescence	10	10	Positive
6350	1	1	S14	Stairs from Center Hallway to Auditorium across from Classroom 105	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	116	Auditorium	yes	W1	Plaster	Beige	Flaking/Cracking	100	11.4	Positive
6350	1	1	116	Auditorium	yes	W2	Plaster	Beige	Efflorescence	50	19	Positive
6350	1	1	116	Auditorium	yes	Door (W2)	Metal	Beige	Friction/Chipping	20	6.7	Positive
6350	1	1	116	Auditorium	yes	Door Frame (W2)	Metal	Beige	Friction/Chipping	20	11	Positive
6350	1	1	116	Auditorium	yes	W3	Plaster	Beige	None	0	N/A	N/A
6350	1	1	116	Auditorium	yes	W4	Plaster	Beige	Efflorescence	50	12.5	Positive
6350	1	1	116	Auditorium	yes	Door (W4)	Metal	Beige	Friction/Chipping	20	7.6	Positive
6350	1	1	116	Auditorium	yes	Door Frame (W4)	Metal	Beige	Friction/Chipping	20	4	Positive
6350	1	1	116	Auditorium	yes	Ceiling	Plaster	Beige	Efflorescence/Flaking/Cracking	200	N/A	N/A
6350	1	1	116	Auditorium	yes	Floor	Wood	Varnish	None	N/A	N/A	N/A
6350	1	1	116A	Auditorium Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	116A	Auditorium Stage	yes	W2	Plaster	Beige	Cracking	20	11	Positive
6350	1	1	116A	Auditorium Stage	yes	W3	Plaster	Beige	Efflorescence/Flaking/Cracking	1,000	10.4	Positive
6350	1	1	116A	Auditorium Stage	yes	W4	Plaster	Beige	Cracking/Flaking	50	13.4	Positive
6350	1	1	116A	Auditorium Stage	yes	Ceiling	Metal	Beige	None	0	N/A	N/A
6350	1	1	116A	Auditorium Stage	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	117	Auditorium Stage Restroom - Left	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	117	Auditorium Stage Restroom - Left	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	117	Auditorium Stage Restroom - Left	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	117	Auditorium Stage Restroom - Left	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	117	Auditorium Stage Restroom - Left	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	117	Auditorium Stage Restroom - Left	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	118	Auditorium Stage Restroom - Right	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	118	Auditorium Stage Restroom - Right	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	118	Auditorium Stage Restroom - Right	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	118	Auditorium Stage Restroom - Right	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	118	Auditorium Stage Restroom - Right	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	118	Auditorium Stage Restroom - Right	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	1	S16	Stairs from Center Hallway to Auditorium across from Classroom 106	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S16	Stairs from Center Hallway to Auditorium across from Classroom 106	yes	W2	Plaster	Beige	Flaking	10	21	Positive
6350	1	1	S16	Stairs from Center Hallway to Auditorium across from Classroom 106	yes	W3	Plaster	Beige	Flaking	10	10	Positive
6350	1	1	S16	Stairs from Center Hallway to Auditorium across from Classroom 106	yes	W4	Plaster	Beige	None	0	N/A	N/A

				Inspection Dates: 11/6/19	School District of Philadelphia							
				Name of Inspector: Jessica Sewell	Lead Safe Certification Assessment Report							
				Inspection Company: VERTEX	Pennypacker Elementary School							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	1	S16	Stairs from Center Hallway to Auditorium across from Classroom 106	yes	Ceiling	Plaster	White	Flaking/Efflorescence	10	20	Positive
6350	1	1	S16	Stairs from Center Hallway to Auditorium across from Classroom 106	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	106	Classroom 106	yes	W1	Plaster	Beige	Chipping/Hole/Cracking	10	3.5	Positive
6350	1	1	106	Classroom 106	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
6350	1	1	106	Classroom 106	yes	W3	Plaster	Beige	Partially Inaccessible	0	9.9	Positive
6350	1	1	106	Classroom 106	yes	W4	Partition Wall	Beige	N/A	N/A	N/A	N/A
6350	1	1	106	Classroom 106	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	106	Classroom 106	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	106A	Classroom 106 Coat Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	10.4	Positive
6350	1	1	106A	Classroom 106 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	11.3	Positive
6350	1	1	106A	Classroom 106 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	6.7	Positive
6350	1	1	106A	Classroom 106 Coat Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	9.7	Positive
6350	1	1	106A	Classroom 106 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	106A	Classroom 106 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	115	Storage Room across from Classroom 106	yes	W1	Plaster	Yellow	Partially Inaccessible	0	10	Positive
6350	1	1	115	Storage Room across from Classroom 106	yes	W2	Plaster	Yellow	Flaking	100	14	Positive
6350	1	1	115	Storage Room across from Classroom 106	yes	W3	Plaster	Yellow	Cracking/Flaking	20	15.7	Positive
6350	1	1	115	Storage Room across from Classroom 106	yes	W4	Plaster	Yellow	Cracking	15	11.3	Positive
6350	1	1	115	Storage Room across from Classroom 106	yes	Ceiling	Concrete	White	Holes/Cracking	10	15.4	Positive
6350	1	1	115	Storage Room across from Classroom 106	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	107	Classroom 107	yes	W1	Plaster	Beige	Holes/Chipping	20	12.3	Positive
6350	1	1	107	Classroom 107	yes	W2	Plaster	Beige	fluorescence/Flaking/Hole	100	14.3	Positive
6350	1	1	107	Classroom 107	yes	W3	Plaster	Beige	Partially Inaccessible	10	10	Positive
6350	1	1	107	Classroom 107	yes	W4	Plaster	Beige	Cracking	10	11.1	Positive
6350	1	1	107	Classroom 107	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	107	Classroom 107	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	107A	Classroom 107 Coat Closet	yes	W1	Plaster	Beige	Cracking	10	4.3	Positive
6350	1	1	107A	Classroom 107 Coat Closet	yes	W2	Plaster	Beige	None	0	5.8	Positive
6350	1	1	107A	Classroom 107 Coat Closet	yes	W3	Plaster	Beige	Chipping	10	9.9	Positive
6350	1	1	107A	Classroom 107 Coat Closet	yes	Pipe (W3)	Metal	Beige	Chipping	5	0.15	Negative
6350	1	1	107A	Classroom 107 Coat Closet	yes	W4	Plaster	Beige	Flaking/Holes	20	8	Positive
6350	1	1	107A	Classroom 107 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	107A	Classroom 107 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	S15	Fire Tower across from Classroom 107	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
6350	1	1	S15	Fire Tower across from Classroom 107	yes	Door (W1)	Metal	Red	Friction	20	2.4	Positive
6350	1	1	S15	Fire Tower across from Classroom 107	yes	Door Frame (W1)	Metal	Black	Friction	20	2.5	Positive
6350	1	1	S15	Fire Tower across from Classroom 107	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
6350	1	1	S15	Fire Tower across from Classroom 107	yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
6350	1	1	S15	Fire Tower across from Classroom 107	yes	Door (W1)	Metal	Red	Friction	20	4.5	Positive

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
6350	1	1	S15	Fire Tower across from Classroom 107	yes	Door Frame (W1)	Metal	Black	Friction	20	4.4	Positive
6350	1	1	S15	Fire Tower across from Classroom 107	yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
6350	1	1	S15	Fire Tower across from Classroom 107	yes	Window Bars (W4)	Metal	Black	Flaking	100	9.8	Positive
6350	1	1	S15	Fire Tower across from Classroom 107	yes	Ceiling	Concrete	White	Flaking	5	7	Positive
6350	1	1	S15	Fire Tower across from Classroom 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	H15	Center Hallway from Boy's to Girl's Restrooms	yes	W1	Plaster	Beige	Cracking	20	23.5	Positive
6350	1	1	H15	Center Hallway from Boy's to Girl's Restrooms	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	1	H15	Center Hallway from Boy's to Girl's Restrooms	yes	W3	Plaster	Beige	Holes	35	21	Positive
6350	1	1	H15	Center Hallway from Boy's to Girl's Restrooms	yes	W4	Plaster	Beige	Holes	35	17.8	Positive
6350	1	1	H15	Center Hallway from Boy's to Girl's Restrooms	yes	Ceiling	Plaster	White	Flaking	30	10.9	Positive
6350	1	1	H15	Center Hallway from Boy's to Girl's Restrooms	yes	Pipe (Ceiling)	Metal	White	Flaking	6	21	Positive
6350	1	1	H15	Center Hallway from Boy's to Girl's Restrooms	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	112	Boy's Restroom next to Classroom 107	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	112	Boy's Restroom next to Classroom 107	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	112	Boy's Restroom next to Classroom 107	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	112	Boy's Restroom next to Classroom 107	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	112	Boy's Restroom next to Classroom 107	yes	Ceiling	Plaster	Beige	Cracking/Flaking/Fall	200	23.5	Positive
6350	1	1	112	Boy's Restroom next to Classroom 107	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	S11	Stairwell outside Classroom 108	yes	W1	Plaster	Beige	Flaking	15	14.3	Positive
6350	1	1	S11	Stairwell outside Classroom 108	yes	Door (W1)	Metal	Brown	Friction	10	0.03	Negative
6350	1	1	S11	Stairwell outside Classroom 108	yes	Door Frame (W1)	Metal	Brown	Friction	10	0.1	Negative
6350	1	1	S11	Stairwell outside Classroom 108	yes	W2	Plaster	Beige	Flaking/Cacking	100	12	Positive
6350	1	1	S11	Stairwell outside Classroom 108	yes	W3	Plaster	Beige	Cracking/Holes	40	11.9	Positive
6350	1	1	S11	Stairwell outside Classroom 108	yes	Door (W3)	Metal	Blue	Friction	20	10	Negative
6350	1	1	S11	Stairwell outside Classroom 108	yes	Door Casing(W3)	Metal	Blue	Friction	20	5.6	Positive
6350	1	1	S11	Stairwell outside Classroom 108	yes	Door (W1)	Wood	Brown	Friction	10	0.02	Negative
6350	1	1	S11	Stairwell outside Classroom 108	yes	Door Frame (W1)	Metal	Brown	Friction	10	0.05	Negative
6350	1	1	S11	Stairwell outside Classroom 108	yes	W4	Plaster	Beige	Cracking/Flaking	100	12	Positive
6350	1	1	S11	Stairwell outside Classroom 108	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S11	Stairwell outside Classroom 108	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	S11	Stairwell outside Classroom 108	yes	Stair Tred	Concrete	Blue	Friction	20	0.03	Negative
6350	1	1	S11	Stairwell outside Classroom 108	yes	Stair Stringer	Concrete	Blue	Friction	20	0.25	Negative
6350	1	1	S11	Stairwell outside Classroom 108	yes	Stair Riser	Concrete	Blue	Friction	40	0.08	Negative
6350	1	1	S11	Stairwell outside Classroom 108	yes	Stair Ballast	Concrete	Blue	Friction	40	12.4	Positive
6350	1	1	S11	Stairwell outside Classroom 108	yes	Stair Newel Post	Concrete	Blue	Friction	5	11	Positive
6350	1	1	108	Classroom 108	yes	W1	Plaster	Beige	Peeling/Cracking	15	13.9	Positive
6350	1	1	108	Classroom 108	yes	W2	Plaster	Beige	Partially Inaccessible	0	9	Positive
6350	1	1	108	Classroom 108	yes	W3	Plaster	Beige	Partially Inaccessible	0	10.1	Positive
6350	1	1	108	Classroom 108	yes	W4	Plaster	Beige	None	0	N/A	N/A
6350	1	1	108	Classroom 108	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	108	Classroom 108	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	108A	Classroom 108 Coat Closet	yes	W1	Plaster	Beige	Flaking	10	4.5	Positive

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	1	108A	Classroom 108 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	7	Positive
6350	1	1	108A	Classroom 108 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	3.2	Positive
6350	1	1	108A	Classroom 108 Coat Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	2.8	Positive
6350	1	1	108A	Classroom 108 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	108A	Classroom 108 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	109	Classroom 109	yes	W1	Plaster	Beige	Holes	3	12.8	Positive
6350	1	1	109	Classroom 109	yes	W2	Plaster	Beige	Cracking/Holes	4	11	Positive
6350	1	1	109	Classroom 109	yes	W3	Plaster	Beige	Alligating/Chipping	35	10.3	Positive
6350	1	1	109	Classroom 109	yes	W4	Plaster	N/A	Partially Inaccessible	0	11.3	Positive
6350	1	1	109	Classroom 109	yes	Ceiling	Plaster	Varnish	N/A	N/A	N/A	N/A
6350	1	1	109	Classroom 109	yes	Floor	Wood	Beige	N/A	N/A	N/A	N/A
6350	1	1	109A	Classroom 109 Coat Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	109A	Classroom 109 Coat Closet	yes	W2	Plaster	Beige	Chipping	3	4.6	Positive
6350	1	1	109A	Classroom 109 Coat Closet	yes	W3	Plaster	Beige	Efflorescence	10	1.9	Positive
6350	1	1	109A	Classroom 109 Coat Closet	yes	W4	Plaster	Beige	Chipping	3	2.8	Positive
6350	1	1	109A	Classroom 109 Coat Closet	yes	Ceiling	Plaster		N/A	N/A	N/A	N/A
6350	1	1	109A	Classroom 109 Coat Closet	yes	Floor	Wood		N/A	N/A	N/A	N/A
6350	1	1	110	Classroom 110	yes	W1	Plaster		Alligating	40	11.7	Positive
6350	1	1	110	Classroom 110	yes	W2	Plaster		None	0	N/A	N/A
6350	1	1	110	Classroom 110	yes	Pipe (W2)	Metal	Beige	Chipping	7	19.7	Positive
6350	1	1	110	Classroom 110	yes	W3	Plaster	Beige	Chipping/Cracking	20	21	Positive
6350	1	1	110	Classroom 110	yes	W4	Plaster	Beige	Alligating/Holes	40	17	Positive
6350	1	1	110	Classroom 110	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	110	Classroom 110	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	110A	Classroom 110 Coat Closet converted into a Student Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	110A	Classroom 110 Coat Closet converted into a Student Restroom	yes	W2	Plaster	Beige	Peeling/Cracking	20	15	Positive
6350	1	1	110A	Classroom 110 Coat Closet converted into a Student Restroom	yes	W3	Plaster	Beige	Cracking/Chipping	7	11.8	Positive
6350	1	1	110A	Classroom 110 Coat Closet converted into a Student Restroom	yes	W4	Plaster	Beige	Peeling/Cracking	15	9.9	Positive
6350	1	1	110A	Classroom 110 Coat Closet converted into a Student Restroom	yes	Radiator (W3)	Metal	Silver	Chipping	20	14.5	Positive
6350	1	1	110A	Classroom 110 Coat Closet converted into a Student Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	110A	Classroom 110 Coat Closet converted into a Student Restroom	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	1	S7	Stairwell outside Classroom 110	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S7	Stairwell outside Classroom 110	yes	W2	Plaster	Beige	ence/Flaking/Moisture D	30	19.8	Positive
6350	1	1	S7	Stairwell outside Classroom 110	yes	W3	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S7	Stairwell outside Classroom 110	yes	W4	Plaster	Beige	None	0	N/A	N/A
6350	1	1	S7	Stairwell outside Classroom 110	yes	Ceiling	Plaster	Beige	Cracking	10	3.9	Positive
6350	1	1	S7	Stairwell outside Classroom 110	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	1	111	Staff Restroom next to Classroom 110	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	111	Staff Restroom next to Classroom 110	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	111	Staff Restroom next to Classroom 110	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	111	Staff Restroom next to Classroom 110	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
6350	1	1	111	Staff Restroom next to Classroom 110	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	111	Staff Restroom next to Classroom 110	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	1	H14	Hallway from Classrooms 108 to 110	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	1	H14	Hallway from Classrooms 108 to 110	yes	W2	Plaster	Beige	Flaking/Cracking	150	10.9	Positive
6350	1	1	H14	Hallway from Classrooms 108 to 110	yes	W3	Plaster	Beige	Cracking	25	13.7	Positive
6350	1	1	H14	Hallway from Classrooms 108 to 110	yes	W4	Plaster	Beige	Hole/Cracking	50	23	Positive
6350	1	1	H14	Hallway from Classrooms 108 to 110	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	1	H14	Hallway from Classrooms 108 to 110	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	2	201	Classroom 201	yes	W1	Plaster	Beige	Chipping	5	14	Positive
6350	1	2	201	Classroom 201	yes	W2	Plaster	Beige	Chipping	5	16.5	Positive
6350	1	2	201	Classroom 201	yes	W3	Plaster	Beige	Cracking/Moisture Damage	50	17	Positive
6350	1	2	201	Classroom 201	yes	Pipe (W3)	Metal	Beige	Cracking	5	20.1	Positive
6350	1	2	201	Classroom 201	yes	W4	Plaster	Beige	Cracking/Chipping/Flaking	50	10	Positive
6350	1	2	201	Classroom 201	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	201	Classroom 201	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	201A	Classroom 201 Coat Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	2	201A	Classroom 201 Coat Closet	yes	W2	Plaster	Beige	Holes/Chipping	20	5.4	Positive
6350	1	2	201A	Classroom 201 Coat Closet	yes	W3	Plaster	Beige	Flaking/Chipping/Hole	25	7.9	Positive
6350	1	2	201A	Classroom 201 Coat Closet	yes	W4	Plaster	Beige	Flaking	5	9.9	Positive
6350	1	2	201A	Classroom 201 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	201A	Classroom 201 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	200	Counselor's Office next to Classroom 201	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	2	200	Counselor's Office next to Classroom 201	yes	Door (W1)	Wood	Beige	Flaking/Chipping	10	8.5	Positive
6350	1	2	200	Counselor's Office next to Classroom 201	yes	Door Frame(W1)	Wood	Beige	Flaking/Chipping	10	10.9	Positive
6350	1	2	200	Counselor's Office next to Classroom 201	yes	W2	Wood	Beige	Peeling	10	0	Negative
6350	1	2	200	Counselor's Office next to Classroom 201	yes	W3	Plaster	Beige	Efflorescence	50	12.7	Positive
6350	1	2	200	Counselor's Office next to Classroom 201	yes	W4	Plaster	Beige	Efflorescence/Moisture/Flaking	50	11.8	Positive
6350	1	2	200	Counselor's Office next to Classroom 201	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	200	Counselor's Office next to Classroom 201	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	200A	Counselor's Office Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	200A	Counselor's Office Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	200A	Counselor's Office Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	200A	Counselor's Office Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	200A	Counselor's Office Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	200A	Counselor's Office Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	W1	Plaster	Beige	Flaking/Cracking	40	10.1	Positive
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	W2	Plaster	Beige	Chipping/Flaking/Cracking	100	12	Positive
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	Window Ledge (W2)	Wood	Tan	Chipping/Cracking	10	0.16	Negative
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	Radiator (W2)	Metal	Silver	Chipping	20	7.7	Positive
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	W3	Plaster	Beige	Flaking	50	14.8	Positive
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	Window Ledge (W2)	Wood	Tan	Chipping/Cracking	10	0.26	Negative
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	W4	Plaster	Beige	Holes/Flaking/Cracking	25	17	Positive
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	212	Teacher's Lounge next to Nurse's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	2	212A	Teacher's Lounge Restroom next to Nurse's Office	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	212A	Teacher's Lounge Restroom next to Nurse's Office	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/6/19			School District of Philadelphia						
				Name of Inspector: Jessica Sewell			Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX			Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
6350	1	2	212A	Teacher's Lounge Restroom next to Nurse's Office	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	212A	Teacher's Lounge Restroom next to Nurse's Office	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	212A	Teacher's Lounge Restroom next to Nurse's Office	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	212A	Teacher's Lounge Restroom next to Nurse's Office	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211	Nurse's Office	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211	Nurse's Office	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Office	yes	Door Frame (W2)	Metal	Blue	Friction	20	0.04	Negative	
6350	1	2	211	Nurse's Office	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211	Nurse's Office	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Office	yes	Door Frame (W2)	Metal	Blue	Friction	20	0.03	Negative	
6350	1	2	211	Nurse's Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211	Nurse's Office	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Exam Room	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Exam Room	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Exam Room	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Exam Room	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Exam Room	yes	Door Frame (W4)	Metal	Blue	Friction	20	0.01	Negative	
6350	1	2	211A	Nurse's Exam Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Exam Room	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Office Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Office Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Office Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Office Restroom	yes	Door Frame (W4)	Metal	Blue	Friction	20	0	Negative	
6350	1	2	211A	Nurse's Office Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Office Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211A	Nurse's Office Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211B	Nurse's Office Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211B	Nurse's Office Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211B	Nurse's Office Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211B	Nurse's Office Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211B	Nurse's Office Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	211B	Nurse's Office Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	202	Classroom 202	yes	W1	Plaster	Beige	Cracking/Cjipping/Flaking	20	15.6	Positive	
6350	1	2	202	Classroom 202	yes	W2	Plaster	Beige	Chipping	5	26	Positive	
6350	1	2	202	Classroom 202	yes	W3	Plaster	Beige	Flaking/Cracking	150	17	Positive	
6350	1	2	202	Classroom 202	yes	W4	Plaster	Beige	Cracking	10	7.9	Positive	
6350	1	2	202	Classroom 202	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	2	202	Classroom 202	yes	Floor	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	202A	Classroom 202 Coat Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A	
6350	1	2	202A	Classroom 202 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A	
6350	1	2	202A	Classroom 202 Coat Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	202A	Classroom 202 Coat Closet	yes	W4	Plaster	Beige	Peeling	10	9.9	Positive	
6350	1	2	202A	Classroom 202 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	2	202A	Classroom 202 Coat Closet	yes	Floor	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	203	Classroom 203	yes	W1	Plaster	Beige	Holes/Flaking	10	10.9	Positive	
6350	1	2	203	Classroom 203	yes	W2	Plaster	Beige	Holes/Flaking	50	15	Positive	

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
6350	1	2	203	Classroom 203	yes	W3	Plaster	Beige	Peeling/Cracking/Flaking	150	14.7	Positive
6350	1	2	203	Classroom 203	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	2	203	Classroom 203	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	203	Classroom 203	yes	Floor	Plaster	Beige	None	0	N/A	N/A
6350	1	2	203A	Classroom 203 Coat Closet	yes	W1	Plaster	Beige	Discoloration/Moisture/Flaking	50	3.5	Positive
6350	1	2	203A	Classroom 203 Coat Closet	yes	W2	Plaster	Beige	Efflorescence/Flaking	50	7.8	Positive
6350	1	2	203A	Classroom 203 Coat Closet	yes	Radiator (W2)	Metal	Silver	Chipping	20	4.8	Positive
6350	1	2	203A	Classroom 203 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	2	203A	Classroom 203 Coat Closet	yes	W4	Plaster	Beige	Cracking/Peeling	10	10	Positive
6350	1	2	203A	Classroom 203 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	203A	Classroom 203 Coat Closet	yes	Floor	Plaster	Beige	None	0	N/A	N/A
6350	1	2	S22	Stairwell outside Classroom 203	yes	W1	Plaster	Beige	Flaking/Chipping	10	14.8	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	Radiator Cover (W1)	Metal	Grey	Chipping/Flaking	30	0.07	Negative
6350	1	2	S22	Stairwell outside Classroom 203	yes	W2	Plaster	Beige	Cracking/Flaking/Efflorescence	10	15.8	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	W3	Plaster	Beige	None	0	N/A	N/A
6350	1	2	S22	Stairwell outside Classroom 203	yes	Door (W3)	Metal	Blue	Friction	20	7.8	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	Door Frame (W3)	Metal	Blue	Friction	20	6.9	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	Door (W3)	Metal	Blue	Friction	20	4.7	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	Door Frame (W3)	Metal	Blue	Friction	20	9.8	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	W4	Plaster	Beige	Flaking/Cracking	20	16.9	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	Ceiling	Plaster	Beige	Discoloration/Efflorescence/Flaking	25	20.9	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	2	S22	Stairwell outside Classroom 203	yes	Stair Stringer	Concrete	Blue	Friction	25	0	Negative
6350	1	2	S22	Stairwell outside Classroom 203	yes	Stair Riser	Concrete	Blue	Friction	40	0.01	Negative
6350	1	2	S22	Stairwell outside Classroom 203	yes	Stair Tred	Concrete	Blue	Friction	40	0.28	Negative
6350	1	2	S22	Stairwell outside Classroom 203	yes	Stair Ballast	Metal	Blue	Flaking/Chipping	20	17	Positive
6350	1	2	S22	Stairwell outside Classroom 203	yes	Stair Newel Post	Metal	Blue	Friction	5	18.8	Positive
6350	1	2	H29	Hallway from Classrooms 201 to 203	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	2	H29	Hallway from Classrooms 201 to 203	yes	Door (W3)	Metal	Blue	Friction	20	8.9	Positive
6350	1	2	H29	Hallway from Classrooms 201 to 203	yes	Door Frame (W3)	Metal	Blue	Friction	20	4.7	Positive
6350	1	2	H29	Hallway from Classrooms 201 to 203	yes	W2	Plaster	Beige	Flaking/Cracking	20	18	Positive
6350	1	2	H29	Hallway from Classrooms 201 to 203	yes	W3	Plaster	Beige	None	0	N/A	N/A
6350	1	2	H29	Hallway from Classrooms 201 to 203	yes	W4	Plaster	Beige	Holes/Cracking	5	18.9	Positive
6350	1	2	H29	Hallway from Classrooms 201 to 203	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	H29	Hallway from Classrooms 201 to 203	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	2	213	Girl's Restroom next to Classroom 204	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	213	Girl's Restroom next to Classroom 204	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	213	Girl's Restroom next to Classroom 204	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	213	Girl's Restroom next to Classroom 204	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	213	Girl's Restroom next to Classroom 204	yes	Ceiling	Plaster	Beige	Cracking/Flaking/Efflorescence	150	24	Positive
6350	1	2	213	Girl's Restroom next to Classroom 204	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	204	Classroom 204	yes	W1	Plaster	Beige	Flaking/Cracking/Holes	20	10.4	Positive
6350	1	2	204	Classroom 204	yes	W2	Partition Wall	Varnish	N/A	N/A	N/A	N/A
6350	1	2	204	Classroom 204	yes	W3	Plaster	Beige	Cracking/Flaking/Holes/Efflorescence	25	15	Positive
6350	1	2	204	Classroom 204	yes	W4	Plaster	Beige	Flaking/Cracking	10	11.9	Positive
6350	1	2	204	Classroom 204	yes	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/6/19			School District of Philadelphia						
				Name of Inspector: Jessica Sewell			Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX			Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
6350	1	2	204	Classroom 204	yes	Floor	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	204A	Classroom 204 Coat Closet	yes	W1	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	204A	Classroom 204 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	204A	Classroom 204 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	204A	Classroom 204 Coat Closet	yes	W4	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	204A	Classroom 204 Coat Closet	yes	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	204A	Classroom 204 Coat Closet	yes	Floor	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	205	Classroom 205	yes	W1	Plaster	Beige	Holes/Chipping/Flaking/	20	16.8	Positive	
6350	1	2	205	Classroom 205	yes	W2	Plaster	Beige	Peeling/Holes	10	28.9	Positive	
6350	1	2	205	Classroom 205	yes	W3	Plaster	Beige	Cracking/Holes/Flaking	10	10	Positive	
6350	1	2	205	Classroom 205	yes	W4	Partition Wall	Varnish	None	0	N/A	N/A	
6350	1	2	205	Classroom 205	yes	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	205	Classroom 205	yes	Floor	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	205A	Classroom 205 Coat Closet	yes	W1	Plaster	Beige	Cracking/Chipping	10	4.6	Positive	
6350	1	2	205A	Classroom 205 Coat Closet	yes	W2	Plaster	Beige	Cracking/Chipping	10	6.9	Positive	
6350	1	2	205A	Classroom 205 Coat Closet	yes	W3	Plaster	Beige	Cracking/Chipping	10	5.5	Positive	
6350	1	2	205A	Classroom 205 Coat Closet	yes	W4	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	205A	Classroom 205 Coat Closet	yes	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	205A	Classroom 205 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	
6350	1	2	214	Storage Room across from Classroom 205	yes	W1	Plaster	Beige	Cracking/Chippine	40	12	Positive	
6350	1	2	214	Storage Room across from Classroom 205	yes	W2	Plaster	Beige	Cracking/Alligatoring	100	10.1	Positive	
6350	1	2	214	Storage Room across from Classroom 205	yes	W3	Plaster	Beige	Efflorescence/Flaking	60	11.3	Positive	
6350	1	2	214	Storage Room across from Classroom 205	yes	W4	Plaster	Beige	Efflorescence/Flaking	60	11.3	Positive	
6350	1	2	214	Storage Room across from Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	214	Storage Room across from Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	214A	Janitor's Closet inside Storage Room across from Classroom 205	no	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	214A	Janitor's Closet inside Storage Room across from Classroom 205	no	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	214A	Janitor's Closet inside Storage Room across from Classroom 205	no	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	214A	Janitor's Closet inside Storage Room across from Classroom 205	no	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	2	214A	Janitor's Closet inside Storage Room across from Classroom 205	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	214A	Janitor's Closet inside Storage Room across from Classroom 205	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
6350	1	2	206	IMC (Library)	yes	W1	Plaster	Beige	Holes/Chipping/Cracking	10	12.3	Positive	
6350	1	2	206	IMC (Library)	yes	W2	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	206	IMC (Library)	yes	W3	Plaster	Beige	Efflorescence/Chipping	5	14	Positive	
6350	1	2	206	IMC (Library)	yes	W4	Plaster	Beige	None	0	N/A	N/A	
6350	1	2	206	IMC (Library)	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	2	206	IMC (Library)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
6350	1	2	206A	IMC Coat Closet adjacent to Classroom 205	yes	W1	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	206A	IMC Coat Closet adjacent to Classroom 205	yes	W2	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	206A	IMC Coat Closet adjacent to Classroom 205	yes	W3	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	206A	IMC Coat Closet adjacent to Classroom 205	yes	W4	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A	
6350	1	2	206A	IMC Coat Closet adjacent to Classroom 205	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
6350	1	2	206A	IMC Coat Closet adjacent to Classroom 205	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	206B	IMC Coat Closet adjacent to Boy's Restroom	yes	W1	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A
6350	1	2	206B	IMC Coat Closet adjacent to Boy's Restroom	yes	W2	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A
6350	1	2	206B	IMC Coat Closet adjacent to Boy's Restroom	yes	W3	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A
6350	1	2	206B	IMC Coat Closet adjacent to Boy's Restroom	yes	W4	Plaster	Beige	Moisture Damage/Flaking	10	17.6	Positive
6350	1	2	206B	IMC Coat Closet adjacent to Boy's Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	206B	IMC Coat Closet adjacent to Boy's Restroom	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	215	Storage/IT MDF Room across from Library 206 (next to Fire Tower)	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	2	215	Storage/IT MDF Room across from Library 206 (next to Fire Tower)	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	2	215	Storage/IT MDF Room across from Library 206 (next to Fire Tower)	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	2	215	Storage/IT MDF Room across from Library 206 (next to Fire Tower)	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
6350	1	2	215	Storage/IT MDF Room across from Library 206 (next to Fire Tower)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
6350	1	2	215	Storage/IT MDF Room across from Library 206 (next to Fire Tower)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
6350	1	2	S25	Fire Tower across from Library 206	yes	W1	Brick	N/A	None	0	N/A	N/A
6350	1	2	S25	Fire Tower across from Library 206	yes	Door (W1)	Wood	Red	Friction	10	11	Positive
6350	1	2	S25	Fire Tower across from Library 206	yes	Door Frame (W1)	Metal	Black	Friction	10	16	Positive
6350	1	2	S25	Fire Tower across from Library 206	yes	W2	Brick	N/A	None	0	N/A	N/A
6350	1	2	S25	Fire Tower across from Library 206	yes	W3	Brick	N/A	None	0	N/A	N/A
6350	1	2	S25	Fire Tower across from Library 206	yes	Door (W3)	Wood	Red	Friction	10	5.7	Positive
6350	1	2	S25	Fire Tower across from Library 206	yes	Door Frame (W3)	Metal	Black	Friction	10	6.7	Positive
6350	1	2	S25	Fire Tower across from Library 206	yes	W4	Brick	N/A	None	0	N/A	N/A
6350	1	2	S25	Fire Tower across from Library 206	yes	Ceiling	Concrete	White	Moisture Damage/Flaking	20	4	Positive
6350	1	2	S25	Fire Tower across from Library 206	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	2	216	Boy's Restroom next to Library	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
6350	1	2	216	Boy's Restroom next to Library	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
6350	1	2	216	Boy's Restroom next to Library	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
6350	1	2	216	Boy's Restroom next to Library	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
6350	1	2	216	Boy's Restroom next to Library	yes	Ceiling	Plaster	Beige	Cracking/Flaking/Moisture Damage	250	27.9	Positive
6350	1	2	216	Boy's Restroom next to Library	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	H28	Center Hallway from Boy's to Girl's Restrooms	yes	W1	Plaster	Beige	Flaking/Cracking/Holes	200	15.6	Positive
6350	1	2	H28	Center Hallway from Boy's to Girl's Restrooms	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	2	H28	Center Hallway from Boy's to Girl's Restrooms	yes	W3	Plaster	Beige	Cracking/Holes/Moisture	300	18	Positive
6350	1	2	H28	Center Hallway from Boy's to Girl's Restrooms	yes	W4	Plaster	Beige	None	0	N/A	N/A
6350	1	2	H28	Center Hallway from Boy's to Girl's Restrooms	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	S21	Center Hallway from Boy's to Girl's Restrooms	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	2	S21	Stairwell outside Classroom 208	yes	W1	Plaster	Beige	ence/Moisture Damage	25	11	Positive
6350	1	2	S21	Stairwell outside Classroom 208	yes	Radiator Cover (W1)	Metal	Grey	Flaking/Chipping	30	0.02	Negative
6350	1	2	S21	Stairwell outside Classroom 208	yes	W2	Plaster	Beige	Cracking/Flaking	120	16	Positive
6350	1	2	S21	Stairwell outside Classroom 208	yes	W3	Plaster	Beige	None	0	N/A	N/A
6350	1	2	S21	Stairwell outside Classroom 208	yes	Door (W3)	Metal	Blue	Friction	20	8.9	Positive
6350	1	2	S21	Stairwell outside Classroom 208	yes	Door Frame (W3)	Metal	Blue	Friction	20	6.5	Positive
6350	1	2	S21	Stairwell outside Classroom 208	yes	W4	Plaster	Beige	presence/ Cracking/Flak	100	16	Positive
6350	1	2	S21	Stairwell outside Classroom 208	yes	Ceiling	Plaster	Beige	flaking/Moisture Damage	50	0.2	Negative
6350	1	2	S21	Stairwell outside Classroom 208	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	2	S21	Stairwell outside Classroom 208	yes	Stair Stringer	Concrete	Blue	Friction	25	0.03	Negative
6350	1	2	S21	Stairwell outside Classroom 208	yes	Stair Riser	Concrete	Blue	Friction	40	0	Negative
6350	1	2	S21	Stairwell outside Classroom 208	yes	Stair Tred	Concrete	Blue	Friction	40	0.16	Negative
6350	1	2	S21	Stairwell outside Classroom 208	yes	Stair Ballast	Metal	Blue	Flaking/Chipping	20	9.8	Positive
6350	1	2	S21	Stairwell outside Classroom 208	yes	Stair Newel Post	Metal	Blue	Friction	5	16	Positive
6350	1	2	208	Classroom 208	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	2	208	Classroom 208	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	2	208	Classroom 208	yes	W3	Plaster	Beige	Partially Inaccessible	0	16	Positive
6350	1	2	208	Classroom 208	yes	W4	Plaster	Beige	Holes	2	17.9	Positive
6350	1	2	208	Classroom 208	yes	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	2	208	Classroom 208	yes	Floor	Plaster	Beige	None	0	N/A	N/A
6350	1	2	208A	Classroom 208 Coat Closet	yes	W1	Plaster	Beige	Efflorescence	5	1.6	Positive
6350	1	2	208A	Classroom 208 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	4.3	Positive
6350	1	2	208A	Classroom 208 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	4.5	Positive
6350	1	2	208A	Classroom 208 Coat Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	1.7	Positive
6350	1	2	208A	Classroom 208 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	208A	Classroom 208 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	209	Classroom 209	yes	W1	Plaster	Beige	Chipping	5	5.6	Positive
6350	1	2	209	Classroom 209	yes	W2	Plaster	Beige	Partially Inaccessible	0	23.4	Positive
6350	1	2	209	Classroom 209	yes	W3	Plaster	Beige	Partially Inaccessible	0	29	Positive
6350	1	2	209	Classroom 209	yes	W4	Plaster	Beige	Partially Inaccessible	0	16.9	Positive
6350	1	2	209	Classroom 209	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	209	Classroom 209	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	209A	Classroom 209 Coat Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	7.6	Positive
6350	1	2	209A	Classroom 209 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	4.9	Positive
6350	1	2	209A	Classroom 209 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	9.9	Positive
6350	1	2	209A	Classroom 209 Coat Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	7.7	Positive
6350	1	2	209A	Classroom 209 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	209A	Classroom 209 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	210	Classroom 210	yes	W1	Plaster	Beige	Cracking/Pin Holes	10	11	Positive
6350	1	2	210	Classroom 210	yes	W2	Plaster	Beige	Cracking	15	9.8	Positive
6350	1	2	210	Classroom 210	yes	W3	Plaster	Beige	Holes/Cracking	30	10.6	Positive
6350	1	2	210	Classroom 210	yes	W4	Plaster	Beige	Chipping	40	12	Positive
6350	1	2	210	Classroom 210	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	210	Classroom 210	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	210A	Classroom 210 Coat Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	2	210A	Classroom 210 Coat Closet	yes	W2	Plaster	Beige	Cracking	5	10	Positive

				Inspection Dates: 11/6/19			School District of Philadelphia					
				Name of Inspector: Jessica Sewell			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			Pennypacker Elementary School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	2	210A	Classroom 210 Coat Closet	yes	W3	Plaster	Beige	Flaking	25	12.7	Positive
6350	1	2	210A	Classroom 210 Coat Closet	yes	W4	Plaster	Beige	Peeling/Cracking	20	9	Positive
6350	1	2	210A	Classroom 210 Coat Closet	yes	Radiator (W4)	Metal	Silver	Chipping	30	2.7	Positive
6350	1	2	210A	Classroom 210 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	210A	Classroom 210 Coat Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	212	Speech Classroom 212	yes	W1	Plaster	Beige	Holes	5	10.1	Positive
6350	1	2	212	Speech Classroom 212	yes	W2	Plaster	Beige	Moisture Damage/Holes	20	11	Positive
6350	1	2	212	Speech Classroom 212	yes	Pipe (W2)	Metal	Beige	Chipping/Flaking	15	15.8	Positive
6350	1	2	212	Speech Classroom 212	yes	W3	Plaster	Beige	Flaking	5	9.4	Positive
6350	1	2	212	Speech Classroom 212	yes	Radiator (W3)	Metal	Silver	Flaking/Chipping	25	10.4	Positive
6350	1	2	212	Speech Classroom 212	yes	W4	Plaster	Beige	Partially Inaccessible	0	13.4	Positive
6350	1	2	212	Speech Classroom 212	yes	W1	Plaster	Beige	N/A	N/A	N/A	N/A
6350	1	2	212	Speech Classroom 212	yes	Door (W1)	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	2	H27	Hallway from Classrooms 208 to 210	yes	Ceiling	Plaster	Beige	N/A	N/A	N/A	N/A
6350	1	2	H27	Hallway from Classrooms 208 to 210	yes	Floor	Metal	Blue	Friction	20	6.7	Positive
6350	1	2	H27	Hallway from Classrooms 208 to 210	yes	Door Frame (W1)	Plaster	Beige	Cracking/Flaking/Holes	150	25.8	Positive
6350	1	2	H27	Hallway from Classrooms 208 to 210	yes	W2	Plaster	Beige	Cracking	50	17.9	Positive
6350	1	2	H27	Hallway from Classrooms 208 to 210	yes	W3	Plaster	Beige	Cracking/Chipping	120	19.8	Positive
6350	1	2	H27	Hallway from Classrooms 208 to 210	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	2	H27	Hallway from Classrooms 208 to 210	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	3	301	Classroom 301	yes	Floor	Plaster	Beige	Flaking/Holes	5	14.5	Positive
6350	1	3	301	Classroom 301	yes	W1	Plaster	Beige	Cracking	40	12	Positive
6350	1	3	301	Classroom 301	yes	W2	Plaster	Beige	Flaking/Moisture/Holes	40	8.3	Positive
6350	1	3	301	Classroom 301	yes	W3	Plaster	Beige	Flaking	15	13.7	Positive
6350	1	3	301	Classroom 301	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	301	Classroom 301	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	301 A	Classroom 301 Closet	yes	Floor	Plaster	Beige	Cracking	30	6.5	Positive
6350	1	3	301 A	Classroom 301 Closet	yes	W1	Plaster	Beige	Flaking	40	8.3	Positive
6350	1	3	301 A	Classroom 301 Closet	yes	W2	Metal	Silver	Chipping	20	4.8	Positive
6350	1	3	301 A	Classroom 301 Closet	yes	Radiator (W1)	Plaster	Beige	Peeling	20	13	Positive
6350	1	3	301 A	Classroom 301 Closet	yes	W3	Metal	Grey	Chipping	10	12.8	Positive
6350	1	3	301 A	Classroom 301 Closet	yes	Radiator (W3)	Plaster	Beige	None	0	13	Positive
6350	1	3	301 A	Classroom 301 Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	301 A	Classroom 301 Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	300	Storage Room outside of Classroom 301	yes	Floor	Plaster	Beige	None	0	N/A	N/A
6350	1	3	300	Storage Room outside of Classroom 301	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	3	300	Storage Room outside of Classroom 301	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	3	300	Storage Room outside of Classroom 301	yes	W3	Plaster	Beige	Flaking/Moisture Damage	20	12.4	Positive
6350	1	3	300	Storage Room outside of Classroom 301	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	300	Storage Room outside of Classroom 301	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	300A	Staff Restroom inside Storage Room outside of Classroom 301	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	300A	Staff Restroom inside Storage Room outside of Classroom 301	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	300A	Staff Restroom inside Storage Room outside of Classroom 301	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
6350	1	3	300A	Staff Restroom inside Storage Room outside of Classroom 301	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	300A	Staff Restroom inside Storage Room outside of Classroom 301	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	300A	Staff Restroom inside Storage Room outside of Classroom 301	yes	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	300B	Janitor's Closet inside Storage Room outside of Classroom 301	no	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	300B	Janitor's Closet inside Storage Room outside of Classroom 301	no	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	300B	Janitor's Closet inside Storage Room outside of Classroom 301	no	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	300B	Janitor's Closet inside Storage Room outside of Classroom 301	no	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	300B	Janitor's Closet inside Storage Room outside of Classroom 301	no	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	300B	Janitor's Closet inside Storage Room outside of Classroom 301	no	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	311	Classroom 311	yes	Floor	Plaster	Beige	ping/Peeling/Cracking/H	15	10	Positive
6350	1	3	311	Classroom 311	yes	W1	Plaster	Beige	Holes/Cracking	20	9	Positive
6350	1	3	311	Classroom 311	yes	W2	Metal	Beige	Flaking	15	12.5	Positive
6350	1	3	311	Classroom 311	yes	Pipe (W2)	Plaster	Beige	Chipping/Cracking	40	13	Positive
6350	1	3	311	Classroom 311	yes	W3	Plaster	Beige	Cracking	20	7	Positive
6350	1	3	311	Classroom 311	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	311	Classroom 311	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	311	Classroom 311 Coat Closet	yes	Floor	Plaster	Beige	Cracking/Chipping/Flaking	35	9	Positive
6350	1	3	311	Classroom 311 Coat Closet	yes	W1	Plaster	Beige	Flaking	60	8.4	Positive
6350	1	3	311	Classroom 311 Coat Closet	yes	W2	Metal	Grey	Cracking/Peeling	25	8	Positive
6350	1	3	311	Classroom 311 Coat Closet	yes	Radiator (W2)	Plaster	Beige	ng/Peeling/Moisture Dan	45	13	Positive
6350	1	3	311	Classroom 311 Coat Closet	yes	W3	Plaster	Beige	Moisture Damage	15	11	Positive
6350	1	3	311	Classroom 311 Coat Closet	yes	W4	Plaster	Beige	Moisture Damage	15	14.5	N/A
6350	1	3	311	Classroom 311 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	302	Classroom 302	yes	Floor	Plaster	Beige	Peeling/Flaking/Cracking	30	16	Positive
6350	1	3	302	Classroom 302	yes	W1	Plaster	Beige	Cracking	2	11	Positive
6350	1	3	302	Classroom 302	yes	W2	Plaster	Beige	Flaking/Cracking/Holes	100	9	Positive
6350	1	3	302	Classroom 302	yes	W3	Metal	Beige	Chipping	5	0.15	Negative
6350	1	3	302	Classroom 302	yes	Pipe (W3)	Plaster	Beige	Cracking/Flaking/Holes	20	11	Positive
6350	1	3	302	Classroom 302	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	302	Classroom 302	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	302A	Classroom 302 Coat Closet	yes	Floor	Plaster	Beige	Cracking/Peeling/Flaking	10	8	Positive
6350	1	3	302A	Classroom 302 Coat Closet	yes	W1	Plaster	Beige	Cracking/Peeling/Flaking	10	9	Positive
6350	1	3	302A	Classroom 302 Coat Closet	yes	W2	Plaster	Beige	Cracking/Peeling/Flaking	10	10	Positive
6350	1	3	302A	Classroom 302 Coat Closet	yes	W3	Plaster	Beige	Cracking/Peeling/Flaking	10	7	Positive
6350	1	3	302A	Classroom 302 Coat Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	302A	Classroom 302 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	303	Computer Lab 303	yes	Floor	Plaster	Beige	Moisture Damage	15	12	Positive
6350	1	3	303	Computer Lab 303	yes	W1	Plaster	Beige	Moisture Damage	25	14.6	Positive
6350	1	3	303	Computer Lab 303	yes	W2	Plaster	Beige	Moisture Damage	10	13.4	Positive
6350	1	3	303	Computer Lab 303	yes	W3	Plaster	Beige	Cracking	10	16.5	Positive

				Inspection Dates: 11/6/19			School District of Philadelphia						
				Name of Inspector: Jessica Sewell			Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX			Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
6350	1	3	303	Computer Lab 303	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	3	303	Computer Lab 303	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A	
6350	1	3	303A	Computer Lab 303 Coat Closet	yes	Floor	Plaster	Beige	Moisture Damage	50	10	Positive	
6350	1	3	303A	Computer Lab 303 Coat Closet	yes	W1	Plaster	Beige	Peeling/Cracking/Moisture	100	13.5	Positive	
6350	1	3	303A	Computer Lab 303 Coat Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A	
6350	1	3	303A	Computer Lab 303 Coat Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A	
6350	1	3	303A	Computer Lab 303 Coat Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	3	303A	Computer Lab 303 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Floor	Plaster	Beige	Moisture Damage	100	12.5	Positive	
6350	1	3	S32	Stairwell outside Classroom 303	yes	W1	Metal	Grey	Chipping/Flaking	20	0.13	Negative	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Radiator Cover (W1)	Plaster	Beige	None	0	N/A	N/A	
6350	1	3	S32	Stairwell outside Classroom 303	yes	W2	Plaster	Beige	None	0	N/A	N/A	
6350	1	3	S32	Stairwell outside Classroom 303	yes	W3	Metal	Blue	Friction/Chipping	15	8.3	Positive	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Door (W3)	Metal	Blue	Friction/Chipping	15	7.7	Positive	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Door Frame (W3)	Plaster	Beige	Moisture Damage/Cracking	40	19.4	Positive	
6350	1	3	S32	Stairwell outside Classroom 303	yes	W4	Plaster	Beige	Moisture Damage/Flaking	80	10	Positive	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Floor	Concrete	Blue	Friction	25	0.1	Negative	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Stair Stringer	Concrete	Blue	Friction	40	0.08	Negative	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Stair Riser	Concrete	Blue	Friction	40	0	Negative	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Stair Tred	Metal	Blue	Flaking/Chipping	20	13	Positive	
6350	1	3	S32	Stairwell outside Classroom 303	yes	Stair Ballast	Metal	Blue	Friction	5	10	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	Stair Newel Post	Plaster	Beige	None	0	N/A	N/A	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	W1	Concrete	Red	Chipping	2	23.9	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	Baseboard (W1)	Metal	Blue	Friction/Chipping	15	9.6	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	Door (W1)	Metal	Blue	Friction/Chipping	15	8.7	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	Door Frame (W1)	Plaster	Beige	Cracking	10	13	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	W2	Concrete	Red	Chipping	10	15	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	Baseboard (W2)	Plaster	Beige	Cracking/Flaking	12	14.4	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	W3	Concrete	Red	Chipping	8	18.9	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	Baseboard (W3)	Plaster	Beige	Cracking/Flaking	20	9.8	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	W4	Concrete	Red	Chipping	10	15	Positive	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	Baseboard(W4)	Plaster	N/A	N/A	N/A	N/A	N/A	
6350	1	3	H312	Hallway from Classrooms 301 to 303	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
6350	1	3	312A	Girl's Restroom next to Classroom 304	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	3	312A	Girl's Restroom next to Classroom 304	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	3	312A	Girl's Restroom next to Classroom 304	yes	W2	Metal	Tan/White	Flaking/Chipping	15	27.8	Positive	
6350	1	3	312A	Girl's Restroom next to Classroom 304	yes	Pipe (W2)	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	3	312A	Girl's Restroom next to Classroom 304	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	3	312A	Girl's Restroom next to Classroom 304	yes	W4	Plaster	Beige	Flaking/Moisture Damage	550	17.9	Positive	
6350	1	3	312A	Girl's Restroom next to Classroom 304	yes	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
6350	1	3	304	Classroom 304	yes	Floor	Plaster	Beige	Cracking	25	13	Positive	
6350	1	3	304	Classroom 304	yes	W1	Partition Wall	Varnish	N/A	N/A	N/A	N/A	
6350	1	3	304	Classroom 304	yes	W2	Plaster	Beige	Moisture Damage/Chipping/Flaking	40	16.9	Positive	
6350	1	3	304	Classroom 304	yes	W3	Wood	Brown	Cracking	10	0.13	Negative	
6350	1	3	304	Classroom 304	yes	Window Sill (W3)	Plaster	Beige	Cracking	25	8.9	Positive	

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	3	304	Classroom 304	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	304	Classroom 304	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	304A	Classroom 304 Coat Closet	yes	Floor	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A
6350	1	3	304A	Classroom 304 Coat Closet	yes	W1	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A
6350	1	3	304A	Classroom 304 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A
6350	1	3	304A	Classroom 304 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A
6350	1	3	304A	Classroom 304 Coat Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	304A	Classroom 304 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	305	Classroom 305	yes	Floor	Plaster	Beige	Chipping/Cracking	15	14	Positive
6350	1	3	305	Classroom 305	yes	W1	Partition Wall	Varnish	N/A	N/A	N/A	N/A
6350	1	3	305	Classroom 305	yes	W2	Plaster	Beige	Holes/Cracking/Flaking/	20	15.9	Positive
6350	1	3	305	Classroom 305	yes	W3	Partition Wall	Varnish	N/A	N/A	N/A	N/A
6350	1	3	305	Classroom 305	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	305	Classroom 305	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	305A	Classroom 305 Coat Closet	yes	Floor	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	3	305A	Classroom 305 Coat Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	3	305A	Classroom 305 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	3	305A	Classroom 305 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	3	305A	Classroom 305 Coat Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	305A	Classroom 305 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	305A	Classroom 305 Book Closet	yes	Floor	Plaster	Beige	Partially Inaccessible	0	0	Negative
6350	1	3	305A	Classroom 305 Book Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	0.2	Negative
6350	1	3	305A	Classroom 305 Book Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	0	Negative
6350	1	3	305A	Classroom 305 Book Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	0	Negative
6350	1	3	305A	Classroom 305 Book Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	305A	Classroom 305 Book Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	306	Classroom 306	yes	Floor	Plaster	Beige	Cracking	10	10.4	Positive
6350	1	3	306	Classroom 306	yes	W1	Partition Wall	Varnish	N/A	N/A	N/A	N/A
6350	1	3	306	Classroom 306	yes	W2	Plaster	Beige	ng/Moisture Damage/Chi	50	8.9	Positive
6350	1	3	306	Classroom 306	yes	W3	Wood	Brown	Chipping	6	0.03	Negative
6350	1	3	306	Classroom 306	yes	Window Ledge (W3)	Partition Wall	Varnish	N/A	N/A	N/A	N/A
6350	1	3	306	Classroom 306	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	306	Classroom 306	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	306A	Classroom 306 Coat Closet	yes	Floor	Plaster	Beige	ng/Moisture Damage/ Fl	100	10.3	Positive
6350	1	3	306A	Classroom 306 Coat Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	3	306A	Classroom 306 Coat Closet	yes	W2	Plaster	Beige	Peeling/Cracking	50	6.7	Positive
6350	1	3	306A	Classroom 306 Coat Closet	yes	W3	Plaster	Beige	Flaking	50	8.9	Positive
6350	1	3	306A	Classroom 306 Coat Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	306A	Classroom 306 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	307	Classroom 307	yes	Floor	Plaster	Beige	Cracking	20	13.9	Positive
6350	1	3	307	Classroom 307	yes	W1	Plaster	Beige	Peeling	5	6.9	Positive
6350	1	3	307	Classroom 307	yes	W2	Plaster	Beige	ng/Cracking/Moisture Da	30	10	Positive
6350	1	3	307	Classroom 307	yes	W3	Partition Wall	Varnish	N/A	N/A	N/A	N/A
6350	1	3	307	Classroom 307	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	307	Classroom 307	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	307A	Classroom 307 Coat Closet	yes	Floor	Plaster	Beige	Peeling/Cracking	50	15.8	Positive

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
6350	1	3	307A	Classroom 307 Coat Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	3	307A	Classroom 307 Coat Closet	yes	W2	Plaster	Beige	Peeling/Flaking	20	9	Positive
6350	1	3	307A	Classroom 307 Coat Closet	yes	W3	Plaster	Beige	Cracking	10	17	Positive
6350	1	3	307A	Classroom 307 Coat Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	307A	Classroom 307 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	315	Storage Room across from Classroom 307 (next to Fire Tower)	yes	Floor	Plaster	Beige	Cracking/Flaking	60	18.9	Positive
6350	1	3	315	Storage Room across from Classroom 307 (next to Fire Tower)	yes	W1	Plaster	Beige	ence/Moisture Damage/	250	18	Positive
6350	1	3	315	Storage Room across from Classroom 307 (next to Fire Tower)	yes	W2	Plaster	Beige	ence/Moisture Damage/	100	15	Positive
6350	1	3	315	Storage Room across from Classroom 307 (next to Fire Tower)	yes	W3	Plaster	Beige	ence/Moisture Damage/	100	19.8	Positive
6350	1	3	315	Storage Room across from Classroom 307 (next to Fire Tower)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
6350	1	3	315	Storage Room across from Classroom 307 (next to Fire Tower)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
6350	1	3	S35	Fire Tower across from Classroom 307	yes	Floor	Brick	N/A	N/A	N/A	N/A	N/A
6350	1	3	S35	Fire Tower across from Classroom 307	yes	W1	Metal	Grey	Friction	10	2.3	Positive
6350	1	3	S35	Fire Tower across from Classroom 307	yes	Door (W1)	Metal	Red	Friction	10	1.8	Positive
6350	1	3	S35	Fire Tower across from Classroom 307	yes	Door Frame (W1)	Brick	N/A	N/A	N/A	N/A	N/A
6350	1	3	S35	Fire Tower across from Classroom 307	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
6350	1	3	S35	Fire Tower across from Classroom 307	yes	W3	Metal	Grey	Friction	10	2.9	Positive
6350	1	3	S35	Fire Tower across from Classroom 307	yes	Door (W3)	Metal	Red	Friction	10	2.2	Positive
6350	1	3	S35	Fire Tower across from Classroom 307	yes	Door Frame (W3)	Brick	N/A	N/A	N/A	N/A	N/A
6350	1	3	S35	Fire Tower across from Classroom 307	yes	W4	Metal	Grey	Flaking	60	10.3	Positive
6350	1	3	S35	Fire Tower across from Classroom 307	yes	Bars (W4)	Concrete	White	Flaking/Holes	5	23.8	Positive
6350	1	3	S35	Fire Tower across from Classroom 307	yes	Ceiling	Metal	White	Chipping	5	11	Positive
6350	1	3	S35	Fire Tower across from Classroom 307	yes	Pipe (Ceiling)	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	3	313	Boy's Restroom next to Classroom 307	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	313	Boy's Restroom next to Classroom 307	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	313	Boy's Restroom next to Classroom 307	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	313	Boy's Restroom next to Classroom 307	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	313	Boy's Restroom next to Classroom 307	yes	W4	Plaster	Beige	ence/Moisture Damage/	500	23.8	Positive
6350	1	3	313	Boy's Restroom next to Classroom 307	yes	Ceiling	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
6350	1	3	H311	Hallway from Boy's to Girl's Restrooms	yes	Floor	Plaster	Beige	acking/Flaking/Moisture	200	23.6	Positive
6350	1	3	H311	Hallway from Boy's to Girl's Restrooms	yes	W1	Plaster	Beige	None	0	N/A	N/A
6350	1	3	H311	Hallway from Boy's to Girl's Restrooms	yes	W2	Plaster	Beige	acking/Flaking/Moisture	200	22	Positive
6350	1	3	H311	Hallway from Boy's to Girl's Restrooms	yes	W3	Plaster	Beige	None	0	N/A	N/A
6350	1	3	H311	Hallway from Boy's to Girl's Restrooms	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	3	H311	Hallway from Boy's to Girl's Restrooms	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	3	S31	Stairwell outside Classroom 308	yes	Floor	Plaster	Beige	None	0	N/A	N/A
6350	1	3	S31	Stairwell outside Classroom 308	yes	W1	Metal	Grey	Chipping/Flaking	20	0.02	Negative
6350	1	3	S31	Stairwell outside Classroom 308	yes	Radiator Cover (W1)	Plaster	Beige	None	0	N/A	N/A
6350	1	3	S31	Stairwell outside Classroom 308	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	3	S31	Stairwell outside Classroom 308	yes	W3	Metal	Blue	Friction/Chipping	15	9.7	Positive
6350	1	3	S31	Stairwell outside Classroom 308	yes	Door (W3)	Metal	Blue	Friction/Chipping	15	7.8	Positive
6350	1	3	S31	Stairwell outside Classroom 308	yes	Door Frame (W3)	Plaster	Beige	None	0	N/A	N/A
6350	1	3	S31	Stairwell outside Classroom 308	yes	W4	Plaster	Beige	Moisture Damage/Flaking	45	19.6	Positive
6350	1	3	S31	Stairwell outside Classroom 308	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	3	S31	Stairwell outside Classroom 308	yes	Floor	Concrete	Blue	Friction	25	0.02	Negative
6350	1	3	S31	Stairwell outside Classroom 308	yes	Stair Stringer	Concrete	Blue	Friction	40	0.21	Negative
6350	1	3	S31	Stairwell outside Classroom 308	yes	Stair Riser	Concrete	Blue	Friction	40	0.2	Negative
6350	1	3	S31	Stairwell outside Classroom 308	yes	Stair Tred	Metal	Blue	Flaking/Chipping	20	13.6	Positive
6350	1	3	S31	Stairwell outside Classroom 308	yes	Stair Ballast	Metal	Blue	Friction	5	19.4	Positive
6350	1	3	308	Classroom 308	yes	Stair Newel Post	Plaster	Beige	Cracking/Chipping	10	10.7	Positive
6350	1	3	308	Classroom 308	yes	W1	Plaster	Beige	Chipping	5	9.7	Positive
6350	1	3	308	Classroom 308	yes	W2	Plaster	Beige	Cracking/Chipping	10	6.9	Positive
6350	1	3	308	Classroom 308	yes	W3	Plaster	Beige	Bubbling/Chipping	20	5	Positive
6350	1	3	308	Classroom 308	yes	W4	Plaster	Beige	Bubbling	2	10.3	Positive
6350	1	3	308	Classroom 308	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	308A	Classroom 308 Coat Closet	yes	Floor	Plaster	Beige	ence/Moisture Damage/	50	9.4	Positive
6350	1	3	308A	Classroom 308 Coat Closet	yes	W1	Plaster	Beige	Peeling/Flaking/Cracking	200	12	Positive
6350	1	3	308A	Classroom 308 Coat Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
6350	1	3	308A	Classroom 308 Coat Closet	yes	W3	Plaster	Beige	Cracking	100	2.3	Positive
6350	1	3	308A	Classroom 308 Coat Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	308A	Classroom 308 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	309	Classroom 309	yes	Floor	Plaster	Beige	Holes/Cracking/Peeling	20	10.3	Positive
6350	1	3	309	Classroom 309	yes	W1	Plaster	Beige	Holes	10	13.2	Positive
6350	1	3	309	Classroom 309	yes	W2	Plaster	Beige	Flaking/Chipping	30	11.4	Positive
6350	1	3	309	Classroom 309	yes	W3	Plaster	Beige	Holes/Cracking	20	19.4	Positive
6350	1	3	309	Classroom 309	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	309	Classroom 309	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	309A	Classroom 309 Coat Closet	yes	Floor	Plaster	Beige	None	0	N/A	N/A
6350	1	3	309A	Classroom 309 Coat Closet	yes	W1	Plaster	Beige	Holes	5	9.7	Positive
6350	1	3	309A	Classroom 309 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	3	309A	Classroom 309 Coat Closet	yes	W3	Plaster	Beige	Cracking	5	4.5	Positive
6350	1	3	309A	Classroom 309 Coat Closet	yes	W4	Plaster	Beige	Holes/Flaking	5	6.6	Positive
6350	1	3	309A	Classroom 309 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	310	Classroom 310	yes	Floor	Plaster	Beige	Cracking/Chipping	10	13	Positive
6350	1	3	310	Classroom 310	yes	W1	Plaster	Beige	Partially Inaccessible	0	10	Positive
6350	1	3	310	Classroom 310	yes	W2	Plaster	Beige	Holes/Cracking/Chipping	30	9	Positive
6350	1	3	310	Classroom 310	yes	W3	Plaster	Beige	Holes/Cracking	10	10.8	Positive
6350	1	3	310	Classroom 310	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	310	Classroom 310	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	310A	Classroom 310 Coat Closet	yes	Floor	Plaster	Beige	Partially Inaccessible	0	N/A	N/A

				Inspection Dates: 11/6/19		School District of Philadelphia						
				Name of Inspector: Jessica Sewell		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		Pennypacker Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
6350	1	3	310A	Classroom 310 Coat Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	3	310A	Classroom 310 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	3	310A	Classroom 310 Coat Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
6350	1	3	310A	Classroom 310 Coat Closet	yes	W4	Plaster	Beige	Holes/Flaking	5	14	Positive
6350	1	3	310A	Classroom 310 Coat Closet	yes	Ceiling	Wood	Varnish	N/A	N/A	N/A	N/A
6350	1	3	312	Storage Room outside Classroom 310	yes	Floor	Plaster	Beige	Partially Inaccessible	0	23.6	Positive
6350	1	3	312	Storage Room outside Classroom 310	yes	W1	Plaster	Beige	Partially Inaccessible	0	14.8	Positive
6350	1	3	312	Storage Room outside Classroom 310	yes	W2	Plaster	Beige	Partially Inaccessible	0	16	Positive
6350	1	3	312	Storage Room outside Classroom 310	yes	W3	Plaster	Beige	Partially Inaccessible	0	10.9	Positive
6350	1	3	312	Storage Room outside Classroom 310	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	312	Storage Room outside Classroom 310	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	Floor	Plaster	Beige	None	0	N/A	N/A
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	W1	Metal	Blue	Friction/Chipping	15	9.8	Positive
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	Door (W3)	Metal	Blue	Friction/Chipping	15	7.6	Positive
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	Door Frame (W3)	Plaster	Beige	Flaking/Cracking	10	21	Positive
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	W2	Plaster	Beige	Holes/Cracking	10	19	Positive
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	W3	Plaster	Beige	Cracking	10	15	Positive
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
6350	1	3	H310	Hallway from Classrooms 308 to 310	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A