

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Boiler Room	W1	CMU	White	None	0	0.2	Negative
5390	1	1	Boiler Room	W2	CMU	Beige	None	0	0	Negative
5390	1	1	Boiler Room	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Boiler Room	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Boiler Room	Door	Metal	Brown	None	0	0	Negative
5390	1	1	Boiler Room	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	1	Boiler Room	Door Casing	Metal	Gray	None	0	0.1	Negative
5390	1	1	Boiler Room	Door	Metal	Gray	None	0	0.1	Negative
5390	1	1	Boiler Room	Door	Metal	Brown	None	0	0	Negative
5390	1	1	Boiler Room	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Boiler Room	Stairs - Railing	Metal	Gray	Peeling	5	0.2	Negative
5390	1	1	Boiler Room	Electrical Panel	Metal	Green	Peeling	3	0.4	Negative
5390	1	1	Boiler Room	Boiler	Metal	Gray	None	0	0.1	Negative
5390	1	1	Boiler Room	Relief Tank	Metal	Gray	None	0	0	Negative
5390	1	1	Boiler Room	Stairs - Railing	Metal	Brown	None	0	0	Negative
5390	1	1	Boiler Room	Stairs - Stringer	Metal	Brown	Cracking	3	0.1	Negative
5390	1	1	Boiler Room	Stairs - Tread	Metal	Brown	Cracking	5	0	Negative
5390	1	1	Boiler Room	Stairs - Riser	Metal	Brown	Cracking	5	0.1	Negative
5390	1	1	Gymnasium	W1	CMU	Beige	Cracking	10	0	Negative
5390	1	1	Gymnasium	W2	CMU	Green	None	0	0.2	Negative
5390	1	1	Gymnasium	W3	CMU	Red	Peeling	20	0.1	Negative
5390	1	1	Gymnasium	W4	CMU	Blue	Peeling	20	0.2	Negative
5390	1	1	Gymnasium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gymnasium	Glazed Block	CMU	Brown	Peeling	5	1.6	Positive
5390	1	1	Gymnasium	Door Casing	Metal	Brown	Peeling	1	0	Negative
5390	1	1	Gymnasium	Door Casing	Metal	Brown	Peeling	1	0.1	Negative
5390	1	1	Gymnasium	Door	Metal	Brown	Peeling	2	0	Negative
5390	1	1	Gymnasium	Door	Metal	Brown	Peeling	2	0.1	Negative
5390	1	1	Gymnasium	Door Casing	Metal	Brown	Peeling	1	0.1	Negative
5390	1	1	Gymnasium	Door Transom	Wood	Brown	Peeling	1	0.1	Negative
5390	1	1	Gym Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gym Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gym Storage	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gym Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gym Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Gym Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gym Office Restroom/Shower	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	Gym Office Restroom/Shower	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Gym Office Restroom/Shower	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Gym Office Restroom/Shower	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Gym Office Restroom/Shower	Ceiling	Plaster	Beige	Cracking	3	0.2	Negative
5390	1	1	Gym Office Restroom/Shower	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gym Office Restroom/Shower	Stall	Metal	Brown	None	0	0.1	Negative
5390	1	1	Gym Office	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Gym Office	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Gym Office	W3	CMU	Beige	None	0	0	Negative
5390	1	1	Gym Office	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Gym Office	Ceiling	Concrete	Beige	None	0	0.1	Negative
5390	1	1	Gym Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Gym Office	Door Casing	Metal	Beige	None	0	0.5	Negative
5390	1	1	Gym Office	Door Casing	Metal	Beige	None	0	0.1	Negative
5390	1	1	Gym Office	Door Casing	Metal	Beige	None	0	0.4	Negative
5390	1	1	Storage/Former Gym Coat Room	W1	CMU	Beige	Cracking	1	0.1	Negative
5390	1	1	Storage/Former Gym Coat Room	W2	CMU	Beige	Cracking	1	0	Negative
5390	1	1	Storage/Former Gym Coat Room	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Storage/Former Gym Coat Room	W4	CMU	Beige	None	0	0	Negative
5390	1	1	Storage/Former Gym Coat Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage/Former Gym Coat Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage/Former Gym Coat Room	Door	Metal	Brown	Cracking	1	0.3	Negative
5390	1	1	Unused Restroom/Former Boy's Locker Room Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Unused Restroom/Former Boy's Locker Room Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Unused Restroom/Former Boy's Locker Room Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Unused Restroom/Former Boy's Locker Room Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Unused Restroom/Former Boy's Locker Room Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Unused Restroom/Former Boy's Locker Room Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Boy's Locker Room/Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Boy's Locker Room/Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Boy's Locker Room/Storage	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Boy's Locker Room/Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Boy's Locker Room/Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Boy's Locker Room/Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Girl's Locker Room/Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Girl's Locker Room/Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Former Girl's Locker Room/Storage	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Girl's Locker Room/Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Girl's Locker Room/Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Former Girl's Locker Room/Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Former Girl's Locker Room/Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Former Girl's Locker Room/Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Former Girl's Locker Room/Storage	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Former Girl's Locker Room/Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Former Girl's Locker Room/Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Former Girl's Locker Room/Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Closet in former Girl's Locker Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Closet in former Girl's Locker Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Closet in former Girl's Locker Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Closet in former Girl's Locker Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Closet in former Girl's Locker Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Closet in former Girl's Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet in Hallway near Locker Rooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet in Hallway near Locker Rooms	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet in Hallway near Locker Rooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet in Hallway near Locker Rooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet in Hallway near Locker Rooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet in Hallway near Locker Rooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway between Former Locker Rooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway between Former Locker Rooms	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Hallway between Former Locker Rooms	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Hallway between Former Locker Rooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway between Former Locker Rooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway between Former Locker Rooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway between Former Locker Rooms	Door Casing	Metal	Brown	Cracking	1	0	Negative
5390	1	1	Hallway between Former Locker Rooms	Door Casing	Metal	Brown	Cracking	1	0.1	Negative
5390	1	1	Hallway between Former Locker Rooms	Door Casing	Metal	Brown	Cracking	1	0.1	Negative
5390	1	1	Hallway between Former Locker Rooms	Door Casing	Metal	Brown	Cracking	1	0	Negative
5390	1	1	Hallway between Former Locker Rooms	Door	Metal	Brown	Cracking	2	0.1	Negative
5390	1	1	Hallway between Former Locker Rooms	Door	Metal	Brown	Cracking	2	0	Negative
5390	1	1	Hallway between Former Locker Rooms	Door	Metal	Brown	None	0	0.1	Negative
5390	1	1	Hallway between Former Locker Rooms	Door	Metal	Brown	None	0	0.1	Negative
5390	1	1	Hallway between Former Locker Rooms	Glazed Block	CMU	Beige	Cracking	1	1.5	Positive
5390	1	1	Hallway between Main Building leading to Gym	W1	CMU	Beige	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Hallway between Main Building leading to Gym	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Hallway between Main Building leading to Gym	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Hallway between Main Building leading to Gym	W4	CMU	Beige	None	0	0	Negative
5390	1	1	Hallway between Main Building leading to Gym	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway between Main Building leading to Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway between Main Building leading to Gym	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Hallway between Main Building leading to Gym	Door	Metal	Brown	None	0	0	Negative
5390	1	1	Hallway between Main Building leading to Gym	Door	Metal	Brown	None	0	0	Negative
5390	1	1	Hallway between Main Building leading to Gym	Door Casing	Metal	Brown	Cracking	1	0	Negative
5390	1	1	Hallway between Main Building leading to Gym	Door Casing	Metal	Brown	Cracking	1	0.5	Negative
5390	1	1	Hallway between Main Building leading to Gym	Door Casing	Metal	Brown	Cracking	1	0	Negative
5390	1	1	Hallway between Main Building leading to Gym	Door	Metal	Brown	Cracking	2	0.1	Negative
5390	1	1	Stairwell between Main Building and Gym	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell between Main Building and Gym	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell between Main Building and Gym	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell between Main Building and Gym	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell between Main Building and Gym	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell between Main Building and Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Men's Restroom near Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Men's Restroom near Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Men's Restroom near Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Men's Restroom near Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Men's Restroom near Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Men's Restroom near Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Women's Restroom near Main Office	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Women's Restroom near Main Office	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Women's Restroom near Main Office	W3	CMU	Beige	None	0	0.3	Negative
5390	1	1	Women's Restroom near Main Office	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Women's Restroom near Main Office	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	1	Women's Restroom near Main Office	Floor	Concrete	Gray	None	0	0.3	Negative
5390	1	1	Women's Restroom near Main Office	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Women's Restroom near Main Office	Stall	Metal	Brown	None	0	0.1	Negative
5390	1	1	Women's Restroom near Main Office	Glazed Base	CMU	Brown	None	0	1.2	Positive
5390	1	1	Women's Restroom near Main Office	Duct	Metal	White	None	0	0.2	Negative
5390	1	1	Women's Restroom near Main Office	Pipe	Metal	White	None	0	0	Negative
5390	1	1	Women's Restroom near Main Office	Door Casing	Metal	Brown	None	0	0.2	Negative
5390	1	1	Women's Restroom near Main Office	Stall	Metal	Brown	None	0	0.1	Negative
5390	1	1	Women's Restroom near Main Office	Duct	Metal	White	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Fan Room behind Men's Restroom by Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Fan Room behind Men's Restroom by Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Fan Room behind Men's Restroom by Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Fan Room behind Men's Restroom by Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Fan Room behind Men's Restroom by Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Fan Room behind Men's Restroom by Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Server Room between Faculty Restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Server Room between Faculty Restrooms	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Computer Server Room between Faculty Restrooms	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Computer Server Room between Faculty Restrooms	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Computer Server Room between Faculty Restrooms	Ceiling	Plaster	Beige	Blistering	2	0.2	Negative
5390	1	1	Computer Server Room between Faculty Restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Server Room between Faculty Restrooms	Pipe	Metal	White	None	0	0.1	Negative
5390	1	1	Computer Server Room between Faculty Restrooms	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Computer Server Room between Faculty Restrooms	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Computer Server Room between Faculty Restrooms	Panel	Wood	Beige	None	0	0.3	Negative
5390	1	1	Computer Server Room between Faculty Restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Server Room between Faculty Restrooms	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Server Room between Faculty Restrooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Server Room between Faculty Restrooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Server Room between Faculty Restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Server Room between Faculty Restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Computer Server Room between Faculty Restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Computer Server Room between Faculty Restrooms	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Computer Server Room between Faculty Restrooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Computer Server Room between Faculty Restrooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Computer Server Room between Faculty Restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Computer Server Room between Faculty Restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse Exam Room	W1	CMU	BEIGE	None	0	0	Negative
5390	1	1	Nurse Exam Room	W2	CMU	BEIGE	None	0	0	Negative
5390	1	1	Nurse Exam Room	W3	CMU	BEIGE	None	0	0	Negative
5390	1	1	Nurse Exam Room	W4	CMU	BEIGE	None	0	0	Negative
5390	1	1	Nurse Exam Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Nurse Exam Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse Exam Room	Convactor	Metal	BROWN	None	0	0	Negative
5390	1	1	Nurse Exam Room	Convactor	Metal	BROWN	None	0	0	Negative
5390	1	1	Nurse Exam Room	EXAM PARTITION	Metal	BROWN	None	0	0	Negative
5390	1	1	Nurse Exam Room	Glazed Base	CMU	BROWN	Cracking	1	1	Positive
5390	1	1	Nurse Exam Room	DOOR CASING	Metal	BROWN	None	0	0.02	Negative
5390	1	1	Nurse Exam Room - Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse Exam Room - Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse Exam Room - Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse Exam Room - Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse Exam Room - Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse Exam Room - Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Student Restroom in Nurse Office	W1	Metal	BEIGE	None	0	0	Negative
5390	1	1	Student Restroom in Nurse Office	W2	Metal	BEIGE	None	0	0	Negative
5390	1	1	Student Restroom in Nurse Office	W3	Metal	BEIGE	None	0	0	Negative
5390	1	1	Student Restroom in Nurse Office	W4	Metal	BEIGE	Cracking		0	Negative
5390	1	1	Student Restroom in Nurse Office	Ceiling	Plaster	BEIGE	None	0	0	Negative
5390	1	1	Student Restroom in Nurse Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Student Restroom in Nurse Office	Glazed Base	Metal	BROWN	None	0	1.7	Positive
5390	1	1	Nurse's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Nurse's Office	Glazed Base	CMU	BROWN	None	0	1.7	Positive
5390	1	1	Nurse's Office	DOOR CASING	Metal	BROWN	None	0	0.04	Negative
5390	1	1	Main Office	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Main Office	W2	CMU	Gray	None	0	0.1	Negative
5390	1	1	Main Office	W3	CMU	Gray	None	0	0.1	Negative
5390	1	1	Main Office	W4	CMU	Gray	None	0	0.2	Negative
5390	1	1	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Main Office	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Main Office	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Main Office	Convactor	Metal	Brown	None	0	0.1	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Main Office	Vent Cover	Metal	Brown	None	0	0.1	Negative
5390	1	1	Main Office	Glazed Base	CMU	Brown	None	0	1.6	Positive
5390	1	1	Principal's Office	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	Principal's Office	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Principal's Office	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Principal's Office	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Principal's Office	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Principal's Office	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Principal's Office	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Principal's Office	Convactor	Metal	Brown	None	0	0	Negative
5390	1	1	Restroom in Principal's Office	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Restroom in Principal's Office	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Restroom in Principal's Office	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Restroom in Principal's Office	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Restroom in Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Restroom in Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Storage	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	Main Office Storage	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Main Office Storage	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Storage	W4	CMU	Beige	None	0	0	Negative
5390	1	1	Main Office Storage	Ceiling	Plaster	Beige	None	0	0.2	Negative
5390	1	1	Main Office Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Storage	Glazed Base	CMU	Brown	None	0	1.4	Positive
5390	1	1	Main Office Storage	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Main Office Storage - Closet	W1	Metal	WHITE	None	0	0	Negative
5390	1	1	Main Office Storage - Closet	W2	Metal	WHITE	None	0	0	Negative
5390	1	1	Main Office Storage - Closet	W3	Metal	WHITE	None	0	0	Negative
5390	1	1	Main Office Storage - Closet	W4	Metal	WHITE	None	0	0	Negative
5390	1	1	Main Office Storage - Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Storage - Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Storage - Closet	Glazed Base	CMU	WHITE	None	0	1.3	Positive
5390	1	1	Main Office Storage - Closet	DOOR CASING	Metal	BROWN	None	0	0.05	Negative
5390	1	1	Special Education Office next to Principal's Office	W1	CMU	YELLOW	None	0	0	Negative
5390	1	1	Special Education Office next to Principal's Office	W2	CMU	YELLOW	None	0	0	Negative
5390	1	1	Special Education Office next to Principal's Office	W3	CMU	YELLOW	None	0	0	Negative
5390	1	1	Special Education Office next to Principal's Office	W4	CMU	YELLOW	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Special Education Office next to Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Special Education Office next to Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Special Education Office next to Principal's Office	Glazed Base	CMU	BROWN	None	0	1.7	Positive
5390	1	1	Special Education Office next to Principal's Office	DOOR CASING	CMU	BROWN	Cracking		0.04	Negative
5390	1	1	Hall to Principal's Office & Special Education Office from Main Office Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hall to Principal's Office & Special Education Office from Main Office Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hall to Principal's Office & Special Education Office from Main Office Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hall to Principal's Office & Special Education Office from Main Office Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hall to Principal's Office & Special Education Office from Main Office Area	Ceiling	Drywall	Beige	Flaking	2	0.2	Negative
5390	1	1	Hall to Principal's Office & Special Education Office from Main Office Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Hallway	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Hallway	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Hallway	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Hallway	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Office Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Counselor's Office (near Nurse's Office)	W1	CMU	BEIGE	None	0	0	Negative
5390	1	1	Counselor's Office (near Nurse's Office)	W2	CMU	BEIGE	None	0	0	Negative
5390	1	1	Counselor's Office (near Nurse's Office)	W3	CMU	BEIGE	None	0	0	Negative
5390	1	1	Counselor's Office (near Nurse's Office)	W4	CMU	BEIGE	None	0	0	Negative
5390	1	1	Counselor's Office (near Nurse's Office)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Counselor's Office (near Nurse's Office)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Counselor's Office (near Nurse's Office)	Glazed Base	CMU	BROWN	None	0	1.4	Positive
5390	1	1	Counselor's Office (near Nurse's Office)	Glazed Base	CMU	BROWN	None	0	1	Positive
5390	1	1	Counselor's Office (near Nurse's Office)	DOOR CASING	CMU	BROWN	Cracking		0.03	Negative
5390	1	1	Counselor's Office (near Nurse's Office)	DOOR CASING	CMU	BROWN	Cracking		0.04	Negative
5390	1	1	Counselor's Office (near Nurse's Office)	Ceiling track	Metal	BEIGE	None	0	0	Negative
5390	1	1	Conference Room (in middle of row of offices)	W1	CMU	Beige	None	0	0.3	Negative
5390	1	1	Conference Room (in middle of row of offices)	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Conference Room (in middle of row of offices)	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Conference Room (in middle of row of offices)	W4	CMU	Beige	None	0	0.3	Negative
5390	1	1	Conference Room (in middle of row of offices)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Conference Room (in middle of row of offices)	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Conference Room (in middle of row of offices)	Glazed Base	CMU	Brown	None	0	1.4	Positive
5390	1	1	Conference Room (in middle of row of offices)	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Conference Room (in middle of row of offices)	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	School Community Coordinator Office	W1	CMU	BEIGE	Cracking		0	Negative
5390	1	1	School Community Coordinator Office	W2	CMU	BEIGE	None	0	0	Negative
5390	1	1	School Community Coordinator Office	W3	CMU	BEIGE	None	0	0	Negative
5390	1	1	School Community Coordinator Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	School Community Coordinator Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	School Community Coordinator Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	School Community Coordinator Office	Glazed Base	CMU	BROWN	None	0	1.6	Positive
5390	1	1	School Community Coordinator Office	DOOR CASING	Metal	BROWN	None	0	0.04	Negative
5390	1	1	School Community Coordinator Office	DOOR CASING	Metal	BROWN	None	0	0.05	Negative
5390	1	1	Hallway from Main Entrance to School (between Main Office and the STS Office)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Main Entrance to School (between Main Office and the STS Office)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Main Entrance to School (between Main Office and the STS Office)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Main Entrance to School (between Main Office and the STS Office)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Main Entrance to School (between Main Office and the STS Office)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Main Entrance to School (between Main Office and the STS Office)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Entrance Foyer	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Entrance Foyer	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Entrance Foyer	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Entrance Foyer	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Entrance Foyer	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Main Entrance Foyer	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	DATA Office - "Community Room"	W1	CMU	BLUE	None	0	0	Negative
5390	1	1	DATA Office - "Community Room"	W2	CMU	BLUE	None	0	0	Negative
5390	1	1	DATA Office - "Community Room"	W3	CMU	BLUE	None	0	0	Negative
5390	1	1	DATA Office - "Community Room"	W4	CMU	BLUE	None	0	0	Negative
5390	1	1	DATA Office - "Community Room"	Ceiling	Concrete	WHITE	Peeling		0	Negative
5390	1	1	DATA Office - "Community Room"	Floor	N/A	N/A		N/A	N/A	N/A
5390	1	1	DATA Office - "Community Room"	Glazed Base	CMU	BROWN	None	0	1.8	Positive
5390	1	1	DATA Office - "Community Room"	Glazed Base	CMU	BROWN	None	0	1.2	Positive
5390	1	1	DATA Office - "Community Room"	Univent	Metal	BROWN	Cracking		0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Computer Lab Storage	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	Computer Lab Storage	W2	CMU	Beige	None	0	0	Negative
5390	1	1	Computer Lab Storage	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Computer Lab Storage	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Computer Lab Storage	Ceiling	Concrete	Beige	None	0	0.3	Negative
5390	1	1	Computer Lab Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Lab Storage	Door Casing	Metal	Brown	None	0	0.2	Negative
5390	1	1	Computer Lab Storage	Door Casing	Metal	Gray	None	0	0.1	Negative
5390	1	1	Computer Lab Storage	panel	Wood	Beige	None	0	0.2	Negative
5390	1	1	Computer Lab (Room 106)	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Computer Lab (Room 106)	W1	Drywall	White	None	0	0.2	Negative
5390	1	1	Computer Lab (Room 106)	W2	CMU	Yellow	None	0	0.2	Negative
5390	1	1	Computer Lab (Room 106)	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Computer Lab (Room 106)	W3	Drywall	Beige	None	0	0.1	Negative
5390	1	1	Computer Lab (Room 106)	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Computer Lab (Room 106)	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	1	Computer Lab (Room 106)	Ceiling	Sheetrock	White	Blistering	5	0.2	Negative
5390	1	1	Computer Lab (Room 106)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Computer Lab (Room 106)	Univent	Metal	Brown	None	0	0	Negative
5390	1	1	Computer Lab (Room 106)	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Computer Lab (Room 106)	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Girl's Restroom near Computer Lab	W1	CMU	White	None	0	0.1	Negative
5390	1	1	Girl's Restroom near Computer Lab	W2	CMU	White	None	0	0.1	Negative
5390	1	1	Girl's Restroom near Computer Lab	W3	CMU	White	None	0	0.1	Negative
5390	1	1	Girl's Restroom near Computer Lab	W4	CMU	White	None	0	0.1	Negative
5390	1	1	Girl's Restroom near Computer Lab	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	1	Girl's Restroom near Computer Lab	Floor	Concrete	Gray	None	0	0.2	Negative
5390	1	1	Girl's Restroom near Computer Lab	Duct	Metal	White	None	0	0.3	Negative
5390	1	1	Girl's Restroom near Computer Lab	Door Jamb	Metal	Brown	None	0	0.1	Negative
5390	1	1	Girl's Restroom near Computer Lab	Door	Metal	Brown	None	0	0.1	Negative
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	W4	CMU	Beige	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	Duct	Metal	White	Peeling	2	0.1	Negative
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	Pipe	Metal	White	None	0	0.7	Positive
5390	1	1	Pipe Chase in Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Custodial Closet between Girl's and Boy's Restrooms - near Computer Lab	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Boy's Restroom near Computer Lab	W1	CMU	Beige	None	0	0	Negative
5390	1	1	Boy's Restroom near Computer Lab	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Boy's Restroom near Computer Lab	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Boy's Restroom near Computer Lab	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Boy's Restroom near Computer Lab	Ceiling	Concrete	Beige	None	0	0.1	Negative
5390	1	1	Boy's Restroom near Computer Lab	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Boy's Restroom near Computer Lab	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	1	Boy's Restroom near Computer Lab	Door	Metal	Brown	None	0	0	Negative
5390	1	1	Boy's Restroom near Computer Lab	Stall	Metal	Brown	None	0	0.1	Negative
5390	1	1	Boy's Restroom near Computer Lab	Duct	Metal	White	None	0	0	Negative
5390	1	1	Stairwell 4 near ESOL Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 4 near ESOL Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 4 near ESOL Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 4 near ESOL Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 4 near ESOL Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 4 near ESOL Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Stairwell 4 near ESOL Area	Convactor	Metal	BEIGE	POOR		0	Negative
5390	1	1	ESOL Office - Door C	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	ESOL Office - Door C	W2	CMU	Beige	None	0	0	Negative
5390	1	1	ESOL Office - Door C	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	ESOL Office - Door C	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	ESOL Office - Door C	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	ESOL Office - Door C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	ESOL Office - Door C	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	ESOL Office - Door B	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	ESOL Office - Door B	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	ESOL Office - Door B	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	ESOL Office - Door B	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	ESOL Office - Door B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	ESOL Office - Door B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	ESOL Office - Door B	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	ESOL Office - Door B	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	1	ESOL Classroom	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	ESOL Classroom	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	ESOL Classroom	W3	CMU	Beige	None	0	0.4	Negative
5390	1	1	ESOL Classroom	W3	Drywall	Beige	None	0	0.2	Negative
5390	1	1	ESOL Classroom	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	ESOL Classroom	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	ESOL Classroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	ESOL Classroom	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	ESOL Classroom	Univent	Metal	Brown	None	0	0	Negative
5390	1	1	ESOL Hallway	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	ESOL Hallway	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	ESOL Hallway	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	ESOL Hallway	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	ESOL Hallway	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	ESOL Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	ESOL Hallway	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	ESOL Hallway	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	ESOL Hallway	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	ESOL Hallway	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Classroom 105	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Classroom 105	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Classroom 105	W3	CMU	Beige	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Classroom 105	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Classroom 105	W4	Drywall	Beige	None	0	0.2	Negative
5390	1	1	Classroom 105	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 105	Univent	Metal	Brown	None	0	0.1	Negative
5390	1	1	Classroom 105	Floor Grate	Metal	Brown	None	0	0	Negative
5390	1	1	Classroom 105	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Classroom 105	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Stairwell 2 near Classroom 105	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 2 near Classroom 105	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 2 near Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 2 near Classroom 105	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 2 near Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 2 near Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 2 near Classroom 105	Convactor	Metal	BEIGE	POOR		0.02	Negative
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Equipment Storage - Located in the Shelter 5 Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Women's Restroom near Classroom 104	W1	CMU	Beige	None	0	0.2	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Women's Restroom near Classroom 104	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Women's Restroom near Classroom 104	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Women's Restroom near Classroom 104	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Women's Restroom near Classroom 104	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	Women's Restroom near Classroom 104	Floor	Concrete	Gray	Cracking	2	0.3	Negative
5390	1	1	Women's Restroom near Classroom 104	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Women's Restroom near Classroom 104	Door Casing	Metal	Brown	None	0	0.2	Negative
5390	1	1	Women's Restroom near Classroom 104	Convactor	Metal	Brown	None	0	0.1	Negative
5390	1	1	Women's Restroom near Classroom 104	Stall	Metal	Brown	None	0	0	Negative
5390	1	1	Women's Restroom near Classroom 104	Duct	Metal	White	None	0	0.2	Negative
5390	1	1	Women's Restroom near Classroom 104	Pipe	Metal	White	None	0	0.5	Negative
5390	1	1	Women's Restroom near Classroom 104	Convactor	Metal	Brown	None	0	0.1	Negative
5390	1	1	Women's Restroom near Classroom 104	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Women's Restroom near Classroom 104	Duct	Metal	White	None	0	0.2	Negative
5390	1	1	Pipe Chase in Women's Restroom near Classroom 104	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Women's Restroom near Classroom 104	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Women's Restroom near Classroom 104	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Women's Restroom near Classroom 104	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Women's Restroom near Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Women's Restroom near Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Men's Restroom near Classroom 104	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Men's Restroom near Classroom 104	W2	CMU	Beige	None	0	0.3	Negative
5390	1	1	Men's Restroom near Classroom 104	W2	CMU	Gray	Cracking	2	0.1	Negative
5390	1	1	Men's Restroom near Classroom 104	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Men's Restroom near Classroom 104	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Men's Restroom near Classroom 104	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	1	Men's Restroom near Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Men's Restroom near Classroom 104	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	1	Men's Restroom near Classroom 104	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Men's Restroom near Classroom 104	Stall	Metal	Brown	Flaking	1	0.1	Negative
5390	1	1	Men's Restroom near Classroom 104	Convactor	Metal	Brown	None	0	0.1	Negative
5390	1	1	Men's Restroom near Classroom 104	Door	Metal	Brown	None	0	0	Negative
5390	1	1	Men's Restroom near Classroom 104	Duct	Metal	White	None	0	0.2	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Men's Restroom near Classroom 104	Pipe	Metal	White	None	0	0.1	Negative
5390	1	1	Book Closet next to Men's Restroom 105	W1	CMU	Beige	Cracking	2	0.2	Negative
5390	1	1	Book Closet next to Men's Restroom 105	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Book Closet next to Men's Restroom 105	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Book Closet next to Men's Restroom 105	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Book Closet next to Men's Restroom 105	Ceiling	Concrete	Beige	None	0	0.2	Negative
5390	1	1	Book Closet next to Men's Restroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Book Closet next to Men's Restroom 105	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Lobby/Coat Room for Classroom 104	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Lobby/Coat Room for Classroom 104	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Lobby/Coat Room for Classroom 104	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Lobby/Coat Room for Classroom 104	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Lobby/Coat Room for Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Lobby/Coat Room for Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 104 Storage	W1	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 104 Storage	W2	CMU	Gray	None	0	0	Negative
5390	1	1	Classroom 104 Storage	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 104 Storage	W4	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 104 Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 104 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 104 Storage	Door Casing	Metal	Gray	None	0	0.1	Negative
5390	1	1	Classroom 104 Restroom	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 104 Restroom	W2	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 104 Restroom	W3	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 104 Restroom	W4	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 104 Restroom	Ceiling	Concrete	Black	None	0	0.3	Negative
5390	1	1	Classroom 104 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 104 Restroom	Door Casing	Metal	Gray	None	0	0.3	Negative
5390	1	1	Classroom 104 Restroom	Duct	Metal	Black	None	0	0.1	Negative
5390	1	1	Classroom 104	W1	CMU	Gray	None	0	0	Negative
5390	1	1	Classroom 104	W1	Drywall	White	None	0	0.2	Negative
5390	1	1	Classroom 104	W2	CMU	Teal	None	0	0.2	Negative
5390	1	1	Classroom 104	W3	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 104	W3	Drywall	White	None	0	0.1	Negative
5390	1	1	Classroom 104	W4	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 104	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 104	Door Casing	Metal	Gray	None	0	0.5	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Classroom 104	Door Casing	Metal	Gray	Peeling	1	0.4	Negative
5390	1	1	Classroom 104	Door Casing	Metal	Gray	None	0	0.5	Negative
5390	1	1	Classroom 104	Univent	Metal	Gray	None	0	0	Negative
5390	1	1	Classroom 104	Convactor	Metal	Gray	None	0	0	Negative
5390	1	1	Classroom 104	Cubby Base	Wood	Brown	Cracking	2	0.1	Negative
5390	1	1	Classroom 104	Glazed Base	CMU	Brown	None	0	1.4	Positive
5390	1	1	Classroom 103 Lobby/Coat Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Lobby/Coat Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Lobby/Coat Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Lobby/Coat Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Lobby/Coat Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Lobby/Coat Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103	W1	Drywall	White	None	0	0.2	Negative
5390	1	1	Classroom 103	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103	W2	CMU	Teal	None	0	0	Negative
5390	1	1	Classroom 103	W3	Drywall	White	None	0	0.1	Negative
5390	1	1	Classroom 103	W3	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103	W4	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103	Door Casing	Metal	Gray	Peeling	1	0.5	Negative
5390	1	1	Classroom 103	Door Casing	Metal	Gray	None	0	0.5	Negative
5390	1	1	Classroom 103	Univent	Metal	Gray	None	0	0	Negative
5390	1	1	Classroom 103 Restroom	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103 Restroom	W2	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103 Restroom	W3	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103 Restroom	W4	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103 Restroom	Ceiling	Concrete	Black	None	0	0.1	Negative
5390	1	1	Classroom 103 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Restroom	Pipe	Metal	Black	None	0	0.5	Negative
5390	1	1	Classroom 103 Restroom	Duct	Metal	Black	None	0	0.3	Negative
5390	1	1	Classroom 103 Restroom	Door Casing	Metal	Gray	None	0	0.2	Negative
5390	1	1	Classroom 103 Storage	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103 Storage	W2	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 103 Storage	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 103 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Classroom 103 Storage	Door Casing	Metal	Gray	None	0	0.4	Negative
5390	1	1	Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator	Door	Metal	Brown	None	0	0.2	Negative
5390	1	1	Elevator	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	School Supplies - Storage near Classroom 103	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	School Supplies - Storage near Classroom 103	W2	CMU	Beige	None	0	0	Negative
5390	1	1	School Supplies - Storage near Classroom 103	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	School Supplies - Storage near Classroom 103	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	School Supplies - Storage near Classroom 103	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	School Supplies - Storage near Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	School Supplies - Storage near Classroom 103	Pipe	Metal	White	None	0	0.2	Negative
5390	1	1	School Supplies - Storage near Classroom 103	Door Casing	Metal	Brown	None	0	0.3	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	W1	CMU	Beige	None	0	0	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Maintenance Supplies - Storage near Classroom 103	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	Duct	Metal	White	None	0	0.3	Negative
5390	1	1	Maintenance Supplies - Storage near Classroom 103	Pipe	Metal	White	None	0	0	Negative
5390	1	1	Pipe Chase in Maintenance Supplies - Storage near Classroom 103	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Maintenance Supplies - Storage near Classroom 103	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Maintenance Supplies - Storage near Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Maintenance Supplies - Storage near Classroom 103	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Maintenance Supplies - Storage near Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Maintenance Supplies - Storage near Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Elevator Mechanical Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator Mechanical Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator Mechanical Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator Mechanical Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator Mechanical Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Elevator Mechanical Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Lobby/Coat Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Lobby/Coat Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Lobby/Coat Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Lobby/Coat Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Lobby/Coat Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Lobby/Coat Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Storage	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 102 Storage	W2	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 102 Storage	W3	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 102 Storage	W4	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 102 Storage	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	1	Classroom 102 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Storage	Door Casing	Metal	Gray	None	0	0.4	Negative
5390	1	1	Classroom 102 Restroom	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 102 Restroom	W2	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 102 Restroom	W3	CMU	Gray	None	0	0	Negative
5390	1	1	Classroom 102 Restroom	W4	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 102 Restroom	Ceiling	Concrete	Black	None	0	0.1	Negative
5390	1	1	Classroom 102 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102 Restroom	Pipe	Metal	Black	None	0	0.4	Negative
5390	1	1	Classroom 102 Restroom	Pipe	Metal	Black	None	0	0	Negative
5390	1	1	Classroom 102 Restroom	Duct	Metal	Black	None	0	0.2	Negative
5390	1	1	Classroom 102	W1	Drywall	White	Peeling	1	0.2	Negative
5390	1	1	Classroom 102	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 102	W2	CMU	Gray	None	0	0	Negative
5390	1	1	Classroom 102	W3	CMU	Gray	None	0	0	Negative
5390	1	1	Classroom 102	W3	Drywall	White	Flaking	1	0.2	Negative
5390	1	1	Classroom 102	W4	CMU	Teal	Flaking	2	0.2	Negative
5390	1	1	Classroom 102	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	1	Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 102	Univent	Metal	Gray	None	0	0	Negative
5390	1	1	Classroom 102	Door Casing	Metal	Gray	Peeling	1	0.1	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Classroom 102	Door Casing	Metal	Gray	Peeling	1	0.5	Negative
5390	1	1	Classroom 101 Lobby/Coat Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Lobby/Coat Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Lobby/Coat Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Lobby/Coat Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Lobby/Coat Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Lobby/Coat Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Storage	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 101 Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Storage	W3	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 101 Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Storage	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	Classroom 101 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Storage	Door Casing	Metal	Gray	None	0	0.5	Negative
5390	1	1	Classroom 101 Restroom	W1	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 101 Restroom	W2	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 101 Restroom	W3	CMU	Gray	None	0	0	Negative
5390	1	1	Classroom 101 Restroom	W4	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 101 Restroom	Ceiling	Concrete	Black	None	0	0.2	Negative
5390	1	1	Classroom 101 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101 Restroom	Duct	Metal	Black	None	0	0.1	Negative
5390	1	1	Classroom 101 Restroom	Door Casing	Metal	Gray	None	0	0.5	Negative
5390	1	1	Classroom 101	W1	Drywall	White	None	0	0.2	Negative
5390	1	1	Classroom 101	W1	CMU	Gray	None	0	0.1	Negative
5390	1	1	Classroom 101	W2	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 101	W3	CMU	Gray	None	0	0.2	Negative
5390	1	1	Classroom 101	W3	Drywall	Teal	None	0	0.2	Negative
5390	1	1	Classroom 101	W4	CMU	Teal	None	0	0.1	Negative
5390	1	1	Classroom 101	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	1	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Classroom 101	Univent	Metal	Gray	None	0	0.1	Negative
5390	1	1	Classroom 101	Convactor	Metal	Gray	None	0	0	Negative
5390	1	1	Classroom 101	Door Casing	Metal	Gray	Peeling	1	0.5	Negative
5390	1	1	Classroom 101	Door Casing	Metal	Gray	Peeling	1	0.5	Negative
5390	1	1	Classroom 101	Door Casing	Metal	Gray	Peeling	1	0.5	Negative
5390	1	1	Classroom 101	Door Casing	Metal	White	None	0	0.2	Negative
5390	1	1	Classroom 101	Door	Metal	Blue	None	0	0.1	Negative
5390	1	1	Classroom 101	Glazed Base	CMU	Brown	None	0	1.6	Positive

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Classroom 101	Cubby Base	Wood	Brown	Flaking	1	0.1	Negative
5390	1	1	Cafeteria Personnel Locker Room	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Cafeteria Personnel Locker Room	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Cafeteria Personnel Locker Room	W3	CMU	Beige	None	0	0	Negative
5390	1	1	Cafeteria Personnel Locker Room	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Cafeteria Personnel Locker Room	Ceiling	Concrete	Black	None	0	0.2	Negative
5390	1	1	Cafeteria Personnel Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Cafeteria Personnel Locker Room	Door Casing	Metal	Brown	None	0	0.2	Negative
5390	1	1	Cafeteria Personnel Locker Room	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Cafeteria Personnel Locker Room	Duct	Metal	Black	None	0	0.1	Negative
5390	1	1	Cafeteria Personnel Restroom	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	Cafeteria Personnel Restroom	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Cafeteria Personnel Restroom	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Cafeteria Personnel Restroom	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Cafeteria Personnel Restroom	Ceiling	Concrete	Black	None	0	0.1	Negative
5390	1	1	Cafeteria Personnel Restroom	Floor	Concrete	Brown	Cracking	2	0.3	Negative
5390	1	1	Cafeteria Personnel Restroom	Duct	Metal	Black	None	0	0.2	Negative
5390	1	1	Cafeteria Personnel Restroom	Door Casing	Metal	Brown	None	0	0.2	Negative
5390	1	1	Cafeteria Personnel Restroom	Stall	Metal	Brown	None	0	0	Negative
5390	1	1	Cleaning Assistant Office	W1	CMU	White	None	0	0	Negative
5390	1	1	Cleaning Assistant Office	W2	CMU	White	None	0	0.1	Negative
5390	1	1	Cleaning Assistant Office	W3	CMU	White	None	0	0.1	Negative
5390	1	1	Cleaning Assistant Office	W4	CMU	White	None	0	0.1	Negative
5390	1	1	Cleaning Assistant Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Cleaning Assistant Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Cleaning Assistant Office	Door	Metal	Brown	None	0	0.1	Negative
5390	1	1	Cleaning Assistant Office	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Cleaning Assistant Office	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Cleaning Assistant Office	Door	Metal	Brown	None	0	0.1	Negative
5390	1	1	Cleaning Assistant Office	Convactor	Metal	Gray	None	0	0.1	Negative
5390	1	1	Pipe Chase in Cleaning Assistant Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Cleaning Assistant Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Cleaning Assistant Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Cleaning Assistant Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Cleaning Assistant Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Pipe Chase in Cleaning Assistant Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Emergency Generator Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Emergency Generator Room	W2	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Emergency Generator Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Emergency Generator Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Emergency Generator Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Emergency Generator Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Transformer Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Transformer Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Transformer Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Transformer Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Transformer Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Transformer Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 1 near Cleaning Assistant Office - 101G and Shelter 8	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 1 near Cleaning Assistant Office - 101G and Shelter 8	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 1 near Cleaning Assistant Office - 101G and Shelter 8	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 1 near Cleaning Assistant Office - 101G and Shelter 8	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 1 near Cleaning Assistant Office - 101G and Shelter 8	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 1 near Cleaning Assistant Office - 101G and Shelter 8	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell 1 near Cleaning Assistant Office - 101G and Shelter 8	Convactor	Metal	BEIGE	POOR		0.01	Negative
5390	1	1	Building Engineer's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Building Engineer's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Building Engineer's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Building Engineer's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Building Engineer's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Building Engineer's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Building Engineer's Office	W1	CMU	Beige	None	0	0	Negative
5390	1	1	Building Engineer's Office	W2	CMU	Blue	None	0	0.2	Negative
5390	1	1	Building Engineer's Office	W3	CMU	Brown	Cracking	1	0.2	Negative
5390	1	1	Building Engineer's Office	W4	CMU	Blue	None	0	0.1	Negative
5390	1	1	Building Engineer's Office	Ceiling	Concrete	Beige	None	0	0.1	Negative
5390	1	1	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Building Engineer's Office	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Building Engineer's Office	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Building Engineer's Office	Door Casing	Metal	Brown	None	0	0.5	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Building Engineer's Office	Door	Metal	Brown	None	0	0.1	Negative
5390	1	1	Storage in Hallway 139A near Loading Dock	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Hallway 139A near Loading Dock	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Hallway 139A near Loading Dock	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Hallway 139A near Loading Dock	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Hallway 139A near Loading Dock	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Hallway 139A near Loading Dock	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W1	Concrete	Beige	None	0	0.2	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W2	Concrete	Beige	None	0	0.2	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W3	CMU	Beige	None	0	0	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Ceiling	Plaster	Beige	Blistering	4	0.2	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Pipe	Metal	White	Peeling	20	0.5	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Door	Metal	Brown	Peeling	2	0	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Door	Metal	Brown	Peeling	1	0.1	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Door	Metal	Brown	Peeling	1	0.1	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Security Panel	Metal	Brown	None	0	0	Negative
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W1	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway for Building Engineer's Office & to the Loading Dock	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	W1	CMU	Blue	None	0	0	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	W3	CMU	Blue	None	0	0.1	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	W4	CMU	Blue	None	0	0	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Door Casing	Metal	Brown	Cracking	1	0.5	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Door	Metal	Brown	Cracking	1	0.1	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Door	Metal	Brown	Cracking	1	0.4	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Door Casing	Metal	Brown	Cracking	1	0.2	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Glazed Base	CMU	Brown	None	0	1.6	Positive
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Electrical Panel	Metal	Brown	None	0	0.1	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Door Casing	Metal	Brown	None	0	0.2	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Door	Metal	Brown	Cracking	2	0	Negative
5390	1	1	Hallway from Cleaning Assistant Office to Women's Restroom	Door Center Post	Metal	Brown	Cracking	1	0	Negative
5390	1	1	Hallway behind Stage and from Classroom 105 to ESOL Area	W1	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Hallway behind Stage and from Classroom 105 to ESOL Area	W2	CMU	Blue	None	0	0.2	Negative
5390	1	1	Hallway behind Stage and from Classroom 105 to ESOL Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway behind Stage and from Classroom 105 to ESOL Area	W4	CMU	Blue	None	0	0.4	Negative
5390	1	1	Hallway behind Stage and from Classroom 105 to ESOL Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway behind Stage and from Classroom 105 to ESOL Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway behind Stage and from Classroom 105 to ESOL Area	Door Casing	Metal	Brown	Cracking	1	0.3	Negative
5390	1	1	Hallway behind Stage and from Classroom 105 to ESOL Area	Door Casing	Metal	Brown	Cracking	1	0.5	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W1	CMU	GREEN	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W1	CMU	WHITE	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W2	CMU	GREEN	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W2	Metal	WHITE	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W2	CMU	BEIGE	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W2	CMU	BEIGE	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W3	CMU	GREEN	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W3	CMU	WHITE	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W4	CMU	WHITE	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W4	CMU	GREEN	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	W4	CMU	BEIGE	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Men's Restroom to ESOL Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway from Men's Restroom to ESOL Area	Glazed Base	CMU	BROWN	None	0	1.2	Positive
5390	1	1	Hallway from Men's Restroom to ESOL Area	Glazed Base	CMU	BROWN	None	0	1.4	Positive
5390	1	1	Hallway from Men's Restroom to ESOL Area	electrical panel	Metal	BROWN	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	DOOR CASING	Metal	BROWN	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	DOOR	Metal	BROWN	Cracking		0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	Convactor	Metal	BROWN	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	DOOR CASING	Metal	BROWN	None	0	0	Negative
5390	1	1	Hallway from Men's Restroom to ESOL Area	DOOR	Metal	BROWN	Cracking		0	Negative
5390	1	1	Hallway along Kitchen Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway along Kitchen Area	W2	Metal	BEIGE	None	0	0	Negative
5390	1	1	Hallway along Kitchen Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway along Kitchen Area	W4	Metal	BEIGE	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Hallway along Kitchen Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway along Kitchen Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway along Kitchen Area	Glazed Base	CMU	BROWN	None	0	1	Positive
5390	1	1	Stairwell to Kitchen	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell to Kitchen	W2	CMU	Beige	None	0	0	Negative
5390	1	1	Stairwell to Kitchen	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell to Kitchen	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell to Kitchen	Ceiling	Plaster	Beige	None	0	0.3	Negative
5390	1	1	Stairwell to Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stairwell to Kitchen	Door Casing	Metal	Brown	None	0	0.3	Negative
5390	1	1	Stairwell to Kitchen	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Stairwell to Kitchen	Stairs - Railing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Kitchen Storage	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Kitchen Storage	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Kitchen Storage	W3	CMU	Beige	None	0	0	Negative
5390	1	1	Kitchen Storage	W4	CMU	Beige	None	0	0.2	Negative
5390	1	1	Kitchen Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Kitchen Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Kitchen Storage	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Kitchen Storage	Door Casing	Metal	Brown	None	0	0.3	Negative
5390	1	1	Kitchen Storage	Duct	Metal	White	None	0	0.4	Negative
5390	1	1	Kitchen Storage	Glazed Base	CMU	Brown	None	0	1.6	Positive
5390	1	1	Kitchen Office	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Kitchen Office	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Kitchen Office	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Kitchen Office	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Kitchen Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Kitchen Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Kitchen Office	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Kitchen Office	Glazed Base	CMU	Beige	None	0	2	Positive
5390	1	1	Lunch/Food Line-Counter	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Lunch/Food Line-Counter	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Lunch/Food Line-Counter	W3	CMU	Beige	None	0	0.1	Negative
5390	1	1	Lunch/Food Line-Counter	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Lunch/Food Line-Counter	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Lunch/Food Line-Counter	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Lunch/Food Line-Counter	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Refrigerator Unit and Mixers Room	W1	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Refrigerator Unit and Mixers Room	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Refrigerator Unit and Mixers Room	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Refrigerator Unit and Mixers Room	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Refrigerator Unit and Mixers Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Refrigerator Unit and Mixers Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Lunch/Food Line-Counter	W1	CMU	Beige	None	0	0.2	Negative
5390	1	1	Lunch/Food Line-Counter	W2	CMU	Beige	None	0	0.2	Negative
5390	1	1	Lunch/Food Line-Counter	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Lunch/Food Line-Counter	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Lunch/Food Line-Counter	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Lunch/Food Line-Counter	Door Casing	Metal	Brown	None	0	0.3	Negative
5390	1	1	Custodial Closet in Kitchen	W1	CMU	White	None	0	0.2	Negative
5390	1	1	Custodial Closet in Kitchen	W2	CMU	Beige	None	0	0	Negative
5390	1	1	Custodial Closet in Kitchen	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Custodial Closet in Kitchen	W4	CMU	Beige	None	0	0	Negative
5390	1	1	Custodial Closet in Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet in Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Custodial Closet in Kitchen	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Custodial Closet in Kitchen	Duct	Metal	White	None	0	0.3	Negative
5390	1	1	Old Walk-in Freezer/Refrigerator	W1	Concrete	White	None	0	0.3	Negative
5390	1	1	Old Walk-in Freezer/Refrigerator	W2	Concrete	White	None	0	0.2	Negative
5390	1	1	Old Walk-in Freezer/Refrigerator	W3	Concrete	White	None	0	0.3	Negative
5390	1	1	Old Walk-in Freezer/Refrigerator	W4	Concrete	White	None	0	0.3	Negative
5390	1	1	Old Walk-in Freezer/Refrigerator	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	Old Walk-in Freezer/Refrigerator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Kitchen	W1	CMU	Beige	None	0	0.1	Negative
5390	1	1	Kitchen	W2	CMU	Beige	None	0	0.1	Negative
5390	1	1	Kitchen	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Kitchen	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Kitchen	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Kitchen	Electrical Panel	Metal	Beige	None	0	0.1	Negative
5390	1	1	Kitchen	Dumbwaiter	Metal	Brown	None	0	0.5	Negative
5390	1	1	Kitchen	Soffit	Plaster	Beige	None	0	0	Negative
5390	1	1	Stairwell to Kitchen	Stairs - Railing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Stairwell to Kitchen	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	1	Stairwell to Kitchen	W4	CMU	Beige	None	0	0.2	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Stairwell to Kitchen	Ceiling	Plaster	Beige	Peeling	2	0	Negative
5390	1	1	Hallway/Ramp to Cafetorium (Main Office Side)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Main Office Side)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Main Office Side)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Main Office Side)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Main Office Side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Main Office Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Across from BE Area)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Across from BE Area)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Across from BE Area)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Across from BE Area)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Across from BE Area)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway/Ramp to Cafetorium (Across from BE Area)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Cafetorium	W1	CMU	BEIGE	None	0	0	Negative
5390	1	1	Cafetorium	W2	CMU	BEIGE	None	0	0	Negative
5390	1	1	Cafetorium	W3	CMU	BEIGE	None	0	0	Negative
5390	1	1	Cafetorium	W4	CMU	BEIGE	None	0	0	Negative
5390	1	1	Cafetorium	Ceiling	Plaster	BEIGE	None	0	0	Negative
5390	1	1	Cafetorium	Ceiling	Plaster	BEIGE	None	0	0	Negative
5390	1	1	Cafetorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Cafetorium	DOOR CASING	Metal	BEIGE	None	0	0.05	Negative
5390	1	1	Cafetorium	DOOR CASING	Metal	BEIGE	None	0	0.04	Negative
5390	1	1	Cafetorium	DOOR CASING	Metal	BEIGE	None	0	0.02	Negative
5390	1	1	Cafetorium	DOOR CASING	Metal	BEIGE	None	0	0.02	Negative
5390	1	1	Hallway and Steps next to stage (Classroom 104 Side)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Classroom 104 Side)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Classroom 104 Side)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Classroom 104 Side)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Classroom 104 Side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Classroom 104 Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Main Office Side)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Main Office Side)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Main Office Side)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Main Office Side)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Main Office Side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Hallway and Steps next to stage (Main Office Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Cafetorium Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Cafetorium Stage	W2	CMU	Beige	None	0	0.1	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Cafetorium Stage	W3	CMU	Beige	None	0	0.2	Negative
5390	1	1	Cafetorium Stage	W4	CMU	Beige	None	0	0.1	Negative
5390	1	1	Cafetorium Stage	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	1	Cafetorium Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Cafetorium Stage	Glazed Base	CMU	Brown	None	0	1.5	Positive
5390	1	1	Cafetorium Stage	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Cafetorium Stage	Door Casing	Metal	Brown	None	0	0.3	Negative
5390	1	1	Cafetorium Stage	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	1	Stage Storage (Classroom 104 Side)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Classroom 104 Side)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Classroom 104 Side)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Classroom 104 Side)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Classroom 104 Side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Classroom 104 Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Main Office Side)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Main Office Side)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Main Office Side)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Main Office Side)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Main Office Side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Stage Storage (Main Office Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 8 (outdoors/covered)	W1	Concrete	Red	None	0	0.3	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	W1	Concrete	Blue	Cracking	30	0.3	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 8 (outdoors/covered)	W3	Concrete	Blue	Cracking	30	0	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	W4	Concrete	Purple	None	0	0.3	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Ceiling	Plaster	Beige	None	0	0	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 8 (outdoors/covered)	Fence Post	Metal	Black	Cracking	3	0.1	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Fence Post	Metal	Black	Cracking	2	0	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Fence Post	Metal	Black	Cracking	1	0.1	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Fence Post	Metal	Black	Cracking	1	0	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Door	Metal	Brown	None	0	0.1	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Door Center Post	Metal	Brown	None	0	0	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Door Center Post	Metal	Brown	None	0	0	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Door	Metal	Brown	None	0	0	Negative
5390	1	1	Shelter No. 8 (outdoors/covered)	Door Casing	Metal	Brown	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	1	Storage in Shelter 8	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Shelter 8	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Shelter 8	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Shelter 8	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Shelter 8	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Storage in Shelter 8	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 6 (outdoors/covered)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 6 (outdoors/covered)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 6 (outdoors/covered)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 6 (outdoors/covered)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 6 (outdoors/covered)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 6 (outdoors/covered)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 7 (outdoors/covered)	W1	Concrete	Blue	None	0	0.3	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	W2	Concrete	Blue	Flaking	15	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	W3	Concrete	Blue	Flaking	25	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	W4	Concrete	Blue	None	0	0.2	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Ceiling	Plaster	Beige	Cracking	2	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 7 (outdoors/covered)	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Door	Metal	Brown	Flaking	1	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Door Center Post	Metal	Brown	Flaking	1	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Door Center Post	Metal	Brown	Flaking	1	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Door Casing	Metal	Brown	Flaking	1	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Door	Metal	Brown	Flaking	1	0.1	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Door	Metal	Brown	Flaking	1	0.1	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Door Casing	Metal	Brown	Flaking	1	0.1	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Fence Post	Metal	Black	Flaking	1	0.1	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Fence Post	Metal	Black	Flaking	1	0.1	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Fence Post	Metal	Black	Flaking	1	0	Negative
5390	1	1	Shelter No. 7 (outdoors/covered)	Vent Cover	Metal	Blue	None	0	0.3	Negative
5390	1	1	Shelter No. 5 (outdoors/covered)	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 5 (outdoors/covered)	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 5 (outdoors/covered)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 5 (outdoors/covered)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 5 (outdoors/covered)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	1	Shelter No. 5 (outdoors/covered)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Stairwell 3 near Rooms 216 and 217	W1	CMU	BEIGE	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Stairwell 3 near Rooms 216 and 217	W2	CMU	BEIGE	None	0	0	Negative
5390	1	2	Stairwell 3 near Rooms 216 and 217	W2	CMU	WHITE	None	0	0	Negative
5390	1	2	Stairwell 3 near Rooms 216 and 217	W3	CMU	BEIGE	None	0	0	Negative
5390	1	2	Stairwell 3 near Rooms 216 and 217	W4	CMU	BEIGE	None	0	0	Negative
5390	1	2	Stairwell 3 near Rooms 216 and 217	Ceiling	Concrete	WHITE	None	0	0	Negative
5390	1	2	Stairwell 3 near Rooms 216 and 217	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Stairwell 3 near Rooms 216 and 217	Convactor	Metal	BEIGE	POOR		0	Negative
5390	1	2	Stairwell 3 near Rooms 216 and 217	Glazed Base	CMU	BROWN	None	0	1.3	Positive
5390	1	2	Stairwell 3 near Rooms 216 and 217	railing	Metal	BEIGE	POOR	0	0.01	Negative
5390	1	2	Stairwell 3 near Rooms 216 and 217	riser	Metal	BROWN	FAIR		0.01	Negative
5390	1	2	Stairwell 3 near Rooms 216 and 217	Stringer	Metal	BROWN	FAIR		0	Negative
5390	1	2	Classroom 217	W1	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 217	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 217	W3	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 217	W4	Drywall	Beige	None	0	0.1	Negative
5390	1	2	Classroom 217	Ceiling	Concrete	White	Flaking	15	0.2	Negative
5390	1	2	Classroom 217	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 217	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 217	Door Casing	Metal	Brown	None	0	0.2	Negative
5390	1	2	Classroom 217	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Classroom 217	Univent	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 216	W1	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 216	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 216	W3	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 216	W4	CMU	Beige	None	0	0.6	Negative
5390	1	2	Classroom 216	Ceiling	Concrete	White	Flaking	20	0.2	Negative
5390	1	2	Classroom 216	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 216	Univent	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 216	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 216	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 215	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 215	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 215	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 215	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 215	Ceiling	Concrete	White	None	0	0.3	Negative
5390	1	2	Classroom 215	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 215	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Classroom 215	Univent	Metal	Brown	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Classroom 215	Radiator	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 215	Soffit	Plaster	Beige	None	0	0.2	Negative
5390	1	2	Book Closet between Rooms 214 and 215	W1	CMU	Beige	None	0	0.2	Negative
5390	1	2	Book Closet between Rooms 214 and 215	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Book Closet between Rooms 214 and 215	W3	CMU	Beige	None	0	0.2	Negative
5390	1	2	Book Closet between Rooms 214 and 215	W4	CMU	Beige	None	0	0	Negative
5390	1	2	Book Closet between Rooms 214 and 215	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Book Closet between Rooms 214 and 215	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Book Closet between Rooms 214 and 215	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Book Closet between Rooms 214 and 215	Door	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 214	W1	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 214	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 214	W3	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 214	W4	CMU	Beige	None	0	0.3	Negative
5390	1	2	Classroom 214	Ceiling	Concrete	White	Flaking	2	0.1	Negative
5390	1	2	Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 214	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 214	Radiator	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 214	Radiator	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 214	Univent	Metal	Brown	None	0	0.2	Negative
5390	1	2	Classroom 214	Door Casing	Metal	Brown	None	0	0.3	Negative
5390	1	2	Classroom 213	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 213	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 213	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 213	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 213	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Classroom 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 213	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Classroom 213	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 213	Univent	Metal	Brown	None	0	0.1	Negative
5390	1	2	Hallway along Rooms 213 to 216	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 213 to 216	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 213 to 216	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 213 to 216	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 213 to 216	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 213 to 216	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 220	W1	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 220	W1	CMU	Taupe	None	0	0.2	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Classroom 220	W2	Drywall	Beige	None	0	0.1	Negative
5390	1	2	Classroom 220	W2	CMU	Taupe	None	0	0.2	Negative
5390	1	2	Classroom 220	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 220	W3	CMU	Taupe	None	0	0	Negative
5390	1	2	Classroom 220	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 220	W4	Drywall	Orange	None	0	0	Negative
5390	1	2	Classroom 220	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	2	Classroom 220	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 220	Univent	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 220	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Classroom 220	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Classroom 220	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 220	Soffit	Plaster	White	None	0	0.2	Negative
5390	1	2	Classroom 220	Door Casing	Metal	Gray	None	0	0.1	Negative
5390	1	2	Classroom 220	Door Casing	Metal	Gray	None	0	0.3	Negative
5390	1	2	Classroom 220	Univent	Metal	Gray	None	0	0	Negative
5390	1	2	Hallway to Classroom 225	W1	N/A					
5390	1	2	Hallway to Classroom 225	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 225	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 225	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 225	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 225	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Men's Restroom near IMC	W1	CMU	Beige	None	0	0.2	Negative
5390	1	2	Men's Restroom near IMC	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Men's Restroom near IMC	W3	CMU	Beige	None	0	0.2	Negative
5390	1	2	Men's Restroom near IMC	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Men's Restroom near IMC	Ceiling	Concrete	White	None	0	0.3	Negative
5390	1	2	Men's Restroom near IMC	Floor	Concrete	Gray	Flaking	2	0	Negative
5390	1	2	Men's Restroom near IMC	Stall	Metal	Brown	None	0	0	Negative
5390	1	2	Men's Restroom near IMC	Convactor	Metal	Brown	None	0	0.1	Negative
5390	1	2	Men's Restroom near IMC	Duct	Metal	White	None	0	0.5	Negative
5390	1	2	Men's Restroom near IMC	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Classroom 228A	W1	CMU	Beige	Cracking	1	0.2	Negative
5390	1	2	Classroom 228A	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 228A	W2	Wood	Beige	None	0	0.3	Negative
5390	1	2	Classroom 228A	W3	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 228A	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 228A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Classroom 228A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 228A	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Portal B/Classroom 228	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Portal B/Classroom 228	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Portal B/Classroom 228	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Portal B/Classroom 228	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Portal B/Classroom 228	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Portal B/Classroom 228	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 228 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 228 Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 228 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 228 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 228 Restroom	Ceiling	Plaster	WHITE	POOR		0	Negative
5390	1	2	Classroom 228 Restroom	Floor	Concrete	WHITE	POOR		0	Negative
5390	1	2	Classroom 228 Restroom	Convector	Concrete	BROWN	None	0	0	Negative
5390	1	2	Classroom 228 Restroom	DOOR CASING	Metal	BROWN	None	0	0	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	W1	CMU	Beige	None	0	4.5	Positive
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	W4	CMU	Beige	None	0	0	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	Glazed Base	CMU	Brown	None	0	1.7	Positive
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	Pipe Chase Cover	Metal	Beige	None	0	1.7	Positive
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	Column	Concrete	Beige	Peeling	3	2.2	Positive
5390	1	2	Entrance Lobby to Teacher Lounge (Classroom 220 Side)	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Teacher Lounge/Dining Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Teacher Lounge/Dining Area	W2	CMU	Beige	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Teacher Lounge/Dining Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Teacher Lounge/Dining Area	W4	CMU	Beige	Flaking	2	0.1	Negative
5390	1	2	Teacher Lounge/Dining Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Teacher Lounge/Dining Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Teacher Lounge/Dining Area	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Teacher Lounge/Dining Area	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Teacher Lounge/Dining Area	Glazed Base	CMU	Brown	None	0	1.7	Positive
5390	1	2	Teacher Lounge/Dining Area	Pipe Chase Cover	Metal	Beige	None	0	0.1	Negative
5390	1	2	Teacher Lounge/Dining Area	Dumbwaiter	Metal	Brown	None	0	0.1	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	W1	CMU	Beige	None	0	0.2	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	W2	CMU	Beige	None	0	0.2	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	Column	Concrete	Beige	None	0	0.3	Negative
5390	1	2	Entrance Lobby to Teacher Lounge (Art Room Side)	Glazed Base	CMU	Brown	None	0	1.3	Positive
5390	1	2	IMC Storage - Room 228A Side	W1	CMU	Beige	None	0	0	Negative
5390	1	2	IMC Storage - Room 228A Side	W2	CMU	Beige	None	0	0.2	Negative
5390	1	2	IMC Storage - Room 228A Side	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	IMC Storage - Room 228A Side	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	IMC Storage - Room 228A Side	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	IMC Storage - Room 228A Side	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	IMC (Library)	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	IMC (Library)	W1	CMU	GREEN	None	0	0	Negative
5390	1	2	IMC (Library)	W2	CMU	Beige	None	0	0	Negative
5390	1	2	IMC (Library)	W2	CMU	BLUE	None	0	0	Negative
5390	1	2	IMC (Library)	W2	Drywall	BEIGE	FAIR		0	Negative
5390	1	2	IMC (Library)	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	IMC (Library)	W3	CMU	WHITE	None	0	0	Negative
5390	1	2	IMC (Library)	W3	CMU	RED	None	0	0	Negative
5390	1	2	IMC (Library)	W3	Drywall	BEIGE	None	0	0	Negative
5390	1	2	IMC (Library)	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	IMC (Library)	W4	CMU	BLUE	None	0	0	Negative
5390	1	2	IMC (Library)	Ceiling	Concrete	WHITE	Peeling		0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	IMC (Library)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	IMC (Library)	Glazed Base	CMU	Beige	None	0	1.8	Positive
5390	1	2	IMC (Library)	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	2	IMC (Library)	Convactor	Metal	BROWN	FAIR		0.01	Negative
5390	1	2	IMC (Library)	Univent	Metal	BROWN	Peeling		0	Negative
5390	1	2	IMC (Library)	DOOR CASING	Plaster	BEIGE	None	0	0.03	Negative
5390	1	2	IMC (Library)	DOOR CASING	Plaster	BEIGE	None	0	0.09	Negative
5390	1	2	IMC (Library)	soffit	Plaster	WHITE	None	0	0	Negative
5390	1	2	IMC (Library)	soffit	Plaster	BLUE	None	0	0	Negative
5390	1	2	IMC (Library)	soffit	Plaster	BLUE	None	0	0	Negative
5390	1	2	IMC (Library)	soffit	Plaster	BLUE	None	0	0	Negative
5390	1	2	IMC Storage - Art Room Side	W1	CMU	BEIGE	None	0	0	Negative
5390	1	2	IMC Storage - Art Room Side	W2	CMU	BEIGE	None	0	0	Negative
5390	1	2	IMC Storage - Art Room Side	W3	CMU	BEIGE	None	0	0	Negative
5390	1	2	IMC Storage - Art Room Side	W3	CMU	BEIGE	None	0	0	Negative
5390	1	2	IMC Storage - Art Room Side	W4	CMU	BEIGE	None	0	0	Negative
5390	1	2	IMC Storage - Art Room Side	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	IMC Storage - Art Room Side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	IMC Storage - Art Room Side	DOOR CASING	Metal	BEIGE	Cracking		0	Negative
5390	1	2	IMC Storage - Art Room Side	DOOR CASING	Metal	BROWN	None	0	0.1	Negative
5390	1	2	Storage Room in IMC (other side)	W1	CMU	BEIGE	None	0	0	Negative
5390	1	2	Storage Room in IMC (other side)	W2	CMU	BEIGE	None	0	0	Negative
5390	1	2	Storage Room in IMC (other side)	W3	CMU	BEIGE	None	0	0	Negative
5390	1	2	Storage Room in IMC (other side)	W4	CMU	BEIGE	None	0	0	Negative
5390	1	2	Storage Room in IMC (other side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Storage Room in IMC (other side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Storage Room in IMC (other side)	DOOR CASING	Metal	BEIGE	Cracking		0	Negative
5390	1	2	Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative
5390	1	2	Boy's Restroom	W2	CMU	BEIGE	None	0	0	Negative
5390	1	2	Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative
5390	1	2	Boy's Restroom	W4	CMU	BEIGE	None	0	0	Negative
5390	1	2	Boy's Restroom	Ceiling	Metal	WHITE	None	0	0	Negative
5390	1	2	Boy's Restroom	Floor	Concrete	GRAY	None	0	0	Negative
5390	1	2	Boy's Restroom	Convactor	Metal	BEIGE	None	0	0	Negative
5390	1	2	Boy's Restroom	DOOR	Metal	BROWN	None	0	0	Negative
5390	1	2	Boy's Restroom	DOOR CASING	Metal	BROWN	None	0	0	Negative
5390	1	2	Boy's Restroom	exhaust duct	Metal	WHITE	None	0	0.4	Negative
5390	1	2	Boy's Restroom	roof drain pipe	Metal	BEIGE	None	0	1.4	Positive

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Boy's Restroom	roof drain pipe	Metal	BEIGE	None	0	1	Positive
5390	1	2	Boy's Restroom	stall partition	Metal	BROWN	None	0	0	Negative
5390	1	2	Custodial Closet between Restrooms	W1	CMU	BEIGE	FAIR		0	Negative
5390	1	2	Custodial Closet between Restrooms	W2	CMU	BEIGE	FAIR		0	Negative
5390	1	2	Custodial Closet between Restrooms	W3	CMU	BEIGE	FAIR		0	Negative
5390	1	2	Custodial Closet between Restrooms	W4	CMU	BEIGE	FAIR		0	Negative
5390	1	2	Custodial Closet between Restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Custodial Closet between Restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Custodial Closet between Restrooms	Conduit	Metal	BEIGE	FAIR		0.01	Negative
5390	1	2	Custodial Closet between Restrooms	DOOR CASING	Metal	BROWN	None	0	0.02	Negative
5390	1	2	Custodial Closet between Restrooms	DOOR CASING pipe chase	Metal	BROWN	FAIR		0.01	Negative
5390	1	2	Pipe Chase in Custodial Closet between Restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Restrooms	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Restrooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Restrooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Girl's Restroom	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	Girl's Restroom	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Girl's Restroom	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Girl's Restroom	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Girl's Restroom	Ceiling	Concrete	White	Peeling	2	0.2	Negative
5390	1	2	Girl's Restroom	Floor	Concrete	Gray	Peeling	2	0	Negative
5390	1	2	Girl's Restroom	Door	Metal	Brown	Peeling	1	0.1	Negative
5390	1	2	Girl's Restroom	Door Casing	Metal	Brown	Peeling	1	0	Negative
5390	1	2	Girl's Restroom	Stall	Metal	Brown	Peeling	1	0.1	Negative
5390	1	2	Girl's Restroom	Duct	Metal	White	Peeling	1	0.3	Negative
5390	1	2	Girl's Restroom	Convactor	Metal	Beige	Peeling	1	0	Negative
5390	1	2	Office 227	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office 227	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office 227	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office 227	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office 227	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office 227	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Music Instrument Storage Room	W1	CMU	Beige	None	0	0.2	Negative
5390	1	2	Music Instrument Storage Room	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Music Instrument Storage Room	W3	CMU	Beige	None	0	0.1	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Music Instrument Storage Room	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Music Instrument Storage Room	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Music Instrument Storage Room	Floor	Concrete	GRAY	Cracking		0	Negative
5390	1	2	Music Instrument Storage Room	Duct	Metal	White	None	0	0.1	Negative
5390	1	2	Music Instrument Storage Room	Convactor	Metal	Beige	None	0	0	Negative
5390	1	2	Music Instrument Storage Room	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Music Instrument Storage Room	Door Cage	Metal	Black	None	0	0.1	Negative
5390	1	2	Classroom 226A	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226A	W2	CMU	BEIGE	Cracking		0	Negative
5390	1	2	Classroom 226A	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226A	W4	Wood Panel	BEIGE	None	0	0	Negative
5390	1	2	Classroom 226A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226A	DOOR CASING	Metal	BROWN	None	0	0	Negative
5390	1	2	Classroom 226 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226 Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226	W1	Wood Panel	BEIGE	None	0	0	Negative
5390	1	2	Classroom 226	W2	Wood Panel	BEIGE	None	0	0	Negative
5390	1	2	Classroom 226	W2	CMU	BEIGE	None	0	0	Negative
5390	1	2	Classroom 226	W3	CMU	BEIGE	None	0	0	Negative
5390	1	2	Classroom 226	W4	Wood Panel	BEIGE	None	0	0	Negative
5390	1	2	Classroom 226	Ceiling	Concrete	WHITE	None	0	0	Negative
5390	1	2	Classroom 226	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 226	Convactor	Metal	BROWN	Cracking		0	Negative
5390	1	2	Classroom 226	Univent	Metal	BROWN	Cracking		0	Negative
5390	1	2	Classroom 226	DOOR CASING	Metal	BROWN	None	0	0	Negative
5390	1	2	Hallway to Classroom 226	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 226	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 226	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 226	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 226	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Classroom 226	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 221	W1	CMU	Beige	Cracking	22	0	Negative
5390	1	2	Classroom 221	W2	CMU	Beige	None	0	0.4	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Classroom 221	W3	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 221	W4	Drywall	Beige	None	0	0.1	Negative
5390	1	2	Classroom 221	Ceiling	Concrete	White	Flaking	15	0.4	Negative
5390	1	2	Classroom 221	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 221	Univent	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 221	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Classroom 221	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Classroom 221	Soffit	Plaster	Beige	None	0	0	Negative
5390	1	2	Classroom 224	W1	CMU	Beige	Flaking	3	0.3	Negative
5390	1	2	Classroom 224	W2	Drywall	Beige	None	0	0	Negative
5390	1	2	Classroom 224	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 224	W4	CMU	Beige	Flaking	10	0.1	Negative
5390	1	2	Classroom 224	Ceiling	Concrete	White	None	0	0.3	Negative
5390	1	2	Classroom 224	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 224	Soffit	Plaster	Beige	None	0	0.5	Negative
5390	1	2	Classroom 224	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 224	Univent	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 212	W1	CMU	White	None	0	0.4	Negative
5390	1	2	Classroom 212	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 212	W3	CMU	White	None	0	0.1	Negative
5390	1	2	Classroom 212	W4	CMU	White	None	0	0.1	Negative
5390	1	2	Classroom 212	Ceiling	Concrete	White	None	0	0.3	Negative
5390	1	2	Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 212	Dividing Wall	Metal	Beige	None	0	0.1	Negative
5390	1	2	Classroom 212	Univent	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 212	Vertical intake	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 212	Soffit	Drywall	Beige	None	0	0.2	Negative
5390	1	2	Classroom 212	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 211	W1	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 211	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 211	W3	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 211	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 211	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 211	Soffit	Plaster	Beige	None	0	0.2	Negative
5390	1	2	Classroom 211	Radiator	Metal	Brown	None	0	0.3	Negative
5390	1	2	Classroom 211	Radiator	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 211	Univent	Metal	Brown	None	0	0.2	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Book Closet between Rooms 210 and 211	W1	CMU	Beige	None	0	0.2	Negative
5390	1	2	Book Closet between Rooms 210 and 211	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Book Closet between Rooms 210 and 211	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Book Closet between Rooms 210 and 211	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Book Closet between Rooms 210 and 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Book Closet between Rooms 210 and 211	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Book Closet between Rooms 210 and 211	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Book Closet between Rooms 210 and 211	Glazed Base	CMU	Brown	None	0	1.6	Positive
5390	1	2	Classroom 210	W1	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 210	W2	Drywall	Beige	None	0	0.1	Negative
5390	1	2	Classroom 210	W3	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 210	W4	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 210	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	2	Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 210	Univent	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 210	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 210	Radiator	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 210	Door Casing	Metal	Brown	None	0	0.3	Negative
5390	1	2	Classroom 209	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 209	W2	CMU	Beige	Flaking	10	0.4	Negative
5390	1	2	Classroom 209	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 209	W4	Drywall	Beige	None	0	0.1	Negative
5390	1	2	Classroom 209	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 209	Door Casing	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 209	Univent	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 209	Soffit	Plaster	Beige	None	0	0	Negative
5390	1	2	Stairwell 4 near Classroom 224	W1	CMU	Beige	None	0	0	Negative
5390	1	2	Stairwell 4 near Classroom 224	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Stairwell 4 near Classroom 224	W2	Concrete	Beige	None	0	0.2	Negative
5390	1	2	Stairwell 4 near Classroom 224	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Stairwell 4 near Classroom 224	W4	CMU	Beige	None	0	0	Negative
5390	1	2	Stairwell 4 near Classroom 224	W4	Concrete	Beige	None	0	0.1	Negative
5390	1	2	Stairwell 4 near Classroom 224	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Stairwell 4 near Classroom 224	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Stairwell 4 near Classroom 224	Door	Metal	Brown	Peeling	1	0	Negative
5390	1	2	Stairwell 4 near Classroom 224	Door Casing	Metal	Brown	Peeling	1	0.5	Negative
5390	1	2	Stairwell 4 near Classroom 224	Stairs - Railing	Metal	Brown	Peeling	1	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Stairwell 4 near Classroom 224	Stairs - Stringer	Metal	Brown	Peeling	1	0.1	Negative
5390	1	2	Stairwell 4 near Classroom 224	Stairs - Riser	Metal	Brown	Peeling	1	0.2	Negative
5390	1	2	Stairwell 4 near Classroom 224	Door Casing	Metal	Brown	Peeling	1	0	Negative
5390	1	2	Stairwell 4 near Classroom 224	Door	Metal	Brown	None	0	0	Negative
5390	1	2	Hallway along Rooms 209 to 212	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 209 to 212	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 209 to 212	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 209 to 212	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 209 to 212	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Rooms 209 to 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway between Classrooms 224 and 217	W1	CMU	Beige	None	0	N/A	N/A
5390	1	2	Hallway between Classrooms 224 and 217	W2	CMU	Beige	None	0	N/A	N/A
5390	1	2	Hallway between Classrooms 224 and 217	W3	CMU	Beige	None	0	N/A	N/A
5390	1	2	Hallway between Classrooms 224 and 217	W4	CMU	Beige	None	0	N/A	N/A
5390	1	2	Hallway between Classrooms 224 and 217	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway between Classrooms 224 and 217	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway between Classrooms 224 and 217	Door	Metal	Brown	None	0	0	Negative
5390	1	2	Hallway between Classrooms 224 and 217	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Hallway between Classrooms 224 and 217	Door Casing	Metal	Brown	None	0	0.3	Negative
5390	1	2	Hallway between Classrooms 224 and 217	Door	Metal	Brown	Peeling	1	0	Negative
5390	1	2	Stairwell 1 near Classroom 218	W1	CMU	BEIGE	None	0	0	Negative
5390	1	2	Stairwell 1 near Classroom 218	W2	CMU	WHITE	None	0	0	Negative
5390	1	2	Stairwell 1 near Classroom 218	W3	CMU	WHITE	None	0	0	Negative
5390	1	2	Stairwell 1 near Classroom 218	W4	CMU	BEIGE	None	0	0	Negative
5390	1	2	Stairwell 1 near Classroom 218	Ceiling	CMU	WHITE	None	0	0	Negative
5390	1	2	Stairwell 1 near Classroom 218	Ceiling	CMU	BEIGE	None	0	0	Negative
5390	1	2	Stairwell 1 near Classroom 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Stairwell 1 near Classroom 218	DOOR	Metal	BROWN	Cracking		0.01	Negative
5390	1	2	Stairwell 1 near Classroom 218	DOOR CASING	Metal	BROWN	None	0	0.02	Negative
5390	1	2	Stairwell 1 near Classroom 218	railing	Metal	BEIGE	POOR		0.03	Negative
5390	1	2	Stairwell 1 near Classroom 218	riser	Metal	BROWN	FAIR		0	Negative
5390	1	2	Stairwell 1 near Classroom 218	stringer	Metal	BEIGE	Cracking		0	Negative
5390	1	2	Classroom 218	W1	CMU	Beige	None	0	0.3	Negative
5390	1	2	Classroom 218	W2	Drywall	Orange	Peeling	2	0.1	Negative
5390	1	2	Classroom 218	W3	CMU	Beige	None	0	0.5	Negative
5390	1	2	Classroom 218	W4	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 218	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Classroom 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Classroom 218	Univent	Metal	Gray	None	0	0	Negative
5390	1	2	Classroom 218	Door Casing	Metal	Gray	None	0	0.5	Negative
5390	1	2	Classroom 218	Door Casing	Metal	Gray	None	0	0.3	Negative
5390	1	2	Classroom 218	Soffit	Plaster	White	None	0	0.1	Negative
5390	1	2	Classroom 219	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 219	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 219	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 219	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 219	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 219	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 201	W1	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 201	W2	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 201	W3	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 201	W3	Drywall	Orange	None	0	0.2	Negative
5390	1	2	Classroom 201	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 201	Ceiling	Concrete	White	None	0	0	Negative
5390	1	2	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 201	Soffit	Plaster	White	None	0	0	Negative
5390	1	2	Classroom 201	Door Casing	Metal	Gray	None	0	0.4	Negative
5390	1	2	Classroom 202	W1	CMU	Taupe	None	0	0.2	Negative
5390	1	2	Classroom 202	W2	Drywall	Orange	None	0	0.1	Negative
5390	1	2	Classroom 202	W3	CMU	Taupe	None	0	0.2	Negative
5390	1	2	Classroom 202	W4	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 202	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 202	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 202	Door Casing	Metal	Gray	None	0	0.1	Negative
5390	1	2	Book Closet between Classrooms 202 and 203	W1	CMU	WHITE	None	0	0	Negative
5390	1	2	Book Closet between Classrooms 202 and 203	W2	CMU	WHITE	None	0	0	Negative
5390	1	2	Book Closet between Classrooms 202 and 203	W3	CMU	WHITE	None	0	0	Negative
5390	1	2	Book Closet between Classrooms 202 and 203	W4	CMU	WHITE	None	0	0	Negative
5390	1	2	Book Closet between Classrooms 202 and 203	Ceiling	CMU	WHITE	None	0	0	Negative
5390	1	2	Book Closet between Classrooms 202 and 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Book Closet between Classrooms 202 and 203	DOOR CASING	Metal	BROWN	None	0	0.1	Negative
5390	1	2	Classroom 203	W1	CMU	Gray	None	0	0.2	Negative
5390	1	2	Classroom 203	W2	CMU	Gray	None	0	0.3	Negative
5390	1	2	Classroom 203	W3	CMU	Gray	None	0	0.1	Negative
5390	1	2	Classroom 203	W4	Drywall	Orange	None	0	0.1	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Classroom 203	Ceiling	Concrete	White	None	0	0.4	Negative
5390	1	2	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 203	Door Casing	Metal	Gray	None	0	0.1	Negative
5390	1	2	Classroom 203	Soffit	Drywall	White	None	0	0.1	Negative
5390	1	2	Classroom 203	Radiator	Metal	Gray	None	0	0	Negative
5390	1	2	Classroom 203	Radiator	Metal	Gray	None	0	0	Negative
5390	1	2	Classroom 203	Radiator	Metal	Gray	None	0	0	Negative
5390	1	2	Classroom 204	W1	CMU	Taupe	None	0	0.2	Negative
5390	1	2	Classroom 204	W2	Drywall	Orange	None	0	0.1	Negative
5390	1	2	Classroom 204	W3	CMU	Taupe	None	0	0.2	Negative
5390	1	2	Classroom 204	W4	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 204	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 204	Door Casing	Metal	Gray	None	0	0.1	Negative
5390	1	2	Classroom 204	Soffit	Plaster	Beige	None	0	0	Negative
5390	1	2	Hallway along Classrooms 201 to 204	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 201 to 204	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 201 to 204	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 201 to 204	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 201 to 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 201 to 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Stairwell 2 near Classroom 223	W1	CMU	Beige	None	0	0.4	Negative
5390	1	2	Stairwell 2 near Classroom 223	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Stairwell 2 near Classroom 223	W2	Concrete	Beige	None	0	0.2	Negative
5390	1	2	Stairwell 2 near Classroom 223	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Stairwell 2 near Classroom 223	W4	CMU	Beige	None	0	0	Negative
5390	1	2	Stairwell 2 near Classroom 223	W4	Concrete	Beige	None	0	0.3	Negative
5390	1	2	Stairwell 2 near Classroom 223	Ceiling	Concrete	White	None	0	0.3	Negative
5390	1	2	Stairwell 2 near Classroom 223	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Stairwell 2 near Classroom 223	Stairs - Stringer	Metal	Brown	None	0	0	Negative
5390	1	2	Stairwell 2 near Classroom 223	Stairs - Riser	Metal	Brown	None	0	0	Negative
5390	1	2	Stairwell 2 near Classroom 223	Stairs - Railing	Metal	Brown	Flaking	1	0	Negative
5390	1	2	Stairwell 2 near Classroom 223	Door	Metal	Brown	Cracking	1	0	Negative
5390	1	2	Stairwell 2 near Classroom 223	Door Casing	Metal	Brown	Cracking	1	0	Negative
5390	1	2	Stairwell 2 near Classroom 223	Door Casing	Metal	Brown	Cracking	1	0.4	Negative
5390	1	2	Stairwell 2 near Classroom 223	Door	Metal	Brown	Cracking	2	0.1	Negative
5390	1	2	Stairwell 2 near Classroom 223	Glazed Base	CMU	Brown	None	0	1.1	Positive
5390	1	2	Stairwell 2 near Classroom 223	Glazed Base	CMU	Brown	None	0	1.3	Positive

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Classroom 223	W1	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 223	W2	CMU	Beige	None	0	0.2	Negative
5390	1	2	Classroom 223	W3	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 223	W4	Drywall	Beige	None	0	0	Negative
5390	1	2	Classroom 223	Ceiling	Concrete	White	None	0	0	Negative
5390	1	2	Classroom 223	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 223	Univent	Metal	Brown	None	0	0.1	Negative
5390	1	2	Classroom 223	Soffit	Plaster	Beige	None	0	0.4	Negative
5390	1	2	Classroom 222	W1	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 222	W2	Drywall	Beige	None	0	0.1	Negative
5390	1	2	Classroom 222	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Classroom 222	W4	CMU	Beige	None	0	0	Negative
5390	1	2	Classroom 222	Ceiling	Concrete	White	None	0	0	Negative
5390	1	2	Classroom 222	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 222	Soffit	Plaster	Beige	None	0	0	Negative
5390	1	2	Classroom 222	Door Casing	Metal	Brown	None	0	0.4	Negative
5390	1	2	Classroom 222	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Classroom 222	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 222	Univent	Metal	Brown	None	0	0	Negative
5390	1	2	Classroom 208	W1	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 208	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 208	W3	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 208	W4	CMU	Taupe	None	0	0	Negative
5390	1	2	Classroom 208	W4	Drywall	Orange	None	0	0.1	Negative
5390	1	2	Classroom 208	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 208	Door Casing	Metal	Gray	None	0	0.3	Negative
5390	1	2	Classroom 208	Soffit	Plaster	White	None	0	0.2	Negative
5390	1	2	Classroom 208	Univent	Metal	Gray	None	0	0.2	Negative
5390	1	2	Classroom 207	W1	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 207	W2	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 207	W3	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 207	W4	Drywall	Orange	None	0	0.1	Negative
5390	1	2	Classroom 207	Ceiling	Concrete	White	None	0	0.2	Negative
5390	1	2	Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 207	Door Casing	Metal	Gray	None	0	0.3	Negative
5390	1	2	Classroom 207	Soffit	Plaster	Beige	None	0	0.1	Negative
5390	1	2	Classroom 207	Radiator	Metal	Gray	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Classroom 207	Radiator	Metal	Gray	None	0	0.1	Negative
5390	1	2	Classroom 207	Univent	Metal	Gray	None	0	0	Negative
5390	1	2	Storage between Classrooms 206 and 207	W1	CMU	Beige	None	0	0	Negative
5390	1	2	Storage between Classrooms 206 and 207	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Storage between Classrooms 206 and 207	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Storage between Classrooms 206 and 207	W4	CMU	Beige	None	0	0.3	Negative
5390	1	2	Storage between Classrooms 206 and 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Storage between Classrooms 206 and 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Storage between Classrooms 206 and 207	Glazed Base	CMU	Beige	None	0	1.6	Positive
5390	1	2	Storage between Classrooms 206 and 207	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Classroom 206	W1	CMU	Taupe	None	0	0	Negative
5390	1	2	Classroom 206	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 206	W3	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 206	W4	CMU	Taupe	None	0	0	Negative
5390	1	2	Classroom 206	W4	Drywall	Orange	None	0	0.2	Negative
5390	1	2	Classroom 206	Ceiling	Concrete	White	Flaking	10	0.1	Negative
5390	1	2	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 206	Univent	Metal	Gray	None	0	0.1	Negative
5390	1	2	Classroom 206	Soffit	Plaster	White	None	0	0.1	Negative
5390	1	2	Classroom 206	Radiator	Metal	Gray	None	0	0	Negative
5390	1	2	Classroom 206	Radiator	Metal	Gray	None	0	0	Negative
5390	1	2	Classroom 206	Door Casing	Metal	Gray	None	0	0.1	Negative
5390	1	2	Classroom 205	W1	CMU	Taupe	None	0	0	Negative
5390	1	2	Classroom 205	W2	CMU	Taupe	None	0	0	Negative
5390	1	2	Classroom 205	W3	CMU	Taupe	None	0	0.1	Negative
5390	1	2	Classroom 205	W4	Drywall	Orange	None	0	0.1	Negative
5390	1	2	Classroom 205	Ceiling	Concrete	White	None	0	0.1	Negative
5390	1	2	Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Classroom 205	Univent	Metal	Gray	None	0	0	Negative
5390	1	2	Classroom 205	Door Casing	Metal	Gray	None	0	0.4	Negative
5390	1	2	Classroom 205	Soffit	Plaster	White	None	0	0.1	Negative
5390	1	2	Hallway along Classrooms 205 to 208	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 205 to 208	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 205 to 208	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 205 to 208	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 205 to 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway along Classrooms 205 to 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Guidance Counselor Office (Room 225)	W1	CMU	Beige	None	0	0.2	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Guidance Counselor Office (Room 225)	W2	CMU	Beige	None	0	0.2	Negative
5390	1	2	Guidance Counselor Office (Room 225)	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Guidance Counselor Office (Room 225)	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Guidance Counselor Office (Room 225)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Guidance Counselor Office (Room 225)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Guidance Counselor Office (Room 225)	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	2	Guidance Counselor Office (Room 225)	Glazed Base	CMU	Beige	None	0	1.6	Positive
5390	1	2	Art Room	W1	CMU	Blue	Peeling	1	0.2	Negative
5390	1	2	Art Room	W2	CMU	Green	Peeling	2	0.1	Negative
5390	1	2	Art Room	W3	CMU	Green	Peeling	2	0.1	Negative
5390	1	2	Art Room	W4	CMU	Blue	Peeling	1	0.1	Negative
5390	1	2	Art Room	Ceiling	Concrete	Green	None	0	0	Negative
5390	1	2	Art Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Art Room	Door	Wood	Green	Peeling	1	0	Negative
5390	1	2	Art Room	Door Casing	Metal	Green	Peeling	1	0.5	Negative
5390	1	2	Art Room	Convactor	Metal	Green	None	0	0	Negative
5390	1	2	Art Room	Univent	Metal	Green	Peeling	1	0	Negative
5390	1	2	Art Room	Window Casing	Metal	Green	None	0	0.2	Negative
5390	1	2	Art Room	Convactor	Metal	Blue	None	0	0	Negative
5390	1	2	Art Room	Door Casing	Metal	Blue	None	0	0.5	Negative
5390	1	2	Art Room	Door	Wood	Blue	None	0	0	Negative
5390	1	2	Art Room	Soffit	Drywall	Blue	Peeling	2	0.2	Negative
5390	1	2	Art Storage	W1	CMU	Green	None	0	0.1	Negative
5390	1	2	Art Storage	W2	CMU	Green	None	0	0.1	Negative
5390	1	2	Art Storage	W3	CMU	Green	None	0	0.1	Negative
5390	1	2	Art Storage	W4	CMU	Green	None	0	0	Negative
5390	1	2	Art Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Art Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Art Storage	Window Casing	Metal	Green	None	0	0.2	Negative
5390	1	2	Art Storage	Convactor	Metal	Green	Cracking	1	0.1	Negative
5390	1	2	Art Storage	Door Casing	Metal	Green	None	0	0.5	Negative
5390	1	2	Art Storage	Door	Wood	Green	None	0	0	Negative
5390	1	2	Hallway to Artroom - B	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - B	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - B	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - B	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - B	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Art/Science Storage	W1	CMU	Blue	None	0	0.1	Negative
5390	1	2	Art/Science Storage	W2	CMU	Blue	None	0	0.1	Negative
5390	1	2	Art/Science Storage	W3	CMU	Blue	None	0	0.2	Negative
5390	1	2	Art/Science Storage	W4	CMU	Blue	None	0	0.1	Negative
5390	1	2	Art/Science Storage	Ceiling	Ceiling Tile	Blue	None	0	0.1	Negative
5390	1	2	Art/Science Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Art/Science Storage	Door	Wood	Blue	None	0	0	Negative
5390	1	2	Art/Science Storage	Door Casing	Metal	Blue	None	0	0.5	Negative
5390	1	2	Art/Science Storage	Convactor	Metal	Blue	None	0	0	Negative
5390	1	2	Hallway to Artroom - A	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - A	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - A	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - A	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway to Artroom - A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office (Spanish-B)	W1	CMU	BEIGE	Cracking		0	Negative
5390	1	2	Office (Spanish-B)	W2	CMU	WHITE	Cracking		0	Negative
5390	1	2	Office (Spanish-B)	W3	CMU	BEIGE	Cracking		0	Negative
5390	1	2	Office (Spanish-B)	W4	CMU	BEIGE	Cracking		0	Negative
5390	1	2	Office (Spanish-B)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office (Spanish-B)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office (Spanish-B)	Wall	CMU GLAZED BASE	BEIGE	Cracking	1	1.5	Positive
5390	1	2	Office (Spanish-B)	Wall	CMU GLAZED BASE	BEIGE	Cracking	1	1.2	Positive
5390	1	2	Office (Spanish-B)	DOOR CASING	Metal	BROWN	None	0	0	Negative
5390	1	2	Office (Spanish-B)	WOOD PANEL WALL	Wood	BEIGE	None	0	0	Negative
5390	1	2	Women's Restroom near Art Room	W1	CMU	PURPLE	Cracking		0	Negative
5390	1	2	Women's Restroom near Art Room	W1	CMU	WHITE	None	0	0	Negative
5390	1	2	Women's Restroom near Art Room	W2	CMU	PURPLE	Cracking		0	Negative
5390	1	2	Women's Restroom near Art Room	W2	CMU	WHITE	None	0	0	Negative
5390	1	2	Women's Restroom near Art Room	W3	CMU	PURPLE	Cracking		0	Negative
5390	1	2	Women's Restroom near Art Room	W3	CMU	WHITE	None	0	0	Negative
5390	1	2	Women's Restroom near Art Room	W4	CMU	PURPLE	Cracking		0	Negative
5390	1	2	Women's Restroom near Art Room	W4	CMU	WHITE	None	0	0	Negative
5390	1	2	Women's Restroom near Art Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Women's Restroom near Art Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Women's Restroom near Art Room	Convactor	CMU	BROWN	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Women's Restroom near Art Room	DOOR CASING	Metal	BROWN	Cracking		0	Negative
5390	1	2	Women's Restroom near Art Room	stall partition	Metal	BROWN	None	0	0	Negative
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	W1	CMU	Beige	None	0	0.2	Negative
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	W3	CMU	Beige	Flaking	2	0.2	Negative
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	W4	CMU	Beige	Flaking	3	0.2	Negative
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	Ceiling	Concrete	White	None	0	0.3	Negative
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	Duct	Metal	White	None	0	0.3	Negative
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	Door Casing	Metal	Brown	Peeling	1	0.3	Negative
5390	1	2	Custodial Closet between Boy's and Girl's Restrooms - near IMC	Shelf	Wood	Beige	Peeling	1	0.3	Negative
5390	1	2	Pipe Chase in Custodial Closet between Boy's and Girl's Restrooms - near IMC	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Boy's and Girl's Restrooms - near IMC	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Boy's and Girl's Restrooms - near IMC	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Boy's and Girl's Restrooms - near IMC	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Boy's and Girl's Restrooms - near IMC	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Pipe Chase in Custodial Closet between Boy's and Girl's Restrooms - near IMC	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Boy's Restroom near Art Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Boy's Restroom near Art Room	W2	CMU	BEIGE	None	0	0	Negative
5390	1	2	Boy's Restroom near Art Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Boy's Restroom near Art Room	W4	CMU	BEIGE	None	0	0	Negative
5390	1	2	Boy's Restroom near Art Room	Ceiling	Ceiling Tile	Green	None	0	0.1	Negative
5390	1	2	Boy's Restroom near Art Room	Ceiling	Concrete	WHITE	None	0	0	Negative
5390	1	2	Boy's Restroom near Art Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Boy's Restroom near Art Room	Convactor	CMU	BROWN	None	0	0	Negative
5390	1	2	Boy's Restroom near Art Room	exhaust duct	Metal	WHITE	None	0	0	Negative

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Boy's Restroom near Art Room	STALL PARTITION	Metal	BLUE	FAIR		0	Negative
5390	1	2	Girl's Restroom near Art Room	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	Girl's Restroom near Art Room	W1	CMU	WHITE	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	W2	CMU	WHITE	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Girl's Restroom near Art Room	W3	CMU	WHITE	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Girl's Restroom near Art Room	W4	CMU	WHITE	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	Ceiling	Concrete	Gray	None	0	0.1	Negative
5390	1	2	Girl's Restroom near Art Room	Ceiling	Concrete	WHITE	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	Floor	Concrete	Gray	None	0	0.1	Negative
5390	1	2	Girl's Restroom near Art Room	Duct	Metal	White	None	0	0.2	Negative
5390	1	2	Girl's Restroom near Art Room	Convector	Metal	Brown	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	Door Casing	Metal	Brown	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	Door	Metal	Brown	None	0	0	Negative
5390	1	2	Girl's Restroom near Art Room	STALL PARTITION	Metal	BLUE	None	0	0	Negative
5390	1	2	Office (Spanish-A)	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	Office (Spanish-A)	W2	CMU	Beige	None	0	0	Negative
5390	1	2	Office (Spanish-A)	W3	CMU	Beige	None	0	0.1	Negative
5390	1	2	Office (Spanish-A)	W3	Wood	Beige	None	0	0.2	Negative
5390	1	2	Office (Spanish-A)	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office (Spanish-A)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office (Spanish-A)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Office (Spanish-A)	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Book Closet by "Spanish A"	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	Book Closet by "Spanish A"	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Book Closet by "Spanish A"	W3	CMU	Beige	None	0	0	Negative
5390	1	2	Book Closet by "Spanish A"	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Book Closet by "Spanish A"	Ceiling	Plaster	Beige	None	0	0	Negative
5390	1	2	Book Closet by "Spanish A"	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Book Closet by "Spanish A"	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Hallway between Classrooms 208 and 218	W1	CMU	Beige	None	0	0.1	Negative
5390	1	2	Hallway between Classrooms 208 and 218	W2	CMU	Beige	None	0	0.1	Negative
5390	1	2	Hallway between Classrooms 208 and 218	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway between Classrooms 208 and 218	W4	CMU	Beige	None	0	0.1	Negative
5390	1	2	Hallway between Classrooms 208 and 218	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: September 7, 9, 14, & 15, 2021							
			Name of Inspector: Kristen Masotes/J. Chuck Wilkins		Lead Safe Certification Assessment Report					
			Inspection Company: ACER Associates		Potter Thomas Promise Academy School					
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5390	1	2	Hallway between Classrooms 208 and 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	2	Hallway between Classrooms 208 and 218	Glazed Base	CMU	Brown	None	0	1.6	Positive
5390	1	2	Hallway between Classrooms 208 and 218	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Hallway between Classrooms 208 and 218	Door	Metal	Brown	None	0	0	Negative
5390	1	2	Hallway between Classrooms 208 and 218	Door	Metal	Brown	None	0	0.1	Negative
5390	1	2	Hallway between Classrooms 208 and 218	Door Casing	Metal	Brown	None	0	0.5	Negative
5390	1	2	Hallway between Classrooms 208 and 218	Door Center Post	Metal	Brown	Flaking	1	0.1	Negative
5390	1	2	Hallway between Classrooms 208 and 218	Electrical Panel	Metal	Brown	None	0	0.1	Negative
5390	1	2	Hallway between Classrooms 208 and 218	Convactor	Metal	Brown	None	0	0	Negative
5390	1	AT	Attic	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	AT	Attic	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	AT	Attic	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	AT	Attic	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	AT	Attic	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	AT	Attic	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	CS	Crawlspace	W1	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	CS	Crawlspace	W2	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	CS	Crawlspace	W3	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	CS	Crawlspace	W4	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	CS	Crawlspace	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5390	1	CS	Crawlspace	Floor	N/A	N/A	N/A	N/A	N/A	N/A