

School District of Philadelphia																				
Lead Safe Certification Assessment Report																				
Inspection Dates: 08/14/2019																				
ULCS#	Element	Floor	Space #	Name of Inspector: Ryan Hutsell		Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
				Inspection Company: Synertech																
2000	1	2	202	Daycare Room 202		yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	202	Daycare Room 202		yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	202	Daycare Room 202		yes	W2	Concrete	Black	Chipping	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	202	Daycare Room 202		yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	202	Daycare Room 202		yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Blue	Chipping	2	0.3	Negative
2000	1	2	202	Daycare Room 202		yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	202	Daycare Room 202		yes	W4	Concrete	Black	Chipping	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	202	Daycare Room 202		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	202	Daycare Room 202		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	W1	Brick	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	W2	Brick	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	2	0.04	Negative
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Stair pan	Metal	Tan	Flaking	10	0.9	Positive
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Tan	Flaking	16	0.86	Positive
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Tan	Flaking	6	0.82	Positive
2000	1	2	S23	Stairwell # 2 next to Classroom 205		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Teal	Flaking	8	0.13	Negative
2000	1	2	S21	Stairwell adjacent to Classroom 200		yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	W2	Plaster	Brown	Flaking	80	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Stair pan	Metal	Tan	Flaking	16	0.91	Positive
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Tan	Flaking	8	0.79	Positive
2000	1	2	S26	Stairwell adjacent to Classroom 200		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Tan	Flaking	8	0.82	Positive
2000	1	2	H21	Hallway from Classrooms 206 to 220		yes	W1	Concrete	White	Cracking	12	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H21	Hallway from Classrooms 206 to 220		yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H21	Hallway from Classrooms 206 to 220		yes	W3	Concrete	White	Cracking	16	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H21	Hallway from Classrooms 206 to 220		yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H21	Hallway from Classrooms 206 to 220		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H21	Hallway from Classrooms 206 to 220		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H22	Hallway from Classrooms 200 to 205		yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H22	Hallway from Classrooms 200 to 205		yes	W2	Concrete	White	Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H22	Hallway from Classrooms 200 to 205		yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H22	Hallway from Classrooms 200 to 205		yes	W4	Concrete	White	Cracking	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H22	Hallway from Classrooms 200 to 205		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	H22	Hallway from Classrooms 200 to 205		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200	Daycare Room 200		yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200	Daycare Room 200		yes	W2	Concrete	White	Cracking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200	Daycare Room 200		yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200	Daycare Room 200		yes	W4	Concrete	White	Flaking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200	Daycare Room 200		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200	Daycare Room 200		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200A	Daycare Room 200 Restroom		yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200A	Daycare Room 200 Restroom		yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200A	Daycare Room 200 Restroom		yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200A	Daycare Room 200 Restroom		yes	W4	Concrete	White	Cracking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200A	Daycare Room 200 Restroom		yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	200A	Daycare Room 200 Restroom		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201	Daycare Room 201		yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201	Daycare Room 201		yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201	Daycare Room 201		yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201	Daycare Room 201		yes	W4	Concrete	White	Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201	Daycare Room 201		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201	Daycare Room 201		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Duct	Metal	White	Flaking	8	0.03	Negative
2000	1	2	201	Daycare Room 201		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201A	Daycare Kitchen		yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201A	Daycare Kitchen		yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201A	Daycare Kitchen		yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201A	Daycare Kitchen		yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	0.45	Negative
2000	1	2	201A	Daycare Kitchen		yes	W4	Concrete	White	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201A	Daycare Kitchen		yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Tan	Flaking	4	0.23	Negative
2000	1	2	201A	Daycare Kitchen		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2000	1	2	201A	Daycare Kitchen		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																				
Lead Safe Certification Assessment Report																				
Inspection Dates: 08/14/2019																				
				Name of Inspector: Ryan Hutsell																
				Inspection Company: Synertech																
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	
2000	1	2	201B	Daycare Room 201 Restroom next to Kitchen	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201B	Daycare Room 201 Restroom next to Kitchen	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201B	Daycare Room 201 Restroom next to Kitchen	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201B	Daycare Room 201 Restroom next to Kitchen	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201B	Daycare Room 201 Restroom next to Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201B	Daycare Room 201 Restroom next to Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201C	Daycare Room 201 Restroom by Door	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201C	Daycare Room 201 Restroom by Door	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201C	Daycare Room 201 Restroom by Door	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201C	Daycare Room 201 Restroom by Door	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201C	Daycare Room 201 Restroom by Door	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201C	Daycare Room 201 Restroom by Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201D	Head Start Office	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201D	Head Start Office	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201D	Head Start Office	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201D	Head Start Office	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201D	Head Start Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	201D	Head Start Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203	Daycare Room 203	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203	Daycare Room 203	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203	Daycare Room 203	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203	Daycare Room 203	yes	W4	Concrete	White	Cracking	6	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203	Daycare Room 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203	Daycare Room 203	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203A	Daycare Storage Room	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203A	Daycare Storage Room	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203A	Daycare Storage Room	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203A	Daycare Storage Room	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203A	Daycare Storage Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	203A	Daycare Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204	Daycare Room 204	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204	Daycare Room 204	yes	W2	Sheetrock	White	Chipping	6	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204	Daycare Room 204	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204	Daycare Room 204	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Flaking	6	0.05	Negative	
2000	1	2	204	Daycare Room 204	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Tan	Chipping	5	0.3	Negative	
2000	1	2	204	Daycare Room 204	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204	Daycare Room 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204	Daycare Room 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	White	Flaking	4	0.17	Negative
2000	1	2	204	Daycare Room 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204A	Daycare Room 204 Restroom	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204A	Daycare Room 204 Restroom	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204A	Daycare Room 204 Restroom	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204A	Daycare Room 204 Restroom	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204A	Daycare Room 204 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204A	Daycare Room 204 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204B	Storage Room across from Daycare Room 204	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204B	Storage Room across from Daycare Room 204	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204B	Storage Room across from Daycare Room 204	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204B	Storage Room across from Daycare Room 204	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204B	Storage Room across from Daycare Room 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	204B	Storage Room across from Daycare Room 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205	Classroom 205	yes	W1	Concrete	White	Cracking	8	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205	Classroom 205	yes	W2	Concrete	White	Flaking	6	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205	Classroom 205	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Tan	Chipping	4	0.15	Negative	
2000	1	2	205	Classroom 205	yes	W3	Concrete	White	Flaking	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205	Classroom 205	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Flaking	10	0.1	Negative	
2000	1	2	205	Classroom 205	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Tan	Chipping	6	0.23	Negative	
2000	1	2	205	Classroom 205	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205	Classroom 205	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Tan	Flaking	2	0.5	Negative	
2000	1	2	205	Classroom 205	yes	Ceiling	Plaster	White	Flaking	750	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205	Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205A	Storage Room inside Classroom 205 next to Stairwell # 2	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205A	Storage Room inside Classroom 205 next to Stairwell # 2	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205A	Storage Room inside Classroom 205 next to Stairwell # 2	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2	205A	Storage Room inside Classroom 205 next to Stairwell # 2	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

School District of Philadelphia																					
Lead Safe Certification Assessment Report																					
Inspection Dates: 08/14/2019																					
		E l e m e n t	F l o o r	Space #	Name of Inspector: Ryan Hutsell		Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
					Inspection Company: Synertech																
ULCS#					On-Site Room Name																
2000	1	2		205A	Storage Room inside Classroom 205 next to Stairwell # 2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205A	Storage Room inside Classroom 205 next to Stairwell # 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205D	Small Storage Closet inside Classroom 205 next to Stairwell # 2	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205D	Small Storage Closet inside Classroom 205 next to Stairwell # 2	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205D	Small Storage Closet inside Classroom 205 next to Stairwell # 2	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205D	Small Storage Closet inside Classroom 205 next to Stairwell # 2	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205D	Small Storage Closet inside Classroom 205 next to Stairwell # 2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205D	Small Storage Closet inside Classroom 205 next to Stairwell # 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205B	Daycare Suite 205 Restroom (Front)	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205B	Daycare Suite 205 Restroom (Front)	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205B	Daycare Suite 205 Restroom (Front)	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205B	Daycare Suite 205 Restroom (Front)	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205B	Daycare Suite 205 Restroom (Front)	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205B	Daycare Suite 205 Restroom (Front)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205C	Daycare Suite 205 Restroom (Rear)	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205C	Daycare Suite 205 Restroom (Rear)	yes	W2	Sheetrock	White	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205C	Daycare Suite 205 Restroom (Rear)	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205C	Daycare Suite 205 Restroom (Rear)	yes	W4	Sheetrock	White	Chipping	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205C	Daycare Suite 205 Restroom (Rear)	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		205C	Daycare Suite 205 Restroom (Rear)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		204B	Hallway Storage adjacent to Daycare Room 204	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		204B	Hallway Storage adjacent to Daycare Room 204	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		204B	Hallway Storage adjacent to Daycare Room 204	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		204B	Hallway Storage adjacent to Daycare Room 204	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		204B	Hallway Storage adjacent to Daycare Room 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	2		204B	Hallway Storage adjacent to Daycare Room 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		H13	Main Hallway along Broad Street	yes	W1	Concrete	White	Cracking	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		H13	Main Hallway along Broad Street	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		H13	Main Hallway along Broad Street	yes	W3	Concrete	White	Cracking	8	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		H13	Main Hallway along Broad Street	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		H13	Main Hallway along Broad Street	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		H13	Main Hallway along Broad Street	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		S11	Stairwell adjacent to Roster Office 100	yes	W1	Concrete	White	Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		S11	Stairwell adjacent to Roster Office 100	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		S11	Stairwell adjacent to Roster Office 100	yes	W3	Concrete	White	Cracking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		S11	Stairwell adjacent to Roster Office 100	yes	W4	Concrete	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		S11	Stairwell adjacent to Roster Office 100	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		S11	Stairwell adjacent to Roster Office 100	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Stair pan	Metal	Tan	Flaking	12	0.91	Positive
2000	1	1		S11	Stairwell adjacent to Roster Office 100	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2000	1	1		S11	Stairwell adjacent to Roster Office 100	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Tan	Chipping	8	0.89	Positive