

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report										Inspection Dates: 4/19/2021-4/23/2021				
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School										ULCS# 6390				
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	100	Cafeteria	Yes	W1	Concrete	Tan	None	0	N/A	N/A	None							
1	1	100	Cafeteria	Yes	W2	Concrete	Tan	None	0	N/A	N/A	None							
1	1	100	Cafeteria	Yes	W3	Concrete	Tan	None	0	N/A	N/A	None							
1	1	100	Cafeteria	Yes	W4	Concrete	Tan	None	0	N/A	N/A	None							
1	1	100	Cafeteria	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None							
1	1	100	Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None							
1	1	100	Cafeteria	Yes	Door Frames	Metal	Brown	Friction	2	0.4	Negative	None							
1	1	100	Cafeteria	Yes	Door	Metal	Brown	Friction	2	0	Negative	None							
1	1	100	Cafeteria	Yes	Columns	Concrete	Red	None	1	0	Negative	None							
1	1	100	Cafeteria	Yes	Columns	Concrete	Blue	None	1	0	Negative	None							
1	1	100	Cafeteria	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	1	100A	Women's Restroom adjacent to Cafeteria	Yes	W1	Concrete	Tan	None	0	N/A	N/A	None							
1	1	100A	Women's Restroom adjacent to Cafeteria	Yes	W2	Concrete	Tan	None	0	N/A	N/A	None							
1	1	100A	Women's Restroom adjacent to Cafeteria	Yes	W3	Concrete	Tan	None	0	N/A	N/A	None							
1	1	100A	Women's Restroom adjacent to Cafeteria	Yes	W4	Concrete	Tan	None	0	N/A	N/A	None							
1	1	100A	Women's Restroom adjacent to Cafeteria	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None							
1	1	100A	Women's Restroom adjacent to Cafeteria	Yes	Floor	Concrete	Gray	None	0	N/A	N/A	None							
1	1	100A	Women's Restroom adjacent to Cafeteria	Yes	Door Frames	Metal	Tan	None	0	N/A	N/A	None							
1	1	100B	Pre-K Bathroom	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100B	Pre-K Bathroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100B	Pre-K Bathroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100B	Pre-K Bathroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100B	Pre-K Bathroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100B	Pre-K Bathroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100B	Pre-K Bathroom	Yes	Door Frames	No Access	Brown	No Access	No Access	0.24	Negative	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100C	Cafeteria Storage Room	No	W1	Concrete	Red	None	0	N/A	N/A	None							
1	1	100C	Cafeteria Storage Room	No	W2	Concrete	Red	None	0	N/A	N/A	None							
1	1	100C	Cafeteria Storage Room	No	W3	Concrete	Red	None	0	N/A	N/A	None							
1	1	100C	Cafeteria Storage Room	No	W4	Concrete	Red	None	0	N/A	N/A	None							
1	1	100C	Cafeteria Storage Room	No	Ceiling	Concrete	White	None	0	N/A	N/A	None							
1	1	100C	Cafeteria Storage Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	Door Frames	Metal	Brown	Friction	1	0.21	Negative								
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	Door Frames	Metal	Red	Friction	0	0.22	Negative	None							
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	Door vents	Metal	Brown	Chipping	1	0	Negative								
1	1	100D	Teacher's Lounge adjacent to Cafeteria																Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	1	100D	Teacher's Lounge adjacent to Cafeteria	Yes	Kickplate	Ceramic	Black	Friction	1	0.84	Positive	None							
1	1	100E	Cafeteria Kitchen	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100E	Cafeteria Kitchen	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100E	Cafeteria Kitchen	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100E	Cafeteria Kitchen	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	100E	Cafeteria Kitchen	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100E	Cafeteria Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100E	Cafeteria Kitchen	Yes	Door Frames	Metal	Red	Friction	2	0.22	Negative								
1	1	100E	Cafeteria Kitchen	Yes	Door	Metal	Grey	Friction	2	0	Negative								
1	1	100E	Cafeteria Kitchen	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	100F	Elevator	Yes	W1	Metal	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100F	Elevator	Yes	W2	Metal	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100F	Elevator	Yes	W3	Metal	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100F	Elevator	Yes	W4	Metal	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100F	Elevator	Yes	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100F	Elevator	Yes	Door	Metal	Blue	Friction	1	0	Negative								
1	1	100F	Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	116	Auditorium	Yes	W1	Concrete	White & tan	None	0	N/A	N/A	None							
1	1	116	Auditorium	Yes	W2	Concrete	White & tan	None	0	N/A	N/A	None							
1	1	116	Auditorium	Yes	W3	Concrete	White & tan	None	0	N/A	N/A	None							
1	1	116	Auditorium	Yes	W4	Concrete	White & tan	None	0	N/A	N/A	None							
1	1	116	Auditorium	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None							
1	1	116	Auditorium	Yes	Floor	Concrete	Black	Friction	10	0	Negative								
1	1	116	Auditorium	Yes	Door Frames	Metal	Brown	Friction	1	0.24	Negative								
1	1	116	Auditorium	Yes	Lighting fit out	Wood	Brown	Friction	1	0.07	Negative								
1	1	116	Auditorium	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	116C	Auditorium Stage	Yes	W1	Concrete	Tan	None	0	N/A	N/A	None							
1	1	116C	Auditorium Stage	Yes	W2	Concrete	Tan	None	0	N/A	N/A	None							
1	1	116C	Auditorium Stage	Yes	W3	Concrete	Tan	Cracking	1	0.03	Negative								
1	1	116C	Auditorium Stage	Yes	W4	Concrete	Tan	None	0	N/A	N/A	None							
1	1	116C	Auditorium Stage	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None							
1	1	116C	Auditorium Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	116C	Auditorium Stage	Yes	Door Frames	Metal	Brown	Friction	1	0.33	Negative								
1	1	S13	Stairwell to Auditorium Right of Stage	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							

						School District of Philadelphia														
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine			Lead Safe Certification Assessment Report						Inspection Dates: 4/19/2021-4/23/2021								
			Inspection Company: REPSG, Inc.			Edward T Steel Elementary School						ULCS# 6390								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	S13	Stairwell to Auditorium Right of Stage	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S13	Stairwell to Auditorium Right of Stage	Yes	W3	Concrete	Tan	None	0		0 Negative	None								
1	1	S13	Stairwell to Auditorium Right of Stage	Yes	W3	Concrete	Beige	None	0		0 Negative	None								
1	1	S13	Stairwell to Auditorium Right of Stage	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S13	Stairwell to Auditorium Right of Stage	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S13	Stairwell to Auditorium Right of Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	S13	Stairwell to Auditorium Right of Stage	Yes	Small kickplate	Ceramic	Black	None	0		1 Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	1	S15	Stairwell to Auditorium Left of Stage	Yes	W1	Concrete	Beige	None	0		0 Negative	None								
1	1	S15	Stairwell to Auditorium Left of Stage	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S15	Stairwell to Auditorium Left of Stage	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S15	Stairwell to Auditorium Left of Stage	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S15	Stairwell to Auditorium Left of Stage	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S15	Stairwell to Auditorium Left of Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	S15	Stairwell to Auditorium Left of Stage	Yes	Small kickplate	Ceramic	Black	None	0		0.8 Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	1	117	Gymnasium	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117	Gymnasium	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117	Gymnasium	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117	Gymnasium	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117	Gymnasium	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117	Gymnasium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117	Gymnasium	Yes	Door Frames	Metal	Blue	Friction	2		0.24 Negative	None								
1	1	117	Gymnasium	Yes	Doors	Metal	Blue	Friction	2		0 Negative	None								
1	1	117	Gymnasium	Yes	Kickplate	Ceramic	Black	Friction	40		0 Negative	None								
1	1	117	Gymnasium	Yes	Ducts	Metal	Tan	Flaking	15	Not accessible	N/A	None								
1	1	117A	Gymnasium Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117A	Gymnasium Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117A	Gymnasium Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117A	Gymnasium Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117A	Gymnasium Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117A	Gymnasium Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117A	Gymnasium Office	Yes	Door Frames	Metal	Blue	Friction	1		0.14 Negative									
1	1	117A	Gymnasium Office	Yes	Window Frames	Metal	Grey	Friction	1		0.18 Negative									
1	1	117A	Gymnasium Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None								
1	1	117B	Gymnasium Office Restroom	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117B	Gymnasium Office Restroom	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117B	Gymnasium Office Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117B	Gymnasium Office Restroom	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117B	Gymnasium Office Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117B	Gymnasium Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117B	Gymnasium Office Restroom	Yes	Door Frames	Metal	Grey	Friction	1		0.02 Negative	None								
1	1	117B	Gymnasium Office Restroom	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None								
1	1	117J	Vestibule outside Boy's Locker Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117J	Vestibule outside Boy's Locker Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117J	Vestibule outside Boy's Locker Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117J	Vestibule outside Boy's Locker Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117J	Vestibule outside Boy's Locker Room	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117J	Vestibule outside Boy's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117J	Vestibule outside Boy's Locker Room	Yes	Door Frames	Metal	Brown	Friction	1		0.25 Negative									
1	1	117J	Vestibule outside Boy's Locker Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	0 Negative									
1	1	117F	Restroom in vestibule outside Boy's Locker Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117F	Restroom in vestibule outside Boy's Locker Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117F	Restroom in vestibule outside Boy's Locker Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117F	Restroom in vestibule outside Boy's Locker Room	Yes	W4	Concrete	Beige	Chipping	0.5		0 Negative									
1	1	117F	Restroom in vestibule outside Boy's Locker Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							One missing ceiling tile	
1	1	117F	Restroom in vestibule outside Boy's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117F	Restroom in vestibule outside Boy's Locker Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	1	117G	Storage closet in Boy's Locker Room	Yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A							No access	
1	1	117C	Boy's Locker Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117C	Boy's Locker Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117C	Boy's Locker Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117C	Boy's Locker Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117C	Boy's Locker Room	Yes	Ceiling	Metal	Beige	Flaking	3		0.01 Negative	None								
1	1	117C	Boy's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None								
1	1	117C	Boy's Locker Room	Yes	Door Frames	Metal	Brown	Friction	1		0.09 Negative	None								
1	1	117C	Boy's Locker Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None								
1	1	117D	Gymnasium Storage Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117D	Gymnasium Storage Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117D	Gymnasium Storage Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117D	Gymnasium Storage Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	117D	Gymnasium Storage Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117D	Gymnasium Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	117D	Gymnasium Storage Room	Yes	Door Frames	Metal	Black	Friction	1		0.13 Negative	None								

						School District of Philadelphia														
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine			Lead Safe Certification Assessment Report						Inspection Dates: 4/19/2021-4/23/2021								
			Inspection Company: REPSG, Inc.			Edward T Steel Elementary School						ULCS# 6390								
E l e m e n t	F l o o r		Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1		117E	Girl's Locker Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117E	Girl's Locker Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117E	Girl's Locker Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117E	Girl's Locker Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117E	Girl's Locker Room	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117E	Girl's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		117E	Girl's Locker Room	Yes	Door Frames	Metal	Grey	None	0	N/A	N/A	None							
1	1		117E	Girl's Locker Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	1		117K	Vestibule outside Girl's Locker Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117K	Vestibule outside Girl's Locker Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117K	Vestibule outside Girl's Locker Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117K	Vestibule outside Girl's Locker Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117K	Vestibule outside Girl's Locker Room	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117K	Vestibule outside Girl's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		117K	Vestibule outside Girl's Locker Room	Yes	Door Frames	Metal	Brown	Friction	1	N/A	N/A								
1	1		117K	Vestibule outside Girl's Locker Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1		117I	Restroom in vestibule outside girls Locker Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117I	Restroom in vestibule outside girls Locker Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117I	Restroom in vestibule outside girls Locker Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117I	Restroom in vestibule outside girls Locker Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117I	Restroom in vestibule outside girls Locker Room	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1		117I	Restroom in vestibule outside girls Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		117I	Restroom in vestibule outside girls Locker Room	Yes	Door Frames	Metal	Grey	None	0	N/A	N/A	None							
1	1		117I	Restroom in vestibule outside girls Locker Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1		116A	Girl's Restroom adjacent to Gymnasium	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116A	Girl's Restroom adjacent to Gymnasium	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116A	Girl's Restroom adjacent to Gymnasium	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116A	Girl's Restroom adjacent to Gymnasium	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116A	Girl's Restroom adjacent to Gymnasium	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116A	Girl's Restroom adjacent to Gymnasium	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116A	Girl's Restroom adjacent to Gymnasium	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None							
1	1		116B	Boy's Restroom adjacent to Gymnasium	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116B	Boy's Restroom adjacent to Gymnasium	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116B	Boy's Restroom adjacent to Gymnasium	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116B	Boy's Restroom adjacent to Gymnasium	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116B	Boy's Restroom adjacent to Gymnasium	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116B	Boy's Restroom adjacent to Gymnasium	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		116B	Boy's Restroom adjacent to Gymnasium	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	Doors	Metal	Beige	None	0		0 Negative	None							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	Door Frames	Metal	Black	None	0		0 Negative	None							
1	1		S14	Stairwell adjacent to Classroom 113	Yes	Window Sill	Concrete	Brown	None	0		0 Negative	None							
1	1		113	Classroom 113	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1		113	Classroom 113	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1		113	Classroom 113	Yes	W3	Concrete	Orange	None	0	N/A	N/A	None							
1	1		113	Classroom 113	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1		113	Classroom 113	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1		113	Classroom 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		113	Classroom 113	Yes	Door Frames	Metal		None	0	N/A	N/A	None							
1	1		113	Classroom 113	Yes	Wall vents	Metal	Gray	None	0		0.39 Negative								
1	1		113	Classroom 113	Yes	Kickplate	Ceramic	Black	Friction	1		0.76 Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	1		113A	Classroom 113 Restroom	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1		113A	Classroom 113 Restroom	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1		113A	Classroom 113 Restroom	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1		113A	Classroom 113 Restroom	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1		113A	Classroom 113 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		113A	Classroom 113 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		113A	Classroom 113 Restroom	Yes	Door Frames	Metal	Grey	Friction	1		0.28 Negative								
1	1		113A	Classroom 113 Restroom	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1		111	Classroom 111	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1		111	Classroom 111	Yes	W2	Concrete	Orange	None	0	N/A	N/A	None							
1	1		111	Classroom 111	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1		111	Classroom 111	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1		111	Classroom 111	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		111	Classroom 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1		111	Classroom 111	Yes	Door Frames	Metal	Grey	Friction	1		0.18 Negative								
1	1		111	Classroom 111	Yes	Door Frames	Metal	Brown	Friction	1										
1	1		111	Classroom 111	Yes	Door	Metal	Tan	None	0	N/A	N/A	None							
1	1		111	Classroom 111	Yes	Wall vents	Metal	Gray	None	0	N/A	N/A								

			School District of Philadelphia																
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine				Lead Safe Certification Assessment Report								Inspection Dates: 4/19/2021-4/23/2021				
			Inspection Company: REPSG, Inc.				Edward T Steel Elementary School								ULCS# 6390				
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	111	Classroom 111	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	111A	Classroom 111 Restroom	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1	111A	Classroom 111 Restroom	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	111A	Classroom 111 Restroom	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1	111A	Classroom 111 Restroom	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1	111A	Classroom 111 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	111A	Classroom 111 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	111A	Classroom 111 Restroom	Yes	Door Frames	Metal	Grey	Friction	1	0.31	Negative								
1	1	111A	Classroom 111 Restroom	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	111B	Classroom 111 and 113 Storage Room	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1	111B	Classroom 111 and 113 Storage Room	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	111B	Classroom 111 and 113 Storage Room	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1	111B	Classroom 111 and 113 Storage Room	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1	111B	Classroom 111 and 113 Storage Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	111B	Classroom 111 and 113 Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	111B	Classroom 111 and 113 Storage Room	Yes	Door Frames	Metal	Grey	Friction	1	0.26	Negative								
1	1	111B	Classroom 111 and 113 Storage Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	109	Classroom 109	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109	Classroom 109	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109	Classroom 109	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109	Classroom 109	Yes	W4	Concrete	Orange	None	0	N/A	N/A	None							
1	1	109	Classroom 109	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	109	Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	109	Classroom 109	Yes	Door Frames	Metal	Grey	None	0	N/A	N/A	None							
1	1	109	Classroom 109	Yes	Wall vents	Metal	Gray	None	0	0.07	Negative								
1	1	109	Classroom 109	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	109A	Classroom 109 Restroom	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109A	Classroom 109 Restroom	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109A	Classroom 109 Restroom	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109A	Classroom 109 Restroom	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109A	Classroom 109 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	109A	Classroom 109 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	109A	Classroom 109 Restroom	Yes	Door Frames	Metal	Grey	Friction	1	0.32	Negative								
1	1	109A	Classroom 109 Restroom	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	109B	Classroom 109 Storage	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109B	Classroom 109 Storage	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109B	Classroom 109 Storage	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109B	Classroom 109 Storage	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1	109B	Classroom 109 Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	109B	Classroom 109 Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	109B	Classroom 109 Storage	Yes	Door Frames	Metal	Grey	Friction	1	0.29	Negative								
1	1	109B	Classroom 109 Storage	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	107	Classroom 107	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1	107	Classroom 107	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	107	Classroom 107	Yes	W3	Concrete	Orange	Friction	1	0	Negative								
1	1	107	Classroom 107	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1	107	Classroom 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	107	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	107	Classroom 107	Yes	Door Frames	Metal	Gray	Friction	1	0.35	Negative								
1	1	107	Classroom 107	Yes	Door Frames	Metal	Brown	Friction	1	0	Negative								
1	1	107	Classroom 107	Yes	Door	Metal	Tan	Friction	1	0	Negative								
1	1	107	Classroom 107	Yes	Wall vents	Metal	Gray	None	0	N/A	N/A								
1	1	107	Classroom 107	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	107A	Classroom 107 Restroom	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1	107A	Classroom 107 Restroom	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	107A	Classroom 107 Restroom	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1	107A	Classroom 107 Restroom	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1	107A	Classroom 107 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	107A	Classroom 107 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	107A	Classroom 107 Restroom	Yes	Door Frames	Metal	Grey	Friction	1	0.26	Negative								
1	1	105	Classroom 105	Yes	W1	Concrete	Grey	None	0	0.03	Negative	None							
1	1	105	Classroom 105	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	105	Classroom 105	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1	105	Classroom 105	Yes	W4	Concrete	Orange	None	0	0	Negative	None							
1	1	105	Classroom 105	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105	Classroom 105	Yes	Door Frames	Metal	Gray	Friction	1	0.1	Negative								
1	1	105	Classroom 105	Yes	Wall vents	Metal	Gray	Chipping	1	0.14	Negative								
1	1	105	Classroom 105	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	105A	Classroom 105 Closet	Yes	W1	Concrete	Grey	None	0	N/A	N/A	None							
1	1	105A	Classroom 105 Closet	Yes	W2	Concrete	Grey	None	0	N/A	N/A	None							
1	1	105A	Classroom 105 Closet	Yes	W3	Concrete	Grey	None	0	N/A	N/A	None							
1	1	105A	Classroom 105 Closet	Yes	W4	Concrete	Grey	None	0	N/A	N/A	None							
1	1	105A	Classroom 105 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105A	Classroom 105 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105A	Classroom 105 Closet	Yes	Door Frames	Metal	Grey	Chipping	1	0.06	Negative								

			School District of Philadelphia																	
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report										Inspection Dates: 4/19/2021-4/23/2021					
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School										ULCS# 6390					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	103	Head Start Office adjacent to Classroom 105	Yes	W1	Concrete	Beige	None	0	0	Negative	None								
1	1	103	Head Start Office adjacent to Classroom 105	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	103	Head Start Office adjacent to Classroom 105	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	103	Head Start Office adjacent to Classroom 105	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	103	Head Start Office adjacent to Classroom 105	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	103	Head Start Office adjacent to Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	103	Head Start Office adjacent to Classroom 105	Yes	Door Frames	Metal	Brown	Friction	1	0.35	Negative	None								
1	1	103	Head Start Office adjacent to Classroom 105	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None								
1	1	115	Closet across from Classroom 113	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	115	Closet across from Classroom 113	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	115	Closet across from Classroom 113	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	115	Closet across from Classroom 113	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	115	Closet across from Classroom 113	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	115	Closet across from Classroom 113	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	115	Closet across from Classroom 113	Yes	Door Frames	Metal	Brown	Friction	1	N/A	N/A	None								
1	1	H13	Hallway from Classroom 109 to Gymnasium	Yes	W1	Concrete	Beige	None	0	0	Negative	None								
1	1	H13	Hallway from Classroom 109 to Gymnasium	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H13	Hallway from Classroom 109 to Gymnasium	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H13	Hallway from Classroom 109 to Gymnasium	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H13	Hallway from Classroom 109 to Gymnasium	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H13	Hallway from Classroom 109 to Gymnasium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	H13	Hallway from Classroom 109 to Gymnasium	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None								
1	1	H11A	Hallway from Main Entrance Lobby to Classroom 109	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H11A	Hallway from Main Entrance Lobby to Classroom 109	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H11A	Hallway from Main Entrance Lobby to Classroom 109	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H11A	Hallway from Main Entrance Lobby to Classroom 109	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H11A	Hallway from Main Entrance Lobby to Classroom 109	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	H11A	Hallway from Main Entrance Lobby to Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	H11A	Hallway from Main Entrance Lobby to Classroom 109	Yes	Door	Metal	Brown	Friction	0	0	Negative	None								
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								One missing ceiling tile
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	Door Frames	Metal	Brown	Friction	1	0.04	Negative	None								
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	Door	Metal	Brown	Friction	1	0	Negative	None								
1	1	101	Office Suite adjacent to Main Lobby Common Area	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None								
1	1	101A	Office Suite adjacent to Main Lobby Left Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101A	Office Suite adjacent to Main Lobby Left Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101A	Office Suite adjacent to Main Lobby Left Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101A	Office Suite adjacent to Main Lobby Left Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101A	Office Suite adjacent to Main Lobby Left Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None								
1	1	101A	Office Suite adjacent to Main Lobby Left Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	101A	Office Suite adjacent to Main Lobby Left Office	Yes	Door Frames	Metal	Brown	Friction	1	0.17	Negative	None								
1	1	101A	Office Suite adjacent to Main Lobby Left Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	N/A								
1	1	101B	Office Suite adjacent to Main Lobby Center Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101B	Office Suite adjacent to Main Lobby Center Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101B	Office Suite adjacent to Main Lobby Center Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101B	Office Suite adjacent to Main Lobby Center Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101B	Office Suite adjacent to Main Lobby Center Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None								
1	1	101B	Office Suite adjacent to Main Lobby Center Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	101B	Office Suite adjacent to Main Lobby Center Office	Yes	Door Frames	Metal	Brown	Friction	1	0.06	Negative	None								
1	1	101B	Office Suite adjacent to Main Lobby Center Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	N/A								
1	1	101C	Office Suite adjacent to Main Lobby Right Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101C	Office Suite adjacent to Main Lobby Right Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101C	Office Suite adjacent to Main Lobby Right Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101C	Office Suite adjacent to Main Lobby Right Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101C	Office Suite adjacent to Main Lobby Right Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	101C	Office Suite adjacent to Main Lobby Right Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	101C	Office Suite adjacent to Main Lobby Right Office	Yes	Door Frames	Metal	Brown	Friction	1	0.03	Negative	None								
1	1	101C	Office Suite adjacent to Main Lobby Right Office	Yes	Kickplate	Ceramic	Black	Friction	1	0.64	Negative	None								
1	1	S11A	Main Entrance Lobby	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11A	Main Entrance Lobby	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11A	Main Entrance Lobby	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11A	Main Entrance Lobby	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11A	Main Entrance Lobby	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11A	Main Entrance Lobby	Yes	Floor	Ceramic	Red	None	0	0	Negative	None								
1	1	S11A	Main Entrance Lobby	Yes	Door Frames	Metal	Brown	Friction	1	N/A	N/A	None								
1	1	S11	Main Entrance Lobby Stairwell	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11	Main Entrance Lobby Stairwell	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11	Main Entrance Lobby Stairwell	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11	Main Entrance Lobby Stairwell	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11	Main Entrance Lobby Stairwell	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	S11	Main Entrance Lobby Stairwell	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	S11	Main Entrance Lobby Stairwell	Yes	Staircase	Metal	Black	Flaking	1	0.82	Positive	None								

					School District of Philadelphia														
					Name of Inspector: Suzanne Shourds, Shalaunda Gourdine							Lead Safe Certification Assessment Report				Inspection Dates: 4/19/2021-4/23/2021			
					Inspection Company: REPSG, Inc.							Edward T Steel Elementary School				ULCS# 6390			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	S11	Main Entrance Lobby Stairwell	Yes	Doors	Metal	Red	Friction	1	0.61	Negative	None							
1	1	102	Main Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102	Main Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102	Main Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102	Main Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102	Main Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None							
1	1	102	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102	Main Office	Yes	Door Frames	Metal	Brown	Friction	1	0.2	Negative								
1	1	102	Main Office	Yes	Doors	Metal	Brown	Friction	1	0	Negative								
1	1	102	Main Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
					Store-front windows														
1	1	102	Main Office	Yes		Metal	Brown	Friction	2	0.24	Negative								
1	1	102B	Main Office School Police Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102B	Main Office School Police Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102B	Main Office School Police Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102B	Main Office School Police Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102B	Main Office School Police Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102B	Main Office School Police Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102B	Main Office School Police Office	Yes	Door Frames	Metal	Brown	Friction	1	0.14	Negative								
																			Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	1	102B	Main Office School Police Office	Yes	Kickplate	Ceramic	Black	Friction	1	0.71	Positive	None							
1	1	102B	Main Office School Police Office	Yes	Cabinets	Metal	Orange	Friction	1	0.73	Positive	None							
1	1	102A	Main Office Copy Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102A	Main Office Copy Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102A	Main Office Copy Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102A	Main Office Copy Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102A	Main Office Copy Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None							
1	1	102A	Main Office Copy Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102A	Main Office Copy Room	Yes	Door Frames	Metal	Brown	None	0	0.32	Negative	None							
1	1	102A	Main Office Copy Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	1	102C	Principal's Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102C	Principal's Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102C	Principal's Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102C	Principal's Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102C	Principal's Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1	102C	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102C	Principal's Office	Yes	Door Frames	Metal	Brown	Friction	1	0.17	Negative	None							
1	1	102C	Principal's Office	Yes	Kickplate	Ceramic	Black	Friction	1	0.63	Negative	None							
1	1	104C	Principal's Office Restroom	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	104C	Principal's Office Restroom	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	104C	Principal's Office Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	104C	Principal's Office Restroom	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	104C	Principal's Office Restroom	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1	104C	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	104C	Principal's Office Restroom	Yes	Door Frames	Metal	Brown	Friction	1	0.17	Negative	None							
1	1	104C	Principal's Office Restroom	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	1	102E	Principal's Office Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102E	Principal's Office Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102E	Principal's Office Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102E	Principal's Office Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102E	Principal's Office Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102E	Principal's Office Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102E	Principal's Office Closet	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None							
1	1	102E	Principal's Office Closet	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	1	102D	Main Office Conference Room	Yes	W1	Concrete	Pink	None	0	0	Negative	None							
1	1	102D	Main Office Conference Room	Yes	W2	Concrete	Pink	None	0	N/A	N/A	None							
1	1	102D	Main Office Conference Room	Yes	W3	Concrete	Pink	None	0	N/A	N/A	None							
1	1	102D	Main Office Conference Room	Yes	W4	Concrete	Pink	None	0	N/A	N/A	None							
1	1	102D	Main Office Conference Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None							
1	1	102D	Main Office Conference Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102D	Main Office Conference Room	Yes	Door Frames	Metal	Brown	Friction	1	0.16	Negative								
1	1	102D	Main Office Conference Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	1	102F	Main Office Conference Room Closet	Yes	W2	Concrete	Pink	None	0	0	Negative	None							
1	1	102F	Main Office Conference Room Closet	Yes	W3	Concrete	Pink	None	0	N/A	N/A	None							
1	1	102F	Main Office Conference Room Closet	Yes	W4	Concrete	Pink	None	0	N/A	N/A	None							
1	1	102F	Main Office Conference Room Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102F	Main Office Conference Room Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102F	Main Office Conference Room Closet	Yes	Door Frames	Metal	Brown	Friction	1										
1	1	102F	Main Office Conference Room Closet	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	1	102G	Custodial Closet adjacent to Main Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102G	Custodial Closet adjacent to Main Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102G	Custodial Closet adjacent to Main Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102G	Custodial Closet adjacent to Main Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102G	Custodial Closet adjacent to Main Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102G	Custodial Closet adjacent to Main Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							

					School District of Philadelphia															
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report										Inspection Dates: 4/19/2021-4/23/2021					
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School										ULCS# 6390					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	102F	Main Office Conference Room Closet	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	1	104B	Office 104 Front Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104B	Office 104 Front Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104B	Office 104 Front Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104B	Office 104 Front Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104B	Office 104 Front Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104B	Office 104 Front Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	104B	Office 104 Front Office	Yes	Door Frames	Metal	Brown	Friction	1	0.05	Negative									
1	1	104B	Office 104 Front Office	Yes	Store-front windows	Metal	Brown	Friction	1	0.15	Negative									
1	1	104B	Office 104 Front Office	Yes	Door vents	Metal	Brown	Chipping	1	0	Negative									
1	1	104B	Office 104 Front Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	1	104A	Office 104 Rear Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104A	Office 104 Rear Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104A	Office 104 Rear Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104A	Office 104 Rear Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104A	Office 104 Rear Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	104A	Office 104 Rear Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	1	104A	Office 104 Rear Office	Yes	Kickplate	Ceramic	Black	Friction	1	0.82	Positive	None								
1	1	104A	Office 104 Rear Office	Yes	Cabinets	Metal	Brown	Friction	1	0.04	Negative	None								
1	1	104A	Office 104 Rear Office	Yes	Door Vent	Metal	Brown	Friction	1	0	Negative	None								
1	1	104A	Office 104 Rear Office	Yes	Window Frame	Metal	Brown	Friction	1	0.15	Negative	None								
1	1	106	Teacher Lounge 106	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	106	Teacher Lounge 106	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	106	Teacher Lounge 106	Yes	W3	Concrete	Beige	Cracking	1	0.03	Negative									
1	1	106	Teacher Lounge 106	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	106	Teacher Lounge 106	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106	Teacher Lounge 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106	Teacher Lounge 106	Yes	Door Frames	Metal	Brown	Friction	1	0.29	Negative									
1	1	106	Teacher Lounge 106	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	1	106A	Teacher Lounge 106 Supply Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	106A	Teacher Lounge 106 Supply Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	106A	Teacher Lounge 106 Supply Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	106A	Teacher Lounge 106 Supply Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	106A	Teacher Lounge 106 Supply Room	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	1	106A	Teacher Lounge 106 Supply Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106A	Teacher Lounge 106 Supply Room	Yes	Door Frames	Metal	Brown	Friction	1	0.22	Negative									
1	1	106A	Teacher Lounge 106 Supply Room	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	1	108A	Computer Room across from Teacher's Lounge	Yes	W1	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	108A	Computer Room across from Teacher's Lounge	Yes	W2	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	108A	Computer Room across from Teacher's Lounge	Yes	W3	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	108A	Computer Room across from Teacher's Lounge	Yes	W4	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	108A	Computer Room across from Teacher's Lounge	Yes	Ceiling	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	108A	Computer Room across from Teacher's Lounge	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	108	Unisex Locker Room adjacent to Nurse's Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	108	Unisex Locker Room adjacent to Nurse's Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	108	Unisex Locker Room adjacent to Nurse's Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	108	Unisex Locker Room adjacent to Nurse's Office	Yes	W4	Concrete	Beige	Cracking	1	0.01	Negative									
1	1	108	Unisex Locker Room adjacent to Nurse's Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None								
1	1	108	Unisex Locker Room adjacent to Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	108	Unisex Locker Room adjacent to Nurse's Office	Yes	Door Frames	Metal	Brown	Friction	1	0.29	Negative									
1	1	108	Unisex Locker Room adjacent to Nurse's Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	W1	Transite Panel	White	None	0	0.09	Negative	None								
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	Door Frames	Metal	Brown	Friction	0	0.21	Negative	None								
1	1	108B	Restroom in Unisex Locker Room adjacent to Nurse's Office	Yes	Kickplate	Ceramic	Black	None	N/A	N/A	N/A									
1	1	110G	Nurse's Office Waiting Area	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	1	110G	Nurse's Office Waiting Area	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	1	110G	Nurse's Office Waiting Area	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	1	110G	Nurse's Office Waiting Area	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	1	110G	Nurse's Office Waiting Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	110G	Nurse's Office Waiting Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								

						School District of Philadelphia													
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine			Lead Safe Certification Assessment Report						Inspection Dates: 4/19/2021-4/23/2021							
			Inspection Company: REPSG, Inc.			Edward T Steel Elementary School						ULCS# 6390							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	110G	Nurse's Office Waiting Area	Yes	Door Frames	Metal	Brown	Friction	1	0.21	Negative								
1	1	110G	Nurse's Office Waiting Area	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	110G	Nurse's Office Waiting Area	Yes	Door vents	Metal	Brown	Chipping	1	0	Negative								
1	1	110D	Nurse's Office Exam Room between Restroom and Unisex Locker Room	Yes	W1	Transite	White	None	0	N/A	N/A	None							
1	1	110D	Nurse's Office Exam Room between Restroom and Unisex Locker Room	Yes	W2	Transite	White	None	0	N/A	N/A	None							
1	1	110D	Nurse's Office Exam Room between Restroom and Unisex Locker Room	Yes	W3	Transite	White	Flaking	1	0.09	Negative								
1	1	110D	Nurse's Office Exam Room between Restroom and Unisex Locker Room	Yes	W4	Transite	White	None	0	N/A	N/A	None							
1	1	110D	Nurse's Office Exam Room between Restroom and Unisex Locker Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110D	Nurse's Office Exam Room between Restroom and Unisex Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110D	Nurse's Office Exam Room between Restroom and Unisex Locker Room	Yes	Door Frames	Metal	Brown	Friction	1	0.21	Negative								
1	1	110A	Nurse's Office Restroom	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110A	Nurse's Office Restroom	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110A	Nurse's Office Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110A	Nurse's Office Restroom	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110A	Nurse's Office Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110A	Nurse's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110A	Nurse's Office Restroom	Yes	Door Frames	Metal	Brown	Friction	1	0.27	Negative								
1	1	110A	Nurse's Office Restroom	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							One missing ceiling tile
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	Door Frames	Metal	Brown	Friction	1	0.36	Negative								
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	110B	Nurse's Office Examination Room between Restroom and Office	Yes	Cabinets	Metal	Orange	Friction	1	0.43	Negative								
1	1	110C	Nurse's Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110C	Nurse's Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110C	Nurse's Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110C	Nurse's Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110C	Nurse's Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							One missing ceiling tile
1	1	110C	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110C	Nurse's Office	Yes	Door Frames	Metal	Brown	Friction	1	0.27	Negative								
1	1	110C	Nurse's Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	110C	Nurse's Office	Yes	Cabinets	Metal	Orange	Friction	1	0.66	Negative								
1	1	110E	Nurse's Office Storage Room adjacent to Therapist Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110E	Nurse's Office Storage Room adjacent to Therapist Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110E	Nurse's Office Storage Room adjacent to Therapist Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110E	Nurse's Office Storage Room adjacent to Therapist Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110E	Nurse's Office Storage Room adjacent to Therapist Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110E	Nurse's Office Storage Room adjacent to Therapist Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110E	Nurse's Office Storage Room adjacent to Therapist Office	Yes	Door Frames	Metal	Brown	Friction	1	0.33	Negative								
1	1	110F	Therapist Office	Yes	W1	Concrete	Blue	Flaking	1	0	Negative								
1	1	110F	Therapist Office	Yes	W2	Concrete	Blue	None	0	N/A	N/A	None							
1	1	110F	Therapist Office	Yes	W3	Concrete	Blue	None	0	N/A	N/A	None							
1	1	110F	Therapist Office	Yes	W4	Concrete	Blue	None	0	N/A	N/A	None							
1	1	110F	Therapist Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	1	110F	Therapist Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	110F	Therapist Office	Yes	Door Frames	Metal	Brown	Friction	1	0.28	Negative								
1	1	110F	Therapist Office	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	1	110F	Therapist Office	Yes	Cabinets	Metal	Orange	Friction	1	0.58	Negative								
1	1	110F	Therapist Office	Yes	Cabinets	Metal	Brown	Friction	1	0.01	Negative								
1	1	112	Boiler Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112	Boiler Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112	Boiler Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112	Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A							

					School District of Philadelphia																
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 4/19/2021-4/23/2021									
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School							ULCS# 6390									
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	112	Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112	Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112	Boiler Room	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112A	Building Engineer's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112A	Building Engineer's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112A	Building Engineer's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112A	Building Engineer's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112A	Building Engineer's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112A	Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112A	Building Engineer's Office	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112B	Building Engineer's Office Restroom	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112B	Building Engineer's Office Restroom	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112B	Building Engineer's Office Restroom	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112B	Building Engineer's Office Restroom	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112B	Building Engineer's Office Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112B	Building Engineer's Office Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112B	Building Engineer's Office Restroom	no	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	114	Storage Room adjacent to Boiler Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	114	Storage Room adjacent to Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	114	Storage Room adjacent to Boiler Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	114	Storage Room adjacent to Boiler Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	114	Storage Room adjacent to Boiler Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	114	Storage Room adjacent to Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	114	Storage Room adjacent to Boiler Room	no	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	112C	Storage Room adjacent to Stairwell adjacent to Gym	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	1	112C	Storage Room adjacent to Stairwell adjacent to Gym	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	1	112C	Storage Room adjacent to Stairwell adjacent to Gym	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	1	112C	Storage Room adjacent to Stairwell adjacent to Gym	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	1	112C	Storage Room adjacent to Stairwell adjacent to Gym	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	1	112C	Storage Room adjacent to Stairwell adjacent to Gym	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	1	112C	Storage Room adjacent to Stairwell adjacent to Gym	no	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	1	H11	Hallway from Main Lobby to Teacher's Lounge 106	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H11	Hallway from Main Lobby to Teacher's Lounge 106	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H11	Hallway from Main Lobby to Teacher's Lounge 106	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H11	Hallway from Main Lobby to Teacher's Lounge 106	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H11	Hallway from Main Lobby to Teacher's Lounge 106	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H11	Hallway from Main Lobby to Teacher's Lounge 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	H11	Hallway from Main Lobby to Teacher's Lounge 106	Yes	Kickplate	Ceramic	Black	None	0	0.68	Negative	None									
1	1	H12	Hallway from Nurse's Office to Gymnasium	Yes	W1	Concrete	Beige	None	0	0	Negative	None									
1	1	H12	Hallway from Nurse's Office to Gymnasium	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H12	Hallway from Nurse's Office to Gymnasium	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H12	Hallway from Nurse's Office to Gymnasium	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H12	Hallway from Nurse's Office to Gymnasium	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None									
1	1	H12	Hallway from Nurse's Office to Gymnasium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	S12	Stairwell adjacent to Gym	Yes	Kickplate	Ceramic	Black	None	0	0.8	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint		
1	1	S12	Stairwell adjacent to Gym	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None									
1	1	S12	Stairwell adjacent to Gym	Yes	W2	Concrete	Beige	None	0	0	Negative	None									
1	1	S12	Stairwell adjacent to Gym	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None									
1	1	S12	Stairwell adjacent to Gym	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None									
1	1	S12	Stairwell adjacent to Gym	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None									
1	1	S12	Stairwell adjacent to Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	S12	Stairwell adjacent to Gym	Yes	Staircase	Metal	Black	Friction	1	5	Positive	None									
1	1	S12	Stairwell adjacent to Gym	Yes	Door Frames	Metal	Black	Friction	1	0	Negative	None									
1	1	S12	Stairwell adjacent to Gym	Yes	Door	Metal	Tan	Friction	1	0	Negative	None									
1	2	S22	Stairwell adjacent to Office 216	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None									
1	2	S22	Stairwell adjacent to Office 216	Yes	W2	Concrete	Beige	None	0	0	Negative	None									
1	2	S22	Stairwell adjacent to Office 216	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None									
1	2	S22	Stairwell adjacent to Office 216	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None									
1	2	S22	Stairwell adjacent to Office 216	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None									
1	2	S22	Stairwell adjacent to Office 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	S22	Stairwell adjacent to Office 216	Yes	Door	Metal	Brown	Friction	1	0.54	Negative	None									
1	2	S22	Stairwell adjacent to Office 216	Yes	Door Frames	Metal	Brown	Friction	1	0.38	Negative	None									
1	2	S22	Stairwell adjacent to Office 216	Yes	Window Sill	Metal	Brown	Friction	0	0	Negative	None									
1	1	S22	Stairwell adjacent to Office 216	Yes	Staircase	Metal	Black	Friction	1	5	Positive	None									
1	2	224	Storage Room adjacent to Elevator Mechanical Room	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	2	224	Storage Room adjacent to Elevator Mechanical Room	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	2	224	Storage Room adjacent to Elevator Mechanical Room	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	2	224	Storage Room adjacent to Elevator Mechanical Room	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	2	224	Storage Room adjacent to Elevator Mechanical Room	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	2	224	Storage Room adjacent to Elevator Mechanical Room	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	2	224	Storage Room adjacent to Elevator Mechanical Room	no	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	2	225	Elevator Mechanical Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	225	Elevator Mechanical Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	225	Elevator Mechanical Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A									

			School District of Philadelphia																
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine			Lead Safe Certification Assessment Report										Inspection Dates: 4/19/2021-4/23/2021			
			Inspection Company: REPSG, Inc.			Edward T Steel Elementary School										ULCS# 6390			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	225	Elevator Mechanical Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	225	Elevator Mechanical Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	225	Elevator Mechanical Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	225	Elevator Mechanical Room	no	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	216	Office 216	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	216	Office 216	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	216	Office 216	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	216	Office 216	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	216	Office 216	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	216	Office 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	216	Office 216	Yes	Door Frames	Metal	Brown	Friction	1	0.44	Negative	N/A							
1	2	216A	Office 216 Storage Room	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	216A	Office 216 Storage Room	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	216A	Office 216 Storage Room	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	216A	Office 216 Storage Room	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	216A	Office 216 Storage Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	216A	Office 216 Storage Room	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	216A	Office 216 Storage Room	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	214	Classroom 214	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214	Classroom 214	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214	Classroom 214	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214	Classroom 214	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214	Classroom 214	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214	Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214	Classroom 214	Yes	Door Frames	Metal	Brown	Friction	1	0.37	Negative	None							
1	2	214	Classroom 214	Yes	Cabinets	Metal	Blue	Friction	1	0.01	Negative	None							
1	2	214A	Girl's Restroom adjacent to Classroom 214	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214A	Girl's Restroom adjacent to Classroom 214	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214A	Girl's Restroom adjacent to Classroom 214	Yes	W3	Concrete	Beige	None	0	0.02	Negative	None							
1	2	214A	Girl's Restroom adjacent to Classroom 214	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214A	Girl's Restroom adjacent to Classroom 214	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214A	Girl's Restroom adjacent to Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214A	Girl's Restroom adjacent to Classroom 214	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None							
1	2	214C	Custodial Closet adjacent to Classroom 214	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214C	Custodial Closet adjacent to Classroom 214	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214C	Custodial Closet adjacent to Classroom 214	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214C	Custodial Closet adjacent to Classroom 214	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214C	Custodial Closet adjacent to Classroom 214	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214C	Custodial Closet adjacent to Classroom 214	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214C	Custodial Closet adjacent to Classroom 214	no	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214B	Boy's Restroom adjacent to Classroom 214	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214B	Boy's Restroom adjacent to Classroom 214	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214B	Boy's Restroom adjacent to Classroom 214	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214B	Boy's Restroom adjacent to Classroom 214	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214B	Boy's Restroom adjacent to Classroom 214	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	214B	Boy's Restroom adjacent to Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	214B	Boy's Restroom adjacent to Classroom 214	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None							
1	2	214B	Boy's Restroom adjacent to Classroom 214	Yes	Kickplate	Ceramic	Black	None	0	0.75	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	2	L1	Library	Yes	W1	Concrete	Multi	None	0	0	Negative	None							
1	2	L1	Library	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L1	Library	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L1	Library	Yes	W4	Concrete	Beige	None	0	0.01	Negative	None							
1	2	L1	Library	Yes	Ceiling	Sheetrock	Beige	Flaking	1	0	Negative	N/A							
1	2	L1	Library	Yes	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	L1	Library	Yes	Door Frames	Metal	Beige	Friction	1	0.22	Negative	N/A							
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	W1	Concrete	Beige	None	0	0	Negative	None							
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	W3	Concrete	Purple	None	0	0	Negative	None							
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None							
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	Door Frames	Metal	Beige	None	0	N/A	N/A	None							
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	Kickplate	Ceramic	Black	None	0	0.82	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	2	L2	IMC Office Odd Side adjacent to Stairwell	Yes	Window Frame	Metal	Beige	None	0	0.2	Negative	None							
1	2	L3	IMC Office Odd Side Rear	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L3	IMC Office Odd Side Rear	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L3	IMC Office Odd Side Rear	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L3	IMC Office Odd Side Rear	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L3	IMC Office Odd Side Rear	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	L3	IMC Office Odd Side Rear	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	L3	IMC Office Odd Side Rear	Yes	Door Frames	Metal	Beige	Friction	1	0.16	Negative	N/A							
1	2	L4	IMC Material Production Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							

			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 4/19/2021-4/23/2021								
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School							ULCS# 6390								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	L4	IMC Material Production Room	Yes	W2	Concrete	Purple	None	0	0	Negative	None								
1	2	L4	IMC Material Production Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	L4	IMC Material Production Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	L4	IMC Material Production Room	Yes	Ceiling	Drop	Beige	None	0	N/A	N/A	None								
1	2	L4	IMC Material Production Room	Yes	Floor	Floor tile	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	L4	IMC Material Production Room	Yes	kickplate	Ceramic	Black	None	0	1	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	2	L4	IMC Material Production Room	Yes	Door Frames	Metal	Beige	None	0	N/A	N/A	None								
1	2	L4A	IMC Material Production Room Telecommunication Equipment Room	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	L4A	IMC Material Production Room Telecommunication Equipment Room	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	L4A	IMC Material Production Room Telecommunication Equipment Room	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	L4A	IMC Material Production Room Telecommunication Equipment Room	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	L4A	IMC Material Production Room Telecommunication Equipment Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	L4A	IMC Material Production Room Telecommunication Equipment Room	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	L4A	IMC Material Production Room Telecommunication Equipment Room	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	S26	Stairwell to IMC between Mechanical Rooms	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26	Stairwell to IMC between Mechanical Rooms	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26	Stairwell to IMC between Mechanical Rooms	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26	Stairwell to IMC between Mechanical Rooms	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26	Stairwell to IMC between Mechanical Rooms	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26	Stairwell to IMC between Mechanical Rooms	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	S26A	Stairwell to IMC on Odd Side	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26A	Stairwell to IMC on Odd Side	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26A	Stairwell to IMC on Odd Side	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26A	Stairwell to IMC on Odd Side	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26A	Stairwell to IMC on Odd Side	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26A	Stairwell to IMC on Odd Side	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	S26B	Stairwell to IMC adjacent to Material Production Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26B	Stairwell to IMC adjacent to Material Production Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26B	Stairwell to IMC adjacent to Material Production Room	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26B	Stairwell to IMC adjacent to Material Production Room	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26B	Stairwell to IMC adjacent to Material Production Room	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S26B	Stairwell to IMC adjacent to Material Production Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	222	Storage Room adjacent to Classroom 220	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	222	Storage Room adjacent to Classroom 220	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	222	Storage Room adjacent to Classroom 220	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	222	Storage Room adjacent to Classroom 220	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	222	Storage Room adjacent to Classroom 220	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	222	Storage Room adjacent to Classroom 220	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	222	Storage Room adjacent to Classroom 220	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	220	Classroom 220	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	220	Classroom 220	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	220	Classroom 220	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	220	Classroom 220	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	220	Classroom 220	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	220	Classroom 220	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	220	Classroom 220	Yes	Door Frames	Metal	Brown	Friction	0	N/A	N/A	None								
1	2	H25	Hallway from Office 216 to Classroom 206	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	H25	Hallway from Office 216 to Classroom 206	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	H25	Hallway from Office 216 to Classroom 206	Yes	W3	Concrete	Beige	None	0	0	Negative	None								
1	2	H25	Hallway from Office 216 to Classroom 206	Yes	W4	Concrete	Beige	None	0	0	Negative	None								
1	2	H25	Hallway from Office 216 to Classroom 206	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	H25	Hallway from Office 216 to Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	H25	Hallway from Office 216 to Classroom 206	Yes	Kickplate	Ceramic	Black	None	0	1	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	2	H25	Hallway from Office 216 to Classroom 206	Yes	Structural Beam	Concrete	Beige	None	0	0	Negative	None								
1	2	212	Classroom 212	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	212	Classroom 212	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	212	Classroom 212	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	212	Classroom 212	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	212	Classroom 212	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	212	Classroom 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	212	Classroom 212	Yes	Door Frames	Metal	Brown	Friction	0	0.07	Negative	None								
1	2	210	Classroom 210	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	210	Classroom 210	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	210	Classroom 210	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	210	Classroom 210	Yes	W4	Metal	Black	Friction	1	0.13	Negative	None								
1	2	210	Classroom 210	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	210	Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								

					School District of Philadelphia															
					Name of Inspector: Suzanne Shourds, Shalaunda Gourdine										Inspection Dates: 4/19/2021-4/23/2021					
					Lead Safe Certification Assessment Report															
					Edward T Steel Elementary School										ULCS# 6390					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	210	Classroom 210	Yes	Door Frames	Metal	Brown	Friction	1	0.04	Negative									
1	2	208	Classroom 208	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	208	Classroom 208	Yes	W2	Metal	Red	Friction	10	0.22	Negative									
1	2	208	Classroom 208	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	208	Classroom 208	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	208	Classroom 208	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	208	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	208	Classroom 208	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None								
1	2	206	Classroom 206	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	206	Classroom 206	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	206	Classroom 206	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	206	Classroom 206	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	206	Classroom 206	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	206	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	206	Classroom 206	Yes	Door Frames	Metal	Grey	Friction	1	0.01	Negative									
1	2	204	Classroom 204	Yes	W1	Concrete	Beige	None	0		Negative	None								
1	2	204	Classroom 204	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	204	Classroom 204	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	204	Classroom 204	Yes	W4	Concrete	Turquoise	None	0	N/A	N/A	None								
1	2	204	Classroom 204	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	204	Classroom 204	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None								
1	2	202	Classroom 202	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	202	Classroom 202	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	202	Classroom 202	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	202	Classroom 202	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	202	Classroom 202	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	202	Classroom 202	Yes	Door Frames	Metal	Brown	Friction	1	N/A	N/A	N/A								
1	2	202A	Classroom 202 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	202A	Classroom 202 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	202A	Classroom 202 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	202A	Classroom 202 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	202A	Classroom 202 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	202A	Classroom 202 Closet	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	218A	Storage Room adjacent to Classroom 202	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	218A	Storage Room adjacent to Classroom 202	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	218A	Storage Room adjacent to Classroom 202	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	218A	Storage Room adjacent to Classroom 202	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	218A	Storage Room adjacent to Classroom 202	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	218A	Storage Room adjacent to Classroom 202	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	218A	Storage Room adjacent to Classroom 202	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	2	218	Mechanical Room adjacent to Classroom 220	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	218	Mechanical Room adjacent to Classroom 220	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	218	Mechanical Room adjacent to Classroom 220	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	218	Mechanical Room adjacent to Classroom 220	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	218	Mechanical Room adjacent to Classroom 220	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	218	Mechanical Room adjacent to Classroom 220	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	218	Mechanical Room adjacent to Classroom 220	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217	Mechanical Room adjacent to Classroom 219	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217	Mechanical Room adjacent to Classroom 219	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217	Mechanical Room adjacent to Classroom 219	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217	Mechanical Room adjacent to Classroom 219	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217	Mechanical Room adjacent to Classroom 219	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217	Mechanical Room adjacent to Classroom 219	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217	Mechanical Room adjacent to Classroom 219	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	S21	Stairwell adjacent to Classroom 201	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S21	Stairwell adjacent to Classroom 201	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S21	Stairwell adjacent to Classroom 201	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S21	Stairwell adjacent to Classroom 201	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S21	Stairwell adjacent to Classroom 201	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	S21	Stairwell adjacent to Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	S21	Stairwell adjacent to Classroom 201	Yes	Doors	Metal	Brown	Friction	1	0.46	Negative	None								
1	2	S21	Stairwell adjacent to Classroom 201	Yes	Staircase	Metal	Black	Friction	1	5	Positive	None								
1	2	219	Classroom 219	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	219	Classroom 219	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	219	Classroom 219	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	2	219	Classroom 219	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	219	Classroom 219	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	2	219	Classroom 219	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	219	Classroom 219	Yes	Door Frames	Metal	Brown	Friction	1	0.21	Negative	None								
1	2	H25A	Hallway from Classrooms 210 to 209	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	2	H25A	Hallway from Classrooms 210 to 209	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	2	H25A	Hallway from Classrooms 210 to 209	Yes	W3	Concrete	Beige	None	0	1	Positive	None								
1	2	H25A	Hallway from Classrooms 210 to 209	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	2	H25A	Hallway from Classrooms 210 to 209	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								

						School District of Philadelphia														
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/2021-4/23/2021							
			Inspection Company: REPSG, Inc.			Edward T Steel Elementary School							ULCS# 6390							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	H25A	Hallway from Classrooms 210 to 209	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	H25A	Hallway from Classrooms 210 to 209	Yes	kickplate	Ceramic	Black	None	0	0	Negative	None								
1	2	201	Classroom 201	Yes	W1	Concrete	Beige	None		N/A	N/A	None								
1	2	201	Classroom 201	Yes	W2	Concrete	Beige	None		N/A	N/A	None								
1	2	201	Classroom 201	Yes	W3	Concrete	Orange	None		0	0	Negative								
1	2	201	Classroom 201	Yes	W4	Concrete	Beige	None		N/A	N/A	None								
1	2	201	Classroom 201	Yes	Ceiling	Concrete	Beige	None		N/A	N/A	None								
1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	201	Classroom 201	Yes	Door Frames	Metal	Grey	Friction		1	0.27	Negative								
1	2	203	Classroom 203	Yes	W1	Concrete	Beige	None		N/A	N/A	None								
1	2	203	Classroom 203	Yes	W2	Concrete	Beige	None		N/A	N/A	None								
1	2	203	Classroom 203	Yes	W3	Concrete	Beige	None		N/A	N/A	None								
1	2	203	Classroom 203	Yes	W4	Sheetrock	Grey	None		0	0	Negative								
1	2	203	Classroom 203	Yes	Ceiling	Concrete	Beige	None		N/A	N/A	None								
1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	203	Classroom 203	Yes	Door Frames	Metal	Grey	Friction		1	0.36	Negative								
1	2	205	Classroom 205	Yes	W1	Concrete	Beige	None		N/A	N/A	None								
1	2	205	Classroom 205	Yes	W2	Concrete	Beige	None		N/A	N/A	None								
1	2	205	Classroom 205	Yes	W3	Concrete	Beige	None		N/A	N/A	None								
1	2	205	Classroom 205	Yes	W4	Sheetrock	Orange	None		0	0	Negative								
1	2	205	Classroom 205	Yes	Ceiling	Concrete	Beige	None		N/A	N/A	None								
1	2	205	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	205	Classroom 205	Yes	Door Frames	Metal	Grey	None		N/A	N/A	None								
1	2	205	Classroom 205	Yes	Wall vent	Metal	Grey	None		0	0.12	Negative								
1	2	205	Classroom 205	Yes	Kickplate	Ceramic	Black	None		0	0.65	Negative								
1	2	207	Classroom 207	Yes	W1	Concrete	Beige	None		N/A	N/A	None								
1	2	207	Classroom 207	Yes	W2	Sheetrock	Turquoise	None		0	0	Negative								
1	2	207	Classroom 207	Yes	W3	Concrete	Beige	None		N/A	N/A	None								
1	2	207	Classroom 207	Yes	W4	Concrete	Beige	None		N/A	N/A	None								
1	2	207	Classroom 207	Yes	Ceiling	Concrete	Beige	None		N/A	N/A	None								
1	2	207	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	207	Classroom 207	Yes	Door Frames	Metal	Grey	None		N/A	N/A	None								
1	2	209	Classroom 209	Yes	W1	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	209	Classroom 209	Yes	W2	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	209	Classroom 209	Yes	W3	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	209	Classroom 209	Yes	W4	No Access	Beige	None	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	209	Classroom 209	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	209	Classroom 209	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	209	Classroom 209	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	211	Classroom 211	Yes	W1	Concrete	Beige	None		N/A	N/A	None								
1	2	211	Classroom 211	Yes	W2	Concrete	Beige	None		N/A	N/A	None								
1	2	211	Classroom 211	Yes	W3	Concrete	Beige	None		N/A	N/A	None								
1	2	211	Classroom 211	Yes	W4	Concrete	Beige	None		N/A	N/A	None								
1	2	211	Classroom 211	Yes	Ceiling	Concrete	Beige	None		N/A	N/A	None								
1	2	211	Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211	Classroom 211	Yes	Door Frames	Metal	Gray	Friction		0	0.33	Negative								
1	2	211	Classroom 211	Yes	Kickplate	Ceramic	Black	None		0	1	Positive							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	2	221	Storage Room across from Classroom 211	Yes	W1	Concrete	Beige	None		N/A	N/A	None								
1	2	221	Storage Room across from Classroom 211	Yes	W2	Concrete	Beige	None		N/A	N/A	None								
1	2	221	Storage Room across from Classroom 211	Yes	W3	Concrete	Beige	None		N/A	N/A	None								
1	2	221	Storage Room across from Classroom 211	Yes	W4	Concrete	Beige	None		N/A	N/A	None								
1	2	221	Storage Room across from Classroom 211	Yes	Ceiling	Concrete	Beige	None		N/A	N/A	None								
1	2	221	Storage Room across from Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	221	Storage Room across from Classroom 211	Yes	Door Frames	Metal	Brown	None		0	0.15	Negative								
1	2	211B	Boy's Restroom adjacent to Classroom 211	Yes	W1	Concrete	Beige	None		N/A	N/A	None								
1	2	211B	Boy's Restroom adjacent to Classroom 211	Yes	W2	Concrete	Beige	None		N/A	N/A	None								
1	2	211B	Boy's Restroom adjacent to Classroom 211	Yes	W3	Concrete	Beige	None		N/A	N/A	None								
1	2	211B	Boy's Restroom adjacent to Classroom 211	Yes	W4	Concrete	Beige	None		N/A	N/A	None								
1	2	211B	Boy's Restroom adjacent to Classroom 211	Yes	Ceiling	Concrete	Beige	None		N/A	N/A	None								
1	2	211B	Boy's Restroom adjacent to Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211B	Boy's Restroom adjacent to Classroom 211	Yes	Door Frames	Metal	Brown	Friction		0	0.17	Negative								
1	2	211C	Custodial Closet adjacent to Classroom 211	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211C	Custodial Closet adjacent to Classroom 211	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211C	Custodial Closet adjacent to Classroom 211	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211C	Custodial Closet adjacent to Classroom 211	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211C	Custodial Closet adjacent to Classroom 211	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211C	Custodial Closet adjacent to Classroom 211	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211C	Custodial Closet adjacent to Classroom 211	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211A	Girl's Restroom adjacent to Classroom 211	Yes	W1	Concrete	Beige	None		N/A	N/A	None								
1	2	211A	Girl's Restroom adjacent to Classroom 211	Yes	W2	Concrete	Beige	None		N/A	N/A	None								
1	2	211A	Girl's Restroom adjacent to Classroom 211	Yes	W3	Concrete	Beige	None		N/A	N/A	None								
1	2	211A	Girl's Restroom adjacent to Classroom 211	Yes	W4	Concrete	Beige	None		N/A	N/A	None								
1	2	211A	Girl's Restroom adjacent to Classroom 211	Yes	Ceiling	Concrete	Beige	None		N/A	N/A	None								
1	2	211A	Girl's Restroom adjacent to Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								

			School District of Philadelphia																
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report								Inspection Dates: 4/19/2021-4/23/2021						
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School								ULCS# 6390						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	211A	Girl's Restroom adjacent to Classroom 211	Yes	Door Frames	Metal	Brown	Friction	0	0.22	Negative	None							
1	2	213	Classroom 213	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	213	Classroom 213	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	213	Classroom 213	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	213	Classroom 213	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	213	Classroom 213	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	213	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	213	Classroom 213	Yes	Door Frames	Metal	Brown	Friction	1	0.29	Negative	None							
1	2	213	Classroom 213	Yes	Kickplate	Ceramic	Black	None	0	0.74	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	2	215C	Classroom 213 Office	Yes	W1	Concrete	Beige	None	0	0.01	Negative	None							
1	2	215C	Classroom 213 Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215C	Classroom 213 Office	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215C	Classroom 213 Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215C	Classroom 213 Office	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215C	Classroom 213 Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	215C	Classroom 213 Office	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None							
1	2	215	Office adjacent to Women's Restroom	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215	Office adjacent to Women's Restroom	Yes	W2	Concrete	Beige	None	0	0.01	Negative	None							
1	2	215	Office adjacent to Women's Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215	Office adjacent to Women's Restroom	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215	Office adjacent to Women's Restroom	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215	Office adjacent to Women's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	215	Office adjacent to Women's Restroom	Yes	Door Frames	Metal	Grey	None	0	N/A	N/A	None							
1	2	215	Office adjacent to Women's Restroom	Yes	Window Frames	Metal	Brown	None	0	0.33	Negative	None							
1	2	215A	Women's Restroom by Classroom 215	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215A	Women's Restroom by Classroom 215	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215A	Women's Restroom by Classroom 215	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215A	Women's Restroom by Classroom 215	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215A	Women's Restroom by Classroom 215	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215A	Women's Restroom by Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	215A	Women's Restroom by Classroom 215	Yes	Door Frames	Metal	Brown	Friction	1	N/A	N/A	None							
1	2	215B	Men's Restroom by Classroom 215	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215B	Men's Restroom by Classroom 215	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215B	Men's Restroom by Classroom 215	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215B	Men's Restroom by Classroom 215	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215B	Men's Restroom by Classroom 215	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	215B	Men's Restroom by Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	215B	Men's Restroom by Classroom 215	Yes	Door Frames	Metal	Brown	Friction	1	N/A	N/A	None							
1	2	H27	Hallway from Classroom 215 to 203	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	H27	Hallway from Classroom 215 to 203	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	H27	Hallway from Classroom 215 to 203	Yes	W3	Concrete	Beige	None	0	0	Negative	None							
1	2	H27	Hallway from Classroom 215 to 203	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	H27	Hallway from Classroom 215 to 203	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	H27	Hallway from Classroom 215 to 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	H27	Hallway from Classroom 215 to 203	Yes	Door Frames	Metal	Brown	Friction	0	N/A	N/A	None							
1	2	H27	Hallway from Classroom 215 to 203	Yes	Kickplate	Ceramic	Black	None	0	1	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 215	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 215	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 215	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 215	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 215	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 215	Yes	Door Frames	Metal	Brown	Friction	0	N/A	N/A	None							
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 215	Yes	Staircase	Metal	Black	None	0	N/A	N/A	None							
1	2	S24	Stairwell adjacent to Women's Restroom by Classroom 216	Yes	Kickplate	Ceramic	Black	None	0	1	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	3	S34	Stairwell near Classroom 313	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S34	Stairwell near Classroom 313	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S34	Stairwell near Classroom 313	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S34	Stairwell near Classroom 313	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S34	Stairwell near Classroom 313	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S34	Stairwell near Classroom 313	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S34	Stairwell near Classroom 313	Yes	Door Frames	Metal	Brown	Friction	0	N/A	N/A	None							
1	3	S34	Stairwell near Classroom 313	Yes	Staircase	Metal	Black	None	0	N/A	N/A	None							
1	3	315A	Former Teacher's Lounge	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							

			School District of Philadelphia																
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report								Inspection Dates: 4/19/2021-4/23/2021						
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School								ULCS# 6390						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	315A	Former Teacher's Lounge	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315A	Former Teacher's Lounge	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315A	Former Teacher's Lounge	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315A	Former Teacher's Lounge	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	315A	Former Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	315A	Former Teacher's Lounge	Yes	Door Frames	Metal	Brown	Friction	1	0.03	Negative								
1	3	315A	Former Teacher's Lounge	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	315B	Men's Restroom near Classroom 313	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315B	Men's Restroom near Classroom 313	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315B	Men's Restroom near Classroom 313	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315B	Men's Restroom near Classroom 313	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315B	Men's Restroom near Classroom 313	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	315B	Men's Restroom near Classroom 313	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	315B	Men's Restroom near Classroom 313	Yes	Door Frames	Metal	Brown	Friction	1	0.58	Negative								
1	3	315B	Men's Restroom near Classroom 313	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	315C	Women's Restroom adjacent to Former Teacher's Lounge	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315C	Women's Restroom adjacent to Former Teacher's Lounge	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315C	Women's Restroom adjacent to Former Teacher's Lounge	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315C	Women's Restroom adjacent to Former Teacher's Lounge	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315C	Women's Restroom adjacent to Former Teacher's Lounge	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315C	Women's Restroom adjacent to Former Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	315C	Women's Restroom adjacent to Former Teacher's Lounge	Yes	Door Frames	Metal	Brown	Friction	1	0.41	Negative								
1	3	315C	Women's Restroom adjacent to Former Teacher's Lounge	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	313	Classroom 313	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	313	Classroom 313	Yes	W2	Concrete	Beige	None	0	0.05	Negative	None							
1	3	313	Classroom 313	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	313	Classroom 313	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	313	Classroom 313	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	313	Classroom 313	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	313	Classroom 313	Yes	Door Frames	Metal	Brown	Friction	1	0.24	Negative								
1	3	313	Classroom 313	Yes	Window Frames	Metal	Black	Friction	1	0	Negative								
1	3	313	Classroom 313	Yes	Cabinets	Metal	Black	Friction	2	0	Negative								
1	3	313	Classroom 313	Yes	Cabinets	Metal	Blue	Friction	2	0.01	Negative								
1	3	313	Classroom 313	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	315	Classroom 313 Restroom	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315	Classroom 313 Restroom	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315	Classroom 313 Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315	Classroom 313 Restroom	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315	Classroom 313 Restroom	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	315	Classroom 313 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	315	Classroom 313 Restroom	Yes	Door Frames	Metal	Brown	Friction	1	0.36	Negative								
1	3	315	Classroom 313 Restroom	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	311A	Girl's Restroom adjacent Classroom 311	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311A	Girl's Restroom adjacent Classroom 311	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311A	Girl's Restroom adjacent Classroom 311	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311A	Girl's Restroom adjacent Classroom 311	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311A	Girl's Restroom adjacent Classroom 311	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311A	Girl's Restroom adjacent Classroom 311	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311A	Girl's Restroom adjacent Classroom 311	Yes	Door Frames	Metal	Brown	Friction	1	0.45	Negative	None							
1	3	311A	Girl's Restroom adjacent Classroom 311	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	311C	Custodial Closet adjacent Classroom 311	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311C	Custodial Closet adjacent Classroom 311	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311C	Custodial Closet adjacent Classroom 311	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311C	Custodial Closet adjacent Classroom 311	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311C	Custodial Closet adjacent Classroom 311	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311C	Custodial Closet adjacent Classroom 311	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311C	Custodial Closet adjacent Classroom 311	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311B	Boy's Restroom adjacent Classroom 311	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311B	Boy's Restroom adjacent Classroom 311	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311B	Boy's Restroom adjacent Classroom 311	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311B	Boy's Restroom adjacent Classroom 311	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	311B	Boy's Restroom adjacent Classroom 311	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							One missing ceiling tile
1	3	311B	Boy's Restroom adjacent Classroom 311	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	311B	Boy's Restroom adjacent Classroom 311	Yes	Door Frames	Metal	Brown	Friction	1	0.76	Positive	None							
1	3	311B	Boy's Restroom adjacent Classroom 311	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	321	Storage across from Classroom 311	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	321	Storage across from Classroom 311	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	321	Storage across from Classroom 311	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	321	Storage across from Classroom 311	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							

					School District of Philadelphia															
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 4/19/2021-4/23/2021								
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School							ULCS# 6390								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	321	Storage across from Classroom 311	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	321	Storage across from Classroom 311	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	321	Storage across from Classroom 311	Yes	Door Frames	Metal	Brown	Friction	1	0.2	Negative									
1	3	319	Classroom 319	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	3	319	Classroom 319	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	3	319	Classroom 319	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	3	319	Classroom 319	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	3	319	Classroom 319	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	3	319	Classroom 319	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	3	319	Classroom 319	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1	3	311	Classroom 311	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	311	Classroom 311	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	311	Classroom 311	yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	311	Classroom 311	yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	311	Classroom 311	yes	W4	Concrete	White	None	0	0	Negative									
1	3	311	Classroom 311	yes	W4	Concrete	Yellow	None	0	0.02	Negative									
1	3	311	Classroom 311	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	311	Classroom 311	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	311	Classroom 311	yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None								
1	3	311	Classroom 311	yes	Wall Vents	Metal	Brown	Friction	1	0.06	Negative									
1	3	311	Classroom 311	yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	3	311	Classroom 311	yes	Cabinets	Metal	Multi	Friction	1	0	Negative									
1	3	309	Classroom 309	yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	309	Classroom 309	yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	309	Classroom 309	yes	W3	Metal	Blue	Friction	1	0.05	Negative									
1	3	309	Classroom 309	yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	309	Classroom 309	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							One missing ceiling tile	
1	3	309	Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	309	Classroom 309	yes	Door Frames	Metal	Brown	Friction	1	0.23	Negative									
1	3	309	Classroom 309	yes	Window Frames	Metal	Black	None	0	N/A	N/A	None								
1	3	309	Classroom 309	yes	Kickplate	Ceramic	Black	Friction	1	1	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	3	309	Classroom 309	yes	Cabinets	Metal	Multi	Friction	2	0.01	Negative									
1	3	307	Classroom 307	yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	307	Classroom 307	yes	W2	Metal	Blue	Friction	7	0.05	Negative									
1	3	307	Classroom 307	yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	307	Classroom 307	yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	307	Classroom 307	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	307	Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	307	Classroom 307	yes	Door Frames	Metal	Brown	Friction	0	N/A	N/A	None								
1	3	307	Classroom 307	yes	Wall vents	Metal	Brown	None	0	0.2	Negative									
1	3	307	Classroom 307	yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	3	307	Classroom 307	yes	Cabinets	Metal	Black	Friction	2	0	Negative									
1	3	305	Classroom 305	yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	305	Classroom 305	yes	W2	Metal	Light Blue	Friction	1	0.04	Negative									
1	3	305	Classroom 305	yes	W2	Metal	Yellow	None	0	0.06	Negative	None								
1	3	305	Classroom 305	yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	305	Classroom 305	yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	305	Classroom 305	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							One missing ceiling tile	
1	3	305	Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	305	Classroom 305	yes	Door Frames	Metal	Brown	Friction	1	0.26	Negative									
1	3	305	Classroom 305	yes	Wall vents	Metal	Brown	None	0	N/A	N/A									
1	3	305	Classroom 305	yes	Window Frames	Metal	Black	None	0	N/A	N/A	None								
1	3	305	Classroom 305	yes	Cabinets	Metal	Light blue & yellow	Friction	1	0	Negative									
1	3	307	Classroom 305	yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	3	303	Classroom 303	yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	303	Classroom 303	yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	303	Classroom 303	yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	303	Classroom 303	yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	303	Classroom 303	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	303	Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	303	Classroom 303	yes	Door Frames	Metal	Brown	Friction	1	0.26	Negative									
1	3	303	Classroom 303	yes	Wall vents	Metal	Brown	None	0	N/A	N/A									
1	3	303	Classroom 303	yes	Window Frames	Metal	Black	None	0	N/A	N/A	None								
1	3	303	Classroom 303	yes	Partition Wall	Metal	Brown	None	0	N/A	N/A	None								
1	3	303	Classroom 303	yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	3	303	Classroom 303	yes	Cabinets	Metal	Green	Friction	1	N/A	N/A									
1	3	301	Classroom 301	yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	301	Classroom 301	yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	301	Classroom 301	yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	301	Classroom 301	yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	301	Classroom 301	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	301	Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	301	Classroom 301	yes	Door Frames	Metal	White	Friction	2	0.41	Negative									
1	3	301	Classroom 301	yes	Wall vents	Metal	White	None	0	N/a	N/A									

			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report								Inspection Dates: 4/19/2021-4/23/2021						
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School								ULCS# 6390						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	301	Classroom 301	yes	Kickplate	Ceramic	Black	Friction	1	0.71	Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	3	301	Classroom 301	yes	Cabinets	Metal	White	Friction	1	0.07	Negative								
1	3	H28	Hallway from Men's Restroom to Classroom 305	yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	H28	Hallway from Men's Restroom to Classroom 305	yes	W2	Concrete	Beige	None	0		Negative	None							
1	3	H28	Hallway from Men's Restroom to Classroom 305	yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	H28	Hallway from Men's Restroom to Classroom 305	yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	H28	Hallway from Men's Restroom to Classroom 305	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	H28	Hallway from Men's Restroom to Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	H28	Hallway from Men's Restroom to Classroom 305	yes	Kickplate	Ceramic	Black	Friction	1	0.54	Negative	None							
1	3	317	Mechanical Room across from Classroom 301	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	317	Mechanical Room across from Classroom 301	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	317	Mechanical Room across from Classroom 301	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	317	Mechanical Room across from Classroom 301	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	317	Mechanical Room across from Classroom 301	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	317	Mechanical Room across from Classroom 301	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	317	Mechanical Room across from Classroom 301	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S36	Stairwell to Roof between Mechanical Rooms	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S36	Stairwell to Roof between Mechanical Rooms	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S36	Stairwell to Roof between Mechanical Rooms	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S36	Stairwell to Roof between Mechanical Rooms	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S36	Stairwell to Roof between Mechanical Rooms	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S36	Stairwell to Roof between Mechanical Rooms	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S36	Stairwell to Roof between Mechanical Rooms	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	318	Mechanical Room across from Classroom 302	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	318	Mechanical Room across from Classroom 302	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	318	Mechanical Room across from Classroom 302	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	318	Mechanical Room across from Classroom 302	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	318	Mechanical Room across from Classroom 302	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	318	Mechanical Room across from Classroom 302	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	318	Mechanical Room across from Classroom 302	No	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S31	Stairwell adjacent to Classroom 301	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S31	Stairwell adjacent to Classroom 301	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S31	Stairwell adjacent to Classroom 301	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S31	Stairwell adjacent to Classroom 301	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S31	Stairwell adjacent to Classroom 301	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S31	Stairwell adjacent to Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S31	Stairwell adjacent to Classroom 301	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	3	318A	Storage Room adjacent to Classroom 302	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	318A	Storage Room adjacent to Classroom 302	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	318A	Storage Room adjacent to Classroom 302	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	318A	Storage Room adjacent to Classroom 302	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	318A	Storage Room adjacent to Classroom 302	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	318A	Storage Room adjacent to Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	318A	Storage Room adjacent to Classroom 302	Yes	Door Frames	Metal	Brown	Friction	2	0.41	Negative	None							
1	3	302	Classroom 302	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	302	Classroom 302	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	302	Classroom 302	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	302	Classroom 302	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	302	Classroom 302	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	302	Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							Three missing ceiling tiles
1	3	302	Classroom 302	Yes	Door Frames	Metal	Grey	Friction	1	0.01	Negative								
1	3	302	Classroom 302	Yes	Window Frames	Metal	Black	None	0	N/A	N/A	None							
1	3	302	Classroom 302	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	302	Classroom 302	Yes	Cabinets	Metal	Multi	Friction	1	0.01	Negative								
1	3	302A	Classroom 302 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	302A	Classroom 302 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	302A	Classroom 302 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	302A	Classroom 302 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	302A	Classroom 302 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	One missing ceiling tile
1	3	302A	Classroom 302 Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	302A	Classroom 302 Closet	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	304	Classroom 304	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	304	Classroom 304	Yes	W2	Sheetrock	Beige	Chipping	2	0	Negative								
1	3	304	Classroom 304	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	304	Classroom 304	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	304	Classroom 304	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	304	Classroom 304	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	304	Classroom 304	Yes	Door Frames	Metal	Tan	Friction	3	0.02	Negative								
1	3	304	Classroom 304	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	304	Classroom 304	Yes	Window Frames	Metal	Black	None	0	N/A	N/A	None							
1	3	306	Classroom 306	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	306	Classroom 306	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	306	Classroom 306	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	306	Classroom 306	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							

					School District of Philadelphia															
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 4/19/2021-4/23/2021								
			Inspection Company: REPSG, Inc.		Edward T Steel Elementary School							ULCS# 6390								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	306	Classroom 306	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	306	Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	306	Classroom 306	Yes	Door Frames	Metal	Beige	Friction	1	N/A	N/A									
1	3	306	Classroom 306	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	3	308	Classroom 308	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	308	Classroom 308	Yes	W2	Sheetrock	Beige	Chipping	1		0 Negative									
1	3	308	Classroom 308	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	308	Classroom 308	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	308	Classroom 308	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	308	Classroom 308	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	308	Classroom 308	Yes	Door Frames	Metal	Beige	Friction	3	N/A	N/A									
1	3	308	Classroom 308	Yes	Kickplate	Ceramic	Black	Friction	1		1 Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	3	308	Classroom 308	Yes	Window Frames	Metal	Black	None	0	N/A	N/A	None								
1	3	310	Classroom 310	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	310	Classroom 310	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	310	Classroom 310	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	310	Classroom 310	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	310	Classroom 310	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							One missing ceiling tile	
1	3	310	Classroom 310	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	310	Classroom 310	Yes	Door Frames	Metal	Brown	Friction	1		0.01 Negative									
1	3	310	Classroom 310	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	3	310	Classroom 310	Yes	Window Frames	Metal	Black	None	0	N/A	N/A	None								
1	3	310	Classroom 310	Yes	Cabinets	Metal	Multi	Friction	2		0.01 Negative									
1	3	312	Classroom 312	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	312	Classroom 312	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	312	Classroom 312	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	312	Classroom 312	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	312	Classroom 312	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	312	Classroom 312	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	312	Classroom 312	Yes	Door Frames	Metal	Brown	Friction	1		0.06 Negative									
1	3	312	Classroom 312	Yes	Door	Metal	Beige	Friction	1		0.25 Negative									
1	3	312	Classroom 312	Yes	Kickplate	Ceramic	Black	None	0	N/a	N/A									
1	3	312	Classroom 312	Yes	Window Frames	Metal	Black	None	0	N/a	N/A	None								
1	3	312	Classroom 312	Yes	Cabinets	Metal	Tan	Friction	1		0.01 Negative									
1	3	H25	Hallway from Classrooms 307 to 310	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	H25	Hallway from Classrooms 307 to 310	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	H25	Hallway from Classrooms 307 to 310	Yes	W3	Concrete	Beige	None	0		0 Negative	None								
1	3	H25	Hallway from Classrooms 307 to 310	Yes	W4	Concrete	Beige	None	0		0 Negative	None								
1	3	H25	Hallway from Classrooms 307 to 310	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	H25	Hallway from Classrooms 307 to 310	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	H25	Hallway from Classrooms 307 to 310	Yes	Door Frames	Metal	Brown	Friction	0	N/A	N/A	None								
1	3	H25	Hallway from Classrooms 307 to 310	Yes	Structural Beam	Concrete	Beige	None	0		0 Negative	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint	
1	3	H25	Hallway from Classrooms 307 to 310	Yes	Kickplate	Ceramic	Black	None	0		1 Positive	None								
1	3	320	Classroom 320	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	320	Classroom 320	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	320	Classroom 320	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	320	Classroom 320	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	320	Classroom 320	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	320	Classroom 320	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	320	Classroom 320	Yes	Door Frames	Metal		None	0	N/A	N/A	None								
1	3	320	Classroom 320	Yes	Store-front windows	Metal	Brown	Friction	1		0.32 Negative									
1	3	320	Classroom 320	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	3	322	Storage Room adjacent to Classroom 320	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	322	Storage Room adjacent to Classroom 320	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	322	Storage Room adjacent to Classroom 320	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	322	Storage Room adjacent to Classroom 320	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	322	Storage Room adjacent to Classroom 320	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	322	Storage Room adjacent to Classroom 320	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	322	Storage Room adjacent to Classroom 320	Yes	Door Frames	Metal	Brown	Friction	1		0.27 Negative									
1	3	314A	Girl's Restroom adjacent to Classroom 314	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None								
1	3	314A	Girl's Restroom adjacent to Classroom 314	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None								
1	3	314A	Girl's Restroom adjacent to Classroom 314	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None								
1	3	314A	Girl's Restroom adjacent to Classroom 314	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None								
1	3	314A	Girl's Restroom adjacent to Classroom 314	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None								
1	3	314A	Girl's Restroom adjacent to Classroom 314	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	314A	Girl's Restroom adjacent to Classroom 314	Yes	Door Frames	Metal	Brown	Friction	0	N/A	N/A	None								
1	3	314A	Girl's Restroom adjacent to Classroom 314	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A									
1	3	314C	Custodial Closet adjacent to Classroom 314	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	314C	Custodial Closet adjacent to Classroom 314	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	314C	Custodial Closet adjacent to Classroom 314	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	314C	Custodial Closet adjacent to Classroom 314	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	314C	Custodial Closet adjacent to Classroom 314	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A								

Element Floor Space #			School District of Philadelphia																
			Name of Inspector: Suzanne Shourds, Shalaunda Gourdine																
			Lead Safe Certification Assessment Report																
			Inspection Company: REPSG, Inc.																
			Edward T Steel Elementary School																
			ULCS# 6390																
			On-Site Room Name	Student/ Teacher Occupied (Yes/No)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	314C	Custodial Closet adjacent to Classroom 314	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	314C	Custodial Closet adjacent to Classroom 314	no	Door Frames	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	314B	Boy's Restroom adjacent to Classroom 314	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314B	Boy's Restroom adjacent to Classroom 314	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314B	Boy's Restroom adjacent to Classroom 314	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314B	Boy's Restroom adjacent to Classroom 314	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314B	Boy's Restroom adjacent to Classroom 314	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314B	Boy's Restroom adjacent to Classroom 314	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	314B	Boy's Restroom adjacent to Classroom 314	Yes	Door Frames	Metal	Brown	Friction	1										
1	3	314B	Boy's Restroom adjacent to Classroom 314	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A	None							
1	3	314	Classroom 314	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314	Classroom 314	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314	Classroom 314	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314	Classroom 314	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	314	Classroom 314	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	314	Classroom 314	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	314	Classroom 314	Yes	Door Frames	Metal	Brown	Friction	0	N/A	N/A	None							
1	3	314	Classroom 314	Yes	Kickplate	Ceramic	Black	None	0	N/A	N/A								
1	3	314	Classroom 314	Yes	Window Frames	Metal	Black	None	0	N/A	N/A	None							
1	3	314D	Classroom 314 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314D	Classroom 314 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314D	Classroom 314 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314D	Classroom 314 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314D	Classroom 314 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314D	Classroom 314 Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314D	Classroom 314 Closet	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	316	Storage Room 316	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	316	Storage Room 316	Yes	W2	Concrete	Beige	None	0	N/A	N/A	None							
1	3	316	Storage Room 316	Yes	W3	Sheetrock	Beige	None	0		0 Negative	None							
1	3	316	Storage Room 316	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	316	Storage Room 316	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							One missing ceiling tile
1	3	316	Storage Room 316	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	316	Storage Room 316	Yes	Door Frames	Metal	Brown	Friction	1										
1	3	324	Storage Room adjacent to Elevator	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	324	Storage Room adjacent to Elevator	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	324	Storage Room adjacent to Elevator	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	324	Storage Room adjacent to Elevator	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	324	Storage Room adjacent to Elevator	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	324	Storage Room adjacent to Elevator	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	324	Storage Room adjacent to Elevator	Yes	Door Frames	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	H26	Hallway from Classroom 304 to Office 316	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	H26	Hallway from Classroom 304 to Office 316	Yes	W2	Concrete	Beige	None	0		0 Negative	None							
1	3	H26	Hallway from Classroom 304 to Office 316	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	H26	Hallway from Classroom 304 to Office 316	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	H26	Hallway from Classroom 304 to Office 316	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	H26	Hallway from Classroom 304 to Office 316	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	H26	Hallway from Classroom 304 to Office 316	Yes	Door Frames	Metal	Brown	None	0	N/A	N/A	None							
1	3	H26	Hallway from Classroom 304 to Office 316	Yes	Kickplate	Ceramic	Black	None	0		1 Positive	None							Substrate is ceramic, high potential that lead content is related to substrate material, and not to surface level paint
1	3	S32	Stairwell adjacent to Office 316	Yes	W1	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S32	Stairwell adjacent to Office 316	Yes	W2	Concrete	Beige	None	0		0 Negative	None							
1	3	S32	Stairwell adjacent to Office 316	Yes	W3	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S32	Stairwell adjacent to Office 316	Yes	W4	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S32	Stairwell adjacent to Office 316	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	None							
1	3	S32	Stairwell adjacent to Office 316	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	3	S32	Stairwell adjacent to Office 316	Yes	Doors	Metal	Brown	Friction	1	0.44	Negative	None							
1	3	S32	Stairwell adjacent to Office 316	Yes	Door Frames	Metal	Brown	Friction	1	0.23	Negative	None							
1	3	S32	Stairwell adjacent to Office 316	Yes	Kickplate	Ceramic	Black	None	1		0 Negative	None							