

			<b>Inspection Dates: 09/13/2021-09/15/2021</b>		<b>School District of Philadelphia</b>					
			<b>Name of Inspector: Lionel Ray Wilson</b>		<b>Lead Safe Certification Assessment Report</b>					
			<b>Inspection Company: Viva EHS</b>		<b>Waring School</b>					
<b>ULCS#</b>	<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
2490	1	3	Hallway from Classrooms 305 to 308	W1	CMU Block Wall	White	None	N/A	0	Negative
2490	1	3	Hallway from Classrooms 305 to 308	W1	CMU Block Wall	Yellow	None	N/A	0	Negative
2490	1	3	Hallway from Classrooms 305 to 308	W2	CMU Block Wall	White	None	N/A	0	Negative
2490	1	3	Hallway from Classrooms 305 to 308	W2	CMU Block Wall	Yellow	None	N/A	0	Negative
2490	1	3	Hallway from Classrooms 305 to 308	W3	CMU Block Wall	White	Cracking	1	0	Negative
2490	1	3	Hallway from Classrooms 305 to 308	W3	CMU Block Wall	Yellow	None	N/A	0	Negative
2490	1	3	Hallway from Classrooms 305 to 308	W4	CMU Block Wall	White	Cracking	2	0	Negative
2490	1	3	Hallway from Classrooms 305 to 308	W4	CMU Block Wall	Yellow	None	N/A	0	Negative
2490	1	3	Hallway from Classrooms 305 to 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway from Classrooms 305 to 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway from Classrooms 305 to 308	Radiator	Metal	Blue	None	0	0.03	Negative
2490	1	3	Hallway at Stairwell C	W1	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell C	W2	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell C	W3	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell C	W4	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell C	Ceiling	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell C	Floor	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Stairwell C	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Stairwell C	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Stairwell C	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Stairwell C	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Stairwell C	Ceiling	Concrete	White	Cracking	1	0.05	Negative
2490	1	3	Stairwell C	Floor	Concrete	Grey	Cracking	1	0.01	Negative
2490	1	3	Stairwell C	Door	Metal	Brown	None	0	0.02	Negative
2490	1	3	Stairwell C	Door Casing	Metal	Brown	None	0	0.03	Negative
2490	1	3	Stairwell C	Handrail	Metal	Grey	Chipping	3	0.04	Negative
2490	1	3	IMC/Library 306/307	W1	Sheetrock	White	Chipping	1	0	Negative
2490	1	3	IMC/Library 306/307	W1	CMU Block Wall	White	Chipping	1	0	Negative
2490	1	3	IMC/Library 306/307	W2	CMU Block Wall	Multi	None	0	0.03	Negative
2490	1	3	IMC/Library 306/307	W2	Sheetrock	Multi	None	0	0.01	Negative
2490	1	3	IMC/Library 306/307	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	IMC/Library 306/307	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	3	IMC/Library 306/307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			<b>Inspection Dates: 09/13/2021-09/15/2021</b>	<b>School District of Philadelphia</b>						
			<b>Name of Inspector: Lionel Ray Wilson</b>	<b>Lead Safe Certification Assessment Report</b>						
			<b>Inspection Company: Viva EHS</b>	<b>Waring School</b>						
<b>ULCS#</b>	<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
2490	1	3	IMC/Library 306/307	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	IMC/Library 306/307	Radiator	Metal	White	Chipping	3	0.04	Negative
2490	1	3	IMC/Library 306/307	Lockers	Metal	Grey	None	0	0.01	Negative
2490	1	3	IMC/Library 306/307	Radiator	Metal	Grey	None	0	0.02	Negative
2490	1	3	Hallway at Stairwell D	W1	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell D	W2	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell D	W3	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell D	W4	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell D	Ceiling	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway at Stairwell D	Floor	Space is apart of H33	N/A	N/A	N/A	N/A	N/A
2490	1	3	Stairwell D	W1	CMU Block Wall	White	Chipping	1	0	Negative
2490	1	3	Stairwell D	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Stairwell D	W3	CMU Block Wall	White	Cracking	2	0	Negative
2490	1	3	Stairwell D	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Stairwell D	Ceiling	Concrete	White	Cracking	2	0.36	Negative
2490	1	3	Stairwell D	Floor	Concrete	Grey	None	0	0	Negative
2490	1	3	Stairwell D	Handrail	Metal	Grey	Chipping	2	0	Negative
2490	1	3	Stairwell D	Door Casing	Metal	Black	None	0	0	Negative
2490	1	3	Classroom 304	W1	CMU Block Wall	White	Chipping	2	0	Negative
2490	1	3	Classroom 304	W2	CMU Block Wall	White	Chipping	3	0	Negative
2490	1	3	Classroom 304	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Classroom 304	W4	CMU Block Wall	White	Chipping	2	0	Negative
2490	1	3	Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Classroom 304	Pipe	Metal	White	Chipping	5	0	Negative
2490	1	3	Classroom 304	Door Casing	Metal	Brown	None	None	0	Negative
2490	1	3	Classroom 304	Radiator	Metal	Brown	None	None	0.21	Negative
2490	1	3	Classroom 303	W1	CMU Block Wall	Blue	Cracking	3	0	Negative
2490	1	3	Classroom 303	W2	CMU Block Wall	Blue	None	0	0	Negative
2490	1	3	Classroom 303	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	1	3	Classroom 303	W4	CMU Block Wall	Blue	Chipping	2	0	Negative
2490	1	3	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	3	Classroom 303	Pipe	Metal	White	Chipping	10	0.23	Negative
2490	1	3	Classroom 303	Door Casing	Metal	Brown	None	None	0	Negative
2490	1	3	Classroom 303	Radiator	Metal	Grey	None	None	0	Negative
2490	1	3	Hallway from Classrooms 303 to 304	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Hallway from Classrooms 303 to 304	W1	CMU Block Wall	Yellow	None	0	0	Negative
2490	1	3	Hallway from Classrooms 303 to 304	W2	CMU Block Wall	White	Chipping	2	0.05	Negative
2490	1	3	Hallway from Classrooms 303 to 304	W2	CMU Block Wall	Yellow	None	0	0	Negative
2490	1	3	Hallway from Classrooms 303 to 304	W3	CMU Block Wall	White	Cracking	3	0.04	Negative
2490	1	3	Hallway from Classrooms 303 to 304	W3	CMU Block Wall	Yellow	None	0	0.02	Negative
2490	1	3	Hallway from Classrooms 303 to 304	W4	CMU Block Wall	White	Cracking	3	0.03	Negative
2490	1	3	Hallway from Classrooms 303 to 304	W4	CMU Block Wall	Yellow	None	0	0.01	Negative
2490	1	3	Hallway from Classrooms 303 to 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway from Classrooms 303 to 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Hallway from Classrooms 303 to 304	Radiator	Metal	Blue	Chipping	3	0.01	Negative
2490	1	3	Office 311	W1	CMU Block Wall	White	Chipping	1	0	Negative
2490	1	3	Office 311	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Office 311	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Office 311	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Office 311	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Office 311	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Office 311	Door Casing	Metal	Brown	Chipping	1	0	Negative
2490	1	3	Office 311	Radiator	Metal	Grey	None	0	0.13	Negative
2490	1	3	Custodial Closet adjacent to Office 311	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Custodial Closet adjacent to Office 311	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Custodial Closet adjacent to Office 311	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Custodial Closet adjacent to Office 311	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Custodial Closet adjacent to Office 311	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Custodial Closet adjacent to Office 311	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Custodial Closet adjacent to Office 311	Door Casing	Metal	White	Chipping	2	0.04	Negative
2490	1	3	Custodial Closet adjacent to Office 311	Duct Work	Metal	White	Chipping	10	0.03	Negative
2490	1	3	Custodial Closet adjacent to Office 311 Pipe Chase	W1	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Custodial Closet adjacent to Office 311 Pipe Chase	W2	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Custodial Closet adjacent to Office 311 Pipe Chase	W3	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Custodial Closet adjacent to Office 311 Pipe Chase	W4	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Custodial Closet adjacent to Office 311 Pipe Chase	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Custodial Closet adjacent to Office 311 Pipe Chase	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Girl's Restroom	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	1	3	Girl's Restroom	W2	CMU Block Wall	Blue	None	0	0	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	3	Girl's Restroom	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	1	3	Girl's Restroom	W4	CMU Block Wall	Blue	None	0	0	Negative
2490	1	3	Girl's Restroom	W1	CMU Block Wall	Purple	None	0	0	Negative
2490	1	3	Girl's Restroom	W2	CMU Block Wall	Purple	None	0	0	Negative
2490	1	3	Girl's Restroom	W3	CMU Block Wall	Purple	None	0	0	Negative
2490	1	3	Girl's Restroom	W4	CMU Block Wall	Purple	None	0	0	Negative
2490	1	3	Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Girl's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Girl's Restroom	Door	Wood	Blue	Chipping	2	0.01	Negative
2490	1	3	Girl's Restroom	Door Casing	Metal	Silver	Chipping	3	0.04	Negative
2490	2	3	Classroom 302	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	2	3	Classroom 302	W2	CMU Block Wall	Blue	None	0	0	Negative
2490	2	3	Classroom 302	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	2	3	Classroom 302	W4	CMU Block Wall	Blue	Chipping	1	0	Negative
2490	2	3	Classroom 302	Ceiling	Concrete	White	Chipping	1	0.04	Negative
2490	2	3	Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	3	Classroom 302	Radiator	Metal	Grey	Chipping	10	0.12	Negative
2490	2	3	Classroom 302	Door	Wood	Green	None	0	0	Negative
2490	2	3	Classroom 302	Door Casing	Metal	Tan	Chipping	15	0.03	Negative
2490	2	3	Boy's Restroom	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Boy's Restroom	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Boy's Restroom	W3	Concrete	White	Chipping	5	0	Negative
2490	2	3	Boy's Restroom	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Boy's Restroom	W1	CMU Block Wall	Purple	None	0	0	Negative
2490	2	3	Boy's Restroom	W2	CMU Block Wall	Purple	None	0	0	Negative
2490	2	3	Boy's Restroom	W3	Concrete	Purple	Chipping	5	0	Negative
2490	2	3	Boy's Restroom	W4	CMU Block Wall	Purple	None	0	0.01	Negative
2490	2	3	Boy's Restroom	Ceiling	Concrete	White	None	0	0	N/A
2490	2	3	Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	2	3	Boy's Restroom	Radiator	Metal	White	None	0	0.02	Negative
2490	2	3	Boy's Restroom	Door	Wood	Grey	Chipping	10	0	Negative
2490	2	3	Boy's Restroom	Door Casing	Metal	Grey	Chipping	4	0.02	Negative
2490	2	3	Women's Restroom	W1	CMU Block Wall	White	None	0	0.05	Negative
2490	2	3	Women's Restroom	W2	CMU Block Wall	White	None	0	0.02	Negative
2490	2	3	Women's Restroom	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Women's Restroom	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Women's Restroom	W1	CMU Block Wall	Purple	None	0	0.03	Negative
2490	2	3	Women's Restroom	W2	CMU Block Wall	Purple	Chipping	1	0.1	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	2	3	Women's Restroom	W3	CMU Block Wall	Purple	Chipping	1	0	Negative
2490	2	3	Women's Restroom	W4	CMU Block Wall	Purple	None	0	0.01	Negative
2490	2	3	Women's Restroom	Ceiling	Concrete	White	None	0	0.12	Negative
2490	2	3	Women's Restroom	Floor	Concrete	Brown	Chipping	4	0	Negative
2490	2	3	Hallway between Classrooms 301 and 302	W1	Space is apart of H31	N/A	N/A	N/A	N/A	N/A
2490	2	3	Hallway between Classrooms 301 and 302	W2	Space is apart of H31	N/A	N/A	N/A	N/A	N/A
2490	2	3	Hallway between Classrooms 301 and 302	W3	Space is apart of H31	N/A	N/A	N/A	N/A	N/A
2490	2	3	Hallway between Classrooms 301 and 302	W4	Space is apart of H31	N/A	N/A	N/A	N/A	N/A
2490	2	3	Hallway between Classrooms 301 and 302	Ceiling	Space is apart of H31	N/A	N/A	N/A	N/A	N/A
2490	2	3	Hallway between Classrooms 301 and 302	Floor	Space is apart of H31	N/A	N/A	N/A	N/A	N/A
2490	2	3	Stairwell F	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Stairwell F	W2	CMU Block Wall	Multi	Cracking	1	0	Negative
2490	2	3	Stairwell F	W3	CMU Block Wall	Blue	Cracking	3	0	Negative
2490	2	3	Stairwell F	W4	CMU Block Wall	Multi	None	0	0.01	Negative
2490	2	3	Stairwell F	Ceiling	Concrete	White	None	0	0.02	Negative
2490	2	3	Stairwell F	Floor	Concrete	Grey	None	0	0.04	Negative
2490	2	3	Stairwell F	Pipe	Metal	White	Chipping	5	0.9	Positive
2490	2	3	Stairwell F	Handrail	Metal	Grey	Chipping	15	0.09	Negative
2490	2	3	Stairwell F	Door	Metal	Brown	Chipping	1	0.09	Negative
2490	2	3	Stairwell F	Door Casing	Metal	Brown	None	0	0.02	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W1	Brick Wall	White	None	0	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W1	CMU Block Wall	White	Cracking	2	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W1	Brick Wall	Purple	None	0	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W1	CMU Block Wall	Purple	None	0	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W2	CMU Block Wall	Purple	Cracking	2	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W3	CMU Block Wall	Purple	None	0	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	W4	CMU Block Wall	Purple	Cracking	2	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	Ceiling	Concrete	White	Chipping	25	0.07	Negative
2490	2	2	Boy's Restroom across from Stairwell F	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	2	2	Boy's Restroom across from Stairwell F	Pipe	Metal	White	Chipping	5	0.1	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	2	2	Boy's Restroom across from Stairwell F	Door	Wood	Grey	Chipping	10	0	Negative
2490	2	2	Boy's Restroom across from Stairwell F	Door Casing	Metal	Grey	Chipping	4	0.03	Negative
2490	2	2	Boy's Restroom across from Stairwell F	Radiator	Metal	White	Chipping	4	0.1	Negative
2490	2	2	Women's Restroom across from Computer Room 201	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Women's Restroom across from Computer Room 201	W2	CMU Block Wall	White	None	0	0.06	Negative
2490	2	2	Women's Restroom across from Computer Room 201	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Women's Restroom across from Computer Room 201	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Women's Restroom across from Computer Room 201	Ceiling	Concrete	White	None	0	0.05	Negative
2490	2	2	Women's Restroom across from Computer Room 201	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	2	2	Women's Restroom across from Computer Room 201	Door Casing	Metal	Green	None	0	0	Negative
2490	2	2	Classroom 202	W1	CMU Block Wall	Blue	Chipping	3	0	Negative
2490	2	2	Classroom 202	W2	CMU Block Wall	Blue	None	0	0	Negative
2490	2	2	Classroom 202	W3	Concrete	Blue	None	0	0	Negative
2490	2	2	Classroom 202	W4	CMU Block Wall	Blue	Cracking	2	0	Negative
2490	2	2	Classroom 202	Ceiling	Concrete	White	None	0	0.01	Negative
2490	2	2	Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	2	Classroom 202	Door	Wood	Grey	None	0	0	Negative
2490	2	2	Classroom 202	Door Casing	Metal	Blue	Chipping	1	0.04	Negative
2490	2	2	Classroom 202	Pipe	Metal	White	Chipping	3	0.03	Negative
2490	2	2	Classroom 202	Radiator	Metal	Grey	None	0	0.09	Negative
2490	1	2	Girl's Restroom adjacent to Stairwell F	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Girl's Restroom adjacent to Stairwell F	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Girl's Restroom adjacent to Stairwell F	W3	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	2	Girl's Restroom adjacent to Stairwell F	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Girl's Restroom adjacent to Stairwell F	Ceiling	Concrete	White	Chipping	15	0.11	Negative
2490	1	2	Girl's Restroom adjacent to Stairwell F	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Girl's Restroom adjacent to Stairwell F	Door	Wood	Grey	Chipping	3	0	Negative
2490	1	2	Girl's Restroom adjacent to Stairwell F	Floor	Metal	Purple	None	0	0.08	Negative
2490	1	2	Girl's Restroom adjacent to Stairwell F	Radiator	Metal	White	None	0	0	Negative
2490	1	2	Girl's Restroom adjacent to Stairwell F	Pipe	Metal	White	None	0	0.16	Negative
2490	1	2	Stairwell F	W1	CMU Block Wall	White	Cracking	1	0	Negative
2490	1	2	Stairwell F	W2	CMU Block Wall	Multi	Cracking	3	0	Negative
2490	1	2	Stairwell F	W3	CMU Block Wall	Multi	Cracking	1	0	Negative
2490	1	2	Stairwell F	W4	Brick Wall	Multi	Chipping	5	0	Negative
2490	1	2	Stairwell F	W4	CMU Block Wall	Multi	Chipping	5	0	Negative
2490	1	2	Stairwell F	Ceiling	Concrete	White	Chipping	3	0.02	Negative
2490	1	2	Stairwell F	Floor	Concrete	Grey	None	0	0	Negative
2490	1	2	Stairwell F	Pipe	Metal	White	Chipping	3	0.4	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	2	Stairwell F	Door	Metal	Brown	Chipping	1	0.06	Negative
2490	1	2	Stairwell F	Handrail	Metal	Grey	Chipping	6	0.16	Negative
2490	1	2	Stairwell F	Tread	Concrete	Grey	None	0	0	Negative
2490	1	2	Custodial Closet adjacent to Dining Room	W1	CMU Block Wall	White	Chipping	2	0	Negative
2490	1	2	Custodial Closet adjacent to Dining Room	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Custodial Closet adjacent to Dining Room	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Custodial Closet adjacent to Dining Room	W4	CMU Block Wall	White	Chipping	2	0	Negative
2490	1	2	Custodial Closet adjacent to Dining Room	Ceiling	Concrete	White	None	0	0	Negative
2490	1	2	Custodial Closet adjacent to Dining Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Custodial Closet adjacent to Dining Room	Duct Work	Metal	White	Flaking	15	0	Negative
2490	1	2	Custodial Closet adjacent to Dining Room	Door Casing	Metal	Grey	Chipping	10	0.11	Negative
2490	1	2	Custodial Closet adjacent to Dining Room Pipe Chase	W1	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Custodial Closet adjacent to Dining Room Pipe Chase	W2	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Custodial Closet adjacent to Dining Room Pipe Chase	W3	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Custodial Closet adjacent to Dining Room Pipe Chase	W4	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Custodial Closet adjacent to Dining Room Pipe Chase	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Custodial Closet adjacent to Dining Room Pipe Chase	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Dining Room	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	1	2	Dining Room	W2	CMU Block Wall	Green	None	0	0	Negative
2490	1	2	Dining Room	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	1	2	Dining Room	W4	CMU Block Wall	Blue	None	0	0	Negative
2490	1	2	Dining Room	Ceiling	Concrete	White	None	0	0	Negative
2490	1	2	Dining Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Dining Room	Door Casing	Metal	Grey	Chipping	2	0.18	Negative
2490	1	2	Dining Room	Radiator	Metal	Grey	Chipping	3	0	Negative
2490	1	2	Dining Room	Pipe	Metal	White	None	0	0.03	Negative
2490	1	2	Stairwell D Hallway	W1	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Stairwell D Hallway	W2	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Stairwell D Hallway	W3	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Stairwell D Hallway	W4	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Stairwell D Hallway	Ceiling	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Stairwell D Hallway	Floor	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Stairwell D	W1	CMU Block Wall	White	Chipping	5	0	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	2	Stairwell D	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Stairwell D	W3	CMU Block Wall	White	Chipping	5	0	Negative
2490	1	2	Stairwell D	W4	CMU Block Wall	White	Chipping	5	0	Negative
2490	1	2	Stairwell D	Ceiling	Concrete	White	None	0	0	Negative
2490	1	2	Stairwell D	Floor	Concrete	Grey	None	0	0	Negative
2490	1	2	Stairwell D	Handrail	Metal	Grey	Chipping	4	0.09	Negative
2490	1	2	Stairwell D	Door Casing	Metal	Brown	Chipping	1	0.15	Negative
2490	1	2	Hallway from Classrooms 203 to 204	W1	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Hallway from Classrooms 203 to 204	W2	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Hallway from Classrooms 203 to 204	W3	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Hallway from Classrooms 203 to 204	W4	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Hallway from Classrooms 203 to 204	Ceiling	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Hallway from Classrooms 203 to 204	Floor	Space is apart of H15	N/A	N/A	N/A	N/A	N/A
2490	1	2	Classroom 205	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Classroom 205	W2	CMU Block Wall	White	Chipping	4	0	Negative
2490	1	2	Classroom 205	W3	CMU Block Wall	White	Chipping	1	0.01	Negative
2490	1	2	Classroom 205	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Classroom 205	Ceiling	Concrete	White	None	0	0.05	Negative
2490	1	2	Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Classroom 205	Radiator	Metal	Grey	None	0	0.07	Negative
2490	1	2	Classroom 205	Door Casing	Metal	Grey	Chipping	1	0.22	Negative
2490	1	2	Classroom 205	Pipe	Metal	White	None	0	0	Negative
2490	1	2	Classroom 206	W1	CMU Block Wall	White	Cracking	1	0	Negative
2490	1	2	Classroom 206	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Classroom 206	W3	Concrete	White	Chipping	3	0	Negative
2490	1	2	Classroom 206	W4	Wood Partition	Brown	None	0	0	Negative
2490	1	2	Classroom 206	Ceiling	Concrete	White	None	0	0.04	Negative
2490	1	2	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Classroom 206	Door Casing	Metal	Grey	None	0	0.03	Negative
2490	1	2	Classroom 207	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Classroom 207	W2	Wood Partition	Blue	None	0	0	Negative
2490	1	2	Classroom 207	W3	Concrete	White	None	0	0	Negative
2490	1	2	Classroom 207	W4	CMU Block Wall	White	None	0	0	Negative



			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	2	Classroom 207	Ceiling	Concrete	White	None	0	0	Negative
2490	1	2	Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Classroom 207	Radiator	Metal	Green	None	0	0.02	Negative
2490	1	2	Classroom 207	Door	Wood	Green	None	0	0	Negative
2490	1	2	Classroom 207	Door Casing	Metal	Green	None	0	0.13	Negative
2490	1	2	Classroom 207	Pipe	Metal	White	None	0	0.02	Negative
2490	1	2	Hallway from Classrooms 205 to 208	W1	CMU Block Wall	White	None	0	0.01	Negative
2490	1	2	Hallway from Classrooms 205 to 208	W2	CMU Block Wall	White	None	0	0.01	Negative
2490	1	2	Hallway from Classrooms 205 to 208	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Hallway from Classrooms 205 to 208	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Hallway from Classrooms 205 to 208	W1	CMU Block Wall	Purple	None	0	0.04	Negative
2490	1	2	Hallway from Classrooms 205 to 208	W2	CMU Block Wall	Purple	None	0	0.03	Negative
2490	1	2	Hallway from Classrooms 205 to 208	W3	CMU Block Wall	Purple	None	0	0	Negative
2490	1	2	Hallway from Classrooms 205 to 208	W4	CMU Block Wall	Purple	None	0	0	Negative
2490	1	2	Hallway from Classrooms 205 to 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Hallway from Classrooms 205 to 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Stairs adjacent Classroom 108	W1	Ceramic Tile Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Stairs adjacent Classroom 108	W2	Ceramic Tile Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Stairs adjacent Classroom 108	W3	Ceramic Tile Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Stairs adjacent Classroom 108	W4	Ceramic Tile Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Stairs adjacent Classroom 108	Ceiling	Concrete	White	Chipping	20	0.5	Negative
2490	1	1	Stairs adjacent Classroom 108	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Stairs adjacent Classroom 108	Handrail	Metal	Grey	Chipping	4	0.01	Negative
2490	1	1	Stairs adjacent Classroom 108	Radiator	Metal	Tan	Chipping	1	0.08	Negative
2490	1	1	Classroom 107	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	1	1	Classroom 107	W2	Wood Partition	Blue	None	0	0	Negative
2490	1	1	Classroom 107	W3	Concrete	Blue	None	0	0	Negative
2490	1	1	Classroom 107	W4	CMU Block Wall	Blue	None	0	0	Negative
2490	1	1	Classroom 107	Ceiling	Concrete	White	None	0	0.03	Negative
2490	1	1	Classroom 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Classroom 107	Door	Wood	Blue	None	0	0	Negative
2490	1	1	Classroom 107	Door Casing	Metal	Grey	Chipping	2	0.13	Negative
2490	1	1	Classroom 107	Radiator	Metal	Purple	None	0	0.05	Negative
2490	1	1	Classroom 106	W1	CMU Block Wall	Blue	Cracking	1	0	Negative
2490	1	1	Classroom 106	W2	CMU Block Wall	Blue	Chipping	2	0.01	Negative
2490	1	1	Classroom 106	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	1	1	Classroom 106	W4	Wood Partition	Blue	None	0	0	Negative
2490	1	1	Classroom 106	Ceiling	Concrete	White	Chipping	3	0.25	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	1	Classroom 106	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Classroom 106	Radiator	Metal	Grey	Chipping	5	0.07	Negative
2490	1	1	Classroom 106	Door Casing	Metal	Grey	Chipping	1	0.07	Negative
2490	1	1	Classroom 105	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	1	1	Classroom 105	W2	CMU Block Wall	Blue	None	0	0	Negative
2490	1	1	Classroom 105	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	1	1	Classroom 105	W4	CMU Block Wall	Blue	None	0	0	Negative
2490	1	1	Classroom 105	Ceiling	Concrete	White	None	0	0.06	Negative
2490	1	1	Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Classroom 105	Door Casing	Metal	Grey	Chipping	5	0.13	Negative
2490	1	1	Classroom 105	Radiator	Metal	Grey	Chipping	8	0	Negative
2490	1	1	1st Floor Stairwell D	W1	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell D	W2	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell D	W3	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell D	W4	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell D	Ceiling	Concrete	White	Chipping	5	0.07	Negative
2490	1	1	1st Floor Stairwell D	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell D	Door Casing	Metal	Grey	Chipping	3	0.16	Negative
2490	1	1	1st Floor Stairwell D	Door	Metal	Brown	Chipping	10	0	Negative
2490	1	1	1st Floor Stairwell D	Handrail	Metal	Grey	Chipping	2	0	Negative
2490	1	1	1st Floor Stairwell D	Radiator	Metal	Grey	None	0	0.06	Negative
2490	1	1	1st Floor Stairwell D	Stair Tread	Concrete	Grey	None	0	0	Negative
2490	1	1	Stairs at Main Entrance	W1	Concrete	Multi	None	0	0	Negative
2490	1	1	Stairs at Main Entrance	W1	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	Stairs at Main Entrance	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Stairs at Main Entrance	W3	Concrete	Multi	None	0	0.04	Negative
2490	1	1	Stairs at Main Entrance	W3	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	Stairs at Main Entrance	W4	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Stairs at Main Entrance	Ceiling	Concrete	White	None	0	No Access	No Access
2490	1	1	Stairs at Main Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Stairs at Main Entrance	Door	Metal	Tan	Chipping	5	0	Negative
2490	1	1	Stairs at Main Entrance	Door Casing	Metal	Tan	Chipping	4	0	Negative
2490	1	1	Stairs at Main Entrance	Radiator	Metal	Pink	None	0	0.04	Negative
2490	1	1	Custodial Closet Outside of the Main Office	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Custodial Closet Outside of the Main Office	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Custodial Closet Outside of the Main Office	W3	CMU Block Wall	White	Cracking	10	0	Negative
2490	1	1	Custodial Closet Outside of the Main Office	W4	CMU Block Wall	White	Cracking	4	0	Negative
2490	1	1	Custodial Closet Outside of the Main Office	Ceiling	Concrete	White	Chipping	2	0.08	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	1	Custodial Closet Outside of the Main Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Custodial Closet Outside of the Main Office	Door	Wood	Blue	Chipping	10	0.01	Negative
2490	1	1	Custodial Closet Outside of the Main Office	Door Casing	Metal	Blue	Chipping	5	0.04	Negative
2490	1	1	Custodial Closet Outside of the Main Office	Pipe	Metal	White	Chipping	10	0.3	Negative
2490	1	1	Main Office	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Main Office	W1	Sheetrock	White	None	0	0	Negative
2490	1	1	Main Office	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Main Office	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Main Office	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Main Office	Ceiling	Concrete	White	None	0	0.14	Negative
2490	1	1	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Main Office	Door	Wood	Tan	None	0	0	Negative
2490	1	1	Main Office	Door Casing	Metal	Tan	None	0	0.18	Negative
2490	1	1	Main Office Small Closet	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Main Office Small Closet	W2	CMU Block Wall	White	Cracking	5	0	Negative
2490	1	1	Main Office Small Closet	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Main Office Small Closet	W4	CMU Block Wall	White	Cracking	5	0	Negative
2490	1	1	Main Office Small Closet	Ceiling	Concrete	White	None	0	0.06	Negative
2490	1	1	Main Office Small Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Main Office Small Closet	Duct Work	Metal	White	Chipping	8	0.11	Negative
2490	1	1	Nurse's Office	W1	CMU Block Wall	White	Cracking	5	0	Negative
2490	1	1	Nurse's Office	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Nurse's Office	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Nurse's Office	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Nurse's Office	Ceiling	Concrete	White	None	0	0.07	Negative
2490	1	1	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Nurse's Office	Radiator	Metal	Tan	None	0	0.03	Negative
2490	1	1	Nurse's Office	Pipe	Metal	White	Chipping	4	0.06	Negative
2490	1	1	Nurse's Office Restroom	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Nurse's Office Restroom	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Nurse's Office Restroom	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Nurse's Office Restroom	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Nurse's Office Restroom	Ceiling	Concrete	White	None	0	0.1	Negative
2490	1	1	Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Nurse's Office closet at the door	W1	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Nurse's Office closet at the door	W2	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Nurse's Office closet at the door	W3	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Nurse's Office closet at the door	W4	No Access	No Access	No Access	No Access	No Access	No Access

			<b>Inspection Dates: 09/13/2021-09/15/2021</b>	<b>School District of Philadelphia</b>						
			<b>Name of Inspector: Lionel Ray Wilson</b>	<b>Lead Safe Certification Assessment Report</b>						
			<b>Inspection Company: Viva EHS</b>	<b>Waring School</b>						
<b>ULCS#</b>	<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
2490	1	1	Nurse's Office closet at the door	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Nurse's Office closet at the door	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Principal's Office	W1	CMU Block Wall	Purple	Cracking	1	0	Negative
2490	1	1	Principal's Office	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Principal's Office	W3	CMU Block Wall	Purple	None	0	0	Negative
2490	1	1	Principal's Office	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Principal's Office	W4	CMU Block Wall	Purple	Cracking	6	0	Negative
2490	1	1	Principal's Office	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Principal's Office	Ceiling	Concrete	White	Cracking	2	0.33	Negative
2490	1	1	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Principal's Office	Radiator	Metal	Pink	None	0	0.1	Negative
2490	1	1	Principal's Office	Door Casing	Metal	Pink	None	0	0.09	Negative
2490	1	1	Principal's Restroom	W1	CMU Block Wall	Tan	Efflorescence	3	0	Negative
2490	1	1	Principal's Restroom	W2	CMU Block Wall	Tan	Cracking	2	0	Negative
2490	1	1	Principal's Restroom	W3	CMU Block Wall	Tan	Cracking	1	0	Negative
2490	1	1	Principal's Restroom	W4	CMU Block Wall	Tan	Cracking	3	0	Negative
2490	1	1	Principal's Restroom	Ceiling	Concrete	White	None	0	0.2	Negative
2490	1	1	Principal's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Women's Restroom adjacent to Main Office	W1	CMU Block Wall	Purple	None	0	0	Negative
2490	1	1	Women's Restroom adjacent to Main Office	W2	CMU Block Wall	Purple	None	0	0	Negative
2490	1	1	Women's Restroom adjacent to Main Office	W3	CMU Block Wall	Purple	None	0	0	Negative
2490	1	1	Women's Restroom adjacent to Main Office	W4	CMU Block Wall	Purple	None	0	0	Negative
2490	1	1	Women's Restroom adjacent to Main Office	Ceiling	Concrete	White	None	0	0.09	Negative
2490	1	1	Women's Restroom adjacent to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Women's Restroom adjacent to Main Office	Door Casing	Metal	Blue	None	0	0.11	Negative
2490	1	1	Classroom 103	W1	CMU Block Wall	Grey	None	0	0	Negative
2490	1	1	Classroom 103	W2	CMU Block Wall	Grey	None	0	0	Negative
2490	1	1	Classroom 103	W3	CMU Block Wall	Grey	None	0	0	Negative
2490	1	1	Classroom 103	W4	CMU Block Wall	Grey	None	0	0	Negative
2490	1	1	Classroom 103	W4	Concrete	White	Chipping	3	0	Negative
2490	1	1	Classroom 103	Ceiling	Concrete	White	None	0	0.04	Negative
2490	1	1	Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Classroom 103	Radiator	Metal	Grey	Chipping	2	0.04	Negative
2490	1	1	Classroom 103	Door Casing	Metal	Grey	Chipping	4	0.16	Negative
2490	1	1	Classroom 103	Door	Wood	Black	None	0	0	Negative
2490	1	1	Classroom 103	Pipe	Metal	Blue	None	0	0.07	Negative
2490	1	1	Classroom 103 Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Classroom 103 Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	1	Classroom 103 Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Classroom 103 Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Classroom 103 Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Classroom 103 Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Boy's Restroom adjacent to Stairwell F	W1	CMU Block Wall	White	Cracking	1	0	Negative
2490	1	1	Boy's Restroom adjacent to Stairwell F	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Boy's Restroom adjacent to Stairwell F	W3	CMU Block Wall	White	Cracking	2	0	Negative
2490	1	1	Boy's Restroom adjacent to Stairwell F	W4	CMU Block Wall	White	Cracking	4	0	Negative
2490	1	1	Boy's Restroom adjacent to Stairwell F	Ceiling	Concrete	White	None	0	0.12	Negative
2490	1	1	Boy's Restroom adjacent to Stairwell F	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Boy's Restroom adjacent to Stairwell F	Door	Wood	Grey	Chipping	4	0	Negative
2490	1	1	Boy's Restroom adjacent to Stairwell F	Door Casing	Metal	Grey	Chipping	7	0.01	Negative
2490	1	1	Boy's Restroom adjacent to Stairwell F	Pipe	Metal	White	Chipping	1	0.15	Negative
2490	1	1	1st Floor Stairwell F	W1	CMU Block Wall	White	Cracking	1	0	Negative
2490	1	1	1st Floor Stairwell F	W2	CMU Block Wall	Multi	Cracking	1	0	Negative
2490	1	1	1st Floor Stairwell F	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	1st Floor Stairwell F	W4	CMU Block Wall	White	Chipping	10	0	Negative
2490	1	1	1st Floor Stairwell F	Ceiling	Concrete	White	Chipping	10	0.01	Negative
2490	1	1	1st Floor Stairwell F	Floor	Concrete	Grey	None	0	0	Negative
2490	1	1	1st Floor Stairwell F	Pipe	Metal	White	Chipping	2	0.8	Positive
2490	1	1	1st Floor Stairwell F	Radiator	Metal	Grey	Chipping	2	0	Negative
2490	1	1	1st Floor Stairwell F	Door	Metal	Grey	Chipping	8	0.13	Negative
2490	1	1	1st Floor Stairwell F	Handrail	Metal	Grey	None	0	0	Negative
2490	1	1	1st Floor Stairwell F	Door Casing	Metal	Grey	Chipping	1	0.04	Negative
2490	1	1	1st Floor Stairwell C	W1	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell C	W2	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell C	W3	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell C	W4	Ceramic Tile Wall	N/A	N/A	N/A	N/A	N/A
2490	1	1	1st Floor Stairwell C	Ceiling	Concrete	White	Chipping	5	0.3	Negative
2490	1	1	1st Floor Stairwell C	Floor	Concrete	Grey	Chipping	3	0.08	Negative
2490	1	1	1st Floor Stairwell C	Radiator	Metal	Grey	Chipping	5	0.01	Negative
2490	1	1	1st Floor Stairwell C	Handrail	Metal	Grey	Chipping	2	0.4	Negative
2490	1	1	1st Floor Stairwell C	Stair Tread	Concrete	Grey	None	0	0.04	Negative
2490	1	1	1st Floor Stairwell C	Door	Metal	Brown	Chipping	2	0	Negative
2490	1	1	1st Floor Stairwell C	Door Casing	Metal	Brown	Chipping	5	0	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	W1	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Hallway from Main Entrance to Classroom 103	W2	CMU Block Wall	White	Cracking	3	0.07	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	W3	CMU Block Wall	White	None	0	0.03	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	1	Hallway from Main Entrance to Classroom 103	W4	CMU Block Wall	White	Cracking	3	0.05	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	W2	CMU Block Wall	Pink	None	0	0.11	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	W3	CMU Block Wall	Pink	None	0	0.05	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	W4	CMU Block Wall	Pink	None	0	0.07	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	Ceiling	Concrete	White	Chipping	10	0.04	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Hallway from Main Entrance to Classroom 103	Door	Metal	Grey	Chipping	10	0.02	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	Door Casing	Metal	Grey	Chipping	1	0.06	Negative
2490	1	1	Hallway from Main Entrance to Classroom 103	USPS Mailbox	Metal	Blue	None	0	0.05	Negative
2490	2	1	Men's Restroom adjacent to School Store	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	1	Men's Restroom adjacent to School Store	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	1	Men's Restroom adjacent to School Store	W2	Brick Wall	White	None	0	0	Negative
2490	2	1	Men's Restroom adjacent to School Store	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	1	Men's Restroom adjacent to School Store	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	1	Men's Restroom adjacent to School Store	Ceiling	Concrete	White	None	0	0.05	Negative
2490	2	1	Men's Restroom adjacent to School Store	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	2	1	Men's Restroom adjacent to School Store	Door Casing	Metal	Grey	None	0	0.01	Negative
2490	2	1	Music Room 102	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	2	1	Music Room 102	W2	CMU Block Wall	Blue	Cracking	2	0	Negative
2490	2	1	Music Room 102	W3	Concrete	Blue	None	0	0	Negative
2490	2	1	Music Room 102	W4	CMU Block Wall	Blue	Cracking	2	0	Negative
2490	2	1	Music Room 102	Ceiling	Concrete	White	Chipping	1	0	Negative
2490	2	1	Music Room 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	1	Music Room 102	Pipe	Metal	White	None	0	0.03	Negative
2490	2	1	Music Room 102	Radiator	Metal	Red	Chipping	10	0.11	Negative
2490	2	1	Music Room 102	Door Casing	Metal	Blue	Chipping	1	0.04	Negative
2490	2	1	Music Room 102	Lockers	Metal	Blue	None	0	0.02	Negative
2490	2	1	Music Room 102 Restroom	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	2	1	Music Room 102 Restroom	W2	CMU Block Wall	Blue	Cracking	2	0	Negative
2490	2	1	Music Room 102 Restroom	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	2	1	Music Room 102 Restroom	W4	CMU Block Wall	Blue	None	0	0	Negative
2490	2	1	Music Room 102 Restroom	Ceiling	Concrete	White	Efflorescence	15	0	Negative
2490	2	1	Music Room 102 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	1	Music Room 102 Restroom	Door	Wood	Red	None	0	0	Negative
2490	2	1	Music Room 102 Restroom	Door Casing	Metal	Blue	Chipping	3	0.04	Negative
2490	2	1	Music Room 102 Restroom	Radiator	Metal	Blue	None	0	0.06	Negative
2490	2	1	Music Room 102 Restroom	Pipe	Metal	White	None	0	0.01	Negative
2490	2	1	School Store	W1	CMU Block Wall	Yellow	None	0	0	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	2	1	School Store	W2	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	1	School Store	W3	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	1	School Store	W4	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	1	School Store	Ceiling	Concrete	White	Moisture Damage	10	0.09	Negative
2490	2	1	School Store	Floor	Concrete	Blue	Chipping	20	0	Negative
2490	2	1	School Store	Door	Wood	Blue	None	0	0	Negative
2490	2	1	School Store	Door Casing	Metal	Yellow	None	0	0	Negative
2490	2	1	School Store	Book Shelving	Metal	Grey	Chipping	1	0.02	Negative
2490	2	1	School Store	Duct Work	Metal	Grey	Moisture Damage	10	0.04	Negative
2490	2	1	Entrance/Exit Foyer	W1	Duplicate of S14	N/A	N/A	N/A	N/A	N/A
2490	2	1	Entrance/Exit Foyer	W2	Duplicate of S14	N/A	N/A	N/A	N/A	N/A
2490	2	1	Entrance/Exit Foyer	W3	Duplicate of S14	N/A	N/A	N/A	N/A	N/A
2490	2	1	Entrance/Exit Foyer	W4	Duplicate of S14	N/A	N/A	N/A	N/A	N/A
2490	2	1	Entrance/Exit Foyer	Ceiling	Duplicate of S14	N/A	N/A	N/A	N/A	N/A
2490	2	1	Entrance/Exit Foyer	Floor	Duplicate of S14	N/A	N/A	N/A	N/A	N/A
2490	2	1	Classroom 101	W1	CMU Block Wall	Yellow	Chipping	3	0.08	Negative
2490	2	1	Classroom 101	W1	CMU Block Wall	White	None	0	0.01	Negative
2490	2	1	Classroom 101	W2	CMU Block Wall	Blue	None	0	0.03	Negative
2490	2	1	Classroom 101	W3	CMU Block Wall	White	Chipping	15	0.02	Negative
2490	2	1	Classroom 101	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	1	Classroom 101	Ceiling	Concrete	White	Chipping	35	0.03	Negative
2490	2	1	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	1	Classroom 101	Radiator	Metal	Black	None	0	0.4	Negative
2490	2	1	Classroom 101	Door Casing	Metal	Blue	Chipping	3	0.02	Negative
2490	2	1	Classroom 101	Lockers	Metal	Grey	Chipping	2	0.02	Negative
2490	2	1	Classroom 101	Pipe	Metal	White	None	0	0.04	Negative
2490	2	1	Classroom 101 Restroom	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	1	Classroom 101 Restroom	W2	CMU Block Wall	White	Flaking	5	0	Negative
2490	2	1	Classroom 101 Restroom	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	1	Classroom 101 Restroom	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	1	Classroom 101 Restroom	Ceiling	Concrete	White	None	0	0.03	Negative
2490	2	1	Classroom 101 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	1	Classroom 101 Restroom	Pipe	Metal	White	None	0	0.01	Negative
2490	2	1	Classroom 101 Restroom	Door Casing	Metal	White	Chipping	5	0.15	Negative
2490	2	1	Hallway between Classrooms 101 and 102	W1	Duplicate of H11	N/A	N/A	N/A	N/A	N/A
2490	2	1	Hallway between Classrooms 101 and 102	W2	Duplicate of H11	N/A	N/A	N/A	N/A	N/A
2490	2	1	Hallway between Classrooms 101 and 102	W3	Duplicate of H11	N/A	N/A	N/A	N/A	N/A
2490	2	1	Hallway between Classrooms 101 and 102	W4	Duplicate of H11	N/A	N/A	N/A	N/A	N/A

			<b>Inspection Dates: 09/13/2021-09/15/2021</b>		<b>School District of Philadelphia</b>					
			<b>Name of Inspector: Lionel Ray Wilson</b>		<b>Lead Safe Certification Assessment Report</b>					
			<b>Inspection Company: Viva EHS</b>		<b>Waring School</b>					
<b>ULCS#</b>	<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
2490	2	1	Hallway between Classrooms 101 and 102	Ceiling	Duplicate of H11	N/A	N/A	N/A	N/A	N/A
2490	2	1	Hallway between Classrooms 101 and 102	Floor	Duplicate of H11	N/A	N/A	N/A	N/A	N/A
2490	1	3	Men's Restroom	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Men's Restroom	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Men's Restroom	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Men's Restroom	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Men's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Men's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	3	Men's Restroom	Pipe	Metal	White	None	None	0.09	Negative
2490	1	3	Men's Restroom	Radiator	Metal	White	None	None	0	Negative
2490	1	3	Classroom 305	W1	CMU Block Wall	White	Chipping	1	0	Negative
2490	1	3	Classroom 305	W2	CMU Block Wall	Blue	None	0	0	Negative
2490	1	3	Classroom 305	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Classroom 305	W4	Sheetrock	White	None	0	0	Negative
2490	1	3	Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Classroom 305	Radiator	Metal	Grey	None	0	0	Negative
2490	1	3	Classroom 305	Door Casing	Metal	Grey	None	0	0	Negative
2490	1	3	Classroom 308	W1	CMU Block Wall	White	None	0	0.02	Negative
2490	1	3	Classroom 308	W2	CMU Block Wall	White	Chipping	1	0	Negative
2490	1	3	Classroom 308	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Classroom 308	W4	CMU Block Wall	White	None	0	0.01	Negative
2490	1	3	Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Classroom 308	Lockers	Metal	Red	Chipping	2	0.07	Negative
2490	1	3	Classroom 308	Door Casing	Metal	Grey	Chipping	2	0.1	Negative
2490	1	3	Storage Room/Roof Access	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Storage Room/Roof Access	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Storage Room/Roof Access	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Storage Room/Roof Access	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	3	Storage Room/Roof Access	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Storage Room/Roof Access	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	3	Storage Room/Roof Access	Book Shelving	Metal	Green	None	0	0	Negative
2490	1	3	Storage Room/Roof Access	Door Casing	Metal	White	Chipping	2	0.04	Negative
2490	2	3	Pipe Chase adjacent Classroom 302	W1	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	3	Pipe Chase adjacent Classroom 302	W2	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	3	Pipe Chase adjacent Classroom 302	W3	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	3	Pipe Chase adjacent Classroom 302	W4	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A



			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	2	3	Pipe Chase adjacent Classroom 302	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	2	3	Pipe Chase adjacent Classroom 302	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	2	3	Classroom 301	W1	CMU Block Wall	Blue	Cracking	3	0	Negative
2490	2	3	Classroom 301	W1	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	3	Classroom 301	W2	CMU Block Wall	Blue	None	0	0	Negative
2490	2	3	Classroom 301	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	2	3	Classroom 301	W4	CMU Block Wall	Blue	None	0	0	Negative
2490	2	3	Classroom 301	Ceiling	Concrete	White	None	0	0.05	Negative
2490	2	3	Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	3	Classroom 301	Radiator	Metal	White	Chipping	2	0.17	Negative
2490	2	3	Classroom 301	Door Casing	Metal	Green	Chipping	2	0.09	Negative
2490	2	3	Office 300	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Office 300	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Office 300	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Office 300	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	3	Office 300	Ceiling	Concrete	White	None	0	0.09	Negative
2490	2	3	Office 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	3	Office 300	Duct Work	Metal	White	None	0	0.03	Negative
2490	2	3	Office 300	Door Casing	Metal	Brown	None	0	0.02	Negative
2490	2	2	Computer Room 201	W1	CMU Block Wall	White	Cracking	3	0	Negative
2490	2	2	Computer Room 201	W2	CMU Block Wall	White	Cracking	2	0	Negative
2490	2	2	Computer Room 201	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Computer Room 201	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Computer Room 201	Ceiling	Concrete	White	None	0	0	Negative
2490	2	2	Computer Room 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	2	Computer Room 201	Pipe	Metal	White	Chipping	5	0	Negative
2490	2	2	Computer Room 201	Lockers	Metal	Grey	None	0	0.01	Negative
2490	2	2	Computer Room 201	Door Casing	Metal	Black	None	0	0	Negative
2490	2	2	Computer Room 201	Radiator	Metal	Grey	None	0	0.12	Negative
2490	2	2	Counselor's Office	W1	CMU Block Wall	Yellow	Chipping	2	0	Negative
2490	2	2	Counselor's Office	W2	CMU Block Wall	Yellow	Cracking	5	0	Negative
2490	2	2	Counselor's Office	W3	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	2	Counselor's Office	W4	CMU Block Wall	Yellow	Chipping	1	0	Negative
2490	2	2	Counselor's Office	Ceiling	Concrete	White	None	0	0	Negative
2490	2	2	Counselor's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	2	Counselor's Office	Radiator	Metal	Grey	Chipping	4	0.12	Negative
2490	2	2	Counselor's Office	Door Casing	Metal	Grey	None	0	0.04	Negative
2490	2	2	Hallway between Classrooms 201 and 202	W1	CMU Block Wall	White	None	0	0	Negative

			<b>Inspection Dates: 09/13/2021-09/15/2021</b>		<b>School District of Philadelphia</b>					
			<b>Name of Inspector: Lionel Ray Wilson</b>		<b>Lead Safe Certification Assessment Report</b>					
			<b>Inspection Company: Viva EHS</b>		<b>Waring School</b>					
<b>ULCS#</b>	<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
2490	2	2	Hallway between Classrooms 201 and 202	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Hallway between Classrooms 201 and 202	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	2	Hallway between Classrooms 201 and 202	W4	CMU Block Wall	White	None	0	0.02	Negative
2490	2	2	Hallway between Classrooms 201 and 202	W1	CMU Block Wall	Purple	None	0	0	Negative
2490	2	2	Hallway between Classrooms 201 and 202	W2	CMU Block Wall	Purple	None	0	0	Negative
2490	2	2	Hallway between Classrooms 201 and 202	W3	CMU Block Wall	Purple	None	0	0	Negative
2490	2	2	Hallway between Classrooms 201 and 202	W4	CMU Block Wall	Purple	None	0	0	Negative
2490	2	2	Hallway between Classrooms 201 and 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	2	Hallway between Classrooms 201 and 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	2	Hallway between Classrooms 201 and 202	Radiator	Metal	Blue	Chipping	4	0.03	Negative
2490	2	2	Pipe Chase adjacent to Classroom 202	W1	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	2	Pipe Chase adjacent to Classroom 202	W2	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	2	Pipe Chase adjacent to Classroom 202	W3	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	2	Pipe Chase adjacent to Classroom 202	W4	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	2	Pipe Chase adjacent to Classroom 202	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	2	2	Pipe Chase adjacent to Classroom 202	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Women's Restroom adjacent to Classroom 204	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Women's Restroom adjacent to Classroom 204	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Women's Restroom adjacent to Classroom 204	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Women's Restroom adjacent to Classroom 204	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Women's Restroom adjacent to Classroom 204	Ceiling	Concrete	White	None	0	0	Negative
2490	1	2	Women's Restroom adjacent to Classroom 204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	2	Women's Restroom adjacent to Classroom 204	Radiator	Metal	White	None	0	0.01	Negative
2490	1	2	Classroom 204	W1	CMU Block Wall	White	Chipping	4	0	Negative
2490	1	2	Classroom 204	W2	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Classroom 204	W3	Concrete	White	Chipping	2	0	Negative
2490	1	2	Classroom 204	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Classroom 204	Ceiling	Concrete	White	None	0	0	Negative
2490	1	2	Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Classroom 204	Pipe	Metal	White	Chipping	2	0.11	Negative
2490	1	2	Classroom 204	Radiator	Metal	Grey	None	0	0.06	Negative
2490	1	2	Classroom 204	Door Casing	Metal	Grey	Chipping	1	0.17	Negative
2490	1	2	Classroom 204	Door	Wood	Grey	None	0	0	Negative
2490	1	2	Classroom 203	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	1	2	Classroom 203	W2	CMU Block Wall	Blue	None	0	0	Negative
2490	1	2	Classroom 203	W3	Concrete	Blue	None	0	0	Negative
2490	1	2	Classroom 203	W4	CMU Block Wall	Blue	Cracking	2	0	Negative
2490	1	2	Classroom 203	Ceiling	Concrete	White	None	0	0	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	2	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Classroom 203	Radiator	Metal	Blue	None	0	0.08	Negative
2490	1	2	Classroom 203	Door	Wood	Grey	None	0	0	Negative
2490	1	2	Classroom 203	Door Casing	Metal	Grey	None	0	0.1	Negative
2490	1	2	Classroom 208	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	1	2	Classroom 208	W2	Concrete	Blue	Chipping	2	0	Negative
2490	1	2	Classroom 208	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	1	2	Classroom 208	W4	CMU Block Wall	Blue	None	0	0	Negative
2490	1	2	Classroom 208	Ceiling	Concrete	White	None	0	0.11	Negative
2490	1	2	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Classroom 208	Radiator	Metal	Grey	Chipping	3	0.03	Negative
2490	1	2	Classroom 208	Door	Wood	Blue	Chipping	1	0	Negative
2490	1	2	Classroom 208	Door Casing	Metal	Tan	Chipping	6	0.19	Negative
2490	1	2	Classroom 208	Pipe	Metal	Blue	None	0	0.01	Negative
2490	1	2	Office 211	W1	Wood	White	None	0	0	Negative
2490	1	2	Office 211	W2	CMU Block Wall	White	Cracking	2	0	Negative
2490	1	2	Office 211	W3	CMU Block Wall	White	Cracking	2	0	Negative
2490	1	2	Office 211	W4	CMU Block Wall	White	Cracking	2	0	Negative
2490	1	2	Office 211	Ceiling	Concrete	White	None	0	0	Negative
2490	1	2	Office 211	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	2	Office 211	Radiator	Metal	Pink	None	0	0.06	Negative
2490	1	2	Office 211	Door	Wood	Grey	Chipping	3	0	Negative
2490	1	2	Office 211	Door Casing	Wood	White	Chipping	8	0.01	Negative
2490	1	2	Stairwell C	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	2	Stairwell C	W2	CMU Block Wall	White	Chipping	2	0	Negative
2490	1	2	Stairwell C	W3	CMU Block Wall	White	Cracking	5	0	Negative
2490	1	2	Stairwell C	W4	CMU Block Wall	White	Cracking	3	0	Negative
2490	1	2	Stairwell C	Ceiling	Concrete	White	Chipping	4	0.01	Negative
2490	1	2	Stairwell C	Floor	Concrete	Grey	None	0	0.05	Negative
2490	1	2	Stairwell C	Handrail	Metal	Grey	Chipping	6	0.22	Negative
2490	1	2	Stairwell C	Door	Metal	Brown	Chipping	2	0.06	Negative
2490	1	2	Stairwell C	Door Casing	Metal	Brown	None	0	0.02	Negative
2490	1	1	Hallway from Classrooms 105 to 108	W1	CMU Block Wall	Pink	None	0	0.04	Negative
2490	1	1	Hallway from Classrooms 105 to 108	W2	CMU Block Wall	White	None	0	0.03	Negative
2490	1	1	Hallway from Classrooms 105 to 108	W3	CMU Block Wall	Pink	None	0	0.06	Negative
2490	1	1	Hallway from Classrooms 105 to 108	W3	CMU Block Wall	White	None	0	0.06	Negative
2490	1	1	Hallway from Classrooms 105 to 108	W4	CMU Block Wall	Pink	None	0	0.05	Negative
2490	1	1	Hallway from Classrooms 105 to 108	W4	CMU Block Wall	White	None	0	0.03	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	1	Hallway from Classrooms 105 to 108	Ceiling	Concrete	White	Efflorescence	25	0.3	Negative
2490	1	1	Hallway from Classrooms 105 to 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Hallway from Classrooms 105 to 108	Door	Metal	Blue	Chipping	5	0	Negative
2490	1	1	Hallway from Classrooms 105 to 108	Door Casing	Metal	Blue	Chipping	2	0	Negative
2490	1	1	Hallway from Classrooms 105 to 108	Radiator	Metal	Tan	Chipping	1	0.03	Negative
2490	1	1	Hallway from Classrooms 105 to 108	Pipe	Metal	Pink	None	0	0.14	Negative
2490	1	1	Closet adjacent to Classroom 108	W1	CMU Block Wall	White	Cracking	3	0	Negative
2490	1	1	Closet adjacent to Classroom 108	W2	CMU Block Wall	White	Cracking	10	0	Negative
2490	1	1	Closet adjacent to Classroom 108	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Closet adjacent to Classroom 108	W4	CMU Block Wall	White	Cracking	8	0	Negative
2490	1	1	Closet adjacent to Classroom 108	Ceiling	Concrete	White	Efflorescence	6	0.15	Negative
2490	1	1	Closet adjacent to Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Closet adjacent to Classroom 108	Duct Work	Metal	White	Chipping	15	0.66	Negative
2490	1	1	Closet adjacent to Classroom 108	Door	Wood	Tan	Chipping	3	0.02	Negative
2490	1	1	Closet adjacent to Classroom 108	Door Casing	Metal	Grey	Chipping	5	0.05	Negative
2490	1	1	Classroom 108	W1	CMU Block Wall	White	Cracking	1	0	Negative
2490	1	1	Classroom 108	W2	Concrete	White	None	0	0	Negative
2490	1	1	Classroom 108	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Classroom 108	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Classroom 108	Ceiling	Concrete	White	None	0	0.2	Negative
2490	1	1	Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Classroom 108	Radiator	Metal	Grey	None	0	0	Negative
2490	1	1	Classroom 108	Pipe	Metal	White	Chipping	1	0.11	Negative
2490	1	1	Classroom 108	Door	Wood	White	Chipping	2	0	Negative
2490	1	1	Classroom 108	Door Casing	Metal	Grey	Chipping	5	0.07	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	W1	CMU Block Wall	White	Cracking	2	0	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	W2	CMU Block Wall	White	Cracking	2	0	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	W3	CMU Block Wall	White	Cracking	1	0	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	W4	CMU Block Wall	White	Cracking	3	0	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	Ceiling	Concrete	White	None	0	0.06	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Girl's Restroom adjacent to Stairwell E	Door	Wood	Grey	Chipping	5	0	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	Door Casing	Metal	Grey	Chipping	3	0.01	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	Radiator	Metal	Tan	None	0	0	Negative
2490	1	1	Girl's Restroom adjacent to Stairwell E	Stalls	Wood	Purple	None	0	0	Negative
2490	1	1	Boy's Restroom Steps	W1	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	1	Boy's Restroom Steps	W2	CMU Block Wall	Pink	None	0	0.12	Negative
2490	1	1	Boy's Restroom Steps	W3	CMU Block Wall	Pink	None	0	0.03	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	1	Boy's Restroom Steps	W4	CMU Block Wall	Pink	None	0	0.06	Negative
2490	1	1	Boy's Restroom Steps	W2	CMU Block Wall	White	None	0	0.13	Negative
2490	1	1	Boy's Restroom Steps	W3	CMU Block Wall	White	None	0	0	Negative
2490	1	1	Boy's Restroom Steps	W4	CMU Block Wall	White	None	0	0.15	Negative
2490	1	1	Boy's Restroom Steps	Ceiling	Concrete	White	Efflorescence	4	0.2	Negative
2490	1	1	Boy's Restroom Steps	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	1	Pipe Chase between Boy's and Girl's Restrooms	W1	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Pipe Chase between Boy's and Girl's Restrooms	W2	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Pipe Chase between Boy's and Girl's Restrooms	W3	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Pipe Chase between Boy's and Girl's Restrooms	W4	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Pipe Chase between Boy's and Girl's Restrooms	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	1	Pipe Chase between Boy's and Girl's Restrooms	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2490	2	B	Cafeteria	W1	CMU Block Wall	White	None	0	0.01	Negative
2490	2	B	Cafeteria	W2	CMU Block Wall	Purple	Chipping	3	0.02	Negative
2490	2	B	Cafeteria	W3	CMU Block Wall	Purple	None	0	0.02	Negative
2490	2	B	Cafeteria	W4	CMU Block Wall	Purple	None	0	0.01	Negative
2490	2	B	Cafeteria	W2	CMU Block Wall	Yellow	None	0	0.01	Negative
2490	2	B	Cafeteria	W3	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	B	Cafeteria	W4	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	B	Cafeteria	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria	Radiator	Metal	Grey	Chipping	15	0.3	Negative
2490	2	B	Cafeteria	Radiator	Metal	Blue	Chipping	15	0.4	Negative
2490	2	B	Cafeteria	Pipe	Metal	Multi	Chipping	5	0	Negative
2490	2	B	Cafeteria Girl's Restroom	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Girl's Restroom	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Girl's Restroom	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Girl's Restroom	W4	Concrete	White	None	0	0	Negative
2490	2	B	Cafeteria Girl's Restroom	W1	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	B	Cafeteria Girl's Restroom	W2	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	B	Cafeteria Girl's Restroom	W3	CMU Block Wall	Yellow	Chipping	2	0	Negative
2490	2	B	Cafeteria Girl's Restroom	W4	Concrete	Yellow	None	0	0	Negative
2490	2	B	Cafeteria Girl's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2490	2	B	Cafeteria Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Girl's Restroom	Door Casing	Metal	Blue	None	0	0.03	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	2	B	Cafeteria Girl's Restroom	Radiator	Metal	White	None	0	0	Negative
2490	2	B	Cafeteria Restroom's Pipe Chase	W1	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Restroom's Pipe Chase	W2	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Restroom's Pipe Chase	W3	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Restroom's Pipe Chase	W4	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Restroom's Pipe Chase	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Restroom's Pipe Chase	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Boy's Restroom	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	W1	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	W2	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	W3	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	W4	CMU Block Wall	Yellow	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	Ceiling	Concrete	White	Chipping	2	0.06	Negative
2490	2	B	Cafeteria Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Boy's Restroom	Radiator	Metal	White	None	0	0	Negative
2490	2	B	Cafeteria Boy's Restroom	Door Casing	Metal	Blue	None	0	0.02	Negative
2490	2	B	Cafeteria Stairs Right	W1	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Stairs Right	W2	Brick Wall	White	Chipping	3	0.02	Negative
2490	2	B	Cafeteria Stairs Right	W3	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Stairs Right	W4	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Stairs Right	Ceiling	Concrete	White	None	0	0.04	Negative
2490	2	B	Cafeteria Stairs Right	Floor	Concrete	Grey	None	0	0.06	Negative
2490	2	B	Cafeteria Stairs Right	Stair Tread	Concrete	Grey	None	0	0	Negative
2490	2	B	Cafeteria Stairs Right	Handrail	Metal	Grey	Chipping	5	0	Negative
2490	2	B	Cafeteria Stairs Right	Door	Metal	Grey	None	0	0.03	Negative
2490	2	B	Cafeteria Stairs Right	Door Casing	Metal	Grey	None	0	0	Negative
2490	2	B	Cafeteria Stairs Left	W1	CMU Block Wall	White	Chipping	1	0.01	Negative
2490	2	B	Cafeteria Stairs Left	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Stairs Left	W3	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Stairs Left	W4	Concrete	White	Cracking	5	0	Negative
2490	2	B	Cafeteria Stairs Left	W4	Concrete	Tan	Cracking	5	0	Negative
2490	2	B	Cafeteria Stairs Left	Ceiling	Concrete	White	None	0	0.02	Negative
2490	2	B	Cafeteria Stairs Left	Floor	Concrete	Grey	None	0	0.03	Negative
2490	2	B	Cafeteria Stairs Left	Stair Tread	Concrete	Grey	None	0	0	Negative
2490	2	B	Cafeteria Stairs Left	Handrail	Metal	Grey	None	0	0	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	2	B	Cafeteria Stairs Left	Door	Metal	Grey	Chipping	2	0.04	Negative
2490	2	B	Cafeteria Stairs Left	Door Casing	Metal	Grey	None	0	0.02	Negative
2490	2	B	Cafeteria Closet #1	W1	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Closet #1	W2	CMU Block Wall	Blue	Chipping	2	0	Negative
2490	2	B	Cafeteria Closet #1	W3	CMU Block Wall	Blue	Chipping	2	0	Negative
2490	2	B	Cafeteria Closet #1	W4	CMU Block Wall	Blue	Chipping	2	0	Negative
2490	2	B	Cafeteria Closet #1	W2	CMU Block Wall	Green	None	0	0	Negative
2490	2	B	Cafeteria Closet #1	W3	CMU Block Wall	Green	None	0	0	Negative
2490	2	B	Cafeteria Closet #1	W4	CMU Block Wall	Green	None	0	0	Negative
2490	2	B	Cafeteria Closet #1	W2	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Closet #1	W3	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Closet #1	W4	CMU Block Wall	White	None	0	0	Negative
2490	2	B	Cafeteria Closet #1	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2490	2	B	Cafeteria Closet #1	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Closet #1	Door	Metal	Blue	None	0	0	Negative
2490	2	B	Cafeteria Closet #1	Door Casing	Metal	Blue	None	0	0	Negative
2490	2	B	Cafeteria Closet #2	W1	CMU Block Wall	Orange	None	0	0	Negative
2490	2	B	Cafeteria Closet #2	W2	CMU Block Wall	Orange	None	0	0	Negative
2490	2	B	Cafeteria Closet #2	W3	Concrete	Orange	None	0	0	Negative
2490	2	B	Cafeteria Closet #2	W4	CMU Block Wall	Orange	None	0	0	Negative
2490	2	B	Cafeteria Closet #2	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2490	2	B	Cafeteria Closet #2	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	2	B	Cafeteria Closet #2	Door Casing	Metal	Grey	None	0	0.08	Negative
2490	2	B	Hallway between Cafeteria Closets 1 & Boy's Restroom	W1	Duplicate of 011	N/A	N/A	N/A	N/A	N/A
2490	2	B	Hallway between Cafeteria Closets 1 & Boy's Restroom	W2	Duplicate of 011	N/A	N/A	N/A	N/A	N/A
2490	2	B	Hallway between Cafeteria Closets 1 & Boy's Restroom	W3	Duplicate of 011	N/A	N/A	N/A	N/A	N/A
2490	2	B	Hallway between Cafeteria Closets 1 & Boy's Restroom	W4	Duplicate of 011	N/A	N/A	N/A	N/A	N/A
2490	2	B	Hallway between Cafeteria Closets 1 & Boy's Restroom	Ceiling	Duplicate of 011	N/A	N/A	N/A	N/A	N/A
2490	2	B	Hallway between Cafeteria Closets 1 & Boy's Restroom	Floor	Duplicate of 011	N/A	N/A	N/A	N/A	N/A
2490	1	B	Storage Room outside Building Engineer's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	B	Storage Room outside Building Engineer's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	B	Storage Room outside Building Engineer's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	B	Storage Room outside Building Engineer's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	B	Storage Room outside Building Engineer's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	B	Storage Room outside Building Engineer's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2490	1	B	Building Engineer's Office	W1	CMU Block	White	None	0	0	Negative
2490	1	B	Building Engineer's Office	W2	Concrete	White	None	0	0	Negative
2490	1	B	Building Engineer's Office	W3	Concrete	White	Cracking	3	0	Negative
2490	1	B	Building Engineer's Office	W4	CMU Block	White	None	0	0	Negative
2490	1	B	Building Engineer's Office	W1	CMU Block	Tan	None	0	0	Negative
2490	1	B	Building Engineer's Office	W2	Concrete	Tan	None	0	0	Negative
2490	1	B	Building Engineer's Office	W4	CMU Block	Tan	None	0	0	Negative
2490	1	B	Building Engineer's Office	Ceiling	Concrete	White	None	0	0.06	Negative
2490	1	B	Building Engineer's Office	Floor	Concrete	Grey	Chipping	20	0.02	Negative
2490	1	B	Building Engineer's Office	Radiator	Metal	Tan	None	0	0.08	Negative
2490	1	B	Building Engineer's Office	Pipe	Metal	White	Chipping	2	0.15	Negative
2490	1	B	Building Engineer's Office	Door Casing	Metal	Grey	Chipping	2	0.08	Negative
2490	1	B	Restroom in Building Engineer's Office	W1	CMU Block Wall	White	None	0	0	Negative
2490	1	B	Restroom in Building Engineer's Office	W2	Concrete	White	None	0	0	Negative
2490	1	B	Restroom in Building Engineer's Office	W3	Concrete	White	None	0	0	Negative
2490	1	B	Restroom in Building Engineer's Office	W4	CMU Block Wall	White	None	0	0	Negative
2490	1	B	Restroom in Building Engineer's Office	Ceiling	Concrete	White	Chipping	2	0.06	Negative
2490	1	B	Restroom in Building Engineer's Office	Floor	Concrete	Grey	Chipping	10	0.04	Negative
2490	1	B	Restroom in Building Engineer's Office	Pipe	Metal	White	None	0	0.01	Negative
2490	1	B	Restroom in Building Engineer's Office	Door Casing	Metal	Grey	None	0	0.08	Negative
2490	1	B	Closet in Building Engineer's Office	W1	CMU Block Wall	Blue	None	0	0	Negative
2490	1	B	Closet in Building Engineer's Office	W2	Concrete	Blue	None	0	0	Negative
2490	1	B	Closet in Building Engineer's Office	W3	CMU Block Wall	Blue	None	0	0	Negative
2490	1	B	Closet in Building Engineer's Office	W4	CMU Block Wall	Blue	None	0	0	Negative
2490	1	B	Closet in Building Engineer's Office	Ceiling	Concrete	White	No Access	No Access	No Access	No Access
2490	1	B	Closet in Building Engineer's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Steps	W1	CMU Block Wall	Tan	Cracking	1	0.14	Negative
2490	1	B	Boiler Room Steps	W1	CMU Block Wall	Tan	None	0	0	Negative
2490	1	B	Boiler Room Steps	W2	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Steps	W3	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Steps	W4	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Steps	Ceiling	Concrete	White	None	0	0.03	Negative
2490	1	B	Boiler Room Steps	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Steps	Handrail	Metal	Grey	Chipping	10	0.1	Negative
2490	1	B	Boiler Room	W1	Concrete	Tan	Chipping	10	0.06	Negative
2490	1	B	Boiler Room	W2	Concrete	Tan	Cracking	10	0.05	Negative



			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	B	Boiler Room	W3	Concrete	Tan	Cracking	10	0.01	Negative
2490	1	B	Boiler Room	W4	Concrete	Tan	Chipping	1	0	Negative
2490	1	B	Boiler Room	W1	Concrete	White	Chipping	15	0.05	Negative
2490	1	B	Boiler Room	W2	Concrete	White	Cracking	10	0.06	Negative
2490	1	B	Boiler Room	W3	Concrete	White	Cracking	10	0.01	Negative
2490	1	B	Boiler Room	W4	Concrete	White	None	0	0.01	Negative
2490	1	B	Boiler Room	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
2490	1	B	Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room	Pipe	Metal	White	Chipping	15	0.15	Negative
2490	1	B	Generator Room	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Generator Room	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Generator Room	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Generator Room	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Generator Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Generator Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Tank Room	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Tank Room	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Tank Room	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Tank Room	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Tank Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Tank Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Art Room	W1	CMU Block Wall	Blue	Cracking	5	0	Negative
2490	1	B	Art Room	W2	Concrete	Black	None	0	0.08	Negative
2490	1	B	Art Room	W3	Concrete	Blue	None	0	0.11	Negative
2490	1	B	Art Room	W4	CMU Block Wall	Blue	Chipping	10	0.04	Negative
2490	1	B	Art Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	B	Art Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	B	Art Room	Door Casing	Metal	Grey	Chipping	1	0.08	Negative
2490	1	B	Gymnasium	W1	Concrete	Blue	Chipping	25	0.06	Negative
2490	1	B	Gymnasium	W2	CMU Block Wall	Multi	None	0	0.05	Negative
2490	1	B	Gymnasium	W3	Concrete	Blue	Chipping	5	0.04	Negative
2490	1	B	Gymnasium	W3	Concrete	White	Chipping	5	0.04	Negative
2490	1	B	Gymnasium	W3	Concrete	Tan	Chipping	5	0.05	Negative
2490	1	B	Gymnasium	W4	CMU Block Wall	Blue	Chipping	5	0.21	Negative
2490	1	B	Gymnasium	Ceiling	Concrete	White	Cracking	30	0.07	Negative
2490	1	B	Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2490	1	B	Gymnasium	Radiator	Metal	Brown	None	0	0.04	Negative
2490	1	B	Gymnasium	Duct Work	Metal	Brown	None	0	0.11	Negative

			Inspection Dates: 09/13/2021-09/15/2021	School District of Philadelphia						
			Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS	Waring School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2490	1	B	Gymnasium	Duct Work	Metal	White	None	0	0.02	Negative
2490	1	B	Gymnasium	Column	Concrete	Blue	Chipping	15	0.03	Negative
2490	1	B	Gymnasium	Pipe	Metal	White	Flaking	20	0	Negative
2490	1	B	Gymnasium Storage Room	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Gymnasium Storage Room	W2	Concrete	White	None	0	0	Negative
2490	1	B	Gymnasium Storage Room	W3	Concrete	Green	None	0	0.05	Negative
2490	1	B	Gymnasium Storage Room	W2	Concrete	White	None	0	0	Negative
2490	1	B	Gymnasium Storage Room	W3	Concrete	Green	None	0	0.05	Negative
2490	1	B	Gymnasium Storage Room	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Gymnasium Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Gymnasium Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Gymnasium Storage Room	Door	Metal	Grey	Chipping	2	0.09	Negative
2490	1	B	Gymnasium Storage Room	Door Casing	Metal	Grey	None	0	0.27	Negative
2490	1	B	Boiler Room Storage at Small Ladder	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Storage at Small Ladder	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Storage at Small Ladder	W3	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Storage at Small Ladder	W4	CMU Block Wall	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Storage at Small Ladder	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Boiler Room Storage at Small Ladder	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage Steps	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage Steps	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage Steps	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage Steps	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage Steps	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Cafeteria Storage Steps	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Hallway at Boiler Room	W1	Concrete	Tan	None	0	0	Negative
2490	1	B	Hallway at Boiler Room	W2	Concrete	Tan	None	0	0	Negative
2490	1	B	Hallway at Boiler Room	W3	CMU Block Wall	Tan	Chipping	1	0	Negative
2490	1	B	Hallway at Boiler Room	W4	CMU Block Wall	Tan	None	0	0	Negative
2490	1	B	Hallway at Boiler Room	Ceiling	Concrete	Tan	Chipping	3	0.04	Negative
2490	1	B	Hallway at Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2490	1	B	Hallway at Boiler Room	Duct Work	Metal	Tan	Chipping	2	0.02	Negative

			<b>Inspection Dates: 09/13/2021-09/15/2021</b>		<b>School District of Philadelphia</b>					
			<b>Name of Inspector: Lionel Ray Wilson</b>		<b>Lead Safe Certification Assessment Report</b>					
			<b>Inspection Company: Viva EHS</b>		<b>Waring School</b>					
<b>ULCS#</b>	<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
2490	1	B	Hallway at Boiler Room	Pipe	Metal	White	Chipping	1	0.9	Positive
2490	1	B	Hallway at Boiler Room	Door Casing	Metal	Grey	Chipping	2	0.1	Negative
2490	1	B	Steps in Building Engineer's Hallway	W1	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Steps in Building Engineer's Hallway	W2	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Steps in Building Engineer's Hallway	W3	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Steps in Building Engineer's Hallway	W4	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Steps in Building Engineer's Hallway	Ceiling	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Steps in Building Engineer's Hallway	Floor	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Building Engineer's Hallway	W1	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Building Engineer's Hallway	W2	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Building Engineer's Hallway	W3	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Building Engineer's Hallway	W4	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Building Engineer's Hallway	Ceiling	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	B	Building Engineer's Hallway	Floor	Duplicate of H02	N/A	N/A	N/A	N/A	N/A
2490	1	AT	Attic - None	W1	X	X	X	X	X	X
2490	1	AT	Attic - None	W2	X	X	X	X	X	X
2490	1	AT	Attic - None	W3	X	X	X	X	X	X
2490	1	AT	Attic - None	W4	X	X	X	X	X	X
2490	1	AT	Attic - None	Ceiling	X	X	X	X	X	X
2490	1	AT	Attic - None	Floor	X	X	X	X	X	X
2490	1	CS	Crawl Space - Outside Basement Lunch/Gym	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Outside Basement Lunch/Gym	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Outside Basement Lunch/Gym	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Outside Basement Lunch/Gym	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Outside Basement Lunch/Gym	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Outside Basement Lunch/Gym	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Lunch Room	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Lunch Room	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Lunch Room	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Lunch Room	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Lunch Room	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
2490	1	CS	Crawl Space - Lunch Room	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A