

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	100	Art Room	yes	W1	CMU	Green	None	0	0	Negative
4470	1	1	100	Art Room	yes	Door Frame	Metal	Black	Friction	1	0.6	Positive
4470	1	1	100	Art Room	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	100	Art Room	yes	Shelves	Wood	Green	Friction	2	0	Negative
4470	1	1	100	Art Room	yes	Door Frame	Wood	Green	Chipping	1	0	Negative
4470	1	1	100	Art Room	yes	Cabinet	Wood	Grey	Friction	4	0	Negative
4470	1	1	100	Art Room	yes	W2	CMU	Green	None	0	0	Negative
4470	1	1	100	Art Room	yes	Cabinet	Wood	Grey	Friction	4	0	Negative
4470	1	1	100	Art Room	yes	Univent	Metal	Tan	Chipping	2	0	Negative
4470	1	1	100	Art Room	yes	W3	CMU	Green	None	0	0	Negative
4470	1	1	100	Art Room	yes	Cabinet	Wood	Grey	Friction	4	0	Negative
4470	1	1	100	Art Room	yes	W4	CMU	Green	None	0	0	Negative
4470	1	1	100	Art Room	yes	Door Frame	Metal	Black	Friction	1	0.36	Negative
4470	1	1	100	Art Room	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	100	Art Room	yes	Cabinet	Wood	Grey	Friction	4	0	Negative
4470	1	1	100	Art Room	yes	Ceiling	Concrete	White	Flaking	4	0.1	Negative
4470	1	1	100	Art Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	100A	Classroom 100 Large Closet	yes	W1	CMU	Purple	None	0	N/A	N/A
4470	1	1	100A	Classroom 100 Large Closet	yes	W2	CMU	Purple	None	0	N/A	N/A
4470	1	1	100A	Classroom 100 Large Closet	yes	W3	CMU	Purple	None	0	N/A	N/A
4470	1	1	100A	Classroom 100 Large Closet	yes	W4	CMU	Purple	None	0	N/A	N/A
4470	1	1	100A	Classroom 100 Large Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	100A	Classroom 100 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	100B	Classroom 100 Small Closet	yes	W1	CMU	Tan	None	0	N/A	N/A
4470	1	1	100B	Classroom 100 Small Closet	yes	W2	CMU	Tan	None	0	N/A	N/A
4470	1	1	100B	Classroom 100 Small Closet	yes	W3	CMU	Tan	None	0	N/A	N/A
4470	1	1	100B	Classroom 100 Small Closet	yes	Shelves	Wood	Tan	Friction	1	0	Negative
4470	1	1	100B	Classroom 100 Small Closet	yes	W4	CMU	Tan	None	0	N/A	N/A
4470	1	1	100B	Classroom 100 Small Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	100B	Classroom 100 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	W1	CMU	Orange	Chipping	1	0.17	Negative
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	Radiator	Metal	Orange	Flaking	4	0.27	Negative
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	W2	CMU	Orange	Chipping	1	0	Negative
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	W3	CMU	Orange	Chipping	1	0.12	Negative
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	W4	CMU	Orange	Chipping	1	0.08	Negative
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	Door Frame	Metal	Black	Friction	3	0.2	Negative
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	Door	Metal	Orange	Friction	1	0	Negative
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	Ceiling	Concrete	White				
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	Stair Soffit	Metal	Black	Flaking	4	2.1	Positive
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21			School District of Philadelphia						
				Name of Inspector: Ryan Hutsell			Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.			R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
4470	1	1	S1	Stair 6 (next to Classroom 100)	yes	Stringer	Metal	Black	Friction	10	0.48	Negative	
4470	1	1	101	Boiler Room	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	
4470	1	1	101	Boiler Room	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	
4470	1	1	101	Boiler Room	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	
4470	1	1	101	Boiler Room	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	
4470	1	1	101	Boiler Room	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4470	1	1	101	Boiler Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4470	1	1	102	Building Engineer Office	no	W1	CMU	Blue	Chipping	6	0.08	Negative	
4470	1	1	102	Building Engineer Office	no	Door Frame	Metal	Black	Chipping	2	0.3	Negative	
4470	1	1	102	Building Engineer Office	no	Door	Metal	White	Chipping	4	0	Negative	
4470	1	1	102	Building Engineer Office	no	W2	CMU	Blue	Chipping	6	0.04	Negative	
4470	1	1	102	Building Engineer Office	no	W3	CMU	Blue	Chipping	6	0	Negative	
4470	1	1	102	Building Engineer Office	no	Door Frame	Metal	Black	Chipping	2	0.3	Negative	
4470	1	1	102	Building Engineer Office	no	Door	Metal	White	Chipping	4	0	Negative	
4470	1	1	102	Building Engineer Office	no	W4	CMU	Blue	Chipping	6	0	Negative	
4470	1	1	102	Building Engineer Office	no	Door Frame	Metal	Black	Chipping	2	0.25	Negative	
4470	1	1	102	Building Engineer Office	no	Door	Metal	White	Chipping	4	0	Negative	
4470	1	1	102	Building Engineer Office	no	Window Frame	Metal	Black	Chipping	3	0.45	Negative	
4470	1	1	102	Building Engineer Office	no	Ceiling	Concrete	White	Cracking	2	0.1	Negative	
4470	1	1	102	Building Engineer Office	no	Duct	Metal	White	Flaking	4	0.03	Negative	
4470	1	1	102	Building Engineer Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
4470	1	1	102RR	Building Engineer Office Restroom	no	W1	CMU	Blue	Chipping	3	0.2	Negative	
4470	1	1	102RR	Building Engineer Office Restroom	no	W2	CMU	Blue	Chipping	6	0.1	Negative	
4470	1	1	102RR	Building Engineer Office Restroom	no	W3	CMU	Blue	Chipping	3	0.04	Negative	
4470	1	1	102RR	Building Engineer Office Restroom	no	W4	CMU	Blue	Chipping	6	0	Negative	
4470	1	1	102RR	Building Engineer Office Restroom	no	Ceiling	Plaster	White	Cracking	1	0.2	Negative	
4470	1	1	102RR	Building Engineer Office Restroom	no	Floor	Concrete	Grey	Chipping	2	0	Negative	
4470	1	1	102RR	Building Engineer Office Restroom	no	Stall Divider	Metal	Grey	Chipping	4	0.1	Negative	
4470	1	1	PC102RR	Pipe Chase in Building Engineer's Restroom	no	W1	CMU	N/A	N/A	N/A	N/A	N/A	
4470	1	1	PC102RR	Pipe Chase in Building Engineer's Restroom	no	W2	CMU	N/A	N/A	N/A	N/A	N/A	
4470	1	1	PC102RR	Pipe Chase in Building Engineer's Restroom	no	W3	CMU	N/A	N/A	N/A	N/A	N/A	
4470	1	1	PC102RR	Pipe Chase in Building Engineer's Restroom	no	W4	CMU	N/A	N/A	N/A	N/A	N/A	
4470	1	1	PC102RR	Pipe Chase in Building Engineer's Restroom	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4470	1	1	PC102RR	Pipe Chase in Building Engineer's Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4470	1	1	102S	Building Engineer's Shower	no	W1	CMU	Blue	None	0	N/A	N/A	

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	102S	Building Engineer's Shower	no	W2	CMU	Blue	None	0	N/A	N/A
4470	1	1	102S	Building Engineer's Shower	no	W3	CMU	Blue	None	0	N/A	N/A
4470	1	1	102S	Building Engineer's Shower	no	W4	CMU	Blue	None	0	N/A	N/A
4470	1	1	102S	Building Engineer's Shower	no	Ceiling	Plaster	White	None	0	N/A	N/A
4470	1	1	102S	Building Engineer's Shower	no	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	102A	Boys' Restroom in Lobby	yes	W1	CMU	Blue	None	0	N/A	N/A
4470	1	1	102A	Boys' Restroom in Lobby	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	102A	Boys' Restroom in Lobby	yes	Door Frame	Metal	Black	Chipping	4	0.32	Negative
4470	1	1	102A	Boys' Restroom in Lobby	yes	W2	CMU	Blue	None	0	N/A	N/A
4470	1	1	102A	Boys' Restroom in Lobby	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	102A	Boys' Restroom in Lobby	yes	W3	CMU	Blue	None	0	N/A	N/A
4470	1	1	102A	Boys' Restroom in Lobby	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	102A	Boys' Restroom in Lobby	yes	W4	CMU	Blue	Efflorescence	2	0	Negative
4470	1	1	102A	Boys' Restroom in Lobby	yes	W4	CMU	White	Efflorescence	2	0	Negative
4470	1	1	102A	Boys' Restroom in Lobby	yes	Ceiling	Concrete	White	Efflorescence	2	0.08	Negative
4470	1	1	102A	Boys' Restroom in Lobby	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	102A-PC	This Pipe Chase is located in the BE Office Restroom	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	102A-PC	This Pipe Chase is located in the BE Office Restroom	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	102A-PC	This Pipe Chase is located in the BE Office Restroom	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	102A-PC	This Pipe Chase is located in the BE Office Restroom	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	102A-PC	This Pipe Chase is located in the BE Office Restroom	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	102A-PC	This Pipe Chase is located in the BE Office Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	102C	Lobby	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	102C	Lobby	yes	W1	CMU	Green	None	0	N/A	N/A
4470	1	1	102C	Lobby	yes	Door Frame	Metal	Brown	Friction	2	0	Negative
4470	1	1	102C	Lobby	yes	Door	Metal	Brown	Friction	2	0	Negative
4470	1	1	102C	Lobby	yes	Push Bar	Metal	Grey	Friction	2	0	Negative
4470	1	1	102C	Lobby	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	102C	Lobby	yes	W2	CMU	Green	None	0	N/A	N/A
4470	1	1	102C	Lobby	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	102C	Lobby	yes	W3	CMU	Green	None	0	N/A	N/A
4470	1	1	102C	Lobby	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	102C	Lobby	yes	W4	CMU	Green	None	0	N/A	N/A
4470	1	1	102C	Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	102C	Lobby	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	102C	Lobby	yes	Column	Concrete	White	None	0	N/A	N/A
4470	1	1	MEV	Main Entrance Vestibule	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
4470	1	1	MEV	Main Entrance Vestibule	yes	Door Frame	Metal	Brown	Friction	2	0	Negative
4470	1	1	MEV	Main Entrance Vestibule	yes	Door	Metal	Brown	Friction	2	0	Negative
4470	1	1	MEV	Main Entrance Vestibule	yes	Push Bar	Metal	Grey	Friction	2	0	Negative
4470	1	1	MEV	Main Entrance Vestibule	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
4470	1	1	MEV	Main Entrance Vestibule	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
4470	1	1	MEV	Main Entrance Vestibule	yes	Door Frame	Metal	Brown	Friction	2	0	Negative
4470	1	1	MEV	Main Entrance Vestibule	yes	Door	Metal	Brown	Friction	2	0	Negative
4470	1	1	MEV	Main Entrance Vestibule	yes	Push Bar	Metal	Grey	Friction	2	0	Negative
4470	1	1	MEV	Main Entrance Vestibule	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
4470	1	1	MEV	Main Entrance Vestibule	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	MEV	Main Entrance Vestibule	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	102B	Girls' Restroom in Lobby	yes	W1	CMU	Orange	None	0	N/A	N/A
4470	1	1	102B	Girls' Restroom in Lobby	yes	W2	CMU	Orange	Chipping	4	0	Negative
4470	1	1	102B	Girls' Restroom in Lobby	yes	W3	CMU	Orange	None	0	N/A	N/A
4470	1	1	102B	Girls' Restroom in Lobby	yes	W4	CMU	Orange	None	0	N/A	N/A
4470	1	1	102B	Girls' Restroom in Lobby	yes	Outlet Plate	Metal	White	Chipping	1	0	Negative
4470	1	1	102B	Girls' Restroom in Lobby	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	102B	Girls' Restroom in Lobby	yes	Floor	Concrete	Grey	Chipping	1	0	Negative
4470	1	1	102B-PC	Pipe Chase in Custodial Closet next to Girls' Restroom	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	102B-PC	Pipe Chase in Custodial Closet next to Girls' Restroom	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	102B-PC	Pipe Chase in Custodial Closet next to Girls' Restroom	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	102B-PC	Pipe Chase in Custodial Closet next to Girls' Restroom	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	102B-PC	Pipe Chase in Custodial Closet next to Girls' Restroom	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	102B-PC	Pipe Chase in Custodial Closet next to Girls' Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	113A	Custodial Closet to Left of Girls' Restroom in Lobby	no	W1	CMU	White	None	0	0	Negative
4470	1	1	113A	Custodial Closet to Left of Girls' Restroom in Lobby	no	Door Frame	Metal	Black	Friction	1	0.28	Negative
4470	1	1	113A	Custodial Closet to Left of Girls' Restroom in Lobby	no	Door	Wood	White	Friction	1	0	Negative
4470	1	1	113A	Custodial Closet to Left of Girls' Restroom in Lobby	no	W2	CMU	White	None	0	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	113A	Custodial Closet to Left of Girls' Restroom in Lobby	no	W3	CMU	White	None	0	0	Negative
4470	1	1	113A	Custodial Closet to Left of Girls' Restroom in Lobby	no	W4	CMU	White	None	0	0	Negative
4470	1	1	113A	Custodial Closet to Left of Girls' Restroom in Lobby	no	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	113A	Custodial Closet to Left of Girls' Restroom in Lobby	no	Floor	Concrete	Grey	Friction	2	0	Negative
4470	1	1	107	School Store in Lobby (used to be Security Office)	yes	W1	CMU	White	None	0	0.02	Negative
4470	1	1	107	School Store in Lobby (used to be Security Office)	yes	Door Frame	Metal	Black	Friction	1	0.2	Negative
4470	1	1	107	School Store in Lobby (used to be Security Office)	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	1	107	School Store in Lobby (used to be Security Office)	yes	W2	CMU	White	None	0	0	Negative
4470	1	1	107	School Store in Lobby (used to be Security Office)	yes	W3	CMU	White	None	0	0	Negative
4470	1	1	107	School Store in Lobby (used to be Security Office)	yes	W4	CMU	White	None	0	0.06	Negative
4470	1	1	107	School Store in Lobby (used to be Security Office)	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	107	School Store in Lobby (used to be Security Office)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	113BB	Pipe Chase in 1st Floor Men's Restroom	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	113BB	Pipe Chase in 1st Floor Men's Restroom	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	113BB	Pipe Chase in 1st Floor Men's Restroom	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	113BB	Pipe Chase in 1st Floor Men's Restroom	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	113BB	Pipe Chase in 1st Floor Men's Restroom	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	113BB	Pipe Chase in 1st Floor Men's Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	107A	Staff Locker Room	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	107A	Staff Locker Room	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	107A	Staff Locker Room	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	107A	Staff Locker Room	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	107A	Staff Locker Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	107A	Staff Locker Room	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	107B	Women's Restroom near Lobby	yes	W1	CMU	White	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	107B	Women's Restroom near Lobby	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	107B	Women's Restroom near Lobby	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	107B	Women's Restroom near Lobby	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	107B	Women's Restroom near Lobby	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	107B	Women's Restroom near Lobby	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	113B	Men's Restroom in Main Lobby	yes	W1	CMU	Blue	None	0	N/A	N/A
4470	1	1	113B	Men's Restroom in Main Lobby	yes	Door Frame	Metal	Black	Friction	1	0.3	Negative
4470	1	1	113B	Men's Restroom in Main Lobby	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	113B	Men's Restroom in Main Lobby	yes	W2	CMU	Blue	None	0	N/A	N/A
4470	1	1	113B	Men's Restroom in Main Lobby	yes	W3	CMU	Blue	None	0	N/A	N/A
4470	1	1	113B	Men's Restroom in Main Lobby	yes	W4	CMU	Blue	None	0	N/A	N/A
4470	1	1	113B	Men's Restroom in Main Lobby	yes	Ceiling	Plaster	White	Cracking	2	0.05	Negative
4470	1	1	113B	Men's Restroom in Main Lobby	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	103	Teacher's Lounge	yes	W1	CMU	Blue	Flaking	2	0.5	Negative
4470	1	1	103	Teacher's Lounge	yes	Door Frame	Metal	Black	Chipping	4	0.3	Negative
4470	1	1	103	Teacher's Lounge	yes	W2	CMU	Blue	None	0	0	Negative
4470	1	1	103	Teacher's Lounge	yes	W3	CMU	Blue	Chipping	3	0.06	Negative
4470	1	1	103	Teacher's Lounge	yes	Univent	Metal	Blue	Chipping	4	0	Negative
4470	1	1	103	Teacher's Lounge	yes	W4	CMU	Blue	None	0	0.04	Negative
4470	1	1	103	Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	103	Teacher's Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	104	Storage Room adjacent to Teacher's Lounge	yes	W1	CMU	Orange	Flaking	3	0.8	Positive
4470	1	1	104	Storage Room adjacent to Teacher's Lounge	yes	W2	CMU	Orange	Flaking	2	0.8	Positive
4470	1	1	104	Storage Room adjacent to Teacher's Lounge	yes	W3	CMU	Orange	None	0	0.1	Negative
4470	1	1	104	Storage Room adjacent to Teacher's Lounge	yes	W4	CMU	Orange	None	0	0	Negative
4470	1	1	104	Storage Room adjacent to Teacher's Lounge	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	104	Storage Room adjacent to Teacher's Lounge	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
4470	1	1	001A	Book Storage Room next to Teacher's Lounge	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	001A	Book Storage Room next to Teacher's Lounge	yes	W2	CMU	White	None	0	0	Negative
4470	1	1	001A	Book Storage Room next to Teacher's Lounge	yes	W3	CMU	White	None	0	0	Negative
4470	1	1	001A	Book Storage Room next to Teacher's Lounge	yes	W4	CMU	White	None	0	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	001A	Book Storage Room next to Teacher's Lounge	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	001A	Book Storage Room next to Teacher's Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	105	Storage room next to Kitchen	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	105	Storage room next to Kitchen	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	105	Storage room next to Kitchen	yes	W2	CMU	White	None	0	0.1	Negative
4470	1	1	105	Storage room next to Kitchen	yes	Door Frame	Metal	Black	Friction	1	0.4	Negative
4470	1	1	105	Storage room next to Kitchen	yes	W3	CMU	White	Chipping	1	0.04	Negative
4470	1	1	105	Storage room next to Kitchen	yes	Door Frame	Metal	Black	Friction	1	0.32	Negative
4470	1	1	105	Storage room next to Kitchen	yes	W4	CMU	White	None	0	0	Negative
4470	1	1	105	Storage room next to Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	105	Storage room next to Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	105A	Kitchen	no	W1	CMU	White	Chipping	12	0	Negative
4470	1	1	105A	Kitchen	no	W2	CMU	White	None	0	N/A	N/A
4470	1	1	105A	Kitchen	no	W3	CMU	White	None	0	N/A	N/A
4470	1	1	105A	Kitchen	no	W4	CMU	White	None	0	N/A	N/A
4470	1	1	105A	Kitchen	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	105A	Kitchen	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	105A	Kitchen	no	Column	Concrete	Grey	Chipping	2	0	Negative
4470	1	1	105W	Walkway behind Kitchen	no	W1	CMU	White	None	0	0.1	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Door Frame	Metal	Black	Friction	1	0.3	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Door	Wood	White	Friction	1	0	Negative
4470	1	1	105W	Walkway behind Kitchen	no	W2	CMU	White	None	0	0	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Door Frame	Metal	Brown	Friction	2	0.2	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Door	Metal	Brown	Friction	2	0	Negative
4470	1	1	105W	Walkway behind Kitchen	no	W3	CMU	White	None	0	0	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Door Frame	Metal	Black	Friction	1	0.32	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Door	Wood	White	Friction	1	0	Negative
4470	1	1	105W	Walkway behind Kitchen	no	W4	CMU	White	None	0	0	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Door	Wood	White	Friction	1	0.06	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Ceiling	Concrete	White	Chipping	2	0.1	Negative
4470	1	1	105W	Walkway behind Kitchen	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	104A	Mechanical Room behind Kitchen Storage	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	104A	Mechanical Room behind Kitchen Storage	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	104A	Mechanical Room behind Kitchen Storage	no	W3	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	104A	Mechanical Room behind Kitchen Storage	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	104A	Mechanical Room behind Kitchen Storage	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	104A	Mechanical Room behind Kitchen Storage	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	104B	Staff Restroom near Kitchen	no	W1	CMU	Blue	None	0	N/A	N/A
4470	1	1	104B	Staff Restroom near Kitchen	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	104B	Staff Restroom near Kitchen	yes	Door Frame	Metal	Black	Friction	1	0.3	Negative
4470	1	1	104B	Staff Restroom near Kitchen	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	104B	Staff Restroom near Kitchen	no	W2	CMU	Blue	None	0	N/A	N/A
4470	1	1	104B	Staff Restroom near Kitchen	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	104B	Staff Restroom near Kitchen	no	W3	CMU	Blue	None	0	N/A	N/A
4470	1	1	104B	Staff Restroom near Kitchen	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	104B	Staff Restroom near Kitchen	no	W4	CMU	Blue	None	0	N/A	N/A
4470	1	1	104B	Staff Restroom near Kitchen	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	104B	Staff Restroom near Kitchen	no	Ceiling	Concrete	White	Cracking	5	0.05	Negative
4470	1	1	104B	Staff Restroom near Kitchen	no	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	W1	CMU	Green	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	W2	CMU	Green	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	Door Frame	Metal	Black	Friction	1	0.2	Negative
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	Push Bar	Metal	Grey	Friction	2	0	Negative
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	W3	CMU	Green	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	W4	CMU	Green	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	H11	Hallway between Classroom 100 and Lobby	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	S2	Stairwell in Rear Right of Cafetorium	yes	W1	CMU	Orange	Friction	3	0.14	Negative
4470	1	1	S2	Stairwell in Rear Right of Cafetorium	yes	Door	Metal	White	Friction	1	0.1	Negative
4470	1	1	S2	Stairwell in Rear Right of Cafetorium	yes	W2	CMU	Orange	None	0	N/A	N/A
4470	1	1	S2	Stairwell in Rear Right of Cafetorium	yes	W3	CMU	Orange	Chipping	1	0.1	Negative
4470	1	1	S2	Stairwell in Rear Right of Cafetorium	yes	Radiator	Metal	Orange	Flaking	4	0.18	Negative
4470	1	1	S2	Stairwell in Rear Right of Cafetorium	yes	W4	CMU	Orange	None	0	N/A	N/A
4470	1	1	S2	Stairwell in Rear Right of Cafetorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	S2	Stairwell in Rear Right of Cafetorium	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	106A	Storage Room 1-B	yes	W1	CMU	White	None	0	0.12	Negative
4470	1	1	106A	Storage Room 1-B	yes	Door	Wood	White	Holes	1	0	Negative
4470	1	1	106A	Storage Room 1-B	yes	W2	CMU	White	Chipping	4	0	Negative
4470	1	1	106A	Storage Room 1-B	yes	Pipe	Metal	White	Flaking	2	0.21	Negative
4470	1	1	106A	Storage Room 1-B	yes	W3	CMU	White	None	0	0.14	Negative
4470	1	1	106A	Storage Room 1-B	yes	Window Frame	Metal	Black	Chipping	4	0.5	Negative
4470	1	1	106A	Storage Room 1-B	yes	W4	CMU	White	None	0	0.06	Negative
4470	1	1	106A	Storage Room 1-B	yes	Pipe	Metal	White	Flaking	4	0.17	Negative
4470	1	1	106A	Storage Room 1-B	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	106A	Storage Room 1-B	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	106	Cafetorium	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	106	Cafetorium	yes	W1	Plaster	White	Chipping	40	0	Negative
4470	1	1	106	Cafetorium	yes	Door Frame	Metal	Black	Friction	1	0.4	Negative
4470	1	1	106	Cafetorium	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	106	Cafetorium	yes	Column	Concrete	White	Chipping	1	0	Negative
4470	1	1	106	Cafetorium	yes	Column	Concrete	Grey	Chipping	1	0	Negative
4470	1	1	106	Cafetorium	yes	Push Bar	Metal	Grey	Friction	2	0	Negative
4470	1	1	106	Cafetorium	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	106	Cafetorium	yes	W2	Plaster	White	Chipping	12	0	Negative
4470	1	1	106	Cafetorium	yes	Door Frame	Metal	Black	Friction	1	0.35	Negative
4470	1	1	106	Cafetorium	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	106	Cafetorium	yes	Stage	Wood	Blue	Chipping	2	0	Negative
4470	1	1	106	Cafetorium	yes	Push Bar	Metal	Grey	Friction	2	0	Negative
4470	1	1	106	Cafetorium	yes	W3	CMU	Orange	None	0	N/A	N/A
4470	1	1	106	Cafetorium	yes	W3	Plaster	White	Chipping	5	0	Negative
4470	1	1	106	Cafetorium	yes	Door Frame	Metal	Black	Friction	1	0.5	Negative
4470	1	1	106	Cafetorium	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	106	Cafetorium	yes	W4	CMU	White	Chipping	1	0.6	Positive
4470	1	1	106	Cafetorium	yes	Column	Concrete	Grey	Chipping	4	0	Negative
4470	1	1	106	Cafetorium	yes	Radiator	Metal	White	Chipping	10	0.3	Negative
4470	1	1	106	Cafetorium	yes	Ceiling	Plaster	White	Flaking	5	0	Negative
4470	1	1	106	Cafetorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	106A	Stage in Cafetorium	yes	W1	CMU	Orange	None	0	0.1	Negative
4470	1	1	106A	Stage in Cafetorium	yes	Window Frame	Metal	Black	Chipping	4	0.23	Negative
4470	1	1	106A	Stage in Cafetorium	yes	W2	CMU	Orange	Flaking	1	0.8	Positive
4470	1	1	106A	Stage in Cafetorium	yes	W2	Concrete	Orange	Chipping	4	0	Negative
4470	1	1	106A	Stage in Cafetorium	yes	W3	CMU	Orange	None	0	0.25	Negative
4470	1	1	106A	Stage in Cafetorium	yes	W3	Concrete	Orange	Chipping	2	0	Negative
4470	1	1	106A	Stage in Cafetorium	yes	W4	CMU	Orange	None	0	0	Negative
4470	1	1	106A	Stage in Cafetorium	yes	Ceiling	Concrete	White	Cracking	5	0	Negative
4470	1	1	106A	Stage in Cafetorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	115C	Elevator Mechanical Room next to Elevator	no	W1	CMU	White	None	0	0	Negative
4470	1	1	115C	Elevator Mechanical Room next to Elevator	no	W2	CMU	White	None	0	0.23	Negative
4470	1	1	115C	Elevator Mechanical Room next to Elevator	no	W3	CMU	White	Chipping	1	0.5	Negative
4470	1	1	115C	Elevator Mechanical Room next to Elevator	no	W4	CMU	White	None	0	0.2	Negative
4470	1	1	115C	Elevator Mechanical Room next to Elevator	no	Ceiling	Concrete	White	Cracking	2	0.1	Negative
4470	1	1	115C	Elevator Mechanical Room next to Elevator	no	Floor	Concrete	Grey	Friction	2	0	Negative
4470	1	1	001C	Storage Closet to the Right of Stage (Front)	no	W1	CMU	White	None	0	N/A	N/A
4470	1	1	001C	Storage Closet to the Right of Stage (Front)	no	W2	CMU	White	None	0	N/A	N/A
4470	1	1	001C	Storage Closet to the Right of Stage (Front)	no	W3	CMU	White	None	0	N/A	N/A
4470	1	1	001C	Storage Closet to the Right of Stage (Front)	no	W4	CMU	White	None	0	N/A	N/A
4470	1	1	001C	Storage Closet to the Right of Stage (Front)	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	001C	Storage Closet to the Right of Stage (Front)	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	H112A	Back Hallway between Stage, Music Practice Room 112-A, Conference Room, and Main Hall by Elevator	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	H112A	Back Hallway between Stage, Music Practice Room 112-A, Conference Room, and Main Hall by Elevator	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	H112A	Back Hallway between Stage, Music Practice Room 112-A, Conference Room, and Main Hall by Elevator	yes	W3	CMU	White	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
4470	1	1	H112A	Back Hallway between Stage, Music Practice Room 112-A, Conference Room, and Main Hall by Elevator	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	H112A	Back Hallway between Stage, Music Practice Room 112-A, Conference Room, and Main Hall by Elevator	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	H112A	Back Hallway between Stage, Music Practice Room 112-A, Conference Room, and Main Hall by Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	112A	Music Practice Room 112-A	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	112A	Music Practice Room 112-A	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	1	112A	Music Practice Room 112-A	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	112A	Music Practice Room 112-A	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	112A	Music Practice Room 112-A	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	112A	Music Practice Room 112-A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	112A	Music Practice Room 112-A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	112B	Music Practice Room 112-B	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	112B	Music Practice Room 112-B	yes	Door Frame	Metal	Black	Friction	1	0.4	Negative
4470	1	1	112B	Music Practice Room 112-B	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	112B	Music Practice Room 112-B	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	112B	Music Practice Room 112-B	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	112B	Music Practice Room 112-B	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	112B	Music Practice Room 112-B	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	PC112B	Pipe Chase across from Music Practice Room	no	W1	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	PC112B	Pipe Chase across from Music Practice Room	no	W2	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	PC112B	Pipe Chase across from Music Practice Room	no	W3	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	PC112B	Pipe Chase across from Music Practice Room	no	W4	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	PC112B	Pipe Chase across from Music Practice Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	PC112B	Pipe Chase across from Music Practice Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	H112B	Back Hallway between Stage, Music Practice Room 112-B, Conference Room, and Main Hall by Teacher Lounge	yes	W1	CMU	White	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	H112B	Back Hallway between Stage, Music Practice Room 112-B, Conference Room, and Main Hall by Teacher Lounge	yes	W2	CMU	White	Chipping	2	0	Negative
4470	1	1	H112B	Back Hallway between Stage, Music Practice Room 112-B, Conference Room, and Main Hall by Teacher Lounge	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	H112B	Back Hallway between Stage, Music Practice Room 112-B, Conference Room, and Main Hall by Teacher Lounge	yes	W4	CMU	White	Chipping	2	0	Negative
4470	1	1	H112B	Back Hallway between Stage, Music Practice Room 112-B, Conference Room, and Main Hall by Teacher Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	H112B	Back Hallway between Stage, Music Practice Room 112-B, Conference Room, and Main Hall by Teacher Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	112	Conference Room 112	yes	W1	CMU	Blue	None	0	N/A	N/A
4470	1	1	112	Conference Room 112	yes	W1	Concrete	Blue	None	0	N/A	N/A
4470	1	1	112	Conference Room 112	yes	Door Frame	Metal	Black	Friction	1	0.35	Negative
4470	1	1	112	Conference Room 112	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	112	Conference Room 112	yes	Sink Cabinet	Metal	Blue	Chipping	2	0.23	Negative
4470	1	1	112	Conference Room 112	yes	W2	CMU	Blue	None	0	N/A	Negative
4470	1	1	112	Conference Room 112	yes	W2	Concrete	Blue	None	0	N/A	Negative
4470	1	1	112	Conference Room 112	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	1	112	Conference Room 112	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	112	Conference Room 112	yes	W3	CMU	Blue	None	0	N/A	Negative
4470	1	1	112	Conference Room 112	yes	W3	Concrete	Blue	None	0	0	Negative
4470	1	1	112	Conference Room 112	yes	Window Frame	Metal	Black	Chipping	4	0.32	Negative
4470	1	1	112	Conference Room 112	yes	W4	CMU	Blue	None	0	N/A	N/A
4470	1	1	112	Conference Room 112	yes	W4	Concrete	Blue	Chipping	4	0.1	Negative
4470	1	1	112	Conference Room 112	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	112	Conference Room 112	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	112	Conference Room 112	yes	Column	Concrete	Grey	Chipping	2	0	Negative
4470	1	1	113	Office 113 in Conference Room	yes	W1	CMU	Orange	Cracking	2	0.23	Negative
4470	1	1	113	Office 113 in Conference Room	yes	Door Frame	Metal	Black	Chipping	2	0.28	Negative
4470	1	1	113	Office 113 in Conference Room	yes	Door	Metal	Orange	Chipping	2	0.1	Negative
4470	1	1	113	Office 113 in Conference Room	yes	Window Frame	Metal	Black	Chipping	4	0.36	Negative
4470	1	1	113	Office 113 in Conference Room	yes	W2	CMU	Orange	Cracking	3	0.4	Negative

				Inspection Dates: 08/30/21-09/14/21			School District of Philadelphia					
				Name of Inspector: Ryan Hutsell			Lead Safe Certification Assessment Report					
				Inspection Company: Synertech, Inc.			R. R. Wright ES School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
4470	1	1	113	Office 113 in Conference Room	yes	W3	CMU	Orange	Cracking	2	0.34	Negative
4470	1	1	113	Office 113 in Conference Room	yes	W4	Plaster	Orange	Chipping	16	0.42	Negative
4470	1	1	113	Office 113 in Conference Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	113	Office 113 in Conference Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	111	Small Kitchen	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	111	Small Kitchen	yes	Door Frame	Metal	Black	Friction	1	0.2	Negative
4470	1	1	111	Small Kitchen	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	111	Small Kitchen	yes	W2	Plaster	White	None	0	0	Negative
4470	1	1	111	Small Kitchen	yes	Window Frame	Metal	Black	Chipping	2	0.31	Negative
4470	1	1	111	Small Kitchen	yes	W3	Plaster	White	None	0	0.04	Negative
4470	1	1	111	Small Kitchen	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	1	111	Small Kitchen	yes	Door	Wood	Blue	Friction	1	0.06	Negative
4470	1	1	111	Small Kitchen	yes	W4	CMU	White	None	0	0.02	Negative
4470	1	1	111	Small Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	111	Small Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	W1	CMU	Green	None	0	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	W2	CMU	Green	None	0	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	Door Frame	Metal	Black	Friction	4	0.35	Negative
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	Door	Wood	Blue	Friction	4	0	Negative
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	Window Frame	Metal	Black	Friction	1	0.4	Negative
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	W3	CMU	Green	None	0	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	W4	CMU	Green	None	0	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	Door Frame	Metal	Black	Friction	4	0.25	Negative
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	Door	Wood	Blue	Friction	4	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	H1	Hallway between Nurse Office, Main Office, and Lobby	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	Door Frame	Metal	Black	Friction	5	0.41	Negative
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	Door	Wood	White	Friction	5	0.06	Negative
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	Door Frame	Metal	Black	Friction	5	0.36	Negative
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	Door	Wood	White	Friction	5	0	Negative
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	H20	Hallway between Classrooms 201 through 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109A	Main Office	yes	W1	CMU	Yellow	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Window Frame	Metal	Black	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Door Frame	Metal	Black	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Door	Metal	Blue	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	W2	CMU	Yellow	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Door Frame	Metal	Black	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Door	Metal	Tan	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	W3	CMU	Yellow	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Door Frame	Metal	Black	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	W4	CMU	Yellow	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Door Frame	Metal	Black	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Door	Metal	Black	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Door	Metal	Tan	None	0	N/A	N/A
4470	1	1	109A	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109A	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	110	Counselor/Discipline Climate Manager in Main Office	yes	W1	CMU	Blue	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	110	Counselor/Discipline Climate Manager in Main Office	yes	W2	CMU	Blue	None	0	N/A	N/A
4470	1	1	110	Counselor/Discipline Climate Manager in Main Office	yes	W3	CMU	Blue	None	0	N/A	N/A
4470	1	1	110	Counselor/Discipline Climate Manager in Main Office	yes	W4	CMU	Blue	None	0	N/A	N/A
4470	1	1	110	Counselor/Discipline Climate Manager in Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	110	Counselor/Discipline Climate Manager in Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109	Counselor's Office	yes	W1	CMU	Purple	None	0	N/A	N/A
4470	1	1	109	Counselor's Office	yes	W2	CMU	Purple	None	0	N/A	N/A
4470	1	1	109	Counselor's Office	yes	W3	CMU	Purple	None	0	N/A	N/A
4470	1	1	109	Counselor's Office	yes	W4	CMU	Purple	None	0	N/A	N/A
4470	1	1	109	Counselor's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109	Counselor's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109E	Main Office Storage Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	109E	Main Office Storage Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	1	109E	Main Office Storage Closet	yes	W3	CMU	White	None	0	0.04	Negative
4470	1	1	109E	Main Office Storage Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	1	109E	Main Office Storage Closet	yes	Ceiling	Concrete	White				
4470	1	1	109E	Main Office Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109D	Principal's Office	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	109D	Principal's Office	yes	Door Frame	Metal	Black	Friction	1	0.38	Negative
4470	1	1	109D	Principal's Office	yes	W2	CMU	White	None	0	0.04	Negative
4470	1	1	109D	Principal's Office	yes	W3	CMU	White	None	0	0.02	Negative
4470	1	1	109D	Principal's Office	yes	W4	CMU	White	None	0	0.06	Negative
4470	1	1	109D	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109D	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109G	Principal's Restroom	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	109G	Principal's Restroom	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	109G	Principal's Restroom	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	109G	Principal's Restroom	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	109G	Principal's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109G	Principal's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	109H	Principal's Office Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	109H	Principal's Office Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	109H	Principal's Office Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	109H	Principal's Office Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	109H	Principal's Office Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	109H	Principal's Office Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
4470	1	1	109F	Main Office Closet next to Principal's Office	yes	W1	CMU	White	None	0	0.12	Negative
4470	1	1	109F	Main Office Closet next to Principal's Office	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	109F	Main Office Closet next to Principal's Office	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	109F	Main Office Closet next to Principal's Office	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	109F	Main Office Closet next to Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109F	Main Office Closet next to Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109B	IT Data Room	no	W1	CMU	White	None	0	0	Negative
4470	1	1	109B	IT Data Room	no	W2	CMU	White	None	0	0	Negative
4470	1	1	109B	IT Data Room	no	Wooden Panel	Wood	White	Chipping	3	0	Negative
4470	1	1	109B	IT Data Room	no	W3	CMU	White	None	0	0.02	Negative
4470	1	1	109B	IT Data Room	no	W4	CMU	White	None	0	0	Negative
4470	1	1	109B	IT Data Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109B	IT Data Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109B-1	Closet in IT Data Room	no	W1	CMU	White	None	0	0.05	Negative
4470	1	1	109B-1	Closet in IT Data Room	no	W2	CMU	White	None	0	0.02	Negative
4470	1	1	109B-1	Closet in IT Data Room	no	W3	CMU	White	None	0	0	Negative
4470	1	1	109B-1	Closet in IT Data Room	no	W4	CMU	White	None	0	0.04	Negative
4470	1	1	109B-1	Closet in IT Data Room	no	Ceiling	Plaster	White	None	0	N/A	N/A
4470	1	1	109B-1	Closet in IT Data Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	108	Gym	yes	W1	CMU	Orange	Chipping	2	0.25	Negative
4470	1	1	108	Gym	yes	Door Frame	Metal	Black	Chipping	10	0.3	Negative
4470	1	1	108	Gym	yes	Door	Wood	Orange	Chipping	10	0.25	Negative
4470	1	1	108	Gym	yes	Vent	Metal	Grey	Chipping	1	0.1	Negative
4470	1	1	108	Gym	yes	Radiator	Metal	Orange	Chipping	5	0.5	Negative
4470	1	1	108	Gym	yes	W2	CMU	Orange	Cracking	2	0.5	Negative
4470	1	1	108	Gym	yes	Door Frame	Metal	Brown	Friction	2	0	Negative
4470	1	1	108	Gym	yes	Door	Metal	Brown	Friction	2	0	Negative
4470	1	1	108	Gym	yes	W3	CMU	Orange	Chipping	4	0.6	Positive
4470	1	1	108	Gym	yes	W3	Concrete	White	Efflorescence	32	0.1	Negative
4470	1	1	108	Gym	yes	Radiator	Metal	Orange	Chipping	4	0.63	Positive
4470	1	1	108	Gym	yes	Door Frame	Metal	Black	Chipping	4	0.35	Negative
4470	1	1	108	Gym	yes	Door	Wood	Orange	Chipping	4	0.19	Negative
4470	1	1	108	Gym	yes	Vent	Metal	Grey	Chipping	1	0.08	Negative
4470	1	1	108	Gym	yes	W4	CMU	Orange	Cracking	4	0.4	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
4470	1	1	108	Gym	yes	Door Frame	Metal	Black	Chipping	10	0.32	Negative
4470	1	1	108	Gym	yes	Door	Wood	Orange	Chipping	10	0.2	Negative
4470	1	1	108	Gym	yes	Vent	Metal	Grey	Chipping	1	0	Negative
4470	1	1	108	Gym	yes	Window Frame	Metal	Black	Chipping	2	0.5	Negative
4470	1	1	108	Gym	yes	Ceiling	Concrete	White	Efflorescence	32	See Comment	See Comment
4470	1	1	108	Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	108	Gym	yes	Column	Concrete	Grey	Chipping	12	0	Negative
4470	1	1	109C	Storage in Gym next to Staff Restroom	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	109C	Storage in Gym next to Staff Restroom	yes	W2	CMU	White	None	0	0	Negative
4470	1	1	109C	Storage in Gym next to Staff Restroom	yes	Shelves	Wood	White	Friction	4	0.15	Negative
4470	1	1	109C	Storage in Gym next to Staff Restroom	yes	Towel Rack	Wood	White	Chipping	2	0.12	Negative
4470	1	1	109C	Storage in Gym next to Staff Restroom	yes	W3	CMU	White	None	0	0	Negative
4470	1	1	109C	Storage in Gym next to Staff Restroom	yes	W4	CMU	White	None	0	0	Negative
4470	1	1	109C	Storage in Gym next to Staff Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	109C	Storage in Gym next to Staff Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	108A	Gym Office	yes	W1	CMU	Blue	Chipping	2	0	Negative
4470	1	1	108A	Gym Office	yes	W1	Concrete	Blue	Chipping	4	0	Negative
4470	1	1	108A	Gym Office	yes	W1	Concrete	Grey	Chipping	1	0	Negative
4470	1	1	108A	Gym Office	yes	W2	CMU	Blue	Chipping	4	0	Negative
4470	1	1	108A	Gym Office	yes	W3	CMU	Blue	Chipping	2	0	Negative
4470	1	1	108A	Gym Office	yes	Closet Shelf	Wood	White	Friction	2	0	Negative
4470	1	1	108A	Gym Office	yes	Shelf Bracket	Wood	White	Friction	2	0	Negative
4470	1	1	108A	Gym Office	yes	W4	CMU	Blue	Chipping	4	0	Negative
4470	1	1	108A	Gym Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	108A	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	W1	CMU	Blue	None	0	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	Door Frame	Metal	Black	Chipping	2	0.3	Negative
4470	1	1	108AA	Restroom in Gym Office	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	W2	CMU	Blue	None	0	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	W3	CMU	Blue	None	0	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	Bench	Wood	Blue	Friction	1	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	108AA	Restroom in Gym Office	yes	Stall Divider	Metal	Blue	Chipping	1	0	Negative
4470	1	1	108AA	Restroom in Gym Office	yes	Stall Divider	Metal	Grey	Chipping	1	0	Negative
4470	1	1	108AA	Restroom in Gym Office	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	W4	CMU	Blue	None	0	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	108AA	Restroom in Gym Office	yes	Floor	Concrete	Grey	Chipping	2	0	Negative
4470	1	1	108AC	Closet in Gym Office	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	108AC	Closet in Gym Office	yes	W2	CMU	White	None	0	0	Negative
4470	1	1	108AC	Closet in Gym Office	yes	W3	CMU	White	None	0	0	Negative
4470	1	1	108AC	Closet in Gym Office	yes	W4	CMU	White	None	0	0	Negative
4470	1	1	108AC	Closet in Gym Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	108AC	Closet in Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	W1	CMU	Blue	Chipping	1	0	Negative
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	Door Frame	Metal	Black	Friction	1	0.32	Negative
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	Door	Wood	Blue	Friction	1	0.08	Negative
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	W2	CMU	Blue	Chipping	2	0	Negative
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	W3	CMU	Blue	None	0	N/A	N/A
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	W4	CMU	Blue	None	0	N/A	N/A
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	W4	CMU	White	Chipping	1	0	Negative
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	Door Frame	Metal	Black	Friction	1	0.38	Negative
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	Duct	Metal	White	Chipping	2	0.05	Negative
4470	1	1	108F	Boys' Restroom in Gymnasium	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	no	W1	CMU	Blue	Cracking	2	0	Negative
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	no	W2	CMU	Blue	Cracking	2	0	Negative
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	yes	Trim	Wood	Blue	Chipping	5	0.1	Negative
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	no	W3	Ceramic	Blue	None	0	N/A	N/A
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	yes	Trim	Wood	Blue	Chipping	5	0	Negative
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	no	W4	CMU	Blue	Cracking	1	0	Negative
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	yes	Trim	Wood	Blue	Chipping	5	0.04	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	yes	Radiator	Metal	Yellow	Flaking	5	0.35	Negative
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	no	Ceiling	Plaster	White	Flaking	80	0	Negative
4470	1	1	108F-1	Boys' Locker Room Area in Gym (Used for Maintenance Storage)	no	Floor	Concrete	Blue	None	0	N/A	N/A
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	no	W1	CMU	Green	None	0	0	Negative
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	yes	Lockers	Metal	Blue	Chipping	20	0	Negative
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	no	W2	CMU	Green	None	0	0	Negative
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	yes	Lockers	Metal	Blue	Chipping	20	0	Negative
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	no	W3	CMU	Green	None	0	0	Negative
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	yes	Pipe	Metal	Blue	Chipping	1	0.3	Negative
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	no	W4	CMU	Green	None	0	0	Negative
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	no	Ceiling	Plaster	White	Cracking	12	0	Negative
4470	1	1	108F-2	Former Drying Area between Boys' Locker Room and Showers (Used for Maintenance Storage)	no	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	W1	CMU	Orange	Chipping	1	0	Negative
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	Door Frame	Metal	Black	Friction	1	0.2	Negative
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	Door	Wood	Orange	Friction	1	0	Negative
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	W2	CMU	Orange	None	0	N/A	N/A
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	Stall Divider	Metal	Blue	Chipping	2	0	Negative
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	W3	CMU	Orange	None	0	N/A	N/A
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	W4	CMU	Orange	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	108D	Girls' Restroom in Gymnasium	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	108D-1	Girls' Locker Room Area in Gym (Used for Maintenance Storage)	no	W1	CMU	Tan	None	0	N/A	N/A
4470	1	1	108D-1	Girls' Locker Room Area in Gym (Used for Maintenance Storage)	yes	Towel Rack	Wood	Tan	Friction	1	0	Negative
4470	1	1	108D-1	Girls' Locker Room Area in Gym (Used for Maintenance Storage)	no	W2	CMU	Tan	None	0	N/A	N/A
4470	1	1	108D-1	Girls' Locker Room Area in Gym (Used for Maintenance Storage)	yes	Radiator	Metal	Yellow	Flaking	6	0.4	Negative
4470	1	1	108D-1	Girls' Locker Room Area in Gym (Used for Maintenance Storage)	no	W3	Ceramic	Tan	None	0	N/A	N/A
4470	1	1	108D-1	Girls' Locker Room Area in Gym (Used for Maintenance Storage)	no	W4	CMU	Tan	None	0	N/A	N/A
4470	1	1	108D-1	Girls' Locker Room Area in Gym (Used for Maintenance Storage)	no	Ceiling	Plaster	White	Flaking	80	0.08	Negative
4470	1	1	108D-1	Girls' Locker Room Area in Gym (Used for Maintenance Storage)	no	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	no	W1	CMU	Tan	None	0	N/A	N/A
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	yes	Door Frame	Metal	Black	Friction	2	0.5	Negative
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	yes	Door	Wood	Orange	Chipping	2	0	Negative
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	yes	Lockers	Metal	Pink	Chipping	12	0.17	Negative
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	no	W2	CMU	Tan	None	0	N/A	N/A
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	yes	Lockers	Metal	Pink	Chipping	12	0.15	Negative
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	no	W3	CMU	Tan	None	0	N/A	N/A
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	yes	Pipe	Metal	Tan	Chipping	2	0.31	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	no	W4	CMU	Tan	None	0	N/A	N/A
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	yes	Lockers	Metal	Pink	Chipping	12	0.21	Negative
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	no	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	108D-2	Former Drying Area between Girls' Locker Room and Showers (Used for Maintenance Storage)	no	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4470	1	1	S4	Stairwell next to Classroom 122	yes	W1	CMU	Orange	Flaking	2	0.1	Negative
4470	1	1	S4	Stairwell next to Classroom 122	yes	W2	CMU	Orange	Chipping	3	0.12	Negative
4470	1	1	S4	Stairwell next to Classroom 122	yes	W3	CMU	Orange	None	0	N/A	N/A
4470	1	1	S4	Stairwell next to Classroom 122	yes	Radiator	Metal	Orange	Flaking	8	0.24	Negative
4470	1	1	S4	Stairwell next to Classroom 122	yes	Door Frame	Metal	Black	Chipping	2	0.29	Negative
4470	1	1	S4	Stairwell next to Classroom 122	yes	Door	Metal	Orange	Chipping	2	0.15	Negative
4470	1	1	S4	Stairwell next to Classroom 122	yes	W4	CMU	Orange	None	0	N/A	N/A
4470	1	1	S4	Stairwell next to Classroom 122	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	S4	Stairwell next to Classroom 122	yes	Stair Soffit	Metal	Black	Flaking	8	2.3	Positive
4470	1	1	S4	Stairwell next to Classroom 122	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	001E	Storage 1E outside Classroom 122	no	W1	CMU	White	None	0	N/A	N/A
4470	1	1	001E	Storage 1E outside Classroom 122	no	W2	CMU	White	None	0	N/A	N/A
4470	1	1	001E	Storage 1E outside Classroom 122	no	W3	CMU	White	None	0	N/A	N/A
4470	1	1	001E	Storage 1E outside Classroom 122	no	W4	CMU	White	None	0	N/A	N/A
4470	1	1	001E	Storage 1E outside Classroom 122	no	Ceiling	CMU	White	None	0	N/A	N/A
4470	1	1	001E	Storage 1E outside Classroom 122	no	Floor	CMU	N/A	N/A	N/A	N/A	N/A
4470	1	1	122	Classroom 122	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	122	Classroom 122	yes	Door Frame	Metal	Black	Friction	1	0.5	Negative
4470	1	1	122	Classroom 122	yes	Door	Wood	White	Friction	1	0.1	Negative
4470	1	1	122	Classroom 122	yes	Cubbies	Wood	Green	Friction	6	0	Negative
4470	1	1	122	Classroom 122	yes	W2	CMU	White	Chipping	20	0	Negative
4470	1	1	122	Classroom 122	yes	W3	CMU	White	Chipping	4	0	Negative
4470	1	1	122	Classroom 122	yes	W3	Concrete	White	Flaking	1	0	Negative
4470	1	1	122	Classroom 122	yes	Univent	Metal	Tan	Chipping	2	0	Negative
4470	1	1	122	Classroom 122	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	122	Classroom 122	yes	Sink Cabinet	Metal	Green	Chipping	10	0.15	Negative
4470	1	1	122	Classroom 122	yes	Shelves	Wood	Green	Friction	10	0	Negative
4470	1	1	122	Classroom 122	yes	Door Frame	Wood	Tan	Friction	1	0	Negative
4470	1	1	122	Classroom 122	yes	Door	Wood	Tan	Friction	1	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	122	Classroom 122	yes	Ceiling	Concrete	White	Chipping	10	0	Negative
4470	1	1	122	Classroom 122	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	122A	Classroom 122 Book Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	122A	Classroom 122 Book Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	1	122A	Classroom 122 Book Closet	yes	Shelves	Wood	Tan	Friction	12	0	Negative
4470	1	1	122A	Classroom 122 Book Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	1	122A	Classroom 122 Book Closet	yes	Shelves	Wood	Tan	Friction	4	0	Negative
4470	1	1	122A	Classroom 122 Book Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	1	122A	Classroom 122 Book Closet	yes	Shelves	Wood	Tan	Friction	12	0	Negative
4470	1	1	122A	Classroom 122 Book Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	122A	Classroom 122 Book Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	122B	Classroom 122 Storage Closet	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	122B	Classroom 122 Storage Closet	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	122B	Classroom 122 Storage Closet	yes	W3	Concrete	White	Flaking	4	0	Negative
4470	1	1	122B	Classroom 122 Storage Closet	yes	Door Frame	Metal	Brown	Friction	4	0	Negative
4470	1	1	122B	Classroom 122 Storage Closet	yes	Door	Metal	Brown	Friction	4	0	Negative
4470	1	1	122B	Classroom 122 Storage Closet	yes	W4	Concrete	White	Flaking	6	0	Negative
4470	1	1	122B	Classroom 122 Storage Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	122B	Classroom 122 Storage Closet	yes	Floor	Concrete	Grey	Flaking	4	0	Negative
4470	1	1	122C	Classroom 122 Restroom	yes	W1	CMU	White	Chipping	1	0	Negative
4470	1	1	122C	Classroom 122 Restroom	yes	Door Frame	Metal	Tan	Chipping	1	0.12	Negative
4470	1	1	122C	Classroom 122 Restroom	yes	Door	Wood	Tan	Chipping	1	0	Negative
4470	1	1	122C	Classroom 122 Restroom	yes	W2	CMU	White	Cracking	4	0	Negative
4470	1	1	122C	Classroom 122 Restroom	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	122C	Classroom 122 Restroom	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	122C	Classroom 122 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	122C	Classroom 122 Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	121	Classroom 121	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	121	Classroom 121	yes	Door Frame	Metal	Black	Friction	1	0.4	Negative
4470	1	1	121	Classroom 121	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	1	121	Classroom 121	yes	Cubbies	Wood	Green	Friction	5	0	Negative
4470	1	1	121	Classroom 121	yes	W2	CMU	White	Chipping	8	0	Negative
4470	1	1	121	Classroom 121	yes	W3	CMU	White	Chipping	4	0	Negative
4470	1	1	121	Classroom 121	yes	W3	Concrete	White	Flaking	1	0	Negative
4470	1	1	121	Classroom 121	yes	Univent	Metal	Tan	Chipping	2	0	Negative
4470	1	1	121	Classroom 121	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	121	Classroom 121	yes	Sink Cabinet	Metal	Purple	Chipping	4	0.1	Negative
4470	1	1	121	Classroom 121	yes	Shelves	Wood	Green	Friction	10	0	Negative
4470	1	1	121	Classroom 121	yes	Door Frame	Wood	Tan	Friction	1	0	Negative
4470	1	1	121	Classroom 121	yes	Door	Wood	Tan	Friction	1	0	Negative

				Inspection Dates: 08/30/21-09/14/21			School District of Philadelphia					
				Name of Inspector: Ryan Hutsell			Lead Safe Certification Assessment Report					
				Inspection Company: Synertech, Inc.			R. R. Wright ES School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	121	Classroom 121	yes	Ceiling	Concrete	White	Chipping	10	0	Negative
4470	1	1	121	Classroom 121	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	121A	Classroom 121 Restroom	yes	W1	CMU	White	Chipping	1	0	Negative
4470	1	1	121A	Classroom 121 Restroom	yes	Door Frame	Metal	Tan	Chipping	1	0.2	Negative
4470	1	1	121A	Classroom 121 Restroom	yes	Door	Wood	Tan	Chipping	1	0	Negative
4470	1	1	121A	Classroom 121 Restroom	yes	W2	CMU	White	Cracking	1	0	Negative
4470	1	1	121A	Classroom 121 Restroom	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	121A	Classroom 121 Restroom	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	121A	Classroom 121 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	121A	Classroom 121 Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	121B	Classroom 121 Book Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	121B	Classroom 121 Book Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	1	121B	Classroom 121 Book Closet	yes	Shelves	Wood	Tan	Friction	12	0	Negative
4470	1	1	121B	Classroom 121 Book Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	1	121B	Classroom 121 Book Closet	yes	Shelves	Wood	Tan	Friction	4	0	Negative
4470	1	1	121B	Classroom 121 Book Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	1	121B	Classroom 121 Book Closet	yes	Shelves	Wood	Tan	Friction	12	0	Negative
4470	1	1	121B	Classroom 121 Book Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	121B	Classroom 121 Book Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	120	Classroom 120	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	120	Classroom 120	yes	Door Frame	Metal	Black	Friction	1	0.4	Negative
4470	1	1	120	Classroom 120	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	1	120	Classroom 120	yes	Cubbies	Wood	Green	Friction	16	0	Negative
4470	1	1	120	Classroom 120	yes	Cubbies	Wood	Purple	Friction	6	0	Negative
4470	1	1	120	Classroom 120	yes	W2	CMU	White	Chipping	8	0	Negative
4470	1	1	120	Classroom 120	yes	W3	CMU	White	Chipping	4	0	Negative
4470	1	1	120	Classroom 120	yes	W3	Concrete	White	Flaking	1	0	Negative
4470	1	1	120	Classroom 120	yes	Univent	Metal	Tan	Chipping	2	0	Negative
4470	1	1	120	Classroom 120	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	120	Classroom 120	yes	Pipe	Metal	White	Flaking	8	0.18	Negative
4470	1	1	120	Classroom 120	yes	Sink Cabinet	Metal	Purple	Chipping	4	0.1	Negative
4470	1	1	120	Classroom 120	yes	Shelves	Wood	Green	Friction	10	0	Negative
4470	1	1	120	Classroom 120	yes	Door Frame	Wood	Tan	Friction	1	0	Negative
4470	1	1	120	Classroom 120	yes	Door	Wood	Tan	Friction	1	0	Negative
4470	1	1	120	Classroom 120	yes	Ceiling	Concrete	White	Chipping	10	0	Negative
4470	1	1	120	Classroom 120	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	120A	Classroom 120 Book Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	1	120A	Classroom 120 Book Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	1	120A	Classroom 120 Book Closet	yes	Shelves	Wood	Tan	Friction	12	0	Negative
4470	1	1	120A	Classroom 120 Book Closet	yes	W3	CMU	White	None	0	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
4470	1	1	120A	Classroom 120 Book Closet	yes	Shelves	Wood	Tan	Friction	4	0	Negative
4470	1	1	120A	Classroom 120 Book Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	1	120A	Classroom 120 Book Closet	yes	Shelves	Wood	Tan	Friction	12	0	Negative
4470	1	1	120A	Classroom 120 Book Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	120A	Classroom 120 Book Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	120B	Classroom 120 Restroom	yes	W1	CMU	White	Chipping	1	0	Negative
4470	1	1	120B	Classroom 120 Restroom	yes	Door Frame	Metal	Tan	Chipping	1	0.2	Negative
4470	1	1	120B	Classroom 120 Restroom	yes	Door	Wood	Tan	Chipping	1	0	Negative
4470	1	1	120B	Classroom 120 Restroom	yes	W2	CMU	White	Cracking	1	0	Negative
4470	1	1	120B	Classroom 120 Restroom	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	120B	Classroom 120 Restroom	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	120B	Classroom 120 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	120B	Classroom 120 Restroom	yes	Floor	Concrete	Grey	Chipping	1	0	Negative
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	W1	CMU	Tan	Chipping	4	0.22	Negative
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	Radiator	Metal	Tan	Flaking	3	0.25	Negative
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	W2	CMU	Tan	Chipping	4	0.24	Negative
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	W3	CMU	Tan	Chipping	4	0.19	Negative
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	W4	Concrete	Tan	Chipping	4	0.1	Negative
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	Stair Soffit	Metal	Black	Friction	1	0.15	Negative
4470	1	1	S2	Stairwell 2 by Cafeteria	yes	Stringer	Metal	Black	Friction	4	0.23	Negative
4470	1	1	116	Special Education Office 116	yes	W1	CMU	Blue	None	0	0	Negative
4470	1	1	116	Special Education Office 116	yes	Door Frame	Metal	Black	Friction	2	0.2	Negative
4470	1	1	116	Special Education Office 116	yes	Door	Wood	Blue	Friction	1	0.02	Negative
4470	1	1	116	Special Education Office 116	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	1	116	Special Education Office 116	yes	W2	CMU	Blue	None	0	0	Negative
4470	1	1	116	Special Education Office 116	yes	W3	CMU	Blue	None	0	0	Negative
4470	1	1	116	Special Education Office 116	yes	W4	CMU	Blue	None	0	0	Negative
4470	1	1	116	Special Education Office 116	yes	Ceiling	Plaster	White	Cracking	2	0	Negative
4470	1	1	116	Special Education Office 116	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	117	Office 117	yes	W1	CMU	Blue	Chipping	10	0	Negative
4470	1	1	117	Office 117	yes	Door Frame	Metal	Black	Friction	1	0.41	Negative
4470	1	1	117	Office 117	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	1	117	Office 117	yes	W2	CMU	Blue	Chipping	6	0	Negative
4470	1	1	117	Office 117	yes	W3	CMU	Blue	Chipping	5	0	Negative
4470	1	1	117	Office 117	yes	W4	CMU	Blue	Chipping	8	0	Negative
4470	1	1	117	Office 117	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	117	Office 117	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	118	Nurse Area Waiting Area	yes	W1	CMU	White	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21			School District of Philadelphia					
				Name of Inspector: Ryan Hutsell			Lead Safe Certification Assessment Report					
				Inspection Company: Synertech, Inc.			R. R. Wright ES School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	118	Nurse Area Waiting Area	yes	W1	Concrete	Grey	Flaking	1	0	Negative
4470	1	1	118	Nurse Area Waiting Area	yes	Door Frame	Metal	Black	Friction	1	0.28	Negative
4470	1	1	118	Nurse Area Waiting Area	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	118	Nurse Area Waiting Area	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	118	Nurse Area Waiting Area	yes	Door Frame	Metal	Black	Friction	1	0.41	Negative
4470	1	1	118	Nurse Area Waiting Area	yes	Door	Wood	Blue	Friction	1	0.12	Negative
4470	1	1	118	Nurse Area Waiting Area	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	118	Nurse Area Waiting Area	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	1	118	Nurse Area Waiting Area	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	118	Nurse Area Waiting Area	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	118	Nurse Area Waiting Area	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	118	Nurse Area Waiting Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119	Nurse's Office 119	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	119	Nurse's Office 119	yes	Closet Shelf	Wood	Tan	Friction	2	0	Negative
4470	1	1	119	Nurse's Office 119	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	119	Nurse's Office 119	yes	Pipe	Metal	White	Chipping	2	0.18	Negative
4470	1	1	119	Nurse's Office 119	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	119	Nurse's Office 119	yes	Univent	Metal	Tan	Chipping	2	0	Negative
4470	1	1	119	Nurse's Office 119	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	119	Nurse's Office 119	yes	Door Frame	Metal	Tan	Friction	1	0	Negative
4470	1	1	119	Nurse's Office 119	yes	Door	Wood	Tan	Friction	2	0	Negative
4470	1	1	119	Nurse's Office 119	yes	Door Frame	Metal	Black	Friction	1	0.32	Negative
4470	1	1	119	Nurse's Office 119	yes	Door	Wood	Tan	Friction	2	0	Negative
4470	1	1	119	Nurse's Office 119	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119	Nurse's Office 119	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119B	Closet in Nurse's Office 119	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	119B	Closet in Nurse's Office 119	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	119B	Closet in Nurse's Office 119	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	119B	Closet in Nurse's Office 119	yes	Shelves	Wood	Tan	Friction	2	0	Negative
4470	1	1	119B	Closet in Nurse's Office 119	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	119B	Closet in Nurse's Office 119	yes	Ceiling	Plaster	White	None	0	N/A	N/A
4470	1	1	119B	Closet in Nurse's Office 119	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119A	Nurse Office 118	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	119A	Nurse Office 118	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	1	119A	Nurse Office 118	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	1	119A	Nurse Office 118	yes	Door Frame	Wood	Grey	Friction	1	0	Negative
4470	1	1	119A	Nurse Office 118	yes	Door	Wood	Grey	Friction	1	0	Negative
4470	1	1	119A	Nurse Office 118	yes	Closet Shelf	Wood	Grey	Friction	3	0	Negative
4470	1	1	119A	Nurse Office 118	yes	Univent	Metal	Grey	Chipping	2	0.15	Negative
4470	1	1	119A	Nurse Office 118	yes	W2	CMU	White	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
4470	1	1	119A	Nurse Office 118	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	119A	Nurse Office 118	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	119A	Nurse Office 118	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119A	Nurse Office 118	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119B	Cubby Area next to Nurse Restroom	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	119B	Cubby Area next to Nurse Restroom	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	119B	Cubby Area next to Nurse Restroom	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	119B	Cubby Area next to Nurse Restroom	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	119B	Cubby Area next to Nurse Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119B	Cubby Area next to Nurse Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119RR	Nurse's Office Restroom	yes	W1	CMU	Blue	None	0	N/A	N/A
4470	1	1	119RR	Nurse's Office Restroom	yes	Door Frame	Metal	Black	Friction	1	0.38	Negative
4470	1	1	119RR	Nurse's Office Restroom	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	119RR	Nurse's Office Restroom	yes	W2	CMU	Blue	None	0	N/A	N/A
4470	1	1	119RR	Nurse's Office Restroom	yes	W3	CMU	Blue	None	0	N/A	N/A
4470	1	1	119RR	Nurse's Office Restroom	yes	W4	CMU	Blue	None	0	N/A	N/A
4470	1	1	119RR	Nurse's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	119RR	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	115	Classroom 115	yes	W1	CMU	White	Friction	20	0	Negative
4470	1	1	115	Classroom 115	yes	Cabinet	Wood	Blue	Friction	2	0	Negative
4470	1	1	115	Classroom 115	yes	Cubbies	Wood	Blue	Friction	10	0	Negative
4470	1	1	115	Classroom 115	yes	W2	CMU	White	Chipping	2	0	Negative
4470	1	1	115	Classroom 115	yes	Cubbies	Wood	Green	Friction	6	0	Negative
4470	1	1	115	Classroom 115	yes	W3	CMU	White	Chipping	20	0	Negative
4470	1	1	115	Classroom 115	yes	Univent	Metal	Tan	Chipping	10	0	Negative
4470	1	1	115	Classroom 115	yes	Door	Metal	Brown	Friction	4	0.1	Negative
4470	1	1	115	Classroom 115	yes	Pipe	Metal	White	Flaking	24	0.2	Negative
4470	1	1	115	Classroom 115	yes	W4	CMU	White	None	0	0.08	Negative
4470	1	1	115	Classroom 115	yes	Ceiling	Concrete	White	Flaking	32	0.1	Negative
4470	1	1	115	Classroom 115	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	115A	Classroom 115 Closet	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	115A	Classroom 115 Closet	yes	Door Frame	Metal	Black	Chipping	1	0.5	Negative
4470	1	1	115A	Classroom 115 Closet	yes	Door	Wood	White	Chipping	1	0.04	Negative
4470	1	1	115A	Classroom 115 Closet	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	115A	Classroom 115 Closet	yes	Shelves	Wood	White	Friction	10	0	Negative
4470	1	1	115A	Classroom 115 Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	115A	Classroom 115 Closet	yes	Shelves	Wood	White	Friction	5	0	Negative
4470	1	1	115A	Classroom 115 Closet	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	115A	Classroom 115 Closet	yes	Shelves	Wood	White	Friction	10	0	Negative
4470	1	1	115A	Classroom 115 Closet	yes	Ceiling	Concrete	White	Cracking	12	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	115A	Classroom 115 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	115B	Classroom 115 Restroom	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	115B	Classroom 115 Restroom	yes	Door Frame	Metal	Black	Friction	1	0.23	Negative
4470	1	1	115B	Classroom 115 Restroom	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	115B	Classroom 115 Restroom	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	115B	Classroom 115 Restroom	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	115B	Classroom 115 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	115B	Classroom 115 Restroom	yes	Floor	Concrete	Grey	Cracking	1	0	Negative
4470	1	1	114	Classroom 114	yes	W1	CMU	White	Chipping	2	0	Negative
4470	1	1	114	Classroom 114	yes	Door Frame	Metal	Black	Friction	2	0.34	Negative
4470	1	1	114	Classroom 114	yes	Cubbies	Wood	White	Friction	8	0	Negative
4470	1	1	114	Classroom 114	yes	Cubbies	Wood	Green	Friction	8	0	Negative
4470	1	1	114	Classroom 114	yes	W2	CMU	White	Chipping	2	0	Negative
4470	1	1	114	Classroom 114	yes	Cabinet	Wood	Green	Friction	2	0	Negative
4470	1	1	114	Classroom 114	yes	W3	CMU	White	Chipping	2	0	Negative
4470	1	1	114	Classroom 114	yes	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
4470	1	1	114	Classroom 114	yes	Door	Metal	Tan	Chipping	2	0.12	Negative
4470	1	1	114	Classroom 114	yes	Column	Concrete	Grey	Chipping	1	0	Negative
4470	1	1	114	Classroom 114	yes	W4	CMU	White	Chipping	2	0	Negative
4470	1	1	114	Classroom 114	yes	Door Frame	Metal	Black	Friction	1	0.38	Negative
4470	1	1	114	Classroom 114	yes	Door	Wood	Green	Friction	1	0	Negative
4470	1	1	114	Classroom 114	yes	Ceiling	Concrete	White	Chipping	4	0	Negative
4470	1	1	114	Classroom 114	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	114A	Classroom 114 Book Closet	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	114A	Classroom 114 Book Closet	yes	W2	CMU	White	Chipping	2	0	Negative
4470	1	1	114A	Classroom 114 Book Closet	yes	Shelves	Wood	White	Friction	10	0	Negative
4470	1	1	114A	Classroom 114 Book Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	114A	Classroom 114 Book Closet	yes	Shelves	Wood	White	Friction	10	0	Negative
4470	1	1	114A	Classroom 114 Book Closet	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	114A	Classroom 114 Book Closet	yes	Shelves	Wood	White	Friction	10	0	Negative
4470	1	1	114A	Classroom 114 Book Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	114A	Classroom 114 Book Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	114B	Classroom 114 Restroom	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	114B	Classroom 114 Restroom	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	114B	Classroom 114 Restroom	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	114B	Classroom 114 Restroom	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	114B	Classroom 114 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	1	114B	Classroom 114 Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	1	114C	Classroom 114 Storage Closet	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	1	114C	Classroom 114 Storage Closet	yes	W2	CMU	White	Efflorescence	3	0	Negative

				Inspection Dates: 08/30/21-09/14/21			School District of Philadelphia						
				Name of Inspector: Ryan Hutsell			Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.			R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)	
4470	1	1	114C	Classroom 114 Storage Closet	yes	W3	Concrete	White	Flaking	3	0.04	Negative	
4470	1	1	114C	Classroom 114 Storage Closet	yes	W4	Concrete	White	Flaking	3	0	Negative	
4470	1	1	114C	Classroom 114 Storage Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	
4470	1	1	114C	Classroom 114 Storage Closet	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4470	1	1	001B	Storage 1D next to S3 Rear Stairwell	yes	W1	CMU	White	None	0	0	Negative	
4470	1	1	001B	Storage 1D next to S3 Rear Stairwell	yes	W2	CMU	White	None	0	0	Negative	
4470	1	1	001B	Storage 1D next to S3 Rear Stairwell	yes	W3	CMU	White	None	0	0	Negative	
4470	1	1	001B	Storage 1D next to S3 Rear Stairwell	yes	W4	CMU	White	None	0	0	Negative	
4470	1	1	001B	Storage 1D next to S3 Rear Stairwell	yes	Ceiling	Concrete	White	Cracking	3	0	Negative	
4470	1	1	001B	Storage 1D next to S3 Rear Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	W1	CMU	White	None	0	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	W1	CMU	Green	None	0	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	Door Frame	Metal	Black	Friction	2	0.36	Negative	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	W2	CMU	White	None	0	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	W2	CMU	Green	None	0	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	W3	CMU	White	None	0	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	W3	CMU	Green	None	0	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	Door Frame	Metal	Black	Friction	2	0.41	Negative	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	W4	CMU	White	None	0	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	W4	CMU	Green	None	0	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	Door Frame	Metal	Brown	Friction	2	0	Negative	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	Door	Metal	Brown	Friction	2	0	Negative	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	Push Bar	Metal	Grey	Friction	2	0	Negative	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
4470	1	1	H117	Hallway between Office 117 and Cafeteria near Classroom 114	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	W1	CMU	White	None	0	N/A	N/A	

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	W1	CMU	Green	None	0	N/A	N/A
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Door	Wood	Blue	Friction	1	0.04	Negative
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	W2	CMU	Green	None	0	N/A	N/A
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Door Frame	Metal	Brown	Friction	2	0	Negative
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Door	Metal	Brown	Friction	2	0	Negative
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Push Bar	Metal	Grey	Friction	2	0	Negative
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	W3	CMU	Green	None	0	N/A	N/A
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Door Frame	Metal	Black	Friction	1	0.34	Negative
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Door	Wood	Blue	Friction	1	0	Negative
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	W4	CMU	Green	None	0	N/A	N/A
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	H120	Hallway between Classrooms 120 and 122	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	W1	CMU	Orange	Flaking	16	0.24	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	Door Frame	Metal	Orange	Chipping	4	0	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	Door	Metal	Orange	Chipping	4	0	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	Radiator	Metal	Orange	Chipping	6	0.14	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	W2	CMU	Orange	Chipping	1	0.13	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	W3	CMU	Orange	Chipping	1	0.12	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	Door Frame	Metal	Brown	Friction	1	0	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	Door	Metal	Brown	Friction	1	0	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	W4	CMU	Orange	Chipping	8	0.05	Negative
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	Ceiling	Concrete	White				

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	Stair Soffit	Metal	Black	Flaking	10	2	Positive
4470	1	1	S3	Stairwell 3 near Classroom 114	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	2	S20	Stairwell 3 next to Classroom 213	yes	W1	Concrete	Orange	Friction	10	0.2	Negative
4470	1	2	S20	Stairwell 3 next to Classroom 213	yes	W2	CMU	Orange	None	0	N/A	N/A
4470	1	2	S20	Stairwell 3 next to Classroom 213	yes	W3	CMU	Orange	Friction	2	0.15	Negative
4470	1	2	S20	Stairwell 3 next to Classroom 213	yes	W4	CMU	Orange	None	0	N/A	N/A
4470	1	2	S20	Stairwell 3 next to Classroom 213	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	S20	Stairwell 3 next to Classroom 213	yes	Stair Soffit	Metal	Black	Flaking	10	2	Positive
4470	1	2	S20	Stairwell 3 next to Classroom 213	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	2	S20	Stairwell 3 next to Classroom 213	yes	Stringer	Metal	Black	Friction	10	0.5	Negative
4470	1	2	201	Classroom 201	yes	W1	CMU	Blue	Cracking	4	0	Negative
4470	1	2	201	Classroom 201	yes	Door Frame	Metal	Black	Friction	2	0.45	Negative
4470	1	2	201	Classroom 201	yes	Door	Wood	Blue	Chipping	2	0	Negative
4470	1	2	201	Classroom 201	yes	Door	Wood	White	Chipping	2	0	Negative
4470	1	2	201	Classroom 201	yes	W2	CMU	Blue	Cracking	5	0	Negative
4470	1	2	201	Classroom 201	yes	W3	CMU	Blue	Cracking	4	0	Negative
4470	1	2	201	Classroom 201	yes	Univent	Metal	White	Chipping	4	0.1	Negative
4470	1	2	201	Classroom 201	yes	W4	CMU	Blue	Cracking	5	0	Negative
4470	1	2	201	Classroom 201	yes	Sink Cabinet	Metal	Grey	Chipping	2	0.2	Negative
4470	1	2	201	Classroom 201	yes	Door Frame	Wood	White	Chipping	2	0	Negative
4470	1	2	201	Classroom 201	yes	Door	Wood	White	Chipping	2	0	Negative
4470	1	2	201	Classroom 201	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	201	Classroom 201	yes	Ceiling	Concrete	White	Cracking	4	0	Negative
4470	1	2	201	Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	201A	Classroom 201 Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	201A	Classroom 201 Closet	yes	Shelves	Wood	White	Friction	0	0	Negative
4470	1	2	201A	Classroom 201 Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	201A	Classroom 201 Closet	yes	Shelves	Wood	White	Friction	0	0	Negative
4470	1	2	201A	Classroom 201 Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	201A	Classroom 201 Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	201A	Classroom 201 Closet	yes	Shelves	Wood	White	Friction	0	0	Negative
4470	1	2	201A	Classroom 201 Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	201A	Classroom 201 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	202	Classroom 202	yes	W1	CMU	White	Chipping	25	0	Negative
4470	1	2	202	Classroom 202	yes	W1	CMU	Black	Chipping	6	0	Negative
4470	1	2	202	Classroom 202	yes	Vent	Flaking	White	Flaking	4	0.2	Negative
4470	1	2	202	Classroom 202	yes	W2	CMU	White	Chipping	12	0	Negative
4470	1	2	202	Classroom 202	yes	W2	Concrete	White	Chipping	4	0.1	Negative
4470	1	2	202	Classroom 202	yes	W1	CMU	Black	Chipping	6	0	Negative
4470	1	2	202	Classroom 202	yes	Univent	Metal	White	Chipping	12	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	202	Classroom 202	yes	W3	CMU	White	Chipping	8	0	Negative
4470	1	2	202	Classroom 202	yes	W4	CMU	White	Chipping	12	0.04	Negative
4470	1	2	202	Classroom 202	yes	Ceiling	Concrete	White	Flaking	6	0	Negative
4470	1	2	202	Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	203	Classroom 203	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	203	Classroom 203	yes	Door Frame	Metal	Black	Friction	1	0.6	Positive
4470	1	2	203	Classroom 203	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	2	203	Classroom 203	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	203	Classroom 203	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	203	Classroom 203	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	203	Classroom 203	yes	Univent	Metal	White	Chipping	16	0	Negative
4470	1	2	203	Classroom 203	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	203	Classroom 203	yes	Door Frame	Wood	White	Chipping	2	0	Negative
4470	1	2	203	Classroom 203	yes	Door	Wood	White	Chipping	2	0.02	Negative
4470	1	2	203	Classroom 203	yes	Sink Cabinet	Metal	Grey	Chipping	4	0.17	Negative
4470	1	2	203	Classroom 203	yes	Ceiling	Concrete	White	Flaking	6	0	Negative
4470	1	2	203	Classroom 203	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	203D	Classroom 203 Storage Room	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	Door Frame	Metal	Black	Chipping	2	0.4	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	Shelves	Wood	White	Friction	1	0	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	Shelves	Wood	White	Friction	1	0	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	Radiator	Metal	Grey	Chipping	4	0.08	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	203D	Classroom 203 Storage Room	yes	Duct	Metal	White	Flaking	1	0.18	Negative
4470	1	2	203D	Classroom 203 Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	203A	Classroom 203 Large Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	Shelves	Wood	White	Friction	12	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	Bracket	Metal	White	Chipping	1	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	Shelves	Wood	White	Friction	12	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	Shelves	Wood	White	Friction	12	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	Ceiling	Wood	White	None	0	0	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	Duct	Metal	White	None	0	0.15	Negative
4470	1	2	203A	Classroom 203 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	203B	Classroom 203 Small Closet	yes	W1	Wood	White	None	0	0	Negative
4470	1	2	203B	Classroom 203 Small Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	203B	Classroom 203 Small Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	203B	Classroom 203 Small Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	203B	Classroom 203 Small Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	203B	Classroom 203 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	204	Classroom 204	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	204	Classroom 204	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	204	Classroom 204	yes	Sink Cabinet	Metal	Green	Chipping	4	0.21	Negative
4470	1	2	204	Classroom 204	yes	Univent	Metal	White	Chipping	4	0.1	Negative
4470	1	2	204	Classroom 204	yes	Door Frame	Metal	Black	Friction	2	0.36	Negative
4470	1	2	204	Classroom 204	yes	Door	Wood	White	Friction	1	0.1	Negative
4470	1	2	204	Classroom 204	yes	Door Frame	Wood	White	Chipping	2	0	Negative
4470	1	2	204	Classroom 204	yes	Door	Wood	White	Chipping	2	0	Negative
4470	1	2	204	Classroom 204	yes	W2	CMU	Green	None	0	1.4	Positive
4470	1	2	204	Classroom 204	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	204	Classroom 204	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	204	Classroom 204	yes	Ceiling	Concrete	White	Cracking	4	0	Negative
4470	1	2	204	Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	204A	Classroom 204 Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	204A	Classroom 204 Closet	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	204A	Classroom 204 Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	204A	Classroom 204 Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	204A	Classroom 204 Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	204A	Classroom 204 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	205	Classroom 205	yes	W1	CMU	White	Chipping	0	0	Negative
4470	1	2	205	Classroom 205	yes	Univent	Metal	Green	Chipping	4	0.12	Negative
4470	1	2	205	Classroom 205	yes	Closet Panel	Transite	White	Chipping	4	0	Negative
4470	1	2	205	Classroom 205	yes	Shelves	Wood	White	Friction	6	0.08	Negative
4470	1	2	205	Classroom 205	yes	Door Frame	Metal	Black	Friction	2	0.2	Negative
4470	1	2	205	Classroom 205	yes	Door	Wood	Black	Friction	2	0	Negative
4470	1	2	205	Classroom 205	yes	Closet Door Frame	Wood	White	Chipping	4	0	Negative
4470	1	2	205	Classroom 205	yes	Closet Door	Wood	White	Chipping	4	0	Negative
4470	1	2	205	Classroom 205	yes	Sink Cabinet	Metal	Green	Chipping	4	0.23	Negative
4470	1	2	205	Classroom 205	yes	W2	CMU	White	Chipping	0	0.1	Negative
4470	1	2	205	Classroom 205	yes	W2	Concrete	Black	Chipping	2	0	Negative
4470	1	2	205	Classroom 205	yes	Radiator	Metal	Grey	Chipping	4	0.05	Negative
4470	1	2	205	Classroom 205	yes	W3	CMU	White	Chipping	4	0.6	Positive
4470	1	2	205	Classroom 205	yes	W4	CMU	White	Chipping	0	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	205	Classroom 205	yes	W4	Concrete	Black	Chipping	2	0	Negative
4470	1	2	205	Classroom 205	yes	Ceiling	Concrete	White	Flaking	8	0	Negative
4470	1	2	205	Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	205A	Classroom 205 Large Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	205A	Classroom 205 Large Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	205A	Classroom 205 Large Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	205A	Classroom 205 Large Closet	yes	Shelves	Wood	White	Friction	4	0.1	Negative
4470	1	2	205A	Classroom 205 Large Closet	yes	Coat Rack	Wood	White	Friction	1	0	Negative
4470	1	2	205A	Classroom 205 Large Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	205A	Classroom 205 Large Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	205A	Classroom 205 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	Negative
4470	1	2	205B	Classroom 205 Small Closet	yes	W1	Wood	White	None	0	0	Negative
4470	1	2	205B	Classroom 205 Small Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	205B	Classroom 205 Small Closet	yes	W3	Wood	White	None	0	0	Negative
4470	1	2	205B	Classroom 205 Small Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	205B	Classroom 205 Small Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	205B	Classroom 205 Small Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	205B	Classroom 205 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	206	Classroom 206	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	206	Classroom 206	yes	Closet Panel	Transite	White	Chipping	2	0	Negative
4470	1	2	206	Classroom 206	yes	Shelves	Wood	White	Friction	4	0	Negative
4470	1	2	206	Classroom 206	yes	Door Frame	Metal	Black	Friction	2	0.35	Negative
4470	1	2	206	Classroom 206	yes	Door	Wood	Black	Friction	2	0	Negative
4470	1	2	206	Classroom 206	yes	Closet Door Frame	Wood	White	Chipping	1	0	Negative
4470	1	2	206	Classroom 206	yes	Closet Door	Wood	White	Chipping	1	0	Negative
4470	1	2	206	Classroom 206	yes	Sink Cabinet	Metal	Green	Chipping	2	0.15	Negative
4470	1	2	206	Classroom 206	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	206	Classroom 206	yes	Univent	Metal	Grey	Chipping	5	0.1	Negative
4470	1	2	206	Classroom 206	yes	Radiator	Metal	Grey	Chipping	3	0.12	Negative
4470	1	2	206	Classroom 206	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	206	Classroom 206	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	206	Classroom 206	yes	Ceiling	Concrete	White	Flaking	4	0	Negative
4470	1	2	206	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	206A	Classroom 206 Large Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	206A	Classroom 206 Large Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	206A	Classroom 206 Large Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	206A	Classroom 206 Large Closet	yes	Shelves	Wood	White	Friction	4	0	Negative
4470	1	2	206A	Classroom 206 Large Closet	yes	Coat Rack	Wood	White	Chipping	1	0.04	Negative
4470	1	2	206A	Classroom 206 Large Closet	yes	W4	CMU	White	None	0	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	206A	Classroom 206 Large Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	206A	Classroom 206 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	206B	Classroom 206 Small Closet	yes	W1	Wood	White	None	0	0	Negative
4470	1	2	206B	Classroom 206 Small Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	206B	Classroom 206 Small Closet	yes	W3	Wood	White	None	0	0	Negative
4470	1	2	206B	Classroom 206 Small Closet	yes	Shelves	Wood	White	Friction	0	0	Negative
4470	1	2	206B	Classroom 206 Small Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	206B	Classroom 206 Small Closet	yes	Ceiling	Wood	White	None	N/A	N/A	N/A
4470	1	2	206B	Classroom 206 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	207	Classroom 207	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	207	Classroom 207	yes	Closet Panel	Transite	White	Chipping	2	0	Negative
4470	1	2	207	Classroom 207	yes	Shelves	Wood	White	Friction	4	0	Negative
4470	1	2	207	Classroom 207	yes	Door Frame	Metal	Black	Friction	1	0.26	Negative
4470	1	2	207	Classroom 207	yes	Door	Wood	Black	Friction	1	0.1	Negative
4470	1	2	207	Classroom 207	yes	Closet Door Frame	Wood	White	Chipping	1	0.05	Negative
4470	1	2	207	Classroom 207	yes	Closet Door	Wood	White	Chipping	1	0	Negative
4470	1	2	207	Classroom 207	yes	Sink Cabinet	Metal	Blue	Chipping	2	0.1	Negative
4470	1	2	207	Classroom 207	yes	Univent	Metal	Tan	Chipping	4	0.06	Negative
4470	1	2	207	Classroom 207	yes	W2	CMU	Orange	None	0	0.4	Negative
4470	1	2	207	Classroom 207	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	207	Classroom 207	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	207	Classroom 207	yes	Ceiling	Concrete	White	Cracking	5	0.1	Negative
4470	1	2	207	Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	207A	Classroom 207 Large Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	207A	Classroom 207 Large Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	207A	Classroom 207 Large Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	207A	Classroom 207 Large Closet	yes	Shelves	Wood	White	Friction	4	0	Negative
4470	1	2	207A	Classroom 207 Large Closet	yes	Coat Rack	Wood	White	Chipping	1	0.04	Negative
4470	1	2	207A	Classroom 207 Large Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	207A	Classroom 207 Large Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	207A	Classroom 207 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	207B	Classroom 207 Small Closet	yes	W1	Wood	White	None	0	0	Negative
4470	1	2	207B	Classroom 207 Small Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	207B	Classroom 207 Small Closet	yes	W3	Wood	White	None	0	0	Negative
4470	1	2	207B	Classroom 207 Small Closet	yes	Shelves	Wood	White	Friction	0	0	Negative
4470	1	2	207B	Classroom 207 Small Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	207B	Classroom 207 Small Closet	yes	Ceiling	Wood	White	None	N/A	N/A	N/A
4470	1	2	207B	Classroom 207 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	208	Classroom 208	yes	W1	CMU	White	Chipping	5	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	208	Classroom 208	yes	Closet Panel	Transite	White	Chipping	4	0	Negative
4470	1	2	208	Classroom 208	yes	Shelves	Wood	White	Friction	12	0	Negative
4470	1	2	208	Classroom 208	yes	Door Frame	Metal	Black	Friction	2	0.36	Negative
4470	1	2	208	Classroom 208	yes	Door	Wood	Black	Friction	2	0	Negative
4470	1	2	208	Classroom 208	yes	Closet Door Frame	Wood	White	Chipping	4	0	Negative
4470	1	2	208	Classroom 208	yes	Closet Door	Wood	White	Chipping	4	0.05	Negative
4470	1	2	208	Classroom 208	yes	Sink Cabinet	Metal	Blue	Chipping	4	0.02	Negative
4470	1	2	208	Classroom 208	yes	W2	CMU	White	Chipping	5	0	Negative
4470	1	2	208	Classroom 208	yes	W2	CMU	Black	Chipping	2	0	Negative
4470	1	2	208	Classroom 208	yes	Univent	Metal	Black	Chipping	3	0	Negative
4470	1	2	208	Classroom 208	yes	Radiator	Metal	Grey	Chipping	4	0.1	Negative
4470	1	2	208	Classroom 208	yes	W3	CMU	White	Chipping	5	0	Negative
4470	1	2	208	Classroom 208	yes	W4	CMU	White	Chipping	5	0	Negative
4470	1	2	208	Classroom 208	yes	W4	CMU	Black	Chipping	2	0	Negative
4470	1	2	208	Classroom 208	yes	Ceiling	Concrete	White	Flaking	8	0	Negative
4470	1	2	208	Classroom 208	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	208A	Classroom 208 Large Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	208A	Classroom 208 Large Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	208A	Classroom 208 Large Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	208A	Classroom 208 Large Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	208A	Classroom 208 Large Closet	yes	Coat Rack	Wood	White	Friction	2	0	Negative
4470	1	2	208A	Classroom 208 Large Closet	yes	Bracket	Wood	White	Friction	1	0	Negative
4470	1	2	208A	Classroom 208 Large Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	208A	Classroom 208 Large Closet	yes	Ceiling	Wood	White	None	0	0	Negative
4470	1	2	208A	Classroom 208 Large Closet	yes	Floor	N/A	White	N/A	N/A	N/A	N/A
4470	1	2	208B	Classroom 208 Small Closet	yes	W1	N/A	White	Friction	1	0	Negative
4470	1	2	208B	Classroom 208 Small Closet	yes	Door Frame	Wood	White	Friction	1	0	Negative
4470	1	2	208B	Classroom 208 Small Closet	yes	Door	Wood	White	None	0	N/A	N/A
4470	1	2	208B	Classroom 208 Small Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	208B	Classroom 208 Small Closet	yes	W3	Wood	White	None	0	N/A	N/A
4470	1	2	208B	Classroom 208 Small Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	208B	Classroom 208 Small Closet	yes	Shelves	Wood	White	Friction	20	0	Negative
4470	1	2	208B	Classroom 208 Small Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	208B	Classroom 208 Small Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	208B	Classroom 208 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	209	Classroom 209	yes	W1	CMU	White	Chipping	1	0	Negative
4470	1	2	209	Classroom 209	yes	Shelves	Wood	White	Friction	6	0	Negative
4470	1	2	209	Classroom 209	yes	Wooden Panel	Wood	White	Cracking	2	0	Negative
4470	1	2	209	Classroom 209	yes	Transite Panel	Transite	White	Chipping	12	0.01	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
4470	1	2	209	Classroom 209	yes	Door Frame	Wood	White	Holes	10	0	Negative
4470	1	2	209	Classroom 209	yes	Door	Wood	White	Cracking	4	0	Negative
4470	1	2	209	Classroom 209	yes	W2	CMU	White	Chipping	20	0	Negative
4470	1	2	209	Classroom 209	yes	W3	CMU	Orange	Chipping	20	0.5	Negative
4470	1	2	209	Classroom 209	yes	W4	CMU	Orange	Chipping	20	0.8	Positive
4470	1	2	209	Classroom 209	yes	Ceiling	Concrete	White	Cracking	4	0.1	Negative
4470	1	2	209	Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	209A	Classroom 209 Large Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	209A	Classroom 209 Large Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	209A	Classroom 209 Large Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	209A	Classroom 209 Large Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	209A	Classroom 209 Large Closet	yes	Coat Rack	Wood	White	Friction	2	0	Negative
4470	1	2	209A	Classroom 209 Large Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	209A	Classroom 209 Large Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	209A	Classroom 209 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	209B	Classroom 209 Small Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	209B	Classroom 209 Small Closet	yes	W2	Wood	White	None	0	0.1	Negative
4470	1	2	209B	Classroom 209 Small Closet	yes	W3	Wood	White	None	0	0	Negative
4470	1	2	209B	Classroom 209 Small Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	209B	Classroom 209 Small Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	209B	Classroom 209 Small Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	209B	Classroom 209 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	210	Classroom 210	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	210	Classroom 210	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	210	Classroom 210	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	210	Classroom 210	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	210	Classroom 210	yes	Ceiling	Concrete	White	Cracking	5	0	Negative
4470	1	2	210	Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	210A	Classroom 210 Large Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	210A	Classroom 210 Large Storage Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	210A	Classroom 210 Large Storage Closet	yes	W3	CMU	White	Cracking	3	0	Negative
4470	1	2	210A	Classroom 210 Large Storage Closet	yes	Shelves	Wood	White	None	0	0	Negative
4470	1	2	210A	Classroom 210 Large Storage Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	210A	Classroom 210 Large Storage Closet	yes	Ceiling	Wood	White	None	0	0	Negative
4470	1	2	210A	Classroom 210 Large Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	210B	Classroom 210 Small Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	210B	Classroom 210 Small Storage Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	210B	Classroom 210 Small Storage Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	210B	Classroom 210 Small Storage Closet	yes	Shelves	Wood	White	None	0	0	Negative
4470	1	2	210B	Classroom 210 Small Storage Closet	yes	W4	Wood	White	None	0	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	210B	Classroom 210 Small Storage Closet	yes	Ceiling	Wood	White	None	0	0	Negative
4470	1	2	210B	Classroom 210 Small Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	211	Classroom 211	yes	W1	CMU	White	Chipping	4	0	Negative
4470	1	2	211	Classroom 211	yes	Door Frame	Metal	Black	Friction	1	0.31	Negative
4470	1	2	211	Classroom 211	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	2	211	Classroom 211	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	211	Classroom 211	yes	Coat Rack	Wood	White	Chipping	1	0	Negative
4470	1	2	211	Classroom 211	yes	Sink Cabinet	Metal	Grey	Chipping	2	0.21	Negative
4470	1	2	211	Classroom 211	yes	W2	Vinyl	White	Chipping	40	0	Negative
4470	1	2	211	Classroom 211	yes	W3	CMU	White	Chipping	4	0	Negative
4470	1	2	211	Classroom 211	yes	W3	Concrete	White	Flaking	12	0	Negative
4470	1	2	211	Classroom 211	yes	Univent	Metal	White	Chipping	10	0.1	Negative
4470	1	2	211	Classroom 211	yes	W4	CMU	White	Chipping	4	0	Negative
4470	1	2	211	Classroom 211	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	211	Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	211A	Classroom 211 Large Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	211A	Classroom 211 Large Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	211A	Classroom 211 Large Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	211A	Classroom 211 Large Closet	yes	Shelves	Wood	White	None	0	0	Negative
4470	1	2	211A	Classroom 211 Large Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	211A	Classroom 211 Large Closet	yes	Ceiling	Wood	White	None	0	0	Negative
4470	1	2	211A	Classroom 211 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	211B	Classroom 211 Small Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	211B	Classroom 211 Small Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	211B	Classroom 211 Small Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	211B	Classroom 211 Small Closet	yes	Shelves	Wood	White	None	0	0	Negative
4470	1	2	211B	Classroom 211 Small Closet	yes	W4	Wood	White	None	0	0	Negative
4470	1	2	211B	Classroom 211 Small Closet	yes	Ceiling	Wood	White	None	0	0	Negative
4470	1	2	211B	Classroom 211 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	212	Classroom 212	yes	W1	CMU	Blue	Chipping	2	0	Negative
4470	1	2	212	Classroom 212	yes	Door Frame	Metal	Black	Friction	1	0.32	Negative
4470	1	2	212	Classroom 212	yes	Door	Wood	White	Friction	1	0.04	Negative
4470	1	2	212	Classroom 212	yes	Door Frame	Wood	Green	Chipping	2	0	Negative
4470	1	2	212	Classroom 212	yes	Door	Wood	Green	Chipping	2	0	Negative
4470	1	2	212	Classroom 212	yes	Sink Cabinet	Metal	Grey	Chipping	1	0.2	Negative
4470	1	2	212	Classroom 212	yes	Univent	Metal	White	Chipping	4	0	Negative
4470	1	2	212	Classroom 212	yes	W2	CMU	Blue	Chipping	2	0	Negative
4470	1	2	212	Classroom 212	yes	W3	CMU	Blue	Chipping	1	0	Negative
4470	1	2	212	Classroom 212	yes	Door Frame	Wood	Green	Chipping	2	0	Negative
4470	1	2	212	Classroom 212	yes	Door	Wood	Green	Chipping	2	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	212	Classroom 212	yes	W4	Vinyl	Blue	None	0	0	Negative
4470	1	2	212	Classroom 212	yes	Door Frame	Wood	White	Chipping	2	0	Negative
4470	1	2	212	Classroom 212	yes	Ceiling	Concrete	White	Cracking	4	0.08	Negative
4470	1	2	212	Classroom 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	212B	Classroom 212 Large Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	212B	Classroom 212 Large Closet	yes	W2	Wood	Green	None	0	N/A	N/A
4470	1	2	212B	Classroom 212 Large Closet	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	212B	Classroom 212 Large Closet	yes	Shelves	Wood	Green	Friction	1	0	Negative
4470	1	2	212B	Classroom 212 Large Closet	yes	Coat Rack	Wood	Green	Friction	1	0	Negative
4470	1	2	212B	Classroom 212 Large Closet	yes	W4	Wood	Green	None	0	N/A	N/A
4470	1	2	212B	Classroom 212 Large Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A
4470	1	2	212B	Classroom 212 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	212C	Classroom 212 Small Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	212C	Classroom 212 Small Closet	yes	W2	Wood	Green	None	0	N/A	N/A
4470	1	2	212C	Classroom 212 Small Closet	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	212C	Classroom 212 Small Closet	yes	Shelves	Wood	White	Friction	1	0	Negative
4470	1	2	212C	Classroom 212 Small Closet	yes	W4	Wood	Green	None	0	N/A	N/A
4470	1	2	212C	Classroom 212 Small Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A
4470	1	2	212C	Classroom 212 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	213	Classroom 213	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	213	Classroom 213	yes	Door Frame	Metal	Black	Friction	1	0.5	Negative
4470	1	2	213	Classroom 213	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	2	213	Classroom 213	yes	Door Frame	Wood	White	Chipping	2	0.1	Negative
4470	1	2	213	Classroom 213	yes	Door	Wood	White	Chipping	2	0	Negative
4470	1	2	213	Classroom 213	yes	Sink Cabinet	Metal	Blue	Chipping	2	0.16	Negative
4470	1	2	213	Classroom 213	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	213	Classroom 213	yes	W2	Vinyl	White	Chipping	4	0	Negative
4470	1	2	213	Classroom 213	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	213	Classroom 213	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	213	Classroom 213	yes	Univent	Metal	Tan	Chipping	2	0	Negative
4470	1	2	213	Classroom 213	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	213	Classroom 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	213B	Classroom 213 Larger Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	213B	Classroom 213 Larger Closet	yes	W2	Wood	Green	None	0	N/A	N/A
4470	1	2	213B	Classroom 213 Larger Closet	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	213B	Classroom 213 Larger Closet	yes	Shelves	Wood	Green	Friction	1	0	Negative
4470	1	2	213B	Classroom 213 Larger Closet	yes	Coat Rack	Wood	Green	Friction	1	0	Negative
4470	1	2	213B	Classroom 213 Larger Closet	yes	W4	Wood	Green	None	0	N/A	N/A
4470	1	2	213B	Classroom 213 Larger Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A
4470	1	2	213B	Classroom 213 Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21			School District of Philadelphia						
				Name of Inspector: Ryan Hutsell			Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.			R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
4470	1	2	213C	Classroom 213 Smaller Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	
4470	1	2	213C	Classroom 213 Smaller Closet	yes	W2	Wood	Green	None	0	N/A	N/A	
4470	1	2	213C	Classroom 213 Smaller Closet	yes	W3	CMU	Green	None	0	0	Negative	
4470	1	2	213C	Classroom 213 Smaller Closet	yes	Shelves	Wood	White	Friction	1	0	Negative	
4470	1	2	213C	Classroom 213 Smaller Closet	yes	W4	Wood	Green	None	0	N/A	N/A	
4470	1	2	213C	Classroom 213 Smaller Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A	
4470	1	2	213C	Classroom 213 Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
4470	1	2	213A	Boys' Restroom outside Boys' 213	yes	W1	CMU	Blue	None	0	N/A	N/A	
4470	1	2	213A	Boys' Restroom outside Classroom 213	yes	W2	CMU	Blue	None	0	N/A	N/A	
4470	1	2	213A	Boys' Restroom outside Classroom 213	yes	W3	CMU	Blue	None	0	N/A	N/A	
4470	1	2	213A	Boys' Restroom outside Classroom 213	yes	Radiator	Metal	Blue	Chipping	1	0.14	Negative	
4470	1	2	213A	Boys' Restroom outside Classroom 213	yes	W4	CMU	Blue	None	0	N/A	N/A	
4470	1	2	213A	Boys' Restroom outside Classroom 213	yes	Ceiling	Concrete	White	Efflorescence	2	0.1	Negative	
4470	1	2	213A	Boys' Restroom outside Classroom 213	yes	Floor	Concrete	Grey	Chipping	1	0	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	W1	CMU	White	None	0	0	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	W2	CMU	White	None	0	0	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	Shelves	Wood	White	Friction	20	0.14	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	W3	CMU	White	None	0	0	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	Shelves	Wood	White	Friction	20	0.12	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	W4	CMU	White	None	0	0	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	Shelves	Wood	White	Friction	20	0.04	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	Ceiling	Concrete	White	None	0	0.08	Negative	
4470	1	2	2C	Storage Room 2C next to Boys Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
4470	1	2	214	Classroom 214	yes	W1	CMU	White	None	0	0	Negative	
4470	1	2	214	Classroom 214	yes	Door Frame	Metal	Black	Friction	1	0.45	Negative	
4470	1	2	214	Classroom 214	yes	Door	Wood	White	Friction	1	0.05	Negative	
4470	1	2	214	Classroom 214	yes	Door Frame	Wood	White	Chipping	2	0	Negative	

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
4470	1	2	214	Classroom 214	yes	Door	Wood	White	Chipping	2	0	Negative
4470	1	2	214	Classroom 214	yes	Univent	Metal	Tan	Chipping	4	0	Negative
4470	1	2	214	Classroom 214	yes	Vent	Metal	White	Chipping	1	0.14	Negative
4470	1	2	214	Classroom 214	yes	Sink Cabinet	Metal	Blue	Chipping	2	0.21	Negative
4470	1	2	214	Classroom 214	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	214	Classroom 214	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	214	Classroom 214	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	214	Classroom 214	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	214	Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	214A	Classroom 214 - Larger Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	214A	Classroom 214 - Larger Closet	yes	W2	Wood	Green	None	0	N/A	N/A
4470	1	2	214A	Classroom 214 - Larger Closet	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	214A	Classroom 214 - Larger Closet	yes	Shelves	Wood	Green	Friction	1	0	Negative
4470	1	2	214A	Classroom 214 - Larger Closet	yes	Coat Rack	Wood	Green	Friction	1	0	Negative
4470	1	2	214A	Classroom 214 - Larger Closet	yes	W4	Wood	Green	None	0	N/A	N/A
4470	1	2	214A	Classroom 214 - Larger Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A
4470	1	2	214A	Classroom 214 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	214B	Classroom 214 - Smaller Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	214B	Classroom 214 - Smaller Closet	yes	W2	Wood	Green	None	0	N/A	N/A
4470	1	2	214B	Classroom 214 - Smaller Closet	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	214B	Classroom 214 - Smaller Closet	yes	Shelves	Wood	White	Friction	1	0	Negative
4470	1	2	214B	Classroom 214 - Smaller Closet	yes	W4	Wood	Green	None	0	N/A	N/A
4470	1	2	214B	Classroom 214 - Smaller Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A
4470	1	2	214B	Classroom 214 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	W1	CMU	White	None	0	0.02	Negative
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	Shelves	Wood	White	None	0	0	Negative
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	Shelves	Wood	White	None	0	0	Negative
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	Shelves	Wood	White	None	0	0	Negative
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	Ceiling	Concrete	White	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	2D	Storage Room 2D next to Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	215	Classroom 215	yes	W1	CMU	White	Cracking	2	0	Negative
4470	1	2	215	Classroom 215	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	2	215	Classroom 215	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	2	215	Classroom 215	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	215	Classroom 215	yes	W3	CMU	White	None	0	0.05	Negative
4470	1	2	215	Classroom 215	yes	Univent	Metal	Black	Chipping	2	0	Negative
4470	1	2	215	Classroom 215	yes	Sink Cabinet	Metal	Black	Chipping	1	0.1	Negative
4470	1	2	215	Classroom 215	yes	W4	CMU	White	None	0	0.02	Negative
4470	1	2	215	Classroom 215	yes	Door Frame	Metal	Black	Friction	1	0.4	Negative
4470	1	2	215	Classroom 215	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	2	215	Classroom 215	yes	Window Frame	Metal	Black	Chipping	1	0.31	Negative
4470	1	2	215	Classroom 215	yes	Ceiling	Concrete	White	Cracking	5	0	Negative
4470	1	2	215	Classroom 215	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	215A	Classroom 215 Closet adjacent to Coat Area	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	215A	Classroom 215 Closet adjacent to Coat Area	yes	W2	Wood	Green	None	0	N/A	N/A
4470	1	2	215A	Classroom 215 Closet adjacent to Coat Area	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	215A	Classroom 215 Closet adjacent to Coat Area	yes	Shelves	Wood	Green	Friction	1	0	Negative
4470	1	2	215A	Classroom 215 Closet adjacent to Coat Area	yes	Coat Rack	Wood	Green	Friction	1	0	Negative
4470	1	2	215A	Classroom 215 Closet adjacent to Coat Area	yes	W4	Wood	Green	None	0	N/A	N/A
4470	1	2	215A	Classroom 215 Closet adjacent to Coat Area	yes	Ceiling	Wood	Green	None	0	N/A	N/A
4470	1	2	215A	Classroom 215 Closet adjacent to Coat Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	215B	Classroom 215 Closet adjacent to Storage Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	215B	Classroom 215 Closet adjacent to Storage Room	yes	W2	Wood	Green	None	0	N/A	N/A
4470	1	2	215B	Classroom 215 Closet adjacent to Storage Room	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	215B	Classroom 215 Closet adjacent to Storage Room	yes	Shelves	Wood	White	Friction	1	0	Negative
4470	1	2	215B	Classroom 215 Closet adjacent to Storage Room	yes	W4	Wood	Green	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	215B	Classroom 215 Closet adjacent to Storage Room	yes	Ceiling	Wood	Green	None	0	N/A	N/A
4470	1	2	215B	Classroom 215 Closet adjacent to Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	215A	Storage Room in Classroom 215	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	215A	Storage Room in Classroom 215	yes	Door Frame	Metal	Black	Friction	1	0.21	Negative
4470	1	2	215A	Storage Room in Classroom 215	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	215A	Storage Room in Classroom 215	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	215A	Storage Room in Classroom 215	yes	Radiator	Metal	Orange	Chipping	1	0.35	Negative
4470	1	2	215A	Storage Room in Classroom 215	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	215A	Storage Room in Classroom 215	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	215A	Storage Room in Classroom 215	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	216	Classroom 216	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	216	Classroom 216	yes	Door Frame	Metal	Black	Friction	1	0.37	Negative
4470	1	2	216	Classroom 216	yes	Door	Wood	White	Friction	1	0.04	Negative
4470	1	2	216	Classroom 216	yes	Window Frame	Metal	Black	Chipping	3	0.29	Negative
4470	1	2	216	Classroom 216	yes	Univent	Metal	White	Chipping	2	0.1	Negative
4470	1	2	216	Classroom 216	yes	Vent	Metal	White	Chipping	1	0.14	Negative
4470	1	2	216	Classroom 216	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	216	Classroom 216	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	216	Classroom 216	yes	Door Frame	Metal	Black	Friction	1	0.26	Negative
4470	1	2	216	Classroom 216	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	2	216	Classroom 216	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	216	Classroom 216	yes	Door Frame	Wood	White	Chipping	1	0	Negative
4470	1	2	216	Classroom 216	yes	Door	Wood	White	Chipping	1	0	Negative
4470	1	2	216	Classroom 216	yes	Transite Panel	Transite	White	Chipping	2	0	Negative
4470	1	2	216	Classroom 216	yes	Sink Cabinet	Metal	Orange	Flaking	4	0.9	Positive
4470	1	2	216	Classroom 216	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	216	Classroom 216	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	216B	Classroom 216 - Larger Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	216B	Classroom 216 - Larger Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	216B	Classroom 216 - Larger Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	216B	Classroom 216 - Larger Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	216B	Classroom 216 - Larger Closet	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	216B	Classroom 216 - Larger Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	216B	Classroom 216 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	216C	Classroom 216 - Smaller Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	216C	Classroom 216 - Smaller Closet	yes	W2	Wood	White	None	0	0	Negative
4470	1	2	216C	Classroom 216 - Smaller Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	216C	Classroom 216 - Smaller Closet	yes	Coat Rack	Wood	White	Friction	2	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	216C	Classroom 216 - Smaller Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	216C	Classroom 216 - Smaller Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	216C	Classroom 216 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	Shelves	Wood	White	Friction	6	0.12	Negative
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	Shelves	Wood	White	Friction	6	0.1	Negative
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	Beam	Metal	White	Chipping	4	0.1	Negative
4470	1	2	2E	Storage Room next to the Elevator across from Classroom 216	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	1	E1	Elevator	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	E1	Elevator	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	E1	Elevator	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	E1	Elevator	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	E1	Elevator	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	1	E1	Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	W1	CMU	White	Cracking	1	0	Negative
4470	1	2	230	Men's Restroom next to 200 Office	yes	W1	CMU	Blue	None	0	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	Stall Divider	Metal	Grey	Flaking	6	0.08	Negative
4470	1	2	230	Men's Restroom next to 200 Office	yes	Stall Divider	Metal	Blue	Chipping	2	0	Negative
4470	1	2	230	Men's Restroom next to 200 Office	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	W2	CMU	Blue	None	0	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	W3	CMU	Blue	None	0	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	W4	CMU	Blue	None	0	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	230	Men's Restroom next to 200 Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	2	217	Classroom 217	yes	W1	CMU	Blue	None	0	0	Negative
4470	1	2	217	Classroom 217	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	217	Classroom 217	yes	Door	Wood	Green	Friction	1	0	Negative
4470	1	2	217	Classroom 217	yes	Door Frame	Wood	Green	Chipping	2	0	Negative
4470	1	2	217	Classroom 217	yes	Door	Wood	Blue	Chipping	2	0	Negative
4470	1	2	217	Classroom 217	yes	Shelves	Wood	Green	Friction	2	0	Negative
4470	1	2	217	Classroom 217	yes	Coat Rack	Wood	White	Friction	2	0	Negative
4470	1	2	217	Classroom 217	yes	Univent	Metal	Green	Chipping	2	0.16	Negative
4470	1	2	217	Classroom 217	yes	W2	CMU	Green	Chipping	2	0.12	Negative
4470	1	2	217	Classroom 217	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	217	Classroom 217	yes	W4	CMU	Green	None	0	0	Negative
4470	1	2	217	Classroom 217	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	217	Classroom 217	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	217A	Classroom 217 - Larger Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	217A	Classroom 217 - Larger Closet	yes	W2	Wood	Black	None	0	N/A	N/A
4470	1	2	217A	Classroom 217 - Larger Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	217A	Classroom 217 - Larger Closet	yes	Shelves	Wood	Black	Friction	1	0	Negative
4470	1	2	217A	Classroom 217 - Larger Closet	yes	W4	Wood	Black	None	0	N/A	N/A
4470	1	2	217A	Classroom 217 - Larger Closet	yes	Ceiling	Wood	Black	None	0	N/A	N/A
4470	1	2	217A	Classroom 217 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	217B	Classroom 217 - Smaller Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	217B	Classroom 217 - Smaller Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	217B	Classroom 217 - Smaller Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	217B	Classroom 217 - Smaller Closet	yes	Shelves	Wood	Black	Friction	1	0	Negative
4470	1	2	217B	Classroom 217 - Smaller Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	217B	Classroom 217 - Smaller Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	217B	Classroom 217 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	218	Classroom 218	yes	W1	CMU	Blue	None	0	0	Negative
4470	1	2	218	Classroom 218	yes	Door Frame	Metal	Black	Friction	1	0.28	Negative
4470	1	2	218	Classroom 218	yes	Door	Wood	Green	Friction	1	0	Negative
4470	1	2	218	Classroom 218	yes	Door Frame	Wood	Green	Chipping	2	0	Negative
4470	1	2	218	Classroom 218	yes	Door	Wood	Blue	Chipping	2	0	Negative
4470	1	2	218	Classroom 218	yes	Shelves	Wood	Green	Friction	2	0.08	Negative
4470	1	2	218	Classroom 218	yes	Coat Rack	Wood	White	Friction	2	0	Negative
4470	1	2	218	Classroom 218	yes	Pipe	Metal	White	Chipping	2	0.32	Negative
4470	1	2	218	Classroom 218	yes	W2	CMU	Green	None	0	0	Negative
4470	1	2	218	Classroom 218	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	218	Classroom 218	yes	W4	CMU	Green	None	0	0	Negative
4470	1	2	218	Classroom 218	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	218	Classroom 218	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	218A	Classroom 218 - Larger Closet	yes	W1	CMU	White	None	None	0	Negative
4470	1	2	218A	Classroom 218 - Larger Closet	yes	W2	CMU	White	None	None	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	218A	Classroom 218 - Larger Closet	yes	W3	CMU	White	None	None	0	Negative
4470	1	2	218A	Classroom 218 - Larger Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	218A	Classroom 218 - Larger Closet	yes	W4	CMU	White	None	None	0	Negative
4470	1	2	218A	Classroom 218 - Larger Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	218A	Classroom 218 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	218B	Classroom 218 - Smaller Closet	yes	W1	CMU	White	None	None	0	Negative
4470	1	2	218B	Classroom 218 - Smaller Closet	yes	W2	CMU	White	None	None	0	Negative
4470	1	2	218B	Classroom 218 - Smaller Closet	yes	W3	CMU	White	None	None	0	Negative
4470	1	2	218B	Classroom 218 - Smaller Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	218B	Classroom 218 - Smaller Closet	yes	W4	CMU	White	None	None	0	Negative
4470	1	2	218B	Classroom 218 - Smaller Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	218B	Classroom 218 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	S218	Stairwell next to Classrooms 218 and 220	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	S218	Stairwell next to Classrooms 218 and 220	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	S218	Stairwell next to Classrooms 218 and 220	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	S218	Stairwell next to Classrooms 218 and 220	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	S218	Stairwell next to Classrooms 218 and 220	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	S218	Stairwell next to Classrooms 218 and 220	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	220	Classroom 220	yes	W1	CMU	Blue	None	0	0	Negative
4470	1	2	220	Classroom 220	yes	Door Frame	Metal	Black	Friction	1	0.35	Negative
4470	1	2	220	Classroom 220	yes	Door	Wood	Green	Friction	1	0	Negative
4470	1	2	220	Classroom 220	yes	Door Frame	Wood	Green	Chipping	2	0.04	Negative
4470	1	2	220	Classroom 220	yes	Door	Wood	Blue	Chipping	2	0.02	Negative
4470	1	2	220	Classroom 220	yes	Shelves	Wood	Green	Friction	2	0	Negative
4470	1	2	220	Classroom 220	yes	Coat Rack	Wood	White	Friction	2	0	Negative
4470	1	2	220	Classroom 220	yes	Pipe	Metal	White	Chipping	2	0.4	Negative
4470	1	2	220	Classroom 220	yes	W2	CMU	Green	None	0	0	Negative
4470	1	2	220	Classroom 220	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	220	Classroom 220	yes	W4	CMU	Green	None	0	0	Negative
4470	1	2	220	Classroom 220	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	220	Classroom 220	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	220A	Classroom 220 - Larger Closet	yes	W1	CMU	White	None	None	0	Negative
4470	1	2	220A	Classroom 220 - Larger Closet	yes	W2	CMU	White	None	None	0	Negative
4470	1	2	220A	Classroom 220 - Larger Closet	yes	W3	CMU	White	None	None	0	Negative
4470	1	2	220A	Classroom 220 - Larger Closet	yes	Shelves	Wood	White	Friction	2	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	220A	Classroom 220 - Larger Closet	yes	W4	CMU	White	None	None	0	Negative
4470	1	2	220A	Classroom 220 - Larger Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	220A	Classroom 220 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	220B	Classroom 220 - Smaller Closet	yes	W1	CMU	White	None	None	0	Negative
4470	1	2	220B	Classroom 220 - Smaller Closet	yes	W2	CMU	White	None	None	0	Negative
4470	1	2	220B	Classroom 220 - Smaller Closet	yes	W3	CMU	White	None	None	0	Negative
4470	1	2	220B	Classroom 220 - Smaller Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	220B	Classroom 220 - Smaller Closet	yes	W4	CMU	White	None	None	0	Negative
4470	1	2	220B	Classroom 220 - Smaller Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	220B	Classroom 220 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	219	Classroom 219	yes	W1	CMU	White	Cracking	2	0	Negative
4470	1	2	219	Classroom 219	yes	Door Frame	Metal	Black	Friction	1	0.37	Negative
4470	1	2	219	Classroom 219	yes	Door	Wood	White	Friction	1	0.02	Negative
4470	1	2	219	Classroom 219	yes	Univent	Metal	Tan	Chipping	1	0	Negative
4470	1	2	219	Classroom 219	yes	Shelves	Wood	Blue	Friction	2	0	Negative
4470	1	2	219	Classroom 219	yes	Sink Cabinet	Metal	Tan	Chipping	2	0.2	Negative
4470	1	2	219	Classroom 219	yes	Transite Panel	Transite	Tan	Chipping	2	0	Negative
4470	1	2	219	Classroom 219	yes	W2	CMU	Green	Cracking	1	0	Negative
4470	1	2	219	Classroom 219	yes	W3	CMU	White	Cracking	2	0	Negative
4470	1	2	219	Classroom 219	yes	Door Frame	Metal	Black	Friction	1	0.35	Negative
4470	1	2	219	Classroom 219	yes	Door	Wood	White	Friction	1	0	Negative
4470	1	2	219	Classroom 219	yes	W4	Sheetrock	White	None	0	0	Negative
4470	1	2	219	Classroom 219	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	219	Classroom 219	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	219A	Classroom 219 - Larger Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	219A	Classroom 219 - Larger Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	219A	Classroom 219 - Larger Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	219A	Classroom 219 - Larger Closet	yes	Shelves	Wood	White	Friction	1	0	Negative
4470	1	2	219A	Classroom 219 - Larger Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	219A	Classroom 219 - Larger Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	219A	Classroom 219 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	219B	Classroom 219 - Smaller Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	219B	Classroom 219 - Smaller Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	219B	Classroom 219 - Smaller Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	219B	Classroom 219 - Smaller Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	219B	Classroom 219 - Smaller Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	219B	Classroom 219 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	227	STS Office 227	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	227	STS Office 227	yes	Door Frame	Metal	Black	Friction	1	0.35	Negative
4470	1	2	227	STS Office 227	yes	Door	Wood	White	Chipping	2	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	227	STS Office 227	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	227	STS Office 227	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	227	STS Office 227	yes	W4	Sheetrock	White	Cracking	8	0	Negative
4470	1	2	227	STS Office 227	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	227	STS Office 227	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	227A	STS Office 227 Large Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	227A	STS Office 227 Large Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	227A	STS Office 227 Large Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	227A	STS Office 227 Large Closet	yes	Shelves	Wood	White	Friction	2	0.1	Negative
4470	1	2	227A	STS Office 227 Large Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	227A	STS Office 227 Large Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	227A	STS Office 227 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	227B	STS Office 227 Small Closet	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	227B	STS Office 227 Small Closet	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	227B	STS Office 227 Small Closet	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	227B	STS Office 227 Small Closet	yes	Shelves	Wood	White	Friction	2	0.06	Negative
4470	1	2	227B	STS Office 227 Small Closet	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	227B	STS Office 227 Small Closet	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
4470	1	2	227B	STS Office 227 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	221	Classroom 221	yes	W1	CMU	Blue	None	0	0.03	Negative
4470	1	2	221	Classroom 221	yes	Door Frame	Metal	Black	Friction	1	0.4	Negative
4470	1	2	221	Classroom 221	yes	Window Frame	Metal	Black	Chipping	1	0.2	Negative
4470	1	2	221	Classroom 221	yes	Univent	Metal	White	Chipping	1	0	Negative
4470	1	2	221	Classroom 221	yes	Door Frame	Wood	White	Chipping	8	0	Negative
4470	1	2	221	Classroom 221	yes	W2	CMU	Blue	None	0	0.02	Negative
4470	1	2	221	Classroom 221	yes	W3	CMU	Blue	Chipping	2	0	Negative
4470	1	2	221	Classroom 221	yes	Door Frame	Metal	Blue	Chipping	2	0.2	Negative
4470	1	2	221	Classroom 221	yes	Door	Wood	Blue	Chipping	2	0	Negative
4470	1	2	221	Classroom 221	yes	W4	CMU	Blue	None	0	0	Negative
4470	1	2	221	Classroom 221	yes	Door Frame	Wood	Blue	Chipping	2	0	Negative
4470	1	2	221	Classroom 221	yes	Door	Wood	Blue	Chipping	2	0	Negative
4470	1	2	221	Classroom 221	yes	Ceiling	Concrete	White	Chipping	2	0	Negative
4470	1	2	221	Classroom 221	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	221A	Classroom 221 - Larger Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	221A	Classroom 221 - Larger Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	221A	Classroom 221 - Larger Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	221A	Classroom 221 - Larger Closet	yes	Coat Rack	Wood	White	Friction	20	0	Negative
4470	1	2	221A	Classroom 221 - Larger Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	221A	Classroom 221 - Larger Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	221A	Classroom 221 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	221B	Classroom 221 - Smaller Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	221B	Classroom 221 - Smaller Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	221B	Classroom 221 - Smaller Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	221B	Classroom 221 - Smaller Closet	yes	Shelves	Wood	White	Friction	20	0	Negative
4470	1	2	221B	Classroom 221 - Smaller Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	221B	Classroom 221 - Smaller Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	221B	Classroom 221 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	222	Classroom 222	yes	W1	CMU	Green	Chipping	20	0.1	Negative
4470	1	2	222	Classroom 222	yes	Door Frame	Metal	Silver	Friction	2	0.25	Negative
4470	1	2	222	Classroom 222	yes	Door	Wood	Silver	Friction	1	0	Negative
4470	1	2	222	Classroom 222	yes	Window Frame	Metal	Silver	Friction	2	0.3	Negative
4470	1	2	222	Classroom 222	yes	Door Frame	Wood	Silver	Friction	1	0	Negative
4470	1	2	222	Classroom 222	yes	Door	Wood	Silver	Friction	1	0	Negative
4470	1	2	222	Classroom 222	yes	W2	CMU	Green	Chipping	8	0	Negative
4470	1	2	222	Classroom 222	yes	Sink Cabinet	Metal	Silver	Chipping	2	0.2	Negative
4470	1	2	222	Classroom 222	yes	Univent	Metal	Silver	Chipping	1	0	Negative
4470	1	2	222	Classroom 222	yes	W3	CMU	Green	Chipping	20	0	Negative
4470	1	2	222	Classroom 222	yes	Door Frame	Metal	Silver	Friction	1	0.24	Negative
4470	1	2	222	Classroom 222	yes	Door	Wood	Silver	Friction	1	0	Negative
4470	1	2	222	Classroom 222	yes	W4	CMU	Green	Chipping	8	0.04	Negative
4470	1	2	222	Classroom 222	yes	Ceiling	Concrete	White	Cracking	4	0	Negative
4470	1	2	222	Classroom 222	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	222A	Left Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	222A	Left Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	222A	Left Closet	yes	W3	Wood	White	None	0	N/A	N/A
4470	1	2	222A	Left Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	222A	Left Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	222A	Left Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	222A	Left Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	222B	Right Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	222B	Right Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	222B	Right Closet	yes	W3	Wood	White	None	0	N/A	N/A
4470	1	2	222B	Right Closet	yes	Shelves	Wood	White	Friction	2	0	Negative
4470	1	2	222B	Right Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	222B	Right Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	222B	Right Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	222C	Storage Closet next to Classroom 222	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	222C	Storage Closet next to Classroom 222	yes	W2	CMU	White	None	0	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	222C	Storage Closet next to Classroom 222	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	222C	Storage Closet next to Classroom 222	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	222C	Storage Closet next to Classroom 222	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	222C	Storage Closet next to Classroom 222	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	2F	Closet 2F by Classroom 221	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	2F	Closet 2F by Classroom 221	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	2F	Closet 2F by Classroom 221	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	2F	Closet 2F by Classroom 221	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	2F	Closet 2F by Classroom 221	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	2F	Closet 2F by Classroom 221	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	223	Classroom 223	yes	W1	CMU	White	Chipping	16	0	Negative
4470	1	2	223	Classroom 223	yes	W2	CMU	White	Chipping	8	0.04	Negative
4470	1	2	223	Classroom 223	yes	W2	Vinyl	White	Gouges	5	0	Negative
4470	1	2	223	Classroom 223	yes	W3	CMU	White	Chipping	16	0.6	Negative
4470	1	2	223	Classroom 223	yes	W3	Concrete	White	Chipping	20	0	Negative
4470	1	2	223	Classroom 223	yes	W3	Concrete	Grey	Chipping	10	0	Negative
4470	1	2	223	Classroom 223	yes	W3	Concrete	Black	Chipping	12	0.04	Negative
4470	1	2	223	Classroom 223	yes	Univent	Metal	White	Chipping	4	0	Negative
4470	1	2	223	Classroom 223	yes	W4	CMU	White	Flaking	10	0.02	Negative
4470	1	2	223	Classroom 223	yes	W4	Transite	White	Chipping	10	0	Negative
4470	1	2	223	Classroom 223	yes	Door	Wood	Blue	Chipping	2	0	Negative
4470	1	2	223	Classroom 223	yes	Door Frame	Metal	Black	Chipping	2	0.3	Negative
4470	1	2	223	Classroom 223	yes	Shelves	Wood	White	Chipping	4	0	Negative
4470	1	2	223	Classroom 223	yes	Coat Rack	Wood	White	Chipping	2	0	Negative
4470	1	2	223	Classroom 223	yes	Door Frame	Wood	White	Chipping	1	0	Negative
4470	1	2	223	Classroom 223	yes	Door	Wood	White	Chipping	1	0	Negative
4470	1	2	223	Classroom 223	yes	Ceiling	Concrete	White	Chipping	10	0	Negative
4470	1	2	223	Classroom 223	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	223A	Classroom 223 - Larger Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	223A	Classroom 223 - Larger Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	223A	Classroom 223 - Larger Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	223A	Classroom 223 - Larger Closet	yes	Shelves	Wood	White	Friction	1	0	Negative
4470	1	2	223A	Classroom 223 - Larger Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	223A	Classroom 223 - Larger Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	223A	Classroom 223 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	223B	Classroom 223 - Smaller Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	223B	Classroom 223 - Smaller Closet	yes	W2	Wood	White	None	0	N/A	N/A
4470	1	2	223B	Classroom 223 - Smaller Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	223B	Classroom 223 - Smaller Closet	yes	Shelves	Wood	White	Friction	1	0	Negative
4470	1	2	223B	Classroom 223 - Smaller Closet	yes	W4	Wood	White	None	0	N/A	N/A
4470	1	2	223B	Classroom 223 - Smaller Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	223B	Classroom 223 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	224	Classroom 224	yes	W1	CMU	Green	None	0	0	Negative
4470	1	2	224	Classroom 224	yes	Door Frame	Wood	White	Chipping	2	0	Negative
4470	1	2	224	Classroom 224	yes	Door	Wood	White	Chipping	4	0	Negative
4470	1	2	224	Classroom 224	yes	Sink Cabinet	Metal	Tan	Chipping	2	0.2	Negative
4470	1	2	224	Classroom 224	yes	W2	CMU	Green	None	0	0	Negative
4470	1	2	224	Classroom 224	yes	W2	Concrete	Black	Chipping	2	0	Negative
4470	1	2	224	Classroom 224	yes	Univent	Metal	White	Chipping	2	0.06	Negative
4470	1	2	224	Classroom 224	yes	W3	CMU	Green	None	0	0	Negative
4470	1	2	224	Classroom 224	yes	W3	Concrete	Green	Chipping	6	0	Negative
4470	1	2	224	Classroom 224	yes	W3	Concrete	Grey	Chipping	4	0	Negative
4470	1	2	224	Classroom 224	yes	W4	Vinyl	White	Holes	10	0	Negative
4470	1	2	224	Classroom 224	yes	Door Frame	Metal	Black	Chipping	2	0.21	Negative
4470	1	2	224	Classroom 224	yes	Ceiling	Concrete	White	Cracking	2	0.1	Negative
4470	1	2	224	Classroom 224	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	224B	Classroom 224 - Larger Closet	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	2	224B	Classroom 224 - Larger Closet	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	224B	Classroom 224 - Larger Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	224B	Classroom 224 - Larger Closet	yes	Shelves	Wood	White	Friction	6	0.08	Negative
4470	1	2	224B	Classroom 224 - Larger Closet	yes	Coat Rack	Wood	White	Friction	2	0	Negative
4470	1	2	224B	Classroom 224 - Larger Closet	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	224B	Classroom 224 - Larger Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	224B	Classroom 224 - Larger Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	Shelves	Wood	White	Friction	4	0	Negative
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	Stringer	Metal	Black	Friction	2	0.2	Negative
4470	1	2	224C	Classroom 224 - Smaller Closet	yes	Handrail	Metal	Black	Friction	2	0.15	Negative
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	W1	CMU	Orange	None	0	N/A	N/A
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	W2	CMU	Orange	None	0	N/A	N/A
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	W3	CMU	Orange	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	W4	CMU	Orange	None	0	N/A	N/A
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	Door Frame	Metal	Black	Friction	1	0.2	Negative
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	Door	Metal	Black	None	1	0	Negative
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	Handrail	Metal	Black	Friction	10	0.24	Negative
4470	1	2	S22	Stairwell 5 next to Classroom 224	yes	Stringer	Metal	Black	Friction	10	0.4	Negative
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	Shelves	Wood	White	Friction	6	0	Negative
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	Shelves	Wood	White	Friction	4	0	Negative
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	Shelves	Wood	White	Friction	6	0	Negative
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	2G	Storage Room 2-G across from Classroom 224	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	224A	Girls' Restroom across from Classroom 224	yes	W1	CMU	Pink	None	0	N/A	N/A
4470	1	2	224A	Girls' Restroom across from Classroom 224	yes	W2	CMU	Pink	None	0	N/A	N/A
4470	1	2	224A	Girls' Restroom across from Classroom 224	yes	W3	CMU	Pink	None	0	N/A	N/A
4470	1	2	224A	Girls' Restroom across from Classroom 224	yes	W4	CMU	Pink	None	0	N/A	N/A
4470	1	2	224A	Girls' Restroom across from Classroom 224	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	224A	Girls' Restroom across from Classroom 224	yes	Floor	Concrete	Grey	None	0	N/A	N/A
4470	1	2	225	Office 225	yes	W1	CMU	White	Chipping	3	0	Negative
4470	1	2	225	Office 225	yes	Door Frame	Metal	Black	Friction	1	0.3	Negative
4470	1	2	225	Office 225	yes	Door	Wood	White	Friction	2	0	Negative
4470	1	2	225	Office 225	yes	Door	Wood	Black	Friction	2	0.04	Negative
4470	1	2	225	Office 225	yes	W2	Concrete	White	None	0	0	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	225	Office 225	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	225	Office 225	yes	W4	CMU	White	Flaking	1	0	Negative
4470	1	2	225	Office 225	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	225	Office 225	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	225A	Large Closet in Office 225	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	2	225A	Large Closet in Office 225	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	225A	Large Closet in Office 225	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	225A	Large Closet in Office 225	yes	Shelves	Wood	White	None	0	0.4	Negative
4470	1	2	225A	Large Closet in Office 225	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	225A	Large Closet in Office 225	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	225A	Large Closet in Office 225	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	226	Computer Storage Room	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	226	Computer Storage Room	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	226	Computer Storage Room	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	226	Computer Storage Room	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	226	Computer Storage Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A
4470	1	2	226	Computer Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	W1	CMU	Green	None	0	N/A	N/A
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	Door Frame	Metal	Black	Friction	4	0.43	Negative
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	Door	Wood	White	Friction	4	0	Negative
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	Door	Wood	Blue	Friction	4	0	Negative
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	Radiator	Metal	Grey	Flaking	4	0.05	Negative
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	W2	CMU	Green	None	0	N/A	N/A
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	W3	CMU	Green	None	0	N/A	N/A
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	W4	CMU	Green	None	0	N/A	N/A
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	H20	Hallway between IMC and Computer Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	Door Frame	Metal	Black	Friction	5	0.32	Negative

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	Door	Wood	White	Friction	5	0	Negative
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	Door Frame	Metal	Black	Friction	5	0.43	Negative
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	Door	Wood	White	Friction	5	0	Negative
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	H21	Hallway between Classrooms 213 through 224	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	Door Frame	Metal	Black	Friction	4	0.32	Negative
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	Door	Wood	White	Friction	4	0	Negative
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	Door Frame	Metal	Black	Friction	4	0.4	Negative
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	Door	Wood	White	Friction	4	0	Negative
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	H21A	Hallway between Classrooms 217 and 220	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	200	IMC	yes	W1	CMU	White	Flaking	2	0.5	Negative
4470	1	2	200	IMC	yes	W1	Concrete	White	None	0	N/A	N/A
4470	1	2	200	IMC	yes	Door Frame	Metal	Black	Friction	2	0.23	Negative
4470	1	2	200	IMC	yes	Door	Metal	Black	Friction	2	0.3	Negative
4470	1	2	200	IMC	yes	Window Sill	Wood	Black	Chipping	2	0.3	Negative
4470	1	2	200	IMC	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	200	IMC	yes	W2	Concrete	White	None	0	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
4470	1	2	200	IMC	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	200	IMC	yes	W3	Concrete	White	None	0	N/A	N/A
4470	1	2	200	IMC	yes	Door Frame	Metal	Black	Friction	2	0.22	Negative
4470	1	2	200	IMC	yes	Door	Metal	Black	Friction	2	0.22	Negative
4470	1	2	200	IMC	yes	Window Sill	Wood	Black	Chipping	2	0.25	Negative
4470	1	2	200	IMC	yes	W4	CMU	White	None	1	0.8	Positive
4470	1	2	200	IMC	yes	W4	Concrete	White	None	0	N/A	N/A
4470	1	2	200	IMC	yes	Door Frame	Wood	White	Friction	1	0.29	Negative
4470	1	2	200	IMC	yes	Door	Wood	White	Chipping	4	0.3	Negative
4470	1	2	200	IMC	yes	Window Frame	Metal	Black	Chipping	1	0.1	Negative
4470	1	2	200	IMC	yes	Door Frame	Metal	Black	Friction	2	0.2	Negative
4470	1	2	200	IMC	yes	Door	Wood	White	Friction	2	0.22	Negative
4470	1	2	200	IMC	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	200	IMC	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	200	IMC	yes	Column	Concrete	White	Chipping	1	0	Negative
4470	1	2	200	IMC	yes	Column	Concrete	Grey	Chipping	4	0	Negative
4470	1	2	229	Library Small Storage Closet with Sliding Door	yes	W1	CMU	White	None	0	N/A	N/A
4470	1	2	229	Library Small Storage Closet with Sliding Door	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	229	Library Small Storage Closet with Sliding Door	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	229	Library Small Storage Closet with Sliding Door	yes	W4	CMU	White	None	0	N/A	N/A
4470	1	2	229	Library Small Storage Closet with Sliding Door	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	229	Library Small Storage Closet with Sliding Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	206A	Library Copy Room	yes	W1	CMU	White	Chipping	3	0	Negative
4470	1	2	206A	Library Copy Room	yes	Window Frame	Metal	Black	Friction	4	0.23	Negative
4470	1	2	206A	Library Copy Room	yes	Door Frame	Metal	Black	Friction	2	0.2	Negative
4470	1	2	206A	Library Copy Room	yes	Door	Wood	White	Friction	2	0.15	Negative
4470	1	2	206A	Library Copy Room	yes	W2	CMU	White	None	0	N/A	N/A
4470	1	2	206A	Library Copy Room	yes	Door Frame	Metal	Black	Friction	2	0.2	Negative
4470	1	2	206A	Library Copy Room	yes	Door	Wood	White	Friction	2	0.24	Negative
4470	1	2	206A	Library Copy Room	yes	Window Frame	Metal	Black	Friction	4	0.25	Negative
4470	1	2	206A	Library Copy Room	yes	W3	CMU	White	None	0	N/A	N/A
4470	1	2	206A	Library Copy Room	yes	W4	CMU	White	Chipping	2	0	Negative
4470	1	2	206A	Library Copy Room	yes	Window Frame	Metal	Black	Friction	4	0.19	Negative
4470	1	2	206A	Library Copy Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	206A	Library Copy Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 08/30/21-09/14/21		School District of Philadelphia						
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						
				Inspection Company: Synertech, Inc.		R. R. Wright ES School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	W1	CMU	White	None	0	0	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	Door Frame	Metal	Black	Friction	1	0.21	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	Door	Wood	White	Friction	1	0.17	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	W2	CMU	White	None	0	0	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	W2	Plaster	White	Chipping	16	0	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	Door Frame	Metal	Black	Friction	1	0.21	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	Door	Wood	White	Friction	1	0.19	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	W3	CMU	White	None	0	0	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	W4	CMU	White	None	0	0	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	Door Frame	Metal	Black	Friction	1	0.29	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	Door	Wood	White	Friction	1	0.23	Negative
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4470	1	2	206B	Book Storage adjacent to Library Copy Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A