

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	100	Classroom 100	W1	Concrete	White, Beige	Chipping, Cracking	7 SF	0.3	Negative
2320	1	1	100	Classroom 100	Door Frame	Metal	Brown	Chipping	8 SF	0.2	Negative
2320	1	1	100	Classroom 100	Electrical Conduit Pipe	Metal	White	Chipping	2 SF	0.1	Negative
2320	1	1	100	Classroom 100	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100	Classroom 100	Chalkboard	Metal	Brown	Chipping	3 SF	0.1	Negative
2320	1	1	100	Classroom 100	Bookcase	Wood	Black	Chipping	20 SF	0.1	Negative
2320	1	1	100	Classroom 100	Radiator	Metal	Brown	Chipping	20 SF	0.1	Negative
2320	1	1	100	Classroom 100	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100	Classroom 100	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100	Classroom 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100C	Storage in Classroom 100 next to Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	100C	Storage in Classroom 100 next to Restroom	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	1	100C	Storage in Classroom 100 next to Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	100C	Storage in Classroom 100 next to Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	100C	Storage in Classroom 100 next to Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	100C	Storage in Classroom 100 next to Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	100C	Storage in Classroom 100 next to Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	100D	Classroom 100 Storage Left Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100D	Classroom 100 Storage Left Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100D	Classroom 100 Storage Left Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100D	Classroom 100 Storage Left Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100D	Classroom 100 Storage Left Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100D	Classroom 100 Storage Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100E	Classroom 100 Storage Right Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100E	Classroom 100 Storage Right Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100E	Classroom 100 Storage Right Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100E	Classroom 100 Storage Right Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100E	Classroom 100 Storage Right Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100E	Classroom 100 Storage Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP1	Classroom 100 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	NP1	Classroom 100 Storage Closet	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	1	NP1	Classroom 100 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	NP1	Classroom 100 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	NP1	Classroom 100 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	NP1	Classroom 100 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	NP1	Classroom 100 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	100A	Classroom 100 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100A	Classroom 100 Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100A	Classroom 100 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100A	Classroom 100 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100A	Classroom 100 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	100A	Classroom 100 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101	Classroom 101	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101	Classroom 101	Door Frame	Metal	Brown	Chipping	8 SF	0.4	Negative
2320	1	1	101	Classroom 101	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101	Classroom 101	Pipes	Plastic	White	Chipping	2 SF	0.2	Negative
2320	1	1	101	Classroom 101	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101	Classroom 101	Pipes	Fiberglass Wrap	Beige	Chipping	3 SF	0.2	Negative
2320	1	1	101	Classroom 101	Radiator	Metal	Brown	Chipping	20 SF	0	Negative
2320	1	1	101	Classroom 101	Radiator	Metal	White	Chipping	10 SF	0.2	Negative
2320	1	1	101	Classroom 101	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101	Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101C	Storage in Classroom 101	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101C	Storage in Classroom 101	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101C	Storage in Classroom 101	Door Frame	Metal	Brown	Chipping, Friction	4 AF	0.2	Negative
2320	1	1	101C	Storage in Classroom 101	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101C	Storage in Classroom 101	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101C	Storage in Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101C	Storage in Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Left Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Left Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Left Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Left Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Left Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Right Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Right Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Right Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Right Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Right Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101 D	Classroom 101 Storage Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101A	Classroom 101 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101A	Classroom 101 Restroom	Door Frame	Metal	Brown	Chipping	2 SF	0.2	Negative
2320	1	1	101A	Classroom 101 Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101A	Classroom 101 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101A	Classroom 101 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101A	Classroom 101 Restroom	Radiator	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	1	101A	Classroom 101 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101A	Classroom 101 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101B	Nurse's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101B	Nurse's Office	Door Frame	Metal	Brown	Chipping	3 SF	0.4	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT A	Girard School						
	E l e m e n t	F l o o r									
ULCS#			Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	101B	Nurse's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101B	Nurse's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101B	Nurse's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101B	Nurse's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101B	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101BA	Nurse's Office Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101BA	Nurse's Office Restroom	Door Frame	Metal	Brown	Chipping	3 SF	0.3	Negative
2320	1	1	101BA	Nurse's Office Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101BA	Nurse's Office Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101BA	Nurse's Office Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101BA	Nurse's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	101BA	Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102	IMC (Library)	W1	Concrete	Beige	None	N/A	N/A	N/A
2320	1	1	102	IMC (Library)	Pipe	Metal	Tan	Chipping	1 SF	0.2	Negative
2320	1	1	102	IMC (Library)	Door Frame	Metal	Brown	Chipping	1 SF	0.4	Negative
2320	1	1	102	IMC (Library)	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102	IMC (Library)	W3	Wood	Beige	Flaking	5 SF	0.4	Negative
2320	1	1	102	IMC (Library)	Pipe	Fiberglass Wrap	Beige	Chipping	1 SF	0.2	Negative
2320	1	1	102	IMC (Library)	Radiator	Metal	Beige	Chipping	38 SF	0.1	Negative
2320	1	1	102	IMC (Library)	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102	IMC (Library)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102	IMC (Library)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Storage Closet inside IMC (Library)	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	Unknown	Storage Closet inside IMC (Library)	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	Unknown	Storage Closet inside IMC (Library)	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	Unknown	Storage Closet inside IMC (Library)	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	Unknown	Storage Closet inside IMC (Library)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	Unknown	Storage Closet inside IMC (Library)	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	102A	Office inside IMC	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102A	Office inside IMC	Door Frame	Metal	Brown	Chipping	1 SF	0.4	Negative
2320	1	1	102A	Office inside IMC	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102A	Office inside IMC	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102A	Office inside IMC	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102A	Office inside IMC	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102A	Office inside IMC	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102B	Front Office next to IMC	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102B	Front Office next to IMC	Door Frame	Metal	Brown	Chipping	7 SF	0.4	Negative
2320	1	1	102B	Front Office next to IMC	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102B	Front Office next to IMC	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102B	Front Office next to IMC	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	102B	Front Office next to IMC	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	102B	Front Office next to IMC	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100B	Rear Office next to IMC	W1	Concrete	Blue, Light Green	Chipping	1 SF	0.3	Negative
2320	1	1	100B	Rear Office next to IMC	Door Frame	Metal	Brown	Chipping	1 SF	0.4	Negative
2320	1	1	100B	Rear Office next to IMC	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100B	Rear Office next to IMC	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100B	Rear Office next to IMC	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100B	Rear Office next to IMC	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	100B	Rear Office next to IMC	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP2	Art Teacher's office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP2	Art Teacher's office	Door Frame	Metal	Brown	Chipping	4 SF	0.2	Negative
2320	1	1	NP2	Art Teacher's office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP2	Art Teacher's office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP2	Art Teacher's office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP2	Art Teacher's office	Ceiling	Concrete	White	Spalling	1 SF	0.3	Negative
2320	1	1	NP2	Art Teacher's office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103	Classroom 103	W1	Concrete	White, Beige	Chipping	10 SF	0.3	Negative
2320	1	1	103	Classroom 103	Door Frame	Metal	Brown	Chipping	8 SF	0.2	Negative
2320	1	1	103	Classroom 103	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103	Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103	Classroom 103	Radiator	Metal	Brown	Chipping	15 SF	0	Negative
2320	1	1	103	Classroom 103	Column	Concrete	White, Beige	Chipping	3 SF	0.2	Negative
2320	1	1	103	Classroom 103	Radiator	Metal	White	Chipping	4 SF	0.2	Negative
2320	1	1	103	Classroom 103	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103	Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103	Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103A	Right side Closet in Classroom 103	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	103A	Right side Closet in Classroom 103	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	103A	Right side Closet in Classroom 103	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	103A	Right side Closet in Classroom 103	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	103A	Right side Closet in Classroom 103	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	103A	Right side Closet in Classroom 103	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	1	103B	Left side Closet in Classroom 103	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103B	Left side Closet in Classroom 103	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103B	Left side Closet in Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103B	Left side Closet in Classroom 103	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103B	Left side Closet in Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	103B	Left side Closet in Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104	Storage Room next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104	Storage Room next to Elevator	Pipes	Metal	Brown	Chipping	5 SF	0.2	Negative
2320	1	1	104	Storage Room next to Elevator	Door Frame	Metal	Brown	Chipping	4 SF	0.2	Negative
2320	1	1	104	Storage Room next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	1	104	Storage Room next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104	Storage Room next to Elevator	W4	Concrete	White	Efflorescence	10 SF	0	Negative
2320	1	1	104	Storage Room next to Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104	Storage Room next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104PC	Pipe Chase at Girls Restroom - accessed from Storage Room next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104PC	Pipe Chase at Girls Restroom - accessed from Storage Room next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104PC	Pipe Chase at Girls Restroom - accessed from Storage Room next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104PC	Pipe Chase at Girls Restroom - accessed from Storage Room next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104PC	Pipe Chase at Girls Restroom - accessed from Storage Room next to Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104PC	Pipe Chase at Girls Restroom - accessed from Storage Room next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104A	Custodial Closet next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104A	Custodial Closet next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104A	Custodial Closet next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104A	Custodial Closet next to Elevator	Shelf	Wood	N/A	Flaking	2 SF	0.6	Negative
2320	1	1	104A	Custodial Closet next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	104A	Custodial Closet next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105	Classroom 105	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105	Classroom 105	Door Frame	Metal	Brown	Chipping	3 SF	0.2	Negative
2320	1	1	105	Classroom 105	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105	Classroom 105	Pipe	Fiberglass Wrap	Tan	Chipping	1 SF	0.1	Negative
2320	1	1	105	Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105	Classroom 105	Radiator	Metal	Beige	Chipping	12 SF	0.1	Negative
2320	1	1	105	Classroom 105	Radiator	Metal	Brown	Chipping	17 SF	0	Negative
2320	1	1	105	Classroom 105	Column	Concrete	White, Beige, Tan	Chipping	8 SF	0.2	Negative
2320	1	1	105	Classroom 105	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105	Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105	Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105A	Middle Closet in Classroom 105	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105A	Middle Closet in Classroom 105	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105A	Middle Closet in Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105A	Middle Closet in Classroom 105	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105A	Middle Closet in Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105A	Middle Closet in Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105B	Right Closet in Classroom 105	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105B	Right Closet in Classroom 105	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105B	Right Closet in Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	105B	Right Closet in Classroom 105	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105B	Right Closet in Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	105B	Right Closet in Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	109	Conference Room next to Principal's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	109	Conference Room next to Principal's Office	Door Frame	Metal	Brown	Chipping	8 SF	0.3	Negative
2320	1	1	109	Conference Room next to Principal's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	109	Conference Room next to Principal's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	109	Conference Room next to Principal's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	109	Conference Room next to Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	109	Conference Room next to Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110	Principal's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110	Principal's Office	Door Frame	Metal	Tan	Chipping	6 SF	0.5	Negative
2320	1	1	110	Principal's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110	Principal's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110	Principal's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110	Principal's Office	Radiator	Metal	Tan	Chipping	1 SF	0.2	Negative
2320	1	1	110	Principal's Office	Column	Concrete	White, Tan	Chipping	5 SF	0.1	Negative
2320	1	1	110	Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110B	Storage closet in Principal's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110B	Storage closet in Principal's Office	Door Frame	Metal	Brown	Chipping	2 SF	0.2	Negative
2320	1	1	110B	Storage closet in Principal's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110B	Storage closet in Principal's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110B	Storage closet in Principal's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110B	Storage closet in Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110B	Storage closet in Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110A	Principal's Office Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110A	Principal's Office Restroom	Door Frame	Metal	Brown	Chipping	8 SF	0.1	Negative
2320	1	1	110A	Principal's Office Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110A	Principal's Office Restroom	W3	Concrete	White	Cracking	5 SF	0.5	Negative
2320	1	1	110A	Principal's Office Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110A	Principal's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	110A	Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111	Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111	Main Office	Door Frame	Metal	Tan	Chipping	6 SF	0.1	Negative
2320	1	1	111	Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111	Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111	Main Office	Radiator	Metal	Tan	Chipping	7 SF	0.2	Negative
2320	1	1	111	Main Office	Column	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111	Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	111	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111A	Main Office Storage/IT Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111A	Main Office Storage/IT Closet	Door Frame	Metal	Tan	Chipping	1 SF	0.4	Negative
2320	1	1	111A	Main Office Storage/IT Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111A	Main Office Storage/IT Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111A	Main Office Storage/IT Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111A	Main Office Storage/IT Closet	Pipes	Metal	White, Tan	Chipping	3 SF	0	Negative
2320	1	1	111A	Main Office Storage/IT Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	111A	Main Office Storage/IT Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Main Office Storage Closet/Small Break Area	W1	Concrete	White	Cracking	10 SF	0	Negative
2320	1	1	Unknown	Main Office Storage Closet/Small Break Area	Door Frame	Metal	Brown	Chipping	2 SF	0.4	Negative
2320	1	1	Unknown	Main Office Storage Closet/Small Break Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Main Office Storage Closet/Small Break Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Main Office Storage Closet/Small Break Area	Column	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Main Office Storage Closet/Small Break Area	W4	Concrete	White	Cracking	2 SF	0.3	Negative
2320	1	1	Unknown	Main Office Storage Closet/Small Break Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Main Office Storage Closet/Small Break Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	112	Office inside Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	112	Office inside Main Office	Door Frame	Metal	Tan	Chipping	5 SF	0.3	Negative
2320	1	1	112	Office inside Main Office	Door	Wood	Tan	Friction	3 SF	0	Negative
2320	1	1	112	Office inside Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	112	Office inside Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	112	Office inside Main Office	Pipes	Fiberglass Wrap	White, Tan	Cracking	1 SF	0.1	Negative
2320	1	1	112	Office inside Main Office	Radiator	Metal	Tan	Chipping	5 SF	0.2	Negative
2320	1	1	112	Office inside Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	112	Office inside Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	112	Office inside Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113	Counselor's Office in Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113	Counselor's Office in Main Office	Door Frame	Metal	Brown	Chipping	9 SF	0.4	Negative
2320	1	1	113	Counselor's Office in Main Office	Door	Wood	Black	Chipping	2 SF	0.1	Negative
2320	1	1	113	Counselor's Office in Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113	Counselor's Office in Main Office	Radiator	Metal	Tan	Chipping	10 SF	0.1	Negative
2320	1	1	113	Counselor's Office in Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113	Counselor's Office in Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113	Counselor's Office in Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113	Counselor's Office in Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113A	Counselor's Office Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113A	Counselor's Office Restroom	Door Frame	Metal	Brown	Chipping	1 SF	0.3	Negative
2320	1	1	113A	Counselor's Office Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113A	Counselor's Office Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	1	113A	Counselor's Office Restroom	W4	Concrete	White	Cracking	5 SF	0.3	Negative
2320	1	1	113A	Counselor's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113A	Counselor's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113B	Storage closet in Counselor's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113B	Storage closet in Counselor's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113B	Storage closet in Counselor's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113B	Storage closet in Counselor's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113B	Storage closet in Counselor's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	113B	Storage closet in Counselor's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114	Teacher's Lounge next to Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114	Teacher's Lounge next to Main Office	Baseboard	Ceramic Tile	Gray over Tan	Chipping	4	4.4	Positive
2320	1	1	114	Teacher's Lounge next to Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114	Teacher's Lounge next to Main Office	Door Frame	Metal	Brown	Chipping	4 SF	0.4	Negative
2320	1	1	114	Teacher's Lounge next to Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114	Teacher's Lounge next to Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114	Teacher's Lounge next to Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114	Teacher's Lounge next to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114A	First Storage closet in Teacher's Lounge next to Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114A	First Storage closet in Teacher's Lounge next to Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114A	First Storage closet in Teacher's Lounge next to Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114A	First Storage closet in Teacher's Lounge next to Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114A	First Storage closet in Teacher's Lounge next to Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114A	First Storage closet in Teacher's Lounge next to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114B	Second Storage closet in Teacher's Lounge next to Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114B	Second Storage closet in Teacher's Lounge next to Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114B	Second Storage closet in Teacher's Lounge next to Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114B	Second Storage closet in Teacher's Lounge next to Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114B	Second Storage closet in Teacher's Lounge next to Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	114B	Second Storage closet in Teacher's Lounge next to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	117	Staff Restroom next to Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	117	Staff Restroom next to Main Office	Door Frame	Metal	Brown	Chipping	6 SF	0.2	Negative
2320	1	1	117	Staff Restroom next to Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	1	117	Staff Restroom next to Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	117	Staff Restroom next to Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	117	Staff Restroom next to Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	117	Staff Restroom next to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118	Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118	Girl's Restroom	Door Frame	Metal	Brown	Chipped	3 SF	0.4	Negative
2320	1	1	118	Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118	Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118	Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118	Girl's Restroom	Door Frame	Metal	Brown	Chipped	4 SF	0.4	Negative
2320	1	1	118	Girl's Restroom	Door	Metal	Brown	Chipped	4 SF	0.7	Negative
2320	1	1	118	Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118	Girl's Restroom	Pipe	Fiberglass Wrap	White	Chipped	10 SF	0.6	Negative
2320	1	1	118	Girl's Restroom	Duct	Metal	White	Chipped	1 SF	0.3	Negative
2320	1	1	118	Girl's Restroom	Floor	Concrete	Gray	Cracked	20 SF	0.3	Negative
2320	1	1	118PC	Pipe Chase between boys & girls restrooms - accessed from outside Girls Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118PC	Pipe Chase between boys & girls restrooms - accessed from outside Girls Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118PC	Pipe Chase between boys & girls restrooms - accessed from outside Girls Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118PC	Pipe Chase between boys & girls restrooms - accessed from outside Girls Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118PC	Pipe Chase between boys & girls restrooms - accessed from outside Girls Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	118PC	Pipe Chase between boys & girls restrooms - accessed from outside Girls Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119	Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119	Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119	Boy's Restroom	Door	Metal	Brown	Chipping	5	1.2	Positive
2320	1	1	119	Boy's Restroom	Door Frame	Metal	Brown	Chipping	5 SF	0.6	Negative
2320	1	1	119	Boy's Restroom	W3	Concrete	Tan	Cracking / Flaking	3 SF	0.5	Negative
2320	1	1	119	Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119	Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119	Boy's Restroom	Ducts	Metal	Tan	Chipping	1 SF	0.1	Negative
2320	1	1	119	Boy's Restroom	Floor	Concrete	Gray	Spalling / Flaking	1 SF	0.1	Negative
2320	1	1	119PC	Pipe Chase at Boys Restroom - accessed from outside Boys Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119PC	Pipe Chase at Boys Restroom - accessed from outside Boys Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119PC	Pipe Chase at Boys Restroom - accessed from outside Boys Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	1	119PC	Pipe Chase at Boys Restroom - accessed from outside Boys Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119PC	Pipe Chase at Boys Restroom - accessed from outside Boys Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	119PC	Pipe Chase at Boys Restroom - accessed from outside Boys Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	120	Boy's Restroom inside Cafeteria	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	120	Boy's Restroom inside Cafeteria	Door Frame	Metal	Brown	Chipping	2 SF	0.1	Negative
2320	1	1	120	Boy's Restroom inside Cafeteria	Door	Wood	Yellow	Friction	4 SF	0	Negative
2320	1	1	120	Boy's Restroom inside Cafeteria	Ceiling/Wall Drain Pipe	Metal	Yellow	Moisture Damage	1 SF	0.4	Negative
2320	1	1	120	Boy's Restroom inside Cafeteria	Access Panel	Metal	Brown	Friction	4 SF	0.1	Negative
2320	1	1	120	Boy's Restroom inside Cafeteria	Door Frame	Metal	Brown	Chipped	2 SF	0	Negative
2320	1	1	120	Boy's Restroom inside Cafeteria	Door	Wood	Blue	Friction	5 SF	0.1	Negative
2320	1	1	120	Boy's Restroom inside Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	120	Boy's Restroom inside Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	120	Boy's Restroom inside Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	120	Boy's Restroom inside Cafeteria	Window Vent/Sill	Metal	Brown	Chipping	10 SF	0.1	Negative
2320	1	1	120	Boy's Restroom inside Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	120	Boy's Restroom inside Cafeteria	Duct	Metal	Yellow	Flaking	3 SF	0.3	Negative
2320	1	1	120	Boy's Restroom inside Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	121	Girl's Restroom inside Cafeteria	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	121	Girl's Restroom inside Cafeteria	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	1	121	Girl's Restroom inside Cafeteria	Door	Wood	Yellow	Friction	4 SF	0.1	Negative
2320	1	1	121	Girl's Restroom inside Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	121	Girl's Restroom inside Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	121	Girl's Restroom inside Cafeteria	Pipes	Metal	Yellow	Chipping	4 SF	0.2	Negative
2320	1	1	121	Girl's Restroom inside Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	121	Girl's Restroom inside Cafeteria	Ceiling	Plaster	White	Moisture Damage	1 SF	0	Negative
2320	1	1	121	Girl's Restroom inside Cafeteria	Access Panel	Metal	White	Flaking	4SF	0.1	Negative
2320	1	1	121	Girl's Restroom inside Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	122	Cafeteria	W1	Concrete	Yellow	Chipping	5 SF	0.1	Negative
2320	1	1	122	Cafeteria	Door Frame	Metal	Brown	Chipping	3 SF	0.2	Negative
2320	1	1	122	Cafeteria	Door Frame	Metal	Brown	Chipping	2 SF	0.3	Negative
2320	1	1	122	Cafeteria	Stair Railing	Metal	Gray	Chipping	45 SF	0.2	Negative
2320	1	1	122	Cafeteria	Windowsill	Metal	Yellow	Chipping	2 SF	0.3	Negative
2320	1	1	122	Cafeteria	Stair Tread	Concrete	Brown	Friction	50 SF	0.1	Negative
2320	1	1	122	Cafeteria	Stair Tread	Metal	Black	Friction	25 SF	0.2	Negative
2320	1	1	122	Cafeteria	Vent	Metal	Yellow	Chipping	2 SF	0	Negative
2320	1	1	122	Cafeteria	Door Frame	Metal	Brown	Chipping	3 SF	0.4	Negative
2320	1	1	122	Cafeteria	Door	Metal	Yellow	Flaking	2 SF	0.1	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	122	Cafeteria	Door Frame	Metal	Brown	Chipping	1 SF	0.4	Negative
2320	1	1	122	Cafeteria	W2	Concrete	Orange	Chipping	46 SF	0	Negative
2320	1	1	122	Cafeteria	Column	Concrete	Yellow	Chipping	10 SF	0.2	Negative
2320	1	1	122	Cafeteria	Door Frame	Metal	Brown	Chipping	20 SF	0.7	Negative
2320	1	1	122	Cafeteria	Door	Metal	Red	Chipping	5 SF	0.2	Negative
2320	1	1	122	Cafeteria	Baseboard	Ceramic Tile	Red, Green	Chipping	40	2.9	Positive
2320	1	1	122	Cafeteria	W3	Concrete	Yellow	Friction	40 SF	0	Negative
2320	1	1	122	Cafeteria	Chin Up Bar	Metal	Yellow	Chipping	6 SF	0.4	Negative
2320	1	1	122	Cafeteria	Chin Up Bar Support	Metal	Yellow	Chipping	2 SF	0.2	Negative
2320	1	1	122	Cafeteria	Column	Concrete	Yellow	Chipping	8 SF	0.3	Negative
2320	1	1	122	Cafeteria	Pipe Cover	Metal	Yellow	Chipping	2 SF	0.2	Negative
2320	1	1	122	Cafeteria	W4	Concrete	Green	Chipping	160 SF	0.4	Negative
2320	1	1	122	Cafeteria	Column	Concrete	Yellow	Chipping	5 SF	0.5	Negative
2320	1	1	122	Cafeteria	Baseboard	Ceramic Tile	Blue, Green, Orange	Chipping	50	4.2	Positive
2320	1	1	122	Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	122	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	Coat Rack	Wood	Tan	Chipping	11 SF	0	Negative
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	Coat Rack	Wood	Tan	Chipping	11 SF	0	Negative
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	Shelf	Wood	Tan	Chipping/Friction	20 SF	0	Negative
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP4	Cafeteria Storage Room next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP5	Gym Storage Room next to Entrance Stairs	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP5	Gym Storage Room next to Entrance Stairs	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP5	Gym Storage Room next to Entrance Stairs	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP5	Gym Storage Room next to Entrance Stairs	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP5	Gym Storage Room next to Entrance Stairs	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP5	Gym Storage Room next to Entrance Stairs	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	116	Cafeteria Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	116	Cafeteria Office	Door Frame	Metal	Yellow	Flaking	5 SF	0	Negative
2320	1	1	116	Cafeteria Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	116	Cafeteria Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	116	Cafeteria Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	116	Cafeteria Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	116	Cafeteria Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	115	Kitchen	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	115	Kitchen	Door Frame	Metal	Brown	Chipping	8 SF	0.4	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	115	Kitchen	Conduit @ Door	Metal	Tan	Chipping	3 SF	0.7	Negative
2320	1	1	115	Kitchen	Door	Metal	Brown	Chipping	17 SF	0.3	Negative
2320	1	1	115	Kitchen	Door Frame	Metal	Brown	Chipping	17 SF	0.7	Negative
2320	1	1	115	Kitchen	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	115	Kitchen	Conduit Box/Pipe	Metal	White	Flaking	6 SF	0.1	Negative
2320	1	1	115	Kitchen	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	115	Kitchen	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	115	Kitchen	Pipe	Metal	White	Flaking	2 SF	0.2	Negative
2320	1	1	115	Kitchen	Ceiling	Plaster	White	Flaking	1 SF	0	Negative
2320	1	1	115	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	106	Auditorium	W1	Concrete	Light Blue	Chipping	8 SF	0.4	Negative
2320	1	1	106	Auditorium	Door	Wood	Blue	Chipping	10 SF	0	Negative
2320	1	1	106	Auditorium	W2	Concrete	Light Blue	Chipping	8 SF	0.2	Negative
2320	1	1	106	Auditorium	Radiator	Metal	Brown	Chipping	3 SF	0	Negative
2320	1	1	106	Auditorium	Door	Metal	Brown	Chipping	4 SF	0.5	Negative
2320	1	1	106	Auditorium	Door Frame	Metal	Brown	Chipping	2	1.1	Positive
2320	1	1	106	Auditorium	W3	Concrete	Brown	Chipping	10 SF	0.2	Negative
2320	1	1	106	Auditorium	Door	Metal	Beige	Chipping	15 SF	0.3	Negative
2320	1	1	106	Auditorium	Door Frame	Metal	Brown	Chipping	1 SF	0.3	Negative
2320	1	1	106	Auditorium	W4	Concrete	Light Blue	Chipping	8 SF	0.4	Negative
2320	1	1	106	Auditorium	Radiator	Metal	Beige	Chipping	3 SF	0	Negative
2320	1	1	106	Auditorium	Door	Metal	Blue	Chipping	5 SF	0.2	Negative
2320	1	1	106	Auditorium	Door Frame	Metal	Brown	Chipping	8 SF	0.3	Negative
2320	1	1	106	Auditorium	Stair Riser	Concrete	Brown	Chipping	10 SF	0.2	Negative
2320	1	1	106	Auditorium	Stair Tread	Concrete	Brown	Chipping	10 SF	0.2	Negative
2320	1	1	106	Auditorium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	106	Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	106 STAGE	Auditorium Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	106 STAGE	Auditorium Stage	Pipe	Fiberglass Wrap	White, Beige	Chipping	10 SF	0.1	Negative
2320	1	1	106 STAGE	Auditorium Stage	Column	Drywall	Tan, Green	Chipping	6 SF	0.4	Negative
2320	1	1	106 STAGE	Auditorium Stage	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	106 STAGE	Auditorium Stage	Pipe	Metal	White, Beige	Chipping	20 SF	0.3	Negative
2320	1	1	106 STAGE	Auditorium Stage	Pipe	Fiberglass Wrap / Metal	White, Beige	Chipping	10 SF	0.3	Negative
2320	1	1	106 STAGE	Auditorium Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	106 STAGE	Auditorium Stage	Door	Metal	Orange	Chipping	8 SF	0.1	Negative
2320	1	1	106 STAGE	Auditorium Stage	Door Frame	Metal	Brown	Chipping	10 SF	0.2	Negative
2320	1	1	106 STAGE	Auditorium Stage	W4	Concrete	White, Beige	Chipping	3 SF	0	Negative
2320	1	1	106 STAGE	Auditorium Stage	Door	Metal	Tan	Chipping	5 SF	0.1	Negative
2320	1	1	106 STAGE	Auditorium Stage	Door Frame	Metal	Brown	Chipping	5 SF	0.3	Negative
2320	1	1	106 STAGE	Auditorium Stage	Pipe	Fiberglass Wrap	Beige	Chipping	10 SF	0.2	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	1	106 STAGE	Auditorium Stage	Access Panel	Metal	Beige	Chipping	2 SF	0.2	Negative
2320	1	1	106 STAGE	Auditorium Stage	Ceiling	Concrete	White	Flaking, Spalling	10 SF	0.3	Negative
2320	1	1	106 STAGE	Auditorium Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	107	Men's Restroom next to Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	107	Men's Restroom next to Auditorium	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	1	107	Men's Restroom next to Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	107	Men's Restroom next to Auditorium	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	107	Men's Restroom next to Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	107	Men's Restroom next to Auditorium	Radiator	Metal	Brown	Chipping	3 SF	0.1	Negative
2320	1	1	107	Men's Restroom next to Auditorium	Ceiling	Plaster	White	Efflorescence, Flaking	1 SF	0	Negative
2320	1	1	107	Men's Restroom next to Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	108	Women's Restroom next to Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	108	Women's Restroom next to Auditorium	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	1	108	Women's Restroom next to Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	108	Women's Restroom next to Auditorium	Radiator	Metal	Brown	Chipping	3 SF	0.1	Negative
2320	1	1	108	Women's Restroom next to Auditorium	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	108	Women's Restroom next to Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	108	Women's Restroom next to Auditorium	Ceiling	Plaster	White	Efflorescence, Flaking	2 SF	0	Negative
2320	1	1	108	Women's Restroom next to Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H11	Hallway outside Classrooms 100 - 103	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H11	Hallway outside Classrooms 100 - 103	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H11	Hallway outside Classrooms 100 - 103	Access Panel	Metal	Brown	Chipping	3 SF	0.1	Negative
2320	1	1	H11	Hallway outside Classrooms 100 - 103	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H11	Hallway outside Classrooms 100 - 103	W4	Concrete	Blue	Chipping	10 SF	0.2	Negative
2320	1	1	H11	Hallway outside Classrooms 100 - 103	Security Gate Track	Metal	Brown	Chipping	10 SF	0.2	Negative
2320	1	1	H11	Hallway outside Classrooms 100 - 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H11	Hallway outside Classrooms 100 - 103	Pipe	Metal	Blue	Chipping	2 SF	0.5	Negative
2320	1	1	H11	Hallway outside Classrooms 100 - 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H12	Hallway outside Main Office Suite	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H12	Hallway outside Main Office Suite	Door	Metal	Red	Chipping	4 SF	0.3	Negative
2320	1	1	H12	Hallway outside Main Office Suite	Door Frame	Metal	Red	Chipping	3 SF	0.6	Negative
2320	1	1	H12	Hallway outside Main Office Suite	Door Frame	Metal	Brown	Chipping	8 SF	0.5	Negative
2320	1	1	H12	Hallway outside Main Office Suite	Door	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	1	H12	Hallway outside Main Office Suite	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H12	Hallway outside Main Office Suite	Vent	Metal	Green	Chipping	10 SF	0.2	Negative
2320	1	1	H12	Hallway outside Main Office Suite	W3	Concrete	White	Cracking	14 SF	0	Negative
2320	1	1	H12	Hallway outside Main Office Suite	W4	Concrete	Blue	Chipping	4 SF	0.4	Negative
2320	1	1	H12	Hallway outside Main Office Suite	Security Gate Tracks	Metal	Brown	Chipping	8 SF	0.1	Negative
2320	1	1	H12	Hallway outside Main Office Suite	Access Panel	Metal	Brown	Chipping	2 SF	0.2	Negative
2320	1	1	H12	Hallway outside Main Office Suite	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	1	H12	Hallway outside Main Office Suite	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H12	Hallway outside Main Office Suite	Stair Railing	Metal	Gray	Friction	20 SF	0.1	Negative
2320	1	1	H12	Hallway outside Main Office Suite	Stair Tread	Concrete	Brown	Friction	16 SF	0.2	Negative
2320	1	1	H12	Hallway outside Main Office Suite	Stair Riser	Concrete	Brown	Friction	16 SF	0.4	Negative
2320	1	1	H13	Hallway outside of Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H13	Hallway outside of Auditorium	W2	Concrete	Blue, Green, Purple, Red, White, Black	Chipping	40 SF	0.5	Negative
2320	1	1	H13	Hallway outside of Auditorium	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H13	Hallway outside of Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H13	Hallway outside of Auditorium	Radiator	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	1	H13	Hallway outside of Auditorium	Door	Metal	Brown	Chipping	20 SF	0.6	Negative
2320	1	1	H13	Hallway outside of Auditorium	Door Frame	Metal	Brown	Chipping	20	0.9	Positive
2320	1	1	H13	Hallway outside of Auditorium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H13	Hallway outside of Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H13	Hallway outside of Auditorium	Stair Railing	Metal	Gray	Chipping	10 SF	0	Negative
2320	1	1	H13	Hallway outside of Auditorium	Stair Riser	Concrete	Brown	Chipping	10 SF	0.1	Negative
2320	1	1	H13	Hallway outside of Auditorium	Stair Tread	Concrete	Brown	Chipping	10 SF	0.1	Negative
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	Door Frame	Metal	Brown	Chipping	8 SF	0.1	Negative
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	W2	Concrete	Light Blue, White	Flaking	200 SF	0.5	Negative
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	W4	Concrete	Light Blue, White	Flaking	200 SF	0.3	Negative
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	Radiator	Metal	Brown	Chipping	5 SF	0	Negative
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	Stair Tread	Concrete	Brown	Chipping	8 SF	0.2	Negative
2320	1	1	Unknown	Entrance Hallway to Auditorium next to Auditorium Stage	Stair Riser	Concrete	Brown	Chipping	8 SF	0.2	Negative
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	Door Frame	Metal	Brown	Chipping	25 SF	0.5	Negative
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	Door	Metal	Brown	Chipping	5 SF	0.8	Negative
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	Door Wall Panel	Metal	Brown	Chipping	4 SF	0.5	Negative
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	Vents	Metal	Brown	Chipping	4 SF	0.1	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	H14	Visitor's Entrance/Hallway next to Auditorium Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP3	Vestibule/Hallway outside Kitchen	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP3	Vestibule/Hallway outside Kitchen	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP3	Vestibule/Hallway outside Kitchen	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP3	Vestibule/Hallway outside Kitchen	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	NP3	Vestibule/Hallway outside Kitchen	Ceiling	Plaster	White	Efflorescence	9 SF	0	Negative
2320	1	1	NP3	Vestibule/Hallway outside Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S11	Stairwell A next to Classroom 100	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S11	Stairwell A next to Classroom 100	Door Frame	Metal	Brown	Chipping	8 SF	0.2	Negative
2320	1	1	S11	Stairwell A next to Classroom 100	Door	Metal	Blue, Green, Yellow, Red	Chipping	2 SF	0.3	Negative
2320	1	1	S11	Stairwell A next to Classroom 100	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S11	Stairwell A next to Classroom 100	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S11	Stairwell A next to Classroom 100	Door Frame	Metal	Brown	Chipping	16 SF	0.4	Negative
2320	1	1	S11	Stairwell A next to Classroom 100	Door	Metal	Gray	Chipping	5 SF	0.1	Negative
2320	1	1	S11	Stairwell A next to Classroom 100	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S11	Stairwell A next to Classroom 100	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S11	Stairwell A next to Classroom 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S11	Stairwell A next to Classroom 100	Stair Riser	Metal	Brown	Chipping	60 SF	0.3	Negative
2320	1	1	S11	Stairwell A next to Classroom 100	Stair Railing	Metal	Gray	Friction	40 SF	0	Negative
2320	1	1	S11	Stairwell A next to Classroom 100	Stair Post	Metal	Gray	Friction	5 SF	0.1	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S12	Stairwell B next to Classroom 103	Door Frame	Metal	Brown	Chipping	4 SF	0.3	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	Door	Metal	White, Blue, Red, Yellow, Orange, Green	Chipping	10 SF	0.3	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S12	Stairwell B next to Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S12	Stairwell B next to Classroom 103	Door	Metal	Brown	Chipping	5 SF	0.6	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	Door Frame	Metal	Brown	Chipping	4 SF	0.6	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S12	Stairwell B next to Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S12	Stairwell B next to Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S12	Stairwell B next to Classroom 103	Stair Stringer	Metal	Brown	Chipping	5 SF	0	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	Stair Post	Metal	Gray	Friction	5 SF	0.1	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	Stair Railings	Metal	Gray	Friction	30 SF	0.2	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	Stair Tread	Concrete	Brown	Chipping	20 SF	0.2	Negative
2320	1	1	S12	Stairwell B next to Classroom 103	Stair Riser	Concrete	Blue	Chipping	10 SF	0.2	Negative
2320	1	1	S13	Stairwell C next to Classroom 105	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	1	S14	Stairwell C next to Classroom 105	Door	Metal	Brown	Chipping	12 SF	0.6	Negative
2320	1	1	S15	Stairwell C next to Classroom 105	Door Frame	Metal	Brown	Chipping	3 SF	0.4	Negative
2320	1	1	S16	Stairwell C next to Classroom 105	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S18	Stairwell C next to Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S19	Stairwell C next to Classroom 105	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S20	Stairwell C next to Classroom 105	Railing	Metal	Brown	Friction	30 SF	0.1	Negative
2320	1	1	S21	Stairwell C next to Classroom 105	Door Frame	Metal	Brown	Chipping	3 SF	0.3	Negative
2320	1	1	S22	Stairwell C next to Classroom 105	Door	Metal	Blue	Chipping	4 SF	0	Negative
2320	1	1	S23	Stairwell C next to Classroom 105	Stringer	Metal	Brown	Friction	12 SF	0.1	Negative
2320	1	1	S24	Stairwell C next to Classroom 105	Riser	Metal	Brown	Chipping	15 SF	0.2	Negative
2320	1	1	S25	Stairwell C next to Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	1	S26	Stairwell C next to Classroom 105	Floor	Concrete	Gray	Friction	10 SF	0	Negative
2320	1	2	200	Classroom 200	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200	Classroom 200	Door Frame	Metal	Brown	Chipping	4 SF	0.4	Negative
2320	1	2	200	Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200	Classroom 200	Chalkboard	Metal	Brown	Chipping	8 SF	0.2	Negative
2320	1	2	200	Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200	Classroom 200	Radiator	Metal	Brown	Chipping	20 SF	0.1	Negative
2320	1	2	200	Classroom 200	Radiator	Metal	White	Chipping	10 SF	0.3	Negative
2320	1	2	200	Classroom 200	Column	Concrete	White, Beige	Flaking	3 SF	0.4	Negative
2320	1	2	200	Classroom 200	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200	Classroom 200	Chalkboard	Metal	Brown	Chipping	8 SF	0.2	Negative
2320	1	2	200	Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200	Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200A	Far right Closet in Classroom 200	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200A	Far right Closet in Classroom 200	Door Frame	Metal	Brown	Chipping	1 SF	0.4	Negative
2320	1	2	200A	Far right Closet in Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200A	Far right Closet in Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200A	Far right Closet in Classroom 200	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200A	Far right Closet in Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200A	Far right Closet in Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200B	Middle Closet in Classroom 200	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200B	Middle Closet in Classroom 200	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	2	200B	Middle Closet in Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200B	Middle Closet in Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200B	Middle Closet in Classroom 200	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200B	Middle Closet in Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200B	Middle Closet in Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200C	Left side Closet in Classroom 200	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200C	Left side Closet in Classroom 200	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	200C	Left side Closet in Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	2	200C	Left side Closet in Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200C	Left side Closet in Classroom 200	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200C	Left side Closet in Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	200C	Left side Closet in Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201	Classroom 201	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201	Classroom 201	Door Frame	Metal	Brown	Chipping	2 SF	0.3	Negative
2320	1	2	201	Classroom 201	Column	Concrete	White, Beige	Chipping	4 SF	0.4	Negative
2320	1	2	201	Classroom 201	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201	Classroom 201	Chalkboard	Metal	Brown	Chipping	25 SF	0.2	Negative
2320	1	2	201	Classroom 201	Pipes	Fiberglass Wrap	White, Beige	Chipping, Flaking	1 SF	0.3	Negative
2320	1	2	201	Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201	Classroom 201	Radiator	Metal	Brown	Chipping	15 SF	0.1	Negative
2320	1	2	201	Classroom 201	Radiator	Metal	White	Chipping	10 SF	0.2	Negative
2320	1	2	201	Classroom 201	Column	Concrete	White, Beige	Chipping, Flaking	5 SF	0.3	Negative
2320	1	2	201	Classroom 201	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201	Classroom 201	Chalkboard	Metal	Brown	Chipping	25 SF	0.2	Negative
2320	1	2	201	Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201A	Far left Closet in Classroom 201	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201A	Far left Closet in Classroom 201	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201A	Far left Closet in Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201A	Far left Closet in Classroom 201	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201A	Far left Closet in Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201A	Far left Closet in Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201B	Middle Closet in Classroom 201	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201B	Middle Closet in Classroom 201	Door Frame	Metal	Brown	Chipping	2 SF	0.3	Negative
2320	1	2	201B	Middle Closet in Classroom 201	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201B	Middle Closet in Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201B	Middle Closet in Classroom 201	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201B	Middle Closet in Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201B	Middle Closet in Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201C	Right side Closet in Classroom 201	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201C	Right side Closet in Classroom 201	Door Frame	Metal	Brown	Chipping	1 SF	0.3	Negative
2320	1	2	201C	Right side Closet in Classroom 201	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201C	Right side Closet in Classroom 201	Duct	Metal	White	Chipping	1 SF	0.1	Negative
2320	1	2	201C	Right side Closet in Classroom 201	Pipes	Fiberglass Wrap	White, Beige	Chipping, Flaking	1 SF	0.3	Negative
2320	1	2	201C	Right side Closet in Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201C	Right side Closet in Classroom 201	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201C	Right side Closet in Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	201C	Right side Closet in Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202	Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	2	202	Classroom 202	Door Frame	Metal	Brown	Chipping	4 SF	0.2	Negative
2320	1	2	202	Classroom 202	Column	Concrete	White, Beige	Flaking	1 SF	0.2	Negative
2320	1	2	202	Classroom 202	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202	Classroom 202	Pipes	Fiberglass Wrap, Plastic	White, Beige	Flaking	2 SF	0.2	Negative
2320	1	2	202	Classroom 202	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202	Classroom 202	Column	Concrete	White, Beige	Flaking	1 S	0.2	Negative
2320	1	2	202	Classroom 202	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202	Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202	Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202B	Left side Closet in Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202B	Left side Closet in Classroom 202	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	202B	Left side Closet in Classroom 202	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202B	Left side Closet in Classroom 202	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202B	Left side Closet in Classroom 202	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202B	Left side Closet in Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202B	Left side Closet in Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202A	Right side Closet in Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202A	Right side Closet in Classroom 202	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	2	202A	Right side Closet in Classroom 202	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202A	Right side Closet in Classroom 202	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202A	Right side Closet in Classroom 202	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202A	Right side Closet in Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	202A	Right side Closet in Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203	Classroom 203	W1	Concrete	White, Beige	Chipping	25 SF	0.3	Negative
2320	1	2	203	Classroom 203	Door Frame	Metal	Brown	Chipping	6 SF	0.2	Negative
2320	1	2	203	Classroom 203	Column	Concrete	Beige	Flaking	8 SF	0	Negative
2320	1	2	203	Classroom 203	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203	Classroom 203	Chalkboard	Metal	Brown	Chipping	10 SF	0.1	Negative
2320	1	2	203	Classroom 203	Pipes	Fiberglass Wrap, Plastic	White, Beige	Flaking	3 SF	0.2	Negative
2320	1	2	203	Classroom 203	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203	Classroom 203	Radiator	Metal	Brown	Chipping	10 SF	0.2	Negative
2320	1	2	203	Classroom 203	Radiator	Metal	Beige	Chipping	20 SF	0.1	Negative
2320	1	2	203	Classroom 203	Column	Concrete	White, Beige	Flaking	3 SF	0	Negative
2320	1	2	203	Classroom 203	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203	Classroom 203	Chalkboard	Metal	Brown	Chipping	10 SF	0.1	Negative
2320	1	2	203	Classroom 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203A	Far left Closet in Classroom 203	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	203A	Far left Closet in Classroom 203	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	203A	Far left Closet in Classroom 203	W2	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATTA	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	2	203A	Far left Closet in Classroom 203	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	203A	Far left Closet in Classroom 203	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	203A	Far left Closet in Classroom 203	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	203A	Far left Closet in Classroom 203	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	203B	Middle Closet in Classroom 203	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203B	Middle Closet in Classroom 203	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	203B	Middle Closet in Classroom 203	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203B	Middle Closet in Classroom 203	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203B	Middle Closet in Classroom 203	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203B	Middle Closet in Classroom 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203B	Middle Closet in Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203C	Right side Closet in Classroom 203	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203C	Right side Closet in Classroom 203	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	203C	Right side Closet in Classroom 203	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203C	Right side Closet in Classroom 203	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203C	Right side Closet in Classroom 203	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203C	Right side Closet in Classroom 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	203C	Right side Closet in Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204	Classroom 204	W1	Concrete	White, Beige	Chipping	5 SF	0.3	Negative
2320	1	2	204	Classroom 204	Door Frame	Metal	Brown	Chipping	5 SF	0.3	Negative
2320	1	2	204	Classroom 204	Column	Concrete	Beige	Chipping	5 SF	0.4	Negative
2320	1	2	204	Classroom 204	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204	Classroom 204	Chalkboard	Metal	Brown	Chipping	8 SF	0.3	Negative
2320	1	2	204	Classroom 204	Pipes	Fiberglass Wrap, Plastic	White, Beige	Chipping	4 SF	0.2	Negative
2320	1	2	204	Classroom 204	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204	Classroom 204	Radiator	Metal	Brown	Chipping	15 SF	0.2	Negative
2320	1	2	204	Classroom 204	Radiator	Metal	Brown	Chipping	10 SF	0.2	Negative
2320	1	2	204	Classroom 204	Column	Concrete	White, Beige	Chipping	5 SF	0.4	Negative
2320	1	2	204	Classroom 204	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204	Classroom 204	Chalkboard	Metal	Brown	Chipping	8 SF	0.3	Negative
2320	1	2	204	Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204	Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204A	Far left Closet in Classroom 204	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204A	Far left Closet in Classroom 204	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	204A	Far left Closet in Classroom 204	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204A	Far left Closet in Classroom 204	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204A	Far left Closet in Classroom 204	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204A	Far left Closet in Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204A	Far left Closet in Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204B	Middle Closet in Classroom 204	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204B	Middle Closet in Classroom 204	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATTA	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	2	204B	Middle Closet in Classroom 204	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204B	Middle Closet in Classroom 204	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204B	Middle Closet in Classroom 204	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204B	Middle Closet in Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204B	Middle Closet in Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204C	Right side Closet in Classroom 204	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204C	Right side Closet in Classroom 204	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	204C	Right side Closet in Classroom 204	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204C	Right side Closet in Classroom 204	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204C	Right side Closet in Classroom 204	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204C	Right side Closet in Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	204C	Right side Closet in Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205	Classroom 205	W1	Concrete	White, Beige	Chipping	5 SF	0.3	Negative
2320	1	2	205	Classroom 205	Door Frame	Metal	Brown	Chipping	3 SF	0.2	Negative
2320	1	2	205	Classroom 205	Column	Concrete	Beige	Flaking	6 SF	0.2	Negative
2320	1	2	205	Classroom 205	Shelf	Metal	Beige	Chipping	1	3.6	Positive
2320	1	2	205	Classroom 205	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205	Classroom 205	Chalkboard	Metal	Brown	Chipping	6 SF	0.1	Negative
2320	1	2	205	Classroom 205	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205	Classroom 205	Radiator	Metal	Brown, Yellow	Chipping, Flaking	6 SF	0.1	Negative
2320	1	2	205	Classroom 205	Radiator	Metal	Beige	Chipping, Flaking	5 SF	0.1	Negative
2320	1	2	205	Classroom 205	Column	Concrete	White, Beige	Flaking	6 SF	0.2	Negative
2320	1	2	205	Classroom 205	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205	Classroom 205	Chalkboard	Metal	Brown	Chipping	6 SF	0.1	Negative
2320	1	2	205	Classroom 205	Ceiling	Concrete	White	Efflorescence	4 SF	0.1	Negative
2320	1	2	205	Classroom 205	Horizontal Support Column	Concrete	White	Efflorescence	4 SF	0.1	Negative
2320	1	2	205	Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205A	Far left Closet in Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205A	Far left Closet in Classroom 205	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205A	Far left Closet in Classroom 205	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205A	Far left Closet in Classroom 205	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205A	Far left Closet in Classroom 205	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205A	Far left Closet in Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205B	Middle Closet in Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205B	Middle Closet in Classroom 205	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205B	Middle Closet in Classroom 205	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205B	Middle Closet in Classroom 205	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205B	Middle Closet in Classroom 205	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205B	Middle Closet in Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205C	Right side Closet in Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205C	Right side Closet in Classroom 205	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	2	205C	Right side Closet in Classroom 205	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205C	Right side Closet in Classroom 205	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205C	Right side Closet in Classroom 205	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	205C	Right side Closet in Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206	Classroom 206	W1	Concrete	White, Beige	Chipping	5 SF	0.5	Negative
2320	1	2	206	Classroom 206	Door Frame	Metal	Brown	Chipping	2 SF	0.4	Negative
2320	1	2	206	Classroom 206	Column	Concrete	Beige	Chipping	4 SF	0.3	Negative
2320	1	2	206	Classroom 206	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206	Classroom 206	Chalkboard	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	2	206	Classroom 206	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206	Classroom 206	Radiator	Metal	Brown	Chipping	15 SF	0.1	Negative
2320	1	2	206	Classroom 206	Radiator	Metal	Beige	Chipping	15 SF	0.1	Negative
2320	1	2	206	Classroom 206	Column	Concrete	White, Beige	Chipping	3 SF	0.2	Negative
2320	1	2	206	Classroom 206	Pipes	Fiberglass Wrap, Plastic	White, Beige	Chipping	1 SF	0.3	Negative
2320	1	2	206	Classroom 206	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206	Classroom 206	Chalkboard	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	2	206	Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206A	Left side Closet in Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206A	Left side Closet in Classroom 206	Door Frame	Metal	Brown	Chipping	1 SF	0.3	Negative
2320	1	2	206A	Left side Closet in Classroom 206	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206A	Left side Closet in Classroom 206	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206A	Left side Closet in Classroom 206	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206A	Left side Closet in Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206A	Left side Closet in Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206B	Middle Closet in Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206B	Middle Closet in Classroom 206	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	2	206B	Middle Closet in Classroom 206	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206B	Middle Closet in Classroom 206	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206B	Middle Closet in Classroom 206	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206B	Middle Closet in Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206B	Middle Closet in Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206C	Right Closet in Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206C	Right Closet in Classroom 206	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	2	206C	Right Closet in Classroom 206	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206C	Right Closet in Classroom 206	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206C	Right Closet in Classroom 206	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206C	Right Closet in Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	206C	Right Closet in Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	216	Office next to Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	216	Office next to Classroom 206	Door Frame	Metal	Brown	Chipping	3 SF	0.3	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATTA	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	2	216	Office next to Classroom 206	W2	Concrete	Beige	Cracked	15 SF	0.3	Negative
2320	1	2	216	Office next to Classroom 206	Pipes	Plastic	Beige	Chipping, Flaking	10 SF	0.1	Negative
2320	1	2	216	Office next to Classroom 206	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	216	Office next to Classroom 206	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	216	Office next to Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	216	Office next to Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207	Classroom 207	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207	Classroom 207	Door Frame	Metal	Brown	Chipping	7 SF	0.3	Negative
2320	1	2	207	Classroom 207	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207	Classroom 207	W3	Concrete	White, Beige	Cracked	2 SF	0	Negative
2320	1	2	207	Classroom 207	Radiator	Metal	Brown	Chipping	10 SF	0	Negative
2320	1	2	207	Classroom 207	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207	Classroom 207	Chalkboard	Metal	Brown	Chipping	16 SF	0.2	Negative
2320	1	2	207	Classroom 207	Ceiling	Concrete	White	Efflorescence, Chipping	6 SF	0.5	Negative
2320	1	2	207	Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207A	Storage in Classroom 207	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207A	Storage in Classroom 207	Door Frame	Metal	Brown	Chipping	8 SF	0.4	Negative
2320	1	2	207A	Storage in Classroom 207	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207A	Storage in Classroom 207	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207A	Storage in Classroom 207	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207A	Storage in Classroom 207	Vent	Metal	White	Flaking	4 SF	0.5	Negative
2320	1	2	207A	Storage in Classroom 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207A	Storage in Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208	Classroom 208	W1	Concrete	White, Beige	Chipping	3 SF	0.5	Negative
2320	1	2	208	Classroom 208	Shelf	Metal	Beige	Chipping	15	3.1	Positive
2320	1	2	208	Classroom 208	Shelf Support	Metal	Beige	Chipping	5 SF	0.1	Negative
2320	1	2	208	Classroom 208	Column	Concrete	Beige	Flaking	10 SF	0.3	Negative
2320	1	2	208	Classroom 208	Door Frame	Metal	Brown	Chipping	13 SF	0.3	Negative
2320	1	2	208	Classroom 208	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208	Classroom 208	Pipes	Plastic	Beige	Chipping	8 SF	0.2	Negative
2320	1	2	208	Classroom 208	Pipes	Fiberglass	White	Cracked	2 SF	0.2	Negative
2320	1	2	208	Classroom 208	Chalkboard	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	2	208	Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208	Classroom 208	Radiator	Metal	Beige	Chipping, Flaking	20 SF	0.1	Negative
2320	1	2	208	Classroom 208	Column	Concrete	White, Beige	Chipping	6 SF	0.3	Negative
2320	1	2	208	Classroom 208	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208	Classroom 208	Chalkboard	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	2	208	Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208	Classroom 208	Horizontal Support Beam	Concrete	White	Chipping	3 SF	0.1	Negative
2320	1	2	208	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	2	208B	Far left Closet in Classroom 208	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208B	Far left Closet in Classroom 208	Door Frame	Metal	Brown	Chipping	4 SF	0.2	Negative
2320	1	2	208B	Far left Closet in Classroom 208	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208B	Far left Closet in Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208B	Far left Closet in Classroom 208	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208B	Far left Closet in Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208B	Far left Closet in Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208C	Middle Closet in Classroom 208	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208C	Middle Closet in Classroom 208	Door Frame	Metal	Brown	Chipping	4 SF	0.2	Negative
2320	1	2	208C	Middle Closet in Classroom 208	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208C	Middle Closet in Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208C	Middle Closet in Classroom 208	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208C	Middle Closet in Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208C	Middle Closet in Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208D	Right side Closet in Classroom 208	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208D	Right side Closet in Classroom 208	Door Frame	Metal	Brown	Chipping	2 SF	0.2	Negative
2320	1	2	208D	Right side Closet in Classroom 208	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208D	Right side Closet in Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208D	Right side Closet in Classroom 208	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208D	Right side Closet in Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208D	Right side Closet in Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208A	Office next to Classroom 208	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208A	Office next to Classroom 208	Door Frame	Metal	Brown	Chipping	4 SF	0.3	Negative
2320	1	2	208A	Office next to Classroom 208	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208A	Office next to Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208A	Office next to Classroom 208	Radiator	Metal	Brown	Chipping	15 SF	0	Negative
2320	1	2	208A	Office next to Classroom 208	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208A	Office next to Classroom 208	Pipes	Plastic	White, Beige	Chipping	1 SF	0	Negative
2320	1	2	208A	Office next to Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	208A	Office next to Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	Unknown	Closet in Administrative Office 208A	W1	Concrete	White, Beige	Chipping	10 SF	0.4	Negative
2320	1	2	Unknown	Closet in Administrative Office 208A	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	Unknown	Closet in Administrative Office 208A	W2	Concrete	White, Beige	Chipping	10 SF	0.4	Negative
2320	1	2	Unknown	Closet in Administrative Office 208A	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	Unknown	Closet in Administrative Office 208A	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	Unknown	Closet in Administrative Office 208A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	Unknown	Closet in Administrative Office 208A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209	Classroom 209	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209	Classroom 209	Door Frame	Metal	Brown	Chipping	7 SF	0.3	Negative
2320	1	2	209	Classroom 209	Column	Concrete	Beige	Chipping	2 SF	0.3	Negative
2320	1	2	209	Classroom 209	Shelf	Metal	Beige	Chipping	7	2.6	Positive

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	2	209	Classroom 209	Shelf Support	Metal	Beige	Chipping	1 SF	0.3	Negative
2320	1	2	209	Classroom 209	W2	Concrete	Beige	Chipping, Spalling	1 SF	0	Negative
2320	1	2	209	Classroom 209	Chalkboard	Metal	Brown	Chipping	8 SF	0	Negative
2320	1	2	209	Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209	Classroom 209	Radiator	Metal	Beige	Chipping, Flaking	5 SF	0	Negative
2320	1	2	209	Classroom 209	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209	Classroom 209	Chalkboard	Metal	Brown	Chipping	8 SF	0	Negative
2320	1	2	209	Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Middle Closet in Classroom 209	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Middle Closet in Classroom 209	Door Frame	Metal	Brown	Chipping	1 SF	0.4	Negative
2320	1	2	209A	Middle Closet in Classroom 209	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Middle Closet in Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Middle Closet in Classroom 209	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Middle Closet in Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Middle Closet in Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Right side Closet in Classroom 209	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Right side Closet in Classroom 209	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	2	209A	Right side Closet in Classroom 209	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Right side Closet in Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Right side Closet in Classroom 209	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Right side Closet in Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	209A	Right side Closet in Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210	Classroom 210	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210	Classroom 210	Door Frame	Metal	Brown	Chipping	8 SF	0.4	Negative
2320	1	2	210	Classroom 210	Shelf	Metal	Beige	Chipping	1	4.2	Positive
2320	1	2	210	Classroom 210	Shelf Support	Metal	Beige	Chipping	1 SF	0.1	Negative
2320	1	2	210	Classroom 210	Column	Concrete	Beige	Flaking	5 SF	0	Negative
2320	1	2	210	Classroom 210	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210	Classroom 210	Chalkboard	Metal	Brown	Chipping	8 SF	0	Negative
2320	1	2	210	Classroom 210	Pipes	Fiberglass, Plastic	White, Beige	Chipping	1 SF	0.2	Negative
2320	1	2	210	Classroom 210	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210	Classroom 210	Radiator	Metal	Brown	Chipping	15 SF	0.1	Negative
2320	1	2	210	Classroom 210	Radiator	Metal	Beige	Chipping	20 SF	0.1	Negative
2320	1	2	210	Classroom 210	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210	Classroom 210	Chalkboard	Metal	Brown	Chipping	8 SF	0	Negative
2320	1	2	210	Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210	Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210A	Far left Closet in Classroom 210	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	210A	Far left Closet in Classroom 210	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	210A	Far left Closet in Classroom 210	W2	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT A	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	2	210A	Far left Closet in Classroom 210	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	210A	Far left Closet in Classroom 210	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	210A	Far left Closet in Classroom 210	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	210A	Far left Closet in Classroom 210	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	210B	Middle Closet in Classroom 210	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210B	Middle Closet in Classroom 210	Door Frame	Metal	Brown	Chipping	5 SF	0.3	Negative
2320	1	2	210B	Middle Closet in Classroom 210	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210B	Middle Closet in Classroom 210	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210B	Middle Closet in Classroom 210	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210B	Middle Closet in Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210B	Middle Closet in Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210C	Right side Closet in Classroom 210	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210C	Right side Closet in Classroom 210	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	2	210C	Right side Closet in Classroom 210	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210C	Right side Closet in Classroom 210	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210C	Right side Closet in Classroom 210	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210C	Right side Closet in Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	210C	Right side Closet in Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	214PC	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Classroom 214	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214PC	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Storage Room 214	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214PC	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Storage Room 214	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214PC	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Storage Room 214	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214PC	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Storage Room 214	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214PC	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Storage Room 214	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	212	Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	212	Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	212	Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	212	Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	212	Boy's Restroom	Ceiling	Concrete	White	Spalling	1 SF	0.5	Negative
2320	1	2	212	Boy's Restroom	Pipes	Fiberglass	White	Chipping, Flaking	10 SF	0.1	Negative
2320	1	2	212	Boy's Restroom	Floor	Concrete	Gray	Chipping, Spalling	4 SF	0.2	Negative
2320	1	2	213	Men's Staff Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	213	Men's Staff Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	213	Men's Staff Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	213	Men's Staff Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	213	Men's Staff Restroom	Ceiling	Concrete	White	Flaking	1 SF	0.2	Negative
2320	1	2	213	Men's Staff Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	2	214	Storage Room next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	214	Storage Room next to Elevator	Door Frame	Metal	Brown	Chipping	2 SF	0.3	Negative
2320	1	2	214	Storage Room next to Elevator	Horizontal Support Column	Concrete	White	Efflorescence	4 SF	0.4	Negative
2320	1	2	214	Storage Room next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	214	Storage Room next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	214	Storage Room next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	214	Storage Room next to Elevator	Ceiling	Concrete	White	Efflorescence	4 SF	0.4	Negative
2320	1	2	214	Storage Room next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	211	Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	211	Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	211	Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	211	Girl's Restroom	Radiator	Metal	Brown	Chipping	5 SF	0.2	Negative
2320	1	2	211	Girl's Restroom	Pipes	Fiberglass	White	Cracked	1 SF	0.2	Negative
2320	1	2	211	Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	211	Girl's Restroom	Ceiling	Concrete	White	Spalling	7 SF	0.4	Negative
2320	1	2	211	Girl's Restroom	Floor	Concrete	Gray	Cracked	5 SF	0.2	Negative
2320	1	2	215	Women's Staff Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215	Women's Staff Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215	Women's Staff Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215	Women's Staff Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215	Women's Staff Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215	Women's Staff Restroom	Duct	Metal	White	Chipping	1 SF	0.2	Negative
2320	1	2	215	Women's Staff Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	207A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 207	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	207A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 207	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	207A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 207	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	207A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 207	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	207A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 207	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	207A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 207	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	215A	Custodial closet between restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215A	Custodial closet between restrooms	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215A	Custodial closet between restrooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215A	Custodial closet between restrooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215A	Custodial closet between restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	215A	Custodial closet between restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	E1	Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	2	E1	Elevator	Door	Metal	Brown	Chipping, Friction	4 SF	0.2	Negative
2320	1	2	E1	Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	E1	Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	E1	Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	E1	Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	E1	Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	214A	IT MDF Room inside Storage Room next to Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214A	IT MDF Room inside Storage Room next to Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214A	IT MDF Room inside Storage Room next to Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214A	IT MDF Room inside Storage Room next to Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214A	IT MDF Room inside Storage Room next to Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	214A	IT MDF Room inside Storage Room next to Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	2	H21	Hallway outside Classrooms 200 - 206	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	H21	Hallway outside Classrooms 200 - 206	Radiator	Metal	Brown	Chipping	1 SF	0	Negative
2320	1	2	H21	Hallway outside Classrooms 200 - 206	W2	Concrete	Beige	Flaking	2 SF	0	Negative
2320	1	2	H21	Hallway outside Classrooms 200 - 206	Access Panel	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	2	H21	Hallway outside Classrooms 200 - 206	Access Panel	Metal	Brown	Chipping	1 SF	0.3	Negative
2320	1	2	H21	Hallway outside Classrooms 200 - 206	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	H21	Hallway outside Classrooms 200 - 206	W4	Concrete	Beige	Cracking	2 SF	0.1	Negative
2320	1	2	H21	Hallway outside Classrooms 200 - 206	W4	Concrete	Beige	Cracking	10 SF	9	Negative
2320	1	2	H21	Hallway outside Classrooms 200 - 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	H21	Hallway outside Classrooms 200 - 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	H22	Hallway outside Classrooms 207 - 210	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	H22	Hallway outside Classrooms 207 - 210	Radiator	Metal	Brown	Chipping	4 SF	0	Negative
2320	1	2	H22	Hallway outside Classrooms 207 - 210	W2	Concrete	Beige	Flaking	2 SF	0.4	Negative
2320	1	2	H22	Hallway outside Classrooms 207 - 210	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	H22	Hallway outside Classrooms 207 - 210	W4	Concrete	White	Flaking	8 SF	0.3	Negative
2320	1	2	H22	Hallway outside Classrooms 207 - 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	H22	Hallway outside Classrooms 207 - 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S21	Stairwell A next to Classroom 200	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S21	Stairwell A next to Classroom 200	Door	Metal	Brown over Orange	Chipping	3 SF	0.2	Negative
2320	1	2	S21	Stairwell A next to Classroom 200	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	2	S21	Stairwell A next to Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S21	Stairwell A next to Classroom 200	Baseboard	Metal	Brown	Chipping	5 SF	0	Negative
2320	1	2	S21	Stairwell A next to Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S21	Stairwell A next to Classroom 200	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S21	Stairwell A next to Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S21	Stairwell A next to Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S21	Stairwell A next to Classroom 200	Stair Stringer	Metal	Brown	Chipping	5 SF	0	Negative
2320	1	2	S21	Stairwell A next to Classroom 200	Stair Railing	Metal	Gray	Friction	30 SF	0	Negative
2320	1	2	S21	Stairwell A next to Classroom 200	Stair Riser	Concrete	Brown	Chipping	5 SF	0	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	2	S22	Stairwell B next to Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S22	Stairwell B next to Classroom 205	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S22	Stairwell B next to Classroom 205	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S22	Stairwell B next to Classroom 205	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S22	Stairwell B next to Classroom 205	Ceiling	Concrete	White	Flaking	10 SF	0.3	Negative
2320	1	2	S22	Stairwell B next to Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S22	Stairwell B next to Classroom 205	Stair Railing	Metal	Gray	Friction	25 SF	0	Negative
2320	1	2	S22	Stairwell B next to Classroom 205	Stair Stringer	Metal	Brown	Chipping	20 SF	0.1	Negative
2320	1	2	S23	Stairwell C next to Classroom 209	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S23	Stairwell C next to Classroom 209	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S23	Stairwell C next to Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S23	Stairwell C next to Classroom 209	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S23	Stairwell C next to Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S23	Stairwell C next to Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	2	S23	Stairwell C next to Classroom 209	Stair Railing	Metal	Gray	Friction	20 SF	0	Negative
2320	1	3	300	Classroom 300	W1	Concrete	Beige	Chipping	2 SF	0.1	Negative
2320	1	3	300	Classroom 300	Door Frame	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	3	300	Classroom 300	Column	Concrete	Beige	Chipping	1 SF	0.1	Negative
2320	1	3	300	Classroom 300	Shelf	Metal	Beige	Chipping	1	7.5	Positive
2320	1	3	300	Classroom 300	Shelf Support	Metal	Beige	Chipping	2 SF	0.1	Negative
2320	1	3	300	Classroom 300	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300	Classroom 300	Chalkboard	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	3	300	Classroom 300	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300	Classroom 300	Radiator	Metal	Brown	Chipping	7 SF	0.1	Negative
2320	1	3	300	Classroom 300	Radiator	Metal	Beige	Chipping	10 SF	0.1	Negative
2320	1	3	300	Classroom 300	Column	Concrete	White, Beige	Flaking	9 SF	0.2	Negative
2320	1	3	300	Classroom 300	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300	Classroom 300	Chalkboard	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	3	300	Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300	Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300A	Far right Closet in Classroom 300	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300A	Far right Closet in Classroom 300	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	300A	Far right Closet in Classroom 300	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300A	Far right Closet in Classroom 300	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300A	Far right Closet in Classroom 300	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300A	Far right Closet in Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300A	Far right Closet in Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300B	Middle Closet in Classroom 300	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300B	Middle Closet in Classroom 300	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	300B	Middle Closet in Classroom 300	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300B	Middle Closet in Classroom 300	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	3	300B	Middle Closet in Classroom 300	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300B	Middle Closet in Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300B	Middle Closet in Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300C	Left side Closet in Classroom 300	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300C	Left side Closet in Classroom 300	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	300C	Left side Closet in Classroom 300	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300C	Left side Closet in Classroom 300	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300C	Left side Closet in Classroom 300	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300C	Left side Closet in Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	300C	Left side Closet in Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301	Classroom 301	W1	Concrete	Beige	Chipping	5 SF	0	Negative
2320	1	3	301	Classroom 301	Door Frame	Metal	Brown	Chipping	11 SF	0.3	Negative
2320	1	3	301	Classroom 301	Column	Concrete	Beige	Chipping	5 SF	0.3	Negative
2320	1	3	301	Classroom 301	Shelf	Metal	Beige	Chipping	1	2.7	Positive
2320	1	3	301	Classroom 301	Shelf Support	Metal	Beige	Chipping	1 SF	0	Negative
2320	1	3	301	Classroom 301	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301	Classroom 301	Column	Concrete	White, Beige	Flaking, Moisture Damage	2 SF	0.2	Negative
2320	1	3	301	Classroom 301	Chalkboard	Metal	Brown	Chipping	5 SF	0	Negative
2320	1	3	301	Classroom 301	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301	Classroom 301	Radiator	Metal	Brown	Chipping	20 SF	0.1	Negative
2320	1	3	301	Classroom 301	Radiator	Metal	Beige	Chipping	20 SF	0.1	Negative
2320	1	3	301	Classroom 301	Column	Concrete	White, Beige	Chipping	2 SF	0.1	Negative
2320	1	3	301	Classroom 301	Column	Concrete	White, Beige	Chipping	2 SF	0.1	Negative
2320	1	3	301	Classroom 301	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301	Classroom 301	Chalkboard	Metal	Brown	Chipping	5 SF	0	Negative
2320	1	3	301	Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301	Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301A	Far left Closet in Classroom 301	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301A	Far left Closet in Classroom 301	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	301A	Far left Closet in Classroom 301	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301A	Far left Closet in Classroom 301	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301A	Far left Closet in Classroom 301	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301A	Far left Closet in Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301A	Far left Closet in Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301B	Middle Closet in Classroom 301	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301B	Middle Closet in Classroom 301	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	301B	Middle Closet in Classroom 301	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301B	Middle Closet in Classroom 301	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301B	Middle Closet in Classroom 301	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301B	Middle Closet in Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301B	Middle Closet in Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	3	301C	Right side Closet in Classroom 301	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301C	Right side Closet in Classroom 301	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	301C	Right side Closet in Classroom 301	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301C	Right side Closet in Classroom 301	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301C	Right side Closet in Classroom 301	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301C	Right side Closet in Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	301C	Right side Closet in Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302	Classroom 302	W1	Concrete	White	Chipping	5 SF	0.3	Negative
2320	1	3	302	Classroom 302	Door Frame	Metal	Brown	Chipping	3 SF	0.3	Negative
2320	1	3	302	Classroom 302	Column	Concrete	Tan	Chipping	4 SF	0.4	Negative
2320	1	3	302	Classroom 302	Shelf	Metal	Tan	Chipping	1	3.3	Positive
2320	1	3	302	Classroom 302	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302	Classroom 302	Chalkboard	Metal	Brown	Chipping/Friction	6 SF	0.1	Negative
2320	1	3	302	Classroom 302	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302	Classroom 302	Radiator	Metal	Brown	Chipping	19 SF	0.1	Negative
2320	1	3	302	Classroom 302	Radiator	Metal	Tan	Chipping	6 SF	0.2	Negative
2320	1	3	302	Classroom 302	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302	Classroom 302	Chalkboard	Metal	Brown	Chipping/Friction	6 SF	0.1	Negative
2320	1	3	302	Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302	Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302A	Right side Closet in Classroom 302	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302A	Right side Closet in Classroom 302	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302A	Right side Closet in Classroom 302	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302A	Right side Closet in Classroom 302	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302A	Right side Closet in Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302A	Right side Closet in Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302B	Left side Closet in Classroom 302	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302B	Left side Closet in Classroom 302	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302B	Left side Closet in Classroom 302	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302B	Left side Closet in Classroom 302	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302B	Left side Closet in Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	302B	Left side Closet in Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303	Classroom 303	W1	Concrete	Beige	Chipping	5 SF	0.3	Negative
2320	1	3	303	Classroom 303	Door Frame	Metal	Brown	Chipping	1 SF	0.4	Negative
2320	1	3	303	Classroom 303	Shelf	Metal	Beige	Chipping	1	3	Positive
2320	1	3	303	Classroom 303	Shelf Support	Metal	Beige	Chipping	1 SF	0.3	Negative
2320	1	3	303	Classroom 303	Column	Concrete	Beige	Chipping	2 SF	0.3	Negative
2320	1	3	303	Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303	Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303	Classroom 303	Radiator	Metal	Beige	Chipping	1 SF	0.1	Negative
2320	1	3	303	Classroom 303	Column	Concrete	White, Beige	Chipping, Flaking	2 SF	0.2	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	3	303	Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303	Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303A	Far left Closet in Classroom 303	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303A	Far left Closet in Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303A	Far left Closet in Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303A	Far left Closet in Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303A	Far left Closet in Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303A	Far left Closet in Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303B	Middle Closet in Classroom 303	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303B	Middle Closet in Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303B	Middle Closet in Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303B	Middle Closet in Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303B	Middle Closet in Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303B	Middle Closet in Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303C	Right side Closet in Classroom 303	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303C	Right side Closet in Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303C	Right side Closet in Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303C	Right side Closet in Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303C	Right side Closet in Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	303C	Right side Closet in Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304	Classroom 304	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304	Classroom 304	Door Frame	Metal	Brown	Chipping	6 SF	0.4	Negative
2320	1	3	304	Classroom 304	Column	Concrete	Beige	Chipping	6 SF	0.2	Negative
2320	1	3	304	Classroom 304	Shelf	Metal	Beige	Chipping	2	1.7	Positive
2320	1	3	304	Classroom 304	Shelf Support	Metal	Beige	Chipping	1 SF	0.1	Negative
2320	1	3	304	Classroom 304	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304	Classroom 304	Chalkboard	Metal	Brown	Chipping	10 SF	0	Negative
2320	1	3	304	Classroom 304	Column	Concrete	White, Beige	Flaking	2 SF	0.2	Negative
2320	1	3	304	Classroom 304	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304	Classroom 304	Radiator	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	3	304	Classroom 304	Radiator	Metal	Beige	Chipping	10 SF	0.2	Negative
2320	1	3	304	Classroom 304	Column	Concrete	White, Beige	Chipping	4 SF	0.1	Negative
2320	1	3	304	Classroom 304	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304	Classroom 304	Chalkboard	Metal	Brown	Chipping	10 SF	0	Negative
2320	1	3	304	Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304	Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304A	Far left Closet in Classroom 304	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304A	Far left Closet in Classroom 304	Door Frame	Metal	Brown	Chipping	7 SF	0.3	Negative
2320	1	3	304A	Far left Closet in Classroom 304	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304A	Far left Closet in Classroom 304	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	3	304A	Far left Closet in Classroom 304	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304A	Far left Closet in Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304A	Far left Closet in Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304B	Middle Closet in Classroom 304	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304B	Middle Closet in Classroom 304	Door Frame	Metal	Brown	Chipping	7 SF	0.3	Negative
2320	1	3	304B	Middle Closet in Classroom 304	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304B	Middle Closet in Classroom 304	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304B	Middle Closet in Classroom 304	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304B	Middle Closet in Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304B	Middle Closet in Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304C	Right side Closet in Classroom 304	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304C	Right side Closet in Classroom 304	Door Frame	Metal	Brown	Chipping	7 SF	0.3	Negative
2320	1	3	304C	Right side Closet in Classroom 304	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304C	Right side Closet in Classroom 304	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304C	Right side Closet in Classroom 304	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304C	Right side Closet in Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	304C	Right side Closet in Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305	Classroom 305	W1	Concrete	Beige	Chipping	1 SF	0.3	Negative
2320	1	3	305	Classroom 305	Door Frame	Metal	Brown	Chipping	1 SF	0.4	Negative
2320	1	3	305	Classroom 305	Column	Concrete	Beige	Chipping	2 SF	0.2	Negative
2320	1	3	305	Classroom 305	Shelf	Metal	Beige	Chipping	3	3.3	Positive
2320	1	3	305	Classroom 305	Shelf Support	Metal	Beige	Chipping	1 SF	0.4	Negative
2320	1	3	305	Classroom 305	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305	Classroom 305	Chalkboard	Metal	Brown	Chipping	3 SF	0.1	Negative
2320	1	3	305	Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305	Classroom 305	Radiator	Metal	Brown	Chipping	18 SF	0.1	Negative
2320	1	3	305	Classroom 305	Radiator	Metal	Beige	Chipping	10 SF	0.1	Negative
2320	1	3	305	Classroom 305	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305	Classroom 305	Chalkboard	Metal	Brown	Chipping	3 SF	0.1	Negative
2320	1	3	305	Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305	Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305A	Far left Closet in Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305A	Far left Closet in Classroom 305	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	3	305A	Far left Closet in Classroom 305	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305A	Far left Closet in Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305A	Far left Closet in Classroom 305	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305A	Far left Closet in Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305A	Far left Closet in Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305B	Middle Closet in Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305B	Middle Closet in Classroom 305	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	3	305B	Middle Closet in Classroom 305	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATTA	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	3	305B	Middle Closet in Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305B	Middle Closet in Classroom 305	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305B	Middle Closet in Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305B	Middle Closet in Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305C	Right side Closet in Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305C	Right side Closet in Classroom 305	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	3	305C	Right side Closet in Classroom 305	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305C	Right side Closet in Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305C	Right side Closet in Classroom 305	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305C	Right side Closet in Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	305C	Right side Closet in Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306	Classroom 306	W1	Concrete	White, Beige	Chipping	3 SF	0.3	Negative
2320	1	3	306	Classroom 306	Door Frame	Metal	Brown	Chipping	6 SF	0.5	Negative
2320	1	3	306	Classroom 306	Shelf	Metal	Beige	Chipping	5	3.5	Positive
2320	1	3	306	Classroom 306	Shelf Support	Metal	Beige	Chipping	1 SF	0.5	Negative
2320	1	3	306	Classroom 306	Column	Concrete	Beige	Chipping	1 SF	0.3	Negative
2320	1	3	306	Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306	Classroom 306	Chalkboard	Metal	Brown	Chipping	15 SF	0.1	Negative
2320	1	3	306	Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306	Classroom 306	Radiator	Metal	Brown	Chipping	10 SF	0	Negative
2320	1	3	306	Classroom 306	Radiator	Metal	Beige	Chipping	15 SF	0.1	Negative
2320	1	3	306	Classroom 306	Column	Concrete	White, Beige	Chipping, Flaking	3 SF	0.4	Negative
2320	1	3	306	Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306	Classroom 306	Chalkboard	Metal	Brown	Chipping	15 SF	0.1	Negative
2320	1	3	306	Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306	Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306A	Far left Closet in Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306A	Far left Closet in Classroom 306	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	306A	Far left Closet in Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306A	Far left Closet in Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306A	Far left Closet in Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306A	Far left Closet in Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306A	Far left Closet in Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306B	Middle Closet in Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306B	Middle Closet in Classroom 306	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	306B	Middle Closet in Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306B	Middle Closet in Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306B	Middle Closet in Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306B	Middle Closet in Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306B	Middle Closet in Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306C	Right side Closet in Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	3	306C	Right side Closet in Classroom 306	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	306C	Right side Closet in Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306C	Right side Closet in Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306C	Right side Closet in Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306C	Right side Closet in Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	306C	Right side Closet in Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308	Classroom 308	W1	Concrete	Beige	Chipping	4 SF	0	Negative
2320	1	3	308	Classroom 308	Door Frame	Metal	Brown	Chipping	5 SF	0.3	Negative
2320	1	3	308	Classroom 308	Column	Concrete	Beige	Chipping	2 SF	0.2	Negative
2320	1	3	308	Classroom 308	Shelf	Metal	Beige	Chipping	8	5.7	Positive
2320	1	3	308	Classroom 308	Shelf Support	Metal	Beige	Chipping	2 SF	0.1	Negative
2320	1	3	308	Classroom 308	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308	Classroom 308	Chalkboard	Metal	Brown	Chipping	10 SF	0.2	Negative
2320	1	3	308	Classroom 308	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308	Classroom 308	Radiator	Metal	Brown	Chipping	15 SF	0	Negative
2320	1	3	308	Classroom 308	Radiator	Metal	Beige	Chipping	15 SF	0.2	Negative
2320	1	3	308	Classroom 308	Column	Concrete	White, Beige	Chipping, Flaking	3 SF	0.1	Negative
2320	1	3	308	Classroom 308	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308	Classroom 308	Chalkboard	Metal	Brown	Chipping	10 SF	0.2	Negative
2320	1	3	308	Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308	Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308B	Far left Closet in Classroom 308	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308B	Far left Closet in Classroom 308	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	308B	Far left Closet in Classroom 308	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308B	Far left Closet in Classroom 308	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308B	Far left Closet in Classroom 308	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308B	Far left Closet in Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308B	Far left Closet in Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308C	Middle Closet in Classroom 308	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308C	Middle Closet in Classroom 308	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	308C	Middle Closet in Classroom 308	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308C	Middle Closet in Classroom 308	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308C	Middle Closet in Classroom 308	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308C	Middle Closet in Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308C	Middle Closet in Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308D	Right side Closet in Classroom 308	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308D	Right side Closet in Classroom 308	Door Frame	Metal	Brown	Chipping	1 SF	0.2	Negative
2320	1	3	308D	Right side Closet in Classroom 308	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308D	Right side Closet in Classroom 308	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308D	Right side Closet in Classroom 308	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308D	Right side Closet in Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATTA	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	3	308D	Right side Closet in Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310	Classroom 310 - Computer Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310	Classroom 310 - Computer Room	Door Frame	Metal	Brown	Chipping	4 SF	0.4	Negative
2320	1	3	310	Classroom 310 - Computer Room	Chalkboard	Metal	Brown	Chipping	10 SF	0.2	Negative
2320	1	3	310	Classroom 310 - Computer Room	Shelf	Metal	Tan	Chipping	1	1.3	Positive
2320	1	3	310	Classroom 310 - Computer Room	Shelf Support	Metal	Tan	Chipping	1 SF	0.1	Negative
2320	1	3	310	Classroom 310 - Computer Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310	Classroom 310 - Computer Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310	Classroom 310 - Computer Room	Radiator	Metal	Red	Chipping	4 SF	0.1	Negative
2320	1	3	310	Classroom 310 - Computer Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310	Classroom 310 - Computer Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310	Classroom 310 - Computer Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310A	Far left Closet in Classroom 310 - Computer Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310A	Far left Closet in Classroom 310 - Computer Room	Door Frame	Metal	Brown	Chipping	4 SF	0	Negative
2320	1	3	310A	Far left Closet in Classroom 310 - Computer Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310A	Far left Closet in Classroom 310 - Computer Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310A	Far left Closet in Classroom 310 - Computer Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310A	Far left Closet in Classroom 310 - Computer Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310A	Far left Closet in Classroom 310 - Computer Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310B	Middle Closet in Classroom 310 - Computer Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310B	Middle Closet in Classroom 310 - Computer Room	Door	Wood	Black	Chipping	2 SF	0.1	Negative
2320	1	3	310B	Middle Closet in Classroom 310 - Computer Room	Door Frame	Metal	Black	Chipping	1 SF	0.4	Negative
2320	1	3	310B	Middle Closet in Classroom 310 - Computer Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310B	Middle Closet in Classroom 310 - Computer Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310B	Middle Closet in Classroom 310 - Computer Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310B	Middle Closet in Classroom 310 - Computer Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310B	Middle Closet in Classroom 310 - Computer Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310C	Right side Closet in Classroom 310 - Computer Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310C	Right side Closet in Classroom 310 - Computer Room	Door	Wood	Black	Chipping	2 SF	0.1	Negative
2320	1	3	310C	Right side Closet in Classroom 310 - Computer Room	Door Frame	Metal	Black	Chipping	4 SF	0.3	Negative
2320	1	3	310C	Right side Closet in Classroom 310 - Computer Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310C	Right side Closet in Classroom 310 - Computer Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310C	Right side Closet in Classroom 310 - Computer Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310C	Right side Closet in Classroom 310 - Computer Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	310C	Right side Closet in Classroom 310 - Computer Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	311	Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	311	Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	311	Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	311	Girl's Restroom	Radiator	Metal	White	Chipping	6 SF	0.2	Negative
2320	1	3	311	Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	311	Girl's Restroom	Ceiling	Concrete	White	Chipping, Spalling	35 SF	0.3	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2320	1	3	311	Girl's Restroom	Duct	Metal	White	Chipping	1 SF	0.1	Negative
2320	1	3	311	Girl's Restroom	Floor	Concrete	Gray	Chipping	2 SF	0	Negative
2320	1	3	312	Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	312	Boy's Restroom	Door Frame	Metal	Brown	Chipping	3 SF	0.1	Negative
2320	1	3	312	Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	312	Boy's Restroom	Radiator	Metal	White	Flaking	1 SF	0.2	Negative
2320	1	3	312	Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	312	Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	312	Boy's Restroom	Ceiling	Concrete	White	Chipping, Spalling	5 SF	0.1	Negative
2320	1	3	312	Boy's Restroom	Floor	Concrete	Gray	Friction	2 SF	0.2	Negative
2320	1	3	313	Men's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313	Men's Restroom	Door Frame	Metal	Brown	Chipping	3 SF	0.3	Negative
2320	1	3	313	Men's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313	Men's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313	Men's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313	Men's Restroom	Ceiling	Concrete	White	Spalling	1 SF	0.4	Negative
2320	1	3	313	Men's Restroom	Floor	Concrete	Gray	Chipping	2 SF	0.1	Negative
2320	1	3	313A	Hallway outside men's/boys restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313A	Hallway outside men's/boys restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313A	Hallway outside men's/boys restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313A	Hallway outside men's/boys restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313A	Hallway outside men's/boys restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	313A	Hallway outside men's/boys restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	314	Office next to Classroom 306	W1	Concrete	Beige	Flaking, Cracking	8 SF	0.3	Negative
2320	1	3	314	Office next to Classroom 306	Door Frame	Metal	Brown	Chipping	4 SF	0.4	Negative
2320	1	3	314	Office next to Classroom 306	Column	Concrete	Beige	Flaking, Cracking	11 SF	0.3	Negative
2320	1	3	314	Office next to Classroom 306	W2	Concrete	Beige	Flaking, Cracking	15 SF	0.3	Negative
2320	1	3	314	Office next to Classroom 306	W3	Concrete	Beige	Flaking, Cracking	11 SF	0	Negative
2320	1	3	314	Office next to Classroom 306	Column	Concrete	Beige	Flaking, Cracking	11 SF	0.1	Negative
2320	1	3	314	Office next to Classroom 306	Radiator	Metal	Beige	Chipping	9 SF	0.1	Negative
2320	1	3	314	Office next to Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	314	Office next to Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	314	Office next to Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315	Storage Room next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315	Storage Room next to Elevator	Door Frame	Metal	Brown	Chipping	5 SF	0.3	Negative
2320	1	3	315	Storage Room next to Elevator	W2	Concrete	White	None	N/A	N/A	N/A
2320	1	3	315	Storage Room next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315	Storage Room next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315	Storage Room next to Elevator	Ceiling	Concrete	White	Efflorescence, Moisture Damage	15 SF	0.3	Negative
2320	1	3	315	Storage Room next to Elevator	Duct	Metal	White	Chipping	15 SF	0.3	Negative
2320	1	3	315	Storage Room next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	3	315A	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Classroom 315	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315A	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Classroom 315	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315A	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Classroom 315	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315A	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Classroom 315	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315A	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Classroom 315	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	315A	Pipe Chase A/W Boys/Men's Restrooms - Accessed from Classroom 315	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	316	Women's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	316	Women's Restroom	Door Frame	Metal	Brown	Chipping	8 SF	0.3	Negative
2320	1	3	316	Women's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	316	Women's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	316	Women's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	316	Women's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	316	Women's Restroom	Floor	Concrete	Gray	Chipping	4 SF	0	Negative
2320	1	3	Unknown	Custodial closet between restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Custodial closet between restrooms	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Custodial closet between restrooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Custodial closet between restrooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Custodial closet between restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Custodial closet between restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 307/309	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 307/309	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 307/309	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 307/309	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 307/309	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307A	Pipe Chase A/W Girls/Women's Restrooms - Accessed from Classroom 307/309	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309	Classroom 307/309	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309	Classroom 307/309	Door Frame	Metal	Black	Chipping	4 SF	0.2	Negative
2320	1	3	307/309	Classroom 307/309	Door	Metal	Black	Chipping	1 SF	0.3	Negative
2320	1	3	307/309	Classroom 307/309	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309	Classroom 307/309	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309	Classroom 307/309	Radiator	Metal	Red	Chipping	4 SF	0.2	Negative
2320	1	3	307/309	Classroom 307/309	Radiator	Metal	Black	Chipping	1 SF	0	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	3	307/309	Classroom 307/309	Column	Concrete	White	Chipping, Flaking	2 SF	0.1	Negative
2320	1	3	307/309	Classroom 307/309	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309	Classroom 307/309	Ceiling	Concrete	White	Spalling	1 SF	0.4	Negative
2320	1	3	307/309	Classroom 307/309	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309A	Left side Closet in Classroom 309	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309A	Left side Closet in Classroom 309	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309A	Left side Closet in Classroom 309	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309A	Left side Closet in Classroom 309	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309A	Left side Closet in Classroom 309	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309A	Left side Closet in Classroom 309	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309B	Right side Closet in Classroom 309	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309B	Right side Closet in Classroom 309	Door Frame	Metal	Black	Chipping	1 SF	0.2	Negative
2320	1	3	307/309B	Right side Closet in Classroom 309	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309B	Right side Closet in Classroom 309	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309B	Right side Closet in Classroom 309	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309B	Right side Closet in Classroom 309	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	307/309B	Right side Closet in Classroom 309	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Office next to Classroom 308	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Office next to Classroom 308	Door Frame	Metal	Brown	Chipping	3 SF	0.4	Negative
2320	1	3	308A	Office next to Classroom 308	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Office next to Classroom 308	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Office next to Classroom 308	Radiator	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	3	308A	Office next to Classroom 308	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Office next to Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Office next to Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Closet in Classroom 308A	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Closet in Classroom 308A	Door Frame	Metal	Brown	Chipping	3 SF	0.4	Negative
2320	1	3	308A	Closet in Classroom 308A	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Closet in Classroom 308A	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Closet in Classroom 308A	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Closet in Classroom 308A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	308A	Closet in Classroom 308A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Roof Access Room next to Stairwell B (S32)	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Roof Access Room next to Stairwell B (S32)	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Roof Access Room next to Stairwell B (S32)	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Roof Access Room next to Stairwell B (S32)	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Roof Access Room next to Stairwell B (S32)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	Unknown	Roof Access Room next to Stairwell B (S32)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	H31	Hallway outside Classrooms 300 - 306	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	H31	Hallway outside Classrooms 300 - 306	Radiator	Metal	Brown	Chipping	5 SF	0.1	Negative
2320	1	3	H31	Hallway outside Classrooms 300 - 306	W2	Concrete	Beige	Flaking	7 SF	0	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATTA	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	3	H31	Hallway outside Classrooms 300 - 306	Access Panel	Metal	Brown	Chipping	4 SF	0.2	Negative
2320	1	3	H31	Hallway outside Classrooms 300 - 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	H31	Hallway outside Classrooms 300 - 306	W4	Concrete	Beige	Flaking	1 SF	0	Negative
2320	1	3	H31	Hallway outside Classrooms 300 - 306	Ceiling	Concrete	White	Moisture Damage, Flaking	12 SF	0.2	Negative
2320	1	3	H31	Hallway outside Classrooms 300 - 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	H32	Hallway outside Classrooms 307 - 310	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	H32	Hallway outside Classrooms 307 - 310	Radiator	Metal	Brown	Chipping	3 SF	0.1	Negative
2320	1	3	H32	Hallway outside Classrooms 307 - 310	W2	Concrete	Beige	Flaking, Cracking	10 SF	0.3	Negative
2320	1	3	H32	Hallway outside Classrooms 307 - 310	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	H32	Hallway outside Classrooms 307 - 310	W4	Concrete	Beige	Flaking	10 SF	0	Negative
2320	1	3	H32	Hallway outside Classrooms 307 - 310	Ceiling	Concrete	White	Moisture Damage	3 SF	0.1	Negative
2320	1	3	H32	Hallway outside Classrooms 307 - 310	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S31	Stairwell A next to Classroom 300	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S31	Stairwell A next to Classroom 300	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S31	Stairwell A next to Classroom 300	Baseboard	Metal	Brown	Chipped	5 SF	0.1	Negative
2320	1	3	S31	Stairwell A next to Classroom 300	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S31	Stairwell A next to Classroom 300	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S31	Stairwell A next to Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S31	Stairwell A next to Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S31	Stairwell A next to Classroom 300	Stair Railing	Metal	Gray	Friction	4 SF	0	Negative
2320	1	3	S31	Stairwell A next to Classroom 300	Stair Stringer	Metal	Brown	Chipped	5 SF	0	Negative
2320	1	3	S31	Stairwell A next to Classroom 300	Stair Riser	Concrete	Brown	Chipping	3 SF	0	Negative
2320	1	3	S32	Stairwell B next to Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S31	Stairwell A next to Classroom 300	Door	Metal	Red	Chipping	5 SF	0.3	Negative
2320	1	3	S31	Stairwell A next to Classroom 300	Door Frame	Metal	Brown	Chipping	6 SF	0.4	Negative
2320	1	3	S32	Stairwell B next to Classroom 305	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S32	Stairwell B next to Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S32	Stairwell B next to Classroom 305	Baseboard	Metal	Brown	Chipping	12 SF	0	Negative
2320	1	3	S32	Stairwell B next to Classroom 305	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S32	Stairwell B next to Classroom 305	Ceiling	Concrete	White	Flaking	2 SF	0.1	Negative
2320	1	3	S32	Stairwell B next to Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S32	Stairwell B next to Classroom 305	Stair Railing	Metal	Gray	Friction	10SF	0	Negative
2320	1	3	S32	Stairwell B next to Classroom 305	Stair Stringer	Metal	Brown	Chipping	5 SF	0	Negative
2320	1	3	S33	Stairwell C next to Classroom 309	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S33	Stairwell C next to Classroom 309	Door	Metal	Blue	Chipping	2 SF	0	Negative
2320	1	3	S33	Stairwell C next to Classroom 309	Door Frame	Metal	Brown	Chipping	1 SF	0.1	Negative
2320	1	3	S33	Stairwell C next to Classroom 309	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S33	Stairwell C next to Classroom 309	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S33	Stairwell C next to Classroom 309	Baseboard	Metal	Brown	Chipping	4 SF	0	Negative
2320	1	3	S33	Stairwell C next to Classroom 309	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S33	Stairwell C next to Classroom 309	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	3	S33	Stairwell C next to Classroom 309	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	3	S33	Stairwell C next to Classroom 309	Stair Railing	Metal	Gray	Friction	15 SF	0	Negative
2320	1	3	S33	Stairwell C next to Classroom 309	Stair Stringer	Metal	Brown	Chipping	10 SF	0	Negative
2320	1	B	3	Fan Room	W1	Concrete	White, Gray	Moisture Damage, Chipping, Cracking	30 SF	0.1	Negative
2320	1	B	3	Fan Room	Door	Metal	Tan	Chipping	12 SF	0.2	Negative
2320	1	B	3	Fan Room	Door Frame	Metal	Brown	Chipping	8 SF	0.3	Negative
2320	1	B	3	Fan Room	Column	Concrete	White, Gray	Flaking	5 SF	0.4	Negative
2320	1	B	3	Fan Room	Pipe	Metal	White	Chipping	20 SF	0.1	Negative
2320	1	B	3	Fan Room	W2	Concrete	White, Gray	Chipping, Flaking	30 SF	0	Negative
2320	1	B	3	Fan Room	W3	Concrete	White, Gray	Chipping, Flaking	120 SF	0	Negative
2320	1	B	3	Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	3	Fan Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	3	Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	3	Fan Room	Steel Frame Support	Metal	Gray	Chipping	4 SF	0.1	Negative
2320	1	B	3	Fan Room	Support Bollards	Concrete	Gray	Flaking	50 SF	0.3	Negative
2320	1	B	4	Storage Room behind Fan Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	4	Storage Room behind Fan Room	Door Frame	Metal	Tan	Chipping	4 SF	0.4	Negative
2320	1	B	4	Storage Room behind Fan Room	W2	Concrete	Tan	Spalling	10 SF	0.2	Negative
2320	1	B	4	Storage Room behind Fan Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	4	Storage Room behind Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	4	Storage Room behind Fan Room	Ceiling	Concrete	Tan	Chipping, Flaking	50 SF	0.3	Negative
2320	1	B	4	Storage Room behind Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	5	Electrical Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	5	Electrical Room	Door Frame	Metal	Brown	Chipping	2 SF	0.5	Negative
2320	1	B	5	Electrical Room	Stairs	Concrete	Gray	Chipping, Friction	3 SF	0.1	Negative
2320	1	B	5	Electrical Room	W2	Concrete	Yellow	Flaking	1 SF	0.3	Negative
2320	1	B	5	Electrical Room	W3	Concrete	Yellow	Efflorescence, Flaking, Spalling	8 Sf	0.2	Negative
2320	1	B	5	Electrical Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	5	Electrical Room	Ceiling	Concrete	White	Flaking, Spalling	20 SF	0.3	Negative
2320	1	B	5	Electrical Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	6	Storage Room next to Electrical Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	6	Storage Room next to Electrical Room	Door Frame	Metal	Brown	Chipping	2 SF	0.1	Negative
2320	1	B	6	Storage Room next to Electrical Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	6	Storage Room next to Electrical Room	W3	Concrete	Light Brown	Flaking, Cracking	10 SF	0.2	Negative
2320	1	B	6	Storage Room next to Electrical Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	6	Storage Room next to Electrical Room	Ceiling	Concrete	Light Brown	Cracking, Flaking	8 SF	0.4	Negative
2320	1	B	6	Storage Room next to Electrical Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	7	Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	B	7	Building Engineer's Office	Door Frame	Metal	Brown	Chipping	8 SF	0.4	Negative
2320	1	B	7	Building Engineer's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	7	Building Engineer's Office	Pipe	Metal	White	Chipping	1 SF	0.2	Negative
2320	1	B	7	Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	7	Building Engineer's Office	W4	Concrete	White	Chipping, Flaking	15 SF	0.1	Negative
2320	1	B	7	Building Engineer's Office	Ceiling	Concrete	White	Flaking	10 SF	0.2	Negative
2320	1	B	7	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	007A	Building Engineer's Office Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	007A	Building Engineer's Office Restroom	Door Frame	Metal	Brown	Chipping	8 SF	0.1	Negative
2320	1	B	007A	Building Engineer's Office Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	007A	Building Engineer's Office Restroom	W3	Concrete	White	Flaking	5 SF	0.3	Negative
2320	1	B	007A	Building Engineer's Office Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	007A	Building Engineer's Office Restroom	Ceiling	Concrete	White	Flaking	50 SF	0.2	Negative
2320	1	B	007A	Building Engineer's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	8	Maintenance Office next to Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	8	Maintenance Office next to Building Engineer's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	8	Maintenance Office next to Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	8	Maintenance Office next to Building Engineer's Office	W4	Concrete	White	Chipping	6 SF	0.1	Negative
2320	1	B	8	Maintenance Office next to Building Engineer's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	8	Maintenance Office next to Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008B	Restroom inside Maintenance Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008B	Restroom inside Maintenance Office	Door Frame	Metal	Brown	Chipping	6 SF	0.2	Negative
2320	1	B	008B	Restroom inside Maintenance Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008B	Restroom inside Maintenance Office	W3	Concrete	White	Flaking	3 SF	0.5	Negative
2320	1	B	008B	Restroom inside Maintenance Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008B	Restroom inside Maintenance Office	Ceiling	Concrete	White	Flaking	42 SF	0.2	Negative
2320	1	B	008B	Restroom inside Maintenance Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008A	Janitor's Closet outside Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008A	Janitor's Closet outside Building Engineer's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008A	Janitor's Closet outside Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008A	Janitor's Closet outside Building Engineer's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	008A	Janitor's Closet outside Building Engineer's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	B	008A	Janitor's Closet outside Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	9	Boiler Room	W1	Concrete	White	Flaking	5 SF	0.1	Negative
2320	1	B	9	Boiler Room	W2	Concrete	White	Flaking	500 SF	0.3	Negative
2320	1	B	9	Boiler Room	Columns	Concrete	White	Flaking	150 SF	0.2	Negative
2320	1	B	9	Boiler Room	W3	Concrete	White	Flaking	300 SF	0.3	Negative
2320	1	B	9	Boiler Room	Columns	Concrete	White	Flaking	50 SF	0.2	Negative
2320	1	B	9	Boiler Room	W4	Concrete	White	Flaking	200 SF	0.1	Negative
2320	1	B	9	Boiler Room	Pipe	Metal	White	Flaking	40 SF	0.3	Negative
2320	1	B	9	Boiler Room	Ceiling	Concrete	White	Flaking	1600 SF	0.3	Negative
2320	1	B	9	Boiler Room	Pipe	Metal	White	Flaking	300 SF	0.3	Negative
2320	1	B	9	Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	9	Boiler Room	Columns	Concrete	White	Flaking, Spalling	100 SF	0.5	Negative
2320	1	B	1	Gas Main/Storage Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	1	Gas Main/Storage Room	Door	Wood	White	Chipping	15 SF	0.1	Negative
2320	1	B	1	Gas Main/Storage Room	Door Frame	Wood	White	Chipping	4 SF	0.1	Negative
2320	1	B	1	Gas Main/Storage Room	W2	Concrete	White	Cracking, Chipping, Moisture Damage	50 SF	0.2	Negative
2320	1	B	1	Gas Main/Storage Room	Column	Concrete	White	Flaking	4 SF	0.2	Negative
2320	1	B	1	Gas Main/Storage Room	Vent	Metal	White	Chipped, Rusted	14 SF	0.5	Negative
2320	1	B	1	Gas Main/Storage Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	1	Gas Main/Storage Room	W4	Concrete	White	Chipping, Spalling	50 SF	0.2	Negative
2320	1	B	1	Gas Main/Storage Room	Ceiling	Concrete	White	Spalling, Chipping, Flaking, Moisture Damage	10 SF	0.3	Negative
2320	1	B	1	Gas Main/Storage Room	Stairs	Metal	White	Moisture Damage, Rust	50 SF	0.4	Negative
2320	1	B	1	Gas Main/Storage Room	Floor	Concrete	Gray	Chipping, Friction	500 SF	0.3	Negative
2320	1	B	2	Emergency Generator/Storage Room	W1	Concrete	White	Flaking	50 SF	0.3	Negative
2320	1	B	2	Emergency Generator/Storage Room	W2	Concrete	White	Efflorescence, Moisture Damage, Chipping	300 SF	0.2	Negative
2320	1	B	2	Emergency Generator/Storage Room	Column	Concrete	White	Flaking	10 SF	0.6	Negative
2320	1	B	2	Emergency Generator/Storage Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	2	Emergency Generator/Storage Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	2	Emergency Generator/Storage Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	2	Emergency Generator/Storage Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	H01	Hallway outside Basement Offices	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	H01	Hallway outside Basement Offices	Pipe	Metal	White	Flaking	2 SF	0.1	Negative
2320	1	B	H01	Hallway outside Basement Offices	W2	Concrete	White	Flaking, Cracking	10 SF	0	Negative
2320	1	B	H01	Hallway outside Basement Offices	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	H01	Hallway outside Basement Offices	Access Panel	Metal	Brown	Chipping	2 SF	0.1	Negative
2320	1	B	H01	Hallway outside Basement Offices	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATTA	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	B	H01	Hallway outside Basement Offices	Ceiling	Concrete	White	Flaking	5 SF	0.3	Negative
2320	1	B	H01	Hallway outside Basement Offices	Pipe	Metal	White	Flaking, Chipping	10 SF	0.2	Negative
2320	1	B	H01	Hallway outside Basement Offices	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	H02	Hallway to Stairwell D next to Gas Main/Storage Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	H02	Hallway to Stairwell D next to Gas Main/Storage Room	W2	Concrete	White	Flaking	750 SF	0.2	Negative
2320	1	B	H02	Hallway to Stairwell D next to Gas Main/Storage Room	W3	Concrete	White	Flaking	120 SF	0.2	Negative
2320	1	B	H02	Hallway to Stairwell D next to Gas Main/Storage Room	W4	Concrete	White	Flaking	750 SF	0.1	Negative
2320	1	B	H02	Hallway to Stairwell D next to Gas Main/Storage Room	Ceiling	Concrete	White	Flaking	600 SF	0.3	Negative
2320	1	B	H02	Hallway to Stairwell D next to Gas Main/Storage Room	Pipe	Metal	White	Flaking	20 SF	0.2	Negative
2320	1	B	H02	Hallway to Stairwell D next to Gas Main/Storage Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S02	Stairwell B next to Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S02	Stairwell B next to Boiler Room	Door	Metal	Gray	Chipping	6 SF	0.4	Negative
2320	1	B	S02	Stairwell B next to Boiler Room	Door Frame	Metal	Brown	Chipping	4 SF	0.1	Negative
2320	1	B	S02	Stairwell B next to Boiler Room	W2	Concrete	White, Beige	Flaking	15 SF	0.2	Negative
2320	1	B	S02	Stairwell B next to Boiler Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S02	Stairwell B next to Boiler Room	W4	Concrete	White, Beige	Flaking	15 SF	0.5	Negative
2320	1	B	S02	Stairwell B next to Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S02	Stairwell B next to Boiler Room	Stairs	Metal	White	Chipping, Rust	12 SF	0.4	Negative
2320	1	B	S02	Stairwell B next to Boiler Room	Pipe	Fiberglass	White	Chipping, Flaking	2 SF	0.2	Negative
2320	1	B	S02	Stairwell B next to Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S02	Stairwell B next to Boiler Room	Stair Riser	Concrete	Brown	Chipping	30 SF	0.1	Negative
2320	1	B	S02	Stairwell B next to Boiler Room	Stair Tread	Concrete	Brown	Chipping	30 SF	0.2	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Door	Metal	Tan	Chipping	1 SF	0.4	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Door Frame	Metal	Brown	Chipping	1 SF	0.3	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Door Frame	Metal	Brown	Flaking	25 SF	0.4	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Door	Metal	Tan	Flaking	40 SF	0.3	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	W2	Concrete	Beige	Flaking	80 SF	0.5	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Door	Metal	Tan	Flaking	5 SF	0.3	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Door Frame	Metal	Brown	Flaking	5 SF	0.5	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	W3	Concrete	Beige	Flaking	30 SF	0.2	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Pipe	Metal	White	Flaking	7 SF	0.1	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	W4	Concrete	Beige	Flaking	45 SF	0.1	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Ceiling	Concrete	White	Efflorescence	50 SF	0.2	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Stringer	Metal	Tan	Flaking	100 SF	0.4	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Pipe	Fiberglass Wrap	White	Flaking/Chipping	2 SF	0.1	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Stair Riser	Concrete	Gray	Flaking/Chipping	90 SF	0.3	Negative
2320	1	B	S04	Stairwell D behind Gas Main/Storage Room	Stair Tread	Concrete	Gray	Flaking/Chipping	90SF	0.2	Negative
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	W1	Concrete	White	Flaking	12 SF	0.5	Negative
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	W2	Concrete	White	Flaking, Cracking	15 SF	0.2	Negative

				Inspection Dates: 11/30 - 12/9/2021	School District of Philadelphia						
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report						
				Inspection Company: BATT	Girard School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	Door	Metal	Brown	Chipping	6 SF	0.4	Negative
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	Ceiling	Concrete	White	Flaking	14 SF	0.2	Negative
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	Piping	Metal	White	Chipping	15 SF	0.2	Negative
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	Stair Riser	Concrete	Brown	Chipping	20 SF	0.2	Negative
2320	1	B	S05	Stairwell from Fan Room to Boiler Room	Stair Tread	Concrete	Brown	Chipping	20 SF	0.3	Negative
2320	1	C	CS	Crawlspace accessible Outside Building Engineer's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	C	CS	Crawlspace accessible Outside Building Engineer's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	C	CS	Crawlspace accessible Outside Building Engineer's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	C	CS	Crawlspace accessible Outside Building Engineer's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	C	CS	Crawlspace accessible Outside Building Engineer's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	C	CS	Crawlspace accessible Outside Building Engineer's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	C	CS	Crawlspace accessible by Stairwell opposite Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace accessible by Stairwell opposite Boiler Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace accessible by Stairwell opposite Boiler Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace accessible by Stairwell opposite Boiler Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace accessible by Stairwell opposite Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace accessible by Stairwell opposite Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace near Fan/Electrical Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace near Fan/Electrical Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace near Fan/Electrical Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace near Fan/Electrical Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace near Fan/Electrical Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	C	CS	Crawlspace near Fan/Electrical Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2320	1	A	AT	Attic	W1	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	A	AT	Attic	W2	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	A	AT	Attic	W3	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	A	AT	Attic	W4	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	A	AT	Attic	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2320	1	A	AT	Attic	Floor	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 11/30 - 12/9/2021 Inspector Name and Certificate Number: Charles Rhodes, 003542	School District of Philadelphia Lead Safe Certification Assessment Report Girard School						
				Inspection Company: BATT							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2320	2	1	TRAILER	Portable Trailer	W1	Drywall	Tan	None	N/A	N/A	N/A
2320	2	1	TRAILER	Portable Trailer	Windowsill	Wood	White	Flaking	8 SF	0.2	Negative
2320	2	1	TRAILER	Portable Trailer	Door Frame	Metal	Tan	Chipping	2 SF	0.2	Negative
2320	2	1	TRAILER	Portable Trailer	Door	Metal	Tan	Chipping	4 SF	0.2	Negative
2320	2	1	TRAILER	Portable Trailer	W2	Drywall	Tan	Flaking	--	0.1	Negative
2320	2	1	TRAILER	Portable Trailer	Shelf	Wood	Gray	Chipping	5 SF	0.2	Negative
2320	2	1	TRAILER	Portable Trailer	W3	Drywall	Tan	Flaking	--	0.2	Negative
2320	2	1	TRAILER	Portable Trailer	W4	Drywall	Tan	Flaking	--	0.3	Negative
2320	2	1	TRAILER	Portable Trailer	Vent	Metal	Tan	Chipping	3 SF	0.3	Negative
2320	2	1	TRAILER	Portable Trailer	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2320	2	1	TRAILER	Portable Trailer	Floor	N/A	N/A	N/A	N/A	N/A	N/A