

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	3	300	Classroom 300	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	300	Classroom 300	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	300	Classroom 300	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	300	Classroom 300	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	300	Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	300	Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	301	Classroom 301	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	3	301	Classroom 301	Yes	W2	CMU	Beige	None	0	0.1	Negative
8430	1	3	301	Classroom 301	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	3	301	Classroom 301	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	3	301	Classroom 301	Yes	Ceiling	Concrete	Beige	Flaking	1	0.3	Negative
8430	1	3	301	Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	301	Classroom 301	Yes	Column3	Concrete	Beige	None	0	0.1	Negative
8430	1	3	301	Classroom 301	Yes	Column1	Concrete	Beige	None	0	0.3	Negative
8430	1	3	301	Classroom 301	Yes	Door Casing	Metal	Tan	None	0	0.4	Negative
8430	1	3	301	Classroom 301	Yes	Door	Wood	Tan	None	0	0.1	Negative
8430	1	3	302	Classroom 302	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	302	Classroom 302	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	302	Classroom 302	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	302	Classroom 302	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	302	Classroom 302	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	302	Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	303	Classroom 303	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	303	Classroom 303	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	303	Classroom 303	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	303	Classroom 303	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	303	Classroom 303	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	303	Classroom 303	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304	Classroom 304	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304	Classroom 304	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304	Classroom 304	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304	Classroom 304	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304	Classroom 304	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304	Classroom 304	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	305	Classroom 305	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	3	305	Classroom 305	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	3	305	Classroom 305	Yes	W3	CMU	Beige	Flaking	1	0	Negative
8430	1	3	305	Classroom 305	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	3	305	Classroom 305	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	3	305	Classroom 305	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	305	Classroom 305	Yes	Door Casing	Metal	Tan	None	0	0.4	Negative
8430	1	3	305	Classroom 305	Yes	Column3	Concrete	Beige	None	0	0.2	Negative
8430	1	3	305	Classroom 305	Yes	Column1	Concrete	Beige	None	0	0.3	Negative
8430	1	3	307	Classroom 307	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	307	Classroom 307	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	307	Classroom 307	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	307	Classroom 307	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	307	Classroom 307	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	307	Classroom 307	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	309	Classroom 309	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	3	309	Classroom 309	Yes	W2	CMU	Beige	Flaking	1	0.1	Negative
8430	1	3	309	Classroom 309	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	3	309	Classroom 309	Yes	W4	CMU	Beige	None	0	0.1	Negative
8430	1	3	309	Classroom 309	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	309	Classroom 309	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	309	Classroom 309	Yes	Column1	Concrete	Beige	None	0	0.3	Negative
8430	1	3	309	Classroom 309	Yes	Column3	Concrete	Beige	Flaking	1	0.2	Negative
8430	1	3	309	Classroom 309	Yes	Door Casing	Metal	Tan	None	0	0.5	Negative
8430	1	3	313	Classroom 313	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	313	Classroom 313	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	313	Classroom 313	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	313	Classroom 313	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	313	Classroom 313	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	313	Classroom 313	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	315	Classroom 315	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	315	Classroom 315	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	315	Classroom 315	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	315	Classroom 315	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	315	Classroom 315	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	315	Classroom 315	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	317	Classroom 317	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	317	Classroom 317	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	317	Classroom 317	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	317	Classroom 317	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	317	Classroom 317	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	317	Classroom 317	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	318	Classroom 318	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	318	Classroom 318	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	3	318	Classroom 318	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	318	Classroom 318	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	318	Classroom 318	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	318	Classroom 318	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	319	Classroom 319	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	319	Classroom 319	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	319	Classroom 319	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	319	Classroom 319	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	319	Classroom 319	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	319	Classroom 319	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	321	Classroom 321	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	321	Classroom 321	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	321	Classroom 321	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	321	Classroom 321	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	321	Classroom 321	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	321	Classroom 321	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	316	Classroom 316	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	316	Classroom 316	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	316	Classroom 316	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	316	Classroom 316	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	316	Classroom 316	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	316	Classroom 316	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	314	Classroom 314	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	3	314	Classroom 314	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	3	314	Classroom 314	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	3	314	Classroom 314	Yes	W4	CMU	Beige	Flaking	1	0	Negative
8430	1	3	314	Classroom 314	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	314	Classroom 314	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	314	Classroom 314	Yes	Door Casing	Metal	Tan	None	0	0.5	Negative
8430	1	3	314	Classroom 314	Yes	Column1	Concrete	Beige	None	0	0.1	Negative
8430	1	3	314	Classroom 314	Yes	Column3	Concrete	Beige	None	0	0.3	Negative
8430	1	B	S03	Stairs next to girl's restroom in basement	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S03	Stairs next to girl's restroom in basement	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S03	Stairs next to girl's restroom in basement	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S03	Stairs next to girl's restroom in basement	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Kristen Masotes, 058358		Greenberg School						
				Inspection Company: Acer		600 Sharon Lane, Philadelphia, PA 19115						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	B	S03	Stairs next to girl's restroom in basement	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S03	Stairs next to girl's restroom in basement	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304A	Girl's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304A	Girl's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304A	Girl's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304A	Girl's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304A	Girl's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304A	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCB	Boy's Restroom Pipe Chase Closest to the Sink	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCB	Boy's Restroom Pipe Chase Closest to the Sink	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCB	Boy's Restroom Pipe Chase Closest to the Sink	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCB	Boy's Restroom Pipe Chase Closest to the Sink	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCB	Boy's Restroom Pipe Chase Closest to the Sink	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCB	Boy's Restroom Pipe Chase Closest to the Sink	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCA	Boy's Restroom Pipe Chase Closest to the Entrance	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCA	Boy's Restroom Pipe Chase Closest to the Entrance	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCA	Boy's Restroom Pipe Chase Closest to the Entrance	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCA	Boy's Restroom Pipe Chase Closest to the Entrance	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCA	Boy's Restroom Pipe Chase Closest to the Entrance	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304PCA	Boy's Restroom Pipe Chase Closest to the Entrance	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304B	Boy's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304B	Boy's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304B	Boy's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304B	Boy's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304B	Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	304B	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306X	Women's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306X	Women's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Kristen Masotes, 058358		Greenberg School						
				Inspection Company: Acer		600 Sharon Lane, Philadelphia, PA 19115						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	3	306X	Women's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306X	Women's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306X	Women's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306X	Women's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306XPC	Pipe Chase between Staff Women's and Men's Restroom	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306XPC	Pipe Chase between Staff Women's and Men's Restroom	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306XPC	Pipe Chase between Staff Women's and Men's Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306XPC	Pipe Chase between Staff Women's and Men's Restroom	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306XPC	Pipe Chase between Staff Women's and Men's Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306XPC	Pipe Chase between Staff Women's and Men's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	308	Men's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	308	Men's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	308	Men's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	308	Men's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	308	Men's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	308	Men's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306	Classroom 306	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306	Classroom 306	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306	Classroom 306	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306	Classroom 306	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306	Classroom 306	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	306	Classroom 306	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3A	Storage Room adjacent to Classroom 300	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3A	Storage Room adjacent to Classroom 300	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3A	Storage Room adjacent to Classroom 300	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3A	Storage Room adjacent to Classroom 300	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3A	Storage Room adjacent to Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3A	Storage Room adjacent to Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3B	Storage Room 3-A adjacent to Classroom 306	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	3	3B	Storage Room 3-A adjacent to Classroom 306	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3B	Storage Room 3-A adjacent to Classroom 306	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3B	Storage Room 3-A adjacent to Classroom 306	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3B	Storage Room 3-A adjacent to Classroom 306	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3B	Storage Room 3-A adjacent to Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3C	Storage Room adjacent to Classroom 314	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3C	Storage Room adjacent to Classroom 314	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3C	Storage Room adjacent to Classroom 314	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3C	Storage Room adjacent to Classroom 314	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3C	Storage Room adjacent to Classroom 314	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3C	Storage Room adjacent to Classroom 314	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3D	Storage Room adjacent to Classroom 318	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3D	Storage Room adjacent to Classroom 318	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3D	Storage Room adjacent to Classroom 318	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3D	Storage Room adjacent to Classroom 318	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3D	Storage Room adjacent to Classroom 318	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	3D	Storage Room adjacent to Classroom 318	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	3	C4	Custodial Storage Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	C4	Custodial Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H310	Hallway Classroom 313-321	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H310	Hallway Classroom 313-321	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H310	Hallway Classroom 313-321	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H310	Hallway Classroom 313-321	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H310	Hallway Classroom 313-321	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H310	Hallway Classroom 313-321	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H311	Hallway Classroom 300-309	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H311	Hallway Classroom 300-309	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H311	Hallway Classroom 300-309	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H311	Hallway Classroom 300-309	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H311	Hallway Classroom 300-309	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	H311	Hallway Classroom 300-309	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S31	Stairs adjacent to Classroom 318	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S31	Stairs adjacent to Classroom 318	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S31	Stairs adjacent to Classroom 318	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S31	Stairs adjacent to Classroom 318	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S31	Stairs adjacent to Classroom 318	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S31	Stairs adjacent to Classroom 318	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S33	Stairs adjacent to Classroom 306	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S33	Stairs adjacent to Classroom 306	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S33	Stairs adjacent to Classroom 306	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S33	Stairs adjacent to Classroom 306	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S33	Stairs adjacent to Classroom 306	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S33	Stairs adjacent to Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S34	Stairs adjacent to Classroom 300	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S34	Stairs adjacent to Classroom 300	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S34	Stairs adjacent to Classroom 300	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S34	Stairs adjacent to Classroom 300	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S34	Stairs adjacent to Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	3	S34	Stairs adjacent to Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	C5	Custodial Storage Room adjacent to ESOL Office	No	W1	CMU	Beige	None	0	0	Negative
8430	1	2	C5	Custodial Storage Room adjacent to ESOL Office	No	W2	CMU	Beige	None	0	0	Negative
8430	1	2	C5	Custodial Storage Room adjacent to ESOL Office	No	W3	CMU	Beige	Flaking	5	0	Negative

				Inspection Dates: 1/24/2022-1/26/2022		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Kristen Masotes, 058358		Greenberg School						
				Inspection Company: Acer		600 Sharon Lane, Philadelphia, PA 19115						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	2	C5	Custodial Storage Room adjacent to ESOL Office	No	W4	CMU	Beige	None	0	0	Negative
8430	1	2	C5	Custodial Storage Room adjacent to ESOL Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	C5	Custodial Storage Room adjacent to ESOL Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2A	Storage Room adjacent to Classroom 200	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2A	Storage Room adjacent to Classroom 200	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2A	Storage Room adjacent to Classroom 200	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2A	Storage Room adjacent to Classroom 200	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2A	Storage Room adjacent to Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2A	Storage Room adjacent to Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2B	Storage Room adjacent to Office 210	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2B	Storage Room adjacent to Office 210	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2B	Storage Room adjacent to Office 210	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2B	Storage Room adjacent to Office 210	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2B	Storage Room adjacent to Office 210	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2B	Storage Room adjacent to Office 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2C	Custodial Storage	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2C	Custodial Storage	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2C	Custodial Storage	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2C	Custodial Storage	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2C	Custodial Storage	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2C	Custodial Storage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2D	Storage Room adjacent to Classroom 216	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2D	Storage Room adjacent to Classroom 216	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2D	Storage Room adjacent to Classroom 216	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2D	Storage Room adjacent to Classroom 216	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2D	Storage Room adjacent to Classroom 216	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2D	Storage Room adjacent to Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Kristen Masotes, 058358		Greenberg School						
				Inspection Company: Acer		600 Sharon Lane, Philadelphia, PA 19115						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	2	2E	Storage Room adjacent to Boy's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2E	Storage Room adjacent to Boy's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2E	Storage Room adjacent to Boy's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2E	Storage Room adjacent to Boy's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2E	Storage Room adjacent to Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2E	Storage Room adjacent to Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2S	MDF Server Room adjacent to 2C	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2S	MDF Server Room adjacent to 2C	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2S	MDF Server Room adjacent to 2C	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2S	MDF Server Room adjacent to 2C	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2S	MDF Server Room adjacent to 2C	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	2S	MDF Server Room adjacent to 2C	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H28	Hallway Classroom 211-217	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H28	Hallway Classroom 211-217	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H28	Hallway Classroom 211-217	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H28	Hallway Classroom 211-217	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H28	Hallway Classroom 211-217	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H28	Hallway Classroom 211-217	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H29	Hallway Classroom 200-210	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H29	Hallway Classroom 200-210	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H29	Hallway Classroom 200-210	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H29	Hallway Classroom 200-210	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H29	Hallway Classroom 200-210	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	H29	Hallway Classroom 200-210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S21	Stairs adjacent to Classroom 216	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S21	Stairs adjacent to Classroom 216	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S21	Stairs adjacent to Classroom 216	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S21	Stairs adjacent to Classroom 216	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S21	Stairs adjacent to Classroom 216	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S21	Stairs adjacent to Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S23	Stairs adjacent to Office 210	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S23	Stairs adjacent to Office 210	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S23	Stairs adjacent to Office 210	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S23	Stairs adjacent to Office 210	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	2	S23	Stairs adjacent to Office 210	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S23	Stairs adjacent to Office 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S24	Stairs adjacent to Classroom 200	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S24	Stairs adjacent to Classroom 200	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S24	Stairs adjacent to Classroom 200	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S24	Stairs adjacent to Classroom 200	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S24	Stairs adjacent to Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	S24	Stairs adjacent to Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	200	Classroom 200	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	2	200	Classroom 200	Yes	W2	CMU	Beige	None	0	0.1	Negative
8430	1	2	200	Classroom 200	Yes	W3	CMU	Beige	Flaking	1	0	Negative
8430	1	2	200	Classroom 200	Yes	W4	CMU	Beige	None	0	0.1	Negative
8430	1	2	200	Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	200	Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	200	Classroom 200	Yes	Column3	Concrete	Beige	Chipping	2	0.1	Negative
8430	1	2	200	Classroom 200	Yes	Column1	Concrete	Beige	Chipping	2	0.1	Negative
8430	1	2	200	Classroom 200	Yes	Door Casing	Metal	Tan	None	0	0.3	Negative
8430	1	2	201	Classroom 201	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	201	Classroom 201	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	201	Classroom 201	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	201	Classroom 201	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	201	Classroom 201	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	202	Classroom 202	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	202	Classroom 202	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	202	Classroom 202	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	202	Classroom 202	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	202	Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	203	Classroom 203	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	203	Classroom 203	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	203	Classroom 203	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	203	Classroom 203	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	203	Classroom 203	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204	Classroom 204	Yes	W1	CMU	Beige	Flaking	4	0	Negative
8430	1	2	204	Classroom 204	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	2	204	Classroom 204	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	2	204	Classroom 204	Yes	W4	CMU	Beige	None	0	0	Negative

				Inspection Dates: 1/24/2022-1/26/2022		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Kristen Masotes, 058358		Greenberg School						
				Inspection Company: Acer		600 Sharon Lane, Philadelphia, PA 19115						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	2	204	Classroom 204	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204	Classroom 204	Yes	Door Casing	Metal	Tan	None	0	0.4	Negative
8430	1	2	204	Classroom 204	Yes	Column1	Concrete	Beige	None	0	0.3	Negative
8430	1	2	204	Classroom 204	Yes	Column3	Concrete	Beige	None	0	0.4	Negative
8430	1	2	205	Classroom 205	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	205	Classroom 205	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	205	Classroom 205	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	205	Classroom 205	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	205	Classroom 205	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	205	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	207	Classroom 207	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	207	Classroom 207	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	207	Classroom 207	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	207	Classroom 207	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	207	Classroom 207	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	207	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	209	Classroom 209	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	2	209	Classroom 209	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	2	209	Classroom 209	Yes	W3	CMU	Beige	Flaking	3	0	Negative
8430	1	2	209	Classroom 209	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	2	209	Classroom 209	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	209	Classroom 209	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	209	Classroom 209	Yes	Column1	Concrete	Beige	None	0	0.3	Negative
8430	1	2	209	Classroom 209	Yes	Column3	Concrete	Beige	None	0	0.4	Negative
8430	1	2	209	Classroom 209	Yes	Door Casing	Metal	Tan	None	0	0.5	Negative
8430	1	2	211	Classroom 211	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211	Classroom 211	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211	Classroom 211	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211	Classroom 211	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211	Classroom 211	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211	Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211A	Classroom 211A	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211A	Classroom 211A	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211A	Classroom 211A	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211A	Classroom 211A	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211A	Classroom 211A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211A	Classroom 211A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	Classroom 211B	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	2	211B	Classroom 211B	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	Classroom 211B	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	Classroom 211B	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	Classroom 211B	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	Classroom 211B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	213	Classroom 213	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	2	213	Classroom 213	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	2	213	Classroom 213	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	2	213	Classroom 213	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	2	213	Classroom 213	Yes	Ceiling	Concrete	Beige	Efflorescence	1	0.3	Negative
8430	1	2	213	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	213	Classroom 213	Yes	Column3	Concrete	Beige	None	0	0.3	Negative
8430	1	2	213	Classroom 213	Yes	Column1	Concrete	Beige	Flaking	1	0.3	Negative
8430	1	2	215	Classroom 215	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	215	Classroom 215	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	215	Classroom 215	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	215	Classroom 215	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	215	Classroom 215	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	215	Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	218	Fan Room above the Cafeteria	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	218	Fan Room above the Cafeteria	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	218	Fan Room above the Cafeteria	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	218	Fan Room above the Cafeteria	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	218	Fan Room above the Cafeteria	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	218	Fan Room above the Cafeteria	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	217	Classroom 217	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	217	Classroom 217	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	217	Classroom 217	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	217	Classroom 217	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	217	Classroom 217	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	217	Classroom 217	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	212	Classroom 212	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	212	Classroom 212	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	212	Classroom 212	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	212	Classroom 212	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	212	Classroom 212	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	212	Classroom 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	214	Classroom 214	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	214	Classroom 214	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	2	214	Classroom 214	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	214	Classroom 214	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	214	Classroom 214	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	214	Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	216	Classroom 216	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	216	Classroom 216	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	216	Classroom 216	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	216	Classroom 216	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	216	Classroom 216	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	216	Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	210	ESOL Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	210	ESOL Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	210	ESOL Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	210	ESOL Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	210	ESOL Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	210	ESOL Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204A	Girl's Restroom	Yes	W1	CMU	Pink	Peeling	15	0	Negative
8430	1	2	204A	Girl's Restroom	Yes	W2	CMU	Pink	None	0	0.1	Negative
8430	1	2	204A	Girl's Restroom	Yes	W3	CMU	Pink	None	0	0	Negative
8430	1	2	204A	Girl's Restroom	Yes	W4	CMU	Pink	Peeling	4	0	Negative
8430	1	2	204A	Girl's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204A	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204PCC	Pipe Chase between Girl's and Boy's Restroom	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204PCC	Pipe Chase between Girl's and Boy's Restroom	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204PCC	Pipe Chase between Girl's and Boy's Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204PCC	Pipe Chase between Girl's and Boy's Restroom	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204PCC	Pipe Chase between Girl's and Boy's Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204PCC	Pipe Chase between Girl's and Boy's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204B	Boy's Restroom	Yes	W1	CMU	Blue	None	0	0.1	Negative
8430	1	2	204B	Boy's Restroom	Yes	W2	CMU	Blue	None	0	0	Negative
8430	1	2	204B	Boy's Restroom	Yes	W3	CMU	Blue	Peeling	1	0	Negative
8430	1	2	204B	Boy's Restroom	Yes	W4	CMU	Blue	None	0	0	Negative
8430	1	2	204B	Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	204B	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Kristen Masotes, 058358		Greenberg School						
				Inspection Company: Acer		600 Sharon Lane, Philadelphia, PA 19115						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	2	206	Women's Restroom	Yes	W1	CMU	Beige	Peeling	7	0	Negative
8430	1	2	206	Women's Restroom	Yes	W2	CMU	Beige	Flaking	2	0	Negative
8430	1	2	206	Women's Restroom	Yes	W3	CMU	Beige	Flaking	2	0.4	Negative
8430	1	2	206	Women's Restroom	Yes	W4	CMU	Beige	Flaking	3	0.1	Negative
8430	1	2	206	Women's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	206	Women's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	208	Men's Restroom	Yes	W1	CMU	Beige	None	0	0.1	Negative
8430	1	2	208	Men's Restroom	Yes	W2	CMU	Beige	Peeling	15	0	Negative
8430	1	2	208	Men's Restroom	Yes	W3	CMU	Beige	Flaking	15	0	Negative
8430	1	2	208	Men's Restroom	Yes	W4	CMU	Beige	Flaking	5	0	Negative
8430	1	2	208	Men's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	208	Men's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	IMC Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	IMC Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	IMC Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	IMC Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	IMC Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211B	IMC Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211C	IMC Office #2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211C	IMC Office #2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211C	IMC Office #2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211C	IMC Office #2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211C	IMC Office #2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211C	IMC Office #2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211D	IMC Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211D	IMC Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211D	IMC Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211D	IMC Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211D	IMC Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	2	211D	IMC Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	112	Auditorium	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	1	112	Auditorium	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	1	112	Auditorium	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	112	Auditorium	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	112	Auditorium	Yes	Ceiling	Plaster	Beige	None	0	0.3	Negative
8430	1	1	112	Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	112	Auditorium	Yes	Column3	Concrete	Beige	None	0	0.2	Negative
8430	1	1	112 STAGE	Auditorium Stage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	112 STAGE	Auditorium Stage	Yes	W2	CMU	Beige	None	0	0	Negative

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	112 STAGE	Auditorium Stage	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	1	112 STAGE	Auditorium Stage	Yes	W4	CMU	Beige	None	0	0.1	Negative
8430	1	1	112 STAGE	Auditorium Stage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	112 STAGE	Auditorium Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H99	Hallway Between Auditorium and Gym	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H99	Hallway Between Auditorium and Gym	Yes	W2	CMU	Beige	None	0	0.1	Negative
8430	1	1	H99	Hallway Between Auditorium and Gym	Yes	W3	CMU	Beige	None	0	0.1	Negative
8430	1	1	H99	Hallway Between Auditorium and Gym	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H99	Hallway Between Auditorium and Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H99	Hallway Between Auditorium and Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S12	Stairs Between Auditorium and Gym	Yes	W1	CMU	Beige	Flaking	45	0	Negative
8430	1	1	S12	Stairs Between Auditorium and Gym	Yes	W2	CMU	Beige	Flaking	52	0	Negative
8430	1	1	S12	Stairs Between Auditorium and Gym	Yes	W3	CMU	Beige	Flaking	26	0	Negative
8430	1	1	S12	Stairs Between Auditorium and Gym	Yes	W4	CMU	Beige	Flaking	30	0	Negative
8430	1	1	S12	Stairs Between Auditorium and Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S12	Stairs Between Auditorium and Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Occupational Therapy Office Bathroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Occupational Therapy Office Bathroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Occupational Therapy Office Bathroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Occupational Therapy Office Bathroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Occupational Therapy Office Bathroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Occupational Therapy Office Bathroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Occupational Therapy Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Occupational Therapy Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Occupational Therapy Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Occupational Therapy Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Occupational Therapy Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Occupational Therapy Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113FR	Gym Fan Room	no	W1	CMU	Yellow	None	0	0.4	Negative
8430	1	1	113FR	Gym Fan Room	no	W2	Concrete	Yellow	None	0	0.3	Negative

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	113FR	Gym Fan Room	no	W3	Concrete	Yellow	None	0	0	Negative
8430	1	1	113FR	Gym Fan Room	no	W4	CMU	Yellow	Chipping	3	0.3	Negative
8430	1	1	113FR	Gym Fan Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113FR	Gym Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113	Gym	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113	Gym	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113	Gym	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113	Gym	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113	Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113	Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Gym Storage Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Gym Storage Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Gym Storage Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Gym Storage Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Gym Storage Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113H	Gym Storage Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113G	Girl's Locker Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113G	Girl's Locker Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113G	Girl's Locker Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113G	Girl's Locker Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113G	Girl's Locker Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113G	Girl's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113F	Girl's Restroom in Gym	Yes	W1	CMU	Purple	None	0	0	Negative
8430	1	1	113F	Girl's Restroom in Gym	Yes	W2	CMU	Purple	None	0	0.1	Negative
8430	1	1	113F	Girl's Restroom in Gym	Yes	W3	CMU	Purple	None	0	0	Negative
8430	1	1	113F	Girl's Restroom in Gym	Yes	W4	CMU	Purple	None	0	0.1	Negative
8430	1	1	113F	Girl's Restroom in Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113F	Girl's Restroom in Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113E	Boy's Restroom in Gym	Yes	W1	CMU	Orange	None	0	0.1	Negative
8430	1	1	113E	Boy's Restroom in Gym	Yes	W2	CMU	Orange	None	0	0	Negative
8430	1	1	113E	Boy's Restroom in Gym	Yes	W3	CMU	Orange	None	0	0	Negative
8430	1	1	113E	Boy's Restroom in Gym	Yes	W4	CMU	Orange	None	0	0	Negative
8430	1	1	113E	Boy's Restroom in Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113E	Boy's Restroom in Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113E PC	Boy's Restroom Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113E PC	Boy's Restroom Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113E PC	Boy's Restroom Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113E PC	Boy's Restroom Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113E PC	Boy's Restroom Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	113E PC	Boy's Restroom Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113D	Boy's Locker Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113D	Boy's Locker Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113D	Boy's Locker Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113D	Boy's Locker Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113D	Boy's Locker Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113D	Boy's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Gym Teacher's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Gym Teacher's Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Gym Teacher's Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Gym Teacher's Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Gym Teacher's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113B	Gym Teacher's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113A	Gym Teacher's Office Storage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113A	Gym Teacher's Office Storage	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113A	Gym Teacher's Office Storage	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113A	Gym Teacher's Office Storage	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113A	Gym Teacher's Office Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113A	Gym Teacher's Office Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113C	Gym Teacher's Office Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113C	Gym Teacher's Office Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113C	Gym Teacher's Office Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113C	Gym Teacher's Office Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113C	Gym Teacher's Office Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	113C	Gym Teacher's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	2X	Storage Outside Gym	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	2X	Storage Outside Gym	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	2X	Storage Outside Gym	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	2X	Storage Outside Gym	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	2X	Storage Outside Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	2X	Storage Outside Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H16	Hallway Outside Gym to Stair 2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H16	Hallway Outside Gym to Stair 2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H16	Hallway Outside Gym to Stair 2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H16	Hallway Outside Gym to Stair 2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H16	Hallway Outside Gym to Stair 2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H16	Hallway Outside Gym to Stair 2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107B	Women's Restroom Outside Gym	Yes	W1	CMU	Pink	Flaking	15	0	Negative
8430	1	1	107B	Women's Restroom Outside Gym	Yes	W2	CMU	Pink	Flaking	15	0	Negative

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	107B	Women's Restroom Outside Gym	Yes	W3	CMU	Pink	Flaking	15	0	Negative
8430	1	1	107B	Women's Restroom Outside Gym	Yes	W4	CMU	Pink	Flaking	15	0	Negative
8430	1	1	107B	Women's Restroom Outside Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107B	Women's Restroom Outside Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107A	Men's Restroom Outside Gym	Yes	W1	CMU	Green	Flaking	3	0.1	Negative
8430	1	1	107A	Men's Restroom Outside Gym	Yes	W2	CMU	Green	Flaking	19	0	Negative
8430	1	1	107A	Men's Restroom Outside Gym	Yes	W3	CMU	Green	Flaking	14	0	Negative
8430	1	1	107A	Men's Restroom Outside Gym	Yes	W4	Sheetrock	Green	Flaking	28	0.1	Negative
8430	1	1	107A	Men's Restroom Outside Gym	Yes	W1	CMU	Beige	None	0	0.1	Negative
8430	1	1	107A	Men's Restroom Outside Gym	Yes	W2	CMU	Beige	None	0	0.1	Negative
8430	1	1	107A	Men's Restroom Outside Gym	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	1	107A	Men's Restroom Outside Gym	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	107A	Men's Restroom Outside Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107A	Men's Restroom Outside Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S13	Stair 2 Across Classroom 107	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S13	Stair 2 Across Classroom 107	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S13	Stair 2 Across Classroom 107	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S13	Stair 2 Across Classroom 107	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S13	Stair 2 Across Classroom 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S13	Stair 2 Across Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107	Home & School 107	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107	Home & School 107	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107	Home & School 107	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107	Home & School 107	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107	Home & School 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	107	Home & School 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	109	Classroom 109	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	1	109	Classroom 109	Yes	W2	CMU	Beige	None	0	0.1	Negative
8430	1	1	109	Classroom 109	Yes	W3	N/A	N/A	Flaking	3	0.3	Negative
8430	1	1	109	Classroom 109	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	109	Classroom 109	Yes	Ceiling	Concrete	Beige	None	0	0.2	Negative
8430	1	1	109	Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	109	Classroom 109	Yes	Column3	Concrete	Beige	None	0	0.3	Negative
8430	1	1	109	Classroom 109	Yes	Column2	Concrete	Beige	None	0	0.4	Negative
8430	1	1	111	Classroom 111	Yes	W1	CMU	Beige	Flaking	1	0	Negative
8430	1	1	111	Classroom 111	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	1	111	Classroom 111	Yes	W3	CMU	Beige	Flaking	2	0	Negative
8430	1	1	111	Classroom 111	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	111	Classroom 111	Yes	Ceiling	Concrete	Beige	None	0	0	Negative

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	111	Classroom 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	111	Classroom 111	Yes	Column3	Concrete	Beige	None	0	0.2	Negative
8430	1	1	111	Classroom 111	Yes	Column1	Concrete	Beige	None	0	0.2	Negative
8430	1	1	S11	Stairs Adjacent to Classroom 108	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S11	Stairs Adjacent to Classroom 108	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S11	Stairs Adjacent to Classroom 108	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S11	Stairs Adjacent to Classroom 108	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S11	Stairs Adjacent to Classroom 108	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	S11	Stairs Adjacent to Classroom 108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108C	Classroom 108 Coat Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108C	Classroom 108 Coat Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108C	Classroom 108 Coat Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108C	Classroom 108 Coat Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108C	Classroom 108 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108C	Classroom 108 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108D	Classroom 108 Closet Near Window	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108D	Classroom 108 Closet Near Window	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108D	Classroom 108 Closet Near Window	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108D	Classroom 108 Closet Near Window	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108D	Classroom 108 Closet Near Window	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108D	Classroom 108 Closet Near Window	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108B	Classroom 108 Closet Near Door	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108B	Classroom 108 Closet Near Door	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108B	Classroom 108 Closet Near Door	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108B	Classroom 108 Closet Near Door	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108B	Classroom 108 Closet Near Door	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108B	Classroom 108 Closet Near Door	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108A	Classroom 108 Restroom	Yes	W1	CMU	Blue	None	0	0.1	Negative
8430	1	1	108A	Classroom 108 Restroom	Yes	W2	CMU	Blue	None	0	0	Negative
8430	1	1	108A	Classroom 108 Restroom	Yes	W3	CMU	Blue	None	0	0	Negative
8430	1	1	108A	Classroom 108 Restroom	Yes	W4	CMU	Blue	Flaking	16	0	Negative
8430	1	1	108A	Classroom 108 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108A	Classroom 108 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	108	Classroom 108	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	1	108	Classroom 108	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	1	108	Classroom 108	Yes	W3	CMU	Beige	Flaking	1	0.1	Negative
8430	1	1	108	Classroom 108	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	108	Classroom 108	Yes	Ceiling	Concrete	White	None	0	0.1	Negative
8430	1	1	108	Classroom 108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Kristen Masotes, 058358		Greenberg School						
				Inspection Company: Acer		600 Sharon Lane, Philadelphia, PA 19115						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	108	Classroom 108	Yes	Column1	Concrete	Beige	None	0	0.1	Negative
8430	1	1	108	Classroom 108	Yes	Column3	Concrete	Beige	None	0	0.1	Negative
8430	1	1	106C	Hallway in Back Connecting Classroom 108 and Classroom 106	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	1	106C	Hallway in Back Connecting Classroom 108 and Classroom 106	Yes	W2	CMU	Beige	Flaking	4	0.1	Negative
8430	1	1	106C	Hallway in Back Connecting Classroom 108 and Classroom 106	Yes	W3	CMU	Beige	None	0	0.1	Negative
8430	1	1	106C	Hallway in Back Connecting Classroom 108 and Classroom 106	Yes	W4	CMU	Beige	None	0	0.1	Negative
8430	1	1	106C	Hallway in Back Connecting Classroom 108 and Classroom 106	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106C	Hallway in Back Connecting Classroom 108 and Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106C	Hallway in Back Connecting Classroom 108 and Classroom 106	Yes	Column3	Concrete	Beige	None	0	0.2	Negative
8430	1	1	106	Classroom 106	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	1	106	Classroom 106	Yes	W2	CMU	Beige	None	0	0.1	Negative
8430	1	1	106	Classroom 106	Yes	W3	CMU	Beige	None	0	0.1	Negative
8430	1	1	106	Classroom 106	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	106	Classroom 106	Yes	Ceiling	Concrete	Beige	None	0	0	Negative
8430	1	1	106	Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106	Classroom 106	Yes	Column3	Concrete	Beige	None	0	0.1	Negative
8430	1	1	106	Classroom 106	Yes	Column1	Concrete	Beige	None	0	0.1	Negative
8430	1	1	106B	Classroom 106 Coat Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106B	Classroom 106 Coat Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106B	Classroom 106 Coat Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106B	Classroom 106 Coat Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106B	Classroom 106 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106B	Classroom 106 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106D	Storage Closet in Classroom 106 Coat Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106D	Storage Closet in Classroom 106 Coat Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106D	Storage Closet in Classroom 106 Coat Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106D	Storage Closet in Classroom 106 Coat Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106D	Storage Closet in Classroom 106 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106D	Storage Closet in Classroom 106 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	106A	Classroom 106 Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106A	Classroom 106 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106A	Classroom 106 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106A	Classroom 106 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106A	Classroom 106 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	106A	Classroom 106 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H17	Hallway from Lobby to Classroom 108	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H17	Hallway from Lobby to Classroom 108	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H17	Hallway from Lobby to Classroom 108	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H17	Hallway from Lobby to Classroom 108	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H17	Hallway from Lobby to Classroom 108	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H17	Hallway from Lobby to Classroom 108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	1D	Storage Closet Across Women's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	1D	Storage Closet Across Women's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	1D	Storage Closet Across Women's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	1D	Storage Closet Across Women's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	1D	Storage Closet Across Women's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	1D	Storage Closet Across Women's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	1X	Custodial Closet Across from Men's Restroom	No	W1	CMU	Beige	None	0	0.1	Negative
8430	1	1	1X	Custodial Closet Across from Men's Restroom	No	W2	CMU	Beige	None	0	0	Negative
8430	1	1	1X	Custodial Closet Across from Men's Restroom	No	W3	CMU	Beige	Flaking	4	0.1	Negative
8430	1	1	1X	Custodial Closet Across from Men's Restroom	No	W4	CMU	Beige	None	0	0	Negative
8430	1	1	1X	Custodial Closet Across from Men's Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	1X	Custodial Closet Across from Men's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	LOBBY	Main Lobby	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	LOBBY	Main Lobby	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	LOBBY	Main Lobby	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	LOBBY	Main Lobby	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	LOBBY	Main Lobby	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	LOBBY	Main Lobby	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	198	Main Entrance Foyer	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	198	Main Entrance Foyer	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	198	Main Entrance Foyer	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	198	Main Entrance Foyer	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	198	Main Entrance Foyer	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	198	Main Entrance Foyer	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199	Storage Closet in Lobby	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199	Storage Closet in Lobby	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199	Storage Closet in Lobby	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199	Storage Closet in Lobby	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199	Storage Closet in Lobby	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199	Storage Closet in Lobby	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199A	Access Panel in Storage Closet in Lobby	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199A	Access Panel in Storage Closet in Lobby	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199A	Access Panel in Storage Closet in Lobby	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199A	Access Panel in Storage Closet in Lobby	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199A	Access Panel in Storage Closet in Lobby	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	199A	Access Panel in Storage Closet in Lobby	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105A	Principal's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105A	Principal's Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105A	Principal's Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105A	Principal's Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105A	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105A	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105AA	Principal's Office Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105AA	Principal's Office Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105AA	Principal's Office Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105AA	Principal's Office Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105AA	Principal's Office Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	105AA	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105W	Storage Closet Outside Principal's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105W	Storage Closet Outside Principal's Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105W	Storage Closet Outside Principal's Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105W	Storage Closet Outside Principal's Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105W	Storage Closet Outside Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105W	Storage Closet Outside Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H15	Hallway from Main Office to Classroom 100	Yes	W1	CMU	White	None	0	0	Negative
8430	1	1	H15	Hallway from Main Office to Classroom 100	Yes	W2	CMU	White	None	0	0	Negative
8430	1	1	H15	Hallway from Main Office to Classroom 100	Yes	W3	CMU	White	Flaking	8	0	Negative
8430	1	1	H15	Hallway from Main Office to Classroom 100	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H15	Hallway from Main Office to Classroom 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	H15	Hallway from Main Office to Classroom 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	100	Classroom 100	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	1	100	Classroom 100	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	1	100	Classroom 100	Yes	W3	CMU	Beige	Flaking	2	0	Negative
8430	1	1	100	Classroom 100	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	100	Classroom 100	Yes	Ceiling	Concrete	Beige	None	0	0.3	Negative
8430	1	1	100	Classroom 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	100	Classroom 100	Yes	Column1	Concrete	Beige	None	0	0.4	Negative
8430	1	1	100	Classroom 100	Yes	Column3	Concrete	Beige	None	0	0.3	Negative
8430	1	1	101	Classroom 101 (Music)	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	1	101	Classroom 101 (Music)	Yes	W2	CMU	Beige	None	0	0.1	Negative
8430	1	1	101	Classroom 101 (Music)	Yes	W3	CMU	Beige	Flaking	2	0.1	Negative
8430	1	1	101	Classroom 101 (Music)	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	101	Classroom 101 (Music)	Yes	Ceiling	Concrete	Beige	None	0	0.1	Negative
8430	1	1	101	Classroom 101 (Music)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	101	Classroom 101 (Music)	Yes	Column3	Concrete	Beige	None	0	0.4	Negative
8430	1	1	101	Classroom 101 (Music)	Yes	Column1	Concrete	Beige	None	0	0.3	Negative
8430	1	1	102	Classroom 102	Yes	W1	CMU	Beige	Flaking	2	0.1	Negative

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	102	Classroom 102	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	1	102	Classroom 102	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	1	102	Classroom 102	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	102	Classroom 102	Yes	Ceiling	Concrete	Beige	None	0	0.4	Negative
8430	1	1	102	Classroom 102	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	102	Classroom 102	Yes	Column1	Concrete	Beige	None	0	0.3	Negative
8430	1	1	102	Classroom 102	Yes	Column3	Concrete	Beige	None	0	0.2	Negative
8430	1	1	103	Classroom 103	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	1	103	Classroom 103	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	1	103	Classroom 103	Yes	W3	CMU	Beige	Flaking	3	0	Negative
8430	1	1	103	Classroom 103	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	1	103	Classroom 103	Yes	Ceiling	Concrete	Beige	None	0	0.3	Negative
8430	1	1	103	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	103	Classroom 103	Yes	Column3	Concrete	Beige	None	0	0.2	Negative
8430	1	1	103	Classroom 103	Yes	Column1	Concrete	Beige	None	0	0.3	Negative
8430	1	1	104C	Book Storage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104C	Book Storage	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104C	Book Storage	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104C	Book Storage	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104C	Book Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104C	Book Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104D	Closet Across from Main Office Side Door	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104D	Closet Across from Main Office Side Door	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104D	Closet Across from Main Office Side Door	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104D	Closet Across from Main Office Side Door	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104D	Closet Across from Main Office Side Door	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104D	Closet Across from Main Office Side Door	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104	Boy's Restroom	Yes	W1	CMU	Blue	Flaking	2	0	Negative
8430	1	1	104	Boy's Restroom	Yes	W2	CMU	Blue	None	0	0	Negative
8430	1	1	104	Boy's Restroom	Yes	W3	CMU	Blue	Flaking	1	0	Negative
8430	1	1	104	Boy's Restroom	Yes	W4	CMU	Blue	None	0	0	Negative
8430	1	1	104	Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105D	Teacher's Lounge	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	1	105D	Teacher's Lounge	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105D	Teacher's Lounge	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105D	Teacher's Lounge	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105D	Teacher's Lounge	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105D	Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105X	Teacher's Lounge Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105X	Teacher's Lounge Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105X	Teacher's Lounge Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105X	Teacher's Lounge Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105X	Teacher's Lounge Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105X	Teacher's Lounge Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105E	Nurse's Office	Yes	W1	CMU	Beige	None	0	0.4	Negative
8430	1	1	105E	Nurse's Office	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	1	105E	Nurse's Office	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	1	105E	Nurse's Office	Yes	W4	CMU	Beige	1	2	0.1	Negative
8430	1	1	105E	Nurse's Office	Yes	Ceiling	Concrete	Beige	None	0	0.3	Negative
8430	1	1	105E	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105	Main Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105	Main Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105	Main Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105	Main Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	105	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104B	Classroom 104	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104B	Classroom 104	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104B	Classroom 104	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104B	Classroom 104	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104B	Classroom 104	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	1	104B	Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S01	Stairs across from IMC	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S01	Stairs across from IMC	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S01	Stairs across from IMC	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S01	Stairs across from IMC	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S01	Stairs across from IMC	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	S01	Stairs across from IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	002/003	IMC (Library)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	002/003	IMC (Library)	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	002/003	IMC (Library)	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	002/003	IMC (Library)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Kristen Masotes, 058358		Greenberg School						
				Inspection Company: Acer		600 Sharon Lane, Philadelphia, PA 19115						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	B	002/003	IMC (Library)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	002/003	IMC (Library)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	400	STEM Lab	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	B	400	STEM Lab	Yes	W2	Drywall	White	None	0	0.1	Negative
8430	1	B	400	STEM Lab	Yes	W3	CMU	Beige	None	0	0.2	Negative
8430	1	B	400	STEM Lab	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	B	400	STEM Lab	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	400	STEM Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	400	STEM Lab	Yes	Column3	Concrete	Beige	Flaking	2	0.2	Negative
8430	1	B	401	Computer Lab	Yes	W1	CMU	Beige	None	0	0	Negative
8430	1	B	401	Computer Lab	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	B	401	Computer Lab	Yes	W3	CMU	Beige	None	0	0.1	Negative
8430	1	B	401	Computer Lab	Yes	W4	Drywall	White	None	0	0	Negative
8430	1	B	401	Computer Lab	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	401	Computer Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	401	Computer Lab	Yes	Column3	Concrete	Beige	Flaking	1	0.3	Negative
8430	1	B	4	Former Bomb Shelter across from IMC	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	4	Former Bomb Shelter across from IMC	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	4	Former Bomb Shelter across from IMC	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	4	Former Bomb Shelter across from IMC	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	4	Former Bomb Shelter across from IMC	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	4	Former Bomb Shelter across from IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H03	Hallway from IMC to Cafeteria to Men's Staff Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H03	Hallway from IMC to Cafeteria to Men's Staff Restroom	Yes	W2	CMU	Beige	Flaking	50	0	Negative
8430	1	B	H03	Hallway from IMC to Cafeteria to Men's Staff Restroom	Yes	W3	Concrete	Beige	Flaking	1	0.2	Negative
8430	1	B	H03	Hallway from IMC to Cafeteria to Men's Staff Restroom	Yes	W4	CMU	Beige	Flaking	16	0.1	Negative
8430	1	B	H03	Hallway from IMC to Cafeteria to Men's Staff Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H03	Hallway from IMC to Cafeteria to Men's Staff Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	5	Kitchen Storage Room	Yes	W1	CMU	Beige	Flaking	4	0.1	Negative
8430	1	B	5	Kitchen Storage Room	Yes	W2	N/A	N/A	Flaking	2	0.1	Negative

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	B	5	Kitchen Storage Room	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	B	5	Kitchen Storage Room	Yes	W4	CMU	Beige	Flaking	20	0	Negative
8430	1	B	5	Kitchen Storage Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	5	Kitchen Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H04	Hallway from Kitchen Storage Room to Cafeteria	Yes	W1	CMU	Beige	Flaking	12	0	Negative
8430	1	B	H04	Hallway from Kitchen Storage Room to Cafeteria	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H04	Hallway from Kitchen Storage Room to Cafeteria	Yes	W3	CMU	Beige	Flaking	8	0	Negative
8430	1	B	H04	Hallway from Kitchen Storage Room to Cafeteria	Yes	W4	CMU	Beige	Flaking	9	0.1	Negative
8430	1	B	H04	Hallway from Kitchen Storage Room to Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H04	Hallway from Kitchen Storage Room to Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	006A	Custodial Closet in Kitchen	no	W1	CMU	Beige	None	0	0.2	Negative
8430	1	B	006A	Custodial Closet in Kitchen	no	W2	CMU	Beige	None	0	0.1	Negative
8430	1	B	006A	Custodial Closet in Kitchen	no	W3	CMU	Beige	Flaking	2	0	Negative
8430	1	B	006A	Custodial Closet in Kitchen	no	W4	CMU	Beige	Flaking	2	0	Negative
8430	1	B	006A	Custodial Closet in Kitchen	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	006A	Custodial Closet in Kitchen	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	6	Kitchen	Yes	W1	CMU	Beige	Flaking	5	0.1	Negative
8430	1	B	6	Kitchen	Yes	W2	CMU	Beige	None	0	0	Negative
8430	1	B	6	Kitchen	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	B	6	Kitchen	Yes	W4	N/A	N/A	Flaking	3	0.3	Negative
8430	1	B	6	Kitchen	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	6	Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	6	Kitchen	Yes	Column4	Concrete	Beige	None	0	0.3	Negative
8430	1	B	7	Cafeteria	Yes	W1	CMU	Beige	Flaking	20	0	Negative
8430	1	B	7	Cafeteria	Yes	W2	CMU	Beige	Flaking	15	0	Negative
8430	1	B	7	Cafeteria	Yes	W3	CMU	Beige	Flaking	10	0	Negative
8430	1	B	7	Cafeteria	Yes	W4	CMU	Beige	Flaking	25	0	Negative
8430	1	B	7	Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	7	Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	7	Cafeteria	Yes	Column	Concrete	Blue	None	0	0.3	Negative
8430	1	B	7	Cafeteria	Yes	Column	Concrete	Blue	None	0	0.3	Negative
8430	1	B	8	Boiler Room Storage Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	8	Boiler Room Storage Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	8	Boiler Room Storage Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	B	8	Boiler Room Storage Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	8	Boiler Room Storage Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	8	Boiler Room Storage Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	9	Girl's Restroom	Yes	W1	CMU	Blue	None	0	0	Negative
8430	1	B	9	Girl's Restroom	Yes	W2	CMU	Blue	None	0	0	Negative
8430	1	B	9	Girl's Restroom	Yes	W3	CMU	Blue	None	0	0	Negative
8430	1	B	9	Girl's Restroom	Yes	W4	CMU	Blue	None	0	0	Negative
8430	1	B	9	Girl's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	9	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	10	Boy's Restroom	Yes	W1	CMU	Blue	None	0	0	Negative
8430	1	B	10	Boy's Restroom	Yes	W2	CMU	Blue	Flaking	2	0.1	Negative
8430	1	B	10	Boy's Restroom	Yes	W3	CMU	Blue	Flaking	2	0	Negative
8430	1	B	10	Boy's Restroom	Yes	W4	CMU	Blue	None	0	0	Negative
8430	1	B	10	Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	10	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	14	Men's Staff Restroom	Yes	W1	CMU	Green	Flaking	3	0	Negative
8430	1	B	14	Men's Staff Restroom	Yes	W2	CMU	Green	Flaking	2	0	Negative
8430	1	B	14	Men's Staff Restroom	Yes	W3	CMU	Green	Flaking	1	0.1	Negative
8430	1	B	14	Men's Staff Restroom	Yes	W4	CMU	Green	None	0	0	Negative
8430	1	B	14	Men's Staff Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	14	Men's Staff Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	11	Women's Staff Restroom	Yes	W1	CMU	Pink	None	0	0	Negative
8430	1	B	11	Women's Staff Restroom	Yes	W2	CMU	Pink	Flaking	1	0	Negative
8430	1	B	11	Women's Staff Restroom	Yes	W3	CMU	Pink	Flaking	1	0	Negative
8430	1	B	11	Women's Staff Restroom	Yes	W4	CMU	Pink	None	0	0.1	Negative
8430	1	B	11	Women's Staff Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	11	Women's Staff Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H01	Hallway from Boiler Room to Maintenance Storage Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H01	Hallway from Boiler Room to Maintenance Storage Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H01	Hallway from Boiler Room to Maintenance Storage Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H01	Hallway from Boiler Room to Maintenance Storage Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H01	Hallway from Boiler Room to Maintenance Storage Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H01	Hallway from Boiler Room to Maintenance Storage Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	16	Custodial Storage	No	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	B	16	Custodial Storage	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	16	Custodial Storage	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	16	Custodial Storage	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	16	Custodial Storage	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	16	Custodial Storage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15	Staff Locker Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15	Staff Locker Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15	Staff Locker Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15	Staff Locker Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15	Staff Locker Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15	Staff Locker Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15B	Staff Locker Room Restroom	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15B	Staff Locker Room Restroom	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15B	Staff Locker Room Restroom	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15B	Staff Locker Room Restroom	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15B	Staff Locker Room Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	15B	Staff Locker Room Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	17	Building Engineer Storage	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	17	Building Engineer Storage	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	17	Building Engineer Storage	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	17	Building Engineer Storage	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	17	Building Engineer Storage	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	17	Building Engineer Storage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	12	Maintenance Storage Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	12	Maintenance Storage Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	12	Maintenance Storage Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	12	Maintenance Storage Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	12	Maintenance Storage Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	12	Maintenance Storage Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H08	Hallway from Boiler Room Storage Room to Lawn Mower Storage Hall	Yes	W1	N/A	N/A	Flaking	15	0	Negative
8430	1	B	H08	Hallway from Boiler Room Storage Room to Lawn Mower Storage Hall	Yes	W2	CMU	Beige	Flaking	20	0.1	Negative
8430	1	B	H08	Hallway from Boiler Room Storage Room to Lawn Mower Storage Hall	Yes	W3	Concrete	Beige	Flaking	15	0.2	Negative
8430	1	B	H08	Hallway from Boiler Room Storage Room to Lawn Mower Storage Hall	Yes	W4	CMU	Beige	None	0	0	Negative
8430	1	B	H08	Hallway from Boiler Room Storage Room to Lawn Mower Storage Hall	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	B	H08	Hallway from Boiler Room Storage Room to Lawn Mower Storage Hall	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13A	Former Bomb Shelter Across from the Lawn Mower Storage Hall	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13A	Former Bomb Shelter Across from the Lawn Mower Storage Hall	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13A	Former Bomb Shelter Across from the Lawn Mower Storage Hall	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13A	Former Bomb Shelter Across from the Lawn Mower Storage Hall	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13A	Former Bomb Shelter Across from the Lawn Mower Storage Hall	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13A	Former Bomb Shelter Across from the Lawn Mower Storage Hall	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13	Lawn Mower Storage Hall	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13	Lawn Mower Storage Hall	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13	Lawn Mower Storage Hall	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13	Lawn Mower Storage Hall	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13	Lawn Mower Storage Hall	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	13	Lawn Mower Storage Hall	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18	Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18A	Building Engineer's Office Restroom	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18A	Building Engineer's Office Restroom	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18A	Building Engineer's Office Restroom	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18A	Building Engineer's Office Restroom	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18A	Building Engineer's Office Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	18A	Building Engineer's Office Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	19	Boiler Room	No	W1	CMU	Yellow	Flaking	150	0.1	Negative
8430	1	B	19	Boiler Room	No	W2	Concrete	Gray	Flaking	153	0.3	Negative
8430	1	B	19	Boiler Room	No	W3	CMU	Yellow	Flaking	160	0.1	Negative

				Inspection Dates: 1/24/2022-1/26/2022	Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Kristen Masotes, 058358	Greenberg School							
				Inspection Company: Acer	600 Sharon Lane, Philadelphia, PA 19115							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8430	1	B	19	Boiler Room	No	W3	Concrete	Yellow	None	0	0.1	Negative
8430	1	B	19	Boiler Room	No	W4	Concrete	Yellow	Flaking	151	0.3	Negative
8430	1	B	19	Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	19	Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	20	Electrical Room in Boiler Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	20	Electrical Room in Boiler Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	20	Electrical Room in Boiler Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	20	Electrical Room in Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	20	Electrical Room in Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	20	Electrical Room in Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	B	H02	Basement Hallway next to Classroom 9	Yes	W1	CMU	Beige	None	0	0.1	Negative
8430	1	B	H02	Basement Hallway next to Classroom 9	Yes	W2	CMU	Beige	None	0	0.1	Negative
8430	1	B	H02	Basement Hallway next to Classroom 9	Yes	W3	CMU	Beige	None	0	0	Negative
8430	1	B	H02	Basement Hallway next to Classroom 9	Yes	W4	CMU	Beige	None	0	0.4	Negative
8430	1	B	H02	Basement Hallway next to Classroom 9	Yes	Ceiling	N/A	N/A	Flaking	N/A	N/A	N/A
8430	1	B	H02	Basement Hallway next to Classroom 9	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	A	AT	Attic	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	A	AT	Attic	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	A	AT	Attic	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	A	AT	Attic	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	A	AT	Attic	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8430	1	A	AT	Attic	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A