

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | | |
|-------|---------------------------------|-----------------------|---------|--------------------------------------|---|---|--------------------|-----------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lead Safe Certification Assessment Report | | | | | | |
| | | | | Inspection Company: Criterion Labs | | Lamberton High School | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | W1 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | W1 | Metal | Blue | Friction | 2 | Negative | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | W2 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | W2 | Metal | Blue | Friction | 2 | Negative | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | W3 | Plaster | Tan | Moisture Damage | 25 | Negative | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | W3 | Metal | Blue | Friction | 2 | Negative | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | W4 | Plaster | White | Moisture Damage | 20 | Negative | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 100 | Auditorium | Yes | Floor | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | W3 | Metal | Blue | None | 0 | Negative | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | W3 | Metal | Blue | None | 0 | Negative | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | W4 | Metal | Blue | None | 0 | Negative | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | W4 | Metal | White | Chipping | 5 | Positive | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | Ceiling | Plaster | White | Moisture Damage | 10 | Negative | |
| 4320 | 1 | 1 | H15 | Hallway at Exit #4 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | W3 | Metal | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | Ceiling | Plaster | Tan | Flaking | 10 | Negative | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | Ceiling | Metal | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | Ceiling | Metal | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 107F | Lavatory off of Stage | yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 107D | Office off of Stage | Yes | W1 | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107D | Office off of Stage | Yes | W2 | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107D | Office off of Stage | Yes | W3 | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107D | Office off of Stage | Yes | W4 | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107D | Office off of Stage | Yes | Ceiling | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107D | Office off of Stage | Yes | Floor | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107E | Office off of Stage next to Restroom | Yes | W1 | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107E | Office off of Stage next to Restroom | Yes | W2 | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107E | Office off of Stage next to Restroom | Yes | W3 | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107E | Office off of Stage next to Restroom | Yes | W4 | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107E | Office off of Stage next to Restroom | Yes | Ceiling | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 107E | Office off of Stage next to Restroom | Yes | Floor | No Access | No Access | No Access | No Access | No Access | |
| 4320 | 1 | 1 | 108I | Storage to the left of Stage | No | W1 | Concrete | Tan | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report Lamberton High School | | | | | |
|------|---|---|------|--|---------------------------------|-----------------------|--|-------------------|---|-----------|--------------------|-------|
| | | | | Name of Inspector: Michael Barth | | | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color |
| 4320 | 1 | 1 | 108I | Storage to the left of Stage | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108I | Storage to the left of Stage | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108I | Storage to the left of Stage | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108I | Storage to the left of Stage | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 108I | Storage to the left of Stage | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 108J | Closet in Storage to the left of Stage | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108J | Closet in Storage to the left of Stage | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108J | Closet in Storage to the left of Stage | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108J | Closet in Storage to the left of Stage | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108J | Closet in Storage to the left of Stage | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 108J | Closet in Storage to the left of Stage | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 101B | Coach's Office to left of Main Entrance | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101B | Coach's Office to left of Main Entrance | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101B | Coach's Office to left of Main Entrance | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101B | Coach's Office to left of Main Entrance | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101B | Coach's Office to left of Main Entrance | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 101B | Coach's Office to left of Main Entrance | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 101C | Men's Restroom to right of Main Entrance | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101C | Men's Restroom to right of Main Entrance | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101C | Men's Restroom to right of Main Entrance | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101C | Men's Restroom to right of Main Entrance | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101C | Men's Restroom to right of Main Entrance | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 101C | Men's Restroom to right of Main Entrance | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 101 | Classroom 101 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101 | Classroom 101 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101 | Classroom 101 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101 | Classroom 101 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 101 | Classroom 101 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 101 | Classroom 101 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 101D | Classroom 101 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101D | Classroom 101 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101D | Classroom 101 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101D | Classroom 101 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101D | Classroom 101 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101D | Classroom 101 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 101E | Classroom 101 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101E | Classroom 101 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101E | Classroom 101 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101E | Classroom 101 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101E | Classroom 101 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 101E | Classroom 101 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report Lamberton High School | | | | | |
|------|---|---|------|-------------------------------------|---------------------------------|-----------------------|--|-------------------|---|-----------|--------------------|-------|
| | | | | Name of Inspector: Michael Barth | | | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color |
| 4320 | 1 | 1 | 102 | Classroom 102 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 102 | Classroom 102 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 102 | Classroom 102 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 102 | Classroom 102 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 102 | Classroom 102 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 102 | Classroom 102 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 102A | Classroom 102 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102A | Classroom 102 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102A | Classroom 102 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102A | Classroom 102 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102A | Classroom 102 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102A | Classroom 102 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 102B | Classroom 102 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102B | Classroom 102 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102B | Classroom 102 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102B | Classroom 102 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102B | Classroom 102 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 102B | Classroom 102 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 103 | Classroom 103 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 103 | Classroom 103 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 103 | Classroom 103 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 103 | Classroom 103 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 103 | Classroom 103 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 103 | Classroom 103 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 103A | Classroom 103 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103A | Classroom 103 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103A | Classroom 103 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103A | Classroom 103 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103A | Classroom 103 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103A | Classroom 103 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 103B | Classroom 103 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103B | Classroom 103 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103B | Classroom 103 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103B | Classroom 103 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103B | Classroom 103 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 103B | Classroom 103 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 104 | Classroom 104 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 104 | Classroom 104 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 104 | Classroom 104 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 104 | Classroom 104 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 104 | Classroom 104 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | | |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lead Safe Certification Assessment Report | | | | | | |
| | | | | Inspection Company: Criterion Labs | | Lamberton High School | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 1 | 104 | Classroom 104 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 104A | Classroom 104 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104A | Classroom 104 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104A | Classroom 104 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104A | Classroom 104 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104A | Classroom 104 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104A | Classroom 104 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 104B | Classroom 104 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104B | Classroom 104 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104B | Classroom 104 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104B | Classroom 104 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104B | Classroom 104 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 104B | Classroom 104 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 105 | Classroom 105 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 105 | Classroom 105 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 105 | Classroom 105 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 105 | Classroom 105 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 105 | Classroom 105 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 105 | Classroom 105 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 105A | Classroom 105 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105A | Classroom 105 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105A | Classroom 105 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105A | Classroom 105 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105A | Classroom 105 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105A | Classroom 105 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 105B | Classroom 105 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105B | Classroom 105 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105B | Classroom 105 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105B | Classroom 105 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105B | Classroom 105 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 105B | Classroom 105 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | H13 | Walkway to Stage next to Stairwell #5 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | H13 | Walkway to Stage next to Stairwell #5 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | H13 | Walkway to Stage next to Stairwell #5 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | H13 | Walkway to Stage next to Stairwell #5 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | H13 | Walkway to Stage next to Stairwell #5 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | H13 | Walkway to Stage next to Stairwell #5 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | S12 | Stairwell #5 at the end of Stage walkway | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | S12 | Stairwell #5 at the end of Stage walkway | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | S12 | Stairwell #5 at the end of Stage walkway | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | S12 | Stairwell #5 at the end of Stage walkway | Yes | W4 | Concrete | Tan | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | |
| | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | 1 | S12 | Stairwell #5 at the end of Stage walkway | Yes | Ceiling | Plaster | Tan | Moisture Damage | 10 | Negative |
| 4320 | 1 | 1 | S12 | Stairwell #5 at the end of Stage walkway | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 106 | Classroom 106 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 106 | Classroom 106 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 106 | Classroom 106 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 106 | Classroom 106 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 106 | Classroom 106 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 106 | Classroom 106 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 106C | Classroom 106 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106C | Classroom 106 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106C | Classroom 106 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106C | Classroom 106 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106C | Classroom 106 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106C | Classroom 106 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 106D | Classroom 106 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106D | Classroom 106 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106D | Classroom 106 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106D | Classroom 106 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106D | Classroom 106 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 106D | Classroom 106 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | S14 | Stairwell #3 next to Classroom 106 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S14 | Stairwell #3 next to Classroom 106 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S14 | Stairwell #3 next to Classroom 106 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S14 | Stairwell #3 next to Classroom 106 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S14 | Stairwell #3 next to Classroom 106 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | S14 | Stairwell #3 next to Classroom 106 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 106A | Women's Teacher's Lounge next to Classroom 106 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 106A | Women's Teacher's Lounge next to Classroom 106 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 106A | Women's Teacher's Lounge next to Classroom 106 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 106A | Women's Teacher's Lounge next to Classroom 106 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 106A | Women's Teacher's Lounge next to Classroom 106 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 106A | Women's Teacher's Lounge next to Classroom 106 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 107 | Classroom 107 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 107 | Classroom 107 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 107 | Classroom 107 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 107 | Classroom 107 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 107 | Classroom 107 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 107 | Classroom 107 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 107I | Classroom 107 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107I | Classroom 107 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107I | Classroom 107 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | |
|-------|---------------------------------|-----------------------|---------|---|---|-----------------------|---|-------|--------------------------|-------------------------|--------------------------------|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | |
| | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | 1 | 107I | Classroom 107 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107I | Classroom 107 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107I | Classroom 107 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 107J | Classroom 107 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107J | Classroom 107 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107J | Classroom 107 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107J | Classroom 107 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107J | Classroom 107 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 107J | Classroom 107 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 107H | Custodial Storage across from Classroom 102 | No | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 107H | Custodial Storage across from Classroom 102 | No | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 107H | Custodial Storage across from Classroom 102 | No | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 107H | Custodial Storage across from Classroom 102 | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 107H | Custodial Storage across from Classroom 102 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 107H | Custodial Storage across from Classroom 102 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | S15 | Stairwell #4 across from Classroom 102 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S15 | Stairwell #4 across from Classroom 102 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S15 | Stairwell #4 across from Classroom 102 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S15 | Stairwell #4 across from Classroom 102 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S15 | Stairwell #4 across from Classroom 102 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | S15 | Stairwell #4 across from Classroom 102 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108H | Book Closet 107A next to Stairwell #4 | No | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108H | Book Closet 107A next to Stairwell #4 | No | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108H | Book Closet 107A next to Stairwell #4 | No | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108H | Book Closet 107A next to Stairwell #4 | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108H | Book Closet 107A next to Stairwell #4 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108H | Book Closet 107A next to Stairwell #4 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | H11A | Hallway from Classrooms 101 to 107 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | H11A | Hallway from Classrooms 101 to 107 | Yes | W1 | Metal | Blue | Friction | 5 | Negative |
| 4320 | 1 | 1 | H11A | Hallway from Classrooms 101 to 107 | Yes | W2 | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | H11A | Hallway from Classrooms 101 to 107 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | H11A | Hallway from Classrooms 101 to 107 | Yes | W3 | Metal | Blue | Friction | 5 | Negative |
| 4320 | 1 | 1 | H11A | Hallway from Classrooms 101 to 107 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | H11A | Hallway from Classrooms 101 to 107 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | H11A | Hallway from Classrooms 101 to 107 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108E | Women's Restroom next to Main Office | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108E | Women's Restroom next to Main Office | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108E | Women's Restroom next to Main Office | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108E | Women's Restroom next to Main Office | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108E | Women's Restroom next to Main Office | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108E | Women's Restroom next to Main Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|---------|---------------------------------------|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | |
| | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | 1 | 108G | Closet in Hallway next to Main Office | No | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108G | Closet in Hallway next to Main Office | No | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108G | Closet in Hallway next to Main Office | No | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108G | Closet in Hallway next to Main Office | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 108G | Closet in Hallway next to Main Office | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108G | Closet in Hallway next to Main Office | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108B | Main Office | Yes | W1 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108B | Main Office | Yes | W2 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108B | Main Office | Yes | W3 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108B | Main Office | Yes | W4 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108B | Main Office | Yes | Ceiling | Plaster | White | None | 0 | Positive |
| 4320 | 1 | 1 | 108B | Main Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108C | Main Office Copier Room | Yes | W1 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108C | Main Office Copier Room | Yes | W2 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108C | Main Office Copier Room | Yes | W3 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108C | Main Office Copier Room | Yes | W4 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108C | Main Office Copier Room | Yes | Ceiling | Plaster | White | None | 0 | Positive |
| 4320 | 1 | 1 | 108C | Main Office Copier Room | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108F | Main Office Closet | No | W1 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108F | Main Office Closet | No | W2 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108F | Main Office Closet | No | W3 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108F | Main Office Closet | No | W4 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108F | Main Office Closet | No | Ceiling | Plaster | White | None | 0 | Positive |
| 4320 | 1 | 1 | 108F | Main Office Closet | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108D | Counselor's Office in Main Office | Yes | W1 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108D | Counselor's Office in Main Office | Yes | W2 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108D | Counselor's Office in Main Office | Yes | W3 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108D | Counselor's Office in Main Office | Yes | W4 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108D | Counselor's Office in Main Office | Yes | Ceiling | Plaster | White | None | 0 | Positive |
| 4320 | 1 | 1 | 108D | Counselor's Office in Main Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108A | Principal's Office | Yes | W1 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108A | Principal's Office | Yes | W2 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108A | Principal's Office | Yes | W3 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108A | Principal's Office | Yes | W4 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108A | Principal's Office | Yes | Ceiling | Plaster | White | None | 0 | Positive |
| 4320 | 1 | 1 | 108A | Principal's Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 108A-1 | Principal's Office Closet | No | W1 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108A-1 | Principal's Office Closet | No | W2 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108A-1 | Principal's Office Closet | No | W3 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108A-1 | Principal's Office Closet | No | W4 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 1 | 108A-1 | Principal's Office Closet | No | Ceiling | Plaster | White | None | 0 | Positive |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | | |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lead Safe Certification Assessment Report | | | | | | |
| | | | | | | Lamberton High School | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 1 | 108A-1 | Principal's Office Closet | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 108 | Classroom 108 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108 | Classroom 108 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108 | Classroom 108 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108 | Classroom 108 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 108 | Classroom 108 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 108 | Classroom 108 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 120A | Stairwell #5 across from Classroom 108 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 120A | Stairwell #5 across from Classroom 108 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 120A | Stairwell #5 across from Classroom 108 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 120A | Stairwell #5 across from Classroom 108 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 120A | Stairwell #5 across from Classroom 108 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 120A | Stairwell #5 across from Classroom 108 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 109 | Classroom 109 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 109 | Classroom 109 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 109 | Classroom 109 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 109 | Classroom 109 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 109 | Classroom 109 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 109 | Classroom 109 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 109A | Classroom 109 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109A | Classroom 109 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109A | Classroom 109 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109A | Classroom 109 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109A | Classroom 109 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109A | Classroom 109 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 109B | Classroom 109 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109B | Classroom 109 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109B | Classroom 109 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109B | Classroom 109 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109B | Classroom 109 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 109B | Classroom 109 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | W1 | Sheetrock | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | W1 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | W1 | Metal | Blue | Friction | 3 | Negative | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | W1 | Metal | Brown | Friction | 3 | Negative | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | W2 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | W3 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | W4 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | Ceiling | Plaster | White | None | 0 | Positive | |
| 4320 | 1 | 1 | 124 | Literacy Office 121A | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | | |
|-------|---------------------------------|-----------------------|---------|-------------------------------------|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lead Safe Certification Assessment Report | | | | | | |
| | | | | Inspection Company: Criterion Labs | | Lamberton High School | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 1 | 125A | Nurse's Suite 121 | Yes | W1 | Plaster | Tan | Cracking | 3 | Positive | |
| 4320 | 1 | 1 | 125A | Nurse's Suite 121 | Yes | W1 | Metal | Brown | Friction | 1 | Negative | |
| 4320 | 1 | 1 | 125A | Nurse's Suite 121 | Yes | W2 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 125A | Nurse's Suite 121 | Yes | W2 | Metal | Brown | Friction | 1 | Negative | |
| 4320 | 1 | 1 | 125A | Nurse's Suite 121 | Yes | W3 | Plaster | Tan | Cracking | 5 | Positive | |
| 4320 | 1 | 1 | 125A | Nurse's Suite 121 | Yes | W4 | Plaster | Tan | Cracking | 3 | Positive | |
| 4320 | 1 | 1 | 125A | Nurse's Suite 121 | Yes | Ceiling | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 125A | Nurse's Suite 121 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 125D | Nurse's Suite Restroom | Yes | W1 | Plaster | Blue | Cracking | 3 | Positive | |
| 4320 | 1 | 1 | 125D | Nurse's Suite Restroom | Yes | W2 | Plaster | Blue | None | 0 | Positive | |
| 4320 | 1 | 1 | 125D | Nurse's Suite Restroom | Yes | W3 | Plaster | Blue | Cracking | 3 | Positive | |
| 4320 | 1 | 1 | 125D | Nurse's Suite Restroom | Yes | W4 | Plaster | Blue | Cracking | 3 | Positive | |
| 4320 | 1 | 1 | 125D | Nurse's Suite Restroom | Yes | Ceiling | Plaster | Blue | Cracking | 3 | Positive | |
| 4320 | 1 | 1 | 125D | Nurse's Suite Restroom | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | W1 | Sheetrock | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | W1 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | W1 | Metal | Blue | Friction | 3 | Negative | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | W1 | Metal | Brown | Friction | 3 | Negative | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | W2 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | W3 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | W4 | Plaster | Tan | None | 0 | Positive | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | Ceiling | Plaster | White | None | 0 | Positive | |
| 4320 | 1 | 1 | 125 | Teacher's Lounge 120A | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 110 | Classroom 110 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 110 | Classroom 110 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 110 | Classroom 110 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 110 | Classroom 110 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 110 | Classroom 110 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 110 | Classroom 110 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 110A | Classroom 110 storage Closet 1 | No | W1 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110A | Classroom 110 storage Closet 1 | No | W2 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110A | Classroom 110 storage Closet 1 | No | W3 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110A | Classroom 110 storage Closet 1 | No | W4 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110A | Classroom 110 storage Closet 1 | No | Ceiling | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110A | Classroom 110 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 110B | Classroom 110 storage Closet 2 | No | W1 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110B | Classroom 110 storage Closet 2 | No | W2 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110B | Classroom 110 storage Closet 2 | No | W3 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110B | Classroom 110 storage Closet 2 | No | W4 | Plaster | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 110B | Classroom 110 storage Closet 2 | No | Ceiling | Plaster | White | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report Lamberton High School | | | | | |
|------|---|---|------|---|---------------------------------|-----------------------|--|-------------------|---|-----------|--------------------|-------|
| | | | | Name of Inspector: Michael Barth | | | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color |
| 4320 | 1 | 1 | 110B | Classroom 110 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 119A | Vice Principal's Office 120 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119A | Vice Principal's Office 120 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119A | Vice Principal's Office 120 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119A | Vice Principal's Office 120 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119A | Vice Principal's Office 120 | Yes | Ceiling | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119A | Vice Principal's Office 120 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 119B | Vice Principal's Office Restroom | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119B | Vice Principal's Office Restroom | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119B | Vice Principal's Office Restroom | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119B | Vice Principal's Office Restroom | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119B | Vice Principal's Office Restroom | Yes | Ceiling | Plaster | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119B | Vice Principal's Office Restroom | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 122 | Boy's Restroom to the left of Vice Principal's Office | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 122 | Boy's Restroom to the left of Vice Principal's Office | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 122 | Boy's Restroom to the left of Vice Principal's Office | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 122 | Boy's Restroom to the left of Vice Principal's Office | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 122 | Boy's Restroom to the left of Vice Principal's Office | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 122 | Boy's Restroom to the left of Vice Principal's Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 122A | Custodial Storage next to Boy's Restroom | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 122A | Custodial Storage next to Boy's Restroom | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 122A | Custodial Storage next to Boy's Restroom | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 122A | Custodial Storage next to Boy's Restroom | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 122A | Custodial Storage next to Boy's Restroom | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 122A | Custodial Storage next to Boy's Restroom | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 121 | Girl's Restroom next to Counseling Office 119 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 121 | Girl's Restroom next to Counseling Office 119 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 121 | Girl's Restroom next to Counseling Office 119 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 121 | Girl's Restroom next to Counseling Office 119 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 121 | Girl's Restroom next to Counseling Office 119 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 121 | Girl's Restroom next to Counseling Office 119 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 119 | Counseling Office 119 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119 | Counseling Office 119 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119 | Counseling Office 119 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119 | Counseling Office 119 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 119 | Counseling Office 119 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 119 | Counseling Office 119 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 119A | Counseling Office 119 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 119A | Counseling Office 119 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 119A | Counseling Office 119 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 119A | Counseling Office 119 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | |
| | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | 1 | 119A | Counseling Office 119 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 119A | Counseling Office 119 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 119B | Counseling Office 119 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 119B | Counseling Office 119 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 119B | Counseling Office 119 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 119B | Counseling Office 119 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 119B | Counseling Office 119 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 119B | Counseling Office 119 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 111 | Classroom 111 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 111 | Classroom 111 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 111 | Classroom 111 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 111 | Classroom 111 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 111 | Classroom 111 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 111 | Classroom 111 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 111B | Classroom 111 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111B | Classroom 111 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111B | Classroom 111 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111B | Classroom 111 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111B | Classroom 111 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111B | Classroom 111 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 111C | Classroom 111 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111C | Classroom 111 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111C | Classroom 111 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111C | Classroom 111 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111C | Classroom 111 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 1 | 111C | Classroom 111 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 111A | Office 111A next to Room 111 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 111A | Office 111A next to Room 111 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 111A | Office 111A next to Room 111 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 111A | Office 111A next to Room 111 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 111A | Office 111A next to Room 111 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 111A | Office 111A next to Room 111 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | S13 | Stairwell #7 next to Classroom 118 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S13 | Stairwell #7 next to Classroom 118 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S13 | Stairwell #7 next to Classroom 118 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S13 | Stairwell #7 next to Classroom 118 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | S13 | Stairwell #7 next to Classroom 118 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | S13 | Stairwell #7 next to Classroom 118 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 112 | Classroom 112 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 112 | Classroom 112 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 1 | 112 | Classroom 112 | Yes | W3 | Concrete | Tan | None | 0 | Negative |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | | |
|-------|---------------------------------|-----------------------|---------|-------------------------------------|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lead Safe Certification Assessment Report | | | | | | |
| | | | | Inspection Company: Criterion Labs | | Lamberton High School | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 1 | 112 | Classroom 112 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 112 | Classroom 112 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 112 | Classroom 112 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 112A | Classroom 112 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112A | Classroom 112 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112A | Classroom 112 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112A | Classroom 112 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112A | Classroom 112 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112A | Classroom 112 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 112B | Classroom 112 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112B | Classroom 112 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112B | Classroom 112 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112B | Classroom 112 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112B | Classroom 112 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 112B | Classroom 112 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 118 | Classroom 118 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 118 | Classroom 118 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 118 | Classroom 118 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 118 | Classroom 118 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 1 | 118 | Classroom 118 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 118 | Classroom 118 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 118A | Classroom 118 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118A | Classroom 118 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118A | Classroom 118 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118A | Classroom 118 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118A | Classroom 118 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118A | Classroom 118 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 1 | 118B | Classroom 118 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118B | Classroom 118 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118B | Classroom 118 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118B | Classroom 118 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118B | Classroom 118 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 1 | 118B | Classroom 118 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 213 | Classroom 213 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 213 | Classroom 213 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 213 | Classroom 213 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 213 | Classroom 213 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 213 | Classroom 213 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 213 | Classroom 213 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 213A | Classroom 213 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213A | Classroom 213 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report Lamberton High School | | | | | |
|------|---|---|------|-------------------------------------|---------------------------------|-----------------------|--|-------------------|---|-----------|--------------------|-------|
| | | | | Name of Inspector: Michael Barth | | | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color |
| 4320 | 1 | 2 | 213A | Classroom 213 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213A | Classroom 213 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213A | Classroom 213 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213A | Classroom 213 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 213B | Classroom 213 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213B | Classroom 213 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213B | Classroom 213 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213B | Classroom 213 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213B | Classroom 213 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 213B | Classroom 213 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219 | Classroom 219 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219 | Classroom 219 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219 | Classroom 219 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219 | Classroom 219 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219 | Classroom 219 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219 | Classroom 219 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219E | Classroom 219 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219E | Classroom 219 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219E | Classroom 219 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219E | Classroom 219 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219E | Classroom 219 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219E | Classroom 219 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219F | Classroom 219 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219F | Classroom 219 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219F | Classroom 219 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219F | Classroom 219 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219F | Classroom 219 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 219F | Classroom 219 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | S23 | Stairwell #7 next to Classroom 219 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S23 | Stairwell #7 next to Classroom 219 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S23 | Stairwell #7 next to Classroom 219 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S23 | Stairwell #7 next to Classroom 219 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S23 | Stairwell #7 next to Classroom 219 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | S23 | Stairwell #7 next to Classroom 219 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 212A | Office next to Classroom 212 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 212A | Office next to Classroom 212 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 212A | Office next to Classroom 212 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 212A | Office next to Classroom 212 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 212A | Office next to Classroom 212 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 212A | Office next to Classroom 212 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 212 | Classroom 212 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | Lead Safe Certification Assessment Report | | | | | | |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 2 | 212 | Classroom 212 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 212 | Classroom 212 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 212 | Classroom 212 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 212 | Classroom 212 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 212 | Classroom 212 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 212B | Classroom 212 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212B | Classroom 212 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212B | Classroom 212 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212B | Classroom 212 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212B | Classroom 212 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212B | Classroom 212 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 212C | Classroom 212 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212C | Classroom 212 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212C | Classroom 212 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212C | Classroom 212 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212C | Classroom 212 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 212C | Classroom 212 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219A | Women's Teacher Lounge next to Classroom 219 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219A | Women's Teacher Lounge next to Classroom 219 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219A | Women's Teacher Lounge next to Classroom 219 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219A | Women's Teacher Lounge next to Classroom 219 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219A | Women's Teacher Lounge next to Classroom 219 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219A | Women's Teacher Lounge next to Classroom 219 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219B | Women's Restroom next to Women's Lounge | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219B | Women's Restroom next to Women's Lounge | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219B | Women's Restroom next to Women's Lounge | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219B | Women's Restroom next to Women's Lounge | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219B | Women's Restroom next to Women's Lounge | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219B | Women's Restroom next to Women's Lounge | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219C | Men's Restroom next to Classroom 220 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219C | Men's Restroom next to Classroom 220 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219C | Men's Restroom next to Classroom 220 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219C | Men's Restroom next to Classroom 220 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219C | Men's Restroom next to Classroom 220 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219C | Men's Restroom next to Classroom 220 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219D | Custodial Closet across from Classroom 212 | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219D | Custodial Closet across from Classroom 212 | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219D | Custodial Closet across from Classroom 212 | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219D | Custodial Closet across from Classroom 212 | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 219D | Custodial Closet across from Classroom 212 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 219D | Custodial Closet across from Classroom 212 | No | Floor | N/A | N/A | N/A | N/A | N/A | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report Lamberton High School | | | | | |
|------|---|---|------|-------------------------------------|---------------------------------|-----------------------|--|-------------------|---|-----------|--------------------|-------|
| | | | | Name of Inspector: Michael Barth | | | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color |
| 4320 | 1 | 2 | 220 | Classroom 220 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 220 | Classroom 220 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 220 | Classroom 220 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 220 | Classroom 220 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 220 | Classroom 220 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 220 | Classroom 220 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 220A | Classroom 220 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220A | Classroom 220 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220A | Classroom 220 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220A | Classroom 220 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220A | Classroom 220 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220A | Classroom 220 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 220B | Classroom 220 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220B | Classroom 220 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220B | Classroom 220 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220B | Classroom 220 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220B | Classroom 220 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 220B | Classroom 220 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 211 | Classroom 211 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 211 | Classroom 211 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 211 | Classroom 211 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 211 | Classroom 211 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 211 | Classroom 211 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 211 | Classroom 211 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 211A | Classroom 211 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211A | Classroom 211 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211A | Classroom 211 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211A | Classroom 211 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211A | Classroom 211 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211A | Classroom 211 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 211B | Classroom 211 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211B | Classroom 211 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211B | Classroom 211 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211B | Classroom 211 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211B | Classroom 211 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 211B | Classroom 211 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 221 | Classroom 221 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 221 | Classroom 221 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 221 | Classroom 221 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 221 | Classroom 221 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 221 | Classroom 221 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | Lead Safe Certification Assessment Report | | | | | | |
|-------|---------------------------------|-----------------------|---------|-------------------------------------|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 2 | 221 | Classroom 221 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 221B | Classroom 221 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221B | Classroom 221 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221B | Classroom 221 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221B | Classroom 221 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221B | Classroom 221 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221B | Classroom 221 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 221C | Classroom 221 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221C | Classroom 221 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221C | Classroom 221 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221C | Classroom 221 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221C | Classroom 221 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 221C | Classroom 221 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 210 | Classroom 210B | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 210 | Classroom 210B | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 210 | Classroom 210B | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 210 | Classroom 210B | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 210 | Classroom 210B | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 210 | Classroom 210B | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 210C | Classroom 210B storage Closet | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210C | Classroom 210B storage Closet | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210C | Classroom 210B storage Closet | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210C | Classroom 210B storage Closet | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210C | Classroom 210B storage Closet | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210C | Classroom 210B storage Closet | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 210A | Classroom 210A | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 210A | Classroom 210A | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 210A | Classroom 210A | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 210A | Classroom 210A | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 210A | Classroom 210A | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 210A | Classroom 210A | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 210D | Classroom 210A storage Closet | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210D | Classroom 210A storage Closet | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210D | Classroom 210A storage Closet | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210D | Classroom 210A storage Closet | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210D | Classroom 210A storage Closet | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 210D | Classroom 210A storage Closet | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | S22 | Stairwell #5 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S22 | Stairwell #5 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S22 | Stairwell #5 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S22 | Stairwell #5 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | | |
|-------|---------------------------------|-----------------------|---------|-------------------------------------|---|-----------|---|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | | Lead Safe Certification Assessment Report | | | | | |
| | | | | Inspection Company: Criterion Labs | | | Lamberton High School | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 2 | S22 | Stairwell #5 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | S22 | Stairwell #5 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 222 | Storage Room next to Stairwell #5 | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 222 | Storage Room next to Stairwell #5 | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 222 | Storage Room next to Stairwell #5 | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 222 | Storage Room next to Stairwell #5 | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 222 | Storage Room next to Stairwell #5 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 222 | Storage Room next to Stairwell #5 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 209 | Classroom 209 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 209 | Classroom 209 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 209 | Classroom 209 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 209 | Classroom 209 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 209 | Classroom 209 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 209 | Classroom 209 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 209A | Classroom 209 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209A | Classroom 209 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209A | Classroom 209 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209A | Classroom 209 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209A | Classroom 209 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209A | Classroom 209 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 209B | Classroom 209 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209B | Classroom 209 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209B | Classroom 209 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209B | Classroom 209 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209B | Classroom 209 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 209B | Classroom 209 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 208 | Classroom 208 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 208 | Classroom 208 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 208 | Classroom 208 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 208 | Classroom 208 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 208 | Classroom 208 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 208 | Classroom 208 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 208A | Classroom 208 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 208A | Classroom 208 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 208A | Classroom 208 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 208A | Classroom 208 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 208A | Classroom 208 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 208A | Classroom 208 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 208B | Classroom 208 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 208B | Classroom 208 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 208B | Classroom 208 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | |
|-------|---------------------------------|-----------------------|----------|-------------------------------------|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | | Name of Inspector: Michael Barth | | Lead Safe Certification Assessment Report | | | | | |
| | | | | Inspection Company: Criterion Labs | | Lamberton High School | | | | | |
| | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | 2 | 208B | Classroom 208 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 208B | Classroom 208 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 208B | Classroom 208 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 200/200B | High School Main Office | Yes | W1 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 2 | 200/200B | High School Main Office | Yes | W2 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 2 | 200/200B | High School Main Office | Yes | W3 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 2 | 200/200B | High School Main Office | Yes | W4 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 2 | 200/200B | High School Main Office | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 200/200B | High School Main Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 200A | Office in High School Main Office | Yes | W1 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 2 | 200A | Office in High School Main Office | Yes | W2 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 2 | 200A | Office in High School Main Office | Yes | W3 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 2 | 200A | Office in High School Main Office | Yes | W4 | Plaster | Blue | None | 0 | Positive |
| 4320 | 1 | 2 | 200A | Office in High School Main Office | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 200A | Office in High School Main Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 201 | Classroom 201 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 201 | Classroom 201 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 201 | Classroom 201 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 201 | Classroom 201 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 201 | Classroom 201 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 201 | Classroom 201 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 201A | Classroom 201 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201A | Classroom 201 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201A | Classroom 201 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201A | Classroom 201 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201A | Classroom 201 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201A | Classroom 201 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 201B | Classroom 201 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201B | Classroom 201 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201B | Classroom 201 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201B | Classroom 201 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201B | Classroom 201 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 201B | Classroom 201 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 202 | Classroom 202 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 202 | Classroom 202 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 202 | Classroom 202 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 202 | Classroom 202 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 202 | Classroom 202 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 202 | Classroom 202 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 202A | Classroom 202 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 202A | Classroom 202 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report Lamberton High School | | | | | |
|------|---|---|------|--|---------------------------------|-----------------------|--|-------------------|---|-----------|--------------------|-------|
| | | | | Name of Inspector: Michael Barth | | | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color |
| 4320 | 1 | 2 | 202A | Classroom 202 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 202A | Classroom 202 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 202A | Classroom 202 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 202A | Classroom 202 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 202B | Classroom 202 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 202B | Classroom 202 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 202B | Classroom 202 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 202B | Classroom 202 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 202B | Classroom 202 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 202B | Classroom 202 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207E | File Room 207D | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207E | File Room 207D | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207E | File Room 207D | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207E | File Room 207D | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207E | File Room 207D | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207E | File Room 207D | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | S25 | Stairwell #4 across from Classroom 202 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S25 | Stairwell #4 across from Classroom 202 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S25 | Stairwell #4 across from Classroom 202 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S25 | Stairwell #4 across from Classroom 202 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | S25 | Stairwell #4 across from Classroom 202 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | S25 | Stairwell #4 across from Classroom 202 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207B | Men's Restroom next to Classroom 207 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207B | Men's Restroom next to Classroom 207 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207B | Men's Restroom next to Classroom 207 | yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207B | Men's Restroom next to Classroom 207 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207B | Men's Restroom next to Classroom 207 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207B | Men's Restroom next to Classroom 207 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207G | Storage next to Men's Restroom | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207G | Storage next to Men's Restroom | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207G | Storage next to Men's Restroom | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207G | Storage next to Men's Restroom | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207G | Storage next to Men's Restroom | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207G | Storage next to Men's Restroom | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207C | Women's Restroom across from Classroom 203 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207C | Women's Restroom across from Classroom 203 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207C | Women's Restroom across from Classroom 203 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207C | Women's Restroom across from Classroom 203 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207C | Women's Restroom across from Classroom 203 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207C | Women's Restroom across from Classroom 203 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 203 | Classroom 203 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|---------|-------------------------------------|---|-----------------------|---|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 2 | 203 | Classroom 203 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 203 | Classroom 203 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 203 | Classroom 203 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 203 | Classroom 203 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 203 | Classroom 203 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 203A | Classroom 203 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203A | Classroom 203 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203A | Classroom 203 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203A | Classroom 203 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203A | Classroom 203 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203A | Classroom 203 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 203B | Classroom 203 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203B | Classroom 203 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203B | Classroom 203 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203B | Classroom 203 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203B | Classroom 203 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 203B | Classroom 203 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207 | Classroom 207 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207 | Classroom 207 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207 | Classroom 207 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207 | Classroom 207 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207 | Classroom 207 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207 | Classroom 207 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207H | Classroom 207 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207H | Classroom 207 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207H | Classroom 207 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207H | Classroom 207 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207H | Classroom 207 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207H | Classroom 207 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207I | Classroom 207 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207I | Classroom 207 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207I | Classroom 207 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207I | Classroom 207 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207I | Classroom 207 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 207I | Classroom 207 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 204 | Classroom 204 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 204 | Classroom 204 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 204 | Classroom 204 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 204 | Classroom 204 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 204 | Classroom 204 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 204 | Classroom 204 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | | |
|-------|---------------------------------|-----------------------|---------|---|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lead Safe Certification Assessment Report | | | | | | |
| | | | | Inspection Company: Criterion Labs | | Lamberton High School | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | 2 | 204A | Classroom 204 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204A | Classroom 204 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204A | Classroom 204 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204A | Classroom 204 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204A | Classroom 204 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204A | Classroom 204 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 204B | Classroom 204 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204B | Classroom 204 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204B | Classroom 204 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204B | Classroom 204 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204B | Classroom 204 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 204B | Classroom 204 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 206A | Women's Teacher Lounge next to Stairwell #3 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 206A | Women's Teacher Lounge next to Stairwell #3 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 206A | Women's Teacher Lounge next to Stairwell #3 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 206A | Women's Teacher Lounge next to Stairwell #3 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 206A | Women's Teacher Lounge next to Stairwell #3 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 206A | Women's Teacher Lounge next to Stairwell #3 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207A | Women's Restroom in Women's Lounge | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207A | Women's Restroom in Women's Lounge | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207A | Women's Restroom in Women's Lounge | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207A | Women's Restroom in Women's Lounge | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 207A | Women's Restroom in Women's Lounge | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 207A | Women's Restroom in Women's Lounge | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 205 | Classroom 205 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 205 | Classroom 205 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 205 | Classroom 205 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 205 | Classroom 205 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | 2 | 205 | Classroom 205 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 205 | Classroom 205 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 205A | Classroom 205 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205A | Classroom 205 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205A | Classroom 205 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205A | Classroom 205 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205A | Classroom 205 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205A | Classroom 205 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | 2 | 205B | Classroom 205 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205B | Classroom 205 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205B | Classroom 205 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205B | Classroom 205 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | 2 | 205B | Classroom 205 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |

| | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|-------------------------------------|--|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | Inspection Company: Criterion Labs | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | 2 | 205B | Classroom 205 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 206 | Classroom 206 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 206 | Classroom 206 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 206 | Classroom 206 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 206 | Classroom 206 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | 206 | Classroom 206 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 206 | Classroom 206 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 206B | Classroom 206 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206B | Classroom 206 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206B | Classroom 206 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206B | Classroom 206 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206B | Classroom 206 storage Closet 1 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206B | Classroom 206 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | 206C | Classroom 206 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206C | Classroom 206 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206C | Classroom 206 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206C | Classroom 206 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206C | Classroom 206 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | 2 | 206C | Classroom 206 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | S24 | Stairwell #3 across from Classroom 204 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | S24 | Stairwell #3 across from Classroom 204 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | S24 | Stairwell #3 across from Classroom 204 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | S24 | Stairwell #3 across from Classroom 204 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | 2 | S24 | Stairwell #3 across from Classroom 204 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 2 | S24 | Stairwell #3 across from Classroom 204 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 001E | Boiler Room | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 001E | Boiler Room | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 001E | Boiler Room | no | W2 | Brick | White | None | 0 | Negative |
| 4320 | 1 | B | 001E | Boiler Room | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 001E | Boiler Room | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 001E | Boiler Room | No | W4 | Metal | Black | None | 0 | Positive |
| 4320 | 1 | B | 001E | Boiler Room | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 001E | Boiler Room | No | Floor | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 002E | Pump Room | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 002E | Pump Room | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 002E | Pump Room | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 002E | Pump Room | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 002E | Pump Room | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 002E | Pump Room | No | Floor | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 003E | Storage Room in Mechanical Area | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 003E | Storage Room in Mechanical Area | No | W2 | Concrete | White | None | 0 | Negative |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report Lamberton High School | | | | |
|------|---|---|------|--|---------------------------------|-----------------------|--|-------------------|---|-----------|--------------------|
| | | | | Name of Inspector: Michael Barth | | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | |
| | | | | ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material |
| 4320 | 1 | B | 003E | Storage Room in Mechanical Area | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 003E | Storage Room in Mechanical Area | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 003E | Storage Room in Mechanical Area | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 003E | Storage Room in Mechanical Area | No | Floor | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 004E | Walkway at Building Engineer's Office | Yes | W1 | Brick | White | Cracking | 20 | Negative |
| 4320 | 1 | B | 004E | Walkway at Building Engineer's Office | Yes | W2 | Brick | White | None | 0 | Negative |
| 4320 | 1 | B | 004E | Walkway at Building Engineer's Office | Yes | W3 | Brick | White | None | 0 | Negative |
| 4320 | 1 | B | 004E | Walkway at Building Engineer's Office | Yes | W4 | Brick | White | None | 0 | Negative |
| 4320 | 1 | B | 004E | Walkway at Building Engineer's Office | Yes | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 1 | B | 004E | Walkway at Building Engineer's Office | Yes | Floor | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 14 | Electrical Room in Mechanical Area | No | W1 | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 14 | Electrical Room in Mechanical Area | No | W2 | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 14 | Electrical Room in Mechanical Area | No | W3 | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 14 | Electrical Room in Mechanical Area | No | W4 | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 14 | Electrical Room in Mechanical Area | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 14 | Electrical Room in Mechanical Area | No | Floor | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | NP-1 | Building Engineer's Office | Yes | W1 | Plaster | Tan | Cracking | 3 | Positive |
| 4320 | 1 | B | NP-1 | Building Engineer's Office | Yes | W2 | Plaster | Tan | None | 0 | Positive |
| 4320 | 1 | B | NP-1 | Building Engineer's Office | Yes | W3 | Plaster | Tan | None | 0 | Positive |
| 4320 | 1 | B | NP-1 | Building Engineer's Office | Yes | W4 | Plaster | Tan | Moisture Damage | 3 | Positive |
| 4320 | 1 | B | NP-1 | Building Engineer's Office | Yes | Ceiling | Plaster | Tan | None | 0 | Positive |
| 4320 | 1 | B | NP-1 | Building Engineer's Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | H02 | Hallway outside Mechanical Area | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H02 | Hallway outside Mechanical Area | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H02 | Hallway outside Mechanical Area | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H02 | Hallway outside Mechanical Area | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H02 | Hallway outside Mechanical Area | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | H02 | Hallway outside Mechanical Area | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 13 | Lawn Equipment Storage | No | W1 | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 13 | Lawn Equipment Storage | No | W2 | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 13 | Lawn Equipment Storage | No | W3 | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 13 | Lawn Equipment Storage | No | W4 | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 13 | Lawn Equipment Storage | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 13 | Lawn Equipment Storage | No | Floor | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 12A | Breakroom in Hallway towards Gym | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 12A | Breakroom in Hallway towards Gym | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 12A | Breakroom in Hallway towards Gym | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 12A | Breakroom in Hallway towards Gym | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 12A | Breakroom in Hallway towards Gym | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 12A | Breakroom in Hallway towards Gym | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | H03 | Hallway to Gym from Building Engineer's Office | Yes | W1 | Concrete | Tan | None | 0 | Negative |

| | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|-------------------------------------|--|---|---|--------------------|--------|--------------------------|-------------------------|--------------------------------|
| | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | Inspection Company: Criterion Labs | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | B | H03 | Hallway to Gym from Building Engineer's Office | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H03 | Hallway to Gym from Building Engineer's Office | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H03 | Hallway to Gym from Building Engineer's Office | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H03 | Hallway to Gym from Building Engineer's Office | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | H03 | Hallway to Gym from Building Engineer's Office | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 19 | Boy's Restroom across from Gym Entrance | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 19 | Boy's Restroom across from Gym Entrance | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 19 | Boy's Restroom across from Gym Entrance | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 19 | Boy's Restroom across from Gym Entrance | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 19 | Boy's Restroom across from Gym Entrance | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 19 | Boy's Restroom across from Gym Entrance | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | S02 | Stairwell #5 by Gym Entrance | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | S02 | Stairwell #5 by Gym Entrance | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | S02 | Stairwell #5 by Gym Entrance | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | S02 | Stairwell #5 by Gym Entrance | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | S02 | Stairwell #5 by Gym Entrance | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | S02 | Stairwell #5 by Gym Entrance | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 17 | Gym | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 17 | Gym | Yes | W2 | Concrete | Tan | Cracking | 10 | Negative |
| 4320 | 1 | B | 17 | Gym | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 17 | Gym | Yes | W4 | Concrete | Tan | Cracking | 10 | Negative |
| 4320 | 1 | B | 17 | Gym | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 17 | Gym | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 16 | Gym Storage | No | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 16 | Gym Storage | No | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 16 | Gym Storage | No | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 16 | Gym Storage | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 16 | Gym Storage | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 16 | Gym Storage | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 18 | Cafeteria | Yes | W1 | Plaster | Yellow | Cracking | 5 | Positive |
| 4320 | 1 | B | 18 | Cafeteria | Yes | W2 | Plaster | Yellow | Cracking | 10 | Positive |
| 4320 | 1 | B | 18 | Cafeteria | Yes | W3 | Plaster | Yellow | Moisture Damage | 5 | Positive |
| 4320 | 1 | B | 18 | Cafeteria | Yes | W4 | Plaster | Yellow | Moisture Damage | 5 | Positive |
| 4320 | 1 | B | 18 | Cafeteria | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 18 | Cafeteria | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 18A | Kitchen | Yes | W1 | Plaster | Tan | Cracking/spalling | 10 | Positive |
| 4320 | 1 | B | 18A | Kitchen | No | W2 | Plaster | Tan | Cracking | 5 | Negative |
| 4320 | 1 | B | 18A | Kitchen | No | W3 | Plaster | Tan | None | 0 | Positive |
| 4320 | 1 | B | 18A | Kitchen | Yes | W4 | Plaster | Tan | Cracking | 4 | Positive |
| 4320 | 1 | B | 18A | Kitchen | Yes | Ceiling | Plaster | Tan | Cracking | 15 | Positive |
| 4320 | 1 | B | 18A | Kitchen | No | Floor | N/A | N/A | N/A | N/A | N/A |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | Lead Safe Certification Assessment Report | | | | | | |
|-------|---------------------------------|-----------------------|---------|---|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 1 | B | 12 | Kitchen Storage next to Breakroom | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 12 | Kitchen Storage next to Breakroom | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 12 | Kitchen Storage next to Breakroom | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 12 | Kitchen Storage next to Breakroom | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 12 | Kitchen Storage next to Breakroom | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 12 | Kitchen Storage next to Breakroom | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 18D | Kitchen Walkway to Restroom | Yes | W1 | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 18D | Kitchen Walkway to Restroom | Yes | W2 | Plaster | Tan | Moisture Damage | 10 | Positive | |
| 4320 | 1 | B | 18D | Kitchen Walkway to Restroom | Yes | W3 | Plaster | Tan | None | 0 | N/A | |
| 4320 | 1 | B | 18D | Kitchen Walkway to Restroom | Yes | W4 | Plaster | Tan | Moisture Damage | 10 | Positive | |
| 4320 | 1 | B | 18D | Kitchen Walkway to Restroom | Yes | Ceiling | Plaster | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 18D | Kitchen Walkway to Restroom | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 008A | Boy's Restroom across from Classroom 001 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 008A | Boy's Restroom across from Classroom 001 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 008A | Boy's Restroom across from Classroom 001 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 008A | Boy's Restroom across from Classroom 001 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 008A | Boy's Restroom across from Classroom 001 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 008A | Boy's Restroom across from Classroom 001 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 008B | Girl's Restroom across from Classroom 001 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 008B | Girl's Restroom across from Classroom 001 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 008B | Girl's Restroom across from Classroom 001 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 008B | Girl's Restroom across from Classroom 001 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 008B | Girl's Restroom across from Classroom 001 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 008B | Girl's Restroom across from Classroom 001 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 1 | Classroom 001 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 1 | Classroom 001 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 1 | Classroom 001 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 1 | Classroom 001 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 1 | Classroom 001 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 1 | Classroom 001 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 001A | Classroom 001 Storage | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 001A | Classroom 001 Storage | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 001A | Classroom 001 Storage | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 001A | Classroom 001 Storage | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 001A | Classroom 001 Storage | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 1 | B | 001A | Classroom 001 Storage | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 1 | B | 001B | Classroom 001B | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 001B | Classroom 001B | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 001B | Classroom 001B | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 001B | Classroom 001B | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 1 | B | 001B | Classroom 001B | Yes | Ceiling | Concrete | Tan | None | 0 | Negative | |

| | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|-------------------------------------|------------------------------------|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | Inspection Company: Criterion Labs | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | B | 001B | Classroom 001B | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 007B | Storage Room next to Stairwell #7 | No | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 007B | Storage Room next to Stairwell #7 | No | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 007B | Storage Room next to Stairwell #7 | No | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 007B | Storage Room next to Stairwell #7 | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 007B | Storage Room next to Stairwell #7 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 007B | Storage Room next to Stairwell #7 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | S03 | Stairwell #7 next to Classroom 007 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | S03 | Stairwell #7 next to Classroom 007 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | S03 | Stairwell #7 next to Classroom 007 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | S03 | Stairwell #7 next to Classroom 007 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | S03 | Stairwell #7 next to Classroom 007 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | S03 | Stairwell #7 next to Classroom 007 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 7 | Classroom 007 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 7 | Classroom 007 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 7 | Classroom 007 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 7 | Classroom 007 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 7 | Classroom 007 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 7 | Classroom 007 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 2 | Classroom 002 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 2 | Classroom 002 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 2 | Classroom 002 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 2 | Classroom 002 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 2 | Classroom 002 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 2 | Classroom 002 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 002A | Classroom 002 Storage | No | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002A | Classroom 002 Storage | No | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002A | Classroom 002 Storage | No | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002A | Classroom 002 Storage | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002A | Classroom 002 Storage | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 002A | Classroom 002 Storage | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 002B | Classroom 002 Restroom | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002B | Classroom 002 Restroom | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002B | Classroom 002 Restroom | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002B | Classroom 002 Restroom | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002B | Classroom 002 Restroom | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 002B | Classroom 002 Restroom | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 002C | Classroom 002C | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002C | Classroom 002C | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002C | Classroom 002C | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | 002C | Classroom 002C | Yes | W4 | Concrete | Tan | None | 0 | Negative |

| | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|-------------------------------------|--------------------------------|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | Inspection Company: Criterion Labs | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 1 | B | 002C | Classroom 002C | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | 002C | Classroom 002C | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | H01 | Hallway at Classrooms 001 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H01 | Hallway at Classrooms 001 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H01 | Hallway at Classrooms 001 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H01 | Hallway at Classrooms 001 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 1 | B | H01 | Hallway at Classrooms 001 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | B | H01 | Hallway at Classrooms 001 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 113 | Classroom 113 | Yes | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113 | Classroom 113 | Yes | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113 | Classroom 113 | Yes | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113 | Classroom 113 | Yes | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113 | Classroom 113 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 113 | Classroom 113 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 113A | Classroom 113 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113A | Classroom 113 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113A | Classroom 113 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113A | Classroom 113 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113A | Classroom 113 storage Closet 1 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 113A | Classroom 113 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 113B | Classroom 113 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113B | Classroom 113 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113B | Classroom 113 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113B | Classroom 113 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 113B | Classroom 113 storage Closet 2 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 113B | Classroom 113 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 114 | Classroom 114 | Yes | W1 | Concrete | White | Flaking | 6 | Negative |
| 4320 | 2 | 1 | 114 | Classroom 114 | Yes | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114 | Classroom 114 | Yes | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114 | Classroom 114 | Yes | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114 | Classroom 114 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 114 | Classroom 114 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 114A | Classroom 114 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114A | Classroom 114 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114A | Classroom 114 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114A | Classroom 114 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114A | Classroom 114 storage Closet 1 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 114A | Classroom 114 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 1 | 114B | Classroom 114 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114B | Classroom 114 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 1 | 114B | Classroom 114 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | | | | | | |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|---|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | | Lead Safe Certification Assessment Report | | | | | |
| | | | | Inspection Company: Criterion Labs | | | Lamberton High School | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 2 | 1 | 114B | Classroom 114 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 114B | Classroom 114 storage Closet 2 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 114B | Classroom 114 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 115 | Classroom 115 | Yes | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115 | Classroom 115 | Yes | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115 | Classroom 115 | Yes | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115 | Classroom 115 | Yes | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115 | Classroom 115 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 115 | Classroom 115 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 115A | Classroom 115 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115A | Classroom 115 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115A | Classroom 115 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115A | Classroom 115 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115A | Classroom 115 storage Closet 1 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 115A | Classroom 115 storage Closet 1 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 115B | Classroom 115 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115B | Classroom 115 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115B | Classroom 115 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115B | Classroom 115 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 115B | Classroom 115 storage Closet 2 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 115B | Classroom 115 storage Closet 2 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | S11 | Stairwell #8 at the end of the Hallway | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | S11 | Stairwell #8 at the end of the Hallway | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | S11 | Stairwell #8 at the end of the Hallway | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | S11 | Stairwell #8 at the end of the Hallway | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | S11 | Stairwell #8 at the end of the Hallway | Yes | W4 | Metal | White | None | 0 | Negative | |
| 4320 | 2 | 1 | S11 | Stairwell #8 at the end of the Hallway | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | S11 | Stairwell #8 at the end of the Hallway | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 116 | Classroom 116 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 116 | Classroom 116 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 116 | Classroom 116 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 116 | Classroom 116 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 116 | Classroom 116 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 116 | Classroom 116 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 116A | Classroom 116 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 116A | Classroom 116 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 116A | Classroom 116 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 116A | Classroom 116 storage Closet 1 | No | W4 | Concrete | White | None | 0 | N/A | |
| 4320 | 2 | 1 | 116A | Classroom 116 storage Closet 1 | No | Ceiling | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 116A | Classroom 116 storage Closet 1 | No | Floor | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 116B | Classroom 116 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | Lead Safe Certification Assessment Report | | | | | | |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|---------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 2 | 1 | 116B | Classroom 116 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 116B | Classroom 116 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 116B | Classroom 116 storage Closet 2 | No | W4 | Concrete | White | None | 0 | N/A | |
| 4320 | 2 | 1 | 116B | Classroom 116 storage Closet 2 | No | Ceiling | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 116B | Classroom 116 storage Closet 2 | No | Floor | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117 | Classroom 117 | Yes | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117 | Classroom 117 | Yes | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117 | Classroom 117 | Yes | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117 | Classroom 117 | Yes | W4 | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117 | Classroom 117 | Yes | Ceiling | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117 | Classroom 117 | Yes | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117G | Classroom 117 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117G | Classroom 117 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117G | Classroom 117 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117G | Classroom 117 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117G | Classroom 117 storage Closet 1 | No | Ceiling | Ceiling | Plaster | White | None | Negative | |
| 4320 | 2 | 1 | 117G | Classroom 117 storage Closet 1 | No | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117H | Classroom 117 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117H | Classroom 117 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117H | Classroom 117 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117H | Classroom 117 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117H | Classroom 117 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 1 | 117H | Classroom 117 storage Closet 2 | No | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117A | Girl's Restroom by Classroom 117 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117A | Girl's Restroom by Classroom 117 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117A | Girl's Restroom by Classroom 117 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117A | Girl's Restroom by Classroom 117 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117A | Girl's Restroom by Classroom 117 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117A | Girl's Restroom by Classroom 117 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117B | Boy's Restroom by Classroom 117 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117B | Boy's Restroom by Classroom 117 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117B | Boy's Restroom by Classroom 117 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117B | Boy's Restroom by Classroom 117 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117B | Boy's Restroom by Classroom 117 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117B | Boy's Restroom by Classroom 117 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117C | Storage Room at Restrooms by Classroom 117 | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117C | Storage Room at Restrooms by Classroom 117 | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117C | Storage Room at Restrooms by Classroom 117 | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117C | Storage Room at Restrooms by Classroom 117 | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117C | Storage Room at Restrooms by Classroom 117 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117C | Storage Room at Restrooms by Classroom 117 | No | Floor | N/A | N/A | N/A | N/A | N/A | |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | Lead Safe Certification Assessment Report | | | | | | |
|-------|---------------------------------|-----------------------|---------|---|---|---|--------------------|---------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | Lamberton High School | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 2 | 1 | 117D | Custodial Closet at Restroom by Classroom 117 | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117D | Custodial Closet at Restroom by Classroom 117 | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117D | Custodial Closet at Restroom by Classroom 117 | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117D | Custodial Closet at Restroom by Classroom 117 | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117D | Custodial Closet at Restroom by Classroom 117 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117D | Custodial Closet at Restroom by Classroom 117 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117E | Women's Teacher Restroom by Classroom 117 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117E | Women's Teacher Restroom by Classroom 117 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117E | Women's Teacher Restroom by Classroom 117 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117E | Women's Teacher Restroom by Classroom 117 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 1 | 117E | Women's Teacher Restroom by Classroom 117 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 1 | 117E | Women's Teacher Restroom by Classroom 117 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | PC207H | Pipe Chase between Restrooms near Classroom 207 | No | W1 | Concrete | N/A | None | 0 | N/A | |
| 4320 | 2 | 2 | PC207H | Pipe Chase between Restrooms near Classroom 207 | No | W2 | Concrete | N/A | None | 0 | N/A | |
| 4320 | 2 | 2 | PC207H | Pipe Chase between Restrooms near Classroom 207 | No | W3 | Concrete | N/A | None | 0 | N/A | |
| 4320 | 2 | 2 | PC207H | Pipe Chase between Restrooms near Classroom 207 | No | W4 | Concrete | N/A | None | 0 | N/A | |
| 4320 | 2 | 2 | PC207H | Pipe Chase between Restrooms near Classroom 207 | No | Ceiling | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | PC207H | Pipe Chase between Restrooms near Classroom 207 | No | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 214 | Classroom 214 | Yes | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214 | Classroom 214 | Yes | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214 | Classroom 214 | Yes | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214 | Classroom 214 | Yes | W4 | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 214 | Classroom 214 | Yes | Ceiling | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 214 | Classroom 214 | Yes | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 214A | Classroom 214 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214A | Classroom 214 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214A | Classroom 214 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214A | Classroom 214 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214A | Classroom 214 storage Closet 1 | No | Ceiling | Ceiling | Plaster | White | None | Negative | |
| 4320 | 2 | 2 | 214A | Classroom 214 storage Closet 1 | No | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 214B | Classroom 214 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214B | Classroom 214 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214B | Classroom 214 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214B | Classroom 214 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214B | Classroom 214 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 214B | Classroom 214 storage Closet 2 | No | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 215 | Classroom 215 | Yes | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 215 | Classroom 215 | Yes | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 215 | Classroom 215 | Yes | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 215 | Classroom 215 | Yes | W4 | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 215 | Classroom 215 | Yes | Ceiling | N/A | N/A | N/A | N/A | N/A | |

| | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|-------------------------------------|--------------------------------|---|---|--------------------|---------|--------------------------|-------------------------|--------------------------------|
| | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | Inspection Company: Criterion Labs | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 2 | 2 | 215 | Classroom 215 | Yes | Floor | Floor | Floor | N/A | N/A | N/A |
| 4320 | 2 | 2 | 215A | Classroom 215 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215A | Classroom 215 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215A | Classroom 215 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215A | Classroom 215 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215A | Classroom 215 storage Closet 1 | No | Ceiling | Ceiling | Plaster | White | None | Negative |
| 4320 | 2 | 2 | 215A | Classroom 215 storage Closet 1 | No | Floor | Floor | Floor | N/A | N/A | N/A |
| 4320 | 2 | 2 | 215B | Classroom 215 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215B | Classroom 215 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215B | Classroom 215 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215B | Classroom 215 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215B | Classroom 215 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 215B | Classroom 215 storage Closet 2 | No | Floor | Floor | Floor | N/A | N/A | N/A |
| 4320 | 2 | 2 | 216 | Classroom 216 | Yes | W1 | Concrete | White | Cracking | 5 | Negative |
| 4320 | 2 | 2 | 216 | Classroom 216 | Yes | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216 | Classroom 216 | Yes | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216 | Classroom 216 | Yes | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216 | Classroom 216 | Yes | Ceiling | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 216 | Classroom 216 | Yes | Floor | Floor | Floor | N/A | N/A | N/A |
| 4320 | 2 | 2 | 216A | Classroom 216 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216A | Classroom 216 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216A | Classroom 216 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216A | Classroom 216 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216A | Classroom 216 storage Closet 1 | No | Ceiling | Ceiling | Plaster | White | None | Negative |
| 4320 | 2 | 2 | 216A | Classroom 216 storage Closet 1 | No | Floor | Floor | Floor | N/A | N/A | N/A |
| 4320 | 2 | 2 | 216B | Classroom 216 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216B | Classroom 216 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216B | Classroom 216 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216B | Classroom 216 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216B | Classroom 216 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 216B | Classroom 216 storage Closet 2 | No | Floor | Floor | Floor | N/A | N/A | N/A |
| 4320 | 2 | 2 | 217 | Classroom 217 | Yes | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 217 | Classroom 217 | Yes | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 217 | Classroom 217 | Yes | W3 | Concrete | White | Flaking | 10 | Negative |
| 4320 | 2 | 2 | 217 | Classroom 217 | Yes | W4 | Concrete | White | None | 0 | N/A |
| 4320 | 2 | 2 | 217 | Classroom 217 | Yes | Ceiling | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 217 | Classroom 217 | Yes | Floor | Floor | Floor | N/A | N/A | N/A |
| 4320 | 2 | 2 | 217A | Classroom 217 storage Closet 1 | no | W1 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 217A | Classroom 217 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 217A | Classroom 217 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative |
| 4320 | 2 | 2 | 217A | Classroom 217 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report Lamberton High School | | | | | |
|------|---|---|------|--|---------------------------------|-----------------------|--|-------------------|---|-----------|--------------------|-------|
| | | | | Name of Inspector: Michael Barth | | | | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color |
| 4320 | 2 | 2 | 217A | Classroom 217 storage Closet 1 | No | Ceiling | Ceiling | Plaster | White | None | Negative | |
| 4320 | 2 | 2 | 217A | Classroom 217 storage Closet 1 | No | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 217B | Classroom 217 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 217B | Classroom 217 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 217B | Classroom 217 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 217B | Classroom 217 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 217B | Classroom 217 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 217B | Classroom 217 storage Closet 2 | No | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 218 | Classroom 218 | Yes | W1 | Concrete | White | Flaking | 3 | Negative | |
| 4320 | 2 | 2 | 218 | Classroom 218 | Yes | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218 | Classroom 218 | Yes | W3 | Concrete | White | Flaking | 5 | Negative | |
| 4320 | 2 | 2 | 218 | Classroom 218 | Yes | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218 | Classroom 218 | Yes | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218 | Classroom 218 | Yes | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 218F | Classroom 218 storage Closet 1 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218F | Classroom 218 storage Closet 1 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218F | Classroom 218 storage Closet 1 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218F | Classroom 218 storage Closet 1 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218F | Classroom 218 storage Closet 1 | No | Ceiling | Ceiling | Plaster | White | None | Negative | |
| 4320 | 2 | 2 | 218F | Classroom 218 storage Closet 1 | No | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 218G | Classroom 218 storage Closet 2 | No | W1 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218G | Classroom 218 storage Closet 2 | No | W2 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218G | Classroom 218 storage Closet 2 | No | W3 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218G | Classroom 218 storage Closet 2 | No | W4 | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218G | Classroom 218 storage Closet 2 | No | Ceiling | Concrete | White | None | 0 | Negative | |
| 4320 | 2 | 2 | 218G | Classroom 218 storage Closet 2 | No | Floor | Floor | Floor | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 218A | Boy's Restroom across from Classroom 214 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218A | Boy's Restroom across from Classroom 214 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218A | Boy's Restroom across from Classroom 214 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218A | Boy's Restroom across from Classroom 214 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218A | Boy's Restroom across from Classroom 214 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 218A | Boy's Restroom across from Classroom 214 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 218B | Girl's Restroom next to Classroom 218 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218B | Girl's Restroom next to Classroom 218 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218B | Girl's Restroom next to Classroom 218 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218B | Girl's Restroom next to Classroom 218 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218B | Girl's Restroom next to Classroom 218 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 218B | Girl's Restroom next to Classroom 218 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | 2 | 218C | Storage Room at Restrooms near Classroom 218 | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218C | Storage Room at Restrooms near Classroom 218 | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | 2 | 218C | Storage Room at Restrooms near Classroom 218 | No | W3 | Concrete | Tan | None | 0 | Negative | |

| | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|-------------------------------------|--|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | Inspection Company: Criterion Labs | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 2 | 2 | 218C | Storage Room at Restrooms near Classroom 218 | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218C | Storage Room at Restrooms near Classroom 218 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 218C | Storage Room at Restrooms near Classroom 218 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 218E | Custodial Closet at Restrooms near Classroom 218 | No | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218E | Custodial Closet at Restrooms near Classroom 218 | No | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218E | Custodial Closet at Restrooms near Classroom 218 | No | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218E | Custodial Closet at Restrooms near Classroom 218 | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218E | Custodial Closet at Restrooms near Classroom 218 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 218E | Custodial Closet at Restrooms near Classroom 218 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 218F | Women's Teacher Restroom | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218F | Women's Teacher Restroom | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218F | Women's Teacher Restroom | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218F | Women's Teacher Restroom | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | 218F | Women's Teacher Restroom | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 218F | Women's Teacher Restroom | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 218G | Pipe Chase between Restrooms near Classroom 218 | No | W1 | Concrete | N/A | None | 0 | N/A |
| 4320 | 2 | 2 | 218G | Pipe Chase between Restrooms near Classroom 218 | No | W2 | Concrete | N/A | None | 0 | N/A |
| 4320 | 2 | 2 | 218G | Pipe Chase between Restrooms near Classroom 218 | No | W3 | Concrete | N/A | None | 0 | N/A |
| 4320 | 2 | 2 | 218G | Pipe Chase between Restrooms near Classroom 218 | No | W4 | Concrete | N/A | None | 0 | N/A |
| 4320 | 2 | 2 | 218G | Pipe Chase between Restrooms near Classroom 218 | No | Ceiling | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | 218G | Pipe Chase between Restrooms near Classroom 218 | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | H21 | Hallway from Classrooms 214 to 218 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | H21 | Hallway from Classrooms 214 to 218 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | H21 | Hallway from Classrooms 214 to 218 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | H21 | Hallway from Classrooms 214 to 218 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | 2 | H21 | Hallway from Classrooms 214 to 218 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | 2 | H21 | Hallway from Classrooms 214 to 218 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | H03 | Hallway across from Boy's Restroom | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | H03 | Hallway across from Boy's Restroom | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | H03 | Hallway across from Boy's Restroom | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | H03 | Hallway across from Boy's Restroom | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | H03 | Hallway across from Boy's Restroom | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | H03 | Hallway across from Boy's Restroom | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 003C | Women's Teacher Restroom in the Hallway by Classroom 003 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003C | Women's Teacher Restroom in the Hallway by Classroom 003 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003C | Women's Teacher Restroom in the Hallway by Classroom 003 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003C | Women's Teacher Restroom in the Hallway by Classroom 003 | Yes | W4 | Concrete | Tan | None | 0 | Negative |

| | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|-------------------------------------|--|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | Inspection Company: Criterion Labs | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 2 | B | 003C | Women's Teacher Restroom in the Hallway by Classroom 003 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 003C | Women's Teacher Restroom in the Hallway by Classroom 003 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 3 | Classroom 003 | Yes | W1 | Concrete | Tan | Cracking | 4 | Negative |
| 4320 | 2 | B | 3 | Classroom 003 | Yes | W2 | Concrete | Tan | Cracking | 3 | Negative |
| 4320 | 2 | B | 3 | Classroom 003 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 3 | Classroom 003 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 3 | Classroom 003 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 3 | Classroom 003 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 003A | Classroom 003 Restroom | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003A | Classroom 003 Restroom | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003A | Classroom 003 Restroom | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003A | Classroom 003 Restroom | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003A | Classroom 003 Restroom | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 003A | Classroom 003 Restroom | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 003B | Classroom 003 Storage | No | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003B | Classroom 003 Storage | No | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003B | Classroom 003 Storage | No | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003B | Classroom 003 Storage | No | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 003B | Classroom 003 Storage | No | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 003B | Classroom 003 Storage | No | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 4 | Classroom 004 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 4 | Classroom 004 | Yes | W2 | Concrete | Tan | Cracking | 5 | Negative |
| 4320 | 2 | B | 4 | Classroom 004 | Yes | W3 | Concrete | Tan | Chipping | 5 | Negative |
| 4320 | 2 | B | 4 | Classroom 004 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 4 | Classroom 004 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 4 | Classroom 004 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | S01 | Stairwell to Exit 8 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | S01 | Stairwell to Exit 8 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | S01 | Stairwell to Exit 8 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | S01 | Stairwell to Exit 8 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | S01 | Stairwell to Exit 8 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | S01 | Stairwell to Exit 8 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 005A | Classroom 005A | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 005A | Classroom 005A | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 005A | Classroom 005A | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 005A | Classroom 005A | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | 005A | Classroom 005A | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 005A | Classroom 005A | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | 005B | Classroom 005B | Yes | W1 | Concrete | Tan | None | 0 | Negative |

| | | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|---|-------|--------------------------|-------------------------|--------------------------------|--|
| | | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | | Inspection Company: Criterion Labs | | | | | | | | |
| | | | | | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) | |
| 4320 | 2 | B | 005B | Classroom 005B | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 005B | Classroom 005B | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 005B | Classroom 005B | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 005B | Classroom 005B | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 005B | Classroom 005B | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 005AC | Classroom 005A Closet | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 005AC | Classroom 005A Closet | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 005AC | Classroom 005A Closet | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 005AC | Classroom 005A Closet | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 005AC | Classroom 005A Closet | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 005AC | Classroom 005A Closet | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 5 | Classroom 005 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 5 | Classroom 005 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 5 | Classroom 005 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 5 | Classroom 005 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 5 | Classroom 005 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 5 | Classroom 005 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 6 | Classroom 6 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 6 | Classroom 6 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 6 | Classroom 6 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 6 | Classroom 6 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 6 | Classroom 6 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 6 | Classroom 6 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 006A | Girl's Restroom next to Classroom 006 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006A | Girl's Restroom next to Classroom 006 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006A | Girl's Restroom next to Classroom 006 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006A | Girl's Restroom next to Classroom 006 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006A | Girl's Restroom next to Classroom 006 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 006A | Girl's Restroom next to Classroom 006 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 006B | Boy's Restroom by Classroom 006 | Yes | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006B | Boy's Restroom by Classroom 006 | Yes | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006B | Boy's Restroom by Classroom 006 | Yes | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006B | Boy's Restroom by Classroom 006 | Yes | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006B | Boy's Restroom by Classroom 006 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 006B | Boy's Restroom by Classroom 006 | Yes | Floor | N/A | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 006C | Custodial Closet at Restrooms by Classroom 006 | No | W1 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006C | Custodial Closet at Restrooms by Classroom 006 | No | W2 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006C | Custodial Closet at Restrooms by Classroom 006 | No | W3 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006C | Custodial Closet at Restrooms by Classroom 006 | No | W4 | Concrete | Tan | None | 0 | Negative | |
| 4320 | 2 | B | 006C | Custodial Closet at Restrooms by Classroom 006 | No | Ceiling | Concrete | N/A | N/A | N/A | N/A | |
| 4320 | 2 | B | 006C | Custodial Closet at Restrooms by Classroom 006 | No | Floor | N/A | N/A | N/A | N/A | N/A | |

| | | | Inspection Dates: 09/08/21-09/17/21 | | | Lead Safe Certification Assessment Report | | | | | |
|-------|---------------------------------|-----------------------|-------------------------------------|------------------------------------|---|---|--------------------|-------|--------------------------|-------------------------|--------------------------------|
| | | | Name of Inspector: Michael Barth | | | Lamberton High School | | | | | |
| | | | Inspection Company: Criterion Labs | | | | | | | | |
| ULCS# | E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Color | Description of Damage | Damage Quantity (sf) | XRF (positive/ negative) |
| 4320 | 2 | B | H01 | Hallway from Classrooms 003 to 006 | Yes | W1 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | H01 | Hallway from Classrooms 003 to 006 | Yes | W2 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | H01 | Hallway from Classrooms 003 to 006 | Yes | W3 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | H01 | Hallway from Classrooms 003 to 006 | Yes | W4 | Concrete | Tan | None | 0 | Negative |
| 4320 | 2 | B | H01 | Hallway from Classrooms 003 to 006 | Yes | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 2 | B | H01 | Hallway from Classrooms 003 to 006 | Yes | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 018B | Kitchen Storage | no | W1 | Concrete | Tan | None | 0 | Positive |
| 4320 | 1 | 1 | 018B | Kitchen Storage | no | W2 | Concrete | Tan | None | 0 | Positive |
| 4320 | 1 | 1 | 018B | Kitchen Storage | no | W3 | Concrete | Tan | None | 0 | Positive |
| 4320 | 1 | 1 | 018B | Kitchen Storage | no | W4 | Concrete | Tan | None | 0 | Positive |
| 4320 | 1 | 1 | 018B | Kitchen Storage | no | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 018B | Kitchen Storage | no | Floor | N/A | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 018C | Kitchen Staff Restroom | no | W1 | Concrete | Tan | None | 0 | Positive |
| 4320 | 1 | 1 | 018C | Kitchen Staff Restroom | no | W2 | Concrete | Tan | None | 0 | Positive |
| 4320 | 1 | 1 | 018C | Kitchen Staff Restroom | no | W3 | Concrete | Tan | None | 0 | Positive |
| 4320 | 1 | 1 | 018C | Kitchen Staff Restroom | no | W4 | Concrete | Tan | None | 0 | Positive |
| 4320 | 1 | 1 | 018C | Kitchen Staff Restroom | no | Ceiling | Concrete | N/A | N/A | N/A | N/A |
| 4320 | 1 | 1 | 018C | Kitchen Staff Restroom | no | Floor | N/A | N/A | N/A | N/A | N/A |