

				Inspection Dates: 12/13-12/17, 12/20, and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	BS	1	Mechanical Room	Main Mechanical Room	No	W1	Concrete	White	Cracking	50	0.05	Negative
7460	1	BS	1	Mechanical Room	Main Mechanical Room	No	W2	Concrete	White	Chipping	50	0.13	Negative
7460	1	BS	1	Mechanical Room	Main Mechanical Room	No	W3	Concrete	White	Chipping	50	0.03	Negative
7460	1	BS	1	Mechanical Room	Main Mechanical Room	No	W4	Concrete	White	Chipping	50	0.1	Negative
7460	1	BS	1	Mechanical Room	Main Mechanical Room	No	Ceiling	Concrete	White	Cracking	10	0.14	Negative
7460	1	BS	1	Mechanical Room	Main Mechanical Room	No	Floor	Concrete	Gray	None	0	0	Negative
7460	1	BS	2	Mechanical Room	South East Mechanical Room Fuel Pump Room	No	W1	Concrete	White	Cracking	5	0.09	Negative
7460	1	BS	2	Mechanical Room	South East Mechanical Room Fuel Pump Room	No	W2	Concrete	White	Chipping	5	0.01	Negative
7460	1	BS	2	Mechanical Room	South East Mechanical Room Fuel Pump Room	No	W3	Concrete	White	None	0	0	Negative
7460	1	BS	2	Mechanical Room	South East Mechanical Room Fuel Pump Room	No	W4	Concrete	White	None	0	0	Negative
7460	1	BS	2	Mechanical Room	South East Mechanical Room Fuel Pump Room	No	Ceiling	Concrete	White	None	0	0.11	Negative
7460	1	BS	2	Mechanical Room	South East Mechanical Room Fuel Pump Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	3	Mechanical Room	Emergency Generator Room	No	W1	Concrete	White	None	0	0	Negative
7460	1	BS	3	Mechanical Room	Emergency Generator Room	No	W2	Concrete	White	Cracking	5	0.07	Negative
7460	1	BS	3	Mechanical Room	Emergency Generator Room	No	W3	Concrete	White	None	0	0.01	Negative
7460	1	BS	3	Mechanical Room	Emergency Generator Room	No	W4	Concrete	White	None	0	0.02	Negative
7460	1	BS	3	Mechanical Room	Emergency Generator Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	3	Mechanical Room	Emergency Generator Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	4	Administrative Office	Building Engineer's Office	No	W1	Concrete	Yellow	None	0	0.05	Negative
7460	1	BS	4	Administrative Office	Building Engineer's Office	No	W1	Metal	Gray	Friction	1	0.04	Negative
7460	1	BS	4	Administrative Office	Building Engineer's Office	No	W1	Metal	Gray	Friction	1	0.01	Negative
7460	1	BS	4	Administrative Office	Building Engineer's Office	No	W2	Concrete	Yellow	None	0	0	Negative
7460	1	BS	4	Administrative Office	Building Engineer's Office	No	W3	Concrete	Yellow	None	0	0.04	Negative
7460	1	BS	4	Administrative Office	Building Engineer's Office	No	W4	Concrete	Yellow	None	0	0.01	Negative
7460	1	BS	4	Administrative Office	Building Engineer's Office	No	Ceiling	Concrete	White	Cracking	20	0	Negative
7460	1	BS	4	Administrative Office	Building Engineer's Office	No	Floor	Concrete	Gray	None	0	0	Negative
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	W1	Concrete	White	None	0	N/A	N/A
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	W1	Metal	Blue	Chipping	1	0.09	Negative
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	W1	Metal	Blue	Friction	1	0.05	Negative
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	W1	Metal	Blue	Chipping	5	0.05	Negative
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	W2	Concrete	White	None	0	N/A	N/A
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	W3	Concrete	White	None	0	N/A	N/A
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	W4	Concrete	White	None	0	N/A	N/A
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	Ceiling	Concrete	White	Cracking	5	0.02	Negative
7460	1	BS	5	Electrical Room	Electrical Room next to Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	6	Storage	Storage at the end of the Building Engineer's Hallway	No	W1	Concrete	White	None	0	0.05	Negative
7460	1	BS	6	Storage	Storage at the end of the Building Engineer's Hallway	No	W1	Metal	Gray	None	0	0	Negative
7460	1	BS	6	Storage	Storage at the end of the Building Engineer's Hallway	No	W1	Metal	Gray	None	0	0	Negative
7460	1	BS	6	Storage	Storage at the end of the Building Engineer's Hallway	No	W2	Concrete	White	None	0	0.13	Negative
7460	1	BS	6	Storage	Storage at the end of the Building Engineer's Hallway	No	W3	Concrete	White	None	0	0.06	Negative
7460	1	BS	6	Storage	Storage at the end of the Building Engineer's Hallway	No	W4	Concrete	White	Cracking	20	0.16	Negative
7460	1	BS	6	Storage	Storage at the end of the Building Engineer's Hallway	No	Ceiling	Concrete	White	None	0	0.03	Negative
7460	1	BS	6	Storage	Storage at the end of the Building Engineer's Hallway	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	W1	Concrete	White	Cracking	10	0.07	Negative
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	W2	Concrete	White	None	0	0.02	Negative
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	W2	Metal	Gray	None	0	0.07	Negative
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	W2	Metal	Blue	Chipping	5	0.02	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	W2	Metal	Blue	None	0	0	Negative
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	S1A	Stairs	Stairs from the Mechanical Room along the Crawlspace	No	Floor	Concrete	Gray	None	0	0	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	W1	Concrete	White	Cracking	5	0	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	W1	Brick	White	Cracking	5	0.21	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	W1	Metal	Gray	Chipping	3	0.08	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	W2	Sheetrock	Gray	None	0	0	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	W3	Concrete	White	Cracking	5	0.1	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	W3	Brick	White	Cracking	5	0.04	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	Ceiling	Concrete	White	None	0	0.02	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	Floor	Concrete	Gray	Friction	10	0.01	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	Floor	Concrete	Gray	None	0	0	Negative
7460	1	BS	S1B	Stairs	Stairs to the Building Engineer's Room	No	Floor	Concrete	Gray	None	0	0	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	W1	Concrete	White	None	0	0.02	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	W2	Concrete	White	None	0	0.14	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	W3	Sheetrock	Gray	None	0	0	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	W3	Metal	White	None	0	0	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	W3	Metal	White	None	0	0	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	W3	Metal	Gray	None	0	0	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	W4	Concrete	White	None	0	0	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	Ceiling	Concrete	White	None	0	0	Negative
7460	1	BS	HBS	Circulation (Hallway)	Hallway in Front of the Building Engineer's Office	No	Floor	Concrete	Brown	Friction	50	0.01	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	Yes	W1	Metal	Gray	None	0	0.03	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	yes	W1	Metal	Gray	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	yes	W1	Metal	Gray	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	yes	W2	Metal	Blue	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	Yes	W2	Sheetrock	Blue	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	Yes	W3	Sheetrock	Blue	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	yes	W3	Metal	Blue	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	yes	W3	Metal	White	None	0	0.01	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	yes	W3	Metal	White	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	yes	W4	Metal	Blue	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	yes	W4	Concrete	Gray	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	Yes	W4	Sheetrock	Blue	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	Yes	Ceiling	Sheetrock	Red	None	0	0	Negative
7460	1	1	ME	Circulation (Hallway)	Main Entrance Foyer	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W1	Concrete	White	None	0	0.04	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W1	Metal	White	None	0	0	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W2	Concrete	White	None	0	0	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W3	Metal	White	None	0	0.12	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W3	Concrete	Gray	None	0	0	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W4	Metal	White	None	0	0.15	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W4	Wood	Blue	None	0	0.01	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	W4	Concrete	White	None	0	0.01	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	Ceiling	Concrete	White	None	0	0.04	Negative
7460	1	1	100A	Principal/Directors Office	Dean's Office 110	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100C	Storage	Dean's Office 110 Closet	Yes	W1	Concrete	Gray	None	0	0	Negative
7460	1	1	100C	Storage	Dean's Office 110 Closet	Yes	W1	Metal	White	None	0	0.11	Negative
7460	1	1	100C	Storage	Dean's Office 110 Closet	Yes	W1	Metal	White	None	0	0.05	Negative
7460	1	1	100C	Storage	Dean's Office 110 Closet	Yes	W2	Concrete	Gray	None	0	0.03	Negative
7460	1	1	100C	Storage	Dean's Office 110 Closet	Yes	W3	Concrete	Gray	None	0	0	Negative
7460	1	1	100C	Storage	Dean's Office 110 Closet	Yes	W4	Concrete	Gray	None	0	0	Negative
7460	1	1	100C	Storage	Dean's Office 110 Closet	Yes	Ceiling	Concrete	White	None	0	0.07	Negative
7460	1	1	100C	Storage	Dean's Office 110 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100B	Storage	Storage Closet at the Main Entrance	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	1	100B	Storage	Storage Closet at the Main Entrance	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	1	100B	Storage	Storage Closet at the Main Entrance	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	1	100B	Storage	Storage Closet at the Main Entrance	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	1	100B	Storage	Storage Closet at the Main Entrance	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	1	100B	Storage	Storage Closet at the Main Entrance	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W1	Metal	Blue	None	0	0	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W1	Metal	Blue	None	0	0.02	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W2	Sheetrock	Gray	None	0	0	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W2	Metal	Blue	None	0	0.01	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W2	Metal	Blue	None	0	0.05	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W2	Metal	White	None	0	0.03	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	W4	Sheetrock	Gray	None	0	0	Negative
7460	1	1	100Q	General Administrative Space	Main Office	yes	W4	Metal	Tan	None		0.05	Negative
7460	1	1	100Q	General Administrative Space	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/13-12/17, 12/20, and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	1	100Q	General Administrative Space	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100R	Copying Room	Main Office Copy Room	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	1	1	100R	Copying Room	Main Office Copy Room	Yes	W2	Sheetrock	White	None	0	0	Negative
7460	1	1	100R	Copying Room	Main Office Copy Room	Yes	W3	Concrete	White	None	0	0	Negative
7460	1	1	100R	Copying Room	Main Office Copy Room	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	1	1	100R	Copying Room	Main Office Copy Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100R	Copying Room	Main Office Copy Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100S	Principal/Directors Office	Principal's Office	yes	W1	Sheetrock	White	None	0	0	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	W2	Sheetrock	Red	None	0	0	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	W2	Metal	White	None	0	0.02	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	W2	Metal	White	None	0	0	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	W3	Concrete	White	None	0	0	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	W4	Sheetrock	Red	None	0	0	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	W4	Metal	Tan	None	0	0.03	Negative
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100S	Principal/Directors Office	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100T	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	100T	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100T	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100T	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100T	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	100T	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	W1	Metal	White	None	0	0.01	Negative
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	W1	Metal	White	None	0	0.01	Negative
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	W2	Sheetrock	White	None	0	0	Negative
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	W3	Metal	White	None	0	0	Negative
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102C	Conference Room	Conference Room 102 adjacent to Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Conference Room 102	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	102B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Conference Room 102	Yes	W1	Metal	White	None	0	0	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	1	102B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Conference Room 102	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Conference Room 102	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Conference Room 102	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Conference Room 102	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Conference Room 102	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102	Primary	Classroom 103	Yes	W1	Concrete	Gray	None	0	0.07	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W1	Metal	Blue	None	0	0.1	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W1	Metal	Blue	None	0	0.09	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W1	Wood	Blue	None	0	0	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W1	Metal	Red	None	0	0.01	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W1	Metal	Red	None	0	0.21	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W2	Sheetrock	Gray	None	0	0	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W1	Metal	White	None	0	0.02	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W1	Wood	White	None	0	0	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W3	Concrete	White	None	0	0	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W3	Metal	Tan	None	0	0.03	Negative
7460	1	1	102	Primary	Classroom 103	Yes	W4	Concrete	White	None	0	0	Negative
7460	1	1	102	Primary	Classroom 103	Yes	Ceiling	Concrete	White	None	0	0.11	Negative
7460	1	1	102	Primary	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	104	Primary	Classroom 104	Yes	W1	Concrete	Blue	None	0	N/A	N/A
7460	1	1	104	Primary	Classroom 104	Yes	W1	Wood	Blue	None	0	N/A	N/A
7460	1	1	104	Primary	Classroom 104	Yes	W1	Metal	White	None	0	N/A	N/A
7460	1	1	104	Primary	Classroom 104	Yes	W1	Metal	White	None	0	N/A	N/A
7460	1	1	104	Primary	Classroom 104	Yes	W2	Concrete	White	None	0	N/A	N/A
7460	1	1	104	Primary	Classroom 104	Yes	W2	Concrete	White	None	0	N/A	N/A
7460	1	1	104	Primary	Classroom 104	Yes	W2	Metal	White	None	0	N/A	N/A
7460	1	1	104	Primary	Classroom 104	Yes	W3	Concrete	White	None	0	N/A	N/A

				Inspection Dates: 12/13-12/17, 12/20,and 12/22							Lead Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Craig Gratz/006207											
				Inspection Company: Criterion											
				Zeigler School											
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)		
7460	1	1	104	Primary	Classroom 104	Yes	W3	Metal	Brown	None	0	N/A	N/A		
7460	1	1	104	Primary	Classroom 104	Yes	W4	Sheetrock	Blue	None	0	N/A	N/A		
7460	1	1	104	Primary	Classroom 104	Yes	W4	Sheetrock	Grey	None	0	N/A	N/A		
7460	1	1	104	Primary	Classroom 104	Yes	Ceiling	Concrete	White	Cracking	10	0.01	Negative		
7460	1	1	104	Primary	Classroom 104	Yes	Ceiling	Metal	White	None	0	N/A	N/A		
7460	1	1	104	Primary	Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Yes	W1	Metal	White	Chipping	2	0	Negative		
7460	1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	105	Primary	Classroom 105	Yes	W1	Sheetrock	Blue	None	0	0	Negative		
7460	1	1	105	Primary	Classroom 105	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	1	105	Primary	Classroom 105	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	1	105	Primary	Classroom 105	Yes	W2	Sheetrock	Blue	None	0	0	Negative		
7460	1	1	105	Primary	Classroom 105	Yes	W3	Concrete	Blue	None	0	0.03	Negative		
7460	1	1	105	Primary	Classroom 105	Yes	W3	Metal	Gray	None	0	0.01	Negative		
7460	1	1	105	Primary	Classroom 105	Yes	W4	Concrete	Blue	None	0	0.05	Negative		
7460	1	1	105	Primary	Classroom 105	Yes	Ceiling	Concrete	White	None	0	0.12	Negative		
7460	1	1	105	Primary	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	106	Primary	Classroom 106	Yes	W1	Concrete	Gray	None	0	0	Negative		

				Inspection Dates: 12/13-12/17, 12/20,and 12/22							Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207													
				Inspection Company: Criterion													
							Zeigler School										
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)				
7460	1	1	106	Primary	Classroom 106	Yes	W1	Metal	White	None	0	0.03	Negative				
7460	1	1	106	Primary	Classroom 106	Yes	W1	Metal	White	None	0	0.02	Negative				
7460	1	1	106	Primary	Classroom 106	Yes	W2	Concrete	Gray	None	0	0.05	Negative				
7460	1	1	106	Primary	Classroom 106	Yes	W3	Concrete	White	None	0	0	Negative				
7460	1	1	106	Primary	Classroom 106	Yes	W4	Sheetrock	Green	None	0	0	Negative				
7460	1	1	106	Primary	Classroom 106	Yes	Ceiling	Concrete	White	None	0	0.13	Negative				
7460	1	1	106	Primary	Classroom 106	Yes	Ceiling	Metal	White	None	0	0.08	Negative				
7460	1	1	106	Primary	Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Yes	W1	Metal	White	None	0	0.03	Negative				
7460	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Yes	W1	Metal	White	None	0	0.01	Negative				
7460	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Yes	W1	Wood	Blue	None	0	0	Negative				
7460	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Yes	W2	Metal	Gray	None	0	0	Negative				
7460	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Yes	Ceiling	Concrete	White	None	0	0.06	Negative				
7460	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Yes	Floor	Concrete	Gray	None	0	0	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	W1	Concrete	White	None	0	0.02	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	W1	Metal	White	None	0	0.04	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	W1	Metal	White	None	0	0	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	W1	Wood	Blue	None	0	0	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	W2	Concrete	White	None	0	0	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	W3	Brick	White	None	0	0.05	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	W3	Metal	White	None	0	0.01	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	W4	Brick	White	None	0	0.01	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	Ceiling	Metal	White	None	0	0.08	Negative				
7460	1	1	103Q	Service Closets	Custodial Closet at entrance to Boy's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103R	Pipe Chase	Custodial Closet at entrance to Boy's Restroom Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103R	Pipe Chase	Custodial Closet at entrance to Boy's Restroom Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103R	Pipe Chase	Custodial Closet at entrance to Boy's Restroom Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103R	Pipe Chase	Custodial Closet at entrance to Boy's Restroom Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103R	Pipe Chase	Custodial Closet at entrance to Boy's Restroom Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	103R	Pipe Chase	Custodial Closet at entrance to Boy's Restroom Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A				
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	W1	Metal	White	Friction	1	0.02	Negative				
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	W1	Metal	White	Friction	1	0	Negative				
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	W1	Wood	Blue	None	0	0	Negative				
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A				

				Inspection Dates: 12/13-12/17, 12/20,and 12/22				Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Craig Gratz/006207									
				Inspection Company: Criterion									
				Zeigler School									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	W3	Metal	Gray	Cracking	2	0	Negative
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	W3	Metal	Gray	None	0	0	Negative
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	W4	Metal	Gray	None	0	0	Negative
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	Ceiling	Concrete	White	None	0	0.16	Negative
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	Ceiling	Metal	White	None	0	0.06	Negative
7460	1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 107	Yes	Floor	Concrete	Gray	None	0	0	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W1	Concrete	Gray	None	0	0.14	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W1	Metal	White	None	0	0.03	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W1	Wood	Blue	None	0	0	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W2	Sheetrock	Green	None	0	0	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W3	Concrete	White	None	0	0.07	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W3	Metal	Gray	None	0	0	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W4	Concrete	Gray	None	0	0.04	Negative
7460	1	1	103	Primary	Classroom 107	Yes	W4	Metal	White	None	0	0.26	Negative
7460	1	1	103	Primary	Classroom 107	Yes	Ceiling	Concrete	White	None	0	0.12	Negative
7460	1	1	103	Primary	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	101	Health Service Room	Nurse's Office 108	Yes	W1	Concrete	White	None	0	0.03	Negative
7460	1	1	101	Health Service Room	Nurse's Office 108	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	101	Health Service Room	Nurse's Office 108	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	101	Health Service Room	Nurse's Office 108	Yes	W2	Concrete	White	None	0	0	Negative
7460	1	1	101	Health Service Room	Nurse's Office 108	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	1	1	101	Health Service Room	Nurse's Office 108	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	1	1	101	Health Service Room	Nurse's Office 108	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	101	Health Service Room	Nurse's Office 108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	101A	Health Service Room	Nurse's Office 108 Exam Room	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	1	1	101A	Health Service Room	Nurse's Office 108 Exam Room	Yes	W2	Sheetrock	White	None	0	0	Negative
7460	1	1	101A	Health Service Room	Nurse's Office 108 Exam Room	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	1	1	101A	Health Service Room	Nurse's Office 108 Exam Room	Yes	W4	Concrete	White	None	0	0	Negative
7460	1	1	101A	Health Service Room	Nurse's Office 108 Exam Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	101A	Health Service Room	Nurse's Office 108 Exam Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	101C	Student Restrooms - Male/Female (Classroom)	Nurse's Office 108 Restroom	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	101C	Student Restrooms - Male/Female (Classroom)	Nurse's Office 108 Restroom	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	101C	Student Restrooms - Male/Female (Classroom)	Nurse's Office 108 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	101C	Student Restrooms - Male/Female (Classroom)	Nurse's Office 108 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	101C	Student Restrooms - Male/Female (Classroom)	Nurse's Office 108 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/13-12/17, 12/20,and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	1	101C	Student Restrooms - Male/Female (Classroom)	Nurse's Office 108 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	101C	Student Restrooms - Male/Female (Classroom)	Nurse's Office 108 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	109	Primary	Classroom 109	Yes	W1	Sheetrock	Gray	None	0	0	Negative
7460	1	1	109	Primary	Classroom 109	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	109	Primary	Classroom 109	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	109	Primary	Classroom 109	Yes	W2	Concrete	White	None	0	0	Negative
7460	1	1	109	Primary	Classroom 109	Yes	W3	Concrete	White	None	0	0	Negative
7460	1	1	109	Primary	Classroom 109	Yes	W3	Concrete	Black	None	0	0.01	Negative
7460	1	1	109	Primary	Classroom 109	Yes	W4	Concrete	White	None	0	0	Negative
7460	1	1	109	Primary	Classroom 109	Yes	W4	Metal	White	None	0	0.3	Negative
7460	1	1	109	Primary	Classroom 109	Yes	Ceiling	Concrete	White	None	0	0.1	Negative
7460	1	1	109	Primary	Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	W1	Metal	White	None	0	0	Negative
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	W2	Metal	Gray	Chipping	2	0	Negative
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	W2	Metal	Gray	None	0	0	Negative
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	W4	Metal	White	None	0	0	Negative
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	W4	Metal	White	None	0	0	Negative
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	Ceiling	Concrete	White	None	0	0.07	Negative
7460	1	1	S2	Stairs	Stairwell 1-A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W1	Brick	White	Cracking	6	0.04	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W1	Brick	Gray	None	0	0.07	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W1	Concrete	Gray	None	0	0.03	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W1	Metal	Gray	None	0	0	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W1	Metal	Gray	None	0	0	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W2	Brick	White	Cracking	5	0.05	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W2	Brick	Gray	None	0	0.02	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W3	Brick	White	Cracking	8	0.1	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W3	Brick	Gray	None	0	0.07	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W3	Concrete	Gray	None	0	0.02	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W3	Metal	Gray	None	0	0.14	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	Ceiling	Metal	White	Cracking	10	0.07	Negative
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	Floor	Concrete	Brown	None	0	0	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22							Lead Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Craig Gratz/006207											
				Inspection Company: Criterion											
				Zeigler School											
ULCS#	E l e m e n t	F l o o r	Space #	Space Type		Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)		
7460	1	1	S1	Stairs	Stairwell to Boiler Room across from Classroom 103 Stairs 1-B	Yes	Floor	Concrete	Brown	None	0	0	Negative		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	Yes	W2	Sheetrock	White	None	0	0	Negative		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	yes	W2	Metal	White	None	0	0	Negative		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	yes	W2	Metal	White	None	0	0	Negative		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	Yes	W3	Metal	White	Chipping	1	0.02	Negative		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	Yes	W4	Metal	Gray	None	0	N/A	N/A		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	yes	W4	Metal	Gray	None	0	0	Negative		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	Yes	Ceiling	Concrete	White	None	0	0.07	Negative		
7460	1	1	S3	Stairs	Stairwell adjacent to Classroom 104 Stairs 1-C	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W1	Concrete	White	None	0	0	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W2	Metal	White	None	0	0	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W2	Sheetrock	Red	None	0	0	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W3	Metal	Red	None	0	0.02	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W3	Concrete	White	None	0	0	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W3	Concrete	Red	None	0	0	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W4	Sheetrock	White	None	0	0	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W4	Metal	White	None	0	0	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	W4	Metal	White	None	0	0.01	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	Ceiling	Concrete	Gray	None	0	0.09	Negative		
7460	1	1	H01	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W1	Sheetrock	White	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W1	Metal	Blue	None	0	0.05	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W2	Sheetrock	Black	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W2	Metal	White	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W2	Metal	White	None	0	0.01	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W3	Sheetrock	Green	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W3	Metal	Blue	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W4	Concrete	Blue	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	W4	Metal	White	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	Ceiling	Sheetrock	Grey	None	0	0	Negative		
7460	1	1	H01A	Circulation (Hallway)	Hallway from Main Entrance to Element 2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	1	111	Primary	Classroom 111	Yes	W1	Sheetrock	White	None	0	0	Negative		
7460	2	1	111	Primary	Classroom 111	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	1	111	Primary	Classroom 111	Yes	W2	Sheetrock	White	None	0	0	Negative		
7460	2	1	111	Primary	Classroom 111	yes	W3	Sheetrock	Yellow	None	0	0	Negative		
7460	2	1	111	Primary	Classroom 111	Yes	W3	Sheetrock	Purple	None	0	0	Negative		
7460	2	1	111	Primary	Classroom 111	Yes	W4	Sheetrock	Purple	None	0	0	Negative		
7460	2	1	111	Primary	Classroom 111	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	1	111	Primary	Classroom 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	1	112	Primary	Classroom 112	Yes	W1	Sheetrock	Purple	None	0	0	Negative		
7460	2	1	112	Primary	Classroom 112	Yes	W1	Sheetrock	White	None	0	0	Negative		
7460	2	1	112	Primary	Classroom 112	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	1	112	Primary	Classroom 112	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	1	112	Primary	Classroom 112	Yes	W2	Sheetrock	Purple	None	0	0	Negative		
7460	2	1	112	Primary	Classroom 112	Yes	W3	Sheetrock	Yellow	None	0	0	Negative		
7460	2	1	112	Primary	Classroom 112	Yes	W3	Sheetrock	Purple	None	0	0	Negative		

				Inspection Dates: 12/13-12/17, 12/20,and 12/22				Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Craig Gratz/006207				Zeigler School					
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	2	1	112	Primary	Classroom 112	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	2	1	112	Primary	Classroom 112	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	112	Primary	Classroom 112	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	113	Primary	Classroom 113	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	1	113	Primary	Classroom 113	Yes	W1	Metal	White	Chipping	1	0	Negative
7460	2	1	113	Primary	Classroom 113	Yes	W1	Metal	White	Friction	1	0	Negative
7460	2	1	113	Primary	Classroom 113	Yes	W2	Sheetrock	White	None	0	0	Negative
7460	2	1	113	Primary	Classroom 113	Yes	W3	Sheetrock	Green	None	0	0	Negative
7460	2	1	113	Primary	Classroom 113	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	2	1	113	Primary	Classroom 113	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	113	Primary	Classroom 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	114	Primary	Classroom 114	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	1	114	Primary	Classroom 114	Yes	W1	Metal	White	Chipping	1	0.01	Negative
7460	2	1	114	Primary	Classroom 114	Yes	W1	Metal	White	Chipping	1	0	Negative
7460	2	1	114	Primary	Classroom 114	Yes	W2	Sheetrock	Pink	None	0	0	Negative
7460	2	1	114	Primary	Classroom 114	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	1	114	Primary	Classroom 114	Yes	W4	Sheetrock	Pink	None	0	0	Negative
7460	2	1	114	Primary	Classroom 114	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	114	Primary	Classroom 114	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	115	Primary	Classroom 115	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	1	115	Primary	Classroom 115	Yes	W1	Metal	White	Chipping	2	0	Negative
7460	2	1	115	Primary	Classroom 115	Yes	W1	Metal	White	Friction	1	0	Negative
7460	2	1	115	Primary	Classroom 115	Yes	W2	Sheetrock	White	None	0	0	Negative
7460	2	1	115	Primary	Classroom 115	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	1	115	Primary	Classroom 115	Yes	W4	Sheetrock	Gray	None	0	0	Negative
7460	2	1	115	Primary	Classroom 115	Yes	Ceiling	N/A	N/A	N/A	N/A	0	Negative
7460	2	1	115	Primary	Classroom 115	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	116	Primary	Classroom 116	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	1	116	Primary	Classroom 116	Yes	W1	Metal	White	None	0	0.01	Negative
7460	2	1	116	Primary	Classroom 116	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	116	Primary	Classroom 116	Yes	W2	Sheetrock	Gray	None	0	0	Negative
7460	2	1	116	Primary	Classroom 116	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	1	116	Primary	Classroom 116	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	2	1	116	Primary	Classroom 116	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	116	Primary	Classroom 116	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	117	Primary	Classroom 117	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	1	117	Primary	Classroom 117	Yes	W1	Metal	White	Friction	1	0	Negative
7460	2	1	117	Primary	Classroom 117	Yes	W1	Metal	White	Friction	1	0	Negative
7460	2	1	117	Primary	Classroom 117	Yes	W2	Sheetrock	White	None	0	0.01	Negative
7460	2	1	117	Primary	Classroom 117	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	1	117	Primary	Classroom 117	Yes	W4	Sheetrock	Gray	None	0	0	Negative
7460	2	1	117	Primary	Classroom 117	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	117	Primary	Classroom 117	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	1G	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 117	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	1G	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 117	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	1G	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 117	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	1G	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 117	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/13-12/17, 12/20,and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	2	1	1G	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 117	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	1G	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 117	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	1G	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 117	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	118	Mechanical Room	Elevator Mechanical Room across from Classroom 117	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	118	Mechanical Room	Elevator Mechanical Room across from Classroom 117	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	118	Mechanical Room	Elevator Mechanical Room across from Classroom 117	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	118	Mechanical Room	Elevator Mechanical Room across from Classroom 117	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	118	Mechanical Room	Elevator Mechanical Room across from Classroom 117	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	118	Mechanical Room	Elevator Mechanical Room across from Classroom 117	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	1B	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 117	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	1B	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 117	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	1B	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 117	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	1B	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 117	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	1B	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 117	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	1B	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 117	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	1B	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 117	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W1	Metal	Gray	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W2	Sheetrock	Red	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W2	Sheetrock	Gray	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W2	Metal	White	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W2	Metal	Gray	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W3	Sheetrock	Red	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W3	Sheetrock	Gray	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W3	Metal	White	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W4	Sheetrock	Red	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W4	Metal	Gray	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W4	Metal	White	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	W4	Sheetrock	Gray	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	Ceiling	Sheetrock	Gray	None	0	0	Negative
7460	2	1	H2	Circulation (Hallway)	Hallway from Classroom 112 to the Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	W1	Concrete	Red	None	0	0	Negative
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	W1	Concrete	Gray	None	0	0	Negative
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	W1	Metal	Gray	None	0	0	Negative
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	W2	Concrete	Gray	None	0	0	Negative
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	W3	Concrete	Gray	None	0	0	Negative
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	W4	Concrete	Gray	None	0	0	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22							Lead Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Craig Gratz/006207											
				Inspection Company: Criterion											
				Zeigler School											
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)		
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	W4	Metal	Gray	None	0	0	Negative		
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	W4	Metal	White	None	0	0	Negative		
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	Ceiling	Sheetrock	White	None	0	0	Negative		
7460	2	1	S1-D	Stairs	Stairwell 1-D next to the Gym	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W1	Concrete	White	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W1	Concrete	Gray	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W2	Concrete	White	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W2	Concrete	Gray	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W3	Concrete	White	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W3	Concrete	Gray	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W4	Concrete	White	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W4	Concrete	Gray	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	W4	Metal	White	None	0	0	Negative		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120	Gymnasium - Intermediate Middle	Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	1	120A	Storage	Gym Storage Room	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120A	Storage	Gym Storage Room	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120A	Storage	Gym Storage Room	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120A	Storage	Gym Storage Room	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120A	Storage	Gym Storage Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120A	Storage	Gym Storage Room	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120B	Administrative Office	Gym Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120B	Administrative Office	Gym Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120B	Administrative Office	Gym Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120B	Administrative Office	Gym Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120B	Administrative Office	Gym Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120B	Administrative Office	Gym Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120C	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120C	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120C	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120C	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120C	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	120C	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	1	H3	Circulation (Hallway)	Hallway from the Gym to the IMC	Yes	W1	Sheetrock	Blue	None	0	0	Negative		

				Inspection Dates: 12/13-12/17, 12/20,and 12/22				Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207				Zeigler School						
				Inspection Company: Criterion										
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
7460	2	1	H3	Circulation (Hallway)	Hallway from the Gym to the IMC	Yes	W2	Sheetrock	Red	None	0	0	Negative	
7460	2	1	H3	Circulation (Hallway)	Hallway from the Gym to the IMC	Yes	W3	Sheetrock	Blue	None	0	0	Negative	
7460	2	1	H3	Circulation (Hallway)	Hallway from the Gym to the IMC	Yes	W2	Metal	White	None	0	0	Negative	
7460	2	1	H3	Circulation (Hallway)	Hallway from the Gym to the IMC	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	H3	Circulation (Hallway)	Hallway from the Gym to the IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	W1	Sheetrock	Blue	None	0	0	Negative	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	W1	Metal	Blue	None	0	0	Negative	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	W2	Sheetrock	Blue	None	0	0	Negative	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	W2	Metal	White	None	0	0	Negative	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	W2	Metal	White	None	0	0	Negative	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	W3	Sheetrock	Red	None	0	0	Negative	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	W3	Metal	Blue	None	0	0	Negative	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	W4	Sheetrock	Blue	None	0	0	Negative	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	H4	Circulation (Hallway)	Hallway in Front of the IMC leading to the Auditorium/Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	125	Primary	Classroom 125 adjacent to Auditorium/Cafeteria	Yes	W1	Sheetrock	White	None	0	0	Negative	
7460	2	1	125	Primary	Classroom 125 adjacent to Auditorium/Cafeteria	Yes	W1	Metal	White	None	0	0	Negative	
7460	2	1	125	Primary	Classroom 125 adjacent to Auditorium/Cafeteria	Yes	W1	Metal	White	None	0	0	Negative	
7460	2	1	125	Primary	Classroom 125 adjacent to Auditorium/Cafeteria	Yes	W2	Sheetrock	White	None	0	0	Negative	
7460	2	1	125	Primary	Classroom 125 adjacent to Auditorium/Cafeteria	Yes	W3	Sheetrock	White	None	0	0	Negative	
7460	2	1	125	Primary	Classroom 125 adjacent to Auditorium/Cafeteria	Yes	W4	Sheetrock	White	None	0	0	Negative	
7460	2	1	125	Primary	Classroom 125 adjacent to Auditorium/Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	125	Primary	Classroom 125 adjacent to Auditorium/Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	127	Electrical Room	Electrical Room adjacent to Classroom 125	No	W1	Sheetrock	White	None	0	0	Negative	
7460	2	1	127	Electrical Room	Electrical Room adjacent to Classroom 125	No	W1	Metal	White	None	0	0	Negative	
7460	2	1	127	Electrical Room	Electrical Room adjacent to Classroom 125	No	W1	Metal	White	None	0	0	Negative	
7460	2	1	127	Electrical Room	Electrical Room adjacent to Classroom 125	No	W2	Sheetrock	White	None	0	0	Negative	
7460	2	1	127	Electrical Room	Electrical Room adjacent to Classroom 125	No	W3	Sheetrock	White	None	0	0	Negative	
7460	2	1	127	Electrical Room	Electrical Room adjacent to Classroom 125	No	W4	Sheetrock	White	None	0	0	Negative	
7460	2	1	127	Electrical Room	Electrical Room adjacent to Classroom 125	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	127	Electrical Room	Electrical Room adjacent to Classroom 125	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	128	Storage	Security Camera Room across from IMC	Yes	W1	Sheetrock	White	None	0	0	Negative	
7460	2	1	128	Storage	Security Camera Room across from IMC	Yes	W1	Metal	White	None	0	0	Negative	
7460	2	1	128	Storage	Security Camera Room across from IMC	Yes	W1	Metal	White	None	0	0	Negative	
7460	2	1	128	Storage	Security Camera Room across from IMC	Yes	W2	Sheetrock	White	None	0	0	Negative	
7460	2	1	128	Storage	Security Camera Room across from IMC	Yes	W3	Sheetrock	White	None	0	0	Negative	
7460	2	1	128	Storage	Security Camera Room across from IMC	Yes	W4	Sheetrock	White	None	0	0	Negative	
7460	2	1	128	Storage	Security Camera Room across from IMC	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	128	Storage	Security Camera Room across from IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	1	129	Service Closets	Custodial Closet across from IMC	No	W1	Sheetrock	Gray	None	0	0	Negative	
7460	2	1	129	Service Closets	Custodial Closet across from IMC	No	W1	Metal	White	None	0	0	Negative	
7460	2	1	129	Service Closets	Custodial Closet across from IMC	No	W1	Metal	White	None	0	0	Negative	
7460	2	1	129	Service Closets	Custodial Closet across from IMC	No	W2	Sheetrock	Gray	None	0	0	Negative	

				Inspection Dates: 12/13-12/17, 12/20, and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	2	1	129	Service Closets	Custodial Closet across from IMC	No	W3	Sheetrock	Gray	None	0	0	Negative
7460	2	1	129	Service Closets	Custodial Closet across from IMC	No	W4	Sheetrock	Gray	None	0	0	Negative
7460	2	1	129	Service Closets	Custodial Closet across from IMC	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	129	Service Closets	Custodial Closet across from IMC	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	129A	Service Closets	Custodial Closet across from IMC Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	129A	Service Closets	Custodial Closet across from IMC Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	129A	Service Closets	Custodial Closet across from IMC Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	129A	Service Closets	Custodial Closet across from IMC Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	129A	Service Closets	Custodial Closet across from IMC Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	129A	Service Closets	Custodial Closet across from IMC Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	121	IMC (Library)	IMC	Yes	W1	Sheetrock	Red	None	0	0	Negative
7460	2	1	121	IMC (Library)	IMC	yes	W1	Metal	White	Chipping	2	0	Negative
7460	2	1	121	IMC (Library)	IMC	yes	W1	Metal	White	None	0	0	Negative
7460	2	1	121	IMC (Library)	IMC	yes	W1	Metal	White	None	0	0	Negative
7460	2	1	121	IMC (Library)	IMC	Yes	W2	Sheetrock	Red	None	0	0	Negative
7460	2	1	121	IMC (Library)	IMC	Yes	W3	Sheetrock	Gray	None	0	0	Negative
7460	2	1	121	IMC (Library)	IMC	Yes	W4	Sheetrock	Gray	None	0	0	Negative
7460	2	1	121	IMC (Library)	IMC	yes	W4	Metal	Gray	None	0	0	Negative
7460	2	1	121	IMC (Library)	IMC	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	121	IMC (Library)	IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W1	Concrete	Gray	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W1	Concrete	White	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W1	Metal	White	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W1	Metal	Blue	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W2	Concrete	White	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W2	Concrete	Gray	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W3	Concrete	Gray	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	W4	Concrete	White	None	0	0	Negative
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	123	Auditorium / Cafeteria	Auditorium/Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	122	Stage	Stage	Yes	W1	Concrete	Gray	None	0	0	Negative
7460	2	1	122	Stage	Stage	Yes	W2	Concrete	Gray	None	0	0	Negative
7460	2	1	122	Stage	Stage	Yes	W3	Concrete	Blue	None	0	0	Negative
7460	2	1	122	Stage	Stage	yes	W3	Metal	White	Chipping	2	0.02	Negative
7460	2	1	122	Stage	Stage	Yes	W4	Concrete	Gray	None	0	0	Negative
7460	2	1	122	Stage	Stage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	122	Stage	Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	124	Storage	Side Room off of Stage	Yes	W1	Concrete	Gray	None	0	0	Negative
7460	2	1	124	Storage	Side Room off of Stage	Yes	W1	Metal	White	None		0.03	Negative
7460	2	1	124	Storage	Side Room off of Stage	Yes	W1	Metal	White	None		0.01	Negative
7460	2	1	124	Storage	Side Room off of Stage	Yes	W2	Concrete	Gray	None	0	0	Negative
7460	2	1	124	Storage	Side Room off of Stage	Yes	W3	Concrete	Blue	None	0	0	Negative
7460	2	1	124	Storage	Side Room off of Stage	Yes	W4	Metal	Gray	None	0	0	Negative
7460	2	1	124	Storage	Side Room off of Stage	Yes	W4	N/A	N/A	N/A	N/A	0	Negative
7460	2	1	124	Storage	Side Room off of Stage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	124	Storage	Side Room off of Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126	Kitchen	Kitchen	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126	Kitchen	Kitchen	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126	Kitchen	Kitchen	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126	Kitchen	Kitchen	No	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/13-12/17, 12/20, and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	2	1	126	Kitchen	Kitchen	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126	Kitchen	Kitchen	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126A	Circulation (Hallway)	Hallway in Kitchen	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126A	Circulation (Hallway)	Hallway in Kitchen	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126A	Circulation (Hallway)	Hallway in Kitchen	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126A	Circulation (Hallway)	Hallway in Kitchen	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126A	Circulation (Hallway)	Hallway in Kitchen	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126A	Circulation (Hallway)	Hallway in Kitchen	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126B	Kitchen Office	Kitchen Office	No	W1	Sheetrock	White	None	0	0	Negative
7460	2	1	126B	Kitchen Office	Kitchen Office	no	W1	Metal	White	None	0	0	Negative
7460	2	1	126B	Kitchen Office	Kitchen Office	no	W1	Metal	White	None	0	0	Negative
7460	2	1	126B	Kitchen Office	Kitchen Office	No	W2	Sheetrock	Gray	None	0	0	Negative
7460	2	1	126B	Kitchen Office	Kitchen Office	No	W3	Sheetrock	White	None	0	0	Negative
7460	2	1	126B	Kitchen Office	Kitchen Office	No	W4	Sheetrock	White	None	0	0	Negative
7460	2	1	126B	Kitchen Office	Kitchen Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126B	Kitchen Office	Kitchen Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126C	Storage	Kitchen Storage with Hot Water Heater	No	W1	Sheetrock	White	None	0	0	Negative
7460	2	1	126C	Storage	Kitchen Storage with Hot Water Heater	no	W1	Metal	White	None	0	0	Negative
7460	2	1	126C	Storage	Kitchen Storage with Hot Water Heater	no	W1	Metal	White	None	0	0	Negative
7460	2	1	126C	Storage	Kitchen Storage with Hot Water Heater	No	W2	Sheetrock	White	None	0	0	Negative
7460	2	1	126C	Storage	Kitchen Storage with Hot Water Heater	No	W3	Sheetrock	White	None	0	0	Negative
7460	2	1	126C	Storage	Kitchen Storage with Hot Water Heater	No	W4	Sheetrock	White	None	0	0	Negative
7460	2	1	126C	Storage	Kitchen Storage with Hot Water Heater	No	Ceiling	Metal	White	None	0	0	Negative
7460	2	1	126C	Storage	Kitchen Storage with Hot Water Heater	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126D	Storage	Kitchen Storage	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	126D	Storage	Kitchen Storage	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	126D	Storage	Kitchen Storage	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	126D	Storage	Kitchen Storage	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	126D	Storage	Kitchen Storage	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	126D	Storage	Kitchen Storage	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
7460	2	1	126E	Lockers - Female	Kitchen Staff Locker Room	No	W1	Sheetrock	White	None	0	0	Negative
7460	2	1	126E	Lockers - Female	Kitchen Staff Locker Room	no	W1	Metal	White	None	0	0	Negative
7460	2	1	126E	Lockers - Female	Kitchen Staff Locker Room	no	W1	Metal	White	None	0	0	Negative
7460	2	1	126E	Lockers - Female	Kitchen Staff Locker Room	No	W2	Metal	Blue	None	0	0	Negative
7460	2	1	126E	Lockers - Female	Kitchen Staff Locker Room	No	W3	Sheetrock	White	None	0	0	Negative
7460	2	1	126E	Lockers - Female	Kitchen Staff Locker Room	No	W4	Sheetrock	White	None	0	0	Negative
7460	2	1	126E	Lockers - Female	Kitchen Staff Locker Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126E	Lockers - Female	Kitchen Staff Locker Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126F	Restrooms, Staff - Male/Female	Kitchen Staff Locker Room Restroom	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126F	Restrooms, Staff - Male/Female	Kitchen Staff Locker Room Restroom	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126F	Restrooms, Staff - Male/Female	Kitchen Staff Locker Room Restroom	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126F	Restrooms, Staff - Male/Female	Kitchen Staff Locker Room Restroom	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126F	Restrooms, Staff - Male/Female	Kitchen Staff Locker Room Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126F	Restrooms, Staff - Male/Female	Kitchen Staff Locker Room Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	1	126G	Storage	Kitchen Storage/Slop Sink	No	W1	Sheetrock	Gray	None	0	0	Negative
7460	2	1	126G	Storage	Kitchen Storage/Slop Sink	No	W1	Metal	White	None	0	0.01	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22							Lead Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Craig Gratz/006207											
				Inspection Company: Criterion											
				Zeigler School											
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)		
7460	2	1	126G	Storage	Kitchen Storage/Slop Sink	No	W1	Metal	White	None	0	0	Negative		
7460	2	1	126G	Storage	Kitchen Storage/Slop Sink	No	W2	Concrete	Gray	None	0	0	Negative		
7460	2	1	126G	Storage	Kitchen Storage/Slop Sink	No	W3	Concrete	Gray	None	0	0	Negative		
7460	2	1	126G	Storage	Kitchen Storage/Slop Sink	No	W4	Sheetrock	Gray	None	0	0	Negative		
7460	2	1	126G	Storage	Kitchen Storage/Slop Sink	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	1	126G	Storage	Kitchen Storage/Slop Sink	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	200	Primary	Classroom 201	Yes	W1	Concrete	White	None	0	0	Negative		
7460	1	2	200	Primary	Classroom 201	Yes	W1	Metal	White	Friction	1	0.01	Negative		
7460	1	2	200	Primary	Classroom 201	Yes	W1	Metal	White	Friction	1	0.01	Negative		
7460	1	2	200	Primary	Classroom 201	Yes	W2	Concrete	White	None	0	0.14	Negative		
7460	1	2	200	Primary	Classroom 201	Yes	W3	Concrete	White	None	0	0.01	Negative		
7460	1	2	200	Primary	Classroom 201	Yes	W3	Metal	Tan	Chipping	2	0.03	Negative		
7460	1	2	200	Primary	Classroom 201	Yes	W4	Concrete	Blue	None	0	0	Negative		
7460	1	2	200	Primary	Classroom 201	Yes	Ceiling	Concrete	White	Cracking	3	0.07	Negative		
7460	1	2	200	Primary	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	202	Primary	Classroom 202	Yes	W1	Concrete	White	None	0	0.01	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W1	Metal	White	Friction	1	0.03	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W1	Metal	White	Friction	1	0	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W1	Wood	Blue	None	0	0	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W1	Metal	Blue	None	0	0.04	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W1	Metal	White	None	0	0.02	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W1	Wood	White	None	0	0	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W2	Sheetrock	Blue	None	0	0	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W3	Concrete	Blue	None	0	0.06	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	W4	Concrete	Blue	None	0	0.01	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	Ceiling	Concrete	White	None	0	0.15	Negative		
7460	1	2	202	Primary	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	203D	Primary	Classroom 203	Yes	W1	Concrete	White	None	0	0.05	Negative		
7460	1	2	203D	Primary	Classroom 203	Yes	W1	Metal	White	None	0	0.06	Negative		
7460	1	2	203D	Primary	Classroom 203	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	2	203D	Primary	Classroom 203	Yes	W2	Sheetrock	Pink	None	0	0	Negative		
7460	1	2	203D	Primary	Classroom 203	Yes	W3	Concrete	White	None	0	0.01	Negative		
7460	1	2	203D	Primary	Classroom 203	Yes	W4	Sheetrock	White	None	0	0	Negative		
7460	1	2	203D	Primary	Classroom 203	Yes	Ceiling	Concrete	White	None	0	0.05	Negative		
7460	1	2	203D	Primary	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	204	Primary	Classroom 204	Yes	W1	Concrete	White	None	0	0	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W1	Metal	White	Friction	1	0.18	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W1	Metal	White	Friction	1	0.02	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W1	Wood	Blue	None	0	0	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W1	Metal	Green	None	0	0	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W1	Metal	White	None	0	0.01	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W1	Metal	White	None	0	0.07	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W1	Wood	White	None	0	0	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W2	Concrete	White	None	0	0	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W3	Concrete	White	None	0	0.02	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	W4	Sheetrock	Blue	None	0	0	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	Ceiling	Concrete	White	Cracking	12	0.06	Negative		
7460	1	2	204	Primary	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	206	Primary	Classroom 205	Yes	W1	Concrete	White	None	0	0	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W1	Metal	White	None	0	0.05	Negative		

				Inspection Dates: 12/13-12/17, 12/20,and 12/22							Lead Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Craig Gratz/006207											
				Inspection Company: Criterion											
				Zeigler School											
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)		
7460	1	2	206	Primary	Classroom 205	Yes	W1	Metal	White	None	0	0.02	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W1	Metal	Blue	None	0	0	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W1	Metal	White	None	0	0.02	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W1	Metal	White	None	0	0.06	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W2	Concrete	Blue	None	0	0.02	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W3	Concrete	Blue	None	0	0	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W3	Metal	Tan	None	0	0	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W4	Concrete	Blue	None	0	0.01	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	W4	Metal	Blue	None	0	0.16	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	Ceiling	Concrete	White	Cracking	30	0.03	Negative		
7460	1	2	206	Primary	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	206A	Storage	Classroom 205 Closet	Yes	W1	Concrete	White	None	0	0	Negative		
7460	1	2	206A	Storage	Classroom 205 Closet	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	2	206A	Storage	Classroom 205 Closet	Yes	W2	Concrete	White	None	0	0	Negative		
7460	1	2	206A	Storage	Classroom 205 Closet	Yes	W3	Concrete	White	None	0	0	Negative		
7460	1	2	206A	Storage	Classroom 205 Closet	Yes	W4	Concrete	White	None	0	0	Negative		
7460	1	2	206A	Storage	Classroom 205 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	206A	Storage	Classroom 205 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	205	Primary	Classroom 206	Yes	W1	Concrete	White	None	0	0	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W1	Metal	White	None	0	0.16	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W1	Metal	White	None	0	0.05	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W1	Metal	Blue	None	0	0.01	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W1	Metal	White	None	0	0.02	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W1	Metal	White	None	0	0.01	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W2	Sheetrock	Blue	None	0	0	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W3	Concrete	Blue	None	0	0.03	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W3	Metal	Gray	None	0	0.01	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	W4	Concrete	Blue	None	0	0	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	Ceiling	Concrete	White	None	0	0.01	Negative		
7460	1	2	205	Primary	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	207	Primary	Classroom 207	Yes	W1	Concrete	White	None	0	0	Negative		
7460	1	2	207	Primary	Classroom 207	Yes	W1	Metal	White	None	0	0	Negative		
7460	1	2	207	Primary	Classroom 207	Yes	W1	Metal	White	None	0	0.02	Negative		
7460	1	2	207	Primary	Classroom 207	Yes	W2	Concrete	Blue	None	0	0	Negative		
7460	1	2	207	Primary	Classroom 207	Yes	W3	Concrete	White	None	0	0.04	Negative		
7460	1	2	207	Primary	Classroom 207	Yes	W4	Sheetrock	White	None	0	0	Negative		
7460	1	2	207	Primary	Classroom 207	Yes	Ceiling	Concrete	White	None	0	0.07	Negative		
7460	1	2	207	Primary	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	W1	Concrete	Green	None	0	0.03	Negative		
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	W1	Metal	Green	None	0	0.26	Negative		
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	W1	Metal	Green	None	0	0.05	Negative		
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	W1	Wood	Green	None	0	0	Negative		
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	W2	Concrete	Green	None	0	0.01	Negative		
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	W3	Concrete	Green	None	0	0.03	Negative		
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	W3	Metal	Gray	None	0	0.06	Negative		

				Inspection Dates: 12/13-12/17, 12/20,and 12/22				Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Craig Gratz/006207									
				Inspection Company: Criterion			Zeigler School						
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	W4	Concrete	Green	None	0	0	Negative
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	Ceiling	Concrete	White	None	0	0.08	Negative
7460	1	2	205A	Teacher Lounge/Dining	Teacher's Lounge 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	205B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Teacher's Lounge 208	Yes	W1	Metal	White	None	0	0	Negative
7460	1	2	205B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Teacher's Lounge 208	Yes	W1	Metal	White	None	0	0	Negative
7460	1	2	205B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Teacher's Lounge 208	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	205B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Teacher's Lounge 208	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	205B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Teacher's Lounge 208	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	205B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Teacher's Lounge 208	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	205B	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Teacher's Lounge 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W1	Metal	White	None	0	0.18	Negative
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W1	Metal	White	None	0	0.04	Negative
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W1	Wood	Blue	None	0	0.01	Negative
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W2	Metal	Gray	None		0	Negative
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W3	Metal	Gray	None	0	0.01	Negative
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	Ceiling	Concrete	White	None	0	0	Negative
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	Ceiling	Metal	White	None	0	0.11	Negative
7460	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 204	Yes	Floor	Concrete	Gray	None	0	0	Negative
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	W1	Metal	White	None	0	0.1	Negative
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	W1	Metal	White	None	0	0.07	Negative
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	W1	Wood	Blue	None	0	0	Negative
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/13-12/17, 12/20, and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	Ceiling	Concrete	White	None	0	0.09	Negative
7460	1	2	203A	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 204	Yes	Floor	Concrete	Gray	None	0	0.01	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	W1	Concrete	Gray	None	0	0.03	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	W1	Wood	Blue	None	0	0	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	W1	Metal	White	Friction	1	0.09	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	W1	Metal	White	Friction	1	0.03	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	W2	Concrete	Gray	None	0	0	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	W2	Wood	Gray	None	0	0.02	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	W3	Brick	Gray	None	0	0.01	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	W4	Concrete	Gray	None	0	0	Negative
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	209A	Service Closets	Custodial Closet adjacent to Girl's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	203C	Telecommunication Equipment Room	MDF Computer Server Room 209B	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203C	Telecommunication Equipment Room	MDF Computer Server Room 209B	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203C	Telecommunication Equipment Room	MDF Computer Server Room 209B	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203C	Telecommunication Equipment Room	MDF Computer Server Room 209B	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203C	Telecommunication Equipment Room	MDF Computer Server Room 209B	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203C	Telecommunication Equipment Room	MDF Computer Server Room 209B	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203E	Pipe Chase	MDF Computer Server Room 209B Pipe Chase	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203E	Pipe Chase	MDF Computer Server Room 209B Pipe Chase	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203E	Pipe Chase	MDF Computer Server Room 209B Pipe Chase	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203E	Pipe Chase	MDF Computer Server Room 209B Pipe Chase	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203E	Pipe Chase	MDF Computer Server Room 209B Pipe Chase	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203E	Pipe Chase	MDF Computer Server Room 209B Pipe Chase	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
7460	1	2	203	Primary	Classroom 210	Yes	W1	Concrete	White	None	0	0	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W1	Metal	White	None	0	0.19	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W1	Metal	White	None	0	0.02	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W1	Metal	Tan	None	0	0	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W1	Wood	Blue	None	0	0	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W1	Metal	White	None	0	0.05	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W1	Metal	White	None	0	0.07	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W2	Sheetrock	Blue	None	0	0	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W3	Concrete	White	None	0	0.02	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W3	Metal	Gray	Chipping	2	0.01	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W4	Concrete	White	None	0	0	Negative
7460	1	2	203	Primary	Classroom 210	Yes	W4	Metal	White	None	0	0.12	Negative
7460	1	2	203	Primary	Classroom 210	Yes	Ceiling	Concrete	White	Cracking	3	0	Negative
7460	1	2	203	Primary	Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	2	211	Primary	Classroom 211	Yes	W1	Concrete	Gray	None	0	0.01	Negative
7460	1	2	211	Primary	Classroom 211	Yes	W1	Metal	White	None	0	0	Negative
7460	1	2	211	Primary	Classroom 211	Yes	W1	Metal	White	None	0	0	Negative
7460	1	2	211	Primary	Classroom 211	Yes	W2	Concrete	Gray	None	0	0	Negative
7460	1	2	211	Primary	Classroom 211	Yes	W3	Sheetrock	Gray	None	0	0	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22				Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207										
				Inspection Company: Criterion										
													Zeigler School	
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
7460	1	2	211	Primary	Classroom 211	Yes	W4	Concrete	Gray	None	0	0.03	Negative	
7460	1	2	211	Primary	Classroom 211	Yes	Ceiling	Concrete	Gray	None	0	0.05	Negative	
7460	1	2	211	Primary	Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	201	Primary	Classroom 212	Yes	W1	Sheetrock	Blue	None	0	0	Negative	
7460	1	2	201	Primary	Classroom 212	yes	W1	Metal	White	None	0	0.01	Negative	
7460	1	2	201	Primary	Classroom 212	yes	W1	Metal	White	None	0	0.07	Negative	
7460	1	2	201	Primary	Classroom 212	Yes	W2	Concrete	White	None	0	0	Negative	
7460	1	2	201	Primary	Classroom 212	yes	W2	Metal	White	None	0	0	Negative	
7460	1	2	201	Primary	Classroom 212	yes	W2	Metal	White	None	0	0	Negative	
7460	1	2	201	Primary	Classroom 212	yes	W2	Metal	White	None	0	0	Negative	
7460	1	2	201	Primary	Classroom 212	Yes	W3	Concrete	Red	None	0	0	Negative	
7460	1	2	201	Primary	Classroom 212	Yes	W4	Concrete	White	None	0	0	Negative	
7460	1	2	201	Primary	Classroom 212	yes	W4	Metal	Gray	Chipping	2	0.03	Negative	
7460	1	2	201	Primary	Classroom 212	Yes	Ceiling	Concrete	White	None	0	0.02	Negative	
7460	1	2	201	Primary	Classroom 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W1	Concrete	White	None	0	0.12	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W1	Concrete	Blue	None	0	0.08	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W1	Metal	White	None	0	0.01	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W2	Concrete	White	None	0	0	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W3	Concrete	White	None	0	0	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W3	Metal	Tan	None	0	0	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W3	Wood	Blue	None	0	0	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W3	Metal	White	None	0	0.03	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W4	Sheetrock	White	None	0	0	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W4	Metal	White	None	0	0	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	W4	Metal	White	None	0	0	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	Ceiling	Concrete	White	None	0	0.1	Negative	
7460	1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	W2	Metal	White	None	0	0	Negative	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	W3	Metal	Gray	None	0	0	Negative	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	Ceiling	Concrete	White	None	0	0	Negative	
7460	1	2	2-C	Stairs	Stairwell 2-C	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-A	Stairs	Stairwell 2-A	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-A	Stairs	Stairwell 2-A	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-A	Stairs	Stairwell 2-A	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-A	Stairs	Stairwell 2-A	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
7460	1	2	2-A	Stairs	Stairwell 2-A	Yes	W4	Metal	Blue	None	0	0	Negative	
7460	1	2	2-A	Stairs	Stairwell 2-A	Yes	W4	Metal	White	None	0	0	Negative	
7460	1	2	2-A	Stairs	Stairwell 2-A	Yes	Ceiling	Concrete	White	None	0	0.12	Negative	
7460	1	2	2-A	Stairs	Stairwell 2-A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
7460	2	2	213	Primary	Classroom 213	Yes	W1	Sheetrock	White	None	0	0	Negative	
7460	2	2	213	Primary	Classroom 213	Yes	W1	Sheetrock	Blue	None	0	0	Negative	
7460	2	2	213	Primary	Classroom 213	Yes	W1	Metal	White	Friction	1	0	Negative	
7460	2	2	213	Primary	Classroom 213	Yes	W1	Metal	White	Friction	1	0	Negative	
7460	2	2	213	Primary	Classroom 213	Yes	W2	Sheetrock	Blue	None	0	0	Negative	
7460	2	2	213	Primary	Classroom 213	Yes	W3	Sheetrock	White	None	0	0	Negative	
7460	2	2	213	Primary	Classroom 213	Yes	W4	Sheetrock	Blue	None	0	0	Negative	

				Inspection Dates: 12/13-12/17, 12/20,and 12/22				Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	2	2	213	Primary	Classroom 213	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	213	Primary	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	214	Primary	Classroom 214	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	2	214	Primary	Classroom 214	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	214	Primary	Classroom 214	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	214	Primary	Classroom 214	Yes	W2	Sheetrock	White	None	0	0	Negative
7460	2	2	214	Primary	Classroom 214	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	2	214	Primary	Classroom 214	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	2	2	214	Primary	Classroom 214	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	214	Primary	Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	215	Primary	Classroom 215	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	2	215	Primary	Classroom 215	Yes	W1	Sheetrock	Blue	None	0	0	Negative
7460	2	2	215	Primary	Classroom 215	Yes	W1	Metal	White	None	0	0.01	Negative
7460	2	2	215	Primary	Classroom 215	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	215	Primary	Classroom 215	Yes	W2	Sheetrock	Blue	None	0	0	Negative
7460	2	2	215	Primary	Classroom 215	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	2	215	Primary	Classroom 215	Yes	W4	Sheetrock	Blue	None	0	0	Negative
7460	2	2	215	Primary	Classroom 215	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	215	Primary	Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	216	Primary	Classroom 216	Yes	W1	Sheetrock	Blue	None	0	0	Negative
7460	2	2	216	Primary	Classroom 216	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	2	216	Primary	Classroom 216	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	216	Primary	Classroom 216	Yes	W2	Sheetrock	Blue	None	0	0	Negative
7460	2	2	216	Primary	Classroom 216	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	2	216	Primary	Classroom 216	Yes	W4	Sheetrock	Blue	None	0	0	Negative
7460	2	2	216	Primary	Classroom 216	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	216	Primary	Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	217	Primary	Classroom 217	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	2	217	Primary	Classroom 217	Yes	W1	Sheetrock	Blue	None	0	0	Negative
7460	2	2	217	Primary	Classroom 217	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	217	Primary	Classroom 217	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	217	Primary	Classroom 217	Yes	W2	Sheetrock	Blue	None	0	0	Negative
7460	2	2	217	Primary	Classroom 217	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	2	217	Primary	Classroom 217	Yes	W4	Sheetrock	Blue	None	0	0	Negative
7460	2	2	217	Primary	Classroom 217	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	217	Primary	Classroom 217	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	218	Primary	Classroom 218	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	2	218	Primary	Classroom 218	Yes	W1	Sheetrock	Blue	None	0	0	Negative
7460	2	2	218	Primary	Classroom 218	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	218	Primary	Classroom 218	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	218	Primary	Classroom 218	Yes	W2	Sheetrock	Blue	None	0	0	Negative
7460	2	2	218	Primary	Classroom 218	Yes	W3	Sheetrock	White	None	0	0	Negative
7460	2	2	218	Primary	Classroom 218	Yes	W4	Sheetrock	Blue	None	0	0	Negative
7460	2	2	218	Primary	Classroom 218	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	218	Primary	Classroom 218	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	219	Primary	Classroom 219	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	2	219	Primary	Classroom 219	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	219	Primary	Classroom 219	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	219	Primary	Classroom 219	Yes	W2	Sheetrock	Gray	None	0	0	Negative
7460	2	2	219	Primary	Classroom 219	Yes	W3	Sheetrock	White	None	0	0	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22				Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Craig Gratz/006207									
				Inspection Company: Criterion									
				Zeigler School									
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
7460	2	2	219	Primary	Classroom 219	Yes	W4	Sheetrock	White	None	0	0	Negative
7460	2	2	219	Primary	Classroom 219	Yes	W4	Metal	White	None	0	0	Negative
7460	2	2	219	Primary	Classroom 219	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	219	Primary	Classroom 219	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	219A	Storage	Classroom 219 Storage Closet	Yes	W1	Sheetrock	White	None	0	0	Negative
7460	2	2	219A	Storage	Classroom 219 Storage Closet	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	219A	Storage	Classroom 219 Storage Closet	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	219A	Storage	Classroom 219 Storage Closet	Yes	W2	Sheetrock	White	None	0	0	Negative
7460	2	2	219A	Storage	Classroom 219 Storage Closet	Yes	W3	Concrete	White	None	0	0	Negative
7460	2	2	219A	Storage	Classroom 219 Storage Closet	Yes	W4	Concrete	White	None	0	0	Negative
7460	2	2	219A	Storage	Classroom 219 Storage Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	219A	Storage	Classroom 219 Storage Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	222	Student Restrooms - Female (4-12)	Girl's Restroom across Classroom 219	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	222	Student Restrooms - Female (4-12)	Girl's Restroom across Classroom 219	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	222	Student Restrooms - Female (4-12)	Girl's Restroom across Classroom 219	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	222	Student Restrooms - Female (4-12)	Girl's Restroom across Classroom 219	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	222	Student Restrooms - Female (4-12)	Girl's Restroom across Classroom 219	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	222	Student Restrooms - Female (4-12)	Girl's Restroom across Classroom 219	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	222	Student Restrooms - Female (4-12)	Girl's Restroom across Classroom 219	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	222A	Storage	Girl's Restroom across Classroom 219 Storage Closet	Yes	W1	Sheetrock	Gray	None	0	0	Negative
7460	2	2	222A	Storage	Girl's Restroom across Classroom 219 Storage Closet	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	222A	Storage	Girl's Restroom across Classroom 219 Storage Closet	Yes	W2	Sheetrock	Gray	None	0	0	Negative
7460	2	2	222A	Storage	Girl's Restroom across Classroom 219 Storage Closet	Yes	W3	Sheetrock	Gray	None	0	0	Negative
7460	2	2	222A	Storage	Girl's Restroom across Classroom 219 Storage Closet	Yes	W4	Sheetrock	Gray	None	0	0	Negative
7460	2	2	222A	Storage	Girl's Restroom across Classroom 219 Storage Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	222A	Storage	Girl's Restroom across Classroom 219 Storage Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	223	Storage	Storage Closet adjacent to Boy's Restroom	Yes	W1	Sheetrock	Gray	None	0	0	Negative
7460	2	2	223	Storage	Storage Closet adjacent to Boy's Restroom	Yes	W2	Sheetrock	Gray	None	0	0	Negative
7460	2	2	223	Storage	Storage Closet adjacent to Boy's Restroom	Yes	W3	Sheetrock	Gray	None	0	0	Negative
7460	2	2	223	Storage	Storage Closet adjacent to Boy's Restroom	Yes	W4	Sheetrock	Gray	None	0	0	Negative
7460	2	2	223	Storage	Storage Closet adjacent to Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	223	Storage	Storage Closet adjacent to Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	221	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 219	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	221	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 219	Yes	W1	Metal	White	None	0	0	Negative
7460	2	2	221	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 219	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	221	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 219	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	221	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 219	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	221	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 219	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	221	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 219	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	W1	Sheetrock	Blue	None	0	0	Negative

				Inspection Dates: 12/13-12/17, 12/20,and 12/22							Lead Safe Certification Assessment Report Zeigler School				
				Inspector Name and Certificate Number: Craig Gratz/006207											
				Inspection Company: Criterion											
ULCS#	E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	W2	Sheetrock	White	None	0	0	Negative		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	W2	Metal	White	None	0	0	Negative		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	W2	Metal	White	None	0	0	Negative		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	W3	Sheetrock	Gray	None	0	0	Negative		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	W3	Metal	White	None	0	0	Negative		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	W4	Sheetrock	White	None	0	0	Negative		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	220	Primary	Classroom 220 Computer Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	220A	Administrative Office	Classroom 220 Computer Lab Office	Yes	W1	Sheetrock	Gray	None	0	0	Negative		
7460	2	2	220A	Administrative Office	Classroom 220 Computer Lab Office	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	2	220A	Administrative Office	Classroom 220 Computer Lab Office	Yes	W2	Sheetrock	Gray	None	0	0	Negative		
7460	2	2	220A	Administrative Office	Classroom 220 Computer Lab Office	Yes	W3	Sheetrock	Gray	None	0	0	Negative		
7460	2	2	220A	Administrative Office	Classroom 220 Computer Lab Office	Yes	W3	Metal	White	None	0	0	Negative		
7460	2	2	220A	Administrative Office	Classroom 220 Computer Lab Office	Yes	W4	Sheetrock	Gray	None	0	0	Negative		
7460	2	2	220A	Administrative Office	Classroom 220 Computer Lab Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	220A	Administrative Office	Classroom 220 Computer Lab Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	220B	Mechanical Room	Classroom 220 Computer Lab Office Mechanical Room	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220B	Mechanical Room	Classroom 220 Computer Lab Office Mechanical Room	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220B	Mechanical Room	Classroom 220 Computer Lab Office Mechanical Room	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220B	Mechanical Room	Classroom 220 Computer Lab Office Mechanical Room	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220B	Mechanical Room	Classroom 220 Computer Lab Office Mechanical Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220B	Mechanical Room	Classroom 220 Computer Lab Office Mechanical Room	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220C	Storage	Classroom 220 Computer Lab Closet adjacent to Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220C	Storage	Classroom 220 Computer Lab Closet adjacent to Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220C	Storage	Classroom 220 Computer Lab Closet adjacent to Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220C	Storage	Classroom 220 Computer Lab Closet adjacent to Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220C	Storage	Classroom 220 Computer Lab Closet adjacent to Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220C	Storage	Classroom 220 Computer Lab Closet adjacent to Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access		
7460	2	2	220D	Storage	Classroom 220 Computer Lab Storage Closet Front of Room near Windows	Yes	W1	Sheetrock	White	None	0	0	Negative		
7460	2	2	220D	Storage	Classroom 220 Computer Lab Storage Closet Front of Room near Windows	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	2	220D	Storage	Classroom 220 Computer Lab Storage Closet Front of Room near Windows	Yes	W1	Metal	White	None	0	0	Negative		
7460	2	2	220D	Storage	Classroom 220 Computer Lab Storage Closet Front of Room near Windows	Yes	W2	Sheetrock	White	None	0	0	Negative		
7460	2	2	220D	Storage	Classroom 220 Computer Lab Storage Closet Front of Room near Windows	Yes	W3	Sheetrock	White	None	0	0	Negative		
7460	2	2	220D	Storage	Classroom 220 Computer Lab Storage Closet Front of Room near Windows	Yes	W4	Sheetrock	White	None	0	0	Negative		
7460	2	2	220D	Storage	Classroom 220 Computer Lab Storage Closet Front of Room near Windows	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		

				Inspection Dates: 12/13-12/17, 12/20,and 12/22							Lead Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Craig Gratz/006207											
				Inspection Company: Criterion											
				Zeigler School											
ULCS#	E l e m e n t	F l o o r	Space #	Space Type		Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)		
7460	2	2	220D	Storage	Classroom 220 Computer Lab Storage Closet Front of Room near Windows	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W1	Metal	Gray	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W2	Sheetrock	Blue	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W2	Sheetrock	Yellow	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W2	Metal	Blue	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W2	Metal	White	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W3	Sheetrock	Blue	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W3	Sheetrock	Yellow	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W4	Sheetrock	Blue	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W4	Sheetrock	Yellow	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W2	Metal	Blue	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	W2	Metal	Yellow	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	Ceiling	Sheetrock	Gray	None	0	0	Negative		
7460	2	2	H23	Circulation (Hallway)	Hallway from Classrooms 213 to 220	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W1	Concrete	Gray	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W1	Concrete	Red	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W2	Concrete	Blue	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W2	Metal	Black	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W3	Concrete	Gray	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W3	Metal	Gray	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W4	Concrete	Gray	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W4	Metal	Gray	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W4	Metal	White	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	W4	Metal	Gray	None	0	0	Negative		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	D2	Stairs	Stairwell 2-D adjacent to Classroom 219	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	E1	Elevators, Passenger	Elevator	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	E1	Elevators, Passenger	Elevator	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	E1	Elevators, Passenger	Elevator	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	E1	Elevators, Passenger	Elevator	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	E1	Elevators, Passenger	Elevator	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	2	2	E1	Elevators, Passenger	Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	BS	001A	Storage	Crawl Space in Mechanical Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	BS	001A	Storage	Crawl Space in Mechanical Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	BS	001A	Storage	Crawl Space in Mechanical Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	BS	001A	Storage	Crawl Space in Mechanical Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	BS	001A	Storage	Crawl Space in Mechanical Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	BS	001A	Storage	Crawl Space in Mechanical Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	AT	AT1	Attic	Attic - None	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	AT	AT1	Attic	Attic - None	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	AT	AT1	Attic	Attic - None	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	AT	AT1	Attic	Attic - None	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	AT	AT1	Attic	Attic - None	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	AT	AT1	Attic	Attic - None	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	W3	Concrete	Tan	Cracking	10	0	Negative		
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	W3	Concrete	Tan	Cracking	12	0.01	Negative		
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	W3	Metal	Gray	None	0	0	Negative		
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	W3	Metal	Gray	None	0	0	Negative		
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	W3	Metal	Gray	None	0	0	Negative		
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	W3	Metal	Gray	None	0	0	Negative		

				Inspection Dates: 12/13-12/17, 12/20, and 12/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Craig Gratz/006207			Zeigler School						
				Inspection Company: Criterion									
ULCS#	Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	W3	Metal	Gray	None	0	0	Negative
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway (Rear of Element 1 Building)	Yes	W3	Metal	Black	Cracking	20	1.8	Positive
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7460	1	EX	Exterior	Building Exterior	Exterior- Front	Yes	W1	Metal	Blue	None	0	0	Negative
7460	1	EX	Exterior	Building Exterior	Exterior- Front	Yes	W1	Metal	Blue	None	0	0	Negative
7460	1	EX	Exterior	Building Exterior	Exterior- Front	Yes	W1	Metal	Green	None	0	0	Negative
7460	1	EX	Exterior	Building Exterior	Exterior- Side	Yes	W4	Metal	Blue	Cracking	12	0	Negative
7460	1	EX	Exterior	Building Exterior	Exterior- Side	Yes	W4	Metal	Blue	None	0	0	Negative
7460	1	EX	Exterior	Building Exterior	Exterior- Side	Yes	W4	Metal	Black	Chipping	2	0	Negative
7460	1	EX	Exterior	Building Exterior	Exterior Vent at Driveway	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A