

2/28/22 - 3/7/22					Lead Safe Certification Assessment Report							
Inspector Name and Certificate Number: Charles Rhodes 003452					Catharine Annex (Headstart)							
Inspection Company: BATA					6900 Greenway Avenue, Philadelphia, PA 19142							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1251	1	1	BR	Boiler Room	no	W1	Concrete	White	Flaking	30	0.3	Negative
1251	1	1	BR	Boiler Room	no	Door	Metal	Grey	Chipping	5	0.1	Negative
1251	1	1	BR	Boiler Room	no	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1251	1	1	BR	Boiler Room	no	Boiler	Metal	Grey	Flaking	7	0.2	Negative
1251	1	1	BR	Boiler Room	no	Boiler Accumulator	Metal	Red	Chipping	2	0.1	Negative
1251	1	1	BR	Boiler Room	no	W2	Concrete	White	Flaking	30	0.3	Negative
1251	1	1	BR	Boiler Room	no	W3	Concrete	White	Flaking	30	0.3	Negative
1251	1	1	BR	Boiler Room	no	W3	Brick	White	Flaking	4	0.1	Negative
1251	1	1	BR	Boiler Room	no	Door	Metal	Grey	Chipping	5	0.1	Negative
1251	1	1	BR	Boiler Room	no	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1251	1	1	BR	Boiler Room	no	W4	Concrete	White	None	0	N/A	N/A
1251	1	1	BR	Boiler Room	no	Ceiling	Concrete	White	Flaking	5	0.3	Negative
1251	1	1	BR	Boiler Room	no	Floor	Concrete	Grey	Chipping	10	0.1	Negative
1251	1	1	FP1	Fire Protection/Storage Room	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	FP1	Fire Protection/Storage Room	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	FP1	Fire Protection/Storage Room	yes	W3	Sheetrock	Tan	Efflorescence	4	0.2	Negative
1251	1	1	FP1	Fire Protection/Storage Room	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	FP1	Fire Protection/Storage Room	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	FP1	Fire Protection/Storage Room	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	ST1	Storage Room next to Electrical Room	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	ST1	Storage Room next to Electrical Room	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	ST1	Storage Room next to Electrical Room	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	ST1	Storage Room next to Electrical Room	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	ST1	Storage Room next to Electrical Room	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	ST1	Storage Room next to Electrical Room	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	E1	Electrical Room	no	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	E1	Electrical Room	no	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	E1	Electrical Room	no	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	E1	Electrical Room	no	W4	Sheetrock	Tan	Moisture Damage	25	0.1	Negative
1251	1	1	E1	Electrical Room	no	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	E1	Electrical Room	no	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	100	Office 100	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	100	Office 100	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	100	Office 100	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	100	Office 100	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	100	Office 100	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	100	Office 100	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	100A	Office 100 Restroom	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	100A	Office 100 Restroom	yes	Door Frame	Metal	Blue	Friction	2	0.1	Negative
1251	1	1	100A	Office 100 Restroom	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	100A	Office 100 Restroom	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	100A	Office 100 Restroom	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	100A	Office 100 Restroom	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	100A	Office 100 Restroom	yes	Floor	N/A	N/A	None	0	N/A	N/A

2/28/22 - 3/7/22					Lead Safe Certification Assessment Report							
Inspector Name and Certificate Number: Charles Rhodes 003452					Catharine Annex (Headstart)							
Inspection Company: BATA					6900 Greenway Avenue, Philadelphia, PA 19142							
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1251	1	1	101	Office 101	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	101	Office 101	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	101	Office 101	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	101	Office 101	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	101	Office 101	yes	Ceiling above Drop	Concrete	White	Flaking	1	1.3	Positive
1251	1	1	101	Office 101	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	RR11	Staff Restroom across from Office 103	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	RR11	Staff Restroom across from Office 103	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	RR11	Staff Restroom across from Office 103	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	RR11	Staff Restroom across from Office 103	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	RR11	Staff Restroom across from Office 103	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	RR11	Staff Restroom across from Office 103	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	S11	Stairwell next to Office 103	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	S11	Stairwell next to Office 103	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	S11	Stairwell next to Office 103	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	S11	Stairwell next to Office 103	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	S11	Stairwell next to Office 103	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	S11	Stairwell next to Office 103	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	S13	Stairwell next to Classroom 102	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	S13	Stairwell next to Classroom 102	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	S13	Stairwell next to Classroom 102	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	S13	Stairwell next to Classroom 102	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	S13	Stairwell next to Classroom 102	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	S13	Stairwell next to Classroom 102	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	AHU1	HVAC Closet outside of Office 103	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	AHU1	HVAC Closet outside of Office 103	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	AHU1	HVAC Closet outside of Office 103	no	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	AHU1	HVAC Closet outside of Office 103	no	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	AHU1	HVAC Closet outside of Office 103	no	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	AHU1	HVAC Closet outside of Office 103	no	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	103	Office 103	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	103	Office 103	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	103	Office 103	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	103	Office 103	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	103	Office 103	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	103	Office 103	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	105	Office 105	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	105	Office 105	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	105	Office 105	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	105	Office 105	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	105	Office 105	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	105	Office 105	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Office 106	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Office 106	yes	W2	N/A	N/A	None	0	N/A	N/A

2/28/22 - 3/7/22					Lead Safe Certification Assessment Report							
Inspector Name and Certificate Number: Charles Rhodes 003452					Catharine Annex (Headstart)							
Inspection Company: BATA					6900 Greenway Avenue, Philadelphia, PA 19142							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1251	1	1	106	Office 106	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Office 106	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Office 106	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Office 106	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL2	Elevator Mechanical Room	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL2	Elevator Mechanical Room	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL2	Elevator Mechanical Room	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL2	Elevator Mechanical Room	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL2	Elevator Mechanical Room	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL2	Elevator Mechanical Room	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	102	Kindergarten Classroom 102	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	102	Kindergarten Classroom 102	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	102	Kindergarten Classroom 102	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	102	Kindergarten Classroom 102	yes	W4	Sheetrock	Blue	Chipping	24	0.2	Negative
1251	1	1	102	Kindergarten Classroom 102	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	102	Kindergarten Classroom 102	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	KRR	Restroom between Kindergarten Classrooms 102 and 104	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	KRR	Restroom between Kindergarten Classrooms 102 and 104	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	KRR	Restroom between Kindergarten Classrooms 102 and 104	yes	Partition	Metal	Tan	Flaking	17	0.2	Negative
1251	1	1	KRR	Restroom between Kindergarten Classrooms 102 and 104	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	KRR	Restroom between Kindergarten Classrooms 102 and 104	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	KRR	Restroom between Kindergarten Classrooms 102 and 104	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	KRR	Restroom between Kindergarten Classrooms 102 and 104	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	104	Kindergarten Classroom 104	yes	W1	Sheetrock	Tan	Flaking	2	0.2	Negative
1251	1	1	104	Kindergarten Classroom 104	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	104	Kindergarten Classroom 104	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	104	Kindergarten Classroom 104	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	104	Kindergarten Classroom 104	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	104	Kindergarten Classroom 104	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL1	Elevator	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL1	Elevator	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL1	Elevator	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL1	Elevator	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL1	Elevator	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	EL1	Elevator	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	107	Storage Room 107	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	107	Storage Room 107	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	107	Storage Room 107	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	107	Storage Room 107	yes	W4	N/A	N/A	None	0	N/A	N/A

				2/28/22 - 3/7/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003452		Catharine Annex (Headstart)						
				Inspection Company: BATA		6900 Greenway Avenue, Philadelphia, PA 19142						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1251	1	1	107	Storage Room 107	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	107	Storage Room 107	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	107A	Storage Room 107 Restroom	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	107A	Storage Room 107 Restroom	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	107A	Storage Room 107 Restroom	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	107A	Storage Room 107 Restroom	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	107A	Storage Room 107 Restroom	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	107A	Storage Room 107 Restroom	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	S14	Stairwell next to Classroom 104	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	S14	Stairwell next to Classroom 104	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	S14	Stairwell next to Classroom 104	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	S14	Stairwell next to Classroom 104	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	S14	Stairwell next to Classroom 104	yes	Ceiling	Sheetrock	White	Efflorescence	8	0.7	Positive
1251	1	1	S14	Stairwell next to Classroom 104	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	S12	Stairwell next to Cafeteria 109	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	S12	Stairwell next to Cafeteria 109	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	S12	Stairwell next to Cafeteria 109	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	S12	Stairwell next to Cafeteria 109	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	S12	Stairwell next to Cafeteria 109	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	S12	Stairwell next to Cafeteria 109	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	109	Cafeteria 109	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	109	Cafeteria 109	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	109	Cafeteria 109	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	109	Cafeteria 109	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	109	Cafeteria 109	yes	Ceiling above Drop	Concrete	N/A	None	0	N/A	N/A
1251	1	1	109	Cafeteria 109	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	109A	Cafeteria 109 Electrical Closet	no	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	109A	Cafeteria 109 Electrical Closet	no	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	109A	Cafeteria 109 Electrical Closet	no	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	109A	Cafeteria 109 Electrical Closet	no	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	109A	Cafeteria 109 Electrical Closet	no	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	109A	Cafeteria 109 Electrical Closet	no	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Kitchen 106	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Kitchen 106	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Kitchen 106	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Kitchen 106	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Kitchen 106	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	106	Kitchen 106	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	1	H11	First Floor Hallway	yes	W1	Sheetrock	Tan	Friction	5	0.2	Negative
1251	1	1	H11	First Floor Hallway	yes	W2	Sheetrock	Tan	Efflorescence	2	0.2	Negative
1251	1	1	H11	First Floor Hallway	yes	Corner Guard	Wood	White	Impact	2	0.1	Negative
1251	1	1	H11	First Floor Hallway	yes	Corner Guard	Wood	White	Impact	3	0	Negative
1251	1	1	H11	First Floor Hallway	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	1	H11	First Floor Hallway	yes	Door Frame	Metal	Blue	Impact	4	0.4	Negative

2/28/22 - 3/7/22				Lead Safe Certification Assessment Report								
Inspector Name and Certificate Number: Charles Rhodes 003452				Catharine Annex (Headstart)								
Inspection Company: BATA				6900 Greenway Avenue, Philadelphia, PA 19142								
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1251	1	1	H11	First Floor Hallway	yes	W4	Sheetrock	Tan	Efflorescence	1	0.2	Negative
1251	1	1	H11	First Floor Hallway	yes	Corner Guard	Wood	White	Impact	4	0	Negative
1251	1	1	H11	First Floor Hallway	yes	Corner Guard	Wood	White	Impact	1	0.1	Negative
1251	1	1	H11	First Floor Hallway	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	1	H11	First Floor Hallway	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	H21	Second Floor Hallway	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	H21	Second Floor Hallway	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	H21	Second Floor Hallway	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	H21	Second Floor Hallway	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	H21	Second Floor Hallway	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	H21	Second Floor Hallway	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	200	Truancy Court Waiting Room 200	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	200	Truancy Court Waiting Room 200	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	200	Truancy Court Waiting Room 200	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	200	Truancy Court Waiting Room 200	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	200	Truancy Court Waiting Room 200	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	200	Truancy Court Waiting Room 200	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	200A	Truancy Court Waiting Room 200 Closet	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	200A	Truancy Court Waiting Room 200 Closet	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	200A	Truancy Court Waiting Room 200 Closet	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	200A	Truancy Court Waiting Room 200 Closet	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	200A	Truancy Court Waiting Room 200 Closet	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	200A	Truancy Court Waiting Room 200 Closet	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	200B	Truancy Court Waiting Room 200 Restroom	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	200B	Truancy Court Waiting Room 200 Restroom	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	200B	Truancy Court Waiting Room 200 Restroom	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	200B	Truancy Court Waiting Room 200 Restroom	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	200B	Truancy Court Waiting Room 200 Restroom	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	200B	Truancy Court Waiting Room 200 Restroom	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	201	Truancy Court Conference Room 201	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	201	Truancy Court Conference Room 201	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	201	Truancy Court Conference Room 201	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	201	Truancy Court Conference Room 201	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	201	Truancy Court Conference Room 201	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	201	Truancy Court Conference Room 201	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	202	Truancy Court Trial Room 202	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	202	Truancy Court Trial Room 202	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	202	Truancy Court Trial Room 202	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	202	Truancy Court Trial Room 202	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	202	Truancy Court Trial Room 202	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	202	Truancy Court Trial Room 202	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	203	Truancy Court Office 203	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	203	Truancy Court Office 203	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	203	Truancy Court Office 203	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	203	Truancy Court Office 203	yes	W4	N/A	N/A	None	0	N/A	N/A

				2/28/22 - 3/7/22		Lead Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Charles Rhodes 003452		Catharine Annex (Headstart)							
				Inspection Company: BATA		6900 Greenway Avenue, Philadelphia, PA 19142							
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1251	1	2	203	Truancy Court Office 203	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	203	Truancy Court Office 203	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	H22	Truancy Court Hallway	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	H22	Truancy Court Hallway	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	H22	Truancy Court Hallway	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	H22	Truancy Court Hallway	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	H22	Truancy Court Hallway	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	H22	Truancy Court Hallway	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S21	Main Entrance Vestibule and Stairwell next to Truancy Court	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S21	Main Entrance Vestibule and Stairwell next to Truancy Court	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S21	Main Entrance Vestibule and Stairwell next to Truancy Court	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S21	Main Entrance Vestibule and Stairwell next to Truancy Court	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S21	Main Entrance Vestibule and Stairwell next to Truancy Court	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S21	Main Entrance Vestibule and Stairwell next to Truancy Court	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S23	Stairwell across from Office 205	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S23	Stairwell across from Office 205	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S23	Stairwell across from Office 205	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S23	Stairwell across from Office 205	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S23	Stairwell across from Office 205	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	S23	Stairwell across from Office 205	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	RR21	Staff Restroom across from Office 207	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	RR21	Staff Restroom across from Office 207	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	RR21	Staff Restroom across from Office 207	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	RR21	Staff Restroom across from Office 207	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	RR21	Staff Restroom across from Office 207	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	RR21	Staff Restroom across from Office 207	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205	Office 205	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205	Office 205	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205	Office 205	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205	Office 205	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205	Office 205	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205	Office 205	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205A	Office 205 Closet	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205A	Office 205 Closet	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205A	Office 205 Closet	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205A	Office 205 Closet	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205A	Office 205 Closet	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	205A	Office 205 Closet	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	AHU2	HVAC Closet outside of Office 205	no	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	AHU2	HVAC Closet outside of Office 205	no	W2	N/A	N/A	None	0	N/A	N/A	

2/28/22 - 3/7/22				Lead Safe Certification Assessment Report									
Inspector Name and Certificate Number: Charles Rhodes 003452				Catharine Annex (Headstart)									
Inspection Company: BATA				6900 Greenway Avenue, Philadelphia, PA 19142									
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1251	1	2	AHU2	HVAC Closet outside of Office 205	no	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	AHU2	HVAC Closet outside of Office 205	no	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	AHU2	HVAC Closet outside of Office 205	no	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	AHU2	HVAC Closet outside of Office 205	no	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	206	Office 206	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	206	Office 206	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	206	Office 206	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	206	Office 206	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	206	Office 206	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	206	Office 206	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	207	Office 207	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	207	Office 207	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	207	Office 207	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	207	Office 207	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	207	Office 207	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	207	Office 207	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	JC1	Janitor's Closet across from Office 208	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	2	JC1	Janitor's Closet across from Office 208	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	2	JC1	Janitor's Closet across from Office 208	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	2	JC1	Janitor's Closet across from Office 208	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	2	JC1	Janitor's Closet across from Office 208	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	2	JC1	Janitor's Closet across from Office 208	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	2	208	Office 208	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208	Office 208	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208	Office 208	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208	Office 208	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208	Office 208	yes	Ceiling above Drop	Concrete	N/A	None	0	N/A	N/A	
1251	1	2	208	Office 208	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208A	IT MDF Room inside Office 208	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208A	IT MDF Room inside Office 208	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208A	IT MDF Room inside Office 208	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208A	IT MDF Room inside Office 208	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208A	IT MDF Room inside Office 208	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	208A	IT MDF Room inside Office 208	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	209	Classroom 209	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	209	Classroom 209	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	209	Classroom 209	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	209	Classroom 209	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	209	Classroom 209	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	209	Classroom 209	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	210	Office 210	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	210	Office 210	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	210	Office 210	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	210	Office 210	yes	W4	N/A	N/A	None	0	N/A	N/A	

2/28/22 - 3/7/22					Lead Safe Certification Assessment Report							
Inspector Name and Certificate Number: Charles Rhodes 003452					Catharine Annex (Headstart)							
Inspection Company: BATA					6900 Greenway Avenue, Philadelphia, PA 19142							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1251	1	2	210	Office 210	yes	Ceiling above Drop	Concrete	N/A	None	0	N/A	N/A
1251	1	2	210	Office 210	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	210A	Office 210 Closet	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	210A	Office 210 Closet	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	210A	Office 210 Closet	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	210A	Office 210 Closet	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	210A	Office 210 Closet	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	210A	Office 210 Closet	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	AHU4	HVAC Closet outside of Office 210	no	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	AHU4	HVAC Closet outside of Office 210	no	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	AHU4	HVAC Closet outside of Office 210	no	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	AHU4	HVAC Closet outside of Office 210	no	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	AHU4	HVAC Closet outside of Office 210	no	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	AHU4	HVAC Closet outside of Office 210	no	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	S24	Stairwell across from Classroom 209	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	S24	Stairwell across from Classroom 209	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	S24	Stairwell across from Classroom 209	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	S24	Stairwell across from Classroom 209	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	S24	Stairwell across from Classroom 209	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	S24	Stairwell across from Classroom 209	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	S22	Stairwell next to Kitchen 211	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	S22	Stairwell next to Kitchen 211	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	S22	Stairwell next to Kitchen 211	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	S22	Stairwell next to Kitchen 211	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	S22	Stairwell next to Kitchen 211	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	S22	Stairwell next to Kitchen 211	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	M2	Men's Staff Restroom next to Kitchen 212	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	M2	Men's Staff Restroom next to Kitchen 212	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	M2	Men's Staff Restroom next to Kitchen 212	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	M2	Men's Staff Restroom next to Kitchen 212	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	M2	Men's Staff Restroom next to Kitchen 212	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	M2	Men's Staff Restroom next to Kitchen 212	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	W2	Women's Staff Restroom next to Kitchen 212	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	W2	Women's Staff Restroom next to Kitchen 212	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	W2	Women's Staff Restroom next to Kitchen 212	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	W2	Women's Staff Restroom next to Kitchen 212	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	W2	Women's Staff Restroom next to Kitchen 212	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	W2	Women's Staff Restroom next to Kitchen 212	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	2	H23	Vestibule outside Staff Restrooms by Room 212	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	2	H23	Vestibule outside Staff Restrooms by Room 212	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	2	H23	Vestibule outside Staff Restrooms by Room 212	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	2	H23	Vestibule outside Staff Restrooms by Room 212	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	2	H23	Vestibule outside Staff Restrooms by Room 212	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	2	H23	Vestibule outside Staff Restrooms by Room 212	yes	Floor	N/A	N/A	None	0	N/A	N/A

2/28/22 - 3/7/22					Lead Safe Certification Assessment Report								
Inspector Name and Certificate Number: Charles Rhodes 003452					Catharine Annex (Headstart)								
Inspection Company: BATA					6900 Greenway Avenue, Philadelphia, PA 19142								
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1251	1	2	211	Kitchen 211	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	211	Kitchen 211	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	211	Kitchen 211	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	211	Kitchen 211	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	211	Kitchen 211	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	211	Kitchen 211	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	212	Kitchen 212	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	212	Kitchen 212	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	212	Kitchen 212	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	212	Kitchen 212	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	212	Kitchen 212	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	212	Kitchen 212	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	213	Classroom 213	yes	W1	Sheetrock	Blue	Chipping	13	0.2	Negative	
1251	1	2	213	Classroom 213	yes	W2	Sheetrock	Tan	Flaking	2	0.3	Negative	
1251	1	2	213	Classroom 213	yes	W3	Sheetrock	Tan	Chipping	5	0.1	Negative	
1251	1	2	213	Classroom 213	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	213	Classroom 213	yes	Ceiling above Drop	Concrete	N/A	None	0	N/A	N/A	
1251	1	2	213	Classroom 213	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	2	213A	Storage Closet inside Classroom 213	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	2	213A	Storage Closet inside Classroom 213	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	2	213A	Storage Closet inside Classroom 213	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	2	213A	Storage Closet inside Classroom 213	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	2	213A	Storage Closet inside Classroom 213	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	2	213A	Storage Closet inside Classroom 213	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H31	Third Floor Hallway	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H31	Third Floor Hallway	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H31	Third Floor Hallway	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H31	Third Floor Hallway	yes	W4	Sheetrock	Tan	Moisture Damage	5	0.2	Negative	
1251	1	3	H31	Third Floor Hallway	yes	Radiator	Metal	Tan	Flaking	1	0.2	Negative	
1251	1	3	H31	Third Floor Hallway	yes	Ceiling above	Concrete	N/A	None	0	N/A	N/A	
1251	1	3	H31	Third Floor Hallway	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S31	Stairwell next to Classroom 322	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S31	Stairwell next to Classroom 322	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S31	Stairwell next to Classroom 322	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S31	Stairwell next to Classroom 322	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S31	Stairwell next to Classroom 322	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S31	Stairwell next to Classroom 322	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S32	Stairwell next to Classroom 326	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S32	Stairwell next to Classroom 326	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S32	Stairwell next to Classroom 326	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S32	Stairwell next to Classroom 326	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S32	Stairwell next to Classroom 326	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	S32	Stairwell next to Classroom 326	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	FT31	Center Fire Tower	yes	W1	N/A	N/A	None	0	N/A	N/A	

				2/28/22 - 3/7/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003452		Catharine Annex (Headstart)						
				Inspection Company: BATA		6900 Greenway Avenue, Philadelphia, PA 19142						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1251	1	3	FT31	Center Fire Tower	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	3	FT31	Center Fire Tower	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	3	FT31	Center Fire Tower	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	3	FT31	Center Fire Tower	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	3	FT31	Center Fire Tower	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	3	320	Classroom 320	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	3	320	Classroom 320	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	3	320	Classroom 320	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	3	320	Classroom 320	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	3	320	Classroom 320	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	3	320	Classroom 320	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	3	320A	Classroom 320 Restroom	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	3	320A	Classroom 320 Restroom	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	3	320A	Classroom 320 Restroom	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	3	320A	Classroom 320 Restroom	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	3	320A	Classroom 320 Restroom	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	3	320A	Classroom 320 Restroom	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	3	321	Office 321	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	3	321	Office 321	yes	W2	Sheetrock	Tan	Moisture Damage	2	0.1	Negative
1251	1	3	321	Office 321	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	3	321	Office 321	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	3	321	Office 321	yes	Ceiling above Drop	Concrete	N/A	None	0	N/A	N/A
1251	1	3	321	Office 321	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	3	H32	Hallway to Classrooms 320-321	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	3	H32	Hallway to Classrooms 320-321	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	3	H32	Hallway to Classrooms 320-321	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	3	H32	Hallway to Classrooms 320-321	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	3	H32	Hallway to Classrooms 320-321	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	3	H32	Hallway to Classrooms 320-321	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	3	322	Classroom 322	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	3	322	Classroom 322	yes	Door Frame	Metal	Blue	Chipping	1	0.2	Negative
1251	1	3	322	Classroom 322	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	3	322	Classroom 322	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	3	322	Classroom 322	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	3	322	Classroom 322	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	3	322	Classroom 322	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	3	B31	Boy's Restroom next to Classroom 323	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	3	B31	Boy's Restroom next to Classroom 323	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	3	B31	Boy's Restroom next to Classroom 323	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	3	B31	Boy's Restroom next to Classroom 323	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	3	B31	Boy's Restroom next to Classroom 323	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	3	B31	Boy's Restroom next to Classroom 323	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	3	G31	Girl's Restroom next to Classroom 323	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	3	G31	Girl's Restroom next to Classroom 323	yes	W2	N/A	N/A	None	0	N/A	N/A

2/28/22 - 3/7/22					Lead Safe Certification Assessment Report								
Inspector Name and Certificate Number: Charles Rhodes 003452					Catharine Annex (Headstart)								
Inspection Company: BATA					6900 Greenway Avenue, Philadelphia, PA 19142								
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1251	1	3	G31	Girl's Restroom next to Classroom 323	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	G31	Girl's Restroom next to Classroom 323	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	G31	Girl's Restroom next to Classroom 323	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	G31	Girl's Restroom next to Classroom 323	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	323	Classroom 323	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	323	Classroom 323	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	323	Classroom 323	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	323	Classroom 323	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	323	Classroom 323	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	323	Classroom 323	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	J31	Janitor's Closet next to Classroom 324	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	3	J31	Janitor's Closet next to Classroom 324	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	3	J31	Janitor's Closet next to Classroom 324	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	3	J31	Janitor's Closet next to Classroom 324	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	3	J31	Janitor's Closet next to Classroom 324	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	3	J31	Janitor's Closet next to Classroom 324	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	3	324	Classroom 324	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	324	Classroom 324	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	324	Classroom 324	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	324	Classroom 324	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	324	Classroom 324	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	324	Classroom 324	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	E31	Classroom 324 Electrical Room	no	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	E31	Classroom 324 Electrical Room	no	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	E31	Classroom 324 Electrical Room	no	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	E31	Classroom 324 Electrical Room	no	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	E31	Classroom 324 Electrical Room	no	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	E31	Classroom 324 Electrical Room	no	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	325	Classroom 325	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	325	Classroom 325	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	325	Classroom 325	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	325	Classroom 325	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	325	Classroom 325	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	325	Classroom 325	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	RR31	Staff Restroom next to Classroom 325	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	RR31	Staff Restroom next to Classroom 325	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	RR31	Staff Restroom next to Classroom 325	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	RR31	Staff Restroom next to Classroom 325	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	RR31	Staff Restroom next to Classroom 325	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	RR31	Staff Restroom next to Classroom 325	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	326	Classroom 326	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	326	Classroom 326	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	326	Classroom 326	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	326	Classroom 326	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	326	Classroom 326	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	

2/28/22 - 3/7/22					Lead Safe Certification Assessment Report								
Inspector Name and Certificate Number: Charles Rhodes 003452					Catharine Annex (Headstart)								
Inspection Company: BATA					6900 Greenway Avenue, Philadelphia, PA 19142								
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1251	1	3	326	Classroom 326	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327	Classroom 327	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327	Classroom 327	yes	Door Frame	Metal	Blue	Chipping	3	0.2	Negative	
1251	1	3	327	Classroom 327	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327	Classroom 327	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327	Classroom 327	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327	Classroom 327	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327	Classroom 327	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327A	Classroom 327 Restroom	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327A	Classroom 327 Restroom	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327A	Classroom 327 Restroom	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327A	Classroom 327 Restroom	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327A	Classroom 327 Restroom	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	327A	Classroom 327 Restroom	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	328	Office 328	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	328	Office 328	yes	Door Frame	Metal	Blue	Chipping	1	0.2	Negative	
1251	1	3	328	Office 328	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	328	Office 328	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	328	Office 328	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	328	Office 328	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	328	Office 328	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H33	Hallway to Classrooms 327-328	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H33	Hallway to Classrooms 327-328	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H33	Hallway to Classrooms 327-328	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H33	Hallway to Classrooms 327-328	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H33	Hallway to Classrooms 327-328	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	3	H33	Hallway to Classrooms 327-328	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	4	H41	Fourth Floor Hallway	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	4	H41	Fourth Floor Hallway	yes	W2	Sheetrock	Tan	Impact	1	0	Negative	
1251	1	4	H41	Fourth Floor Hallway	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	4	H41	Fourth Floor Hallway	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	4	H41	Fourth Floor Hallway	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	4	H41	Fourth Floor Hallway	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S41	Stairwell next to Classroom 400	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S41	Stairwell next to Classroom 400	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S41	Stairwell next to Classroom 400	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S41	Stairwell next to Classroom 400	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S41	Stairwell next to Classroom 400	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S41	Stairwell next to Classroom 400	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S42	Stairwell next to Classroom 405	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S42	Stairwell next to Classroom 405	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S42	Stairwell next to Classroom 405	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S42	Stairwell next to Classroom 405	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S42	Stairwell next to Classroom 405	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	4	S42	Stairwell next to Classroom 405	yes	Floor	N/A	N/A	None	0	N/A	N/A	

2/28/22 - 3/7/22					Lead Safe Certification Assessment Report								
Inspector Name and Certificate Number: Charles Rhodes 003452					Catharine Annex (Headstart)								
Inspection Company: BATA					6900 Greenway Avenue, Philadelphia, PA 19142								
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1251	1	4	400	Classroom 400	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	4	400	Classroom 400	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	4	400	Classroom 400	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	4	400	Classroom 400	yes	Door	Metal	Grey	Flaking	5	0.1	Negative	
1251	1	4	400	Classroom 400	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	4	400	Classroom 400	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	4	400	Classroom 400	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	4	B41	Boy's Restroom next to Classroom 401	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	4	B41	Boy's Restroom next to Classroom 401	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	4	B41	Boy's Restroom next to Classroom 401	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	4	B41	Boy's Restroom next to Classroom 401	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	4	B41	Boy's Restroom next to Classroom 401	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	4	B41	Boy's Restroom next to Classroom 401	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	4	G41	Girl's Restroom next to Classroom 401	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	4	G41	Girl's Restroom next to Classroom 401	yes	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	4	G41	Girl's Restroom next to Classroom 401	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	4	G41	Girl's Restroom next to Classroom 401	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	4	G41	Girl's Restroom next to Classroom 401	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	4	G41	Girl's Restroom next to Classroom 401	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	4	401	Classroom 401	yes	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	4	401	Classroom 401	yes	W2	Sheetrock	Tan	Chipping	2	0.2	Negative	
1251	1	4	401	Classroom 401	yes	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	4	401	Classroom 401	yes	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	4	401	Classroom 401	yes	Ceiling above Drop	Concrete	N/A	None	0	N/A	N/A	
1251	1	4	401	Classroom 401	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	4	J41	Janitor's Closet next to Classroom 403	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	4	J41	Janitor's Closet next to Classroom 403	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	4	J41	Janitor's Closet next to Classroom 403	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	4	J41	Janitor's Closet next to Classroom 403	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	4	J41	Janitor's Closet next to Classroom 403	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	4	J41	Janitor's Closet next to Classroom 403	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1251	1	4	403	Classroom 403	yes	W1	Sheetrock	Tan	Flaking	8	0.2	Negative	
1251	1	4	403	Classroom 403	yes	Door Frame	Metal	Blue	Chipping	6	0.1	Negative	
1251	1	4	403	Classroom 403	yes	Central Column	Sheetrock	Tan	Chipping	19	0.3	Negative	
1251	1	4	403	Classroom 403	yes	W2	Sheetrock	Tan	Flaking	12	0.3	Negative	
1251	1	4	403	Classroom 403	yes	W3	Sheetrock	Tan	Flaking	13	0.2	Negative	
1251	1	4	403	Classroom 403	yes	W4	Sheetrock	Tan	Flaking	16	0.3	Negative	
1251	1	4	403	Classroom 403	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	
1251	1	4	403	Classroom 403	yes	Floor	N/A	N/A	None	0	N/A	N/A	
1251	1	4	E41	Classroom 403 Electrical Room	no	W1	N/A	N/A	None	0	N/A	N/A	
1251	1	4	E41	Classroom 403 Electrical Room	no	W2	N/A	N/A	None	0	N/A	N/A	
1251	1	4	E41	Classroom 403 Electrical Room	no	W3	N/A	N/A	None	0	N/A	N/A	
1251	1	4	E41	Classroom 403 Electrical Room	no	W4	N/A	N/A	None	0	N/A	N/A	
1251	1	4	E41	Classroom 403 Electrical Room	no	Ceiling	N/A	N/A	None	0	N/A	N/A	

				2/28/22 - 3/7/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003452		Catharine Annex (Headstart)						
				Inspection Company: BATA		6900 Greenway Avenue, Philadelphia, PA 19142						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1251	1	4	E41	Classroom 403 Electrical Room	no	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	4	404	Classroom 404	yes	W1	Sheetrock	Tan	Chipping	8	0.2	Negative
1251	1	4	404	Classroom 404	yes	Door Frame	Metal	Blue	Chipping	9	0.1	Negative
1251	1	4	404	Classroom 404	yes	Central Column	Sheetrock	Tan	Impact	17	0.2	Negative
1251	1	4	404	Classroom 404	yes	W2	Sheetrock	Tan	Moisture Damage	13	0.2	Negative
1251	1	4	404	Classroom 404	yes	W3	Sheetrock	Tan	Flaking	22	0.2	Negative
1251	1	4	404	Classroom 404	yes	W4	Sheetrock	Tan	Chipping	23	0.2	Negative
1251	1	4	404	Classroom 404	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	4	404	Classroom 404	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	4	RR41	Staff Restroom next to Classroom 404	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	4	RR41	Staff Restroom next to Classroom 404	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	4	RR41	Staff Restroom next to Classroom 404	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	4	RR41	Staff Restroom next to Classroom 404	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	4	RR41	Staff Restroom next to Classroom 404	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	4	RR41	Staff Restroom next to Classroom 404	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	4	405	Classroom 405	yes	W1	Sheetrock	Grey	Chipping	2	0.2	Negative
1251	1	4	405	Classroom 405	yes	Door Frame	Metal	Blue	Chipping	3	0.1	Negative
1251	1	4	405	Classroom 405	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	4	405	Classroom 405	yes	Windowsill Trim	Wood	White	Chipping	12	0	Negative
1251	1	4	405	Classroom 405	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	4	405	Classroom 405	yes	Windowsill Trim	Wood	White	Chipping	6	0	Negative
1251	1	4	405	Classroom 405	yes	Access Door to Roof	Metal	Grey	Chipping	8	0.1	Negative
1251	1	4	405	Classroom 405	yes	W4	Sheetrock	Grey	Impact	1	0.2	Negative
1251	1	4	405	Classroom 405	yes	Door Frame	Metal	Blue	Chipping	3	0.2	Negative
1251	1	4	405	Classroom 405	yes	Ceiling above Drop	Concrete	N/A	None	0	N/A	N/A
1251	1	4	405	Classroom 405	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	4	405A	Classroom 405 Restroom	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	4	405A	Classroom 405 Restroom	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	4	405A	Classroom 405 Restroom	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	4	405A	Classroom 405 Restroom	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	4	405A	Classroom 405 Restroom	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	4	405A	Classroom 405 Restroom	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	4	406	Office 406	yes	W1	N/A	N/A	None	0	N/A	N/A
1251	1	4	406	Office 406	yes	W2	N/A	N/A	None	0	N/A	N/A
1251	1	4	406	Office 406	yes	W3	N/A	N/A	None	0	N/A	N/A
1251	1	4	406	Office 406	yes	W4	N/A	N/A	None	0	N/A	N/A
1251	1	4	406	Office 406	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
1251	1	4	406	Office 406	yes	Floor	N/A	N/A	None	0	N/A	N/A
1251	1	A	RF	Roof	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1251	1	A	RF	Roof	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1251	1	A	RF	Roof	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1251	1	A	RF	Roof	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1251	1	A	RF	Roof	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

				2/28/22 - 3/7/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003452		Catharine Annex (Headstart)						
				Inspection Company: BATTA		6900 Greenway Avenue, Philadelphia, PA 19142						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1251	1	A	RF	Roof	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access