

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8310	1	2	205A	Classroom 205B	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	205A	Classroom 205B	Yes	Door Frame	Metal	Grey	Chipping	2	0.3	Negative
8310	1	2	205A	Classroom 205B	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	205A	Classroom 205B	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	205A	Classroom 205B	Yes	Univent/Shelf	Metal	Grey	Chipping	2	0.1	Negative
8310	1	2	205A	Classroom 205B	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	205A	Classroom 205B	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	205A	Classroom 205B	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	205	Classroom 205A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	205	Classroom 205A	Yes	Door Frame	Metal	Grey	Chipping	2	0.6	Negative
8310	1	2	205	Classroom 205A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	205	Classroom 205A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	205	Classroom 205A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	205	Classroom 205A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	205	Classroom 205A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	205SC1	Storage Closet next to 205A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	205SC1	Storage Closet next to 205A	Yes	Door Frame	Metal	Green	Chipping	3	0.5	Negative
8310	1	2	205SC1	Storage Closet next to 205A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	205SC1	Storage Closet next to 205A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	205SC1	Storage Closet next to 205A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	205SC1	Storage Closet next to 205A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	205SC1	Storage Closet next to 205A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	SC1	Storage Closet next to Stairwell 2	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	SC1	Storage Closet next to Stairwell 2	Yes	Door Frame	Metal	Green	Chipping	3	0.5	Negative
8310	1	2	SC1	Storage Closet next to Stairwell 2	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	SC1	Storage Closet next to Stairwell 2	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	SC1	Storage Closet next to Stairwell 2	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	SC1	Storage Closet next to Stairwell 2	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	SC1	Storage Closet next to Stairwell 2	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XA	Classroom 205A - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XA	Classroom 205A - Left Closet	Yes	Door Frame	Metal	Beige	Friction	2	0.6	Negative
8310	1	2	205XA	Classroom 205A - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XA	Classroom 205A - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XA	Classroom 205A - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XA	Classroom 205A - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XA	Classroom 205A - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XB	Classroom 205A - Middle Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XB	Classroom 205A - Middle Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XB	Classroom 205A - Middle Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XB	Classroom 205A - Middle Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	205XB	Classroom 205A - Middle Closet	Yes	Ceiling	Concrete	White	Chipping	1	0.2	Negative
8310	1	2	205XB	Classroom 205A - Middle Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	Door	Metal	Brown	Chipping	10	0.4	Negative
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	Door	Metal	Beige	Chipping	5	0.4	Negative
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	Railing	Metal	Gray	Chipping, Friction	5	3.3	Positive

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	204B	Girl's Restroom next to Classroom 205A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	204B	Girl's Restroom next to Classroom 205A	Yes	Door Frame	Metal	Beige	Chipping	5	0.6	Negative
8310	1	2	204B	Girl's Restroom next to Classroom 205A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	204B	Girl's Restroom next to Classroom 205A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	204B	Girl's Restroom next to Classroom 205A	Yes	Univent/Shelf	Metal	Grey	Chipping	4	0.1	Negative
8310	1	2	204B	Girl's Restroom next to Classroom 205A	Yes	W4	Concrete	White	Chipping	1	0.2	Negative
8310	1	2	204B	Girl's Restroom next to Classroom 205A	Yes	Ceiling	Concrete	White	Flaking	15	0.4	Negative
8310	1	2	204B	Girl's Restroom next to Classroom 205A	Yes	Floor	Concrete	Grey	Friction	15	0.4	Negative
8310	1	2	204C	Custodial Closet adjacent to Classroom 205A	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	204C	Custodial Closet adjacent to Classroom 205A	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	204C	Custodial Closet adjacent to Classroom 205A	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	204C	Custodial Closet adjacent to Classroom 205A	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	204C	Custodial Closet adjacent to Classroom 205A	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	204C	Custodial Closet adjacent to Classroom 205A	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	204D	Storage Closet adjacent to Classroom 205A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	204D	Storage Closet adjacent to Classroom 205A	Yes	Door Frame	Metal	Beige	Chipping	5	0.4	Negative
8310	1	2	204D	Storage Closet adjacent to Classroom 205A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	204D	Storage Closet adjacent to Classroom 205A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	204D	Storage Closet adjacent to Classroom 205A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	204D	Storage Closet adjacent to Classroom 205A	Yes	Pipe	Metal	Beige	Moisture Damage	10	0.4	Negative
8310	1	2	204D	Storage Closet adjacent to Classroom 205A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	204D	Storage Closet adjacent to Classroom 205A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	Door Frame	Metal	Grey	Chipping	10	0.1	Negative
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	Door Frame	Metal	Beige	Chipping	1	0.5	Negative
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	Univent	Metal	Grey	Chipping	2	0.1	Negative
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	Ceiling	Concrete	White	Flaking	5	0.3	Negative
8310	1	2	204E	Boy's Restroom next to Classroom 205A	Yes	Floor	Concrete	Grey	Friction	3	0.2	Negative
8310	1	2	204	Classroom 204	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	204	Classroom 204	Yes	Door Frame	Metal	Grey	Chipping	1	0.5	Negative
8310	1	2	204	Classroom 204	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	204	Classroom 204	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	204	Classroom 204	Yes	Univent/Shelf	Metal	Grey	Chipping	10	0	Negative
8310	1	2	204	Classroom 204	Yes	Univent/Shelf	Metal	Brown	Chipping	10	0.3	Negative
8310	1	2	204	Classroom 204	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	204	Classroom 204	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XA	Classroom 204 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XA	Classroom 204 - Left Closet	Yes	Door Frame	Metal	Green	Chipping	4	0.3	Negative
8310	1	2	204XA	Classroom 204 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	204XA	Classroom 204 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XA	Classroom 204 - Left Closet	Yes	Coat Rack	Metal	Beige	Chipping	2	1.5	Positive
8310	1	2	204XA	Classroom 204 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XA	Classroom 204 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XA	Classroom 204 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XB	Classroom 204 - Middle Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XB	Classroom 204 - Middle Closet	Yes	Door Frame	Metal	Green	Chipping	4	0.3	Negative
8310	1	2	204XB	Classroom 204 - Middle Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XB	Classroom 204 - Middle Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XB	Classroom 204 - Middle Closet	Yes	Coat Rack	Metal	Beige	Chipping	2	1.5	Positive
8310	1	2	204XB	Classroom 204 - Middle Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XB	Classroom 204 - Middle Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XB	Classroom 204 - Middle Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XC	Classroom 204 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XC	Classroom 204 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XC	Classroom 204 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XC	Classroom 204 - Right Closet	Yes	Shelf	Wood	Green	Chipping	2	0.4	Negative
8310	1	2	204XC	Classroom 204 - Right Closet	Yes	Rod	Wood	Green	Friction	1	0.3	Negative
8310	1	2	204XC	Classroom 204 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XC	Classroom 204 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	204XC	Classroom 204 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	203	Classroom 203	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	203	Classroom 203	Yes	Door Frame	Metal	Grey	Chipping	1	0.6	Negative
8310	1	2	203	Classroom 203	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	203	Classroom 203	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	203	Classroom 203	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	203	Classroom 203	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	203	Classroom 203	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XD	Classroom 203 - Corner Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XD	Classroom 203 - Corner Closet	Yes	Door Frame	Metal	Green	Chipping	4	0.6	Negative
8310	1	2	203XD	Classroom 203 - Corner Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XD	Classroom 203 - Corner Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XD	Classroom 203 - Corner Closet	Yes	Univent/Shelf	Metal	Grey	Chipping	8	0.1	Negative
8310	1	2	203XD	Classroom 203 - Corner Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XD	Classroom 203 - Corner Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XD	Classroom 203 - Corner Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	Door Frame	Metal	Green	Chipping	2	0.5	Negative
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	Shelf	Wood	Green	Chipping	2	0.4	Negative
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	Rod	Wood	Green	Friction	2	0.3	Negative
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XA	Classroom 203 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XB	Classroom 203 - Middle Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	203XB	Classroom 203 - Middle Closet	Yes	Door Frame	Wood	Beige	Chipping	6	0.9	Positive
8310	1	2	203XB	Classroom 203 - Middle Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XB	Classroom 203 - Middle Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XB	Classroom 203 - Middle Closet	Yes	Coat Rack	Metal	Beige	Chipping	8	0.5	Negative
8310	1	2	203XB	Classroom 203 - Middle Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XB	Classroom 203 - Middle Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XB	Classroom 203 - Middle Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XC	Classroom 203 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XC	Classroom 203 - Right Closet	Yes	Door Frame	Wood	Beige	Chipping	6	0.9	Positive
8310	1	2	203XC	Classroom 203 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XC	Classroom 203 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XC	Classroom 203 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XC	Classroom 203 - Right Closet	Yes	Coat Rack	Wood	Beige	Chipping	8	0.5	Negative
8310	1	2	203XC	Classroom 203 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	203XC	Classroom 203 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	Door Frame	Metal	Grey	Chipping	1	0.3	Negative
8310	1	2	202	Classroom 202	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	Univent/Shelf	Metal	Grey	Chipping	4	0	Negative
8310	1	2	202	Classroom 202	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	Ceiling	Concrete	White/Beige	Flaking	2	0.4	Negative
8310	1	2	202	Classroom 202	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	Door Frame	Metal	Black	Chipping	6	0.1	Negative
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	Door Frame	Metal	Black	Chipping	2	0.1	Negative
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	Coat Rack	Metal	Black	Chipping	1	0	Negative
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	Support	Metal	Black	Chipping	2	0.2	Negative
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XA	Classroom 202 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	Door Frame	Metal	Black	Chipping	6	0.1	Negative
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	Door Frame	Metal	Black	Chipping	2	0.1	Negative
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	Coat Rack	Metal	Black	Chipping	1	0	Negative
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	Support	Metal	Black	Chipping	2	0.2	Negative
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XB	Classroom 202 - Middle Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XC	Classroom 202 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XC	Classroom 202 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XC	Classroom 202 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	202XC	Classroom 202 - Right Closet	Yes	Shelf	Wood	Green	Chipping	2	0.6	Negative
8310	1	2	202XC	Classroom 202 - Right Closet	Yes	Coat Rack	Wood	Green	Chipping	1	0.2	Negative
8310	1	2	202XC	Classroom 202 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XC	Classroom 202 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	202XC	Classroom 202 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	Door Frame	Metal	Grey	Chipping	1	0.3	Negative
8310	1	2	202	Classroom 202	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	Univent/Shelf	Metal	Grey	Chipping	4	0	Negative
8310	1	2	202	Classroom 202	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	202	Classroom 202	Yes	Ceiling	Concrete	White/Beige	Flaking	2	0.4	Negative
8310	1	2	202	Classroom 202	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	S21	Stairwell next to Classroom 205 (Stairwell 2)	Yes	Railing	Metal	Gray	Chipping, Friction	4	0.1	Negative
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	Door	Metal	Brown	Chipping	3	0.4	Negative
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	Baseboard	Metal	Gray	Rust, Chipping, Flaking	10	0.3	Negative
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	Door Frame	Metal	Gray	Chipping	10	0.1	Negative
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	Access Panel	Metal	White	Flaking	1	0	Negative
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	Ceiling	Concrete	White	Chipping	1	0.4	Negative
8310	1	2	S20	Stairwell next to Classroom 202 (Stairwell 1)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	201	Classroom 201	Yes	W1	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201	Classroom 201	Yes	Door Frame	Metal	Grey	Chipping	2	0.3	Negative
8310	1	2	201	Classroom 201	Yes	W2	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201	Classroom 201	Yes	W3	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201	Classroom 201	Yes	Univent/Shelf	Metal	Grey	Chipping	4	0.3	Negative
8310	1	2	201	Classroom 201	Yes	W4	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201	Classroom 201	Yes	Ceiling	Concrete	White	Chipping	1	0.4	Negative
8310	1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201A	Classroom 201 - Right Closet	Yes	W1	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201A	Classroom 201 - Right Closet	Yes	Door Frame	Wood	Beige	Chipping	4	0.2	Negative
8310	1	2	201A	Classroom 201 - Right Closet	Yes	W2	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201A	Classroom 201 - Right Closet	Yes	W3	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201A	Classroom 201 - Right Closet	Yes	Coat Rack	Metal	Beige	Chipping	2	15	Positive
8310	1	2	201A	Classroom 201 - Right Closet	Yes	W4	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201A	Classroom 201 - Right Closet	Yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201A	Classroom 201 - Right Closet	Yes	Floor	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201B	Classroom 201 - Left Closet	Yes	W1	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201B	Classroom 201 - Left Closet	Yes	Door Frame	Wood	Beige	Chipping	4	0.2	Negative
8310	1	2	201B	Classroom 201 - Left Closet	Yes	W2	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201B	Classroom 201 - Left Closet	Yes	W3	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201B	Classroom 201 - Left Closet	Yes	Coat Rack	Metal	Beige	Chipping	2	15	Positive
8310	1	2	201B	Classroom 201 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	201B	Classroom 201 - Left Closet	Yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	201B	Classroom 201 - Left Closet	Yes	Floor	N/A	N/A	N/A	0	N/A	N/A
8310	1	2	H22	Hallway next to Classrooms 205 through 201	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	H22	Hallway next to Classrooms 205 through 201	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	H22	Hallway next to Classrooms 205 through 201	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	H22	Hallway next to Classrooms 205 through 201	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	H22	Hallway next to Classrooms 205 through 201	Yes	Ceiling	Concrete	White	Flaking	6	0	Negative
8310	1	2	H22	Hallway next to Classrooms 205 through 201	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	218	Classroom 218	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	218	Classroom 218	Yes	Door Frame	Metal	Grey	Chipping	1	0.6	Negative
8310	1	2	218	Classroom 218	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	218	Classroom 218	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	218	Classroom 218	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	218	Classroom 218	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	218	Classroom 218	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XA	Classroom 218 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XA	Classroom 218 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XA	Classroom 218 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XA	Classroom 218 - Left Closet	Yes	Shelf	Wood	Beige	Chipping	1	0.2	Negative
8310	1	2	218XA	Classroom 218 - Left Closet	Yes	Univent/Shelf	Metal	Grey	Chipping	5	0.1	Negative
8310	1	2	218XA	Classroom 218 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XA	Classroom 218 - Left Closet	Yes	Ceiling	Concrete	White	Flaking	20	0.2	Negative
8310	1	2	218XA	Classroom 218 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XB	Classroom 218 - Middle Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XB	Classroom 218 - Middle Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XB	Classroom 218 - Middle Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XB	Classroom 218 - Middle Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XB	Classroom 218 - Middle Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XB	Classroom 218 - Middle Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XC	Classroom 218 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XC	Classroom 218 - Right Closet	Yes	Door Frame	Metal	Beige	Chipping	6	0.5	Negative
8310	1	2	218XC	Classroom 218 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XC	Classroom 218 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XC	Classroom 218 - Right Closet	Yes	W4	Concrete	White	Flaking	5	0.1	Negative
8310	1	2	218XC	Classroom 218 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	218XC	Classroom 218 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	217	Classroom 217	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	217	Classroom 217	Yes	Door Frame	Metal	Grey	Chipping	2	0.6	Negative
8310	1	2	217	Classroom 217	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	217	Classroom 217	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	217	Classroom 217	Yes	Univent/Shelf	Metal	Grey	Chipping	4	0.1	Negative
8310	1	2	217	Classroom 217	Yes	Univent/Shelf	Metal	Brown	Chipping	10	0.3	Negative
8310	1	2	217	Classroom 217	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	217	Classroom 217	Yes	Ceiling	Concrete	White	Flaking	8	0.1	Negative
8310	1	2	217	Classroom 217	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XA	Classroom 217 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XA	Classroom 217 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	217XA	Classroom 217 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XA	Classroom 217 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XA	Classroom 217 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XA	Classroom 217 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XB	Classroom 217 - Middle Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XB	Classroom 217 - Middle Closet	Yes	Door Frame	Metal	Beige	Chipping	10	0.6	Negative
8310	1	2	217XB	Classroom 217 - Middle Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XB	Classroom 217 - Middle Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XB	Classroom 217 - Middle Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XB	Classroom 217 - Middle Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XB	Classroom 217 - Middle Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XC	Classroom 217 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XC	Classroom 217 - Right Closet	Yes	Door Frame	Metal	Beige	Chipping	10	0.5	Negative
8310	1	2	217XC	Classroom 217 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XC	Classroom 217 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XC	Classroom 217 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XC	Classroom 217 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	217XC	Classroom 217 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	216	Classroom 216	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	216	Classroom 216	Yes	Door Frame	Metal	Grey	Chipping	1	0.6	Negative
8310	1	2	216	Classroom 216	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	216	Classroom 216	Yes	W3	Concrete	White	Flaking	1	0.2	Negative
8310	1	2	216	Classroom 216	Yes	Univent/Shelf	Metal	Grey	Chipping	4	0.1	Negative
8310	1	2	216	Classroom 216	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	216	Classroom 216	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	216	Classroom 216	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XA	Classroom 216 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XA	Classroom 216 - Left Closet	Yes	Door Frame	Metal	Grey	Chipping	1	0.4	Negative
8310	1	2	216XA	Classroom 216 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XA	Classroom 216 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XA	Classroom 216 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XA	Classroom 216 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XA	Classroom 216 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XB	Classroom 216 - Middle Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XB	Classroom 216 - Middle Closet	Yes	Door Frame	Metal	Beige	Chipping	6	0.6	Negative
8310	1	2	216XB	Classroom 216 - Middle Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XB	Classroom 216 - Middle Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XB	Classroom 216 - Middle Closet	Yes	Coat Rack	Wood	Beige	Chipping	6	0.6	Negative
8310	1	2	216XB	Classroom 216 - Middle Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XB	Classroom 216 - Middle Closet	Yes	Ceiling	Concrete	White	Flaking	15	0.2	Negative
8310	1	2	216XB	Classroom 216 - Middle Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XC	Classroom 216 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XC	Classroom 216 - Right Closet	Yes	Door Frame	Metal	Beige	Chipping	6	0.6	Negative
8310	1	2	216XC	Classroom 216 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XC	Classroom 216 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	216XC	Classroom 216 - Right Closet	Yes	Coat Rack	Wood	Beige	Chipping	6	0.6	Negative
8310	1	2	216XC	Classroom 216 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	216XC	Classroom 216 - Right Closet	Yes	Ceiling	Concrete	White	Flaking	15	0.2	Negative
8310	1	2	216XC	Classroom 216 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	215	Classroom 215	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	215	Classroom 215	Yes	Door Frame	Metal	Grey	Chipping	1	0.4	Negative
8310	1	2	215	Classroom 215	Yes	Door Frame	Metal	Beige	Chipping	3	0.4	Negative
8310	1	2	215	Classroom 215	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	215	Classroom 215	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	215	Classroom 215	Yes	Univent/Shelf	Metal	Grey	Chipping	2	0.1	Negative
8310	1	2	215	Classroom 215	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	215	Classroom 215	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	215	Classroom 215	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	219A	Storage Closet to Left of Classroom 215	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	219A	Storage Closet to Left of Classroom 215	Yes	Door Frame	Metal	Green/Grey	Chipping	4	0.5	Negative
8310	1	2	219A	Storage Closet to Left of Classroom 215	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	219A	Storage Closet to Left of Classroom 215	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	219A	Storage Closet to Left of Classroom 215	Yes	Ceiling	Concrete	White	Efflorescence	5	0.1	Negative
8310	1	2	219A	Storage Closet to Left of Classroom 215	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	219A	Storage Closet to Left of Classroom 215	Yes	Ceiling	Concrete	White	Efflorescence	5	0.1	Negative
8310	1	2	219A	Storage Closet to Left of Classroom 215	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	219	Office 219	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	219	Office 219	Yes	Door Frame	Metal	Beige	Chipping	1	0.5	Negative
8310	1	2	219	Office 219	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	219	Office 219	Yes	Univent	Metal	Beige	Chipping	1	0.2	Negative
8310	1	2	219	Office 219	Yes	Window Frame	CMU	Beige	Flaking	6	0.2	Negative
8310	1	2	219	Office 219	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	219	Office 219	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	219	Office 219	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	219	Office 219	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	219B	Staff Restroom in Office 219	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	219B	Staff Restroom in Office 219	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	219B	Staff Restroom in Office 219	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	219B	Staff Restroom in Office 219	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	219B	Staff Restroom in Office 219	Yes	Ceiling	Concrete	White	Efflorescence	5	0.4	Negative
8310	1	2	219B	Staff Restroom in Office 219	Yes	HVAC Exhaust	Metal	White	Flaking	1	0.5	Negative
8310	1	2	219B	Staff Restroom in Office 219	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	214A	Mechanical Room (Former Fan Room/HVAC) to Right of Office 219	No	W1	Concrete	Green	Cracking, Chipping	2	0.2	Negative
8310	1	2	214A	Mechanical Room (Former Fan Room/HVAC) to Right of Office 219	No	Door	Metal	Tan	Chipping	3	0.1	Negative
8310	1	2	214A	Mechanical Room (Former Fan Room/HVAC) to Right of Office 219	No	Door Frame	Metal	Gray	Chipping	1	0.2	Negative
8310	1	2	214A	Mechanical Room (Former Fan Room/HVAC) to Right of Office 219	No	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	214A	Mechanical Room (Former Fan Room/HVAC) to Right of Office 219	No	W3	Concrete	Green	Chipping, Cracking	10	0.2	Negative
8310	1	2	214A	Mechanical Room (Former Fan Room/HVAC) to Right of Office 219	No	W4	N/A	N/A	None	0	N/A	N/A



				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	214A	Mechanical Room (Former Fan Room/HVAC) to Right of Office 219	No	Ceiling	Concrete	White	Efflorescence, Moisture Damage	30	0.1	Negative
8310	1	2	214A	Mechanical Room (Former Fan Room/HVAC) to Right of Office 219	No	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	214	Classroom 214 Library	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	214	Classroom 214 Library	Yes	Door Frame	Metal	Grey/Beige	Chipping	4	0.6	Negative
8310	1	2	214	Classroom 214 Library	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	214	Classroom 214 Library	Yes	Univent/Shelf	Metal	Grey	Friction	8	0.1	Negative
8310	1	2	214	Classroom 214 Library	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	214	Classroom 214 Library	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	214	Classroom 214 Library	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	214	Classroom 214 Library	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	213A	Copy Room near Classroom 213	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	213A	Copy Room near Classroom 213	Yes	Door Frame	Metal	Tan	Chipping	1	0.6	Negative
8310	1	2	213A	Copy Room near Classroom 213	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	213A	Copy Room near Classroom 213	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	213A	Copy Room near Classroom 213	Yes	W4	CMU	Tan	Flaking	4	0.2	Negative
8310	1	2	213A	Copy Room near Classroom 213	Yes	Univent	Metal	Tan	Chipping	5	0	Negative
8310	1	2	213A	Copy Room near Classroom 213	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	213A	Copy Room near Classroom 213	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	213B	Staff Restroom in Copy Room near Classroom 213	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	213B	Staff Restroom in Copy Room near Classroom 213	Yes	Door Frame	Metal	Tan	Chipping	2	0.4	Negative
8310	1	2	213B	Staff Restroom in Copy Room near Classroom 213	Yes	W2	CMU	White	Chipping	3	0.3	Negative
8310	1	2	213B	Staff Restroom in Copy Room near Classroom 213	Yes	Pipe	Metal	White	Chipping	1	0.5	Negative
8310	1	2	213B	Staff Restroom in Copy Room near Classroom 213	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	213B	Staff Restroom in Copy Room near Classroom 213	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	213B	Staff Restroom in Copy Room near Classroom 213	Yes	Ceiling	Concrete	White	Efflorescence, Flaking	1	0.1	Negative
8310	1	2	213B	Staff Restroom in Copy Room near Classroom 213	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	206	Classroom 206 - Computer Lab	Yes	W1	Concrete	White	Chipping	2	0	Negative
8310	1	2	206	Classroom 206 - Computer Lab	Yes	Door Frame	Metal	Black	Chipping	1	0.5	Negative
8310	1	2	206	Classroom 206 - Computer Lab	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	206	Classroom 206 - Computer Lab	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	206	Classroom 206 - Computer Lab	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	206	Classroom 206 - Computer Lab	Yes	Univent	Metal	Tan	Chipping	10	0.1	Negative
8310	1	2	206	Classroom 206 - Computer Lab	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	206	Classroom 206 - Computer Lab	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Left Storage Closet in Classroom 206	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Left Storage Closet in Classroom 206	Yes	Door Frame	Metal	Tan	Chipping	2	0.6	Negative
8310	1	2	206A	Left Storage Closet in Classroom 206	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Left Storage Closet in Classroom 206	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Left Storage Closet in Classroom 206	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Left Storage Closet in Classroom 206	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Left Storage Closet in Classroom 206	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Right Storage Closet in Classroom 206	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Right Storage Closet in Classroom 206	Yes	Door Frame	Metal	Tan	Chipping	2	0.6	Negative
8310	1	2	206B	Right Storage Closet in Classroom 206	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Right Storage Closet in Classroom 206	Yes	W3	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	206B	Right Storage Closet in Classroom 206	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Right Storage Closet in Classroom 206	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Right Storage Closet in Classroom 206	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Storage Room 207B (Next to Storage Room 207A)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Storage Room 207B (Next to Storage Room 207A)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Storage Room 207B (Next to Storage Room 207A)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Storage Room 207B (Next to Storage Room 207A)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Storage Room 207B (Next to Storage Room 207A)	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	206A	Storage Room 207B (Next to Storage Room 207A)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Storage Room 207A (Next to Classroom 207)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Storage Room 207A (Next to Classroom 207)	Yes	Door Frame	Metal	Tan	Chipping	5	0.4	Negative
8310	1	2	206B	Storage Room 207A (Next to Classroom 207)	Yes	Pipe	Metal	Green	Flaking	10	0.4	Negative
8310	1	2	206B	Storage Room 207A (Next to Classroom 207)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Storage Room 207A (Next to Classroom 207)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Storage Room 207A (Next to Classroom 207)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Storage Room 207A (Next to Classroom 207)	Yes	Ceiling	Concrete	White	Efflorescence, Flaking	5	0.2	Negative
8310	1	2	206B	Storage Room 207A (Next to Classroom 207)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	213C	Storage Closet to Right of Classroom 213	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	213C	Storage Closet to Right of Classroom 213	Yes	Door Frame	Metal	Tan	Chipping	1	0.6	Negative
8310	1	2	213C	Storage Closet to Right of Classroom 213	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	213C	Storage Closet to Right of Classroom 213	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	213C	Storage Closet to Right of Classroom 213	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	213C	Storage Closet to Right of Classroom 213	Yes	Ceiling	Concrete	White	Moisture Damage	2	0.2	Negative
8310	1	2	213C	Storage Closet to Right of Classroom 213	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Classroom 213	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Classroom 213	Yes	Door Frame	Metal	Gray	Chipping	2	0.5	Negative
8310	1	2	213	Classroom 213	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Classroom 213	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Classroom 213	Yes	Univent/Shelf	Metal	Gray	Chipping	5	0.1	Negative
8310	1	2	213	Classroom 213	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Classroom 213	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Classroom 213	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Left Closet in Classroom 213	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	213	Left Closet in Classroom 213	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	213	Left Closet in Classroom 213	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	213	Left Closet in Classroom 213	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	213	Left Closet in Classroom 213	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	213	Left Closet in Classroom 213	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	213	Left Closet in Classroom 213	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	213	Middle Closet in Classroom 213	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Middle Closet in Classroom 213	Yes	Door Frame	Metal	Gray	Chipping	1	0.4	Negative
8310	1	2	213	Middle Closet in Classroom 213	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Middle Closet in Classroom 213	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Middle Closet in Classroom 213	Yes	Shelf Rack	Wood	Tan	Chipping	1	1.2	Positive
8310	1	2	213	Middle Closet in Classroom 213	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Middle Closet in Classroom 213	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	213	Middle Closet in Classroom 213	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Right Closet in Classroom 213	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Right Closet in Classroom 213	Yes	Door Frame	Metal	Gray	Chipping	1	0.3	Negative
8310	1	2	213	Right Closet in Classroom 213	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Right Closet in Classroom 213	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Right Closet in Classroom 213	Yes	Shelf Rack	Wood	Tan	Chipping	1	0.6	Negative
8310	1	2	213	Right Closet in Classroom 213	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Right Closet in Classroom 213	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	213	Right Closet in Classroom 213	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	Door	Metal	Beige	Chipping	12	0.4	Negative
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	Door	Metal	Brown	Chipping	2	0.3	Negative
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	Railing	Metal	Gray	Friction	2	1.8	Positive
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Office 207A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Office 207A	Yes	Door Frame	Metal	Gray, Beige	Chipping	4	0.5	Negative
8310	1	2	206B	Office 207A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Office 207A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Office 207A	Yes	Univent	Metal	Tan	Chipping	1	0.1	Negative
8310	1	2	206B	Office 207A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Office 207A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	206B	Office 207A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	207	Classroom 207	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	207	Classroom 207	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	207	Classroom 207	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	207	Classroom 207	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	207	Classroom 207	Yes	Univent/Shelf	Metal	Gray	Chipping	5	0	Negative
8310	1	2	207	Classroom 207	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	207	Classroom 207	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	207	Classroom 207	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XA	Left Closet in Classroom 207	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XA	Left Closet in Classroom 207	Yes	Door Frame	Metal	Tan	Chipping	5	0.3	Negative
8310	1	2	207XA	Left Closet in Classroom 207	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XA	Left Closet in Classroom 207	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XA	Left Closet in Classroom 207	Yes	Shelf Rack	Wood	Tan	Chipping	2	1.1	Positive
8310	1	2	207XA	Left Closet in Classroom 207	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XA	Left Closet in Classroom 207	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XA	Left Closet in Classroom 207	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XB	Middle Closet in Classroom 207	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XB	Middle Closet in Classroom 207	Yes	Door Frame	Metal	Tan	Chipping	5	0.1	Negative
8310	1	2	207XB	Middle Closet in Classroom 207	Yes	W2	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	207XB	Middle Closet in Classroom 207	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XB	Middle Closet in Classroom 207	Yes	Shelf Rack	Wood	Tan	Chipping	2	0.6	Negative
8310	1	2	207XB	Middle Closet in Classroom 207	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XB	Middle Closet in Classroom 207	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XB	Middle Closet in Classroom 207	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XC	Right Closet in Classroom 207	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XC	Right Closet in Classroom 207	Yes	Door Frame	Metal	Tan	Chipping	1	0.2	Negative
8310	1	2	207XC	Right Closet in Classroom 207	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XC	Right Closet in Classroom 207	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XC	Right Closet in Classroom 207	Yes	Shelf	Wood	Green	Chipping	1	0.3	Negative
8310	1	2	207XC	Right Closet in Classroom 207	Yes	Rod	Wood	Green	Chipping	1	0.2	Negative
8310	1	2	207XC	Right Closet in Classroom 207	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XC	Right Closet in Classroom 207	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	207XC	Right Closet in Classroom 207	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	212	Classroom 212	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	212	Classroom 212	Yes	Door Frame	Metal	Gray	Chipping	1	0.4	Negative
8310	1	2	212	Classroom 212	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	212	Classroom 212	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	212	Classroom 212	Yes	Univert/Shelf	Metal	Gray	Chipping	4	0.1	Negative
8310	1	2	212	Classroom 212	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	212	Classroom 212	Yes	Ceiling	Concrete	White	Flaking	2	0.1	Negative
8310	1	2	212	Classroom 212	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XA	Left Closet in Classroom 212	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XA	Left Closet in Classroom 212	Yes	Door Frame	Metal	Gray	Chipping	1	0.6	Negative
8310	1	2	212XA	Left Closet in Classroom 212	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XA	Left Closet in Classroom 212	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XA	Left Closet in Classroom 212	Yes	Rod	Wood	Tan	Chipping	1	0.1	Negative
8310	1	2	212XA	Left Closet in Classroom 212	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XA	Left Closet in Classroom 212	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XA	Left Closet in Classroom 212	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XB	Middle Closet in Classroom 212	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XB	Middle Closet in Classroom 212	Yes	Door Frame	Metal	Gray	Chipping	2	0.4	Negative
8310	1	2	212XB	Middle Closet in Classroom 212	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XB	Middle Closet in Classroom 212	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XB	Middle Closet in Classroom 212	Yes	Shelf Rack	Wood	Tan	Chipping	3	0.8	Positive
8310	1	2	212XB	Middle Closet in Classroom 212	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XB	Middle Closet in Classroom 212	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XB	Middle Closet in Classroom 212	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XC	Right Closet in Classroom 212	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XC	Right Closet in Classroom 212	Yes	Door Frame	Metal	Gray	Chipping	2	0.5	Negative
8310	1	2	212XC	Right Closet in Classroom 212	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XC	Right Closet in Classroom 212	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XC	Right Closet in Classroom 212	Yes	Shelf Rack	Wood	Tan	Chipping	3	0.8	Positive
8310	1	2	212XC	Right Closet in Classroom 212	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XC	Right Closet in Classroom 212	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	212XC	Right Closet in Classroom 212	Yes	Floor	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	Stair Post	Metal	Gray	Friction	4	5.7	Positive
8310	1	2	S22	Stairwell adjacent to Classroom 206 (Stairwell 3)	Yes	Railing	Metal	Gray	Friction	8	3	Positive
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	Door Frame	Metal	Tan	Chipping	4	0.6	Negative
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	Door	Metal	Gray	Chipping	1	0.1	Negative
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	Univent	Metal	Green	Chipping	1	0	Negative
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	Ceiling	Concrete	White	Flaking	5	0	Negative
8310	1	2	207A	Girl's Restroom across from Classroom 212	Yes	Floor	Concrete	Green	Chipping	1	0.3	Negative
8310	1	2	207B	Custodial Closet across from Classroom 212	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	207B	Custodial Closet across from Classroom 212	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	207B	Custodial Closet across from Classroom 212	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	207B	Custodial Closet across from Classroom 212	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	207B	Custodial Closet across from Classroom 212	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	207B	Custodial Closet across from Classroom 212	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	Door Frame	Metal	Gray, Tan	Chipping	2	0.6	Negative
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	Pipe	Metal	Gray	Flaking	5	0.4	Negative
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	Pipe	Metal	Gray	Flaking	10	0.4	Negative
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	Ceiling	Concrete	White	Efflorescence	4	0.2	Negative
8310	1	2	207D	Storage Closet between Restrooms near Classroom 212	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	Door Frame	Metal	Tan	Chipping	4	0.6	Negative
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	Door	Metal	Gray	Chipping	1	0.1	Negative
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	Univent	Metal	Green	Chipping	1	0	Negative
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	Ceiling	Concrete	White	Flaking	5	0	Negative
8310	1	2	207A	Girl's Restroom across hallway from Classroom 212	Yes	Floor	Concrete	Green	Chipping	1	0.3	Negative
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	Door Frame	Metal	Tan	Chipping	6	0.6	Negative
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	Vent	Metal	White	Chipping	1	0.1	Negative
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	Door	Metal	Gray	Chipping	1	0.1	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	Ceiling	Concrete	White	Flaking	5	0.1	Negative
8310	1	2	207C	Boy's Restroom across hallway from Classroom 212	Yes	Floor	Concrete	Gray	Friction	4	0	Negative
8310	1	2	211	Classroom 211	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Classroom 211	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	211	Classroom 211	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Classroom 211	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Classroom 211	Yes	Univent/Shelf	Metal	Gray	Chipping	6	0.1	Negative
8310	1	2	211	Classroom 211	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Classroom 211	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Classroom 211	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Left Closet in Classroom 211	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Left Closet in Classroom 211	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	211	Left Closet in Classroom 211	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Left Closet in Classroom 211	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Left Closet in Classroom 211	Yes	Shelf Rack	Wood	Tan	Chipping	3	0.9	Positive
8310	1	2	211	Left Closet in Classroom 211	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Left Closet in Classroom 211	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Left Closet in Classroom 211	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Middle Closet in Classroom 211	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Middle Closet in Classroom 211	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	211	Middle Closet in Classroom 211	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Middle Closet in Classroom 211	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Middle Closet in Classroom 211	Yes	Shelf Rack	Wood	Tan	Chipping	3	1	Positive
8310	1	2	211	Middle Closet in Classroom 211	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Middle Closet in Classroom 211	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Middle Closet in Classroom 211	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Right Closet in Classroom 211	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Right Closet in Classroom 211	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	211	Right Closet in Classroom 211	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Right Closet in Classroom 211	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Right Closet in Classroom 211	Yes	Rod	Wood	Tan	Chipping	1	0.1	Negative
8310	1	2	211	Right Closet in Classroom 211	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Right Closet in Classroom 211	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	211	Right Closet in Classroom 211	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	208	Classroom 208	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	208	Classroom 208	Yes	Door Frame	Metal	Gray	Chipping	1	0.3	Negative
8310	1	2	208	Classroom 208	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	208	Classroom 208	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	208	Classroom 208	Yes	Univent/Shelf	Metal	Gray	Chipping	5	0	Negative
8310	1	2	208	Classroom 208	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	208	Classroom 208	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	208	Classroom 208	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XA	Left Closet in Classroom 208	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	208XA	Left Closet in Classroom 208	Yes	Door Frame	Metal	Tan	Chipping	1	0.5	Negative
8310	1	2	208XA	Left Closet in Classroom 208	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	208XA	Left Closet in Classroom 208	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	208XA	Left Closet in Classroom 208	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	208XA	Left Closet in Classroom 208	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	208XA	Left Closet in Classroom 208	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	208XB	Middle Closet in Classroom 208	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XB	Middle Closet in Classroom 208	Yes	Door Frame	Metal	Tan	Chipping	1	0.5	Negative
8310	1	2	208XB	Middle Closet in Classroom 208	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XB	Middle Closet in Classroom 208	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XB	Middle Closet in Classroom 208	Yes	Shelf Rack	Wood	Tan	Chipping	1	1	Positive
8310	1	2	208XB	Middle Closet in Classroom 208	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XB	Middle Closet in Classroom 208	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XB	Middle Closet in Classroom 208	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XC	Right Closet in Classroom 208	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XC	Right Closet in Classroom 208	Yes	Door Frame	Metal	Tan	Chipping	1	0.6	Negative
8310	1	2	208XC	Right Closet in Classroom 208	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XC	Right Closet in Classroom 208	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XC	Right Closet in Classroom 208	Yes	Shelf Rack	Wood	Tan	Chipping	1	0.5	Negative
8310	1	2	208XC	Right Closet in Classroom 208	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XC	Right Closet in Classroom 208	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	208XC	Right Closet in Classroom 208	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Classroom 210	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Classroom 210	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	210	Classroom 210	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Classroom 210	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Classroom 210	Yes	Univent/Shelf	Metal	Gray	Chipping	8	0	Negative
8310	1	2	210	Classroom 210	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Classroom 210	Yes	Ceiling	Concrete (Support Beam)	White	Chipping	2	0.2	Negative
8310	1	2	210	Classroom 210	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Left Closet in Classroom 210	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Left Closet in Classroom 210	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Left Closet in Classroom 210	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Left Closet in Classroom 210	Yes	Shelf	Wood	Green	Chipping	1	0.1	Negative
8310	1	2	210	Left Closet in Classroom 210	Yes	Rod	Wood	Green	Chipping	1	0.2	Negative
8310	1	2	210	Left Closet in Classroom 210	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Left Closet in Classroom 210	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Left Closet in Classroom 210	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Middle Closet in Classroom 210	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Middle Closet in Classroom 210	Yes	Door Frame	Metal	Tan	Chipping	5	0.6	Negative
8310	1	2	210	Middle Closet in Classroom 210	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Middle Closet in Classroom 210	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Middle Closet in Classroom 210	Yes	Shelf Rack	Wood	Tan	Chipping	1	0.8	Positive
8310	1	2	210	Middle Closet in Classroom 210	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Middle Closet in Classroom 210	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Middle Closet in Classroom 210	Yes	Floor	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	210	Right Closet in Classroom 210	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Right Closet in Classroom 210	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Right Closet in Classroom 210	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Right Closet in Classroom 210	Yes	Shelf Rack	Wood	Tan	Chipping	1	0.9	Positive
8310	1	2	210	Right Closet in Classroom 210	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Right Closet in Classroom 210	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	210	Right Closet in Classroom 210	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	210A	Classroom 210A (to Right of Classroom 210B)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	210A	Classroom 210A (to Right of Classroom 210B)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	210A	Classroom 210A (to Right of Classroom 210B)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	210A	Classroom 210A (to Right of Classroom 210B)	Yes	Univent/Shelf	Metal	Gray	Chipping	10	0.1	Negative
8310	1	2	210A	Classroom 210A (to Right of Classroom 210B)	Yes	W4	Sheetrock	White	Chipping	1	0.1	Negative
8310	1	2	210A	Classroom 210A (to Right of Classroom 210B)	Yes	Ceiling	Concrete	White	Flaking	4	0.2	Negative
8310	1	2	210A	Classroom 210A (to Right of Classroom 210B)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Classroom 210B	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Classroom 210B	Yes	Door Frame	Metal	Gray	Flaking	6	0.3	Negative
8310	1	2	210B	Classroom 210B	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Classroom 210B	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Classroom 210B	Yes	Univent/Shelf	Metal	Gray	Flaking, Chipping	5	0.1	Negative
8310	1	2	210B	Classroom 210B	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Classroom 210B	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Classroom 210B	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Left Closet in Classroom 210B	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Left Closet in Classroom 210B	Yes	Door Frame	Metal	Gray	Chipping	1	0.6	Negative
8310	1	2	210B	Left Closet in Classroom 210B	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Left Closet in Classroom 210B	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Left Closet in Classroom 210B	Yes	Shelf	Wood	Tan	Chipping	1	0.3	Negative
8310	1	2	210B	Left Closet in Classroom 210B	Yes	Rod	Wood	Tan	Chipping	1	0.3	Negative
8310	1	2	210B	Left Closet in Classroom 210B	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Left Closet in Classroom 210B	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Left Closet in Classroom 210B	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	210B	Right Closet in Classroom 210B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	210B	Right Closet in Classroom 210B	Yes	Door Frame	Metal	Tan	Chipping, Friction	5	0.5	Negative
8310	1	2	210B	Right Closet in Classroom 210B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	210B	Right Closet in Classroom 210B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	210B	Right Closet in Classroom 210B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	210B	Right Closet in Classroom 210B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	210B	Right Closet in Classroom 210B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	2	210XA	Closet in Classroom 210A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	210XA	Closet in Classroom 210A	Yes	Door Frame	Metal	Gray	Chipping	2	0.4	Negative
8310	1	2	210XA	Closet in Classroom 210A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	210XA	Closet in Classroom 210A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	210XA	Closet in Classroom 210A	Yes	Shelf Rack	Wood	Beige	Chipping	1	0.6	Negative
8310	1	2	210XA	Closet in Classroom 210A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	210XA	Closet in Classroom 210A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A



				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	210XA	Closet in Classroom 210A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	S23 (S4)	Stairwell next to Classroom 210	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	S23 (S4)	Stairwell next to Classroom 210	Yes	Door	Metal	Brown	Chipping	1	0.4	Negative
8310	1	2	S23 (S4)	Stairwell next to Classroom 210	Yes	W2	Concrete	White	Flaking	1	0.3	Negative
8310	1	2	S23 (S4)	Stairwell next to Classroom 210	Yes	Pipe	Metal	White	Flaking	4	0.3	Negative
8310	1	2	S23 (S4)	Stairwell next to Classroom 210	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	S23 (S4)	Stairwell next to Classroom 210	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	S23 (S4)	Stairwell next to Classroom 210	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	S23 (S4)	Stairwell next to Classroom 210	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	209	Classroom 209	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	209	Classroom 209	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	2	209	Classroom 209	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	209	Classroom 209	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	209	Classroom 209	Yes	Univent/Shelf	Metal	Gray	Chipping	8	0	Negative
8310	1	2	209	Classroom 209	Yes	W4	Concrete	White	Chipping	2	0	Negative
8310	1	2	209	Classroom 209	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	209	Classroom 209	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	209A	Left Closet in Classroom 209	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	209A	Left Closet in Classroom 209	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	209A	Left Closet in Classroom 209	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	209A	Left Closet in Classroom 209	Yes	Shelf	Wood	Green	Chipping	1	0.1	Negative
8310	1	2	209A	Left Closet in Classroom 209	Yes	Rod	Wood	Green	Chipping	1	0.2	Negative
8310	1	2	209A	Left Closet in Classroom 209	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	209A	Left Closet in Classroom 209	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	209A	Left Closet in Classroom 209	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	209B	Middle Closet in Classroom 209	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	209B	Middle Closet in Classroom 209	Yes	Door Frame	Metal	Tan	Chipping	5	0.6	Negative
8310	1	2	209B	Middle Closet in Classroom 209	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	209B	Middle Closet in Classroom 209	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	209B	Middle Closet in Classroom 209	Yes	Shelf Rack	Wood	Tan	Chipping	1	0.8	Positive
8310	1	2	209B	Middle Closet in Classroom 209	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	209B	Middle Closet in Classroom 209	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	209B	Middle Closet in Classroom 209	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	209C	Right Closet in Classroom 209	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	209C	Right Closet in Classroom 209	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	2	209C	Right Closet in Classroom 209	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	209C	Right Closet in Classroom 209	Yes	Shelf Rack	Wood	Tan	Chipping	1	0.9	Positive
8310	1	2	209C	Right Closet in Classroom 209	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	2	209C	Right Closet in Classroom 209	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	2	209C	Right Closet in Classroom 209	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	2	H21	Hallway next to Classrooms 209 through 213 and through upper parts of Gym and Auditorium	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	2	H21	Hallway next to Classrooms 209 through 213 and through upper parts of Gym and Auditorium	Yes	W2	Concrete	Blue, Green	Chipping	1	0.1	Negative
8310	1	2	H21	Hallway next to Classrooms 209 through 213 and through upper parts of Gym and Auditorium	Yes	Access Panel	Metal	Green	Chipping	1	0.2	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	2	H21	Hallway next to Classrooms 209 through 213 and through upper parts of Gym and Auditorium	Yes	Vent	Metal	Blue	Chipping	1	0.3	Negative
8310	1	2	H21	Hallway next to Classrooms 209 through 213 and through upper parts of Gym and Auditorium	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	2	H21	Hallway next to Classrooms 209 through 213 and through upper parts of Gym and Auditorium	Yes	W4	CMU	White	Spalling	1	0.1	Negative
8310	1	2	H21	Hallway next to Classrooms 209 through 213 and through upper parts of Gym and Auditorium	Yes	Ceiling	Concrete	White	Flaking	8	0	Negative
8310	1	2	H21	Hallway next to Classrooms 209 through 213 and through upper parts of Gym and Auditorium	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	Door Frame	Metal	Gray	Chipping	2	0.4	Negative
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	Door Frame	Metal	Beige	Chipping	7	0.3	Negative
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	Door	Wood	Beige	Chipping	1	0.1	Negative
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	Railing	Metal	Beige	Friction	10	1.9	Positive
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	W3	Concrete Masonry Unit	Gray	Chipping	3	0	Negative
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	Railing	Metal	Beige	Friction	10	2	Positive
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	S123A	Auditorium Stairwell - Right Side Entrance to Stage	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	Door	Metal	Gray	Chipping	10	0	Negative
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	Door Frame	Metal	Gray	Chipping	1	0.2	Negative
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	W2	Concrete Masonry Unit	White	Spalling	15	0	Negative
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	Railing	Metal	Beige	Friction, Chipping	10	3.9	Positive
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	Stair Riser	Metal	Beige	Friction, Chipping	3	1	Positive
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	Door	Metal	Beige	Chipping	2	0.1	Negative
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	Door Frame	Metal	Beige	Chipping	2	0.4	Negative
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	W4	Concrete Masonry Unit	White	Spalling	15	0	Negative
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	Ceiling	Concrete	White	Efflorescence, Flaking	20	0.2	Negative
8310	1	1	S123B	Auditorium Stairwell - Left Side Entrance to Stage	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	107	Classroom 107	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	107	Classroom 107	Yes	Door Frame	Metal	Gray	Chipping	3	0.4	Negative
8310	1	1	107	Classroom 107	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	107	Classroom 107	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	107	Classroom 107	Yes	Univent/Shelf	Metal	Gray	Chipping	6	0.1	Negative
8310	1	1	107	Classroom 107	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	107	Classroom 107	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	107	Classroom 107	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XA	Left Closet in Classroom 107	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XA	Left Closet in Classroom 107	Yes	Door Frame	Metal	Brown	Chipping	1	0.6	Negative
8310	1	1	107XA	Left Closet in Classroom 107	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XA	Left Closet in Classroom 107	Yes	W3	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	107XA	Left Closet in Classroom 107	Yes	Shelf	Wood	Green	Chipping	1	0.1	Negative
8310	1	1	107XA	Left Closet in Classroom 107	Yes	Rod	Wood	Green	Friction	1	0	Negative
8310	1	1	107XA	Left Closet in Classroom 107	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XA	Left Closet in Classroom 107	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XA	Left Closet in Classroom 107	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XB	Middle Closet in Classroom 107	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XB	Middle Closet in Classroom 107	Yes	Door Frame	Metal	Brown	Chipping	5	0.7	Positive
8310	1	1	107XB	Middle Closet in Classroom 107	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XB	Middle Closet in Classroom 107	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XB	Middle Closet in Classroom 107	Yes	Shelf Rack	Wood	Brown	Chipping	2	0.4	Negative
8310	1	1	107XB	Middle Closet in Classroom 107	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XB	Middle Closet in Classroom 107	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XB	Middle Closet in Classroom 107	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XC	Right Closet in Classroom 107	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XC	Right Closet in Classroom 107	Yes	Door Frame	Metal	Brown	Chipping	3	0.5	Negative
8310	1	1	107XC	Right Closet in Classroom 107	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XC	Right Closet in Classroom 107	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XC	Right Closet in Classroom 107	Yes	Shelf Rack	Wood	Brown	Chipping	2	0.9	Positive
8310	1	1	107XC	Right Closet in Classroom 107	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XC	Right Closet in Classroom 107	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	107XC	Right Closet in Classroom 107	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	108	Classroom 108	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	108	Classroom 108	Yes	Door Frame	Metal	Gray	Chipping	1	0.4	Negative
8310	1	1	108	Classroom 108	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	108	Classroom 108	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	108	Classroom 108	Yes	Univent/Shelf	Metal	Gray	Chipping	2	0.2	Negative
8310	1	1	108	Classroom 108	Yes	Univent/Shelf	Metal	Tan	Chipping, Flaking	10	0.2	Negative
8310	1	1	108	Classroom 108	Yes	Pipe Cover	Metal	White	Flaking	1	0.5	Negative
8310	1	1	108	Classroom 108	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	108	Classroom 108	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	108	Classroom 108	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XA	Left Closet in Classroom 108	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XA	Left Closet in Classroom 108	Yes	Door Frame	Metal	Brown	Chipping	1	0.5	Negative
8310	1	1	108XA	Left Closet in Classroom 108	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XA	Left Closet in Classroom 108	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XA	Left Closet in Classroom 108	Yes	Rod	Wood	Beige	Friction	1	0.4	Negative
8310	1	1	108XA	Left Closet in Classroom 108	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XA	Left Closet in Classroom 108	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XA	Left Closet in Classroom 108	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XB	Middle Closet in Classroom 108	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XB	Middle Closet in Classroom 108	Yes	Door Frame	Metal	Brown	Chipping	2	0.5	Negative
8310	1	1	108XB	Middle Closet in Classroom 108	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XB	Middle Closet in Classroom 108	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XB	Middle Closet in Classroom 108	Yes	Shelf Rack	Wood	Brown	Chipping	2	0.9	Positive
8310	1	1	108XB	Middle Closet in Classroom 108	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XB	Middle Closet in Classroom 108	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	108XB	Middle Closet in Classroom 108	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XC	Right Closet in Classroom 108	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XC	Right Closet in Classroom 108	Yes	Door Frame	Metal	Brown	Chipping	1	0.4	Negative
8310	1	1	108XC	Right Closet in Classroom 108	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XC	Right Closet in Classroom 108	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XC	Right Closet in Classroom 108	Yes	Shelf Rack	Wood	Brown	Chipping	1	0.9	Positive
8310	1	1	108XC	Right Closet in Classroom 108	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XC	Right Closet in Classroom 108	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	108XC	Right Closet in Classroom 108	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Door	Metal	Brown	Chipping	5	0.4	Negative
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Door Frame	Metal	Brown	Chipping	5	0.2	Negative
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Access Panel	Metal	Brown	Chipping	1	0.2	Negative
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Vent	Metal	Brown	Chipping	1	0.1	Negative
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Stair Post	Metal	Gray	Friction, Chipping	1	2.2	Positive
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Railing	Metal	Gray	Friction, Chipping	2	0.5	Negative
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Railing	Metal	Gray	Friction, Chipping	2	5.7	Positive
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Railing	Metal	Gray	Friction, Chipping	1	5	Positive
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	S12 (S4)	Stairwell next to Classroom 108	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	109	Classroom 109	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	109	Classroom 109	Yes	Door Frame	Metal	Gray	Chipping	1	0.6	Negative
8310	1	1	109	Classroom 109	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	109	Classroom 109	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	109	Classroom 109	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	109	Classroom 109	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	109	Classroom 109	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XA	Restroom in Classroom 109	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XA	Restroom in Classroom 109	Yes	W2	Ceramic Tile	White	Chipping, Flaking	9	0	Negative
8310	1	1	109XA	Restroom in Classroom 109	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XA	Restroom in Classroom 109	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XA	Restroom in Classroom 109	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XA	Restroom in Classroom 109	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XB	Left Closet in Classroom 109	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XB	Left Closet in Classroom 109	Yes	Door Frame	Metal	Brown	Chipping	1	0.5	Negative
8310	1	1	109XB	Left Closet in Classroom 109	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XB	Left Closet in Classroom 109	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XB	Left Closet in Classroom 109	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XB	Left Closet in Classroom 109	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XB	Left Closet in Classroom 109	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XC	Right Closet in Classroom 109	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XC	Right Closet in Classroom 109	Yes	Door Frame	Metal	Brown	Chipping	2	0.5	Negative
8310	1	1	109XC	Right Closet in Classroom 109	Yes	W2	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	109XC	Right Closet in Classroom 109	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XC	Right Closet in Classroom 109	Yes	Shelf Rack	Wood	Brown	Chipping	1	0.8	Positive
8310	1	1	109XC	Right Closet in Classroom 109	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XC	Right Closet in Classroom 109	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	109XC	Right Closet in Classroom 109	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	110	Classroom 110	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	110	Classroom 110	Yes	Door Frame	Metal	Gray	Chipping	3	0.6	Negative
8310	1	1	110	Classroom 110	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	110	Classroom 110	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	110	Classroom 110	Yes	Univent/Shelf	Metal	Gray	Chipping	5	0.2	Negative
8310	1	1	110	Classroom 110	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	110	Classroom 110	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	110	Classroom 110	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Classroom 110 Restroom	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	110A	Classroom 110 Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	110A	Classroom 110 Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	110A	Classroom 110 Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	110A	Classroom 110 Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	110A	Classroom 110 Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	106	Classroom 106	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Classroom 106	Yes	Door Frame	Metal	Gray	Chipping, Flaking	3	0.5	Negative
8310	1	1	106	Classroom 106	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Classroom 106	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Classroom 106	Yes	Univent/Shelf	Metal	Gray	Chipping	3	0.5	Negative
8310	1	1	106	Classroom 106	Yes	Univent/Shelf	Metal	Tan	Chipping	5	0.1	Negative
8310	1	1	106	Classroom 106	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Classroom 106	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Left Closet in Classroom 106	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Left Closet in Classroom 106	Yes	Door Frame	Metal	Brown	Chipping	1	0.6	Negative
8310	1	1	106	Left Closet in Classroom 106	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Left Closet in Classroom 106	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Left Closet in Classroom 106	Yes	Shelf	Wood	White	Chipping	1	0.2	Negative
8310	1	1	106	Left Closet in Classroom 106	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Left Closet in Classroom 106	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Left Closet in Classroom 106	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Middle Closet in Classroom 106	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Middle Closet in Classroom 106	Yes	Door Frame	Metal	Brown	Chipping	2	0.5	Negative
8310	1	1	106	Middle Closet in Classroom 106	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Middle Closet in Classroom 106	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Middle Closet in Classroom 106	Yes	Shelf Rack	Wood	White	Chipping	1	0.8	Positive
8310	1	1	106	Middle Closet in Classroom 106	Yes	Shelf Support	Metal	White	Chipping	1	0.1	Negative
8310	1	1	106	Middle Closet in Classroom 106	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Middle Closet in Classroom 106	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Middle Closet in Classroom 106	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Right Closet in Classroom 106	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Right Closet in Classroom 106	Yes	Door Frame	Metal	Brown	Chipping	4	0.5	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	106	Right Closet in Classroom 106	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Right Closet in Classroom 106	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Right Closet in Classroom 106	Yes	Shelf Rack	Wood	White	Chipping	2	0.9	Positive
8310	1	1	106	Right Closet in Classroom 106	Yes	Shelf Support	Metal	White	Chipping	1	0	Negative
8310	1	1	106	Right Closet in Classroom 106	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Right Closet in Classroom 106	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	106	Right Closet in Classroom 106	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	Door Frame	Metal	Brown	Flaking	3	0.6	Negative
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	Univent/Shelf	Metal	Brown	Chipping	2	0	Negative
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	Ceiling	Concrete	White	Flaking	1	0	Negative
8310	1	1	117	Girl's Restroom across hallway from Classroom 110A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Boy's Restroom adjacent to Classroom 110A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Boy's Restroom across hallway from Classroom 110A	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	1	115	Boy's Restroom across hallway from Classroom 110A	Yes	Door Frame	Metal	Brown	Chipping	2	0.7	Positive
8310	1	1	115	Boy's Restroom across hallway from Classroom 110A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Boy's Restroom across hallway from Classroom 110A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Boy's Restroom across hallway from Classroom 110A	Yes	Univent/Shelf	Metal	Brown	Chipping	1	0.1	Negative
8310	1	1	115	Boy's Restroom across hallway from Classroom 110A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Boy's Restroom across hallway from Classroom 110A	Yes	Ceiling	Concrete	White	Flaking	1	0.1	Negative
8310	1	1	115	Boy's Restroom across hallway from Classroom 110A	Yes	Floor	Concrete	Gray	Friction	6	0.1	Negative
8310	1	1	115A	Custodial Closet across from Classroom 110A	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	115A	Custodial Closet across from Classroom 110A	No	Door Frame	Metal	Gray	Chipping	3	0.3	Negative
8310	1	1	115A	Custodial Closet across from Classroom 110A	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	115A	Custodial Closet across from Classroom 110A	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	115A	Custodial Closet across from Classroom 110A	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	115A	Custodial Closet across from Classroom 110A	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	115A	Custodial Closet across from Classroom 110A	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	118	Lobby/Waiting Area	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	118	Lobby/Waiting Area	Yes	Door Frame	Metal	Brown	Chipping	3	0.7	Positive
8310	1	1	118	Lobby/Waiting Area	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	118	Lobby/Waiting Area	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	118	Lobby/Waiting Area	Yes	Door Frame	Metal	Brown	Chipping	1	0.6	Negative
8310	1	1	118	Lobby/Waiting Area	Yes	Door Frame	Metal	Brown	Chipping	1	0.6	Negative
8310	1	1	118	Lobby/Waiting Area	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	118	Lobby/Waiting Area	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	118	Lobby/Waiting Area	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	118A	Student Exam Room	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	118A	Student Exam Room	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	118A	Student Exam Room	Yes	Door Frame	Metal	Brown	Chipping	2	0.4	Negative
8310	1	1	118A	Student Exam Room	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	118A	Student Exam Room	Yes	Univent/Shelf	Metal	Brown	Chipping	4	0	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	118A	Student Exam Room	Yes	Pipe	Metal	White	Flaking	1	0.4	Negative
8310	1	1	118A	Student Exam Room	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	118A	Student Exam Room	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	118A	Student Exam Room	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	118B	Nurse's Office	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	118B	Nurse's Office	Yes	Door Frame	Metal	Brown	Chipping	2	0.5	Negative
8310	1	1	118B	Nurse's Office	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	118B	Nurse's Office	Yes	Door Frame	Metal	Brown	Chipping	1	0.4	Negative
8310	1	1	118B	Nurse's Office	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	118B	Nurse's Office	Yes	Univent/Shelf	Metal	Brown	Chipping	4	0	Negative
8310	1	1	118B	Nurse's Office	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	118B	Nurse's Office	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	118B	Nurse's Office	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	118D	Restroom in Student Exam Room	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	118D	Restroom in Student Exam Room	Yes	Door Frame	Metal	Brown	Chipping	2	0.5	Negative
8310	1	1	118D	Restroom in Student Exam Room	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	118D	Restroom in Student Exam Room	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	118D	Restroom in Student Exam Room	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	118D	Restroom in Student Exam Room	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	118D	Restroom in Student Exam Room	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	118E	Storage Closet in Student Exam Room	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	118E	Storage Closet in Student Exam Room	Yes	Door Frame	Metal	Brown	Chipping	1	0.7	Positive
8310	1	1	118E	Storage Closet in Student Exam Room	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	118E	Storage Closet in Student Exam Room	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	118E	Storage Closet in Student Exam Room	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	118E	Storage Closet in Student Exam Room	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	118E	Storage Closet in Student Exam Room	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	118F	Right Storage Closet in Front Lobby/Waiting Area	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	118F	Right Storage Closet in Front Lobby/Waiting Area	Yes	Door Frame	Metal	Brown	Chipping	1	0.5	Negative
8310	1	1	118F	Right Storage Closet in Front Lobby/Waiting Area	Yes	Door Frame	Metal	Green	Chipping	1	0.5	Negative
8310	1	1	118F	Right Storage Closet in Front Lobby/Waiting Area	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	118F	Right Storage Closet in Front Lobby/Waiting Area	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	118F	Right Storage Closet in Front Lobby/Waiting Area	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	118F	Right Storage Closet in Front Lobby/Waiting Area	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	118F	Right Storage Closet in Front Lobby/Waiting Area	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	118G	Left Storage Closet in Front Lobby/Waiting Area	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	118G	Left Storage Closet in Front Lobby/Waiting Area	Yes	Door Frame	Metal	Brown	Chipping	1	0.5	Negative
8310	1	1	118G	Left Storage Closet in Front Lobby/Waiting Area	Yes	Door Frame	Metal	Green	Chipping	1	0.6	Negative
8310	1	1	118G	Left Storage Closet in Front Lobby/Waiting Area	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	118G	Left Storage Closet in Front Lobby/Waiting Area	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	118G	Left Storage Closet in Front Lobby/Waiting Area	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	118G	Left Storage Closet in Front Lobby/Waiting Area	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	118G	Left Storage Closet in Front Lobby/Waiting Area	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Conference Room	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Conference Room	Yes	Door Frame	Metal	Gray	Chipping	2	0.5	Negative
8310	1	1	110A	Conference Room	Yes	Door Frame	Metal	Tan	Chipping	2	0.5	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	110A	Conference Room	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Conference Room	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Conference Room	Yes	Built-In Shelf	Metal	Tan	Chipping	3	0.1	Negative
8310	1	1	110A	Conference Room	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Conference Room	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Conference Room	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Right Office in 110A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Right Office in 110A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Right Office in 110A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Right Office in 110A	Yes	Univent/Shelf	Metal	Tan	Chipping	8	0.2	Negative
8310	1	1	110A	Right Office in 110A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Right Office in 110A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Right Office in 110A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Left Office in 110A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Left Office in 110A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Left Office in 110A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Left Office in 110A	Yes	Univent/Shelf	Metal	Tan	Chipping	4	0.1	Negative
8310	1	1	110A	Left Office in 110A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Left Office in 110A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Left Office in 110A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Speech/Therapy Room in 110A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Speech/Therapy Room in 110A	Yes	Door Frame	Metal	Tan	Chipping	1	0.5	Negative
8310	1	1	110A	Speech/Therapy Room in 110A	Yes	W2	CMU	White	Flaking	12	0	Negative
8310	1	1	110A	Speech/Therapy Room in 110A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Speech/Therapy Room in 110A	Yes	W4	Sheetrock	White	Chipping	1	0.1	Negative
8310	1	1	110A	Speech/Therapy Room in 110A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	110A	Speech/Therapy Room in 110A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	S11	Stairwell next to Visitor Entrance/ Main Office	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	S11	Stairwell next to Visitor Entrance/ Main Office	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	S11	Stairwell next to Visitor Entrance/ Main Office	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	S11	Stairwell next to Visitor Entrance/ Main Office	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	S11	Stairwell next to Visitor Entrance/ Main Office	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	S11	Stairwell next to Visitor Entrance/ Main Office	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Locker Room next to Principal's Office	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Locker Room next to Principal's Office	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Locker Room next to Principal's Office	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Locker Room next to Principal's Office	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Locker Room next to Principal's Office	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Locker Room next to Principal's Office	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Principal's Office	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Principal's Office	Yes	Door Frame	Metal	Brown	Chipping	4	0.5	Negative
8310	1	1	119	Principal's Office	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Principal's Office	Yes	Door Frame	Metal	Brown	Chipping	3	0.6	Negative
8310	1	1	119	Principal's Office	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Principal's Office	Yes	Univent/Shelf	Metal	Brown	Chipping	4	0.1	Negative
8310	1	1	119	Principal's Office	Yes	W4	N/A	N/A	None	0	N/A	N/A



				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATT		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	119	Principal's Office	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	119	Principal's Office	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XA	Principal's Office Storage Closet (by bathroom)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XA	Principal's Office Storage Closet (by bathroom)	Yes	Door Frame	Metal	Brown	Chipping	1	0.6	Negative
8310	1	1	119XA	Principal's Office Storage Closet (by bathroom)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XA	Principal's Office Storage Closet (by bathroom)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XA	Principal's Office Storage Closet (by bathroom)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XA	Principal's Office Storage Closet (by bathroom)	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XA	Principal's Office Storage Closet (by bathroom)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XB	Principal's Office Storage Closet (by entrance door to main office)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XB	Principal's Office Storage Closet (by entrance door to main office)	Yes	Door Frame	Metal	Brown	Chipping	3	0.4	Negative
8310	1	1	119XB	Principal's Office Storage Closet (by entrance door to main office)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XB	Principal's Office Storage Closet (by entrance door to main office)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XB	Principal's Office Storage Closet (by entrance door to main office)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XC	Principal's Office Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XB	Principal's Office Storage Closet (by entrance door to main office)	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XB	Principal's Office Storage Closet (by entrance door to main office)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XC	Principal's Office Restroom	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XC	Principal's Office Restroom	Yes	Door Frame	Metal	Brown	Chipping	2	0.5	Negative
8310	1	1	119XC	Principal's Office Restroom	Yes	Pipe	Metal	White	Chipping,Flaking	1	0.5	Negative
8310	1	1	119XC	Principal's Office Restroom	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XC	Principal's Office Restroom	Yes	Shelf	Wood	Green	Chipping	1	0.4	Negative
8310	1	1	119XC	Principal's Office Restroom	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XC	Principal's Office Restroom	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	119XC	Principal's Office Restroom	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	120	Main Office	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	120	Main Office	Yes	Door Frame	Metal	Gray	Chipping	1	0.4	Negative
8310	1	1	120	Main Office	Yes	Door Frame	Metal	Brown	Chipping	5	0.6	Negative
8310	1	1	120	Main Office	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	120	Main Office	Yes	W3	CMU	White	Flaking	1	0.1	Negative
8310	1	1	120	Main Office	Yes	Univent/Shelf	Metal	Brown	Chipping	8	0.2	Negative
8310	1	1	120	Main Office	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	120	Main Office	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	120	Main Office	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	120A	Main Office Storage Room	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	120A	Main Office Storage Room	Yes	Door Frame	Metal	Brown	Chipping	5	0.5	Negative
8310	1	1	120A	Main Office Storage Room	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	120A	Main Office Storage Room	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	120A	Main Office Storage Room	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	120A	Main Office Storage Room	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	120A	Main Office Storage Room	Yes	Floor	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	120B	Computer Server Room in Main Office	No	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	120B	Computer Server Room in Main Office	No	Door Frame	Metal	Brown	Chipping	5	0.6	Negative
8310	1	1	120B	Computer Server Room in Main Office	No	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	120B	Computer Server Room in Main Office	No	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	120B	Computer Server Room in Main Office	No	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	120B	Computer Server Room in Main Office	No	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	120B	Computer Server Room in Main Office	No	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	Door	Metal	Black	Chipping	1	0.1	Negative
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	Door Frame	Metal	Gray, Brown	Chipping	7	0.3	Negative
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	Pipe	Metal	Beige	Flaking, Chipping	5	0.8	Positive
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	Ceiling	Concrete	White	Flaking, Moisture Damage	8	0	Negative
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Sitting Area	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	Door	Metal	Beige	Chipping	3	0.3	Negative
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	Radiator	Metal	Brown	Chipping	3	0	Negative
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	Window Frame	CMU	Flaking	Beige	4	0.1	Negative
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	111 (125)	Vice Principal Office 111 (IDF Room) - Office Area	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	111A (125A)	Storage Closet in Vice Principal's Office	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	111A (125A)	Storage Closet in Vice Principal's Office	Yes	Door Frame	Metal	Brown	Chipping	1	0.5	Negative
8310	1	1	111A (125A)	Storage Closet in Vice Principal's Office	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	111A (125A)	Storage Closet in Vice Principal's Office	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	111A (125A)	Storage Closet in Vice Principal's Office	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	111A (125A)	Storage Closet in Vice Principal's Office	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	111A (125A)	Storage Closet in Vice Principal's Office	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	111B (125B)	Storage Closet in Vice Principal's Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B (125B)	Storage Closet in Vice Principal's Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B (125B)	Storage Closet in Vice Principal's Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B (125B)	Storage Closet in Vice Principal's Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B (125B)	Storage Closet in Vice Principal's Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B (125B)	Storage Closet in Vice Principal's Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B	Compressor Room in Main Lobby	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B	Compressor Room in Main Lobby	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B	Compressor Room in Main Lobby	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B	Compressor Room in Main Lobby	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B	Compressor Room in Main Lobby	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	111B	Compressor Room in Main Lobby	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	120C	Custodial Closet outside of Auditorium	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	120C	Custodial Closet outside of Auditorium	No	W2	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	120C	Custodial Closet outside of Auditorium	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	120C	Custodial Closet outside of Auditorium	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	120C	Custodial Closet outside of Auditorium	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	120C	Custodial Closet outside of Auditorium	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123A	Auditorium Foyer	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	123A	Auditorium Foyer	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	123A	Auditorium Foyer	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	123A	Auditorium Foyer	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	123A	Auditorium Foyer	Yes	Door Frame	Metal	Grey	Chipping	2	0	Negative
8310	1	1	123A	Auditorium Foyer	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	123A	Auditorium Foyer	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	123B	Girl's Restroom in Rear of Auditorium	Yes	W1	Concrete	Grey	Chipping	2	0.1	Negative
8310	1	1	123B	Girl's Restroom in Rear of Auditorium	Yes	W2	Concrete	Grey	Chipping	2	0.1	Negative
8310	1	1	123B	Girl's Restroom in Rear of Auditorium	Yes	W3	Concrete	Grey	Chipping	2	0.1	Negative
8310	1	1	123B	Girl's Restroom in Rear of Auditorium	Yes	W4	Concrete	Grey	Chipping	2	0.1	Negative
8310	1	1	123B	Girl's Restroom in Rear of Auditorium	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	123B	Girl's Restroom in Rear of Auditorium	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	123C	Boy's Restroom in Rear of Auditorium	Yes	W1	Concrete	Grey	Chipping	4	0.1	Negative
8310	1	1	123C	Boy's Restroom in Rear of Auditorium	Yes	W2	Concrete	Grey	Chipping	4	0.1	Negative
8310	1	1	123C	Boy's Restroom in Rear of Auditorium	Yes	W3	Concrete	Grey	Chipping	4	0.1	Negative
8310	1	1	123C	Boy's Restroom in Rear of Auditorium	Yes	W4	Concrete	Grey	Chipping	4	0.1	Negative
8310	1	1	123C	Boy's Restroom in Rear of Auditorium	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	123C	Boy's Restroom in Rear of Auditorium	Yes	Floor	Concrete	Grey	Chipping	5	0.1	Negative
8310	1	1	123	Auditorium	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Auditorium	Yes	Door Frame	Metal	Grey	Chipping	2	0.4	Negative
8310	1	1	123	Auditorium	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Auditorium	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Auditorium	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Auditorium	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Auditorium	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	123D	Auditorium Right rear Storage with Exterior access	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123D	Auditorium Right rear Storage with Exterior access	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123D	Auditorium Right rear Storage with Exterior access	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123D	Auditorium Right rear Storage with Exterior access	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123D	Auditorium Right rear Storage with Exterior access	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123D	Auditorium Right rear Storage with Exterior access	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123E	Storage Rooms in Center Rear of Stage	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	123E	Storage Rooms in Center Rear of Stage	Yes	Door Frame	Metal	Beige	Chipping	3	0.2	Negative
8310	1	1	123E	Storage Rooms in Center Rear of Stage	Yes	Door	Metal	Beige	Chipping	5	0.2	Negative
8310	1	1	123E	Storage Rooms in Center Rear of Stage	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	123E	Storage Rooms in Center Rear of Stage	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	123E	Storage Rooms in Center Rear of Stage	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	123E	Storage Rooms in Center Rear of Stage	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	123E	Storage Rooms in Center Rear of Stage	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	123F	Storage Room next to Stairwell on Left	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	123F	Storage Room next to Stairwell on Left	Yes	Door Frame	Metal	Beige	Chipping	3	0.2	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	123F	Storage Room next to Stairwell on Left	Yes	Door	Metal	Beige	Chipping	5	0.2	Negative
8310	1	1	123F	Storage Room next to Stairwell on Left	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	123F	Storage Room next to Stairwell on Left	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	123F	Storage Room next to Stairwell on Left	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	123F	Storage Room next to Stairwell on Left	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	123F	Storage Room next to Stairwell on Left	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	123G	Storage Closet near rear Right exterior access of Stage	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123G	Storage Closet near rear Right exterior access of Stage	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123G	Storage Closet near rear Right exterior access of Stage	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123G	Storage Closet near rear Right exterior access of Stage	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123G	Storage Closet near rear Right exterior access of Stage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123G	Storage Closet near rear Right exterior access of Stage	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	112A	Lounge 112A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	112A	Lounge 112A	Yes	Door Frame	Metal	Brown	Chipping	6	0.5	Negative
8310	1	1	112A	Lounge 112A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	112A	Lounge 112A	Yes	Pipe	Metal	White	Flaking	10	0.5	Negative
8310	1	1	112A	Lounge 112A	Yes	Window Frame	CMU	White	Flaking	6	0.2	Negative
8310	1	1	112A	Lounge 112A	Yes	Radiator	Metal	Brown	Chipping	3	0	Negative
8310	1	1	112A	Lounge 112A	Yes	W3	CMU	White	Flaking	10	0.1	Negative
8310	1	1	112A	Lounge 112A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	112A	Lounge 112A	Yes	Ceiling	Concrete	White	Efflorescence	12	0.3	Negative
8310	1	1	112A	Lounge 112A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	112B	Lounge 112A Restroom	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	112B	Lounge 112A Restroom	Yes	Door Frame	Metal	Brown	Chipping	4	0.3	Negative
8310	1	1	112B	Lounge 112A Restroom	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	112B	Lounge 112A Restroom	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	112B	Lounge 112A Restroom	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	112B	Lounge 112A Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	112B	Lounge 112A Restroom	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	112BB	IDF Room next to Women's Restroom 112A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	112BB	IDF Room next to Women's Restroom 112A	Yes	Door Frame	Metal	Brown	Chipping	5	0.8	Positive
8310	1	1	112BB	IDF Room next to Women's Restroom 112A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	112BB	IDF Room next to Women's Restroom 112A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	112BB	IDF Room next to Women's Restroom 112A	Yes	Pipe	Metal	Green	Flaking	10	0.4	Negative
8310	1	1	112BB	IDF Room next to Women's Restroom 112A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	112BB	IDF Room next to Women's Restroom 112A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	112BB	IDF Room next to Women's Restroom 112A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	123F	Music Teacher's Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123F	Music Teacher's Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123F	Music Teacher's Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123F	Music Teacher's Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123F	Music Teacher's Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	123F	Music Teacher's Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	105B	Storage next to Office 105A	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	105B	Storage next to Office 105A	Yes	Door Frame	Metal	Green	Chipping	3	0.4	Negative
8310	1	1	105B	Storage next to Office 105A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	105B	Storage next to Office 105A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	105B	Storage next to Office 105A	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	105B	Storage next to Office 105A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	105B	Storage next to Office 105A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	105A	Storage next to Classroom 105	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	105A	Storage next to Classroom 105	Yes	Door Frame	Metal	Green, White	Chipping	6	0.4	Negative
8310	1	1	105A	Storage next to Classroom 105	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	105A	Storage next to Classroom 105	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	105A	Storage next to Classroom 105	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	105A	Storage next to Classroom 105	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	105A	Storage next to Classroom 105	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	105	Classroom 105	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	105	Classroom 105	Yes	Door Frame	Metal	Grey	Chipping	1	0.4	Negative
8310	1	1	105	Classroom 105	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	105	Classroom 105	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	105	Classroom 105	Yes	Univent/Shelf	Metal	Grey	Chipping	5	0.1	Negative
8310	1	1	105	Classroom 105	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	105	Classroom 105	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	105	Classroom 105	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XA	Classroom 105 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XA	Classroom 105 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XA	Classroom 105 - Left Closet	Yes	Shelf	Wood	Brown	Chipping	1	0.3	Negative
8310	1	1	105XA	Classroom 105 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XA	Classroom 105 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XA	Classroom 105 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XA	Classroom 105 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XB	Classroom 105 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XB	Classroom 105 - Right Closet	Yes	Door Frame	Metal	Brown	Chipping	1	0.2	Negative
8310	1	1	105XB	Classroom 105 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XB	Classroom 105 - Right Closet	Yes	Shelf	Wood	Brown	Chipping	1	0.3	Negative
8310	1	1	105XB	Classroom 105 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XB	Classroom 105 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XB	Classroom 105 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	105XB	Classroom 105 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	112	Classroom 112	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	112	Classroom 112	Yes	Door Frame	Metal	Grey	Chipping	2	0.5	Negative
8310	1	1	112	Classroom 112	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	112	Classroom 112	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	112	Classroom 112	Yes	Univent/Shelf	Metal	Grey	Chipping	10	0.2	Negative
8310	1	1	112	Classroom 112	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	112	Classroom 112	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	112	Classroom 112	Yes	Floor	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	Door Frame	Metal	Brown	Chipping	4	0.2	Negative
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	Shelf	Wood	Brown	Chipping	6	0.9	Positive
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	Shelf Support	Metal	Black	Chipping	1	0	Negative
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XA	Classroom 112 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	Door Frame	Metal	Brown	Chipping	4	0.2	Negative
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	Shelf	Wood	Brown	Chipping	6	0.9	Positive
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	Shelf Support	Metal	Black	Chipping	1	0	Negative
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XB	Classroom 112 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XC	Classroom 112 - Small Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XC	Classroom 112 - Small Closet	Yes	Door Frame	Metal	Brown	Chipping	4	0.5	Negative
8310	1	1	112XC	Classroom 112 - Small Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XC	Classroom 112 - Small Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XC	Classroom 112 - Small Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XC	Classroom 112 - Small Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	112XC	Classroom 112 - Small Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	Door Frame	Metal	Gray	Chipping	4	0.5	Negative
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	Door	Metal	Gray	Chipping	2	0.2	Negative
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	Door Frame	Metal	Gray	Chipping, Peeling	4	0.3	Negative
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	Radiator	Metal	Brown	Chipping	2	0	Negative
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	Ceiling	Concrete	White	Chipping	2	0	Negative
8310	1	1	104B	Girl's Restroom next to Classroom 105	Yes	Floor	Concrete	Gray	Friction	3	0.2	Negative
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	Door Frame	Metal	Gray	Chipping	4	0.6	Negative
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	Door Frame	Metal	Gray	Chipping	6	0.3	Negative
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	Radiator	Metal	Brown	Chipping	2	0.1	Negative
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	Ceiling	Concrete	White	Efflorescence, Chipping	4	0	Negative
8310	1	1	104A	Boy's Restroom next to Classroom 105	Yes	Floor	Concrete	Gray	Chipping	5	0.2	Negative
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	W2	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	Radiator	Metal	Orange	Chipping	1	0.1	Negative
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	Radiator	Metal	Orange	Chipping	1	0.2	Negative
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	Radiator	Metal	Orange	Chipping	1	0.2	Negative
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	W4	Concrete	Orange	Chipping	1	0.5	Negative
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	Door Frame	Metal	Gray	Chipping	4	0.6	Negative
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	H11	Hallway next to Classrooms 112 through 101	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	104C	Storage across from Classroom 113	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	104C	Storage across from Classroom 113	Yes	Door Frame	Metal	Gray	Chipping	1	0.5	Negative
8310	1	1	104C	Storage across from Classroom 113	Yes	Door Frame	Metal	Green	Chipping	4	0.4	Negative
8310	1	1	104C	Storage across from Classroom 113	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	104C	Storage across from Classroom 113	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	104C	Storage across from Classroom 113	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	104C	Storage across from Classroom 113	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	104C	Storage across from Classroom 113	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	113	Classroom 113	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	113	Classroom 113	Yes	Door Frame	Metal	Grey	Chipping	1	0.5	Negative
8310	1	1	113	Classroom 113	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	113	Classroom 113	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	113	Classroom 113	Yes	Univent/Shelf	Metal	Grey	Chipping	15	0.2	Negative
8310	1	1	113	Classroom 113	Yes	Pipe Cover	Metal	White	Chipping	2	0.5	Negative
8310	1	1	113	Classroom 113	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	113	Classroom 113	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	113	Classroom 113	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	Door Frame	Metal	Brown	Chipping	7	0.6	Negative
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	Shelf	Metal	Brown	Chipping	25	0.8	Positive
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	Shelf Support	Metal	Black	Chipping	1	0.1	Negative
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XA	Classroom 113 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	Door Frame	Metal	Brown	Chipping	7	0.6	Negative
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	Shelf	Metal	Brown	Chipping	25	0.8	Positive
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	Shelf Support	Metal	Black	Chipping	1	0.1	Negative
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	113XB	Classroom 113 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	104	Office 104	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	104	Office 104	Yes	Door Frame	Metal	Gray	Chipping	1	0.4	Negative
8310	1	1	104	Office 104	Yes	W2	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	104	Office 104	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	104	Office 104	Yes	Univent/Shelf	Metal	Gray	Chipping	5	0.1	Negative
8310	1	1	104	Office 104	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	104	Office 104	Yes	Ceiling	Concrete	White	Spalling	2	0	Negative
8310	1	1	104	Office 104	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Left Closet in Office 104	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Left Closet in Office 104	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Left Closet in Office 104	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Left Closet in Office 104	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Left Closet in Office 104	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	104A	Left Closet in Office 104	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Right Closet in Office 104	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Right Closet in Office 104	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Right Closet in Office 104	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Right Closet in Office 104	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Right Closet in Office 104	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	104B	Right Closet in Office 104	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	114	Classroom 114	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	114	Classroom 114	Yes	Door Frame	Metal	Grey	Chipping	2	0.5	Negative
8310	1	1	114	Classroom 114	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	114	Classroom 114	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	114	Classroom 114	Yes	Univent/Shelf	Metal	Grey	Chipping	4	0.1	Negative
8310	1	1	114	Classroom 114	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	114	Classroom 114	Yes	Pipe	Metal	Orange	Chipping	2	0.1	Negative
8310	1	1	114	Classroom 114	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	114	Classroom 114	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	Door Frame	Metal	Brown	Chipping	12	0.6	Negative
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	Shelf	Wood	Brown	Chipping	5	1.3	Positive
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	Shelf Support	Metal	Brown	Chipping	1	0	Negative
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XA	Classroom 114 - Left Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	Door Frame	Metal	Brown	Chipping	12	0.6	Negative
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	Shelf	Wood	Brown	Chipping	10	1.3	Positive
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	Shelf Support	Metal	Brown	Chipping	1	0.1	Negative
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	114XB	Classroom 114 - Right Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	103	Classroom 103B	Yes	W1	CMU	Beige	Chipping	1	0.5	Negative
8310	1	1	103	Classroom 103B	Yes	Door Frame	Metal	Grey	Chipping	1	0.6	Negative



				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	103	Classroom 103B	Yes	W2	Sheetrock	Beige	Chipping	2	0.1	Negative
8310	1	1	103	Classroom 103B	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	103	Classroom 103B	Yes	Univent/Shelf	Metal	Grey	Chipping	4	0.3	Negative
8310	1	1	103	Classroom 103B	Yes	Shelf	Metal	Black	Chipping	10	0	Negative
8310	1	1	103	Classroom 103B	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	103	Classroom 103B	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	103	Classroom 103B	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Classroom 115	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Classroom 115	Yes	Door Frame	Metal	Grey	Chipping	4	0.5	Negative
8310	1	1	115	Classroom 115	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Classroom 115	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Classroom 115	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Classroom 115	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	115	Classroom 115	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	116	School Store	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	116	School Store	Yes	Door Frame	Metal	Brown	Chipping	4	0.4	Negative
8310	1	1	116	School Store	Yes	Door Frame	Metal	Brown	Chipping	3	0.3	Negative
8310	1	1	116	School Store	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	116	School Store	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	116	School Store	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	116	School Store	Yes	Univent/Shelf	Metal	Brown	Chipping	10	0.1	Negative
8310	1	1	116	School Store	Yes	Pipe Cover	Plastic	White	Chipping	1	0.1	Negative
8310	1	1	116	School Store	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	116	School Store	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	103A	Classroom 103A	Yes	W1	CMU	White	Chipping	5	0.1	Negative
8310	1	1	103A	Classroom 103A	Yes	Door Frame	Metal	Grey	Chipping	5	0.1	Negative
8310	1	1	103A	Classroom 103A	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	103A	Classroom 103A	Yes	Shelf	Metal	Grey	Chipping	5	0.4	Negative
8310	1	1	103A	Classroom 103A	Yes	Univent/Shelf	Metal	Grey	Chipping	1	0.1	Negative
8310	1	1	103A	Classroom 103A	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	103A	Classroom 103A	Yes	W4	Sheetrock	White	Peeling	5	0.1	Negative
8310	1	1	103A	Classroom 103A	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	103A	Classroom 103A	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	102	Classroom 102	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	102	Classroom 102	Yes	Door Frame	Metal	Grey	Chipping	5	0.2	Negative
8310	1	1	102	Classroom 102	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	102	Classroom 102	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	102	Classroom 102	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	102	Classroom 102	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	102	Classroom 102	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom Adj Entrance in Classroom 102	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom Adj Entrance in Classroom 102	Yes	Door Frame	Metal	Brown	Chipping	4	0.1	Negative
8310	1	1	102A	Student Restroom Adj Entrance in Classroom 102	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom Adj Entrance in Classroom 102	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom Adj Entrance in Classroom 102	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom Adj Entrance in Classroom 102	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	102A	Student Restroom Adj Entrance in Classroom 102	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	Door Frame	Metal	Brown	Chipping	8	0.2	Negative
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	Counter Top	Wood	Brown	Chipping	25	0.4	Negative
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	Shelf	Wood	Blue	Chipping	40	0.4	Negative
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	Univent/Shelf	Metal	Grey	Chipping	5	0.2	Negative
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	102A	Student Restroom, Center Room, in Classroom 102	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	S13	Stairwell next to Classroom 102 (Stairwell 1)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	S13	Stairwell next to Classroom 102 (Stairwell 1)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	S13	Stairwell next to Classroom 102 (Stairwell 1)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	S13	Stairwell next to Classroom 102 (Stairwell 1)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	S13	Stairwell next to Classroom 102 (Stairwell 1)	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	S13	Stairwell next to Classroom 102 (Stairwell 1)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	102B	Classroom 102B Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	102B	Classroom 102B Closet	Yes	Door Frame	Metal	Brown	Chipping	5	0.4	Negative
8310	1	1	102B	Classroom 102B Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	102B	Classroom 102B Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	102B	Classroom 102B Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	102B	Classroom 102B Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	102B	Classroom 102B Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	115A	School Store 116	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	115A	School Store 116	Yes	Door Frame	Metal	Brown	Chipping	4	0.4	Negative
8310	1	1	115A	School Store 116	Yes	Door Frame	Metal	Brown	Chipping	2	0.4	Negative
8310	1	1	115A	School Store 116	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	115A	School Store 116	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	115A	School Store 116	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	115A	School Store 116	Yes	Univent/Shelf	Metal	Brown	Chipping	10	0.1	Negative
8310	1	1	115A	School Store 116	Yes	Pipe Cover	Plastic	White	Chipping	1	0.4	Negative
8310	1	1	115A	School Store 116	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	115A	School Store 116	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	101	Classroom 101	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	101	Classroom 101	Yes	Door Frame	Metal	Grey	Chipping	4	0.5	Negative
8310	1	1	101	Classroom 101	Yes	W2	Concrete	Orange	Chipping	1	0.1	Negative
8310	1	1	101	Classroom 101	Yes	Built-in Shelf	Metal	Grey	Chipping	7	0	Negative
8310	1	1	101	Classroom 101	Yes	Univent/Shelf	Metal	Grey	Chipping	5	0.1	Negative
8310	1	1	101	Classroom 101	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	101	Classroom 101	Yes	Cabinet	Wood	White	Chipping	5	0.1	Negative
8310	1	1	101	Classroom 101	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	101	Classroom 101	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	101	Classroom 101	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	101A	Classroom 101 Rear Storage Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	101A	Classroom 101 Rear Storage Closet	Yes	Door Frame	Metal	Brown	Chipping	2	0.5	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	101A	Classroom 101 Rear Storage Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	101A	Classroom 101 Rear Storage Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	101A	Classroom 101 Rear Storage Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	101A	Classroom 101 Rear Storage Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	101A	Classroom 101 Rear Storage Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	101B	Classroom 101 Restroom	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	101B	Classroom 101 Restroom	Yes	Door Frame	Metal	Black	Chipping	2	0.5	Negative
8310	1	1	101B	Classroom 101 Restroom	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	101B	Classroom 101 Restroom	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	101B	Classroom 101 Restroom	Yes	Door Frame	Metal	Black	Chipping	3	0.5	Negative
8310	1	1	101B	Classroom 101 Restroom	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	101B	Classroom 101 Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	101B	Classroom 101 Restroom	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	101C	Classroom 101 Front Storage Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	101C	Classroom 101 Front Storage Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	101C	Classroom 101 Front Storage Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	101C	Classroom 101 Front Storage Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	101C	Classroom 101 Front Storage Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	101C	Classroom 101 Front Storage Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	121	Gymateria	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	121	Gymateria	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	121	Gymateria	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	121	Gymateria	Yes	Door	Metal	Grey	Friction	10	0.2	Negative
8310	1	1	121	Gymateria	Yes	Door Frame	Metal	Beige	Friction	2	0.3	Negative
8310	1	1	121	Gymateria	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	121	Gymateria	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	121	Gymateria	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	121A	Gym Rear Storage	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	121A	Gym Rear Storage	Yes	Pipe	Metal	White	Chipping	7	0.4	Negative
8310	1	1	121A	Gym Rear Storage	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	121A	Gym Rear Storage	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	121A	Gym Rear Storage	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	121A	Gym Rear Storage	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	121A	Gym Rear Storage	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	121B	Girl's Restroom in Gym	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	121B	Girl's Restroom in Gym	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	121B	Girl's Restroom in Gym	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	121B	Girl's Restroom in Gym	Yes	Bench	Wood	Black	Friction	1	0.2	Negative
8310	1	1	121B	Girl's Restroom in Gym	Yes	Rod	Wood	Black	Chipping	1	0	Negative
8310	1	1	121B	Girl's Restroom in Gym	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	121B	Girl's Restroom in Gym	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	121B	Girl's Restroom in Gym	Yes	Floor	Concrete	Grey	Friction	10	0.3	Negative
8310	1	1	121C	Boy's Restroom in Gym	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	121C	Boy's Restroom in Gym	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	121C	Boy's Restroom in Gym	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	121C	Boy's Restroom in Gym	Yes	Rod	Wood	Black	Chipping	5	0	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	121C	Boy's Restroom in Gym	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	121C	Boy's Restroom in Gym	Yes	Pipe	Metal	White	Chipping	4	0.4	Negative
8310	1	1	121C	Boy's Restroom in Gym	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	121C	Boy's Restroom in Gym	Yes	Floor	Concrete	Grey	Friction	20	0.2	Negative
8310	1	1	121D	Gym Teacher's Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	121D	Gym Teacher's Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	121D	Gym Teacher's Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	121D	Gym Teacher's Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	121D	Gym Teacher's Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	121D	Gym Teacher's Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
8310	1	1	123	Kitchen	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Kitchen	Yes	Door	Metal	Brown	Chipping	5	0.4	Negative
8310	1	1	123	Kitchen	Yes	Door Frame	Metal	Brown	Chipping	10	0.4	Negative
8310	1	1	123	Kitchen	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Kitchen	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Kitchen	Yes	Serving Window Shield	Metal	White	Chipping	40	0.9	Positive
8310	1	1	123	Kitchen	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Kitchen	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	123	Kitchen	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	122	Kitchen Storage Closet	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	122	Kitchen Storage Closet	Yes	Door Frame	Metal	Brown	Chipping	5	0.5	Negative
8310	1	1	122	Kitchen Storage Closet	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	122	Kitchen Storage Closet	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	122	Kitchen Storage Closet	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	122	Kitchen Storage Closet	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	122	Kitchen Storage Closet	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	Door	Metal	Brown	Chipping	15	0.4	Negative
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	Door Frame	Metal	Gray	Chipping	2	0.6	Negative
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	Door Frame	Metal	Gray	Chipping	10	0.1	Negative
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	Railing	Metal	Gray	Chipping, Friction	10	2.8	Positive
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	W2	CMU	White	Flaking	1	0.5	Negative
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	Access Panel	Metal	Gray	Flaking	1	0.1	Negative
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	Pipe	Metal	White	Flaking, Chipping	3	0.2	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	Pipe Cover	Plastic	White	Chipping	1	0.1	Negative
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	Univent/Shelf	Metal	Yellow	Chipping	1	0	Negative
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	1	H10	Hallway near Classroom 107 through Gymnasium and Auditorium	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	W1	CMU	White	Chipping	5	0.6	Negative
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	Stall	Wood	Brown	Chipping	5	0	Negative
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	Door	Metal	Brown	Chipping	10	0.3	Negative
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	Door Frame	Metal	Brown	Chipping	3	0.5	Negative
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	Pipe	Metal	White	Flaking	20	0	Negative
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	Baseboard	Concrete	Brown	Flaking	20	0.2	Negative
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	Ceiling	Concrete	White	Flaking	20	0.1	Negative
8310	1	B	1	Building Engineer's Office (in stair Landing to Basement)	Yes	Floor	Concrete	Red	Friction	100	0.2	Negative
8310	1	B	2	Boiler Room	No	W1	Concrete	White	Flaking	70	0.1	Negative
8310	1	B	2	Boiler Room	No	W1	CMU	Brown	Flaking	10	0.2	Negative
8310	1	B	2	Boiler Room	No	Sink	Metal	Grey	Flaking	6	0.9	Positive
8310	1	B	2	Boiler Room	No	Incinerator Door	Metal	Grey	Chipping	40	0.1	Negative
8310	1	B	2	Boiler Room	No	Door	Metal	Brown	Chipping	10	0.5	Negative
8310	1	B	2	Boiler Room	No	Door	Metal	Grey	Chipping	40	0.4	Negative
8310	1	B	2	Boiler Room	No	Door Frame	Metal	Brown	Chipping	26	0.4	Negative
8310	1	B	2	Boiler Room	No	W2	CMU	Brown	Flaking	10	0.1	Negative
8310	1	B	2	Boiler Room	No	W2	Concrete	White/Grey	Flaking	200	0.2	Negative
8310	1	B	2	Boiler Room	No	W2	Concrete	Grey/Yellow	Flaking	290	0	Negative
8310	1	B	2	Boiler Room	No	Access Panel	Metal	Green	Flaking	40	0.8	Positive
8310	1	B	2	Boiler Room	No	W3	Concrete	Yellow/Green	Flaking	200	0.1	Negative
8310	1	B	2	Boiler Room	No	W3	CMU	Brown	Flaking	10	0.1	Negative
8310	1	B	2	Boiler Room	No	W3	Concrete	White	Flaking	70	0.2	Negative
8310	1	B	2	Boiler Room	No	Access Panel	Metal	Green	Flaking	40	0.8	Positive
8310	1	B	2	Boiler Room	No	Pipe	Metal	White/Grey	Chipping	25	0.2	Negative
8310	1	B	2	Boiler Room	No	W4	Concrete	White	Flaking	70	0.1	Negative

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	B	2	Boiler Room	No	W4	CMU	Brown	Flaking	10	0.2	Negative
8310	1	B	2	Boiler Room	No	Pipe	Metal	White	Chipping	10	0.3	Negative
8310	1	B	2	Boiler Room	No	Ceiling	Concrete	White	Flaking	10	0.2	Negative
8310	1	B	2	Boiler Room	No	Pipe	Metal	White	Chipping	25	0.1	Negative
8310	1	B	2	Boiler Room	No	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	B	2XA	Boiler Room Restroom	Yes	W1	CMU	White/Brown	Spalling	1	0.6	Negative
8310	1	B	2XA	Boiler Room Restroom	Yes	W2	Concrete	White	Moisture Damage	10	0.1	Negative
8310	1	B	2XA	Boiler Room Restroom	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	B	2XA	Boiler Room Restroom	Yes	Pipe	Metal	White	Chipping	5	0.1	Negative
8310	1	B	2XA	Boiler Room Restroom	Yes	W4	CMU	White	Chipping	3	0.7	Positive
8310	1	B	2XA	Boiler Room Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	B	2XA	Boiler Room Restroom	Yes	Floor	Concrete	Grey	Flaking	10	0.2	Negative
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	Pipe	Metal	Yellow	Chipping	3	0	Negative
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	Baseboard	CMU	Grey	Flaking	35	0.2	Negative
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	W2	CMU	White	Chipping	15	0	Negative
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	Baseboard	CMU	Grey	Flaking	35	0.2	Negative
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	Baseboard	CMU	Grey	Flaking	35	0.2	Negative
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	Baseboard	CMU	Grey	Flaking	35	0.2	Negative
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	B	4	Large Storage Room next to Boiler Room	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	B	4A	Smaller Storage Room next to Boiler Room	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	B	4A	Smaller Storage Room next to Boiler Room	Yes	Door Frame	Metal	Brown	Chipping	20	0.6	Negative
8310	1	B	4A	Smaller Storage Room next to Boiler Room	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	1	B	4A	Smaller Storage Room next to Boiler Room	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	B	4A	Smaller Storage Room next to Boiler Room	Yes	Shelf	Wood	White	Chipping	15	0.1	Negative
8310	1	B	4A	Smaller Storage Room next to Boiler Room	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	1	B	4A	Smaller Storage Room next to Boiler Room	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	B	4A	Smaller Storage Room next to Boiler Room	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	W1	Concrete	White	Flaking	100	0.1	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	W2	Concrete	White	Flaking	100	0.2	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	W3	Concrete	White	Flaking	135	0.3	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Pipe Cover	Plastic	White	Chipping	6	0.1	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Pipe	Metal	White	Chipping	5	0.1	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	W4	Concrete	White	Flaking	100	0.1	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Ceiling	Metal	White	Chipping	40	6.2	Positive
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Ceiling	Concrete	White	Flaking	100	0.3	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Floor	Concrete	Grey	Flaking	220	0.2	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Stringer	Metal	Brown	Flaking	2	0.4	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Riser	Concrete	Grey	Spalling	50	0.2	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Tread	Concrete	Grey	Flaking	50	0	Negative
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Railing	Metal	Brown	Friction	40	6.4	Positive
8310	1	B	SB01	Stairwell to Boiler Room and Building Engineer's Office	Yes	Stair Post	Metal	Brown	Friction	2	2.6	Positive
8310	1	B	5	Electrical Area next to Boiler Room	No	W1	N/A	N/A	None	0	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	1	B	5	Electrical Area next to Boiler Room	No	Door Frame	Concrete	Brown	Flaking	15	0.3	Negative
8310	1	B	5	Electrical Area next to Boiler Room	No	Door Frame	Metal	Brown	Flaking	15	0	Negative
8310	1	B	5	Electrical Area next to Boiler Room	No	Door Frame	Concrete	Yellow	Flaking	2	0.2	Negative
8310	1	B	5	Electrical Area next to Boiler Room	No	W2	Concrete	White	Flaking	100	0.2	Negative
8310	1	B	5	Electrical Area next to Boiler Room	No	Baseboard	Concrete	Grey	Flaking	30	0.2	Negative
8310	1	B	5	Electrical Area next to Boiler Room	No	W3	N/A	N/A	None	0	N/A	N/A
8310	1	B	5	Electrical Area next to Boiler Room	No	W4	N/A	N/A	None	0	N/A	N/A
8310	1	B	5	Electrical Area next to Boiler Room	No	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	B	5	Electrical Area next to Boiler Room	No	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	B	SX2	Stairs to Mezzanine	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	B	SX2	Stairs to Mezzanine	Yes	W2	Concrete	White/Yellow	Flaking	100	0.3	Negative
8310	1	B	SX2	Stairs to Mezzanine	Yes	W2	Concrete	Brown	Flaking	75	0.3	Negative
8310	1	B	SX2	Stairs to Mezzanine	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	1	B	SX2	Stairs to Mezzanine	Yes	W4	Concrete	White/Yellow	Flaking	100	0.3	Negative
8310	1	B	SX2	Stairs to Mezzanine	Yes	W4	Concrete	Brown	Flaking	75	0.3	Negative
8310	1	B	SX2	Stairs to Mezzanine	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	1	B	SX2	Stairs to Mezzanine	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	1	B	SX2	Stairs to Mezzanine	Yes	Riser	Concrete	Grey	Chipping	75	0.3	Negative
8310	1	B	SX2	Stairs to Mezzanine	Yes	Railing	Metal	Grey	Friction	25	2	Positive
8310	1	B	6X	Mezzanine	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	1	B	6X	Mezzanine	Yes	W2	Concrete	Green/White	Spalling	50	0.4	Negative
8310	1	B	6X	Mezzanine	Yes	W3	Concrete	Green/White	Spalling	50	0.4	Negative
8310	1	B	6X	Mezzanine	Yes	W4	Concrete	Green/White	Spalling	50	0.4	Negative
8310	1	B	6X	Mezzanine	Yes	Door	Metal	Grey	Chipping	4	0	Negative
8310	1	B	6X	Mezzanine	Yes	Ceiling	Concrete	White	Chipping	100	0.1	Negative
8310	1	B	6X	Mezzanine	Yes	Floor	Concrete	Grey	Chipping	50	0.2	Negative
8310	1	B	6X	Mezzanine	Yes	Railing	Metal	White/Grey	Flaking	50	5.1	Positive
8310	1	B	6X	Mezzanine	Yes	Floor	Concrete	Blue/Silver	Chipping	35	6.3	Positive
8310	1	1	S10	Stairwell next to Gymnasium (Stairwell 2)	Yes	Railing	Metal	Gray	Chipping, Friction	10	0.1	Negative
8310	2	1	A1	Classroom A1	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A1	Classroom A1	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A1	Classroom A1	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A1	Classroom A1	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A1	Classroom A1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A1	Classroom A1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A2	Classroom A2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A2	Classroom A2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A2	Classroom A2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A2	Classroom A2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A2	Classroom A2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A2	Classroom A2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A3	Classroom A3	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A3	Classroom A3	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A3	Classroom A3	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A3	Classroom A3	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A3	Classroom A3	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	2	1	A3	Classroom A3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A4	Classroom A4	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A4	Classroom A4	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A4	Classroom A4	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A4	Classroom A4	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A4	Classroom A4	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A4	Classroom A4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A5	Classroom A5	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A5	Classroom A5	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A5	Classroom A5	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A5	Classroom A5	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A5	Classroom A5	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A5	Classroom A5	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A6	Classroom A6	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A6	Classroom A6	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A6	Classroom A6	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A6	Classroom A6	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A6	Classroom A6	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A6	Classroom A6	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A7	Classroom A7	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A7	Classroom A7	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A7	Classroom A7	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A7	Classroom A7	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A7	Classroom A7	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A7	Classroom A7	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A8	Classroom A8	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A8	Classroom A8	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A8	Classroom A8	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A8	Classroom A8	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A8	Classroom A8	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	A8	Classroom A8	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	H1	Main Hallway	Yes	W1	N/A	N/A	None	0	N/A	N/A
8310	2	1	H1	Main Hallway	Yes	Door Frame	Metal	Gray	Chipping	4	0	Negative
8310	2	1	H1	Main Hallway	Yes	W2	N/A	N/A	None	0	N/A	N/A
8310	2	1	H1	Main Hallway	Yes	W3	N/A	N/A	None	0	N/A	N/A
8310	2	1	H1	Main Hallway	Yes	Door Frame	Metal	Gray	Chipping	2	0	Negative
8310	2	1	H1	Main Hallway	Yes	W4	N/A	N/A	None	0	N/A	N/A
8310	2	1	H1	Main Hallway	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
8310	2	1	H1	Main Hallway	Yes	Floor	N/A	N/A	None	0	N/A	N/A
8310	2	1	SR	Staff Restroom in Hallway	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	SR	Staff Restroom in Hallway	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	SR	Staff Restroom in Hallway	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	SR	Staff Restroom in Hallway	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	SR	Staff Restroom in Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	SR	Staff Restroom in Hallway	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	GR	Girls Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A



				Inspection Dates: 01/18/2022 - 2/3/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes 003542		J Hampton Moore School						
				Inspection Company: BATTA		6900 Summerdale Ave., Philadelphia, PA						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8310	2	1	GR	Girls Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	GR	Girls Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	GR	Girls Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	GR	Girls Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	GR	Girls Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	BR	Boys Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	BR	Boys Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	BR	Boys Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	BR	Boys Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	BR	Boys Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	BR	Boys Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	E	Electrical Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	E	Electrical Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	E	Electrical Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	E	Electrical Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	E	Electrical Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8310	2	1	E	Electrical Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A