

# LEAD SAFE ASSESSMENT REPORT

---



## Anna Blakiston Day Elementary School

6324 Crittenden Street  
Philadelphia, Pennsylvania 19138

May 25, 2022

Prepared For:



440 N. Broad Street  
Philadelphia, PA 19130

Prepared by:



1012 Industrial Drive  
West Berlin, NJ 08091

---

ACER Project Number: SDP059  
EP#2022-0290-6200



## **TABLE OF CONTENTS**

### **1.0 INTRODUCTION**

### **2.0 SCOPE OF WORK**

#### 2.1 Building Description

### **3.0 FINDINGS & RECOMMENDATIONS**

#### 3.1 Inspection Findings

#### 3.2 Limitations

### **4.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS**

### **5.0 APPENDICES**

#### Appendix A Lead Safe Certification Assessment



## **I.0 INTRODUCTION**

Acer Associates, LLC (ACER) has prepared this report to summarize the findings of the Lead Safe Assessment at the Anna Blakiston Day Elementary School, located at 6324 Crittenden Street in Philadelphia, Pennsylvania. The purpose of the inspection was to identify and assess painted surfaces within the school.

The inspection was completed on March 28, 2022, through April 1, 2022, by Mr. Kevin Rumbol of ACER. Mr. Rumbol (006794) are licensed Commonwealth of Pennsylvania Lead Risk Assessors. Mr. John Chuck Wilkins (006732) returned to the site on May 17, 2022 to sample the gym ceiling.

The lead survey was conducted in accordance with the requirements of Federal, State and local regulations pertaining to lead paint, including the United States Department of Housing and Urban Development (HUD) Guidelines for the Evaluation of Lead-Based Paint Hazards in Housing. The findings in this report are consistent with accepted principles and practices established and prescribed by the City of Philadelphia, Commonwealth of Pennsylvania, EPA, and HUD.

This report, and the supporting data, findings, conclusions, opinions, and the recommendations it contains, represents the result of ACER's efforts. This report is not an abatement specification and should not be used for specifying removal methods or techniques. The results, assessments, conclusions, and recommendations stated in this report are factually representative of the conditions observed at this location on the dates of the inspection. ACER cannot assume responsibility for any change in conditions that occurred after the inspection.

Any reliance on this report by a party other than The School District of Philadelphia shall be at the party's sole risk unless that party has written authorization from ACER to use this document. The purpose of this restriction is to attempt to protect the interest of parties to whom the report may not be appropriately directed.

END OF SECTION



## **2.0 INSPECTION**

### **2.1 Building Description**

Anna Blakiston Day Elementary School is a two (2) story building. Interior finishes surveyed included CMU and concrete walls, concrete ceilings, and concrete floors and floor tile floors.

Please Note: Direction “W1” corresponds to the entry wall of each room/location. Direction “W2” corresponds to the next adjacent wall in the clockwise directions and so forth for directions “W3” and “W4”.

A Viken Detection Pb200i X-ray fluorescence lead paint analyzer was used for determination of lead content in paint. Calibration checks of the PB200i were done in accordance with Performance Characteristic Sheets (PCS). Calibration checks were performed on this instrument at the beginning and end of each day's testing and at intervals of every four (4) hours during the testing. Calibration checks consist of the average of three (3) readings taken of the nominal 1.0 mg/cm<sup>2</sup> paint film. If for any reason the instrument does not maintain a consistent reproducible calibration, it is immediately removed from active service and sent back to the manufacturer for examination, service and/or recalibration.

The inspection consisted of collecting test readings of all substrate types in a room as depicted above and described as follows. One (1) test point (reading) was taken for each testing combination, except for the walls where at least four (4) were tested, to determine the amount of lead contained in the paint for that substrate. A testing combination is characterized by the room equivalent (Room 102, Main Office, etc.), component type (door, window, wall, etc.) and substrate (metal, sheetrock, etc.). The resulting test readings are then classified as POSITIVE OR NEGATIVE according to the action level, which is set in accordance with the applicable action level of the governing municipality, county, or state. The lead safe certification assessment report for this inspection is provided in Appendix A.

END OF SECTION



### 3.0 FINDINGS

From March 28, 2022, through April 1, 2022 and May 17, 2022, ACER conducted an inspection for lead-based paint at Anna Blakiston Day Elementary School, located at 6324 Crittenden Street in Philadelphia, Pennsylvania.

#### 3.1 Findings

In accordance with The Philadelphia Code, Chapter 6-800, lead-based paint is defined as greater than 0.7 mg/cm<sup>2</sup>. **No lead-based painted components were identified during the inspection.**

#### 3.2 Limitations

The inspection and sample procedures used to complete this inspection are consistent with prevalent environmental and industrial hygiene standards for lead-based paint. All reasonable efforts were made to identify the presence of lead-based paint within the inspected areas. Materials not identified in this report should be considered as not sampled. ACER cannot assume responsibility for any change in conditions that occurred after the inspection.

END OF SECTION



#### 4.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONAL

Sincerely,  
Acer Associates, LLC

Prepared By:

Kevin Rumbol  
Environmental Scientist  
PA Lead Risk Assessor #006794

Reviewed By:

Matthew J. DePalma  
Vice President



## **5.0 APPENDICES**



**Appendix A**

**Lead Safe Certification Assessment Report**



				Inspector Name and Certificate Number: Kevin Rumbol/ 006794		Day Elementary School															
				Inspection Company: ACER Associates, LLC		6324 Crittenden St, Philadelphia, PA 19138															
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
6200	1	1	100	IMC (Library)	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100	IMC (Library)	yes	W2	Concrete	Tan	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	100	IMC (Library)	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100	IMC (Library)	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100	IMC (Library)	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100	IMC (Library)	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100	IMC (Library)	yes	Duct	Metal	Tan	Flaking	50	0.2	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	100A	IMC (Library) Closet	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100A	IMC (Library) Closet	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100A	IMC (Library) Closet	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100A	IMC (Library) Closet	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100A	IMC (Library) Closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100A	IMC (Library) Closet	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100B	Hall to IMC	yes	W1	Concrete	Tan	Flaking	4	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	100B	Hall to IMC	yes	W2	Brick	Tan	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	100B	Hall to IMC	yes	W3	Concrete	Tan	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	100B	Hall to IMC	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	100B	Hall to IMC	yes	Ceiling	Concrete	White	Flaking	3	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	100B	Hall to IMC	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no		
6200	1	1	101	Classroom 101	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	101	Classroom 101	yes	W2	Concrete	Blue	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	101	Classroom 101	yes	W3	Concrete	Blue	Flaking	3	0.1	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	101	Classroom 101	yes	W4	CMU	Blue	Flaking	5	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	101	Classroom 101	yes	Ceiling	Concrete	White	Flaking	3	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	101	Classroom 101	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	102	Classroom 102	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	102	Classroom 102	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	102	Classroom 102	yes	W3	Concrete	Tan	Flaking	2	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	102	Classroom 102	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	102	Classroom 102	yes	Ceiling	Concrete	White	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	102	Classroom 102	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	103	Classroom 103	yes	W1	CMU	Blue	Flaking	1	0.5	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	103	Classroom 103	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	103	Classroom 103	yes	W3	Concrete	Blue	Flaking	23	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	103	Classroom 103	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	103	Classroom 103	yes	Ceiling	Concrete	White	Flaking	44	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	103	Classroom 103	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104	Classroom 104	yes	W1	Concrete	Tan	Flaking	3	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	104	Classroom 104	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104	Classroom 104	yes	W3	Concrete	Tan	Flaking	16	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	104	Classroom 104	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104	Classroom 104	yes	Ceiling	Concrete	Tan	Flaking	60	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	104	Classroom 104	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104B	Classroom 104 Closet ( former Restroom )	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104B	Classroom 104 Closet ( former Restroom )	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104B	Classroom 104 Closet ( former Restroom )	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104B	Classroom 104 Closet ( former Restroom )	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104B	Classroom 104 Closet ( former Restroom )	yes	Ceiling	Concrete	Blue	Flaking	1	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	104B	Classroom 104 Closet ( former Restroom )	yes	Floor	Concrete	Gray	Flaking	20	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	104C	Classroom 104 Closet	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104C	Classroom 104 Closet	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104C	Classroom 104 Closet	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104C	Classroom 104 Closet	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104C	Classroom 104 Closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	104C	Classroom 104 Closet	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	126	Boy's Restroom	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	126	Boy's Restroom	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	126	Boy's Restroom	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	126	Boy's Restroom	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	126	Boy's Restroom	yes	Ceiling	Concrete	Tan	Flaking	5	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	126	Boy's Restroom	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	105	Classroom 105	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	105	Classroom 105	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	105	Classroom 105	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	105	Classroom 105	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	105	Classroom 105	yes	Ceiling	Concrete	W	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no		
6200	1	1	105	Classroom 105	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	106	Classroom 106	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	106	Classroom 106	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	106	Classroom 106	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	1	106	Classroom 106	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		

				Lead Safe Certification Assessment Report																
				Inspector Name and Certificate Number: Kevin Rumbol/ 006794		Day Elementary School														
				Inspection Company: ACER Associates, LLC		6324 Crittenden St, Philadelphia, PA 19138														
	E l e m e n t	F l o o r			Student/ Teacher Occupied (yes/no)															
ULCS#			Space #	On-Site Room Name		Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
6200	1	1	106	Classroom 106	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	106	Classroom 106	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	107	Classroom 107	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	107	Classroom 107	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	107	Classroom 107	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	107	Classroom 107	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	107	Classroom 107	yes	Ceiling	Concrete	White	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	107	Classroom 107	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	108	Classroom 108	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	108	Classroom 108	yes	W2	Concrete	Blue	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	108	Classroom 108	yes	W3	Concrete	Blue	Flaking	3	0.2	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	108	Classroom 108	yes	W4	CMU	Blue	Flaking	5	0.4	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	108	Classroom 108	yes	Ceiling	Concrete	White	Flaking	3	0.5	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	108	Classroom 108	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109	Women Teacher's Lounge	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109	Women Teacher's Lounge	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109	Women Teacher's Lounge	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109	Women Teacher's Lounge	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109	Women Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109	Women Teacher's Lounge	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109A	Women's Restroom	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109A	Women's Restroom	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109A	Women's Restroom	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109A	Women's Restroom	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109A	Women's Restroom	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109A	Women's Restroom	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109B	IT Data Closet in Women Teacher's Lounge	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109B	IT Data Closet in Women Teacher's Lounge	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109B	IT Data Closet in Women Teacher's Lounge	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109B	IT Data Closet in Women Teacher's Lounge	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109B	IT Data Closet in Women Teacher's Lounge	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	109B	IT Data Closet in Women Teacher's Lounge	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	110	Storage Room between Lounge and Counselor's Office	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	110	Storage Room between Lounge and Counselor's Office	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	110	Storage Room between Lounge and Counselor's Office	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	110	Storage Room between Lounge and Counselor's Office	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	110	Storage Room between Lounge and Counselor's Office	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	110	Storage Room between Lounge and Counselor's Office	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	111	Counselor's Office	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	111	Counselor's Office	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	111	Counselor's Office	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	111	Counselor's Office	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	111	Counselor's Office	yes	Ceiling	Concrete	White	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	111	Counselor's Office	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112	Principal's Office	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112	Principal's Office	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112	Principal's Office	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112	Principal's Office	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112	Principal's Office	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112	Principal's Office	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112A	Principal's Restroom	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112A	Principal's Restroom	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112A	Principal's Restroom	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112A	Principal's Restroom	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112A	Principal's Restroom	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112A	Principal's Restroom	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113	Main Office	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113	Main Office	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113	Main Office	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113	Main Office	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113	Main Office	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113	Main Office	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113A	Main Office Closet	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113A	Main Office Closet	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113A	Main Office Closet	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113A	Main Office Closet	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

					Lead Safe Certification Assessment Report															
					Inspector Name and Certificate Number: Kevin Rumbol/ 006794															
					Day Elementary School															
					6324 Crittenden St, Philadelphia, PA 19138															
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
6200	1	1	113A	Main Office Closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	113A	Main Office Closet	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115	Girl's Restroom	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115	Girl's Restroom	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115	Girl's Restroom	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115	Girl's Restroom	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115	Girl's Restroom	yes	Ceiling	Concrete	Tan	Flaking	36	0.2	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	115	Girl's Restroom	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115A	Custodial Closet	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115A	Custodial Closet	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115A	Custodial Closet	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115A	Custodial Closet	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115A	Custodial Closet	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	115A	Custodial Closet	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116	Nurse's Office	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116	Nurse's Office	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116	Nurse's Office	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116	Nurse's Office	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116	Nurse's Office	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117	Nurse's Waiting Area	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117	Nurse's Waiting Area	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117	Nurse's Waiting Area	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117	Nurse's Waiting Area	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117	Nurse's Waiting Area	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117	Nurse's Waiting Area	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116A	Nurse's Restroom	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116A	Nurse's Restroom	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116A	Nurse's Restroom	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116A	Nurse's Restroom	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116A	Nurse's Restroom	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116A	Nurse's Restroom	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116B	Nurse's Supply Closet	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116B	Nurse's Supply Closet	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116B	Nurse's Supply Closet	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116B	Nurse's Supply Closet	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116B	Nurse's Supply Closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	116B	Nurse's Supply Closet	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117A	Nurse's Foyer	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117A	Nurse's Foyer	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117A	Nurse's Foyer	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117A	Nurse's Foyer	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117A	Nurse's Foyer	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117A	Nurse's Foyer	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	118	Storage across from Main Office & Auditorium	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	118	Storage across from Main Office & Auditorium	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	118	Storage across from Main Office & Auditorium	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	118	Storage across from Main Office & Auditorium	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	118	Storage across from Main Office & Auditorium	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	118	Storage across from Main Office & Auditorium	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117B	School Police Office	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117B	School Police Office	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117B	School Police Office	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117B	School Police Office	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117B	School Police Office	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	117B	School Police Office	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	119	Girl's Restroom across from Auditorium	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	119	Girl's Restroom across from Auditorium	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	119	Girl's Restroom across from Auditorium	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	119	Girl's Restroom across from Auditorium	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	119	Girl's Restroom across from Auditorium	yes	Ceiling	Concrete	White	Flaking	13	0.2	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	119	Girl's Restroom across from Auditorium	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	119A	Storage #1 adjacent to Girl's Restroom	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A							

				Inspector Name and Certificate Number: Kevin Rumbol/ 006794		Day Elementary School														
				Inspection Company: ACER Associates, LLC		6324 Crittenden St, Philadelphia, PA 19138														
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
6200	1	1	119B	Storage #2 adjacent to Girl's Restroom	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	119B	Storage #2 adjacent to Girl's Restroom	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	119B	Storage #2 adjacent to Girl's Restroom	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121	Custodial Storeroom ( former Boy's Shower)	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121	Custodial Storeroom ( former Boy's Shower)	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121	Custodial Storeroom ( former Boy's Shower)	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121	Custodial Storeroom ( former Boy's Shower)	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121	Custodial Storeroom ( former Boy's Shower)	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121	Custodial Storeroom ( former Boy's Shower)	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121A	Custodial Storeroom (former Boy's Locker Room)	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121A	Custodial Storeroom (former Boy's Locker Room)	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121A	Custodial Storeroom (former Boy's Locker Room)	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121A	Custodial Storeroom (former Boy's Locker Room)	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121A	Custodial Storeroom (former Boy's Locker Room)	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121A	Custodial Storeroom (former Boy's Locker Room)	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121B	Boy's Restroom across from Auditorium	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121B	Boy's Restroom across from Auditorium	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121B	Boy's Restroom across from Auditorium	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121B	Boy's Restroom across from Auditorium	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121B	Boy's Restroom across from Auditorium	yes	Ceiling	Concrete	White	Flaking	3	0.2	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	121B	Boy's Restroom across from Auditorium	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	121B	Boy's Restroom across from Auditorium	yes	Duct	Metal	Tan	Flaking	3	0.2	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	122	Kitchen	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	122	Kitchen	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	122	Kitchen	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	122	Kitchen	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	122	Kitchen	no	Ceiling	Concrete	Tan	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no	
6200	1	1	122	Kitchen	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	122	Kitchen	no	Roll-up Door	Metal	Gray	Flaking	20	0.2	Negative	None	N/A	Negative	No	No	no	No	
6200	1	1	122A	Kitchen Closet	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
6200	1	1	122A	Kitchen Closet	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
6200	1	1	122A	Kitchen Closet	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
6200	1	1	122A	Kitchen Closet	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
6200	1	1	122A	Kitchen Closet	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
6200	1	1	122A	Kitchen Closet	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
6200	1	1	124	Cafeteria/Gymnasium	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	124	Cafeteria/Gymnasium	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	124	Cafeteria/Gymnasium	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	124	Cafeteria/Gymnasium	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	124	Cafeteria/Gymnasium	yes	Ceiling	Concrete	Tan	Flaking	20	0.3	Negative	None	N/A	Negative	no	No	no	no	
6200	1	1	124	Cafeteria/Gymnasium	yes	Truss Assembly	Metal	Tan	N/A	0	0.1	Negative	N/A	N/A	N/A	No	No	No	No	
6200	1	1	124	Cafeteria/Gymnasium	yes	Duct	Metal	Yellow	N/A	0	0.1	Negative	N/A	N/A	N/A	No	No	no	No	
6200	1	1	124	Cafeteria/Gymnasium	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125	Auditorium	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125	Auditorium	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125	Auditorium	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125	Auditorium	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125	Auditorium	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125A	Auditorium Exit Vestibule on Stage Left	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125A	Auditorium Exit Vestibule on Stage Left	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125A	Auditorium Exit Vestibule on Stage Left	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125A	Auditorium Exit Vestibule on Stage Left	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125A	Auditorium Exit Vestibule on Stage Left	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125A	Auditorium Exit Vestibule on Stage Left	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125B	Auditorium Entrance Vestibule on Stage Right	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125B	Auditorium Entrance Vestibule on Stage Right	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125B	Auditorium Entrance Vestibule on Stage Right	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125B	Auditorium Entrance Vestibule on Stage Right	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125B	Auditorium Entrance Vestibule on Stage Right	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	125B	Auditorium Entrance Vestibule on Stage Right	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	H11	Hallway from Main Entrance Lobby to Classroom 104	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A							



				Lead Safe Certification Assessment Report																				
				Inspector Name and Certificate Number: Kevin Rumbol/ 006794					Day Elementary School															
				Inspection Company: ACER Associates, LLC					6324 Crittenden St, Philadelphia, PA 19138															
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
6200	1	1	H13	Hallway from Main Entrance Lobby to Kitchen	yes	Ceiling	Concrete	White	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	1	H13	Hallway from Main Entrance Lobby to Kitchen	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	S12	Stairwell next to Girl's Restroom	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	S12	Stairwell next to Girl's Restroom	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	S12	Stairwell next to Girl's Restroom	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	S12	Stairwell next to Girl's Restroom	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	S12	Stairwell next to Girl's Restroom	yes	Ceiling	Metal	White	Flaking	15	0.5	Negative	None	N/A	Negative	No	No	no	no					
6200	1	1	S12	Stairwell next to Girl's Restroom	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	S14	Stairwell adjacent to Boy's Restroom	yes	W1	CMU	Tan	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	1	S14	Stairwell adjacent to Boy's Restroom	yes	W2	CMU	Tan	Flaking	14	0.5	Negative	None	N/A	Negative	No	No	no	no					
6200	1	1	S14	Stairwell adjacent to Boy's Restroom	yes	W3	CMU	Tan	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	1	S14	Stairwell adjacent to Boy's Restroom	yes	W4	CMU	Tan	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	1	S14	Stairwell adjacent to Boy's Restroom	yes	Ceiling	Concrete	Tan	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	1	S14	Stairwell adjacent to Boy's Restroom	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	127	Main Entrance Lobby	yes	W1	Concrete	Tan	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	1	127	Main Entrance Lobby	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	127	Main Entrance Lobby	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	127	Main Entrance Lobby	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	127	Main Entrance Lobby	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	1	127	Main Entrance Lobby	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	120	Fan Room near Gym	no	W1	Brick	White	Flaking	180	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	W2	Brick	White	Flaking	100	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	W3	Brick	White	Flaking	50	0.1	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	120	Fan Room near Gym	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	120	Fan Room near Gym	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	120	Fan Room near Gym	no	Door (W1)	Metal	Brown	Flaking	20	0.1	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	Door Casing (W1)	Metal	Brown	Flaking	20	0.1	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	Door (W3)	Metal	Brown	Flaking	18	0.1	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	Door Casing (W3)	Metal	Brown	Flaking	18	0.1	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	Auditorium Fan Unit	Metal	Yellow	Flaking	20	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	Gym Fan Unit	Metal	Yellow	Flaking	20	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	Kitchen Exhaust Fan	Metal	Yellow	Flaking	20	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	Bathroom Exhaust Fan	Metal	Yellow	Flaking	20	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	120	Fan Room near Gym	no	I-Beam	Metal	Green	Flaking	60	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	201	Classroom 201	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	201	Classroom 201	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	201	Classroom 201	yes	W3	Concrete	Tan	Flaking	1	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	201	Classroom 201	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	201	Classroom 201	yes	Ceiling	Concrete	White	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	201	Classroom 201	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	202	Classroom 202	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	202	Classroom 202	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	202	Classroom 202	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	202	Classroom 202	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	202	Classroom 202	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	202	Classroom 202	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	203	Classroom 203	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	203	Classroom 203	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	203	Classroom 203	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	203	Classroom 203	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	203	Classroom 203	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	203	Classroom 203	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	204	Classroom 204	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	204	Classroom 204	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	204	Classroom 204	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	204	Classroom 204	yes	W4	Concrete	Tan	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	204	Classroom 204	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	204	Classroom 204	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	205	Classroom 205	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	205	Classroom 205	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	205	Classroom 205	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	205	Classroom 205	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	205	Classroom 205	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	205	Classroom 205	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	206	Classroom 206	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	206																					

				Inspector Name and Certificate Number: Kevin Rumbol/ 006794		Day Elementary School															Comments/ Description/ Notes
				Inspection Company: ACER Associates, LLC		6324 Crittenden St, Philadelphia, PA 19138															
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)		
6200	1	2	206	Classroom 206	yes	W3	Concrete	Pink	Flaking	1	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	206	Classroom 206	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	206	Classroom 206	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	206	Classroom 206	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	207	Office 207	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207	Office 207	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207	Office 207	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207	Office 207	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207	Office 207	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207	Office 207	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207	Office 207	yes	Radiator Cover	Metal	Tan	Flaking	2	0.1	Negative	None	N/A	Negative	No	No	no	No		
6200	1	2	208	Classroom 208	yes	W1	CMU	Pink	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	208	Classroom 208	yes	W1	CMU	White	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	208	Classroom 208	yes	W2	CMU	Pink	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	208	Classroom 208	yes	W2	CMU	White	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	208	Classroom 208	yes	W3	Concrete	Pink	Flaking	1	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	208	Classroom 208	yes	W3	Concrete	White	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	208	Classroom 208	yes	W4	CMU	Pink	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	208	Classroom 208	yes	W4	CMU	White	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	208	Classroom 208	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	208	Classroom 208	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	209	Classroom 209	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	209	Classroom 209	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	209	Classroom 209	yes	W3	Concrete	Blue	Flaking	3	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	209	Classroom 209	yes	W4	N/A	N/A	N/A	0	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	209	Classroom 209	yes	Ceiling	Concrete	White	Flaking	10	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	209	Classroom 209	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	210	Classroom 210	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	210	Classroom 210	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	210	Classroom 210	yes	W3	Concrete	Tan	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	210	Classroom 210	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	210	Classroom 210	yes	Ceiling	Concrete	White	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	210	Classroom 210	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	211	Classroom 211	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	211	Classroom 211	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	211	Classroom 211	yes	W3	Concrete	Tan	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	211	Classroom 211	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	211	Classroom 211	yes	Ceiling	Concrete	White	Flaking	6	0.4	Negative	None	N/A	Negative	No	No	no	no		
6200	1	2	211	Classroom 211	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6200	1	2	212	Closet adjacent to Girl's Restroom	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	212	Closet adjacent to Girl's Restroom	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	212	Closet adjacent to Girl's Restroom	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	212	Closet adjacent to Girl's Restroom	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	212	Closet adjacent to Girl's Restroom	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	212	Closet adjacent to Girl's Restroom	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	213PC	Pipe Chase off Closet adjacent to Girl's Restroom	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	213PC	Pipe Chase off Closet adjacent to Girl's Restroom	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	213PC	Pipe Chase off Closet adjacent to Girl's Restroom	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	213PC	Pipe Chase off Closet adjacent to Girl's Restroom	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	213PC	Pipe Chase off Closet adjacent to Girl's Restroom	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	213PC	Pipe Chase off Closet adjacent to Girl's Restroom	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216	Office next to Office 207	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216	Office next to Office 207	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216	Office next to Office 207	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216	Office next to Office 207	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216	Office next to Office 207	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216	Office next to Office 207	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216B	Gender Neutral Restroom	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216B	Gender Neutral Restroom	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216B	Gender Neutral Restroom	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216B	Gender Neutral Restroom	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216B	Gender Neutral Restroom	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	216B	Gender Neutral Restroom	yes	Floor	N/A</														

				Inspector Name and Certificate Number: Kevin Rumbol/ 006794		Day Elementary School																		
				Inspection Company: ACER Associates, LLC		6324 Crittenden St, Philadelphia, PA 19138																		
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
6200	1	2	218	Closet adjacent to Boy's Restroom	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	218	Closet adjacent to Boy's Restroom	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	218	Closet adjacent to Boy's Restroom	no	Ceiling	Concrete	White	Flaking	3	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	218	Closet adjacent to Boy's Restroom	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	216A	Closet in Office next to Office 207	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	216A	Closet in Office next to Office 207	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	216A	Closet in Office next to Office 207	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	216A	Closet in Office next to Office 207	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	216A	Closet in Office next to Office 207	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	216A	Closet in Office next to Office 207	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H14	Stairwell Hallway adjacent to Boy's Restroom	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H14	Stairwell Hallway adjacent to Boy's Restroom	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H14	Stairwell Hallway adjacent to Boy's Restroom	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H14	Stairwell Hallway adjacent to Boy's Restroom	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H14	Stairwell Hallway adjacent to Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H14	Stairwell Hallway adjacent to Boy's Restroom	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H219	Hallway from Classrooms 201 to 208	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H219	Hallway from Classrooms 201 to 208	yes	W2	CMU	Yellow	Flaking	1	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	H219	Hallway from Classrooms 201 to 208	yes	W2	CMU	White	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	H219	Hallway from Classrooms 201 to 208	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	H219	Hallway from Classrooms 201 to 208	yes	W4	CMU	Yellow	Flaking	1	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	H219	Hallway from Classrooms 201 to 208	yes	W4	CMU	White	Flaking	7	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	H219	Hallway from Classrooms 201 to 208	yes	Ceiling	Concrete	White	Flaking	4	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	H219	Hallway from Classrooms 201 to 208	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	S22	Stairwell across from Classroom 202	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	S22	Stairwell across from Classroom 202	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	S22	Stairwell across from Classroom 202	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	S22	Stairwell across from Classroom 202	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	2	S22	Stairwell across from Classroom 202	yes	Ceiling	Concrete	White	Flaking	15	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	2	S22	Stairwell across from Classroom 202	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	A	AT1	1st Floor Attic	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	A	AT1	1st Floor Attic	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	A	AT1	1st Floor Attic	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	A	AT1	1st Floor Attic	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	A	AT1	1st Floor Attic	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	A	AT1	1st Floor Attic	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	B	Generator Room	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	B	Generator Room	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	B	Generator Room	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	B	Generator Room	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	B	Generator Room	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	B	Generator Room	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	1	Old Boiler Room	no	W1	Concrete	White	Flaking	342	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	W1	Concrete	Gray	Flaking	136	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	W2	Concrete	White	Flaking	508	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	W2	Concrete	Gray	Flaking	84	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	W3	Concrete	White	Flaking	390	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	W3	Concrete	Gray	Flaking	234	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	W4	Concrete	White	Flaking	293	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	W4	Concrete	Gray	Flaking	160	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	Ceiling	Concrete	White	Flaking	1440	0.3	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	Floor	Concrete	Gray	Flaking	1436	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	Columns	Concrete	White	Flaking	180	0.4	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	Columns	Concrete	Gray	Flaking	99	0.2	Negative	None	N/A	Negative	No	No	no	no					
6200	1	B	1	Old Boiler Room	no	Boilers	Metal	Silver	Flaking	180	0.2	Negative	None	N/A	Negative	No	No	no	No					
6200	1	B	1	Old Boiler Room	no	Electrical Panels	Metal	Green	Flaking	28	0.2	Negative	None	N/A	Negative	No	No	no	No					
6200	1	B	S02	Old Boiler Room Metal Stairs #1	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	S02	Old Boiler Room Metal Stairs #1	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B	S02	Old Boiler Room Metal Stairs #1	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
6200	1	B																						



				Lead Safe Certification Assessment Report																Comments/ Description/ Notes		
				Inspector Name and Certificate Number: Kevin Rumbol/ 006794		Day Elementary School																
				Inspection Company: ACER Associates, LLC		6324 Crittenden St, Philadelphia, PA 19138																
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)			
6200	1	B	S03	Old Boiler Room Metal Stairs #2	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	S03	Old Boiler Room Metal Stairs #2	no	Railings	Metal	Gray	Flaking	15	0.5	Negative	None	N/A	Negative	No	No	no	No			
6200	1	B	S03	Old Boiler Room Metal Stairs #2	no	Stringer	Metal	Gray	Flaking	12	0.1	Negative	None	N/A	Negative	No	No	no	No			
6200	1	B	S03	Old Boiler Room Metal Stairs #2	no	Threads	Metal	Gray	Flaking	52	0.1	Negative	None	N/A	Negative	No	No	no	No			
6200	1	B	2	Electrical/Tank Room	no	W1	Concrete	White	Flaking	8	0.4	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	2	Electrical/Tank Room	no	W1	Concrete	Gray	Flaking	4	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	2	Electrical/Tank Room	no	W2	Concrete	White	Flaking	166	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	2	Electrical/Tank Room	no	W2	Concrete	Gray	Flaking	25	0.2	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	2	Electrical/Tank Room	no	W3	Concrete	White	Flaking	96	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	2	Electrical/Tank Room	no	W3	Concrete	Gray	Flaking	96	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	2	Electrical/Tank Room	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	2	Electrical/Tank Room	no	Ceiling	Concrete	White	Flaking	722	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	2	Electrical/Tank Room	no	Floor	Concrete	Gray	Flaking	562	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	2	Electrical/Tank Room	no	Electrical Conduit Box	Metal	Gray	Flaking	15	0.1	Negative	None	N/A	Negative	No	No	no	No			
6200	1	B	3	Crawlspace accessed from Electrical/Tank Room	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	3	Crawlspace accessed from Electrical/Tank Room	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	3	Crawlspace accessed from Electrical/Tank Room	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	3	Crawlspace accessed from Electrical/Tank Room	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	3	Crawlspace accessed from Electrical/Tank Room	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	3	Crawlspace accessed from Electrical/Tank Room	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	4	Maintenance Staff Locker Room	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	4	Maintenance Staff Locker Room	no	W2	CMU	Gray	Flaking	1	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	4	Maintenance Staff Locker Room	no	W3	Concrete	Blue	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	4	Maintenance Staff Locker Room	no	W3	Concrete	Gray	Flaking	4	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	4	Maintenance Staff Locker Room	no	W4	Concrete	Blue	Flaking	2	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	4	Maintenance Staff Locker Room	no	W4	Concrete	Gray	Flaking	4	0.2	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	4	Maintenance Staff Locker Room	no	Ceiling	Concrete	White	Flaking	2	0.2	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	4	Maintenance Staff Locker Room	no	Floor	Concrete	Gray	Flaking	1	0.2	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	4	Maintenance Staff Locker Room	no	Duct	Metal	Tan	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	No			
6200	1	B	004A	Maintenance Staff Restroom	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	004A	Maintenance Staff Restroom	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	004A	Maintenance Staff Restroom	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	004A	Maintenance Staff Restroom	no	W4	Concrete	Green	Flaking	4	0.4	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	004A	Maintenance Staff Restroom	no	Ceiling	Concrete	White	Flaking	1	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	004A	Maintenance Staff Restroom	no	Floor	Concrete	Gray	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	004A	Maintenance Staff Restroom	no	Duct	Metal	Tan	Flaking	5	0.3	Negative	None	N/A	Negative	No	No	no	No			
6200	1	B	004B	Maintenance Staff Locker Room Closet	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	004B	Maintenance Staff Locker Room Closet	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	004B	Maintenance Staff Locker Room Closet	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	004B	Maintenance Staff Locker Room Closet	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	004B	Maintenance Staff Locker Room Closet	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	004B	Maintenance Staff Locker Room Closet	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	5	Building Engineer's Office	no	W1	CMU	Tan	Flaking	4	0.5	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	5	Building Engineer's Office	no	W2	Concrete	Tan	Flaking	70	0.4	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	5	Building Engineer's Office	no	W3	Concrete	Tan	Flaking	22	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	5	Building Engineer's Office	no	W4	Concrete	Tan	Flaking	2	0.2	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	5	Building Engineer's Office	no	Ceiling	Concrete	White	Flaking	59	0.4	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	5	Building Engineer's Office	no	Ceiling	Concrete	Gray	Flaking	55	0.4	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	5	Building Engineer's Office	no	Floor	Concrete	Gray	Flaking	20	0.3	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	5	Building Engineer's Office	no	Duct	Metal	Gray	Flaking	25	0.3	Negative	None	N/A	Negative	No	No	no	No			
6200	1	B	005A	Building Engineer's Restroom	no	W1	CMU	Tan	Flaking	5	0.5	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	005A	Building Engineer's Restroom	no	W2	CMU	Tan	Flaking	14	0.4	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	005A	Building Engineer's Restroom	no	W3	CMU	Tan	Flaking	15	0.4	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	005A	Building Engineer's Restroom	no	W4	CMU	Tan	Flaking	24	0.4	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	005A	Building Engineer's Restroom	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	005A	Building Engineer's Restroom	no	Floor	CMU	Tan	Flaking	4	0.2	Negative	None	N/A	Negative	No	No	no	no			
6200	1	B	005B	Building Engineer's Closet	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	005B	Building Engineer's Closet	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	005B	Building Engineer's Closet	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	005B	Building Engineer's Closet	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	005B	Building Engineer's Closet	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	005B	Building Engineer's Closet	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	007PC	Pipe Chase adjacent to 007 Space	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	007PC	Pipe Chase adjacent to 007 Space	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	007PC	Pipe Chase adjacent to 007 Space	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	007PC	Pipe Chase adjacent to 007 Space	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
6200	1	B	007PC	Pipe Chase adjacent to 007 Space	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			



				Lead Safe Certification Assessment Report																
				Inspector Name and Certificate Number: Kevin Rumbol/ 006794				Day Elementary School												
				Inspection Company: ACER Associates, LLC				6324 Crittenden St, Philadelphia, PA 19138												
	E l e m e n t	F l o o r			Student/ Teacher Occupied (yes/no)															
ULCS#			Space #	On-Site Room Name		Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
6200	1	B	006DPC	Pipe Chase adjacent to 006D Space	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	006DPC	Pipe Chase adjacent to 006D Space	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	006DPC	Pipe Chase adjacent to 006D Space	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	006DPC	Pipe Chase adjacent to 006D Space	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001A	Water Treatment Room	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001A	Water Treatment Room	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001A	Water Treatment Room	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001A	Water Treatment Room	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001A	Water Treatment Room	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001A	Water Treatment Room	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001B	New Boiler Room	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001B	New Boiler Room	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001B	New Boiler Room	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001B	New Boiler Room	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001B	New Boiler Room	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	B	001B	New Boiler Room	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS1	Crawl Space accessed from Boiler Room	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS1	Crawl Space accessed from Boiler Room	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS1	Crawl Space accessed from Boiler Room	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS1	Crawl Space accessed from Boiler Room	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS1	Crawl Space accessed from Boiler Room	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS1	Crawl Space accessed from Boiler Room	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS2	Crawl Space - Electrical Room	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS2	Crawl Space - Electrical Room	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS2	Crawl Space - Electrical Room	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS2	Crawl Space - Electrical Room	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS2	Crawl Space - Electrical Room	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	C	CS2	Crawl Space - Electrical Room	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207A	Office 207 Closet	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207A	Office 207 Closet	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207A	Office 207 Closet	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207A	Office 207 Closet	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207A	Office 207 Closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	207A	Office 207 Closet	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	219	Service Closet next to Classroom 202	no	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	219	Service Closet next to Classroom 202	no	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	219	Service Closet next to Classroom 202	no	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	219	Service Closet next to Classroom 202	no	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	219	Service Closet next to Classroom 202	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	2	219	Service Closet next to Classroom 202	no	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112B	Principal's Office Closet	yes	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112B	Principal's Office Closet	yes	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112B	Principal's Office Closet	yes	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112B	Principal's Office Closet	yes	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112B	Principal's Office Closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6200	1	1	112B	Principal's Office Closet	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	