

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	IMC (Library)	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library)	W2	Concrete	Tan	Flaking	1	0.2	Negative
1	1	IMC (Library)	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library)	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library)	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library)	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library)	Duct	Metal	Tan	Flaking	50	0.2	Negative
1	1	IMC (Library) Closet	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library) Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library) Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library) Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library) Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	IMC (Library) Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Hall to IMC	W1	Concrete	Tan	Flaking	4	0.3	Negative
1	1	Hall to IMC	W2	Brick	Tan	Flaking	1	0.2	Negative
1	1	Hall to IMC	W3	Concrete	Tan	Flaking	5	0.3	Negative
1	1	Hall to IMC	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Hall to IMC	Ceiling	Concrete	White	Flaking	3	0.4	Negative
1	1	Hall to IMC	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 101	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 101	W2	Concrete	Blue	Flaking	1	0.2	Negative
1	1	Classroom 101	W3	Concrete	Blue	Flaking	3	0.1	Negative
1	1	Classroom 101	W4	CMU	Blue	Flaking	5	0.4	Negative
1	1	Classroom 101	Ceiling	Concrete	White	Flaking	3	0.3	Negative
1	1	Classroom 101	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 102	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 102	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 102	W3	Concrete	Tan	Flaking	2	0.3	Negative
1	1	Classroom 102	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 102	Ceiling	Concrete	White	Flaking	5	0.3	Negative
1	1	Classroom 102	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 103	W1	CMU	Blue	Flaking	1	0.5	Negative
1	1	Classroom 103	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 103	W3	Concrete	Blue	Flaking	23	0.3	Negative
1	1	Classroom 103	W4	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Classroom 103	Ceiling	Concrete	White	Flaking	44	0.3	Negative
1	1	Classroom 103	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104	W1	Concrete	Tan	Flaking	3	0.4	Negative
1	1	Classroom 104	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104	W3	Concrete	Tan	Flaking	16	0.4	Negative
1	1	Classroom 104	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104	Ceiling	Concrete	Tan	Flaking	60	0.3	Negative
1	1	Classroom 104	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet ( former Restroom )	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet ( former Restroom )	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet ( former Restroom )	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet ( former Restroom )	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet ( former Restroom )	Ceiling	Concrete	Blue	Flaking	1	0.3	Negative
1	1	Classroom 104 Closet ( former Restroom )	Floor	Concrete	Gray	Flaking	20	0.4	Negative
1	1	Classroom 104 Closet	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom	Ceiling	Concrete	Tan	Flaking	5	0.4	Negative
1	1	Boy's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105	Ceiling	Concrete	W	Flaking	1	0.2	Negative
1	1	Classroom 105	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 106	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 106	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 106	W3	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Classroom 106	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 106	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 106	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 107	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 107	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 107	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 107	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 107	Ceiling	Concrete	White	Flaking	5	0.3	Negative
1	1	Classroom 107	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 108	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 108	W2	Concrete	Blue	Flaking	1	0.2	Negative
1	1	Classroom 108	W3	Concrete	Blue	Flaking	3	0.2	Negative
1	1	Classroom 108	W4	CMU	Blue	Flaking	5	0.4	Negative
1	1	Classroom 108	Ceiling	Concrete	White	Flaking	3	0.5	Negative
1	1	Classroom 108	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Women Teacher's Lounge	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Women Teacher's Lounge	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Women Teacher's Lounge	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Women Teacher's Lounge	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Women Teacher's Lounge	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Women Teacher's Lounge	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Women's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Women's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Women's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Women's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Women's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Women's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	IT Data Closet in Women Teacher's Lounge	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	IT Data Closet in Women Teacher's Lounge	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	IT Data Closet in Women Teacher's Lounge	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	IT Data Closet in Women Teacher's Lounge	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	IT Data Closet in Women Teacher's Lounge	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	IT Data Closet in Women Teacher's Lounge	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage Room between Lounge and Counselor's Office	W1	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Storage Room between Lounge and Counselor's Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage Room between Lounge and Counselor's Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage Room between Lounge and Counselor's Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage Room between Lounge and Counselor's Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage Room between Lounge and Counselor's Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Counselor's Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Counselor's Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Counselor's Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Counselor's Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Counselor's Office	Ceiling	Concrete	White	Flaking	1	0.4	Negative
1	1	Counselor's Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office Closet	W1	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Main Office Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Office Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom	Ceiling	Concrete	Tan	Flaking	36	0.2	Negative
1	1	Girl's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Closet	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Waiting Area	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Waiting Area	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Waiting Area	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Waiting Area	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Waiting Area	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Waiting Area	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Nurse's Supply Closet	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Supply Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Supply Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Supply Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Supply Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Supply Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Foyer	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Foyer	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Foyer	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Foyer	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Foyer	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Nurse's Foyer	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage across from Main Office & Auditorium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage across from Main Office & Auditorium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage across from Main Office & Auditorium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage across from Main Office & Auditorium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage across from Main Office & Auditorium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage across from Main Office & Auditorium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	School Police Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	School Police Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	School Police Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	School Police Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	School Police Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	School Police Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom across from Auditorium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom across from Auditorium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom across from Auditorium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom across from Auditorium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom across from Auditorium	Ceiling	Concrete	White	Flaking	13	0.2	Negative
1	1	Girl's Restroom across from Auditorium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #1 adjacent to Girl's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #1 adjacent to Girl's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #1 adjacent to Girl's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #1 adjacent to Girl's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #1 adjacent to Girl's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Storage #1 adjacent to Girl's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #2 adjacent to Girl's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #2 adjacent to Girl's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #2 adjacent to Girl's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #2 adjacent to Girl's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #2 adjacent to Girl's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage #2 adjacent to Girl's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom ( former Boy's Shower)	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom ( former Boy's Shower)	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom ( former Boy's Shower)	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom ( former Boy's Shower)	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom ( former Boy's Shower)	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom ( former Boy's Shower)	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom (former Boy's Locker Room)	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom (former Boy's Locker Room)	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom (former Boy's Locker Room)	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom (former Boy's Locker Room)	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom (former Boy's Locker Room)	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Storeroom (former Boy's Locker Room)	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom across from Auditorium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom across from Auditorium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom across from Auditorium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom across from Auditorium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom across from Auditorium	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	1	Boy's Restroom across from Auditorium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom across from Auditorium	Duct	Metal	Tan	Flaking	3	0.2	Negative
1	1	Kitchen	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	Ceiling	Concrete	Tan	Flaking	1	0.4	Negative
1	1	Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	Roll-up Door	Metal	Gray	Flaking	20	0.2	Negative
1	1	Kitchen Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Kitchen Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Kitchen Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Kitchen Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Kitchen Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Kitchen Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Cafeteria/Gymnasium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Cafeteria/Gymnasium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Cafeteria/Gymnasium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Cafeteria/Gymnasium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Cafeteria/Gymnasium	Ceiling	Concrete	Tan	Flaking	20	0.3	Negative
1	1	Cafeteria/Gymnasium	Truss Assembly	Metal	Tan	N/A	0	0.1	Negative
1	1	Cafeteria/Gymnasium	Duct	Metal	Yellow	N/A	0	0.1	Negative
1	1	Cafeteria/Gymnasium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Exit Vestibule on Stage Left	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Exit Vestibule on Stage Left	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Exit Vestibule on Stage Left	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Exit Vestibule on Stage Left	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Exit Vestibule on Stage Left	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Exit Vestibule on Stage Left	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Entrance Vestibule on Stage Right	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Entrance Vestibule on Stage Right	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Entrance Vestibule on Stage Right	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Entrance Vestibule on Stage Right	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Entrance Vestibule on Stage Right	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Auditorium Entrance Vestibule on Stage Right	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway from Main Entrance Lobby to Classroom 104	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway from Main Entrance Lobby to Classroom 104	W2	CMU	Tan	Flaking	2	0.4	Negative
1	1	Hallway from Main Entrance Lobby to Classroom 104	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway from Main Entrance Lobby to Classroom 104	W4	CMU	White	Flaking	10	0.4	Negative
1	1	Hallway from Main Entrance Lobby to Classroom 104	Ceiling	Concrete	White	Flaking	3	0.2	Negative



		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Hallway from Main Entrance Lobby to Classroom 104	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway from Main Entrance Lobby to Kitchen	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway from Main Entrance Lobby to Kitchen	W2	CMU	Tan	Flaking	3	0.3	Negative
1	1	Hallway from Main Entrance Lobby to Kitchen	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway from Main Entrance Lobby to Kitchen	W4	CMU	Tan	Flaking	1	0.4	Negative
1	1	Hallway from Main Entrance Lobby to Kitchen	Ceiling	Concrete	White	Flaking	1	0.4	Negative
1	1	Hallway from Main Entrance Lobby to Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell next to Girl's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell next to Girl's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell next to Girl's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell next to Girl's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell next to Girl's Restroom	Ceiling	Metal	White	Flaking	15	0.5	Negative
1	1	Stairwell next to Girl's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell adjacent to Boy's Restroom	W1	CMU	Tan	Flaking	5	0.3	Negative
1	1	Stairwell adjacent to Boy's Restroom	W2	CMU	Tan	Flaking	14	0.5	Negative
1	1	Stairwell adjacent to Boy's Restroom	W3	CMU	Tan	Flaking	1	0.4	Negative
1	1	Stairwell adjacent to Boy's Restroom	W4	CMU	Tan	Flaking	1	0.2	Negative
1	1	Stairwell adjacent to Boy's Restroom	Ceiling	Concrete	Tan	Flaking	1	0.2	Negative
1	1	Stairwell adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Entrance Lobby	W1	Concrete	Tan	Flaking	1	0.2	Negative
1	1	Main Entrance Lobby	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Entrance Lobby	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Entrance Lobby	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Entrance Lobby	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Entrance Lobby	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Fan Room near Gym	W1	Brick	White	Flaking	180	0.2	Negative
1	2	Fan Room near Gym	W2	Brick	White	Flaking	100	0.3	Negative
1	2	Fan Room near Gym	W3	Brick	White	Flaking	50	0.1	Negative
1	2	Fan Room near Gym	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Fan Room near Gym	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Fan Room near Gym	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Fan Room near Gym	Door (W1)	Metal	Brown	Flaking	20	0.1	Negative
1	2	Fan Room near Gym	Door Casing (W1)	Metal	Brown	Flaking	20	0.1	Negative
1	2	Fan Room near Gym	Door (W3)	Metal	Brown	Flaking	18	0.1	Negative

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Fan Room near Gym	Door Casing (W3)	Metal	Brown	Flaking	18	0.1	Negative
1	2	Fan Room near Gym	Auditorium Fan Unit	Metal	Yellow	Flaking	20	0.3	Negative
1	2	Fan Room near Gym	Gym Fan Unit	Metal	Yellow	Flaking	20	0.2	Negative
1	2	Fan Room near Gym	Kitchen Exhaust Fan	Metal	Yellow	Flaking	20	0.3	Negative
1	2	Fan Room near Gym	Bathroom Exhaust Fan	Metal	Yellow	Flaking	20	0.2	Negative
1	2	Fan Room near Gym	I-Beam	Metal	Green	Flaking	60	0.4	Negative
1	2	Classroom 201	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 201	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 201	W3	Concrete	Tan	Flaking	1	0.3	Negative
1	2	Classroom 201	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 201	Ceiling	Concrete	White	Flaking	1	0.4	Negative
1	2	Classroom 201	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 204	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 204	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 204	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 204	W4	Concrete	Tan	Flaking	1	0.4	Negative
1	2	Classroom 204	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 204	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 205	W1	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Classroom 205	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 205	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 205	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 205	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 205	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 206	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 206	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 206	W3	Concrete	Pink	Flaking	1	0.3	Negative
1	2	Classroom 206	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 206	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 206	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207	Radiator Cover	Metal	Tan	Flaking	2	0.1	Negative
1	2	Classroom 208	W1	CMU	Pink	Flaking	1	0.4	Negative
1	2	Classroom 208	W1	CMU	White	Flaking	1	0.4	Negative
1	2	Classroom 208	W2	CMU	Pink	Flaking	1	0.4	Negative
1	2	Classroom 208	W2	CMU	White	Flaking	1	0.4	Negative
1	2	Classroom 208	W3	Concrete	Pink	Flaking	1	0.3	Negative
1	2	Classroom 208	W3	Concrete	White	Flaking	5	0.3	Negative
1	2	Classroom 208	W4	CMU	Pink	Flaking	1	0.4	Negative
1	2	Classroom 208	W4	CMU	White	Flaking	1	0.4	Negative
1	2	Classroom 208	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 208	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 209	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 209	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 209	W3	Concrete	Blue	Flaking	3	0.4	Negative
1	2	Classroom 209	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 209	Ceiling	Concrete	White	Flaking	10	0.4	Negative
1	2	Classroom 209	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 210	W1	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Classroom 210	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 210	W3	Concrete	Tan	Flaking	1	0.2	Negative
1	2	Classroom 210	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 210	Ceiling	Concrete	White	Flaking	1	0.4	Negative
1	2	Classroom 210	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 211	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 211	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 211	W3	Concrete	Tan	Flaking	1	0.2	Negative
1	2	Classroom 211	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 211	Ceiling	Concrete	White	Flaking	6	0.4	Negative
1	2	Classroom 211	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Girl's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Girl's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Girl's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Girl's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Girl's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Girl's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Girl's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Girl's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Girl's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Girl's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Girl's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Girl's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office next to Office 207	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Office next to Office 207	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Office next to Office 207	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Office next to Office 207	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Office next to Office 207	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office next to Office 207	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Gender Neutral Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Gender Neutral Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Gender Neutral Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Gender Neutral Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Gender Neutral Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Gender Neutral Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Pipe Chase off Closet adjacent to Boy's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Boy's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Boy's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Boy's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Boy's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Pipe Chase off Closet adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Boy's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Boy's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Boy's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Boy's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet adjacent to Boy's Restroom	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	2	Closet adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Office next to Office 207	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Office next to Office 207	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Office next to Office 207	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Office next to Office 207	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Office next to Office 207	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Office next to Office 207	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell Hallway adjacent to Boy's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell Hallway adjacent to Boy's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell Hallway adjacent to Boy's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell Hallway adjacent to Boy's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell Hallway adjacent to Boy's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell Hallway adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Hallway from Classrooms 201 to 208	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Hallway from Classrooms 201 to 208	W2	CMU	Yellow	Flaking	1	0.3	Negative
1	2	Hallway from Classrooms 201 to 208	W2	CMU	White	Flaking	5	0.3	Negative
1	2	Hallway from Classrooms 201 to 208	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Hallway from Classrooms 201 to 208	W4	CMU	Yellow	Flaking	1	0.4	Negative
1	2	Hallway from Classrooms 201 to 208	W4	CMU	White	Flaking	7	0.3	Negative
1	2	Hallway from Classrooms 201 to 208	Ceiling	Concrete	White	Flaking	4	0.3	Negative
1	2	Hallway from Classrooms 201 to 208	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell across from Classroom 202	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell across from Classroom 202	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell across from Classroom 202	W3	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Stairwell across from Classroom 202	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell across from Classroom 202	Ceiling	Concrete	White	Flaking	15	0.4	Negative
1	2	Stairwell across from Classroom 202	Floor	N/A	N/A	N/A	0	N/A	N/A
1	A	1st Floor Attic	W1	N/A	N/A	N/A	0	N/A	N/A
1	A	1st Floor Attic	W2	N/A	N/A	N/A	0	N/A	N/A
1	A	1st Floor Attic	W3	N/A	N/A	N/A	0	N/A	N/A
1	A	1st Floor Attic	W4	N/A	N/A	N/A	0	N/A	N/A
1	A	1st Floor Attic	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	A	1st Floor Attic	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Generator Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Generator Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Generator Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Generator Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Generator Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Generator Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room	W1	Concrete	White	Flaking	342	0.4	Negative
1	B	Old Boiler Room	W1	Concrete	Gray	Flaking	136	0.4	Negative
1	B	Old Boiler Room	W2	Concrete	White	Flaking	508	0.4	Negative
1	B	Old Boiler Room	W2	Concrete	Gray	Flaking	84	0.3	Negative
1	B	Old Boiler Room	W3	Concrete	White	Flaking	390	0.3	Negative
1	B	Old Boiler Room	W3	Concrete	Gray	Flaking	234	0.2	Negative
1	B	Old Boiler Room	W4	Concrete	White	Flaking	293	0.3	Negative
1	B	Old Boiler Room	W4	Concrete	Gray	Flaking	160	0.4	Negative
1	B	Old Boiler Room	Ceiling	Concrete	White	Flaking	1440	0.3	Negative
1	B	Old Boiler Room	Floor	Concrete	Gray	Flaking	1436	0.2	Negative
1	B	Old Boiler Room	Columns	Concrete	White	Flaking	180	0.4	Negative
1	B	Old Boiler Room	Columns	Concrete	Gray	Flaking	99	0.2	Negative
1	B	Old Boiler Room	Boilers	Metal	Silver	Flaking	180	0.2	Negative
1	B	Old Boiler Room	Electrical Panels	Metal	Green	Flaking	28	0.2	Negative
1	B	Old Boiler Room Metal Stairs #1	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #1	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #1	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #1	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #1	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	B	Old Boiler Room Metal Stairs #1	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #1	Railings	Metal	Beige	Flaking	15	0.6	Negative
1	B	Old Boiler Room Metal Stairs #1	Stringer	Metal	Beige	Flaking	12	0.3	Negative
1	B	Old Boiler Room Metal Stairs #1	Threads	Metal	Beige	Flaking	52	0.1	Negative
1	B	Old Boiler Room Metal Stairs #2	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #2	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #2	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #2	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #2	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #2	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Old Boiler Room Metal Stairs #2	Railings	Metal	Gray	Flaking	15	0.5	Negative
1	B	Old Boiler Room Metal Stairs #2	Stringer	Metal	Gray	Flaking	12	0.1	Negative
1	B	Old Boiler Room Metal Stairs #2	Threads	Metal	Gray	Flaking	52	0.1	Negative
1	B	Electrical/Tank Room	W1	Concrete	White	Flaking	8	0.4	Negative
1	B	Electrical/Tank Room	W1	Concrete	Gray	Flaking	4	0.3	Negative
1	B	Electrical/Tank Room	W2	Concrete	White	Flaking	166	0.3	Negative
1	B	Electrical/Tank Room	W2	Concrete	Gray	Flaking	25	0.2	Negative
1	B	Electrical/Tank Room	W3	Concrete	White	Flaking	96	0.3	Negative
1	B	Electrical/Tank Room	W3	Concrete	Gray	Flaking	96	0.3	Negative
1	B	Electrical/Tank Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Electrical/Tank Room	Ceiling	Concrete	White	Flaking	722	0.3	Negative
1	B	Electrical/Tank Room	Floor	Concrete	Gray	Flaking	562	0.3	Negative
1	B	Electrical/Tank Room	Electrical Conduit Box	Metal	Gray	Flaking	15	0.1	Negative
1	B	Crawlspace accessed from Electrical/Tank Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Crawlspace accessed from Electrical/Tank Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Crawlspace accessed from Electrical/Tank Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Crawlspace accessed from Electrical/Tank Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Crawlspace accessed from Electrical/Tank Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Crawlspace accessed from Electrical/Tank Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Locker Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Locker Room	W2	CMU	Gray	Flaking	1	0.3	Negative
1	B	Maintenance Staff Locker Room	W3	Concrete	Blue	Flaking	1	0.2	Negative
1	B	Maintenance Staff Locker Room	W3	Concrete	Gray	Flaking	4	0.3	Negative
1	B	Maintenance Staff Locker Room	W4	Concrete	Blue	Flaking	2	0.3	Negative

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	B	Maintenance Staff Locker Room	W4	Concrete	Gray	Flaking	4	0.2	Negative
1	B	Maintenance Staff Locker Room	Ceiling	Concrete	White	Flaking	2	0.2	Negative
1	B	Maintenance Staff Locker Room	Floor	Concrete	Gray	Flaking	1	0.2	Negative
1	B	Maintenance Staff Locker Room	Duct	Metal	Tan	Flaking	5	0.3	Negative
1	B	Maintenance Staff Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Restroom	W4	Concrete	Green	Flaking	4	0.4	Negative
1	B	Maintenance Staff Restroom	Ceiling	Concrete	White	Flaking	1	0.3	Negative
1	B	Maintenance Staff Restroom	Floor	Concrete	Gray	Flaking	5	0.3	Negative
1	B	Maintenance Staff Restroom	Duct	Metal	Tan	Flaking	5	0.3	Negative
1	B	Maintenance Staff Locker Room Closet	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Locker Room Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Locker Room Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Locker Room Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Locker Room Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Maintenance Staff Locker Room Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Building Engineer's Office	W1	CMU	Tan	Flaking	4	0.5	Negative
1	B	Building Engineer's Office	W2	Concrete	Tan	Flaking	70	0.4	Negative
1	B	Building Engineer's Office	W3	Concrete	Tan	Flaking	22	0.3	Negative
1	B	Building Engineer's Office	W4	Concrete	Tan	Flaking	2	0.2	Negative
1	B	Building Engineer's Office	Ceiling	Concrete	White	Flaking	59	0.4	Negative
1	B	Building Engineer's Office	Ceiling	Concrete	Gray	Flaking	55	0.4	Negative
1	B	Building Engineer's Office	Floor	Concrete	Gray	Flaking	20	0.3	Negative
1	B	Building Engineer's Office	Duct	Metal	Gray	Flaking	25	0.3	Negative
1	B	Building Engineer's Restroom	W1	CMU	Tan	Flaking	5	0.5	Negative
1	B	Building Engineer's Restroom	W2	CMU	Tan	Flaking	14	0.4	Negative
1	B	Building Engineer's Restroom	W3	CMU	Tan	Flaking	15	0.4	Negative
1	B	Building Engineer's Restroom	W4	CMU	Tan	Flaking	24	0.4	Negative
1	B	Building Engineer's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Building Engineer's Restroom	Floor	CMU	Tan	Flaking	4	0.2	Negative
1	B	Building Engineer's Closet	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Building Engineer's Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Building Engineer's Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Building Engineer's Closet	W4	N/A	N/A	N/A	0	N/A	N/A



		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	B	Building Engineer's Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Building Engineer's Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 007 Space	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 007 Space	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 007 Space	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 007 Space	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 007 Space	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 007 Space	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 006D Space	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 006D Space	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 006D Space	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 006D Space	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 006D Space	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Pipe Chase adjacent to 006D Space	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	Water Treatment Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	Water Treatment Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	Water Treatment Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	Water Treatment Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	Water Treatment Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	Water Treatment Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	New Boiler Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	New Boiler Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	New Boiler Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	New Boiler Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	New Boiler Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	New Boiler Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space accessed from Boiler Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space accessed from Boiler Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space accessed from Boiler Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space accessed from Boiler Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space accessed from Boiler Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space accessed from Boiler Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space - Electrical Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space - Electrical Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space - Electrical Room	W3	N/A	N/A	N/A	0	N/A	N/A

		<b>Lead Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: <b>Kevin Rumbol/ 006794</b>	<b>Day Elementary School</b>						
		Inspection Company: <b>ACER Associates, LLC</b>	<b>6324 Crittenden St, Philadelphia, PA 19138</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	C	Crawl Space - Electrical Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space - Electrical Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	C	Crawl Space - Electrical Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207 Closet	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207 Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207 Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207 Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 207 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Service Closet next to Classroom 202	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	Service Closet next to Classroom 202	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	Service Closet next to Classroom 202	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	Service Closet next to Classroom 202	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	Service Closet next to Classroom 202	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Service Closet next to Classroom 202	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office Closet	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office Closet	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Principal's Office Closet	Floor	N/A	N/A	N/A	0	N/A	N/A