

<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF (positive/ negative)</b>
1	1	Classroom 100 Coat Room	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 100 Coat Room	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 100 Closet across from Girl's Restroom	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 100 Closet across from Boy's Restroom	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Classroom 100 Girl's Restroom	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 100 Boy's Restroom	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 101	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 101	Window Frame	Wood	Tan	Chipping	1	Positive
1	1	Classroom 110	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 110	Window Frame	Wood	Tan	Cracking	2	Positive
1	1	Classroom 109	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 109	Window Frame	Wood	Tan	Chipping	2	Positive
1	1	Classroom 102	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 102	Window Frame	Wood	Tan	Cracking	1	Positive
1	1	Copy Room	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Copy Room	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Copy Room	W3	CMU	Blue	Cracking	5	Positive
1	1	Copy Room	Window Frame	Wood	Tan	Chipping	1	Positive
1	1	Mechanical/Storage Room in the Copy Room	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Mechanical/Storage Room in the Copy Room	W2	CMU	Yellow	Cracking	2	Positive
1	1	Mechanical/Storage Room in the Copy Room	Panel	Metal	Tan	Chipping	1	Positive
1	1	Mechanical/Storage Room in the Copy Room	W4	CMU	Yellow	Chipping	1	Positive
1	1	Mechanical/Storage Room in the Copy Room	Pipe	Metal	Tan	Chipping	2	Positive
1	1	Counselor's Office next to Nurse's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Counselor's Office next to Nurse's Office	Window Frame	Wood	Tan	Cracking	1	Positive
1	1	Hallway from Science Office to Counselor's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Hallway from Science Office to Counselor's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Hallway from Science Office to Counselor's Office	Door Frame	Metal	Tan	Chipping	2	Positive

<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF (positive/ negative)</b>
1	1	Hallway from Science Office to Counselor's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Staff Restroom next to Counselor's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Science Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Nurse's Office	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Nurse's Office	Window Frame	Wood	Tan	Chipping	1	Positive
1	1	Nurse's Office	Radiator	Metal	Tan	Chipping	2	Positive
1	1	Lobby area to Nurse's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Lobby area to Nurse's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Lobby area to Nurse's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Lobby area to Nurse's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Counselor's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Counselor's Office	Window Frame	Wood	Tan	Cracking	1	Positive
1	1	Women's Restroom by Counselor's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Principal's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Principal's Office - Closet	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Principal's Conference Room	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Principal's Conference Room Closet	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Hallway between Main Office and Principal's Office	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Main Office Restroom	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Main Office	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Main Office	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Principal's Hallway	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Principal's Hallway	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Principal's Hallway	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Closet next to Principal's Conference Room	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Closet furthest from Principal's Conference Room	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Classroom 108	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 108	Window Frame	Wood	Tan	Cracking	1	Positive
1	1	Classroom 103	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Classroom 103	Window Frame	Wood	Tan	Cracking	2	Positive

<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF (positive/ negative)</b>
1	1	Classroom 107	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 107	Window Frame	Wood	Tan	Cracking	1	Positive
1	1	Classroom 104	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Classroom 104	Window Frame	Wood	Tan	Cracking	2	Positive
1	1	Classroom 106	Door Frame	Metal	Tan	Friction	2	Positive
1	1	Classroom 106	Window Frame	Wood	Tan	Cracking	2	Positive
1	1	Classroom 105	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Classroom 105	Window Frame	Wood	Tan	Cracking	1	Positive
1	1	Hallway from Nurse's Office to Classroom 110	Door Frame	Metal	Tan	Chipping	5	Positive
1	1	Hallway from Nurse's Office to Classroom 110	Door Frame	Metal	Tan	Chipping	5	Positive
1	1	Hallway from next to Stair 1 to Gym/Cafeteria Lobby	Window Frame	Wood	Tan	Chipping	1	Positive
1	1	Hallway from next to Stair 1 to Gym/Cafeteria Lobby	Door Frame	Metal	Tan	Chipping	5	Positive
1	1	Hallway from next to Stair 1 to Gym/Cafeteria Lobby	Door Frame	Metal	Tan	Chipping	5	Positive
1	1	Gymnasium	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Gymnasium	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Gymnasium	Window Frame	Wood	Tan	Chipping	2	Positive
1	1	Gymnasium	Window Frame	Wood	Tan	Chipping	1	Positive
1	1	Kitchen Hallway	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Kitchen Hallway Closet next to Refrigerator Room	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Kitchen Hallway Closet closest to Exit Vestibule	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Kitchen	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Kitchen Storeroom	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Kitchen Office	Window Frame	Wood	Brown	Cracking	1	Positive
1	1	Cafeteria Serving Area	Door Frame	Metal	Brown	Chipping	3	Positive
1	1	Cafeteria	Door Frame	Metal	Tan	Chipping	2	Positive
1	1	Cafeteria	Window Frame	Wood	Tan	Cracking	4	Positive
1	1	Cafeteria	Window Frame	Wood	Tan	Chipping	3	Positive

<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF (positive/ negative)</b>
1	1	Gym/Cafeteria Lobby	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Gym/Cafeteria Lobby	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Gym/Cafeteria Lobby	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Gym Boy's Restroom Custodial Closet	Door Frame	Metal	Tan	Chipping	1	Positive
1	1	Boy's Restroom in Gym	Door Frame	Metal	Brown	Chipping	1	Positive
1	1	Gym Girl's Restroom	Door Frame	Metal	Brown	Chipping	1	Positive
1	2	Classroom 202	Door Frame	Metal	Tan	Chipping	2	Positive
1	2	Classroom 202	Window Frame	Wood	Tan	Chipping	1	Positive
1	2	Classroom 203	Door Frame	Metal	Tan	Friction	2	Positive
1	2	Classroom 203	Window Frame	Wood	Tan	Cracking	2	Positive
1	2	Hallway to ESOL Room from Main Hallway	Door Frame	Metal	Tan	Chipping	2	Positive
1	2	Hallway to ESOL Room from Main Hallway	Door Frame	Metal	Tan	Chipping	2	Positive
1	2	IMC/Library	Door Frame	Metal	Tan	Chipping	1	Positive
1	2	Teacher Lounge/Dining	Window Frame	Wood	Tan	Cracking	1	Positive
1	2	Office next to Stair 2	Window Frame	Wood	Tan	Cracking	2	Positive
1	2	Office next to Stair 2	W4	CMU	Tan	Chipping	4	Positive
1	2	Girl's Restroom	Window Frame	Wood	Tan	Cracking	2	Positive
1	2	Classroom 200	Door Frame	Metal	Tan	Chipping	2	Positive
1	2	Classroom 204	Door Frame	Metal	Tan	Friction	2	Positive
1	2	Classroom 204	Window Frame	Wood	Tan	Cracking	2	Positive
1	2	Hallway from Classrooms 200 to 204	Door Frame	Metal	Tan	Chipping	5	Positive
1	2	Hallway from Classrooms 200 to 204	Door Frame	Metal	Tan	Chipping	5	Positive
2	1	Classroom A6	Door Frame	Metal	Tan	Chipping	2	Positive
2	1	Classroom A6	Window Frame	Wood	Tan	Chipping	4	Positive
2	1	Classroom A6	Window Sill	Wood	Tan	Chipping	4	Positive
2	1	Classroom A6	Window Frame Support Beam	Metal	Tan	Flaking	2	Positive
2	1	Classroom A6	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A6 Closet	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A1	Door Frame	Metal	Tan	Chipping	2	Positive
2	1	Classroom A1	Window Frame	Wood	Tan	Chipping	4	Positive
2	1	Classroom A1	Window Sill	Wood	Tan	Chipping	4	Positive

<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF (positive/ negative)</b>
2	1	Classroom A1	Window Frame Support Beam	Metal	Tan	Flaking	2	Positive
2	1	Classroom A1	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A1 Closet	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A5	Door Frame	Metal	Tan	Chipping	2	Positive
2	1	Classroom A5	Window Frame	Wood	Tan	Chipping	4	Positive
2	1	Classroom A5	Window Sill	Wood	Tan	Chipping	4	Positive
2	1	Classroom A5	Window Frame Support Beam	Metal	Tan	Flaking	2	Positive
2	1	Classroom A5	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A5 Closet	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A2	Door Frame	Metal	Tan	Chipping	2	Positive
2	1	Classroom A2	Window Frame	Wood	Tan	Chipping	4	Positive
2	1	Classroom A2	Window Sill	Wood	Tan	Chipping	4	Positive
2	1	Classroom A2	Window Frame Support Beam	Metal	Tan	Flaking	2	Positive
2	1	Classroom A2	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A2 Closet	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A4	Door Frame	Metal	Tan	Chipping	2	Positive
2	1	Classroom A4	Window Frame	Wood	Tan	Chipping	4	Positive
2	1	Classroom A4	Window Sill	Wood	Tan	Chipping	4	Positive
2	1	Classroom A4	Window Frame Support Beam	Metal	Tan	Flaking	2	Positive
2	1	Classroom A4	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A4 Closet	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A3	Door Frame	Metal	Tan	Chipping	2	Positive
2	1	Classroom A3	Window Frame	Wood	Tan	Chipping	4	Positive
2	1	Classroom A3	Window Frame Support Beam	Metal	Tan	Flaking	2	Positive
2	1	Classroom A3	Door Frame	Metal	Tan	Chipping	1	Positive
2	1	Classroom A3 Closet	Door Frame	Metal	Tan	Chipping	1	Positive