

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	1	Boiler Room	Boiler Room	W1	Concrete	White	Flaking	22	0.4	Negative
1	B	1	Boiler Room	Boiler Room	W2	Concrete	White	Flaking	12	0.2	Negative
1	B	1	Boiler Room	Boiler Room	W3	Concrete	White	Flaking	10	0.4	Negative
1	B	1	Boiler Room	Boiler Room	W4	Concrete	White	Flaking	13	0.4	Negative
1	B	1	Boiler Room	Boiler Room	Ceiling	Concrete	White	Flaking	16	0.1	Negative
1	B	1	Boiler Room	Boiler Room	Floor	N/a	N/A	N/A	0	N/A	N/A
1	B	2	Administrative Office	Office inside Boiler Room	W1	CMU	Yellow	Intact	0	0.4	Negative
1	B	2	Administrative Office	Office inside Boiler Room	W2	Concrete	Yellow	Intact	0	0.1	Negative
1	B	2	Administrative Office	Office inside Boiler Room	W3	Concrete	Yellow	Intact	0	0.2	Negative
1	B	2	Administrative Office	Office inside Boiler Room	W4	CMU	Yellow	Intact	0	0	Negative
1	B	2	Administrative Office	Office inside Boiler Room	Ceiling	Concrete	White	Flaking	20	0.3	Negative
1	B	2	Administrative Office	Office inside Boiler Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	002A	Restrooms, Staff - Male/Female	Office Restroom inside Boiler Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	002A	Restrooms, Staff - Male/Female	Office Restroom inside Boiler Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	002A	Restrooms, Staff - Male/Female	Office Restroom inside Boiler Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	002A	Restrooms, Staff - Male/Female	Office Restroom inside Boiler Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	002A	Restrooms, Staff - Male/Female	Office Restroom inside Boiler Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	002A	Restrooms, Staff - Male/Female	Office Restroom inside Boiler Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	S5	Stairs	Stairwell 5	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	S5	Stairs	Stairwell 5	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	S5	Stairs	Stairwell 5	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	S5	Stairs	Stairwell 5	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	S5	Stairs	Stairwell 5	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	S5	Stairs	Stairwell 5	Floor	N/A	N/A	N/A	0	N/A	N/A
1	B	S7	Stairs	Stairwell 7	W1	N/A	N/A	N/A	0	N/A	N/A
1	B	S7	Stairs	Stairwell 7	W2	N/A	N/A	N/A	0	N/A	N/A
1	B	S7	Stairs	Stairwell 7	W3	N/A	N/A	N/A	0	N/A	N/A
1	B	S7	Stairs	Stairwell 7	W4	N/A	N/A	N/A	0	N/A	N/A
1	B	S7	Stairs	Stairwell 7	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	B	S7	Stairs	Stairwell 7	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	V01	Circulation (Hallway)	Front Entrance Vestibule	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	V01	Circulation (Hallway)	Front Entrance Vestibule	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	V01	Circulation (Hallway)	Front Entrance Vestibule	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	V01	Circulation (Hallway)	Front Entrance Vestibule	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	V01	Circulation (Hallway)	Front Entrance Vestibule	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	V01	Circulation (Hallway)	Front Entrance Vestibule	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	100	General Administrative Space	Main Office	W1	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	100	General Administrative Space	Main Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	100	General Administrative Space	Main Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	100	General Administrative Space	Main Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	100	General Administrative Space	Main Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	100	General Administrative Space	Main Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	100A	Conference Room	Main Office Conference Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	100A	Conference Room	Main Office Conference Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	100A	Conference Room	Main Office Conference Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	100A	Conference Room	Main Office Conference Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	100A	Conference Room	Main Office Conference Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	100A	Conference Room	Main Office Conference Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	100B	Principal/Directors Office	Principal's Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	100B	Principal/Directors Office	Principal's Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	100B	Principal/Directors Office	Principal's Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	100B	Principal/Directors Office	Principal's Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	100B	Principal/Directors Office	Principal's Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	100B	Principal/Directors Office	Principal's Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	105A	Restrooms, Staff - Male	Principal's Office Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	105A	Restrooms, Staff - Male	Principal's Office Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	105A	Restrooms, Staff - Male	Principal's Office Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	105A	Restrooms, Staff - Male	Principal's Office Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	105A	Restrooms, Staff - Male	Principal's Office Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	105A	Restrooms, Staff - Male	Principal's Office Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	100C	Kitchen	Main Office Kitchen	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	100C	Kitchen	Main Office Kitchen	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	100C	Kitchen	Main Office Kitchen	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	100C	Kitchen	Main Office Kitchen	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	100C	Kitchen	Main Office Kitchen	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	100C	Kitchen	Main Office Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	100D	Mail Room	Mail Room	W1	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	100D	Mail Room	Mail Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	100D	Mail Room	Mail Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	100D	Mail Room	Mail Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	100D	Mail Room	Mail Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	100D	Mail Room	Mail Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	100E	Administrative Office	Office next to Mail Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	100E	Administrative Office	Office next to Mail Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	100E	Administrative Office	Office next to Mail Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	100E	Administrative Office	Office next to Mail Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	100E	Administrative Office	Office next to Mail Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	100E	Administrative Office	Office next to Mail Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	100	Cafeteria (Dining Area)	Cafeteria	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	100	Cafeteria (Dining Area)	Cafeteria	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	100	Cafeteria (Dining Area)	Cafeteria	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	100	Cafeteria (Dining Area)	Cafeteria	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	100	Cafeteria (Dining Area)	Cafeteria	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	100	Cafeteria (Dining Area)	Cafeteria	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Electrical Room	Electrical Room outside of Cafeteria	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Electrical Room	Electrical Room outside of Cafeteria	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Electrical Room	Electrical Room outside of Cafeteria	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Electrical Room	Electrical Room outside of Cafeteria	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Electrical Room	Electrical Room outside of Cafeteria	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Electrical Room	Electrical Room outside of Cafeteria	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	101E	Telecommunication Equipment Room	IT MDF Room 101E outside of Cafeteria	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	101E	Telecommunication Equipment Room	IT MDF Room 101E outside of Cafeteria	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	101E	Telecommunication Equipment Room	IT MDF Room 101E outside of Cafeteria	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	101E	Telecommunication Equipment Room	IT MDF Room 101E outside of Cafeteria	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	101E	Telecommunication Equipment Room	IT MDF Room 101E outside of Cafeteria	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	101E	Telecommunication Equipment Room	IT MDF Room 101E outside of Cafeteria	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	S1	Stairs	Stairwell outside Main Office and Cafeteria	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	S1	Stairs	Stairwell outside Main Office and Cafeteria	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	S1	Stairs	Stairwell outside Main Office and Cafeteria	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	S1	Stairs	Stairwell outside Main Office and Cafeteria	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	S1	Stairs	Stairwell outside Main Office and Cafeteria	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	S1	Stairs	Stairwell outside Main Office and Cafeteria	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	C102	Circulation (Hallway)	Hallway from Main Office and Cafeteria to Staff Lounge 111	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	C102	Circulation (Hallway)	Hallway from Main Office and Cafeteria to Staff Lounge 111	W2	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	C102	Circulation (Hallway)	Hallway from Main Office and Cafeteria to Staff Lounge 111	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	C102	Circulation (Hallway)	Hallway from Main Office and Cafeteria to Staff Lounge 111	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	C102	Circulation (Hallway)	Hallway from Main Office and Cafeteria to Staff Lounge 111	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	C102	Circulation (Hallway)	Hallway from Main Office and Cafeteria to Staff Lounge 111	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	EL1	Elevators, Passenger	Elevator	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	EL1	Elevators, Passenger	Elevator	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	EL1	Elevators, Passenger	Elevator	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	EL1	Elevators, Passenger	Elevator	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	EL1	Elevators, Passenger	Elevator	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	EL1	Elevators, Passenger	Elevator	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom outside of Cafeteria	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom outside of Cafeteria	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom outside of Cafeteria	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom outside of Cafeteria	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom outside of Cafeteria	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom outside of Cafeteria	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	121	Student Restrooms - Male (4-12)	Boy's Restroom outside of Cafeteria	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	121	Student Restrooms - Male (4-12)	Boy's Restroom outside of Cafeteria	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	121	Student Restrooms - Male (4-12)	Boy's Restroom outside of Cafeteria	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	121	Student Restrooms - Male (4-12)	Boy's Restroom outside of Cafeteria	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	121	Student Restrooms - Male (4-12)	Boy's Restroom outside of Cafeteria	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	121	Student Restrooms - Male (4-12)	Boy's Restroom outside of Cafeteria	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	101	Kitchen	Main Kitchen	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	101	Kitchen	Main Kitchen	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	101	Kitchen	Main Kitchen	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	101	Kitchen	Main Kitchen	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	101	Kitchen	Main Kitchen	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	101	Kitchen	Main Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	101A	Kitchen Office	Main Kitchen Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	101A	Kitchen Office	Main Kitchen Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	101A	Kitchen Office	Main Kitchen Office	W3	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	101A	Kitchen Office	Main Kitchen Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	101A	Kitchen Office	Main Kitchen Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	101A	Kitchen Office	Main Kitchen Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	101B	Kitchen and Dry Storage Area	Storage Room inside Main Kitchen	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	101B	Kitchen and Dry Storage Area	Storage Room inside Main Kitchen	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	101B	Kitchen and Dry Storage Area	Storage Room inside Main Kitchen	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	101B	Kitchen and Dry Storage Area	Storage Room inside Main Kitchen	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	101B	Kitchen and Dry Storage Area	Storage Room inside Main Kitchen	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	101B	Kitchen and Dry Storage Area	Storage Room inside Main Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	C101	Circulation (Hallway)	Hallway from Classrooms 102 to 107	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	C101	Circulation (Hallway)	Hallway from Classrooms 102 to 107	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	C101	Circulation (Hallway)	Hallway from Classrooms 102 to 107	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	C101	Circulation (Hallway)	Hallway from Classrooms 102 to 107	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	C101	Circulation (Hallway)	Hallway from Classrooms 102 to 107	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	C101	Circulation (Hallway)	Hallway from Classrooms 102 to 107	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	102	Primary	Classroom 102	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	102	Primary	Classroom 102	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	102	Primary	Classroom 102	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	102	Primary	Classroom 102	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	102	Primary	Classroom 102	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	102	Primary	Classroom 102	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Primary	Classroom 104	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Primary	Classroom 104	W2	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	104	Primary	Classroom 104	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Primary	Classroom 104	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Primary	Classroom 104	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Primary	Classroom 104	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	106	Primary	Classroom 106	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	106	Primary	Classroom 106	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	106	Primary	Classroom 106	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	106	Primary	Classroom 106	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	106	Primary	Classroom 106	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	106	Primary	Classroom 106	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	103	Primary	Classroom 103	W1	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	103	Primary	Classroom 103	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	103	Primary	Classroom 103	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	103	Primary	Classroom 103	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	103	Primary	Classroom 103	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	103	Primary	Classroom 103	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	105	Primary	Classroom 105	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	105	Primary	Classroom 105	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	105	Primary	Classroom 105	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	105	Primary	Classroom 105	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	105	Primary	Classroom 105	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	105	Primary	Classroom 105	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	107	Primary	Classroom 107	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	107	Primary	Classroom 107	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	107	Primary	Classroom 107	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	107	Primary	Classroom 107	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	107	Primary	Classroom 107	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	107	Primary	Classroom 107	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	S2	Stairs	Stairwell outside Classrooms 106 and 107	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	S2	Stairs	Stairwell outside Classrooms 106 and 107	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	S2	Stairs	Stairwell outside Classrooms 106 and 107	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	S2	Stairs	Stairwell outside Classrooms 106 and 107	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	S2	Stairs	Stairwell outside Classrooms 106 and 107	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	S2	Stairs	Stairwell outside Classrooms 106 and 107	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	116	Restrooms, Staff - Male/Female	Staff Restroom next to Office 100E	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	116	Restrooms, Staff - Male/Female	Staff Restroom next to Office 100E	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	116	Restrooms, Staff - Male/Female	Staff Restroom next to Office 100E	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	116	Restrooms, Staff - Male/Female	Staff Restroom next to Office 100E	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	116	Restrooms, Staff - Male/Female	Staff Restroom next to Office 100E	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	116	Restrooms, Staff - Male/Female	Staff Restroom next to Office 100E	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	117	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 103A	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	117	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 103A	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	117	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 103A	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	117	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 103A	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	117	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 103A	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	117	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 103A	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	103A	Service Closets	Custodial Closet 103A	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	103A	Service Closets	Custodial Closet 103A	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	103A	Service Closets	Custodial Closet 103A	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	103A	Service Closets	Custodial Closet 103A	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	103A	Service Closets	Custodial Closet 103A	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	103A	Service Closets	Custodial Closet 103A	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	103B	Mechanical Room	Elevator Mechanical Room 103B	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	103B	Mechanical Room	Elevator Mechanical Room 103B	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	103B	Mechanical Room	Elevator Mechanical Room 103B	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	103B	Mechanical Room	Elevator Mechanical Room 103B	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	103B	Mechanical Room	Elevator Mechanical Room 103B	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	103B	Mechanical Room	Elevator Mechanical Room 103B	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	108A	Mechanical Room	Pump Room 108A	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	108A	Mechanical Room	Pump Room 108A	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	108A	Mechanical Room	Pump Room 108A	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	108A	Mechanical Room	Pump Room 108A	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	108A	Mechanical Room	Pump Room 108A	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	108A	Mechanical Room	Pump Room 108A	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	137	Mechanical Room	Mechanical Room across from Classroom 109's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	137	Mechanical Room	Mechanical Room across from Classroom 109's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	137	Mechanical Room	Mechanical Room across from Classroom 109's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	137	Mechanical Room	Mechanical Room across from Classroom 109's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	137	Mechanical Room	Mechanical Room across from Classroom 109's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	137	Mechanical Room	Mechanical Room across from Classroom 109's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	S7	Stairs	Stairwell next to Classroom 108	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	S7	Stairs	Stairwell next to Classroom 108	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	S7	Stairs	Stairwell next to Classroom 108	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	S7	Stairs	Stairwell next to Classroom 108	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	S7	Stairs	Stairwell next to Classroom 108	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	S7	Stairs	Stairwell next to Classroom 108	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	136	Student Restrooms - Male/Female (Classroom)	Classroom 109's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	136	Student Restrooms - Male/Female (Classroom)	Classroom 109's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	136	Student Restrooms - Male/Female (Classroom)	Classroom 109's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	136	Student Restrooms - Male/Female (Classroom)	Classroom 109's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	136	Student Restrooms - Male/Female (Classroom)	Classroom 109's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	136	Student Restrooms - Male/Female (Classroom)	Classroom 109's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	C104	Circulation (Hallway)	Hallway from Classrooms 109 to 114	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	C104	Circulation (Hallway)	Hallway from Classrooms 109 to 114	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	C104	Circulation (Hallway)	Hallway from Classrooms 109 to 114	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	C104	Circulation (Hallway)	Hallway from Classrooms 109 to 114	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	C104	Circulation (Hallway)	Hallway from Classrooms 109 to 114	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	C104	Circulation (Hallway)	Hallway from Classrooms 109 to 114	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	108	Primary	Classroom 108	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	108	Primary	Classroom 108	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	108	Primary	Classroom 108	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	108	Primary	Classroom 108	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	108	Primary	Classroom 108	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	108	Primary	Classroom 108	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Primary	Classroom 109	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Primary	Classroom 109	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Primary	Classroom 109	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Primary	Classroom 109	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Primary	Classroom 109	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	109	Primary	Classroom 109	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	111	Teacher Lounge/Dining	Staff Lounge 111	W1	CMU	White	Intact	0	0.1	Negative
1	1	111	Teacher Lounge/Dining	Staff Lounge 111	W2	Concrete	White	Flaking	5	0.1	Negative
1	1	111	Teacher Lounge/Dining	Staff Lounge 111	W3	CMU	White	Intact	0	0.1	Negative
1	1	111	Teacher Lounge/Dining	Staff Lounge 111	W4	Drywall	White	Intact	0	0.1	Negative
1	1	111	Teacher Lounge/Dining	Staff Lounge 111	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	111	Teacher Lounge/Dining	Staff Lounge 111	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	110A	Administrative Office	Office 110A	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	110A	Administrative Office	Office 110A	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	110A	Administrative Office	Office 110A	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	110A	Administrative Office	Office 110A	W4	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	110A	Administrative Office	Office 110A	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	110A	Administrative Office	Office 110A	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	110B	Storage	Storage Room 110B	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	110B	Storage	Storage Room 110B	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	110B	Storage	Storage Room 110B	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	110B	Storage	Storage Room 110B	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	110B	Storage	Storage Room 110B	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	110B	Storage	Storage Room 110B	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	112	Health Service Room	Nurse's Office Waiting Room 112	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	112	Health Service Room	Nurse's Office Waiting Room 112	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	112	Health Service Room	Nurse's Office Waiting Room 112	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	112	Health Service Room	Nurse's Office Waiting Room 112	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	112	Health Service Room	Nurse's Office Waiting Room 112	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	112	Health Service Room	Nurse's Office Waiting Room 112	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	112A	Health Service Room	Nurse's Office Room 112A	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	112A	Health Service Room	Nurse's Office Room 112A	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	112A	Health Service Room	Nurse's Office Room 112A	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	112A	Health Service Room	Nurse's Office Room 112A	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	112A	Health Service Room	Nurse's Office Room 112A	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	112A	Health Service Room	Nurse's Office Room 112A	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	124B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	124B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	124B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	124B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	124B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	124B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	124C	Health Service Room	Nurse's Office Exam Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	124C	Health Service Room	Nurse's Office Exam Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	124C	Health Service Room	Nurse's Office Exam Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	124C	Health Service Room	Nurse's Office Exam Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	124C	Health Service Room	Nurse's Office Exam Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	124C	Health Service Room	Nurse's Office Exam Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	132	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 115	W1	CMU	White	Intact	0	0.5	Negative

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	132	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 115	W2	CMU	White	Intact	0	0.1	Negative
1	1	132	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 115	W3	CMU	White	Intact	0	0	Negative
1	1	132	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 115	W4	CMU	White	Intact	0	0.4	Negative
1	1	132	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 115	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	132	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 115	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	132	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 115	Door Frame	Metal	Gray	Flaking	5	1.1	Positive
1	1	113	Administrative Office	Office 113	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	113	Administrative Office	Office 113	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	113	Administrative Office	Office 113	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	113	Administrative Office	Office 113	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	113	Administrative Office	Office 113	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	113	Administrative Office	Office 113	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	114	Primary	Classroom 114	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	114	Primary	Classroom 114	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	114	Primary	Classroom 114	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	114	Primary	Classroom 114	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	114	Primary	Classroom 114	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	114	Primary	Classroom 114	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	114A	Storage	Classroom 114 Storage Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	114A	Storage	Classroom 114 Storage Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	114A	Storage	Classroom 114 Storage Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	114A	Storage	Classroom 114 Storage Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	114A	Storage	Classroom 114 Storage Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	114A	Storage	Classroom 114 Storage Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	115	Primary	Classroom 115	W1	Drywall	White	Intact	0	0.1	Negative
1	1	115	Primary	Classroom 115	W2	Drywall	White	Intact	0	0.2	Negative
1	1	115	Primary	Classroom 115	W3	Concrete	White	Flaking	1	0.2	Negative
1	1	115	Primary	Classroom 115	W4	CMU	White	Intact	0	0.1	Negative
1	1	115	Primary	Classroom 115	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	115	Primary	Classroom 115	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	129	Student Restrooms - Male/Female (Classroom)	Classroom 115 Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	129	Student Restrooms - Male/Female (Classroom)	Classroom 115 Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	129	Student Restrooms - Male/Female (Classroom)	Classroom 115 Restroom	W3	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	129	Student Restrooms - Male/Female (Classroom)	Classroom 115 Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	129	Student Restrooms - Male/Female (Classroom)	Classroom 115 Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	129	Student Restrooms - Male/Female (Classroom)	Classroom 115 Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	S6	Stairs	Stairwell 6	W1	CMU	White	Intact	0	0.1	Negative
1	1	S6	Stairs	Stairwell 6	W2	CMU	White	Intact	0	0.5	Negative
1	1	S6	Stairs	Stairwell 6	W3	CMU	White	Intact	0	0.4	Negative
1	1	S6	Stairs	Stairwell 6	W4	CMU	White	Intact	0	0.4	Negative
1	1	S6	Stairs	Stairwell 6	Ceiling	Concrete	White	Flaking	2	0.4	Negative
1	1	S6	Stairs	Stairwell 6	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	CH-1	Mechanical Room	Chiller Room next to Stairwell 6	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	CH-1	Mechanical Room	Chiller Room next to Stairwell 6	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	CH-1	Mechanical Room	Chiller Room next to Stairwell 6	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	CH-1	Mechanical Room	Chiller Room next to Stairwell 6	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	CH-1	Mechanical Room	Chiller Room next to Stairwell 6	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	CH-1	Mechanical Room	Chiller Room next to Stairwell 6	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	E-1	Electrical Room	Electrical Room inside Chiller Room next to Stairwell 6	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	E-1	Electrical Room	Electrical Room inside Chiller Room next to Stairwell 6	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	E-1	Electrical Room	Electrical Room inside Chiller Room next to Stairwell 6	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	E-1	Electrical Room	Electrical Room inside Chiller Room next to Stairwell 6	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	E-1	Electrical Room	Electrical Room inside Chiller Room next to Stairwell 6	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	E-1	Electrical Room	Electrical Room inside Chiller Room next to Stairwell 6	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	C106	Circulation (Hallway)	Hallway from IMC to Gymnasium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	C106	Circulation (Hallway)	Hallway from IMC to Gymnasium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	C106	Circulation (Hallway)	Hallway from IMC to Gymnasium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	C106	Circulation (Hallway)	Hallway from IMC to Gymnasium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	C106	Circulation (Hallway)	Hallway from IMC to Gymnasium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	C106	Circulation (Hallway)	Hallway from IMC to Gymnasium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	116	IMC (Library)	IMC (Library)	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	116	IMC (Library)	IMC (Library)	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	116	IMC (Library)	IMC (Library)	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	116	IMC (Library)	IMC (Library)	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	116	IMC (Library)	IMC (Library)	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	116	IMC (Library)	IMC (Library)	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	116A	Administrative Office	IMC Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	116A	Administrative Office	IMC Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	116A	Administrative Office	IMC Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	116A	Administrative Office	IMC Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	116A	Administrative Office	IMC Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	116A	Administrative Office	IMC Office	Floor	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	116B	Storage	IMC Storage Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	116B	Storage	IMC Storage Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	116B	Storage	IMC Storage Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	116B	Storage	IMC Storage Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	116B	Storage	IMC Storage Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	116B	Storage	IMC Storage Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	143C	Storage	IMC Storage Closet next to Entrance	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	143C	Storage	IMC Storage Closet next to Entrance	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	143C	Storage	IMC Storage Closet next to Entrance	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	143C	Storage	IMC Storage Closet next to Entrance	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	143C	Storage	IMC Storage Closet next to Entrance	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	143C	Storage	IMC Storage Closet next to Entrance	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	145	Student Restrooms - Male (4-12)	Boy's Restroom outside of Gymnasium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	145	Student Restrooms - Male (4-12)	Boy's Restroom outside of Gymnasium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	145	Student Restrooms - Male (4-12)	Boy's Restroom outside of Gymnasium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	145	Student Restrooms - Male (4-12)	Boy's Restroom outside of Gymnasium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	145	Student Restrooms - Male (4-12)	Boy's Restroom outside of Gymnasium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	145	Student Restrooms - Male (4-12)	Boy's Restroom outside of Gymnasium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	146	Student Restrooms - Female (4-12)	Girl's Restroom outside of Gymnasium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	146	Student Restrooms - Female (4-12)	Girl's Restroom outside of Gymnasium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	146	Student Restrooms - Female (4-12)	Girl's Restroom outside of Gymnasium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	146	Student Restrooms - Female (4-12)	Girl's Restroom outside of Gymnasium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	146	Student Restrooms - Female (4-12)	Girl's Restroom outside of Gymnasium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	146	Student Restrooms - Female (4-12)	Girl's Restroom outside of Gymnasium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	V03	Circulation (Hallway)	Entrance Vestibule across from Boy's Restroom outside of Gymnasium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	V03	Circulation (Hallway)	Entrance Vestibule across from Boy's Restroom outside of Gymnasium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	V03	Circulation (Hallway)	Entrance Vestibule across from Boy's Restroom outside of Gymnasium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	V03	Circulation (Hallway)	Entrance Vestibule across from Boy's Restroom outside of Gymnasium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	V03	Circulation (Hallway)	Entrance Vestibule across from Boy's Restroom outside of Gymnasium	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	V03	Circulation (Hallway)	Entrance Vestibule across from Boy's Restroom outside of Gymnasium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	V04	Circulation (Hallway)	Entrance Vestibule next to Gym Storage Room 117F	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	V04	Circulation (Hallway)	Entrance Vestibule next to Gym Storage Room 117F	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	V04	Circulation (Hallway)	Entrance Vestibule next to Gym Storage Room 117F	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	V04	Circulation (Hallway)	Entrance Vestibule next to Gym Storage Room 117F	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	V04	Circulation (Hallway)	Entrance Vestibule next to Gym Storage Room 117F	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	V04	Circulation (Hallway)	Entrance Vestibule next to Gym Storage Room 117F	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	156	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 117C	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	156	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 117C	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	156	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 117C	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	156	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 117C	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	156	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 117C	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	156	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet 117C	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	117C	Service Closets	Custodial Closet 117C	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	117C	Service Closets	Custodial Closet 117C	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	117C	Service Closets	Custodial Closet 117C	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	117C	Service Closets	Custodial Closet 117C	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	117C	Service Closets	Custodial Closet 117C	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	117C	Service Closets	Custodial Closet 117C	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	117A	Storage	Stage Storage Room 117A	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	117A	Storage	Stage Storage Room 117A	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	117A	Storage	Stage Storage Room 117A	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	117A	Storage	Stage Storage Room 117A	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	117A	Storage	Stage Storage Room 117A	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	117A	Storage	Stage Storage Room 117A	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	152A	Electrical Room	Electrical Room inside Stage Storage Room 117A	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	152A	Electrical Room	Electrical Room inside Stage Storage Room 117A	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	152A	Electrical Room	Electrical Room inside Stage Storage Room 117A	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	152A	Electrical Room	Electrical Room inside Stage Storage Room 117A	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	152A	Electrical Room	Electrical Room inside Stage Storage Room 117A	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	152A	Electrical Room	Electrical Room inside Stage Storage Room 117A	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	C110	Circulation (Hallway)	Hallway between Stage and Stage Storage Room 117A	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	C110	Circulation (Hallway)	Hallway between Stage and Stage Storage Room 117A	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	C110	Circulation (Hallway)	Hallway between Stage and Stage Storage Room 117A	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	C110	Circulation (Hallway)	Hallway between Stage and Stage Storage Room 117A	W4	N/A	N/A	N/A	0	N/A	N/A

15

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	117G	Gymnasium Storage	Gymnasium Storage Room 117G	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	117F	Storage	Storage Room 117F	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	117F	Storage	Storage Room 117F	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	117F	Storage	Storage Room 117F	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	117F	Storage	Storage Room 117F	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	117F	Storage	Storage Room 117F	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	117F	Storage	Storage Room 117F	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	155	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	155	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	155	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	155	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	155	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	155	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	155A	Storage	Storage Room inside Gymnasium Boy's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	155A	Storage	Storage Room inside Gymnasium Boy's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	155A	Storage	Storage Room inside Gymnasium Boy's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	155A	Storage	Storage Room inside Gymnasium Boy's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	155A	Storage	Storage Room inside Gymnasium Boy's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	155A	Storage	Storage Room inside Gymnasium Boy's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	153	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	153	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	153	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	153	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	153	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	153	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	153A	Storage	Storage Room inside Gymnasium Girl's Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	153A	Storage	Storage Room inside Gymnasium Girl's Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	153A	Storage	Storage Room inside Gymnasium Girl's Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	153A	Storage	Storage Room inside Gymnasium Girl's Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	153A	Storage	Storage Room inside Gymnasium Girl's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	153A	Storage	Storage Room inside Gymnasium Girl's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	S9	Stairs	Stairwell 9 to Fan Room 117E	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	S9	Stairs	Stairwell 9 to Fan Room 117E	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	S9	Stairs	Stairwell 9 to Fan Room 117E	W3	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S9	Stairs	Stairwell 9 to Fan Room 117E	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	S9	Stairs	Stairwell 9 to Fan Room 117E	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	S9	Stairs	Stairwell 9 to Fan Room 117E	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	154	Administrative Office	Gymnasium Office	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	154	Administrative Office	Gymnasium Office	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	154	Administrative Office	Gymnasium Office	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	154	Administrative Office	Gymnasium Office	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	154	Administrative Office	Gymnasium Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	154	Administrative Office	Gymnasium Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	154A	Restrooms, Staff - Male/Female	Gymnasium Office Restroom	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	154A	Restrooms, Staff - Male/Female	Gymnasium Office Restroom	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	154A	Restrooms, Staff - Male/Female	Gymnasium Office Restroom	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	154A	Restrooms, Staff - Male/Female	Gymnasium Office Restroom	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	154A	Restrooms, Staff - Male/Female	Gymnasium Office Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	154A	Restrooms, Staff - Male/Female	Gymnasium Office Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	117E	Mechanical Room	Upper Fan Room 117E	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	117E	Mechanical Room	Upper Fan Room 117E	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	117E	Mechanical Room	Upper Fan Room 117E	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	117E	Mechanical Room	Upper Fan Room 117E	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	117E	Mechanical Room	Upper Fan Room 117E	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	117E	Mechanical Room	Upper Fan Room 117E	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	240	Mechanical Room	Upper Fan Room accessed from Stairwell 10 inside Gymnasium	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	240	Mechanical Room	Upper Fan Room accessed from Stairwell 10 inside Gymnasium	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	240	Mechanical Room	Upper Fan Room accessed from Stairwell 10 inside Gymnasium	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	240	Mechanical Room	Upper Fan Room accessed from Stairwell 10 inside Gymnasium	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	240	Mechanical Room	Upper Fan Room accessed from Stairwell 10 inside Gymnasium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	240	Mechanical Room	Upper Fan Room accessed from Stairwell 10 inside Gymnasium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	S1	Stairs	Stairwell outside of Computer Lab 205	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	S1	Stairs	Stairwell outside of Computer Lab 205	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	S1	Stairs	Stairwell outside of Computer Lab 205	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	S1	Stairs	Stairwell outside of Computer Lab 205	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	S1	Stairs	Stairwell outside of Computer Lab 205	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	S1	Stairs	Stairwell outside of Computer Lab 205	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	C200	Circulation (Hallway)	Second Floor Hallway	W1	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	C200	Circulation (Hallway)	Second Floor Hallway	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	C200	Circulation (Hallway)	Second Floor Hallway	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	C200	Circulation (Hallway)	Second Floor Hallway	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	C200	Circulation (Hallway)	Second Floor Hallway	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	C200	Circulation (Hallway)	Second Floor Hallway	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	200	Primary	Classroom 200	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	200	Primary	Classroom 200	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	200	Primary	Classroom 200	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	200	Primary	Classroom 200	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	200	Primary	Classroom 200	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	200	Primary	Classroom 200	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	201	Primary	Classroom 201	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	201	Primary	Classroom 201	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	201	Primary	Classroom 201	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	201	Primary	Classroom 201	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	201	Primary	Classroom 201	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	201	Primary	Classroom 201	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	202	Primary	Classroom 202	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	202	Primary	Classroom 202	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	202	Primary	Classroom 202	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	202	Primary	Classroom 202	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	202	Primary	Classroom 202	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	202	Primary	Classroom 202	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	203	Primary	Classroom 203	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	203	Primary	Classroom 203	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	203	Primary	Classroom 203	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	203	Primary	Classroom 203	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	203	Primary	Classroom 203	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	203	Primary	Classroom 203	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	204	Primary	Classroom 204	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	204	Primary	Classroom 204	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	204	Primary	Classroom 204	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	204	Primary	Classroom 204	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	204	Primary	Classroom 204	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	204	Primary	Classroom 204	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	205	Computer - Intermediate Middle	Computer Classroom 205	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	205	Computer - Intermediate Middle	Computer Classroom 205	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	205	Computer - Intermediate Middle	Computer Classroom 205	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	205	Computer - Intermediate Middle	Computer Classroom 205	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	205	Computer - Intermediate Middle	Computer Classroom 205	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	205	Computer - Intermediate Middle	Computer Classroom 205	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	206	Primary	Classroom 206	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	206	Primary	Classroom 206	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	206	Primary	Classroom 206	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	206	Primary	Classroom 206	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	206	Primary	Classroom 206	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	206	Primary	Classroom 206	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	207	Primary	Classroom 207	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	207	Primary	Classroom 207	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	207	Primary	Classroom 207	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	207	Primary	Classroom 207	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	207	Primary	Classroom 207	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	207	Primary	Classroom 207	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	208	Primary	Classroom 208	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	208	Primary	Classroom 208	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	208	Primary	Classroom 208	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	208	Primary	Classroom 208	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	208	Primary	Classroom 208	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	208	Primary	Classroom 208	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	209	Primary	Classroom 209	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	209	Primary	Classroom 209	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	209	Primary	Classroom 209	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	209	Primary	Classroom 209	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	209	Primary	Classroom 209	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	209	Primary	Classroom 209	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	210	Primary	Classroom 210	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	210	Primary	Classroom 210	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	210	Primary	Classroom 210	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	210	Primary	Classroom 210	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	210	Primary	Classroom 210	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	210	Primary	Classroom 210	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	211	Primary	Classroom 211	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	211	Primary	Classroom 211	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	211	Primary	Classroom 211	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	211	Primary	Classroom 211	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	211	Primary	Classroom 211	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	211	Primary	Classroom 211	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	212	Primary	Classroom 212	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	212	Primary	Classroom 212	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	212	Primary	Classroom 212	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	212	Primary	Classroom 212	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	212	Primary	Classroom 212	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	212	Primary	Classroom 212	Floor	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S2	Stairs	Stairwell between Classrooms 211 and 212	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	S2	Stairs	Stairwell between Classrooms 211 and 212	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	S2	Stairs	Stairwell between Classrooms 211 and 212	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	S2	Stairs	Stairwell between Classrooms 211 and 212	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	S2	Stairs	Stairwell between Classrooms 211 and 212	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	S2	Stairs	Stairwell between Classrooms 211 and 212	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	209A	Storage	Storage Room 209A across from Classroom 209	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	209A	Storage	Storage Room 209A across from Classroom 209	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	209A	Storage	Storage Room 209A across from Classroom 209	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	209A	Storage	Storage Room 209A across from Classroom 209	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	209A	Storage	Storage Room 209A across from Classroom 209	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	209A	Storage	Storage Room 209A across from Classroom 209	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	213	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 207	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	213	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 207	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	213	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 207	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	213	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 207	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	213	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 207	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	213	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 207	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 206	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 206	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 206	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 206	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 206	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 206	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	201A	Storage	Storage Room 201A across from Classroom 201	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	201A	Storage	Storage Room 201A across from Classroom 201	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	201A	Storage	Storage Room 201A across from Classroom 201	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	201A	Storage	Storage Room 201A across from Classroom 201	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	201A	Storage	Storage Room 201A across from Classroom 201	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	201A	Storage	Storage Room 201A across from Classroom 201	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	202A	Electrical Room	Electrical Room 202A across from Classroom 204	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	202A	Electrical Room	Electrical Room 202A across from Classroom 204	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	202A	Electrical Room	Electrical Room 202A across from Classroom 204	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	202A	Electrical Room	Electrical Room 202A across from Classroom 204	W4	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	202A	Electrical Room	Electrical Room 202A across from Classroom 204	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	202A	Electrical Room	Electrical Room 202A across from Classroom 204	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	205A	Telecommunication Equipment Room	IT MDF Room 205A across from Computer Classroom 205	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	205A	Telecommunication Equipment Room	IT MDF Room 205A across from Computer Classroom 205	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	205A	Telecommunication Equipment Room	IT MDF Room 205A across from Computer Classroom 205	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	205A	Telecommunication Equipment Room	IT MDF Room 205A across from Computer Classroom 205	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	205A	Telecommunication Equipment Room	IT MDF Room 205A across from Computer Classroom 205	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	205A	Telecommunication Equipment Room	IT MDF Room 205A across from Computer Classroom 205	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	205B	Storage	Storage Room 205B across from Computer Classroom 205	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	205B	Storage	Storage Room 205B across from Computer Classroom 205	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	205B	Storage	Storage Room 205B across from Computer Classroom 205	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	205B	Storage	Storage Room 205B across from Computer Classroom 205	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	205B	Storage	Storage Room 205B across from Computer Classroom 205	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	205B	Storage	Storage Room 205B across from Computer Classroom 205	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	217	Restrooms, Staff - Male/Female	Staff Restroom across from Computer Classroom 205	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	217	Restrooms, Staff - Male/Female	Staff Restroom across from Computer Classroom 205	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	217	Restrooms, Staff - Male/Female	Staff Restroom across from Computer Classroom 205	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	217	Restrooms, Staff - Male/Female	Staff Restroom across from Computer Classroom 205	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	217	Restrooms, Staff - Male/Female	Staff Restroom across from Computer Classroom 205	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	217	Restrooms, Staff - Male/Female	Staff Restroom across from Computer Classroom 205	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	218	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet next to Elevator	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	218	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet next to Elevator	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	218	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet next to Elevator	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	218	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet next to Elevator	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	218	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet next to Elevator	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	218	Restrooms, Staff - Male/Female	Staff Restroom next to Custodial Closet next to Elevator	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	242	Service Closets	Custodial Closet next to Elevator	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	242	Service Closets	Custodial Closet next to Elevator	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	242	Service Closets	Custodial Closet next to Elevator	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	242	Service Closets	Custodial Closet next to Elevator	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	242	Service Closets	Custodial Closet next to Elevator	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	242	Service Closets	Custodial Closet next to Elevator	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	216A	Administrative Office	Office 216A	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	216A	Administrative Office	Office 216A	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	216A	Administrative Office	Office 216A	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	216A	Administrative Office	Office 216A	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	216A	Administrative Office	Office 216A	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	216A	Administrative Office	Office 216A	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	216B	Administrative Office	Office 216B	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	216B	Administrative Office	Office 216B	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	216B	Administrative Office	Office 216B	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	216B	Administrative Office	Office 216B	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	216B	Administrative Office	Office 216B	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	216B	Administrative Office	Office 216B	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	233	Student Restrooms - Male/Female (Classroom)	Boy's Restroom next to Stairwell 5	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	233	Student Restrooms - Male/Female (Classroom)	Boy's Restroom next to Stairwell 5	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	233	Student Restrooms - Male/Female (Classroom)	Boy's Restroom next to Stairwell 5	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	233	Student Restrooms - Male/Female (Classroom)	Boy's Restroom next to Stairwell 5	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	233	Student Restrooms - Male/Female (Classroom)	Boy's Restroom next to Stairwell 5	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	233	Student Restrooms - Male/Female (Classroom)	Boy's Restroom next to Stairwell 5	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	234	Service Closets	Custodial Closet inside Boy's Restroom next to Stairwell 5	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	234	Service Closets	Custodial Closet inside Boy's Restroom next to Stairwell 5	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	234	Service Closets	Custodial Closet inside Boy's Restroom next to Stairwell 5	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	234	Service Closets	Custodial Closet inside Boy's Restroom next to Stairwell 5	W4	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	234	Service Closets	Custodial Closet inside Boy's Restroom next to Stairwell 5	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	234	Service Closets	Custodial Closet inside Boy's Restroom next to Stairwell 5	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	214B	Telecommunication Equipment Room	IT MDF/Storage Room 214B	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	214B	Telecommunication Equipment Room	IT MDF/Storage Room 214B	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	214B	Telecommunication Equipment Room	IT MDF/Storage Room 214B	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	214B	Telecommunication Equipment Room	IT MDF/Storage Room 214B	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	214B	Telecommunication Equipment Room	IT MDF/Storage Room 214B	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	214B	Telecommunication Equipment Room	IT MDF/Storage Room 214B	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	236	Restrooms, Staff - Male/Female	Staff Restroom next to IT MDF/Storage Room 214B	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	236	Restrooms, Staff - Male/Female	Staff Restroom next to IT MDF/Storage Room 214B	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	236	Restrooms, Staff - Male/Female	Staff Restroom next to IT MDF/Storage Room 214B	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	236	Restrooms, Staff - Male/Female	Staff Restroom next to IT MDF/Storage Room 214B	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	236	Restrooms, Staff - Male/Female	Staff Restroom next to IT MDF/Storage Room 214B	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	236	Restrooms, Staff - Male/Female	Staff Restroom next to IT MDF/Storage Room 214B	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	237	Restrooms, Staff - Male/Female	Staff Restroom across from Stairwell 5	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	237	Restrooms, Staff - Male/Female	Staff Restroom across from Stairwell 5	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	237	Restrooms, Staff - Male/Female	Staff Restroom across from Stairwell 5	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	237	Restrooms, Staff - Male/Female	Staff Restroom across from Stairwell 5	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	237	Restrooms, Staff - Male/Female	Staff Restroom across from Stairwell 5	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	237	Restrooms, Staff - Male/Female	Staff Restroom across from Stairwell 5	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	213	Primary	Classroom 213	W1	Drywall	White	Intact	0	0.2	Negative
1	2	213	Primary	Classroom 213	W2	Drywall	White	Intact	0	0.2	Negative
1	2	213	Primary	Classroom 213	W3	Concrete	White	Flaking	5	0.4	Negative
1	2	213	Primary	Classroom 213	W4	Drywall	White	Intact	0	0.1	Negative
1	2	213	Primary	Classroom 213	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	213	Primary	Classroom 213	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	214	Primary	Science Classroom 214	W1	Drywall	White	Intact	0	0.2	Negative

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	214	Primary	Science Classroom 214	W2	Drywall	White	Intact	0	0.3	Negative
1	2	214	Primary	Science Classroom 214	W3	Concrete	White	Flaking	2	0.4	Negative
1	2	214	Primary	Science Classroom 214	W4	Drywall	White	Intact	0	0.1	Negative
1	2	214	Primary	Science Classroom 214	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	214	Primary	Science Classroom 214	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	214A	Storage	Science Classroom 214 Storage Room	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	214A	Storage	Science Classroom 214 Storage Room	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	214A	Storage	Science Classroom 214 Storage Room	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	214A	Storage	Science Classroom 214 Storage Room	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	214A	Storage	Science Classroom 214 Storage Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	214A	Storage	Science Classroom 214 Storage Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Primary	Classroom 215	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Primary	Classroom 215	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Primary	Classroom 215	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Primary	Classroom 215	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Primary	Classroom 215	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	215	Primary	Classroom 215	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	217	Primary	Classroom 217	W1	Drywall	White	Intact	0	0.1	Negative
1	2	217	Primary	Classroom 217	W2	Concrete	White	Flaking	3	0.2	Negative
1	2	217	Primary	Classroom 217	W3	Concrete	White	Intact	0	0.3	Negative
1	2	217	Primary	Classroom 217	W4	Drywall	White	Intact	0	0.2	Negative
1	2	217	Primary	Classroom 217	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	217	Primary	Classroom 217	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	218	Primary	Classroom 218	W1	Drywall	White	Intact	0	0.1	Negative
1	2	218	Primary	Classroom 218	W2	CMU	White	Intact	0	0.1	Negative
1	2	218	Primary	Classroom 218	W3	Concrete	White	Flaking	1	0.2	Negative
1	2	218	Primary	Classroom 218	W4	Drywall	White	Intact	0	0.2	Negative
1	2	218	Primary	Classroom 218	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	218	Primary	Classroom 218	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	220	Primary	Classroom 220	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	220	Primary	Classroom 220	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	220	Primary	Classroom 220	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	220	Primary	Classroom 220	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	220	Primary	Classroom 220	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	220	Primary	Classroom 220	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	228	Student Restrooms - Female (4-12)	Girl's Restroom next to Stairwell 6	W1	N/A	N/A	N/A	0	N/A	N/A
1	2	228	Student Restrooms - Female (4-12)	Girl's Restroom next to Stairwell 6	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	228	Student Restrooms - Female (4-12)	Girl's Restroom next to Stairwell 6	W3	N/A	N/A	N/A	0	N/A	N/A
1	2	228	Student Restrooms - Female (4-12)	Girl's Restroom next to Stairwell 6	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	228	Student Restrooms - Female (4-12)	Girl's Restroom next to Stairwell 6	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 2/7/22 - 2/8/22			Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Kevin Rumbol #006794			Bridesburg School						
		Inspection Company: Acer			2824 Jenks St, Philadelphia, PA 19137						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	228	Student Restrooms - Female (4-12)	Girl's Restroom next to Stairwell 6	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	217A	Storage	Storage Closet 217A outside Girl's Restroom next to Stairwell 6	W1	CMU	Green	Flaking	5	0.4	Negative
1	2	217A	Storage	Storage Closet 217A outside Girl's Restroom next to Stairwell 6	W2	CMU	Green	Flaking	5	0.4	Negative
1	2	217A	Storage	Storage Closet 217A outside Girl's Restroom next to Stairwell 6	W3	Concrete	Green	Flaking	5	0.3	Negative
1	2	217A	Storage	Storage Closet 217A outside Girl's Restroom next to Stairwell 6	W4	CMU	Green	Intact	0	0.4	Negative
1	2	217A	Storage	Storage Closet 217A outside Girl's Restroom next to Stairwell 6	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	217A	Storage	Storage Closet 217A outside Girl's Restroom next to Stairwell 6	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	217A	Storage	Storage Closet 217A outside Girl's Restroom next to Stairwell 7	Pipe	Metal	Green	Flaking	2	0.4	Negative