

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E	F	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	IMC	W1	CMU	Blue	Partially Inaccessible	0	0	Negative
1	2	IMC	Door Frame	Metal	Grey	Chipping	2	0.15	Negative
1	2	IMC	Door	Metal	Grey	Chipping	2	0.04	Negative
1	2	IMC	W2	CMU	Blue	Partially Inaccessible	0	0.02	Negative
1	2	IMC	W3	CMU	Blue	Partially Inaccessible	0	0.05	Negative
1	2	IMC	W4	CMU	Green	Partially Inaccessible	0	0.04	Negative
1	2	IMC	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1	2	IMC	Door	Metal	Grey	Chipping	2	0.08	Negative
1	2	IMC	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	IMC	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	IMC Office	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	IMC Office	Door Frame	Metal	Grey	Chipping	2	0.21	Negative
1	2	IMC Office	Door	Metal	Grey	Chipping	2	0	Negative
1	2	IMC Office	W2	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	IMC Office	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	IMC Office	W4	Sheetrock	White	Partially Inaccessible	0	0	Negative
1	2	IMC Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	IMC Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	IMC Storage	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	IMC Storage	Door Frame	Metal	Grey	Chipping	2	0.15	Negative
1	2	IMC Storage	Door	Metal	Grey	Chipping	2	0	Negative
1	2	IMC Storage	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	IMC Storage	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	IMC Storage	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	IMC Storage	Door Frame	Metal	Grey	Chipping	2	0.12	Negative
1	2	IMC Storage	Door	Metal	Grey	Chipping	2	0	Negative
1	2	IMC Storage	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	IMC Storage	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Custodial Closet outside IMC	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Custodial Closet outside IMC	W2	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Custodial Closet outside IMC	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Custodial Closet outside IMC	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Custodial Closet outside IMC	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Custodial Closet outside IMC	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	W1	CMU	White	Partially Inaccessible	0	0.01	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Girl's Restroom across from Classroom 200	Door Frame	Metal	Grey	Chipping	2
1	2	Girl's Restroom across from Classroom 200	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Girl's Restroom across from Classroom 200	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Girl's Restroom across from Classroom 200	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Girl's Restroom across from Classroom 200	Radiator	Metal	Grey	None	0	0	Negative
1	2	Girl's Restroom across from Classroom 200	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Girl's Restroom across from Classroom 200	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 201	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Boy's Restroom across from Classroom 201	Door Frame	Metal	Grey	Chipping	2	0.19	Negative
1	2	Boy's Restroom across from Classroom 201	Door	Metal	Grey	Chipping	2	0.06	Negative
1	2	Boy's Restroom across from Classroom 201	W2	CMU	White	Partially Inaccessible	0	0.1	Negative
1	2	Boy's Restroom across from Classroom 201	W3	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Boy's Restroom across from Classroom 201	Radiator	Metal	Grey	None	0	0.06	Negative
1	2	Boy's Restroom across from Classroom 201	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Boy's Restroom across from Classroom 201	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 201	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 200	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 200	Door Frame	Metal	Grey	Chipping	2	0.1	Negative
1	2	Classroom 200	W2	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Classroom 200	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 200	W4	Drywall	White	Partially Inaccessible	0	0.01	Negative
1	2	Classroom 200	Door Frame	Metal	Grey	Chipping	2	0.1	Negative
1	2	Classroom 200	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 200	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 200A in Classroom 200	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 200A in Classroom 200	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 200A in Classroom 200	W3	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Office 200A in Classroom 200	Shelf	Wood	White	Friction	2	0	Negative
1	2	Office 200A in Classroom 200	Brackets	Wood	White	Friction	2	0	Negative
1	2	Office 200A in Classroom 200	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 200A in Classroom 200	Shelf	Wood	White	Friction	2	0	Negative
1	2	Office 200A in Classroom 200	Brackets	Wood	White	Friction	2	0	Negative
1	2	Office 200A in Classroom 200	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 200A in Classroom 200	Floor	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Classroom 202	W1	CMU	White	Partially Inaccessible	0
1	2	Classroom 202	Door Frame	Metal	Grey	Chipping	2	0.25	Negative
1	2	Classroom 202	Door	Metal	Grey	Chipping	2	0.02	Negative
1	2	Classroom 202	W2	Sheetrock	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 202	Door Frame	Metal	Grey	Chipping	2	0.23	Negative
1	2	Classroom 202	Window Frame	Metal	Grey	Chipping	1	0.1	Negative
1	2	Classroom 202	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202	Door Frame	Metal	Grey	Chipping	2	0.19	Negative
1	2	Classroom 202	Door	Metal	Grey	Chipping	2	0.04	Negative
1	2	Classroom 202	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 202	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 202	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 202	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202 Office	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202 Office	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202 Office	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202 Office	Radiator	Metal	Tan	Chipping	2	0	Negative
1	2	Classroom 202 Office	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202 Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202 Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202 Storage Room #1	W1	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 202 Storage Room #1	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 202 Storage Room #1	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 202 Storage Room #1	Shelf	Metal	Brown	Friction	1	0	Negative
1	2	Classroom 202 Storage Room #1	Pipe	Metal	White	Chipping	1	0.12	Negative
1	2	Classroom 202 Storage Room #1	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202 Storage Room #1	Shelf	Metal	Brown	Friction	1	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Classroom 202 Storage Room #1	Ceiling	N/A	N/A	N/A	0
1	2	Classroom 202 Storage Room #1	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202 Storage Room #2	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202 Storage Room #2	W2	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Classroom 202 Storage Room #2	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202 Storage Room #2	W4	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Classroom 202 Storage Room #2	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202 Storage Room #2	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202 Storage Room #3	W1	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 202 Storage Room #3	Door Frame	Metal	Grey	Chipping	2	0.12	Negative
1	2	Classroom 202 Storage Room #3	Door	Metal	Grey	Chipping	2	0.05	Negative
1	2	Classroom 202 Storage Room #3	W2	CMU	White	Partially Inaccessible	0	0.01	Negative
1	2	Classroom 202 Storage Room #3	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 202 Storage Room #3	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 202 Storage Room #3	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 202 Storage Room #3	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Teacher's Lounge	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Teacher's Lounge	Door Frame	Metal	Grey	Chipping	2	0.18	Negative
1	2	Teacher's Lounge	W2	CMU	White	Partially Inaccessible	0	0.13	Negative
1	2	Teacher's Lounge	Door Frame	Metal	Grey	Chipping	2	0.29	Negative
1	2	Teacher's Lounge	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Teacher's Lounge	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Teacher's Lounge	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Teacher's Lounge	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Teachers Lounge Storage	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Teachers Lounge Storage	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Teachers Lounge Storage	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Teachers Lounge Storage	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Teachers Lounge Storage	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Teachers Lounge Storage	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office B6 and Supply Room across from Teachers Lounge	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Office B6 and Supply Room across from Teachers Lounge	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office B6 and Supply Room across from Teachers Lounge	W3	CMU	White	Partially Inaccessible	0	0.04	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Office B6 and Supply Room across from Teachers Lounge	W4	CMU	White	Partially Inaccessible	0
1	2	Office B6 and Supply Room across from Teachers Lounge	Door Frame	Metal	Grey	Chipping	2	0.12	Negative
1	2	Office B6 and Supply Room across from Teachers Lounge	Door	Metal	Grey	Chipping	2	0.04	Negative
1	2	Office B6 and Supply Room across from Teachers Lounge	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office B6 and Supply Room across from Teachers Lounge	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Book Closet across from Classroom 204 (Pump Room for Gym)	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Book Closet across from Classroom 204 (Pump Room for Gym)	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1	2	Book Closet across from Classroom 204 (Pump Room for Gym)	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Book Closet across from Classroom 204 (Pump Room for Gym)	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Book Closet across from Classroom 204 (Pump Room for Gym)	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Book Closet across from Classroom 204 (Pump Room for Gym)	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Book Closet across from Classroom 204 (Pump Room for Gym)	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Book Closet across from Classroom 204 (Pump Room for Gym)	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Storage Room with Server outside Classroom 204	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Storage Room with Server outside Classroom 204	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Storage Room with Server outside Classroom 204	W3	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Storage Room with Server outside Classroom 204	W4	CMU	White	Partially Inaccessible	0	0.01	Negative
1	2	Storage Room with Server outside Classroom 204	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Storage Room with Server outside Classroom 204	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Mens Restroom Lounge	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Mens Restroom Lounge	Door Frame	Metal	Grey	Chipping	2	0.15	Negative
1	2	Mens Restroom Lounge	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Mens Restroom Lounge	W2	CMU	White	Partially Inaccessible	0	0.27	Negative
1	2	Mens Restroom Lounge	W3	CMU	White	Partially Inaccessible	0	0.2	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E	F	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Mens Restroom Lounge	Door Frame	Metal	Grey	None	2	0	Negative
1	2	Mens Restroom Lounge	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Mens Restroom Lounge	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Mens Restroom Lounge	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Men's Restroom	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Men's Restroom	Door Frame	Metal	Grey	Chipping	1	0.15	Negative
1	2	Men's Restroom	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Men's Restroom	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Men's Restroom	Radiator	Metal	Grey	Chipping	2	0.08	Negative
1	2	Men's Restroom	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Men's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Men's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Womens Restroom Lounge	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Womens Restroom Lounge	Door Frame	Metal	Grey	Chipping	2	0.19	Negative
1	2	Womens Restroom Lounge	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Womens Restroom Lounge	W2	CMU	White	Partially Inaccessible	0	0.03	Negative
1	2	Womens Restroom Lounge	Door Frame	Metal	Grey	None	0	0	Negative
1	2	Womens Restroom Lounge	W3	CMU	White	Partially Inaccessible	0	0.18	Negative
1	2	Womens Restroom Lounge	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Womens Restroom Lounge	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Womens Restroom Lounge	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Women's Restroom	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Women's Restroom	Door Frame	Metal	Grey	Chipping	2	0.19	Negative
1	2	Women's Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Women's Restroom	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Women's Restroom	Door Frame	Metal	Grey	None	0	0	Negative
1	2	Women's Restroom	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Women's Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Women's Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 203	Door Frame	Metal	Grey	Chipping	2	0.14	Negative
1	2	Classroom 203	Door	Metal	Grey	Chipping	2	0.1	Negative
1	2	Classroom 203	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 203	Door Frame	Metal	Grey	Chipping	2	0.12	Negative
1	2	Classroom 203	W3	CMU	White	Partially Inaccessible	0	0.06	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Classroom 203	Door Frame	Metal	Grey	Chipping	2
1	2	Classroom 203	W4	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 203	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 203	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 203	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 203	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203 Closet	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 203 Closet	W2	CMU	White	Partially Inaccessible	0	0.01	Negative
1	2	Classroom 203 Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 203 Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 203 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203 Small Closet	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 203 Small Closet	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 203 Small Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 203 Small Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 203 Small Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 203 Small Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 204	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Classroom 204	Door Frame	Metal	Grey	Chipping	2	0.26	Negative
1	2	Classroom 204	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 204	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 204	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 204	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 204	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 204	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 204	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 204	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 204	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 204 Closet	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 204 Closet	W2	CMU	White	Partially Inaccessible	0	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School							
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
		1	2	Classroom 204 Closet	W3	CMU	White	Partially Inaccessible	0	0
1	2	Classroom 204 Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 204 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 204 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 204 Small Closet	W1	CMU	White	Partially Inaccessible	0	0.04	Negative	
1	2	Classroom 204 Small Closet	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 204 Small Closet	W3	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	2	Classroom 204 Small Closet	W4	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	2	Classroom 204 Small Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 204 Small Closet	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Hallway from Classrooms 203 to 204	W1	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Hallway from Classrooms 203 to 204	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Hallway from Classrooms 203 to 204	W3	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	2	Hallway from Classrooms 203 to 204	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Hallway from Classrooms 203 to 204	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	
1	2	Hallway from Classrooms 203 to 204	Door	Metal	Brown	Chipping	2	0.02	Negative	
1	2	Hallway from Classrooms 203 to 204	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Hallway from Classrooms 203 to 204	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 205	W1	CMU	White	Partially Inaccessible	0	0.04	Negative	
1	2	Classroom 205	Door Frame	Metal	Grey	Chipping	2	0.18	Negative	
1	2	Classroom 205	Door	Metal	Grey	Chipping	2	0.02	Negative	
1	2	Classroom 205	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 205	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 205	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 205	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 205	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 205 Closet	W1	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 205 Closet	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 205 Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 205 Closet	W4	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	2	Classroom 205 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 205 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Office adjacent to Classroom 205 (205b)	W1	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Office adjacent to Classroom 205 (205b)	Door Frame	Metal	Grey	Chipping	2	0.23	Negative	
1	2	Office adjacent to Classroom 205 (205b)	Door	Metal	Grey	Chipping	2	0	Negative	

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Office adjacent to Classroom 205 (205b)	W2	CMU	White	Partially Inaccessible	0
1	2	Office adjacent to Classroom 205 (205b)	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Office adjacent to Classroom 205 (205b)	W4	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Office adjacent to Classroom 205 (205b)	Shelf	Metal	Orange	Friction	2	0.13	Negative
1	2	Office adjacent to Classroom 205 (205b)	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office adjacent to Classroom 205 (205b)	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 206	W1	CMU	White	Alligatoring	10	0.06	Negative
1	2	Classroom 206	Door Frame	Metal	Grey	Chipping	2	0.27	Negative
1	2	Classroom 206	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 206	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 206	W3	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Classroom 206	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 206	Door Frame	Metal	Grey	Chipping	1	0.19	Negative
1	2	Classroom 206	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 206	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 206	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 206	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 206	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 207	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 207	Door Frame	Metal	Grey	Chipping	2	0.18	Negative
1	2	Classroom 207	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 207	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 207	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 207	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 207	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 207	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 207	Closet Shelf	Metal	Brown	Friction	2	0.13	Negative
1	2	Classroom 207	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 207	Door Frame	Metal	Grey	Chipping	1	0.12	Negative
1	2	Classroom 207	Closet Shelf	Metal	Brown	Friction	2	0.1	Negative
1	2	Classroom 207	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 207	Floor	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 02/28-03/18/22		Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon		John Hancock Demonstrative Elementary School					
		Inspection Company: Synertech		3700 Morrell Ave, Philadelphia, PA 19114					
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Office across from Classroom 207	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office across from Classroom 207	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1	2	Office across from Classroom 207	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office across from Classroom 207	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office across from Classroom 207	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1	2	Office across from Classroom 207	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office across from Classroom 207	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office across from Classroom 207	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Custodial Closet across from Classroom 207	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Custodial Closet across from Classroom 207	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Custodial Closet across from Classroom 207	W3	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Custodial Closet across from Classroom 207	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Custodial Closet across from Classroom 207	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Custodial Closet across from Classroom 207	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 208	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 208	Door Frame	Metal	Grey	Chipping	2	0.12	Negative
1	2	Classroom 208	Door	Metal	Grey	Chipping	2	0.04	Negative
1	2	Classroom 208	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 208	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 208	Closet Shelf	Metal	Brown	Friction	1	0.12	Negative
1	2	Classroom 208	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 208	Door Frame	Metal	Grey	Friction	1	0.28	Negative
1	2	Classroom 208	Closet Shelf	Metal	Brown	Friction	1	0.05	Negative
1	2	Classroom 208	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 208	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell next to 208	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Stairwell next to 208	Door Frame	Metal	Brown	Chipping	2	0.13	Negative
1	2	Stairwell next to 208	Door	Metal	Brown	Chipping	2	0.21	Negative
1	2	Stairwell next to 208	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Stairwell next to 208	W3	CMU	White	Partially Inaccessible	0	0.6	Negative
1	2	Stairwell next to 208	Fence	Metal	Grey	Chipping	3	0.5	Negative
1	2	Stairwell next to 208	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Stairwell next to 208	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell next to 208	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell next to 208	Stringer	Metal	Grey	Chipping	1	0.5	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Stairwell next to 208	Riser	Metal	Grey	Chipping	1
1	2	Stairwell next to 208	Soffit	Metal	Grey	Chipping	1	0.42	Negative
1	2	Girl's Restroom across from Classroom 208	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Girl's Restroom across from Classroom 208	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1	2	Girl's Restroom across from Classroom 208	Door	Metal	Grey	Chipping	2	0.24	Negative
1	2	Girl's Restroom across from Classroom 208	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Girl's Restroom across from Classroom 208	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Girl's Restroom across from Classroom 208	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Girl's Restroom across from Classroom 208	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 208	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 209	W1	CMU	White	Partially Inaccessible	0	0.09	Negative
1	2	Boy's Restroom across from Classroom 209	Door Frame	Metal	Grey	Chipping	2	0.24	Negative
1	2	Boy's Restroom across from Classroom 209	W2	CMU	White	Partially Inaccessible	0	0.01	Negative
1	2	Boy's Restroom across from Classroom 209	Radiator	Metal	Grey	Cracking	1	0.14	Negative
1	2	Boy's Restroom across from Classroom 209	W3	CMU	White	Partially Inaccessible	0	0.11	Negative
1	2	Boy's Restroom across from Classroom 209	W4	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Boy's Restroom across from Classroom 209	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 209	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 209	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 209	Door Frame	Metal	Grey	Chipping	2	0.3	Negative
1	2	Classroom 209	Door	Metal	Grey	Chipping	2	0.04	Negative
1	2	Classroom 209	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 209	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 209	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 209	Door Frame	Metal	Grey	Chipping	1	0.19	Negative
1	2	Classroom 209	Door	Metal	Grey	Chipping	1	0	Negative
1	2	Classroom 209	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 209	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 209	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 209	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 209	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Psychologist Office across from Classroom 210	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Psychologist Office across from Classroom 210	Door Frame	Metal	Tan	Chipping	2	0.5	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E	F	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Psychologist Office across from Classroom 210	Window Frame	Metal	Tan	Chipping	2	0.4	Negative
1	2	Psychologist Office across from Classroom 210	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Psychologist Office across from Classroom 210	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Psychologist Office across from Classroom 210	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Psychologist Office across from Classroom 210	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Psychologist Office across from Classroom 210	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 210	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 210	Door Frame	Metal	Grey	Chipping	2	0.16	Negative
1	2	Classroom 210	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 210	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 210	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 210	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 210	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 210	W3	CMU	White	Partially Inaccessible	0	0.1	Negative
1	2	Classroom 210	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 210	Door Frame	Metal	Grey	Chipping	2	0.22	Negative
1	2	Classroom 210	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 210	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 210	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 210 Restroom	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Classroom 210 Restroom	Door Frame	Metal	Grey	Chipping	1	0.18	Negative
1	2	Classroom 210 Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 210 Restroom	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 210 Restroom	Stall Divider	Metal	Green	Chipping	2	0.07	Negative
1	2	Classroom 210 Restroom	Pipe	Metal	White	Chipping	2	0.04	Negative
1	2	Classroom 210 Restroom	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 210 Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 210 Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Storage Closet across from Classroom 211	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Storage Closet across from Classroom 211	Door Frame	Metal	Grey	Chipping	2	0.14	Negative
1	2	Storage Closet across from Classroom 211	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Storage Closet across from Classroom 211	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Storage Closet across from Classroom 211	W3	CMU	White	Partially Inaccessible	0	0.13	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E	F	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Storage Closet across from Classroom 211	Door Frame	Metal	Grey	Chipping	2	0	Negative
1	2	Storage Closet across from Classroom 211	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Storage Closet across from Classroom 211	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Storage Closet across from Classroom 211	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Storage Closet across from Classroom 211	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Hallway adjacent to Classroom 211	W1	CMU	Blue	Partially Inaccessible	0	0	Negative
1	2	Hallway adjacent to Classroom 211	W2	CMU	Blue	Partially Inaccessible	0	0	Negative
1	2	Hallway adjacent to Classroom 211	Door Frame	Metal	Brown	Chipping	2	0.05	Negative
1	2	Hallway adjacent to Classroom 211	Door	Metal	Brown	Chipping	2	0.05	Negative
1	2	Hallway adjacent to Classroom 211	Radiator	Metal	Grey	Chipping	2	0.11	Negative
1	2	Hallway adjacent to Classroom 211	W3	CMU	Blue	Partially Inaccessible	0	0.08	Negative
1	2	Hallway adjacent to Classroom 211	W4	CMU	Blue	Partially Inaccessible	0	0	Negative
1	2	Hallway adjacent to Classroom 211	Door Frame	Metal	Brown	Chipping	2	0.1	Negative
1	2	Hallway adjacent to Classroom 211	Door	Metal	Brown	Chipping	2	0	Negative
1	2	Hallway adjacent to Classroom 211	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Hallway adjacent to Classroom 211	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 211	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 211	Door Frame	Metal	Grey	Chipping	2	0.22	Negative
1	2	Classroom 211	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 211	W2	CMU	White	Partially Inaccessible	0	0.1	Negative
1	2	Classroom 211	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 211	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 211	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 211	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 212	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 212	Door Frame	Metal	Grey	Chipping	2	0.25	Negative
1	2	Classroom 212	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 212	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 212	W3	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Classroom 212	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 212	Door Frame	Metal	Grey	Chipping	2	0.25	Negative
1	2	Classroom 212	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 212	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Classroom 212	Partition Trim	Wood	Tan	Chipping	0
1	2	Classroom 212	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 212	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 215	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 215	Door Frame	Metal	Grey	Chipping	2	0.01	Negative
1	2	Office 215	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 215	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 215	Partition Room Divider	Wood	Tan	Chipping	0	0.01	Negative
1	2	Office 215	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 215	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 215	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell next to 208	Stringer	Metal	Black	Chipping	2	0.35	Negative
1	2	Stairwell next to 208	Soffit	Metal	Black	Chipping	2	0.4	Negative
1	2	Stairwell next to 208	Tread	Metal	Black	Chipping	4	0.15	Negative
1	2	Stairwell next to 208	Cage	Metal	Black	Chipping	3	0.48	Negative
1	2	Stairwell S23 next to 215	W1	Concrete	White	None	0	0	Negative
1	2	Stairwell S23 next to 215	Door Frame	Metal	Grey	Chipping	2	0.01	Negative
1	2	Stairwell S23 next to 215	W2	Concrete	White	Partially Inaccessible	0	0	Negative
1	2	Stairwell S23 next to 215	W3	Concrete	White	Partially Inaccessible	0	0	Negative
1	2	Stairwell S23 next to 215	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell S23 next to 215	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	h200c next to 211	W1	Concrete	Blue	Partially Inaccessible	0	0.04	Negative
1	2	h200c next to 211	W1	Concrete	Brown	Partially Inaccessible	0	0.07	Negative
1	2	h200c next to 211	Door	Metal	Brown	Chipping	2	0.06	Negative
1	2	h200c next to 211	Door Frame	Metal	Brown	Chipping	2	0.12	Negative
1	2	h200c next to 211	W2	Concrete	Blue	Partially Inaccessible	0	0.11	Negative
1	2	h200c next to 211	W3	Concrete	Blue	Partially Inaccessible	0	0.05	Negative
1	2	h200c next to 211	Door	Metal	Brown	Chipping	2	0.1	Negative
1	2	h200c next to 211	Door Frame	Metal	Brown	Chipping	2	0.3	Negative
1	2	h200c next to 211	W4	Concrete	White	Partially Inaccessible	0	0.5	Negative
1	2	Classroom 216	W1	CMU	White	Partially Inaccessible	0	0.09	Negative
1	2	Classroom 216	Door Frame	Metal	Grey	Chipping	2	0.01	Negative
1	2	Classroom 216	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 216	W3	CMU	White	Partially Inaccessible	0	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E	F	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Office 215	Partition Room Divider	Wood	Tan	Chipping	0	0.01	Negative
1	2	Classroom 216	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 216	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 216	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 213	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 213	Door Frame	Metal	Grey	Chipping	2	0.19	Negative
1	2	Classroom 213	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 213	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 213	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 213	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 213	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 213	Closet Shelf	Metal	Tan	Chipping	2	0.09	Negative
1	2	Classroom 213	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Classroom 213	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 213	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 213	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 214	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 214	Door Frame	Metal	Grey	Chipping	2	0.16	Negative
1	2	Classroom 214	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 214	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 214	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 214	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 214	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 214	W3	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 214	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 214	Door Frame	Metal	Grey	Chipping	2	0.3	Negative
1	2	Classroom 214	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 214	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Hallway adjacent to Classroom 214	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Hallway adjacent to Classroom 214	W2	CMU	White	Partially Inaccessible	0	0.26	Negative
1	2	Hallway adjacent to Classroom 214	Door Frame	Metal	Brown	Chipping	2	0.18	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School							
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
		1	2	Hallway adjacent to Classroom 214	Door	Metal	Brown	Chipping	2	0.03
1	2	Hallway adjacent to Classroom 214	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Hallway adjacent to Classroom 214	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Hallway adjacent to Classroom 214	Door Frame	Metal	Brown	Chipping	2	0.29	Negative	
1	2	Hallway adjacent to Classroom 214	Door	Metal	Brown	Chipping	2	0.16	Negative	
1	2	Hallway adjacent to Classroom 214	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Hallway adjacent to Classroom 214	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Nurse's Office	W1	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Nurse's Office	Door Frame	Metal	Grey	Chipping	2	0.23	Negative	
1	2	Nurse's Office	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Nurse's Office	Door Frame	Metal	Grey	Chipping	2	0.28	Negative	
1	2	Nurse's Office	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Nurse's Office	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Nurse's Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Nurse's Office	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Nurse's Office Restroom	W1	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Nurse's Office Restroom	Door Frame	Metal	Grey	Chipping	2	0.4	Negative	
1	2	Nurse's Office Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Nurse's Office Restroom	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Nurse's Office Restroom	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Nurse's Office Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Nurse's Office Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 217	W1	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217	Door Frame	Metal	Grey	Chipping	2	0.29	Negative	
1	2	Classroom 217	Door	Metal	Grey	Chipping	2	0.05	Negative	
1	2	Classroom 217	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217	Closet Shelf	Metal	Tan	Friction	2	0	Negative	
1	2	Classroom 217	W3	CMU	White	Partially Inaccessible	0	0.06	Negative	
1	2	Classroom 217	Door Frame	Metal	Grey	Chipping	2	0.21	Negative	
1	2	Classroom 217	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217	Radiator	Metal	Grey	Chipping	1	0	Negative	
1	2	Classroom 217	Door Frame	Metal	Grey	Chipping	2	0.16	Negative	
1	2	Classroom 217	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 217	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 217 Closet	W1	CMU	White	Partially Inaccessible	0	0.11	Negative	

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School							
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
		1	2	Classroom 217 Closet	Door Frame	Metal	Grey	Chipping	2	0.17
1	2	Classroom 217 Closet	Door	Metal	Grey	Chipping	2	0.04	Negative	
1	2	Classroom 217 Closet	W2	CMU	White	Partially Inaccessible	0	0.04	Negative	
1	2	Classroom 217 Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217 Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 217 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 217 Restroom	W1	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	2	Classroom 217 Restroom	Door Frame	Metal	Grey	Chipping	2	0.33	Negative	
1	2	Classroom 217 Restroom	Door	Metal	Grey	Chipping	2	0.05	Negative	
1	2	Classroom 217 Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217 Restroom	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217 Restroom	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217 Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 217 Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 217 Closet at Rear	W1	CMU	White	Partially Inaccessible	0	0.04	Negative	
1	2	Classroom 217 Closet at Rear	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 217 Closet at Rear	W3	CMU	White	Partially Inaccessible	0	0.06	Negative	
1	2	Classroom 217 Closet at Rear	W4	CMU	White	Partially Inaccessible	0	0.08	Negative	
1	2	Classroom 217 Closet at Rear	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 217 Closet at Rear	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Hallway from Classrooms 217 to 219	W1	CMU	White	Partially Inaccessible	0	0.01	Negative	
1	2	Hallway from Classrooms 217 to 219	Door Frame	Metal	Brown	Chipping	1	0.5	Negative	
1	2	Hallway from Classrooms 217 to 219	Door	Metal	Brown	Chipping	1	0.2	Negative	
1	2	Hallway from Classrooms 217 to 219	W2	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	2	Hallway from Classrooms 217 to 219	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Hallway from Classrooms 217 to 219	Radiator	Metal	Brown	Flaking	2	0	Negative	
1	2	Hallway from Classrooms 217 to 219	W4	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Hallway from Classrooms 217 to 219	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Hallway from Classrooms 217 to 219	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 219	W1	CMU	White	Partially Inaccessible	0	0.04	Negative	
1	2	Classroom 219	Door Frame	Metal	Grey	Chipping	2	0.18	Negative	
1	2	Classroom 219	Door	Metal	Grey	Chipping	2	0	Negative	
1	2	Classroom 219	W2	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 219	Door Frame	Metal	Grey	Chipping	2	0.25	Negative	

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Classroom 219	Door	Metal	Grey	Chipping	2
1	2	Classroom 219	W3	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Classroom 219	Door Frame	Metal	Grey	Chipping	2	0.21	Negative
1	2	Classroom 219	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 219	W4	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 219	Door Frame	Metal	Grey	Chipping	2	0.3	Negative
1	2	Classroom 219	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 219	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 219	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 219 Closet	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 219 Closet	Door Frame	Metal	Grey	Chipping	2	0.24	Negative
1	2	Classroom 219 Closet	Door	Metal	Grey	Chipping	2	0.02	Negative
1	2	Classroom 219 Closet	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 219 Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 219 Closet	Shelf	Wood	White	Friction	1	0.08	Negative
1	2	Classroom 219 Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 219 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 219 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 219 Restroom	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Classroom 219 Restroom	Door Frame	Metal	Grey	Chipping	2	0.21	Negative
1	2	Classroom 219 Restroom	Door	Metal	Grey	Chipping	2	0.1	Negative
1	2	Classroom 219 Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 219 Restroom	Shelf	Wood	White	Friction	2	0.1	Negative
1	2	Classroom 219 Restroom	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 219 Restroom	Shelf	Wood	White	Friction	2	0.1	Negative
1	2	Classroom 219 Restroom	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 219 Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 219 Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 219 Closet at Rear of Classroom	W1	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Classroom 219 Closet at Rear of Classroom	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 219 Closet at Rear of Classroom	W3	CMU	White	Partially Inaccessible	0	0.12	Negative
1	2	Classroom 219 Closet at Rear of Classroom	W4	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 219 Closet at Rear of Classroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 219 Closet at Rear of Classroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 220	W1	CMU	White	Partially Inaccessible	0	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Office 220	Door Frame	Metal	Grey	Chipping	2
1	2	Office 220	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 220	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 220	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 220	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 220	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Main Office	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Main Office	Door Frame	Metal	Brown	Chipping	1	0.12	Negative
1	2	Main Office	Window Frame	Metal	Brown	Chipping	1	0.15	Negative
1	2	Main Office	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Main Office	Door Frame	Metal	Grey	Chipping	2	0.26	Negative
1	2	Main Office	W3	CMU	Black	Partially Inaccessible	0	0	Negative
1	2	Main Office	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Main Office	Door Frame	Metal	Grey	Chipping	2	0.18	Negative
1	2	Main Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Main Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Main Office	Cabinets	Metal	Grey	Friction	2	0	Negative
1	2	Main Office Conference Room	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Office Conference Room	Door Frame	Metal	Grey	Chipping	2	0.22	Negative
1	2	Main Office Conference Room	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Main Office Conference Room	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Main Office Conference Room	Door Frame	Metal	Grey	Friction	1	0.27	Negative
1	2	Main Office Conference Room	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Office Conference Room	Door Frame	Metal	Grey	Friction	1	0.14	Negative
1	2	Main Office Conference Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Main Office Conference Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Principal's Office	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Principal's Office	Door Frame	Metal	Grey	Chipping	1	0.32	Negative
1	2	Principal's Office	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Principal's Office	W3	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Principal's Office	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Principal's Office	Door Frame	Metal	Grey	Chipping	2	0.19	Negative
1	2	Principal's Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Principal's Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Principal Training Office	W1	CMU	Blue	Partially Inaccessible	0	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Principal Training Office	W2	CMU	Blue	Partially Inaccessible	0
1	2	Principal Training Office	W3	CMU	Blue	Partially Inaccessible	0	0	Negative
1	2	Principal Training Office	W4	CMU	Blue	Partially Inaccessible	0	0.04	Negative
1	2	Principal Training Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Principal Training Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office Kitchen	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office Kitchen	Door Frame	Metal	Grey	Chipping	2	0.28	Negative
1	2	Office Kitchen	Door	Metal	Grey	Chipping	2	0.02	Negative
1	2	Office Kitchen	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Office Kitchen	W3	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Office Kitchen	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office Kitchen	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Staff Restroom	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Staff Restroom	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1	2	Staff Restroom	Door	Metal	Grey	Chipping	2	0.02	Negative
1	2	Staff Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Staff Restroom	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Staff Restroom	Door Frame	Metal	Grey	Chipping	2	0.25	Negative
1	2	Staff Restroom	Door	Metal	Grey	Chipping	2	0.03	Negative
1	2	Staff Restroom	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Staff Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Staff Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Principal's Office Restroom	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Principal's Office Restroom	W2	CMU	White	Partially Inaccessible	0	0.13	Negative
1	2	Principal's Office Restroom	Radiator	Metal	Grey	Chipping	1	0.15	Negative
1	2	Principal's Office Restroom	W3	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Principal's Office Restroom	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Principal's Office Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Principal's Office Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Main Office Storage in Principal Training Office	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Office Storage in Principal Training Office	W2	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Main Office Storage in Principal Training Office	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Office Storage in Principal Training Office	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Office Storage in Principal Training Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Main Office Storage in Principal Training Office	Floor	N/A	N/A	N/A	0
1	2	Closet in Main Office next to Conference Room	W1	CMU	White	Partially Inaccessible	0	0.12	Negative
1	2	Closet in Main Office next to Conference Room	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Closet in Main Office next to Conference Room	W3	CMU	White	Partially Inaccessible	0	0.1	Negative
1	2	Closet in Main Office next to Conference Room	Shelf	Wood	White	Friction	1	0.08	Negative
1	2	Closet in Main Office next to Conference Room	Bracket	Wood	White	Friction	1	0.12	Negative
1	2	Closet in Main Office next to Conference Room	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Closet in Main Office next to Conference Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Main Office next to Conference Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Main Office Conference Room	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Closet in Main Office Conference Room	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Closet in Main Office Conference Room	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Closet in Main Office Conference Room	Shelf	Wood	White	Friction	1	0.04	Negative
1	2	Closet in Main Office Conference Room	Bracket	Wood	White	Friction	1	0.06	Negative
1	2	Closet in Main Office Conference Room	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Closet in Main Office Conference Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Closet in Main Office Conference Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	MDF Computer Server Room	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	MDF Computer Server Room	Door Frame	Metal	Grey	Chipping	2	0.16	Negative
1	2	MDF Computer Server Room	Door	Metal	Grey	Chipping	2	0.1	Negative
1	2	MDF Computer Server Room	W2	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	MDF Computer Server Room	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	MDF Computer Server Room	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	MDF Computer Server Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	MDF Computer Server Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 223	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 223	W2	CMU	White	Partially Inaccessible	0	0.03	Negative
1	2	Office 223	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 223	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Office 223	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Office 223	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym	W1	CMU	White	Alligatoring	200	0.1	Negative
1	2	Gym	W2	CMU	White	Alligatoring	200	0.02	Negative
1	2	Gym	W3	CMU	White	Alligatoring	200	0.04	Negative
1	2	Gym	W4	CMU	White	Alligatoring	200	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E	F	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Gym	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Girls Restroom	W1	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Gym Girls Restroom	Door Frame	Metal	Grey	Chipping	2	0.12	Negative
1	2	Gym Girls Restroom	Door	Metal	Grey	Chipping	2	0.04	Negative
1	2	Gym Girls Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Girls Restroom	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Girls Restroom	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Gym Girls Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Girls Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Boys Restroom	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Gym Boys Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Boys Restroom	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Boys Restroom	W4	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Gym Boys Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Boys Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Storage next to Boys Bathroom	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Storage next to Boys Bathroom	Door Frame	Metal	Grey	Chipping	2	0.29	Negative
1	2	Gym Storage next to Boys Bathroom	Door	Metal	Grey	Chipping	2	0.11	Negative
1	2	Gym Storage next to Boys Bathroom	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Gym Storage next to Boys Bathroom	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Storage next to Boys Bathroom	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Storage next to Boys Bathroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Storage next to Boys Bathroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Office	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Office	W2	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Gym Office	W3	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Gym Office	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Gym Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Office Restroom	W1	CMU	White	Partially Inaccessible	0	0.1	Negative
1	2	Gym Office Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Office Restroom	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Gym Office Restroom	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Gym Office Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Gym Office Restroom	Floor	N/A	N/A	N/A	0
1	2	Gym Storage in Gym Office	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Storage in Gym Office	Door Frame	Metal	Grey	Chipping	2	0.3	Negative
1	2	Gym Storage in Gym Office	Door	Metal	Grey	Chipping	2	0.16	Negative
1	2	Gym Storage in Gym Office	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Storage in Gym Office	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Storage in Gym Office	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Gym Storage in Gym Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Gym Storage in Gym Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Main Hallway	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Hallway	Door Frame	Metal	Grey	Friction	5	0.16	Negative
1	2	Main Hallway	Door Frame	Metal	Brown	Chipping	2	0.08	Negative
1	2	Main Hallway	Door	Metal	Brown	Chipping	2	0.06	Negative
1	2	Main Hallway	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Hallway	Radiator	Metal	Grey	Chipping	1	0.08	Negative
1	2	Main Hallway	Door Frame	Metal	Grey	Friction	5	0.23	Negative
1	2	Main Hallway	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Hallway	Door Frame	Metal	Grey	Friction	5	0.21	Negative
1	2	Main Hallway	Door Frame	Metal	Brown	Chipping	2	0.05	Negative
1	2	Main Hallway	Door	Metal	Brown	Chipping	2	0.12	Negative
1	2	Main Hallway	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Main Hallway	Radiator	Metal	Grey	Chipping	1	0.05	Negative
1	2	Main Hallway	Door Frame	Metal	Grey	Friction	5	0.29	Negative
1	2	Main Hallway	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Main Hallway	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Lobby Hallway	W1	Brick	N/A	N/A	0	N/A	N/A
1	2	Lobby Hallway	Door Frame	Metal	Brown	Chipping	2	0.4	Negative
1	2	Lobby Hallway	Door	Metal	Brown	Chipping	2	0.4	Negative
1	2	Lobby Hallway	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Lobby Hallway	Door Frame	Metal	Brown	Chipping	2	0.2	Negative
1	2	Lobby Hallway	Window Frame	Metal	Brown	Chipping	2	0.17	Negative
1	2	Lobby Hallway	Radiator	Metal	Grey	Chipping	1	0.1	Negative
1	2	Lobby Hallway	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Lobby Hallway	Door Frame	Metal	Brown	Chipping	2	0.2	Negative
1	2	Lobby Hallway	Door	Metal	Brown	Chipping	2	0.2	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Lobby Hallway	W4	CMU	White	Chipping	10
1	2	Lobby Hallway	Door Frame	Metal	Brown	Chipping	2	0.15	Negative
1	2	Lobby Hallway	Window Frame	Metal	Brown	Chipping	2	0.23	Negative
1	2	Lobby Hallway	Radiator	Metal	Grey	Chipping	1	0.1	Negative
1	2	Lobby Hallway	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Lobby Hallway	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Hallway adjacent to Nurse's Office	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Hallway adjacent to Nurse's Office	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Hallway adjacent to Nurse's Office	W3	CMU	White	Partially Inaccessible	0	0.4	Negative
1	2	Hallway adjacent to Nurse's Office	W4	CMU	White	Partially Inaccessible	0	0.01	Negative
1	2	Hallway adjacent to Nurse's Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Hallway adjacent to Nurse's Office	Radiator	Metal	Silver	Cracking	1	0.28	Negative
1	2	Hallway adjacent to Nurse's Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell adjacent to Classroom 202	W1	CMU	White	Partially Inaccessible	0	0.1	Negative
1	2	Stairwell adjacent to Classroom 202	Door Frame	Metal	Brown	Chipping	1	0.15	Negative
1	2	Stairwell adjacent to Classroom 202	Door	Metal	Brown	Chipping	1	0.1	Negative
1	2	Stairwell adjacent to Classroom 202	W2	CMU	White	Partially Inaccessible	0	0.23	Negative
1	2	Stairwell adjacent to Classroom 202	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Stairwell adjacent to Classroom 202	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Stairwell adjacent to Classroom 202	Stringer	Metal	Black	Chipping	2	0.28	Negative
1	2	Stairwell adjacent to Classroom 202	Soffit	Metal	Black	Chipping	2	0.32	Negative
1	2	Stairwell adjacent to Classroom 202	Tread	Metal	Black	Chipping	4	0.12	Negative
1	2	Stairwell adjacent to Classroom 202	Cage	Metal	Black	Chipping	3	0.51	Negative
1	2	Stairwell adjacent to Classroom 202	Door Frame	Metal	Brown	Chipping	2	0	Negative
1	2	Stairwell adjacent to Classroom 202	Door	Metal	Brown	Chipping	2	0	Negative
1	2	Stairwell adjacent to Classroom 202	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Stairwell adjacent to Classroom 202	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Entrance Stairwell	W1	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	Main Entrance Stairwell	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Main Entrance Stairwell	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Main Entrance Stairwell	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Main Entrance Stairwell	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Main Entrance Stairwell	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Closet near Cafeteria	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Custodial Closet near Cafeteria	W2	CMU	White	Partially Inaccessible	0	0.04	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Custodial Closet near Cafeteria	W3	CMU	White	Partially Inaccessible	0
1	1	Custodial Closet near Cafeteria	Shelf	Wood	White	Friction	1	0.14	Negative
1	1	Custodial Closet near Cafeteria	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Custodial Closet near Cafeteria	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Closet near Cafeteria	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom on the Main Lobby side	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Girl's Restroom on the Main Lobby side	Door Frame	Metal	Grey	Chipping	2	0.31	Negative
1	1	Girl's Restroom on the Main Lobby side	Door	Metal	Grey	Chipping	2	0.03	Negative
1	1	Girl's Restroom on the Main Lobby side	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Girl's Restroom on the Main Lobby side	W3	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	Girl's Restroom on the Main Lobby side	W4	CMU	White	Partially Inaccessible	0	0.08	Negative
1	1	Girl's Restroom on the Main Lobby side	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom on the Main Lobby side	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom on the Main Lobby side	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Boy's Restroom on the Main Lobby side	Door Frame	Metal	Grey	Chipping	2	0.26	Negative
1	1	Boy's Restroom on the Main Lobby side	Door	Metal	Grey	Chipping	2	0.02	Negative
1	1	Boy's Restroom on the Main Lobby side	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Boy's Restroom on the Main Lobby side	W3	CMU	White	Partially Inaccessible	0	0.1	Negative
1	1	Boy's Restroom on the Main Lobby side	W4	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	Boy's Restroom on the Main Lobby side	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom on the Main Lobby side	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	ESOL Office adjacent to Kitchen	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	ESOL Office adjacent to Kitchen	Door Frame	Metal	Grey	Chipping	2	0.14	Negative
1	1	ESOL Office adjacent to Kitchen	Door	Metal	Grey	Chipping	2	0.02	Negative
1	1	ESOL Office adjacent to Kitchen	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	ESOL Office adjacent to Kitchen	Door Frame	Metal	Grey	Chipping	1	0.27	Negative
1	1	ESOL Office adjacent to Kitchen	W3	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	ESOL Office adjacent to Kitchen	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	ESOL Office adjacent to Kitchen	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	ESOL Office adjacent to Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 101	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 101	Door Frame	Metal	Grey	Chipping	2	0.1	Negative
1	2	Classroom 101	Door	Metal	Grey	Chipping	2	0.04	Negative
1	2	Classroom 101	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 101	W3	CMU	White	Partially Inaccessible	0	0.05	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Classroom 101	W4	CMU	White	Partially Inaccessible	0
1	2	Classroom 101	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 101	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 101	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 101	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 101	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 102	W1	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Classroom 102	Door Frame	Metal	Grey	Chipping	2	0.28	Negative
1	2	Classroom 102	Door	Metal	Grey	Chipping	2	0.05	Negative
1	2	Classroom 102	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 102	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 102	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 102	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 102	W3	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Classroom 102	W4	CMU	White	Partially Inaccessible	0	0.12	Negative
1	2	Classroom 102	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 102	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 102 Small Closet	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 102 Small Closet	W2	CMU	White	Partially Inaccessible	0	0.15	Negative
1	1	Classroom 102 Small Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 102 Small Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 102 Small Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 102 Small Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen Dry Storage	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Kitchen Dry Storage	Door Frame	Metal	Grey	Chipping	2	0.18	Negative
1	1	Kitchen Dry Storage	Door	Metal	Grey	Chipping	2	0	Negative
1	1	Kitchen Dry Storage	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Kitchen Dry Storage	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Kitchen Dry Storage	W4	CMU	White	Partially Inaccessible	0	0.03	Negative
1	1	Kitchen Dry Storage	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen Dry Storage	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	W1	CMU	White	Partially Inaccessible	0	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E	F	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Kitchen	Door Frame	Metal	Grey	Chipping	2	0.15	Negative
1	1	Kitchen	Door	Metal	Grey	Chipping	2	0.02	Negative
1	1	Kitchen	W2	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	Kitchen	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Kitchen	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Kitchen	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	W1	CMU	White	Partially Inaccessible	0	0.08	Negative
1	1	Kitchen	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Kitchen	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Kitchen	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Kitchen	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen (Cold Storage)	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Kitchen (Cold Storage)	Door Frame	Metal	Grey	Chipping	2	0.24	Negative
1	1	Kitchen (Cold Storage)	Door	Metal	Grey	Chipping	2	0	Negative
1	1	Kitchen (Cold Storage)	W2	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Kitchen (Cold Storage)	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Kitchen (Cold Storage)	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Kitchen (Cold Storage)	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen (Cold Storage)	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen Locker/Restroom	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Kitchen Locker/Restroom	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Kitchen Locker/Restroom	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Kitchen Locker/Restroom	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Kitchen Locker/Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Kitchen Locker/Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage Room with Computer Server next to Classroom 103	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Storage Room with Computer Server next to Classroom 103	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Storage Room with Computer Server next to Classroom 103	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Storage Room with Computer Server next to Classroom 103	Closet Shelf	Wood	White	Friction	1	0.2	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Storage Room with Computer Server next to Classroom 103	Coat Rack	Wood	White	Friction	1
1	1	Storage Room with Computer Server next to Classroom 103	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Storage Room with Computer Server next to Classroom 103	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Storage Room with Computer Server next to Classroom 103	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell adjacent to Classroom 103	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Women's Restroom Outside 103	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Women's Restroom Outside 103	Door Frame	Metal	Grey	Chipping	2	0.15	Negative
1	1	Women's Restroom Outside 103	Door	Metal	Grey	Chipping	2	0	Negative
1	1	Women's Restroom Outside 103	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Women's Restroom Outside 103	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Women's Restroom Outside 103	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Men's Restroom Outside 103	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Men's Restroom Outside 103	Door Frame	Metal	Grey	Chipping	2	0.28	Negative
1	1	Men's Restroom Outside 103	Door	Metal	Grey	Chipping	2	0.05	Negative
1	1	Men's Restroom Outside 103	Door Frame	Metal	Grey	Chipping	2	0.22	Negative
1	1	Men's Restroom Outside 103	Door	Metal	Grey	Chipping	2	0.02	Negative
1	1	Men's Restroom Outside 103	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Men's Restroom Outside 103	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Men's Restroom Outside 103	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Stairwell adjacent to Classroom 103	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Stairwell adjacent to Classroom 103	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Stairwell adjacent to Classroom 103	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Stairwell adjacent to Classroom 103	Door Frame	Metal	Brown	Chipping	2	0.08	Negative
1	1	Stairwell adjacent to Classroom 103	Door	Metal	Brown	Chipping	2	0.05	Negative
1	1	Stairwell adjacent to Classroom 103	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell adjacent to Classroom 103	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 103	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 103	Door Frame	Metal	Grey	Chipping	2	0.17	Negative
1	2	Classroom 103	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 103	W2	CMU	White	Partially Inaccessible	0	0.06	Negative
1	2	Classroom 103	W3	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Classroom 103	W4	CMU	White	Partially Inaccessible	0	0.1	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 103	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 103	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 103 Closet	W1	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Classroom 103 Closet	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	Classroom 103 Closet	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Classroom 103 Closet	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Classroom 103 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 103 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 103 Small Closet	W1	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	Classroom 103 Small Closet	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Classroom 103 Small Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 103 Small Closet	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Classroom 103 Small Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 103 Small Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 104	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 104	W2	CMU	White	Partially Inaccessible	0	0.07	Negative
1	2	Classroom 104	Partition	Canvas	Tan	Chipping	1	0.05	Negative
1	2	Classroom 104	Partition Trim	Wood	Tan	Chipping	1	0.03	Negative
1	2	Classroom 104	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 104	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 104	Partition	Canvas	Tan	Chipping	1	0.04	Negative
1	2	Classroom 104	Partition Trim	Wood	Tan	Chipping	1	0	Negative
1	2	Classroom 104	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 104	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 104 Closet	W2	CMU	White	Partially Inaccessible	0	0.03	Negative
1	1	Classroom 104 Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 104 Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 104 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 104 Small Closet	W1	CMU	White	Partially Inaccessible	0	0.03	Negative
1	1	Classroom 104 Small Closet	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 104 Small Closet	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Classroom 104 Small Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 104 Small Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Classroom 104 Small Closet	Floor	N/A	N/A	N/A	0
1	1	Hallway adjacent to Room 104	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Hallway adjacent to Room 104	W2	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Hallway adjacent to Room 104	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Hallway adjacent to Room 104	W4	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	Stairwell adjacent to Classroom 103	Door Frame	Metal	Brown	Chipping	2	0.05	Negative
1	1	Stairwell adjacent to Classroom 103	Door	Metal	Brown	Chipping	2	0	Negative
1	1	Hallway adjacent to Room 104	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway adjacent to Room 104	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 105	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 105	Door Frame	Metal	Grey	Chipping	2	0.33	Negative
1	2	Classroom 105	Door	Metal	Grey	Chipping	2	0.02	Negative
1	2	Classroom 105	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 105	Door Frame	Metal	Grey	Friction	1	0.27	Negative
1	2	Classroom 105	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 105	Door Frame	Metal	Grey	Friction	1	0.32	Negative
1	2	Classroom 105	W4	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 105	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 105	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105 Closet	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 105 Closet	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	Classroom 105 Closet	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 105 Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 105 Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105 Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105 Small Closet	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Classroom 105 Small Closet	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 105 Small Closet	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Classroom 105 Small Closet	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Classroom 105 Small Closet	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Classroom 105 Small Closet	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom/Utility Closet at the Kitchen	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Boy's Restroom/Utility Closet at the Kitchen	Door Frame	Metal	Grey	Chipping	2	0.24	Negative
1	1	Boy's Restroom/Utility Closet at the Kitchen	Door	Metal	Grey	Chipping	2	0.02	Negative
1	1	Boy's Restroom/Utility Closet at the Kitchen	W2	CMU	White	Partially Inaccessible	0	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Boy's Restroom/Utility Closet at the Kitchen	W3	CMU	White	Partially Inaccessible	0
1	1	Boy's Restroom/Utility Closet at the Kitchen	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Boy's Restroom/Utility Closet at the Kitchen	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom/Utility Closet at the Kitchen	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom at Classroom 105	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Girl's Restroom at Classroom 105	Door Frame	Metal	Grey	Chipping	2	0.15	Negative
1	1	Girl's Restroom at Classroom 105	Door	Metal	Grey	Chipping	2	0.05	Negative
1	1	Girl's Restroom at Classroom 105	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Girl's Restroom at Classroom 105	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Girl's Restroom at Classroom 105	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Girl's Restroom at Classroom 105	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Girl's Restroom at Classroom 105	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom/Utility Closet at Classroom 105	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Boy's Restroom/Utility Closet at Classroom 105	W2	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	Boy's Restroom/Utility Closet at Classroom 105	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Boy's Restroom/Utility Closet at Classroom 105	W4	CMU	White	Partially Inaccessible	0	0.08	Negative
1	1	Boy's Restroom/Utility Closet at Classroom 105	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Boy's Restroom/Utility Closet at Classroom 105	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway next to Classroom 106	W1	CMU	Green	Partially Inaccessible	0	0	Negative
1	1	Hallway next to Classroom 106	Radiator	Metal	Brown	Chipping	2	0	Negative
1	1	Hallway next to Classroom 106	W2	CMU	Green	Partially Inaccessible	0	0.02	Negative
1	1	Hallway next to Classroom 106	W3	CMU	Green	Partially Inaccessible	0	0.02	Negative
1	1	Hallway next to Classroom 106	W4	CMU	Green	Partially Inaccessible	0	0	Negative
1	1	Hallway next to Classroom 106	Door Frame	Metal	Brown	Chipping	2	0.12	Negative
1	1	Hallway next to Classroom 106	Door	Metal	Brown	Chipping	2	0.04	Negative
1	1	Hallway next to Classroom 106	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Hallway next to Classroom 106	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 106	W1	CMU	White	Partially Inaccessible	0	0.01	Negative
1	2	Classroom 106	Door Frame	Metal	Grey	Chipping	2	0.09	Negative
1	2	Classroom 106	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 106	Coat Rack	Metal	Brown	Friction	2	0.11	Negative
1	2	Classroom 106	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 106	W3	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 106	W4	CMU	White	Partially Inaccessible	0	0.02	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E	F	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 106	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 106	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 106	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 106	Door Frame	Metal	Grey	Chipping	1	0.3	Negative
1	2	Classroom 106	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 106	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 107	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 107	Door Frame	Metal	Grey	Chipping	2	0.15	Negative
1	2	Classroom 107	Door	Metal	Grey	Chipping	2	0.08	Negative
1	2	Classroom 107	Coat Rack	Metal	Brown	Friction	2	0.15	Negative
1	2	Classroom 107	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 107	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 107	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 107	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 107	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	2	Classroom 107	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 107	Door Frame	Metal	Grey	Chipping	1	0.32	Negative
1	2	Classroom 107	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 107	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Office A12	W1	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	Office A12	Door Frame	Metal	Grey	Chipping	2	0.22	Negative
1	1	Office A12	Door	Metal	Grey	Chipping	2	0.02	Negative
1	1	Office A12	W2	CMU	White	Partially Inaccessible	0	0.12	Negative
1	1	Office A12	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Office A12	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Office A12	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Office A12	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Office A13	W1	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	Office A13	Door Frame	Metal	Grey	Chipping	2	0.28	Negative
1	1	Office A13	Door	Metal	Grey	Chipping	2	0.04	Negative
1	1	Office A13	W2	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Office A13	W3	CMU	White	Partially Inaccessible	0	0.01	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Office A13	W4	CMU	White	Partially Inaccessible	0
1	1	Office A13	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Office A13	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 108	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 108	Door Frame	Metal	Grey	Chipping	2	0.3	Negative
1	2	Classroom 108	Door	Metal	Grey	Chipping	2	0.05	Negative
1	2	Classroom 108	Coat Rack	Metal	Brown	Friction	2	0.11	Negative
1	2	Classroom 108	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 108	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 108	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 108	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 108	W3	CMU	White	Partially Inaccessible	0	0.03	Negative
1	2	Classroom 108	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 108	Door Frame	Metal	Grey	Chipping	1	0.15	Negative
1	2	Classroom 108	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 108	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell next to Classroom 108	W1	CMU	White	Partially Inaccessible	0	0.1	Negative
1	1	Stairwell next to Classroom 108	Door Frame	Metal	Brown	Chipping	2	0.05	Negative
1	1	Stairwell next to Classroom 108	Door	Metal	Brown	Chipping	2	0	Negative
1	1	Stairwell next to Classroom 108	W2	CMU	White	Partially Inaccessible	0	0.12	Negative
1	1	Stairwell next to Classroom 108	Door Frame	Metal	Brown	Chipping	2	0.1	Negative
1	1	Stairwell next to Classroom 108	Door	Metal	Brown	Chipping	2	0.02	Negative
1	1	Stairwell next to Classroom 108	W3	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	Stairwell next to Classroom 108	Radiator	Metal	Grey	Chipping	4	0	Negative
1	1	Stairwell next to Classroom 108	W4	CMU	White	Partially Inaccessible	0	0.16	Negative
1	1	Stairwell next to Classroom 108	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell next to Classroom 108	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell next to Classroom 108	Soffit	Metal	Grey	Chipping	2	0.5	Negative
1	1	Stairwell next to Classroom 108	Stringer	Metal	Grey	Chipping	1	0.16	Negative
1	1	Stairwell next to Classroom 108	Riser	Metal	Grey	Chipping	4	0.4	Negative
1	2	Classroom 109	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	2	Classroom 109	Door Frame	Metal	Grey	Chipping	2	0.16	Negative
1	2	Classroom 109	Door	Metal	Grey	Chipping	2	0.1	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School							
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
		1	2	Classroom 109	W2	CMU	White	Partially Inaccessible	0	0.04
1	2	Classroom 109	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	2	Classroom 109	W4	CMU	White	Partially Inaccessible	0	0.08	Negative	
1	2	Classroom 109	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative	
1	2	Classroom 109	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative	
1	2	Classroom 109	Partition Trim	Wood	Tan	Chipping	0	0	Negative	
1	2	Classroom 109	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 109	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	1	Auditorium Storage	W1	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	1	Auditorium Storage	Door Frame	Metal	Grey	Chipping	2	0.12	Negative	
1	1	Auditorium Storage	Door	Metal	Grey	Chipping	2	0.12	Negative	
1	1	Auditorium Storage	W2	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	1	Auditorium Storage	W3	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	1	Auditorium Storage	Shelf	Wood	White	Friction	2	0	Negative	
1	1	Auditorium Storage	W4	CMU	White	Partially Inaccessible	0	0.05	Negative	
1	1	Auditorium Storage	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	1	Auditorium Storage	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	1	Office A15 across from Classroom 110	W1	CMU	White	Partially Inaccessible	0	0	Negative	
1	1	Office A15 across from Classroom 110	Door Frame	Metal	Grey	Chipping	2	0.26	Negative	
1	1	Office A15 across from Classroom 110	Door	Metal	Grey	Chipping	2	0.02	Negative	
1	1	Office A15 across from Classroom 110	W2	CMU	White	Partially Inaccessible	0	0.04	Negative	
1	1	Office A15 across from Classroom 110	W3	CMU	White	Partially Inaccessible	0	0	Negative	
1	1	Office A15 across from Classroom 110	W4	CMU	White	Partially Inaccessible	0	0.04	Negative	
1	1	Office A15 across from Classroom 110	Ceiling	N/A	N/A	N/A	0	N/A	N/A	
1	1	Office A15 across from Classroom 110	Floor	N/A	N/A	N/A	0	N/A	N/A	
1	2	Classroom 110	W1	CMU	White	Partially Inaccessible	0	0.06	Negative	
1	2	Classroom 110	Door Frame	Metal	Grey	Chipping	2	0.18	Negative	
1	2	Classroom 110	Door	Metal	Grey	Chipping	2	0	Negative	
1	2	Classroom 110	W2	CMU	White	Partially Inaccessible	0	0.02	Negative	
1	2	Classroom 110	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative	
1	2	Classroom 110	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative	
1	2	Classroom 110	Partition Trim	Wood	Tan	Chipping	0	0	Negative	

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	2	Classroom 110	W3	CMU	White	Partially Inaccessible	0
1	2	Classroom 110	W4	CMU	White	Partially Inaccessible	0	0.05	Negative
1	2	Classroom 110	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 110	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 111	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 111	Door Frame	Metal	Grey	Chipping	2	0.21	Negative
1	2	Classroom 111	Door	Metal	Grey	Chipping	2	0	Negative
1	2	Classroom 111	Coat Rack	Metal	Brown	Friction	1	0.09	Negative
1	2	Classroom 111	W2	CMU	White	Partially Inaccessible	0	0.08	Negative
1	2	Classroom 111	Partition Room Divider	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 111	Partition Baseboard	Wood	Brown	Chipping	0	0	Negative
1	2	Classroom 111	Partition Trim	Wood	Tan	Chipping	0	0	Negative
1	2	Classroom 111	W3	CMU	White	Partially Inaccessible	0	0.1	Negative
1	2	Classroom 111	Radiator	Metal	Tan	Chipping	1	0	Negative
1	2	Classroom 111	Door Frame	Metal	Grey	Chipping	1	0.24	Negative
1	2	Classroom 111	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1	2	Classroom 111	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	Classroom 111	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell adjacent to Classroom 111	W1	CMU	White	Partially Inaccessible	0	0.07	Negative
1	1	Stairwell adjacent to Classroom 111	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	Stairwell adjacent to Classroom 111	W3	CMU	White	Partially Inaccessible	0	0.18	Negative
1	1	Stairwell next to Classroom 108	Door Frame	Metal	Brown	Chipping	2	0.06	Negative
1	1	Stairwell next to Classroom 108	Door	Metal	Brown	Chipping	2	0.04	Negative
1	1	Stairwell adjacent to Classroom 111	W4	CMU	White	Partially Inaccessible	0	0.12	Negative
1	1	Stairwell adjacent to Classroom 111	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell adjacent to Classroom 111	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stairwell adjacent to Classroom 111	Riser	Concrete	Grey	Friction	0	0	Negative
1	1	Stairwell adjacent to Classroom 111	Stringer	Metal	Grey	Friction	0.5	0.5	Negative
1	1	Music Room	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Music Room	Door Frame	Metal	Grey	Chipping	2	0.14	Negative
1	1	Music Room	Door	Metal	Grey	Chipping	2	0.04	Negative
1	1	Music Room	W2	CMU	White	Partially Inaccessible	0	0.01	Negative
1	1	Music Room	W3	CMU	White	Partially Inaccessible	0	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Music Room	W4	CMU	White	Partially Inaccessible	0
1	1	Music Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Music Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Cafeteria/Auditorium	W1	CMU	White	None	0	0	Negative
1	1	Cafeteria/Auditorium	Column	Concrete	White	Friction	4	0.09	Negative
1	1	Cafeteria/Auditorium	Expansion Joint	Metal	White	Chipping	2	0	Negative
1	1	Cafeteria/Auditorium	W2	CMU	White	None	0	0	Negative
1	1	Cafeteria/Auditorium	Column	Concrete	White	Friction	4	0.12	Negative
1	1	Cafeteria/Auditorium	W3	CMU	White	None	0	0.02	Negative
1	1	Cafeteria/Auditorium	Column	Concrete	White	Friction	4	0.08	Negative
1	1	Cafeteria/Auditorium	W4	CMU	White	None	0	0.05	Negative
1	1	Cafeteria/Auditorium	Column	Concrete	White	Friction	4	0.1	Negative
1	1	Cafeteria/Auditorium	Ceiling	Concrete	White	Chipping	20	0.1	Negative
1	1	Cafeteria/Auditorium	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Cafeteria/Auditorium	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stage Steps	W1	CMU	Black	Partially Inaccessible	0	0	Negative
1	1	Stage Steps	W2	CMU	Black	Partially Inaccessible	0	0	Negative
1	1	Stage Steps	Column	Concrete	Black	Partially Inaccessible	0	0.04	Negative
1	1	Stage Steps	W3	CMU	Black	Partially Inaccessible	0	0	Negative
1	1	Stage Steps	Column	Concrete	Black	Partially Inaccessible	0	0.12	Negative
1	1	Stage Steps	W4	CMU	Black	Partially Inaccessible	0	0.09	Negative
1	1	Stage Steps	Column	Concrete	Black	Partially Inaccessible	0	0.04	Negative
1	1	Stage Steps	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Stage Steps	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Stage	W1	CMU	Black	Partially Inaccessible	0	0.1	Negative
1	1	Stage	W2	CMU	Black	Partially Inaccessible	0	0	Negative
1	1	Stage	W3	CMU	Black	Partially Inaccessible	0	0.04	Negative
1	1	Stage	W4	CMU	Black	Partially Inaccessible	0	0.06	Negative
1	1	Stage	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Stage	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Open Stage Storage behind Stage Curtains	W1	CMU	White	Partially Inaccessible	0	0.11	Negative
1	1	Open Stage Storage behind Stage Curtains	W2	CMU	White	Partially Inaccessible	0	0.06	Negative
1	1	Open Stage Storage behind Stage Curtains	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Open Stage Storage behind Stage Curtains	W4	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	Open Stage Storage behind Stage Curtains	Ceiling	N/A	N/A	N/A	0	N/A	N/A

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Open Stage Storage behind Stage Curtains	Floor	N/A	N/A	N/A	0
1	1	Stage Dressing Room	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Stage Dressing Room	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1	1	Stage Dressing Room	Door	Metal	Grey	Chipping	2	0.06	Negative
1	1	Stage Dressing Room	W2	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Stage Dressing Room	W3	CMU	White	Partially Inaccessible	0	0.14	Negative
1	1	Stage Dressing Room	W4	CMU	White	Partially Inaccessible	0	0.09	Negative
1	1	Stage Dressing Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Stage Dressing Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Electrical Room	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Electrical Room	Door Frame	Metal	Grey	Chipping	2	0.2	Negative
1	1	Electrical Room	Door	Metal	Grey	Chipping	2	0.04	Negative
1	1	Electrical Room	W2	CMU	White	Flaking	12	0.21	Negative
1	1	Electrical Room	W3	CMU	White	Flaking	12	0.17	Negative
1	1	Electrical Room	W4	CMU	White	Flaking	12	0.14	Negative
1	1	Electrical Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Electrical Room	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Building Engineer's Office Restroom	W1	CMU	White	None	0	0.24	Negative
1	1	Building Engineer's Office Restroom	Door Frame	Metal	Grey	Chipping	2	0.18	Negative
1	1	Building Engineer's Office Restroom	Door	Metal	Grey	Chipping	2	0	Negative
1	1	Building Engineer's Office Restroom	W2	CMU	White	None	0	0.2	Negative
1	1	Building Engineer's Office Restroom	W3	CMU	White	Cracking	2	0.3	Negative
1	1	Building Engineer's Office Restroom	Mirror Frame	Wood	White	Cracking	1	0	Negative
1	1	Building Engineer's Office Restroom	Radiator	Metal	Black	Chipping	1	0.01	Negative
1	1	Building Engineer's Office Restroom	W4	Concrete	White	None	0	0.4	Negative
1	1	Building Engineer's Office Restroom	Radiator	Metal	Grey	Chipping	1	0.1	Negative
1	1	Building Engineer's Office Restroom	Stall Divider	Metal	Grey	Chipping	1	0.12	Negative
1	1	Building Engineer's Office Restroom	Ceiling	Sheetrock	White	None	0	0	Negative
1	1	Building Engineer's Office Restroom	Floor	Concrete	Grey	Friction	4	0	Negative
1	1	Building Engineer's Office	W1	CMU	White	Flaking	12	0.3	Negative
1	1	Building Engineer's Office	Door Frame	Metal	Grey	Chipping	2	0.17	Negative
1	1	Building Engineer's Office	Door	Metal	Grey	Chipping	2	0	Negative
1	1	Building Engineer's Office	W2	CMU	White	Flaking	2	0.23	Negative
1	1	Building Engineer's Office	W3	CMU	White	Flaking	12	0.3	Negative
1	1	Building Engineer's Office	W4	CMU	White	Flaking	6	0.1	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Building Engineer's Office	Radiator	Metal	Grey	Chipping	1
1	1	Building Engineer's Office	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Building Engineer's Office	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Building Engineer's Office	Diamond Plate	Metal	Grey	Chipping	2	0.04	Negative
1	1	Receiving Dock	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Receiving Dock	Door Frame	Metal	Grey	Chipping	1	0.16	Negative
1	1	Receiving Dock	Door	Metal	Grey	Chipping	1	0.08	Negative
1	1	Receiving Dock	Window Frame	Metal	Grey	Chipping	1	0.12	Negative
1	1	Receiving Dock	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1	1	Receiving Dock	W3	CMU	White	Partially Inaccessible	0	0.14	Negative
1	1	Receiving Dock	W4	CMU	White	Partially Inaccessible	0	0.1	Negative
1	1	Receiving Dock	Ceiling	N/A	N/A	N/A	0	0.16	Negative
1	1	Receiving Dock	Floor	N/A	N/A	N/A	0	0.08	Negative
1	1	Boiler Room	W1	CMU	White	Partially Inaccessible	0	0.4	Negative
1	1	Boiler Room	Door Frame	Metal	Grey	Chipping	1	0.2	Negative
1	1	Boiler Room	Door	Metal	Grey	Chipping	1	0.19	Negative
1	1	Boiler Room	Window Frame	Metal	Grey	Chipping	1	0.1	Negative
1	1	Boiler Room	W2	CMU	White	Partially Inaccessible	0	0.13	Negative
1	1	Boiler Room	Door Frame	Metal	Grey	Chipping	1	0.23	Negative
1	1	Boiler Room	Door	Metal	Grey	Chipping	1	0.29	Negative
1	1	Boiler Room	W3	CMU	White	Partially Inaccessible	0	0.27	Negative
1	1	Boiler Room	W3	Brick	White	Partially Inaccessible	0	0	Negative
1	1	Boiler Room	Door Frame	Metal	Grey	Chipping	1	0.2	Negative
1	1	Boiler Room	Door	Metal	Grey	Chipping	1	0.1	Negative
1	1	Boiler Room	Conduit	Metal	White	Chipping	2	0.05	Negative
1	1	Boiler Room	W4	CMU	White	Partially Inaccessible	0	0.3	Negative
1	1	Boiler Room	Door Frame	Metal	Grey	Chipping	1	0.24	Negative
1	1	Boiler Room	Door	Metal	Grey	Chipping	1	0.08	Negative
1	1	Boiler Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Boiler Room	Duct	Metal	White	Chipping	1	0.09	Negative
1	1	Boiler Room	Floor	Concrete	Grey	Chipping	20	0	Negative
1	1	Boiler Room	Diamond Plate	Metal	Grey	Chipping	20	0.1	Negative
1	1	Boiler Room Storage	W1	CMU	White	Partially Inaccessible	0	0.12	Negative
1	1	Boiler Room Storage	Door Frame	Metal	Grey	Chipping	2	0.26	Negative
1	1	Boiler Room Storage	Door	Metal	Grey	Chipping	2	0	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Boiler Room Storage	W2	CMU	White	Partially Inaccessible	0
1	1	Boiler Room Storage	W3	CMU	White	Partially Inaccessible	0	0.25	Negative
1	1	Boiler Room Storage	W4	CMU	White	Partially Inaccessible	0	0.24	Negative
1	1	Boiler Room Storage	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Boiler Room Storage	Floor	Concrete	Grey	None	0	0	Negative
1	1	Pump Room	W1	CMU	Tan	None	0	0.05	Negative
1	1	Pump Room	W1	CMU	White	Chipping	4	0.07	Negative
1	1	Pump Room	Door Frame	Metal	Grey	Chipping	1	0.07	Negative
1	1	Pump Room	Door	Metal	White	Chipping	1	0.11	Negative
1	1	Pump Room	Conduit	Metal	White	Flaking	2	0.21	Negative
1	1	Pump Room	W2	CMU	White	Chipping	5	0.28	Negative
1	1	Pump Room	Door Frame	Metal	Grey	Chipping	1	0.19	Negative
1	1	Pump Room	Door	Metal	White	Chipping	1	0.3	Negative
1	1	Pump Room	Conduit	Metal	White	Flaking	2	0.21	Negative
1	1	Pump Room	W3	CMU	White	Partially Inaccessible	0	0.07	Negative
1	1	Pump Room	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1	1	Pump Room	Conduit	Metal	White	Chipping	2	0.09	Negative
1	1	Pump Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Pump Room	Floor	Concrete	Grey	Chipping	10	0	Negative
1	1	Water Main Room	W1	CMU	Tan	Partially Inaccessible	0	0.2	Negative
1	1	Water Main Room	W1	CMU	Brown	Partially Inaccessible	0	0.25	Negative
1	1	Water Main Room	W2	CMU	Tan	Partially Inaccessible	0	0.26	Negative
1	1	Water Main Room	W3	CMU	Tan	Partially Inaccessible	0	0.06	Negative
1	1	Water Main Room	Door Frame	Metal	Grey	Friction	1	0.11	Negative
1	1	Water Main Room	Door	Metal	Grey	Friction	1	0.4	Negative
1	1	Water Main Room	W4	CMU	Tan	Partially Inaccessible	0	0.1	Negative
1	1	Water Main Room	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Water Main Room	Floor	Concrete	Grey	Chipping	20	0	Negative
1	1	Custodial Lounge	W1	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Custodial Lounge	W2	CMU	White	Partially Inaccessible	0	0.01	Negative
1	1	Custodial Lounge	W3	CMU	White	Cracking	1	0.05	Negative
1	1	Custodial Lounge	Door Frame	Metal	Black	Chipping	1	0.2	Negative
1	1	Custodial Lounge	W4	CMU	White	Partially Inaccessible	0	0	Negative
1	1	Custodial Lounge	Door Frame	Metal	Brown	Chipping	1	0.21	Negative
1	1	Custodial Lounge	Door	Metal	Brown	Chipping	1	0.21	Negative

		Inspection Dates: 02/28-03/18/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: R. Hutsell/B. McMahon	John Hancock Demonstrative Elementary School						
		Inspection Company: Synertech	3700 Morrell Ave, Philadelphia, PA 19114						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	1	Custodial Lounge	Ceiling	N/A	N/A	N/A	0
1	1	Custodial Lounge	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Restroom	W1	CMU	White	Partially Inaccessible	0	0.07	Negative
1	1	Custodial Restroom	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1	1	Custodial Restroom	W3	CMU	White	Partially Inaccessible	0	0.18	Negative
1	1	Custodial Restroom	Radiator	Metal	Black	Chipping	1	0.01	Negative
1	1	Custodial Restroom	W4	CMU	White	Partially Inaccessible	0	0.12	Negative
1	1	Custodial Restroom	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	Custodial Restroom	Floor	N/A	N/A	N/A	0	N/A	N/A