

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Boiler Room	W1	Concrete	White	None	0	0.03	Negative
1	B	Boiler Room	W1	CMU Block Wall	White	None	0	0.04	Negative
1	B	Boiler Room	W2	Concrete	White	None	0	0.02	Negative
1	B	Boiler Room	W2	CMU Block Wall	White	None	0	0.01	Negative
1	B	Boiler Room	W3	Concrete	White	None	0	0	Negative
1	B	Boiler Room	W4	Concrete	White	Flaking	10	0	Negative
1	B	Boiler Room	Ceiling	Concrete	White	None	0	0.01	Negative
1	B	Boiler Room	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Boiler Room Mezzanine	W1	N/A	N/A	None	0	N/A	N/A
1	B	Boiler Room Mezzanine	W2	Concrete	White	Chipping	2	0	Negative
1	B	Boiler Room Mezzanine	W2	CMU Block Wall	White	Flaking	2	0	Negative
1	B	Boiler Room Mezzanine	W3	Concrete	White	Flaking	15	0	Negative
1	B	Boiler Room Mezzanine	W4	CMU Block Wall	White	Flaking	6	0	Negative
1	B	Boiler Room Mezzanine	Ceiling	Concrete	White	None	0	0.12	Negative
1	B	Boiler Room Mezzanine	Floor	Concrete	Brown	Friction	20	0	Negative
1	B	Boiler Room Mezzanine	Electrical Panels	Metal	Grey	Chipping	20	0.14	Negative
1	B	Building Engineers Office	W1	CMU Block Wall	White	Chipping	4	0	Negative
1	B	Building Engineers Office	W2	Concrete	White	Chipping	10	0	Negative
1	B	Building Engineers Office	W3	Concrete	White	Flaking	10	0	Negative
1	B	Building Engineers Office	W4	CMU Block Wall	White	Chipping	5	0	Negative
1	B	Building Engineers Office	Ceiling	Concrete	White	Chipping	8	0.1	Negative
1	B	Building Engineers Office	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Boiler Room Custodial Storage	W1	CMU Block Wall	Tan	None	0	0	Negative
1	B	Boiler Room Custodial Storage	W2	Concrete	Tan	Chipping	8	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Boiler Room Custodial Storage	W3	Concrete	Tan	None	0	0	Negative
1	B	Boiler Room Custodial Storage	W4	CMU Block Wall	Tan	None	0	0	Negative
1	B	Boiler Room Custodial Storage	Ceiling	Concrete	White	None	0	0.07	Negative
1	B	Boiler Room Custodial Storage	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Maintenance Office	W1	X	X	None	0	N/A	N/A
1	B	Maintenance Office	W2	X	X	None	0	N/A	N/A
1	B	Maintenance Office	W3	X	X	None	0	N/A	N/A
1	B	Maintenance Office	W4	X	X	None	0	N/A	N/A
1	B	Maintenance Office	Ceiling	X	X	None	0	N/A	N/A
1	B	Maintenance Office	Floor	X	X	None	0	N/A	N/A
1	B	Maintenance Office Restroom	W1	CMU Block Wall	White	None	0	0.07	Negative
1	B	Maintenance Office Restroom	W2	CMU Block Wall	White	None	0	0.06	Negative
1	B	Maintenance Office Restroom	W3	CMU Block Wall	White	None	0	0.09	Negative
1	B	Maintenance Office Restroom	W4	CMU Block Wall	White	None	0	0.08	Negative
1	B	Maintenance Office Restroom	Ceiling	Plaster	Grey	Efflorescence	30	0.01	Negative
1	B	Maintenance Office Restroom	Floor	Concrete	Grey	Friction	10	0	Negative
1	B	Maintenance Office Closet	W1	CMU Block Wall	Pink	None	0	0	Negative
1	B	Maintenance Office Closet	W2	CMU Block Wall	Pink	None	0	0	Negative
1	B	Maintenance Office Closet	W3	Concrete	Pink	Chipping	1	0	Negative
1	B	Maintenance Office Closet	W4	CMU Block Wall	Pink	Chipping	1	0	Negative
1	B	Maintenance Office Closet	Ceiling	Plaster	Tan	Chipping	10	0.03	Negative
1	B	Maintenance Office Closet	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Girl's Restroom in Hallway adjacent to Small Cafeteria	W1	Concrete	Pink	None	0	0.4	Negative
1	B	Girl's Restroom in Hallway adjacent to Small Cafeteria	W2	Concrete	Pink	Chipping	1	0.6	Negative
1	B	Girl's Restroom in Hallway adjacent to Small Cafeteria	W3	Concrete	Pink	None	0	1	Positive
1	B	Girl's Restroom in Hallway adjacent to Small Cafeteria	W4	Concrete	Pink	None	0	0.7	Positive
1	B	Girl's Restroom in Hallway adjacent to Small Cafeteria	Ceiling	Plaster	Pink	None	0	0	Negative
1	B	Girl's Restroom in Hallway adjacent to Small Cafeteria	Floor	Concrete	Grey	Friction	10	0	Negative
1	B	Girl's Restroom in Hallway adjacent to Small Cafeteria	Door	Wood	Pink	Chipping	10	0	Negative
1	B	Boy's Bathroom in Hallway adjacent to Small Cafeteria	W1	Concrete	White	None	0	0.05	Negative
1	B	Boy's Bathroom in Hallway adjacent to Small Cafeteria	W2	Concrete	White	None	0	0.03	Negative
1	B	Boy's Bathroom in Hallway adjacent to Small Cafeteria	W3	Concrete	White	None	0	0.03	Negative
1	B	Boy's Bathroom in Hallway adjacent to Small Cafeteria	W4	Concrete	White	Cracking	2	0.04	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Boy's Bathroom in Hallway adjacent to Small Cafeteria	Ceiling	Plaster	White	Chipping	2	0.02	Negative
1	B	Boy's Bathroom in Hallway adjacent to Small Cafeteria	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Cafeteria	W1	CMU Block Wall	Blue	None	0	0	Negative
1	B	Cafeteria	W2	CMU Block Wall	Blue	Chipping	3	0.03	Negative
1	B	Cafeteria	W3	CMU Block Wall	Blue	Friction	6	0.02	Negative
1	B	Cafeteria	W4	CMU Block Wall	Blue	Chipping	3	0.3	Negative
1	B	Cafeteria	Ceiling	N/A	N/A	None	0	N/A	N/A
1	B	Cafeteria	Floor	N/A	N/A	None	0	N/A	N/A
1	B	Cafeteria	Column	Concrete	Dark Blue	Friction	4	0.04	Negative
1	B	Cafeteria	Univent	Metal	Beige	Friction	24	0.09	Negative
1	B	Kitchen	W1	Concrete	Yellow	None	0	0.01	Negative
1	B	Kitchen	W2	Concrete	Yellow	Chipping	2	0.01	Negative
1	B	Kitchen	W3	Concrete	Yellow	Chipping	2	0.05	Negative
1	B	Kitchen	W4	Concrete	Yellow	None	0	0.02	Negative
1	B	Kitchen	Ceiling	Concrete	White	None	0	0.06	Negative
1	B	Kitchen	Floor	N/A	N/A	None	0	N/A	N/A
1	B	Kitchen Storage	W1	Concrete	Yellow	Cracking	5	0.04	Negative
1	B	Kitchen Storage	W2	Brick	White	None	0	1.2	Positive
1	B	Kitchen Storage	W3	CMU Block Wall	White	None	0	0.03	Negative
1	B	Kitchen Storage	W4	CMU Block Wall	White	Chipping	1	0.02	Negative
1	B	Kitchen Storage	Ceiling	Concrete	White	Flaking	5	0.02	Negative
1	B	Kitchen Storage	Floor	N/A	N/A	None	0	N/A	N/A
1	B	Kitchen Restroom	W1	Concrete	White	None	0	0.01	Negative
1	B	Kitchen Restroom	W2	Concrete	White	None	0	0.01	Negative
1	B	Kitchen Restroom	W3	Concrete	White	None	0	0.01	Negative
1	B	Kitchen Restroom	W4	Concrete	White	None	0	0.02	Negative
1	B	Kitchen Restroom	Ceiling	Plaster	White	None	0	0	Negative
1	B	Kitchen Restroom	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Small Cafeteria	W1	X	X	None	0	N/A	N/A
1	B	Small Cafeteria	W2	X	X	None	0	N/A	N/A
1	B	Small Cafeteria	W3	X	X	None	0	N/A	N/A
1	B	Small Cafeteria	W4	X	X	None	0	N/A	N/A
1	B	Small Cafeteria	Ceiling	X	X	None	0	N/A	N/A
1	B	Small Cafeteria	Floor	X	X	None	0	N/A	N/A
1	B	Stairwell next to Kitchen	W1	CMU Block Wall	White	None	0	0.06	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Stairwell next to Kitchen	W2	CMU Block Wall	White	None	0	0.05	Negative
1	B	Stairwell next to Kitchen	W3	CMU Block Wall	White	None	0	0.06	Negative
1	B	Stairwell next to Kitchen	W4	CMU Block Wall	White	None	0	0.04	Negative
1	B	Stairwell next to Kitchen	Ceiling	Concrete	White	Chipping	1	0.09	Negative
1	B	Stairwell next to Kitchen	Floor	N/A	N/A	None	0	N/A	N/A
1	B	Stairwell next to Kitchen	Riser	Metal	Blue	Chipping	15	5.2	Positive
1	B	Stairwell next to Kitchen	Door	Metal	Blue	Chipping	3	0.03	Negative
1	B	Stairwell next to Kitchen	Radiator	Metal	Blue	Chipping	1	0	Negative
1	B	Stairwell next to Kitchen	Handrail	Metal	Blue	Chipping	10	0.24	Negative
1	B	Cafeteria Storage Room	W1	CMU Block Wall	Tan	Chipping	3	0.02	Negative
1	B	Cafeteria Storage Room	W2	CMU Block Wall	Tan	Chipping	8	0	Negative
1	B	Cafeteria Storage Room	W3	CMU Block Wall	Tan	Cracking	2	0.03	Negative
1	B	Cafeteria Storage Room	W4	CMU Block Wall	Tan	None	0	0.4	Negative
1	B	Cafeteria Storage Room	Ceiling	Sheetrock	White	Chipping	10	0	Negative
1	B	Cafeteria Storage Room	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Cafeteria Storage Room	Door Casing	Metal	Orange	Chipping	10	0.02	Negative
1	B	Hallway adjacent to Cafeteria	W1	Concrete	Blue	Chipping	1	0.01	Negative
1	B	Hallway adjacent to Cafeteria	W2	Concrete	Blue	Chipping	2	0.04	Negative
1	B	Hallway adjacent to Cafeteria	W3	Concrete	Blue	Chipping	2	0.03	Negative
1	B	Hallway adjacent to Cafeteria	W4	Concrete	Blue	Chipping	3	0	Negative
1	B	Hallway adjacent to Cafeteria	Ceiling	N/A	N/A	None	0	N/A	N/A
1	B	Hallway adjacent to Cafeteria	Floor	N/A	N/A	None	0	N/A	N/A
1	B	Hallway adjacent to Cafeteria	Door	Wood	Blue	Flaking	5	0	Negative
1	B	Ludlow Street Stairwell	W1	Brick	Unpainted	None	0	N/A	N/A
1	B	Ludlow Street Stairwell	W2	Brick	Unpainted	None	0	N/A	N/A
1	B	Ludlow Street Stairwell	W3	Brick	Unpainted	None	0	N/A	N/A
1	B	Ludlow Street Stairwell	W4	Brick	Unpainted	None	0	N/A	N/A
1	B	Ludlow Street Stairwell	Ceiling	Plaster	White	None	0	0	Negative
1	B	Ludlow Street Stairwell	Floor	N/A	N/A	None	0	N/A	N/A
1	B	Ludlow Street Stairwell	Door	Metal	Brown	Chipping	3	0	Negative
1	B	Ludlow Street Stairwell	Door Casing	Metal	Brown	Chipping	2	0.14	Negative
1	B	Storage Room in Basement Stairway	W1	CMU Block Wall	White	Cracking	2	0	Negative
1	B	Storage Room in Basement Stairway	W2	CMU Block Wall	White	None	0	0	Negative
1	B	Storage Room in Basement Stairway	W3	Concrete	White	None	0	0.04	Negative
1	B	Storage Room in Basement Stairway	W4	Concrete	White	Chipping	1	0.03	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Storage Room in Basement Stairway	Ceiling	Concrete	White	Cracking	3	0.04	Negative
1	B	Storage Room in Basement Stairway	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Storage Room in Basement Stairway	Door Casing	Metal	Blue	Chipping	5	0.02	Negative
1	1	Ludlow Street Front Lobby	W1	CMU Block Wall	White	None	0	0.02	Negative
1	1	Ludlow Street Front Lobby	W2	CMU Block Wall	Black	None	0	0.02	Negative
1	1	Ludlow Street Front Lobby	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Ludlow Street Front Lobby	W4	CMU Block Wall	White	None	0	0.01	Negative
1	1	Ludlow Street Front Lobby	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Ludlow Street Front Lobby	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Ludlow Street Front Lobby	Door	Metal	Blue	Friction	5	0.01	Negative
1	1	Ludlow Street Front Lobby	Door Casing	Metal	Blue	Chipping	5	0.04	Negative
1	1	Ludlow Street Front Lobby	Univent	Metal	Blue	Chipping	5	0.03	Negative
1	1	Girl's Restroom in Main Entrance Lobby outside Auditorium	W1	CMU Block Wall	Purple	None	0	0.02	Negative
1	1	Girl's Restroom in Main Entrance Lobby outside Auditorium	W2	CMU Block Wall	Purple	None	0	0.01	Negative
1	1	Girl's Restroom in Main Entrance Lobby outside Auditorium	W3	CMU Block Wall	Purple	None	0	0.03	Negative
1	1	Girl's Restroom in Main Entrance Lobby outside Auditorium	W4	CMU Block Wall	Purple	Chipping	2	0.03	Negative
1	1	Girl's Restroom in Main Entrance Lobby outside Auditorium	Ceiling	Plaster	Purple	None	0	0.01	Negative
1	1	Girl's Restroom in Main Entrance Lobby outside Auditorium	Floor	Concrete	Grey	Cracking	3	0	Negative
1	1	Boy's Restroom in Main Entrance Lobby outside Auditorium	W1	CMU Block Wall	Tan	None	0	0.02	Negative
1	1	Boy's Restroom in Main Entrance Lobby outside Auditorium	W2	CMU Block Wall	Tan	None	0	0.02	Negative
1	1	Boy's Restroom in Main Entrance Lobby outside Auditorium	W3	CMU Block Wall	Tan	None	0	0.03	Negative
1	1	Boy's Restroom in Main Entrance Lobby outside Auditorium	W4	CMU Block Wall	Tan	None	0	0.06	Negative
1	1	Boy's Restroom in Main Entrance Lobby outside Auditorium	Ceiling	Plaster	Tan	Alligating	5	0.03	Negative
1	1	Boy's Restroom in Main Entrance Lobby outside Auditorium	Floor	Concrete	Grey	Water Damage	5	0	Negative
1	1	Security Office in Auditorium	W1	CMU Block Wall	White	None	0	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Security Office in Auditorium	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Security Office in Auditorium	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Security Office in Auditorium	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Security Office in Auditorium	Ceiling	Plaster	White	None	0	0	Negative
1	1	Security Office in Auditorium	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Auditorium	W1	CMU Block Wall	Orange	None	0	0.02	Negative
1	1	Auditorium	W2	CMU Block Wall	Orange	None	0	0.01	Negative
1	1	Auditorium	W3	CMU Block Wall	Orange	None	0	0.4	Negative
1	1	Auditorium	W4	CMU Block Wall	Orange	None	0	0.4	Negative
1	1	Auditorium	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Auditorium	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Auditorium Stage	W1	CMU Block Wall	White	None	0	0.01	Negative
1	1	Auditorium Stage	W1	CMU Block Wall	Orange	None	0	0.01	Negative
1	1	Auditorium Stage	W2	CMU Block Wall	Orange	None	0	0.01	Negative
1	1	Auditorium Stage	W3	CMU Block Wall	Orange	Chipping	30	0.01	Negative
1	1	Auditorium Stage	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Auditorium Stage	Ceiling	Concrete	Unpainted	None	0	N/A	N/A
1	1	Auditorium Stage	Floor	Wood	Varnish	None	0	0	Negative
1	1	Auditorium Stage Crawlspace	W1	Concrete	White	None	0	0	Negative
1	1	Auditorium Stage Crawlspace	W2	Concrete	White	None	0	0	Negative
1	1	Auditorium Stage Crawlspace	W3	Concrete	White	None	0	0	Negative
1	1	Auditorium Stage Crawlspace	W4	Concrete	Unpainted	None	0	N/A	N/A
1	1	Auditorium Stage Crawlspace	Ceiling	Concrete	Unpainted	None	0	N/A	N/A
1	1	Auditorium Stage Crawlspace	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	1	Hallway between Main Hallway and Ludlow Street Lobby	W1	N/A	N/A	None	0	N/A	N/A
1	1	Hallway between Main Hallway and Ludlow Street Lobby	W2	CMU Block Wall	White	None	0	0.04	Negative
1	1	Hallway between Main Hallway and Ludlow Street Lobby	W3	CMU Block Wall	White	None	0	0.03	Negative
1	1	Hallway between Main Hallway and Ludlow Street Lobby	W4	CMU Block Wall	White	None	0	0.03	Negative
1	1	Hallway between Main Hallway and Ludlow Street Lobby	Ceiling	Plaster	White	None	0	0.07	Negative
1	1	Hallway between Main Hallway and Ludlow Street Lobby	Floor	N/A	N/A	None	0	N/A	N/A

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Stairwell next to Principal's Office	W1	Brick	Unpainted	None	0	N/A	N/A
1	1	Stairwell next to Principal's Office	W2	Brick	Unpainted	None	0	N/A	N/A
1	1	Stairwell next to Principal's Office	W3	Brick	Unpainted	None	0	N/A	N/A
1	1	Stairwell next to Principal's Office	W4	Brick	Unpainted	None	0	N/A	N/A
1	1	Stairwell next to Principal's Office	Ceiling	Concrete	White	Moisture Damage	5	0.05	Negative
1	1	Stairwell next to Principal's Office	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Stairwell next to Principal's Office	Door	Metal	Blue	Chipping	4	0	Negative
1	1	Stairwell next to Principal's Office	Door Casing	Metal	Blue	None	0	0	Negative
1	1	Stairwell next to Principal's Office	Handrail	Metal	Blue	Friction	25	0.28	Negative
1	1	Stairwell next to Principal's Office	Riser	Metal	Blue	Chipping	20	4.4	Positive
1	1	Stairwell next to Principal's Office	Radiator	Metal	Blue	Chipping	1	0.03	Negative
1	1	Stairwell next to Principal's Office	Newel Post	Metal	Blue	Chipping	10	9.5	Positive
1	1	Stairwell next to Principal's Office	Door	Metal	Brown	Chipping	8	0	Negative
1	1	Stairwell next to Principal's Office	Door Casing	Metal	Brown	Chipping	5	0.13	Negative
1	1	1st Floor Main Hallway	W1	CMU Block Wall	Blue	None	0	0.01	Negative
1	1	1st Floor Main Hallway	W2	CMU Block Wall	Blue	None	0	0.03	Negative
1	1	1st Floor Main Hallway	W3	CMU Block Wall	Blue	None	0	0.01	Negative
1	1	1st Floor Main Hallway	W4	CMU Block Wall	Blue	None	0	0.03	Negative
1	1	1st Floor Main Hallway	W1	CMU Block Wall	White	None	0	0.03	Negative
1	1	1st Floor Main Hallway	W2	CMU Block Wall	White	None	0	0.02	Negative
1	1	1st Floor Main Hallway	W3	CMU Block Wall	White	None	0	0.03	Negative
1	1	1st Floor Main Hallway	W4	CMU Block Wall	White	None	0	0.02	Negative
1	1	1st Floor Main Hallway	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	1st Floor Main Hallway	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Main Office	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office	W2	Metal Wall	White	None	0	0	Negative
1	1	Main Office	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Main Office	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Main Office Copy Room	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office Copy Room	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office Copy Room	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office Copy Room	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office Copy Room	Ceiling	N/A	N/A	None	0	N/A	N/A

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Main Office Copy Room	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Main Office Kitchen	W1	Metal	White	None	0	0.05	Negative
1	1	Main Office Kitchen	W2	Metal	White	None	0	0.05	Negative
1	1	Main Office Kitchen	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office Kitchen	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Main Office Kitchen	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Main Office Kitchen	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Office in Back of Main Office	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Office in Back of Main Office	W1	CMU Block Wall	Green	None	0	0	Negative
1	1	Office in Back of Main Office	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Office in Back of Main Office	W2	CMU Block Wall	Green	None	0	0	Negative
1	1	Office in Back of Main Office	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Office in Back of Main Office	W3	CMU Block Wall	Green	None	0	0	Negative
1	1	Office in Back of Main Office	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Office in Back of Main Office	W4	CMU Block Wall	Green	None	0	0	Negative
1	1	Office in Back of Main Office	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Office in Back of Main Office	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Office in Back of Principal's Office	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Office in Back of Principal's Office	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Office in Back of Principal's Office	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Office in Back of Principal's Office	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Office in Back of Principal's Office	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Office in Back of Principal's Office	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Principal's Restroom	W1	CMU Block Wall	Purple	None	0	0	Negative
1	1	Principal's Restroom	W2	CMU Block Wall	Purple	None	0	0	Negative
1	1	Principal's Restroom	W3	CMU Block Wall	Purple	None	0	0	Negative
1	1	Principal's Restroom	W4	CMU Block Wall	Purple	None	0	0	Negative
1	1	Principal's Restroom	Ceiling	Plaster	White	None	0	0.02	Negative
1	1	Principal's Restroom	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Principal's Office	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Principal's Office	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Principal's Office	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Principal's Office	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Principal's Office	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Principal's Office	Floor	N/A	N/A	None	0	N/A	N/A

		Inspection Dates: 03/07/2022-03/11/2022		Lead Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672		Robeson High School					
		Inspection Company: Viva EHS		4125 Ludlow St, Philadelphia, PA 19104					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 108 Art Room	W1	CMU Block Wall	Black	Chipping	1	0.02	Negative
1	1	Classroom 108 Art Room	W1	CMU Block Wall	Grey	None	0	0.03	Negative
1	1	Classroom 108 Art Room	W1	CMU Block Wall	White	None	0	0.03	Negative
1	1	Classroom 108 Art Room	W2	CMU Block Wall	Grey	None	0	0	Negative
1	1	Classroom 108 Art Room	W2	CMU Block Wall	White	None	0	0.02	Negative
1	1	Classroom 108 Art Room	W3	CMU Block Wall	Grey	None	0	0	Negative
1	1	Classroom 108 Art Room	W3	CMU Block Wall	White	None	0	0.04	Negative
1	1	Classroom 108 Art Room	W4	CMU Block Wall	Grey	None	0	0.4	Negative
1	1	Classroom 108 Art Room	Ceiling	Plaster	White	Chipping	8	0.03	Negative
1	1	Classroom 108 Art Room	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Classroom 108 Art Room	Duct Work	Metal	White	None	0	0	Negative
1	1	Classroom 108 Art Room	Door Casing	Metal	Grey	Chipping	1	0.04	Negative
1	1	Classroom 108 Art Room	Door	Wood	Blue	Chipping	1	0	Negative
1	1	Classroom 106 across from Nurse's Office	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom 106 across from Nurse's Office	W1	CMU Block Wall	Tan	None	0	0	Negative
1	1	Classroom 106 across from Nurse's Office	W2	CMU Block Wall	Tan	None	0	0.02	Negative
1	1	Classroom 106 across from Nurse's Office	W3	CMU Block Wall	Tan	Cracking	1	0.4	Negative
1	1	Classroom 106 across from Nurse's Office	W4	CMU Block Wall	Tan	None	0	0.05	Negative
1	1	Classroom 106 across from Nurse's Office	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	Classroom 106 across from Nurse's Office	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Classroom 106 across from Nurse's Office	Column	CMU Block Wall	Green	None	0	0.07	Negative
1	1	Classroom 108 Art Room Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 108 Art Room Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 108 Art Room Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 108 Art Room Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 108 Art Room Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 108 Art Room Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 106 across from Nurse's Office Electrical Panel / Storage Closet	W1	CMU Block Wall	Yellow	None	0	0.01	Negative
1	1	Classroom 106 across from Nurse's Office Electrical Panel / Storage Closet	W2	CMU Block Wall	Yellow	None	0	0.01	Negative
1	1	Classroom 106 across from Nurse's Office Electrical Panel / Storage Closet	W3	CMU Block Wall	Yellow	None	0	0.01	Negative
1	1	Classroom 106 across from Nurse's Office Electrical Panel / Storage Closet	W4	CMU Block Wall	Yellow	None	0	0.13	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom 106 across from Nurse's Office Electrical Panel / Storage Closet	Ceiling	Plaster	White	None	0	0	Negative
1	1	Classroom 106 across from Nurse's Office Electrical Panel / Storage Closet	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Classroom 106 across from Nurse's Office Electrical Panel / Storage Closet	Electrical Panel	Metal	Green	Flaking	8	0.24	Negative
1	1	Classroom 106 across from Nurse's Office Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 106 across from Nurse's Office Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 106 across from Nurse's Office Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 106 across from Nurse's Office Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 106 across from Nurse's Office Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 106 across from Nurse's Office Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Office Room 105	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Nurse's Office Room 105	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Nurse's Office Room 105	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Nurse's Office Room 105	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Nurse's Office Room 105	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Nurse's Office Room 105	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Nurse's Office Restroom	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Nurse's Office Restroom	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Nurse's Office Restroom	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Nurse's Office Restroom	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Nurse's Office Restroom	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	Nurse's Office Restroom	Floor	Concrete	Grey	Friction	5	0	Negative
1	1	Teacher's Lounge Room 103	W1	CMU Block Wall	White	None	0	0.02	Negative
1	1	Teacher's Lounge Room 103	W2	CMU Block Wall	White	None	0	0.01	Negative
1	1	Teacher's Lounge Room 103	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Teacher's Lounge Room 103	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Teacher's Lounge Room 103	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Teacher's Lounge Room 103	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Classroom B2	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom B2	W1	CMU Block Wall	Green	None	0	0	Negative
1	1	Classroom B2	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom B2	W2	CMU Block Wall	Green	None	0	0	Negative
1	1	Classroom B2	W3	Sheetrock	Green	None	0	0	Negative
1	1	Classroom B2	W3	CMU Block Wall	Green	None	0	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom B2	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom B2	W4	CMU Block Wall	Green	None	0	0	Negative
1	1	Classroom B2	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Classroom B2	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Classroom B2	Door	Metal	Black	Chipping	2	0.02	Negative
1	1	Classroom B2 Storage	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom B2 Storage	W1	Concrete	White	None	0	0	Negative
1	1	Classroom B2 Storage	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom B2 Storage	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom B2 Storage	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom B2 Storage	Ceiling	Plaster	White	None	0	0	Negative
1	1	Classroom B2 Storage	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Girl's Restroom across from Gym	W1	CMU Block Wall	Pink	None	0	0	Negative
1	1	Girl's Restroom across from Gym	W2	CMU Block Wall	Pink	None	0	0	Negative
1	1	Girl's Restroom across from Gym	W3	CMU Block Wall	Pink	None	0	0	Negative
1	1	Girl's Restroom across from Gym	W4	CMU Block Wall	Pink	None	0	0	Negative
1	1	Girl's Restroom across from Gym	Ceiling	Plaster	Pink	None	0	0.01	Negative
1	1	Girl's Restroom across from Gym	Floor	Concrete	Grey	Friction	10	0	Negative
1	1	IMC/Library	W1	CMU Block Wall	Tan	None	0	0	Negative
1	1	IMC/Library	W1	CMU Block Wall	White	None	0	0	Negative
1	1	IMC/Library	W2	CMU Block Wall	Tan	Cracking	2	0	Negative
1	1	IMC/Library	W2	CMU Block Wall	White	None	0	0	Negative
1	1	IMC/Library	W3	CMU Block Wall	Tan	None	0	0	Negative
1	1	IMC/Library	W3	CMU Block Wall	White	None	0	0	Negative
1	1	IMC/Library	W4	CMU Block Wall	Tan	None	0	0	Negative
1	1	IMC/Library	W4	CMU Block Wall	White	None	0	0.4	Negative
1	1	IMC/Library	Ceiling	Plaster	White	Alligatoring	10	0	Negative
1	1	IMC/Library	Floor	N/A	N/A	None	0	N/A	N/A
1	1	IMC/Library	Concrete Column	Concrete	Tan	None	0	0	Negative
1	1	IMC/Library	Concrete Column	Concrete	White	None	0	0.4	Negative
1	1	IMC/Library	Electrical Panel	Metal	Blue	Chipping	5	0.04	Negative
1	1	Boy's Restroom across from Gym	W1	CMU Block Wall	Blue	None	0	0	Negative
1	1	Boy's Restroom across from Gym	W2	CMU Block Wall	Blue	None	0	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Boy's Restroom across from Gym	W3	CMU Block Wall	Blue	None	0	0	Negative
1	1	Boy's Restroom across from Gym	W4	CMU Block Wall	Blue	None	0	0	Negative
1	1	Boy's Restroom across from Gym	Ceiling	Plaster	Blue	Chipping	2	0	Negative
1	1	Boy's Restroom across from Gym	Floor	Concrete	Grey	Friction	10	0	Negative
1	1	Boy's Restroom across from Gym	Door	Metal	Blue	None	0	0.06	Negative
1	1	Boy's Restroom across from Gym	Door	Metal	Tan	None	0	0.12	Negative
1	1	Boy's Restroom across from Gym	Door	Wood	Blue	Chipping	5	0	Negative
1	1	Staff Restroom across from Gym	W1	CMU Block Wall	Tan	None	0	0.02	Negative
1	1	Staff Restroom across from Gym	W2	CMU Block Wall	Tan	None	0	0.01	Negative
1	1	Staff Restroom across from Gym	W3	CMU Block Wall	Tan	None	0	0.02	Negative
1	1	Staff Restroom across from Gym	W4	CMU Block Wall	Tan	None	0	0.04	Negative
1	1	Staff Restroom across from Gym	Ceiling	Plaster	Tan	None	0	0.02	Negative
1	1	Staff Restroom across from Gym	Floor	Concrete	Grey	Friction	15	0	Negative
1	1	Staff Restroom across from Gym	Door Casing	Metal	Blue	Chipping	3	0	Negative
1	1	Custodial Closet across from Gym	W1	CMU Block Wall	Tan	None	0	0	Negative
1	1	Custodial Closet across from Gym	W2	CMU Block Wall	Tan	None	0	0	Negative
1	1	Custodial Closet across from Gym	W3	CMU Block Wall	Tan	None	0	0	Negative
1	1	Custodial Closet across from Gym	W4	Sheetrock	White	None	0	0	Negative
1	1	Custodial Closet across from Gym	Ceiling	Plaster	Tan	Hole	10	0	Negative
1	1	Custodial Closet across from Gym	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	1	Classroom 115 Office by Windows	W1	CMU Block Wall	White	None	0	0.02	Negative
1	1	Classroom 115 Office by Windows	W2	CMU Block Wall	White	None	0	0.02	Negative
1	1	Classroom 115 Office by Windows	W3	CMU Block Wall	White	None	0	0.02	Negative
1	1	Classroom 115 Office by Windows	W4	CMU Block Wall	Blue	Cracking	5	0.03	Negative
1	1	Classroom 115 Office by Windows	Ceiling	Plaster	White	None	0	0.02	Negative
1	1	Classroom 115 Office by Windows	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Classroom 115 Storage	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom 115 Storage	W2	CMU Block Wall	White	Cracking	6	0	Negative
1	1	Classroom 115 Storage	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom 115 Storage	W4	CMU Block Wall	Blue	Cracking	5	0	Negative
1	1	Classroom 115 Storage	Ceiling	Plaster	White	Chipping	3	0	Negative
1	1	Classroom 115 Storage	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	1	Classroom 115 Office by Hallway	W1	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom 115 Office by Hallway	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Classroom 115 Office by Hallway	W3	CMU Block Wall	White	None	0	0.1	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom 115 Office by Hallway	W4	CMU Block Wall	White	None	0	0.1	Negative
1	1	Classroom 115 Office by Hallway	Ceiling	Plaster	White	None	0	0	Negative
1	1	Classroom 115 Office by Hallway	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Classroom 115 Copy Room	W1	CMU Block Wall	White	Cracking	3	0.04	Negative
1	1	Classroom 115 Copy Room	W2	CMU Block Wall	White	Cracking	3	0.05	Negative
1	1	Classroom 115 Copy Room	W3	CMU Block Wall	White	Cracking	4	0.1	Negative
1	1	Classroom 115 Copy Room	W4	CMU Block Wall	White	Cracking	2	0.05	Negative
1	1	Classroom 115 Copy Room	Ceiling	Plaster	White	None	0	0.03	Negative
1	1	Classroom 115 Copy Room	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	1	Gymnasium	W1	CMU Block Wall	Tan	None	0	0.1	Negative
1	1	Gymnasium	W1	CMU Block Wall	White	Cracking	5	0	Negative
1	1	Gymnasium	W2	CMU Block Wall	Tan	None	0	0.1	Negative
1	1	Gymnasium	W2	CMU Block Wall	White	None	0	0.15	Negative
1	1	Gymnasium	W3	CMU Block Wall	Tan	None	0	0.05	Negative
1	1	Gymnasium	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Gymnasium	W4	CMU Block Wall	Tan	None	0	0.04	Negative
1	1	Gymnasium	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Gymnasium	Ceiling	Tectum	White	None	0	N/A	N/A
1	1	Gymnasium	Floor	Wood	Varnish	None	0	0	Negative
1	1	Gym Office	W1	Plaster	White	None	0	0	Negative
1	1	Gym Office	W1	CMU Block Wall	White	Cracking	2	0.3	Negative
1	1	Gym Office	W2	CMU Block Wall	White	Cracking	2	0.03	Negative
1	1	Gym Office	W3	CMU Block Wall	White	None	0	0.05	Negative
1	1	Gym Office	W4	Sheetrock	White	None	0	0.01	Negative
1	1	Gym Office	W4	CMU Block Wall	White	Cracking	1	0.06	Negative
1	1	Gym Office	Ceiling	Plaster	White	Chipping	4	0.03	Negative
1	1	Gym Office	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Gym Office Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Gym Office Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Gym Office Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Gym Office Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Gym Office Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Gym Office Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Water Main Closet adjacent to Gym Office	W1	Sheetrock	White	None	0	0	Negative
1	1	Water Main Closet adjacent to Gym Office	W2	Sheetrock	White	Chipping	1	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Water Main Closet adjacent to Gym Office	W2	CMU Block Wall	Tan	None	0	0.1	Negative
1	1	Water Main Closet adjacent to Gym Office	W3	CMU Block Wall	White	Cracking	9	0.4	Negative
1	1	Water Main Closet adjacent to Gym Office	W4	CMU Block Wall	White	None	0	0.4	Negative
1	1	Water Main Closet adjacent to Gym Office	Ceiling	Plaster	White	Alligatoring	5	0.03	Negative
1	1	Water Main Closet adjacent to Gym Office	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Large Gym Storage	W1	CMU Block Wall	White	None	0	0.04	Negative
1	1	Large Gym Storage	W1	Concrete	White	Chipping	3	0.02	Negative
1	1	Large Gym Storage	W2	CMU Block Wall	White	None	0	0	Negative
1	1	Large Gym Storage	W3	CMU Block Wall	White	None	0	0	Negative
1	1	Large Gym Storage	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Large Gym Storage	Ceiling	Plaster	White	None	0	0.04	Negative
1	1	Large Gym Storage	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	1	Small Gym Storage	W1	CMU Block Wall	White	None	0	0.01	Negative
1	1	Small Gym Storage	W2	CMU Block Wall	White	None	0	0.05	Negative
1	1	Small Gym Storage	W3	CMU Block Wall	White	None	0	0.03	Negative
1	1	Small Gym Storage	W4	CMU Block Wall	White	None	0	0	Negative
1	1	Small Gym Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Small Gym Storage	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	1	Stairwell outside Gym	W1	CMU Block Wall	Blue	Chipping	1	0	Negative
1	1	Stairwell outside Gym	W2	CMU Block Wall	Blue	Chipping	1	0	Negative
1	1	Stairwell outside Gym	W3	CMU Block Wall	Blue	Chipping	3	0.01	Negative
1	1	Stairwell outside Gym	W4	CMU Block Wall	Blue	Chipping	6	0.01	Negative
1	1	Stairwell outside Gym	Ceiling	N/A	N/A	None	0	N/A	N/A
1	1	Stairwell outside Gym	Floor	N/A	N/A	None	0	N/A	N/A
1	1	Stairwell outside Gym	Door	Wood	Blue	Friction	4	0	Negative
1	1	Stairwell outside Gym	Door Casing	Metal	Blue	Chipping	1	0.07	Negative
1	1	Stairwell outside Gym	Riser	Metal	Blue	Chipping	20	4.8	Positive
1	1	Stairwell outside Gym	Radiator	Metal	Grey	Chipping	6	0.02	Negative
1	1	Stairwell outside Gym	Newel Post	Metal	Blue	Chipping	2	4.8	Positive
1	2	Stairwell across from Classroom 200	W1	Brick	Unpainted	None	0	N/A	N/A
1	2	Stairwell across from Classroom 200	W2	Brick	Unpainted	None	0	N/A	N/A
1	2	Stairwell across from Classroom 200	W3	Brick	Unpainted	None	0	N/A	N/A
1	2	Stairwell across from Classroom 200	W4	Brick	Unpainted	None	0	N/A	N/A
1	2	Stairwell across from Classroom 200	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Stairwell across from Classroom 200	Floor	N/A	N/A	None	0	N/A	N/A

		Inspection Dates: 03/07/2022-03/11/2022		Lead Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672		Robeson High School					
		Inspection Company: Viva EHS		4125 Ludlow St, Philadelphia, PA 19104					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Stairwell across from Classroom 200	Handrail	Metal	Blue	Friction	20	0.1	Negative
1	2	Stairwell across from Classroom 200	Riser	Metal	Blue	Chipping	20	5.6	Positive
1	2	Stairwell across from Classroom 200	Newel Post	Metal	Blue	Chipping	15	2.4	Positive
1	2	Stairwell across from Classroom 200	Door	Metal	Blue	Chipping	8	0.05	Negative
1	2	Stairwell across from Classroom 200	Door Casing	Metal	Blue	None	0	0	Negative
1	2	Boy's Restroom next to Classroom 200	W1	CMU Block Wall	White	None	0	0.02	Negative
1	2	Boy's Restroom next to Classroom 200	W2	CMU Block Wall	White	None	0	0	Negative
1	2	Boy's Restroom next to Classroom 200	W3	CMU Block Wall	White	None	0	0	Negative
1	2	Boy's Restroom next to Classroom 200	W4	CMU Block Wall	White	None	0	0	Negative
1	2	Boy's Restroom next to Classroom 200	Ceiling	Plaster	White	None	0	0.03	Negative
1	2	Boy's Restroom next to Classroom 200	Floor	Concrete	Grey	Chipping	25	0	Negative
1	2	Boy's Restroom next to Classroom 200	Door	Wood	Blue	Chipping	1	0	Negative
1	2	Girl's Restroom near Classroom 200	W1	CMU Block Wall	White	None	0	0	Negative
1	2	Girl's Restroom near Classroom 200	W1	CMU Block Wall	Yellow	None	0	0	Negative
1	2	Girl's Restroom near Classroom 200	W2	CMU Block Wall	White	Cracking	1	0	Negative
1	2	Girl's Restroom near Classroom 200	W2	CMU Block Wall	Yellow	Cracking	1	0	Negative
1	2	Girl's Restroom near Classroom 200	W3	CMU Block Wall	White	None	0	0	Negative
1	2	Girl's Restroom near Classroom 200	W3	CMU Block Wall	Yellow	None	0	0	Negative
1	2	Girl's Restroom near Classroom 200	W4	CMU Block Wall	White	None	0	0	Negative
1	2	Girl's Restroom near Classroom 200	W4	CMU Block Wall	Yellow	None	0	0	Negative
1	2	Girl's Restroom near Classroom 200	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Girl's Restroom near Classroom 200	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Girl's Restroom near Classroom 200	Door	Wood	Blue	Chipping	2	0	Negative
1	2	Girl's Restroom near Classroom 200	Pipe	Metal	Yellow	Chipping	3	0.05	Negative
1	2	Classroom 200	W1	CMU Block Wall	White	Chipping	6	0	Negative
1	2	Classroom 200	W2	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 200	W3	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 200	W4	CMU Block Wall	White	Cracking	2	0.4	Negative
1	2	Classroom 200	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Classroom 200	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 200 Restroom	W1	CMU Block Wall	Red	None	0	0.03	Negative
1	2	Classroom 200 Restroom	W2	CMU Block Wall	Red	None	0	0.01	Negative
1	2	Classroom 200 Restroom	W3	CMU Block Wall	Red	None	0	0.01	Negative
1	2	Classroom 200 Restroom	W4	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 200 Restroom	Ceiling	Plaster	White	None	0	0.04	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 200 Restroom	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 202	W1	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 202	W2	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 202	W3	CMU Block Wall	White	Cracking	1	0.05	Negative
1	2	Classroom 202	W4	CMU Block Wall	White	None	0	0.08	Negative
1	2	Classroom 202	Ceiling	Plaster	White	None	0	0.04	Negative
1	2	Classroom 202	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 204	W1	CMU Block Wall	White	Chipping	5	0	Negative
1	2	Classroom 204	W2	CMU Block Wall	White	None	0	0.01	Negative
1	2	Classroom 204	W3	CMU Block Wall	White	Chipping	3	0	Negative
1	2	Classroom 204	W4	CMU Block Wall	White	Chipping	2	0	Negative
1	2	Classroom 204	Ceiling	Plaster	White	Chipping	1	0.05	Negative
1	2	Classroom 204	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 205	W1	CMU Block Wall	White	Chipping	4	0	Negative
1	2	Classroom 205	W2	CMU Block Wall	White	None	0	0.03	Negative
1	2	Classroom 205	W3	CMU Block Wall	White	Friction	1	0.03	Negative
1	2	Classroom 205	W4	CMU Block Wall	White	None	0	0.02	Negative
1	2	Classroom 205	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Classroom 205	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 205	Door	Metal	Grey	Chipping	12	0.09	Negative
1	2	Classroom 206	W1	CMU Block Wall	Purple	None	0	0	Negative
1	2	Classroom 206	W2	CMU Block Wall	Purple	None	0	0.02	Negative
1	2	Classroom 206	W3	CMU Block Wall	Tan	Chipping	4	0.05	Negative
1	2	Classroom 206	W4	CMU Block Wall	Purple	None	0	0.02	Negative
1	2	Classroom 206	Ceiling	Plaster	White	Efflorescence	15	0.02	Negative
1	2	Classroom 206	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 206	Door	Metal	Grey	Chipping	12	0.03	Negative
1	2	Classroom 206 Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 206 Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 206 Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 206 Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 206 Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 206 Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 207	W1	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 207	W2	CMU Block Wall	White	None	0	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 207	W3	CMU Block Wall	White	Cracking	5	0.03	Negative
1	2	Classroom 207	W4	CMU Block Wall	White	None	0	0.05	Negative
1	2	Classroom 207	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Classroom 207	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 207	Door	Wood	Blue	Chipping	3	0	Negative
1	2	Classroom 207	Door Casing	Metal	Blue	Chipping	10	0.09	Negative
1	2	Classroom 208	W1	CMU Block Wall	Blue	None	0	0	Negative
1	2	Classroom 208	W1	CMU Block Wall	Tan	None	0	0	Negative
1	2	Classroom 208	W2	CMU Block Wall	Blue	None	0	0.4	Negative
1	2	Classroom 208	W3	CMU Block Wall	Yellow	None	0	0.02	Negative
1	2	Classroom 208	W3	CMU Block Wall	White	None	0	0.02	Negative
1	2	Classroom 208	W4	CMU Block Wall	Blue	None	0	0	Negative
1	2	Classroom 208	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Classroom 208	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 209	W1	CMU Block Wall	Blue	None	0	0.02	Negative
1	2	Classroom 209	W2	CMU Block Wall	Blue	None	0	0.13	Negative
1	2	Classroom 209	W3	CMU Block Wall	Blue	None	0	0.09	Negative
1	2	Classroom 209	W4	CMU Block Wall	Blue	None	0	0.14	Negative
1	2	Classroom 209	Ceiling	Plaster	White	Chipping	10	0.1	Negative
1	2	Classroom 209	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Stairwell next to Classroom 209	W1	Brick	Unpainted	None	0	N/A	N/A
1	2	Stairwell next to Classroom 209	W2	Brick	Unpainted	None	0	N/A	N/A
1	2	Stairwell next to Classroom 209	W3	Brick	Unpainted	None	0	N/A	N/A
1	2	Stairwell next to Classroom 209	W4	Brick	Unpainted	None	0	N/A	N/A
1	2	Stairwell next to Classroom 209	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Stairwell next to Classroom 209	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Stairwell next to Classroom 209	Handrail	Metal	Blue	Friction	15	0.13	Negative
1	2	Stairwell next to Classroom 209	Riser	Metal	Blue	Chipping	20	3.8	Positive
1	2	Stairwell next to Classroom 209	Newel Post	Metal	Blue	Friction	10	6.6	Positive
1	2	Stairwell next to Classroom 209	Radiator	Metal	Blue	Chipping	3	0	Negative
1	2	Stairwell next to Classroom 209	Door	Metal	Blue	Chipping	2	0.02	Negative
1	2	Teacher's Lounge next to Classroom 208	W1	CMU Block Wall	Pink	None	0	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022		Lead Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672		Robeson High School					
		Inspection Company: Viva EHS		4125 Ludlow St, Philadelphia, PA 19104					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Teacher's Lounge next to Classroom 208	W2	CMU Block Wall	Pink	None	0	0.03	Negative
1	2	Teacher's Lounge next to Classroom 208	W3	CMU Block Wall	Pink	None	0	0	Negative
1	2	Teacher's Lounge next to Classroom 208	W4	CMU Block Wall	Pink	None	0	0	Negative
1	2	Teacher's Lounge next to Classroom 208	Ceiling	Plaster	White	None	0	0.1	Negative
1	2	Teacher's Lounge next to Classroom 208	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Teacher's Lounge next to Classroom 208	Door	Metal	Blue	Chipping	2	0.03	Negative
1	2	Staff Restroom adjacent to Teacher's Lounge	W1	Plaster	White	None	0	0	Negative
1	2	Staff Restroom adjacent to Teacher's Lounge	W2	Plaster	White	None	0	0	Negative
1	2	Staff Restroom adjacent to Teacher's Lounge	W3	Plaster	White	None	0	0	Negative
1	2	Staff Restroom adjacent to Teacher's Lounge	W4	Plaster	White	None	0	0	Negative
1	2	Staff Restroom adjacent to Teacher's Lounge	Ceiling	Plaster	White	None	0	0.13	Negative
1	2	Staff Restroom adjacent to Teacher's Lounge	Floor	Wood	Varnish	None	0	0	Negative
1	2	Hallway between Main Hallway and Classroom 210	W1	N/A	N/A	None	0	N/A	N/A
1	2	Hallway between Main Hallway and Classroom 210	W2	CMU Block Wall	Blue	None	0	0.01	Negative
1	2	Hallway between Main Hallway and Classroom 210	W2	CMU Block Wall	White	None	0	0.02	Negative
1	2	Hallway between Main Hallway and Classroom 210	W3	CMU Block Wall	Blue	None	0	0.02	Negative
1	2	Hallway between Main Hallway and Classroom 210	W3	CMU Block Wall	White	None	0	0.01	Negative
1	2	Hallway between Main Hallway and Classroom 210	W4	CMU Block Wall	Blue	None	0	0.02	Negative
1	2	Hallway between Main Hallway and Classroom 210	W4	CMU Block Wall	White	None	0	0.03	Negative
1	2	Hallway between Main Hallway and Classroom 210	Ceiling	N/A	N/A	None	0	N/A	N/A
1	2	Hallway between Main Hallway and Classroom 210	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 210	W1	CMU Block Wall	Purple	None	0	0	Negative
1	2	Classroom 210	W2	CMU Block Wall	Purple	None	0	0	Negative
1	2	Classroom 210	W3	CMU Block Wall	Purple	None	0	0	Negative
1	2	Classroom 210	W4	CMU Block Wall	Purple	None	0	0.4	Negative
1	2	Classroom 210	Ceiling	Plaster	White	None	0	0.02	Negative
1	2	Classroom 210	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 210 Closet	W1	CMU Block Wall	Blue	None	0	0	Negative
1	2	Classroom 210 Closet	W2	CMU Block Wall	Blue	None	0	0.02	Negative
1	2	Classroom 210 Closet	W3	CMU Block Wall	Yellow	None	0	0.01	Negative
1	2	Classroom 210 Closet	W4	CMU Block Wall	Yellow	None	0	0.03	Negative
1	2	Classroom 210 Closet	W4	CMU Block Wall	Blue	None	0	0	Negative
1	2	Classroom 210 Closet	Ceiling	Plaster	White	Chipping	15	0.09	Negative
1	2	Classroom 210 Closet	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	2	Classroom 211	W1	CMU Block Wall	White	None	0	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 211	W2	CMU Block Wall	White	None	0	0.02	Negative
1	2	Classroom 211	W3	CMU Block Wall	White	Cracking	15	0.02	Negative
1	2	Classroom 211	W4	CMU Block Wall	White	Chipping	4	0	Negative
1	2	Classroom 211	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Classroom 211	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 211 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	W1	CMU Block Wall	Pink	None	0	0	Negative
1	2	Classroom 212	W1	CMU Block Wall	White	None	0	0	Negative
0	2	Classroom 212	W2	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 212	W3	CMU Block Wall	Blue	None	0	0.03	Negative
1	2	Classroom 212	W3	CMU Block Wall	Pink	None	0	0.08	Negative
1	2	Classroom 212	W4	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 212	W4	CMU Block Wall	Pink	None	0	0	Negative
1	2	Classroom 212	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Classroom 212	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 212 Storage	W1	CMU Block Wall	White	None	0	0.01	Negative
1	2	Classroom 212 Storage	W2	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 212 Storage	W3	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 212 Storage	W4	CMU Block Wall	White	None	0	0.02	Negative
1	2	Classroom 212 Storage	Ceiling	Plaster	White	None	0	0.04	Negative
1	2	Classroom 212 Storage	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	2	Classroom 212 Restroom	W1	CMU Block Wall	Grey	None	0	0.03	Negative
1	2	Classroom 212 Restroom	W2	CMU Block Wall	Grey	None	0	0.11	Negative
1	2	Classroom 212 Restroom	W3	CMU Block Wall	Grey	None	0	0.01	Negative
1	2	Classroom 212 Restroom	W4	CMU Block Wall	Grey	None	0	0.07	Negative
1	2	Classroom 212 Restroom	Ceiling	Plaster	Grey	None	0	0.05	Negative
1	2	Classroom 212 Restroom	Floor	Concrete	Unpainted	None	0	0.06	Negative
1	2	Classroom 213	W1	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 213	W2	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 213	W3	CMU Block Wall	White	Cracking	3	0	Negative

		Inspection Dates: 03/07/2022-03/11/2022	Lead Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672	Robeson High School						
		Inspection Company: Viva EHS	4125 Ludlow St, Philadelphia, PA 19104						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 213	W4	CMU Block Wall	White	None	0	0	Negative
1	2	Classroom 213	Ceiling	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 213	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 213 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 213 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 213 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 213 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 213 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 213 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 213 Restroom	W1	CMU Block Wall	White	None	0	0.02	Negative
1	2	Classroom 213 Restroom	W2	CMU Block Wall	White	None	0	0.01	Negative
1	2	Classroom 213 Restroom	W3	CMU Block Wall	White	Cracking	5	0.01	Negative
1	2	Classroom 213 Restroom	W4	CMU Block Wall	White	None	0	0.04	Negative
1	2	Classroom 213 Restroom	Ceiling	Plaster	White	None	0	0.03	Negative
1	2	Classroom 213 Restroom	Floor	N/A	N/A	None	0	N/A	N/A
1	2	2nd Floor Main Hallway	W1	CMU Block Wall	Blue	None	0	0.04	Negative
1	2	2nd Floor Main Hallway	W2	CMU Block Wall	Blue	None	0	0.02	Negative
1	2	2nd Floor Main Hallway	W3	CMU Block Wall	Blue	None	0	0.02	Negative
1	2	2nd Floor Main Hallway	W4	CMU Block Wall	Blue	None	0	0.01	Negative
1	2	2nd Floor Main Hallway	W1	CMU Block Wall	White	None	0	0.03	Negative
1	2	2nd Floor Main Hallway	W3	CMU Block Wall	White	None	0	0.01	Negative
1	2	2nd Floor Main Hallway	W4	CMU Block Wall	White	None	0	0.02	Negative
1	2	2nd Floor Main Hallway	Radiator	Metal	Blue	None	0	0	Negative
1	2	2nd Floor Main Hallway	Ceiling	N/A	N/A	None	0	N/A	N/A
1	2	2nd Floor Main Hallway	Floor	N/A	N/A	None	0	N/A	N/A
1	2	Classroom 205 Bathroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 205 Bathroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 205 Bathroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 205 Bathroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 205 Bathroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 205 Bathroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 202 Bathroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 202 Bathroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 202 Bathroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 202 Bathroom	W4	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 03/07/2022-03/11/2022		Lead Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Lionel Ray Wilson & #006672		Robeson High School					
		Inspection Company: Viva EHS		4125 Ludlow St, Philadelphia, PA 19104					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 202 Bathroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 202 Bathroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Stairwell outside Gym	Handrail	Metal	Blue	Friction	20	0.13	Negative
1	1	Stairwell outside Gym	Radiator	Metal	Blue	None	0	0.01	Negative