

Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	B	H01	Hallway from Classroom B1 to Rear Exit past Boy's Restroom	W3	Brick	Brown	Chipping	1	Previous data used	Positive
1	B	H01	Hallway from Classroom B1 to Rear Exit past Boy's Restroom	Duct	Metal	White	Chipping	5	Previous data used	Positive
1	B	H01	Hallway from Classroom B1 to Rear Exit past Boy's Restroom	Conduit	Metal	White	Flaking	4	0.4	Negative
1	B	H01	Hallway from Classroom B1 to Rear Exit past Boy's Restroom	Pipe	Metal	Grey	Flaking	5	Previous data used	Positive
1	B	H01	Hallway from Classroom B1 to Rear Exit past Boy's Restroom	Diamond Plate Trench Covers	Metal	Grey	Flaking	5	Previous data used	Positive
1	B	S08	Rear Stairwell near Boy's Restroom	Ceiling	Concrete	White	Flaking	8	Previous data used	Positive
1	B	011B	Boy's Restroom	Ceiling	Concrete	White	Flaking	22	Previous data used	Positive
1	B	011B	Boy's Restroom	W3	Concrete	White	Efflorescence	8	22.8	Positive
1	B	H02	Hallway from Classroom B1 to Gymnasium	W3	Plaster	Grey	Chipping	1	Previous data used	Positive
1	B	H02	Hallway from Classroom B1 to Gymnasium	Baseboard	Concrete	Grey	Chipping	12	Previous data used	Positive
1	B	H02	Hallway from Classroom B1 to Gymnasium	Diamond Plate Trench Covers	Metal	Grey	Chipping	1	Previous data used	Positive
1	B	S04	Stairwell (Left side of Lobby) at Main Entrance	Ceiling	Concrete	White	Efflorescence	2	Previous data used	Positive
1	B	0177RR	Building Engineer's Office - Restroom	W1	Brick	White	Flaking	40	Previous data used	Positive
1	B	0177RR	Building Engineer's Office - Restroom	W2	Brick	White	Flaking	80	Previous data used	Positive
1	B	0177RR	Building Engineer's Office - Restroom	W3	Brick	White	Flaking	40	Previous data used	Positive
1	B	0177RR	Building Engineer's Office - Restroom	W4	Brick	White	Flaking	80	Previous data used	Positive
1	B	H07	Hallway from Classroom B4 (Art Room) to Cafeteria	Baseboard	Concrete	Grey	Chipping	10	Previous data used	Positive

Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	B	014B	Classroom B6	W2	Plaster	Purple	Efflorescence	10	Previous data used	Positive
1	B	014B	Classroom B6	W3	Plaster	Purple	Efflorescence	2	Previous data used	Positive
1	B	H05	Hallway along Side of Cafeteria	W2	Brick	White	Chipping	10	Previous data used	Positive
1	B	H05	Hallway along Side of Cafeteria	W4	Brick	White	Chipping	10	Previous data used	Positive
1	B	H05	Hallway along Side of Cafeteria	Ceiling	Concrete	White	Chipping	70	Previous data used	Positive
1	B	H08	Hallway leading to IMC from Hallway along side of Cafeteria	W1	CMU	White	Chipping	2	31	Positive
1	B	H08	Hallway leading to IMC from Hallway along side of Cafeteria	W2	CMU	White	Chipping	10	26.5	Positive
1	B	H08	Hallway leading to IMC from Hallway along side of Cafeteria	W3	CMU	White	Chipping	5	25.9	Positive
1	B	H08	Hallway leading to IMC from Hallway along side of Cafeteria	W4	CMU	White	Chipping	10	30.2	Positive
1	B	H08	Hallway leading to IMC from Hallway along side of Cafeteria	Ceiling	Concrete	White	Chipping	10	Previous data used	Positive
1	B	015B	Storage/Fan Room	Fan Unit	Metal	Silver	Flaking	200	25.2	Positive
1	B	S05	Rear Stairwell between Cafeteria and IMC	Ceiling	Concrete	White	Chipping	20	Previous data used	Positive
1	B	019B	IMC/Library	W1	CMU	White	Chipping	3	24.7	Positive
1	B	019B	IMC/Library	W3	CMU	White	Chipping	2	16.2	Positive
1	B	005A	Cafeteria	W3	Plaster	White	Chipping	20	Previous data used	Positive
1	B	005B	Kitchen	W3	Plaster	White	Chipping	5	Previous data used	Positive
1	B	016B	Girl's Restroom	W1	Plaster	White	Chipping	12	Previous data used	Positive
1	B	016B	Girl's Restroom	Pipe	Metal	White	Chipping	4	Previous data used	Positive

Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	B	017C	Storage under Stairwell (near Boy's Restroom)	W1	Plaster	White	Flaking	2	Previous data used	Positive
1	B	017C	Storage under Stairwell (near Boy's Restroom)	W2	Plaster	White	Flaking	4	Previous data used	Positive
1	B	017C	Storage under Stairwell (near Boy's Restroom)	Ceiling	Plaster	White	Efflorescence	2	22.6	Positive
1	1	S18	Rear Stairwell near Classroom 112	W4	Plaster	White	Efflorescence	40	Previous data used	Positive
1	1	S18	Rear Stairwell near Classroom 112	Ceiling	Plaster	White	Efflorescence	20	18.5	Positive
1	1	109	Classroom 109	W1	Plaster	White	Chipping	8	Previous data used	Positive
1	1	109	Classroom 109	W4	Plaster	White	Flaking	20	Previous data used	Positive
1	1	105A	Storage adjacent Women's Restroom	W1	Plaster	White	Chipping	1	Previous data used	Positive
1	1	105A-1	Women's Restroom	W3	Plaster	White	Flaking	3	Previous data used	Positive
1	1	105A-1	Women's Restroom	Window Sill	Wood	Brown	Chipping	2	0.1	Negative
1	1	105A-1	Women's Restroom	Radiator	Metal	Silver	Flaking	4	Previous data used	Positive
1	1	102C	Girls' Restroom	W2	Concrete	White	Chipping	4	20.9	Positive
1	1	102C	Girls' Restroom	Vent	Metal	White	Chipping	2	0.12	Negative
1	1	102C	Girls' Restroom	Radiator	Metal	Grey	Flaking	2	Previous data used	Positive
1	1	102A	Classroom 102 Restroom	Ceiling	Plaster	White	Efflorescence	16	21.4	Positive
1	1	102A	Classroom 102 Restroom	Baseboard	Concrete	Brown	Chipping	1	Previous data used	Positive
1	1	102E	Classroom 102 - Closet next to Restroom	W1	Plaster	White	Chipping	1	Previous data used	Positive
1	1	102	Classroom 102	W1	Plaster	White	Chipping	1	Previous data used	Positive
1	1	102	Classroom 102	W3	Plaster	White	Efflorescence	4	Previous data used	Positive
1	1	102	Classroom 102	Baseboard	Concrete	Brown	Chipping	2	Previous data used	Positive
1	1	101	Classroom 101	W1	Plaster	Grey	Chipping	1	Previous data used	Positive

Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	1	101A	Classroom 101A	W2	Plaster	Grey	Flaking	8	Previous data used	Positive
1	1	101A	Classroom 101A	Radiator	Metal	Grey	Flaking	3	Previous data used	Positive
1	1	101A	Classroom 101A	Ceiling	Plaster	White	Cracking	4	20.9	Positive
1	1	103	Classroom 103	W1	Plaster	White	Chipping	1	Previous data used	Positive
1	1	S15	Rear Stairwell near Classroom 101	W3	Plaster	White	Efflorescence	3	Previous data used	Positive
1	1	S15	Rear Stairwell near Classroom 101	Ceiling	Plaster	White	Efflorescence	8	20.2	Positive
1	1	S15	Rear Stairwell near Classroom 101	Handrail	Metal	Brown	Friction	8	Previous data used	Negative
1	1	S15	Rear Stairwell near Classroom 101	Stair Risers	Concrete	Grey	Friction	10	1.5	Positive
1	1	H112	Hallway to Fire Tower next to Classroom 101	Ceiling	Concrete	White	Cracking	5	Previous data used	Positive
1	1	H112	Hallway to Fire Tower next to Classroom 101	Door Frame	Metal	Brown	Chipping	2	Previous data used	Positive
1	1	H112	Hallway to Fire Tower next to Classroom 101	Door	Metal	Brown	Chipping	2	Previous data used	Positive
1	1	H111	Hallway from Classroom 103 to Rear Stairwell past Classroom 101	Vent	Metal	Brown	Chipping	4	0.2	Negative
1	1	012C	Auditorium	W2	Plaster	White	Efflorescence	60	Previous data used	Positive
1	1	012C	Auditorium	W4	Plaster	White	Efflorescence	60	Previous data used	Positive
1	1	012C	Auditorium	Ceiling	Plaster	White	Flaking	10	23.6	Positive
1	1	012C	Auditorium	Curtains	Fabric	N/A	N/A	N/A	N/A	N/A
1	1	STAGE	Stage	W1	Plaster	White	Flaking	4	Previous data used	Positive
1	1	STAGE	Stage	W3	Plaster	White	Efflorescence	2	Previous data used	Positive
1	1	S113H	Hallway behind Stage	W3	Plaster	White	Efflorescence	4	Previous data used	Positive
1	1	S114D	Stage Left Dressing Room-Female	W1	Plaster	White	Flaking	20	Previous data used	Positive

Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	1	S114D	Stage Left Dressing Room-Female	W2	Plaster	White	Flaking	5	Previous data used	Positive
1	1	S114D	Stage Left Dressing Room-Female	W4	Plaster	White	Flaking	10	Previous data used	Positive
1	1	S111	Stairwell - Near Stage Right	W1	Plaster	White	Flaking	5	Previous data used	Positive
1	1	S113D	Stage Right Dressing Room-Male	W1	Plaster	White	Flaking	40	Previous data used	Positive
1	1	105	Classroom 105	W1	Plaster	White	Chipping	5	Previous data used	Positive
1	1	106	Classroom 106	W1	Plaster	White	Chipping	5	Previous data used	Positive
1	1	107	Classroom 107	W1	Plaster	White	Chipping	4	Previous data used	Positive
1	1	108	Classroom 108	W1	Plaster	White	Chipping	10	Previous data used	Positive
1	1	109	Classroom 109	W2	Plaster	White	Chipping	4	Previous data used	Positive
1	1	109A	Principal's Restroom/Storage Area	W1	Plaster	White	Flaking	3	Previous data used	Positive
1	1	109A	Principal's Restroom/Storage Area	W3	Plaster	White	Flaking	5	Previous data used	Positive
1	1	S13	Stairwell near Classroom 110	W3	Plaster	White	Chipping	4	Previous data used	Positive
1	1	110	Classroom 110	W3	Plaster	White	Chipping	5	Previous data used	Positive
1	1	111	Classroom 111	W4	Plaster	White	Chipping	5	Previous data used	Positive
1	1	112	Classroom 112	W4	Plaster	White	Flaking	20	Previous data used	Positive
1	1	112A	Boys' Restroom	Ceiling	Concrete	White	Flaking	10	Previous data used	Positive
1	1	H109	Hallway to Fire Tower next to Classroom 112	Door Frame	Metal	Brown	Chipping	2	Previous data used	Positive
1	1	H109	Hallway to Fire Tower next to Classroom 112	Door	Metal	Brown	Chipping	2	Previous data used	Positive
1	1	111C	Principal's Office	W4	Plaster	White	Chipping	1	Previous data used	Positive

<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component (see terms)</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage (see terms)</b>	<b>Component Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm<sup>2</sup>)</b>	<b>Component XRF (positive/negative)</b>
1	1	111A	Main Office	W4	Plaster	White	Chipping	12	Previous data used	Positive
1	2	S15	Rear Stairwell near Classroom 101	Ceiling	Plaster	White	Efflorescence	10	13.9	Positive
1	2	S15	Rear Stairwell near Classroom 101	Handrail	Metal	Brown	Friction	20	Previous data used	Negative
1	2	S15	Rear Stairwell near Classroom 101	Stair Risers	Concrete	Grey	Chipping	20	1.8	Positive
1	2	H216	Hallway to Fire Tower Stairwell next to Classroom 213	Ceiling	Concrete	White	Efflorescence	24	23.1	Positive
1	2	H216	Hallway to Fire Tower Stairwell next to Classroom 213	Window Bars	Metal	Grey	Chipping	4	Previous data used	Positive
1	2	H216	Hallway to Fire Tower Stairwell next to Classroom 213	Door Frame	Metal	Brown	Chipping	2	3.2	Positive
1	2	H216	Hallway to Fire Tower Stairwell next to Classroom 213	Door	Metal	Brown	Chipping	2	2.4	Positive
1	2	213	Classroom 213	W1	Plaster	White	Chipping	1	Previous data used	Positive
1	2	213	Classroom 213	W3	Plaster	White	Flaking	12	Previous data used	Positive
1	2	213	Classroom 213	W4	Plaster	White	Chipping	4	Previous data used	Positive
1	2	213	Classroom 213	Ceiling	Plaster	White	Flaking	3	18.4	Positive
1	2	213	Classroom 213	Pipe	Metal	Grey	Chipping	12	Previous data used	Positive
1	2	215	Classroom 215	W3	Plaster	White	Chipping	3	Previous data used	Positive
1	2	215A	Classroom 215 Closet	Pipe	Metal	White	Chipping	1	Previous data used	Positive
1	2	216A	Book Closet adj. Men's Restroom	W1	Plaster	White	Chipping	4	Previous data used	Positive
1	2	216A-1	Men's Restroom	W3	Plaster	White	Flaking	6	Previous data used	Positive
1	2	216	Classroom 216	W1	Plaster	White	Chipping	1	Previous data used	Positive

Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	2	H215	Hallway along Classrooms 213-214	W1	Plaster	Blue	Chipping	2	Previous data used	Positive
1	2	H215	Hallway along Classrooms 213-214	W1	Plaster	Yellow	Chipping	3	Previous data used	Positive
1	2	H215	Hallway along Classrooms 213-214	W3	Plaster	Blue	Chipping	2	Previous data used	Positive
1	2	H215	Hallway along Classrooms 213-214	Baseboard	Concrete	Brown	Chipping	10	Previous data used	Positive
1	2	S23	Stairwell near Classroom 221	W3	Plaster	Blue	Efflorescence	2	Previous data used	Positive
1	2	S23	Stairwell near Classroom 221	Newel Posts	Metal	Black	Friction	2	Previous data used	Negative
1	2	221	Classroom 221	W2	Plaster	White	Flaking	4	Previous data used	Positive
1	2	221	Classroom 221	W3	Plaster	White	Flaking	5	Previous data used	Positive
1	2	221A	Classroom 221 Closet	W1	Plaster	White	Chipping	2	Previous data used	Positive
1	2	222A	Faculty Dining (Room 224)	W1	Plaster	White	Flaking	4	Previous data used	Positive
1	2	222A	Faculty Dining (Room 224)	W3	Plaster	White	Flaking	2	Previous data used	Positive
1	2	222A	Faculty Dining (Room 224)	W4	Plaster	White	Flaking	2	Previous data used	Positive
1	2	S28	Rear Stairwell across from Boy's Restroom	Ceiling	Plaster	White	Flaking	5	20.2	Positive
1	2	H213	Hallway along Classrooms 222-223	Sink	Ceramic	Grey	Flaking	2	13.9	Positive
1	2	H213	Hallway along Classrooms 222-223	Door Frame	Metal	Brown	Chipping	2	2.5	Positive
1	2	H213	Hallway along Classrooms 222-223	Door	Metal	Brown	Chipping	2	4.2	Positive
1	2	H213	Hallway along Classrooms 222-223	Stair Risers	Concrete	Grey	Chipping	4	2.8	Positive
1	2	H223B	Hallway to Fire Tower next to Classroom 223	Door	Metal	Brown	Chipping	2	3.6	Positive
1	2	H223B	Hallway to Fire Tower next to Classroom 223	Door Frame	Metal	Brown	Chipping	2	1.4	Positive

Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	2	S223B	Fire Tower next to Classroom 223	Door	Metal	Brown	Chipping	2	3.9	Positive
1	2	S223B	Fire Tower next to Classroom 223	Door Frame	Metal	Brown	Chipping	2	3	Positive
1	2	218A	Auditorium Balcony	W2	Plaster	White	Flaking	50	Previous data used	Positive
1	2	218A	Auditorium Balcony	W4	Plaster	White	Flaking	50	Previous data used	Positive
1	2	217	Classroom 217	W2	Plaster	White	Chipping	2	Previous data used	Positive
1	2	217	Classroom 217	W4	Plaster	White	Chipping	2	Previous data used	Positive
1	2	218	Classroom 218	W4	Plaster	White	Flaking	20	Previous data used	Positive
1	2	219	Classroom 219	W1	Plaster	White	Chipping	2	Previous data used	Positive
1	2	219	Classroom 219	W3	Plaster	White	Chipping	2	Previous data used	Positive
1	2	220	Classroom 220	W2	Plaster	White	Chipping	3	Previous data used	Positive
1	2	202A	Women's Restroom/Storage	Ceiling	Plaster	White	Flaking	5	24.1	Positive
1	2	S23	Stairwell near Classroom 221	W1	Plaster	White	Chipping	1	Previous data used	Positive
1	2	S28	Rear Stairwell across from Boy's Restroom	Ceiling	Plaster	White	Chipping	10	23.6	Positive
1	2	H223B	Hallway to Fire Tower next to Classroom 223	Ceiling	Concrete	White	Flaking	10	19.8	Positive
1	2	H223B	Hallway to Fire Tower next to Classroom 223	Door Frame	Metal	Brown	Chipping	2	2.7	Positive
1	2	H223B	Hallway to Fire Tower next to Classroom 223	Door	Metal	Brown	Chipping	2	2.5	Positive
1	2	221	Classroom 221	W4	Plaster	White	Chipping	2	Previous data used	Positive
1	2	222	Classroom 222	W3	Plaster	White	Chipping	2	Previous data used	Positive
1	2	223	Classroom 223	W4	Plaster	White	Chipping	2	Previous data used	Positive



Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	2	222B	Nurse's Office	W3	Plaster	White	Chipping	3	Previous data used	Positive
1	3	324	Classroom 324	W2	Plaster	White	Flaking	10	Previous data used	Positive
1	3	324	Classroom 324	W3	Plaster	White	Flaking	12	Previous data used	Positive
1	3	H317	Hallway along Classrooms 324-325	W4	Plaster	White	Flaking	12	Previous data used	Positive
1	3	325	Classroom 325	W2	Plaster	White	Chipping	5	Previous data used	Positive
1	3	325	Classroom 325	W4	Plaster	White	Chipping	6	Previous data used	Positive
1	3	326	Classroom 326	W3	Plaster	White	Flaking	16	Previous data used	Positive
1	3	327	Classroom 327	W3	Plaster	White	Flaking	5	Previous data used	Positive
1	3	328	Classroom 328	W1	Plaster	White	Chipping	1	Previous data used	Positive
1	3	331A	Women's Restroom	W1	Plaster	White	Flaking	1	Previous data used	Positive
1	3	S15	Stairwell to Attic	W3	Plaster	White	Chipping	4	Previous data used	Positive
1	3	S15	Stairwell to Attic	Stair Risers	Metal	Grey	Friction	6	Previous data used	Positive
1	3	S15	Stairwell to Attic	Newel Posts	Metal	Grey	Friction	2	Previous data used	Negative
1	3	S15	Stairwell to Attic	Baluster	Metal	Grey	Friction	10	Previous data used	Positive
1	3	S15	Stairwell to Attic	Stair Stringer	Metal	Grey	Friction	6	Previous data used	Positive
1	3	H319	Hallway along Classrooms 333-334	W2	Plaster	White	Bubbling	5	Previous data used	Positive
1	3	H323	Hallway to Women's Restroom	W2	Plaster	White	Chipping	2	Previous data used	Positive
1	3	H323	Hallway to Women's Restroom	W3	Plaster	White	Chipping	3	Previous data used	Positive
1	3	S33	Stairwell near Classroom 332	W1	Plaster	White	Chipping	10	Previous data used	Positive
1	3	S33	Stairwell near Classroom 332	W2	Plaster	White	Chipping	10	Previous data used	Positive

Element	Floor	Space #	On-Site Room Name	Component (see terms)	Substrate Material	Color	Description of Damage (see terms)	Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Component XRF (positive/negative)
1	3	332	Classroom 332	W1	Plaster	White	Chipping	1	Previous data used	Positive
1	3	333	Classroom 333	W1	Plaster	White	Chipping	2	Previous data used	Positive
1	3	334	Classroom 334	W4	Plaster	White	Chipping	1	Previous data used	Positive
1	3	S38	Rear Stairwell near Boy's Restroom	W4	Plaster	White	Chipping	5	Previous data used	Positive
1	3	S38	Rear Stairwell near Boy's Restroom	Handrail	Metal	Grey	Friction	20	Previous data used	Negative
1	3	H230	Hallway to Fire Tower next to Classroom 334	Ceiling	Concrete	White	Chipping	12	22.1	Positive
1	3	H230	Hallway to Fire Tower next to Classroom 334	Door	Metal	Brown	Chipping	2	Previous data used	Positive
1	3	H230	Hallway to Fire Tower next to Classroom 334	Door Frame	Metal	Brown	Chipping	2	1.9	Positive
1	3	S321	Fire Tower near Classroom 324	Door	Metal	Brown	Chipping	2	Previous data used	Positive
1	3	S321	Fire Tower near Classroom 324	Door Frame	Metal	Brown	Chipping	2	4.2	Positive
1	3	S35	Rear Stairwell near Classroom 324	Handrail	Metal	Brown	Friction	5	Previous data used	Negative
1	3	S35	Rear Stairwell near Classroom 324	Stair Risers	Concrete	Grey	Chipping	10	Previous data used	Positive
1	3	H317	Hallway along Classrooms 324-325	W2	Plaster	White	Efflorescence	4	Previous data used	Positive
1	3	H317	Hallway along Classrooms 324-325	W3	Plaster	White	Flaking	6	Previous data used	Positive
1	3	H317	Hallway along Classrooms 324-325	Vent	Metal	Brown	Chipping	1	0.25	Negative
1	3	327A	Men's Restroom	W3	Plaster	White	Flaking	3	Previous data used	Positive
1	3	S15	Stairwell to Attic	W1	Plaster	White	Flaking	25	Previous data used	Positive
1	3	S15	Stairwell to Attic	Ceiling	Plaster	White	Moisture Damage	2	21.5	Positive
1	3	S15	Stairwell to Attic	Stair Risers	Concrete	Grey	Chipping	20	Previous data used	Positive
1	3	S15	Stairwell to Attic	Stair Stringer	Concrete	Grey	Chipping	20	0.15	Negative

<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component (see terms)</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage (see terms)</b>	<b>Component Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm<sup>2</sup>)</b>	<b>Component XRF (positive/negative)</b>
1	3	331A	Women's Restroom	W2	Plaster	White	Flaking	3	Previous data used	Positive
1	3	331A	Women's Restroom	W3	Plaster	White	Efflorescence	12	Previous data used	Positive
1	3	S33	Stairwell near Classroom 332	W2	Plaster	White	Gouge	1	Previous data used	Positive
1	3	S33	Stairwell near Classroom 332	W3	Plaster	Blue	Flaking	4	Previous data used	Positive
1	3	S33	Stairwell near Classroom 332	Ceiling	Plaster	White	Flaking	20	Previous data used	Positive
1	3	S38	Rear Stairwell near Boy's Restroom	Ceiling	Plaster	White	Flaking	4	Previous data used	Positive
1	3	S38	Rear Stairwell near Boy's Restroom	Handrail	Metal	Brown	Friction	20	Previous data used	Negative
1	3	H230	Hallway to Fire Tower next to Classroom 334	Ceiling	Concrete	White	Cracking	8	23.6	Positive
1	3	H230	Hallway to Fire Tower next to Classroom 334	Door Frame	Metal	Brown	Chipping	2	2.4	Positive
1	3	H230	Hallway to Fire Tower next to Classroom 334	Door	Metal	Brown	Chipping	2	Previous data used	Positive