

		Dates: 9/8/2022-9/13/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Charles Rhodes 003542	Bridesburg Annex Elementary School						
		Inspection Company: BATTA	4435 E. Almond Street, Philadelphia, PA 19137						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		1	B	Hallway adjacent to Boiler Room	W1	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Boiler Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Boiler Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Boiler Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Boiler Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Men's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Men's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Men's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Men's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Men's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Men's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Men's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Men's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Men's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Men's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Men's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Men's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Restrooms	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Restrooms	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Restrooms	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Restrooms	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Restrooms	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway adjacent to Restrooms	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Women's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Women's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Women's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Women's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Women's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Women's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Women's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Women's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Women's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Women's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Women's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Closet adjacent to Women's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	South Wing Main Hallway	Floor	No Access	No Access	No Access	No Access	No Access	No Access

		Dates: 9/8/2022-9/13/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Charles Rhodes 003542	Bridesburg Annex Elementary School						
		Inspection Company: BATTA	4435 E. Almond Street, Philadelphia, PA 19137						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	South Wing Main Hallway	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	South Wing Main Hallway	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	South Wing Main Hallway	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	South Wing Main Hallway	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	South Wing Main Hallway	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room - Front of Building	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room - Front of Building	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room - Front of Building	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room - Front of Building	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room - Front of Building	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room - Front of Building	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room Under Stairs	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room Under Stairs	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room Under Stairs	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room Under Stairs	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room Under Stairs	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room Under Stairs	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Gym Table/Chair Storage Room	Floor	Concrete	Grey	Chipping	100	0.3	Negative
1	B	Gym Table/Chair Storage Room	W1	Concrete	Tan	Chipping	50	0.5	Negative
1	B	Gym Table/Chair Storage Room	Conduit	Metal	White	Chipping	40	0.3	Negative
1	B	Gym Table/Chair Storage Room	W2	Concrete	Tan	Chipping	25	0.1	Negative
1	B	Gym Table/Chair Storage Room	W3	Concrete	Tan	Chipping	40	0.5	Negative
1	B	Gym Table/Chair Storage Room	W4	Concrete	Tan	Chipping	30	0.5	Negative
1	B	Gym Table/Chair Storage Room	Ceiling	Plaster	White	Chipping	10	0.3	Negative
1	B	Stage Storage Room Right Facing	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Right Facing	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Right Facing	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Right Facing	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Right Facing	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Right Facing	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Left Facing	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Left Facing	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Left Facing	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Left Facing	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Left Facing	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage Storage Room Left Facing	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

		<b>Dates: 9/8/2022-9/13/22</b>	<b>Lead-Safe Certification Assessment Report</b>						
		<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>	<b>Bridesburg Annex Elementary School</b>						
		<b>Inspection Company: BATTA</b>	<b>4435 E. Almond Street, Philadelphia, PA 19137</b>						
<b>E</b>	<b>F</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	B	Hallway Behind Stage	Floor	Concrete	grey	Chipping	20	0.6	Negative
1	B	Hallway Behind Stage	W1	Plaster	tan	Moisture Damage	12	2.7	Positive
1	B	Hallway Behind Stage	W2	Plaster	tan	Moisture Damage	40	2.3	Positive
1	B	Hallway Behind Stage	W3	Plaster	Tan	Moisture Damage	10	0.1	Negative
1	B	Hallway Behind Stage	W4	Plaster	Tan	Moisture Damage	20	3.2	Positive
1	B	Hallway Behind Stage	Ceiling	Metal	white	Flaking	12	0.8	Positive
1	B	Music Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Band Storage/Science Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Band Storage/Science Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Band Storage/Science Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Band Storage/Science Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Band Storage/Science Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Band Storage/Science Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Computer Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Computer Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Computer Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Computer Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Computer Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Computer Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Music Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Maintenance Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Maintenance Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Maintenance Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Maintenance Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Maintenance Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Maintenance Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

		Dates: 9/8/2022-9/13/22	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Bridesburg Annex Elementary School</b>						
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Pipe Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Tunnel to Church	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Tunnel to Church	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Tunnel to Church	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Tunnel to Church	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Tunnel to Church	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Pipe Tunnel to Church	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Custodian Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Custodian Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Custodian Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Custodian Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Custodian Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Custodian Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage #1 adjacent to Custodian Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage #1 adjacent to Custodian Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage #1 adjacent to Custodian Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage #1 adjacent to Custodian Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage #1 adjacent to Custodian Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage #1 adjacent to Custodian Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Small Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Small Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Small Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Small Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Small Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Small Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boiler Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boiler Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boiler Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boiler Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boiler Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boiler Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

		Dates: 9/8/2022-9/13/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Charles Rhodes 003542	Bridesburg Annex Elementary School						
		Inspection Company: BATTA	4435 E. Almond Street, Philadelphia, PA 19137						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Girl's Restroom in Gym	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Restroom in Gym	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Restroom in Gym	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Restroom in Gym	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Restroom in Gym	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Restroom in Gym	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boys' Restroom in Gym	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boys' Restroom in Gym	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boys' Restroom in Gym	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boys' Restroom in Gym	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boys' Restroom in Gym	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Boys' Restroom in Gym	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Gym/Auditorium	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Gym/Auditorium	W1	Plaster	White	Moisture Damage	10	0.1	Negative
1	B	Gym/Auditorium	Radiator	Metal	Grey	None	0	0.1	Negative
1	B	Gym/Auditorium	Conduit	Metal	White	None	0	0.5	Negative
1	B	Gym/Auditorium	W2	Plaster	White	Moisture Damage	15	0.3	Negative
1	B	Gym/Auditorium	Pipe	Metal	White	None	0	0.1	Negative
1	B	Gym/Auditorium	Column	Plaster	Blue	None	0	3.2	Positive
1	B	Gym/Auditorium	W3	Plaster	White	Moisture Damage	50	0.1	Negative
1	B	Gym/Auditorium	W4	Plaster	White	Moisture Damage	10	0.3	Negative
1	B	Gym/Auditorium	Doorframe	Wood	Tan	Flaking	10	1.9	Positive
1	B	Gym/Auditorium	Ceiling	Metal	White	Moisture Damage	25	0.4	Negative
1	B	Gym/Auditorium Stage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Gym/Auditorium Stage	W1	Plaster	White	Chipping	10	1.1	Positive
1	B	Gym/Auditorium Stage	Stringer	Wood	Brown	Chipping	16	2	Positive
1	B	Gym/Auditorium Stage	Railing	Metal	Black	None	0	0	Negative
1	B	Gym/Auditorium Stage	W2	Plaster	White	Cracking	45	0.9	Positive
1	B	Gym/Auditorium Stage	W3	Plaster	White	Flaking	100	0.9	Positive
1	B	Gym/Auditorium Stage	W4	Plaster	White	Flaking	40	0.7	Positive
1	B	Gym/Auditorium Stage	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	B	Gym - Women's Restroom	Floor	Terracotta	N/A	N/A	N/A	N/A	N/A
1	B	Gym - Women's Restroom	W1	Plaster	White	Flaking	6	0.1	Negative
1	B	Gym - Women's Restroom	Doorframe	Wood	Black	Chipping	5	0.1	Negative
1	B	Gym - Women's Restroom	W2	Plaster	White	Flaking	10	1.4	Positive
1	B	Gym - Women's Restroom	radiator	Metal	Grey	None	0	0.2	Negative

		Dates: 9/8/2022-9/13/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Charles Rhodes 003542	Bridesburg Annex Elementary School						
		Inspection Company: BATTA	4435 E. Almond Street, Philadelphia, PA 19137						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Gym - Women's Restroom	Partition	Metal	Blue	Chipping	20	0.2	Negative
1	B	Gym - Women's Restroom	W3	Plaster	White	Flaking	12	1.7	Positive
1	B	Gym - Women's Restroom	W4	Plaster	White	Flaking	20	0.2	Negative
1	B	Gym - Women's Restroom	Ceiling	Plaster	White	Flaking	30	0.3	Negative
1	B	Gym Storage #1 (adjacent to Women's Restroom)	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Gym Storage #1 (adjacent to Women's Restroom)	W1	Plaster	White	Chipping	10	2.7	Positive
1	B	Gym Storage #1 (adjacent to Women's Restroom)	Doorframe/Door	Metal	Grey	Chipping	10	0.3	Negative
1	B	Gym Storage #1 (adjacent to Women's Restroom)	W2	Plaster	White	Cracking	40	0.4	Negative
1	B	Gym Storage #1 (adjacent to Women's Restroom)	W3	Plaster	White	No Access	No Access	No Access	No Access
1	B	Gym Storage #1 (adjacent to Women's Restroom)	W4	CMU	White	None	0	0	Negative
1	B	Gym Storage #1 (adjacent to Women's Restroom)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Gym Lobby Entrance	Floor	Concrete	Grey	Chipping	25	0.3	Negative
1	B	Gym Lobby Entrance	W1	Plaster	Blue	Cracking	25	0.7	Positive
1	B	Gym Lobby Entrance	W2	CMU	Blue	Chipping	4	0.1	Negative
1	B	Gym Lobby Entrance	W3	CMU	Blue	Cracking	5	0.1	Negative
1	B	Gym Lobby Entrance	W4	CMU	Blue	None	0	0	Negative
1	B	Gym Lobby Entrance	Ceiling	Metal	White	Flaking	100	3	Positive
1	B	Gym Storage #2 (adjacent to Men's Restroom)	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Gym Storage #2 (adjacent to Men's Restroom)	W1	Plaster	White	Chipping	10	50	Positive
1	B	Gym Storage #2 (adjacent to Men's Restroom)	Doorframe/Door	Metal	Grey	Chipping	20	0.3	Negative
1	B	Gym Storage #2 (adjacent to Men's Restroom)	Inner Doorframe	Wood	Tan	Chipping	16	1.4	Positive
1	B	Gym Storage #2 (adjacent to Men's Restroom)	W2	CMU	White	Cracking	40	0.4	Negative
1	B	Gym Storage #2 (adjacent to Men's Restroom)	W3	Plaster	White	No Access	No Access	No Access	No Access
1	B	Gym Storage #2 (adjacent to Men's Restroom)	W4	Plaster	White	None	0	0	Negative
1	B	Gym Storage #2 (adjacent to Men's Restroom)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Gym - Men's Restroom	Floor	Terracotta	N/A	N/A	N/A	N/A	N/A
1	B	Gym - Men's Restroom	W1	Plaster	White	Flaking	40	0.3	Negative
1	B	Gym - Men's Restroom	Doorframe	Wood	Black	Chipping	2	0.2	Negative
1	B	Gym - Men's Restroom	W2	Plaster	White	Flaking	10	0.4	Negative
1	B	Gym - Men's Restroom	W3	Plaster	White	Flaking	30	0.5	Negative
1	B	Gym - Men's Restroom	Radiator	Metal	Grey	Chipping	1	0.2	Negative
1	B	Gym - Men's Restroom	partition	Metal	Blue	Chipping	12	0.1	Negative
1	B	Gym - Men's Restroom	W4	Plaster	White	Flaking	10	0.1	Negative
1	B	Gym - Men's Restroom	Ceiling	Metal	White	Flaking	33	0.1	Negative
1	B	Cafeteria	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria	W1	CMU	Pink	Chipping	18	0.1	Negative

		Dates: 9/8/2022-9/13/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Charles Rhodes 003542	Bridesburg Annex Elementary School						
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Cafeteria	Doorframe/Door	Metal	Pink	Chipping	7	0.6	Negative
1	B	Cafeteria	W2	CMU	Pink	Chipping	12	0	Negative
1	B	Cafeteria	W3	CMU	Pink	Flaking	41	0	Negative
1	B	Cafeteria	W4	CMU	Pink	Chipping	15	0.1	Negative
1	B	Cafeteria	Pipe	Metal	White	Chipping	2	0.3	Negative
1	B	Cafeteria	Ceiling	Metal	White	Flaking	25	5.3	Positive
1	B	Kitchen	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen	W1	CMU	White	None	0	0	Negative
1	B	Kitchen	Doorframe	Metal	Pink	Chipping	5	0.3	Negative
1	B	Kitchen	W2	CMU	White	None	0	0.2	Negative
1	B	Kitchen	W3	CMU	White	None	0	0	Negative
1	B	Kitchen	W4	CMU	White	None	0	0.1	Negative
1	B	Kitchen	Ceiling	Metal	White	None	0	9.3	Positive
1	B	Kitchen Pantry	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Kitchen Pantry	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Kitchen Pantry	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Kitchen Pantry	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Kitchen Pantry	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Kitchen Pantry	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Restroom in Cafeteria	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom in Cafeteria	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom in Cafeteria	Doorframe	Metal	Pink	None	0	0.1	Negative
1	B	Girl's Restroom in Cafeteria	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom in Cafeteria	partition	Metal	Tan	Chipping	1	0.1	Negative
1	B	Girl's Restroom in Cafeteria	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom in Cafeteria	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom in Cafeteria	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom in Cafeteria	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom in Cafeteria	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom in Cafeteria	Doorframe	Metal	Pink	None	0	0.4	Negative
1	B	Boy's Restroom in Cafeteria	Door	Metal	Pink	None	0	0	Negative
1	B	Boy's Restroom in Cafeteria	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom in Cafeteria	partition	Metal	Tan	None	0	0	Negative
1	B	Boy's Restroom in Cafeteria	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom in Cafeteria	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom in Cafeteria	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A

		Dates: 9/8/2022-9/13/22	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Bridesburg Annex Elementary School</b>							
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B	Kitchen Storage Room 1	Floor	Concrete	Grey	Chipping	15	0.3	Negative	
1	B	Kitchen Storage Room 1	W1	Plaster	White	None	0	0.3	Negative	
1	B	Kitchen Storage Room 1	Door/Doorframe	Metal	Pink	Chipping	10	0.6	Negative	
1	B	Kitchen Storage Room 1	W2	Plaster	White	None	0	0.1	Negative	
1	B	Kitchen Storage Room 1	W3	Plaster	White	Chipping	3	0.4	Negative	
1	B	Kitchen Storage Room 1	Shelf	Wood	White	None	0	0.1	Negative	
1	B	Kitchen Storage Room 1	W4	Plaster	White	None	0	0	Negative	
1	B	Kitchen Storage Room 1	Ceiling	Metal	White	None	0	3.6	Positive	
1	B	Kitchen Storage Room Hall	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen Storage Room Hall	W1	Plaster	Pink	None	0	0.4	Negative	
1	B	Kitchen Storage Room Hall	Conduit	Metal	Tan	Chipping	3	0.2	Negative	
1	B	Kitchen Storage Room Hall	W2	Plaster	Pink	Chipping	13	0.4	Negative	
1	B	Kitchen Storage Room Hall	Pipe Insulation	Fiberglass	pink	None	0	0.2	Negative	
1	B	Kitchen Storage Room Hall	pipe	Metal	pink	None	0	0.3	Negative	
1	B	Kitchen Storage Room Hall	W3	CMU	Pink	None	0	0.3	Negative	
1	B	Kitchen Storage Room Hall	W4	Plaster	Pink	Chipping	8	0.2	Negative	
1	B	Kitchen Storage Room Hall	Ceiling	Metal	White	None	0	7.4	Positive	
1	B	Boy's Bathroom 1st Floor	Floor	Tile	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Bathroom 1st Floor	W1	Plaster	White	Flaking	6	0.2	Negative	
1	B	Boy's Bathroom 1st Floor	Doorframe/Door	Metal	Blue	Chipping	10	0.2	Negative	
1	B	Boy's Bathroom 1st Floor	W2	Plaster	White	Flaking	2	0.4	Negative	
1	B	Boy's Bathroom 1st Floor	W3	Plaster	White	Flaking	6	0.4	Negative	
1	B	Boy's Bathroom 1st Floor	Partition	Metal	Blue	Chipping	43	0.1	Negative	
1	B	Boy's Bathroom 1st Floor	W4	Plaster	White	Efflorescence	14	0.2	Negative	
1	B	Boy's Bathroom 1st Floor	Radiator	Metal	White	Flaking	15	0.1	Negative	
1	B	Boy's Bathroom 1st Floor	Pipe	Metal	White	None	0	1.4	Positive	
1	B	Boy's Bathroom 1st Floor	Ceiling	Metal	White	Flaking	48	0.4	Negative	
1	B	Girl's Restroom 1st Floor	Floor	Tile	N/A	N/A	N/A	N/A	N/A	
1	B	Girl's Restroom 1st Floor	W1	Plaster	White	Cracking	6	0.2	Negative	
1	B	Girl's Restroom 1st Floor	Doorframe/Door	Metal	Blue	Chipping	15	0.1	Negative	
1	B	Girl's Restroom 1st Floor	W2	Plaster	White	Moisture Damage	5	0.6	Negative	
1	B	Girl's Restroom 1st Floor	W3	Plaster	White	Cracking	3	0.2	Negative	
1	B	Girl's Restroom 1st Floor	Partition	Metal	Blue	Chipping	10	0.2	Negative	
1	B	Girl's Restroom 1st Floor	W4	Plaster	White	None	0	0	Negative	
1	B	Girl's Restroom 1st Floor	Radiator	Metal	White	None	0	0.4	Negative	
1	B	Girl's Restroom 1st Floor	Pipe	Metal	White	Flaking	10	0.5	Negative	



		Dates: 9/8/2022-9/13/22	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Bridesburg Annex Elementary School</b>						
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137						
<b>E</b>	<b>F</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	B	Girl's Restroom 1st Floor	Ceiling	Metal	White	Flaking	33	0.3	Negative
1	1	1st Floor Hallway	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	1	1st Floor Hallway	W1	Plaster	White	Chipping	6	0.3	Negative
1	1	1st Floor Hallway	doorframe/door	Metal	Blue	Chipping	8	0.2	Negative
1	1	1st Floor Hallway	W2	Plaster	White	Cracking	14	4.3	Positive
1	1	1st Floor Hallway	W3	Plaster	White	Chipping	5	0	Negative
1	1	1st Floor Hallway	W4	Plaster	White	Chipping	8	5.8	Positive
1	1	1st Floor Hallway	Ceiling	Plaster	White	Chipping	10	0.2	Negative
1	1	Building Engineer's Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W1	Plaster	White	None	0	0.5	Negative
1	1	Building Engineer's Office	Doorframe	Wood	Blue	None	0	0.2	Negative
1	1	Building Engineer's Office	W2	Plaster	White	None	0	0.3	Negative
1	1	Building Engineer's Office	W3	Plaster	White	None	0	5.1	Positive
1	1	Building Engineer's Office	W4	Plaster	White	None	0	0.9	Positive
1	1	Building Engineer's Office	Ceiling	Plaster	White	None	0	6.2	Positive
1	1	Main Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	W1	Plaster	White	None	0	6.4	Positive
1	1	Main Office	Doorframe	Wood	Blue	Chipping	7	0.7	Positive
1	1	Main Office	Conduit	Metal	White	Chipping	3	0.8	Positive
1	1	Main Office	W2	Plaster	White	Cracking	20	7.2	Positive
1	1	Main Office	Chalkboard	Wood	Blue	None	0	1	Positive
1	1	Main Office	W3	Plaster	White	Cracking	3	7.9	Positive
1	1	Main Office	W4	Sheetrock	White	Flaking	4	0.2	Negative
1	1	Main Office	Ceiling	Metal	White	Flaking	11	0.3	Negative
1	1	Principal's Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Principal's Office	W1	Plaster	White	Cracking	5	8.7	Positive
1	1	Principal's Office	Doorframe	Wood	Blue	Chipping	4	0.8	Positive
1	1	Principal's Office	Chalkboard	Wood	Blue	Chipping	4	1.6	Positive
1	1	Principal's Office	W2	Sheetrock	White	None	0	0.2	Negative
1	1	Principal's Office	W3	Plaster	White	Chipping	1	0.1	Negative
1	1	Principal's Office	conduit	Metal	White	Chipping	1	0.5	Negative
1	1	Principal's Office	W4	Plaster	White	Cracking	16	6.5	Positive
1	1	Principal's Office	Ceiling	Metal	White	Flaking	20	0.3	Negative
1	1	Classroom 5	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 5	W1	Plaster	Pink	Cracking	2	8.2	Positive
1	1	Classroom 5	Doorframe	Wood	Blue	Chipping	10	0.4	Negative

		Dates: 9/8/2022-9/13/22	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Bridesburg Annex Elementary School</b>							
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 5	Chalkboard	Wood	Blue	Chipping	12	1.3	Positive	
1	1	Classroom 5	W2	Plaster	Pink	Cracking	16	12.7	Positive	
1	1	Classroom 5	Conduit	Metal	Pink	None	0	0.6	Negative	
1	1	Classroom 5	W3	Plaster	Pink	Cracking	31	7.3	Positive	
1	1	Classroom 5	Radiator	Metal	Grey	None	0	0.1	Negative	
1	1	Classroom 5	W4	Plaster	Pink	Cracking	13	7.4	Positive	
1	1	Classroom 5	Ceiling	Metal	White	Moisture Damage	10	0.5	Negative	
1	1	Classroom 5 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 5 Closet	W1	Plaster	White	Cracking	6	5.6	Positive	
1	1	Classroom 5 Closet	Doorframe	Wood	Blue	Chipping	5	0.4	Negative	
1	1	Classroom 5 Closet	door	Wood	Blue	Cracking	5	0.6	Negative	
1	1	Classroom 5 Closet	pipe	Metal	Blue	None	0	0.2	Negative	
1	1	Classroom 5 Closet	W2	Plaster	White	Cracking	3	0	Negative	
1	1	Classroom 5 Closet	W3	Plaster	White	None	0	8.6	Positive	
1	1	Classroom 5 Closet	W4	Plaster	White	None	0	8.2	Positive	
1	1	Classroom 5 Closet	Ceiling	Plaster	White	Moisture Damage	4	0.5	Negative	
1	1	Classroom 3	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 3	W1	Plaster	Blue	Cracking	2	4.8	Positive	
1	1	Classroom 3	Doorframe	Wood	Blue	Chipping	8	0.6	Negative	
1	1	Classroom 3	chalkboard	Wood	Blue	Chipping	3	1.4	Positive	
1	1	Classroom 3	W2	Plaster	Blue	Cracking	12	7.9	Positive	
1	1	Classroom 3	Conduit	Metal	Blue	None	0	0.5	Negative	
1	1	Classroom 3	W3	Plaster	Blue	Cracking	8	5.7	Positive	
1	1	Classroom 3	Radiator	Metal	Grey	None	0	0.3	Negative	
1	1	Classroom 3	W4	Plaster	Blue	Cracking	1	5.2	Positive	
1	1	Classroom 3	Ceiling	Metal	White	None	0	0.6	Negative	
1	1	Classroom 3 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 3 Closet	W1	Plaster	White	Cracking	5	6.3	Positive	
1	1	Classroom 3 Closet	Doorframe	Wood	Blue	Cracking	5	0.5	Negative	
1	1	Classroom 3 Closet	Door	Wood	Blue	Cracking	5	0.4	Negative	
1	1	Classroom 3 Closet	Pipe	Metal	White	None	0	0.2	Negative	
1	1	Classroom 3 Closet	W2	Plaster	White	Cracking	2	0.2	Negative	
1	1	Classroom 3 Closet	W3	Plaster	White	Cracking	16	5.7	Positive	
1	1	Classroom 3 Closet	W4	Plaster	White	Cracking	4	7	Positive	
1	1	Classroom 3 Closet	Ceiling	Plaster	White	Cracking	9	0.5	Negative	
1	1	Classroom 6	Floor	Wood	N/A	N/A	N/A	N/A	N/A	

		Dates: 9/8/2022-9/13/22	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Bridesburg Annex Elementary School</b>							
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 6	W1	Plaster	Green	Cracking	5	8.3	Positive	
1	1	Classroom 6	Doorframe	Wood	Blue	Chipping	14	0.4	Negative	
1	1	Classroom 6	chalkboard	Wood	Blue	Chipping	10	1.4	Positive	
1	1	Classroom 6	Conduit	Metal	Green	Chipping	1	0.6	Negative	
1	1	Classroom 6	W2	Plaster	Green	Cracking	29	10.8	Positive	
1	1	Classroom 6	W3	Plaster	Green	Cracking	28	0.1	Negative	
1	1	Classroom 6	radiator	Metal	Grey	Chipping	2	0.3	Negative	
1	1	Classroom 6	W4	Plaster	Green	Cracking	12	6.5	Positive	
1	1	Classroom 6	Ceiling	Metal	White	Flaking	8	0.3	Negative	
1	1	Classroom 6 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 6 Closet	W1	Plaster	White	Cracking	21	6.3	Positive	
1	1	Classroom 6 Closet	Doorframe	Wood	Blue	Chipping	6	0.5	Negative	
1	1	Classroom 6 Closet	Door	Wood	Blue	Cracking	17	0.1	Negative	
1	1	Classroom 6 Closet	pipe	Metal	Blue	Chipping	2	0.2	Negative	
1	1	Classroom 6 Closet	W2	Plaster	White	Cracking	1	0.3	Negative	
1	1	Classroom 6 Closet	W3	Plaster	White	Cracking	18	6.9	Positive	
1	1	Classroom 6 Closet	W4	Plaster	White	Cracking	4	8.6	Positive	
1	1	Classroom 6 Closet	Ceiling	Plaster	White	Cracking	8	0.5	Negative	
1	1	Room 2 - Teacher's Lounge	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Room 2 - Teacher's Lounge	W1	Plaster	White	Cracking	3	7.1	Positive	
1	1	Room 2 - Teacher's Lounge	Doorframe	Wood	Blue	Chipping	15	0.4	Negative	
1	1	Room 2 - Teacher's Lounge	chalkboard	Wood	Blue	Chipping	12	1.7	Positive	
1	1	Room 2 - Teacher's Lounge	Conduit	Metal	White	Chipping	3	1.1	Positive	
1	1	Room 2 - Teacher's Lounge	W2	Plaster	White	Cracking	10	1.2	Positive	
1	1	Room 2 - Teacher's Lounge	W3	Plaster	White	None	0	7.3	Positive	
1	1	Room 2 - Teacher's Lounge	Radiator	Metal	Grey	None	0	0.2	Negative	
1	1	Room 2 - Teacher's Lounge	W4	Plaster	White	Cracking	12	6.1	Positive	
1	1	Room 2 - Teacher's Lounge	Ceiling	Metal	White	Flaking	9	0.2	Negative	
1	1	Room 2 - Teacher's Lounge Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Room 2 - Teacher's Lounge Closet	W1	Plaster	White	Cracking	1	7.1	Positive	
1	1	Room 2 - Teacher's Lounge Closet	Doorframe	Wood	Blue	Cracking	5	0.4	Negative	
1	1	Room 2 - Teacher's Lounge Closet	Pipe	Metal	Blue	Chipping	2	0.2	Negative	
1	1	Room 2 - Teacher's Lounge Closet	W2	Plaster	White	None	0	0.1	Negative	
1	1	Room 2 - Teacher's Lounge Closet	W3	Plaster	White	Cracking	10	6.2	Positive	
1	1	Room 2 - Teacher's Lounge Closet	W4	Plaster	White	Cracking	4	6.8	Positive	
1	1	Room 2 - Teacher's Lounge Closet	Ceiling	Plaster	White	Cracking	3	0.5	Negative	

		Dates: 9/8/2022-9/13/22	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Bridesburg Annex Elementary School</b>							
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 1	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 1	W1	Plaster	Blue	Cracking	8	6.2	Positive	
1	1	Classroom 1	Doorframe	Wood	Blue	Chipping	13	0.5	Negative	
1	1	Classroom 1	Chalkboard	Wood	Blue	Chipping	21	1.4	Positive	
1	1	Classroom 1	Conduit	Metal	Blue	Chipping	5	0.5	Negative	
1	1	Classroom 1	W2	Plaster	Blue	Cracking	15	6	Positive	
1	1	Classroom 1	W3	Plaster	Blue	Cracking	8	0.1	Negative	
1	1	Classroom 1	radiator	Metal	Grey	None	0	0.2	Negative	
1	1	Classroom 1	W4	Plaster	Blue	Cracking	13	8.7	Positive	
1	1	Classroom 1	Ceiling	Metal	White	Flaking	16	0.4	Negative	
1	1	Classroom 1 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 1 Closet	W1	Plaster	White	Cracking	11	4.6	Positive	
1	1	Classroom 1 Closet	Doorframe	Wood	Blue	Chipping	11	0.4	Negative	
1	1	Classroom 1 Closet	door	Wood	Blue	Chipping	16	0.1	Negative	
1	1	Classroom 1 Closet	pipe	Metal	Blue	Chipping	3	0.2	Negative	
1	1	Classroom 1 Closet	W2	Plaster	White	None	0	0	Negative	
1	1	Classroom 1 Closet	W3	Plaster	White	Chipping	8	6	Positive	
1	1	Classroom 1 Closet	W4	Plaster	White	None	0	8	Positive	
1	1	Classroom 1 Closet	Ceiling	Plaster	White	Cracking	9	0.5	Negative	
1	1	Classroom 7	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 7	W1	Plaster	Orange	Cracking	2	6.2	Positive	
1	1	Classroom 7	Doorframe	Wood	Blue	Chipping	22	0.5	Negative	
1	1	Classroom 7	chalkboard	Wood	Blue	Chipping	17	1.3	Positive	
1	1	Classroom 7	Conduit	Metal	Blue	Chipping	2	0.3	Negative	
1	1	Classroom 7	W2	Wood	Orange	Chipping	1	4.6	Positive	
1	1	Classroom 7	W3	Wood	Orange	Cracking	4	5.7	Positive	
1	1	Classroom 7	Radiator	Metal	Grey	None	0	0.1	Negative	
1	1	Classroom 7	W4	Plaster	Orange	Cracking	1	6.3	Positive	
1	1	Classroom 7	Ceiling	Metal	White	Flaking	37	0.4	Negative	
1	1	Classroom 7 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 7 Closet	W1	Plaster	White	Cracking	6	5.8	Positive	
1	1	Classroom 7 Closet	Doorframe	Wood	Blue	Chipping	14	0.4	Negative	
1	1	Classroom 7 Closet	door	Wood	Blue	Cracking	20	0.4	Negative	
1	1	Classroom 7 Closet	pipe	Metal	Blue	None	0	0.1	Negative	
1	1	Classroom 7 Closet	W2	Plaster	White	Moisture Damage	10	0.1	Negative	
1	1	Classroom 7 Closet	W3	Plaster	White	Cracking	15	6.1	Positive	

		Dates: 9/8/2022-9/13/22	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Bridesburg Annex Elementary School</b>							
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
		1	1	Classroom 7 Closet	W4	Plaster	White	Cracking	4	6.3
1	1	Classroom 7 Closet	Ceiling	Plaster	White	Cracking	8	0.4	Negative	
1	1	Front (Almond Street) Storage Room	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Front (Almond Street) Storage Room	W1	Plaster	Tan	Cracking	3	0.5	Negative	
1	1	Front (Almond Street) Storage Room	Doorframe	Wood	Blue	Chipping	15	0.4	Negative	
1	1	Front (Almond Street) Storage Room	Baseboard	Wood	Blue	None	0	1	Positive	
1	1	Front (Almond Street) Storage Room	Conduit	Metal	Tan	Flaking	2	0.4	Negative	
1	1	Front (Almond Street) Storage Room	W2	Plaster	Tan	Cracking	5	0.7	Positive	
1	1	Front (Almond Street) Storage Room	Closet Doorframe	Wood	Blue	Chipping	12	0.3	Negative	
1	1	Front (Almond Street) Storage Room	W3	Plaster	Tan	None	0	0.1	Negative	
1	1	Front (Almond Street) Storage Room	Pipe	Metal	Tan	Chipping	3	0.1	Negative	
1	1	Front (Almond Street) Storage Room	W4	Plaster	Tan	Cracking	15	0.7	Positive	
1	1	Front (Almond Street) Storage Room	radiator	Metal	Blue	Chipping	3	0.1	Negative	
1	1	Front (Almond Street) Storage Room	Ceiling	Plaster	White	Moisture Damage	20	0.1	Negative	
1	1	Bathroom inside Front (Almond Street) Storage Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1	1	Bathroom inside Front (Almond Street) Storage Room	W1	Plaster	Tan	None	0	0.1	Negative	
1	1	Bathroom inside Front (Almond Street) Storage Room	Doorframe	Wood	Blue	Chipping	8	0.2	Negative	
1	1	Bathroom inside Front (Almond Street) Storage Room	W2	Plaster	Tan	Cracking	7	0.4	Negative	
1	1	Bathroom inside Front (Almond Street) Storage Room	W3	Plaster	Tan	Cracking	10	0.3	Negative	
1	1	Bathroom inside Front (Almond Street) Storage Room	radiator	Metal	Blue	None	0	0.1	Negative	
1	1	Bathroom inside Front (Almond Street) Storage Room	W4	Plaster	Tan	Flaking	6	0.8	Positive	
1	1	Bathroom inside Front (Almond Street) Storage Room	Ceiling	Plaster	White	Flaking	14	0.3	Negative	
1	1	Stairwell (Almond Street)	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell (Almond Street)	W1	Plaster	White	None	0	4.9	Positive	
1	1	Stairwell (Almond Street)	Stair Post	Wood	Blue	Chipping	3	3.6	Positive	
1	1	Stairwell (Almond Street)	Railing	Wood	Blue	None	0	0.2	Negative	
1	1	Stairwell (Almond Street)	Baluster	Metal	Blue	Chipping	12	3.3	Positive	
1	1	Stairwell (Almond Street)	stringer	Metal	Blue	Chipping	2	1.1	Positive	
1	1	Stairwell (Almond Street)	Riser	Metal	Blue	Chipping	10	2.1	Positive	
1	1	Stairwell (Almond Street)	Fence Door	Metal	Blue	Chipping	5	0.1	Negative	
1	1	Stairwell (Almond Street)	W2	Plaster	White	Cracking	10	4.5	Positive	
1	1	Stairwell (Almond Street)	W3	Plaster	White	Chipping	5	6.1	Positive	
1	1	Stairwell (Almond Street)	Doorframe	Wood	Blue	Flaking	28	0.6	Negative	
1	1	Stairwell (Almond Street)	W4	Plaster	White	Cracking	5	0.3	Negative	
1	1	Stairwell (Almond Street)	Radiator	Metal	Blue	None	0	0.2	Negative	

		Dates: 9/8/2022-9/13/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Charles Rhodes 003542	Bridesburg Annex Elementary School						
		Inspection Company: BATTA	4435 E. Almond Street, Philadelphia, PA 19137						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Stairwell (Almond Street)	Ceiling	Plaster	White	Flaking	8	0.2	Negative
1	1	Stairwell (Rear)	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell (Rear)	W1	Plaster	White	Chipping	10	5.2	Positive
1	1	Stairwell (Rear)	Stair Post	Wood	White	None	0	2.2	Positive
1	1	Stairwell (Rear)	Railing	Wood	Blue	None	0	0.2	Negative
1	1	Stairwell (Rear)	Baluster	Metal	Blue	Chipping	12	2.5	Positive
1	1	Stairwell (Rear)	stringer	Metal	Blue	Chipping	3	4.2	Positive
1	1	Stairwell (Rear)	Stair Pan	Metal	Blue	Chipping	8	2.8	Positive
1	1	Stairwell (Rear)	Riser	Metal	Blue	Chipping	18	3.4	Positive
1	1	Stairwell (Rear)	Doorframe/Door	Metal	Blue	None	0	0.1	Negative
1	1	Stairwell (Rear)	W2	Plaster	White	Chipping	3	1.2	Positive
1	1	Stairwell (Rear)	W3	Plaster	White	Cracking	12	3.1	Positive
1	1	Stairwell (Rear)	Doorframe	Wood	Blue	Chipping	24	0.8	Positive
1	1	Stairwell (Rear)	W4	Plaster	White	Cracking	8	0.3	Negative
1	1	Stairwell (Rear)	Radiator	Metal	Blue	None	0	0.2	Negative
1	1	Stairwell (Rear)	Ceiling	Plaster	White	Cracking	5	0.1	Negative
1	2	Hallway	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	2	Hallway	W1	Plaster	White	Cracking	3	5	Positive
1	2	Hallway	W2	Plaster	White	Cracking	5	5.9	Positive
1	2	Hallway	Conduit	Metal	White	None	0	0.3	Negative
1	2	Hallway	W3	Plaster	White	Cracking	4	3	Positive
1	2	Hallway	W4	Plaster	White	Cracking	5	5	Positive
1	2	Hallway	Ceiling	Metal	White	None	0	0.4	Negative
1	2	Front (Almond Street) Nurse's Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Front (Almond Street) Nurse's Office	W1	Plaster	Tan	Cracking	8	1.7	Positive
1	2	Front (Almond Street) Nurse's Office	Doorframe	Wood	Blue	Chipping	10	0.7	Positive
1	2	Front (Almond Street) Nurse's Office	Conduit	Metal	Tan	Chipping	3	0.5	Negative
1	2	Front (Almond Street) Nurse's Office	baseboard	Wood	Blue	Chipping	5	0.3	Negative
1	2	Front (Almond Street) Nurse's Office	W2	Plaster	Tan	Cracking	5	0.9	Positive
1	2	Front (Almond Street) Nurse's Office	Closet Doorframe	Wood	Blue	Chipping	6	0.8	Positive
1	2	Front (Almond Street) Nurse's Office	Closet Shelf	Wood	Tan	None	0	0.7	Positive
1	2	Front (Almond Street) Nurse's Office	Closet Wall	Plaster	Tan	None	0	1.2	Positive
1	2	Front (Almond Street) Nurse's Office	Closet Ceiling	Plaster	White	None	0	1.7	Positive
1	2	Front (Almond Street) Nurse's Office	W3	Plaster	Tan	Cracking	5	0	Negative
1	2	Front (Almond Street) Nurse's Office	Pipe	Metal	Blue	None	0	0	Negative

		Dates: 9/8/2022-9/13/22	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Charles Rhodes 003542	Bridesburg Annex Elementary School							
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	2	Front (Almond Street) Nurse's Office	W4	Plaster	Tan	Chipping	15	0.1	Negative	
1	2	Front (Almond Street) Nurse's Office	Radiator	Metal	Blue	None	0	0	Negative	
1	2	Front (Almond Street) Nurse's Office	Window Frame	Wood	Tan	None	0	0.4	Negative	
1	2	Front (Almond Street) Nurse's Office	Ceiling	Plaster	White	Cracking	10	1.7	Positive	
1	2	Front Almond Street Restroom In Nurse's Office	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1	2	Front Almond Street Restroom In Nurse's Office	W1	Plaster	Tan	None	0	0.5	Negative	
1	2	Front Almond Street Restroom In Nurse's Office	Doorframe	Wood	Blue	Chipping	10	0.1	Negative	
1	2	Front Almond Street Restroom In Nurse's Office	W2	Plaster	Tan	None	0	0.6	Negative	
1	2	Front Almond Street Restroom In Nurse's Office	W3	Plaster	Tan	Cracking	3	1.8	Positive	
1	2	Front Almond Street Restroom In Nurse's Office	Radiator	Metal	Blue	None	0	0.1	Negative	
1	2	Front Almond Street Restroom In Nurse's Office	W4	Plaster	Tan	Flaking	1	2.4	Positive	
1	2	Front Almond Street Restroom In Nurse's Office	Window Frame	Wood	Tan	None	0	0.1	Negative	
1	2	Front Almond Street Restroom In Nurse's Office	Ceiling	Plaster	White	None	0	1.7	Positive	
1	2	Classroom 8	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 8	W1	Plaster	White	None	0	5.6	Positive	
1	2	Classroom 8	Doorframe	Wood	Blue	Chipping	12	0.3	Negative	
1	2	Classroom 8	Conduit	Metal	Blue	None	0	0.6	Negative	
1	2	Classroom 8	W2	Plaster	White	Cracking	13	8.4	Positive	
1	2	Classroom 8	W3	Plaster	White	Cracking	8	0.3	Negative	
1	2	Classroom 8	Radiator	Metal	Grey	Chipping	5	0	Negative	
1	2	Classroom 8	W4	Plaster	White	Cracking	11	7.3	Positive	
1	2	Classroom 8	Chalkboard	Wood	Blue	Chipping	5	1.2	Positive	
1	2	Classroom 8	Chalkboard Tray	Wood	Blue	Chipping	14	0.3	Negative	
1	2	Classroom 8	Ceiling	Metal	Tan	Flaking	14	0.3	Negative	
1	2	Classroom 8 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 8 Closet	W1	Plaster	White	Cracking	7	6	Positive	
1	2	Classroom 8 Closet	door	Wood	Blue	Cracking	15	0.3	Negative	
1	2	Classroom 8 Closet	Doorframe	Wood	Blue	Flaking	6	0.6	Negative	
1	2	Classroom 8 Closet	W2	Plaster	White	Cracking	5	0	Negative	
1	2	Classroom 8 Closet	W3	Plaster	White	Cracking	18	6.1	Positive	
1	2	Classroom 8 Closet	W4	Plaster	White	Cracking	5	7.4	Positive	
1	2	Classroom 8 Closet	Ceiling	Plaster	White	None	0	0.5	Negative	
1	2	Classroom 8 Closet	Pipe	Metal	Blue	None	0	0.2	Negative	
1	2	Classroom 15	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 15	W1	Plaster	White	None	0	4.6	Positive	

		<b>Dates: 9/8/2022-9/13/22</b>	<b>Lead-Safe Certification Assessment Report</b>							
		<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>	<b>Bridesburg Annex Elementary School</b>							
		<b>Inspection Company: BATA</b>	<b>4435 E. Almond Street, Philadelphia, PA 19137</b>							
<b>E</b>	<b>F</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>	
1	2	Classroom 15	Doorframe	Wood	Blue	Chipping	14	2.9	Positive	
1	2	Classroom 15	chalkboard	Wood	Blue	Chipping	6	0.2	Negative	
1	2	Classroom 15	Conduit	Metal	White	None	0	1.4	Positive	
1	2	Classroom 15	W2	Plaster	White	None	0	6.8	Positive	
1	2	Classroom 15	W3	Plaster	White	Cracking	4	0.2	Negative	
1	2	Classroom 15	Radiator	Metal	Grey	Chipping	8	0.1	Negative	
1	2	Classroom 15	W4	Plaster	White	Cracking	5	3.6	Positive	
1	2	Classroom 15	Ceiling	Metal	White	Chipping	5	0.6	Negative	
1	2	Classroom 15 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 15 Closet	W1	Plaster	White	Cracking	28	5	Positive	
1	2	Classroom 15 Closet	Doorframe	Wood	Blue	Chipping	6	1.8	Positive	
1	2	Classroom 15 Closet	Door	Wood	Blue	Cracking	23	1.5	Positive	
1	2	Classroom 15 Closet	W2	Plaster	White	Cracking	8	0	Negative	
1	2	Classroom 15 Closet	W3	Plaster	White	Cracking	22	5	Positive	
1	2	Classroom 15 Closet	W4	Plaster	White	Cracking	5	7.1	Positive	
1	2	Classroom 15 Closet	Ceiling	Plaster	White	Chipping	10	0.6	Negative	
1	2	Classroom 9	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 9	W1	Plaster	White	None	0	8.6	Positive	
1	2	Classroom 9	Doorframe	Wood	Blue	Chipping	20	0.6	Negative	
1	2	Classroom 9	Conduit	Metal	Blue	None	0	0.8	Positive	
1	2	Classroom 9	W2	Plaster	White	Cracking	19	8.7	Positive	
1	2	Classroom 9	W3	Plaster	White	Cracking	14	0	Negative	
1	2	Classroom 9	radiator	Metal	Grey	Chipping	4	0.2	Negative	
1	2	Classroom 9	W4	Plaster	White	Cracking	9	8.7	Positive	
1	2	Classroom 9	chalkboard	Wood	Blue	Chipping	15	0.5	Negative	
1	2	Classroom 9	Ceiling	Metal	White	Flaking	41	0.3	Negative	
1	2	Classroom 9 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 9 Closet	W1	Plaster	White	Cracking	8	4.5	Positive	
1	2	Classroom 9 Closet	Doorframe	Wood	Blue	Chipping	9	0.6	Negative	
1	2	Classroom 9 Closet	Door	Wood	Blue	Chipping	25	0.4	Negative	
1	2	Classroom 9 Closet	Pipe	Metal	Blue	None	0	0.1	Negative	
1	2	Classroom 9 Closet	W2	Plaster	White	Cracking	10	0	Negative	
1	2	Classroom 9 Closet	W3	Plaster	White	Cracking	13	3	Positive	
1	2	Classroom 9 Closet	W4	Plaster	White	Cracking	3	7	Positive	
1	2	Classroom 9 Closet	Ceiling	Metal	White	Flaking	9	0.3	Negative	
1	2	Classroom 14	Floor	Wood	N/A	N/A	N/A	N/A	N/A	



		Dates: 9/8/2022-9/13/22	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Charles Rhodes 003542	Bridesburg Annex Elementary School						
		Inspection Company: BATA	4435 E. Almond Street, Philadelphia, PA 19137						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 14	W1	Plaster	White	Cracking	4	4	Positive
1	2	Classroom 14	Doorframe	Wood	Blue	Chipping	16	0.8	Positive
1	2	Classroom 14	Conduit	Metal	White	None	0	0.8	Positive
1	2	Classroom 14	Chalkboard	Wood	Blue	Chipping	6	0.1	Negative
1	2	Classroom 14	W2	Plaster	White	Cracking	23	9.4	Positive
1	2	Classroom 14	W3	Plaster	White	Cracking	12	6.5	Positive
1	2	Classroom 14	Radiator	Metal	Grey	Chipping	6	0.2	Negative
1	2	Classroom 14	W4	Plaster	White	Cracking	12	6.8	Positive
1	2	Classroom 14	Ceiling	Metal	White	Flaking	12	0.6	Negative
1	2	Classroom 14 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 14 Closet	W1	Plaster	White	Cracking	11	5.5	Positive
1	2	Classroom 14 Closet	Doorframe	Wood	Blue	Chipping	5	0.6	Negative
1	2	Classroom 14 Closet	door	Wood	Blue	Chipping	18	0.5	Negative
1	2	Classroom 14 Closet	W2	Plaster	White	Cracking	2	0	Negative
1	2	Classroom 14 Closet	Pipe	Metal	Blue	None	0	0.2	Negative
1	2	Classroom 14 Closet	W3	Plaster	White	Cracking	17	7.3	Positive
1	2	Classroom 14 Closet	W4	Plaster	White	None	0	8.6	Positive
1	2	Classroom 14 Closet	Ceiling	Plaster	White	None	0	0.6	Negative
1	2	Classroom 10	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 10	W1	Plaster	White	None	0	10.3	Positive
1	2	Classroom 10	Doorframe	Wood	Blue	Chipping	25	0.6	Negative
1	2	Classroom 10	Conduit	Metal	Blue	None	0	0.6	Negative
1	2	Classroom 10	W2	Plaster	White	Cracking	10	10.5	Positive
1	2	Classroom 10	Chalkboard	Wood	Blue	Chipping	17	0.6	Negative
1	2	Classroom 10	W3	Plaster	White	Cracking	21	6.2	Positive
1	2	Classroom 10	Radiator	Metal	Grey	Chipping	5	0.1	Negative
1	2	Classroom 10	W4	Plaster	White	Cracking	4	12.1	Positive
1	2	Classroom 10	Ceiling	Metal	White	Flaking	26	0.5	Negative
1	2	Classroom 10 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 10 Closet	W1	Plaster	White	Cracking	7	5.4	Positive
1	2	Classroom 10 Closet	Doorframe	Wood	Blue	Chipping	10	0.4	Negative
1	2	Classroom 10 Closet	door	Wood	Blue	Chipping	16	0.4	Negative
1	2	Classroom 10 Closet	pipe	Metal	Blue	None	0	0.1	Negative
1	2	Classroom 10 Closet	W2	Plaster	White	Cracking	4	0	Negative
1	2	Classroom 10 Closet	W3	Plaster	White	Cracking	7	3.8	Positive
1	2	Classroom 10 Closet	W4	Plaster	White	Cracking	6	8.7	Positive

		<b>Dates: 9/8/2022-9/13/22</b>	<b>Lead-Safe Certification Assessment Report</b>							
		<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>	<b>Bridesburg Annex Elementary School</b>							
		<b>Inspection Company: BATTA</b>	<b>4435 E. Almond Street, Philadelphia, PA 19137</b>							
<b>E</b>	<b>F</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>	
1	2	Classroom 10 Closet	Ceiling	Plaster	White	Flaking	5	0.3	Negative	
1	2	Classroom 13	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 13	W1	Plaster	White	None	0	8.8	Positive	
1	2	Classroom 13	Doorframe	Wood	Blue	Chipping	23	0.3	Negative	
1	2	Classroom 13	Conduit	Metal	Blue	None	0	0.4	Negative	
1	2	Classroom 13	chalkboard	Wood	Blue	Chipping	12	0.5	Negative	
1	2	Classroom 13	W2	Plaster	White	Cracking	4	8.4	Positive	
1	2	Classroom 13	W3	Plaster	White	Cracking	9	7.5	Positive	
1	2	Classroom 13	Radiator	Metal	Grey	None	0	0.2	Negative	
1	2	Classroom 13	W4	Plaster	White	Cracking	16	7	Positive	
1	2	Classroom 13	Ceiling	Metal	White	None	0	0.5	Negative	
1	2	Classroom 13 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 13 Closet	W1	Plaster	White	Cracking	18	6.4	Positive	
1	2	Classroom 13 Closet	door	Wood	Blue	Cracking	23	0.2	Negative	
1	2	Classroom 13 Closet	Doorframe	Wood	Blue	Cracking	5	0.6	Negative	
1	2	Classroom 13 Closet	pipe	Metal	Blue	None	0	0.2	Negative	
1	2	Classroom 13 Closet	W2	Plaster	White	None	0	0.3	Negative	
1	2	Classroom 13 Closet	W3	Plaster	White	Cracking	20	6.1	Positive	
1	2	Classroom 13 Closet	W4	Plaster	White	Cracking	8	7.9	Positive	
1	2	Classroom 13 Closet	Ceiling	Metal	White	Cracking	2	0.3	Negative	
1	2	Classroom 11	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 11	W1	Plaster	White	Cracking	13	8.4	Positive	
1	2	Classroom 11	Doorframe	Wood	Blue	Chipping	15	0.6	Negative	
1	2	Classroom 11	Conduit	Metal	Blue	None	0	1.2	Positive	
1	2	Classroom 11	chalkboard	Wood	Blue	None	0	1.7	Positive	
1	2	Classroom 11	W2	Plaster	White	Cracking	24	8	Positive	
1	2	Classroom 11	W3	Plaster	White	Cracking	6	0.2	Negative	
1	2	Classroom 11	radiator	Metal	Grey	Chipping	3	0.3	Negative	
1	2	Classroom 11	W4	Plaster	White	Cracking	8	5.1	Positive	
1	2	Classroom 11	Ceiling	Metal	White	Flaking	2	0.5	Negative	
1	2	Classroom 11 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 11 Closet	W1	Plaster	White	Cracking	7	4.5	Positive	
1	2	Classroom 11 Closet	Doorframe	Wood	Blue	Cracking	7	0.2	Negative	
1	2	Classroom 11 Closet	Door	Wood	Blue	Cracking	12	0.4	Negative	
1	2	Classroom 11 Closet	Pipe	Metal	Blue	None	0	0	Negative	
1	2	Classroom 11 Closet	W2	Plaster	White	Flaking	3	0	Negative	

		<b>Dates: 9/8/2022-9/13/22</b>	<b>Lead-Safe Certification Assessment Report</b>							
		<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>	<b>Bridesburg Annex Elementary School</b>							
		<b>Inspection Company: BATTA</b>	<b>4435 E. Almond Street, Philadelphia, PA 19137</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>	
1	2	Classroom 11 Closet	W3	Plaster	White	Cracking	15	7.5	Positive	
1	2	Classroom 11 Closet	W4	Plaster	White	Cracking	2	10.3	Positive	
1	2	Classroom 11 Closet	Ceiling	Plaster	White	Cracking	3	0.2	Negative	
1	2	Classroom 12	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 12	W1	Plaster	White	None	0	8.1	Positive	
1	2	Classroom 12	Doorframe	Wood	Blue	Chipping	14	0.4	Negative	
1	2	Classroom 12	Conduit	Metal	Blue	None	0	0.6	Negative	
1	2	Classroom 12	chalkboard	Wood	Blue	None	0	2.3	Positive	
1	2	Classroom 12	W2	Plaster	White	Cracking	8	8.5	Positive	
1	2	Classroom 12	W3	Plaster	White	Cracking	7	0.1	Negative	
1	2	Classroom 12	radiator	Metal	Grey	None	0	0	Negative	
1	2	Classroom 12	W4	Plaster	White	Cracking	10	7.5	Positive	
1	2	Classroom 12	Ceiling	Metal	White	Flaking	10	0.3	Negative	
1	2	Classroom 12 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 12 Closet	W1	Plaster	White	Cracking	4	12.1	Positive	
1	2	Classroom 12 Closet	Doorframe	Wood	Blue	Chipping	6	0.3	Negative	
1	2	Classroom 12 Closet	Door	Wood	Blue	Cracking	17	0.3	Negative	
1	2	Classroom 12 Closet	pipe	Metal	Blue	None	0	0.2	Negative	
1	2	Classroom 12 Closet	W2	Plaster	White	Cracking	3	0	Negative	
1	2	Classroom 12 Closet	W3	Plaster	White	Cracking	1	10.8	Positive	
1	2	Classroom 12 Closet	W4	Plaster	White	Cracking	13	12	Positive	
1	2	Classroom 12 Closet	Ceiling	Plaster	White	Cracking	4	0.5	Negative	
1	2	Rear Storage Classroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	Rear Storage Classroom	W1	Plaster	White	Cracking	7	0.9	Positive	
1	2	Rear Storage Classroom	Doorframe	Wood	Tan	Chipping	7	0.6	Negative	
1	2	Rear Storage Classroom	W2	Plaster	White	Cracking	17	2.1	Positive	
1	2	Rear Storage Classroom	W3	Plaster	White	Cracking	12	0.3	Negative	
1	2	Rear Storage Classroom	Radiator	Metal	Grey	None	0	0.1	Negative	
1	2	Rear Storage Classroom	W4	Plaster	White	Cracking	13	0.9	Positive	
1	2	Rear Storage Classroom	Closet Doorframe	Wood	Tan	Cracking	13	0.4	Negative	
1	2	Rear Storage Classroom	Shelf	Wood	Tan	Chipping	4	0.4	Negative	
1	2	Rear Storage Classroom	Ceiling	Plaster	White	Cracking	20	0.5	Negative	
1	2	Almond Street Stairwell	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1	2	Almond Street Stairwell	W1	Plaster	tan	Cracking	5	3.1	Positive	
1	2	Almond Street Stairwell	Chair Rail	Wood	Blue	None	0	0.6	Negative	

		<b>Dates: 9/8/2022-9/13/22</b>	<b>Lead-Safe Certification Assessment Report</b>						
		<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>	<b>Bridesburg Annex Elementary School</b>						
		<b>Inspection Company: BATTA</b>	<b>4435 E. Almond Street, Philadelphia, PA 19137</b>						
<b>E</b>	<b>F</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Almond Street Stairwell	W2	Plaster	Tan	Cracking	6	6	Positive
1	2	Almond Street Stairwell	Conduit	Metal	White	None	0	0.6	Negative
1	2	Almond Street Stairwell	W3	Plaster	Tan	Cracking	25	3.9	Positive
1	2	Almond Street Stairwell	Window Frame	Wood	White	Chipping	4	0.3	Negative
1	2	Almond Street Stairwell	radiator	Metal	Blue	None	0	0.2	Negative
1	2	Almond Street Stairwell	W4	Plaster	Tan	Cracking	6	3.9	Positive
1	2	Almond Street Stairwell	Stair Post	Metal	Blue	Chipping	4	5.2	Positive
1	2	Almond Street Stairwell	Railing	Wood	Blue	Chipping	7	0.2	Negative
1	2	Almond Street Stairwell	Baluster	Metal	Blue	Chipping	7	2.1	Positive
1	2	Almond Street Stairwell	stringer	Metal	Blue	Chipping	3	0.5	Negative
1	2	Almond Street Stairwell	Riser	Metal	Blue	Chipping	3	0.5	Negative
1	2	Almond Street Stairwell	Ceiling	Metal	White	Moisture Damage	24	0.4	Negative
1	2	Rear Stairwell	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	2	Rear Stairwell	W1	Plaster	White	Chipping	2	6.2	Positive
1	2	Rear Stairwell	W2	Plaster	White	Cracking	20	5.2	Positive
1	2	Rear Stairwell	Stair Post	Metal	Blue	None	0	2.8	Positive
1	2	Rear Stairwell	Railing	Wood	Blue	None	0	0.5	Negative
1	2	Rear Stairwell	Baluster	Metal	Blue	None	0	2.8	Positive
1	2	Rear Stairwell	stringer	Metal	Blue	None	0	0.1	Negative
1	2	Rear Stairwell	Riser	Metal	Blue	None	0	2.7	Positive
1	2	Rear Stairwell	W3	Plaster	White	Cracking	36	6.4	Positive
1	2	Rear Stairwell	Radiator	Metal	Blue	None	0	0.1	Negative
1	2	Rear Stairwell	W4	Plaster	White	Flaking	4	4.7	Positive
1	2	Rear Stairwell	Ceiling	Metal	White	Flaking	3	0.5	Negative
1	A	Attic	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	A	Attic	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	A	Attic	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	A	Attic	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	A	Attic	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	A	Attic	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

		<b>Dates: 9/8/2022-9/13/22</b>	<b>Lead-Safe Certification Assessment Report</b>						
		<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>	<b>Bridesburg Annex Elementary School</b>						
		<b>Inspection Company: BATA</b>	<b>4435 E. Almond Street, Philadelphia, PA 19137</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/ negative)</b>
1	C	Crawl Space	Floor	No Access	No Access	No Access	No Access	No Access	No Access