



September 23, 2022

Mr. Stephen Link
Office of Environmental
School District of Philadelphia
440 North Broad Street
Philadelphia, Pa 19130-4015

BEA#: 543522BA
OEP#: EP2023-0018-2009

**RE: Lead Safe Assessment
South Philadelphia High School – Field House
1000 Bigler Street., Philadelphia, PA 19148**

Dear Mr. Link,

The purpose of this lead safe inspection was to determine the existence and condition of lead-based paint at the South Philadelphia High School – Field House using an x-ray fluorescence (XRF) analyzer. Lead-Based Paint (LBP) is defined by The City of Philadelphia Department of Health to contain equal or greater than 0.70 mg/cm² lead via XRF. LBP is defined by the Federal Department of Housing and Urban Development (HUD) and Environmental Protection Agency (EPA) to contain equal or greater than 1.00 mg/cm² lead via XRF.

The inspection of the subject property was performed by Charles Rhodes of Batta Environmental Associates, Inc., a Pennsylvania licensed lead-inspector.

From August 25th – 26th, 2022, BATTAs completed Lead-Based Paint (LBP) XRF Inspection at the following property:

- **South Philadelphia High School – Field House – 1000 Bigler Street., Philadelphia, PA**

Results

Results of the XRF readings can be found attached to this letter. The survey and testing were performed to locate any damaged Lead-Based Paint (LBP) that may be present throughout the interior of the building prior to planned stabilization. At the time of the assessment from 8/25 – 8/26/2022, **no damaged LBP was identified in student or teacher occupied areas.**



Batta Environmental Associates, Inc. is pleased to provide the School District of Philadelphia with our professional environmental services. If you should have any questions about regarding the information or data provided in this correspondence, please contact our office at (302)-737-3376.

Sincerely,

A handwritten signature in dark purple ink, appearing to read "Alyssa M. Cartagena".

Alyssa M. Cartagena

Project Manager

BATTA Environmental Associates, Inc.

Consulting | Laboratories | Products | Training

(O) 302.737.3376 | (C) 267.467.2774 | alyssa.cartagena@battaenv.com





Philadelphia Department of Public Health Certification of School Lead Safe Status

By signing this certificate, I confirm that I have done a visual inspection of the areas where children have access, including contact surfaces where children store their equipment or materials, and confirm these areas do not have deteriorated lead-based paint. A certified risk assessor or lead dust sampling technician completed verification wipe tests in accordance with the EPA's RRP guidelines and confirms they meet the EPA's cleanliness standard. A certified risk assessor or lead dust sampling technician collected interior dust wipe samples in compliance with EPA regulations in work areas and confirms they did not contain lead contaminated dust in excess of EPA dust lead standards in Pre-K, Kindergarten, and 1st Grade classrooms as well as the restrooms, offices, cafeterias, gymnasiums, and auditoriums these children routinely occupy. This certificate is valid for 4 years from date of verification.

South Philadelphia High School Field House

1000 Bigler Street., Philadelphia, PA 19148

School Name

Street Address

Batta Environmental Associates, Inc.

003542

Certifying Company (print)

Risk Assessor, Lead Inspector PA Lic. #, EPA Firm Certification or Lead Dust Sampling Technician Certification #

Charles Rhodes

8/26/2022

Inspector/Risk Assessor or Dust Wipe Sampling Technician Name (Signature)

Date of Verification

Stephen Link - 215.400.5768 - slink@philasd.org

School Official Name, Telephone and E-mail Address

Please note: A visual inspection of the areas listed above has been completed by a certified risk assessor and no damage to Lead Based Painted surfaces was observed. Therefore, no verification wipe samples were completed. This school will be reassessed within 4 years of this certification.

				Dates: 8/25/2022 - 8/26/2022 Inspector Name and Certificate Number: Charles Rhodes 003542 Inspection Company: BATA							Lead-Safe Certification Assessment Report South Philadelphia HS Field House 1000 Bigler Street, Philadelphia, PA 19148						
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Floor	Concrete	Green	Friction	200	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	W1	CMU	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Doorframe	Metal	Green	Flaking	6	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Door	Metal	Grey	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	W2	CMU	White	Cracking	5	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	W3	CMU	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Pipe Cover	Metal	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Pipe Insulation	Fiberglass	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	W4	CMU	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Divider	Metal	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Bench	Wood	Grey	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Room (JV Football)	Ceiling	Concrete	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	Floor	Concrete	Green	Chipping	40	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	W1	CMU	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	Doorframe	Metal	Green	Chipping	1	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	Radiator	Metal	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	Pipe Cover	Metal	White	Chipping	1	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	W2	CMU	White	Cracking	10	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	W3	CMU	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	Partition	Wood	Green	Chipping	3	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	W4	CMU	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	Conduit	Metal	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Locker Restroom (JV Football)	Ceiling	Concrete	White	Cracking	10	Negative							
2009	1	B200901-1	1	Boy's Visitor Shower (JV Football)	Floor	Concrete	Green	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Shower (JV Football)	W1	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Visitor Shower (JV Football)	W2	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Visitor Shower (JV Football)	W3	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Visitor Shower (JV Football)	W4	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Visitor Shower (JV Football)	Ceiling	Concrete	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Restroom (JV Football)	Floor	Concrete	Green	None	0	Negative							
2009	1	B200901-1	1	Boy's Visitor Restroom (JV Football)	W1	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Visitor Restroom (JV Football)	W2	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Visitor Restroom (JV Football)	W3	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Visitor Restroom (JV Football)	W4	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Visitor Restroom (JV Football)	Ceiling	Concrete	White	None	0	Negative							
2009	1	B200901-1	1	Boy's Home Locker (JV Football)	Floor	N/A	N/A	N/A	N/A	N/A							
2009	1	B200901-1	1	Boy's Home Locker (JV Football)	W1	N/A	N/A	N/A	N/A	N/A							

				Lead-Safe Certification Assessment Report						
				South Philadelphia HS Field House						
				1000 Bigler Street, Philadelphia, PA 19148						
				Inspector Name and Certificate Number: Charles Rhodes 003542						
				Inspection Company: BATA						
				Dates: 8/25/2022 - 8/26/2022						
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2009	1	B200901-1	1	Boy's Home Locker (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker (JV Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	Floor	Concrete	Green	Chipping	40	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	W1	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	Doorframe	Metal	Green	Chipping	1	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	Radiator	Metal	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	Pipe Cover	Metal	White	Chipping	1	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	W2	CMU	White	Cracking	10	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	W3	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	Partition	Wood	Green	Chipping	3	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	W4	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	Conduit	Metal	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Restroom (JV Football)	Ceiling	Concrete	White	Cracking	10	Negative
2009	1	B200901-1	1	Boy's Home Locker Showers (JV Football)	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker Showers (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker Showers (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker Showers (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker Showers (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker Showers (JV Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	Floor	Concrete	Green	Chipping	40	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	W1	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	Doorframe	Metal	Green	Chipping	1	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	Radiator	Metal	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	Pipe Cover	Metal	White	Chipping	1	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	W2	CMU	White	Cracking	10	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	W3	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	Partition	Wood	Green	Chipping	3	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	W4	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	Conduit	Metal	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker Restroom (JV Football)	Ceiling	Concrete	White	Cracking	10	Negative
2009	1	B200901-1	1	Visitor's Coach's Office (JV Football)	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office (JV Football)	W4	N/A	N/A	N/A	N/A	N/A

				Lead-Safe Certification Assessment Report						
				South Philadelphia HS Field House						
				1000 Bigler Street, Philadelphia, PA 19148						
				Dates: 8/25/2022 - 8/26/2022 Inspector Name and Certificate Number: Charles Rhodes 003542 Inspection Company: BATA						
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2009	1	B200901-1	1	Visitor's Coach's Office (JV Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office Storage (JV Football)	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office Storage (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office Storage (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office Storage (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office Storage (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Office Storage (JV Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	Floor	Concrete	Green	Chipping	40	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	W1	CMU	White	None	0	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	Doorframe	Metal	Green	Chipping	1	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	Radiator	Metal	White	None	0	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	Pipe Cover	Metal	White	Chipping	1	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	W2	CMU	White	Cracking	10	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	W3	CMU	White	None	0	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	Partition	Wood	Green	Chipping	3	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	W4	CMU	White	None	0	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	Conduit	Metal	White	None	0	Negative
2009	1	B200901-1	1	Visitor's Coach's Restroom (JV Football)	Ceiling	Concrete	White	Cracking	10	Negative
2009	1	B200901-1	1	Varsity Coach's Office (Varsity Football)	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office (Varsity Football)	W1	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office (Varsity Football)	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office (Varsity Football)	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office (Varsity Football)	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office (Varsity Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office Storage	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office Storage	W1	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office Storage	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office Storage	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office Storage	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Varsity Coach's Office Storage	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor Locker Room (Varsity Football)	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor Locker Room (Varsity Football)	W1	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor Locker Room (Varsity Football)	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor Locker Room (Varsity Football)	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor Locker Room (Varsity Football)	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Visitor Locker Room (Varsity Football)	Floor	Concrete	Green	Chipping	40	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	W1	CMU	White	None	0	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	Doorframe	Metal	Green	Chipping	1	Negative

				Lead-Safe Certification Assessment Report						
				South Philadelphia HS Field House						
				1000 Bigler Street, Philadelphia, PA 19148						
				1000 Bigler Street, Philadelphia, PA 19148						
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	Baseboard	CMU/Tile	Green	None	0	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	Radiator	Metal	White	None	0	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	Pipe Cover	Metal	White	Chipping	1	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	W2	CMU	White	Cracking	10	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	W3	CMU	White	None	0	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	Partition	Wood	Green	Chipping	3	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	W4	CMU	White	None	0	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	Conduit	Metal	White	None	0	Negative
2009	1	B200901-1	1	Visitor Locker Restroom (Varsity Football)	Ceiling	Concrete	White	Cracking	10	Negative
2009	1	B200901-1	1	Boy's Visitor Showers (Varsity Football)	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Visitor Showers (Varsity Football)	W1	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Visitor Showers (Varsity Football)	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Visitor Showers (Varsity Football)	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Visitor Showers (Varsity Football)	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Visitor Showers (Varsity Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Floor	Concrete	Green	Friction	200	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	W1	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Doorframe	Metal	Green	Flaking	6	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Door	Metal	Grey	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	W2	CMU	White	Cracking	5	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Baseboard	CMU/Tile	Green	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	W3	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Pipe Cover	Metal	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Pipe Insulation	Fiberglass	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	W4	CMU	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Bench	Wood	Grey	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Ceiling	Concrete	White	None	0	Negative
2009	1	B200901-1	1	Boy's Home Locker (Varsity Football)	Divider	Metal	White	None	0	Negative
2009	1	B200901-1	1	Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boiler Room	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boiler Room	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boiler Room	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Garage - Field Attendant's Storage for Lawn Equipment	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Garage - Field Attendant's Storage for Lawn Equipment	W1	N/A	N/A	N/A	N/A	N/A

				Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
				Inspection Company: BATA	1000 Bigler Street, Philadelphia, PA 19148					
ULCS#	Element	BldgElmt ID	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
2009	1	B200901-1	1	Garage - Field Attendant's Storage for Lawn Equipment	W2	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Garage - Field Attendant's Storage for Lawn Equipment	W3	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Garage - Field Attendant's Storage for Lawn Equipment	W4	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Garage - Field Attendant's Storage for Lawn Equipment	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	1	Building Engineer's Office	W1	CMU	White	None	0	Negative
2009	1	B200901-1	1	Building Engineer's Office	Conduit	Metal	White	None	0	Negative
2009	1	B200901-1	1	Building Engineer's Office	W2	CMU	White	None	0	Negative
2009	1	B200901-1	1	Building Engineer's Office	Post	Wood	Grey	None	0	Negative
2009	1	B200901-1	1	Building Engineer's Office	W3	CMU	White	None	0	Negative
2009	1	B200901-1	1	Building Engineer's Office	W4	CMU	White	None	0	Negative
2009	1	B200901-1	1	Building Engineer's Office	Ceiling	Concrete	White	None	0	Negative
2009	1	B200901-1	2	Conference Room	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	2	Conference Room	W1	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Conference Room	W2	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Conference Room	W3	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Conference Room	W4	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Conference Room	Ceiling	Concrete	White	None	0	Negative
2009	1	B200901-1	2	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	2	Kitchen	W1	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Kitchen	W2	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Kitchen	W3	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Kitchen	W4	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Kitchen	Ceiling	Concrete	White	None	0	Negative
2009	1	B200901-1	2	Office 202	Floor	No Access	No Access	No Access	No Access	No Access
2009	1	B200901-1	2	Office 202	W1	No Access	No Access	No Access	No Access	No Access
2009	1	B200901-1	2	Office 202	W2	No Access	No Access	No Access	No Access	No Access
2009	1	B200901-1	2	Office 202	W3	No Access	No Access	No Access	No Access	No Access
2009	1	B200901-1	2	Office 202	W4	No Access	No Access	No Access	No Access	No Access
2009	1	B200901-1	2	Office 202	Ceiling	No Access	No Access	No Access	No Access	No Access
2009	1	B200901-1	2	Restroom	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	2	Restroom	W1	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Restroom	W2	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Restroom	W3	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Restroom	W4	Plaster	White	None	0	Negative

				Lead-Safe Certification Assessment Report						
				South Philadelphia HS Field House						
				1000 Bigler Street, Philadelphia, PA 19148						
				Dates: 8/25/2022 - 8/26/2022						
				Inspector Name and Certificate Number: Charles Rhodes 003542						
				Inspection Company: BATA						
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2009	1	B200901-1	2	Restroom	Ceiling	Concrete	White	None	0	Negative
2009	1	B200901-1	2	2nd Floor Hallway	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	2	2nd Floor Hallway	W1	Plaster	White	None	0	Negative
2009	1	B200901-1	2	2nd Floor Hallway	W2	Plaster	White	None	0	Negative
2009	1	B200901-1	2	2nd Floor Hallway	W3	Plaster	White	None	0	Negative
2009	1	B200901-1	2	2nd Floor Hallway	W4	Plaster	White	None	0	Negative
2009	1	B200901-1	2	2nd Floor Hallway	Ceiling	Concrete	White	None	0	Negative
2009	1	B200901-1	2	Conference Room 203	Floor	N/A	N/A	N/A	N/A	N/A
2009	1	B200901-1	2	Conference Room 203	W1	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Conference Room 203	W2	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Conference Room 203	W3	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Conference Room 203	W4	Plaster	White	None	0	Negative
2009	1	B200901-1	2	Conference Room 203	Ceiling	Concrete	White	None	0	Negative
2009	2	B200902-1	1	Boy's Visitor Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Locker Room (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Locker Room (Soccer)	W1	CMU	White	None	0	Negative
2009	2	B200902-1	1	Boy's Visitor Locker Room (Soccer)	W2	CMU	White	None	0	Negative
2009	2	B200902-1	1	Boy's Visitor Locker Room (Soccer)	W3	CMU	White	None	0	Negative
2009	2	B200902-1	1	Boy's Visitor Locker Room (Soccer)	W4	CMU	White	None	0	Negative
2009	2	B200902-1	1	Boy's Visitor Locker Room (Soccer)	Ceiling	Concrete	White	None	0	Negative
2009	2	B200902-1	1	Boy's Visitor Showers (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Showers (Soccer)	W1	N/A	N/A	N/A	N/A	N/A

				Dates: 8/25/2022 - 8/26/2022		Lead-Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Charles Rhodes 003542		South Philadelphia HS Field House				
				Inspection Company: BATT		1000 Bigler Street, Philadelphia, PA 19148				
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2009	2	B200902-1	1	Boy's Visitor Showers (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Showers (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Showers (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Showers (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Locker Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Locker Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Locker Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Locker Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Locker Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Visitor Locker Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Locker Room (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Locker Room (Soccer)	W1	CMU	White	None	0	Negative
2009	2	B200902-1	1	Girl's Visitor Locker Room (Soccer)	W2	CMU	White	None	0	Negative
2009	2	B200902-1	1	Girl's Visitor Locker Room (Soccer)	W3	CMU	White	None	0	Negative
2009	2	B200902-1	1	Girl's Visitor Locker Room (Soccer)	W4	CMU	White	None	0	Negative
2009	2	B200902-1	1	Girl's Visitor Locker Room (Soccer)	Ceiling	Concrete	White	None	0	Negative
2009	2	B200902-1	1	Girl's Visitor Showers (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Showers (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Showers (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Showers (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Showers (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Showers (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Locker Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Locker Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Locker Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Locker Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Locker Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Visitor Locker Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Locker Room Storage	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Locker Room Storage	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Locker Room Storage	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Locker Room Storage	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Locker Room Storage	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Locker Room Storage	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Coach's Office	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Coach's Office	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Coach's Office	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Coach's Office	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Boy's Coach's Office	W4	N/A	N/A	N/A	N/A	N/A

				Dates: 8/25/2022 - 8/26/2022		Lead-Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Charles Rhodes 003542		South Philadelphia HS Field House				
				Inspection Company: BATA		1000 Bigler Street, Philadelphia, PA 19148				
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2009	2	B200902-1	1	Boy's Coach's Office	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Coach's Restroom	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Coach's Restroom	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Coach's Restroom	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Coach's Restroom	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Coach's Restroom	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Coach's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Locker Room Storage	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Locker Room Storage	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Locker Room Storage	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Locker Room Storage	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Locker Room Storage	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Locker Room Storage	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Coach's Office	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Coach's Office	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Coach's Office	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Coach's Office	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Coach's Office	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Girl's Coach's Office	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Showers Female	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Showers Female	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Showers Female	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Showers Female	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Showers Female	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Home Showers Female	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	W1	N/A	N/A	N/A	N/A	N/A

				Dates: 8/25/2022 - 8/26/2022		Lead-Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Charles Rhodes 003542		South Philadelphia HS Field House				
				Inspection Company: BATTA		1000 Bigler Street, Philadelphia, PA 19148				
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2009	2	B200902-1	1	Visitor's Showers Female	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	Floor	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	W1	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	W2	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	W3	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	W4	N/A	N/A	N/A	N/A	N/A
2009	2	B200902-1	1	Visitor's Showers Female	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom (Home)	Floor	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom (Home)	W1	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom (Home)	W2	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom (Home)	W3	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom (Home)	W4	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom (Home)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom Storage Room	Floor	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom Storage Room	W1	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom Storage Room	W2	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom Storage Room	W3	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom Storage Room	W4	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Women's Restroom Storage Room	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom	Floor	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom	W1	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom	W2	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom	W3	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom	W4	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom Storage Room	Floor	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom Storage Room	W1	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom Storage Room	W2	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom Storage Room	W3	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom Storage Room	W4	N/A	N/A	N/A	N/A	N/A
2009	3	B200905-1	1	Public Men's Restroom Storage Room	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	4	B200906-1	1	Public Women's Restroom (Visitor)	Floor	N/A	N/A	N/A	N/A	N/A
2009	4	B200906-1	1	Public Women's Restroom (Visitor)	W1	N/A	N/A	N/A	N/A	N/A
2009	4	B200906-1	1	Public Women's Restroom (Visitor)	W2	N/A	N/A	N/A	N/A	N/A
2009	4	B200906-1	1	Public Women's Restroom (Visitor)	W3	N/A	N/A	N/A	N/A	N/A
2009	4	B200906-1	1	Public Women's Restroom (Visitor)	W4	N/A	N/A	N/A	N/A	N/A

				Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
				Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2009	4	B200906-1	1	Public Women's Restroom (Visitor)	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	5	B200909-1	1	Ticket Booth	Floor	N/A	N/A	N/A	N/A	N/A
2009	5	B200909-1	1	Ticket Booth	W1	N/A	N/A	N/A	N/A	N/A
2009	5	B200909-1	1	Ticket Booth	W2	N/A	N/A	N/A	N/A	N/A
2009	5	B200909-1	1	Ticket Booth	W3	N/A	N/A	N/A	N/A	N/A
2009	5	B200909-1	1	Ticket Booth	W4	N/A	N/A	N/A	N/A	N/A
2009	5	B200909-1	1	Ticket Booth	Ceiling	N/A	N/A	N/A	N/A	N/A
2009	1	B200909-1	A	Attic	Floor	No Access	No Access	No Access	No Access	No Access
2009	1	B200909-1	A	Attic	W1	No Access	No Access	No Access	No Access	No Access
2009	1	B200909-1	A	Attic	W2	No Access	No Access	No Access	No Access	No Access
2009	1	B200909-1	A	Attic	W3	No Access	No Access	No Access	No Access	No Access
2009	1	B200909-1	A	Attic	W4	No Access	No Access	No Access	No Access	No Access
2009	1	B200909-1	A	Attic	Ceiling	No Access	No Access	No Access	No Access	No Access
2009	1	B200909-1	A	Attic	Floor	No Access	No Access	No Access	No Access	No Access