

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	500	Classroom 500	W1	CMU	White	Cracking	6	0.3	Negative
1	5	500	Classroom 500	Door Frame	Metal	Black	Chipping	8	0.9	Positive
1	5	500	Classroom 500	Baseboard (W1-4)	CMU	Multi	Chipping	18	1.1	Positive
1	5	500	Classroom 500	W2	CMU	White	Cracking	3	0.4	Negative
1	5	500	Classroom 500	W3	CMU	White	Flaking	12	0.2	Negative
1	5	500	Classroom 500	Column w/ Beams	Concrete	White	Flaking	14	0	Negative
1	5	500	Classroom 500	Univent	Metal	Grey	Chipping	15	0.1	Negative
1	5	500	Classroom 500	Conduit (W3/4)	Metal	White	Cracking	5	0.2	Negative
1	5	500	Classroom 500	W4	CMU	White	Cracking	2	0.4	Negative
1	5	500	Classroom 500	Ceiling	Metal	White	Flaking	6	0.3	Negative
1	5	500	Classroom 500	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	500A	Classroom 500 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.5	Negative
1	5	500B	Classroom 500 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	5	501	Classroom 501	W1	CMU	White	Flaking	37	0.2	Negative
1	5	501	Classroom 501	Baseboard (W1-4)	CMU/Tile	Black	Friction	25	2.1	Positive
1	5	501	Classroom 501	Door Frame	Metal	Black	Chipping	8	1.4	Positive
1	5	501	Classroom 501	W2	CMU	White	Flaking	28	0.3	Negative
1	5	501	Classroom 501	W3	CMU	White	Flaking	13	0.2	Negative
1	5	501	Classroom 501	Column w/ Beams	Concrete	White	Flaking	77	0.2	Negative
1	5	501	Classroom 501	Univent	Metal	Grey	Flaking	77	0.2	Negative
1	5	501	Classroom 501	W4	CMU	White	Flaking	34	0.3	Negative
1	5	501	Classroom 501	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	5	501	Classroom 501	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	501A	Classroom 501 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.5	Negative
1	5	501B	Classroom 501 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.6	Negative
1	5	502	Classroom 502	W1	CMU	White/Blue	Flaking	50	0.2	Negative
1	5	502	Classroom 502	Baseboard (W1-4)	CMU/Tile	Black	Friction	37	1.5	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	502	Classroom 502	Door	Wood	Black	Chipping	3	0.1	Negative
1	5	502	Classroom 502	Door Frame	Metal	Black	Chipping	5	0.2	Negative
1	5	502	Classroom 502	W2	CMU	White/Blue	Flaking	10	0.2	Negative
1	5	502	Classroom 502	W3	CMU	White/Blue	Flaking	23	0.3	Negative
1	5	502	Classroom 502	Column	Concrete	White/Blue	Flaking	44	0.2	Negative
1	5	502	Classroom 502	Univent	Metal	Grey	Chipping	38	0.1	Negative
1	5	502	Classroom 502	W4	CMU	White/Blue	Flaking	32	0.3	Negative
1	5	502	Classroom 502	Ceiling	Concrete	White	Flaking	60	0.2	Negative
1	5	502	Classroom 502	Beams (Ceiling and Window)	Concrete	White	Flaking	26	0.1	Negative
1	5	502	Classroom 502	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	502A	Classroom 502 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	5	502B	Classroom 502 - Closet 2	Door (W1)	Wood	Black	Chipping	2	0.2	Negative
1	5	502B	Classroom 502 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.6	Negative
1	5	503	Classroom 503	W1	CMU	Blue/Grey	Flaking	55	0	Negative
1	5	503	Classroom 503	Column	Concrete	Grey	Flaking	14	0.1	Negative
1	5	503	Classroom 503	Baseboard (W1-4)	CMU	Black	Chipping	36	1.5	Positive
1	5	503	Classroom 503	W2	CMU	Blue/Grey	Flaking	18	0.5	Negative
1	5	503	Classroom 503	Pipe	Metal	White	Flaking	10	0.3	Negative
1	5	503	Classroom 503	Column w/ Beam	Concrete	White	Flaking	2	0.2	Negative
1	5	503	Classroom 503	Univent/Radiator (W2/3)	Metal	Grey	Chipping	22	0.2	Negative
1	5	503	Classroom 503	W3	CMU	Blue/Grey	Flaking	6	0.5	Negative
1	5	503	Classroom 503	Column w/ Beam	Concrete	White	Flaking	3	0.2	Negative
1	5	503	Classroom 503	Conduit	Metal	White	Chipping	1	0.1	Negative
1	5	503	Classroom 503	W4	CMU	Blue/Grey	Flaking	7	0	Negative
1	5	503	Classroom 503	Ceiling	Concrete	White	Flaking	2	0.3	Negative
1	5	503	Classroom 503	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	503A	Classroom 503 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.9	Positive
1	5	503A	Classroom 503 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.4	Negative
1	5	503B	Classroom 503 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.8	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	W2	CMU	White	Chipping	12	0	Negative
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	Vent	Metal	White	None	0	0.2	Negative
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	Electrical Panel	Metal	Black	Chipping	3	0.1	Negative
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	W4	CMU	White	Chipping	8	0	Negative
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	Baseboard	CMU/Tile	Black	None	0	1.6	Positive
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	Pipe	Metal	White	Chipping	5	0	Negative
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	Univent	Metal	White	Chipping	2	0.1	Negative
1	5	H53	Hallway from Classroom 500 to Storeroom 503A	Ceiling Beam	Concrete	White	Chipping	4	0.4	Negative
1	5	503A	Storeroom 503A	W1	CMU	White	None	0	0.1	Negative
1	5	503A	Storeroom 503A	Door Frame	Metal	Black	None	0	0.7	Positive
1	5	503A	Storeroom 503A	Baseboard (W1-4)	CMU/Tile	Black	Friction	12	1.1	Positive
1	5	503A	Storeroom 503A	W2	CMU	White	Chipping	1	0.5	Negative
1	5	503A	Storeroom 503A	Column (W2/3)	Concrete	White	Flaking	10	0.2	Negative
1	5	503A	Storeroom 503A	Univent/Radiator	Metal	White	Flaking	8	0.1	Negative
1	5	503A	Storeroom 503A	Pipe	Metal	White	Chipping	1	0	Negative
1	5	503A	Storeroom 503A	W3	CMU	White	Cracking	4	0.4	Negative
1	5	503A	Storeroom 503A	Pipe	Metal	Grey	Efflorescence	3	0.7	Positive
1	5	503A	Storeroom 503A	W4	CMU	White	Cracking	2	0.3	Negative
1	5	503A	Storeroom 503A	Ceiling	Concrete	White	None	0	0.2	Negative
1	5	503A	Storeroom 503A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	503B	Storeroom 503B	W1	CMU	White	Flaking	2	0	Negative
1	5	503B	Storeroom 503B	Door Frame	Metal	Black	Chipping	6	0.5	Negative
1	5	503B	Storeroom 503B	Baseboard (W1-4)	CMU/Tile	Black	Chipping	5	0.9	Positive
1	5	503B	Storeroom 503B	W2	CMU	White	Chipping	2	0	Negative
1	5	503B	Storeroom 503B	Column (W2/3)	Concrete	White	Flaking	5	0.1	Negative
1	5	503B	Storeroom 503B	W3	CMU	Red	Chipping	4	0.4	Negative
1	5	503B	Storeroom 503B	Univent	Metal	White	Flaking	6	0.2	Negative
1	5	503B	Storeroom 503B	W4	CMU	White	Flaking	5	0.3	Negative
1	5	503B	Storeroom 503B	Ceiling	Concrete	White	Flaking	1	0.3	Negative
1	5	503B	Storeroom 503B	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	504	Classroom 504	W1	CMU	White	Flaking	8	0	Negative
1	5	504	Classroom 504	Door Frame	Metal	Black	None	0	0.4	Negative
1	5	504	Classroom 504	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.6	Positive
1	5	504	Classroom 504	W2	CMU	White	Flaking	2	0.2	Negative
1	5	504	Classroom 504	W3	CMU	White	Flaking	5	0.4	Negative
1	5	504	Classroom 504	Column	Concrete	White	Flaking	10	0.2	Negative
1	5	504	Classroom 504	Univent	Metal	Grey	Chipping	21	0.1	Negative
1	5	504	Classroom 504	W4	CMU	White	Flaking	5	0.4	Negative
1	5	504	Classroom 504	Ceiling	Concrete	White	Flaking	15	0.3	Negative
1	5	504	Classroom 504	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	504A	Classroom 504 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.2	Negative
1	5	504B	Classroom 504 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.3	Negative
1	5	505	Youth Court	W1	CMU	Multi	None	0	0.5	Negative
1	5	505	Youth Court	Door Frame	Metal	Black	Friction	16	0.8	Positive
1	5	505	Youth Court	Baseboard (W1-3)	CMU/Tile	Black	Friction	10	1.4	Positive
1	5	505	Youth Court	W2	CMU	White	None	0	0.6	Negative
1	5	505	Youth Court	W3	CMU	White	None	0	0.5	Negative
1	5	505	Youth Court	Columns	Concrete	White	Chipping	1	0.2	Negative
1	5	505	Youth Court	Beams	Concrete	White	Flaking	1	0.2	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	505	Youth Court	Univent	Metal	Black	Chipping	13	0.1	Negative
1	5	505	Youth Court	W4	Sheetrock	White	None	0	0.1	Negative
1	5	505	Youth Court	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	5	505	Youth Court	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
1	5	505A	Youth Court Closet	W1	Sheetrock	White	None	0	0.1	Negative
1	5	505A	Youth Court Closet	Door Frame	Metal	Black	None	0	0.2	Negative
1	5	505A	Youth Court Closet	W2	CMU	White	None	0	0.6	Negative
1	5	505A	Youth Court Closet	Baseboard (W2-4)	CMU/Tile	Black	None	0	1.7	Positive
1	5	505A	Youth Court Closet	W3	CMU	White	None	0	0.5	Negative
1	5	505A	Youth Court Closet	W4	CMU	White	None	0	0	Negative
1	5	505A	Youth Court Closet	Door Frame	Metal	Black	None	0	0.2	Negative
1	5	505A	Youth Court Closet	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	5	505A	Youth Court Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	506	Classroom 506	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	506	Classroom 506	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	506	Classroom 506	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	506	Classroom 506	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	506	Classroom 506	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	506	Classroom 506	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	506A	Storeroom next to Classroom 506	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	5	506A	Storeroom next to Classroom 506	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	5	506A	Storeroom next to Classroom 506	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	5	506A	Storeroom next to Classroom 506	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	5	506A	Storeroom next to Classroom 506	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S56	Stairwell adjacent to Classroom 507	Floor	Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	S56	Stairwell adjacent to Classroom 507	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S56	Stairwell adjacent to Classroom 507	Doorframe	Metal	Black	Chipping	8	0.3	Negative
1	5	S56	Stairwell adjacent to Classroom 507	Door	Metal	Red	Friction	20	0.1	Negative
1	5	S56	Stairwell adjacent to Classroom 507	W2	CMU	White	None	0	0	Negative
1	5	S56	Stairwell adjacent to Classroom 507	Conduit	Metal	White	Chipping	8	0.1	Negative
1	5	S56	Stairwell adjacent to Classroom 507	Riser	Metal	Tan	Chipping	10	0.1	Negative
1	5	S56	Stairwell adjacent to Classroom 507	Stringer	Metal	Tan	Chipping	8	0.1	Negative
1	5	S56	Stairwell adjacent to Classroom 507	Stair Pan	Metal	Tan	Chipping	5	0.1	Negative
1	5	S56	Stairwell adjacent to Classroom 507	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S56	Stairwell adjacent to Classroom 507	Baseboard	Metal	Tan	Chipping	14	0.1	Negative
1	5	S56	Stairwell adjacent to Classroom 507	W4	CMU	White	None	0	0	Negative
1	5	S56	Stairwell adjacent to Classroom 507	Fire Pipe	Metal	White	None	0	0.3	Negative
1	5	S56	Stairwell adjacent to Classroom 507	Ceiling	Concrete	White	Flaking	33	0.2	Negative
1	5	507	Classroom 507	W1	CMU	Blue	Chipping	8	0.3	Negative
1	5	507	Classroom 507	Door Frame	Metal	Black	Chipping	4	0.6	Negative
1	5	507	Classroom 507	W2	CMU	Blue	Flaking	12	0.3	Negative
1	5	507	Classroom 507	Radiator	Metal	Blue	Chipping	1	0.2	Negative
1	5	507	Classroom 507	Baseboard	CMU/Tile	Black	Friction	10	1.2	Positive
1	5	507	Classroom 507	W3	CMU	Blue	Cracking	13	0.5	Negative
1	5	507	Classroom 507	Beam	Concrete	Blue/White	Flaking	6	0.2	Negative
1	5	507	Classroom 507	Column	Concrete	Blue	Flaking	13	0.1	Negative

			Dates: 7/11 - 8/31/2022		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Charles Rhodes 003542		South Philadelphia High School					
			Inspection Company: BATTA		2101 S Broad St, Philadelphia, PA 19148					
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	507	Classroom 507	Univent	Metal	Grey	Chipping	6	0.1	Negative
1	5	507	Classroom 507	W4	CMU	Blue	Cracking	3	0.5	Negative
1	5	507	Classroom 507	Ceiling	Concrete	White	Flaking	20	0.2	Negative
1	5	507	Classroom 507	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	507A	Classroom 507 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.6	Negative
1	5	507B	Classroom 507 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	5	508	Classroom 508	W1	CMU	White	Flaking	16	0.3	Negative
1	5	508	Classroom 508	Door Frame	Metal	Black	Chipping	8	0.9	Positive
1	5	508	Classroom 508	Baseboard (W1-4)	CMU/Tile	Black	Friction	24	1	Positive
1	5	508	Classroom 508	W2	CMU	White	Flaking	4	0.3	Negative
1	5	508	Classroom 508	W3	CMU	White	Flaking	4	0.5	Negative
1	5	508	Classroom 508	Columns	Concrete	White	Chipping	5	0.2	Negative
1	5	508	Classroom 508	Pipe	Metal	White	Chipping	5	0.4	Negative
1	5	508	Classroom 508	Beam	Concrete	White	Flaking	6	0.2	Negative
1	5	508	Classroom 508	Univent	Metal	Grey	Chipping	10	0.2	Negative
1	5	508	Classroom 508	Conduit (W3/4)	Metal	White	None	0	0.5	Negative
1	5	508	Classroom 508	W4	CMU	White	Flaking	6	0.5	Negative
1	5	508	Classroom 508	Ceiling	Concrete	White	Flaking	10	0.3	Negative
1	5	508	Classroom 508	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	508A	Classroom 508 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	5	508B	Classroom 508 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	5	509	Classroom 509	W1	CMU	White/Grey	Chipping	2	0.5	Negative
1	5	509	Classroom 509	Door Frame	Metal	Black	Chipping	5	0.5	Negative
1	5	509	Classroom 509	Baseboard (W1-4)	CMU/Tile	Black	Friction	6	1.1	Positive
1	5	509	Classroom 509	W2	CMU	White/Grey	Chipping	2	0.4	Negative
1	5	509	Classroom 509	W3	CMU	White/Grey	Chipping	2	0.5	Negative
1	5	509	Classroom 509	Univent	Metal	Grey	Chipping	11	0.1	Negative
1	5	509	Classroom 509	Column/Beam	Concrete	White	Chipping	6	0.1	Negative
1	5	509	Classroom 509	Conduit (W3/4)	Metal	White	None	0	0.5	Negative
1	5	509	Classroom 509	W4	CMU	White/Grey	Chipping	3	0.4	Negative



			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	509	Classroom 509	Ceiling	Concrete	White	Efflorescence	10	0.3	Negative
1	5	509	Classroom 509	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	509A	Classroom 509 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.9	Positive
1	5	509B	Classroom 509 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.6	Negative
1	5	510	Classroom 510	W1	CMU	White	None	0	0.4	Negative
1	5	510	Classroom 510	Baseboard (W1-4)	CMU/Tile	Black	Friction	3	1.1	Positive
1	5	510	Classroom 510	W2	CMU	White	Flaking	1	0.4	Negative
1	5	510	Classroom 510	W3	CMU	White	None	0	0.4	Negative
1	5	510	Classroom 510	Univent	Metal	Beige	Chipping	3	0.2	Negative
1	5	510	Classroom 510	Column	Concrete	Beige	Flaking	2	0.1	Negative
1	5	510	Classroom 510	Beam	Concrete	White	Flaking	2	0.3	Negative
1	5	510	Classroom 510	W4	CMU	White	None	0	0.4	Negative
1	5	510	Classroom 510	Conduit	Metal	White	None	0	0.2	Negative
1	5	510	Classroom 510	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	5	510	Classroom 510	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	510A	Classroom 510 Storeroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	510A	Classroom 510 Storeroom	W1	CMU	White	None	0	0.4	Negative
1	5	510A	Classroom 510 Storeroom	Door Frame	Metal	Black	Chipping	4	0.3	Negative
1	5	510A	Classroom 510 Storeroom	Door	Wood	Black	Chipping	3	0.2	Negative
1	5	510A	Classroom 510 Storeroom	Conduit (W1-3)	Metal	White	None	0	0.5	Negative
1	5	510A	Classroom 510 Storeroom	W2	CMU	White	None	0	0.3	Negative
1	5	510A	Classroom 510 Storeroom	Pipe	Metal	White	None	0	0.2	Negative
1	5	510A	Classroom 510 Storeroom	W3	CMU	White	None	0	0.3	Negative
1	5	510A	Classroom 510 Storeroom	Beam	Concrete	White	None	0	0.2	Negative
1	5	510A	Classroom 510 Storeroom	Column	Concrete	White	None	0	0.2	Negative
1	5	510A	Classroom 510 Storeroom	W4	CMU	White	None	0	0.4	Negative
1	5	510A	Classroom 510 Storeroom	Radiator	Metal	Beige	Chipping	10	0.2	Negative
1	5	510A	Classroom 510 Storeroom	Ceiling	Concrete	White	None	0	0.2	Negative
1	5	S57	Stairwell adjacent to Classroom 510	Floor	Tile	N/A	N/A	N/A	N/A	N/A



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	S57	Stairwell adjacent to Classroom 510	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	5	S57	Stairwell adjacent to Classroom 510	Doorframe	Metal	Black	Chipping	3	0.5	Negative
1	5	S57	Stairwell adjacent to Classroom 510	Door	Metal	Red	Chipping	16	0	Negative
1	5	S57	Stairwell adjacent to Classroom 510	Pipe insulation	Fiberglass	White	Flaking	10	0.1	Negative
1	5	S57	Stairwell adjacent to Classroom 510	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
1	5	S57	Stairwell adjacent to Classroom 510	Conduit	Metal	White	Chipping	4	0.5	Negative
1	5	S57	Stairwell adjacent to Classroom 510	Baseboard	ceramic	Black	Chipping	4	2	Positive
1	5	S57	Stairwell adjacent to Classroom 510	Riser	Metal	Black	Chipping	4	0.2	Negative
1	5	S57	Stairwell adjacent to Classroom 510	Stringer	Metal	Black	Chipping	3	0.1	Negative
1	5	S57	Stairwell adjacent to Classroom 510	Stair Pan	Metal	Tan	Chipping	15	0.6	Negative
1	5	S57	Stairwell adjacent to Classroom 510	radiator	Metal	Tan	Chipping	3	0.2	Negative
1	5	S57	Stairwell adjacent to Classroom 510	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	5	S57	Stairwell adjacent to Classroom 510	Baseboard	Metal	Black	Chipping	4	0	Negative
1	5	S57	Stairwell adjacent to Classroom 510	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	5	S57	Stairwell adjacent to Classroom 510	Ceiling	Concrete	White	Chipping	2	0.3	Negative
1	5	S57	Stairwell adjacent to Classroom 510	Roof Access Door	Metal	Black	Friction	5	0.3	Negative
1	5	S57	Stairwell adjacent to Classroom 510	Roof Access Doorframe	Metal	Black	Chipping	5	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	510B	Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	510B	Girl's Restroom	W1	CMU	White	Flaking	5	0	Negative
1	5	510B	Girl's Restroom	Doorframe	Metal	Tan	Chipping	4	0.3	Negative
1	5	510B	Girl's Restroom	Door	Wood	Tan	Chipping	10	0	Negative
1	5	510B	Girl's Restroom	Partition	Metal	Brown	Chipping	80	1.3	Positive
1	5	510B	Girl's Restroom	W2	CMU	White	None	0	0.5	Negative
1	5	510B	Girl's Restroom	Metal Panel	Metal	Brown	None	0	0.6	Negative
1	5	510B	Girl's Restroom	W3	CMU	White	None	0	0.5	Negative
1	5	510B	Girl's Restroom	Baseboard	Tile	Black	None	0	1.3	Positive
1	5	510B	Girl's Restroom	W4	CMU	White	None	0	0.4	Negative
1	5	510B	Girl's Restroom	Pipe Cover	Metal	White	None	0	0.3	Negative
1	5	510B	Girl's Restroom	Radiator	Metal	White	None	0	0.2	Negative
1	5	510B	Girl's Restroom	vent	Metal	White	None	0	0.1	Negative
1	5	510B	Girl's Restroom	Ceiling	Concrete	White	None	0	0.4	Negative
1	5	511	Classroom 511	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	511	Classroom 511	W1	CMU	Blue/Grey	Chipping	20	0.4	Negative
1	5	511	Classroom 511	Door Frame	Metal	Black	Flaking	1	0.3	Negative
1	5	511	Classroom 511	Baseboard (W1-4)	CMU/Tile	Black	Chipping	4	1.1	Positive
1	5	511	Classroom 511	Conduit (W1,2,4)	Metal	Blue	Chipping	2	0.8	Positive
1	5	511	Classroom 511	W2	CMU	Blue/Grey	Chipping	26	0.4	Negative
1	5	511	Classroom 511	W3	CMU	Blue/Grey	Flaking	8	0.3	Negative
1	5	511	Classroom 511	Beam	Concrete	White	Flaking	7	0.3	Negative
1	5	511	Classroom 511	Column	Concrete	Blue/Grey	Chipping	17	0.1	Negative
1	5	511	Classroom 511	Univent	Metal	Red	Chipping	22	0.2	Negative
1	5	511	Classroom 511	W4	CMU	Blue/Grey	Flaking	16	0.5	Negative
1	5	511	Classroom 511	Ceiling	Concrete	White	Flaking	6	0.3	Negative
1	5	511A	Classroom 511 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.4	Negative
1	5	511A	Classroom 511 - Closet 1	Door (W1)	Wood	Red	None	0	0	Negative
1	5	511B	Classroom 511 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.9	Positive
1	5	511B	Classroom 511 - Closet 2	Door (W1)	Wood	Red	None	0	0.1	Negative
1	5	512	Classroom 512	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	512	Classroom 512	W1	CMU	Blue	Chipping	9	0.4	Negative
1	5	512	Classroom 512	W2	CMU	Blue	Chipping	2	0.4	Negative
1	5	512	Classroom 512	W3	CMU	Blue	Chipping	1	0.5	Negative
1	5	512	Classroom 512	Beam	Concrete	White	None	0	0.2	Negative
1	5	512	Classroom 512	Column	Concrete	Blue	Flaking	3	0.3	Negative
1	5	512	Classroom 512	Pipe	Metal	Blue	Chipping	3	0.4	Negative
1	5	512	Classroom 512	Univent	Metal	Grey	Chipping	10	0.1	Negative
1	5	512	Classroom 512	W4	CMU	Blue	Cracking	3	0.4	Negative
1	5	512	Classroom 512	Conduit	Metal	Blue	Chipping	2	0.5	Negative
1	5	512	Classroom 512	Ceiling	Concrete	White	Flaking	10	0.3	Negative
1	5	513	Classroom 513	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	513	Classroom 513	W1	CMU	White	Chipping	8	0.5	Negative
1	5	513	Classroom 513	Door Frame	Metal	Black	Chipping	13	0.5	Negative
1	5	513	Classroom 513	Baseboard (W1-4)	CMU/Tile	Black	Friction	11	1.1	Positive
1	5	513	Classroom 513	W2	CMU	White	Flaking	3	0.4	Negative
1	5	513	Classroom 513	W3	CMU	White	Cracking	9	0	Negative
1	5	513	Classroom 513	Beam	Concrete	White	Flaking	1	0.3	Negative
1	5	513	Classroom 513	Column	Concrete	White	Cracking	19	0.3	Negative
1	5	513	Classroom 513	Univent	Metal	Grey	Chipping	14	0.1	Negative
1	5	513	Classroom 513	W4	CMU	White	Cracking	3	0.3	Negative
1	5	513	Classroom 513	Ceiling	Concrete	White	Flaking	1	0.3	Negative
1	5	513CA	Classroom 513 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.4	Negative
1	5	513CB	Classroom 513 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	5	514A	Women's Lounge across from Classroom 513	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	514A	Women's Lounge across from Classroom 513	W1	CMU	White	Cracking	13	0.5	Negative
1	5	514A	Women's Lounge across from Classroom 513	Door Frame	Metal	Black	None	0	0.7	Positive
1	5	514A	Women's Lounge across from Classroom 513	W2	CMU	White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	514A	Women's Lounge across from Classroom 513	Baseboard	Tile	Black	None	0	1.1	Positive
1	5	514A	Women's Lounge across from Classroom 513	W3	CMU	White	None	0	0.2	Negative
1	5	514A	Women's Lounge across from Classroom 513	Pipe Cover	Metal	White	Chipping	5	0.2	Negative
1	5	514A	Women's Lounge across from Classroom 513	Radiator	Metal	White	Chipping	4	0.2	Negative
1	5	514A	Women's Lounge across from Classroom 513	pipe insulation	Fiberglass	White	Cracking	6	0.1	Negative
1	5	514A	Women's Lounge across from Classroom 513	W4	CMU	White	None	0	0.4	Negative
1	5	514A	Women's Lounge across from Classroom 513	Ceiling	Concrete	White	Flaking	10	0.4	Negative
1	5	514B	Women's Lounge Restroom on windows side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	514B	Women's Lounge Restroom on windows side	W1	CMU	White	None	0	0.3	Negative
1	5	514B	Women's Lounge Restroom on windows side	Door Frame	Metal	Black	None	0	0.8	Positive
1	5	514B	Women's Lounge Restroom on windows side	W2	CMU	White	None	0	0.5	Negative
1	5	514B	Women's Lounge Restroom on windows side	W3	CMU	White	None	0	0.5	Negative
1	5	514B	Women's Lounge Restroom on windows side	W4	CMU	White	None	0	0.2	Negative
1	5	514B	Women's Lounge Restroom on windows side	Pipe	Metal	White	Flaking	3	0.9	Positive
1	5	514B	Women's Lounge Restroom on windows side	Ceiling	Concrete	White	None	0	0.2	Negative
1	5	514C	Women's Lounge Restroom on hallway side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	514C	Women's Lounge Restroom on hallway side	W1	CMU	White	None	0	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	514C	Women's Lounge Restroom on hallway side	Door Frame	Metal	Black	None	0	0.8	Positive
1	5	514C	Women's Lounge Restroom on hallway side	W2	CMU	White	None	0	0.4	Negative
1	5	514C	Women's Lounge Restroom on hallway side	W3	CMU	White	None	0	0.4	Negative
1	5	514C	Women's Lounge Restroom on hallway side	W4	CMU	White	None	0	0.3	Negative
1	5	514C	Women's Lounge Restroom on hallway side	Duct	Metal	White	None	0	0.1	Negative
1	5	514C	Women's Lounge Restroom on hallway side	Ceiling	Concrete	White	None	0	0.3	Negative
1	5	513A	Office 513A	W1	CMU	White	Cracking	11	0.4	Negative
1	5	513A	Office 513A	Door Frame	Metal	Black	Chipping	7	0.2	Negative
1	5	513A	Office 513A	Baseboard (W1-4)	CMU/Tile	Black	Friction	6	1.1	Positive
1	5	513A	Office 513A	Conduit (W1/4)	Metal	White	None	0	0.4	Negative
1	5	513A	Office 513A	W2	CMU	White	Cracking	10	0.2	Negative
1	5	513A	Office 513A	W3	CMU	White	Flaking	5	0.4	Negative
1	5	513A	Office 513A	Beam	Concrete	White	Chipping	2	0.4	Negative
1	5	513A	Office 513A	Column	Concrete	White	Flaking	3	0.3	Negative
1	5	513A	Office 513A	Radiator	Metal	White	Flaking	8	0.4	Negative
1	5	513A	Office 513A	W4	CMU	White	Flaking	7	0.4	Negative
1	5	513A	Office 513A	Ceiling	Concrete	White	Flaking	1	0.3	Negative
1	5	513A	Office 513A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	514	Classroom 514	W1	CMU	Grey/Blue	Chipping	15	0.5	Negative
1	5	514	Classroom 514	Door Frame	Metal	Black	Chipping	5	0.6	Negative
1	5	514	Classroom 514	Baseboard (W1-4)	CMU/Tile	Black	Cracking	3	0.7	Positive
1	5	514	Classroom 514	W2	CMU	Grey/Blue	Flaking	6	0.4	Negative
1	5	514	Classroom 514	W3	CMU	Grey/Blue	Moisture Damage	16	0.3	Negative
1	5	514	Classroom 514	Beam	Concrete	White	Flaking	4	0.2	Negative
1	5	514	Classroom 514	Column	Concrete	Grey/Blue	Flaking	10	0.3	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>							
			<b>Inspection Company: BATA</b>							
			<b>South Philadelphia High School</b>							
			<b>2101 S Broad St, Philadelphia, PA 19148</b>							
<b>E</b>	<b>F</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	514	Classroom 514	Univent	Metal	Grey	Friction	8	0.1	Negative
1	5	514	Classroom 514	W4	CMU	Grey/Blue	Flaking	2	0.4	Negative
1	5	514	Classroom 514	Ceiling	Concrete	White	Flaking	3	0.3	Negative
1	5	514	Classroom 514	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	514A	Classroom 514 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	5	514B	Classroom 514 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.5	Negative
1	5	514B	Custodial Closet next to Classroom 514	W1	CMU	Tan	Flaking	5	0.4	Negative
1	5	514B	Custodial Closet next to Classroom 514	Doorframe	Metal	Black	Chipping	4	0.3	Negative
1	5	514B	Custodial Closet next to Classroom 514	W2	CMU	Tan	Flaking	20	0	Negative
1	5	514B	Custodial Closet next to Classroom 514	Conduit	Metal	Tan	Flaking	10	0.2	Negative
1	5	514B	Custodial Closet next to Classroom 514	Shelf	Wood	Tan	Chipping	4	1.6	Positive
1	5	514B	Custodial Closet next to Classroom 514	Electrical Panel	Metal	Tan	Chipping	10	0.2	Negative
1	5	514B	Custodial Closet next to Classroom 514	W3	CMU	Tan	Flaking	5	0.2	Negative
1	5	514B	Custodial Closet next to Classroom 514	W4	CMU	Tan	Flaking	5	0.5	Negative
1	5	514B	Custodial Closet next to Classroom 514	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	5	514B	Custodial Closet next to Classroom 514	Pipe	Metal	Tan	Flaking	3	0.5	Negative
1	5	515	Classroom 515	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	515	Classroom 515	W1	CMU	Green	Chipping	2	0.4	Negative
1	5	515	Classroom 515	Door Frame	Metal	Black	Friction	5	0.6	Negative
1	5	515	Classroom 515	Baseboard (W1-4)	CMU/Tile	Black	Friction	2	1.1	Positive
1	5	515	Classroom 515	W2	CMU	Green	None	0	0.3	Negative
1	5	515	Classroom 515	W3	CMU	Green	Flaking	6	0.3	Negative

			Dates: 7/11 - 8/31/2022		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Charles Rhodes 003542		South Philadelphia High School					
			Inspection Company: BATTA		2101 S Broad St, Philadelphia, PA 19148					
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	515	Classroom 515	Column	Concrete	Green	Flaking	8	0.2	Negative
1	5	515	Classroom 515	Univent	Metal	Grey	Friction	5	0.2	Negative
1	5	515	Classroom 515	W4	CMU	Green	Chipping	2	0.3	Negative
1	5	515	Classroom 515	Ceiling	Concrete	White	Flaking	3	0.1	Negative
1	5	515A	Classroom 515 - Closet 1	Door Frame (W2)	Metal	Black	Chipping	1	0.7	Positive
1	5	515B	Classroom 515 - Closet 2	Door Frame (W3)	Metal	Black	Chipping	1	0.6	Negative
1	5	516	Classroom 516	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	516	Classroom 516	W1	CMU	Yellow	Cracking	2	0.4	Negative
1	5	516	Classroom 516	Door Frame	Metal	Black	Chipping	9	0.8	Positive
1	5	516	Classroom 516	Baseboard (W1-4)	CMU/Tile	Black	Friction	8	1.2	Positive
1	5	516	Classroom 516	W2	CMU	Yellow	Chipping	8	0.3	Negative
1	5	516	Classroom 516	W3	CMU	Yellow	Flaking	13	0.3	Negative
1	5	516	Classroom 516	Beam	Concrete	White	Flaking	9	0.3	Negative
1	5	516	Classroom 516	Column	Concrete	Yellow	Flaking	12	0.2	Negative
1	5	516	Classroom 516	Univent	Metal	Grey	Chipping	8	0.2	Negative
1	5	516	Classroom 516	W4	CMU	Yellow	Flaking	6	0.4	Negative
1	5	516	Classroom 516	Ceiling	Concrete	White	Flaking	4	0.3	Negative
1	5	516A	Classroom 516 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.6	Negative
1	5	516B	Classroom 516 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.8	Positive
1	5	517	Classroom 517	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	517	Classroom 517	W1	CMU	White	Chipping	4	0.3	Negative
1	5	517	Classroom 517	Door Frame	Metal	Black	Chipping	13	0.6	Negative
1	5	517	Classroom 517	Baseboard (W1-4)	CMU/Tile	Black	Chipping	1	1	Positive
1	5	517	Classroom 517	W2	CMU	White	Chipping	5	0.5	Negative
1	5	517	Classroom 517	W3	CMU	White	Flaking	9	0.4	Negative
1	5	517	Classroom 517	Beam	Concrete	White	Flaking	3	0.3	Negative
1	5	517	Classroom 517	Column	Concrete	White	Chipping	10	0.3	Negative
1	5	517	Classroom 517	Univent	Metal	Grey	Chipping	8	0.1	Negative
1	5	517	Classroom 517	W4	CMU	White	Chipping	3	0.1	Negative
1	5	517	Classroom 517	Ceiling	Concrete	White	Flaking	4	0.2	Negative



			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E</b>	<b>F</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	517A	Classroom 517 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.6	Negative
1	5	517B	Classroom 517 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.7	Positive
1	5	518	Classroom 518	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	518	Classroom 518	W1	CMU	Purple	Flaking	14	0.3	Negative
1	5	518	Classroom 518	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.4	Positive
1	5	518	Classroom 518	Door Frame	Metal	Black	Chipping	10	0.8	Positive
1	5	518	Classroom 518	W2	CMU	Purple	Flaking	2	0.4	Negative
1	5	518	Classroom 518	Column (W2/3)	Concrete	Purple/White	Flaking	55	0.1	Negative
1	5	518	Classroom 518	Univent/Radiator (W2/3)	Metal	Grey/Purple	Chipping	8	0.2	Negative
1	5	518	Classroom 518	W3	CMU	Purple	Moisture Damage	7	0.3	Negative
1	5	518	Classroom 518	W4	CMU	Purple	None	0	0.5	Negative
1	5	518	Classroom 518	Ceiling	Concrete	White	None	0	0.2	Negative
1	5	518A	Classroom 518 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.6	Negative
1	5	518B	Classroom 518 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.6	Negative
1	5	518B	Classroom 518 - Closet 2	Door (W1)	Wood	Blue	None	0	0.2	Negative
1	5	517A	Office 519A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	517A	Office 519A	W1	CMU	Blue	Flaking	1	0.2	Negative
1	5	517A	Office 519A	Door Frame	Metal	Black	Chipping	1	0.7	Positive
1	5	517A	Office 519A	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.8	Positive
1	5	517A	Office 519A	Conduit (W1/2)	Metal	Blue	None	0	0.2	Negative
1	5	517A	Office 519A	W2	CMU	Blue	Flaking	1	0.4	Negative
1	5	517A	Office 519A	W3	CMU	Blue	Flaking	3	0.5	Negative
1	5	517A	Office 519A	W3	Metal	Blue	Chipping	1	0.2	Negative
1	5	517A	Office 519A	W4	CMU	Blue	Flaking	4	0.4	Negative
1	5	517A	Office 519A	Ceiling	Concrete	White	Flaking	1	0.1	Negative
1	5	S55	Stairwell next to Office 519A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S55	Stairwell next to Office 519A	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S55	Stairwell next to Office 519A	Doorframe	Metal	Black	Chipping	8	0.3	Negative
1	5	S55	Stairwell next to Office 519A	Door	Metal	Red	Friction	20	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	S55	Stairwell next to Office 519A	W2	CMU	White	None	0	0	Negative
1	5	S55	Stairwell next to Office 519A	Conduit	Metal	White	Chipping	8	0.1	Negative
1	5	S55	Stairwell next to Office 519A	Riser	Metal	Tan	Chipping	10	0.1	Negative
1	5	S55	Stairwell next to Office 519A	Stringer	Metal	Tan	Chipping	8	0.1	Negative
1	5	S55	Stairwell next to Office 519A	Stair Pan	Metal	Tan	Chipping	5	0.1	Negative
1	5	S55	Stairwell next to Office 519A	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S55	Stairwell next to Office 519A	Baseboard	Metal	Tan	Chipping	14	0.1	Negative
1	5	S55	Stairwell next to Office 519A	W4	CMU	White	None	0	0	Negative
1	5	S55	Stairwell next to Office 519A	Fire Pipe	Metal	White	None	0	0.3	Negative
1	5	S55	Stairwell next to Office 519A	Ceiling	Concrete	White	Flaking	33	0.2	Negative
1	5	519	Classroom 519	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	519	Classroom 519	W1	CMU	Yellow	Flaking	40	0.4	Negative
1	5	519	Classroom 519	Baseboard (W1-4)	CMU/Tile	Black	Chipping	1	1	Positive
1	5	519	Classroom 519	Door Frame	Metal	Black	Chipping	11	0.4	Negative
1	5	519	Classroom 519	W2	CMU	Yellow	Flaking	18	0.5	Negative
1	5	519	Classroom 519	W3	CMU	Yellow	Flaking	9	0.4	Negative
1	5	519	Classroom 519	Beams (W3/4)	Concrete	Grey	Flaking	19	0.1	Negative
1	5	519	Classroom 519	Columns	Concrete	Yellow/Grey	Flaking	20	0.2	Negative
1	5	519	Classroom 519	Univent	Metal	Grey	Chipping	8	0.1	Negative
1	5	519	Classroom 519	W4	CMU	Yellow	Flaking	16	0.5	Negative
1	5	519	Classroom 519	Ceiling	Concrete	White	Flaking	4	0.2	Negative
1	5	519A	Classroom 519 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	3	0.4	Negative
1	5	519B	Classroom 519 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.6	Negative
1	5	520	Computer Lab 520	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	520	Computer Lab 520	W1	CMU	White	Flaking	16	0.4	Negative
1	5	520	Computer Lab 520	Door Frame	Metal	Black	Chipping	7	0.5	Negative
1	5	520	Computer Lab 520	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.5	Positive
1	5	520	Computer Lab 520	W2	CMU	White	None	0	0.5	Negative
1	5	520	Computer Lab 520	W3	CMU	White	Flaking	6	0.4	Negative
1	5	520	Computer Lab 520	Beam	Concrete	White	Flaking	5	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	520	Computer Lab 520	Column	Concrete	White	Flaking	8	0.2	Negative
1	5	520	Computer Lab 520	Univent	Metal	Red	Chipping	8	0.1	Negative
1	5	520	Computer Lab 520	W4	CMU	White	Cracking	4	0.3	Negative
1	5	520	Computer Lab 520	Ceiling	Concrete	White	Flaking	4	0.4	Negative
1	5	520A	Computer Lab 520 - Closet 1	Door Frame (W1)	Metal	Black	None	0	1	Positive
1	5	520B	Computer Lab 520 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.9	Positive
1	5	521	Classroom 521	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	521	Classroom 521	W1	CMU	Pink	None	0	0.3	Negative
1	5	521	Classroom 521	Door Frame	Metal	Black	Chipping	6	0.5	Negative
1	5	521	Classroom 521	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.4	Positive
1	5	521	Classroom 521	W2	CMU	Pink	None	0	0.3	Negative
1	5	521	Classroom 521	W3	CMU	Pink	Flaking	2	0.4	Negative
1	5	521	Classroom 521	Beam	Concrete	Pink	Flaking	9	0.3	Negative
1	5	521	Classroom 521	Column	Concrete	Pink	Flaking	2	0.2	Negative
1	5	521	Classroom 521	Univent	Metal	Pink	Chipping	1	0.2	Negative
1	5	521	Classroom 521	W4	CMU	Pink	None	0	0.2	Negative
1	5	521	Classroom 521	Ceiling	Concrete	White	Flaking	2	0.4	Negative
1	5	521A	Classroom 521 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.6	Negative
1	5	521B	Classroom 521 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.5	Negative
1	5	522	Classroom 522	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	522	Classroom 522	W1	CMU	Blue/Grey	Chipping	16	0.5	Negative
1	5	522	Classroom 522	Door Frame	Metal	Black	Chipping	12	0.5	Negative
1	5	522	Classroom 522	Baseboard (W1-4)	CMU/Tile	Black	Friction	3	1.4	Positive
1	5	522	Classroom 522	W2	CMU	Blue/Grey	Friction	8	0.4	Negative
1	5	522	Classroom 522	W3	CMU	Blue/Grey	Moisture Damage	13	0.4	Negative
1	5	522	Classroom 522	Beam	Concrete	White	Flaking	2	0.4	Negative
1	5	522	Classroom 522	Column	Concrete	Blue/Grey	Moisture Damage	17	0.4	Negative
1	5	522	Classroom 522	Univent	Metal	Grey	Friction	8	0.1	Negative
1	5	522	Classroom 522	W4	CMU	Blue/Grey	None	0	0.4	Negative
1	5	522	Classroom 522	Ceiling	Concrete	White	Flaking	1	0.2	Negative

			Dates: 7/11 - 8/31/2022		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Charles Rhodes 003542		South Philadelphia High School					
			Inspection Company: BATA		2101 S Broad St, Philadelphia, PA 19148					
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	522A	Classroom 522 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.6	Negative
1	5	522B	Classroom 522 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	5	522A	Storage Room 522A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522A	Storage Room 522A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522A	Storage Room 522A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522A	Storage Room 522A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522A	Storage Room 522A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522A	Storage Room 522A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522B	Storage Room 522B	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522B	Storage Room 522B	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522B	Storage Room 522B	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522B	Storage Room 522B	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522B	Storage Room 522B	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	522B	Storage Room 522B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	H52	Hallway between Classrooms 518 and 522	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	H52	Hallway between Classrooms 518 and 522	W1	N/A	N/A	None	0	N/A	N/A
1	5	H52	Hallway between Classrooms 518 and 522	W2	CMU	White	Chipping	40	0.4	Negative
1	5	H52	Hallway between Classrooms 518 and 522	Radiator	Metal	White	Chipping	4	0.2	Negative
1	5	H52	Hallway between Classrooms 518 and 522	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	5	H52	Hallway between Classrooms 518 and 522	W3	N/A	N/A	None	0	N/A	N/A
1	5	H52	Hallway between Classrooms 518 and 522	W4	CMU	White	Chipping	39	0	Negative
1	5	H52	Hallway between Classrooms 518 and 522	Vent	Metal	White	None	0	0.2	Negative
1	5	H52	Hallway between Classrooms 518 and 522	Electrical Panel	Metal	Black	Chipping	2	0.2	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	H52	Hallway between Classrooms 518 and 522	Ceiling Beam	Concrete	White	None	0	0.4	Negative
1	5	523	Classroom 523	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	523	Classroom 523	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	523	Classroom 523	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	523	Classroom 523	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	523	Classroom 523	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	523	Classroom 523	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	524	Classroom 524	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	524	Classroom 524	W1	CMU	Grey	Flaking	25	0	Negative
1	5	524	Classroom 524	Door Frame	Metal	Black	Chipping	7	0.4	Negative
1	5	524	Classroom 524	W2	CMU	Grey	Flaking	10	0.3	Negative
1	5	524	Classroom 524	W3	CMU	Grey	Flaking	8	0	Negative
1	5	524	Classroom 524	Beam	Concrete	White	Flaking	1	0.5	Negative
1	5	524	Classroom 524	Column	Concrete	White	Flaking	15	0.1	Negative
1	5	524	Classroom 524	Univent	Metal	Grey	Chipping	2	0.1	Negative
1	5	524	Classroom 524	Baseboard	CMU/Tile	Black	Friction	10	1.4	Positive
1	5	524	Classroom 524	W4	CMU	Grey	Cracking	8	0.4	Negative
1	5	524	Classroom 524	Ceiling	Concrete	White	Flaking	4	0.5	Negative
1	5	524A	Classroom 524 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.6	Negative
1	5	524B	Classroom 524 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	5	525	Classroom 525	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	525	Classroom 525	W1	CMU	Grey	Flaking	9	0.4	Negative
1	5	525	Classroom 525	Door Frame	Metal	Black	Chipping	4	0.2	Negative
1	5	525	Classroom 525	Conduit (W1/2)	Metal	Grey/Blue	Chipping	1	0.4	Negative
1	5	525	Classroom 525	W2	CMU	Grey	Chipping	2	0.4	Negative
1	5	525	Classroom 525	W3	CMU	Grey	Cracking	3	0.5	Negative
1	5	525	Classroom 525	Beam	Concrete	White	Flaking	1	0.4	Negative
1	5	525	Classroom 525	Column	Concrete	Grey	Chipping	16	0.2	Negative
1	5	525	Classroom 525	Univent	Metal	Grey	Chipping	2	0.1	Negative
1	5	525	Classroom 525	W4	CMU	Grey	Flaking	4	0.5	Negative
1	5	525	Classroom 525	Baseboard	CMU/Tile	Black	Chipping	4	1.4	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	525	Classroom 525	Ceiling	Concrete	White	Flaking	14	0.3	Negative
1	5	525A	Classroom 525 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0	Negative
1	5	525B	Classroom 525 - Closet 2	Door Frame (W1)	Metal	Black	Friction	1	1	Positive
1	5	526	Computer Lab 526	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	526	Computer Lab 526	W1	CMU	White	Chipping	3	0.4	Negative
1	5	526	Computer Lab 526	Door Frame	Metal	Black	Chipping	8	0.5	Negative
1	5	526	Computer Lab 526	Baseboard (w1-4)	CMU/Tile	Black	None	0	1.2	Positive
1	5	526	Computer Lab 526	W2	CMU	White	Chipping	5	0.5	Negative
1	5	526	Computer Lab 526	W3	CMU	White	Flaking	5	0.5	Negative
1	5	526	Computer Lab 526	Beam	Concrete	White	Flaking	2	0.1	Negative
1	5	526	Computer Lab 526	Column	Concrete	White	Flaking	13	0	Negative
1	5	526	Computer Lab 526	Univent	Metal	Grey	Flaking	1	0	Negative
1	5	526	Computer Lab 526	W4	CMU	White	None	0	0.4	Negative
1	5	526	Computer Lab 526	Ceiling	Concrete	White	Flaking	1	0.3	Negative
1	5	526D	Computer Lab 526 Storeroom	Floor	Concrete	Bare	N/A	N/A	N/A	N/A
1	5	526D	Computer Lab 526 Storeroom	W1	CMU	Bare	N/A	N/A	N/A	N/A
1	5	526D	Computer Lab 526 Storeroom	Door Frame	Metal	Black	Chipping	4	0.5	Negative
1	5	526D	Computer Lab 526 Storeroom	W2	CMU	Bare	N/A	N/A	N/A	N/A
1	5	526D	Computer Lab 526 Storeroom	Shelf Support (W2-4)	Wood	Grey	Friction	10	0.5	Negative
1	5	526D	Computer Lab 526 Storeroom	W3	CMU	Bare	N/A	N/A	N/A	N/A
1	5	526D	Computer Lab 526 Storeroom	W4	CMU	Bare	N/A	N/A	N/A	N/A
1	5	526D	Computer Lab 526 Storeroom	Ceiling	CMU	Bare	N/A	N/A	N/A	N/A
1	5	526CA	Computer Lab 526 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	5	526CB	Computer Lab 526 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	5	527	Classroom 527	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	527	Classroom 527	W1	CMU	White	Flaking	20	0.2	Negative
1	5	527	Classroom 527	Door Frame	Metal	Black	Chipping	5	0.5	Negative
1	5	527	Classroom 527	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	1.5	Positive
1	5	527	Classroom 527	W2	CMU	White	Flaking	18	0.3	Negative
1	5	527	Classroom 527	W3	CMU	White	Flaking	8	0.5	Negative



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	527	Classroom 527	Beam	Concrete	White	Flaking	1	0.4	Negative
1	5	527	Classroom 527	Column	Concrete	White	Flaking	17	0.2	Negative
1	5	527	Classroom 527	Univent	Metal	Grey	Friction	10	0.2	Negative
1	5	527	Classroom 527	W4	CMU	White	Flaking	9	0.4	Negative
1	5	527	Classroom 527	Ceiling	Concrete	White	None	0	0.3	Negative
1	5	527A	Classroom 527 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	5	527B	Classroom 527 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.6	Negative
1	5	526B	Boy's Restroom	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	5	526B	Boy's Restroom	W1	CMU	Tan	None	0	0.5	Negative
1	5	526B	Boy's Restroom	Door Frame	Metal	Tan	Chipping	3	0.8	Positive
1	5	526B	Boy's Restroom	door	Metal	Tan	Friction	16	0	Negative
1	5	526B	Boy's Restroom	baseboard	CMU/Tile	Black	Chipping	10	0.8	Positive
1	5	526B	Boy's Restroom	W2	CMU	Tan	None	0	0.4	Negative
1	5	526B	Boy's Restroom	Radiator	Metal	White	None	0	0.1	Negative
1	5	526B	Boy's Restroom	W3	CMU	Tan	None	0	0.5	Negative
1	5	526B	Boy's Restroom	Column	Concrete	Tan	None	0	0.1	Negative
1	5	526B	Boy's Restroom	Lower Wall 1-4	Ceramic	Tan	Chipping	4	1.8	Positive
1	5	526B	Boy's Restroom	W4	CMU	Tan	None	0	0.3	Negative
1	5	526B	Boy's Restroom	Vent	Metal	White	None	0	0.3	Negative
1	5	526B	Boy's Restroom	Panel	Metal	Tan	Chipping	2	0.3	Negative
1	5	526B	Boy's Restroom	Duct	Metal	White	None	0	0.2	Negative
1	5	526B	Boy's Restroom	Ceiling	Concrete	White	None	0	0.5	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S51	Stairwell adjacent to Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S51	Stairwell adjacent to Boy's Restroom	Doorframe	Metal	Black	Chipping	8	0.3	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	Door	Metal	Red	Friction	20	0.1	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	S51	Stairwell adjacent to Boy's Restroom	Conduit	Metal	White	Chipping	8	0.1	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	Riser	Metal	Tan	Chipping	10	0.1	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	Stringer	Metal	Tan	Chipping	8	0.1	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	Stair Pan	Metal	Tan	Chipping	5	0.1	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S51	Stairwell adjacent to Boy's Restroom	Baseboard	Metal	Tan	Chipping	14	0.1	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S51	Stairwell adjacent to Boy's Restroom	Fire Pipe	Metal	White	None	0	0.3	Negative
1	5	S51	Stairwell adjacent to Boy's Restroom	Ceiling	Concrete	White	Flaking	33	0.2	Negative
1	5	526A	Men's Lounge	Floor	Tile	Bare	N/A	N/A	N/A	N/A
1	5	526A	Men's Lounge	W1	CMU	Tan	Flaking	12	0.3	Negative
1	5	526A	Men's Lounge	Door Frame	Metal	Black	Chipping	4	0.4	Negative
1	5	526A	Men's Lounge	W2	CMU	Tan	Flaking	6	0.4	Negative
1	5	526A	Men's Lounge	Closet Doorframe	Metal	Black	None	0	0.4	Negative
1	5	526A	Men's Lounge	Closet Shelf	Wood	White	Chipping	13	1.4	Positive
1	5	526A	Men's Lounge	Baseboard	CMU/Tile	Black	None	0	1.3	Positive
1	5	526A	Men's Lounge	W3	CMU	Tan	Flaking	6	0.5	Negative
1	5	526A	Men's Lounge	Column	Concrete	Tan	Flaking	7	0.1	Negative
1	5	526A	Men's Lounge	Radiator	Metal	Tan	Chipping	11	0.1	Negative
1	5	526A	Men's Lounge	W4	CMU	Tan	Flaking	8	0.4	Negative
1	5	526A	Men's Lounge	Pipe Insulation	Fiberglass	White	Cracking	7	0.1	Negative
1	5	526A	Men's Lounge	Ceiling	Concrete	White	Flaking	8	0.3	Negative
1	5	526C	Men's Lounge Restroom	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	5	526C	Men's Lounge Restroom	W1	CMU	Tan	Flaking	5	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	526C	Men's Lounge Restroom	Door Frame	Metal	Black	Chipping	4	0.8	Positive
1	5	526C	Men's Lounge Restroom	W2	CMU	Tan	Cracking	3	0.4	Negative
1	5	526C	Men's Lounge Restroom	Radiator	Metal	Tan	Flaking	8	0.2	Negative
1	5	526C	Men's Lounge Restroom	Pipe Cover	Metal	Tan	Chipping	1	0.4	Negative
1	5	526C	Men's Lounge Restroom	Pipe Insulation	Fiberglass	Tan	Cracking	4	0.1	Negative
1	5	526C	Men's Lounge Restroom	Column	Concrete	Tan	Flaking	2	0.2	Negative
1	5	526C	Men's Lounge Restroom	W3	CMU	Tan	Flaking	3	0.5	Negative
1	5	526C	Men's Lounge Restroom	W4	Ceramic	Bare	N/A	N/A	N/A	N/A
1	5	526C	Men's Lounge Restroom	Ceiling	Concrete	White	Flaking	9	0.2	Negative
1	5	528	Classroom 528	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	528	Classroom 528	W1	CMU	Tan	Flaking	15	0.4	Negative
1	5	528	Classroom 528	Door Frame	Metal	Black	Chipping	5	0.8	Positive
1	5	528	Classroom 528	Baseboard (W1-4)	CMU/Tile	Black	Friction	19	1.2	Positive
1	5	528	Classroom 528	W2	CMU	Tan	Flaking	4	0.4	Negative
1	5	528	Classroom 528	W3	CMU	Tan	Flaking	3	0.6	Negative
1	5	528	Classroom 528	Beam	Concrete	White	None	0	0.2	Negative
1	5	528	Classroom 528	Column	Concrete	Tan	Moisture Damage	9	0.3	Negative
1	5	528	Classroom 528	Univent	Metal	Grey	Chipping	8	0	Negative
1	5	528	Classroom 528	W4	CMU	Tan	Flaking	4	0.5	Negative
1	5	528	Classroom 528	Ceiling	Concrete	White	Flaking	3	0.4	Negative
1	5	528A	Classroom 528 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.3	Negative
1	5	528B	Classroom 528 - Closet 2	Door Frame (W1)	Metal	Black	Friction	1	0.7	Positive
1	5	529	Classroom 529	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	529	Classroom 529	W1	CMU	Tan	Flaking	9	0.5	Negative
1	5	529	Classroom 529	Door Frame	Metal	Black	Chipping	6	0.2	Negative
1	5	529	Classroom 529	Baseboard (W1-4)	CMU/Tile	Black	Cracking	10	1	Positive
1	5	529	Classroom 529	W2	CMU	Tan	Flaking	4	0.5	Negative
1	5	529	Classroom 529	W3	CMU	Tan	Flaking	9	0.5	Negative
1	5	529	Classroom 529	Beam	Concrete	White	Flaking	2	0.3	Negative
1	5	529	Classroom 529	Column	Concrete	Tan	Chipping	11	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	529	Classroom 529	Univent	Metal	Grey	Chipping	12	0.2	Negative
1	5	529	Classroom 529	W4	CMU	Tan	Flaking	8	0.5	Negative
1	5	529	Classroom 529	Conduit	Metal	Tan	None	0	0.4	Negative
1	5	529	Classroom 529	Ceiling	Concrete	White	Flaking	3	0.3	Negative
1	5	529A	Classroom 529 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.3	Negative
1	5	529B	Classroom 529 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.4	Negative
1	5	530	Classroom 530	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	530	Classroom 530	W1	CMU	Tan	Flaking	10	0.5	Negative
1	5	530	Classroom 530	Door Frame	Metal	Black	Chipping	12	0.5	Negative
1	5	530	Classroom 530	Baseboard (W1-4)	CMU/Tile	Black	Friction	12	1.3	Positive
1	5	530	Classroom 530	W2	CMU	Tan	Flaking	7	0.4	Negative
1	5	530	Classroom 530	Univent/Radiator (W2/3)	Metal	Tan	Chipping	22	0.1	Negative
1	5	530	Classroom 530	W3	CMU	Tan	Moisture Damage	16	0.5	Negative
1	5	530	Classroom 530	Beam	Concrete	White	Flaking	3	0.4	Negative
1	5	530	Classroom 530	Column	Concrete	Tan	Flaking	7	0.2	Negative
1	5	530	Classroom 530	W4	CMU	Tan	Flaking	7	0.4	Negative
1	5	530	Classroom 530	Conduit	Metal	White	None	0	0.4	Negative
1	5	530	Classroom 530	Ceiling	Concrete	White	Flaking	1	0.2	Negative
1	5	530A	Classroom 530 - Closet 1	Door Frame (W1)	Metal	Black	Friction	1	0.3	Negative
1	5	530B	Classroom 530 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.7	Positive
1	5	S52	Stairwell adjacent to Classroom 530	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S52	Stairwell adjacent to Classroom 530	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S52	Stairwell adjacent to Classroom 530	Doorframe	Metal	Black	Chipping	8	0.3	Negative
1	5	S52	Stairwell adjacent to Classroom 530	Door	Metal	Red	Friction	20	0.1	Negative
1	5	S52	Stairwell adjacent to Classroom 530	W2	CMU	White	None	0	0	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	S52	Stairwell adjacent to Classroom 530	Conduit	Metal	White	Chipping	8	0.1	Negative
1	5	S52	Stairwell adjacent to Classroom 530	Riser	Metal	Tan	Chipping	10	0.1	Negative
1	5	S52	Stairwell adjacent to Classroom 530	Stringer	Metal	Tan	Chipping	8	0.1	Negative
1	5	S52	Stairwell adjacent to Classroom 530	Stair Pan	Metal	Tan	Chipping	5	0.1	Negative
1	5	S52	Stairwell adjacent to Classroom 530	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S52	Stairwell adjacent to Classroom 530	Baseboard	Metal	Tan	Chipping	14	0.1	Negative
1	5	S52	Stairwell adjacent to Classroom 530	W4	CMU	White	None	0	0	Negative
1	5	S52	Stairwell adjacent to Classroom 530	Fire Pipe	Metal	White	None	0	0.3	Negative
1	5	S52	Stairwell adjacent to Classroom 530	Ceiling	Concrete	White	Flaking	33	0.2	Negative
1	5	531	Classroom 531	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	531	Classroom 531	W1	CMU	White	Flaking	45	0.4	Negative
1	5	531	Classroom 531	Door Frame	Metal	Black	Chipping	3	0.2	Negative
1	5	531	Classroom 531	Baseboard (W1-4)	CMU/Tile	Black	Friction	6	1.7	Positive
1	5	531	Classroom 531	W2	CMU	White	Flaking	15	0.4	Negative
1	5	531	Classroom 531	W3	CMU	White	Flaking	8	0.3	Negative
1	5	531	Classroom 531	Beam	Concrete	White	None	0	0.3	Negative
1	5	531	Classroom 531	Column	Concrete	White	Flaking	4	0.3	Negative
1	5	531	Classroom 531	Univent/Radiator (W3/4)	Metal	White	Flaking	20	0.4	Negative
1	5	531	Classroom 531	W4	CMU	White	Flaking	15	0.4	Negative
1	5	531	Classroom 531	Ceiling	Concrete	White	Flaking	1	0.3	Negative
1	5	531A	Classroom 531 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	2	0.5	Negative
1	5	531B	Classroom 531 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.7	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	H51	Hallway from Classrooms 507 to 531	Floor	Floor Tile	N/A	None	0	N/A	N/A
1	5	H51	Hallway from Classrooms 507 to 531	W1	N/A	N/A	None	0	N/A	N/A
1	5	H51	Hallway from Classrooms 507 to 531	Door Frame	Metal	Black	Chipping	10	0.9	Positive
1	5	H51	Hallway from Classrooms 507 to 531	Door	Metal	Red	Friction	25	0	Negative
1	5	H51	Hallway from Classrooms 507 to 531	W2	CMU	White	Flaking	75	0.4	Negative
1	5	H51	Hallway from Classrooms 507 to 531	Vent	Metal	White	None	0	0.2	Negative
1	5	H51	Hallway from Classrooms 507 to 531	Baseboard	CMU/Tile	Black	None	0	1.4	Positive
1	5	H51	Hallway from Classrooms 507 to 531	Electrical Panel	Metal	Black	Chipping	2	0	Negative
1	5	H51	Hallway from Classrooms 507 to 531	Radiator	Metal	White	None	0	0.2	Negative
1	5	H51	Hallway from Classrooms 507 to 531	W3	N/A	N/A	None	0	N/A	N/A
1	5	H51	Hallway from Classrooms 507 to 531	Door Frame	Metal	Black	None	0	1.4	Positive
1	5	H51	Hallway from Classrooms 507 to 531	Door	Metal	Red	Flaking	15	0	Negative
1	5	H51	Hallway from Classrooms 507 to 531	W4	CMU	White	Chipping	40	0.4	Negative
1	5	H51	Hallway from Classrooms 507 to 531	Ceiling Beam	Concrete	White	None	0	0.4	Negative
1	5	532	Classroom 532	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	532	Classroom 532	W1	CMU	Blue	Friction	8	0	Negative
1	5	532	Classroom 532	Door Frame	Metal	Black	Chipping	8	0.4	Negative
1	5	532	Classroom 532	Baseboard	CMU/Tile	Black	Friction	5	0.9	Positive
1	5	532	Classroom 532	W2	Brick	Blue	Friction	4	0	Negative
1	5	532	Classroom 532	W3	CMU	Black/Yellow	Flaking	20	0	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E</b>	<b>F</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	532	Classroom 532	Beam	Concrete	White	Cracking	4	0	Negative
1	5	532	Classroom 532	Column	CMU	Black/Yellow	Chipping	10	0.2	Negative
1	5	532	Classroom 532	Univent	Metal	Grey	Chipping	18	0.1	Negative
1	5	532	Classroom 532	W4	CMU	Blue	Chipping	3	0	Negative
1	5	532	Classroom 532	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	5	532A	Classroom 532 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.3	Negative
1	5	532B	Classroom 532 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.4	Negative
1	5	533	Classroom 533	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	533	Classroom 533	W1	CMU	Purple	Chipping	8	0.2	Negative
1	5	533	Classroom 533	Door Frame	Metal	Black	Friction	8	0.3	Negative
1	5	533	Classroom 533	W2	CMU	Purple	Chipping	3	0.1	Negative
1	5	533	Classroom 533	Baseboard	CMU/Tile	Black	None	0	0.9	Positive
1	5	533	Classroom 533	W3	CMU	Purple	Chipping	1	0	Negative
1	5	533	Classroom 533	Beam	Concrete	White	Flaking	4	0.2	Negative
1	5	533	Classroom 533	Column	CMU	Purple	Flaking	4	0	Negative
1	5	533	Classroom 533	Univent	Metal	Purple	Chipping	5	0.1	Negative
1	5	533	Classroom 533	W4	CMU	Purple	Chipping	1	0.1	Negative
1	5	533	Classroom 533	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	5	533A	Classroom 533 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.3	Negative
1	5	533B	Classroom 533 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.4	Negative
1	5	534	Classroom 534	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	534	Classroom 534	W1	CMU	White	Friction	4	0.3	Negative
1	5	534	Classroom 534	Door Frame	Metal	Black	Chipping	6	0.6	Negative
1	5	534	Classroom 534	Baseboard (W1-4)	CMU/Tile	Black	Friction	2	1	Positive
1	5	534	Classroom 534	W2	CMU	White	Friction	3	0.2	Negative
1	5	534	Classroom 534	W3	CMU	White	Flaking	2	0.2	Negative
1	5	534	Classroom 534	Column	CMU	White	None	0	0.3	Negative
1	5	534	Classroom 534	Univent	Metal	Black	Chipping	8	0.1	Negative
1	5	534	Classroom 534	W4	CMU	White	Chipping	2	0.3	Negative
1	5	534	Classroom 534	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	5	534A	Classroom 534 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.4	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	5	534B	Classroom 534 - Closet 2	Door Frame (w1)	Metal	Black	None	0	0.6	Negative
1	5	535	Classroom 535	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	535	Classroom 535	W1	CMU	Blue/White	Flaking	30	0.4	Negative
1	5	535	Classroom 535	Door Frame	Metal	Black	Chipping	9	0.6	Negative
1	5	535	Classroom 535	Baseboard (W1-4)	CMU/Tile	Black	Friction	4	1.1	Positive
1	5	535	Classroom 535	W2	CMU	Blue/White	Flaking	10	0.4	Negative
1	5	535	Classroom 535	W3	CMU	Blue/White	Flaking	40	0.2	Negative
1	5	535	Classroom 535	Beam	Concrete	White	Flaking	5	0.1	Negative
1	5	535	Classroom 535	Column	CMU	Blue/White	Flaking	12	0.2	Negative
1	5	535	Classroom 535	Univent	Metal	Grey	Chipping	20	0.1	Negative
1	5	535	Classroom 535	W4	CMU	Blue/White	Flaking	10	0.1	Negative
1	5	535	Classroom 535	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	5	535A	Classroom 535 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	2	0.6	Negative
1	5	535B	Classroom 535 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.5	Negative
1	5	S53	Stairwell adjacent to Classroom 535	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S53	Stairwell adjacent to Classroom 535	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S53	Stairwell adjacent to Classroom 535	Doorframe	Metal	Black	Chipping	8	0.3	Negative
1	5	S53	Stairwell adjacent to Classroom 535	Door	Metal	Red	Friction	20	0.1	Negative
1	5	S53	Stairwell adjacent to Classroom 535	W2	CMU	White	None	0	0	Negative
1	5	S53	Stairwell adjacent to Classroom 535	Conduit	Metal	White	Chipping	8	0.1	Negative
1	5	S53	Stairwell adjacent to Classroom 535	Riser	Metal	Tan	Chipping	10	0.1	Negative
1	5	S53	Stairwell adjacent to Classroom 535	Stringer	Metal	Tan	Chipping	8	0.1	Negative
1	5	S53	Stairwell adjacent to Classroom 535	Stair Pan	Metal	Tan	Chipping	5	0.1	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	5	S53	Stairwell adjacent to Classroom 535	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	5	S53	Stairwell adjacent to Classroom 535	Baseboard	Metal	Tan	Chipping	14	0.1	Negative
1	5	S53	Stairwell adjacent to Classroom 535	W4	CMU	White	None	0	0	Negative
1	5	S53	Stairwell adjacent to Classroom 535	Fire Pipe	Metal	White	None	0	0.3	Negative
1	5	S53	Stairwell adjacent to Classroom 535	Ceiling	Concrete	White	Flaking	33	0.2	Negative
1	5	H54	Hallway from Office 519A to Storeroom 503B	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	5	H54	Hallway from Office 519A to Storeroom 503B	W1	N/A	N/A	None	0	N/A	N/A
1	5	H54	Hallway from Office 519A to Storeroom 503B	W2	CMU	White	Chipping	15	0	Negative
1	5	H54	Hallway from Office 519A to Storeroom 503B	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	5	H54	Hallway from Office 519A to Storeroom 503B	W3	N/A	N/A	None	0	N/A	N/A
1	5	H54	Hallway from Office 519A to Storeroom 503B	W4	CMU	White	Chipping	20	0	Negative
1	5	H54	Hallway from Office 519A to Storeroom 503B	Radiator	Metal	Tan	Chipping	25	0.1	Negative
1	5	H54	Hallway from Office 519A to Storeroom 503B	Electrical Panel	Metal	Black	Chipping	2	0	Negative
1	5	H54	Hallway from Office 519A to Storeroom 503B	Pipe	Metal	White	Chipping	4	0.1	Negative
1	5	H54	Hallway from Office 519A to Storeroom 503B	Ceiling Beam	Concrete	White	Flaking	50	0.2	Negative
1	5	H51A	Custodial Closet across from Classroom 508	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	5	H51A	Custodial Closet across from Classroom 508	W1	CMU	White	Flaking	10	0.4	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm<sup>2</sup>)</b>	<b>XRF (positive/negative)</b>
1	5	H51A	Custodial Closet across from Classroom 508	Door Frame	Metal	Black	Chipping	3	0.4	Negative
1	5	H51A	Custodial Closet across from Classroom 508	Shelf Support (W1-3)	Wood	White	Chipping	5	0.3	Negative
1	5	H51A	Custodial Closet across from Classroom 508	Shelf (W1-3)	Wood	White	Friction	25	0.3	Negative
1	5	H51A	Custodial Closet across from Classroom 508	W2	CMU	White	Chipping	2	0.5	Negative
1	5	H51A	Custodial Closet across from Classroom 508	W3	CMU	White	Moisture Damage	20	0.4	Negative
1	5	H51A	Custodial Closet across from Classroom 508	Beam	Concrete	White	Flaking	2	0.3	Negative
1	5	H51A	Custodial Closet across from Classroom 508	W4	CMU	White	Flaking	14	0.5	Negative
1	5	H51A	Custodial Closet across from Classroom 508	Ceiling	Concrete	White	Flaking	1	0.3	Negative
1	4	S46	Stairwell next to Classroom 400	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	4	S46	Stairwell next to Classroom 400	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S46	Stairwell next to Classroom 400	Door Frame	Metal	Red	Chipping	4	1.6	Positive
1	4	S46	Stairwell next to Classroom 400	Door	Metal	Red	Friction	26	0.1	Negative
1	4	S46	Stairwell next to Classroom 400	W2	CMU	White	None	0	0.1	Negative
1	4	S46	Stairwell next to Classroom 400	riser	Metal	Tan	Chipping	26	0.1	Negative
1	4	S46	Stairwell next to Classroom 400	Stringer	Metal	Tan	Chipping	16	0.1	Negative
1	4	S46	Stairwell next to Classroom 400	Stair Pan	Metal	Tan	Moisture Damage	24	0.4	Negative
1	4	S46	Stairwell next to Classroom 400	W3	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	S46	Stairwell next to Classroom 400	Baseboard	Metal	Tan	Chipping	17	0	Negative
1	4	S46	Stairwell next to Classroom 400	W4	CMU	White	None	0	0.2	Negative
1	4	S46	Stairwell next to Classroom 400	Fire Pipe	Metal	White	Chipping	1	0.3	Negative
1	4	S46	Stairwell next to Classroom 400	Conduit	Metal	White	Chipping	8	0.5	Negative
1	4	S46	Stairwell next to Classroom 400	Ceiling	Concrete	White	Flaking	8	0.3	Negative
1	4	400	Computer Lab 400	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	400	Computer Lab 400	W1	CMU	Cream	None	0	0.3	Negative
1	4	400	Computer Lab 400	Door Frame	Metal	Black	Chipping	1	1	Positive
1	4	400	Computer Lab 400	W2	CMU	Cream	None	0	0.5	Negative
1	4	400	Computer Lab 400	W3	CMU	Cream	Chipping	1	0.5	Negative
1	4	400	Computer Lab 400	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	4	400	Computer Lab 400	Pipe Cover	Metal	Cream, White	None	0	0.1	Negative
1	4	400	Computer Lab 400	Pipe Insulation	Fiberglass	Cream, White	Flaking	2	0	Negative
1	4	400	Computer Lab 400	Univent	Metal	Gray	Chipping	1	0	Negative
1	4	400	Computer Lab 400	Univent	Metal	Black	Chipping	1	0.1	Negative
1	4	400	Computer Lab 400	Conduit	Metal	Cream	None	0	0.1	Negative
1	4	400	Computer Lab 400	Column	Concrete	Cream	None	0	0.3	Negative
1	4	400	Computer Lab 400	W4	CMU	Cream	None	0	0.4	Negative
1	4	400	Computer Lab 400	Ceiling Beam	Concrete	White	None	0	0.3	Negative
1	4	400	Computer Lab 400	Wood Cover on Beam	Wood	White	None	0	0.1	Negative
1	4	400A	Computer Lab 400 Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.8	Positive
1	4	400B	Computer Lab 400 Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	1.5	Positive
1	4	401	Computer Lab 401	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	401	Computer Lab 401	W1	CMU	Orange	Chipping	5	0.4	Negative
1	4	401	Computer Lab 401	Door Frame	Metal	Black	Chipping	5	0.9	Positive
1	4	401	Computer Lab 401	Baseboard (W1-4)	CMU/Tile	Black	None	0	0.9	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	401	Computer Lab 401	W2	CMU	Orange	Chipping	6	0.3	Negative
1	4	401	Computer Lab 401	W3	CMU	Orange	Flaking	8	0.5	Negative
1	4	401	Computer Lab 401	Column	Concrete	Orange	Flaking	15	0.1	Negative
1	4	401	Computer Lab 401	Univent	Metal	Grey	Chipping	14	0.1	Negative
1	4	401	Computer Lab 401	Pipe Cover	Metal	Orange	Chipping	3	0.2	Negative
1	4	401	Computer Lab 401	W4	CMU	Orange	Flaking	2	0.5	Negative
1	4	401	Computer Lab 401	Ceiling	Concrete	White	Flaking	4	0.3	Negative
1	4	401A	Computer Lab 401 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.7	Positive
1	4	401B	Computer Lab 401 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.8	Positive
1	4	402	Computer Lab 402	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	402	Computer Lab 402	W1	CMU	White	Flaking	8	0.4	Negative
1	4	402	Computer Lab 402	Door Frame	Metal	Black	Chipping	6	0.8	Positive
1	4	402	Computer Lab 402	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	1	Positive
1	4	402	Computer Lab 402	W2	CMU	White	Flaking	4	0.4	Negative
1	4	402	Computer Lab 402	Pipe Cover	Metal	White	Flaking	11	0.2	Negative
1	4	402	Computer Lab 402	W3	CMU	White	Flaking	10	0.5	Negative
1	4	402	Computer Lab 402	Univent	Metal	Grey	Chipping	6	0.2	Negative
1	4	402	Computer Lab 402	W4	CMU	White	Chipping	8	0.5	Negative
1	4	402	Computer Lab 402	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	4	402A	Computer Lab 402 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.9	Positive
1	4	402B	Computer Lab 402 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.8	Positive
1	4	403	Computer Lab 403	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	403	Computer Lab 403	W1	CMU	Yellow	Chipping	3	0.3	Negative
1	4	403	Computer Lab 403	Baseboard (W1-4)	CMU/Tile	Black	Friction	4	1.1	Positive
1	4	403	Computer Lab 403	Door Frame	Metal	Black	Chipping	7	1.5	Positive
1	4	403	Computer Lab 403	Conduit	Metal	Yellow	Flaking	1	0.5	Negative
1	4	403	Computer Lab 403	W2	CMU	Yellow	Flaking	5	0.4	Negative
1	4	403	Computer Lab 403	Column (W2/3)	Concrete	Yellow	Flaking	12	0.2	Negative
1	4	403	Computer Lab 403	Pipe	Metal	White	Flaking	10	0.3	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	4	403	Computer Lab 403	Pipe Cover (W2-4)	Metal	Yellow	Flaking	17	0.2	Negative
1	4	403	Computer Lab 403	Radiator (W2/3)	Metal	Yellow	Chipping	6	0.2	Negative
1	4	403	Computer Lab 403	W3	CMU	Yellow	Flaking	8	0.4	Negative
1	4	403	Computer Lab 403	Univent	Metal	Grey	Chipping	11	0.1	Negative
1	4	403	Computer Lab 403	W4	CMU	Yellow	Chipping	2	0.3	Negative
1	4	403	Computer Lab 403	Ceiling	Concrete	White	Flaking	10	0.3	Negative
1	4	403CA	Computer Lab 403 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	1.5	Positive
1	4	403CB	Computer Lab 403 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.9	Positive
1	4	403A	Office 403A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	403A	Office 403A	W1	CMU	Blue/Grey	Flaking	6	0.4	Negative
1	4	403A	Office 403A	Baseboard (W1-4)	CMU/Tile	Black	Friction	5	1.3	Positive
1	4	403A	Office 403A	Door Frame	Metal	Black	Chipping	7	1.1	Positive
1	4	403A	Office 403A	W2	CMU	Blue/Grey	Flaking	15	0	Negative
1	4	403A	Office 403A	W3	CMU	Blue/Grey	Flaking	29	0.2	Negative
1	4	403A	Office 403A	Pipe Cover	Metal	Blue	Chipping	2	0.2	Negative
1	4	403A	Office 403A	Univent	Metal	Grey	Chipping	2	0.1	Negative
1	4	403A	Office 403A	W3	CMU	Blue/Grey	Flaking	29	0.2	Negative
1	4	403A	Office 403A	W4	CMU	Blue/Grey	Flaking	2	0.4	Negative
1	4	403A	Office 403A	Ceiling	Concrete	White	Flaking	2	0.2	Negative
1	4	403ACA	Office 403A - Closet	Door Frame (W1)	Metal	Black	Chipping	1	0.9	Positive
1	4	404	Classroom 404	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	404	Classroom 404	W1	CMU	Blue	Flaking	11	0	Negative
1	4	404	Classroom 404	Door Frame	Metal	Black	Chipping	5	0.9	Positive
1	4	404	Classroom 404	Baseboard (W1-4)	CMU/Tile	Black	Friction	5	1.2	Positive
1	4	404	Classroom 404	Conduit (W1/4)	Metal	Blue/Grey	None	0	0.6	Negative
1	4	404	Classroom 404	W2	CMU	Blue	Flaking	3	0.1	Negative
1	4	404	Classroom 404	W3	CMU	Blue	Flaking	15	0	Negative
1	4	404	Classroom 404	Pipe Cover	Metal	Blue	Chipping	6	0.1	Negative
1	4	404	Classroom 404	Univent	Metal	Grey	Chipping	8	0	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	404	Classroom 404	Column	Concrete	Blue	Flaking	14	0.2	Negative
1	4	404	Classroom 404	W4	CMU	Blue	Chipping	5	0	Negative
1	4	404	Classroom 404	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	4	404A	Classroom 404 - Closet 1	Door Frame (W1)	Metal	Black	None	0	1	Positive
1	4	404B	Classroom 404 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	4	405	Computer Lab 405	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	405	Computer Lab 405	W1	CMU	White	Chipping	3	0.5	Negative
1	4	405	Computer Lab 405	Door Frame	Metal	Black	Chipping	5	1	Positive
1	4	405	Computer Lab 405	W2	CMU	White	None	0	0.4	Negative
1	4	405	Computer Lab 405	Conduit	Metal	White	None	0	0.5	Negative
1	4	405	Computer Lab 405	W3	CMU	White	Flaking	4	0.5	Negative
1	4	405	Computer Lab 405	Column	Concrete	White	Flaking	3	0.2	Negative
1	4	405	Computer Lab 405	Univent	Metal	Grey	Chipping	6	0.1	Negative
1	4	405	Computer Lab 405	Pipe Cover	Metal	White	None	0	0	Negative
1	4	405	Computer Lab 405	W4	CMU	White	Chipping	3	0.5	Negative
1	4	405	Computer Lab 405	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	4	405A	Computer Lab 405 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	2	0.9	Positive
1	4	405B	Computer Lab 405 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	2	0.9	Positive
1	4	406	Classroom 406	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	406	Classroom 406	Metal panel	Metal	Black	Chipping	10	0.1	Negative
1	4	406	Classroom 406	W1	CMU	White	None	0	0.4	Negative
1	4	406	Classroom 406	Doorframe	Metal	Black	Chipping	5	0	Negative
1	4	406	Classroom 406	Closet A Doorframe	Metal	Black	None	0	0.1	Negative
1	4	406	Classroom 406	Closet B Doorframe	Metal	Black	None	0	0.3	Negative
1	4	406	Classroom 406	W2	CMU	White	Chipping	5	0.5	Negative
1	4	406	Classroom 406	Baseboard	Tile	Black	None	0	1.2	Positive
1	4	406	Classroom 406	W3	CMU	White	Chipping	20	0.5	Negative
1	4	406	Classroom 406	Pipe Cover	Metal	White	Chipping	3	0.3	Negative
1	4	406	Classroom 406	pipe insulation	Fiberglass	White	Cracking	4	0.2	Negative
1	4	406	Classroom 406	Univent	Metal	Grey	Chipping	10	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	406	Classroom 406	W4	CMU	White	None	0	0.5	Negative
1	4	406	Classroom 406	Ceiling	Concrete	White	None	0	0.3	Negative
1	4	H42	Hallway from Classroom 400 to Office 403A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	H42	Hallway from Classroom 400 to Office 403A	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H42	Hallway from Classroom 400 to Office 403A	W2	CMU	White	Chipping	20	0.4	Negative
1	4	H42	Hallway from Classroom 400 to Office 403A	Pipe	Metal	White	None	0	0.2	Negative
1	4	H42	Hallway from Classroom 400 to Office 403A	Radiator	Metal	White	None	0	0.3	Negative
1	4	H42	Hallway from Classroom 400 to Office 403A	Vent	Metal	White	None	0	0.1	Negative
1	4	H42	Hallway from Classroom 400 to Office 403A	Baseboard	CMU/Tile	Black	None	0	1.2	Positive
1	4	H42	Hallway from Classroom 400 to Office 403A	Electrical Panel	Metal	Black	Chipping	4	0.1	Negative
1	4	H42	Hallway from Classroom 400 to Office 403A	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H42	Hallway from Classroom 400 to Office 403A	W4	CMU	White	Chipping	10	0.5	Negative
1	4	H42	Hallway from Classroom 400 to Office 403A	Ceiling	Concrete	White	Chipping	8	0.3	Negative
1	4	407	Classroom 407	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	407	Classroom 407	W1	CMU	Blue/Gray	Chipping	2	0.4	Negative
1	4	407	Classroom 407	Doorframe	Metal	Black	Chipping	1	0.2	Negative
1	4	407	Classroom 407	Closet Doorframe A	Metal	Black	Chipping	1	0.6	Negative
1	4	407	Classroom 407	Closet Door Frame B	Metal	Black	Chipping	1	0.9	Positive
1	4	407	Classroom 407	Pipe Cover	Metal	Gray, Black	Chipping, Flaking	2	0.4	Negative
1	4	407	Classroom 407	W2	CMU	Blue/Gray	Chipping, Flaking, Moisture Damage	8	0.4	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	407	Classroom 407	Baseboard	CMU/Tile	Black	Cracked	1	1	Positive
1	4	407	Classroom 407	Univent	Metal	Gray	Chipping	4	0.1	Negative
1	4	407	Classroom 407	Pipe Cover	Metal	Gray, Black	Chipping	2	0.1	Negative
1	4	407	Classroom 407	W3	CMU	Blue/Gray	Chipping, Flaking, Spalling	3	0.3	Negative
1	4	407	Classroom 407	Column	Concrete	Gray	Chipping	3	0.1	Negative
1	4	407	Classroom 407	Univent	Metal	Gray	Chipping	4	0.1	Negative
1	4	407	Classroom 407	W4	CMU	Blue/Gray	Chipping	1	0.3	Negative
1	4	407	Classroom 407	Ceiling	Concrete	White	Chipping, Flaking	2	0.3	Negative
1	4	407	Classroom 407	Ceiling Beam	Concrete	White	Flaking	1	0.4	Negative
1	4	408	Classroom 408	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	408	Classroom 408	W1	CMU	Cream	None	0	0.5	Negative
1	4	408	Classroom 408	Conduit	Metal	Cream	Chipping	4	0.6	Negative
1	4	408	Classroom 408	Door Frame	Metal	Black	Chipping	1	1.2	Positive
1	4	408	Classroom 408	Closet Door Frame A	Metal	Black	Chipping	1	0.8	Positive
1	4	408	Classroom 408	Baseboard	CMU/Tile	Black	None	0	0.9	Positive
1	4	408	Classroom 408	Closet Door Frame B	Metal	Black	Chipping	1	0.8	Positive
1	4	408	Classroom 408	W2	CMU	Cream	None	0	0.4	Negative
1	4	408	Classroom 408	W3	CMU	Cream	Chipping, Flaking	3	0	Negative
1	4	408	Classroom 408	Column	Concrete	Cream	Chipping	1	0.1	Negative
1	4	408	Classroom 408	Pipe Cover	Metal	Cream	Chipping	4	0.1	Negative
1	4	408	Classroom 408	Pipe Insulation	Fiberglass	Cream	Chipping	4	0	Negative
1	4	408	Classroom 408	Univent	Metal	Gray	Chipping	3	0.2	Negative
1	4	408	Classroom 408	W4	CMU	Cream	Chipping	1	0.4	Negative
1	4	408	Classroom 408	Chalkboard	Wood	Cream	Chipping	2	0.1	Negative
1	4	408	Classroom 408	Ceiling	Concrete	White	Chipping, Flaking	15	0.3	Negative
1	4	408	Classroom 408	Ceiling Beam	Concrete	White	Chipping, Flaking	6	0.3	Negative
1	4	408B	Janitor's Closet across from Classroom 408	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	408B	Janitor's Closet across from Classroom 408	W1	CMU	Tan	Flaking	7	0.3	Negative
1	4	408B	Janitor's Closet across from Classroom 408	Door Frame	Metal	Black	None	0	0.7	Positive
1	4	408B	Janitor's Closet across from Classroom 408	Door	Wood	Red	Chipping	3	0	Negative
1	4	408B	Janitor's Closet across from Classroom 408	W2	CMU	Tan	Flaking	16	0.4	Negative
1	4	408B	Janitor's Closet across from Classroom 408	W3	CMU	Tan	Flaking	6	0.3	Negative
1	4	408B	Janitor's Closet across from Classroom 408	W4	CMU	Tan	Flaking	4	0.4	Negative
1	4	408B	Janitor's Closet across from Classroom 408	Shelf	Wood	Tan	Chipping	44	1.8	Positive
1	4	408B	Janitor's Closet across from Classroom 408	Ceiling	Concrete	White	No Access	0	0.4	Negative
1	4	408A	Room next to Elevator # 1 (South Elevator)	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	408A	Room next to Elevator # 1 (South Elevator)	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	408A	Room next to Elevator # 1 (South Elevator)	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	408A	Room next to Elevator # 1 (South Elevator)	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	408A	Room next to Elevator # 1 (South Elevator)	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	408A	Room next to Elevator # 1 (South Elevator)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	409	Classroom 409	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	409	Classroom 409	W1	CMU	White	None	0	0.2	Negative
1	4	409	Classroom 409	Door Frame	Metal	Black	Chipping	1	0.7	Positive
1	4	409	Classroom 409	Closet Door Frame A	Metal	Black	Chipping	1	0.8	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	409	Classroom 409	Closet Door Frame B	Metal	Black	Chipping	1	1	Positive
1	4	409	Classroom 409	Baseboard	CMU/Tile	Black	None	0	1.4	Positive
1	4	409	Classroom 409	W2	CMU	White	None	0	0.4	Negative
1	4	409	Classroom 409	W3	CMU	White	None	0	0.5	Negative
1	4	409	Classroom 409	Pipe Cover	Metal	White	Chipping	1	0.2	Negative
1	4	409	Classroom 409	Pipe Insulation	Fiberglass	White	None	0	0	Negative
1	4	409	Classroom 409	Univent	Metal	Gray	Chipping	4	0.2	Negative
1	4	409	Classroom 409	Column	Concrete	White	None	0	0.2	Negative
1	4	409	Classroom 409	W4	CMU	White	None	0	0.4	Negative
1	4	409	Classroom 409	Conduit	Metal	White	None	0	0.6	Negative
1	4	409	Classroom 409	Ceiling	Concrete	White	Chipping, Flaking	10	0.3	Negative
1	4	410	Classroom 410	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	410	Classroom 410	W1	CMU	Peach	Chipping	3	0.5	Negative
1	4	410	Classroom 410	Door Frame	Metal	Black	Chipping	1	0.7	Positive
1	4	410	Classroom 410	Closet Door Frame A	Metal	Black	Chipping	1	0.8	Positive
1	4	410	Classroom 410	Closet Door Frame B	Metal	Black	Chipping	1	1	Positive
1	4	410	Classroom 410	Baseboard	CMU/Tile	Black	None	0	1.2	Positive
1	4	410	Classroom 410	W2	CMU	Peach	Chipping, Flaking	2	0.4	Negative
1	4	410	Classroom 410	W3	CMU	Peach	Chipping, Flaking	3	0.3	Negative
1	4	410	Classroom 410	Pipe Cover	Metal	Peach	Chipping, Flaking	3	0.4	Negative
1	4	410	Classroom 410	Pipe Insulation	Fiberglass	Peach	None	0	0	Negative
1	4	410	Classroom 410	Pipe Insulation	Fiberglass	White	None	0	0	Negative
1	4	410	Classroom 410	Univent	Metal	Gray	Chipping	3	0.2	Negative
1	4	410	Classroom 410	Column	Concrete	Peach	Chipping, Flaking	3	0.3	Negative
1	4	410	Classroom 410	W4	CMU	Peach	Chipping	1	0.3	Negative
1	4	410	Classroom 410	Conduit	Metal	Peach	Flaking	2	0.3	Negative
1	4	410	Classroom 410	Ceiling	Concrete	White	Chipping, Flaking	5	0.2	Negative
1	4	410A	Storeroom 410A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	410A	Storeroom 410A	W1	CMU	Yellow/White	Cracking	16	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	410A	Storeroom 410A	Door Frame	Metal	Black	Chipping	5	0.9	Positive
1	4	410A	Storeroom 410A	Baseboard (W1-4)	CMU/Tile	Black	Chipping	5	0.9	Positive
1	4	410A	Storeroom 410A	W2	CMU	Yellow/White	Chipping	2	0.4	Negative
1	4	410A	Storeroom 410A	W3	CMU	Yellow/White	Flaking	8	0.4	Negative
1	4	410A	Storeroom 410A	Pipe Cover	Metal	White	Flaking	4	0.2	Negative
1	4	410A	Storeroom 410A	Column	Concrete	White	Flaking	9	0.2	Negative
1	4	410A	Storeroom 410A	Radiator	Metal	Yellow	Flaking	6	0.2	Negative
1	4	410A	Storeroom 410A	W4	CMU	Yellow/White	Flaking	3	0.5	Negative
1	4	410A	Storeroom 410A	Ceiling	Concrete	White	Flaking	3	0.4	Negative
1	4	410AC	Storeroom 410A - Closet	Door Frame (W1)	Metal	Black	Chipping	5	0.9	Positive
1	4	S47	Stairwell next to Classroom 410	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	4	S47	Stairwell next to Classroom 410	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	4	S47	Stairwell next to Classroom 410	Doorframe	Metal	Red	Chipping	4	0.2	Negative
1	4	S47	Stairwell next to Classroom 410	Door	Metal	Red	Friction	7	0.1	Negative
1	4	S47	Stairwell next to Classroom 410	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S47	Stairwell next to Classroom 410	Baseboard	Ceramic	Black	Chipping	8	2.1	Positive
1	4	S47	Stairwell next to Classroom 410	Conduit	Metal	Tan	Chipping	2	0.3	Negative
1	4	S47	Stairwell next to Classroom 410	Riser	Metal	Black	Chipping	20	0.1	Negative
1	4	S47	Stairwell next to Classroom 410	Stringer	Metal	Black	Chipping	8	0.1	Negative
1	4	S47	Stairwell next to Classroom 410	Stair Pan	Metal	Tan	Moisture Damage	12	0.8	Positive
1	4	S47	Stairwell next to Classroom 410	W3	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	S47	Stairwell next to Classroom 410	Baseboard	Metal	Black	Chipping	3	0.1	Negative
1	4	S47	Stairwell next to Classroom 410	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S47	Stairwell next to Classroom 410	Ceiling	Concrete	White	Flaking	8	0.5	Negative
1	4	410B	Women's Lounge across from Classroom 413	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410B	Women's Lounge across from Classroom 413	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410B	Women's Lounge across from Classroom 413	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410B	Women's Lounge across from Classroom 413	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410B	Women's Lounge across from Classroom 413	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410B	Women's Lounge across from Classroom 413	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410D	Women's Rear Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410D	Women's Rear Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410D	Women's Rear Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410D	Women's Rear Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410D	Women's Rear Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410D	Women's Rear Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410E	Women's Front Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410E	Women's Front Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410E	Women's Front Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410E	Women's Front Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410E	Women's Front Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410E	Women's Front Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410C	Room next to Elevator # 2 (Center Elevator)	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	410C	Room next to Elevator # 2 (Center Elevator)	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410C	Room next to Elevator # 2 (Center Elevator)	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410C	Room next to Elevator # 2 (Center Elevator)	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410C	Room next to Elevator # 2 (Center Elevator)	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	410C	Room next to Elevator # 2 (Center Elevator)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	411	Classroom 411	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	411	Classroom 411	W1	CMU	Peach, White	Chipping	2	0.4	Negative
1	4	411	Classroom 411	Door Frame	Metal	Black	Chipping	1	0.2	Negative
1	4	411	Classroom 411	Closet Door Frame A	Metal	Black	Chipping	1	0.7	Positive
1	4	411	Classroom 411	Closet Door Frame B	Metal	Black	Chipping	1	1.1	Positive
1	4	411	Classroom 411	W2	CMU	Peach, White	Chipping	3	0.4	Negative
1	4	411	Classroom 411	W3	CMU	Peach, White	Chipping, Flaking	3	0.1	Negative
1	4	411	Classroom 411	Univent	Metal	Gray	Chipping	4	0	Negative
1	4	411	Classroom 411	Column	Concrete	Peach	Chipping, Flaking	4	0.1	Negative
1	4	411	Classroom 411	Pipe Cover	Metal	Peach	Flaking	1	0.4	Negative
1	4	411	Classroom 411	Pipe Insulation	Fiberglass	White	None	0	0.1	Negative
1	4	411	Classroom 411	Baseboard	Ceramic	Black	None	0	1.2	Positive
1	4	411	Classroom 411	W4	CMU	Peach, White	Chipping	1	0.5	Negative
1	4	411	Classroom 411	Ceiling	Concrete	White	Chipping, Flaking	5	0.3	Negative
1	4	412	Classroom 412	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	412	Classroom 412	W1	CMU	Gray, Blue, White	None	0	0.5	Negative
1	4	412	Classroom 412	Door	Wood	Blue	None	0	0.1	Negative
1	4	412	Classroom 412	Door Frame	Metal	Black	Chipping	1	0.9	Positive
1	4	412	Classroom 412	Closet Door A	Wood	Blue	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	412	Classroom 412	Closet Door Frame A	Metal	Black	Chipping	1	0.8	Positive
1	4	412	Classroom 412	Closet Door B	Wood	Blue	None	0	0.1	Negative
1	4	412	Classroom 412	Closet Door Frame B	Metal	Black	Chipping	1	0.8	Positive
1	4	412	Classroom 412	W2	CMU	Gray, Blue, White	None	0	0.3	Negative
1	4	412	Classroom 412	Baseboard	Ceramic	Black	None	0	1.3	Positive
1	4	412	Classroom 412	W3	CMU	Gray, Blue, White	None	0	0.5	Negative
1	4	412	Classroom 412	Column	Concrete	Gray, Blue, White	None	0	0.1	Negative
1	4	412	Classroom 412	Univent	Metal	Gray	Chipping	4	0.1	Negative
1	4	412	Classroom 412	Pipe Cover	Metal	Gray	Chipping	2	0.4	Negative
1	4	412	Classroom 412	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	4	412	Classroom 412	Pipe	Metal	Gray	Chipping, Flaking	8	0.4	Negative
1	4	412	Classroom 412	W4	CMU	Gray, Blue, White	None	0	0.4	Negative
1	4	412	Classroom 412	Ceiling	Concrete	White	Flaking	7	0.2	Negative
1	4	412A	Counselor's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	412A	Counselor's Office	W1	CMU	Green, White	None	0	0.4	Negative
1	4	412A	Counselor's Office	Door	Wood	Green	Chipping	1	0.1	Negative
1	4	412A	Counselor's Office	Door Frame	Metal	Gray	Chipping	1	0.8	Positive
1	4	412A	Counselor's Office	Baseboard	Ceramic	Black	None	0	1.3	Positive
1	4	412A	Counselor's Office	Bulletin Board	Wood	Gray	None	0	0.2	Negative
1	4	412A	Counselor's Office	W2	CMU	Green, White	None	0	0.4	Negative
1	4	412A	Counselor's Office	W3	CMU	Green, White	None	0	0	Negative
1	4	412A	Counselor's Office	Univent	Metal	Gray	Chipping	1	0.2	Negative
1	4	412A	Counselor's Office	Pipe Cover	Metal	Gray	None	0	0.3	Negative
1	4	412A	Counselor's Office	Pipe Insulation	Fiberglass	Gray/White	Flaking	1	0	Negative
1	4	412A	Counselor's Office	Column	Concrete	Green, White	None	0	0.2	Negative
1	4	412A	Counselor's Office	W4	CMU	Green, White	None	0	0.4	Negative
1	4	412A	Counselor's Office	Conduit	Metal	Yellow	Chipping	1	0.6	Negative



			<b>Lead-Safe Certification Assessment Report</b>							
			<b>South Philadelphia High School</b>							
			<b>2101 S Broad St, Philadelphia, PA 19148</b>							
<b>E</b>	<b>F</b>									
<b>l</b>	<b>l</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
<b>e</b>	<b>o</b>									
<b>m</b>	<b>r</b>									
<b>e</b>										
<b>n</b>										
<b>t</b>										
1	4	412A	Counselor's Office	Ceiling	Concrete	White	None	0	0.2	Negative
1	4	413	Classroom 413	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	413	Classroom 413	W1	CMU	Cream	Chipping, Flaking	8	0.3	Negative
1	4	413	Classroom 413	Baseboard	Ceramic	Black	None	0	1	Positive
1	4	413	Classroom 413	Conduit	Metal	Cream	None	0	0.3	Negative
1	4	413	Classroom 413	Door Frame	Metal	Black	Chipping	1	0.6	Negative
1	4	413	Classroom 413	Closet Door Frame A	Metal	Black	Chipping	1	1.3	Positive
1	4	413	Classroom 413	Closet Door Frame B	Metal	Black	Chipping	1	1.1	Positive
1	4	413	Classroom 413	W2	CMU	Cream	Chipping, Flaking	10	0.4	Negative
1	4	413	Classroom 413	W3	CMU	Cream	Chipping, Flaking	10	0.5	Negative
1	4	413	Classroom 413	Column	Concrete	Cream	Chipping	2	0.2	Negative
1	4	413	Classroom 413	Pipe Cover	Metal	Cream	Flaking	3	0.1	Negative
1	4	413	Classroom 413	Pipe Insulation	Fiberglass	White	None	0	0	Negative
1	4	413	Classroom 413	Pipe	Metal	White	Flaking	1	0.1	Negative
1	4	413	Classroom 413	Expansion Joint	Metal	Cream	Flaking	3	0.4	Negative
1	4	413	Classroom 413	Univent	Metal	Gray	Chipping	5	0.1	Negative
1	4	413	Classroom 413	W4	CMU	Cream	Chipping, Flaking	2	0.5	Negative
1	4	413	Classroom 413	Ceiling	Concrete	White	Flaking	15	0.4	Negative
1	4	414	Classroom 414	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	414	Classroom 414	W1	CMU	Blue/Grey	Flaking	15	0.5	Negative
1	4	414	Classroom 414	Door Frame	Metal	Black	Chipping	4	0.9	Positive
1	4	414	Classroom 414	Baseboard (W1-4)	CMU/Tile	Black	Friction	6	1.3	Positive
1	4	414	Classroom 414	W2	CMU	Blue/Grey	Flaking	10	0.5	Negative
1	4	414	Classroom 414	W3	CMU	Blue/Grey	Flaking	30	0.5	Negative
1	4	414	Classroom 414	Column	Concrete	Blue/Grey	Flaking	10	0.2	Negative
1	4	414	Classroom 414	Pipe Cover	Metal	Blue/Grey	Flaking	5	0.2	Negative
1	4	414	Classroom 414	Univent	Metal	Grey	Chipping	12	0.2	Negative
1	4	414	Classroom 414	W4	CMU	Blue/Grey	Flaking	10	0.4	Negative
1	4	414	Classroom 414	Ceiling	Concrete	White	Flaking	15	0.2	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>South Philadelphia High School</b>							
			<b>2101 S Broad St, Philadelphia, PA 19148</b>							
<b>E</b>	<b>F</b>									
<b>l</b>	<b>l</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
<b>e</b>	<b>o</b>									
<b>n</b>	<b>r</b>									
<b>t</b>										
1	4	414A	Classroom 414 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	4	414B	Classroom 414 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.9	Positive
1	4	414A	Janitor's Closet next to Classroom 414	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	414A	Janitor's Closet next to Classroom 414	W1	CMU	Tan	Chipping	4	0.4	Negative
1	4	414A	Janitor's Closet next to Classroom 414	W2	CMU	Tan	Flaking	10	0.5	Negative
1	4	414A	Janitor's Closet next to Classroom 414	Electrical Panel	Metal	Tan	Flaking	3	0.1	Negative
1	4	414A	Janitor's Closet next to Classroom 414	Conduit	Metal	Tan	Chipping	6	0.2	Negative
1	4	414A	Janitor's Closet next to Classroom 414	Pipe	Metal	Tan	Flaking	2	0.6	Negative
1	4	414A	Janitor's Closet next to Classroom 414	Doorframe	Metal	Black	Chipping	12	0.5	Negative
1	4	414A	Janitor's Closet next to Classroom 414	W3	CMU	Tan	Flaking	10	0.5	Negative
1	4	414A	Janitor's Closet next to Classroom 414	W4	CMU	Tan	Flaking	26	0.5	Negative
1	4	414A	Janitor's Closet next to Classroom 414	Shelf	Wood	Tan	Chipping	50	0.5	Negative
1	4	414A	Janitor's Closet next to Classroom 414	Ceiling	Concrete	White	None	0	0	Negative
1	4	414B	Storeroom across from Classroom 413	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	414B	Storeroom across from Classroom 413	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	414B	Storeroom across from Classroom 413	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	414B	Storeroom across from Classroom 413	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	414B	Storeroom across from Classroom 413	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	414B	Storeroom across from Classroom 413	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	415	Classroom 415	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	415	Classroom 415	W1	CMU	White	Chipping	16	0.5	Negative
1	4	415	Classroom 415	Door Frame	Metal	Black	Chipping	5	0.5	Negative
1	4	415	Classroom 415	Baseboard (W1-4)	CMU/Tile	Black	Chipping	2	1.2	Positive
1	4	415	Classroom 415	W2	CMU	White	Flaking	13	0.5	Negative
1	4	415	Classroom 415	W3	CMU	White	Flaking	4	0.3	Negative
1	4	415	Classroom 415	Column	Concrete	White	Flaking	5	0.1	Negative
1	4	415	Classroom 415	Pipe Cover	Metal	White	Chipping	5	0.1	Negative
1	4	415	Classroom 415	Univent	Metal	Grey	Chipping	8	0.1	Negative
1	4	415	Classroom 415	W4	CMU	White	Flaking	6	0.5	Negative
1	4	415	Classroom 415	Ceiling	Concrete	White	Flaking	2	0.3	Negative
1	4	415A	Classroom 415 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	4	415B	Classroom 415 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	4	416	Classroom 416	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	416	Classroom 416	W1	CMU	White	Flaking	8	0.1	Negative
1	4	416	Classroom 416	Door Frame	Metal	Black	Chipping	5	0.8	Positive
1	4	416	Classroom 416	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.1	Positive
1	4	416	Classroom 416	W2	CMU	White	Flaking	10	0.3	Negative
1	4	416	Classroom 416	W3	CMU	White	Flaking	4	0.3	Negative
1	4	416	Classroom 416	Column	Concrete	White	Flaking	6	0.1	Negative
1	4	416	Classroom 416	Univent	Metal	Grey	Chipping	7	0.2	Negative
1	4	416	Classroom 416	Pipe Cover	Metal	White	Chipping	5	0.1	Negative
1	4	416	Classroom 416	W4	CMU	White	Flaking	8	0.2	Negative
1	4	416	Classroom 416	Ceiling	Concrete	White	Flaking	10	0.2	Negative
1	4	416A	Classroom 416 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	4	416B	Classroom 416 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.7	Positive
1	4	417	Classroom 417	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	417	Classroom 417	W1	CMU	Orange	Chipping	21	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	417	Classroom 417	Door Frame	Metal	Black	Chipping	8	1	Positive
1	4	417	Classroom 417	Baseboard (W1-4)	CMU/Tile	Black	Friction	6	1.2	Positive
1	4	417	Classroom 417	W2	CMU	Orange	Flaking	9	0.2	Negative
1	4	417	Classroom 417	W3	CMU	Orange	Flaking	11	0.3	Negative
1	4	417	Classroom 417	Column	Concrete	White	Chipping	6	0.3	Negative
1	4	417	Classroom 417	Pipe Cover	Metal	White	Chipping	8	0.2	Negative
1	4	417	Classroom 417	Univent	Metal	Grey	Chipping	11	0.2	Negative
1	4	417	Classroom 417	W4	CMU	Orange	Flaking	7	0.3	Negative
1	4	417	Classroom 417	Ceiling	Concrete	White	None	0	0.2	Negative
1	4	417A	Classroom 417 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	2	0.9	Positive
1	4	417B	Classroom 417 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	2	0.8	Positive
1	4	418	Classroom 418	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	418	Classroom 418	W1	CMU	Green	Chipping	5	0.4	Negative
1	4	418	Classroom 418	Door Frame	Metal	Black	Chipping	6	0.7	Positive
1	4	418	Classroom 418	Baseboard (W1-4)	CMU/Tile	Black	Friction	5	1.1	Positive
1	4	418	Classroom 418	W2	CMU	Green	Chipping	3	0.5	Negative
1	4	418	Classroom 418	Radiator	Metal	Green	Chipping	11	0.3	Negative
1	4	418	Classroom 418	W3	CMU	Green	Flaking	8	0.4	Negative
1	4	418	Classroom 418	Column	Concrete	Green	Flaking	6	0.4	Negative
1	4	418	Classroom 418	Univent	Metal	Grey	Chipping	5	0	Negative
1	4	418	Classroom 418	Pipe	Metal	White	Chipping	10	0.4	Negative
1	4	418	Classroom 418	W4	CMU	Green	Chipping	2	0.2	Negative
1	4	418	Classroom 418	Ceiling	Concrete	White	Flaking	24	0.2	Negative
1	4	418CA	Classroom 418 - Closet 1	Door Frame (W1)	Metal	Black	None	0	1	Positive
1	4	418CB	Classroom 418 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	1	Positive
1	4	H43	Hallway from Classrooms 414 to 418	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	H43	Hallway from Classrooms 414 to 418	W1	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	H43	Hallway from Classrooms 414 to 418	W2	CMU	White	Chipping	18	0.5	Negative
1	4	H43	Hallway from Classrooms 414 to 418	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	4	H43	Hallway from Classrooms 414 to 418	Radiator	Metal	White	None	0	0.2	Negative
1	4	H43	Hallway from Classrooms 414 to 418	Electrical Panel	Metal	Black	Chipping	5	0	Negative
1	4	H43	Hallway from Classrooms 414 to 418	Vent	Metal	White	None	0	0.1	Negative
1	4	H43	Hallway from Classrooms 414 to 418	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H43	Hallway from Classrooms 414 to 418	W4	CMU	White	Chipping	5	0.4	Negative
1	4	H43	Hallway from Classrooms 414 to 418	Ceiling	Concrete	White	None	0	0.3	Negative
1	4	418A	Office 418A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	418A	Office 418A	W1	CMU	White	None	0	0.4	Negative
1	4	418A	Office 418A	Door Frame	Metal	Black	Chipping	3	0.7	Positive
1	4	418A	Office 418A	Baseboard (W1-4)	CMU/Tile	Black	Chipping	2	1	Positive
1	4	418A	Office 418A	W2	CMU	White	Chipping	8	0.4	Negative
1	4	418A	Office 418A	W3	CMU	White	Flaking	14	0.3	Negative
1	4	418A	Office 418A	Column	Concrete	White	Flaking	3	0.2	Negative
1	4	418A	Office 418A	Univent	Metal	Grey	Chipping	8	0.2	Negative
1	4	418A	Office 418A	Pipe	Metal	White	Chipping	2	0.5	Negative
1	4	418A	Office 418A	W4	CMU	White	Chipping	4	0.3	Negative
1	4	418A	Office 418A	Ceiling	Concrete	White	Flaking	5	0.2	Negative
1	4	S45	Stairwell # 4 next to Office 418A	Floor	tile	N/A	N/A	N/A	N/A	N/A
1	4	S45	Stairwell # 4 next to Office 418A	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	4	S45	Stairwell # 4 next to Office 418A	Doorframe	Metal	Red	Chipping	4	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	S45	Stairwell # 4 next to Office 418A	Door	Metal	Red	Friction	7	0.1	Negative
1	4	S45	Stairwell # 4 next to Office 418A	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S45	Stairwell # 4 next to Office 418A	Baseboard	Ceramic	Black	Chipping	8	2.1	Positive
1	4	S45	Stairwell # 4 next to Office 418A	Conduit	Metal	Tan	Chipping	2	0.3	Negative
1	4	S45	Stairwell # 4 next to Office 418A	Riser	Metal	Black	Chipping	20	0.1	Negative
1	4	S45	Stairwell # 4 next to Office 418A	Stringer	Metal	Black	Chipping	8	0.1	Negative
1	4	S45	Stairwell # 4 next to Office 418A	Stair Pan	Metal	Tan	Moisture Damage	12	0.8	Positive
1	4	S45	Stairwell # 4 next to Office 418A	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S45	Stairwell # 4 next to Office 418A	Baseboard	Metal	Black	Chipping	3	0.1	Negative
1	4	S45	Stairwell # 4 next to Office 418A	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S45	Stairwell # 4 next to Office 418A	Ceiling	Concrete	White	Flaking	8	0.5	Negative
1	4	419	Classroom 419	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	419	Classroom 419	W1	CMU	White	Flaking	6	0.5	Negative
1	4	419	Classroom 419	Door Frame	Metal	Black	Chipping	4	0.9	Positive
1	4	419	Classroom 419	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	4	419	Classroom 419	W2	CMU	White	Flaking	4	0.3	Negative
1	4	419	Classroom 419	Door Frame (W2)	Metal	Black	Chipping	1	0.9	Positive
1	4	419	Classroom 419	W3	CMU	White	Flaking	3	0.5	Negative
1	4	419	Classroom 419	Univent	Metal	Black	Flaking	19	0.2	Negative
1	4	419	Classroom 419	Column	Concrete	White	Flaking	23	0.4	Negative
1	4	419	Classroom 419	Pipe	Metal	White	Flaking	7	0.2	Negative
1	4	419	Classroom 419	W4	CMU	White	Cracking	4	0.5	Negative

			Dates: 7/11 - 8/31/2022		<b>Lead-Safe Certification Assessment Report</b>					
			Inspector Name and Certificate Number: Charles Rhodes 003542		<b>South Philadelphia High School</b>					
			Inspection Company: BATTA		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E</b>	<b>F</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	4	419	Classroom 419	Door Frame	Metal	Black	Chipping	1	0.8	positive
1	4	419	Classroom 419	Ceiling	Concrete	White	Flaking	8	0.3	Negative
1	4	419A	Classroom 419 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	419A	Classroom 419 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	419A	Classroom 419 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	419A	Classroom 419 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	419A	Classroom 419 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	419A	Classroom 419 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420B	Storeroom between Classrooms 419 and 420	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420B	Storeroom between Classrooms 419 and 420	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420B	Storeroom between Classrooms 419 and 420	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420B	Storeroom between Classrooms 419 and 420	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420B	Storeroom between Classrooms 419 and 420	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420B	Storeroom between Classrooms 419 and 420	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420	Classroom 420	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	420	Classroom 420	W1	CMU	White	Flaking	6	0.5	Negative
1	4	420	Classroom 420	Door Frame	Metal	Black	Chipping	4	0.9	Positive
1	4	420	Classroom 420	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	4	420	Classroom 420	W2	CMU	White	Flaking	4	0.3	Negative
1	4	420	Classroom 420	Door Frame (W2)	Metal	Black	Chipping	1	0.9	Positive
1	4	420	Classroom 420	W3	CMU	White	Flaking	3	0.5	Negative
1	4	420	Classroom 420	Univent	Metal	Black	Flaking	19	0.2	Negative
1	4	420	Classroom 420	Column	Concrete	White	Flaking	23	0.4	Negative
1	4	420	Classroom 420	Pipe	Metal	White	Flaking	7	0.2	Negative
1	4	420	Classroom 420	W4	CMU	White	Cracking	4	0.5	Negative
1	4	420	Classroom 420	Door Frame	Metal	Black	Chipping	1	0.8	positive



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	420	Classroom 420	Ceiling	Concrete	White	Flaking	8	0.3	Negative
1	4	420	Classroom 420	Beam (C)	Concrete	White	Flaking	10	0.2	Negative
1	4	420A	Classroom 420 Small Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420A	Classroom 420 Small Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420A	Classroom 420 Small Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420A	Classroom 420 Small Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420A	Classroom 420 Small Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420A	Classroom 420 Small Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420C	Classroom 420 Large Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420C	Classroom 420 Large Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420C	Classroom 420 Large Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420C	Classroom 420 Large Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420C	Classroom 420 Large Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	420C	Classroom 420 Large Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S41	Stairwell # 5 across from Classroom 421	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S41	Stairwell # 5 across from Classroom 421	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	4	S41	Stairwell # 5 across from	Doorframe	Metal	Red	Chipping	4	0.2	Negative
1	4	S41	Stairwell # 5 across from	Door	Metal	Red	Friction	7	0.1	Negative
1	4	S41	Stairwell # 5 across from	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S41	Stairwell # 5 across from	Baseboard	Ceramic	Black	Chipping	8	2.1	Positive
1	4	S41	Stairwell # 5 across from	Conduit	Metal	Tan	Chipping	2	0.3	Negative
1	4	S41	Stairwell # 5 across from	Riser	Metal	Black	Chipping	20	0.1	Negative
1	4	S41	Stairwell # 5 across from	Stringer	Metal	Black	Chipping	8	0.1	Negative
1	4	S41	Stairwell # 5 across from	Stair Pan	Metal	Tan	Moisture Damage	12	0.8	Positive
1	4	S41	Stairwell # 5 across from	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S41	Stairwell # 5 across from Classroom 421	Baseboard	Metal	Black	Chipping	3	0.1	Negative
1	4	S41	Stairwell # 5 across from Classroom 421	W4	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	S41	Stairwell # 5 across from Classroom 421	Ceiling	Concrete	White	Flaking	8	0.5	Negative
1	4	421	Classroom 421	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	421	Classroom 421	W1	CMU	Teal	Chipping	2	0.4	Negative
1	4	421	Classroom 421	Door Frame	Metal	Black	Chipping	1	0	Negative
1	4	421	Classroom 421	Baseboard	Ceramic	Black	None	0	1.1	Positive
1	4	421	Classroom 421	Closet Door Frame A	Metal	Black	Chipping	1	0.7	Positive
1	4	421	Classroom 421	Closet Door Frame B	Metal	Black	Chipping	1	0.6	Negative
1	4	421	Classroom 421	W2	CMU	Teal	Chipping, Flaking	3	0.5	Negative
1	4	421	Classroom 421	W3	CMU	Teal	Chipping, Flaking	4	0.5	Negative
1	4	421	Classroom 421	Column	Concrete	Teal	None	0	0.1	Negative
1	4	421	Classroom 421	Pipe Cover	Metal	Teal	None	0	0.3	Negative
1	4	421	Classroom 421	Pipe Insulation	Fiberglass	Teal	None	0	0	Negative
1	4	421	Classroom 421	Univent	Metal	Gray	Chipping	3	0.2	Negative
1	4	421	Classroom 421	W4	CMU	Teal	None	0	0.4	Negative
1	4	421	Classroom 421	Ceiling	Concrete	White	Flaking	5	0.4	Negative
1	4	421	Classroom 421	Ceiling Beam	Concrete	Teal	None	0	0.3	Negative
1	4	422	Classroom 422	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	422	Classroom 422	W1	CMU	Peach	Chipping, Flaking	2	0.3	Negative
1	4	422	Classroom 422	Door Frame	Metal	Black	Chipping	1	0.2	Negative
1	4	422	Classroom 422	Closet Door Frame A	Metal	Black	Chipping	1	0.3	Negative
1	4	422	Classroom 422	Closet Door Frame B	Metal	Black	Chipping	1	0.8	Positive
1	4	422	Classroom 422	W2	CMU	Peach	Chipping, Flaking	2	0.5	Negative
1	4	422	Classroom 422	W3	CMU	Peach	Chipping	4	0.5	Negative
1	4	422	Classroom 422	Column	Concrete	Peach, Tan	Flaking	3	0.2	Negative
1	4	422	Classroom 422	Pipe Cover	Metal	Peach	Chipping, Flaking	2	0.1	Negative
1	4	422	Classroom 422	Pipe Insulation	Fiberglass	White	None	0	0	Negative
1	4	422	Classroom 422	Univent	Metal	Gray	Chipping, Friction	3	0.1	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E</b>	<b>F</b>									
<b>l</b>	<b>l</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
<b>e</b>	<b>o</b>									
<b>m</b>	<b>r</b>									
<b>e</b>										
<b>n</b>										
<b>t</b>										
1	4	422	Classroom 422	Baseboard	Ceramic	Black	Cracked	1	1.1	Positive
1	4	422	Classroom 422	W4	CMU	Peach	None	0	0.3	Negative
1	4	422	Classroom 422	Ceiling	Concrete	White	Flaking	5	0.3	Negative
1	4	423	Classroom 423	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	423	Classroom 423	W1	CMU	Blue/White	Chipping	15	0.4	Negative
1	4	423	Classroom 423	Door Frame	Metal	Black	Chipping	8	0.8	Positive
1	4	423	Classroom 423	Baseboard (W1-4)	CMU/Tile	Black	Friction	5	0.9	Positive
1	4	423	Classroom 423	W2	CMU	Blue/White	Flaking	6	0.5	Negative
1	4	423	Classroom 423	W3	CMU	Blue/White	Flaking	10	0.3	Negative
1	4	423	Classroom 423	Column	Concrete	Blue	Flaking	14	0.1	Negative
1	4	423	Classroom 423	Univent	Metal	Grey	Chipping	12	0.2	Negative
1	4	423	Classroom 423	Pipe Cover	Metal	Grey	Flaking	4	0	Negative
1	4	423	Classroom 423	W4	CMU	Blue/White	Chipping	7	0.4	Negative
1	4	423	Classroom 423	Conduit	Metal	Blue/White	None	0	0.4	Negative
1	4	423	Classroom 423	Ceiling	Concrete	White	Flaking	26	0.3	Negative
1	4	423A	Classroom 423 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	2	0.8	Positive
1	4	423B	Classroom 423 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.8	Positive
1	4	424	Classroom 424	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	424	Classroom 424	W1	CMU	White	None	0	0.4	Negative
1	4	424	Classroom 424	Door Frame	Metal	Black	Chipping	1	1.1	Positive
1	4	424	Classroom 424	Closet Door Frame A	Metal	Black	Chipping	1	0.8	Positive
1	4	424	Classroom 424	Closet Door Frame B	Metal	Black	Chipping	1	0.7	Positive
1	4	424	Classroom 424	W2	CMU	White	None	0	0.2	Negative
1	4	424	Classroom 424	W3	CMU	White	None	0	0.6	Negative
1	4	424	Classroom 424	Column	Concrete	White	None	0	0.1	Negative
1	4	424	Classroom 424	Univent	Metal	White	Chipping	4	0.1	Negative
1	4	424	Classroom 424	Pipe Cover	Metal	White	Flaking	3	0.4	Negative
1	4	424	Classroom 424	Pipe Insulation	Fiberglass	White	None	0	0	Negative
1	4	424	Classroom 424	W4	CMU	White	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	424	Classroom 424	Baseboard	Ceramic	Black	None	0	1	Positive
1	4	424	Classroom 424	Ceiling	Concrete	White	Chipping, Flaking	10	0.3	Negative
1	4	425	Classroom 425	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	425	Classroom 425	W1	CMU	Cream	Chipping, Friction	2	0.3	Negative
1	4	425	Classroom 425	Door Frame	Metal	Black	Chipping	1	0.5	Negative
1	4	425	Classroom 425	Closet Door Frame A	Metal	Black	Chipping	1	0.7	Positive
1	4	425	Classroom 425	Closet Door Frame B	Metal	Black	Chipping	1	0.8	Positive
1	4	425	Classroom 425	W2	CMU	Cream	Chipping, Friction	2	0.3	Negative
1	4	425	Classroom 425	W3	CMU	Cream	Chipping, Flaking	3	0.5	Negative
1	4	425	Classroom 425	Column	Concrete	Cream	Flaking	1	0.1	Negative
1	4	425	Classroom 425	Univent	Metal	Gray	Chipping	1	0.1	Negative
1	4	425	Classroom 425	Pipe Cover	Metal	Cream	Flaking	2	0.3	Negative
1	4	425	Classroom 425	Pipe Insulation	Fiberglass	White	None	0	0.1	Negative
1	4	425	Classroom 425	W4	CMU	Cream	Chipping	1	0.4	Negative
1	4	425	Classroom 425	Baseboard	Ceramic	Black	None	0	1.5	Positive
1	4	425	Classroom 425	Ceiling	Concrete	White	Chipping, Flaking	10	0.3	Negative
1	4	426	Classroom 426	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	426	Classroom 426	W1	CMU	Yellow	Chipping	4	0.4	Negative
1	4	426	Classroom 426	Door Frame	Metal	Black	Chipping	6	0.9	Positive
1	4	426	Classroom 426	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	1.2	Positive
1	4	426	Classroom 426	W2	CMU	Yellow	Chipping	3	0.4	Negative
1	4	426	Classroom 426	W3	CMU	Yellow	Flaking	12	0.3	Negative
1	4	426	Classroom 426	Column	Concrete	Yellow	Flaking	15	0.4	Negative
1	4	426	Classroom 426	Univent	Metal	Grey	Chipping	12	0.1	Negative
1	4	426	Classroom 426	Pipe Cover	Metal	Yellow	Flaking	4	0.1	Negative
1	4	426	Classroom 426	W4	CMU	Yellow	Flaking	4	0.5	Negative
1	4	426	Classroom 426	Ceiling	Concrete	White	Flaking	72	0.3	Negative
1	4	426A	Classroom 426 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	2	0.8	Positive
1	4	426B	Classroom 426 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	2	0.8	Positive

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	427	Classroom 427	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	427	Classroom 427	W1	CMU	White	Chipping, Friction, Spalling	4	0.2	Negative
1	4	427	Classroom 427	Door Frame	Metal	Black	Chipping	1	0.7	Positive
1	4	427	Classroom 427	Closet Door Frame A	Metal	Black	Chipping	1	0.7	Positive
1	4	427	Classroom 427	Closet Door Frame B	Metal	Black	Chipping	1	0.9	Positive
1	4	427	Classroom 427	W2	CMU	White	Chipping, Friction	3	0.4	Negative
1	4	427	Classroom 427	W3	CMU	White	Chipping, Flaking	5	0.1	Negative
1	4	427	Classroom 427	Pipe Insulation	Fiberglass	White	None	0	0.1	Negative
1	4	427	Classroom 427	Pipe Cover	Metal	White	Chipping, Flaking	3	0.2	Negative
1	4	427	Classroom 427	Univent	Metal	Gray	Chipping	2	0.1	Negative
1	4	427	Classroom 427	Column	Concrete	White	Chipping, Flaking	3	0.3	Negative
1	4	427	Classroom 427	Baseboard	Ceramic	Black	None	0	1.3	Positive
1	4	427	Classroom 427	W4	CMU	White	Chipping, Flaking	2	0.4	Negative
1	4	427	Classroom 427	Ceiling	Concrete	White	Flaking	4	0.2	Negative
1	4	428	Classroom 428	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	428	Classroom 428	W1	CMU	Blue	Chipping	2	0.5	Negative
1	4	428	Classroom 428	Pipe Cover	Metal	Gray	Chipping	1	0.2	Negative
1	4	428	Classroom 428	Pipe Insulation	Fiberglass	White, Gray	Chipping, Flaking	3	0.1	Negative
1	4	428	Classroom 428	Door	Wood	Yellow	None	0	0.1	Negative
1	4	428	Classroom 428	Door Frame	Metal	Black	Chipping	1	0.6	Negative
1	4	428	Classroom 428	Closet Door A	Wood	Yellow	None	0	0.1	Negative
1	4	428	Classroom 428	Closet Door Frame A	Metal	Black	Chipping	1	0.5	Negative
1	4	428	Classroom 428	Closet Door B	Wood	Yellow	None	0	0.1	Negative
1	4	428	Classroom 428	Closet Door Frame B	Metal	Black	Chipping	1	1	Positive
1	4	428	Classroom 428	W2	CMU	Blue	Chipping, Flaking	8	0.4	Negative
1	4	428	Classroom 428	Univent	Metal	Blue	Chipping	2	0.1	Negative
1	4	428	Classroom 428	W3	CMU	Blue	Chipping, Flaking	8	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	428	Classroom 428	Column	Concrete	Blue	Chipping, Flaking	12	0.1	Negative
1	4	428	Classroom 428	Univent	Metal	Blue	Chipping	2	0	Negative
1	4	428	Classroom 428	Pipe Cover	Metal	Blue	Chipping	1	0.2	Negative
1	4	428	Classroom 428	W4	CMU	Blue	Chipping	2	0.3	Negative
1	4	428	Classroom 428	Baseboard	Ceramic	Black	None	0	1.8	Positive
1	4	428	Classroom 428	Ceiling	Concrete	White	None	0	0.3	Negative
1	4	S42	Stairwell next to Classroom 428	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S42	Stairwell next to Classroom 428	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	4	S42	Stairwell next to Classroom 428	Doorframe	Metal	Red	Chipping	4	0.2	Negative
1	4	S42	Stairwell next to Classroom 428	Door	Metal	Red	Friction	7	0.1	Negative
1	4	S42	Stairwell next to Classroom 428	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S42	Stairwell next to Classroom 428	Baseboard	Ceramic	Black	Chipping	8	2.1	Positive
1	4	S42	Stairwell next to Classroom 428	Conduit	Metal	Tan	Chipping	2	0.3	Negative
1	4	S42	Stairwell next to Classroom 428	Riser	Metal	Black	Chipping	20	0.1	Negative
1	4	S42	Stairwell next to Classroom 428	Stringer	Metal	Black	Chipping	8	0.1	Negative
1	4	S42	Stairwell next to Classroom 428	Stair Pan	Metal	Tan	Moisture Damage	12	0.8	Positive
1	4	S42	Stairwell next to Classroom 428	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S42	Stairwell next to Classroom 428	Baseboard	Metal	Black	Chipping	3	0.1	Negative
1	4	S42	Stairwell next to Classroom 428	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S42	Stairwell next to Classroom 428	Ceiling	Concrete	White	Flaking	8	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	429	Classroom 429	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	429	Classroom 429	W1	CMU	White	None	0	0.3	Negative
1	4	429	Classroom 429	Door Frame	Metal	Black	Chipping	1	0.8	Positive
1	4	429	Classroom 429	Closet Door Frame A	Metal	Black	Chipping	1	0.8	Positive
1	4	429	Classroom 429	Closet Door Frame B	Metal	Black	Chipping	1	0.8	Positive
1	4	429	Classroom 429	W2	CMU	White	None	0	0.3	Negative
1	4	429	Classroom 429	Conduit	Metal	White	None	0	0.2	Negative
1	4	429	Classroom 429	Baseboard	Ceramic	Black	None	0	1.5	Positive
1	4	429	Classroom 429	W3	CMU	White	None	0	0.5	Negative
1	4	429	Classroom 429	Pipe Insulation	Fiberglass	White	Chipping, Flaking	3	0.1	Negative
1	4	429	Classroom 429	Pipe Cover	Metal	White	Chipping, Flaking	3	0.4	Negative
1	4	429	Classroom 429	Column	Concrete	White	Chipping, Flaking	4	0.2	Negative
1	4	429	Classroom 429	Univent	Metal	Gray	Chipping, Friction	4	0.2	Negative
1	4	429	Classroom 429	W4	CMU	White	Chipping, Flaking	3	0.5	Negative
1	4	429	Classroom 429	Radiator	Metal	White	Chipping, Friction	2	0.2	Negative
1	4	429	Classroom 429	Ceiling	Concrete	White	Flaking	10	0.4	Negative
1	4	H41	Hallway from Classrooms 407 to 429	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H41	Hallway from Classrooms 407 to 429	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H41	Hallway from Classrooms 407 to 429	Doorframe	Metal	Red	Chipping	16	2.5	Positive
1	4	H41	Hallway from Classrooms 407 to 429	Door	Metal	Red	Friction	26	0.1	Negative
1	4	H41	Hallway from Classrooms 407 to 429	W2	CMU	White	Chipping	125	0.3	Negative
1	4	H41	Hallway from Classrooms 407 to 429	Elevator Door	Metal	Black	None	0	0.1	Negative
1	4	H41	Hallway from Classrooms 407 to 429	Elevator Doorframe	Metal	Black	None	0	0.2	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	H41	Hallway from Classrooms 407 to 429	Baseboard	CMU/Tile	Black	None	0	1.2	Positive
1	4	H41	Hallway from Classrooms 407 to 429	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H41	Hallway from Classrooms 407 to 429	Doorframe	Metal	Red	Chipping	10	0.2	Negative
1	4	H41	Hallway from Classrooms 407 to 429	Door	Metal	Red	Friction	11	0.1	Negative
1	4	H41	Hallway from Classrooms 407 to 429	W4	CMU	White	Chipping	89	0.4	Negative
1	4	H41	Hallway from Classrooms 407 to 429	Radiator	Metal	White	None	0	0.2	Negative
1	4	H41	Hallway from Classrooms 407 to 429	Vent	Metal	White	None	0	0	Negative
1	4	H41	Hallway from Classrooms 407 to 429	Pipe	Metal	White	Chipping	5	0.5	Negative
1	4	H41	Hallway from Classrooms 407 to 429	Ceiling	Concrete	White	None	0	0.2	Negative
1	4	432	Classroom 432	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	432	Classroom 432	W1	CMU	White	Flaking	10	0	Negative
1	4	432	Classroom 432	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	4	432	Classroom 432	Door Frame	Metal	Black	Chipping	6	0.5	Negative
1	4	432	Classroom 432	W2	CMU	White	Flaking	7	0	Negative
1	4	432	Classroom 432	W3	CMU	White	Flaking	22	0	Negative
1	4	432	Classroom 432	Column	CMU	White	Flaking	29	0.1	Negative
1	4	432	Classroom 432	Univent	Metal	Grey	Chipping	18	0.1	Negative
1	4	432	Classroom 432	Pipe	Metal	White	Chipping	3	0	Negative
1	4	432	Classroom 432	W4	CMU	White	Flaking	25	0.1	Negative
1	4	432	Classroom 432	Ceiling	Concrete	White	None	0	0.2	Negative
1	4	432A	Classroom 432 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.8	Positive
1	4	432B	Classroom 432 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.2	Negative
1	4	433	Staff Lounge 433	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	433	Staff Lounge 433	W1	CMU	Blue	None	0	0	Negative
1	4	433	Staff Lounge 433	Door Frame	Metal	Black	Chipping	8	0.3	Negative
1	4	433	Staff Lounge 433	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	4	433	Staff Lounge 433	W2	CMU	Blue	None	0	0.1	Negative
1	4	433	Staff Lounge 433	W3	CMU	Blue	None	0	0	Negative
1	4	433	Staff Lounge 433	Column	CMU	Blue	None	0	0	Negative
1	4	433	Staff Lounge 433	Pipe	Metal	Blue	None	0	0	Negative
1	4	433	Staff Lounge 433	Univent	Metal	Blue	None	0	0.1	Negative
1	4	433	Staff Lounge 433	W4	CMU	Blue	None	0	0	Negative
1	4	433	Staff Lounge 433	Ceiling	Concrete	White	None	0	0.1	Negative
1	4	433A	Staff Lounge 433 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.3	Negative
1	4	433B	Staff Lounge 433 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.5	Negative
1	4	434	Classroom 434	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	434	Classroom 434	W1	CMU	White	Flaking	9	0	Negative
1	4	434	Classroom 434	Door Frame	Metal	Black	Chipping	10	0.5	Negative
1	4	434	Classroom 434	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	4	434	Classroom 434	W2	CMU	White	Flaking	5	0.1	Negative
1	4	434	Classroom 434	W3	CMU	White	Flaking	3	0	Negative
1	4	434	Classroom 434	Column	CMU	White	Flaking	22	0.1	Negative
1	4	434	Classroom 434	Univent	Metal	Grey	Chipping	5	0.2	Negative
1	4	434	Classroom 434	Pipe Cover	Metal	White	Chipping	2	0	Negative
1	4	434	Classroom 434	Pipe	Metal	White	Flaking	5	0.1	Negative
1	4	434	Classroom 434	W4	CMU	White	Flaking	17	0.1	Negative
1	4	434	Classroom 434	Ceiling	Concrete	White	None	0	0.2	Negative
1	4	434A	Classroom 434 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.3	Negative
1	4	434B	Classroom 434 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.3	Negative
1	4	435	Photo Studio 435	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	4	435	Photo Studio 435	W1	CMU	Yellow	Flaking	4	0	Negative
1	4	435	Photo Studio 435	Door Frame	Metal	Black	None	0	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	435	Photo Studio 435	Baseboard (W1-3)	CMU/Tile	Black	None	0	0.9	Positive
1	4	435	Photo Studio 435	W2	CMU	Yellow	None	0	0	Negative
1	4	435	Photo Studio 435	W3	CMU	Yellow	Flaking	5	0.1	Negative
1	4	435	Photo Studio 435	Pipe Cover	Metal	White	Chipping	4	0.2	Negative
1	4	435	Photo Studio 435	Univent	Metal	Grey	Chipping	5	0.2	Negative
1	4	435	Photo Studio 435	W4	Brick	Yellow	None	0	0.1	Negative
1	4	435	Photo Studio 435	Ceiling	Concrete	White	None	0	0	Negative
1	4	435A	Photo Studio 435 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.2	Negative
1	4	435B	Photo Studio 435 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.3	Negative
1	4	S43	Stairwell next to Classroom 435	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S43	Stairwell next to Classroom 435	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	4	S43	Stairwell next to Classroom 435	Doorframe	Metal	Red	Chipping	4	0.2	Negative
1	4	S43	Stairwell next to Classroom 435	Door	Metal	Red	Friction	7	0.1	Negative
1	4	S43	Stairwell next to Classroom 435	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S43	Stairwell next to Classroom 435	Baseboard	Ceramic	Black	Chipping	8	2.1	Positive
1	4	S43	Stairwell next to Classroom 435	Conduit	Metal	Tan	Chipping	2	0.3	Negative
1	4	S43	Stairwell next to Classroom 435	Riser	Metal	Black	Chipping	20	0.1	Negative
1	4	S43	Stairwell next to Classroom 435	Stringer	Metal	Black	Chipping	8	0.1	Negative
1	4	S43	Stairwell next to Classroom 435	Stair Pan	Metal	Tan	Moisture Damage	12	0.8	Positive
1	4	S43	Stairwell next to Classroom 435	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S43	Stairwell next to Classroom 435	Baseboard	Metal	Black	Chipping	3	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia HighSchool</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	S43	Stairwell next to Classroom 435	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S43	Stairwell next to Classroom 435	Ceiling	Concrete	White	Flaking	8	0.5	Negative
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	W2	CMU	White	Chipping	15	0.5	Negative
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	Pipe Cover	Metal	Blue	Chipping	10	0.2	Negative
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	Pipe Insulation	Fiberglass	White	Chipping	6	0.1	Negative
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	Radiator	Metal	White	Chipping	20	0.2	Negative
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	Electrical Panel	Metal	Black	Chipping	4	0	Negative
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	Vent	Metal	White	None	0	0.1	Negative
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	W3	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	W4	CMU	White	Chipping	65	0.4	Negative
1	4	H44	Hallway from Classroom 418 to Stairwell next to Classroom 435	Ceiling	Concrete	White	Chipping	40	0.2	Negative
1	3	S36	Stairwell next to Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S36	Stairwell next to Classroom 300	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S36	Stairwell next to Classroom 300	Door Frame	Metal	Red	Chipping	9	0.9	Positive
1	3	S36	Stairwell next to Classroom 300	Door	Metal	Red	Friction	20	0.2	Negative
1	3	S36	Stairwell next to Classroom 300	W2	CMU	White	None	0	0	Negative
1	3	S36	Stairwell next to Classroom 300	Riser	Metal	White	Chipping	20	0.1	Negative
1	3	S36	Stairwell next to Classroom 300	Stringer	Metal	White	Chipping	12	0.1	Negative
1	3	S36	Stairwell next to Classroom 300	Stair pan	Metal	Tan	Flaking	8	0.2	Negative
1	3	S36	Stairwell next to Classroom 300	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S36	Stairwell next to Classroom 300	Baseboard	Metal	Black	Chipping	6	0	Negative
1	3	S36	Stairwell next to Classroom 300	W4	CMU	White	None	0	0.1	Negative
1	3	S36	Stairwell next to Classroom 300	Fire pipe	Metal	Tan	Chipping	3	0.3	Negative
1	3	S36	Stairwell next to Classroom 300	Conduit	Metal	White	None	0	0.1	Negative
1	3	S36	Stairwell next to Classroom 300	Ceiling	Concrete	White	Flaking	15	0.3	Negative
1	3	300C	Office 300B	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	300C	Office 300B	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300C	Office 300B	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300C	Office 300B	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300C	Office 300B	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300C	Office 300B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300	Science Lab 300	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	300	Science Lab 300	W1	CMU	White	Flaking	17	0.1	Negative
1	3	300	Science Lab 300	Door Frame	Metal	Black	Chipping	6	0.9	Positive
1	3	300	Science Lab 300	W2	CMU	White	Flaking	46	0.2	Negative
1	3	300	Science Lab 300	W3	CMU	White	Flaking	51	0.4	Negative
1	3	300	Science Lab 300	Column	Concrete	Tan	Flaking	12	0.2	Negative
1	3	300	Science Lab 300	Univent	Metal	Grey	Chipping	13	0.1	Negative
1	3	300	Science Lab 300	Pipe Cover	Metal	White	Chipping	9	0.1	Negative
1	3	300	Science Lab 300	W4	CMU	White	Flaking	31	0.3	Negative
1	3	300	Science Lab 300	Ceiling	Concrete	White	Flaking	53	0.3	Negative
1	3	300	Science Lab 300	Pipe (C)	Metal	White	None	0	0.3	Negative
1	3	300B	Science Lab 300 Closet next to Prep Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	300B	Science Lab 300 Closet next to Prep Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300B	Science Lab 300 Closet next to Prep Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300B	Science Lab 300 Closet next to Prep Room	Door Frame (W2)	Metal	Black	Chipping	3	0.7	Positive
1	3	300B	Science Lab 300 Closet next to Prep Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300B	Science Lab 300 Closet next to Prep Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300B	Science Lab 300 Closet next to Prep Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	301A	Prep Room between Labs 300 and 301	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	301A	Prep Room between Labs 300 and 301	W1	CMU	White	Flaking	25	0.2	Negative
1	3	301A	Prep Room between Labs 300 and 301	Door Frame	Metal	Black	Chipping	3	0.7	Positive
1	3	301A	Prep Room between Labs 300 and 301	W2	CMU	White	Flaking	9	0.1	Negative
1	3	301A	Prep Room between Labs 300 and 301	W3	CMU	White	Flaking	23	0.1	Negative
1	3	301A	Prep Room between Labs 300 and 301	W4	CMU	White	Flaking	10	0.3	Negative
1	3	301A	Prep Room between Labs 300 and 301	Column	Concrete	White	Flaking	14	0.1	Negative
1	3	301A	Prep Room between Labs 300 and 301	Univent	Metal	White	Flaking	2	0	Negative
1	3	301A	Prep Room between Labs 300 and 301	Pipe Cover	Metal	White	Flaking	13	0.3	Negative
1	3	301A	Prep Room between Labs 300 and 301	Ceiling	Concrete	White	Flaking	3	0.3	Negative
1	3	300A	Storeroom next to Science Lab 300	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	300A	Storeroom next to Science Lab 300	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300A	Storeroom next to Science Lab 300	Door Frame (W1)	Metal	Black	Chipping	1	0.9	Positive
1	3	300A	Storeroom next to Science Lab 300	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300A	Storeroom next to Science Lab 300	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300A	Storeroom next to Science Lab 300	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300A	Storeroom next to Science Lab 300	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	301B	Janitor's Closet next to Science Lab 301	Floor	Concrete	Grey	Friction	20	0.1	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	301B	Janitor's Closet next to Science Lab 301	W1	CMU	Tan	Flaking	1	0.4	Negative
1	3	301B	Janitor's Closet next to Science Lab 301	doorframe	Metal	Black	Chipping	6	0.5	Negative
1	3	301B	Janitor's Closet next to Science Lab 301	W2	CMU	Tan	Chipping	1	0.4	Negative
1	3	301B	Janitor's Closet next to Science Lab 301	Shelf	Wood	Tan	Chipping	17	0.5	Negative
1	3	301B	Janitor's Closet next to Science Lab 301	W3	CMU	Tan	Flaking	1	0.4	Negative
1	3	301B	Janitor's Closet next to Science Lab 301	W4	CMU	Tan	Chipping	2	0.4	Negative
1	3	301B	Janitor's Closet next to Science Lab 301	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	3	301B	Janitor's Closet next to Science Lab 301	Duct	Metal	Tan	None	0	0.7	Positive
1	3	301B	Janitor's Closet next to Science Lab 301	Pipe	Metal	tan	None	0	0.4	Negative
1	3	301B	Janitor's Closet next to Science Lab 301	Pipe Insulation	Fiberglass	Tan	Chipping	3	0.1	Negative
1	3	301	Science Lab 301	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	301	Science Lab 301	W1	CMU	White	Chipping	14	0.5	Negative
1	3	301	Science Lab 301	Door Frame	Metal	Black	Chipping	5	0.9	Positive
1	3	301	Science Lab 301	Baseboard (W1-4)	CMU/Tile	Black	Friction	3	1.6	Positive
1	3	301	Science Lab 301	W2	CMU	White	Flaking	10	0.1	Negative
1	3	301	Science Lab 301	Door Frame	Metal	Black	Chipping	2	0.7	Positive
1	3	301	Science Lab 301	W3	CMU	White	Flaking	16	0.5	Negative
1	3	301	Science Lab 301	Column	Concrete	White	Flaking	4	0.2	Negative
1	3	301	Science Lab 301	Univent	Metal	Grey	Flaking	6	0.2	Negative
1	3	301	Science Lab 301	Pipe Cover	Metal	White	Flaking	4	0.2	Negative
1	3	301	Science Lab 301	W4	CMU	White	Flaking	14	0.5	Negative
1	3	301	Science Lab 301	Door Frame	Metal	Black	Chipping	2	0.7	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	301	Science Lab 301	Ceiling	Concrete	White	Flaking	8	0.3	Negative
1	3	301C	Science Lab 301 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	301C	Science Lab 301 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	301C	Science Lab 301 Closet	Door Frame	Metal	Black	None	0	1	Positive
1	3	301C	Science Lab 301 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	301C	Science Lab 301 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	301C	Science Lab 301 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	301C	Science Lab 301 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	302	Classroom 302	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	W1	CMU	White	Moisture Damage	27	0.3	Negative
1	3	302	Classroom 302	Door Frame	Metal	Black	Chipping	4	0.8	Positive
1	3	302	Classroom 302	W2	CMU	White	Flaking	9	0.2	Negative
1	3	302	Classroom 302	Conduit (W2/3)	Metal	White	None	0	0.5	Negative
1	3	302	Classroom 302	Door Frame	Metal	Black	Chipping	3	1	Positive
1	3	302	Classroom 302	W3	CMU	White	Flaking	12	0.5	Negative
1	3	302	Classroom 302	Column	Concrete	White	Flaking	10	0.2	Negative
1	3	302	Classroom 302	Pipe Cover	Metal	Grey	Flaking	4	0.1	Negative
1	3	302	Classroom 302	Univent	Metal	Grey	Flaking	7	0.2	Negative
1	3	302	Classroom 302	W4	CMU	White	Flaking	9	0.5	Negative
1	3	302	Classroom 302	Ceiling	Concrete	White	Flaking	11	0.3	Negative
1	3	302	Classroom 302	Pipe (C)	Metal	White	None	0	0.4	Negative
1	3	302CA	Classroom 302 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	2	1.2	Positive
1	3	302CB	Classroom 302 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	2	2	Positive
1	3	303A	Science Storage Room across from Classroom 302	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Science Storage Room across from Classroom 302	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Science Storage Room across from Classroom 302	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Science Storage Room across from Classroom 302	W3	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	303A	Science Storage Room across from Classroom 302	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Science Storage Room across from Classroom 302	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	302A	Storeroom 302A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	302A	Storeroom 302A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	302A	Storeroom 302A	Door Frame	Metal	Black	Chipping	3	1	Positive
1	3	302A	Storeroom 302A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	302A	Storeroom 302A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	302A	Storeroom 302A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	302A	Storeroom 302A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303	Science Lab 303	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	303	Science Lab 303	W1	CMU	White	Flaking	3	0.5	Negative
1	3	303	Science Lab 303	Baseboard (W1-4)	CMU/Tile	Black	Friction	3	1.1	Positive
1	3	303	Science Lab 303	Door Frame	Metal	Black	Chipping	5	1.1	Positive
1	3	303	Science Lab 303	W2	CMU	White	Flaking	2	0.4	Negative
1	3	303	Science Lab 303	W3	CMU	White	Flaking	6	0.5	Negative
1	3	303	Science Lab 303	Column	Concrete	White	Flaking	8	0.2	Negative
1	3	303	Science Lab 303	Univent	Metal	Grey	Chipping	6	0.1	Negative
1	3	303	Science Lab 303	Pipe Cover	Metal	White	Chipping	7	0.1	Negative
1	3	303	Science Lab 303	W4	CMU	White	Flaking	6	0.5	Negative
1	3	303	Science Lab 303	Ceiling	Concrete	White	Flaking	5	0.2	Negative
1	3	303CA	Science Lab 303 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	0.7	Positive
1	3	303B	Prep Room between Classroom 302 and 303	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303B	Prep Room between Classroom 302 and 303	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303B	Prep Room between Classroom 302 and 303	Door Frame	Metal	Black	Chipping	3	0.8	Positive
1	3	303B	Prep Room between Classroom 302 and 303	W2	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	303B	Prep Room between Classroom 302 and 303	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303B	Prep Room between Classroom 302 and 303	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303B	Prep Room between Classroom 302 and 303	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303C	Classroom 303 Closet on Stairwell side	Floor	Concrete	Grey	Flaking	22	0.5	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	W1	CMU	White	None	0	0.4	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	Door Frame	Metal	Black	Chipping	3	0.9	Positive
1	3	303C	Classroom 303 Closet on Stairwell side	W2	CMU	White	None	0	0.4	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	Shelf (W2/4)	Wood	White	None	0	0.7	Positive
1	3	303C	Classroom 303 Closet on Stairwell side	Column (W2/3)	Concrete	White	Flaking	6	0.3	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	W3	CMU	White	None	0	0.5	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	Radiator	Metal	White	Flaking	7	0.3	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	Pipe Cover	Metal	White	None	0	0.9	Positive
1	3	303C	Classroom 303 Closet on Stairwell side	W4	CMU	White	None	0	0.5	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	Conduit	Metal	White	None	0	0	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	Door Frame (W4)	Metal	Red	None	0	0.3	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	Door	Metal	Red	None	0	0	Negative
1	3	303C	Classroom 303 Closet on Stairwell side	Ceiling	Concrete	White	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	303E	Classroom 303 Closet on 302 side	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303E	Classroom 303 Closet on 302 side	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303E	Classroom 303 Closet on 302 side	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303E	Classroom 303 Closet on 302 side	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303E	Classroom 303 Closet on 302 side	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303E	Classroom 303 Closet on 302 side	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303D	Classroom 303 Greenhouse	Floor	Concrete	Red	Flaking	60	0.3	Negative
1	3	303D	Classroom 303 Greenhouse	W1	CMU	White/Green	Flaking	2	0.5	Negative
1	3	303D	Classroom 303 Greenhouse	Door Frame	Metal	Black	Chipping	2	0.8	Positive
1	3	303D	Classroom 303 Greenhouse	Door Frame	Metal	Red	None	0	0.8	Positive
1	3	303D	Classroom 303 Greenhouse	Door	Metal	Red	Friction	2	0	Negative
1	3	303D	Classroom 303 Greenhouse	W2	CMU	White	Chipping	2	0.5	Negative
1	3	303D	Classroom 303 Greenhouse	Door Frame	Metal	Red	Friction	6	1.1	Positive
1	3	303D	Classroom 303 Greenhouse	W3	CMU	White	Flaking	8	0.5	Negative
1	3	303D	Classroom 303 Greenhouse	Pipe Cover	Metal	White	Flaking	7	0.1	Negative
1	3	303D	Classroom 303 Greenhouse	Conduit	Metal	White	None	0	0.2	Negative
1	3	303D	Classroom 303 Greenhouse	Column	Concrete	White	Flaking	10	0.3	Negative
1	3	303D	Classroom 303 Greenhouse	Pipe	Metal	White	Flaking	30	0.5	Negative
1	3	303D	Classroom 303 Greenhouse	W4	CMU	Multi	Flaking	7	0.5	Negative
1	3	303D	Classroom 303 Greenhouse	Ceiling	Concrete	White	Flaking	5	0.3	Negative
1	3	S33	Stairwell next to Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S33	Stairwell next to Classroom 303	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S33	Stairwell next to Classroom 303	Door Frame	Metal	Tan	Chipping	5	0.8	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia HighSchool</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	S33	Stairwell next to Classroom 303	door	Metal	Red	Friction	3	0.2	Negative
1	3	S33	Stairwell next to Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S33	Stairwell next to Classroom 303	stringer	Metal	Tan	None	0	0.1	Negative
1	3	S33	Stairwell next to Classroom 303	Stair pan	Metal	Tan	None	0	0.3	Negative
1	3	S33	Stairwell next to Classroom 303	riser	Metal	Tan	None	0	0.2	Negative
1	3	S33	Stairwell next to Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S33	Stairwell next to Classroom 303	Stair Cage	Metal	Blue	Chipping	5	0.1	Negative
1	3	S33	Stairwell next to Classroom 303	radiator	Metal	Tan	None	0	0.3	Negative
1	3	S33	Stairwell next to Classroom 303	baseboard	Metal	Tan	Chipping	2	0.1	Negative
1	3	S33	Stairwell next to Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S33	Stairwell next to Classroom 303	fire pipe	Metal	Tan	None	0	0.5	Negative
1	3	S33	Stairwell next to Classroom 303	Doorframe	Metal	Tan	Chipping	1	0.2	Negative
1	3	S33	Stairwell next to Classroom 303	Ceiling	Concrete	White	Flaking	5	0.2	Negative
1	3	H32	Hallway from Classrooms 300 to 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H32	Hallway from Classrooms 300 to 303	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H32	Hallway from Classrooms 300 to 303	Door Frame	Metal	Blue	Chipping	8	1.2	Positive
1	3	H32	Hallway from Classrooms 300 to 303	Door	Wood	Red	Chipping	3	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	H32	Hallway from Classrooms 300 to 303	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	3	H32	Hallway from Classrooms 300 to 303	W2	CMU	White	Flaking	12	0.4	Negative
1	3	H32	Hallway from Classrooms 300 to 303	Radiator	Metal	White	None	0	0.3	Negative
1	3	H32	Hallway from Classrooms 300 to 303	Electrical Panels	Metal	Black	Chipping	2	0.4	Negative
1	3	H32	Hallway from Classrooms 300 to 303	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H32	Hallway from Classrooms 300 to 303	W4	CMU	White	Flaking	6	0.5	Negative
1	3	H32	Hallway from Classrooms 300 to 303	Vent	Metal	White	None	0	0.3	Negative
1	3	H32	Hallway from Classrooms 300 to 303	Ceiling	Concrete	White	None	0	0.4	Negative
1	3	H32	Hallway from Classrooms 300 to 303	Pipe Insulation	Fiberglass	White	Chipping	10	0.1	Negative
1	3	304	Classroom 304	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	W1	CMU	White	Flaking	14	0.4	Negative
1	3	304	Classroom 304	Door Frame Cabinets	Metal	Black	Chipping	2	0.8	Positive
1	3	304	Classroom 304	Door Frame	Metal	Black	Friction	6	0.9	Positive
1	3	304	Classroom 304	Baseboard (W1-4)	CMU/Tile	Black	Friction	2	1	Positive
1	3	304	Classroom 304	Duct	Metal	White	None	0	0.2	Negative
1	3	304	Classroom 304	Pipe	Metal	White	Flaking	3	0.2	Negative
1	3	304	Classroom 304	W2	CMU	White	Flaking	18	0.4	Negative
1	3	304	Classroom 304	Radiator	Metal	White	Friction	3	0.3	Negative
1	3	304	Classroom 304	W3	CMU	White	Flaking	15	0.4	Negative
1	3	304	Classroom 304	Column	Concrete	White	Flaking	27	0.1	Negative
1	3	304	Classroom 304	Univent	Metal	Grey	Chipping	13	0.1	Negative
1	3	304	Classroom 304	Pipe Cover	Metal	White	Chipping	17	0.2	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	304	Classroom 304	W4	CMU	White	Flaking	10	0.4	Negative
1	3	304	Classroom 304	Door Frame (W4)	Metal	Black	Chipping	3	0.7	Positive
1	3	304	Classroom 304	Ceiling	Concrete	White	Flaking	6	0.5	Negative
1	3	304CA	Classroom 304 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	2	1.4	Positive
1	3	304A	Office next to Classroom 304	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	304A	Office next to Classroom 304	W1	CMU	Blue	Flaking	9	0.4	Negative
1	3	304A	Office next to Classroom 304	Door Frame	Metal	Black	Chipping	3	1	Positive
1	3	304A	Office next to Classroom 304	W2	CMU	Blue	Flaking	2	0.4	Negative
1	3	304A	Office next to Classroom 304	Door Frame (2)	Metal	Black	Chipping	4	1	Positive
1	3	304A	Office next to Classroom 304	W3	CMU	Blue	Chipping	6	0.5	Negative
1	3	304A	Office next to Classroom 304	Radiator	Metal	Blue	Chipping	5	0.3	Negative
1	3	304A	Office next to Classroom 304	W4	CMU	Blue	Chipping	2	0.4	Negative
1	3	304A	Office next to Classroom 304	Door Frame	Metal	Black	Chipping	4	1	Positive
1	3	304A	Office next to Classroom 304	Ceiling	Concrete	White	Flaking	2	0.4	Negative
1	3	304A	Office next to Classroom 304	Pipe (C)	Metal	White	Flaking	2	0.1	Negative
1	3	305	Classroom 305	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	W1	CMU	White	Flaking	4	0.4	Negative
1	3	305	Classroom 305	Door Frame	Metal	Black	Friction	6	0.9	Positive
1	3	305	Classroom 305	Baseboard (W1-4)	CMU/Tile	Black	Friction	2	1	Positive
1	3	305	Classroom 305	Door Frame Cabinet	Metal	Black	Friction	1	0.6	Negative
1	3	305	Classroom 305	W2	CMU	White	None	0	0.4	Negative
1	3	305	Classroom 305	Door Frame	Metal	Black	Chipping	2	1	Positive
1	3	305	Classroom 305	W3	CMU	White	Flaking	2	0.5	Negative
1	3	305	Classroom 305	Column	Concrete	White	Flaking	17	0.1	Negative
1	3	305	Classroom 305	Pipe Cover	Metal	White	Chipping	10	0.1	Negative
1	3	305	Classroom 305	Univent	Metal	Grey	Flaking	17	0.1	Negative
1	3	305	Classroom 305	Pipe	Metal	White	None	0	0.3	Negative
1	3	305	Classroom 305	W4	CMU	White	Flaking	3	0.4	Negative
1	3	305	Classroom 305	Ceiling	Concrete	White	Flaking	24	0.5	Negative
1	3	305A	Office 305A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	305A	Office 305A	W1	CMU	White	None	0	0.4	Negative
1	3	305A	Office 305A	Baseboard (W1-4)	CMU/Tile	Black	None	0	0.9	Positive
1	3	305A	Office 305A	Door Frame	Metal	Black	Chipping	2	0.2	Negative
1	3	305A	Office 305A	Duct	Metal	White	None	0	0.2	Negative
1	3	305A	Office 305A	W2	CMU	White	None	0	0.4	Negative
1	3	305A	Office 305A	Door Frame	Metal	Black	None	0	0.2	Negative
1	3	305A	Office 305A	W3	CMU	White	None	0	0.4	Negative
1	3	305A	Office 305A	Radiator	Metal	White	None	0	0.1	Negative
1	3	305A	Office 305A	W4	CMU	White	None	0	0.3	Negative
1	3	305A	Office 305A	Chase Door	Metal	White	None	0	0.1	Negative
1	3	305A	Office 305A	Ceiling	Concrete	White	Flaking	1	0.3	Negative
1	3	305A	Office 305A	Pipe (C)	Metal	White	None	0	0.2	Negative
1	3	305C	Office 305A Copy Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	305C	Office 305A Copy Room	W1	CMU	White	None	0	0.4	Negative
1	3	305C	Office 305A Copy Room	Door Frame	Metal	Black	Chipping	2	0.3	Negative
1	3	305C	Office 305A Copy Room	Baseboard (W1-4)	CMU/Tile	Black	None	0	0.8	Positive
1	3	305C	Office 305A Copy Room	W2	CMU	White	None	0	0.3	Negative
1	3	305C	Office 305A Copy Room	W3	CMU	White	None	0	0.4	Negative
1	3	305C	Office 305A Copy Room	W4	CMU	White	None	0	0.4	Negative
1	3	305C	Office 305A Copy Room	Ceiling	Concrete	White	None	0	0.3	Negative
1	3	305C	Office 305A Copy Room	Pipe	Metal	White	None	0	0.1	Negative
1	3	305B	Storage Room 305B	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	305B	Storage Room 305B	W1	CMU	White	None	0	0.4	Negative
1	3	305B	Storage Room 305B	W2	CMU	White	None	0	0.3	Negative
1	3	305B	Storage Room 305B	W3	CMU	White	None	0	0.2	Negative
1	3	305B	Storage Room 305B	W4	CMU	White	None	0	0.4	Negative
1	3	305B	Storage Room 305B	Ceiling	Concrete	White	None	0	0.1	Negative
1	3	305B	Storage Room 305B	Duct	Metal	White	Flaking	1	0.1	Negative
1	3	305B	Storage Room 305B	Pipe	Metal	White	None	0	0.3	Negative
1	3	305D	Women's Staff Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	305D	Women's Staff Lounge	W1	CMU	White	Flaking	6	0.5	Negative
1	3	305D	Women's Staff Lounge	Closet Doorframe	Metal	Black	None	0	0.3	Negative
1	3	305D	Women's Staff Lounge	W2	CMU	White	Flaking	10	0.5	Negative
1	3	305D	Women's Staff Lounge	Baseboard	Tile	Black	None	0	1.1	Positive
1	3	305D	Women's Staff Lounge	W3	CMU	White	Flaking	13	0.4	Negative
1	3	305D	Women's Staff Lounge	Radiator	Metal	White	None	0	0.1	Negative
1	3	305D	Women's Staff Lounge	Pipe Cover	Metal	White	Flaking	3	0.3	Negative
1	3	305D	Women's Staff Lounge	pipe insulation	Fiberglass	White	None	0	0.1	Negative
1	3	305D	Women's Staff Lounge	W4	CMU	White	Flaking	5	0.3	Negative
1	3	305D	Women's Staff Lounge	Ceiling	Concrete	White	None	0	0.1	Negative
1	3	305D1	Women's Staff Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305D1	Women's Staff Lounge Restroom	W1	CMU	White	None	0	0.3	Negative
1	3	305D1	Women's Staff Lounge Restroom	doorframe	Metal	Black	None	0	0.2	Negative
1	3	305D1	Women's Staff Lounge Restroom	W2	CMU	White	None	0	0.3	Negative
1	3	305D1	Women's Staff Lounge Restroom	W3	CMU	White	None	0	0.3	Negative
1	3	305D1	Women's Staff Lounge Restroom	W4	CMU	White	None	0	0.5	Negative
1	3	305D1	Women's Staff Lounge Restroom	Pipe Cover	Metal	White	None	0	0.1	Negative
1	3	305D1	Women's Staff Lounge Restroom	pipe insulation	Fiberglass	White	None	0	0.2	Negative
1	3	305D1	Women's Staff Lounge Restroom	Radiator	Metal	White	None	0	0	Negative
1	3	305D1	Women's Staff Lounge Restroom	Duct	Metal	White	None	0	0.3	Negative
1	3	305D1	Women's Staff Lounge Restroom	Ceiling	Concrete	White	None	0	0.4	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	S37	Stairwell next to Women's Staff Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Women's Staff Lounge	Doorframe	Metal	Red	Chipping	4	0.2	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	Door	Metal	Red	Friction	12	0.1	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Women's Staff Lounge	riser	Metal	Black	Chipping	10	0.4	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	stringer	Metal	Black	Chipping	8	0.3	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	stair pan	Metal	Black	None	0	0.1	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	conduit	Metal	Tan	Chipping	4	0.6	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Women's Staff Lounge	baseboard	Metal	Black	Chipping	4	0.2	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	radiator	Metal	tan	None	0	0.1	Negative
1	3	S37	Stairwell next to Women's Staff Lounge	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Women's Staff Lounge	Ceiling	Concrete	White	Flaking	3	0.4	Negative
1	3	306	Classroom 306	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	W1	CMU	White	Chipping	3	0.4	Negative
1	3	306	Classroom 306	Door Frame	Metal	Black	Chipping	5	0.1	Negative
1	3	306	Classroom 306	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.3	Positive
1	3	306	Classroom 306	W2	CMU	White	Flaking	8	0.5	Negative
1	3	306	Classroom 306	W3	CMU	White	Flaking	4	0.4	Negative
1	3	306	Classroom 306	Column	Concrete	White	Flaking	18	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>r</b>	<b>S</b> <b>p</b> <b>a</b> <b>c</b> <b>e</b> <b>#</b>	<b>O</b> <b>n</b> <b>-</b> <b>S</b> <b>i</b> <b>t</b> <b>e</b> <b>R</b> <b>o</b> <b>o</b> <b>m</b> <b>N</b> <b>a</b> <b>m</b> <b>e</b>	<b>C</b> <b>o</b> <b>m</b> <b>p</b> <b>o</b> <b>n</b> <b>e</b>	<b>S</b> <b>u</b> <b>b</b> <b>s</b> <b>t</b> <b>r</b> <b>a</b> <b>t</b> <b>e</b> <b>M</b> <b>a</b> <b>t</b> <b>e</b> <b>r</b> <b>i</b> <b>a</b> <b>l</b>	<b>C</b> <b>o</b> <b>l</b> <b>o</b> <b>r</b>	<b>D</b> <b>e</b> <b>s</b> <b>c</b> <b>r</b> <b>i</b> <b>p</b> <b>t</b> <b>i</b> <b>o</b> <b>n</b> <b>o</b> <b>f</b> <b>D</b> <b>a</b> <b>m</b> <b>a</b> <b>g</b> <b>e</b>	<b>D</b> <b>a</b> <b>m</b> <b>a</b> <b>g</b> <b>e</b> <b>Q</b> <b>u</b> <b>a</b> <b>n</b> <b>t</b> <b>i</b> <b>(</b> <b>s</b> <b>f</b> <b>)</b>	<b>X</b> <b>R</b> <b>F</b> <b>R</b> <b>e</b> <b>a</b> <b>d</b> <b>i</b> <b>n</b> <b>g</b> <b>(</b> <b>m</b> <b>g</b> <b>/</b> <b>c</b> <b>m</b> <b>2</b> <b>)</b>	<b>X</b> <b>R</b> <b>F</b> <b>(</b> <b>p</b> <b>o</b> <b>s</b> <b>i</b> <b>t</b> <b>i</b> <b>v</b> <b>e</b> <b>/</b> <b>n</b> <b>e</b> <b>g</b> <b>a</b> <b>t</b> <b>i</b> <b>v</b> <b>e</b> <b>)</b>
1	3	306	Classroom 306	Univent	Metal	Grey	Chipping	16	0.1	Negative
1	3	306	Classroom 306	Pipe Cover	Metal	White	Flaking	8	0.3	Negative
1	3	306	Classroom 306	W4	CMU	White	Flaking	3	0.4	Negative
1	3	306	Classroom 306	Door Frame	Metal	Black	Chipping	3	1	Positive
1	3	306	Classroom 306	Ceiling	Concrete	White	Flaking	19	0.3	Negative
1	3	306CA	Classroom 306 - Closet 1	Door Frame (W1)	Metal	Black	Chipping	1	1	Positive
1	3	306CB	Classroom 306 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	1	Positive
1	3	306A	Storage Room between Classrooms 306 and 307	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	306A	Storage Room between Classrooms 306 and 307	W1	CMU	Blue	Chipping	2	0.4	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	Door Frame	Metal	Black	Chipping	7	0.1	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	W2	CMU	Blue	None	0	0.4	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	Chase Door/Frame	Metal	Blue	None	0	0.3	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	Door Frame	Metal	Black	Chipping	1	1	Positive
1	3	306A	Storage Room between Classrooms 306 and 307	W3	CMU	Blue	Flaking	2	0.3	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	Radiator	Metal	Blue	None	0	0.2	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	Pipe	Metal	Blue	None	0	0.6	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	Pipe Cover	Metal	Blue	Chipping	1	0.3	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	W4	CMU	Blue	Chipping	2	0.4	Negative
1	3	306A	Storage Room between Classrooms 306 and 307	Door Frame	Metal	Black	Chipping	6	1	Positive
1	3	306A	Storage Room between Classrooms 306 and 307	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	3	307	Classroom 307	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	307	Classroom 307	W1	CMU	White	Flaking	12	0.5	Negative
1	3	307	Classroom 307	Door Frame	Metal	Black	Chipping	4	0.9	Positive
1	3	307	Classroom 307	Baseboard (W1-4)	CMU/Tile	Black	Chipping	2	0.9	Positive
1	3	307	Classroom 307	W2	CMU	White	Flaking	7	0.4	Negative
1	3	307	Classroom 307	Door Frame	Metal	Black	Chipping	8	1.2	Positive
1	3	307	Classroom 307	W3	CMU	White	Flaking	6	0.5	Negative
1	3	307	Classroom 307	Univent	Metal	Grey	Chipping	12	0.1	Negative
1	3	307	Classroom 307	Column	Concrete	White	Flaking	15	0.2	Negative
1	3	307	Classroom 307	Pipe Cover	Metal	White	Flaking	6	0.1	Negative
1	3	307	Classroom 307	W4	CMU	White	Flaking	4	0.3	Negative
1	3	307	Classroom 307	Ceiling	Concrete	White	Flaking	12	0.3	Negative
1	3	307	Classroom 307	Ceiling	Metal	White	Flaking	10	0.4	Negative
1	3	307CA	Classroom 307 - Closet 1	Door Frame (W1)	Metal	Black	None	0	1	Positive
1	3	307CB	Classroom 307 - Closet 2	Door Frame (W1)	Metal	Black	Chipping	1	0.7	Positive
1	3	307B	Men's Lounge across from Classroom 307	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307B	Men's Lounge across from Classroom 307	W1	CMU	White	None	0	0.5	Negative
1	3	307B	Men's Lounge across from Classroom 307	W2	CMU	White	None	0	0.4	Negative
1	3	307B	Men's Lounge across from Classroom 307	W3	CMU	White	None	0	0.5	Negative
1	3	307B	Men's Lounge across from Classroom 307	W4	CMU	White	Cracking	3	0.4	Negative
1	3	307B	Men's Lounge across from Classroom 307	Ceiling	Concrete	White	None	0	0.1	Negative
1	3	307C	Storeroom across from IMC	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307C	Storeroom across from IMC	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307C	Storeroom across from IMC	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307C	Storeroom across from IMC	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307C	Storeroom across from IMC	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307C	Storeroom across from IMC	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	308	IMC 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	IMC 308	W1	CMU	White	None	0	0.4	Negative
1	3	308	IMC 308	Doorframe	Metal	Black	Friction	7	0.5	Negative
1	3	308	IMC 308	Baseboard	CMU/Tile	Black	None	0	1	Positive
1	3	308	IMC 308	W2	CMU	White	None	0	0.3	Negative
1	3	308	IMC 308	W3	CMU	White	None	0	0.4	Negative
1	3	308	IMC 308	Window frame	Metal	Tan	None	0	0.6	Negative
1	3	308	IMC 308	W4	CMU	White	Flaking	25	0.5	Negative
1	3	308	IMC 308	Pipe Cover	Metal	White	Flaking	17	0.3	Negative
1	3	308	IMC 308	Drain Pipe	Metal	White	Flaking	14	0.3	Negative
1	3	308	IMC 308	Pipe Insulation	Fiberglass	White	Flaking	4	0.1	Negative
1	3	308	IMC 308	Univent	Metal	Grey	Chipping	34	0.1	Negative
1	3	308	IMC 308	Column	Concrete	White	Flaking	5	0.3	Negative
1	3	308	IMC 308	Ceiling	Concrete	White	None	0	0.2	Negative
1	3	308A	IMC Archives Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308A	IMC Archives Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308A	IMC Archives Room	Door Frame	Metal	White	None	0	0.7	Positive
1	3	308A	IMC Archives Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308A	IMC Archives Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308A	IMC Archives Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308A	IMC Archives Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308B	IMC Archives/Server Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308B	IMC Archives/Server Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308B	IMC Archives/Server Room	Doorframe	Metal	Black	None	0	0.3	Negative
1	3	308B	IMC Archives/Server Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308B	IMC Archives/Server Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308B	IMC Archives/Server Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308B	IMC Archives/Server Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308C	IMC Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308C	IMC Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308C	IMC Office	Door Frame	Metal	White	None	0	0.9	Positive



			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E</b>	<b>F</b>									
<b>l</b>	<b>l</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
<b>e</b>	<b>o</b>									
<b>n</b>	<b>r</b>									
<b>t</b>										
1	3	308C	IMC Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308C	IMC Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308C	IMC Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308C	IMC Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308D	IMC Work Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308D	IMC Work Room	W1	CMU	White	None	0	0.5	Negative
1	3	308D	IMC Work Room	Door Frame	Metal	White	Chipping	5	1.1	Positive
1	3	308D	IMC Work Room	Column	Concrete	White	None	0	0.1	Negative
1	3	308D	IMC Work Room	Radiator	Metal	White	None	0	0.1	Negative
1	3	308D	IMC Work Room	Pipe Cover	Metal	White	None	0	0.3	Negative
1	3	308D	IMC Work Room	Piper Insulation	Fiberglass	White	None	0	0.1	Negative
1	3	308D	IMC Work Room	W2	CMU	White	None	0	0.5	Negative
1	3	308D	IMC Work Room	Doorframe	Metal	Black	None	0	0.1	Negative
1	3	308D	IMC Work Room	W3	CMU	White	None	0	0.3	Negative
1	3	308D	IMC Work Room	W4	CMU	White	None	0	0.4	Negative
1	3	308D	IMC Work Room	Ceiling	Concrete	White	Moisture Damage	3	0.3	Negative
1	3	308E	IMC Media Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308E	IMC Media Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308E	IMC Media Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308E	IMC Media Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308E	IMC Media Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308E	IMC Media Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308F	IMC Work Room Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308F	IMC Work Room Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308F	IMC Work Room Closet	Door Frame	Metal	Black	None	0	0.7	Positive
1	3	308F	IMC Work Room Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308F	IMC Work Room Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308F	IMC Work Room Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308F	IMC Work Room Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308G	IMC Work Room Restroom	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	3	308G	IMC Work Room Restroom	W1	CMU	White	None	0	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	308G	IMC Work Room Restroom	Door Frame	Metal	Black	None	0	0.9	Positive
1	3	308G	IMC Work Room Restroom	Wall Tile	Ceramic	Grey	None	0	0.1	Negative
1	3	308G	IMC Work Room Restroom	W2	CMU	White	None	0	0.4	Negative
1	3	308G	IMC Work Room Restroom	W3	CMU	White	None	0	0.4	Negative
1	3	308G	IMC Work Room Restroom	W4	CMU	White	None	0	0.4	Negative
1	3	308G	IMC Work Room Restroom	Baseboard (not painted )	Ceramic	Red	None	0	0.4	Negative
1	3	308G	IMC Work Room Restroom	Ceiling	Concrete	White	Moisture Damage	18	0.5	Negative
1	3	308G	IMC Work Room Restroom	Drain Pipe	Metal	White	None	0	0.4	Negative
1	3	H33	IMC Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H33	IMC Hallway	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H33	IMC Hallway	Doorframe	Metal	Tan	None	0	0.2	Negative
1	3	H33	IMC Hallway	Door	Metal	Red	None	0	0.1	Negative
1	3	H33	IMC Hallway	W2	CMU	White	Chipping	50	0.5	Negative
1	3	H33	IMC Hallway	Conduit	Metal	White	None	0	0.1	Negative
1	3	H33	IMC Hallway	Electrical Panel	Metal	White	Chipping	3	0.1	Negative
1	3	H33	IMC Hallway	Radiator	Metal	White	None	0	0.2	Negative
1	3	H33	IMC Hallway	Pipe Insulation	Fiberglass	White	Chipping	10	0.2	Negative
1	3	H33	IMC Hallway	Vent	Metal	White	None	0	0.2	Negative
1	3	H33	IMC Hallway	Baseboard	CMU/Tile	Black	None	0	1.4	Positive
1	3	H33	IMC Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H33	IMC Hallway	W4	CMU	White	Chipping	25	0.4	Negative
1	3	H33	IMC Hallway	Ceiling	Concrete	White	None	0	0.1	Negative
1	3	S35	Stairwell # 4 next to IMC	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S35	Stairwell # 4 next to IMC	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S35	Stairwell # 4 next to IMC	Doorframe	Metal	Red	Chipping	2	0.1	Negative
1	3	S35	Stairwell # 4 next to IMC	Door	Metal	Red	None	0	0.1	Negative
1	3	S35	Stairwell # 4 next to IMC	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S35	Stairwell # 4 next to IMC	Fire Pipe	Metal	White	Chipping	2	0.5	Negative
1	3	S35	Stairwell # 4 next to IMC	Doorframe	Metal	Tan	Chipping	2	0.2	Negative
1	3	S35	Stairwell # 4 next to IMC	Conduit	Metal	Tan	None	0	0.5	Negative
1	3	S35	Stairwell # 4 next to IMC	riser	Metal	Tan	Chipping	30	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	S35	Stairwell # 4 next to IMC	stringer	Metal	Tan	Chipping	15	0.1	Negative
1	3	S35	Stairwell # 4 next to IMC	Stair Cage	Metal	Blue	Chipping	10	0.1	Negative
1	3	S35	Stairwell # 4 next to IMC	stair pan	Metal	Tan	Moisture Damage	8	0.4	Negative
1	3	S35	Stairwell # 4 next to IMC	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S35	Stairwell # 4 next to IMC	baseboard	Metal	Tan	Flaking	11	0.1	Negative
1	3	S35	Stairwell # 4 next to IMC	Radiator	Metal	Brown	None	0	0.3	Negative
1	3	S35	Stairwell # 4 next to IMC	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S35	Stairwell # 4 next to IMC	Ceiling	Concrete	White	Chipping	7	0.4	Negative
1	3	309	Classroom 309	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309	Classroom 309	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309	Classroom 309	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309	Classroom 309	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309	Classroom 309	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309	Classroom 309	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309A	Boy's Restroom across Classroom 309	Floor	Concrete	Bare	N/A	N/A	N/A	N/A
1	3	309A	Boy's Restroom across Classroom 309	W1	CMU	White	None	0	0.3	Negative
1	3	309A	Boy's Restroom across Classroom 309	Doorframe	Metal	Tan	Chipping	3	0.6	Negative
1	3	309A	Boy's Restroom across Classroom 309	Door	Metal	Tan	Chipping	11	0.3	Negative
1	3	309A	Boy's Restroom across Classroom 309	W2	CMU	White	None	0	0.2	Negative
1	3	309A	Boy's Restroom across Classroom 309	Conduit	Metal	White	None	0	0.5	Negative
1	3	309A	Boy's Restroom across Classroom 309	Pipe Insulation	Fiberglass	White	Chipping	2	0.2	Negative
1	3	309A	Boy's Restroom across Classroom 309	W3	CMU	White	None	0	0.3	Negative
1	3	309A	Boy's Restroom across Classroom 309	Baseboard	CMU/Tile	Black	None	0	1.4	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	309A	Boy's Restroom across Classroom 309	W4	CMU	White	None	0	0.4	Negative
1	3	309A	Boy's Restroom across Classroom 309	Divider	Metal	tan	Chipping	2	0.2	Negative
1	3	309A	Boy's Restroom across Classroom 309	Drain pipe	Metal	White	None	0	0.2	Negative
1	3	309A	Boy's Restroom across Classroom 309	Radiator	Metal	Tan	None	0	0	Negative
1	3	309A	Boy's Restroom across Classroom 309	Ceiling	Concrete	White	None	0	0.3	Negative
1	3	310	Book Storage Room 310	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	310	Book Storage Room 310	W1	CMU	White	None	0	0.2	Negative
1	3	310	Book Storage Room 310	Door Frame	Metal	Black	None	0	0.2	Negative
1	3	310	Book Storage Room 310	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.2	Positive
1	3	310	Book Storage Room 310	W2	CMU	White	None	0	0.2	Negative
1	3	310	Book Storage Room 310	W3	CMU	White	None	0	0.2	Negative
1	3	310	Book Storage Room 310	W4	CMU	White	None	0	0.2	Negative
1	3	310	Book Storage Room 310	Ceiling	Concrete	White	None	0	0.2	Negative
1	3	310CA	Book Storage Room 310 - Closet 1	Door Frame (W1)	Metal	Black	None	0	0.2	Negative
1	3	310CB	Book Storage Room 310 - Closet 2	Door Frame (W1)	Metal	Black	None	0	0.3	Negative
1	3	311A	Classroom 311A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	311A	Classroom 311A	W1	CMU	Red/White	None	0	0.4	Negative
1	3	311A	Classroom 311A	W2	CMU	Blue/Red	None	0	0.2	Negative
1	3	311A	Classroom 311A	W3	CMU	White	None	0	0.1	Negative
1	3	311A	Classroom 311A	Column	Concrete	Black/Tan	None	0	0.1	Negative
1	3	311A	Classroom 311A	W4	CMU	Tan	None	0	0.1	Negative
1	3	311A	Classroom 311A	Door Frame	Metal	Black	Chipping	6	1	Positive
1	3	311A	Classroom 311A	Ceiling	Concrete	White	Flaking	12	0.2	Negative
1	3	311A	Classroom 311A	Beam (C)	Concrete	White	Flaking	8	0.2	Negative
1	3	311A	Classroom 311A	Duct (C)	Metal	White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	311A1	IT MDF Closet inside Classroom 311A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	311A1	IT MDF Closet inside Classroom 311A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	311A1	IT MDF Closet inside Classroom 311A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	311A1	IT MDF Closet inside Classroom 311A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	311A1	IT MDF Closet inside Classroom 311A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	311A1	IT MDF Closet inside Classroom 311A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C	Culinary Hallway/Locker Area	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C	Culinary Hallway/Locker Area	W1	CMU	White	Cracking	4	0.5	Negative
1	3	313C	Culinary Hallway/Locker Area	Doorframe	Metal	Black	Chipping	8	0.2	Negative
1	3	313C	Culinary Hallway/Locker Area	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	3	313C	Culinary Hallway/Locker Area	W2	CMU	White	None	0	0.5	Negative
1	3	313C	Culinary Hallway/Locker Area	W3	Drywall	White	Chipping	6	0.2	Negative
1	3	313C	Culinary Hallway/Locker Area	W4	CMU	White	Cracking	6	0.5	Negative
1	3	313C	Culinary Hallway/Locker Area	Pipe Cover	Metal	White	Moisture Damage	5	0.3	Negative
1	3	313C	Culinary Hallway/Locker Area	Pipe Insulation	Fiberglass	White	Moisture Damage	3	0	Negative
1	3	313C	Culinary Hallway/Locker Area	Ceiling	Concrete	White	Moisture Damage	10	0.4	Negative
1	3	313E	Office 313E	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	313E	Office 313E	W1	Sheetrock	Blue	None	0	0.1	Negative
1	3	313E	Office 313E	W2	Sheetrock	Blue	None	0	0.2	Negative
1	3	313E	Office 313E	W3	Sheetrock	Blue	None	0	0.1	Negative
1	3	313E	Office 313E	W4	Sheetrock	Blue	None	0	0.1	Negative
1	3	313E	Office 313E	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	3	313C1	Culinary Hallway/Locker Area Closet next to Entrance	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C1	Culinary Hallway/Locker Area Closet next to Entrance	W1	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	313C1	Culinary Hallway/Locker Area Closet next to Entrance	Door Frame	Metal	Black	None	0	0.7	Positive
1	3	313C1	Culinary Hallway/Locker Area Closet next to Entrance	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C1	Culinary Hallway/Locker Area Closet next to Entrance	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C1	Culinary Hallway/Locker Area Closet next to Entrance	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C1	Culinary Hallway/Locker Area Closet next to Entrance	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C2	Culinary Hallway/Locker Area Middle Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C2	Culinary Hallway/Locker Area Middle Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C2	Culinary Hallway/Locker Area Middle Closet	Door Frame	Metal	Black	Chipping	3	1	Positive
1	3	313C2	Culinary Hallway/Locker Area Middle Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C2	Culinary Hallway/Locker Area Middle Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C2	Culinary Hallway/Locker Area Middle Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C2	Culinary Hallway/Locker Area Middle Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C3	Culinary Hallway/Locker Area Closet opposite 311B	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313C3	Culinary Hallway/Locker Area Closet opposite 311B	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	313C3	Culinary Hallway/Locker Area Closet opposite 311B	Door Frame	Metal	Black	Chipping	5	1	Positive
1	3	313C3	Culinary Hallway/Locker Area Closet opposite 311B	W2	Wood	White	None	0	0.1	Negative
1	3	313C3	Culinary Hallway/Locker Area Closet opposite 311B	W3	Wood	White	None	0	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	313C3	Culinary Hallway/Locker Area Closet opposite 311B	Shelf	Wood	White	None	0	0.4	Negative
1	3	313C3	Culinary Hallway/Locker Area Closet opposite 311B	W4	Wood	White	None	0	0.3	Negative
1	3	313C3	Culinary Hallway/Locker Area Closet opposite 311B	Ceiling	Wood	White	None	0	0.1	Negative
1	3	311B	Culinary Classroom 311B	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	311B	Culinary Classroom 311B	W1	CMU	White	Flaking	6	0.2	Negative
1	3	311B	Culinary Classroom 311B	Door Frame	Metal	Black	Chipping	5	0.1	Negative
1	3	311B	Culinary Classroom 311B	W2	CMU	White	Flaking	4	0.3	Negative
1	3	311B	Culinary Classroom 311B	Univent	Metal	Grey	Friction	10	0.1	Negative
1	3	311B	Culinary Classroom 311B	W3	Sheetrock	White	Chipping	2	0.2	Negative
1	3	311B	Culinary Classroom 311B	W4	CMU	White	Flaking	6	0.4	Negative
1	3	311B	Culinary Classroom 311B	Door Frame	Metal	Black	Chipping	2	1	Positive
1	3	311B	Culinary Classroom 311B	Ceiling	Concrete	White	Flaking	9	0.2	Negative
1	3	311B	Culinary Classroom 311B	Duct (C)	Metal	White	None	0	0.2	Negative
1	3	311C	Culinary Classroom 311B Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	311C	Culinary Classroom 311B Closet	W1	CMU	White	None	0	0.2	Negative
1	3	311C	Culinary Classroom 311B Closet	Door Frame	Metal	Black	Chipping	7	0.1	Negative
1	3	311C	Culinary Classroom 311B Closet	W2	CMU	White	Flaking	3	0.2	Negative
1	3	311C	Culinary Classroom 311B Closet	Door Frame	Metal	Black	Chipping	5	1	Positive
1	3	311C	Culinary Classroom 311B Closet	W3	Sheetrock	White	Flaking	12	0.3	Negative
1	3	311C	Culinary Classroom 311B Closet	Door Frame	Metal	Black	Chipping	2	0.2	Negative
1	3	311C	Culinary Classroom 311B Closet	W4	Sheetrock	White	Flaking	3	0.3	Negative
1	3	311C	Culinary Classroom 311B Closet	Door Frame	Metal	Black	Chipping	4	0.2	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	311C	Culinary Classroom 311B Closet	Ceiling	Concrete	White	Flaking	12	0.3	Negative
1	3	313D	Classroom 313B	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	313D	Classroom 313B	W1	Sheetrock	Blue	None	0	0.1	Negative
1	3	313D	Classroom 313B	W2	Sheetrock	Blue	None	0	0.1	Negative
1	3	313D	Classroom 313B	W3	Sheetrock	Blue	None	0	0.1	Negative
1	3	313D	Classroom 313B	W4	Sheetrock	Blue	None	0	0.1	Negative
1	3	313D	Classroom 313B	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	3	314A	Culinary Suite - Cafe Storage/ Staging Area	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A	Culinary Suite - Cafe Storage/ Staging Area	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A	Culinary Suite - Cafe Storage/ Staging Area	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A	Culinary Suite - Cafe Storage/ Staging Area	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A	Culinary Suite - Cafe Storage/ Staging Area	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A	Culinary Suite - Cafe Storage/ Staging Area	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313A	Ram's Cafe	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	313A	Ram's Cafe	W1	Sheetrock	Tan	None	0	0.1	Negative
1	3	313A	Ram's Cafe	Door Frame	Metal	Tan	None	0	0.2	Negative
1	3	313A	Ram's Cafe	W2	Sheetrock	Tan	None	0	0.2	Negative
1	3	313A	Ram's Cafe	W3	Sheetrock	Tan	None	0	0.1	Negative
1	3	313A	Ram's Cafe	Door Frame	Metal	Blue	None	0	0.8	Positive
1	3	313A	Ram's Cafe	W4	Sheetrock	Tan	None	0	0.1	Negative
1	3	313A	Ram's Cafe	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	3	313	Cafe Seating Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	313	Cafe Seating Area	W1	Sheetrock	Blue	None	0	0.1	Negative
1	3	313	Cafe Seating Area	W2	Sheetrock	Blue	None	0	0.2	Negative
1	3	313	Cafe Seating Area	Door Frame	Metal	Blue	None	0	0.2	Negative
1	3	313	Cafe Seating Area	W3	Sheetrock	Blue	None	0	0.2	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	3	313	Cafe Seating Area	Door Frame	Metal	Blue	None	0	0.2	Negative
1	3	313	Cafe Seating Area	W4	Sheetrock	Blue	None	0	0.1	Negative
1	3	313	Cafe Seating Area	Door Frame	Metal	Blue	None	0	0.2	Negative
1	3	313	Cafe Seating Area	Ceiling	Concrete	White	None	0	0.2	Negative
1	3	313B	Culinary Suite - Cafe Staging	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313B	Culinary Suite - Cafe Staging	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313B	Culinary Suite - Cafe Staging	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313B	Culinary Suite - Cafe Staging	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313B	Culinary Suite - Cafe Staging	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	313B	Culinary Suite - Cafe Staging	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A1	Culinary Suite - Break Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A1	Culinary Suite - Break Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A1	Culinary Suite - Break Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A1	Culinary Suite - Break Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A1	Culinary Suite - Break Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A1	Culinary Suite - Break Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A2	Culinary Suite - Storeroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A2	Culinary Suite - Storeroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A2	Culinary Suite - Storeroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A2	Culinary Suite - Storeroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A2	Culinary Suite - Storeroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314A2	Culinary Suite - Storeroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314	Culinary Suite - Cafe	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314	Culinary Suite - Cafe	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314	Culinary Suite - Cafe	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314	Culinary Suite - Cafe	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314	Culinary Suite - Cafe	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	314	Culinary Suite - Cafe	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	315	Culinary Suite - Kitchen	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	315	Culinary Suite - Kitchen	W1	Sheetrock	White	None	0	0.1	Negative
1	3	315	Culinary Suite - Kitchen	Door Frame	Metal	Blue	Chipping	1	0.4	Negative
1	3	315	Culinary Suite - Kitchen	W2	Sheetrock	White	None	0	0.2	Negative
1	3	315	Culinary Suite - Kitchen	W3	Sheetrock	White	None	0	0.3	Negative
1	3	315	Culinary Suite - Kitchen	Column	Concrete	White	Flaking	1	0.2	Negative
1	3	315	Culinary Suite - Kitchen	W4	Sheetrock	White	None	0	0.2	Negative
1	3	315	Culinary Suite - Kitchen	Door Frame	Metal	Blue	Chipping	2	0.4	Negative
1	3	315	Culinary Suite - Kitchen	Ceiling	Concrete	White	Flaking	2	0.2	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	Floor	Terracota	Red	None	0	0.2	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	W1	Metal	White	None	0	0.3	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	Door Frame	Metal	Blue	Chipping	3	0.2	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	W2	Metal	White	None	0	0.3	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	Door Frame	Metal	Blue	Chipping	1	0.2	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	Sill	Metal	Brown	Chipping	20	0.2	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	W3	Metal	White	None	0	0.3	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	Door Frame	Metal	Blue	Chipping	1	0.1	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	W4	Metal	White	None	0	0.2	Negative
1	3	315A	Culinary Suite - Kitchen/Dish Washing Room	Ceiling	Concrete	White	None	0	0.2	Negative
1	3	315B	Culinary Suite - Kitchen Unisex Restroom	Floor	Terracota	Red	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	315B	Culinary Suite - Kitchen Unisex Restroom	W1	Ceramic	Grey	None	0	0.2	Negative
1	3	315B	Culinary Suite - Kitchen Unisex Restroom	W2	Ceramic	Grey	None	0	0.4	Negative
1	3	315B	Culinary Suite - Kitchen Unisex Restroom	W3	Ceramic	Grey	None	0	0.2	Negative
1	3	315B	Culinary Suite - Kitchen Unisex Restroom	W4	Ceramic	Grey	None	0	0.2	Negative
1	3	315B	Culinary Suite - Kitchen Unisex Restroom	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	3	315C	Culinary Suite - Kitchen Handicapped Restroom	Floor	Terracota	Red	None	0	0.1	Negative
1	3	315C	Culinary Suite - Kitchen Handicapped Restroom	W1	Ceramic	Grey	None	0	0.2	Negative
1	3	315C	Culinary Suite - Kitchen Handicapped Restroom	W2	Ceramic	Grey	None	0	0.4	Negative
1	3	315C	Culinary Suite - Kitchen Handicapped Restroom	W3	Ceramic	Grey	None	0	0.3	Negative
1	3	315C	Culinary Suite - Kitchen Handicapped Restroom	W4	Ceramic	Grey	None	0	0.2	Negative
1	3	315C	Culinary Suite - Kitchen Handicapped Restroom	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	3	315D	Small Hallway by Kitchen	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	315D	Small Hallway by Kitchen	W1	Sheetrock	Tan	None	0	0.1	Negative
1	3	315D	Small Hallway by Kitchen	Door Frame	Metal	Tan	None	0	0.4	Negative
1	3	315D	Small Hallway by Kitchen	W2	Sheetrock	Tan	None	0	0.1	Negative
1	3	315D	Small Hallway by Kitchen	Door Frame	Metal	Tan	None	0	0.2	Negative
1	3	315D	Small Hallway by Kitchen	W3	Sheetrock	Tan	None	0	0.1	Negative
1	3	315D	Small Hallway by Kitchen	W4	Sheetrock	Tan	None	0	0.1	Negative
1	3	315D	Small Hallway by Kitchen	Door Frame	Metal	Blue	None	0	0.2	Negative
1	3	315D	Small Hallway by Kitchen	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	3	315DA	Storage in Small Hallway by Kitchen Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	315DA	Storage in Small Hallway by Kitchen Area	W1	Sheetrock	Tan	None	0	0.1	Negative
1	3	315DA	Storage in Small Hallway by Kitchen Area	W2	Sheetrock	Tan	None	0	0.2	Negative
1	3	315DA	Storage in Small Hallway by Kitchen Area	Pipe Cover	Metal	Tan	None	0	0.3	Negative
1	3	315DA	Storage in Small Hallway by Kitchen Area	Shelf (W2-4)	Wood	Tan	Chipping	4	0.2	Negative
1	3	315DA	Storage in Small Hallway by Kitchen Area	W2	Sheetrock	Tan	None	0	0.2	Negative
1	3	315DA	Storage in Small Hallway by Kitchen Area	W3	Sheetrock	Tan	None	0	0.1	Negative
1	3	315DA	Storage in Small Hallway by Kitchen Area	W4	Sheetrock	Tan	None	0	0.1	Negative
1	3	315DA	Storage in Small Hallway by Kitchen Area	Ceiling	Concrete	Tan	None	0	0.2	Negative
1	3	312	Classroom 312C	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	312	Classroom 312C	W1	CMU	White	Chipping	3	0.2	Negative
1	3	312	Classroom 312C	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	1.1	Positive
1	3	312	Classroom 312C	W2	CMU	White	Chipping	1	0.1	Negative
1	3	312	Classroom 312C	W3	CMU	White	Chipping	5	0.2	Negative
1	3	312	Classroom 312C	Radiator	Metal	White	None	0	0.1	Negative
1	3	312	Classroom 312C	Chase Door/Frame	Metal	White	None	0	0.1	Negative
1	3	312	Classroom 312C	Door Frame	Metal	Black	None	0	0.5	Negative
1	3	312	Classroom 312C	W4	CMU	White	None	0	0.2	Negative
1	3	312	Classroom 312C	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312D	Classroom 312C Closet on 312B side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312D	Classroom 312C Closet on 312B side	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312D	Classroom 312C Closet on 312B side	W2	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	312D	Classroom 312C Closet on 312B side	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312D	Classroom 312C Closet on 312B side	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312D	Classroom 312C Closet on 312B side	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312E	Classroom 312C Closet across from Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312E	Classroom 312C Closet across from Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312E	Classroom 312C Closet across from Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312E	Classroom 312C Closet across from Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312E	Classroom 312C Closet across from Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312E	Classroom 312C Closet across from Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312A	Office 312A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	312A	Office 312A	W1	CMU	Tan	None	0	0.5	Negative
1	3	312A	Office 312A	Door Frame	Metal	Black	Chipping	6	0.8	Positive
1	3	312A	Office 312A	Baseboard (W1-3)	CMU/Tile	Black/Tan	Chipping	5	1.3	Positive
1	3	312A	Office 312A	W3	CMU	Tan	None	0	0.5	Negative
1	3	312A	Office 312A	Door Frame	Metal	Tan	Chipping	2	0.2	Negative
1	3	312A	Office 312A	Conduit	Metal	Tan	None	0	0.3	Negative
1	3	312A	Office 312A	W4	Sheetrock	Tan	None	0	0.3	Negative
1	3	312A	Office 312A	Ceiling	Concrete	Tan	Flaking	5	0.3	Negative
1	3	312F	Storage Room inside Office 312A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312F	Storage Room inside Office 312A	W1	CMU	N/A	N/A	N/A	N/A	N/A
1	3	312F	Storage Room inside Office 312A	Shelf (W1-3)	Wood	Grey	Chipping	3	0.4	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	312F	Storage Room inside Office 312A	W2	CMU	N/A	N/A	N/A	N/A	N/A
1	3	312F	Storage Room inside Office 312A	W3	CMU	N/A	N/A	N/A	N/A	N/A
1	3	312F	Storage Room inside Office 312A	Pipe	Metal	Grey	None	0	1.1	Positive
1	3	312F	Storage Room inside Office 312A	Pipe Cover	Metal	Grey	None	0	0.3	Negative
1	3	312F	Storage Room inside Office 312A	Access Door	Metal	Grey	Chipping	6	0.4	Negative
1	3	312F	Storage Room inside Office 312A	W4	CMU	N/A	N/A	N/A	N/A	N/A
1	3	312F	Storage Room inside Office 312A	Ceiling	Concrete	White	None	0	0.2	Negative
1	3	312G	Storage Room next to Office 312A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	312G	Storage Room next to Office 312A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	312G	Storage Room next to Office 312A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	312G	Storage Room next to Office 312A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	312G	Storage Room next to Office 312A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	312G	Storage Room next to Office 312A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	312B	Office 312B	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	3	312B	Office 312B	W1	CMU	Grey	None	0	0.5	Negative
1	3	312B	Office 312B	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	3	312B	Office 312B	Door Frame	Metal	Black	Chipping	4	0.7	Positive
1	3	312B	Office 312B	W2	CMU	Grey	None	0	0.4	Negative
1	3	312B	Office 312B	W3	CMU	Grey	None	0	0.4	Negative
1	3	312B	Office 312B	Conduit	Metal	Grey	None	0	0.3	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	312B	Office 312B	W4	CMU	Grey	None	0	0.4	Negative
1	3	312B	Office 312B	Ceiling	Concrete	White	None	0	0.2	Negative
1	3	H34	Hallway from Classrooms 311 to 315	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H34	Hallway from Classrooms 311 to 315	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H34	Hallway from Classrooms 311 to 315	Door Frame	Metal	Blue	Chipping	8	1.2	Positive
1	3	H34	Hallway from Classrooms 311 to 315	Door	Wood	Red	Chipping	3	0.1	Negative
1	3	H34	Hallway from Classrooms 311 to 315	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	3	H34	Hallway from Classrooms 311 to 315	W2	CMU	White	Flaking	12	0.4	Negative
1	3	H34	Hallway from Classrooms 311 to 315	Radiator	Metal	White	None	0	0.3	Negative
1	3	H34	Hallway from Classrooms 311 to 315	Electrical Panels	Metal	Black	Chipping	2	0.4	Negative
1	3	H34	Hallway from Classrooms 311 to 315	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H34	Hallway from Classrooms 311 to 315	W4	CMU	White	Flaking	6	0.5	Negative
1	3	H34	Hallway from Classrooms 311 to 315	Vent	Metal	White	None	0	0.3	Negative
1	3	H34	Hallway from Classrooms 311 to 315	Ceiling	Concrete	White	None	0	0.4	Negative
1	3	H34	Hallway from Classrooms 311 to 315	Pipe Insulation	Fiberglass	White	Chipping	10	0.1	Negative
1	3	316	Computer Lab 316	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
1	3	316	Computer Lab 316	W1	Sheetrock	White	Chipping	3	0.2	Negative
1	3	316	Computer Lab 316	Door Frame	Metal	Tan	Chipping	2	1.1	Positive
1	3	316	Computer Lab 316	Door Frame	Metal	Tan	Chipping	4	1	Positive
1	3	316	Computer Lab 316	W2	Sheetrock	White	Chipping	1	0.2	Negative
1	3	316	Computer Lab 316	W3	Sheetrock	White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	316	Computer Lab 316	Pipe Cover	Metal	White	None	0	0.6	Negative
1	3	316	Computer Lab 316	Column	Concrete	White	Flaking	4	0.2	Negative
1	3	316	Computer Lab 316	Electrical Panel	Metal	Grey	None	0	0	Negative
1	3	316	Computer Lab 316	Pipe	Metal	White	None	0	0.1	Negative
1	3	316	Computer Lab 316	W4	Sheetrock	White	None	0	0.2	Negative
1	3	316	Computer Lab 316	Sill	Metal	Brown	Chipping	8	0.1	Negative
1	3	316	Computer Lab 316	Ceiling	Concrete	White	Flaking	3	0.3	Negative
1	3	S32	Stairwell adjacent to Classroom 316	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell adjacent to Classroom 316	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell adjacent to Classroom 316	Doorframe	Metal	Red	Chipping	5	0.2	Negative
1	3	S32	Stairwell adjacent to Classroom 316	Door	Metal	Red	Chipping	7	0.1	Negative
1	3	S32	Stairwell adjacent to Classroom 316	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell adjacent to Classroom 316	Conduit	Metal	Tan	None	0	0.3	Negative
1	3	S32	Stairwell adjacent to Classroom 316	stair pan	Metal	Tan	Flaking	15	0.3	Negative
1	3	S32	Stairwell adjacent to Classroom 316	Riser	Metal	Black	Chipping	30	0.2	Negative
1	3	S32	Stairwell adjacent to Classroom 316	Stringer	Metal	Black	Chipping	11	0.1	Negative
1	3	S32	Stairwell adjacent to Classroom 316	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell adjacent to Classroom 316	Baseboard	Metal	Black	Chipping	9	0.2	Negative
1	3	S32	Stairwell adjacent to Classroom 316	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell adjacent to Classroom 316	Fire Pipe	Metal	Tan	Flaking	2	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	S32	Stairwell adjacent to Classroom 316	Doorframe	Metal	Tan	Chipping	1	0.5	Negative
1	3	S32	Stairwell adjacent to Classroom 316	Ceiling	Concrete	White	Flaking	13	0.3	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell #5 adjacent to Classroom 310	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell #5 adjacent to Classroom 310	Doorframe	Metal	Red	Chipping	9	0.2	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	Door	Metal	Red	Friction	6	0.1	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell #5 adjacent to Classroom 310	Conduit	Metal	Tan	Chipping	4	0.2	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	Stair Pan	Metal	tan	Flaking	6	0.9	Positive
1	3	S31	Stairwell #5 adjacent to Classroom 310	Riser	Metal	Black	Chipping	22	0.1	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	Stringer	Metal	Black	Chipping	8	0.1	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell #5 adjacent to Classroom 310	Baseboard	Metal	Black	Chipping	4	0.1	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell #5 adjacent to Classroom 310	Fire Pipe	Metal	Tan	Chipping	2	0.3	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	Doorframe	Metal	Tan	Chipping	5	0.5	Negative
1	3	S31	Stairwell #5 adjacent to Classroom 310	Ceiling	Concrete	White	Flaking	10	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	3	H31	Hallway from Classrooms 304 to 316	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H31	Hallway from Classrooms 304 to 316	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H31	Hallway from Classrooms 304 to 316	Door Frame	Metal	Red	Chipping	7	1.5	Positive
1	3	H31	Hallway from Classrooms 304 to 316	Door	Metal	Red	Friction	14	0.1	Negative
1	3	H31	Hallway from Classrooms 304 to 316	W2	CMU	White	Flaking	185	0.4	Negative
1	3	H31	Hallway from Classrooms 304 to 316	Radiator	Metal	White	None	0	0	Negative
1	3	H31	Hallway from Classrooms 304 to 316	Vent	Metal	White	None	0	0.1	Negative
1	3	H31	Hallway from Classrooms 304 to 316	Elevator Door and Doorframe	Metal	Black	None	0	0.1	Negative
1	3	H31	Hallway from Classrooms 304 to 316	Electrical Panel	Metal	Black	Chipping	8	0.1	Negative
1	3	H31	Hallway from Classrooms 304 to 316	Baseboard	CMU/Tile	Black	None	0	1.4	Positive
1	3	H31	Hallway from Classrooms 304 to 316	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H31	Hallway from Classrooms 304 to 316	W4	CMU	White	Flaking	75	0.5	Negative
1	3	H31	Hallway from Classrooms 304 to 316	doorframe	Metal	Red	Chipping	4	0.4	Negative
1	3	H31	Hallway from Classrooms 304 to 316	door	Metal	Red	Friction	10	0.2	Negative
1	3	H31	Hallway from Classrooms 304 to 316	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S26	Stairwell adjacent to Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S26	Stairwell adjacent to Classroom 200	W1	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S26	Stairwell adjacent to Classroom 200	Doorframe	Metal	Tan	Chipping	3	0	Negative
1	2	S26	Stairwell adjacent to Classroom 200	Door	Metal	Red	Chipping	9	0.1	Negative
1	2	S26	Stairwell adjacent to Classroom 200	W2	CMU	White	None	0	0	Negative
1	2	S26	Stairwell adjacent to Classroom 200	Pipe	Metal	White	None	0	0.3	Negative
1	2	S26	Stairwell adjacent to Classroom 200	Riser	Metal	Black	Chipping	5	0.1	Negative
1	2	S26	Stairwell adjacent to Classroom 200	Stringer	Metal	Black	Chipping	6	0.1	Negative
1	2	S26	Stairwell adjacent to Classroom 200	Baseboard	Metal	Black	None	0	0.1	Negative
1	2	S26	Stairwell adjacent to Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S26	Stairwell adjacent to Classroom 200	Stair Pan	Metal	White	None	0	0.3	Negative
1	2	S26	Stairwell adjacent to Classroom 200	W4	CMU	White	None	0	0	Negative
1	2	S26	Stairwell adjacent to Classroom 200	Conduit	Metal	White	Chipping	4	0.3	Negative
1	2	S26	Stairwell adjacent to Classroom 200	Fire Pipe	Metal	White	Chipping	1	0.3	Negative
1	2	S26	Stairwell adjacent to Classroom 200	Ceiling	Concrete	White	Flaking	20	0.3	Negative
1	2	200	Classroom 200	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	200	Classroom 200	W1	CMU	White	Flaking	6	0.3	Negative
1	2	200	Classroom 200	Door Frame	Metal	Blue	Chipping	4	1	Positive
1	2	200	Classroom 200	Window Frame	Wood	Brown	Chipping	1	0.1	Negative
1	2	200	Classroom 200	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	1.3	Positive
1	2	200	Classroom 200	W2	CMU	White	Flaking	8	0.5	Negative
1	2	200	Classroom 200	Univent	Metal	Blue	Chipping	3	0	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	200	Classroom 200	Beam	Concrete	White	Flaking	10	0.3	Negative
1	2	200	Classroom 200	W3	CMU	White	Flaking	7	0.5	Negative
1	2	200	Classroom 200	Column	Concrete	White	Chipping	2	0.2	Negative
1	2	200	Classroom 200	Pipe Cover	Metal	White	None	0	0.3	Negative
1	2	200	Classroom 200	Door Frame	Metal	Blue	Chipping	3	1	Positive
1	2	200	Classroom 200	Pipe	Metal	White	None	0	0.2	Negative
1	2	200	Classroom 200	W4	CMU	White	Cracking	4	0.4	Negative
1	2	200	Classroom 200	Duct	Metal	White	None	0	0.2	Negative
1	2	200	Classroom 200	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	2	H22	Hallway from Classrooms 200 to 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H22	Hallway from Classrooms 200 to 205	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H22	Hallway from Classrooms 200 to 205	W2	CMU	White	Flaking	10	0.3	Negative
1	2	H22	Hallway from Classrooms 200 to 205	Radiator	Metal	White	None	0	0.2	Negative
1	2	H22	Hallway from Classrooms 200 to 205	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H22	Hallway from Classrooms 200 to 205	Doorframe	Metal	Tan	Chipping	2	0.3	Negative
1	2	H22	Hallway from Classrooms 200 to 205	Door	Wood	Brown	Chipping	4	0.1	Negative
1	2	H22	Hallway from Classrooms 200 to 205	W4	CMU	White	Flaking	12	0.4	Negative
1	2	H22	Hallway from Classrooms 200 to 205	Electrical Panel	Metal	White	Chipping	1	0.1	Negative
1	2	H22	Hallway from Classrooms 200 to 205	Vent	Metal	White	None	0	0.2	Negative
1	2	H22	Hallway from Classrooms 200 to 205	Baseboard	CMU/Tile	Black	None	0	1.4	Positive
1	2	H22	Hallway from Classrooms 200 to 205	Conduit	Metal	White	None	0	0.7	Positive

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	H22	Hallway from Classrooms 200 to 205	Ceiling	Concrete	White	Flaking	8	0.3	Negative
1	2	200	Nap/Play Room off Daycare Room 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Nap/Play Room off Daycare Room 201	W1	CMU	White	None	0	0.4	Negative
1	2	200	Nap/Play Room off Daycare Room 201	Door Frame	Metal	Blue	Chipping	6	0.8	Positive
1	2	200	Nap/Play Room off Daycare Room 201	Baseboard (W1-4)	CMU/Tile	Black	Friction	4	1.5	Positive
1	2	200	Nap/Play Room off Daycare Room 201	Door Frame	Metal	Blue/Brown	Chipping	5	0.7	Positive
1	2	200	Nap/Play Room off Daycare Room 201	W2	CMU	White	None	0	0.4	Negative
1	2	200	Nap/Play Room off Daycare Room 201	Door Frame	Metal	Brown/Blue	Chipping	4	0.8	Positive
1	2	200	Nap/Play Room off Daycare Room 201	W3	CMU	White	None	0	0.5	Negative
1	2	200	Nap/Play Room off Daycare Room 201	Beam	Concrete	White	Flaking	2	0.3	Negative
1	2	200	Nap/Play Room off Daycare Room 201	Univent	Metal	Blue	Chipping	3	0.1	Negative
1	2	200	Nap/Play Room off Daycare Room 201	Pipe Cover	Metal	Tan	None	0	0.1	Negative
1	2	200	Nap/Play Room off Daycare Room 201	W4	CMU	White	None	0	0.2	Negative
1	2	200	Nap/Play Room off Daycare Room 201	Door Frame	Metal	Blue	None	0	0.6	Negative
1	2	200	Nap/Play Room off Daycare Room 201	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	2	201	Daycare Room 201	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	201	Daycare Room 201	W1	CMU	White	None	0	0.4	Negative
1	2	201	Daycare Room 201	Door Frame	Metal	Blue	Chipping	6	0.8	Positive



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	201	Daycare Room 201	Baseboard (W1-4)	CMU/Tile	Black	Friction	4	1.5	Positive
1	2	201	Daycare Room 201	Door Frame	Metal	Blue/Brown	Chipping	5	0.7	Positive
1	2	201	Daycare Room 201	W2	CMU	White	None	0	0.4	Negative
1	2	201	Daycare Room 201	Door Frame	Metal	Brown/Blue	Chipping	4	0.8	Positive
1	2	201	Daycare Room 201	W3	CMU	White	None	0	0.5	Negative
1	2	201	Daycare Room 201	Beam	Concrete	White	Flaking	2	0.3	Negative
1	2	201	Daycare Room 201	Univent	Metal	Blue	Chipping	3	0.1	Negative
1	2	201	Daycare Room 201	Pipe Cover	Metal	Tan	None	0	0.1	Negative
1	2	201	Daycare Room 201	W4	CMU	White	None	0	0.2	Negative
1	2	201	Daycare Room 201	Door Frame	Metal	Blue	None	0	0.6	Negative
1	2	201	Daycare Room 201	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	2	200A	Daycare Room 201 Student Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	200A	Daycare Room 201 Student Restroom	W1	Plaster	White	None	0	0.3	Negative
1	2	200A	Daycare Room 201 Student Restroom	W1-W4	Ceramic	Tan	None	0	0.1	Negative
1	2	200A	Daycare Room 201 Student Restroom	Pipe	Metal	White	None	0	0.2	Negative
1	2	200A	Daycare Room 201 Student Restroom	Door Frame	Metal	Blue	None	0	0.2	Negative
1	2	200A	Daycare Room 201 Student Restroom	W2	Plaster	White	None	0	0.2	Negative
1	2	200A	Daycare Room 201 Student Restroom	Tub	Ceramic	White	None	0	10.1	Positive
1	2	200A	Daycare Room 201 Student Restroom	W3	Plaster	White	Cracking	10	0.4	Negative
1	2	200A	Daycare Room 201 Student Restroom	Stall Divider	Metal	Tan	Moisture Damage	32	0.2	Negative
1	2	200A	Daycare Room 201 Student Restroom	W4	Plaster	White	None	0	0.3	Negative
1	2	200A	Daycare Room 201 Student Restroom	Radiator	Metal	Tan	None	0	0.1	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>							
			<b>Inspection Company: BATA</b>							
			<b>South Philadelphia High School</b>							
			<b>2101 S Broad St, Philadelphia, PA 19148</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>r</b>	<b>S</b> <b>p</b> <b>a</b> <b>c</b> <b>e</b> <b>#</b>	<b>O</b> <b>n</b> <b>-</b> <b>S</b> <b>i</b> <b>t</b> <b>e</b> <b>R</b> <b>o</b> <b>o</b> <b>m</b> <b>N</b> <b>a</b> <b>m</b> <b>e</b>	<b>C</b> <b>o</b> <b>m</b> <b>p</b> <b>o</b> <b>n</b> <b>e</b> <b>n</b> <b>t</b>	<b>S</b> <b>u</b> <b>b</b> <b>s</b> <b>t</b> <b>r</b> <b>a</b> <b>t</b> <b>e</b> <b>M</b> <b>a</b> <b>t</b> <b>e</b> <b>r</b> <b>i</b> <b>a</b> <b>l</b>	<b>C</b> <b>o</b> <b>l</b> <b>o</b> <b>r</b>	<b>D</b> <b>e</b> <b>s</b> <b>c</b> <b>r</b> <b>i</b> <b>p</b> <b>t</b> <b>i</b> <b>o</b> <b>n</b> <b>o</b> <b>f</b> <b>D</b> <b>a</b> <b>m</b> <b>a</b> <b>g</b> <b>e</b>	<b>D</b> <b>a</b> <b>m</b> <b>a</b> <b>g</b> <b>e</b> <b>Q</b> <b>u</b> <b>a</b> <b>n</b> <b>t</b> <b>i</b> <b>t</b> <b>y</b> <b>(</b> <b>s</b> <b>f</b> <b>)</b>	<b>X</b> <b>R</b> <b>F</b> <b>R</b> <b>e</b> <b>a</b> <b>d</b> <b>i</b> <b>n</b> <b>g</b> <b>(</b> <b>m</b> <b>g</b> <b>/</b> <b>c</b> <b>m</b> <b>2</b> <b>)</b>	<b>X</b> <b>R</b> <b>F</b> <b>(</b> <b>p</b> <b>o</b> <b>s</b> <b>i</b> <b>t</b> <b>i</b> <b>v</b> <b>e</b> <b>/</b> <b>n</b> <b>e</b> <b>g</b> <b>a</b> <b>t</b> <b>i</b> <b>v</b> <b>e</b> <b>)</b>
1	2	200A	Daycare Room 201 Student Restroom	Ceiling	Concrete	White	None	0	0.2	Negative
1	2	201C	Daycare Room 201 Staff Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	201C	Daycare Room 201 Staff Restroom	W1	CMU	White	None	0	0.2	Negative
1	2	201C	Daycare Room 201 Staff Restroom	W2	CMU	White	None	0	0	Negative
1	2	201C	Daycare Room 201 Staff Restroom	Door Frame	Metal	Brown	Chipping	2	0.3	Negative
1	2	201C	Daycare Room 201 Staff Restroom	Coat Rack	Wood	White	None	0	0.5	Negative
1	2	201C	Daycare Room 201 Staff Restroom	W3	CMU	White	None	0	0.4	Negative
1	2	201C	Daycare Room 201 Staff Restroom	Door Frame	Metal	Blue	Chipping	3	0.5	Negative
1	2	201C	Daycare Room 201 Staff Restroom	W4	CMU	White	None	0	0	Negative
1	2	201C	Daycare Room 201 Staff Restroom	Ceiling	Concrete	White	None	0	0.2	Negative
1	2	201B	Daycare Room 201 Closet next to Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Daycare Room 201 Closet next to Kitchen	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Daycare Room 201 Closet next to Kitchen	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Daycare Room 201 Closet next to Kitchen	Shelf	Wood	Green	None	0	0.3	Negative
1	2	201B	Daycare Room 201 Closet next to Kitchen	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Daycare Room 201 Closet next to Kitchen	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Daycare Room 201 Closet next to Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	201A	Daycare Kitchen	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	201A	Daycare Kitchen	W1	CMU	White	None	0	0.1	Negative
1	2	201A	Daycare Kitchen	Pipe	Metal	White	None	0	0.8	Positive
1	2	201A	Daycare Kitchen	Baseboard (W1-4)	CMU/Tile	Black	Chipping	5	1	Positive
1	2	201A	Daycare Kitchen	W2	CMU	White	None	0	0.3	Negative
1	2	201A	Daycare Kitchen	Door Frame	Metal	Brown	Chipping	6	0.6	Negative
1	2	201A	Daycare Kitchen	W3	CMU	White	None	0	0.2	Negative
1	2	201A	Daycare Kitchen	Soffit	Transite	White	Flaking	3	0.1	Negative
1	2	201A	Daycare Kitchen	Door Frame	Metal	Brown	Chipping	7	1.1	Positive
1	2	201A	Daycare Kitchen	W4	CMU	White	None	0	0	Negative
1	2	201A	Daycare Kitchen	Univent	Metal	Tan	Chipping	4	0.1	Negative
1	2	201A	Daycare Kitchen	Pipe Cover	Metal	Tan	Chipping	3	0.4	Negative
1	2	201A	Daycare Kitchen	Ceiling	Concrete	White	Flaking	7	0.4	Negative
1	2	201E	Custodial Closet across from Daycare Room 201	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	201E	Custodial Closet across from Daycare Room 201	W1	CMU	White	Flaking	5	0	Negative
1	2	201E	Custodial Closet across from Daycare Room 201	Door Frame	Metal	Black	Chipping	10	0.9	Positive
1	2	201E	Custodial Closet across from Daycare Room 201	W2	CMU	White	Flaking	2	0.4	Negative
1	2	201E	Custodial Closet across from Daycare Room 201	W3	CMU	White	Flaking	2	0.4	Negative
1	2	201E	Custodial Closet across from Daycare Room 201	Shelf	Wood	White	Chipping	19	0.4	Negative
1	2	201E	Custodial Closet across from Daycare Room 201	Pipe Insulation	Fiberglass	White	Flaking	7	0.4	Negative
1	2	201E	Custodial Closet across from Daycare Room 201	Duct	Metal	White	Moisture Damage	4	0.4	Negative
1	2	201E	Custodial Closet across from Daycare Room 201	W4	CMU	White	Flaking	6	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	201E	Custodial Closet across from Daycare Room 201	Ceiling	Concrete	White	None	0	0.2	Negative
1	2	201D	Head Start Storeroom next to Custodial Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201D	Head Start Storeroom next to Custodial Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201D	Head Start Storeroom next to Custodial Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201D	Head Start Storeroom next to Custodial Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201D	Head Start Storeroom next to Custodial Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201D	Head Start Storeroom next to Custodial Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Daycare Room 202	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	202	Daycare Room 202	W1	CMU	White	Flaking	2	0.5	Negative
1	2	202	Daycare Room 202	Soffit (W1,2,4)	Metal	White	None	0	0.2	Negative
1	2	202	Daycare Room 202	Baseboard (W1-4)	CMU/Tile	Black	Chipping	31	0.5	Negative
1	2	202	Daycare Room 202	Door Frame	Metal	Blue	Chipping	2	0.3	Negative
1	2	202	Daycare Room 202	W2	CMU	White	Chipping	2	0.4	Negative
1	2	202	Daycare Room 202	Dividers	Sheetrock/Wood	White	Chipping	5	0.2	Negative
1	2	202	Daycare Room 202	Door Frame	Metal	Blue	None	0	1.1	Positive
1	2	202	Daycare Room 202	Window Frame	Wood	Brown	Chipping	3	0	Negative
1	2	202	Daycare Room 202	W3	CMU	White	Chipping	2	0.5	Negative
1	2	202	Daycare Room 202	Column	Concrete	White	Chipping	4	0.1	Negative
1	2	202	Daycare Room 202	Univent	Metal	Blue	Chipping	6	0.1	Negative
1	2	202	Daycare Room 202	Pipe Cover	Metal	White	None	0	0.2	Negative
1	2	202	Daycare Room 202	W4	CMU	White	None	0	0.3	Negative
1	2	202	Daycare Room 202	Pipe	Metal	White	None	0	0.5	Negative
1	2	202	Daycare Room 202	Ceiling	Concrete	White	Chipping	5	0.2	Negative
1	2	203	Storeroom 203	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	203	Storeroom 203	W1	CMU	White	None	0	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	203	Storeroom 203	Door Frame	Metal	Black	Chipping	4	0.1	Negative
1	2	203	Storeroom 203	Door Frame	Metal	Black	Chipping	2	0.5	Negative
1	2	203	Storeroom 203	Conduit (W1,4)	Metal	White	None	0	0.4	Negative
1	2	203	Storeroom 203	Baseboard (w1-4)	CMU/Tile	Black	Chipping	6	1.3	Positive
1	2	203	Storeroom 203	W2	CMU	White	Flaking	4	0	Negative
1	2	203	Storeroom 203	Door Frame	Metal	Black	Chipping	1	0.6	Negative
1	2	203	Storeroom 203	Door Frame	Metal	Brown	Chipping	2	0.4	Negative
1	2	203	Storeroom 203	W3	CMU	White	None	0	0.5	Negative
1	2	203	Storeroom 203	Univent	Metal	Tan	Chipping	4	0.1	Negative
1	2	203	Storeroom 203	Pipe Cover	Metal	Tan	None	0	0.2	Negative
1	2	203	Storeroom 203	W4	CMU	White	Flaking	4	0.5	Negative
1	2	203	Storeroom 203	Window Frame	Wood	Black	None	0	0	Negative
1	2	203	Storeroom 203	Ceiling	Spline CT	N/A	N/A	N/A	N/A	N/A
1	2	203	Storeroom 203	Beam (C)	Concrete	White	Flaking	8	0.4	Negative
1	2	203	Storeroom 203	Pipe	Metal	White	None	0	0.4	Negative
1	2	203A	Storeroom 203 Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	203A	Storeroom 203 Closet	W1	CMU	White	None	0	0.4	Negative
1	2	203A	Storeroom 203 Closet	Soffit (W1,3)	Metal	White	None	0	0.1	Negative
1	2	203A	Storeroom 203 Closet	W2	CMU	White	None	0	0.5	Negative
1	2	203A	Storeroom 203 Closet	Electrical Panel	Metal	White	None	0	0.1	Negative
1	2	203A	Storeroom 203 Closet	W3	CMU	White	None	0	0.5	Negative
1	2	203A	Storeroom 203 Closet	W4	CMU	White	None	0	0.5	Negative
1	2	203A	Storeroom 203 Closet	Ceiling	Concrete	White	None	0	0.2	Negative
1	2	204	Storeroom 204	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	204	Storeroom 204	W1	CMU	White	Chipping	2	0.4	Negative
1	2	204	Storeroom 204	Door Frame	Metal	Brown	Chipping	3	0.6	Negative
1	2	204	Storeroom 204	Baseboard (W1-4)	CMU/Tile	Black	Chipping	2	0.9	Positive
1	2	204	Storeroom 204	W2	CMU	White	Chipping	4	0.5	Negative
1	2	204	Storeroom 204	Door Frame	Metal	Black	Chipping	5	0.6	Negative
1	2	204	Storeroom 204	W2	Sheetrock	White	Flaking	6	0.2	Negative
1	2	204	Storeroom 204	W3	CMU	White	Flaking	2	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	204	Storeroom 204	Univent	Metal	Tan	Chipping	8	0	Negative
1	2	204	Storeroom 204	Column	Concrete	White	Flaking	1	0.5	Negative
1	2	204	Storeroom 204	Pipe Cover	Metal	White	Flaking	1	0.2	Negative
1	2	204	Storeroom 204	W4	CMU	White	Flaking	1	0.4	Negative
1	2	204	Storeroom 204	Soffit	Sheetrock	White	Flaking	3	0.1	Negative
1	2	204	Storeroom 204	Door Frame	Metal	Black	Chipping	1	0.3	Negative
1	2	204	Storeroom 204	Ceiling	Concrete	White	Flaking	4	0.4	Negative
1	2	204	Storeroom 204	Pipe (C)	Metal	White	Chipping	1	0.2	Negative
1	2	204A	Storeroom 204 Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	204A	Storeroom 204 Restroom	W1	Sheetrock	White	None	0	0.1	Negative
1	2	204A	Storeroom 204 Restroom	W2	Sheetrock	White	Flaking	1	0.1	Negative
1	2	204A	Storeroom 204 Restroom	W3	CMU	White	None	0	0.4	Negative
1	2	204A	Storeroom 204 Restroom	W4	Sheetrock	White	Flaking	1	0.2	Negative
1	2	204A	Storeroom 204 Restroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	204D	Storeroom 204 Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204D	Storeroom 204 Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204D	Storeroom 204 Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204D	Storeroom 204 Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204D	Storeroom 204 Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204D	Storeroom 204 Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	Doorframe	Metal	Black	None	0	0.2	Negative
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	W2	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	Duct	Metal	Grey	None	0	0.2	Negative
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	Pipe	Metal	Grey	None	0	0.3	Negative
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	Storeroom/Fan Room Vestibule across from Storeroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204C	Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204C	Fan Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204C	Fan Room	Doorframe	Metal	Black	None	0	0.4	Negative
1	2	204C	Fan Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204C	Fan Room	Steel Beam	Metal	Orange	None	0	10.3	Positive
1	2	204C	Fan Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204C	Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204C	Fan Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Storeroom 205	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	205	Storeroom 205	W1	CMU	White	None	0	0.4	Negative
1	2	205	Storeroom 205	Door Frame	Metal	Brown	Chipping	6	0.5	Negative
1	2	205	Storeroom 205	Baseboard (W1-4)	CMU/Tile	Black	Chipping	5	0.9	Positive
1	2	205	Storeroom 205	W2	CMU	White	None	0	0.4	Negative
1	2	205	Storeroom 205	Column (w2,3)	Concrete	White	Flaking	16	0.2	Negative
1	2	205	Storeroom 205	Radiator	Metal	White	Chipping	6	0.4	Negative
1	2	205	Storeroom 205	Pipe Cover (W2, 3)	Metal	Tan	Chipping	10	0.3	Negative



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	205	Storeroom 205	Pipe (W2,3)	Metal	Tan	Chipping	5	0.2	Negative
1	2	205	Storeroom 205	W3	CMU	White	None	0	0.4	Negative
1	2	205	Storeroom 205	Univent	Metal	Tan	Chipping	4	0.1	Negative
1	2	205	Storeroom 205	W4	CMU	White	None	0	0.5	Negative
1	2	205	Storeroom 205	Ceiling	Concrete	White	Flaking	75	0.2	Negative
1	2	205A	Storeroom 205 Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	205A	Storeroom 205 Closet	W1	CMU	White	None	0	0	Negative
1	2	205A	Storeroom 205 Closet	Door Frame	Metal	Black	None	0	0.8	Positive
1	2	205A	Storeroom 205 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	Storeroom 205 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	Storeroom 205 Closet	W4	CMU	White	None	0	0.3	Negative
1	2	205A	Storeroom 205 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205D	Storeroom 205 Small Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205D	Storeroom 205 Small Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205D	Storeroom 205 Small Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205D	Storeroom 205 Small Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205D	Storeroom 205 Small Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205D	Storeroom 205 Small Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	Storeroom 205 Restroom on Hallway side	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	205B	Storeroom 205 Restroom on Hallway side	W1	CMU	White	Chipping	1	0.5	Negative
1	2	205B	Storeroom 205 Restroom on Hallway side	Door Frame	Metal	Black	Chipping	1	0.5	Negative
1	2	205B	Storeroom 205 Restroom on Hallway side	W2	Sheetrock	White	None	0	0.2	Negative
1	2	205B	Storeroom 205 Restroom on Hallway side	W3	Sheetrock	White	None	0	0.2	Negative
1	2	205B	Storeroom 205 Restroom on Hallway side	W4	Sheetrock	White	None	0	0.1	Negative
1	2	205B	Storeroom 205 Restroom on Hallway side	Ceiling	Concrete	White	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	205C	Storeroom 205 Restroom on Windows side	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	205C	Storeroom 205 Restroom on Windows side	W1	CMU	White/Tan	None	0	0.4	Negative
1	2	205C	Storeroom 205 Restroom on Windows side	Door Frame	Metal	Black	None	0	0.5	Negative
1	2	205C	Storeroom 205 Restroom on Windows side	W2	CMU	White/Tan	None	0	0.2	Negative
1	2	205C	Storeroom 205 Restroom on Windows side	W3	CMU	White/Tan	None	0	0.2	Negative
1	2	205C	Storeroom 205 Restroom on Windows side	W4	CMU	White/Tan	None	0	0.2	Negative
1	2	205C	Storeroom 205 Restroom on Windows side	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S23	Stairwell # 2 next to Classroom 205	W1	ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S23	Stairwell # 2 next to Classroom 205	Doorframe	Metal	Tan	Chipping	7	0.2	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	Door	Wood	Brown	Chipping	6	0	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S23	Stairwell # 2 next to Classroom 205	Stair Pan	Metal	Tan	Moisture Damage	5	0.3	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	Riser	Metal	Tan	None	0	0.2	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	Stringer	Metal	tan	None	0	0.1	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S23	Stairwell # 2 next to Classroom 205	Stair Cage	Metal	Blue	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S23	Stairwell # 2 next to Classroom 205	Radiator	Metal	Brown	None	0	0.3	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S23	Stairwell # 2 next to Classroom 205	Fire Pipe	Metal	Tan	None	0	0.5	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	Doorframe	Metal	Tan	None	0	0.4	Negative
1	2	S23	Stairwell # 2 next to Classroom 205	Ceiling	Concrete	White	Flaking	4	0.2	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H21	Hallway from Classrooms 206 to 220	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H21	Hallway from Classrooms 206 to 220	Door Frame	Metal	Black	Chipping	3	1.4	Positive
1	2	H21	Hallway from Classrooms 206 to 220	Door	Metal	Red	Chipping	17	0.1	Negative
1	2	H21	Hallway from Classrooms 206 to 220	W2	CMU	White	Flaking	115	0.4	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Electrical Panel	Metal	White	Chipping	3	0.1	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Vent	Metal	White	None	0	0.1	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Radiator	Metal	White	None	0	0.2	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Baseboard	CMU/Tile	Black	Chipping	15	1.3	Positive
1	2	H21	Hallway from Classrooms 206 to 220	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H21	Hallway from Classrooms 206 to 220	Doorframe	Metal	Black	None	0	0.2	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Door	Metal	Red	Friction	10	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	H21	Hallway from Classrooms 206 to 220	W4	CMU	White	Flaking	165	0.3	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Elevator Door	Metal	Black	None	0	0.1	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Elevator Doorframe	Metal	Black	None	0	0.2	Negative
1	2	H21	Hallway from Classrooms 206 to 220	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	W1	CMU	Orange	None	0	0.5	Negative
1	2	206	Classroom 206	Door Frame	Metal	Black	Chipping	5	0.8	Positive
1	2	206	Classroom 206	Door Frame	Metal	Black	Chipping	4	1	Positive
1	2	206	Classroom 206	W2	CMU	Orange	Flaking	3	0.4	Negative
1	2	206	Classroom 206	Radiator	Metal	Orange	Chipping	12	0.2	Negative
1	2	206	Classroom 206	Pipe Cover	Metal	Orange	Chipping	14	0.2	Negative
1	2	206	Classroom 206	W3	CMU	Orange	Flaking	2	0.4	Negative
1	2	206	Classroom 206	Column	Concrete	Orange	Flaking	5	0.1	Negative
1	2	206	Classroom 206	Univent	Metal	Grey	Chipping	7	0.3	Negative
1	2	206	Classroom 206	W4	CMU	Orange	Chipping	4	0.5	Negative
1	2	206	Classroom 206	Ceiling	Concrete	White	Flaking	4	0.2	Negative
1	2	207	Classroom 207	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	W1	CMU	White	Chipping	4	0.5	Negative
1	2	207	Classroom 207	Door Frame	Metal	Black	Chipping	6	0.8	Positive
1	2	207	Classroom 207	Baseboard (W1-4)	CMU/Tile	Black	Chipping	2	1	Positive
1	2	207	Classroom 207	Door Frame	Metal	Black	Chipping	2	1	Positive
1	2	207	Classroom 207	W2	CMU	Purple	None	0	0.4	Negative
1	2	207	Classroom 207	W3	CMU	White	Flaking	2	0.4	Negative
1	2	207	Classroom 207	Pipe Cover	Metal	White	Chipping	12	0.2	Negative
1	2	207	Classroom 207	Column	Concrete	White	Flaking	3	0.1	Negative
1	2	207	Classroom 207	Univent	Metal	White	Chipping	13	0.2	Negative
1	2	207	Classroom 207	W4	CMU	White	Flaking	2	0.5	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	207	Classroom 207	Ceiling	Concrete	White	Flaking	4	0.2	Negative
1	2	207	Classroom 207	Pipe (C)	Metal	White	Flaking	5	0.2	Negative
1	2	208	Classroom 208	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	W1	CMU	White	None	0	0.3	Negative
1	2	208	Classroom 208	Door Frame	Metal	Black	Chipping	6	0.8	Positive
1	2	208	Classroom 208	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	1.4	Positive
1	2	208	Classroom 208	Door Frame	Metal	Black	None	0	0.9	Positive
1	2	208	Classroom 208	W2	CMU	White	None	0	0.5	Negative
1	2	208	Classroom 208	W3	CMU	White	Chipping	2	0.4	Negative
1	2	208	Classroom 208	Univent	Metal	Grey	Chipping	12	0.1	Negative
1	2	208	Classroom 208	Pipe Cover	Metal	White	Chipping	12	0.2	Negative
1	2	208	Classroom 208	Column	Concrete	White	Flaking	12	0.3	Negative
1	2	208	Classroom 208	W4	CMU	White	None	0	0.5	Negative
1	2	208	Classroom 208	Ceiling	Concrete	White	Flaking	10	0.3	Negative
1	2	208	Classroom 208	Pipe (C)	Metal	White	Chipping	3	0.2	Negative
1	2	209	Classroom 209	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	W1	CMU	Orange	Chipping	2	0.4	Negative
1	2	209	Classroom 209	Door Frame	Metal	Black	Chipping	7	1.1	Positive
1	2	209	Classroom 209	Door Frame	Metal	Black	Chipping	3	1	Positive
1	2	209	Classroom 209	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.5	Positive
1	2	209	Classroom 209	W2	CMU	Orange	None	0	0.4	Negative
1	2	209	Classroom 209	W3	CMU	Orange	Chipping	3	0.5	Negative
1	2	209	Classroom 209	Column	Concrete	Orange	Chipping	10	0.1	Negative
1	2	209	Classroom 209	Pipe Cover	Metal	Orange	Chipping	10	0.2	Negative
1	2	209	Classroom 209	Univent	Metal	Grey	Chipping	10	0.1	Negative
1	2	209	Classroom 209	W4	CMU	Orange	None	0	0.4	Negative
1	2	209	Classroom 209	Ceiling	Concrete	White	Chipping	5	0.2	Negative
1	2	209	Classroom 209	Pipe (C)	Metal	White	Chipping	2	0	Negative
1	2	209A	Office 209A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	209A	Office 209A	W1	CMU	Orange	Flaking	2	0.5	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	209A	Office 209A	Baseboard (W1-4)	CMU/Tile	Black	Cracking	1	1.1	Positive
1	2	209A	Office 209A	Door Frame	Metal	Black	Flaking	4	0.2	Negative
1	2	209A	Office 209A	Duct	Metal	White	Flaking	1	0.1	Negative
1	2	209A	Office 209A	W2	CMU	Orange	Flaking	2	0.5	Negative
1	2	209A	Office 209A	Door Frame	Metal	Black	None	0	0.5	Negative
1	2	209A	Office 209A	W3	CMU	Orange	Flaking	4	0.4	Negative
1	2	209A	Office 209A	Radiator	Metal	Orange	Chipping	3	0.1	Negative
1	2	209A	Office 209A	W4	CMU	Orange	Flaking	2	0.4	Negative
1	2	209A	Office 209A	Ceiling	Concrete	White	Flaking	1	0.2	Negative
1	2	209D	Office off Office 209A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209D	Office off Office 209A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209D	Office off Office 209A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209D	Office off Office 209A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209D	Office off Office 209A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209D	Office off Office 209A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209B	Office 209B	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	209B	Office 209B	W1	CMU	Orange	None	0	0.4	Negative
1	2	209B	Office 209B	Door Frame	Metal	Black	None	0	0.2	Negative
1	2	209B	Office 209B	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.5	Positive
1	2	209B	Office 209B	W2	CMU	Orange	Chipping	2	0.3	Negative
1	2	209B	Office 209B	Door Frame	Metal	Black	Chipping	2	0.2	Negative
1	2	209B	Office 209B	Radiator	Metal	Orange	Chipping	3	0.3	Negative
1	2	209B	Office 209B	W3	CMU	Orange	Moisture Damage	4	0.3	Negative
1	2	209B	Office 209B	W4	CMU	Orange	None	0	0.4	Negative
1	2	209B	Office 209B	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	209C	Women's Lounge	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	209C	Women's Lounge	W1	CMU	White	Chipping	1	0.3	Negative
1	2	209C	Women's Lounge	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.4	Positive
1	2	209C	Women's Lounge	W2	CMU	White	Chipping	1	0.4	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	209C	Women's Lounge	W3	CMU	White	Chipping	3	0.4	Negative
1	2	209C	Women's Lounge	Door Frame	Metal	Black	None	0	0.2	Negative
1	2	209C	Women's Lounge	W4	CMU	White	Chipping	4	0.5	Negative
1	2	209C	Women's Lounge	Radiator	Metal	White	Chipping	2	0.2	Negative
1	2	209C	Women's Lounge	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	210	Classroom 210	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	W1	CMU	Tan	None	0	0.5	Negative
1	2	210	Classroom 210	Door Frame	Metal	Black	Chipping	12	0.7	Positive
1	2	210	Classroom 210	Door Frame	Metal	Black	Chipping	4	0.8	Positive
1	2	210	Classroom 210	Baseboard (W1-4)	CMU/Tile	Black	Chipping	1	0.7	Positive
1	2	210	Classroom 210	W2	CMU	Tan	None	0	0.4	Negative
1	2	210	Classroom 210	W3	CMU	Tan	None	0	0	Negative
1	2	210	Classroom 210	Univent	Metal	Grey	Chipping	10	0.2	Negative
1	2	210	Classroom 210	Pipe Cover	Metal	White	Chipping	10	0.2	Negative
1	2	210	Classroom 210	Column	Concrete	Tan	Chipping	9	0	Negative
1	2	210	Classroom 210	W4	CMU	Tan	None	0	0.4	Negative
1	2	210	Classroom 210	Ceiling	Concrete	White	Flaking	5	0.1	Negative
1	2	210	Classroom 210	Pipe (C)	Metal	White	Chipping	2	0.2	Negative
1	2	211	Classroom 211	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	W1	CMU	Tan	None	0	0.5	Negative
1	2	211	Classroom 211	Door Frame	Metal	Black	None	0	0.7	Positive
1	2	211	Classroom 211	Door Frame	Metal	Black	Chipping	2	0.9	Positive
1	2	211	Classroom 211	Baseboard (W1-4)	CMU/Tile	Black	Moisture Damage	5	1.3	Positive
1	2	211	Classroom 211	W2	CMU	Tan	Moisture Damage	4	0.3	Negative
1	2	211	Classroom 211	W3	CMU	Tan	Moisture Damage	3	0.4	Negative
1	2	211	Classroom 211	Univent	Metal	Grey	Chipping	10	0.1	Negative
1	2	211	Classroom 211	Pipe Cover	Metal	Tan	Chipping	8	0	Negative
1	2	211	Classroom 211	Column	Concrete	Tan	Flaking	13	0.1	Negative
1	2	211	Classroom 211	W4	CMU	Tan	Cracking	10	0.4	Negative
1	2	211	Classroom 211	Ceiling	Concrete	White	Flaking	10	0.3	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	211	Classroom 211	Pipe (C)	Metal	White	Flaking	5	0	Negative
1	2	S25	Stairwell adjacent to Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classroom 212	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classroom 212	Doorframe	Metal	Tan	Chipping	2	0.2	Negative
1	2	S25	Stairwell adjacent to Classroom 212	Door	Metal	Red	None	0	0.1	Negative
1	2	S25	Stairwell adjacent to Classroom 212	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classroom 212	Fire Pipe	Metal	White	Chipping	2	0.5	Negative
1	2	S25	Stairwell adjacent to Classroom 212	Door Frame	Metal	White	None	0	0.4	Negative
1	2	S25	Stairwell adjacent to Classroom 212	Riser	Metal	tan	Chipping	16	0.2	Negative
1	2	S25	Stairwell adjacent to Classroom 212	Stringers	Metal	tan	Chipping	14	0.3	Negative
1	2	S25	Stairwell adjacent to Classroom 212	Stair Pan	Metal	White	Moisture Damage	10	0.4	Negative
1	2	S25	Stairwell adjacent to Classroom 212	Stair Cage	Metal	Blue	Chipping	12	0	Negative
1	2	S25	Stairwell adjacent to Classroom 212	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classroom 212	Baseboard	Metal	Tan	Chipping	15	0.3	Negative
1	2	S25	Stairwell adjacent to Classroom 212	Radiator	Metal	Brown	None	0	0.1	Negative
1	2	S25	Stairwell adjacent to Classroom 212	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classroom 212	Ceiling	Concrete	White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	S27	Stairwell next to Women's Staff Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S27	Stairwell next to Women's Staff Lounge	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S27	Stairwell next to Women's Staff Lounge	Doorframe	Metal	Tan	Chipping	13	0.4	Negative
1	2	S27	Stairwell next to Women's Staff Lounge	Door	Metal	Red	Friction	8	0.1	Negative
1	2	S27	Stairwell next to Women's Staff Lounge	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S27	Stairwell next to Women's Staff Lounge	Conduit	Metal	Tan	Chipping	5	0.6	Negative
1	2	S27	Stairwell next to Women's Staff Lounge	Stair Pan	Metal	Tan	Chipping	8	0.8	Positive
1	2	S27	Stairwell next to Women's Staff Lounge	Riser	Metal	Black	Chipping	10	0	Negative
1	2	S27	Stairwell next to Women's Staff Lounge	Stringer	Metal	Black	Chipping	5	0.1	Negative
1	2	S27	Stairwell next to Women's Staff Lounge	W3	Ceramic	N/A	N/A	N/A	2.2	Positive
1	2	S27	Stairwell next to Women's Staff Lounge	Baseboard	Ceramic	Black	Chipping	12	2	Positive
1	2	S27	Stairwell next to Women's Staff Lounge	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S27	Stairwell next to Women's Staff Lounge	Ceiling	Concrete	White	Flaking	11	0.3	Negative
1	2	H23A	Hallway from Classrooms 212 to 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23A	Hallway from Classrooms 212 to 213	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23A	Hallway from Classrooms 212 to 213	W2	CMU	White	Flaking	5	0.4	Negative
1	2	H23A	Hallway from Classrooms 212 to 213	Locker	Metal	Grey	Flaking	15	0.2	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	H23A	Hallway from Classrooms 212 to 213	W3	CMU	White	Flaking	5	0.3	Negative
1	2	H23A	Hallway from Classrooms 212 to 213	W4	CMU	White	Flaking	10	0.3	Negative
1	2	H23A	Hallway from Classrooms 212 to 213	Baseboard	CMU/Tile	Black	None	0	1.3	Positive
1	2	H23A	Hallway from Classrooms 212 to 213	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	212	Classroom 212	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	212	Classroom 212	W1	CMU	Blue	None	0	0.4	Negative
1	2	212	Classroom 212	Door Frame	Metal	Black	Chipping	8	0.2	Negative
1	2	212	Classroom 212	Door Frame	Metal	Black	Chipping	2	0.4	Negative
1	2	212	Classroom 212	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	2	212	Classroom 212	Chalkboard Frame (W1-4)	Metal	Red/White	Chipping	6	0.2	Negative
1	2	212	Classroom 212	Chalkboard Panel (W1-4)	Metal	Multi	Chipping	2	0.1	Negative
1	2	212	Classroom 212	Door	Wood	Black	Chipping	1	0	Negative
1	2	212	Classroom 212	Doors	Wood	Tan	Chipping	2	0	Negative
1	2	212	Classroom 212	W2	CMU	Blue	None	0	0.4	Negative
1	2	212	Classroom 212	W3	CMU	Blue	None	0	0.4	Negative
1	2	212	Classroom 212	Univent	Metal	Tan	Chipping	6	0	Negative
1	2	212	Classroom 212	Pipe Cover	Metal	Blue	Chipping	6	0.4	Negative
1	2	212	Classroom 212	Column	Concrete	Blue	Flaking	2	0.2	Negative
1	2	212	Classroom 212	W3	CMU	Blue	None	0	0.4	Negative
1	2	212	Classroom 212	W4	CMU	Blue	None	0	0.5	Negative
1	2	212	Classroom 212	Conduit	Metal	Blue/White	Chipping	2	0.5	Negative
1	2	212	Classroom 212	Ceiling	Concrete	White	Flaking	13	0.3	Negative
1	2	213	Classroom 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Classroom 213	W1	CMU	Green	None	0	0.4	Negative
1	2	213	Classroom 213	Baseboard	CMU/Tile	Black	Chipping	1	1.1	Positive
1	2	213	Classroom 213	Conduit	Metal	Green	None	0	0.1	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	213	Classroom 213	Door Frame	Metal	Black	Chipping	8	0.7	Positive
1	2	213	Classroom 213	Closet Door Frame	Metal	Black	None	0	0.4	Negative
1	2	213	Classroom 213	W2	CMU	White	None	0	0.5	Negative
1	2	213	Classroom 213	W3	CMU	White	None	0	0	Negative
1	2	213	Classroom 213	Pipe Cover	Metal	White	None	0	0.3	Negative
1	2	213	Classroom 213	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	2	213	Classroom 213	Column	Concrete	White	None	0	0.4	Negative
1	2	213	Classroom 213	Univent	Metal	Tan	Chipping	14	0	Negative
1	2	213	Classroom 213	W4	CMU	White	None	0	0.4	Negative
1	2	213	Classroom 213	Ceiling Beam	Concrete	White	None	0	0.3	Negative
1	2	214D	Studio 3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214D	Studio 3	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214D	Studio 3	Doorframe	Metal	Black	None	0	0.2	Negative
1	2	214D	Studio 3	Pipe	Metal	Grey	Flaking	10	0.4	Negative
1	2	214D	Studio 3	Duct	Metal	Grey	None	0	0.6	Negative
1	2	214D	Studio 3	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214D	Studio 3	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214D	Studio 3	W4	CMU	Red	None	0	0.4	Negative
1	2	214D	Studio 3	Doorframe	Metal	Black	None	0	0.4	Negative
1	2	214D	Studio 3	Column	Concrete	Grey	None	0	0.3	Negative
1	2	214D	Studio 3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214E	Fan Room off Studio 3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214E	Fan Room off Studio 3	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214E	Fan Room off Studio 3	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214E	Fan Room off Studio 3	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214E	Fan Room off Studio 3	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214E	Fan Room off Studio 3	Duct	Metal	Grey	None	0	0.1	Negative
1	2	214E	Fan Room off Studio 3	Fan Assembly	Metal	Grey	None	0	0.1	Negative
1	2	214E	Fan Room off Studio 3	Steel Beam	Metal	Orange	None	0	13.4	Positive
1	2	214E	Fan Room off Studio 3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Music Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	214	Music Classroom 214	Riser	Metal	Black	Chipping	10	0	Negative
1	2	214	Music Classroom 214	W1	CMU	White	Chipping	5	0.5	Negative
1	2	214	Music Classroom 214	Door Frame	Metal	Black	Chipping	12	0.2	Negative
1	2	214	Music Classroom 214	Conduit	Metal	White	None	0	0.3	Negative
1	2	214	Music Classroom 214	W2	CMU	White	None	0	0.6	Negative
1	2	214	Music Classroom 214	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	2	214	Music Classroom 214	Soffit	Wood	White	None	0	0	Negative
1	2	214	Music Classroom 214	Door	Wood	Brown	None	0	0.1	Negative
1	2	214	Music Classroom 214	W3	CMU	White	Chipping	4	0.4	Negative
1	2	214	Music Classroom 214	Pipe Cover	Metal	White	Chipping	5	0.1	Negative
1	2	214	Music Classroom 214	Pipe Insulation	Fiberglass	White	Chipping	2	0.2	Negative
1	2	214	Music Classroom 214	Univent	Metal	Grey	Chipping	16	0.1	Negative
1	2	214	Music Classroom 214	Column	Concrete	White	Flaking	2	0.2	Negative
1	2	214	Music Classroom 214	W4	CMU	White	None	0	0.5	Negative
1	2	214	Music Classroom 214	Ceiling Beam	Concrete	White	Chipping	3	0.2	Negative
1	2	214A	Maintenance Shop next to Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Maintenance Shop next to Classroom 214	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Maintenance Shop next to Classroom 214	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Maintenance Shop next to Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Maintenance Shop next to Classroom 214	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Maintenance Shop next to Classroom 214	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214B	Music Storeroom next to Maintenance Shop	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214B	Music Storeroom next to Maintenance Shop	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214B	Music Storeroom next to Maintenance Shop	W2	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	214B	Music Storeroom next to Maintenance Shop	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214B	Music Storeroom next to Maintenance Shop	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214B	Music Storeroom next to Maintenance Shop	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217A	Classroom 217A Graphic Arts	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217A	Classroom 217A Graphic Arts	W1	CMU	White	None	0	0.5	Negative
1	2	217A	Classroom 217A Graphic Arts	Conduit	Metal	White	None	0	0.1	Negative
1	2	217A	Classroom 217A Graphic Arts	Door Frame	Metal	Black	None	0	0.8	Positive
1	2	217A	Classroom 217A Graphic Arts	Baseboard	CMU/Tile	Black	None	0	1.2	Positive
1	2	217A	Classroom 217A Graphic Arts	W2	CMU	White	None	0	0.4	Negative
1	2	217A	Classroom 217A Graphic Arts	W3	Sheetrock	Red	None	0	0.1	Negative
1	2	217A	Classroom 217A Graphic Arts	Pipe Cover	Metal	White	None	0	0	Negative
1	2	217A	Classroom 217A Graphic Arts	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	2	217A	Classroom 217A Graphic Arts	Column	Concrete	White	None	0	0.1	Negative
1	2	217A	Classroom 217A Graphic Arts	Expansion Joint	Metal	White	None	0	0.1	Negative
1	2	217A	Classroom 217A Graphic Arts	W4	CMU	White	None	0	0.5	Negative
1	2	217A	Classroom 217A Graphic Arts	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	217A	Classroom 217A Graphic Arts	Sprinkler Pipe	Metal	White	None	0	0.1	Negative
1	2	217E	Classroom 217A Closet by entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217E	Classroom 217A Closet by entrance	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217E	Classroom 217A Closet by entrance	Doorframe	Metal	Black	None	0	0.5	Negative
1	2	217E	Classroom 217A Closet by entrance	Duct	Metal	Grey	None	0	0.3	Negative
1	2	217E	Classroom 217A Closet by entrance	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217E	Classroom 217A Closet by entrance	W3	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	217E	Classroom 217A Closet by entrance	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217E	Classroom 217A Closet by entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217D	Classroom 217A Middle Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217D	Classroom 217A Middle Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217D	Classroom 217A Middle Closet	Door Frame	Metal	Black	None	0	1.1	Positive
1	2	217D	Classroom 217A Middle Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217D	Classroom 217A Middle Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217D	Classroom 217A Middle Closet	Shelf	Wood	Grey	None	0	0.9	Positive
1	2	217D	Classroom 217A Middle Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217D	Classroom 217A Middle Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215A	Classroom 217A Closet furthest from entrance	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215A	Classroom 217A Closet furthest from entrance	Pipe	Metal	Grey	Flaking	8	1.1	Positive
1	2	215A	Classroom 217A Closet furthest from entrance	Pipe Cover	Metal	Grey	None	0	0.8	Positive
1	2	215A	Classroom 217A Closet furthest from entrance	Door Frame	Metal	Black	None	0	1	Positive
1	2	215A	Classroom 217A Closet furthest from entrance	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215A	Classroom 217A Closet furthest from entrance	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215A	Classroom 217A Closet furthest from entrance	W4	N/A	N/A	N/A	N/A	N/A	N/A



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	215A	Classroom 217A Closet furthest from entrance	Door	Metal	Red	None	0	0.4	Negative
1	2	215A	Classroom 217A Closet furthest from entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214C	Classroom 217A Server Room	Floor	Concrete	Grey	Friction	20	0	Negative
1	2	214C	Classroom 217A Server Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214C	Classroom 217A Server Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214C	Classroom 217A Server Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214C	Classroom 217A Server Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214C	Classroom 217A Server Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211B	Janitor's Closet across from Classroom 217A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211B	Janitor's Closet across from Classroom 217A	W1	CMU	Tan	Flaking	7	0.3	Negative
1	2	211B	Janitor's Closet across from Classroom 217A	Door Frame	Metal	Black	None	0	0.7	Positive
1	2	211B	Janitor's Closet across from Classroom 217A	Door	Wood	Red	Chipping	3	0	Negative
1	2	211B	Janitor's Closet across from Classroom 217A	W2	CMU	Tan	Flaking	16	0.4	Negative
1	2	211B	Janitor's Closet across from Classroom 217A	W3	CMU	Tan	Flaking	6	0.3	Negative
1	2	211B	Janitor's Closet across from Classroom 217A	W4	CMU	Tan	Flaking	4	0.4	Negative
1	2	211B	Janitor's Closet across from Classroom 217A	Shelf	Wood	Tan	Chipping	44	1.8	Positive
1	2	211B	Janitor's Closet across from Classroom 217A	Ceiling	Concrete	White	No Access	0	0.4	Negative
1	2	211A	Men's Lounge across from Classroom 217A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	211A	Men's Lounge across from Classroom 217A	W1	CMU	White	Chipping	1	0.3	Negative
1	2	211A	Men's Lounge across from Classroom 217A	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.4	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	211A	Men's Lounge across from Classroom 217A	W2	CMU	White	Chipping	1	0.4	Negative
1	2	211A	Men's Lounge across from Classroom 217A	W3	CMU	White	Chipping	3	0.4	Negative
1	2	211A	Men's Lounge across from Classroom 217A	Door Frame	Metal	Black	None	0	0.2	Negative
1	2	211A	Men's Lounge across from Classroom 217A	W4	CMU	White	Chipping	4	0.5	Negative
1	2	211A	Men's Lounge across from Classroom 217A	Radiator	Metal	White	Chipping	2	0.2	Negative
1	2	211A	Men's Lounge across from Classroom 217A	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	H23	Hallway from Classrooms 212 to 217A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Hallway from Classrooms 212 to 217A	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Hallway from Classrooms 212 to 217A	W2	CMU	White	Flaking	31	0.5	Negative
1	2	H23	Hallway from Classrooms 212 to 217A	Electrical Panel	Metal	Black	Chipping	1	0.1	Negative
1	2	H23	Hallway from Classrooms 212 to 217A	Baseboard	CMU/Tile	Black	None	0	1.5	Positive
1	2	H23	Hallway from Classrooms 212 to 217A	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Hallway from Classrooms 212 to 217A	Door Frame	Metal	Black	None	0	0.7	Positive
1	2	H23	Hallway from Classrooms 212 to 217A	Door	Metal	Red	None	0	0.1	Negative
1	2	H23	Hallway from Classrooms 212 to 217A	W4	CMU	White	Flaking	31	0	Negative
1	2	H23	Hallway from Classrooms 212 to 217A	Radiator	Metal	White	Flaking	2	0.2	Negative
1	2	H23	Hallway from Classrooms 212 to 217A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	215	Classroom 215	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	215	Classroom 215	W1	CMU	Yellow	None	0	0.5	Negative
1	2	215	Classroom 215	Door Frame	Metal	Black	Chipping	6	0.6	Negative
1	2	215	Classroom 215	Door Frame	Metal	Black	Chipping	1	0.2	Negative
1	2	215	Classroom 215	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	paint chips samples	Negative
1	2	215	Classroom 215	W2	CMU	Yellow	Moisture Damage	3	0.4	Negative
1	2	215	Classroom 215	W3	CMU	Yellow	Moisture Damage	10	0.1	Negative
1	2	215	Classroom 215	Vent Cover	Metal	Yellow	None	0	0.3	Negative
1	2	215	Classroom 215	Column	Concrete	Yellow	Moisture Damage	8	0.2	Negative
1	2	215	Classroom 215	W4	CMU	Yellow	None	0	0.4	Negative
1	2	215	Classroom 215	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	215	Classroom 215	Pipe (C)	Metal	White	None	0	0.1	Negative
1	2	S28	Stairwell adjacent to Classroom 215	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S28	Stairwell adjacent to Classroom 215	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S28	Stairwell adjacent to Classroom 215	Door	Metal	Red	Friction	8	0.1	Negative
1	2	S28	Stairwell adjacent to Classroom 215	Doorframe	Metal	Tan	Chipping	8	0.4	Negative
1	2	S28	Stairwell adjacent to Classroom 215	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S28	Stairwell adjacent to Classroom 215	Conduit	Metal	White	Chipping	2	0.4	Negative
1	2	S28	Stairwell adjacent to Classroom 215	Riser	Metal	Black	Chipping	22	0.1	Negative
1	2	S28	Stairwell adjacent to Classroom 215	Stringer	Metal	Black	Chipping	7	0.1	Negative
1	2	S28	Stairwell adjacent to Classroom 215	Baseboard	Metal	Black	Chipping	4	0.1	Negative
1	2	S28	Stairwell adjacent to Classroom 215	Stair Pan	Metal	White	Moisture Damage	20	0.9	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	S28	Stairwell adjacent to Classroom 215	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S28	Stairwell adjacent to Classroom 215	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S28	Stairwell adjacent to Classroom 215	Door Frame	Metal	Tan	Chipping	3	0.3	Negative
1	2	S28	Stairwell adjacent to Classroom 215	Fire Pipe	Metal	Tan	Chipping	1	0.4	Negative
1	2	S28	Stairwell adjacent to Classroom 215	Ceiling	Concrete	White	Chipping	4	0.1	Negative
1	2	216	Physical Education Suite - Storeroom 216	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	216	Physical Education Suite - Storeroom 216	W1	CMU	White	Flaking	2	0.1	Negative
1	2	216	Physical Education Suite - Storeroom 216	Door Frame	Metal	Black	None	0	0.7	Positive
1	2	216	Physical Education Suite - Storeroom 216	Baseboard (W1-4)	CMU/Tile	Black	Chipping	5	1.3	Positive
1	2	216	Physical Education Suite - Storeroom 216	W2	CMU	White	Flaking	5	0.4	Negative
1	2	216	Physical Education Suite - Storeroom 216	Door Frame	Metal	Black	None	0	0.7	Positive
1	2	216	Physical Education Suite - Storeroom 216	W3	CMU	White	Flaking	2	0	Negative
1	2	216	Physical Education Suite - Storeroom 216	Univent	Metal	White	Chipping	1	0.2	Negative
1	2	216	Physical Education Suite - Storeroom 216	Column	Concrete	White	None	0	0.1	Negative
1	2	216	Physical Education Suite - Storeroom 216	Door Frame	Metal	Black	None	0	0.5	Negative
1	2	216	Physical Education Suite - Storeroom 216	W4	CMU	White	Flaking	5	0.4	Negative
1	2	216	Physical Education Suite - Storeroom 216	Ceiling	Concrete	White	None	0	0.3	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia HighSchool</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	216A	Physical Education Suite - Storeroom 216A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	216A	Physical Education Suite - Storeroom 216A	W1	CMU	White	None	0	0.4	Negative
1	2	216A	Physical Education Suite - Storeroom 216A	Door Frame	Metal	Black	Chipping	3	0.6	Negative
1	2	216A	Physical Education Suite - Storeroom 216A	Baseboard (W1-4)	CMU/Tile	Black	Chipping	2	1.3	Positive
1	2	216A	Physical Education Suite - Storeroom 216A	W2	CMU	White	None	0	0.4	Negative
1	2	216A	Physical Education Suite - Storeroom 216A	W3	CMU	White	None	0	0.3	Negative
1	2	216A	Physical Education Suite - Storeroom 216A	Door Frame	Metal	Black	None	0	0.3	Negative
1	2	216A	Physical Education Suite - Storeroom 216A	Univent	Metal	White	Chipping	5	0	Negative
1	2	216A	Physical Education Suite - Storeroom 216A	W4	CMU	White	None	0	0.4	Negative
1	2	216A	Physical Education Suite - Storeroom 216A	Ceiling	Concrete	White	None	0	0.1	Negative
1	2	216D	Physical Education Suite - Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	216D	Physical Education Suite - Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	216D	Physical Education Suite - Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	216D	Physical Education Suite - Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	216D	Physical Education Suite - Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	216D	Physical Education Suite - Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	216B	Physical Education Suite - Storeroom 216B	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia HighSchool</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	216B	Physical Education Suite - Storeroom 216B	W1	CMU	White	None	0	0.1	Negative
1	2	216B	Physical Education Suite - Storeroom 216B	Door Frame	Metal	Black	None	0	0.8	Positive
1	2	216B	Physical Education Suite - Storeroom 216B	Baseboard (W1-4)	CMU/Tile	Black	None	0	0.9	Positive
1	2	216B	Physical Education Suite - Storeroom 216B	W2	CMU	White	None	0	0.1	Negative
1	2	216B	Physical Education Suite - Storeroom 216B	W3	CMU	White	None	0	0.3	Negative
1	2	216B	Physical Education Suite - Storeroom 216B	Univent	Metal	White	None	0	0.1	Negative
1	2	216B	Physical Education Suite - Storeroom 216B	W4	CMU	White	None	0	0.4	Negative
1	2	216B	Physical Education Suite - Storeroom 216B	Door Frame	Metal	Black	Chipping	2	0.8	Positive
1	2	216B	Physical Education Suite - Storeroom 216B	Door Frame	Metal	Black	None	0	0.1	Negative
1	2	216B	Physical Education Suite - Storeroom 216B	Pipe	Metal	White	None	0	0.3	Negative
1	2	216B	Physical Education Suite - Storeroom 216B	Ceiling	Concrete	White	None	0	0.4	Negative
1	2	216C	Physical Education Suite - Restroom	Floor	Concrete	Grey	Friction	10	0.3	Negative
1	2	216C	Physical Education Suite - Restroom	W1	CMU	White	None	0	0.5	Negative
1	2	216C	Physical Education Suite - Restroom	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.3	Positive
1	2	216C	Physical Education Suite - Restroom	W2	CMU	White	None	0	0.4	Negative
1	2	216C	Physical Education Suite - Restroom	W3	CMU	White	None	0	0.3	Negative
1	2	216C	Physical Education Suite - Restroom	Stall Partition	Metal	Pink	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	216C	Physical Education Suite - Restroom	W4	CMU	White	None	0	0.4	Negative
1	2	216C	Physical Education Suite - Restroom	W4	Ceramic	White	None	0	0.2	Negative
1	2	216C	Physical Education Suite - Restroom	Duct	Metal	White	None	0	0.1	Negative
1	2	216C	Physical Education Suite - Restroom	Ceiling	Concrete	White	Flaking	12	0.3	Negative
1	2	218	Storeroom 218	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	218	Storeroom 218	W1	CMU	White	None	0	0.4	Negative
1	2	218	Storeroom 218	Door Frame	Metal	Black	None	0	0.4	Negative
1	2	218	Storeroom 218	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.7	Positive
1	2	218	Storeroom 218	W2	CMU	White	None	0	0.4	Negative
1	2	218	Storeroom 218	Door Frame	Metal	Black	None	0	1	Positive
1	2	218	Storeroom 218	W3	CMU	White	None	0	0.4	Negative
1	2	218	Storeroom 218	Univent	Metal	Grey	Flaking	5	0.1	Negative
1	2	218	Storeroom 218	Pipe Cover	Metal	White	Flaking	2	0.4	Negative
1	2	218	Storeroom 218	W4	CMU	White	None	0	0.3	Negative
1	2	218	Storeroom 218	Door Frame	Metal	Black	Chipping	4	0.6	Negative
1	2	218	Storeroom 218	Ceiling	Concrete	White	Flaking	10	0.3	Negative
1	2	218D	Storeroom 218 Restroom	Floor	Concrete	Grey	Friction	10	0.3	Negative
1	2	218D	Storeroom 218 Restroom	W1	CMU	White	None	0	0.5	Negative
1	2	218D	Storeroom 218 Restroom	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.3	Positive
1	2	218D	Storeroom 218 Restroom	Door Frame	Metal	Black	None	0	0.6	Negative
1	2	218D	Storeroom 218 Restroom	W2	CMU	White	None	0	0.4	Negative
1	2	218D	Storeroom 218 Restroom	W2	Ceramic	Green	None	0	2.2	Positive
1	2	218D	Storeroom 218 Restroom	W3	CMU	White	None	0	0.5	Negative
1	2	218D	Storeroom 218 Restroom	W4	CMU	White	None	0	0.3	Negative
1	2	218D	Storeroom 218 Restroom	Duct	Metal	White	None	0	0.4	Negative
1	2	218D	Storeroom 218 Restroom	Univent	Metal	Grey	None	0	0.1	Negative
1	2	218D	Storeroom 218 Restroom	Ceiling	Concrete	White	Flaking	10	0.3	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	218A	Storeroom 218A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	218A	Storeroom 218A	W1	CMU	White	Flaking	10	0.5	Negative
1	2	218A	Storeroom 218A	Door Frame	Metal	Black	Chipping	4	0.2	Negative
1	2	218A	Storeroom 218A	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.6	Positive
1	2	218A	Storeroom 218A	W2	CMU	White	None	0	0.5	Negative
1	2	218A	Storeroom 218A	Pipe	Metal	Grey	None	0	0.7	Positive
1	2	218A	Storeroom 218A	Shelf	Wood	Grey	None	0	0.6	Negative
1	2	218A	Storeroom 218A	W3	CMU	White	Flaking	12	0.4	Negative
1	2	218A	Storeroom 218A	Univent	Metal	White	Chipping	2	0.5	Negative
1	2	218A	Storeroom 218A	Door Frame	Metal	Black	Flaking	4	0.5	Negative
1	2	218A	Storeroom 218A	W4	CMU	White	None	0	0.5	Negative
1	2	218A	Storeroom 218A	Door Frame	Metal	Black	None	0	0.5	Negative
1	2	218A	Storeroom 218A	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	218B	Athletic Director Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	218B	Athletic Director Office	W1	CMU	White	Flaking	4	0.3	Negative
1	2	218B	Athletic Director Office	Door Frame	Metal	Black	Chipping	8	0.1	Negative
1	2	218B	Athletic Director Office	Baseboard (w1-4)	CMU/Tile	Black	None	0	1.3	Positive
1	2	218B	Athletic Director Office	W2	CMU	White	Flaking	2	0.3	Negative
1	2	218B	Athletic Director Office	W3	CMU	White	None	0	0.5	Negative
1	2	218B	Athletic Director Office	Univent	Metal	White	None	0	0.1	Negative
1	2	218B	Athletic Director Office	Pipe Cover	Metal	White	Chipping	3	0.3	Negative
1	2	218B	Athletic Director Office	Column	Concrete	White	Flaking	7	0.3	Negative
1	2	218B	Athletic Director Office	W4	CMU	White	None	0	0	Negative
1	2	218B	Athletic Director Office	Door Frame	Metal	Black	Chipping	4	0.9	Positive
1	2	218B	Athletic Director Office	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	S21	Stairwell # 5 next to Classroom 217B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell # 5 next to Classroom 217B	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell # 5 next to Classroom 217B	Door	Metal	Red	Friction	8	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	S21	Stairwell # 5 next to Classroom 217B	Doorframe	Metal	Tan	Chipping	8	0.4	Negative
1	2	S21	Stairwell # 5 next to Classroom 217B	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell # 5 next to Classroom 217B	Conduit	Metal	White	Chipping	2	0.4	Negative
1	2	S21	Stairwell # 5 next to Classroom 217B	Riser	Metal	Black	Chipping	22	0.1	Negative
1	2	S21	Stairwell # 5 next to Classroom 217B	Stringer	Metal	Black	Chipping	7	0.1	Negative
1	2	S21	Stairwell # 5 next to Classroom 217B	Baseboard	Metal	Black	Chipping	4	0.1	Negative
1	2	S21	Stairwell # 5 next to Classroom 217B	Stair Pan	Metal	White	Moisture Damage	20	0.9	Positive
1	2	S21	Stairwell # 5 next to Classroom 217B	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell # 5 next to Classroom 217B	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell # 5 next to Classroom 217B	Door Frame	Metal	Tan	Chipping	3	0.3	Negative
1	2	S21	Stairwell # 5 next to Classroom 217B	Fire Pipe	Metal	Tan	Chipping	1	0.4	Negative
1	2	S21	Stairwell # 5 next to Classroom 217B	Ceiling	Concrete	White	Chipping	4	0.1	Negative
1	2	217B	Classroom 217B	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217B	Classroom 217B	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217B	Classroom 217B	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217B	Classroom 217B	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217B	Classroom 217B	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217B	Classroom 217B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217F	Classroom 217B Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217F	Classroom 217B Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217F	Classroom 217B Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217F	Classroom 217B Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	217F	Classroom 217B Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	217F	Classroom 217B Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	219A	College Prep Room 219A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	219A	College Prep Room 219A	W1	CMU	White	None	0	0.4	Negative
1	2	219A	College Prep Room 219A	Door Frame	Metal	Black	Chipping	2	0.7	Positive
1	2	219A	College Prep Room 219A	Baseboard (w1-4)	CMU/Tile	Black	Chipping	8	1.1	Positive
1	2	219A	College Prep Room 219A	W2	CMU	White	None	0	0.5	Negative
1	2	219A	College Prep Room 219A	Pipe Cover	Metal	Tan	Flaking	5	0.5	Negative
1	2	219A	College Prep Room 219A	Electrical Panel	Metal	Tan	None	0	0.1	Negative
1	2	219A	College Prep Room 219A	Column	Concrete	Tan	None	0	0.1	Negative
1	2	219A	College Prep Room 219A	W3	Sheetrock	White	None	0	0.3	Negative
1	2	219A	College Prep Room 219A	Univent	Metal	Tan	Chipping	12	0	Negative
1	2	219A	College Prep Room 219A	W4	CMU	White	None	0	0.3	Negative
1	2	219A	College Prep Room 219A	Door Frame	Metal	Black	Chipping	5	1	Positive
1	2	219A	College Prep Room 219A	Ceiling	Concrete	White	None	0	0.5	Negative
1	2	219A	College Prep Room 219A	Pipe Sprinkler	Metal	White	None	0	0.2	Negative
1	2	219D	Storage Room inside College Prep Room 219A	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	219D	Storage Room inside College Prep Room 219A	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	219D	Storage Room inside College Prep Room 219A	W2	CMU	White	None	0	0.3	Negative
1	2	219D	Storage Room inside College Prep Room 219A	Shelf	Wood	White	None	0	0.2	Negative
1	2	219D	Storage Room inside College Prep Room 219A	W3	Wood	White	None	0	0.5	Negative
1	2	219D	Storage Room inside College Prep Room 219A	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	219D	Storage Room inside College Prep Room 219A	Ceiling	Wood	White	None	0	0.1	Negative
1	2	219D	Storage Room inside College Prep Room 219A	Duct	Metal	White	None	0	0.2	Negative
1	2	219F	Janitor's Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	219F	Janitor's Closet	W1	CMU	Tan	Flaking	7	0.3	Negative
1	2	219F	Janitor's Closet	Door Frame	Metal	Black	None	0	0.7	Positive
1	2	219F	Janitor's Closet	Door	Wood	Red	Chipping	3	0	Negative
1	2	219F	Janitor's Closet	W2	CMU	Tan	Flaking	16	0.4	Negative
1	2	219F	Janitor's Closet	W3	CMU	Tan	Flaking	6	0.3	Negative
1	2	219F	Janitor's Closet	W4	CMU	Tan	Flaking	4	0.4	Negative
1	2	219F	Janitor's Closet	Shelf	Wood	Tan	Chipping	44	1.8	Positive
1	2	219F	Janitor's Closet	Ceiling	Concrete	White	No Access	0	0.4	Negative
1	2	219C	Community Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	219C	Community Closet	W1	CMU	White	None	0	0.4	Negative
1	2	219C	Community Closet	W2	CMU	White	None	0	0.5	Negative
1	2	219C	Community Closet	W3	CMU	White	None	0	0.5	Negative
1	2	219C	Community Closet	W4	CMU	White	None	0	0.3	Negative
1	2	219C	Community Closet	Ceiling	Concrete	White	None	0	0.1	Negative
1	2	219E	Community Closet IT Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	219E	Community Closet IT Room	W1	CMU	N/A	N/A	N/A	N/A	N/A
1	2	219E	Community Closet IT Room	Door Frame	Metal	Black	Chipping	2	0.2	Negative
1	2	219E	Community Closet IT Room	W2	CMU	N/A	N/A	N/A	N/A	N/A
1	2	219E	Community Closet IT Room	W3	CMU	N/A	N/A	N/A	N/A	N/A
1	2	219E	Community Closet IT Room	Pipe Cover	Metal	Green	Flaking	4	0.9	Positive
1	2	219E	Community Closet IT Room	W4	CMU	N/A	N/A	N/A	N/A	N/A
1	2	219E	Community Closet IT Room	Ceiling	Concrete	White	None	0	0.2	Negative
1	2	220	Classroom 220	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	220	Classroom 220	W1	CMU	Yellow	Flaking	5	0.5	Negative
1	2	220	Classroom 220	Door Frame	Metal	Black	Chipping	7	0	Negative
1	2	220	Classroom 220	Baseboard (W1-4)	CMU/Tile	Black	Chipping	5	1.2	Positive
1	2	220	Classroom 220	Door Frame	Metal	Black	Chipping	3	0.9	Positive
1	2	220	Classroom 220	W2	CMU	Yellow	Flaking	2	0.4	Negative
1	2	220	Classroom 220	W3	CMU	Yellow	Flaking	7	0.4	Negative
1	2	220	Classroom 220	Column	Concrete	Yellow	Chipping	2	0.1	Negative
1	2	220	Classroom 220	W4	CMU	Yellow	Flaking	20	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	220	Classroom 220	Univent	Metal	Grey	Chipping	28	0.1	Negative
1	2	220	Classroom 220	Pipe Cover	Metal	Yellow	Chipping	18	0.3	Negative
1	2	220	Classroom 220	Ceiling	Concrete	White	Flaking	18	0.4	Negative
1	2	S29	Stairwell adjacent to Classroom 220	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S29	Stairwell adjacent to Classroom 220	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S29	Stairwell adjacent to Classroom 220	Doorframe	Metal	Tan	Chipping	5	0.2	Negative
1	2	S29	Stairwell adjacent to Classroom 220	Door	Metal	Red	Friction	6	0.1	Negative
1	2	S29	Stairwell adjacent to Classroom 220	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S29	Stairwell adjacent to Classroom 220	Conduit	Metal	Tan	Chipping	1	0.4	Negative
1	2	S29	Stairwell adjacent to Classroom 220	Riser	Metal	Black	Chipping	80	0.2	Negative
1	2	S29	Stairwell adjacent to Classroom 220	Stringer	Metal	Black	Chipping	15	0.2	Negative
1	2	S29	Stairwell adjacent to Classroom 220	Stair pan	Metal	tan	Flaking	10	0.2	Negative
1	2	S29	Stairwell adjacent to Classroom 220	Baseboard	Metal	Black	Chipping	1	0.1	Negative
1	2	S29	Stairwell adjacent to Classroom 220	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S29	Stairwell adjacent to Classroom 220	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S29	Stairwell adjacent to Classroom 220	Fire Pipe	Metal	Tan	Chipping	2	0.4	Negative
1	2	S29	Stairwell adjacent to Classroom 220	Doorframe	Metal	tan	Chipping	1	0.3	Negative
1	2	S29	Stairwell adjacent to Classroom 220	Ceiling	Concrete	White	Flaking	10	0.3	Negative
1	2	221A	Women's Restroom	Floor	Concrete	Grey	Chipping	5	0.3	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	221A	Women's Restroom	W1	CMU	White	None	0	0.2	Negative
1	2	221A	Women's Restroom	Doorframe	Metal	Black	None	0	0.2	Negative
1	2	221A	Women's Restroom	Conduit	Metal	White	None	0	0.3	Negative
1	2	221A	Women's Restroom	W2	CMU	White	None	0	0.3	Negative
1	2	221A	Women's Restroom	W3	CMU	White	None	0	0.1	Negative
1	2	221A	Women's Restroom	W4	CMU	White	None	0	0	Negative
1	2	221A	Women's Restroom	Ceiling	Concrete	White	None	0	0.1	Negative
1	2	221B	Men's Restroom	Floor	No Access	No Access	N/A	N/A	N/A	N/A
1	2	221B	Men's Restroom	W1	No Access	No Access	N/A	N/A	N/A	N/A
1	2	221B	Men's Restroom	W2	No Access	No Access	N/A	N/A	N/A	N/A
1	2	221B	Men's Restroom	W3	No Access	No Access	N/A	N/A	N/A	N/A
1	2	221B	Men's Restroom	W4	No Access	No Access	N/A	N/A	N/A	N/A
1	2	221B	Men's Restroom	Ceiling	No Access	No Access	N/A	N/A	N/A	N/A
1	2	221	Classroom 221	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
1	2	221	Classroom 221	W1	CMU	White	None	0	0	Negative
1	2	221	Classroom 221	Glazed Block	Ceramic	tan	None	0	2.4	Positive
1	2	221	Classroom 221	Doorframe	Metal	Black	Chipping	1	0.1	Negative
1	2	221	Classroom 221	Closet Doorframe	Metal	Black	None	0	0.2	Negative
1	2	221	Classroom 221	Door	Wood	Tan	Chipping	2	0	Negative
1	2	221	Classroom 221	conduit	Metal	White	None	0	0.1	Negative
1	2	221	Classroom 221	Baseboard	CMU/Tile	Black	Chipping	2	1.6	Positive
1	2	221	Classroom 221	W2	CMU	Grey	None	0	0.5	Negative
1	2	221	Classroom 221	Glazed Block	Ceramic	grey	None	0	2.2	Positive
1	2	221	Classroom 221	W3	CMU	White	None	0	0.5	Negative
1	2	221	Classroom 221	Univent	Metal	Grey	Chipping	14	0.1	Negative
1	2	221	Classroom 221	column	Concrete	White	Chipping	4	0.2	Negative
1	2	221	Classroom 221	Pipe Cover	Metal	White	Chipping	5	0.3	Negative
1	2	221	Classroom 221	Pipe Insulation	Fiberglass	White	Chipping	2	0	Negative
1	2	221	Classroom 221	W4	CMU	White	None	0	0.4	Negative
1	2	221	Classroom 221	Pipe	Metal	White	None	0	0.1	Negative
1	2	221	Classroom 221	Ceiling	Concrete	White	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	221C	Classroom 221 Small Closet	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	2	221C	Classroom 221 Small Closet	W1	Wood	N/A	N/A	N/A	N/A	N/A
1	2	221C	Classroom 221 Small Closet	Doorframe	Metal	Black	Chipping	1	0.1	Negative
1	2	221C	Classroom 221 Small Closet	Door	Wood	Tan	Chipping	1	0.1	Negative
1	2	221C	Classroom 221 Small Closet	W2	Wood	White	None	0	0.3	Negative
1	2	221C	Classroom 221 Small Closet	shelf	Wood	White	None	0	0	Negative
1	2	221C	Classroom 221 Small Closet	W3	Wood	White	None	0	0.3	Negative
1	2	221C	Classroom 221 Small Closet	W4	Wood	White	None	0	0.2	Negative
1	2	221C	Classroom 221 Small Closet	Ceiling	Wood	White	None	0	0.2	Negative
1	2	221D	Classroom 221 Large Closet	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	2	221D	Classroom 221 Large Closet	W1	CMU	White	None	0	0.5	Negative
1	2	221D	Classroom 221 Large Closet	Column	Concrete	White	None	0	0.2	Negative
1	2	221D	Classroom 221 Large Closet	Doorframe	Metal	Blue	None	0	0.2	Negative
1	2	221D	Classroom 221 Large Closet	Door	Wood	Tan	None	0	0	Negative
1	2	221D	Classroom 221 Large Closet	W2	CMU	White	None	0	0.6	Negative
1	2	221D	Classroom 221 Large Closet	Case Frame/Door	Wood	White	None	0	0.2	Negative
1	2	221D	Classroom 221 Large Closet	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	2	221D	Classroom 221 Large Closet	W3	CMU	White	None	0	0.4	Negative
1	2	221D	Classroom 221 Large Closet	W4	CMU	White	None	0	0.2	Negative
1	2	221D	Classroom 221 Large Closet	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	222	Classroom 222	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
1	2	222	Classroom 222	W1	CMU	White	None	0	0	Negative
1	2	222	Classroom 222	Glazed Block	Ceramic	tan	None	0	2.4	Positive
1	2	222	Classroom 222	Doorframe	Metal	Black	Chipping	1	0.1	Negative
1	2	222	Classroom 222	Closet Doorframe	Metal	Black	None	0	0.2	Negative
1	2	222	Classroom 222	Door	Wood	Tan	Chipping	2	0	Negative
1	2	222	Classroom 222	conduit	Metal	White	None	0	0.1	Negative
1	2	222	Classroom 222	Baseboard	CMU/Tile	Black	Chipping	2	1.6	Positive
1	2	222	Classroom 222	W2	CMU	Grey	None	0	0.5	Negative
1	2	222	Classroom 222	Glazed Block	Ceramic	grey	None	0	2.2	Positive
1	2	222	Classroom 222	W3	CMU	White	None	0	0.5	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	222	Classroom 222	Univent	Metal	Grey	Chipping	14	0.1	Negative
1	2	222	Classroom 222	column	Concrete	White	Chipping	4	0.2	Negative
1	2	222	Classroom 222	Pipe Cover	Metal	White	Chipping	5	0.3	Negative
1	2	222	Classroom 222	Pipe Insulation	Fiberglass	White	Chipping	2	0	Negative
1	2	222	Classroom 222	W4	CMU	White	None	0	0.4	Negative
1	2	222	Classroom 222	Pipe	Metal	White	None	0	0.1	Negative
1	2	222	Classroom 222	Ceiling	Concrete	White	None	0	0.2	Negative
1	2	222C	Classroom 222 Closet closest to entrance	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	2	222C	Classroom 222 Closet closest to entrance	W1	Wood	N/A	N/A	N/A	N/A	N/A
1	2	222C	Classroom 222 Closet closest to entrance	Doorframe	Metal	Black	Chipping	1	0.1	Negative
1	2	222C	Classroom 222 Closet closest to entrance	Door	Wood	Tan	Chipping	1	0.1	Negative
1	2	222C	Classroom 222 Closet closest to entrance	W2	Wood	White	None	0	0.3	Negative
1	2	222C	Classroom 222 Closet closest to entrance	shelf	Wood	White	None	0	0	Negative
1	2	222C	Classroom 222 Closet closest to entrance	W3	Wood	White	None	0	0.3	Negative
1	2	222C	Classroom 222 Closet closest to entrance	W4	Wood	White	None	0	0.2	Negative
1	2	222C	Classroom 222 Closet closest to entrance	Ceiling	Wood	White	None	0	0.2	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	2	222D	Classroom 222 Closet furthest from entrance	W1	CMU	White	None	0	0.5	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	Column	Concrete	White	None	0	0.2	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	Doorframe	Metal	Blue	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	222D	Classroom 222 Closet furthest from entrance	Door	Wood	Tan	None	0	0	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	W2	CMU	White	None	0	0.6	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	Case Frame/Door	Wood	White	None	0	0.2	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	W3	CMU	White	None	0	0.4	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	W4	CMU	White	None	0	0.2	Negative
1	2	222D	Classroom 222 Closet furthest from entrance	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	223	Classroom 223	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	223	Classroom 223	W1	CMU	Tan	None	0	0.3	Negative
1	2	223	Classroom 223	Door Frame	Metal	Black	Chipping	5	0	Negative
1	2	223	Classroom 223	Door	Wood	Grey	Chipping	5	0.1	Negative
1	2	223	Classroom 223	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.1	Positive
1	2	223	Classroom 223	Conduit	Metal	Tan	None	0	0.3	Negative
1	2	223	Classroom 223	W2	CMU	Tan	None	0	0.4	Negative
1	2	223	Classroom 223	Column	Concrete	Tan	None	0	0.1	Negative
1	2	223	Classroom 223	W3	CMU	Tan	None	0	0.5	Negative
1	2	223	Classroom 223	Univent	Metal	Grey	Chipping	30	0.1	Negative
1	2	223	Classroom 223	W4	CMU	Tan	None	0	0	Negative
1	2	223	Classroom 223	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	223A	Classroom 223 Girl's Restroom	Floor	Concrete	Grey	Flaking	10	0.1	Negative
1	2	223A	Classroom 223 Girl's Restroom	W1	CMU	White	None	0	0.5	Negative
1	2	223A	Classroom 223 Girl's Restroom	Doorframe	Metal	Black	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	2	223A	Classroom 223 Girl's Restroom	Conduit	Metal	White	None	0	0.1	Negative
1	2	223A	Classroom 223 Girl's Restroom	W2	CMU	White	None	0	0.5	Negative
1	2	223A	Classroom 223 Girl's Restroom	Pipe Insulation	Fiberglass	White	None	0	0.1	Negative
1	2	223A	Classroom 223 Girl's Restroom	Drain Pipe	Metal	White	None	0	0	Negative
1	2	223A	Classroom 223 Girl's Restroom	W3	CMU	White	None	0	0.4	Negative
1	2	223A	Classroom 223 Girl's Restroom	W4	CMU	White	None	0	0	Negative
1	2	223A	Classroom 223 Girl's Restroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	223B	Classroom 223 Boy's Restroom	Floor	Concrete	Grey	Friction	12	0.3	Negative
1	2	223B	Classroom 223 Boy's Restroom	W1	CMU	White	None	0	0	Negative
1	2	223B	Classroom 223 Boy's Restroom	Doorframe	Metal	Black	None	0	0.3	Negative
1	2	223B	Classroom 223 Boy's Restroom	Conduit	Metal	White	None	0	0.1	Negative
1	2	223B	Classroom 223 Boy's Restroom	W2	CMU	White	None	0	0.3	Negative
1	2	223B	Classroom 223 Boy's Restroom	Pipe	Metal	White	None	0	0.2	Negative
1	2	223B	Classroom 223 Boy's Restroom	Pipe Insulation	Fiberglass	White	None	0	0.1	Negative
1	2	223B	Classroom 223 Boy's Restroom	W3	CMU	White	None	0	0.4	Negative
1	2	223B	Classroom 223 Boy's Restroom	Stall Dividers	Metal	Grey	Chipping	15	0.2	Negative
1	2	223B	Classroom 223 Boy's Restroom	W4	CMU	White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	223B	Classroom 223 Boy's Restroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	223C	Classroom 223 Large Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223C	Classroom 223 Large Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223C	Classroom 223 Large Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223C	Classroom 223 Large Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223C	Classroom 223 Large Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223C	Classroom 223 Large Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell # 9 next to Classroom 223	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell # 9 next to Classroom 223	W1	ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell # 9 next to Classroom 223	Doorframe	Metal	Tan	Chipping	4	0.1	Negative
1	2	S24	Stairwell # 9 next to Classroom 223	Door	Metal	Grey	Friction	5	0	Negative
1	2	S24	Stairwell # 9 next to Classroom 223	W2	ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell # 9 next to Classroom 223	Door/Doorframe	Metal	Tan	None	0	0.3	Negative
1	2	S24	Stairwell # 9 next to Classroom 223	Fire Pipe	Metal	Tan	Chipping	2	0.5	Negative
1	2	S24	Stairwell # 9 next to Classroom 223	Conduit	Metal	Tan	Chipping	3	0.4	Negative
1	2	S24	Stairwell # 9 next to Classroom 223	W3	ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell # 9 next to Classroom 223	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell # 9 next to Classroom 223	Riser	Metal	Tan	None	0	0.1	Negative
1	2	S24	Stairwell # 9 next to Classroom 223	Stringer	Metal	Tan	None	0	0.1	Negative
1	2	S24	Stairwell # 9 next to Classroom 223	baseboard	Metal	Tan	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S24	Stairwell # 9 next to Classroom 223	Stair Pan	Metal	tan	None	0	0.6	Negative
1	2	S24	Stairwell # 9 next to Classroom 223	Ceiling	Concrete	White	None	0	0.3	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H24	Hallway from Classrooms 221 to 223	W1	Sheetrock	White	None	0	0.1	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Doorframe	Metal	White	Chipping	16	0.1	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Door	Wood	Red	Friction	10	0.1	Negative
1	2	H24	Hallway from Classrooms 221 to 223	W2	CMU	White	Flaking	47	0	Negative
1	2	H24	Hallway from Classrooms 221 to 223	W3	CMU	White	Flaking	4	0.5	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Doorframe	Metal	White	Flaking	5	0.1	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Door	Metal	Grey	Friction	18	0.1	Negative
1	2	H24	Hallway from Classrooms 221 to 223	W4	CMU	White	Flaking	70	0	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Electrical Panel	Metal	White	Chipping	1	0.1	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Pipe	Metal	Black	None	0	0.1	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Baseboard	CMU/Tile	Black	Chipping	12	1.8	Positive
1	2	H24	Hallway from Classrooms 221 to 223	Conduit	Metal	White	None	0	0.3	Negative
1	2	H24	Hallway from Classrooms 221 to 223	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Doorframe	Metal	Red	Chipping	10	0.3	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Door	Metal	Red	Friction	30	0.1	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	W2	CMU	White	None	0	0.3	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Conduit	Metal	White	Chipping	5	0.4	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Fire Pipe	Metal	White	Flaking	9	0.3	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Riser	Metal	Black	Chipping	18	0.2	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Stringer	Metal	Black	Chipping	8	0.1	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Stair Pan	Metal	Tan	Flaking	6	0.3	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	W3	Plaster	White	Flaking	10	0	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Baseboard	Metal	Black	None	0	0	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Pipe	Metal	White	Chipping	3	0.4	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Doorframe	Metal	Black	Chipping	8	0.2	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Door	Metal	Grey	Flaking	20	0.1	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	W4	CMU	White	None	0	0.3	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Radiator	Metal	Black	None	0	0	Negative
1	1	S11	Stairwell adjacent to Community Coordinator's Office 100	Ceiling	Concrete	White	Flaking	60	0.3	Negative
1	1	100	Community Coordinator's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Community Coordinator's Office	W1	CMU	White	Chipping	8	0.5	Negative
1	1	100	Community Coordinator's Office	Pipe Cover	Metal	White	None	0	0.3	Negative
1	1	100	Community Coordinator's Office	Pipe Insulation	Fiberglass	White	Chipping	4	0.1	Negative
1	1	100	Community Coordinator's Office	Panel	Metal	Tan	None	0	0	Negative
1	1	100	Community Coordinator's Office	Doorframe	Metal	Black	Chipping	2	0.4	Negative
1	1	100	Community Coordinator's Office	Closet Doorframe A	Metal	Black	None	0	0.1	Negative
1	1	100	Community Coordinator's Office	Closet Doorframe B	Metal	Black	None	0	0.2	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	100	Community Coordinator's Office	W2	CMU	White	Flaking	10	0.5	Negative
1	1	100	Community Coordinator's Office	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	100	Community Coordinator's Office	Baseboard	CMU/Tile	Black	None	0	1.4	Positive
1	1	100	Community Coordinator's Office	W3	CMU	Red	Chipping	5	0.4	Negative
1	1	100	Community Coordinator's Office	Column	Concrete	White	None	0	0.3	Negative
1	1	100	Community Coordinator's Office	Univent	Metal	Grey	None	0	0.2	Negative
1	1	100	Community Coordinator's Office	W4	CMU	White	Chipping	5	0.4	Negative
1	1	100	Community Coordinator's Office	Ceiling	Concrete	White	Flaking	15	0.4	Negative
1	1	101	Parent Resource Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101	Parent Resource Room	W1	CMU	Yellow	None	0	0.1	Negative
1	1	101	Parent Resource Room	Doorframe	Metal	Black	Chipping	4	0.5	Negative
1	1	101	Parent Resource Room	Closet Doorframe A	Metal	Black	Chipping	2	0	Negative
1	1	101	Parent Resource Room	Closet Doorframe B	Metal	Black	Chipping	2	0.3	Negative
1	1	101	Parent Resource Room	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	1	101	Parent Resource Room	W2	CMU	Yellow	None	0	0	Negative
1	1	101	Parent Resource Room	W3	CMU	Yellow	Chipping	5	0.4	Negative
1	1	101	Parent Resource Room	Pipe Cover	Metal	Tan	Chipping	10	0.3	Negative
1	1	101	Parent Resource Room	Pipe Insulation	Fiberglass	Tan	Flaking	8	0.1	Negative
1	1	101	Parent Resource Room	Column	Concrete	Tan	Chipping	2	0.2	Negative
1	1	101	Parent Resource Room	Univent	Metal	Grey	Chipping	5	0.1	Negative
1	1	101	Parent Resource Room	W4	CMU	Yellow	None	0	0.3	Negative
1	1	101	Parent Resource Room	Ceiling	Concrete	White	Flaking	12	0.3	Negative
1	1	102D	EOP Suite - Suite Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	102D	EOP Suite - Suite Lobby	W1	CMU	White	None	0	0.1	Negative
1	1	102D	EOP Suite - Suite Lobby	Doorframe	Metal	Black	Chipping	3	0.5	Negative
1	1	102D	EOP Suite - Suite Lobby	Closet Doorframe	Metal	Black	Chipping	2	0.3	Negative
1	1	102D	EOP Suite - Suite Lobby	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	1	102D	EOP Suite - Suite Lobby	Chalkboard	Metal	Black	None	0	1.3	Positive
1	1	102D	EOP Suite - Suite Lobby	W2	Metal	White	None	0	0.2	Negative
1	1	102D	EOP Suite - Suite Lobby	W3	Metal	White	None	0	0.1	Negative
1	1	102D	EOP Suite - Suite Lobby	W4	CMU	White	None	0	0.3	Negative
1	1	102D	EOP Suite - Suite Lobby	Ceiling	Concrete	White	Flaking	4	0.3	Negative
1	1	102	EOP Suite - Office closest to Main Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	EOP Suite - Office closest to Main Lobby	W1	Metal	White	None	0	0.2	Negative
1	1	102	EOP Suite - Office closest to Main Lobby	W2	Metal	White	None	0	0.1	Negative
1	1	102	EOP Suite - Office closest to Main Lobby	W3	CMU	White	None	0	0.2	Negative
1	1	102	EOP Suite - Office closest to Main Lobby	Baseboard	CMU/Tile	Black	Chipping	1	0.9	Positive
1	1	102	EOP Suite - Office closest to Main Lobby	Pipe Cover	Metal	White	Chipping	1	0.1	Negative
1	1	102	EOP Suite - Office closest to Main Lobby	Pipe Insulation	Fiberglass	White	None	0	0.1	Negative
1	1	102	EOP Suite - Office closest to Main Lobby	Radiator	Metal	White	None	0	0.1	Negative
1	1	102	EOP Suite - Office closest to Main Lobby	W4	CMU	White	None	0	0.2	Negative
1	1	102	EOP Suite - Office closest to Main Lobby	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	1	102A	EOP Suite - Middle Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102A	EOP Suite - Middle Office	W1	Metal	White	None	0	0.1	Negative
1	1	102A	EOP Suite - Middle Office	Doorframe	Metal	Black	None	0	0.2	Negative
1	1	102A	EOP Suite - Middle Office	Conduit	Metal	White	None	0	0.9	Positive

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E</b>	<b>F</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	102A	EOP Suite - Middle Office	W2	Metal	White	None	0	0.1	Negative
1	1	102A	EOP Suite - Middle Office	W3	CMU	White	None	0	0.2	Negative
1	1	102A	EOP Suite - Middle Office	Radiator	Metal	White	None	0	0.1	Negative
1	1	102A	EOP Suite - Middle Office	Pipe Cover	Metal	White	None	0	0.2	Negative
1	1	102A	EOP Suite - Middle Office	Pipe Insulation	Fiberglass	White	Cracking	5	0.1	Negative
1	1	102A	EOP Suite - Middle Office	Column	Concrete	White	None	0	0	Negative
1	1	102A	EOP Suite - Middle Office	W4	Metal	White	None	0	0.1	Negative
1	1	102A	EOP Suite - Middle Office	Ceiling	Concrete	White	Flaking	4	0.2	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102B	EOP Suite - Office on Room 101 side	W1	Metal	Tan	None	0	0.1	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Doorframe	Metal	Tan	Friction	2	0.1	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Conduit	Metal	Tan	None	0	0.8	Positive
1	1	102B	EOP Suite - Office on Room 101 side	W2	CMU	Tan	Flaking	3	0.3	Negative
1	1	102B	EOP Suite - Office on Room 101 side	W3	CMU	Tan	Flaking	2	0.2	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Pipe Insulation	Fiberglass	Tan	Cracking	8	0.1	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Pipe Cover	Metal	Tan	Chipping	6	0.1	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Pipe	Metal	Black	Chipping	3	0.3	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Column	Concrete	Tan	Flaking	4	0.1	Negative
1	1	102B	EOP Suite - Office on Room 101 side	Baseboard	CMU/Tile	Black	Chipping	1	0.9	Positive
1	1	102B	EOP Suite - Office on Room 101 side	W4	Metal	Tan	Flaking	2	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	102B	EOP Suite - Office on Room 101 side	Ceiling	Concrete	White	Cracking	8	0.2	Negative
1	1	102C	EOP Suite - Storeroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102C	EOP Suite - Storeroom	W1	Metal	White	None	0	0.2	Negative
1	1	102C	EOP Suite - Storeroom	Doorframe	Metal	White	None	0	0.1	Negative
1	1	102C	EOP Suite - Storeroom	W2	CMU	White	None	0	0.2	Negative
1	1	102C	EOP Suite - Storeroom	W3	CMU	White	None	0	0.2	Negative
1	1	102C	EOP Suite - Storeroom	W4	Metal	White	None	0	0.2	Negative
1	1	102C	EOP Suite - Storeroom	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	1	117A	School Store	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	School Store	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	School Store	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	School Store	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	School Store	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	School Store	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103D	Suite 103 - Suite Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103D	Suite 103 - Suite Lobby	W1	CMU	White	None	0	0.4	Negative
1	1	103D	Suite 103 - Suite Lobby	Baseboard	CMU/Tile	Black	Chipping	2	1	Positive
1	1	103D	Suite 103 - Suite Lobby	Conduit	Metal	White	None	0	0.3	Negative
1	1	103D	Suite 103 - Suite Lobby	Closet A Door Frame	Metal	Black	None	0	0.4	Negative
1	1	103D	Suite 103 - Suite Lobby	Corkboard	Cork	Black	None	0	0.3	Negative
1	1	103D	Suite 103 - Suite Lobby	Doorframe	Metal	Black	Chipping	6	0.5	Negative
1	1	103D	Suite 103 - Suite Lobby	W2	Metal	White	Chipping	2	0.1	Negative
1	1	103D	Suite 103 - Suite Lobby	W3	Metal	White	Chipping	3	0.1	Negative
1	1	103D	Suite 103 - Suite Lobby	W4	CMU	White	None	0	0.3	Negative
1	1	103D	Suite 103 - Suite Lobby	Ceiling	Concrete	White	Flaking	2	0.2	Negative
1	1	103	Suite 103 - Office across from Suite Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Suite 103 - Office across from Suite Entrance	W1	Metal	White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	103	Suite 103 - Office across from Suite Entrance	W2	Metal	White	None	0	0.1	Negative
1	1	103	Suite 103 - Office across from Suite Entrance	W3	CMU	White	None	0	0.4	Negative
1	1	103	Suite 103 - Office across from Suite Entrance	Pipe Cover	Metal	White	Chipping	1	0.3	Negative
1	1	103	Suite 103 - Office across from Suite Entrance	Pipe Insulation	Fiberglass	White	Cracking	1	0.1	Negative
1	1	103	Suite 103 - Office across from Suite Entrance	Radiator	Metal	White	Chipping	1	0.1	Negative
1	1	103	Suite 103 - Office across from Suite Entrance	Column	Concrete	White	Flaking	2	0.1	Negative
1	1	103	Suite 103 - Office across from Suite Entrance	W4	CMU	White	None	0	0.4	Negative
1	1	103	Suite 103 - Office across from Suite Entrance	Ceiling	Concrete	White	None	0	0.5	Negative
1	1	103A	Suite 103 - Middle Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103A	Suite 103 - Middle Office	W1	Metal	White	None	0	0.2	Negative
1	1	103A	Suite 103 - Middle Office	W2	Metal	White	None	0	0.2	Negative
1	1	103A	Suite 103 - Middle Office	W3	CMU	White	Flaking	1	0.4	Negative
1	1	103A	Suite 103 - Middle Office	Radiator	Metal	White	None	0	0.2	Negative
1	1	103A	Suite 103 - Middle Office	Pipe Cover	Metal	White	Chipping	2	0.2	Negative
1	1	103A	Suite 103 - Middle Office	Pipe Insulation	Fiberglass	White	None	0	0.1	Negative
1	1	103A	Suite 103 - Middle Office	W4	Metal	White	None	0	0.2	Negative
1	1	103A	Suite 103 - Middle Office	Ceiling	Concrete	White	Flaking	2	0.4	Negative
1	1	103B	Suite 103 - Back Office on Main Entrance side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103B	Suite 103 - Back Office on Main Entrance side	W1	Metal	White	None	0	0	Negative
1	1	103B	Suite 103 - Back Office on Main Entrance side	W2	CMU	White	None	0	0.5	Negative
1	1	103B	Suite 103 - Back Office on Main Entrance side	Baseboard	CMU/Tile	Black	None	0	1	Positive
1	1	103B	Suite 103 - Back Office on Main Entrance side	W3	CMU	White	None	0	0.5	Negative
1	1	103B	Suite 103 - Back Office on Main Entrance side	W4	Metal	White	None	0	0	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	103B	Suite 103 - Back Office on Main Entrance side	Ceiling	Concrete	White	Flaking	2	0.5	Negative
1	1	103C	Suite 103 - Front Office on Main Entrance side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103C	Suite 103 - Front Office on Main Entrance side	W1	Metal	White	None	0	0.2	Negative
1	1	103C	Suite 103 - Front Office on Main Entrance side	conduit	Metal	White	None	0	0.5	Negative
1	1	103C	Suite 103 - Front Office on Main Entrance side	W2	CMU	White	Flaking	18	0.4	Negative
1	1	103C	Suite 103 - Front Office on Main Entrance side	W3	CMU	White	Flaking	18	0.4	Negative
1	1	103C	Suite 103 - Front Office on Main Entrance side	Baseboard	CMU/Tile	Black	None	0	1	Positive
1	1	103C	Suite 103 - Front Office on Main Entrance side	radiator	Metal	White	None	0	0.3	Negative
1	1	103C	Suite 103 - Front Office on Main Entrance side	W4	Metal	White	None	0	0.2	Negative
1	1	103C	Suite 103 - Front Office on Main Entrance side	Ceiling	Concrete	White	None	0	0.4	Negative
1	1	H11A	Custodial Closet across from Classroom 104	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11A	Custodial Closet across from Classroom 104	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11A	Custodial Closet across from Classroom 104	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11A	Custodial Closet across from Classroom 104	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11A	Custodial Closet across from Classroom 104	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11A	Custodial Closet across from Classroom 104	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11B	Storeroom next to Custodial Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	H11B	Storeroom next to Custodial Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11B	Storeroom next to Custodial Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11B	Storeroom next to Custodial Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11B	Storeroom next to Custodial Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11B	Storeroom next to Custodial Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104	Suite 104 - Classroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Suite 104 - Classroom	W1	CMU	White	Cracking	8	0.4	Negative
1	1	104	Suite 104 - Classroom	Doorframe	Metal	Black	None	0	0.1	Negative
1	1	104	Suite 104 - Classroom	Baseboard	CMU/Tile	Black	None	0	1	Positive
1	1	104	Suite 104 - Classroom	W2	CMU	White	None	0	0.4	Negative
1	1	104	Suite 104 - Classroom	W3	CMU	White	None	0	0.5	Negative
1	1	104	Suite 104 - Classroom	Univent	Metal	Grey	None	0	0	Negative
1	1	104	Suite 104 - Classroom	W4	CMU	White	Chipping	5	0.4	Negative
1	1	104	Suite 104 - Classroom	Column	Concrete	White	Flaking	8	0.1	Negative
1	1	104	Suite 104 - Classroom	Pipe Cover	Metal	White	Chipping	6	0.1	Negative
1	1	104	Suite 104 - Classroom	Pipe Insulation	Fiberglass	White	Flaking	10	0.1	Negative
1	1	104	Suite 104 - Classroom	Ceiling	Concrete	White	Flaking	18	0.4	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104D	Suite 104 - Storeroom off Classroom	W1	Plaster	Tan	Cracking	20	0.1	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	Door Frame	Metal	Black	None	0	0.9	Positive
1	1	104D	Suite 104 - Storeroom off Classroom	Baseboard	Tile	Black	None	0	1.2	Positive
1	1	104D	Suite 104 - Storeroom off Classroom	W2	CMU	White	None	0	0.5	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	104D	Suite 104 - Storeroom off Classroom	Pipe Cover	Metal	White	Chipping	10	0.3	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	Pipe Insulation	Fiberglass	White	Chipping	3	0.1	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	Column	Concrete	White	Chipping	5	0.1	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	Radiator	Metal	White	Flaking	25	0.4	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	W3	Plaster	Tan	Chipping	8	0.2	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	Window frame	Metal	Tan	Chipping	3	0.1	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	W4	Plaster	Tan	Cracking	20	0.1	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	Doorframe	Metal	Black	None	0	0.2	Negative
1	1	104D	Suite 104 - Storeroom off Classroom	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	104A	Suite 104 - First Office Main Hallway Side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104A	Suite 104 - First Office Main Hallway Side	W1	Plaster	White	None	0	0.1	Negative
1	1	104A	Suite 104 - First Office Main Hallway Side	Doorframe	Metal	Black	None	0	0.3	Negative
1	1	104A	Suite 104 - First Office Main Hallway Side	W2	Plaster	White	Cracking	2	0.2	Negative
1	1	104A	Suite 104 - First Office Main Hallway Side	Window Frame	Metal	White	None	0	0.1	Negative
1	1	104A	Suite 104 - First Office Main Hallway Side	W3	Plaster	White	None	0	0.2	Negative
1	1	104A	Suite 104 - First Office Main Hallway Side	W4	Plaster	White	None	0	0.3	Negative
1	1	104A	Suite 104 - First Office Main Hallway Side	Baseboard	Tile	Black	None	0	1	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	104A	Suite 104 - First Office Main Hallway Side	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	1	104B	Suite 104 - Second Office Main Hallway Side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104B	Suite 104 - Second Office Main Hallway Side	W1	Plaster	White	None	0	0.1	Negative
1	1	104B	Suite 104 - Second Office Main Hallway Side	Door Frame	Metal	Black	None	0	0.8	Positive
1	1	104B	Suite 104 - Second Office Main Hallway Side	Baseboard	Tile	Black	None	0	1.1	Positive
1	1	104B	Suite 104 - Second Office Main Hallway Side	W2	Plaster	White	None	0	0.1	Negative
1	1	104B	Suite 104 - Second Office Main Hallway Side	Window Frame	Metal	White	Chipping	2	0.7	Positive
1	1	104B	Suite 104 - Second Office Main Hallway Side	W3	Plaster	White	None	0	0.2	Negative
1	1	104B	Suite 104 - Second Office Main Hallway Side	W4	Plaster	White	None	0	0.1	Negative
1	1	104B	Suite 104 - Second Office Main Hallway Side	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	1	104C	Suite 104 - Third Office Main Hallway Side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104C	Suite 104 - Third Office Main Hallway Side	W1	Plaster	Pink	Cracking	2	0.1	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	Door Frame	Metal	Black	None	0	0.9	Positive
1	1	104C	Suite 104 - Third Office Main Hallway Side	Window frame	Metal	Pink	None	0	0.2	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	W2	CMU	White	Flaking	8	0.5	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	Univent	Metal	Black	Chipping	6	0.3	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	Duct	Metal	Pink	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	104C	Suite 104 - Third Office Main Hallway Side	Radiator	Metal	Black	None	0	0.1	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	W3	Plaster	Tan	None	0	0.2	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	Baseboard	Tile	Black	None	0	1	Positive
1	1	104C	Suite 104 - Third Office Main Hallway Side	Pipe Cover	Metal	Tan	Chipping	8	0.3	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	Pipe Insulation	Fiberglass	Tan	Chipping	2	0.2	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	Column	Concrete	Tan	Chipping	10	0.4	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	W4	Plaster	Tan	None	0	0.2	Negative
1	1	104C	Suite 104 - Third Office Main Hallway Side	Ceiling	Concrete	White	None	0	0.5	Negative
1	1	104E	Suite 104 - Second Storeroom Classroom side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104E	Suite 104 - Second Storeroom Classroom side	W1	Plaster	Tan	Cracking	8	0.1	Negative
1	1	104E	Suite 104 - Second Storeroom Classroom side	Door Frame	Metal	Black	None	0	1.2	Positive
1	1	104E	Suite 104 - Second Storeroom Classroom side	W2	Plaster	Tan	None	0	0.2	Negative
1	1	104E	Suite 104 - Second Storeroom Classroom side	Window Frame	Metal	Tan	None	0	0.7	Positive
1	1	104E	Suite 104 - Second Storeroom Classroom side	Baseboard	Tile	Black	None	0	1.4	Positive
1	1	104E	Suite 104 - Second Storeroom Classroom side	W3	Plaster	Tan	None	0	0.2	Negative
1	1	104E	Suite 104 - Second Storeroom Classroom side	W4	Plaster	Tan	None	0	0.2	Negative
1	1	104E	Suite 104 - Second Storeroom Classroom side	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	1	104F	Suite 104 - First Storeroom Classroom side	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	104F	Suite 104 - First Storeroom Classroom side	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104F	Suite 104 - First Storeroom Classroom side	Door Frame	Metal	Black	None	0	1	Positive
1	1	104F	Suite 104 - First Storeroom Classroom side	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104F	Suite 104 - First Storeroom Classroom side	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104F	Suite 104 - First Storeroom Classroom side	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104F	Suite 104 - First Storeroom Classroom side	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	W1	CMU	Pink	None	0	0.5	Negative
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	Door Frame	Metal	Black	None	0	1.1	Positive
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	W2	CMU	Pink	None	0	0.4	Negative
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	Conduit	Metal	Pink	None	0	0.3	Negative
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	Door Frame	Metal	Black	None	0	0.7	Positive
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	W3	CMU	Pink	None	0	0.4	Negative
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	W4	CMU	Pink	None	0	0.5	Negative
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	Vent	Metal	Pink	None	0	0.1	Negative
1	1	104G	Suite 104 - Hallway from Main Hallway to Classroom	Ceiling	Concrete	White	Flaking	5	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	104H	Suite 104 - Office/Storeroom Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104H	Suite 104 - Office/Storeroom Hallway	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104H	Suite 104 - Office/Storeroom Hallway	W2	CMU	Pink	None	0	0.4	Negative
1	1	104H	Suite 104 - Office/Storeroom Hallway	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	1	104H	Suite 104 - Office/Storeroom Hallway	W3	CMU	Pink	None	0	0.2	Negative
1	1	104H	Suite 104 - Office/Storeroom Hallway	W4	CMU	Pink	None	0	0.1	Negative
1	1	104H	Suite 104 - Office/Storeroom Hallway	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell next to Suite 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell next to Suite 104	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell next to Suite 104	Doorframe	Metal	Red	Chipping	5	0.4	Negative
1	1	S15	Stairwell next to Suite 104	Door	Metal	Red	Chipping	8	0.1	Negative
1	1	S15	Stairwell next to Suite 104	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell next to Suite 104	Fire Pipe	Metal	Tan	Chipping	2	0.4	Negative
1	1	S15	Stairwell next to Suite 104	Frame	Metal	Tan	Chipping	4	0.3	Negative
1	1	S15	Stairwell next to Suite 104	Riser	Metal	Tan	Chipping	12	0.1	Negative
1	1	S15	Stairwell next to Suite 104	Stringer	Metal	Tan	Chipping	10	0.1	Negative
1	1	S15	Stairwell next to Suite 104	Stair Pan	Metal	Tan	Flaking	10	0.4	Negative
1	1	S15	Stairwell next to Suite 104	W3	Concrete	Tan	Flaking	15	0.1	Negative
1	1	S15	Stairwell next to Suite 104	Baseboard	Metal	Black	None	0	0	Negative
1	1	S15	Stairwell next to Suite 104	Doorframe	Metal	Grey	None	0	0.1	Negative
1	1	S15	Stairwell next to Suite 104	Door	Metal	Grey	Friction	8	0.1	Negative
1	1	S15	Stairwell next to Suite 104	Radiator	Metal	Grey	None	0	0.4	Negative
1	1	S15	Stairwell next to Suite 104	Stair Cage	Metal	Blue	Chipping	10	0	Negative
1	1	S15	Stairwell next to Suite 104	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell next to Suite 104	Conduit	Metal	Tan	None	0	0.3	Negative
1	1	S15	Stairwell next to Suite 104	Ceiling	Concrete	White	Flaking	20	0.2	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	H11	Music Wing Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H11	Music Wing Hallway	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H11	Music Wing Hallway	W2	CMU	White	None	0	0.4	Negative
1	1	H11	Music Wing Hallway	Radiator	Metal	White	None	0	0.1	Negative
1	1	H11	Music Wing Hallway	Vent	Metal	White	None	0	0.1	Negative
1	1	H11	Music Wing Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H11	Music Wing Hallway	W4	CMU	White	None	0	0.2	Negative
1	1	H11	Music Wing Hallway	Baseboard	Tile	Black	None	0	1.1	Positive
1	1	H11	Music Wing Hallway	Ceiling	Concrete	White	None	0	0.1	Negative
1	1	105	Music Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105	Music Classroom 105	W1	CMU	White	None	0	0.3	Negative
1	1	105	Music Classroom 105	Doorframe	Metal	Black	None	0	0.2	Negative
1	1	105	Music Classroom 105	Baseboard	CMU/Tile	Black	None	0	1.4	Positive
1	1	105	Music Classroom 105	W2	CMU	White	None	0	0.4	Negative
1	1	105	Music Classroom 105	Riser	Metal	Black	Chipping	15	0.1	Negative
1	1	105	Music Classroom 105	Tread	Metal	Red	Friction	20	0.2	Negative
1	1	105	Music Classroom 105	Column	Concrete	Red	Chipping	6	0.3	Negative
1	1	105	Music Classroom 105	Univent	Metal	Grey	Chipping	8	0	Negative
1	1	105	Music Classroom 105	Pipe Cover	Metal	Red	Chipping	15	0.2	Negative
1	1	105	Music Classroom 105	Pipe Insulation	Fiberglass	Red	None	0	0.1	Negative
1	1	105	Music Classroom 105	W3	CMU	White	None	0	0.6	Negative
1	1	105	Music Classroom 105	W4	CMU	White	None	0	0.4	Negative
1	1	105	Music Classroom 105	Ceiling	Concrete	White	Flaking	25	0.4	Negative
1	1	105C	Classroom 105 Center Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105C	Classroom 105 Center Closet	W1	CMU	White	None	0	0.3	Negative
1	1	105C	Classroom 105 Center Closet	Door Frame	Metal	Black	Chipping	4	0.7	Positive
1	1	105C	Classroom 105 Center Closet	W2	CMU	White	None	0	0.4	Negative
1	1	105C	Classroom 105 Center Closet	W3	CMU	White	None	0	0.5	Negative
1	1	105C	Classroom 105 Center Closet	W4	CMU	White	None	0	0.4	Negative
1	1	105C	Classroom 105 Center Closet	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	105D	Classroom 105 Rear Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm<sup>2</sup>)</b>	<b>XRF (positive/negative)</b>
1	1	105D	Classroom 105 Rear Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105D	Classroom 105 Rear Closet	Door Frame	Metal	Black	None	0	0.9	Positive
1	1	105D	Classroom 105 Rear Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105D	Classroom 105 Rear Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105D	Classroom 105 Rear Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105D	Classroom 105 Rear Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105F	Classroom 105 Front Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105F	Classroom 105 Front Closet	W1	CMU	White	None	0	0.4	Negative
1	1	105F	Classroom 105 Front Closet	W2	CMU	White	None	0	0.3	Negative
1	1	105F	Classroom 105 Front Closet	W3	CMU	White	None	0	0.4	Negative
1	1	105F	Classroom 105 Front Closet	Column	Concrete	White	None	0	0.2	Negative
1	1	105F	Classroom 105 Front Closet	W4	CMU	White	None	0	0.4	Negative
1	1	105F	Classroom 105 Front Closet	Radiator	Metal	White	Flaking	4	0.1	Negative
1	1	105F	Classroom 105 Front Closet	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	105B	Custodial Closet by Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Custodial Closet by Classroom 105	W1	CMU	White	None	0	0.3	Negative
1	1	105B	Custodial Closet by Classroom 105	Doorframe	Metal	Black	None	0	0.2	Negative
1	1	105B	Custodial Closet by Classroom 105	W2	CMU	White	Chipping	4	0.4	Negative
1	1	105B	Custodial Closet by Classroom 105	Shelf	Wood	White	Chipping	7	0.3	Negative
1	1	105B	Custodial Closet by Classroom 105	Ceramic Wall	Ceramic	White	Flaking	8	0.3	Negative
1	1	105B	Custodial Closet by Classroom 105	W3	CMU	White	Chipping	3	0.4	Negative
1	1	105B	Custodial Closet by Classroom 105	Electrical Panel	Metal	White	Chipping	4	0.2	Negative
1	1	105B	Custodial Closet by Classroom 105	W4	CMU	White	None	0	0.4	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	105B	Custodial Closet by Classroom 105	conduit	Metal	White	None	0	0.5	Negative
1	1	105B	Custodial Closet by Classroom 105	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	105A	Storage Room 105 A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105A	Storage Room 105 A	W1	CMU	White	None	0	0.5	Negative
1	1	105A	Storage Room 105 A	Doorframe	Metal	Black	None	0	0.2	Negative
1	1	105A	Storage Room 105 A	W2	Sheetrock	White	None	0	0.1	Negative
1	1	105A	Storage Room 105 A	Column	Concrete	White	None	0	0.2	Negative
1	1	105A	Storage Room 105 A	W3	CMU	White	None	0	0.3	Negative
1	1	105A	Storage Room 105 A	W4	Sheetrock	White	None	0	0.4	Negative
1	1	105A	Storage Room 105 A	Conduit	Metal	White	None	0	0.4	Negative
1	1	105A	Storage Room 105 A	Radiator	Metal	White	Chipping	5	0.2	Negative
1	1	105A	Storage Room 105 A	Doorframe	Metal	Black	None	0	0.2	Negative
1	1	105A	Storage Room 105 A	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	117E	Auditorium Entrance Ramp across from Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	117E	Auditorium Entrance Ramp across from Classroom 105	W1	CMU	White	None	0	0.3	Negative
1	1	117E	Auditorium Entrance Ramp across from Classroom 105	W2	CMU	White	None	0	0.4	Negative
1	1	117E	Auditorium Entrance Ramp across from Classroom 105	W3	CMU	White	None	0	0.3	Negative
1	1	117E	Auditorium Entrance Ramp across from Classroom 105	W4	CMU	White	None	0	0.4	Negative
1	1	117E	Auditorium Entrance Ramp across from Classroom 105	Ceiling	Concrete	White	None	0	0.4	Negative
1	1	117F	Auditorium Entrance Ramp across from Classroom 105A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	117F	Auditorium Entrance Ramp across from Classroom 105A	W1	CMU	White	None	0	0.4	Negative
1	1	117F	Auditorium Entrance Ramp across from Classroom 105A	W2	CMU	White	None	0	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	117F	Auditorium Entrance Ramp across from Classroom 105A	W3	CMU	White	None	0	0.4	Negative
1	1	117F	Auditorium Entrance Ramp across from Classroom 105A	W4	CMU	White	None	0	0.2	Negative
1	1	117F	Auditorium Entrance Ramp across from Classroom 105A	Ceiling	Concrete	White	None	0	0.4	Negative
1	1	S16	Stairwell # 5 next to Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S16	Stairwell # 5 next to Boy's Restroom	W1	CMU	White	None	0	0.3	Negative
1	1	S16	Stairwell # 5 next to Boy's Restroom	W2	CMU	White	None	0	0.3	Negative
1	1	S16	Stairwell # 5 next to Boy's Restroom	W3	CMU	White	None	0	0.4	Negative
1	1	S16	Stairwell # 5 next to Boy's Restroom	W4	CMU	White	None	0	0.5	Negative
1	1	S16	Stairwell # 5 next to Boy's Restroom	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	116X	Hallway behind Stairwell # 5	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	116X	Hallway behind Stairwell # 5	W1	CMU	White	None	0	0.3	Negative
1	1	116X	Hallway behind Stairwell # 5	W2	CMU	White	None	0	0.3	Negative
1	1	116X	Hallway behind Stairwell # 5	W3	CMU	White	None	0	0.4	Negative
1	1	116X	Hallway behind Stairwell # 5	W4	CMU	White	None	0	0.5	Negative
1	1	116X	Hallway behind Stairwell # 5	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	106	School Police Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	School Police Office	W1	CMU	White	Chipping	9	0.4	Negative
1	1	106	School Police Office	Doorframe	Metal	Black	Chipping	3	0.2	Negative
1	1	106	School Police Office	Doorframe Closet A	Metal	Black	None	0	0.3	Negative
1	1	106	School Police Office	Doorframe Closet B	Metal	Black	None	0	0.3	Negative
1	1	106	School Police Office	Conduit	Metal	White	Chipping	5	0.9	Positive
1	1	106	School Police Office	Baseboard	CMU/Tile	Black	None	0	1.3	Positive

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	106	School Police Office	W2	CMU	White	Flaking	12	0.5	Negative
1	1	106	School Police Office	W3	CMU	White	Flaking	10	0.5	Negative
1	1	106	School Police Office	Univent	Metal	Grey	Chipping	10	0.1	Negative
1	1	106	School Police Office	Pipe Cover	Metal	White	Chipping	8	0.3	Negative
1	1	106	School Police Office	Pipe Insulation	Fiberglass	White	Chipping	10	0.2	Negative
1	1	106	School Police Office	Column	Concrete	White	Chipping	5	0.2	Negative
1	1	106	School Police Office	W4	CMU	White	None	0	0.5	Negative
1	1	106	School Police Office	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	107	Carpentry Shop	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Carpentry Shop	Column	Concrete	Tan/White	Chipping	16	0.2	Negative
1	1	107	Carpentry Shop	W1	CMU	Tan/White	Chipping	2	0.3	Negative
1	1	107	Carpentry Shop	Pipe	MEtal	White	Chipping	4	0.2	Negative
1	1	107	Carpentry Shop	Door Frame	Metal	Black	Chipping	6	0.5	Negative
1	1	107	Carpentry Shop	Window Frame/Panel	Metal	Tan	Chipping	1	0.1	Negative
1	1	107	Carpentry Shop	Conduit	Metal	Tan/White	Chipping	7	0.1	Negative
1	1	107	Carpentry Shop	Pipe	Metal	Tan/White	Chipping	2	0.3	Negative
1	1	107	Carpentry Shop	Baseboard	CMU/Tile	Black	Chipping	2	1.4	Positive
1	1	107	Carpentry Shop	Door Frame	Metal	Tan	None	0	0.1	Negative
1	1	107	Carpentry Shop	Door Frame	Metal	Tan	None	0	0.1	Negative
1	1	107	Carpentry Shop	Window Frame/Panel	Metal/Sheetrock	Tan	None	0	0.1	Negative
1	1	107	Carpentry Shop	W2	CMU	Tan	None	0	0.4	Negative
1	1	107	Carpentry Shop	Radiator/Univent	Metal	Gray	Chipping	6	0.1	Negative
1	1	107	Carpentry Shop	Pipe Cover	Metal	Tan	Chipping	9	0.1	Negative
1	1	107	Carpentry Shop	Pipe Insulation	Fiberglass	White	Flaking	39	0.1	Negative
1	1	107	Carpentry Shop	Conduit	Metal	Tan/White	Chipping	7	0.1	Negative
1	1	107	Carpentry Shop	Baseboard	CMU/Tile	Black	Chipping	2	1.4	Positive
1	1	107	Carpentry Shop	W3	CMU/Sheetrock	Tan/White	Flaking	3	0.2	Negative
1	1	107	Carpentry Shop	Pipe Insulation	Fiberglass	White	Flaking	39	0.1	Negative
1	1	107	Carpentry Shop	Conduit	Metal	Tan/White	Chipping	7	0.1	Negative
1	1	107	Carpentry Shop	Duct	Metal	Tan/White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	107	Carpentry Shop	Wall Tile	Ceramic	Gray	None	0	1.8	Positive
1	1	107	Carpentry Shop	Baseboard	CMU/Tile	Black	Chipping	2	1.4	Positive
1	1	107	Carpentry Shop	Door Frame	MEtal	Tan	None	0	0.1	Negative
1	1	107	Carpentry Shop	W4	CMU/Sheetrock	Tan/White	Flaking	6	0.4	Negative
1	1	107	Carpentry Shop	Baseboard	CMU/Tile	Black	Chipping	2	1.4	Positive
1	1	107	Carpentry Shop	Roll-Up Door	Metal	Gray	Flaking	15	0.5	Negative
1	1	107	Carpentry Shop	Roll-Up Door Frame	Metal	Gray	Flaking	6	0.5	Negative
1	1	107	Carpentry Shop	Door	Metal	Black	Chipping	2	0.1	Negative
1	1	107	Carpentry Shop	Door Frame	MEtal	Black	Chipping	2	0	Negative
1	1	107	Carpentry Shop	Ceiling	Concrete	White	Flaking	5	0.3	Negative
1	1	107	Carpentry Shop	Pipe Insulation	Fiberglass	White	Flaking	39	0.1	Negative
1	1	107	Carpentry Shop	Pipe	Metal	Tan/White	Chipping	2	0.3	Negative
1	1	107A	Carpentry Shop Paint Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Carpentry Shop Paint Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Carpentry Shop Paint Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Carpentry Shop Paint Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Carpentry Shop Paint Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Carpentry Shop Paint Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107B	Carpentry Shop Air Compressor Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107B	Carpentry Shop Air Compressor Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107B	Carpentry Shop Air Compressor Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107B	Carpentry Shop Air Compressor Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107B	Carpentry Shop Air Compressor Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107B	Carpentry Shop Air Compressor Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Carpentry Shop Equipment Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	107C	Carpentry Shop Equipment Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Carpentry Shop Equipment Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Carpentry Shop Equipment Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Carpentry Shop Equipment Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Carpentry Shop Equipment Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107D	Carpentry Shop Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107D	Carpentry Shop Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107D	Carpentry Shop Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107D	Carpentry Shop Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107D	Carpentry Shop Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107D	Carpentry Shop Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S14	Stairwell # 9 behind Carpentry Shop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S14	Stairwell # 9 behind Carpentry Shop	Riser	Concrete	Grey	Friction	21	0.4	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	Tread	Concrete	Grey	Friction	21	0.4	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	W1	CMU	Tan	None	0	0.2	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	Baseboard (W1-4)	CMU/Tile	Black	Chipping	4	1.2	Positive
1	1	S14	Stairwell # 9 behind Carpentry Shop	W2	CMU	Tan	Flaking	20	0.3	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	Coduit (W2-3)	Metal	Tan	None	0	0.5	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	Electrical Panel	Metal	Tan/Black	Chipping	6	0.3	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	W3	CMU	Tan	Flaking	12	0.3	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S14	Stairwell # 9 behind Carpentry Shop	Column	Concrete	Tan	Flaking	2	0.2	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	W4	CMU	Tan	Flaking	18	0.5	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	Pipe Cover	Metal	Tan	None	0	0.3	Negative
1	1	S14	Stairwell # 9 behind Carpentry Shop	Ceiling	Concrete	Tan	None	0	0.4	Negative
1	1	H15	Hallway at Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H15	Hallway at Classroom 108	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H15	Hallway at Classroom 108	W2	CMU/Sheetrock	Tan	Flaking	14	0.3	Negative
1	1	H15	Hallway at Classroom 108	Door Frame	Metal	Red	Flaking	3	8.5	Positive
1	1	H15	Hallway at Classroom 108	Door Frame	Metal	Red	Flaking	4	8.5	Positive
1	1	H15	Hallway at Classroom 108	Baseboard (W2, 4)	CMU/Tile	Black	None	0	1.2	Positive
1	1	H15	Hallway at Classroom 108	Conduit (W2,4)	Metal	Tan	None	0	0.5	Negative
1	1	H15	Hallway at Classroom 108	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H15	Hallway at Classroom 108	W4	CMU/Sheetrock	Tan	Flaking	4	0.3	Negative
1	1	H15	Hallway at Classroom 108	Electrical Panel	Metal	Black	Flaking	1	0.2	Negative
1	1	H15	Hallway at Classroom 108	Door Panel	Metal	Black/Red	Flaking	1	0.2	Negative
1	1	H15	Hallway at Classroom 108	Ceiling	Concrete	White	Moisture Damage	6	0.2	Negative
1	1	108	Tech Suite 108 - Workshop	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Tech Suite 108 - Workshop	W1	CMU	Tan	None	0	0.4	Negative
1	1	108	Tech Suite 108 - Workshop	Doorframe	Metal	Black	Chipping	3	0	Negative
1	1	108	Tech Suite 108 - Workshop	Closet Doorframe	Metal	Black	None	0	0.5	Negative
1	1	108	Tech Suite 108 - Workshop	Closet Shelf	Wood	Tan	Chipping	10	0.1	Negative
1	1	108	Tech Suite 108 - Workshop	Baseboard	CMU/Tile	Black	None	0	1.3	Positive
1	1	108	Tech Suite 108 - Workshop	Conduit	Metal	Tan	Chipping	4	0.2	Negative
1	1	108	Tech Suite 108 - Workshop	Pipe Cover	Metal	Tan	None	0	0.3	Negative
1	1	108	Tech Suite 108 - Workshop	Pipe Insulation	Fiberglass	Tan	None	0	0	Negative
1	1	108	Tech Suite 108 - Workshop	Duct	Metal	Tan	None	0	0.3	Negative
1	1	108	Tech Suite 108 - Workshop	W2	CMU	Tan	None	0	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	108	Tech Suite 108 - Workshop	Electrical Panel	Metal	Tan	None	0	0.1	Negative
1	1	108	Tech Suite 108 - Workshop	Window Panel	Metal	Tan	None	0	0	Negative
1	1	108	Tech Suite 108 - Workshop	W3	CMU	Tan	None	0	0.4	Negative
1	1	108	Tech Suite 108 - Workshop	Column	Concrete	Tan	Chipping	6	0.2	Negative
1	1	108	Tech Suite 108 - Workshop	Radiator	Metal	Black	None	0	0.3	Negative
1	1	108	Tech Suite 108 - Workshop	Univent	Metal	Black	Chipping	10	0.3	Negative
1	1	108	Tech Suite 108 - Workshop	Pipe	Metal	Tan	None	0	0.1	Negative
1	1	108	Tech Suite 108 - Workshop	W4	CMU	White	None	0	0.5	Negative
1	1	108	Tech Suite 108 - Workshop	Ceiling	Concrete	White	None	0	0.4	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Tech Suite 108 - PC Repair Shop	W1	CMU	Tan	None	0	0.2	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Doorframe	Metal	Black	Chipping	2	0.2	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	W2	CMU	Tan	None	0	0.4	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Conduit	Metal	White	Chipping	3	0.1	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Baseboard	CMU/Tile	Black	None	0	1	Positive
1	1	108A	Tech Suite 108 - PC Repair Shop	W3	CMU	Tan	None	0	0.5	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Electrical Panel	Metal	Tan	None	0	0.2	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	W4	CMU	Tan	None	0	0.4	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Pipe Cover	Metal	White	None	0	0.3	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Pipe Insulation	Fiberglass	White	Cracking	2	0.1	Negative



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	108A	Tech Suite 108 - PC Repair Shop	Column	Concrete	Tan	None	0	0.1	Negative
1	1	108A	Tech Suite 108 - PC Repair Shop	Ceiling	Concrete	White	None	0	0.4	Negative
1	1	108B	Tech Suite 108 - Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Tech Suite 108 - Closet	W1	CMU	Tan	None	0	0.3	Negative
1	1	108B	Tech Suite 108 - Closet	Doorframe	Metal	Black	None	0	0.5	Negative
1	1	108B	Tech Suite 108 - Closet	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	1	108B	Tech Suite 108 - Closet	W2	CMU	Tan	None	0	0.3	Negative
1	1	108B	Tech Suite 108 - Closet	Conduit	Metal	White	None	0	0.3	Negative
1	1	108B	Tech Suite 108 - Closet	W3	CMU	Tan	None	0	0.3	Negative
1	1	108B	Tech Suite 108 - Closet	Electrical Panel	Metal	Tan	None	0	0.3	Negative
1	1	108B	Tech Suite 108 - Closet	Radiator	Metal	Tan	None	0	0.2	Negative
1	1	108B	Tech Suite 108 - Closet	W4	CMU	Tan	None	0	0.4	Negative
1	1	108B	Tech Suite 108 - Closet	Pipe	Metal	White	None	0	0.3	Negative
1	1	108B	Tech Suite 108 - Closet	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	1	108B	Tech Suite 108 - Closet	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	108C	Tech Suite 108 - Classroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108C	Tech Suite 108 - Classroom	W1	CMU	White	Chipping	2	0.5	Negative
1	1	108C	Tech Suite 108 - Classroom	Doorframe	Metal	White	Chipping	3	0.2	Negative
1	1	108C	Tech Suite 108 - Classroom	Window Panels	Metal	White	None	0	0.2	Negative
1	1	108C	Tech Suite 108 - Classroom	W2	CMU	White	None	0	0.3	Negative
1	1	108C	Tech Suite 108 - Classroom	Pipe Cover	Metal	White	Chipping	2	0.4	Negative
1	1	108C	Tech Suite 108 - Classroom	Pipe Insulation	Fiberglass	White	Cracking	2	0.4	Negative
1	1	108C	Tech Suite 108 - Classroom	Column	Concrete	White	None	0	0.2	Negative
1	1	108C	Tech Suite 108 - Classroom	Baseboard	CMU/Tile	Black	None	0	0.7	Positive
1	1	108C	Tech Suite 108 - Classroom	Conduit	Metal	White	None	0	0.2	Negative
1	1	108C	Tech Suite 108 - Classroom	W3	CMU	White	Chipping	4	0.4	Negative
1	1	108C	Tech Suite 108 - Classroom	W4	CMU	White	Chipping	3	0.5	Negative
1	1	108C	Tech Suite 108 - Classroom	Radiator	Metal	Black	Chipping	8	0.2	Negative
1	1	108C	Tech Suite 108 - Classroom	Ceiling	Concrete	White	Chipping	4	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	108D	Walk-In Safe next to Elevator # 3	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108D	Walk-In Safe next to Elevator # 3	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108D	Walk-In Safe next to Elevator # 3	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108D	Walk-In Safe next to Elevator # 3	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108D	Walk-In Safe next to Elevator # 3	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108D	Walk-In Safe next to Elevator # 3	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108E	Room next to Walk-In Safe	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108E	Room next to Walk-In Safe	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108E	Room next to Walk-In Safe	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108E	Room next to Walk-In Safe	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108E	Room next to Walk-In Safe	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108E	Room next to Walk-In Safe	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Floor	Metal	Tan	Moisture Damage	10	0.3	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Doorframe	Metal	Red/Tan	Chipping	13	0.2	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Door	Metal	Red/Black	Chipping	18	0.2	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Baseboard	CMU/Tile	Black	Chipping	10	2	Positive
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Conduit	Metal	Tan	Chipping	3	0.2	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Riser	Metal	Black	Chipping	90	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Stringer	Metal	Black	Chipping	14	0.1	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Tread	Concrete	Black	Chipping	50	0.3	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	W3	Sheetrock	Tan	Flaking	4	0	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Doorframe	Metal	Black	Flaking	10	0.1	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Door	Metal	Tan	Chipping	8	0.1	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Radiator	Metal	Black	None	0	0.4	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Fire Pipe	Metal	Tan	Chipping	3	0.6	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Fire Pipe Frame	Metal	Tan	Chipping	4	0.1	Negative
1	1	S12	Stairwell # 6 adjacent to Wrestling Room	Ceiling	Concrete	White	Flaking	4	0	Negative
1	1	109	Wrestling Room next to Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Wrestling Room next to Gymnasium	W1	CMU	Yellow	None	0	0.4	Negative
1	1	109	Wrestling Room next to Gymnasium	Doorframe	Metal	Black	None	0	0.5	Negative
1	1	109	Wrestling Room next to Gymnasium	Closet Doorframe A	Metal	Black	None	0	0.5	Negative
1	1	109	Wrestling Room next to Gymnasium	Closet Doorframe B	Metal	Black	None	0	0.5	Negative
1	1	109	Wrestling Room next to Gymnasium	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	1	109	Wrestling Room next to Gymnasium	W2	CMU	Yellow	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	109	Wrestling Room next to Gymnasium	W3	CMU	Yellow	None	0	0.5	Negative
1	1	109	Wrestling Room next to Gymnasium	Closet Doorframe C	Metal	Black	None	0	0.3	Negative
1	1	109	Wrestling Room next to Gymnasium	Pipe Cover	Metal	Yellow	None	0	0.3	Negative
1	1	109	Wrestling Room next to Gymnasium	Pipe insulation	Fiberglass	Yellow	Cracking	8	0.1	Negative
1	1	109	Wrestling Room next to Gymnasium	Univent	Metal	Grey	Chipping	10	0.2	Negative
1	1	109	Wrestling Room next to Gymnasium	W4	CMU	Yellow	Chipping	8	0.5	Negative
1	1	109	Wrestling Room next to Gymnasium	Ceiling	Concrete	White	Flaking	320	0.3	Negative
1	1	110	Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Gymnasium	W1	CMU	White	Flaking	90	0.4	Negative
1	1	110	Gymnasium	Wall Strip(W1-4)	CMU	Red	None	0	0.4	Negative
1	1	110	Gymnasium	Wall Strip (W1-4)	CMU	Black	None	0	0.5	Negative
1	1	110	Gymnasium	W2	CMU	White	Flaking	40	0.3	Negative
1	1	110	Gymnasium	W3	CMU	White	Flaking	110	0.4	Negative
1	1	110	Gymnasium	W4	CMU	White	Flaking	90	0.3	Negative
1	1	110	Gymnasium	High beam	Metal	White	None	0	11.9	Positive
1	1	110	Gymnasium	Rafters	Metal	White	None	0	10.9	Positive
1	1	110	Gymnasium	Ladder	Metal	White	None	0	0.1	Negative
1	1	110	Gymnasium	Duct	Metal	White	None	0	0.1	Negative
1	1	110	Gymnasium	Ceiling	Wood	White	None	0	0	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	W1	CMU	White	Flaking	40	0.3	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	Doorframe	Metal	Black	None	0	0.5	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	Door	Metal	Red	Friction	20	0.1	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	W2	CMU	White	Flaking	20	0.3	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	Doorframe	Metal	Black	None	0	0	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	Baseboard	CMU/Tile	Black	None	0	1.2	Positive
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	W3	CMU	White	Flaking	18	0.4	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	Pipe Insulation	Fiberglass	White	Cracking	10	0	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	Doorframe	Metal	Grey	None	0	0	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	W4	CMU	White	Chipping	25	0.5	Negative
1	1	110F	Gymnasium Foyer next to Wrestling Room 109	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	110E	Gym Closet next to Boys Side Foyer	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110E	Gym Closet next to Boys Side Foyer	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110E	Gym Closet next to Boys Side Foyer	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110E	Gym Closet next to Boys Side Foyer	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110E	Gym Closet next to Boys Side Foyer	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110E	Gym Closet next to Boys Side Foyer	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Gym Boys Side Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Gym Boys Side Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Gym Boys Side Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Gym Boys Side Office	W3	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	110A	Gym Boys Side Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Gym Boys Side Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110L	Gymnasium Equipment Storeroom next to Boys side Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110L	Gymnasium Equipment Storeroom next to Boys side Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110L	Gymnasium Equipment Storeroom next to Boys side Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110L	Gymnasium Equipment Storeroom next to Boys side Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110L	Gymnasium Equipment Storeroom next to Boys side Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110L	Gymnasium Equipment Storeroom next to Boys side Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Gymnasium Equipment Storeroom next to Girls side Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Gymnasium Equipment Storeroom next to Girls side Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Gymnasium Equipment Storeroom next to Girls side Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Gymnasium Equipment Storeroom next to Girls side Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Gymnasium Equipment Storeroom next to Girls side Office	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	110B	Gymnasium Equipment Storeroom next to Girls side Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110D	Gymnasium Office on Girls Side	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110D	Gymnasium Office on Girls Side	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110D	Gymnasium Office on Girls Side	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110D	Gymnasium Office on Girls Side	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110D	Gymnasium Office on Girls Side	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110D	Gymnasium Office on Girls Side	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110C	Gymnasium Girls Side Foyer	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110C	Gymnasium Girls Side Foyer	W1	CMU	White	Chipping	10	0.5	Negative
1	1	110C	Gymnasium Girls Side Foyer	Door Frame	Metal	Black	Chipping	8	0.8	Positive
1	1	110C	Gymnasium Girls Side Foyer	Door	Metal	Red	Chipping	16	0.6	Negative
1	1	110C	Gymnasium Girls Side Foyer	W2	CMU	White	Flaking	12	0.4	Negative
1	1	110C	Gymnasium Girls Side Foyer	Baseboard	CMU/Tile	Black	None	0	0.9	Positive
1	1	110C	Gymnasium Girls Side Foyer	W3	CMU	White	Flaking	25	0.5	Negative
1	1	110C	Gymnasium Girls Side Foyer	Doorframe	Metal	Grey	Chipping	4	0.4	Negative
1	1	110C	Gymnasium Girls Side Foyer	door	Metal	Grey	Chipping	10	0.1	Negative
1	1	110C	Gymnasium Girls Side Foyer	Pipe Insulation	Fiberglass	White	Chipping	6	0.1	Negative
1	1	110C	Gymnasium Girls Side Foyer	W4	CMU	White	Flaking	8	0.5	Negative
1	1	110C	Gymnasium Girls Side Foyer	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	110M	Gym Closet next to Girls Side Foyer	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110M	Gym Closet next to Girls Side Foyer	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110M	Gym Closet next to Girls Side Foyer	W2	No Access	No Access	No Access	No Access	No Access	No Access



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	110M	Gym Closet next to Girls Side Foyer	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110M	Gym Closet next to Girls Side Foyer	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110M	Gym Closet next to Girls Side Foyer	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110K	Gym Equipment Storeroom next to Main Patio door	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110K	Gym Equipment Storeroom next to Main Patio door	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110K	Gym Equipment Storeroom next to Main Patio door	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110K	Gym Equipment Storeroom next to Main Patio door	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110K	Gym Equipment Storeroom next to Main Patio door	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110K	Gym Equipment Storeroom next to Main Patio door	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110G	Boys' Side Exit Foyer	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110G	Boys' Side Exit Foyer	W1	CMU	White	Flaking	190	0.2	Negative
1	1	110G	Boys' Side Exit Foyer	W2	CMU	White	Flaking	25	0.3	Negative
1	1	110G	Boys' Side Exit Foyer	W3	CMU	White	Flaking	20	0.4	Negative
1	1	110G	Boys' Side Exit Foyer	W4	CMU	White	Flaking	30	0.4	Negative
1	1	110G	Boys' Side Exit Foyer	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	1	110G1	Boys' Side Exit Foyer Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110G1	Boys' Side Exit Foyer Closet	W1	CMU	White	Flaking	10	0.2	Negative
1	1	110G1	Boys' Side Exit Foyer Closet	W2	CMU	White	Flaking	5	0.3	Negative
1	1	110G1	Boys' Side Exit Foyer Closet	W3	CMU	White	Flaking	9	0.4	Negative
1	1	110G1	Boys' Side Exit Foyer Closet	W4	CMU	White	Flaking	4	0.4	Negative
1	1	110G1	Boys' Side Exit Foyer Closet	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	1	S110G	Boys' Side Exit Foyer Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110G	Boys' Side Exit Foyer Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110G	Boys' Side Exit Foyer Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S110G	Boys' Side Exit Foyer Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110G	Boys' Side Exit Foyer Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110G	Boys' Side Exit Foyer Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110H	Girls' Side Exit Foyer	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110H	Girls' Side Exit Foyer	W1	CMU	White	Flaking	45	0.4	Negative
1	1	110H	Girls' Side Exit Foyer	W2	CMU	White	Flaking	90	0.5	Negative
1	1	110H	Girls' Side Exit Foyer	W3	CMU	White	Flaking	130	0.4	Negative
1	1	110H	Girls' Side Exit Foyer	W4	CMU	White	Flaking	120	0.3	Negative
1	1	110H	Girls' Side Exit Foyer	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
1	1	110H1	Girls' Side Exit Foyer Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110H1	Girls' Side Exit Foyer Closet	W1	CMU	White	Flaking	4	0.4	Negative
1	1	110H1	Girls' Side Exit Foyer Closet	W2	CMU	White	Flaking	8	0.5	Negative
1	1	110H1	Girls' Side Exit Foyer Closet	W3	CMU	White	Flaking	12	0.4	Negative
1	1	110H1	Girls' Side Exit Foyer Closet	W4	CMU	White	Flaking	10	0.3	Negative
1	1	110H1	Girls' Side Exit Foyer Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S110H	Girls' Side Exit Foyer Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110H	Girls' Side Exit Foyer Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110H	Girls' Side Exit Foyer Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110H	Girls' Side Exit Foyer Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110H	Girls' Side Exit Foyer Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S110H	Girls' Side Exit Foyer Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	120	Alumni Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	120	Alumni Room	W1	CMU	White	None	0	0	Negative
1	1	120	Alumni Room	Doorframe	Metal	Black	None	0	0.4	Negative
1	1	120	Alumni Room	Conduit	Metal	White	None	0	0.8	Positive
1	1	120	Alumni Room	Window frame	Metal	Black	None	0	0.1	Negative
1	1	120	Alumni Room	W2	Sheetrock	White	None	0	0.1	Negative
1	1	120	Alumni Room	W3	Sheetrock	White	None	0	0.2	Negative
1	1	120	Alumni Room	W4	Sheetrock	White	None	0	0.1	Negative
1	1	120	Alumni Room	Ceiling	Concrete	White	None	0	0.4	Negative
1	1	112	Counselor's Suite Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	112	Counselor's Suite Hallway	W1	CMU	Blue	None	0	0.3	Negative
1	1	112	Counselor's Suite Hallway	Doorframe	Metal	Black	None	0	0.5	Negative
1	1	112	Counselor's Suite Hallway	W2	CMU	Blue	None	0	0.4	Negative
1	1	112	Counselor's Suite Hallway	Duct	Metal	White	Chipping	2	0.1	Negative
1	1	112	Counselor's Suite Hallway	Baseboard	Tile	Black	None	0	0.9	Positive
1	1	112	Counselor's Suite Hallway	W3	CMU	Blue	None	0	0.3	Negative
1	1	112	Counselor's Suite Hallway	Upper Wall	Plaster	White	Chipping	5	0.2	Negative
1	1	112	Counselor's Suite Hallway	Pipe Insulation	Fiberglass	White	None	0	0	Negative
1	1	112	Counselor's Suite Hallway	W4	CMU	Blue	None	0	0.4	Negative
1	1	112	Counselor's Suite Hallway	Radiator	Metal	Blue	None	0	0.1	Negative
1	1	112	Counselor's Suite Hallway	Ceiling	Concrete	White	Chipping	5	0.5	Negative
1	1	112A	Counselor's Suite Office A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112A	Counselor's Suite Office A	W1	Plaster	Yellow	Cracking	2	0.1	Negative
1	1	112A	Counselor's Suite Office A	Doorframe	Metal	Black	None	0	0.1	Negative
1	1	112A	Counselor's Suite Office A	Window Frame	Metal	Yellow	Chipping	3	0.8	Positive
1	1	112A	Counselor's Suite Office A	W2	Plaster	Yellow	None	0	0.1	Negative
1	1	112A	Counselor's Suite Office A	W3	CMU	Yellow	None	0	0.5	Negative
1	1	112A	Counselor's Suite Office A	Pipe Cover	Metal	Yellow	None	0	0.4	Negative
1	1	112A	Counselor's Suite Office A	Pipe Insulation	Fiberglass	Yellow	None	0	0.2	Negative
1	1	112A	Counselor's Suite Office A	Column	Concrete	Yellow	Chipping	1	0.2	Negative
1	1	112A	Counselor's Suite Office A	Conduit	Metal	Yellow	None	0	0.2	Negative
1	1	112A	Counselor's Suite Office A	W4	CMU	Yellow	None	0	0.4	Negative
1	1	112A	Counselor's Suite Office A	Radiator	Metal	Yellow	None	0	0.2	Negative
1	1	112A	Counselor's Suite Office A	Ceiling	Concrete	White	Cracking	2	0.5	Negative
1	1	112B	Counselor's Suite Office B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112B	Counselor's Suite Office B	W1	Plaster	Yellow	None	0	0.1	Negative
1	1	112B	Counselor's Suite Office B	W2	Plaster	Yellow	None	0	0.1	Negative
1	1	112B	Counselor's Suite Office B	Window Frame	Metal	Yellow	Chipping	3	0.8	Positive
1	1	112B	Counselor's Suite Office B	W3	CMU	Yellow	None	0	0.5	Negative
1	1	112B	Counselor's Suite Office B	Pipe Cover	Metal	Yellow	Chipping	2	0.4	Negative
1	1	112B	Counselor's Suite Office B	Pipe Insulation	Fiberglass	Yellow	Chipping	4	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	112B	Counselor's Suite Office B	Column	Concrete	Yellow	Chipping	1	0.2	Negative
1	1	112B	Counselor's Suite Office B	W4	CMU	Yellow	None	0	0.4	Negative
1	1	112B	Counselor's Suite Office B	Ceiling	Concrete	White	Cracking	2	0.5	Negative
1	1	112C	Counselor's Suite Office C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112C	Counselor's Suite Office C	W1	Plaster	Yellow	None	0	0.1	Negative
1	1	112C	Counselor's Suite Office C	W2	Plaster	Yellow	None	0	0.1	Negative
1	1	112C	Counselor's Suite Office C	W3	CMU	Yellow	None	0	0.5	Negative
1	1	112C	Counselor's Suite Office C	W4	CMU	Yellow	None	0	0.4	Negative
1	1	112C	Counselor's Suite Office C	Ceiling	Concrete	White	Cracking	2	0.5	Negative
1	1	112D	Counselor's Suite Office D	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112D	Counselor's Suite Office D	W1	Plaster	Yellow	None	0	0.1	Negative
1	1	112D	Counselor's Suite Office D	W2	Plaster	Yellow	None	0	0.1	Negative
1	1	112D	Counselor's Suite Office D	W3	CMU	Yellow	None	0	0.5	Negative
1	1	112D	Counselor's Suite Office D	W4	CMU	Yellow	None	0	0.4	Negative
1	1	112D	Counselor's Suite Office D	Ceiling	Concrete	White	Cracking	2	0.5	Negative
1	1	112E	Counselor's Suite Office E	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112E	Counselor's Suite Office E	W1	Plaster	Yellow	None	0	0.1	Negative
1	1	112E	Counselor's Suite Office E	W2	Plaster	Yellow	None	0	0.1	Negative
1	1	112E	Counselor's Suite Office E	W3	CMU	Yellow	None	0	0.5	Negative
1	1	112E	Counselor's Suite Office E	W4	CMU	Yellow	None	0	0.4	Negative
1	1	112E	Counselor's Suite Office E	Ceiling	Concrete	White	Cracking	2	0.5	Negative
1	1	112F	Counselor's Suite Server Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112F	Counselor's Suite Server Room	W1	Plaster	Yellow	None	0	0.1	Negative
1	1	112F	Counselor's Suite Server Room	W2	Plaster	Yellow	None	0	0.1	Negative
1	1	112F	Counselor's Suite Server Room	W3	CMU	Yellow	None	0	0.5	Negative
1	1	112F	Counselor's Suite Server Room	W4	CMU	Yellow	None	0	0.4	Negative
1	1	112F	Counselor's Suite Server Room	Ceiling	Concrete	White	Cracking	2	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	W1	CMU	White	Flaking	2	0.4	Negative
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	Door Frame	Metal	Black	None	0	0.2	Negative
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.1	Positive
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	W2	CMU	White	Flaking	7	0.3	Negative
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	W4	CMU	White	Flaking	11	0.4	Negative
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	Elevator Door	Metal	Black	None	0	0.1	Negative
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	Elevator Doorframe	Metal	Black	None	0	0.1	Negative
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	Electrical Panel	Metal	Black	Flaking	1	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	H13	Hallway from Community Coordinator's Office to Wrestling Room	Ceiling	Concrete	White	Flaking	6	0.2	Negative
1	1	H13A	Main Entrance Lobby	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Main Entrance Lobby	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Main Entrance Lobby	Door Frame Panel	Metal	Black	None	0	0.1	Negative
1	1	H13A	Main Entrance Lobby	Door Frame	Metal	Black	Chipping	20	0.1	Negative
1	1	H13A	Main Entrance Lobby	Door	Metal	Red	Chipping	25	0.1	Negative
1	1	H13A	Main Entrance Lobby	W2	Marble	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Main Entrance Lobby	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Main Entrance Lobby	Door Frame Panel	Metal	Black	None	0	0.1	Negative
1	1	H13A	Main Entrance Lobby	Door Frame	Metal	Black	Chipping	20	0.1	Negative
1	1	H13A	Main Entrance Lobby	Door	Metal	Red	Chipping	25	0.1	Negative
1	1	H13A	Main Entrance Lobby	W4	Marble	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Main Entrance Lobby	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A1	Main Entrance Vestibule	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A1	Main Entrance Vestibule	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A1	Main Entrance Vestibule	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A1	Main Entrance Vestibule	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A1	Main Entrance Vestibule	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A1	Main Entrance Vestibule	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Main Office - Mail Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Main Office - Mail Room	W1	CMU	Tan	None	0	0.4	Negative
1	1	111	Main Office - Mail Room	Doorframe	Metal	Black	Chipping	3	0.3	Negative
1	1	111	Main Office - Mail Room	Door	Wood	Tan	Chipping	6	0.1	Negative
1	1	111	Main Office - Mail Room	W2	CMU	Tan	Flaking	2	0.4	Negative
1	1	111	Main Office - Mail Room	W2-W3	Drywall	Tan	None	0	0.1	Negative
1	1	111	Main Office - Mail Room	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	1	111	Main Office - Mail Room	W3	CMU	Tan	Moisture Damage	30	0.5	Negative
1	1	111	Main Office - Mail Room	W4	CMU	Tan	Flaking	5	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	111	Main Office - Mail Room	Radiator	Metal	White	None	0	0.2	Negative
1	1	111	Main Office - Mail Room	Pipe	Metal	White	Flaking	1	0.3	Negative
1	1	111	Main Office - Mail Room	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	1	111	Main Office - Mail Room	Expansion joint cover	Metal	White	Flaking	4	0.6	Negative
1	1	111	Main Office - Mail Room	Duct	Metal	White	Flaking	5	0.2	Negative
1	1	111	Main Office - Mail Room	Ceiling	Concrete	White	Flaking	19	0.3	Negative
1	1	113	Main Office	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	1	113	Main Office	W1	CMU	White	None	0	0.4	Negative
1	1	113	Main Office	Doorframe	Metal	Red	Chipping	10	0.2	Negative
1	1	113	Main Office	Window frame	Metal	Red	Chipping	18	0.1	Negative
1	1	113	Main Office	W2	CMU	White	None	0	0.4	Negative
1	1	113	Main Office	Baseboard	CMU/Tile	Black	None	0	1.3	Positive
1	1	113	Main Office	Conduit	Metal	White	None	0	0.5	Negative
1	1	113	Main Office	W3	CMU	White	None	0	0.5	Negative
1	1	113	Main Office	Pipe Cover	Metal	White	Chipping	8	0.3	Negative
1	1	113	Main Office	Univent	Metal	Grey	Chipping	8	0.2	Negative
1	1	113	Main Office	Pipe Insulation	Fiberglass	White	Flaking	20	0.1	Negative
1	1	113	Main Office	Column	Concrete	White	None	0	0.2	Negative
1	1	113	Main Office	Pipe	Metal	White	None	0	0.2	Negative
1	1	113	Main Office	W4	CMU	White	None	0	0.5	Negative
1	1	113	Main Office	Ceiling	Concrete	White	Flaking	56	0.3	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113B	Main Office - Storeroom next to Mail Room	W1	CMU	White	Flaking	2	0.5	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	Doorframe	Metal	Black	None	0	0.5	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	Baseboard	CMU/Tile	Black	None	0	1.7	Positive
1	1	113B	Main Office - Storeroom next to Mail Room	W2	CMU	White	None	0	0.3	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	113B	Main Office - Storeroom next to Mail Room	W3	CMU	White	None	0	0.3	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	W4	CMU	White	None	0	0.4	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	Conduit	Metal	White	None	0	0.5	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	Windowframe	Metal	Tan	None	0	0	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	Closet A Doorframe	Metal	Black	None	0	0.2	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	Closet B Doorframe	Metal	Black	None	0	0.2	Negative
1	1	113B	Main Office - Storeroom next to Mail Room	Ceiling	Concrete	White	Flaking	1	0.2	Negative
1	1	113A	Main Office - Roster Office	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	1	113A	Main Office - Roster Office	W1	CMU	White	None	0	0.4	Negative
1	1	113A	Main Office - Roster Office	Doorframe	Metal	Black	None	0	0.4	Negative
1	1	113A	Main Office - Roster Office	Radiator	Metal	White	None	0	0.2	Negative
1	1	113A	Main Office - Roster Office	Conduit	Metal	White	None	0	0.6	Negative
1	1	113A	Main Office - Roster Office	W2	CMU	White	None	0	0.2	Negative
1	1	113A	Main Office - Roster Office	Panel	Metal	White	None	0	0.3	Negative
1	1	113A	Main Office - Roster Office	Baseboard	CMU/Tile	Black	None	0	1.1	Positive
1	1	113A	Main Office - Roster Office	W3	CMU	White	None	0	0.5	Negative
1	1	113A	Main Office - Roster Office	Doorframe	Metal	Black	None	0	0.3	Negative
1	1	113A	Main Office - Roster Office	W4	CMU	White	None	0	0.5	Negative
1	1	113A	Main Office - Roster Office	Windowframe	Wood	White	None	0	0.1	Negative
1	1	113A	Main Office - Roster Office	Pipe	Metal	White	None	0	0.6	Negative
1	1	113A	Main Office - Roster Office	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	1	113A	Main Office - Roster Office	Window Panel	Transite	White	None	0	0.1	Negative
1	1	113A	Main Office - Roster Office	Ceiling	Concrete	White	None	0	0.4	Negative
1	1	113C	Main Office - Principal's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	113C	Main Office - Principal's Office	W1	CMU	White	Flaking	2	0.5	Negative
1	1	113C	Main Office - Principal's Office	Door Frame	Metal	Black	Chipping	6	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	113C	Main Office - Principal's Office	Conduit	Metal	White	None	0	0.7	Positive
1	1	113C	Main Office - Principal's Office	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.2	Positive
1	1	113C	Main Office - Principal's Office	W2	CMU	Blue	Flaking	2	0.4	Negative
1	1	113C	Main Office - Principal's Office	Radiator	Metal	Blue	None	0	0.2	Negative
1	1	113C	Main Office - Principal's Office	Pipe Cover	Metal	Blue	None	0	0.2	Negative
1	1	113C	Main Office - Principal's Office	W3	CMU	Blue	None	0	0.4	Negative
1	1	113C	Main Office - Principal's Office	W4	CMU	Blue	None	0	0.5	Negative
1	1	113C	Main Office - Principal's Office	Ceiling	Concrete	White	Flaking	10	0.3	Negative
1	1	113H	Principal's Office Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	113H	Principal's Office Restroom	W1	CMU	Tan	None	0	0.3	Negative
1	1	113H	Principal's Office Restroom	Door Frame	Metal	Black	Chipping	3	0.9	Positive
1	1	113H	Principal's Office Restroom	W2	CMU	Tan	None	0	0.4	Negative
1	1	113H	Principal's Office Restroom	W3	CMU	Tan	None	0	0.4	Negative
1	1	113H	Principal's Office Restroom	W4	CMU	Tan	None	0	0.4	Negative
1	1	113H	Principal's Office Restroom	Ceiling	Concrete	White	Flaking	6	0.3	Negative
1	1	113H	Principal's Office Restroom	Pipe (C)	Metal	White	None	0	0.3	Negative
1	1	113I	Principal's Office Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	113I	Principal's Office Closet	W1	CMU	Grey	None	0	0.4	Negative
1	1	113I	Principal's Office Closet	Door Frame	Metal	Black	None	0	1	Positive
1	1	113I	Principal's Office Closet	W2	CMU	Grey	None	0	0.4	Negative
1	1	113I	Principal's Office Closet	W3	CMU	Grey	None	0	0.5	Negative
1	1	113I	Principal's Office Closet	Shelf	Wood	Grey	None	0	0.2	Negative
1	1	113I	Principal's Office Closet	W4	CMU	Grey	None	0	0.5	Negative
1	1	113I	Principal's Office Closet	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	113D	Main Office - Vice Principal's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	113D	Main Office - Vice Principal's Office	W1	CMU	Tan	Flaking	4	0.3	Negative
1	1	113D	Main Office - Vice Principal's Office	Door Frame	Metal	Black	None	0	0.2	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 7/11 - 8/31/2022</b>							
			<b>Inspector Name and Certificate Number: Charles Rhodes 003542</b>		<b>South Philadelphia High School</b>					
			<b>Inspection Company: BATTA</b>		<b>2101 S Broad St, Philadelphia, PA 19148</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	113D	Main Office - Vice Principal's Office	Duct	Metal	White	None	0	0.2	Negative
1	1	113D	Main Office - Vice Principal's Office	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.2	Positive
1	1	113D	Main Office - Vice Principal's Office	W2	CMU	Tan	Flaking	19	0.5	Negative
1	1	113D	Main Office - Vice Principal's Office	Column	Concrete	White	Flaking	8	0.2	Negative
1	1	113D	Main Office - Vice Principal's Office	W3	CMU	Tan	Flaking	3	0.4	Negative
1	1	113D	Main Office - Vice Principal's Office	Pipe Cover	Metal	Tan	Flaking	4	0.5	Negative
1	1	113D	Main Office - Vice Principal's Office	Radiator	Metal	Tan	Flaking	4	0.2	Negative
1	1	113D	Main Office - Vice Principal's Office	W4	CMU	Tan	Flaking	1	0.4	Negative
1	1	113D	Main Office - Vice Principal's Office	Door Frame	Metal	Black	None	0	0.2	Negative
1	1	113D	Main Office - Vice Principal's Office	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	113E	Main Office - Attendance Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	113E	Main Office - Attendance Office	Floor	Metal	Grey	Chipping	7	0.2	Negative
1	1	113E	Main Office - Attendance Office	W1	CMU	Tan	Flaking	6	0.5	Negative
1	1	113E	Main Office - Attendance Office	Door Frame	Metal	Black	Chipping	6	0.2	Negative
1	1	113E	Main Office - Attendance Office	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	1	113E	Main Office - Attendance Office	W2	CMU	Tan	None	0	0.5	Negative
1	1	113E	Main Office - Attendance Office	Door Frame	Metal	Black	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	113E	Main Office - Attendance Office	Conduit	Metal	Tan	None	0	0.7	Positive
1	1	113E	Main Office - Attendance Office	W3	CMU	Tan	Flaking	1	0.4	Negative
1	1	113E	Main Office - Attendance Office	Column	Concrete	White	None	0	0.2	Negative
1	1	113E	Main Office - Attendance Office	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	113E	Main Office - Attendance Office	Pipe Cover	Metal	White	None	0	0.1	Negative
1	1	113E	Main Office - Attendance Office	W4	CMU	Tan	None	0	0.3	Negative
1	1	113E	Main Office - Attendance Office	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	113G	Main Office - Staff Restroom across from Mail Room	Floor	Tile	N/A	N/a	N/A	N/A	N/A
1	1	113G	Main Office - Staff Restroom across from Mail Room	W1	CMU	Blue	None	0	0.5	Negative
1	1	113G	Main Office - Staff Restroom across from Mail Room	Doorframe	Metal	Black	None	0	0.2	Negative
1	1	113G	Main Office - Staff Restroom across from Mail Room	W2	CMU	Blue	None	0	0.4	Negative
1	1	113G	Main Office - Staff Restroom across from Mail Room	W3	CMU	Blue	Chipping	1	0.4	Negative
1	1	113G	Main Office - Staff Restroom across from Mail Room	W4	CMU	Blue	None	0	0.4	Negative
1	1	113G	Main Office - Staff Restroom across from Mail Room	Pipe Insulation	Fiberglass	White	None	0	0.3	Negative
1	1	113G	Main Office - Staff Restroom across from Mail Room	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	H113	Main Office - Hallway	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H113	Main Office - Hallway	W1	N/A	N/A	N/a	N/A	N/a	N/A
1	1	H113	Main Office - Hallway	W2	CMU	White	None	0	0.5	Negative
1	1	H113	Main Office - Hallway	W3	CMU	White	None	0	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	H113	Main Office - Hallway	Baseboard	CMU/Tile	Black	None	0	1.6	Positive
1	1	H113	Main Office - Hallway	W4	CMU	White	None	0	0.3	Negative
1	1	H113	Main Office - Hallway	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	1	H113	Main Office - Hallway	Duct	Metal	White	None	0	0.3	Negative
1	1	H113	Main Office - Hallway	Pipe	Metal	White	None	0	0.3	Negative
1	1	H113	Main Office - Hallway	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	113F	Room inside Main Office next to Hallway to Nurse's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113F	Room inside Main Office next to Hallway to Nurse's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113F	Room inside Main Office next to Hallway to Nurse's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113F	Room inside Main Office next to Hallway to Nurse's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113F	Room inside Main Office next to Hallway to Nurse's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113F	Room inside Main Office next to Hallway to Nurse's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114D/114F	Hallway between Main and Nurse's Offices	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114D/114F	Hallway between Main and Nurse's Offices	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114D/114F	Hallway between Main and Nurse's Offices	Conduit	Metal	White	None	0	0.5	Negative
1	1	114D/114F	Hallway between Main and Nurse's Offices	Doorframe	Metal	Black	None	0	0.5	Negative
1	1	114D/114F	Hallway between Main and Nurse's Offices	W2	CMU	White	None	0	0.2	Negative
1	1	114D/114F	Hallway between Main and Nurse's Offices	W3	CMU	White	None	0	0.5	Negative
1	1	114D/114F	Hallway between Main and Nurse's Offices	Baseboard	CMU/Tile	Black	None	0	1.7	Positive
1	1	114D/114F	Hallway between Main and Nurse's Offices	Duct	Metal	White	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	114D/114F	Hallway between Main and Nurse's Offices	W4	CMU	White	None	0	0.4	Negative
1	1	114D/114F	Hallway between Main and Nurse's Offices	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	114B	Storeroom between Main and Nurse's Offices	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114B	Storeroom between Main and Nurse's Offices	W1	CMU	Bare	N/A	N/A	N/A	N/A
1	1	114B	Storeroom between Main and Nurse's Offices	Doorframe	Metal	Black	None	0	0.3	Negative
1	1	114B	Storeroom between Main and Nurse's Offices	Duct	Metal	Grey	None	0	0.1	Negative
1	1	114B	Storeroom between Main and Nurse's Offices	Radiator	Metal	Grey	None	0	0.2	Negative
1	1	114B	Storeroom between Main and Nurse's Offices	W2	CMU	Bare	N/A	N/A	N/A	N/A
1	1	114B	Storeroom between Main and Nurse's Offices	W3	CMU	bare	N/A	N/A	N/A	N/A
1	1	114B	Storeroom between Main and Nurse's Offices	W4	CMU	bare	N/A	N/A	N/A	N/A
1	1	114B	Storeroom between Main and Nurse's Offices	Ceiling	Concrete	Bare	N/A	N/A	N/A	N/A
1	1	114C	Staff Restroom between Main and Nurse's Offices	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114C	Staff Restroom between Main and Nurse's Offices	W1	CMU	White	None	0	0.4	Negative
1	1	114C	Staff Restroom between Main and Nurse's Offices	Doorframe	Metal	Black	None	0	0	Negative
1	1	114C	Staff Restroom between Main and Nurse's Offices	Baseboard	Tile	Black	None	0	1	Positive
1	1	114C	Staff Restroom between Main and Nurse's Offices	Stall	Wood	Yellow	None	0	0.1	Negative
1	1	114C	Staff Restroom between Main and Nurse's Offices	W2	CMU	White	None	0	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	114C	Staff Restroom between Main and Nurse's Offices	Duct	Metal	White	Flaking	7	0.2	Negative
1	1	114C	Staff Restroom between Main and Nurse's Offices	Pipe	Metal	White	Flaking	8	0.4	Negative
1	1	114C	Staff Restroom between Main and Nurse's Offices	W3	CMU	White	None	0	0.4	Negative
1	1	114C	Staff Restroom between Main and Nurse's Offices	W4	CMU	White	None	0	0.5	Negative
1	1	114C	Staff Restroom between Main and Nurse's Offices	Ceiling	Concrete	White	Flaking	1	0.2	Negative
1	1	114E	Office between Main and Nurse's Offices	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	1	114E	Office between Main and Nurse's Offices	W1	CMU	Blue	None	0	0.5	Negative
1	1	114E	Office between Main and Nurse's Offices	Doorframe	Metal	Black	None	0	0.3	Negative
1	1	114E	Office between Main and Nurse's Offices	Conduit	Metal	Blue	None	0	0.7	Positive
1	1	114E	Office between Main and Nurse's Offices	Baseboard	CMU/Tile	Black	None	0	1.7	Positive
1	1	114E	Office between Main and Nurse's Offices	W2	CMU	Blue	None	0	0	Negative
1	1	114E	Office between Main and Nurse's Offices	Radiator	Metal	White	Flaking	3	0.2	Negative
1	1	114E	Office between Main and Nurse's Offices	W3	CMU	Blue	None	0	0.4	Negative
1	1	114E	Office between Main and Nurse's Offices	W4	CMU	Blue	None	0	0.5	Negative
1	1	114E	Office between Main and Nurse's Offices	Ceiling	Concrete	White	Flaking	12	0.3	Negative
1	1	114A	Staff Lounge next to Nurse's Office	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	1	114A	Staff Lounge next to Nurse's Office	W1	CMU	White	None	0	0.5	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	114A	Staff Lounge next to Nurse's Office	Door Frame	Metal	Black	None	0	0.9	Positive
1	1	114A	Staff Lounge next to Nurse's Office	Baseboard	CMU/Tile	Black	None	0	1.4	Positive
1	1	114A	Staff Lounge next to Nurse's Office	W2	CMU	White	None	0	0.5	Negative
1	1	114A	Staff Lounge next to Nurse's Office	Pipe Cover	Metal	White	Chipping	1	0.3	Negative
1	1	114A	Staff Lounge next to Nurse's Office	Pipe Insulation	Fiberglass	White	Cracking	2	0.1	Negative
1	1	114A	Staff Lounge next to Nurse's Office	Column	Concrete	White	None	0	0.3	Negative
1	1	114A	Staff Lounge next to Nurse's Office	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	114A	Staff Lounge next to Nurse's Office	W3	CMU	White	None	0	0.4	Negative
1	1	114A	Staff Lounge next to Nurse's Office	Closet Doorframe	Metal	Black	None	0	0.8	Positive
1	1	114A	Staff Lounge next to Nurse's Office	Closet Shelf	Wood	White	None	0	0.2	Negative
1	1	114A	Staff Lounge next to Nurse's Office	W4	CMU	White	None	0	0.3	Negative
1	1	114A	Staff Lounge next to Nurse's Office	Ceiling	Ceiling Tile	Bare	N/A	N/A	N/A	N/A
1	1	114A1	Staff Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A1	Staff Lounge Restroom	W1	CMU	White	Flaking	4	0.2	Negative
1	1	114A1	Staff Lounge Restroom	Door Frame	Metal	Black	None	0	1	Positive
1	1	114A1	Staff Lounge Restroom	W2	CMU	White	None	0	0.2	Negative
1	1	114A1	Staff Lounge Restroom	W3	CMU	White	Flaking	4	0.2	Negative
1	1	114A1	Staff Lounge Restroom	Pipe Insulation	Fiberglass	White	Chipping	3	0	Negative
1	1	114A1	Staff Lounge Restroom	Radiator	Metal	White	Chipping	2	0.2	Negative
1	1	114A1	Staff Lounge Restroom	W4	Tile	Bare	N/A	N/A	N/A	N/A
1	1	114A1	Staff Lounge Restroom	Ceiling	Concrete	White	Flaking	4	0.2	Negative
1	1	115	Nurse's Office	Floor	Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	115	Nurse's Office	W1	CMU	Peach	Cracking	5	0.4	Negative
1	1	115	Nurse's Office	Doorframe	Metal	Tan	Chipping	8	0.6	Negative
1	1	115	Nurse's Office	Door	Wood	Red	Chipping	6	0	Negative
1	1	115	Nurse's Office	Conduit	Metal	White	None	0	0.5	Negative
1	1	115	Nurse's Office	W2	CMU	Peach	None	0	0	Negative
1	1	115	Nurse's Office	Baseboard	CMU/Tile	Black	None	0	1.5	Positive
1	1	115	Nurse's Office	Closet Doorframe	Metal	Black	Chipping	2	0.6	Negative
1	1	115	Nurse's Office	Closet Wall 2-4	CMU	White	None	0	0.4	Negative
1	1	115	Nurse's Office	Closet Shelf	Wood	White	None	0	0.1	Negative
1	1	115	Nurse's Office	Radiator	Metal	Brown	Chipping	15	0.1	Negative
1	1	115	Nurse's Office	Pipe Insulation	Fiberglass	White	Cracking	6	0.1	Negative
1	1	115	Nurse's Office	Column	Concrete	Peach	Chipping	4	0.3	Negative
1	1	115	Nurse's Office	W3	CMU	Peach	Chipping	4	0	Negative
1	1	115	Nurse's Office	Pipe Cover	Metal	White	Chipping	2	0.3	Negative
1	1	115	Nurse's Office	W4	CMU	Peach	Cracking	6	0.5	Negative
1	1	115	Nurse's Office	Ceiling	Concrete	White	Chipping	20	0.3	Negative
1	1	115A	Nurse's Office Restroom	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	1	115A	Nurse's Office Restroom	W1	CMU	Tan	None	0	0.4	Negative
1	1	115A	Nurse's Office Restroom	Door Frame	Metal	Black	Chipping	2	1.1	Positive
1	1	115A	Nurse's Office Restroom	Pipe Cover	Metal	White	Chipping	4	0.1	Negative
1	1	115A	Nurse's Office Restroom	Pipe Insulation	Fiberglass	White	Chipping	6	0.1	Negative
1	1	115A	Nurse's Office Restroom	Baseboard	Tile	Black	None	0	1.5	Positive
1	1	115A	Nurse's Office Restroom	W2	CMU	Tan	None	0	0.5	Negative
1	1	115A	Nurse's Office Restroom	Column	Concrete	Tan	Flaking	4	0.2	Negative
1	1	115A	Nurse's Office Restroom	Radiator	Metal	Tan	Chipping	5	0.1	Negative
1	1	115A	Nurse's Office Restroom	W3	CMU	Tan	None	0	0.6	Negative
1	1	115A	Nurse's Office Restroom	Pipe	Metal	White	Flaking	8	0.3	Negative
1	1	115A	Nurse's Office Restroom	W4	CMU	Tan	None	0	0.5	Negative
1	1	115A	Nurse's Office Restroom	Ceiling	Concrete	White	Flaking	9	0.2	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	115B	Examination Room - Male adjacent to Restroom	W1	CMU	White	None	0	0.6	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Coat Rack	Wood	Tan	None	0	0.2	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Doorframe	Metal	Black	None	0	0.5	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	W2	CMU	White	None	0	0.5	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Baseboard	CMU/Tile	Black	None	0	1.3	Positive
1	1	115B	Examination Room - Male adjacent to Restroom	W3	CMU	White	Flaking	1	0	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Radiator	Metal	White	Flaking	5	0	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Pipe Cover	Metal	White	Chipping	1	0.1	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Pipe Insulation	Fiberglass	White	Flaking	4	0.1	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Pipe	Metal	White	Flaking	10	0.2	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Column	Concrete	White	Flaking	2	0.2	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	W4	CMU	White	None	0	0.5	Negative
1	1	115B	Examination Room - Male adjacent to Restroom	Ceiling	Concrete	White	Flaking	10	0.2	Negative
1	1	115C	Nurse's Office Storage Room	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	1	115C	Nurse's Office Storage Room	W1	CMU	Yellow	None	0	0.6	Negative
1	1	115C	Nurse's Office Storage Room	Baseboard	CMU/Tile	Black	None	0	1.5	Positive
1	1	115C	Nurse's Office Storage Room	Door Frame	Metal	Black	Chipping	3	0.9	Positive
1	1	115C	Nurse's Office Storage Room	Column	Concrete	Yellow	Flaking	4	0.3	Negative
1	1	115C	Nurse's Office Storage Room	W2	CMU	Yellow	None	0	0.4	Negative
1	1	115C	Nurse's Office Storage Room	Pipe Cover	Metal	Yellow	Chipping	3	0.3	Negative
1	1	115C	Nurse's Office Storage Room	Pipe Insulation	Fiberglass	Yellow	Chipping	2	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	115C	Nurse's Office Storage Room	radiator	Metal	Yellow	Flaking	4	0.1	Negative
1	1	115C	Nurse's Office Storage Room	W3	CMU	Yellow	Flaking	6	0.4	Negative
1	1	115C	Nurse's Office Storage Room	Pipe	Metal	White	Flaking	8	0.5	Negative
1	1	115C	Nurse's Office Storage Room	W4	CMU	Yellow	Flaking	1	0.4	Negative
1	1	115C	Nurse's Office Storage Room	Ceiling	Concrete	White	Flaking	5	0.3	Negative
1	1	115D	Nurse's Office Examination Room - Female	Floor	Tile	N/A	N/A	N/A	N/A	N/A
1	1	115D	Nurse's Office Examination Room - Female	W1	CMU	Pink	None	0	0.3	Negative
1	1	115D	Nurse's Office Examination Room - Female	Doorframe	Metal	Black	None	0	0.5	Negative
1	1	115D	Nurse's Office Examination Room - Female	Conduit	Metal	Pink	None	0	0.9	Positive
1	1	115D	Nurse's Office Examination Room - Female	Closet Door Frame	Metal	Black	None	0	1.1	Positive
1	1	115D	Nurse's Office Examination Room - Female	Closet Shelf	Wood	White	None	0	0.2	Negative
1	1	115D	Nurse's Office Examination Room - Female	W2	CMU	Pink	Cracking	4	0.5	Negative
1	1	115D	Nurse's Office Examination Room - Female	Baseboard	CMU/Tile	Black	None	0	1.2	Positive
1	1	115D	Nurse's Office Examination Room - Female	Pipe Cover	Metal	Pink	None	0	0	Negative
1	1	115D	Nurse's Office Examination Room - Female	Pipe Insulation	Fiberglass	Pink	None	0	0.2	Negative
1	1	115D	Nurse's Office Examination Room - Female	Column	Concrete	Pink	None	0	0.1	Negative
1	1	115D	Nurse's Office Examination Room - Female	W3	CMU	Pink	Flaking	4	0.5	Negative
1	1	115D	Nurse's Office Examination Room - Female	Radiator	Metal	Pink	Chipping	2	0.1	Negative
1	1	115D	Nurse's Office Examination Room - Female	W4	CMU	Pink	None	0	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	115D	Nurse's Office Examination Room - Female	Ceiling	Concrete	White	Flaking	14	0.3	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	W1	ceramic	N/A	N/A	N/A	N/A	N/A
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Doorframe	Metal	Tan	Chipping	4	0.1	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Door	Metal	Grey	Friction	5	0	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	W2	ceramic	N/A	N/A	N/A	N/A	N/A
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Door/Doorframe	Metal	Tan	None	0	0.3	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Fire Pipe	Metal	Tan	Chipping	2	0.5	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Conduit	Metal	Tan	Chipping	3	0.4	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	W3	ceramic	N/A	N/A	N/A	N/A	N/A
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Riser	Metal	Tan	None	0	0.1	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Stringer	Metal	Tan	None	0	0.1	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	baseboard	Metal	Tan	None	0	0.1	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Stair Pan	Metal	tan	None	0	0.6	Negative
1	1	S13	Stairwell # 2 next to Nurse's Office Suite	Ceiling	Concrete	White	None	0	0.3	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	W2	CMU	Tan	Flaking	8	0.4	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Exp Joint Cover	Metal	White	None	0	0.2	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Baseboard (W2, 4)	CMU/Tile	Black	None	0	1.3	Positive
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Door Frame	Metal	Red	None	0	0.4	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Door	Metal	Black	None	0	0.2	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	W4	CMU	Tan	Flaking	4	0.4	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Window Frame	Metal	Red	Flaking	2	0.2	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Door Frame	Metal	Red	Flaking	2	0.2	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Electrical Panel	Metal	Black	Chipping	1	0.3	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Radiator	Metal	Tan	Chipping	2	0.1	Negative
1	1	H12	Hallway from Main Office Mail Room to Nurse's Office	Ceiling	Concrete	White	Flaking	8	0.3	Negative
1	1	117G	NTA Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117G	NTA Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117G	NTA Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117G	NTA Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117G	NTA Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117G	NTA Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117C	Auditorium Entrance Ramp across from Main Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	1	117C	Auditorium Entrance Ramp across from Main Office	W1	CMU	White	None	0	0.5	Negative
1	1	117C	Auditorium Entrance Ramp across from Main Office	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.3	Positive
1	1	117C	Auditorium Entrance Ramp across from Main Office	W2	CMU	White	None	0	0.5	Negative
1	1	117C	Auditorium Entrance Ramp across from Main Office	W3	CMU	White	None	0	0.5	Negative
1	1	117C	Auditorium Entrance Ramp across from Main Office	Door Frame	Metal	Grey	None	0	0.1	Negative
1	1	117C	Auditorium Entrance Ramp across from Main Office	Door	Wood	Red	None	0	0.1	Negative
1	1	117C	Auditorium Entrance Ramp across from Main Office	W4	CMU	White	None	0	0.4	Negative
1	1	117C	Auditorium Entrance Ramp across from Main Office	Ceiling	Concrete	White	None	0	0.2	Negative
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	W1	CMU	White	None	0	0.4	Negative
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	Baseboard (W1-4)	CMU/Tile	Black	None	0	1.2	Positive
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	W2	CMU	White	None	0	0.4	Negative
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	W3	CMU	White	None	0	0.5	Negative
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	Door Frame	Metal	Grey	None	0	0.1	Negative



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	Door	Wood	Red	None	0	0.1	Negative
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	W4	CMU	White	None	0	0.3	Negative
1	1	117D	Auditorium Entrance Ramp across from Main Office Mail Room	Ceiling	Concrete	White	None	0	0.1	Negative
1	1	116	Loading Dock	Floor	Concrete	red/black	Chipping	9	0.2	Negative
1	1	116	Loading Dock	W1	CMU	White	None	0	0.4	Negative
1	1	116	Loading Dock	Doorframe	Metal	Grey	None	0	0.5	Negative
1	1	116	Loading Dock	Door	Metal	Black	None	0	0.1	Negative
1	1	116	Loading Dock	W2	CMU	White	Cracking	10	0.5	Negative
1	1	116	Loading Dock	Pipe Cover	Metal	White	Chipping	25	0.4	Negative
1	1	116	Loading Dock	Pipe Insulation	Fiberglass	White	Flaking	95	0.2	Negative
1	1	116	Loading Dock	column	Concrete	White	None	0	0.1	Negative
1	1	116	Loading Dock	Radiator	Metal	White	None	0	0.1	Negative
1	1	116	Loading Dock	Door	Metal	Tan	Chipping	12	12	Positive
1	1	116	Loading Dock	W3	CMU	White	None	0	0.4	Negative
1	1	116	Loading Dock	Pipe	Metal	White	Flaking	15	0.6	Negative
1	1	116	Loading Dock	Door	Metal	Grey	Chipping	20	0	Negative
1	1	116	Loading Dock	W4	CMU	White	None	0	0.4	Negative
1	1	116	Loading Dock	Duct	Metal	White	None	0	0.2	Negative
1	1	116	Loading Dock	Ceiling	Concrete	White	None	0	0.1	Negative
1	1	117	Auditorium	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	117	Auditorium	W1	Wood	N/A	N/A	N/A	N/A	N/A
1	1	117	Auditorium	Column	Concrete	White	Flaking	8	0.2	Negative
1	1	117	Auditorium	Door Frame	Metal	Black/Red	Chipping	15	0.1	Negative
1	1	117	Auditorium	Column Base	Wood	White	Moisture Damage	10	0.1	Negative
1	1	117	Auditorium	W2	CMU	White	None	0	0.2	Negative
1	1	117	Auditorium	Door	Metal	Black	Chipping	6	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	117	Auditorium	W3	CMU	White	None	0	0.4	Negative
1	1	117	Auditorium	Column	Concrete	White	Flaking	2	0.3	Negative
1	1	117	Auditorium	Steps	Wood	Black	Flaking	3	0.2	Negative
1	1	117	Auditorium	W4	CMU	White	None	0	0.2	Negative
1	1	117	Auditorium	Door	Metal	Black	Chipping	15	0.1	Negative
1	1	117	Auditorium	Door Post	Metal	Black	Chipping	6	0.2	Negative
1	1	117	Auditorium	Ceiling	Plaster	White	Flaking	70	0.2	Negative
1	1	117	Inspector	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	117	Inspector	W1	Wood	N/A	N/A	N/A	N/A	N/A
1	1	117	Inspector	W2	CMU	White	None	0	0.1	Negative
1	1	117	Inspector	Door	Metal	Black	Chipping	6	0.1	Negative
1	1	117	Inspector	W3	CMU	White	None	0	0.4	Negative
1	1	117	Inspector	Column	Concrete	White	Flaking	2	0.2	Negative
1	1	117	Inspector	Steps	Wood	Black	Flaking	3	0.2	Negative
1	1	117	Inspector	W4	CMU	White	None	0	0.2	Negative
1	1	117	Inspector	Door	Metal	Black	Chipping	15	0.1	Negative
1	1	117	Inspector	Door Post	Metal	White	Chipping	6	0.2	Negative
1	1	117	Inspector	Ceiling	Concrete	White	Moisture Damage	70	0.2	Negative
1	1	117B	Auditorium Stage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	117B	Auditorium Stage	W1	CMU	White	Flaking	6	0.5	Negative
1	1	117B	Auditorium Stage	Door Frame	Metal	Black	Chipping	2	0.2	Negative
1	1	117B	Auditorium Stage	W2	CMU	White	Flaking	8	0.4	Negative
1	1	117B	Auditorium Stage	Door Frame	Metal	Black	Chipping	5	0.2	Negative
1	1	117B	Auditorium Stage	W3	CMU	White	Flaking	5	0.5	Negative
1	1	117B	Auditorium Stage	Pipe	Metal	White	None	0	0.4	Negative
1	1	117B	Auditorium Stage	Door Frame	Metal	Black	Chipping	2	0.2	Negative
1	1	117B	Auditorium Stage	W4	CMU	White	Flaking	6	0.5	Negative
1	1	117B	Auditorium Stage	Door Frame	Metal	Grey	Chipping	6	0.5	Negative
1	1	117B	Auditorium Stage	Door Cover	Metal	Grey	Chipping	2	0.5	Negative
1	1	117B	Auditorium Stage	Ceiling	Concrete	Green	Flaking	3	0.3	Negative
1	1	ELEV2	Elevator 2	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	ELEV2	Elevator 2	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV2	Elevator 2	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV2	Elevator 2	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV2	Elevator 2	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV2	Elevator 2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV1	Elevator 1	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV1	Elevator 1	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV1	Elevator 1	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV1	Elevator 1	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV1	Elevator 1	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV1	Elevator 1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV3	Elevator 3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV3	Elevator 3	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV3	Elevator 3	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV3	Elevator 3	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV3	Elevator 3	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	ELEV3	Elevator 3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	27	Food Services Suite - Training Room next to Staff Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	27	Food Services Suite - Training Room next to Staff Restroom	W1	CMU	White	None	0	0.5	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	Radiator	Metal	White	None	0	0.1	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	conduit	Metal	White	None	0	0.5	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	Pipe Cover	Metal	White	None	0	0.4	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	pipe insulation	Fiberglass	White	None	0	0.2	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	doorframe	Metal	Black	None	0	0.4	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	Baseboard	Tile	Black	None	0	1.6	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	27	Food Services Suite - Training Room next to Staff Restroom	W2	CMU	White	None	0	0.5	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	W3	CMU	White	None	0	0.5	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	W4	CMU	White	None	0	0.1	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	Pipe	Metal	White	None	0	0.1	Negative
1	B	27	Food Services Suite - Training Room next to Staff Restroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	27A	Food Services Suite - Training Room Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	27A	Food Services Suite - Training Room Closet	W1	CMU	White	None	0	0.1	Negative
1	B	27A	Food Services Suite - Training Room Closet	Doorframe	Metal	Black	None	0	0.3	Negative
1	B	27A	Food Services Suite - Training Room Closet	W2	CMU	White	None	0	0.3	Negative
1	B	27A	Food Services Suite - Training Room Closet	pipe insulation	Fiberglass	White	None	0	0.2	Negative
1	B	27A	Food Services Suite - Training Room Closet	W3	Concrete	White	None	0	0.2	Negative
1	B	27A	Food Services Suite - Training Room Closet	Conduit	Metal	White	None	0	0.2	Negative
1	B	27A	Food Services Suite - Training Room Closet	W4	CMU	White	None	0	0.5	Negative
1	B	27A	Food Services Suite - Training Room Closet	Pipe Cover	Metal	White	None	0	0.1	Negative
1	B	27A	Food Services Suite - Training Room Closet	Pipe	Metal	White	None	0	0.2	Negative
1	B	27A	Food Services Suite - Training Room Closet	Duct	Metal	White	None	0	0.1	Negative
1	B	27A	Food Services Suite - Training Room Closet	Insulation	Fiberglass	White	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia HighSchool</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	27A	Food Services Suite - Training Room Closet	Ceiling	Concrete	White	Flaking	2	0.5	Negative
1	B	27B	Food Services Suite - Men's Staff Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	27B	Food Services Suite - Men's Staff Restroom	W1	Ceramic	White	None	0	1.8	Positive
1	B	27B	Food Services Suite - Men's Staff Restroom	doorframe	Metal	Black	None	0	0.2	Negative
1	B	27B	Food Services Suite - Men's Staff Restroom	W2	CMU	White	None	0	0.5	Negative
1	B	27B	Food Services Suite - Men's Staff Restroom	W3	CMU	White	None	0	0.5	Negative
1	B	27B	Food Services Suite - Men's Staff Restroom	Baseboard	Tile	Black	None	0	1.5	Positive
1	B	27B	Food Services Suite - Men's Staff Restroom	W4	Sheetrock	White	None	0	0.1	Negative
1	B	27B	Food Services Suite - Men's Staff Restroom	Insulation	Fiberglass	White	None	0	0	Negative
1	B	27B	Food Services Suite - Men's Staff Restroom	duct	Metal	White	None	0	0.4	Negative
1	B	27B	Food Services Suite - Men's Staff Restroom	pipe	Metal	White	None	0	0.3	Negative
1	B	27B	Food Services Suite - Men's Staff Restroom	Ceiling	Concrete	White	None	0	0.5	Negative
1	B	28F	Food Services Suite - Closet next to Staff Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	28F	Food Services Suite - Closet next to Staff Restroom	W1	Sheetrock	White	None	0	0.1	Negative
1	B	28F	Food Services Suite - Closet next to Staff Restroom	W2	Sheetrock	White	None	0	0.1	Negative
1	B	28F	Food Services Suite - Closet next to Staff Restroom	W3	Concrete	White	None	0	0.2	Negative
1	B	28F	Food Services Suite - Closet next to Staff Restroom	W4	CMU	White	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	28F	Food Services Suite - Closet next to Staff Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S028	Stairs next to Food Services Suite-Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S028	Stairs next to Food Services Suite-Lobby	W1	Sheetrock	White	Chipping	15	0.1	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	Doorframe	Metal	Black	none	0	0.1	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	W2	CMU	white	Chipping	15	0.5	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	W3	CMU	white	Chipping	45	0.5	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	Riser	Metal	black	Chipping	12	0.1	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	stringer	Metal	black	Chipping	10	0.2	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	tread	Concrete	black	none	0	0.2	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	Railing	Metal	black	Chipping	10	0.2	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	W4	CMU	white	None	0	0	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	Pipe Cover	Metal	white	Chipping	7	0.1	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	pipe insulation	Fiberglass	white	Chipping	4	0.2	Negative
1	B	S028	Stairs next to Food Services Suite-Lobby	Ceiling	Concrete	white	Chipping	10	0.3	Negative
1	B	28	Food Services Suite - Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	28	Food Services Suite - Lobby	W1	CMU	Tan	None	0	0.5	Negative
1	B	28	Food Services Suite - Lobby	Pipe Cover	Metal	Tan	None	0	0.2	Negative
1	B	28	Food Services Suite - Lobby	Pipe Insulation	Fiberglass	Tan	None	0	0.2	Negative
1	B	28	Food Services Suite - Lobby	Radiator	Metal	Grey	None	0	0.1	Negative
1	B	28	Food Services Suite - Lobby	Conduit	Metal	Tan	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	28	Food Services Suite - Lobby	Riser	Concrete	Black	None	0	0.3	Negative
1	B	28	Food Services Suite - Lobby	Railing	Metal	Black	None	0	0.3	Negative
1	B	28	Food Services Suite - Lobby	Ramp	Wood	Tan	None	0	0.1	Negative
1	B	28	Food Services Suite - Lobby	Doorframe	Metal	Grey	None	0	0.1	Negative
1	B	28	Food Services Suite - Lobby	Door	Metal	Grey	None	0	0.2	Negative
1	B	28	Food Services Suite - Lobby	W2	CMU	Tan	None	0	0.6	Negative
1	B	28	Food Services Suite - Lobby	W3	Sheetrock	Tan	None	0	0.1	Negative
1	B	28	Food Services Suite - Lobby	Column	CMU	Tan	None	0	0.3	Negative
1	B	28	Food Services Suite - Lobby	W4	CMU	Tan	None	0	0.5	Negative
1	B	28	Food Services Suite - Lobby	Pipe	Metal	White	None	0	0.1	Negative
1	B	28	Food Services Suite - Lobby	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	28A	Food Services Suite - Break Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28A	Food Services Suite - Break Room	W1	Drywall	Tan	None	0	0.2	Negative
1	B	28A	Food Services Suite - Break Room	Doorframe	Metal	Black	None	0	0.1	Negative
1	B	28A	Food Services Suite - Break Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28A	Food Services Suite - Break Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28A	Food Services Suite - Break Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28A	Food Services Suite - Break Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28B	Food Services Suite - Field Supervisors Office next to Break Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28B	Food Services Suite - Field Supervisors Office next to Break Room	W1	Drywall	Tan	None	0	0.2	Negative
1	B	28B	Food Services Suite - Field Supervisors Office next to Break Room	Doorframe	Metal	Black	None	0	0.2	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	28B	Food Services Suite - Field Supervisors Office next to Break Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28B	Food Services Suite - Field Supervisors Office next to Break Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28B	Food Services Suite - Field Supervisors Office next to Break Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28B	Food Services Suite - Field Supervisors Office next to Break Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28C	Food Services Suite - Middle Field Supervisors Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28C	Food Services Suite - Middle Field Supervisors Office	W1	Drywall	Tan	None	0	0.2	Negative
1	B	28C	Food Services Suite - Middle Field Supervisors Office	Doorframe	Metal	Black	None	0	0.2	Negative
1	B	28C	Food Services Suite - Middle Field Supervisors Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28C	Food Services Suite - Middle Field Supervisors Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28C	Food Services Suite - Middle Field Supervisors Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28C	Food Services Suite - Middle Field Supervisors Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28D	Food Services Suite - Field Supervisors Office next to Middle Field Supervisors Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28D	Food Services Suite - Field Supervisors Office next to Middle Field Supervisors Office	W1	Drywall	Tan	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	28D	Food Services Suite - Field Supervisors Office next to Middle Field Supervisors Office	Doorframe	Metal	Black	None	0	0.2	Negative
1	B	28D	Food Services Suite - Field Supervisors Office next to Middle Field Supervisors Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28D	Food Services Suite - Field Supervisors Office next to Middle Field Supervisors Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28D	Food Services Suite - Field Supervisors Office next to Middle Field Supervisors Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28D	Food Services Suite - Field Supervisors Office next to Middle Field Supervisors Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28E	Food Services Suite - Field Supervisors Office on Women's Restroom side	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28E	Food Services Suite - Field Supervisors Office on Women's Restroom side	W1	Drywall	Tan	None	0	0.2	Negative
1	B	28E	Food Services Suite - Field Supervisors Office on Women's Restroom side	Doorframe	Metal	Black	None	0	0.1	Negative
1	B	28E	Food Services Suite - Field Supervisors Office on Women's Restroom side	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28E	Food Services Suite - Field Supervisors Office on Women's Restroom side	W3	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	28E	Food Services Suite - Field Supervisors Office on Women's Restroom side	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	28E	Food Services Suite - Field Supervisors Office on Women's Restroom side	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	29A	Food Services Suite - Women's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	29A	Food Services Suite - Women's Restroom	W1	Ceramic	White	None	0	0.2	Negative
1	B	29A	Food Services Suite - Women's Restroom	Baseboard	Tile	Black	None	0	1.7	Positive
1	B	29A	Food Services Suite - Women's Restroom	Doorframe	Metal	Black	None	0	0.1	Negative
1	B	29A	Food Services Suite - Women's Restroom	W2	CMU	Purple	None	0	0.3	Negative
1	B	29A	Food Services Suite - Women's Restroom	W3	CMU	Purple	None	0	0.3	Negative
1	B	29A	Food Services Suite - Women's Restroom	W4	CMU	Purple	None	0	0.3	Negative
1	B	29A	Food Services Suite - Women's Restroom	Pipe	Metal	White	None	0	0.3	Negative
1	B	29A	Food Services Suite - Women's Restroom	insulation	Fiberglass	White	None	0	0.2	Negative
1	B	29A	Food Services Suite - Women's Restroom	duct	Metal	White	None	0	0.3	Negative
1	B	29A	Food Services Suite - Women's Restroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	29	Food Services Suite - Training Room next to Women's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	29	Food Services Suite - Training Room next to Women's Restroom	W1	Sheetrock	Tan	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	29	Food Services Suite - Training Room next to Women's Restroom	Doorframe	Metal	Black	Chipping	3	0.3	Negative
1	B	29	Food Services Suite - Training Room next to Women's Restroom	W2	CMU	Tan	None	0	0.5	Negative
1	B	29	Food Services Suite - Training Room next to Women's Restroom	Metal panel	Metal	Tan	None	0	0.1	Negative
1	B	29	Food Services Suite - Training Room next to Women's Restroom	Pipe	Metal	Tan	None	0	0.6	Negative
1	B	29	Food Services Suite - Training Room next to Women's Restroom	Baseboard	Tile	Black	None	0	1.2	Positive
1	B	29	Food Services Suite - Training Room next to Women's Restroom	W3	CMU	White	None	0	0.4	Negative
1	B	29	Food Services Suite - Training Room next to Women's Restroom	W4	CMU	White	None	0	0.5	Negative
1	B	29	Food Services Suite - Training Room next to Women's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	W1	CMU	White	Flaking	8	0.4	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	Doorframe	Metal	black	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	W2	CMU	White	Flaking	2	0.1	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	W3	CMU	white	Flaking	28	0.3	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	Stringer	Metal	brown	Flaking	12	0.1	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	Riser	Metal	grey	Chipping	18	0.1	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	Tread	Concrete	brown	Flaking	30	0.2	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	Railing	Metal	black	Chipping	60	0.3	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	W4	CMU	white	Flaking	9	0.3	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	Pipe	Metal	White	Chipping	3	0.5	Negative
1	B	S029	Stairs next to Food Services Suite-Training Room next to Women's Restroom	Ceiling	Concrete	White	Flaking	26	0.3	Negative
1	B	1	ROTC Suite - Main Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	1	ROTC Suite - Main Room	Column (Center)	Concrete	White	None	0	0.3	Negative
1	B	1	ROTC Suite - Main Room	Column (Center)	Tile	Black	None	0	0.2	Negative
1	B	1	ROTC Suite - Main Room	W1	CMU	White	None	0	0.5	Negative
1	B	1	ROTC Suite - Main Room	Door Frame	Metal	Black	None	0	0.5	Negative
1	B	1	ROTC Suite - Main Room	Door	Wood	Black	None	0	0.1	Negative
1	B	1	ROTC Suite - Main Room	Door Frame	Metal	Black	None	0	0.5	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	1	ROTC Suite - Main Room	Baseboard (W1, 3,4)	Tile	Black	None	0	1.5	Positive
1	B	1	ROTC Suite - Main Room	Conduit (W1/C)	Metal	White	None	0	0.5	Negative
1	B	1	ROTC Suite - Main Room	W2	Sheetrock	White	None	0	0.2	Negative
1	B	1	ROTC Suite - Main Room	W3	CMU/Sheetrock	White	None	0	0.3	Negative
1	B	1	ROTC Suite - Main Room	W4	CMU	White	None	0	0.5	Negative
1	B	1	ROTC Suite - Main Room	Pipe Cover	Metal	White	None	0	0.2	Negative
1	B	1	ROTC Suite - Main Room	Pipe	Metal	White	None	0	0.3	Negative
1	B	1	ROTC Suite - Main Room	Ceiling	Concrete	White	None	0	0.5	Negative
1	B	1	ROTC Suite - Main Room	Conduit (C)	Metal	White	None	0	0.3	Negative
1	B	S05	ROTC Suite - Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S05	ROTC Suite - Stairwell	W1	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S05	ROTC Suite - Stairwell	Doorframe	Metal	Tan	Chipping	4	0.1	Negative
1	B	S05	ROTC Suite - Stairwell	Door	Metal	Grey	Friction	5	0	Negative
1	B	S05	ROTC Suite - Stairwell	W2	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S05	ROTC Suite - Stairwell	Door/Doorframe	Metal	Tan	None	0	0.3	Negative
1	B	S05	ROTC Suite - Stairwell	Fire Pipe	Metal	Tan	Chipping	2	0.5	Negative
1	B	S05	ROTC Suite - Stairwell	Conduit	Metal	Tan	Chipping	3	0.4	Negative
1	B	S05	ROTC Suite - Stairwell	W3	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S05	ROTC Suite - Stairwell	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S05	ROTC Suite - Stairwell	Riser	Metal	Tan	None	0	0.1	Negative
1	B	S05	ROTC Suite - Stairwell	Stringer	Metal	Tan	None	0	0.1	Negative
1	B	S05	ROTC Suite - Stairwell	baseboard	Metal	Tan	None	0	0.1	Negative
1	B	S05	ROTC Suite - Stairwell	Stair Pan	Metal	tan	None	0	0.6	Negative
1	B	S05	ROTC Suite - Stairwell	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	001A	ROTC Suite - Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	001A	ROTC Suite - Office	W1	Sheetrock	White	None	0	0.2	Negative
1	B	001A	ROTC Suite - Office	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	001A	ROTC Suite - Office	W2	Sheetrock	White	None	0	0.2	Negative
1	B	001A	ROTC Suite - Office	W3	CMU	White	None	0	0.3	Negative
1	B	001A	ROTC Suite - Office	Radiator	Metal	White	None	0	0.2	Negative
1	B	001A	ROTC Suite - Office	W4	CMU	White	None	0	0.5	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	001A	ROTC Suite - Office	Ceiling	Concrete	White	None	0	0.5	Negative
1	B	001A	ROTC Suite - Office	Pipe	Metal	White	None	0	0.3	Negative
1	B	001B	ROTC Suite - Classroom next to Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	001B	ROTC Suite - Classroom next to Office	W1	Sheetrock	White	None	0	0.3	Negative
1	B	001B	ROTC Suite - Classroom next to Office	Column (W1/3)	Concrete	White	Flaking	1	0.2	Negative
1	B	001B	ROTC Suite - Classroom next to Office	Door Frame	Metal	Black	Chipping	2	0.2	Negative
1	B	001B	ROTC Suite - Classroom next to Office	Pipe (W1/3)	Metal	White	Flaking	5	0.3	Negative
1	B	001B	ROTC Suite - Classroom next to Office	W2	Sheetrock	White	Flaking	5	0.2	Negative
1	B	001B	ROTC Suite - Classroom next to Office	W3	CMU	White	Flaking	5	0.5	Negative
1	B	001B	ROTC Suite - Classroom next to Office	Baseboard (W3/4)	CMU/Tile	Black	Cracking	1	1.3	Positive
1	B	001B	ROTC Suite - Classroom next to Office	Pipe Cover	Metal	White	Chipping	5	0.2	Negative
1	B	001B	ROTC Suite - Classroom next to Office	Univent	Metal	Grey	Chipping	2	0.1	Negative
1	B	001B	ROTC Suite - Classroom next to Office	W4	CMU	White	Flaking	3	0.5	Negative
1	B	001B	ROTC Suite - Classroom next to Office	Radiator	Metal	White	Chipping	2	0.1	Negative
1	B	001B	ROTC Suite - Classroom next to Office	Ceiling	Concrete	White	Flaking	2	0.5	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	001C	ROTC Suite - Classroom closer to entrance	W1	Sheetrock	White	None	0	0.2	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	W2	CMU	White	None	0	0.5	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia HighSchool</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	001C	ROTC Suite - Classroom closer to entrance	Baseboard (W2/3)	CMU/Tile	Black	None	0	1.4	Positive
1	B	001C	ROTC Suite - Classroom closer to entrance	Conduit (W2/3)	Metal	White	None	0	0.5	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	W3	CMU	White	Cracking	3	0.4	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	Column	Concrete	White	Flaking	3	0.2	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	Pipe Cover	Metal	White	Chipping	2	0.2	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	Univent (2x)	Metal	Grey	Chipping	6	0	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	Pipe	Metal	White	Flaking	3	0.1	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	W4	Sheetrock	White	None	0	0.2	Negative
1	B	001C	ROTC Suite - Classroom closer to entrance	Ceiling	Concrete	White	None	0	0.5	Negative
1	B	2	ROTC Suite - Main Room Closet next to Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	2	ROTC Suite - Main Room Closet next to Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	2	ROTC Suite - Main Room Closet next to Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	2	ROTC Suite - Main Room Closet next to Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	2	ROTC Suite - Main Room Closet next to Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	2	ROTC Suite - Main Room Closet next to Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	3	ROTC Suite - Main Room Closet next to entrance	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	3	ROTC Suite - Main Room Closet next to entrance	W1	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	3	ROTC Suite - Main Room Closet next to entrance	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	3	ROTC Suite - Main Room Closet next to entrance	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	3	ROTC Suite - Main Room Closet next to entrance	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	3	ROTC Suite - Main Room Closet next to entrance	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	H01	Hallway from Main Hallway to ROTC Suite	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	H01	Hallway from Main Hallway to ROTC Suite	W1	CMU	White	Flaking	1	0.3	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	W2	CMU	White	Flaking	22	0.5	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Pipe	Metal	White	None	0	0.3	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Conduit (W2/3/4)	Metal	White	None	0	0.3	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Door Frame	Metal	Black	None	0	0.5	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Door	Wood	Black	None	0	0.1	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Baseboard (W2/4)	CMU/Tile	Black	None	0	1.2	Positive
1	B	H01	Hallway from Main Hallway to ROTC Suite	Electrical Panel	Metal	White	None	0	0.2	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	W3	CMU	White	Flaking	4	0.4	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Door Frame	Metal	Black	None	0	0.5	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Door	Wood	Black	None	0	0.1	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	W4	CMU	White	Flaking	18	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	H01	Hallway from Main Hallway to ROTC Suite	Door Frame	Metal	Black	None	0	0.5	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Door	Wood	Black	None	0	0.1	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Pipe	Metal	White	None	0	0.3	Negative
1	B	H01	Hallway from Main Hallway to ROTC Suite	Ceiling	Ceiling w/ Spline	White	None	0	0.2	Negative
1	B	4	Building Engineer's Storeroom next to ROTC Suite	Floor	Concrete	Brown	Chipping	25	0.3	Negative
1	B	4	Building Engineer's Storeroom	W1	CMU	White	Chipping	6	0.3	Negative
1	B	4	Building Engineer's Storeroom next to ROTC Suite	Door Frame	Metal	Black	Chipping	4	0.2	Negative
1	B	4	Building Engineer's Storeroom next to ROTC Suite	Door	Wood	Black	Chipping	6	0	Negative
1	B	4	Building Engineer's Storeroom next to ROTC Suite	W2	CMU	White	Chipping	6	0	Negative
1	B	4	Building Engineer's Storeroom next to ROTC Suite	W3	CMU	White	Chipping	4	0.3	Negative
1	B	4	Building Engineer's Storeroom next to ROTC Suite	Pipe	Metal	White	Flaking	4	0.5	Negative
1	B	4	Building Engineer's Storeroom next to ROTC Suite	W4	Sheetrock	White	Friction	10	0.2	Negative
1	B	4	Building Engineer's Storeroom next to ROTC Suite	Ceiling	Concrete	White	Flaking	5	0.4	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	Floor	Concrete	Brown	Chipping	25	0.3	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	W1	CMU	White	Chipping	6	0.3	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	Door Frame	Metal	Black	Chipping	4	0.2	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	Door	Wood	Black	Chipping	6	0	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	W2	CMU	White	Chipping	6	0	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	W3	CMU	White	Chipping	4	0.3	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	Pipe	Metal	White	Flaking	4	0.5	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	W4	Sheetrock	White	Friction	10	0.2	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	Duct	Metal	White	None	0	0.4	Negative
1	B	13	ROTC Storeroom next to Building Engineer's Storeroom	Ceiling	Concrete	White	Flaking	5	0.4	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	Floor	Concrete	Brown	Chipping	25	0.3	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	W1	CMU	White	Chipping	6	0.3	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	Door Frame	Metal	Black	Chipping	4	0.2	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	Door	Wood	Black	Chipping	6	0	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	W2	CMU	White	Chipping	6	0	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	W3	CMU	White	Chipping	4	0.3	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	Pipe	Metal	White	Flaking	4	0.5	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	W4	Sheetrock	White	Friction	10	0.2	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	Duct	Metal	White	None	0	0.4	Negative
1	B	32	Building Engineer's Restroom behind Center Elevator	Ceiling	Concrete	White	Flaking	5	0.4	Negative
1	B	14	Building Engineer's Office	Floor	Concrete	Brown	Chipping	25	0.3	Negative
1	B	14	Building Engineer's Office	W1	CMU	White	Chipping	6	0.3	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	14	Building Engineer's Office	Door Frame	Metal	Black	Chipping	4	0.2	Negative
1	B	14	Building Engineer's Office	Door	Wood	Black	Chipping	6	0	Negative
1	B	14	Building Engineer's Office	W2	CMU	White	Chipping	6	0	Negative
1	B	14	Building Engineer's Office	W3	CMU	White	Chipping	4	0.3	Negative
1	B	14	Building Engineer's Office	Pipe	Metal	White	Flaking	4	0.5	Negative
1	B	14	Building Engineer's Office	W4	Sheetrock	White	Friction	10	0.2	Negative
1	B	14	Building Engineer's Office	Duct	Metal	White	None	0	0.4	Negative
1	B	14	Building Engineer's Office	Ceiling	Concrete	White	Flaking	5	0.4	Negative
1	B	14	Building Engineer's Office	Pipe Insulation	Fiberglass	White	Chipping	3	0	Negative
1	B	14	Building Engineer's Office	Pipe	Metal	White	Chipping	8	0.5	Negative
1	B	14	Building Engineer's Office	Duct	Metal	White	None	0	0.4	Negative
1	B	S01	Stairwell next to Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S01	Stairwell next to Building Engineer's Office	W1	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S01	Stairwell next to Building Engineer's Office	Doorframe	Metal	Tan	Chipping	4	0.1	Negative
1	B	S01	Stairwell next to Building Engineer's Office	Door	Metal	Grey	Friction	5	0	Negative
1	B	S01	Stairwell next to Building Engineer's Office	W2	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S01	Stairwell next to Building Engineer's Office	Door/Doorframe	Metal	Tan	None	0	0.3	Negative
1	B	S01	Stairwell next to Building Engineer's Office	Fire Pipe	Metal	Tan	Chipping	2	0.5	Negative
1	B	S01	Stairwell next to Building Engineer's Office	Conduit	Metal	Tan	Chipping	3	0.4	Negative
1	B	S01	Stairwell next to Building Engineer's Office	W3	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S01	Stairwell next to Building Engineer's Office	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S01	Stairwell next to Building Engineer's Office	Riser	Metal	Tan	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	S01	Stairwell next to Building Engineer's Office	Stringer	Metal	Tan	None	0	0.1	Negative
1	B	S01	Stairwell next to Building Engineer's Office	baseboard	Metal	Tan	None	0	0.1	Negative
1	B	S01	Stairwell next to Building Engineer's Office	Stair Pan	Metal	tan	None	0	0.6	Negative
1	B	S01	Stairwell next to Building Engineer's Office	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	12	Custodial Supply Storeroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	12	Custodial Supply Storeroom	W1	CMU	White	None	0	0.4	Negative
1	B	12	Custodial Supply Storeroom	W2	CMU	White	None	0	0.3	Negative
1	B	12	Custodial Supply Storeroom	W3	CMU	White	None	0	0.3	Negative
1	B	12	Custodial Supply Storeroom	W4	CMU	White	None	0	0.2	Negative
1	B	12	Custodial Supply Storeroom	Ceiling	Concrete	White	None	0	0.1	Negative
1	B	5	Electrical Room off Custodial Supply Storeroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Electrical Room off Custodial Supply Storeroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Electrical Room off Custodial Supply Storeroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Electrical Room off Custodial Supply Storeroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Electrical Room off Custodial Supply Storeroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Electrical Room off Custodial Supply Storeroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	18	Storeroom next to Boiler Control Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	18	Storeroom next to Boiler Control Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	18	Storeroom next to Boiler Control Room	Door Frame	Metal	Black	Chipping	3	0	Negative
1	B	18	Storeroom next to Boiler Control Room	Door	Wood	Black	Chipping	2	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	18	Storeroom next to Boiler Control Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	18	Storeroom next to Boiler Control Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	18	Storeroom next to Boiler Control Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	18	Storeroom next to Boiler Control Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17	Boiler Control Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17	Boiler Control Room	W1	CMU	White	Chipping	2	0.1	Negative
1	B	17	Boiler Control Room	Door Frame	Metal	Black	Chipping	3	0	Negative
1	B	17	Boiler Control Room	Door	Wood	Black	Chipping	2	0.1	Negative
1	B	17	Boiler Control Room	Baseboard	CMU/Tile	Black	Chipping	4	0.5	Negative
1	B	17	Boiler Control Room	W2	CMU	White	Chipping	2	0.1	Negative
1	B	17	Boiler Control Room	Electrical Panel	MEtal	Black	Chipping	1	0.2	Negative
1	B	17	Boiler Control Room	Baseboard	CMU/Tile	Black	Chipping	4	0.5	Negative
1	B	17	Boiler Control Room	W3	CMU	White	Flaking	3	0.1	Negative
1	B	17	Boiler Control Room	Baseboard	CMU/Tile	Black	Chipping	4	0.5	Negative
1	B	17	Boiler Control Room	Window Header	Concrete	White	Flaking	6	0	Negative
1	B	17	Boiler Control Room	Window Frame	Metal	Black	Chipping	4	0.1	Negative
1	B	17	Boiler Control Room	Door Frame	Metal	Black	Chipping	4	0.5	Negative
1	B	17	Boiler Control Room	Door	Metal	Black	Chipping	7	8.6	Positive
1	B	17	Boiler Control Room	W4	CMU	White	Flaking	3	0.3	Negative
1	B	17	Boiler Control Room	Baseboard	CMU/Tile	Black	Chipping	4	0.5	Negative
1	B	17	Boiler Control Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17A	Boiler Control Room Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17A	Boiler Control Room Restroom	W1	CMU	White	Flaking	2	0.3	Negative
1	B	17A	Boiler Control Room Restroom	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	17A	Boiler Control Room Restroom	Door	Wood	Black	Chipping	1	0.1	Negative
1	B	17A	Boiler Control Room Restroom	Wall Tile	Ceramic	Blue/Green	None	0	0.1	Negative
1	B	17A	Boiler Control Room Restroom	W2	CMU	White	Flaking	2	0.3	Negative
1	B	17A	Boiler Control Room Restroom	Wall Tile	Ceramic	Blue/Green	None	0	0.1	Negative



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	17A	Boiler Control Room Restroom	W3	CMU	White	Flaking	2	0.2	Negative
1	B	17A	Boiler Control Room Restroom	Wall Tile	Ceramic	Blue/Green	None	0	0.1	Negative
1	B	17A	Boiler Control Room Restroom	W4	CMU	White	Flaking	2	0.1	Negative
1	B	17A	Boiler Control Room Restroom	Wall Tile	Ceramic	Blue/Green	None	0	0.1	Negative
1	B	17A	Boiler Control Room Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	16	Custodial Storeroom (former Tool Shop)	Floor	Concrete	Grey	None	0	0.2	Negative
1	B	16	Custodial Storeroom (former Tool Shop)	W1	CMU	Blue	None	0	0.5	Negative
1	B	16	Custodial Storeroom (former Tool Shop)	doorframe	Metal	Black	None	0	0.3	Negative
1	B	16	Custodial Storeroom (former Tool Shop)	Door	Wood	Black	None	0	0.3	Negative
1	B	16	Custodial Storeroom (former Tool Shop)	W2	CMU	Blue	None	0	0.1	Negative
1	B	16	Custodial Storeroom (former Tool Shop)	W3	CMU	Blue	None	0	0.5	Negative
1	B	16	Custodial Storeroom (former Tool Shop)	W4	CMU	Blue	None	0	0.5	Negative
1	B	16	Custodial Storeroom (former Tool Shop)	pipe insulation	Fiberglass	Blue	None	0	0.2	Negative
1	B	16	Custodial Storeroom (former Tool Shop)	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	15	Custodial Kitchen / Lounge (unused)	W1	CMU	Blue	None	0	0.5	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	Doorframe	Metal	Black	None	0	0.2	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	door	Metal	Black	None	0	0.2	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	W2	CMU	Blue	None	0	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	15	Custodial Kitchen / Lounge (unused)	Conduit	Metal	Blue	None	0	0.5	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	pipe insulation	Fiberglass	Blue	None	0	0.1	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	pipe	Metal	Blue	None	0	0.6	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	W3	CMU	Blue	None	0	0.5	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	W4	CMU	Blue	None	0	0.4	Negative
1	B	15	Custodial Kitchen / Lounge (unused)	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairwell next to Night Engineer's Storeroom	W1	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairwell next to Night Engineer's Storeroom	Doorframe	Metal	Black	None	0	0.1	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairwell next to Night Engineer's Storeroom	Stringer	Metal	Black	Chipping	3	0.1	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	Riser	Metal	Black	Chipping	23	0.1	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	Tread	Concrete	Black	Chipping	22	0.1	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairwell next to Night Engineer's Storeroom	Radiator	Metal	Tan	None	0	0.5	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	Stair pan	Metal	Tan	None	0	0.2	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	W4	Ceramic	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	S02	Stairwell next to Night Engineer's Storeroom	Fire pipe	Metal	Tan	Chipping	3	0.4	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	Doorframe	Metal	Tan	None	0	0.4	Negative
1	B	S02	Stairwell next to Night Engineer's Storeroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	19	Night Building Engineer's Storeroom	Floor	Concrete	Black	Friction	50	0.3	Negative
1	B	19	Night Building Engineer's Storeroom	W1	CMU	White	None	0	0.4	Negative
1	B	19	Night Building Engineer's Storeroom	Doorframe	Metal	Black	Chipping	10	0.2	Negative
1	B	19	Night Building Engineer's Storeroom	baseboard	CMU	Black	Chipping	20	0.5	Negative
1	B	19	Night Building Engineer's Storeroom	W2	CMU	White	None	0	0.5	Negative
1	B	19	Night Building Engineer's Storeroom	Closet Doorframe	Metal	Black	None	0	0.2	Negative
1	B	19	Night Building Engineer's Storeroom	Closet Shelf	Wood	Green	Chipping	4	0	Negative
1	B	19	Night Building Engineer's Storeroom	W3	CMU	White	None	0	0.5	Negative
1	B	19	Night Building Engineer's Storeroom	W4	CMU	White	None	0	0.5	Negative
1	B	19	Night Building Engineer's Storeroom	Conduit	Metal	White	None	0	0.4	Negative
1	B	19	Night Building Engineer's Storeroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	22	Boy's Locker Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	22	Boy's Locker Room	Column (Center)	Concrete	Tan/White	Chipping	15	0.2	Negative
1	B	22	Boy's Locker Room	W1	CMU	Tan	Flaking	28	0.4	Negative
1	B	22	Boy's Locker Room	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	22	Boy's Locker Room	Door	Metal	Black	None	0	0.1	Negative
1	B	22	Boy's Locker Room	Pipe Cover	Metal	Tan/White	Flaking	10	0.2	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	22	Boy's Locker Room	Baseboard (W1-4)	CMU/Tile	Black	Chipping	4	1	Positive
1	B	22	Boy's Locker Room	W2	CMU	Tan	None	0	0.4	Negative
1	B	22	Boy's Locker Room	W3	CMU	Tan	None	0	0.2	Negative
1	B	22	Boy's Locker Room	W4	CMU	Tan	None	0	0.4	Negative
1	B	22	Boy's Locker Room	Ceiling	Concrete	White	Flaking	50	0.2	Negative
1	B	22	Boy's Locker Room	Duct (C)	Metal	White	Flaking	35	0.2	Negative
1	B	022A	Boy's Locker Room Storage	Floor	Concrete	Grey	None	0	0.3	Negative
1	B	022A	Boy's Locker Room Storage	W1	CMU	White	None	0	0.4	Negative
1	B	022A	Boy's Locker Room Storage	doorframe	Metal	Black	None	0	0.2	Negative
1	B	022A	Boy's Locker Room Storage	Pipe Cover	Metal	White	None	0	0.3	Negative
1	B	022A	Boy's Locker Room Storage	pipe insulation	Fiberglass	White	None	0	0.2	Negative
1	B	022A	Boy's Locker Room Storage	W2	CMU	White	None	0	0.4	Negative
1	B	022A	Boy's Locker Room Storage	W3	CMU	White	None	0	0.4	Negative
1	B	022A	Boy's Locker Room Storage	Radiator	Metal	Tan	Chipping	3	0.2	Negative
1	B	022A	Boy's Locker Room Storage	W4	CMU	White	None	0	0.4	Negative
1	B	022A	Boy's Locker Room Storage	duct	Metal	White	None	0	0.1	Negative
1	B	022A	Boy's Locker Room Storage	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	022C	Boy's Gang Shower	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	022C	Boy's Gang Shower	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	022C	Boy's Gang Shower	Door Frame	Metal	Black	Chipping	4	0.3	Negative
1	B	022C	Boy's Gang Shower	Door	Metal	Black	Chipping	4	0.2	Negative
1	B	022C	Boy's Gang Shower	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	022C	Boy's Gang Shower	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	022C	Boy's Gang Shower	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	022C	Boy's Gang Shower	Ceiling	Concrete	White	Flaking	10	0.2	Negative
1	B	022D	Boy's Locker Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	022D	Boy's Locker Restroom	W1	Ceramic	White	None	0	0.2	Negative
1	B	022D	Boy's Locker Restroom	Baseboard	Tile	Black	None	0	1.7	Positive
1	B	022D	Boy's Locker Restroom	Doorframe	Metal	Black	None	0	0.1	Negative
1	B	022D	Boy's Locker Restroom	W2	CMU	White	None	0	0.3	Negative
1	B	022D	Boy's Locker Restroom	W3	CMU	White	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	022D	Boy's Locker Restroom	W4	CMU	White	None	0	0.3	Negative
1	B	022D	Boy's Locker Restroom	Pipe	Metal	White	None	0	0.3	Negative
1	B	022D	Boy's Locker Restroom	insulation	Fiberglass	White	None	0	0.2	Negative
1	B	022D	Boy's Locker Restroom	duct	Metal	White	None	0	0.3	Negative
1	B	022D	Boy's Locker Restroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	022H	Boy's Visitor Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022H	Boy's Visitor Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022H	Boy's Visitor Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022H	Boy's Visitor Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022H	Boy's Visitor Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022H	Boy's Visitor Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022F	Boy's Visitor Locker Room Showers	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022F	Boy's Visitor Locker Room Showers	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022F	Boy's Visitor Locker Room Showers	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022F	Boy's Visitor Locker Room Showers	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022F	Boy's Visitor Locker Room Showers	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022F	Boy's Visitor Locker Room Showers	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022Z	Boy's Visitor Locker Room Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022Z	Boy's Visitor Locker Room Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022Z	Boy's Visitor Locker Room Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022Z	Boy's Visitor Locker Room Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022Z	Boy's Visitor Locker Room Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	022Z	Boy's Visitor Locker Room Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	022I	Boy's Home Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	022I	Boy's Home Locker Room	W1	CMU	White	flaking	5	0.2	Negative
1	B	022I	Boy's Home Locker Room	W2	CMU	White	Flaking	10	0.4	Negative
1	B	022I	Boy's Home Locker Room	W3	CMU	White	Flaking	16	0.5	Negative
1	B	022I	Boy's Home Locker Room	Metal panel	Metal	White	Chipping	2	0.2	Negative
1	B	022I	Boy's Home Locker Room	W4	CMU	White	Flaking	35	0.5	Negative
1	B	022I	Boy's Home Locker Room	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	B	022I	Boy's Home Locker Room	Radiator	Metal	White	Chipping	1	0.1	Negative
1	B	022I	Boy's Home Locker Room	Ceiling	Concrete	White	Chipping	9	0.2	Negative
1	B	022G	Boy's Home Locker Room Showers	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	022G	Boy's Home Locker Room Showers	W1	ceramic	Green	None	0	2.2	Positive
1	B	022G	Boy's Home Locker Room Showers	W2	ceramic	Green	None	0	2.2	Positive
1	B	022G	Boy's Home Locker Room Showers	W3	ceramic	Green	None	0	2.2	Positive
1	B	022G	Boy's Home Locker Room Showers	W4	ceramic	Green	None	0	2.2	Positive
1	B	022G	Boy's Home Locker Room Showers	Duct	Metal	White	None	0	0.3	Negative
1	B	022G	Boy's Home Locker Room Showers	Ceiling	Concrete	White	None	0	0.4	Negative
1	B	022Y	Boy's Home Locker Room Restroom	Floor	Concrete	White	None	0	0.2	Negative
1	B	022Y	Boy's Home Locker Room Restroom	W1	CMU	White	Flaking	10	0.5	Negative
1	B	022Y	Boy's Home Locker Room Restroom	Doorframe	Metal	Black	None	0	0.5	Negative
1	B	022Y	Boy's Home Locker Room Restroom	W2	CMU	White	Flaking	11	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	022Y	Boy's Home Locker Room Restroom	radiator	Metal	Tan	None	0	0.1	Negative
1	B	022Y	Boy's Home Locker Room Restroom	W3	CMU	White	Flaking	31	0.6	Negative
1	B	022Y	Boy's Home Locker Room Restroom	W4	CMU	White	Flaking	29	0.5	Negative
1	B	022Y	Boy's Home Locker Room Restroom	Pipe	Metal	White	Moisture Damage	2	0.4	Negative
1	B	022Y	Boy's Home Locker Room Restroom	Ceiling	Concrete	White	Chipping	15	0.3	Negative
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	W1	CMU	Tan	Flaking	5	0.1	Negative
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	W2	CMU	Tan	Flaking	50	0.2	Negative
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	Baseboard (W2/4)	CMU/Tile	Black	None	0	1	Positive
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	W3	CMU	Tan	Flaking	10	0.3	Negative
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	Door Frame	Metal	Black	Flaking	2	0.3	Negative
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	W4	CMU	Tan	Flaking	30	0.3	Negative
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	Ceiling	Concrete	White	Flaking	6	0.2	Negative
1	B	H021	Hallway to Boy's Home/Visitor Locker Rooms	Duct (C)	Metal	White	Flaking	5	0.1	Negative
1	B	H022	Hallway to Boy's Locker Room Exit Stairwell	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	H022	Hallway to Boy's Locker Room Exit Stairwell	W1	Tile	N/A	N/A	N/A	N/A	N/A
1	B	H022	Hallway to Boy's Locker Room Exit Stairwell	W2	Tile	N/A	N/A	N/A	N/A	N/A



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	H022	Hallway to Boy's Locker Room Exit Stairwell	W3	Tile	N/A	N/A	N/A	N/A	N/A
1	B	H022	Hallway to Boy's Locker Room Exit Stairwell	W4	Tile	N/A	N/A	N/A	N/A	N/A
1	B	H022	Hallway to Boy's Locker Room Exit Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S022	Boy's Locker Room Exit Stairwell	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S022	Boy's Locker Room Exit Stairwell	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S022	Boy's Locker Room Exit Stairwell	Door Frame	Metal	Black	None	0	0.1	Negative
1	B	S022	Boy's Locker Room Exit Stairwell	W2	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S022	Boy's Locker Room Exit Stairwell	W3	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S022	Boy's Locker Room Exit Stairwell	W4	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S022	Boy's Locker Room Exit Stairwell	Ceiling	Concrete	White	Flaking	4	0.1	Negative
1	B	S022	Boy's Locker Room Exit Stairwell	Duct (C)	Metal	White	None	0	0.1	Negative
1	B	25	Weight Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	25	Weight Room	W1	CMU	White	None	0	0.4	Negative
1	B	25	Weight Room	Duct	Metal	White	None	0	0.4	Negative
1	B	25	Weight Room	W2	CMU	White	None	0	0.5	Negative
1	B	25	Weight Room	Doorframe	Metal	Black	None	0	0.5	Negative
1	B	25	Weight Room	W3	CMU	White	None	0	0.4	Negative
1	B	25	Weight Room	Baseboard	Wood	Black	Chipping	45	1.1	Positive
1	B	25	Weight Room	Column	CMU	White	None	0	0.3	Negative
1	B	25	Weight Room	W4	CMU	White	None	0	0.3	Negative
1	B	25	Weight Room	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	025C	Weight Room Closet on Boy's side	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	025C	Weight Room Closet on Boy's side	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025C	Weight Room Closet on Boy's side	Doorframe	Metal	Black	None	0	0.4	Negative
1	B	025C	Weight Room Closet on Boy's side	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025C	Weight Room Closet on Boy's side	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025C	Weight Room Closet on Boy's side	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025C	Weight Room Closet on Boy's side	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025B	Weight Room Office on Boy's side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	025B	Weight Room Office on Boy's side	W1	CMU	White	None	0	0.4	Negative
1	B	025B	Weight Room Office on Boy's side	Window frame	Metal	Black	None	0	0.2	Negative
1	B	025B	Weight Room Office on Boy's side	W2	CMU	White	None	0	0.5	Negative
1	B	025B	Weight Room Office on Boy's side	W3	CMU	White	None	0	0.3	Negative
1	B	025B	Weight Room Office on Boy's side	radiator	Metal	White	None	0	0.2	Negative
1	B	025B	Weight Room Office on Boy's side	Pipe Cover	Metal	White	None	0	0.3	Negative
1	B	025B	Weight Room Office on Boy's side	Pipe Insulation	Fiberglass	White	None	0	0.1	Negative
1	B	025B	Weight Room Office on Boy's side	Baseboard	CMU/Tile	Black	None	0	1.3	Positive
1	B	025B	Weight Room Office on Boy's side	W4	CMU	White	None	0	0.4	Negative
1	B	025B	Weight Room Office on Boy's side	Column	Concrete	White	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia HighSchool</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	025B	Weight Room Office on Boy's side	Pipe	Metal	White	None	0	0.1	Negative
1	B	025B	Weight Room Office on Boy's side	Ceiling	Concrete	White	None	0	0.4	Negative
1	B	025F	Restroom in Weight Room Office on Boy's side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	025F	Restroom in Weight Room Office on Boy's side	W1	CMU	White	None	0	0.5	Negative
1	B	025F	Restroom in Weight Room Office on Boy's side	W2	CMU	White	None	0	0.3	Negative
1	B	025F	Restroom in Weight Room Office on Boy's side	Radiator	Metal	White	None	0	0.1	Negative
1	B	025F	Restroom in Weight Room Office on Boy's side	Pipe Cover	Metal	White	None	0	0.3	Negative
1	B	025F	Restroom in Weight Room Office on Boy's side	pipe insulation	Fiberglass	White	None	0	0.2	Negative
1	B	025F	Restroom in Weight Room Office on Boy's side	W3	CMU	White	None	0	0.2	Negative
1	B	025F	Restroom in Weight Room Office on Boy's side	W4	CMU	White	None	0	0.4	Negative
1	B	025F	Restroom in Weight Room Office on Boy's side	Ceiling	Concrete	White	None	0	0.5	Negative
1	B	025A	Weight Room Office on Girl's side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	025A	Weight Room Office on Girl's side	W1	CMU	White	Chipping	1	0.3	Negative
1	B	025A	Weight Room Office on Girl's side	Doorframe	Metal	Black	None	0	0.2	Negative
1	B	025A	Weight Room Office on Girl's side	W2	CMU	White	None	0	0.4	Negative
1	B	025A	Weight Room Office on Girl's side	W3	CMU	White	Flaking	3	0.4	Negative
1	B	025A	Weight Room Office on Girl's side	Radiator	Metal	White	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	025A	Weight Room Office on Girl's side	Pipe Cover	Metal	White	None	0	0.3	Negative
1	B	025A	Weight Room Office on Girl's side	pipe insulation	Fiberglass	White	None	0	0.1	Negative
1	B	025A	Weight Room Office on Girl's side	Baseboard	tile	Black	None	0	1.4	Positive
1	B	025A	Weight Room Office on Girl's side	W4	CMU	White	Flaking	10	0.4	Negative
1	B	025A	Weight Room Office on Girl's side	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	025E	Restroom in Weight Room Office on Girl's side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	025E	Restroom in Weight Room Office on Girl's side	W1	CMU	White	None	0	0.5	Negative
1	B	025E	Restroom in Weight Room Office on Girl's side	W2	ceramic	Green	None	0	0.2	Negative
1	B	025E	Restroom in Weight Room Office on Girl's side	W3	CMU	White	None	0	0.2	Negative
1	B	025E	Restroom in Weight Room Office on Girl's side	W4	CMU	White	Flaking	4	0.5	Negative
1	B	025E	Restroom in Weight Room Office on Girl's side	Pipe Cover	Metal	White	None	0	0.2	Negative
1	B	025E	Restroom in Weight Room Office on Girl's side	pipe insulation	Fiberglass	White	None	0	0	Negative
1	B	025E	Restroom in Weight Room Office on Girl's side	radiator	Metal	White	None	0	0.1	Negative
1	B	025E	Restroom in Weight Room Office on Girl's side	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	025D	Weight Room Closet on Girl's side	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025D	Weight Room Closet on Girl's side	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025D	Weight Room Closet on Girl's side	Doorframe	Metal	Black	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	025D	Weight Room Closet on Girl's side	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025D	Weight Room Closet on Girl's side	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025D	Weight Room Closet on Girl's side	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	025D	Weight Room Closet on Girl's side	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	20	Fan Room next to Boy's Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	20	Fan Room next to Boy's Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	20	Fan Room next to Boy's Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	20	Fan Room next to Boy's Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	20	Fan Room next to Boy's Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	20	Fan Room next to Boy's Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	21	Storeroom next to Fan Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	21	Storeroom next to Fan Room	W1	CMU	N/A	N/A	N/A	N/A	N/A
1	B	21	Storeroom next to Fan Room	Door Frame	Metal	Black	None	0	0.3	Negative
1	B	21	Storeroom next to Fan Room	W2	CMU	N/A	N/A	N/A	N/A	N/A
1	B	21	Storeroom next to Fan Room	W3	CMU	N/A	N/A	N/A	N/A	N/A
1	B	21	Storeroom next to Fan Room	W4	CMU	N/A	N/A	N/A	N/A	N/A
1	B	21	Storeroom next to Fan Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	24	Storeroom next to Trophy Case	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	24	Storeroom next to Trophy Case	W1	CMU	Tan	None	0	0.4	Negative
1	B	24	Storeroom next to Trophy Case	Door Frame	Metal	Black	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	24	Storeroom next to Trophy Case	Door	Metal	Black	None	0	0.1	Negative
1	B	24	Storeroom next to Trophy Case	W2	CMU	Tan	None	0	0.3	Negative
1	B	24	Storeroom next to Trophy Case	W3	CMU	Tan	None	0	0.4	Negative
1	B	24	Storeroom next to Trophy Case	W4	CMU	Tan	None	0	0.4	Negative
1	B	24	Storeroom next to Trophy Case	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	B	23	Girl's Locker Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	23	Girl's Locker Room	Floor	Concrete	Red	Flaking	60	0.1	Negative
1	B	23	Girl's Locker Room	Column (Center)	Concrete	Tan/White	Flaking	30	0.2	Negative
1	B	23	Girl's Locker Room	W1	CMU	Tan/White	Flaking	120	0.4	Negative
1	B	23	Girl's Locker Room	Door Frame	Metal	Black	Chipping	2	0.2	Negative
1	B	23	Girl's Locker Room	Door	Metal	Black	None	0	0.1	Negative
1	B	23	Girl's Locker Room	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	1	Positive
1	B	23	Girl's Locker Room	Pipe Cover	Metal	Tan/White	Chipping	10	0.2	Negative
1	B	23	Girl's Locker Room	W2	CMU	Tan/White	Flaking	160	0.3	Negative
1	B	23	Girl's Locker Room	W3	CMU	Tan/White	Flaking	85	0.3	Negative
1	B	23	Girl's Locker Room	W4	CMU	Tan/White	Flaking	170	0.4	Negative
1	B	23	Girl's Locker Room	Ceiling	Metal	White	Flaking	40	0.2	Negative
1	B	023A	Girl's Locker Room Gang Shower	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023A	Girl's Locker Room Gang Shower	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023A	Girl's Locker Room Gang Shower	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023A	Girl's Locker Room Gang Shower	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023A	Girl's Locker Room Gang Shower	W4	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	023A	Girl's Locker Room Gang Shower	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023B	Girl's Locker Room Shower Stalls	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023B	Girl's Locker Room Shower Stalls	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023B	Girl's Locker Room Shower Stalls	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023B	Girl's Locker Room Shower Stalls	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023B	Girl's Locker Room Shower Stalls	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023B	Girl's Locker Room Shower Stalls	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023K	Girl's Locker Room Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023K	Girl's Locker Room Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023K	Girl's Locker Room Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023K	Girl's Locker Room Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023K	Girl's Locker Room Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023K	Girl's Locker Room Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	Floor	Concrete	Red	None	0	0.2	Negative
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	W1	CMU	Tan/White	Flaking	4	0.4	Negative
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	W2	CMU	Tan/White	None	0	0.9	Positive
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	Baseboard (W2/4)	CMU/Tile	Black	None	60	0.4	Negative
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	Door Frame	Metal	Black	Chipping	8	0.5	Negative
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	W3	CMU	Tan/White	Flaking	45	0.4	Negative
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	Door Frame	Metal	Black	Chipping	2	0.2	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	W4	CMU	Tan/White	Flaking	75	0.3	Negative
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	Door Frame	Metal	Black	Chipping	4	0.4	Negative
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	Ceiling	Concrete	White	Flaking	50	0.2	Negative
1	B	H023	Hallway to Girl's Home/Visitor Locker Rooms	Duct (C)	Metal	White	Flaking	45	0.1	Negative
1	B	023D	Girl's Visitor Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023D	Girl's Visitor Locker Room	W1	CMU	White	flaking	5	0.2	Negative
1	B	023D	Girl's Visitor Locker Room	W2	CMU	White	Flaking	10	0.4	Negative
1	B	023D	Girl's Visitor Locker Room	W3	CMU	White	Flaking	16	0.5	Negative
1	B	023D	Girl's Visitor Locker Room	Metal panel	Metal	White	Chipping	2	0.2	Negative
1	B	023D	Girl's Visitor Locker Room	W4	CMU	White	Flaking	35	0.5	Negative
1	B	023D	Girl's Visitor Locker Room	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	B	023D	Girl's Visitor Locker Room	Radiator	Metal	White	Chipping	1	0.1	Negative
1	B	023D	Girl's Visitor Locker Room	Ceiling	Concrete	White	Chipping	9	0.2	Negative
1	B	023E	Girl's Visitor Locker Room Showers	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023E	Girl's Visitor Locker Room Showers	W1	ceramic	Green	None	0	2.2	Positive
1	B	023E	Girl's Visitor Locker Room Showers	W2	ceramic	Green	None	0	2.2	Positive
1	B	023E	Girl's Visitor Locker Room Showers	W3	ceramic	Green	None	0	2.2	Positive
1	B	023E	Girl's Visitor Locker Room Showers	W4	ceramic	Green	None	0	2.2	Positive
1	B	023E	Girl's Visitor Locker Room Showers	Duct	Metal	White	None	0	0.3	Negative
1	B	023E	Girl's Visitor Locker Room Showers	Ceiling	Concrete	White	None	0	0.4	Negative
1	B	023P	Girl's Visitor Locker Room Restroom	Floor	Concrete	White	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	023P	Girl's Visitor Locker Room Restroom	W1	CMU	White	Flaking	10	0.5	Negative
1	B	023P	Girl's Visitor Locker Room Restroom	Doorframe	Metal	Black	None	0	0.5	Negative
1	B	023P	Girl's Visitor Locker Room Restroom	W2	CMU	White	Flaking	11	0.5	Negative
1	B	023P	Girl's Visitor Locker Room Restroom	radiator	Metal	Tan	None	0	0.1	Negative
1	B	023P	Girl's Visitor Locker Room Restroom	W3	CMU	White	Flaking	31	0.6	Negative
1	B	023P	Girl's Visitor Locker Room Restroom	W4	CMU	White	Flaking	29	0.5	Negative
1	B	023P	Girl's Visitor Locker Room Restroom	Pipe	Metal	White	Moisture Damage	2	0.4	Negative
1	B	023P	Girl's Visitor Locker Room Restroom	Ceiling	Concrete	White	Chipping	15	0.3	Negative
1	B	023G	Girl's Home Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023G	Girl's Home Locker Room	W1	CMU	White	flaking	5	0.2	Negative
1	B	023G	Girl's Home Locker Room	W2	CMU	White	Flaking	10	0.4	Negative
1	B	023G	Girl's Home Locker Room	W3	CMU	White	Flaking	16	0.5	Negative
1	B	023G	Girl's Home Locker Room	Metal panel	Metal	White	Chipping	2	0.2	Negative
1	B	023G	Girl's Home Locker Room	W4	CMU	White	Flaking	35	0.5	Negative
1	B	023G	Girl's Home Locker Room	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
1	B	023G	Girl's Home Locker Room	Radiator	Metal	White	Chipping	1	0.1	Negative
1	B	023G	Girl's Home Locker Room	Ceiling	Concrete	White	Chipping	9	0.2	Negative
1	B	023H	Girl's Home Locker Room Showers	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	023H	Girl's Home Locker Room Showers	W1	ceramic	Green	None	0	2.2	Positive
1	B	023H	Girl's Home Locker Room Showers	W2	ceramic	Green	None	0	2.2	Positive
1	B	023H	Girl's Home Locker Room Showers	W3	ceramic	Green	None	0	2.2	Positive

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	023H	Girl's Home Locker Room Showers	W4	ceramic	Green	None	0	2.2	Positive
1	B	023H	Girl's Home Locker Room Showers	Duct	Metal	White	None	0	0.3	Negative
1	B	023H	Girl's Home Locker Room Showers	Ceiling	Concrete	White	None	0	0.4	Negative
1	B	023Q	Girl's Home Locker Room Restroom	Floor	Concrete	White	None	0	0.2	Negative
1	B	023Q	Girl's Home Locker Room Restroom	W1	CMU	White	Flaking	10	0.5	Negative
1	B	023Q	Girl's Home Locker Room Restroom	Doorframe	Metal	Black	None	0	0.5	Negative
1	B	023Q	Girl's Home Locker Room Restroom	W2	CMU	White	Flaking	11	0.5	Negative
1	B	023Q	Girl's Home Locker Room Restroom	radiator	Metal	Tan	None	0	0.1	Negative
1	B	023Q	Girl's Home Locker Room Restroom	W3	CMU	White	Flaking	31	0.6	Negative
1	B	023Q	Girl's Home Locker Room Restroom	W4	CMU	White	Flaking	29	0.5	Negative
1	B	023Q	Girl's Home Locker Room Restroom	Pipe	Metal	White	Moisture Damage	2	0.4	Negative
1	B	023Q	Girl's Home Locker Room Restroom	Ceiling	Concrete	White	Chipping	15	0.3	Negative
1	B	H025	Hallway to Girl's Locker Room Exit Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H025	Hallway to Girl's Locker Room Exit Stairwell	W1	CMU	White	Flaking	40	0.2	Negative
1	B	H025	Hallway to Girl's Locker Room Exit Stairwell	W2	CMU	White	Flaking	34	0.4	Negative
1	B	H025	Hallway to Girl's Locker Room Exit Stairwell	W3	CMU	White	Flaking	20	0.3	Negative
1	B	H025	Hallway to Girl's Locker Room Exit Stairwell	W4	CMU	White	Flaking	15	0.1	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>r</b>	<b>S</b> <b>p</b> <b>a</b> <b>c</b> <b>e</b> <b>#</b>	<b>O</b> <b>n</b> <b>-</b> <b>S</b> <b>i</b> <b>t</b> <b>e</b> <b>R</b> <b>o</b> <b>o</b> <b>m</b> <b>N</b> <b>a</b> <b>m</b> <b>e</b>	<b>C</b> <b>o</b> <b>m</b> <b>p</b> <b>o</b> <b>n</b> <b>e</b> <b>n</b> <b>t</b>	<b>S</b> <b>u</b> <b>b</b> <b>s</b> <b>t</b> <b>r</b> <b>a</b> <b>t</b> <b>e</b> <b>M</b> <b>a</b> <b>t</b> <b>e</b> <b>r</b> <b>i</b> <b>a</b> <b>l</b>	<b>C</b> <b>o</b> <b>l</b> <b>o</b> <b>r</b>	<b>D</b> <b>e</b> <b>s</b> <b>c</b> <b>r</b> <b>i</b> <b>p</b> <b>t</b> <b>i</b> <b>o</b> <b>n</b> <b>o</b> <b>f</b> <b>D</b> <b>a</b> <b>m</b> <b>a</b> <b>g</b> <b>e</b>	<b>D</b> <b>a</b> <b>m</b> <b>a</b> <b>g</b> <b>e</b> <b>Q</b> <b>u</b> <b>a</b> <b>n</b> <b>t</b> <b>i</b> <b>t</b> <b>y</b> <b>(</b> <b>s</b> <b>f</b> <b>)</b>	<b>X</b> <b>R</b> <b>F</b> <b>R</b> <b>e</b> <b>a</b> <b>d</b> <b>i</b> <b>n</b> <b>g</b> <b>(</b> <b>m</b> <b>g</b> <b>/</b> <b>c</b> <b>m</b> <b>2</b> <b>)</b>	<b>X</b> <b>R</b> <b>F</b> <b>(</b> <b>p</b> <b>o</b> <b>s</b> <b>i</b> <b>t</b> <b>i</b> <b>v</b> <b>e</b> <b>/</b> <b>n</b> <b>e</b> <b>g</b> <b>a</b> <b>t</b> <b>i</b> <b>v</b> <b>e</b> <b>)</b>
1	B	H025	Hallway to Girl's Locker Room Exit Stairwell	Ceiling	Concrete	White	Flaking	20	0.1	Negative
1	B	S023	Girl's Locker Room Exit Stairwell	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S023	Girl's Locker Room Exit Stairwell	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S023	Girl's Locker Room Exit Stairwell	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S023	Girl's Locker Room Exit Stairwell	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S023	Girl's Locker Room Exit Stairwell	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S023	Girl's Locker Room Exit Stairwell	Ceiling	Concrete	White	Flaking	6	0.2	Negative
1	B	26	Fan Room next to Girl's Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	26	Fan Room next to Girl's Locker Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	26	Fan Room next to Girl's Locker Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	26	Fan Room next to Girl's Locker Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	26	Fan Room next to Girl's Locker Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	26	Fan Room next to Girl's Locker Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	80	Custodial Closet next to Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	80	Custodial Closet next to Cafeteria	W1	CMU	White	None	0	0.3	Negative
1	B	80	Custodial Closet next to Cafeteria	Doorframe	Metal	Black	None	0	0.2	Negative
1	B	80	Custodial Closet next to Cafeteria	W2	CMU	White	Chipping	4	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	80	Custodial Closet next to Cafeteria	Shelf	Wood	White	Chipping	7	0.3	Negative
1	B	80	Custodial Closet next to Cafeteria	Ceramic Wall	Ceramic	White	Flaking	8	0.3	Negative
1	B	80	Custodial Closet next to Cafeteria	W3	CMU	White	Chipping	3	0.4	Negative
1	B	80	Custodial Closet next to Cafeteria	Electrical Panel	Metal	White	Chipping	4	0.2	Negative
1	B	80	Custodial Closet next to Cafeteria	W4	CMU	White	None	0	0.4	Negative
1	B	80	Custodial Closet next to Cafeteria	conduit	Metal	White	None	0	0.5	Negative
1	B	80	Custodial Closet next to Cafeteria	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	81	Storeroom next to Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	81	Storeroom next to Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	81	Storeroom next to Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	81	Storeroom next to Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	81	Storeroom next to Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	81	Storeroom next to Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	39	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	39	Cafeteria	W1	CMU	Grey	Cracking	26	0.5	Negative
1	B	39	Cafeteria	Baseboard	CMU/Tile	Black	Flaking	8	1	Positive
1	B	39	Cafeteria	Doorframe	Metal	Black	Chipping	15	0.1	Negative
1	B	39	Cafeteria	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	39	Cafeteria	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	39	Cafeteria	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	39	Cafeteria	Ceiling	Concrete	White	Chipping	100	0.1	Negative
1	B	039A	Cafeteria Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	039A	Cafeteria Fan Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	039A	Cafeteria Fan Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	039A	Cafeteria Fan Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	039A	Cafeteria Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	039A	Cafeteria Fan Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	42	Kitchen	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	42	Kitchen	W1	CMU	White	None	0	0.3	Negative
1	B	42	Kitchen	Door Frame	Metal	Red	Chipping	4	0.2	Negative
1	B	42	Kitchen	Door	Wood	Tan	Chipping	4	0.1	Negative
1	B	42	Kitchen	W2	CMU	White	None	0	0.4	Negative
1	B	42	Kitchen	W3	CMU	White	None	0	0.6	Negative
1	B	42	Kitchen	W3	Sheetrock	White	None	0	0.6	Negative
1	B	42	Kitchen	Door Frame	Metal	Red	Chipping	6	0.4	Negative
1	B	42	Kitchen	Door	Wood	Red	Chipping	4	0.2	Negative
1	B	42	Kitchen	W4	CMU	White	None	0	0.4	Negative
1	B	42	Kitchen	Ceiling	Concrete	White	None	0	0.4	Negative
1	B	42	Kitchen	Duct (C)	Metal	White	None	0	0.2	Negative
1	B	42A	Kitchen Office	Floor	Concrete	Brown	Chipping	25	0.3	Negative
1	B	42A	Kitchen Office	W1	CMU	White	Chipping	6	0.3	Negative
1	B	42A	Kitchen Office	Door Frame	Metal	Black	Chipping	4	0.2	Negative
1	B	42A	Kitchen Office	Door	Wood	Black	Chipping	6	0	Negative
1	B	42A	Kitchen Office	W2	CMU	White	Chipping	6	0	Negative
1	B	42A	Kitchen Office	W3	CMU	White	Chipping	4	0.3	Negative
1	B	42A	Kitchen Office	Pipe	Metal	White	Flaking	4	0.5	Negative
1	B	42A	Kitchen Office	W4	Sheetrock	White	Friction	10	0.2	Negative
1	B	42A	Kitchen Office	Duct	Metal	White	None	0	0.4	Negative
1	B	42A	Kitchen Office	Ceiling	Concrete	White	Flaking	5	0.4	Negative
1	B	42A	Kitchen Office	Pipe Insulation	Fiberglass	White	Chipping	3	0	Negative
1	B	42A	Kitchen Office	Pipe	Metal	White	Chipping	8	0.5	Negative
1	B	42A	Kitchen Office	Duct	Metal	White	None	0	0.4	Negative
1	B	42A	Kitchen Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	042C	Kitchen Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	042C	Kitchen Office Restroom	W1	Ceramic	White	None	0	0.2	Negative
1	B	042C	Kitchen Office Restroom	Baseboard	Tile	Black	None	0	1.7	Positive
1	B	042C	Kitchen Office Restroom	Doorframe	Metal	Black	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	042C	Kitchen Office Restroom	W2	CMU	White	None	0	0.3	Negative
1	B	042C	Kitchen Office Restroom	W3	CMU	White	None	0	0.3	Negative
1	B	042C	Kitchen Office Restroom	W4	CMU	White	None	0	0.3	Negative
1	B	042C	Kitchen Office Restroom	Pipe	Metal	White	None	0	0.3	Negative
1	B	042C	Kitchen Office Restroom	insulation	Fiberglass	White	None	0	0.2	Negative
1	B	042C	Kitchen Office Restroom	duct	Metal	White	None	0	0.3	Negative
1	B	042C	Kitchen Office Restroom	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	042B	Mechanical Room next to Kitchen Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042B	Mechanical Room next to Kitchen Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042B	Mechanical Room next to Kitchen Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042B	Mechanical Room next to Kitchen Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042B	Mechanical Room next to Kitchen Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042B	Mechanical Room next to Kitchen Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042D	Kitchen Storeroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042D	Kitchen Storeroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042D	Kitchen Storeroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042D	Kitchen Storeroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042D	Kitchen Storeroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	042D	Kitchen Storeroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	82	Telecom Closet next to Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	82	Telecom Closet next to Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	82	Telecom Closet next to Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	82	Telecom Closet next to Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access



			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	82	Telecom Closet next to Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	82	Telecom Closet next to Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	40	Health Classroom 005	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	40	Health Classroom 005	W1	CMU/Drywall	White	Flaking	25	0.4	Negative
1	B	40	Health Classroom 005	Door Frame	Metal	Black	Chipping	3	0.2	Negative
1	B	40	Health Classroom 005	Pipe Cover	Metal	White	Chipping	3	0.2	Negative
1	B	40	Health Classroom 005	Baseboard (W1-4)	CMU/Tile	Black	Chipping	3	1	Positive
1	B	40	Health Classroom 005	W2	CMU	White	Flaking	5	0.2	Negative
1	B	40	Health Classroom 005	W3	CMU	White	Flaking	10	0.5	Negative
1	B	40	Health Classroom 005	Pipe	Metal	White	None	0	0	Negative
1	B	40	Health Classroom 005	Radiator	Metal	Black	Chipping	3	0	Negative
1	B	40	Health Classroom 005	Door Frame	Metal	Black	Chipping	1	0.1	Negative
1	B	40	Health Classroom 005	Column	Concrete	White	Flaking	4	0.1	Negative
1	B	40	Health Classroom 005	W4	CMU	White	Flaking	5	0.4	Negative
1	B	40	Health Classroom 005	Window Frame	Metal	Black	None	0	0.1	Negative
1	B	40	Health Classroom 005	Ceiling	Concrete w/ Spline	White	Flaking	15	0.2	Negative
1	B	40A	Health Classroom Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	40A	Health Classroom Restroom	W1	Sheetrock	White	None	0	0.2	Negative
1	B	40A	Health Classroom Restroom	Door Frame	Metal	Black	None	0	0.1	Negative
1	B	40A	Health Classroom Restroom	W2	Sheetrock	White	None	0	0.2	Negative
1	B	40A	Health Classroom Restroom	W3	CMU	White	None	0	0.4	Negative
1	B	40A	Health Classroom Restroom	W4	CMU	White	None	0	0.5	Negative
1	B	40A	Health Classroom Restroom	Ceiling	Concrete	White	None	0	0.1	Negative
1	B	41	Nursing Program Classroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	41	Nursing Program Classroom	Column (Center)	Concrete	White	None	0	0.1	Negative
1	B	41	Nursing Program Classroom	W1	CMU	White	Flaking	4	0.4	Negative
1	B	41	Nursing Program Classroom	Pipe Cover	Metal	White	Chipping	2	0.2	Negative
1	B	41	Nursing Program Classroom	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	41	Nursing Program Classroom	W2	CMU/Sheetrock	White	Flaking	8	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	41	Nursing Program Classroom	Door Frame	Metal	Black	Chipping	4	0.2	Negative
1	B	41	Nursing Program Classroom	W3	CMU	White	Chipping	4	0.3	Negative
1	B	41	Nursing Program Classroom	Door Frame	Metal	Black	Flaking	2	0	Negative
1	B	41	Nursing Program Classroom	W4	CMU/Sheetrock	White	Chipping	3	0.2	Negative
1	B	41	Nursing Program Classroom	Ceiling	Concrete w/ Spline	White	Flaking	6	0.2	Negative
1	B	41	Nursing Program Classroom	Duct (C)	Metal	White	Flaking	2	0.1	Negative
1	B	041A	Nursing Program Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	041A	Nursing Program Office	W1	CMU	White	None	0	0.4	Negative
1	B	041A	Nursing Program Office	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	041A	Nursing Program Office	W2	CMU	White	None	0	0.4	Negative
1	B	041A	Nursing Program Office	W3	Sheetrock	White	None	0	0.2	Negative
1	B	041A	Nursing Program Office	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	041A	Nursing Program Office	W4	CMU	White	None	0	0.2	Negative
1	B	041A	Nursing Program Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	041A1	Nursing Program Office Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	041A1	Nursing Program Office Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	041A1	Nursing Program Office Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	041A1	Nursing Program Office Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	041A1	Nursing Program Office Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	041A1	Nursing Program Office Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	S06	Stairwell next to Health Classroom 005	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S06	Stairwell next to Health Classroom 005	W1	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S06	Stairwell next to Health Classroom 005	Doorframe	Metal	Tan	Chipping	4	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HighSchool						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	S06	Stairwell next to Health Classroom 005	Door	Metal	Grey	Friction	5	0	Negative
1	B	S06	Stairwell next to Health Classroom 005	W2	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S06	Stairwell next to Health Classroom 005	Door/Doorframe	Metal	Tan	None	0	0.3	Negative
1	B	S06	Stairwell next to Health Classroom 005	Fire Pipe	Metal	Tan	Chipping	2	0.5	Negative
1	B	S06	Stairwell next to Health Classroom 005	Conduit	Metal	Tan	Chipping	3	0.4	Negative
1	B	S06	Stairwell next to Health Classroom 005	W3	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S06	Stairwell next to Health Classroom 005	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S06	Stairwell next to Health Classroom 005	Riser	Metal	Tan	None	0	0.1	Negative
1	B	S06	Stairwell next to Health Classroom 005	Stringer	Metal	Tan	None	0	0.1	Negative
1	B	S06	Stairwell next to Health Classroom 005	baseboard	Metal	Tan	None	0	0.1	Negative
1	B	S06	Stairwell next to Health Classroom 005	Stair Pan	Metal	tan	None	0	0.6	Negative
1	B	S06	Stairwell next to Health Classroom 005	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	H03A	Robotics Wing/Nursing Program Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03A	Robotics Wing/Nursing Program Lobby	W1	CMU	White	None	0	0.3	Negative
1	B	H03A	Robotics Wing/Nursing Program Lobby	W2	CMU	White	None	0	0.4	Negative
1	B	H03A	Robotics Wing/Nursing Program Lobby	W3	CMU	White	None	0	0.2	Negative
1	B	H03A	Robotics Wing/Nursing Program Lobby	W4	CMU	White	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	H03A	Robotics Wing/Nursing Program Lobby	Ceiling	Concrete	White	None	0	0.1	Negative
1	B	38	Storeroom next to Stair 1	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	38	Storeroom next to Stair 1	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	38	Storeroom next to Stair 1	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	38	Storeroom next to Stair 1	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	38	Storeroom next to Stair 1	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	38	Storeroom next to Stair 1	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	38	Closet next to Stair 1	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	38	Closet next to Stair 1	W1	CMU	White	Flaking	11	0	Negative
1	B	38	Closet next to Stair 1	Doorframe	Metal	Black	Chipping	2	0.2	Negative
1	B	38	Closet next to Stair 1	W2	CMU	White	Flaking	25	0.5	Negative
1	B	38	Closet next to Stair 1	W3	CMU	White	Flaking	31	0.4	Negative
1	B	38	Closet next to Stair 1	W4	CMU	White	Flaking	21	0.5	Negative
1	B	38	Closet next to Stair 1	Ceiling	Concrete	White	Flaking	15	0.3	Negative
1	B	37	Custodial Closet next to Robotics Wing entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	37	Custodial Closet next to Robotics Wing entrance	W1	CMU	White	None	0	0.4	Negative
1	B	37	Custodial Closet next to Robotics Wing entrance	Doorframe	Metal	Black	Chipping	4	0.2	Negative
1	B	37	Custodial Closet next to Robotics Wing entrance	W2	CMU	White	Chipping	4	0	Negative
1	B	37	Custodial Closet next to Robotics Wing entrance	W3	CMU	White	Chipping	4	0.4	Negative
1	B	37	Custodial Closet next to Robotics Wing entrance	Metal panel	Metal	White	Chipping	4	0.1	Negative
1	B	37	Custodial Closet next to Robotics Wing entrance	Radiator	Metal	White	Chipping	2	0.2	Negative
1	B	37	Custodial Closet next to Robotics Wing entrance	W4	CMU	White	Flaking	4	0.2	Negative
1	B	37	Custodial Closet next to Robotics Wing entrance	Pipe insulation	Fiberglass	White	Cracking	4	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	37	Custodial Closet next to Robotics Wing entrance	Ceiling	Concrete	White	Flaking	15	0.2	Negative
1	B	64	Robotics Shop	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	64	Robotics Shop	W1	Sheetrock	White	None	0	0.1	Negative
1	B	64	Robotics Shop	Door Frame	Metal	Black	Chipping	1	0.2	Negative
1	B	64	Robotics Shop	Conduit (W1/4)	Metal	White	None	0	0.5	Negative
1	B	64	Robotics Shop	W2	Sheetrock	White	Flaking	2	0.2	Negative
1	B	64	Robotics Shop	W3	CMU	White	Flaking	3	0.5	Negative
1	B	64	Robotics Shop	Radiator	Metal	White	Chipping	1	0.2	Negative
1	B	64	Robotics Shop	Baseboard (W3/4)	CMU/Tile	Black	None	0	1.1	Positive
1	B	64	Robotics Shop	Pipe Cover	Metal	White	None	0	0.2	Negative
1	B	64	Robotics Shop	W4	CMU/Sheetrock	White	Flaking	5	0.4	Negative
1	B	64	Robotics Shop	Ceiling	Concrete w/ Spline	White	None	0	0.2	Negative
1	B	65	Small Classroom next to Robotics Shop	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	65	Small Classroom next to Robotics Shop	Column (Center	CMU	White	None	0	0.4	Negative
1	B	65	Small Classroom next to Robotics Shop	W1	Sheetrock	White	None	0	0.2	Negative
1	B	65	Small Classroom next to Robotics Shop	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	65	Small Classroom next to Robotics Shop	W2	Sheetrock	White	None	0	0.1	Negative
1	B	65	Small Classroom next to Robotics Shop	W3	CMU	White	None	0	0.4	Negative
1	B	65	Small Classroom next to Robotics Shop	Baseboard	CMU/Tile	Black	None	0	1	Positive
1	B	65	Small Classroom next to Robotics Shop	Radiator	Metal	White	None	0	0.2	Negative
1	B	65	Small Classroom next to Robotics Shop	Pipe Cover	Metal	White	Chipping	1	0.2	Negative
1	B	65	Small Classroom next to Robotics Shop	W4	Sheetrock	White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	65	Small Classroom next to Robotics Shop	Ceiling	Concrete w/ Spline	White	None	0	0.3	Negative
1	B	65	Small Classroom next to Robotics Shop	Pipe (C)	Metal	White	Flaking	1	0.4	Negative
1	B	65	Small Classroom next to Robotics Shop	Conduit (C)	Concrete w/ Spline	White	None	0	0.5	Negative
1	B	65A	Small Classroom Server Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	65A	Small Classroom Server Room	W1	Sheetrock	White	None	0	0.1	Negative
1	B	65A	Small Classroom Server Room	W2	Sheetrock	White	None	0	0.1	Negative
1	B	65A	Small Classroom Server Room	W3	Sheetrock	White	None	0	0.1	Negative
1	B	65A	Small Classroom Server Room	W4	Sheetrock	White	None	0	0.1	Negative
1	B	65A	Small Classroom Server Room	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	66	Robotics Classroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	66	Robotics Classroom	W1	Sheetrock	White	None	0	0.1	Negative
1	B	66	Robotics Classroom	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	66	Robotics Classroom	W2	Sheetrock	White	None	0	0.2	Negative
1	B	66	Robotics Classroom	W3	CMU	White	None	0	0.4	Negative
1	B	66	Robotics Classroom	Radiator	Metal	White	None	0	0.1	Negative
1	B	66	Robotics Classroom	Pipe Cover	Metal	White	None	0	0.2	Negative
1	B	66	Robotics Classroom	W4	Sheetrock	White	None	0	0.2	Negative
1	B	66	Robotics Classroom	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	66	Robotics Classroom	Ceiling	Concrete w/ Beam	White	None	0	0.2	Negative
1	B	66	Robotics Classroom	Conduit	Metal	White	None	0	0.4	Negative
1	B	66	Robotics Classroom	Pipe	Metal	White	None	0	0.3	Negative
1	B	066A	Robotics Classroom Restroom on Shop side	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	066A	Robotics Classroom Restroom on Shop side	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	066A	Robotics Classroom Restroom on Shop side	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	066A	Robotics Classroom Restroom on Shop side	W2	Sheetrock	White	None	0	0.1	Negative
1	B	066A	Robotics Classroom Restroom on Shop side	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	066A	Robotics Classroom Restroom on Shop side	W4	CMU	White	None	0	0.5	Negative
1	B	066A	Robotics Classroom Restroom on Shop side	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	066B	Robotics Classroom Restroom on former Kitchen side	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	066B	Robotics Classroom Restroom on former Kitchen side	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	066B	Robotics Classroom Restroom on former Kitchen side	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	066B	Robotics Classroom Restroom on former Kitchen side	W2	Sheetrock	White	None	0	0.1	Negative
1	B	066B	Robotics Classroom Restroom on former Kitchen side	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	066B	Robotics Classroom Restroom on former Kitchen side	W4	CMU	White	None	0	0.5	Negative
1	B	066B	Robotics Classroom Restroom on former Kitchen side	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	066C	Robotics Classroom Closet on former Kitchen side	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	066C	Robotics Classroom Closet on former Kitchen side	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	066C	Robotics Classroom Closet on former Kitchen side	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	066C	Robotics Classroom Closet on former Kitchen side	W2	Sheetrock	White	None	0	0.1	Negative



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	066C	Robotics Classroom Closet on former Kitchen side	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	066C	Robotics Classroom Closet on former Kitchen side	W4	CMU	White	None	0	0.5	Negative
1	B	066C	Robotics Classroom Closet on former Kitchen side	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	066D	Robotics Classroom Closet on Shop side	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	066D	Robotics Classroom Closet on Shop side	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	066D	Robotics Classroom Closet on Shop side	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	066D	Robotics Classroom Closet on Shop side	W2	Sheetrock	White	None	0	0.1	Negative
1	B	066D	Robotics Classroom Closet on Shop side	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	066D	Robotics Classroom Closet on Shop side	W4	CMU	White	None	0	0.5	Negative
1	B	066D	Robotics Classroom Closet on Shop side	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	H03	Hallway from Robotics Shop to Former Childcare Kitchen	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	H03	Hallway from Robotics Shop to Former Childcare Kitchen	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	H03	Hallway from Robotics Shop to Former Childcare Kitchen	W2	Sheetrock	White	None	0	0.1	Negative
1	B	H03	Hallway from Robotics Shop to Former Childcare Kitchen	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	H03	Hallway from Robotics Shop to Former Childcare Kitchen	W4	CMU	White	None	0	0.5	Negative
1	B	H03	Hallway from Robotics Shop to Former Childcare Kitchen	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	30	Former Childcare Kitchen - Main Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	30	Former Childcare Kitchen - Main Area	W1	CMU/Sheetrock	White	None	0	0.9	Positive
1	B	30	Former Childcare Kitchen - Main Area	Baseboard (W1-4)	CMU/Tile	Black	None	0	0.4	Negative
1	B	30	Former Childcare Kitchen - Main Area	W2	CMU	White	Flaking	8	0.4	Negative
1	B	30	Former Childcare Kitchen - Main Area	Column	Concrete	White	Flaking	3	0.1	Negative
1	B	30	Former Childcare Kitchen - Main Area	Pipe Cover	Metal	White	Chipping	2	0.2	Negative
1	B	30	Former Childcare Kitchen - Main Area	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	30	Former Childcare Kitchen - Main Area	Radiator	Metal	White	Flaking	4	0.1	Negative
1	B	30	Former Childcare Kitchen - Main Area	W3	CMU	White	Flaking	8	0.4	Negative
1	B	30	Former Childcare Kitchen - Main Area	W3	Sheetrock	White	None	0	0.1	Negative
1	B	30	Former Childcare Kitchen - Main Area	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	30	Former Childcare Kitchen - Main Area	W4	CMU/Sheetrock	White	None	0	0.1	Negative
1	B	30	Former Childcare Kitchen - Main Area	Ceiling	Concrete	White	Flaking	2	0.1	Negative
1	B	30	Former Childcare Kitchen - Main Area	Duct (C)	Metal	White	Flaking	3	0.1	Negative
1	B	030A	Former Childcare Kitchen - Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	030A	Former Childcare Kitchen - Restroom	W1	CMU	White	None	0	0.2	Negative
1	B	030A	Former Childcare Kitchen - Restroom	Door Frame	Metal	Black	Chipping	1	0.2	Negative
1	B	030A	Former Childcare Kitchen - Restroom	W2	CMU	White	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia HighSchool</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	030A	Former Childcare Kitchen - Restroom	W3	CMU	White	None	0	0.4	Negative
1	B	030A	Former Childcare Kitchen - Restroom	W4	CMU	White	None	0	0.2	Negative
1	B	030A	Former Childcare Kitchen - Restroom	Ceiling	Concrete	White	Flaking	2	0.2	Negative
1	B	30B	Server Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	30B	Server Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	30B	Server Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	30B	Server Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	30B	Server Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	30B	Server Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	30C	Former Childcare Kitchen - Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	30C	Former Childcare Kitchen - Kitchen	W1	CMU	White	None	0	0.2	Negative
1	B	30C	Former Childcare Kitchen - Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	30C	Former Childcare Kitchen - Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	30C	Former Childcare Kitchen - Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	30C	Former Childcare Kitchen - Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	30C	Former Childcare Kitchen - Kitchen	Ceiling	Concrete	White	Flaking	2	0.2	Negative
1	B	30D	Former Childcare Kitchen - Storeroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	30D	Former Childcare Kitchen - Storeroom	W1	CMU	White	None	0	0.2	Negative
1	B	30D	Former Childcare Kitchen - Storeroom	Door Frame	Metal	Black	Chipping	1	0.2	Negative
1	B	30D	Former Childcare Kitchen - Storeroom	W2	CMU	White	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia HighSchool</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	30D	Former Childcare Kitchen - Storeroom	W3	CMU	White	None	0	0.4	Negative
1	B	30D	Former Childcare Kitchen - Storeroom	W4	CMU	White	None	0	0.2	Negative
1	B	30D	Former Childcare Kitchen - Storeroom	Ceiling	Concrete	White	Flaking	2	0.2	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S03	Stairwell next to former Childcare Kitchen	W1	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S03	Stairwell next to former Childcare Kitchen	Doorframe	Metal	Tan	Chipping	4	0.1	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	Door	Metal	Grey	Friction	5	0	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	W2	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S03	Stairwell next to former Childcare Kitchen	Door/Doorframe	Metal	Tan	None	0	0.3	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	Fire Pipe	Metal	Tan	Chipping	2	0.5	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	Conduit	Metal	Tan	Chipping	3	0.4	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	W3	ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S03	Stairwell next to former Childcare Kitchen	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	S03	Stairwell next to former Childcare Kitchen	Riser	Metal	Tan	None	0	0.1	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	Stringer	Metal	Tan	None	0	0.1	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	baseboard	Metal	Tan	None	0	0.1	Negative
1	B	S03	Stairwell next to former Childcare Kitchen	Stair Pan	Metal	tan	None	0	0.6	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	S03	Stairwell next to former Childcare Kitchen	Ceiling	Concrete	White	None	0	0.3	Negative
1	B	31	Storeroom across from Former Childcare Kitchen	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	31	Storeroom across from Former Childcare Kitchen	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	31	Storeroom across from Former Childcare Kitchen	Door Frame	Metal	Black	None	0	0.2	Negative
1	B	31	Storeroom across from Former Childcare Kitchen	W2	Sheetrock	White	None	0	0.1	Negative
1	B	31	Storeroom across from Former Childcare Kitchen	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	B	31	Storeroom across from Former Childcare Kitchen	W4	CMU	White	None	0	0.5	Negative
1	B	31	Storeroom across from Former Childcare Kitchen	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	W1	CMU	White	Flaking	5	0.5	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Door	Metal	Black	None	0	0	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Door Frame	Metal	Black	None	0	0.1	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	W2	CMU	White	Flaking	25	0.5	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Radiator	Metal	Tan	None	0	0	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Baseboard (W2/4)	CMU/Tile	Black	None	0	1.1	Positive
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Door Frame (Elev)	Metal	Black	None	0	0.1	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	W3	CMU	White	Flaking	5	0.5	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	W4	CMU	White	Flaking	15	0.4	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Door Frame	Metal	Black	Chipping	3	0.3	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Door	Wood	Black	Chipping	3	0.1	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Conduit (W4/C)	Metal	White	None	0	1.6	Positive
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Electrical Panel	Metal	Black	None	0	0.2	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Conduit	Metal	White	None	0	0.5	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Pipe	Metal	White	None	0	1.1	Positive
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Radiator	Metal	Tan	None	0	0.2	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Column	Sheetrock/Plaster	White	None	0	0.1	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Window Frame	Metal	Black	Chipping	12	0	Negative
1	B	H02	Hallway from Night Engineer's Storeroom to Cafeteria	Ceiling	Concrete w/ Spline	White	None	0	0.2	Negative
1	B	36	Boy's Restroom across from Cafeteria	Floor	Concrete	Grey	Chipping	10	0.4	Negative
1	B	36	Boy's Restroom across from Cafeteria	W1	Plaster	White	None	0	0.2	Negative
1	B	36	Boy's Restroom across from Cafeteria	W1	Tile	Green	None	0	2.6	Positive
1	B	36	Boy's Restroom across from Cafeteria	Radiator	Metal	White	None	0	0.2	Negative
1	B	36	Boy's Restroom across from Cafeteria	Door Frame	Metal	Tan	Chipping	4	0.3	Negative
1	B	36	Boy's Restroom across from Cafeteria	W2	Plaster	White	None	0	0.4	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	36	Boy's Restroom across from Cafeteria	W2	Tile	Green	None	0	2.6	Positive
1	B	36	Boy's Restroom across from Cafeteria	Conduit	Metal	White	None	0	0.5	Negative
1	B	36	Boy's Restroom across from Cafeteria	Duct	Metal	White	None	0	0.3	Negative
1	B	36	Boy's Restroom across from Cafeteria	W3	Plaster	White	Flaking	1	0.4	Negative
1	B	36	Boy's Restroom across from Cafeteria	W3	Tile	Green	None	0	2.6	Positive
1	B	36	Boy's Restroom across from Cafeteria	W4	Plaster	White	None	0	0.4	Negative
1	B	36	Boy's Restroom across from Cafeteria	W4	Tile	Green	None	0	2.6	Positive
1	B	36	Boy's Restroom across from Cafeteria	Stall Partition	Transite	Blue	None	0	0.8	Positive
1	B	36	Boy's Restroom across from Cafeteria	Ceiling	Concrete	White	None	0	0.2	Negative
1	B	35	Male Cleaners' Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	35	Male Cleaners' Locker Room	W1	CMU	White	Flaking	10	0.3	Negative
1	B	35	Male Cleaners' Locker Room	Door Frame	Metal	White/Black	Flaking	6	0.1	Negative
1	B	35	Male Cleaners' Locker Room	W2	CMU	White	Flaking	7	0.1	Negative
1	B	35	Male Cleaners' Locker Room	Wall Tile	Ceramic	Blue	Chipping	6	0.1	Negative
1	B	35	Male Cleaners' Locker Room	Stall Divider	Metal	Tan	Flaking	16	0.1	Negative
1	B	35	Male Cleaners' Locker Room	W3	CMU	White	Flaking	6	0.4	Negative
1	B	35	Male Cleaners' Locker Room	Locker	Metal	Black/Blue	Chipping	16	0	Negative
1	B	35	Male Cleaners' Locker Room	W4	CMU	White	Flaking	6	0.2	Negative
1	B	35	Male Cleaners' Locker Room	Radiator	Metal	White	Chipping	3	0.1	Negative
1	B	35	Male Cleaners' Locker Room	Chase Panel (To Girls)	Metal	White	Chipping	2	0	Negative
1	B	35	Male Cleaners' Locker Room	Ceiling	Concrete	White	Flaking	30	0.2	Negative
1	B	34	Female Cleaners' Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	34	Female Cleaners' Locker Room	W1	CMU	Blue	Flaking	5	0.2	Negative
1	B	34	Female Cleaners' Locker Room	Duct	Metal	White	None	0	0.3	Negative
1	B	34	Female Cleaners' Locker Room	Door	Wood	White/Black	Flaking	12	0.1	Negative
1	B	34	Female Cleaners' Locker Room	Door Frame	Metal	Black	Flaking	10	0.4	Negative
1	B	34	Female Cleaners' Locker Room	Baseboard	CMU/Tile	Black	Friction	20	1.4	Positive
1	B	34	Female Cleaners' Locker Room	W2	CMU	White	Flaking	2	0.2	Negative
1	B	34	Female Cleaners' Locker Room	Chase Door Frame	Metal	Blue	Flaking	6	0.2	Negative
1	B	34	Female Cleaners' Locker Room	Baseboard	CMU/Tile	Black	Friction	20	1.4	Positive
1	B	34	Female Cleaners' Locker Room	W3	CMU	White	None	0	0.4	Negative
1	B	34	Female Cleaners' Locker Room	Baseboard	CMU/Tile	Black	Friction	20	1.4	Positive
1	B	34	Female Cleaners' Locker Room	W4	CMU	White	Flaking	2	0.3	Negative
1	B	34	Female Cleaners' Locker Room	Baseboard	CMU/Tile	Black	Friction	20	1.4	Positive
1	B	34	Female Cleaners' Locker Room	Ceiling	Concrete	White	Flaking	2	0.3	Negative
1	B	34	Female Cleaners' Locker Room	Pipe Insulation	Fiberglass	Blue	Chipping	1	0.2	Negative
1	B	034A	Female Cleaners' Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	034A	Female Cleaners' Restroom	W1	CMU	White	Moisture Damage	5	0.3	Negative
1	B	034A	Female Cleaners' Restroom	Wall Tile	Ceramic	Gray/Red	None	0	0.3	Negative
1	B	034A	Female Cleaners' Restroom	Door Frame	Metal	Black	Chipping	3	0.2	Negative
1	B	034A	Female Cleaners' Restroom	W2	CMU	White	Moisture Damage	4	0.3	Negative
1	B	034A	Female Cleaners' Restroom	Wall Tile	Ceramic	Gray/Red	None	0	0.3	Negative

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	B	034A	Female Cleaners' Restroom	Duct	MEtal	White	Chipping	2	0.2	Negative
1	B	034A	Female Cleaners' Restroom	W3	CMU	White	Cracking	6	0.4	Negative
1	B	034A	Female Cleaners' Restroom	Wall Tile	Ceramic	Gray/Red	None	0	0.3	Negative
1	B	034A	Female Cleaners' Restroom	W4	CMU	White	Cracking	9	0.3	Negative
1	B	034A	Female Cleaners' Restroom	Wall Tile	Ceramic	Gray/Red	None	0	0.3	Negative
1	B	034A	Female Cleaners' Restroom	Radiator	Metal	White	Chipping	3	0.1	Negative
1	B	034A	Female Cleaners' Restroom	Ceiling	Concrete	White	Flaking	12	0.2	Negative
1	B	33	Girl's Restroom across from Cafeteria	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	B	33	Girl's Restroom across from Cafeteria	W1	Tile	Tan	None	0	0.2	Negative
1	B	33	Girl's Restroom across from Cafeteria	Door	Wood	Blue	Chipping	2	0.1	Negative
1	B	33	Girl's Restroom across from Cafeteria	Door Frame	Metal	Blue	Chipping	1	0.2	Negative
1	B	33	Girl's Restroom across from Cafeteria	Partition (W1/2)	Transite	Blue	None	0	0.7	Positive
1	B	33	Girl's Restroom across from Cafeteria	Baseboard (W1-4)	CMU/Tile	Black	None	0	1	Positive
1	B	33	Girl's Restroom across from Cafeteria	Radiator	Metal	White	None	0	0	Negative
1	B	33	Girl's Restroom across from Cafeteria	W2	Tile	Tan	None	0	0.2	Negative
1	B	33	Girl's Restroom across from Cafeteria	W3	Tile	Tan	None	0	0.2	Negative
1	B	33	Girl's Restroom across from Cafeteria	W4	Tile	Tan	None	0	0.2	Negative
1	B	33	Girl's Restroom across from Cafeteria	Conduit	Metal	White	None	0	0.5	Negative
1	B	33	Girl's Restroom across from Cafeteria	Duct	Metal	White	None	0	0.3	Negative
1	B	33	Girl's Restroom across from Cafeteria	Ceiling	Concrete	White	None	0	0.1	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	33	Girl's Restroom across from Cafeteria	Pipe	Metal	White	None	0	0.3	Negative
1	SB	6	Storage Room next to Boiler Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	6	Storage Room next to Boiler Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	6	Storage Room next to Boiler Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	6	Storage Room next to Boiler Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	6	Storage Room next to Boiler Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	6	Storage Room next to Boiler Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	7	Tank Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	7	Tank Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	7	Tank Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	7	Tank Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	7	Tank Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	7	Tank Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	8	Incinerator Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	8	Incinerator Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	8	Incinerator Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	8	Incinerator Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	8	Incinerator Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	8	Incinerator Room	Column	Concrete	Gray/White	Flaking	40	0.3	Negative
1	SB	8	Incinerator Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17B	Boiler Control Room Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17B	Boiler Control Room Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17B	Boiler Control Room Storage Closet	Door Frame	Metal	Black	None	0	0.2	Negative

			Dates: 7/11 - 8/31/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia High School						
			Inspection Company: BATTA	2101 S Broad St, Philadelphia, PA 19148						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	17B	Boiler Control Room Storage Closet	Door	Wood	Black	None	0	0.2	Negative
1	B	17B	Boiler Control Room Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17B	Boiler Control Room Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17B	Boiler Control Room Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	17B	Boiler Control Room Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	10	Boiler Room	Floor	Concrete	Black	Flaking	40	0	Negative
1	SB	10	Boiler Room	W1	CMU	Gray/White	Flaking	90	0.3	Negative
1	SB	10	Boiler Room	Stairtread	Metal	Black	Chipping	185	0.1	Negative
1	SB	10	Boiler Room	Stairstringer	Metal	Black	Chipping	80	0.2	Negative
1	SB	10	Boiler Room	Stair Railing	Metal	Black	Friction	290	0.3	Negative
1	SB	10	Boiler Room	Door Frame	Metal	Black	None	0	0.3	Negative
1	SB	10	Boiler Room	Door	Wood	Black	None	0	0.3	Negative
1	SB	10	Boiler Room	W2	CMU	Black	Flaking	40	0.3	Negative
1	SB	10	Boiler Room	Curb	Concrete	Black	Flaking	20	0.1	Negative
1	SB	10	Boiler Room	Walkway	Concrete	Black	Flaking	40	0.3	Negative
1	SB	10	Boiler Room	W3	Brick	Gray/White	Flaking	300	0.2	Negative
1	SB	10	Boiler Room	Stairstringer	Metal	Black	Chipping	80	0.2	Negative
1	SB	10	Boiler Room	Stair Railing	Metal	Black	Friction	290	0.3	Negative
1	SB	10	Boiler Room	Stairtread	Metal	Black	Chipping	185	0.1	Negative
1	SB	10	Boiler Room	Water Tank	Metal	Gray/White	Flaking	150	6.7	Positive
1	SB	10	Boiler Room	Water Tank B	Metal	White	Flaking	120	7.6	Positive
1	SB	10	Boiler Room	W4	CMU/Concrete	Gray/White	Flaking	200	0.3	Negative
1	SB	10	Boiler Room	Stairtread	Metal	Black	Chipping	185	0.1	Negative
1	SB	10	Boiler Room	Stairstringer	Metal	Black	Chipping	80	0.2	Negative
1	SB	10	Boiler Room	Stair Railing	Metal	Black	Friction	290	0.3	Negative
1	SB	10	Boiler Room	Ceiling	Concrete	White	Flaking	240	0.5	Negative
1	SB	S01	Stairwell from Boiler Room up to 13th Street	Floor	Metal	N/A	N/A	N/A	N/A	N/A

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATTA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	SB	S01	Stairwell from Boiler Room up to 13th Street	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	S01	Stairwell from Boiler Room up to 13th Street	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	S01	Stairwell from Boiler Room up to 13th Street	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	S01	Stairwell from Boiler Room up to 13th Street	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	SB	S01	Stairwell from Boiler Room up to 13th Street	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Auditorium Attic accessible on 3rd Floor Hallway	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic accessible on 3rd Floor Hallway	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic accessible on 3rd Floor Hallway	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic accessible on 3rd Floor Hallway	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic accessible on 3rd Floor Hallway	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic accessible on 3rd Floor Hallway	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace adjacent to Girl's Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace adjacent to Girl's Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace adjacent to Girl's Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace adjacent to Girl's Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace adjacent to Girl's Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace adjacent to Girl's Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>S</b> <b>p</b> <b>a</b> <b>c</b> <b>e</b> <b>#</b>	<b>O</b> <b>n</b> <b>-</b> <b>S</b> <b>i</b> <b>t</b> <b>e</b> <b>R</b> <b>o</b> <b>o</b> <b>m</b> <b>N</b> <b>a</b> <b>m</b> <b>e</b>	<b>C</b> <b>o</b> <b>m</b> <b>p</b> <b>o</b> <b>n</b> <b>e</b> <b>n</b> <b>t</b>	<b>S</b> <b>u</b> <b>b</b> <b>s</b> <b>t</b> <b>r</b> <b>a</b> <b>t</b> <b>e</b> <b>M</b> <b>a</b> <b>t</b> <b>e</b> <b>r</b> <b>i</b> <b>a</b> <b>l</b>	<b>C</b> <b>o</b> <b>l</b> <b>o</b> <b>r</b>	<b>D</b> <b>e</b> <b>s</b> <b>c</b> <b>r</b> <b>i</b> <b>p</b> <b>t</b> <b>i</b> <b>o</b> <b>n</b> <b>o</b> <b>f</b> <b>D</b> <b>a</b> <b>m</b> <b>a</b> <b>g</b> <b>e</b>	<b>D</b> <b>a</b> <b>m</b> <b>a</b> <b>g</b> <b>e</b> <b>Q</b> <b>u</b> <b>a</b> <b>n</b> <b>t</b> <b>i</b> <b>t</b> <b>y</b> <b>(</b> <b>s</b> <b>f</b> <b>)</b>	<b>X</b> <b>R</b> <b>F</b> <b>R</b> <b>e</b> <b>a</b> <b>d</b> <b>i</b> <b>n</b> <b>g</b> <b>(</b> <b>m</b> <b>g</b> <b>/</b> <b>c</b> <b>m</b> <b>2</b> <b>)</b>	<b>X</b> <b>R</b> <b>F</b> <b>(</b> <b>p</b> <b>o</b> <b>s</b> <b>i</b> <b>t</b> <b>i</b> <b>v</b> <b>e</b> <b>/</b> <b>n</b> <b>e</b> <b>g</b> <b>a</b> <b>t</b> <b>i</b> <b>v</b> <b>e</b> <b>)</b>
1	PH	PH2	Penthouse 2 accessible by Rooftop	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH2	Penthouse 2 accessible by Rooftop	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH2	Penthouse 2 accessible by Rooftop	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH2	Penthouse 2 accessible by Rooftop	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH2	Penthouse 2 accessible by Rooftop	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH2	Penthouse 2 accessible by Rooftop	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH1	Penthouse 1 accessible by Rooftop	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH1	Penthouse 1 accessible by Rooftop	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH1	Penthouse 1 accessible by Rooftop	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH1	Penthouse 1 accessible by Rooftop	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH1	Penthouse 1 accessible by Rooftop	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH1	Penthouse 1 accessible by Rooftop	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH3	Penthouse 3 accessible by Rooftop	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH3	Penthouse 3 accessible by Rooftop	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH3	Penthouse 3 accessible by Rooftop	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH3	Penthouse 3 accessible by Rooftop	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	PH	PH3	Penthouse 3 accessible by Rooftop	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	PH	PH3	Penthouse 3 accessible by Rooftop	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic accessible by 3rd Floor Hallway	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic accessible by 3rd Floor Hallway	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic accessible by 3rd Floor Hallway	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic accessible by 3rd Floor Hallway	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic accessible by 3rd Floor Hallway	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic accessible by 3rd Floor Hallway	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Auditorium Attic	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Ash Pit - East Crawlspace	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Ash Pit - East Crawlspace	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Ash Pit - East Crawlspace	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Ash Pit - East Crawlspace	W3	No Access	No Access	No Access	No Access	No Access	No Access



			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	C	CS	Crawlspace under Basement adjacent to Ash Pit - East Crawlspace	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Ash Pit - East Crawlspace	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Basement Hallway-West crawlspace	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Basement Hallway-West crawlspace	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Basement Hallway-West crawlspace	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Basement Hallway-West crawlspace	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Basement Hallway-West crawlspace	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Basement Hallway-West crawlspace	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Pump Area	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 7/11 - 8/31/2022	<b>Lead-Safe Certification Assessment Report</b>						
			Inspector Name and Certificate Number: Charles Rhodes 003542	<b>South Philadelphia High School</b>						
			Inspection Company: BATA	<b>2101 S Broad St, Philadelphia, PA 19148</b>						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Pump Area	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Pump Area	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Pump Area	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Pump Area	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawlspace under Basement adjacent to Boiler Room/Pump Area	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic adjacent to 3rd Floor Library	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic adjacent to 3rd Floor Library	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic adjacent to 3rd Floor Library	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic adjacent to 3rd Floor Library	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic adjacent to 3rd Floor Library	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT	Attic adjacent to 3rd Floor Library	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access