

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	"Exit 2" Stairwell Next to Boys' Restroom	W1	Brick	Beige	Cracking	2	5	Positive
1	1	"Exit 2" Stairwell Next to Boys' Restroom	W2	Brick	Beige	Flaking	3	2.83	Positive
1	1	"Exit 2" Stairwell Next to Boy's Restroom	W3	Brick	Beige	Flaking	15	0.18	Negative
1	1	"Exit 2" Stairwell Next to Boy's Restroom	W4	Brick	Beige	None	N/A	0	Negative
1	1	"Exit 2" Stairwell Next to Boy's Restroom	Ceiling	Concrete	Beige	None	N/A	N/A	N/A
1	1	"Exit 2" Stairwell Next to Boy's Restroom	Floor	Concrete	Gray	None	N/A	0.01	Negative
1	1	"Exit 2" Stairwell Next to Boy's Restroom	Railing	Metal	Black	Chipping	20	0.7	Positive
1	1	"Exit 2" Stairwell Next to Boy's Restroom	Staircase	Concrete	Gray	None	N/A	0.17	Negative
1	1	Boys' Restroom next to Elevator	W1	Concrete	Beige / Blue	Chipping	1	0	Negative
1	1	Boys' Restroom next to Elevator	W2	Brick	Beige	Chipping	8	2.58	Positive
1	1	Boys' Restroom next to Elevator	W3	Brick	Beige / Blue	Chipping	1	2.38	Positive
1	1	Boys' Restroom next to Elevator	W4	Brick	Beige / Blue	Chipping	10	2.48	Positive
1	1	Boys' Restroom next to Elevator	Ceiling	Concrete	White	Flaking	5	No Access	No Access
1	1	Boys' Restroom next to Elevator	Floor	Concrete	Gray	Friction	3	0.7	Positive
1	1	Stairwell near Elevator	W1	Concrete	Green / Blue / Beige	Friction	1	0	Negative
1	1	Stairwell near Elevator	W2	Brick	Green / Blue / Beige	Friction	1	0.03	Negative
1	1	Stairwell near Elevator	W3	Concrete	Green / Blue / Beige	Friction	1	0.04	Negative
1	1	Stairwell near Elevator	W4	Concrete	Green / Blue / Beige	Friction	1	0	Negative
1	1	Stairwell near Elevator	Ceiling	Metal	Beige	Moisture Damage	2	No Access	No Access
1	1	Stairwell near Elevator	Floor	Concrete	Gray	Friction	1	0	Negative
1	1	Stairwell near Elevator	Railing	Metal	Black	Friction	20	0.03	Negative
1	1	Classroom 101	W1	Concrete	Light Green	None	0	0	Negative
1	1	Classroom 101	W2	Concrete / Brick	Light Green / White	Efflorescence	1	5	Positive
1	1	Classroom 101	W3	Concrete	Light Green	None	0	N/A	N/A
1	1	Classroom 101	W4	Concrete	Light Green	None	0	N/A	N/A
1	1	Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1st Floor Staff Lounge to Left of Boiler Room	W1	Concrete	Beige	None	0	N/A	N/A

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report							
		Inspection Company: REPSG	Feltonville Intermediate School							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	1st Floor Staff Lounge to Left of Boiler Room	W2	Concrete	Beige	None	0	0.05	Negative	
1	1	1st Floor Staff Lounge to Left of Boiler Room	W3	Concrete	Beige	None	0	N/A	N/A	
1	1	1st Floor Staff Lounge to Left of Boiler Room	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	1st Floor Staff Lounge to Left of Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	1st Floor Staff Lounge to Left of Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Office between 151A and 152A	W1	Concrete	Beige	None	0	N/A	N/A	
1	1	Office between 151A and 152A	W2	Concrete	Beige	None	0	N/A	N/A	
1	1	Office between 151A and 152A	W3	Concrete	Beige	Friction	1	2.3	Positive	
1	1	Office between 151A and 152A	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	Office between 151A and 152A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Office between 151A and 152A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	ECS OST Office to Left of 1st Floor Staff Lounge	W1	Concrete	Beige	None	0	N/A	N/A	
1	1	ECS OST Office to Left of 1st Floor Staff Lounge	W2	Concrete	Beige	None	0	N/A	N/A	
1	1	ECS OST Office to Left of 1st Floor Staff Lounge	W3	Concrete	Beige	None	0	N/A	N/A	
1	1	ECS OST Office to Left of 1st Floor Staff Lounge	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	ECS OST Office to Left of 1st Floor Staff Lounge	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	ECS OST Office to Left of 1st Floor Staff Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	ECS OST Program Director's Office to right of classroom 101	W1	Concrete	Beige	None	0	N/A	N/A	
1	1	ECS OST Program Director's Office to right of classroom 101	W2	Concrete	Beige	None	0	N/A	N/A	
1	1	ECS OST Program Director's Office to right of classroom 101	W3	Concrete	Beige	None	0	N/A	N/A	
1	1	ECS OST Program Director's Office to right of classroom 101	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	ECS OST Program Director's Office to right of classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	ECS OST Program Director's Office to right of classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Assistant Principal's Office	W1	Concrete	Beige	None	0	N/A	N/A	
1	1	Assistant Principal's Office	W2	Concrete	Beige	None	0	N/A	N/A	
1	1	Assistant Principal's Office	W3	Concrete / Brick	Beige	None	0	N/A	N/A	
1	1	Assistant Principal's Office	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	Assistant Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Assistant Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Main Office Conference Room	W1	Concrete	Beige	None	0	N/A	N/A	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report							
		Inspection Company: REPSG	Feltonville Intermediate School							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Main Office Conference Room	W2	Concrete	Beige	None	0	N/A	N/A	
1	1	Main Office Conference Room	W3	Concrete	Beige	None	0	N/A	N/A	
1	1	Main Office Conference Room	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	Main Office Conference Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Main Office Conference Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Principal's Office	W1	Concrete	Powder Blue	None	0	N/A	N/A	
1	1	Principal's Office	W2	Sheetrock / Brick	Powder Blue	Moisture Damage	2	0.068	Negative	
1	1	Principal's Office	W3	Concrete	Powder Blue	None	0	N/A	N/A	
1	1	Principal's Office	W4	Concrete	Powder Blue	None	0	N/A	N/A	
1	1	Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Principal's Office	Window Sill	Wood	Gray	Friction	1	3.71	Positive	
1	1	Principal's Restroom	W1	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Principal's Restroom	W2	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Principal's Restroom	W3	Concrete / Brick	Beige	Cracking	1	0.94	Positive	
1	1	Principal's Restroom	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	Principal's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Principal's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Main Office Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Main Office Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Main Office Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Main Office Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Main Office Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Main Office Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	IT/Date room	W1	No Access	White/Tan	No Access	No Access	No Access	No Access	
1	1	IT/Date room	W2	No Access	White/Tan	No Access	No Access	No Access	No Access	
1	1	IT/Date room	W3	No Access	White/Tan	No Access	No Access	No Access	No Access	
1	1	IT/Date room	W4	No Access	White/Tan	No Access	No Access	No Access	No Access	
1	1	IT/Date room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	IT/Date room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Parent Resource Center Office near Main Office Entrance	W1	Concrete	Beige	None	0	0	Negative	
1	1	Parent Resource Center Office near Main Office Entrance	W2	Concrete	Beige	None	0	N/A	N/A	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Parent Resource Center Office near Main Office Entrance	W3	Concrete	Beige	None	0	N/A	N/A
1	1	Parent Resource Center Office near Main Office Entrance	W4	Concrete / Brick	Beige	Chipping	4	0.24	Negative
1	1	Parent Resource Center Office near Main Office Entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Parent Resource Center Office near Main Office Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Parent Resource Center Office near Main Office Entrance	Window Frame	Wood	Tan	Chipping	2	3.28	Positive
1	1	Parent Resource Center Office near Main Office Entrance	Radiator	Metal	Silver	Chipping	4	1.34	Positive
1	1	Main Office	W1	Concrete	Beige	None	0	N/A	N/A
1	1	Main Office	W2	Concrete / Brick	Beige	Chipping	15	0	Negative
1	1	Main Office	W3	Sheetrock / Concrete	Beige	None	0	N/A	N/A
1	1	Main Office	W4	Concrete	Beige	None	0	N/A	N/A
1	1	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	Window Sill	Wood	Tan	Chipping	1	1.88	Positive
1	1	Nurse's Restroom	W1	Concrete	Beige	None	0	N/A	N/A
1	1	Nurse's Restroom	W2	Brick	Beige	Chipping	10	0.771	Positive
1	1	Nurse's Restroom	W3	Concrete	Beige	None	0	N/A	N/A
1	1	Nurse's Restroom	W4	Concrete	Beige	None	0	N/A	N/A
1	1	Nurse's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Restroom	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Nurse's Office	W1	Concrete	Beige	None	0	N/A	N/A
1	1	Nurse's Office	W2	Concrete	Beige	None	0	N/A	N/A
1	1	Nurse's Office	W3	Concrete	Blue	None	0	N/A	N/A
1	1	Nurse's Office	W4	Brick	Beige	Chipping	4	0.717	Positive
1	1	Nurse's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office	Radiator	Metal	Silver	Chipping	10	3.15	Positive
1	1	Counselor's Office	W1	Concrete	Beige	None	0	N/A	N/A
1	1	Counselor's Office	W2	Concrete	Beige	None	0	N/A	N/A
1	1	Counselor's Office	W3	Concrete	Beige	None	0	N/A	N/A

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	<b>School District of Philadelphia</b>							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	<b>Lead Safe Certification Assessment Report</b>							
		Inspection Company: REPSG	<b>Feltonville Intermediate School</b>							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Counselor's Office	W4	Concrete / Brick	Beige	Chipping	4	0.701	Positive	
1	1	Counselor's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Counselor's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Counselor's Office	Radiator	Metal	Silver	Chipping	10	1.504	Positive	
1	1	Psychologist	W1	Concrete	Beige / Multi	None	0	N/A	N/A	
1	1	Psychologist	W2	Concrete	Beige / Multi	None	0	N/A	N/A	
1	1	Psychologist	W3	Concrete	Beige / Multi	None	0	N/A	N/A	
1	1	Psychologist	W4	Concrete	Beige / Multi	None	0	N/A	N/A	
1	1	Psychologist	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Psychologist	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Office across from Girl's Restroom adjacent to Auditorium	W1	Concrete	Beige	None	0	0	Negative	
1	1	Office across from Girl's Restroom adjacent to Auditorium	W2	Concrete	Beige	None	0	N/A	N/A	
1	1	Office across from Girl's Restroom adjacent to Auditorium	W3	Concrete	Beige	None	0	N/A	N/A	
1	1	Office across from Girl's Restroom adjacent to Auditorium	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	Office across from Girl's Restroom adjacent to Auditorium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Office across from Girl's Restroom adjacent to Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Custodial Closet inside Girl's Restroom near Auditorium	W1	Concrete	Pink / Beige	None	0	N/A	N/A	
1	1	Custodial Closet inside Girl's Restroom near Auditorium	W2	Concrete	Pink / Beige	None	0	N/A	N/A	
1	1	Custodial Closet inside Girl's Restroom near Auditorium	W3	Concrete	Pink / Beige	Flaking	3	0.8	Positive	
1	1	Custodial Closet inside Girl's Restroom near Auditorium	W4	Concrete	Pink / Beige	Flaking	3	1.13	Positive	
1	1	Custodial Closet inside Girl's Restroom near Auditorium	Ceiling	Concrete	Beige	Flaking	10	No Access	No Access	
1	1	Custodial Closet inside Girl's Restroom near Auditorium	Floor	Concrete	Gray	None	0	N/A	N/A	
1	1	Girl's Restroom near Auditorium	W1	Brick	Beige	Moisture Damage	5	0.31	Negative	
1	1	Girl's Restroom near Auditorium	W2	Brick	Beige	Chipping	7	2.81	Positive	
1	1	Girl's Restroom near Auditorium	W3	Sheetrock	Pink / Beige	Chipping	3	0	Negative	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Girl's Restroom near Auditorium	W4	Brick / Concrete	Beige	Chipping	3	3.83	Positive
1	1	Girl's Restroom near Auditorium	Ceiling	Concrete	Beige	Moisture Damage	7	No Access	No Access
1	1	Girl's Restroom near Auditorium	Floor	Concrete	Gray	None	0	0	Negative
1	1	Staff Restroom across from Classroom 100	W1	Sheetrock	Gray	None	0	N/A	N/A
1	1	Staff Restroom across from Classroom 100	W2	Sheetrock	Gray / Pink / White	None	0	0	Negative
1	1	Staff Restroom across from Classroom 100	W3	Brick	Pink	None	0	2.67	Positive
1	1	Staff Restroom across from Classroom 100	W4	Brick	Beige	None	0	N/A	N/A
1	1	Staff Restroom across from Classroom 100	Ceiling	Sheetrock	White	Moisture Damage	4	0	Negative
1	1	Staff Restroom across from Classroom 100	Floor	Concrete	Gray	None	0	0	Negative
1	1	Stairwell near Elevator	Staircase	Metal	Gray	Friction	1	0.08	Negative
1	1	Stairwell near Classroom 100	W1	Brick / Concrete	Green / Blue / Beige	None	0	N/A	N/A
1	1	Stairwell near Classroom 100	W2	Brick / Concrete	Green / Blue / Beige	Chipping	1	1.58	Positive
1	1	Stairwell near Classroom 100	W3	Brick / Concrete	Green / Blue / Beige	None	0	N/A	N/A
1	1	Stairwell near Classroom 100	W4	Brick / Concrete	Green / Blue / Beige	Chipping	4	2.43	Positive
1	1	Stairwell near Classroom 100	Ceiling	Concrete	Beige	None	0	N/A	N/A
1	1	Stairwell near Classroom 100	Floor	Concrete	Gray	None	0	0.26	Negative
1	1	Stairwell near Classroom 100	Railing	Metal	Black	Friction	20	0.1	Negative
1	1	Stairwell near Classroom 100	Staircase	Concrete	Gray	None	0	0.7	Positive
1	1	Stairwell near Classroom 100	Radiator	Metal	Silver	Chipping	10	0.01	Negative
1	1	Classroom 100	W1	Concrete	Beige	None	0	N/A	N/A
1	1	Classroom 100	W2	Brick	Beige	Chipping	10	0.01	Negative
1	1	Classroom 100	W3	Concrete	Beige	None	0	N/A	N/A
1	1	Classroom 100	W4	Concrete	Beige	Chipping	1	0.7	Positive
1	1	Classroom 100	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Auditorium	W1	Concrete	Beige / Multi (mural)	None	0	N/A	N/A
1	1	Auditorium	W2	Concrete	Beige	None	0	0	Negative
1	1	Auditorium	W3	Concrete	Beige / Multi (mural)	Efflorescence	2	0	Negative
1	1	Auditorium	W4	Concrete	Beige	None	0	N/A	N/A
1	1	Auditorium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	Radiator	Metal	Silver	Chipping	1	0.74	Positive
1	1	Auditorium	Window Frame	Wood	Beige	Chipping	1	1.01	Positive
1	1	Auditorium Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Auditorium Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Auditorium Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Auditorium Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Auditorium Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Auditorium Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5th grade dean's office	W1	Concrete	Blue	None	0	N/A	N/A
1	1	5th grade dean's office	W2	Concrete	Blue	None	0	N/A	N/A
1	1	5th grade dean's office	W3	Concrete	Blue	None	0	N/A	N/A
1	1	5th grade dean's office	W4	Brick	Blue	None	0	N/A	N/A
1	1	5th grade dean's office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	5th grade dean's office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fan room next to room 157 5th grade Dean's office	W1	Concrete	Beige	None	0	N/A	N/A
1	1	Fan room next to room 157 5th grade Dean's office	W2	Concrete	Beige	None	0	N/A	N/A
1	1	Fan room next to room 157 5th grade Dean's office	W3	Concrete	Beige	None	0	N/A	N/A
1	1	Fan room next to room 157 5th grade Dean's office	W4	Concrete	Beige	None	0	N/A	N/A
1	1	Fan room next to room 157 5th grade Dean's office	Ceiling	Concrete	White	Chipping	10	No Access	No Access
1	1	Fan room next to room 157 5th grade Dean's office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1st Floor Main Building Hallways	W1	Concrete	Beige	Efflorescence	2	0	Negative
1	1	1st Floor Main Building Hallways	W2	Concrete	Beige	None	0	N/A	N/A
1	1	1st Floor Main Building Hallways	W3	Concrete	Beige	None	0	N/A	N/A
1	1	1st Floor Main Building Hallways	W4	Brick	Beige	Chipping	2	0.7	Positive
1	1	1st Floor Main Building Hallways	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1st Floor Main Building Hallways	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	W1	Sheetrock	Beige	None	0	N/A	N/A

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report							
		Inspection Company: REPSG	Feltonville Intermediate School							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 107	W2	Sheetrock	Beige	Chipping	1	0.7	Positive	
1	1	Classroom 107	W3	Sheetrock	Beige	Chipping	1	0	Negative	
1	1	Classroom 107	W4	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Classroom 107	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Boy's Restroom to left of Classroom 109	W1	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Boy's Restroom to left of Classroom 109	W2	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Boy's Restroom to left of Classroom 109	W3	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Boy's Restroom to left of Classroom 109	W4	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Boy's Restroom to left of Classroom 109	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Boy's Restroom to left of Classroom 109	Floor	Ceramic	White / Green	N/A	N/A	N/A	N/A	
1	1	Boy's Restroom to left of Classroom 109	Radiator	Metal	Brown	Friction	2	2.28	Positive	
1	1	Girl's Restroom next to Classroom 109	W1	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Girl's Restroom next to Classroom 109	W2	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Girl's Restroom next to Classroom 109	W3	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Girl's Restroom next to Classroom 109	W4	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Girl's Restroom next to Classroom 109	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Girl's Restroom next to Classroom 109	Floor	Ceramic	Brown / Cream	N/A	N/A	N/A	N/A	
1	1	Girl's Restroom next to Classroom 109	Radiator	Metal	Brown	Friction	2	0.91	Positive	
1	1	Classroom 109 and 111	W1	Sheetrock	Powder Blue	Chipping	2	0	Negative	
1	1	Classrooms 109 and 111	W2	Concrete	Powder Blue	Chipping	7	2.13	Positive	
1	1	Classrooms 109 and 111	W3	Concrete / Brick	Powder Blue	Chipping	5	1.7	Positive	
1	1	Classrooms 109 and 111	W4	Concrete	Powder Blue	Chipping	3	1.57	Positive	
1	1	Classroom 109 and 111	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 109 and 111	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 106 Closet	W1	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Classroom 106 Closet	W2	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Classroom 106 Closet	W3	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Classroom 106 Closet	W4	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Classroom 106 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 106 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 106	W1	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Classroom 106	W2	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Classroom 106	W3	Brick	Beige	Moisture Damage	1	1.73	Positive	
1	1	Classroom 106	W4	Sheetrock	Blue	None	0	0	Negative	



		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report							
		Inspection Company: REPSG	Feltonville Intermediate School							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 106	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Exit 7 Stairwell Next to Classroom 111/109	W1	Concrete	Green / Blue / Beige	Chipping	2	0.11	Negative	
1	1	Exit 7 Stairwell Next to Classroom 111/109	W2	Concrete	Green / Blue / Beige	Chipping	1	2.13	Positive	
1	1	Exit 7 Stairwell Next to Classroom 111/109	W3	Brick	Green / Blue / Beige	Chipping	3	2.09	Positive	
1	1	Exit 7 Stairwell Next to Classroom 111/109	W4	Concrete	Green / Blue / Beige	Chipping	5	3.19	Positive	
1	1	Exit 7 Stairwell Next to Classroom 111/109	Ceiling	Metal / Concrete	Beige	Chipping	1	0.02	Negative	
1	1	Exit 7 Stairwell Next to Classroom 111/109	Floor	Concrete	Gray	Friction	1	0	Negative	
1	1	Exit 7 Stairwell Next to Classroom 111/109	Railings	Metal	Gray	Friction	2	0.01	Negative	
1	1	Exit 7 Stairwell Next to Classroom 111/109	Staircase	Metal	Gray	None	0	0.7	Positive	
1	1	Classroom 104	W1	Sheetrock	Beige	Chipping	1	0	Negative	
1	1	Classroom 104	W2	Sheetrock	Beige	Chipping	1	0	Negative	
1	1	Classroom 104	W3	Brick / Concrete	Beige	Chipping	1	1.92	Positive	
1	1	Classroom 104	W4	Sheetrock / Brick	Beige	Chipping	1	2.11	Positive	
1	1	Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 104	Window Frame	Wood	Tan	Chipping	2	0.92	Positive	
1	1	Storage Room in Classroom 104	W1	Sheetrock	Beige	Chipping	1	0	Negative	
1	1	Storage Room in Classroom 104	W2	Sheetrock	Beige	Chipping	1	0	Negative	
1	1	Storage Room in Classroom 104	W3	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Storage Room in Classroom 104	W4	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Storage Room in Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Room in Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet within Classroom 104 Storage Room	W1	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Storage Closet within Classroom 104 Storage Room	W2	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Storage Closet within Classroom 104 Storage Room	W3	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Storage Closet within Classroom 104 Storage Room	W4	Sheetrock	Beige	None	0	N/A	N/A	
1	1	Storage Closet within Classroom 104 Storage Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet within Classroom 104 Storage Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 108	W1	Sheetrock	Beige	None	0	0	Negative	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom 108	W2	Compressed Cloth Board	Light Gray	None	0	N/A	N/A
1	1	Classroom 108	W3	Brick	Beige	None	0	N/A	N/A
1	1	Classroom 108	W4	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 108	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Window Frame	Wood	Tan	Friction	1	0.83	Positive
1	1	Classroom 108	Support Column	Sheetrock	Blue	Chipping	1	0	Negative
1	1	Classroom 108 Storage Closet	W1	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 108 Storage Closet	W2	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 108 Storage Closet	W3	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 108 Storage Closet	W4	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 108 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110	W1	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 110	W2	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 110	W3	Sheetrock / Brick	Beige	None	0	0.7	Positive
1	1	Classroom 110	W4	Sheetrock	Blue	None	0	0	Negative
1	1	Classroom 110	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110 Storage Closet on window side of room	W1	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 110 Storage Closet on window side of room	W2	Sheetrock	Beige	Friction	1	0	Negative
1	1	Classroom 110 Storage Closet on window side of room	W3	Sheetrock / Brick	Beige	Chipping	1	0	Negative
1	1	Classroom 110 Storage Closet on window side of room	W4	Sheetrock	Blue	Cracking	1	0	Negative
1	1	Classroom 110 Storage Closet on window side of room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110 Storage Closet on window side of room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110 Storage Closet near Entrance	W1	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 110 Storage Closet near Entrance	W2	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 110 Storage Closet near Entrance	W3	Sheetrock	Beige	None	0	N/A	N/A
1	1	Classroom 110 Storage Closet near Entrance	W4	Sheetrock	Beige	None	0	N/A	N/A

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom 110 Storage Closet near Entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110 Storage Closet near Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Library/IMC (Room 113)	W1	Sheetrock	Beige	Chipping	1	0	Negative
1	1	Library/IMC (Room 113)	W2	Concrete	Beige	Chipping	1	0.07	Negative
1	1	Library/IMC (Room 113)	W3	Concrete / Brick	Beige	Chipping	1	0.18	Negative
1	1	Library/IMC (Room 113)	W4	Brick	Beige	Efflorescence	2	0	Negative
1	1	Library/IMC (Room 113)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Library/IMC (Room 113)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Library/IMC (Room 113)	Window Frame	Wood	Tan	Chipping	1	2.79	Positive
1	1	Library Server Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Library Server Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Library Server Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Library Server Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Library Server Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Library Server Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 112	W1	Sheetrock	Beige	Chipping	3	0	Negative
1	1	Classroom 112	W2	Sheetrock	Beige	Chipping	5	0	Negative
1	1	Classroom 112	W3	Sheetrock / Brick	Beige	Chipping	5	2.08	Positive
1	1	Classroom 112	W4	Sheetrock	Beige	Chipping	3	0	Negative
1	1	Classroom 112	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 112	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 112	Window Frame	Wood	Tan	Chipping	5	2.12	Positive
1	1	Storage in stairwall between 112 and 114	W1	Concrete	Beige	None	0	N/A	N/A
1	1	Storage in stairwall between 112 and 114	W2	Sheetrock	Beige	None	0	N/A	N/A
1	1	Storage in stairwall between 112 and 114	W3	Concrete	Beige	None	0	N/A	N/A
1	1	Storage in stairwall between 112 and 114	W4	Concrete	Beige	Chipping	1	0	Negative
1	1	Storage in stairwall between 112 and 114	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage in stairwall between 112 and 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 118	W1	Concrete	Beige	None	0	N/A	N/A
1	1	Classroom 118	W2	Concrete	Blue	None	0	0	Negative
1	1	Classroom 118	W3	Concrete	Beige	None	0	N/A	N/A
1	1	Classroom 118	W4	Concrete	Beige	None	0	N/A	N/A
1	1	Classroom 118	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 118	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 114	W1	Sheetrock	Blue	None	0	0	Negative

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report							
		Inspection Company: REPSG	Feltonville Intermediate School							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 114	W2	Concrete	Beige	None	0	N/A	N/A	
1	1	Classroom 114	W3	Concrete	Beige	None	0	N/A	N/A	
1	1	Classroom 114	W4	Concrete / Brick	Beige	None	0	0	Negative	
1	1	Classroom 114	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 114 Storage near Stairwell to second floor	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 114 Storage near Stairwell to second floor	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 114 Storage near Stairwell to second floor	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 114 Storage near Stairwell to second floor	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 114 Storage near Stairwell to second floor	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 114 Storage near Stairwell to second floor	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 114 Storage near Windows	W1	Concrete	Beige	None	0	0.7	Positive	
1	1	Classroom 114 Storage near Windows	W2	Concrete	Beige	None	0	N/A	N/A	
1	1	Classroom 114 Storage near Windows	W3	Brick	Beige	None	0	N/A	N/A	
1	1	Classroom 114 Storage near Windows	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	Classroom 114 Storage near Windows	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 114 Storage near Windows	Floor	Concrete	N/A	None	0	N/A	N/A	
1	1	Classroom 116	W1	Sheetrock	Beige	Chipping	3	0	Negative	
1	1	Classroom 116	W2	Sheetrock / Concrete	Beige	Friction	3	0	Negative	
1	1	Classroom 116	W3	Concrete	Beige	None	0	N/A	N/A	
1	1	Classroom 116	W4	Concrete	Beige	None	0	N/A	N/A	
1	1	Classroom 116	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 116	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Gymnasium Storage Closet near Entrance	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Gymnasium Storage Closet near Entrance	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Gymnasium Storage Closet near Entrance	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Gymnasium Storage Closet near Entrance	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Gymnasium Storage Closet near Entrance	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Gymnasium Storage Closet near Entrance	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Gym Teacher's Office next to Girl's Locker Room	W1	Concrete	White / Tan	None	0	0.7	Positive	
1	1	Gym Teacher's Office next to Girl's Locker Room	W2	Concrete	White / Tan	None	0	N/A	N/A	
1	1	Gym Teacher's Office next to Girl's Locker Room	W3	Concrete	White / Tan	None	0	N/A	N/A	
1	1	Gym Teacher's Office next to Girl's Locker Room	W4	Concrete	White / Tan	None	0	N/A	N/A	
1	1	Gym Teacher's Office next to Girl's Locker Room	Ceiling	Wood	White	Moisture Damage	20	No Access	No Access	
1	1	Gym Teacher's Office next to Girl's Locker Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Girl's Gym Locker Rooms	W1	Concrete	White / Beige	None	0	0	Negative
1	1	Girl's Gym Locker Rooms	W2	Sheetrock / Concrete	Beige	None	0	N/A	N/A
1	1	Girl's Gym Locker Rooms	W3	Concrete	White / Beige	None	0	N/A	N/A
1	1	Girl's Gym Locker Rooms	W4	Concrete	White / Beige	None	0	N/A	N/A
1	1	Girl's Gym Locker Rooms	Ceiling	Wood	White	Moisture Damage	10	No Access	No Access
1	1	Girl's Gym Locker Rooms	Floor	Concrete	Red	Friction	20	0	Negative
1	1	Boy's Gym Locker Rooms now used as Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Locker Rooms now used as Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Locker Rooms now used as Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Locker Rooms now used as Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Locker Rooms now used as Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Locker Rooms now used as Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage room next to Men's Locker room	W1	Concrete	White / Gray	None	0	N/A	N/A
1	1	Storage room next to Men's Locker room	W2	Concrete	White / Gray	None	0	0.02	Negative
1	1	Storage room next to Men's Locker room	W3	Concrete	White / Gray	None	0	0.02	Negative
1	1	Storage room next to Men's Locker room	W4	Concrete	White / Gray	None	0	N/A	N/A
1	1	Storage room next to Men's Locker room	Ceiling	Wood	White	Moisture Damage	50	No Access	No Access
1	1	Storage room next to Men's Locker room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Gymnasium	W1	Concrete	White / Beige	None	0	N/A	N/A
1	1	Gymnasium	W2	Concrete	White / Beige	None	0	N/A	N/A
1	1	Gymnasium	W3	Concrete	White / Beige	None	0	0	Negative
1	1	Gymnasium	W4	Concrete	White / Beige	None	0	N/A	N/A
1	1	Gymnasium	Ceiling	Wood	White	Chipping	5	No Access	No Access
1	1	Gymnasium	Floor	Concrete	Blue / Yellow	Cracking	4	0	Negative
1	1	Hallway from gym through Classroom 104	W1	Sheetrock / Brick	Tan	None	0	0	Negative
1	1	Hallway from gym through Classroom 104	W2	Sheetrock / Concrete	Beige	None	0	0	Negative
1	1	Hallway from gym through Classroom 104	W3	Sheetrock / Concrete	Beige	None	0	N/A	N/A
1	1	Hallway from gym through Classroom 104	W4	Sheetrock / Concrete	Beige	None	0	1.26	Positive
1	1	Hallway from gym through Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from gym through Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from gym through Classroom 104	Staircase	Metal	Black	Friction	1	0.7	Positive
1	1	Hallway from gym through Classroom 104	Railing	Metal	Black	Friction	15	0.22	Negative
1	1	Storage to Left of Classroom 116	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage to Left of Classroom 116	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage to Left of Classroom 116	W3	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report							
		Inspection Company: REPSG	Feltonville Intermediate School							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Storage to Left of Classroom 116	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage to Left of Classroom 116	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage to Left of Classroom 116	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage to Right of Gym	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage to Right of Gym	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage to Right of Gym	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage to Right of Gym	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage to Right of Gym	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage to Right of Gym	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Machine room next to sprinkler room	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Machine room next to sprinkler room	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Machine room next to sprinkler room	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Machine room next to sprinkler room	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Machine room next to sprinkler room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Machine room next to sprinkler room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Building Engineer's Office	W1	Brick / Concrete	Green	Moisture Damage	1	0	Negative	
1	1	Building Engineer's Office	W2	Brick / Concrete	Green	Friction	3	0	Negative	
1	1	Building Engineer's Office	W3	Concrete	Green	Friction	3	0	Negative	
1	1	Building Engineer's Office	W4	Brick / Concrete	Green	Efflorescence	3	0	Negative	
1	1	Building Engineer's Office	Ceiling	Metal	Beige	Partially Inaccessible	N/A	No Access	No Access	
1	1	Building Engineer's Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	1	Boiler Room	W1	Brick / Concrete	Beige / White	Flaking	3	2.05	Positive	
1	1	Boiler Room	W2	Brick / Concrete	Beige / White	Flaking	3	0.26	Negative	
1	1	Boiler Room	W3	Brick / Concrete / Sheetrock	Beige / White	Flaking	10	3.42	Positive	
1	1	Boiler Room	W4	Brick	Beige / White	Flaking	5	0.88	Positive	
1	1	Boiler Room	Ceiling	Metal	Beige	Partially Inaccessible	N/A	No Access	No Access	
1	1	Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	1	Boiler Room Restroom	W1	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Boiler Room Restroom	W2	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Boiler Room Restroom	W3	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Boiler Room Restroom	W4	Ceramic	Tan	N/A	N/A	N/A	N/A	
1	1	Boiler Room Restroom	Ceiling	Concrete	White	Moisture Damage	4	No Access	No Access	
1	1	Boiler Room Restroom	Floor	Concrete	Red	Friction	10	0.04	Negative	
1	2	"Exit 2" Stairwell near Staff Restroom	W1	Brick	Beige	None	0	N/A	N/A	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	<b>School District of Philadelphia</b>							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	<b>Lead Safe Certification Assessment Report</b>							
		Inspection Company: REPSG	<b>Feltonville Intermediate School</b>							
<b>E</b>	<b>F</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>	
1	2	"Exit 2" Stairwell near Staff Restroom	W2	Brick	Beige	Flaking	5	0.09	Negative	
1	2	"Exit 2" Stairwell near Staff Restroom	W3	Brick	Beige	Chipping	10	0.52	Negative	
1	2	"Exit 2" Stairwell near Staff Restroom	W4	Brick	Beige	None	0	N/A	N/A	
1	2	"Exit 2" Stairwell near Staff Restroom	Ceiling	Concrete	Beige	None	0	N/A	N/A	
1	2	"Exit 2" Stairwell near Staff Restroom	Floor	Concrete	Dark Grey	Friction	5	4.84	Positive	
1	2	Staff Restrooms next to Exit 2 Stairwell	W1	Concrete	Blue / Orange	None	0	N/A	N/A	
1	2	Staff Restrooms next to Exit 2 Stairwell	W2	Brick	Blue / Orange	None	0	1.7	Positive	
1	2	Staff Restrooms next to Exit 2 Stairwell	W3	Brick	Blue / Orange	None	0	N/A	N/A	
1	2	Staff Restrooms next to Exit 2 Stairwell	W4	Concrete	Blue / Orange	None	0	0	Negative	
1	2	Staff Restrooms next to Exit 2 Stairwell	Ceiling	Concrete	Dark Grey	None	0	N/A	N/A	
1	2	Staff Restrooms next to Exit 2 Stairwell	Floor	Concrete	Dark Grey	None	0	N/A	N/A	
1	2	Staff Restrooms next to Exit 2 Stairwell	Radiator	Metal	Silver	Friction	1	0.06	Negative	
1	2	Boy's Restroom near Elevator	W1	Concrete	Beige / Blue	None	0	0	Negative	
1	2	Boy's Restroom near Elevator	W2	Concrete	Beige	None	0	N/A	N/A	
1	2	Boy's Restroom near Elevator	W3	Brick	Beige	Chipping	5	0.06	Negative	
1	2	Boy's Restroom near Elevator	W4	Brick	Beige	Chipping	5	3.06	Positive	
1	2	Boy's Restroom near Elevator	Ceiling	Concrete	Beige	Chipping	5	No Access	No Access	
1	2	Boy's Restroom near Elevator	Floor	Concrete	Dark Grey	None	0	0	Negative	
1	2	Classroom 208	W1	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 208	W2	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 208	W3	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 208	W4	Concrete/Brick	Beige	Flaking	10	0.95	Positive	
1	2	Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	"Exit 2" Stairwell near Staff Restroom	Stair Risers	Concrete	Beige	None	0	N/A	N/A	
1	2	"Exit 2" Stairwell near Staff Restroom	Railing	Metal	Black	Friction	10	0.43	Negative	
1	2	"Exit 3" Stairwell Next to Elevator	W1	Concrete	Green / Blue / Beige	Chipping	5	0	Negative	
1	2	"Exit 3" Stairwell Next to Elevator	W2	Concrete	Green / Blue / Beige	None	0	N/A	N/A	
1	2	"Exit 3" Stairwell Next to Elevator	W3	Concrete	Green / Blue / Beige / White	None	0	N/A	N/A	
1	2	"Exit 3" Stairwell Next to Elevator	W4	Concrete	Green / Blue / Beige / White	None	0	N/A	N/A	
1	2	"Exit 3" Stairwell Next to Elevator	Ceiling	Concrete	Beige	None	0	N/A	N/A	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	"Exit 3" Stairwell Next to Elevator	Floor	Concrete	Dark Grey	None	0	N/A	N/A
1	2	"Exit 3" Stairwell Next to Elevator	Stair Risers	Metal	Black	None	0	N/A	N/A
1	2	"Exit 3" Stairwell Next to Elevator	Railing	Metal	Black	Friction	20	0.05	Negative
1	1	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W1	Brick	Beige / White	None	0	N/A	N/A
1	1	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W2	Brick	Beige / White	None	0	N/A	N/A
1	1	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W3	Brick	Beige / White	Cracking	1	0	Negative
1	1	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W4	Brick	Beige / White	Chipping	1	0	Negative
1	1	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	Ceiling	Concrete	White	Cracking	1	No Access	No Access
1	1	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	Floor	Concrete	Grey	None	0	0	Negative
1	2	"Exit 1" Stairwell near Girl's Restroom	W1	Brick	Green / Blue / Beige	None	0	N/A	N/A
1	2	"Exit 1" Stairwell near Girl's Restroom	W2	Brick	Green / Blue / Beige	Flaking	3	1.95	Positive
1	2	"Exit 1" Stairwell near Girl's Restroom	W3	Brick	Green / Blue / Beige / White	Friction	3	0.7	Positive
1	2	"Exit 1" Stairwell near Girl's Restroom	W4	Brick	Green / Blue / Beige	Flaking	3	0.56	Negative
1	2	"Exit 1" Stairwell near Girl's Restroom	Ceiling	Concrete	Beige	None	0	N/A	N/A
1	2	"Exit 1" Stairwell near Girl's Restroom	Floor	Concrete	Dark Grey	None	0	N/A	N/A
1	2	Classroom 208	Window Sill	Concrete	Tan	Chipping	12	2.53	Positive
1	2	Classroom 207	W1	Concrete	Purple/Beige	None	0	N/A	N/A
1	2	Classroom 207	W2	Concrete/Brick	Purple/Beige	None	0	1.3	Positive
1	2	Classroom 207	W3	Concrete	Purple/Beige	None	0	N/A	N/A
1	2	Classroom 207	W4	Concrete	Purple/Beige	None	0	N/A	N/A
1	2	Classroom 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 207	Window Sill	Concrete	Purple	None	0	N/A	N/A
1	2	Classroom 207	Radiator	Metal	Silver	Friction	2	1.25	Positive
1	2	Office 207A	W1	Concrete	Beige	None	0	N/A	N/A



		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021		School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine		Lead Safe Certification Assessment Report						
		Inspection Company: REPSG		Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	2	Office 207A	W2	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 207A	W3	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 207A	W4	Concrete	Beige	None	0	0.02	Negative	
1	2	Office 207A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Office 207A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Office 208A	W1	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 208A	W2	Concrete	Beige	None	0	0.7	Positive	
1	2	Office 208A	W3	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 208A	W4	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 208A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Office 208A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Custodial Closet to Left of Office 208A	W1	Concrete	Beige/Green	None	0	0.06	Negative	
1	2	Custodial Closet to Left of Office 208A	W2	Concrete	Beige/Green	None	0	N/A	N/A	
1	2	Custodial Closet to Left of Office 208A	W3	Concrete	Beige/Green	None	0	N/A	N/A	
1	2	Custodial Closet to Left of Office 208A	W4	Concrete	Beige/Green	None	0	N/A	N/A	
1	2	Custodial Closet to Left of Office 208A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Custodial Closet to Left of Office 208A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Office 206A	W1	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 206A	W2	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 206A	W3	Concrete	Beige	None	0	1.67	Positive	
1	2	Office 206A	W4	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 206A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Office 206A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 206	W1	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 206	W2	Sheetrock	Beige / Mint Green	Chipping	1	0	Negative	
1	2	Classroom 206	W3	Concrete	Beige / Mint Green	Chipping	1	0.12	Negative	
1	2	Classroom 206	W4	Concrete	Beige / Mint Green	None	0	N/A	N/A	
1	2	Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 205	W1	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 205	W2	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 205	W3	Concrete / Sheetrock	Beige	Chipping	10	0.8	Positive	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	<b>School District of Philadelphia</b>							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	<b>Lead Safe Certification Assessment Report</b>							
		Inspection Company: REPSG	<b>Feltonville Intermediate School</b>							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	2	Classroom 205	W4	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 205	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 204	W1	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 204	W2	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 204	W3	Concrete/Brick	Blue/Beige	None	0	1.15	Positive	
1	2	Classroom 204	W4	Sheetrock	Beige	Friction	15	0	Negative	
1	2	Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 204	Window Sill	Concrete	Tan	Chipping	12	1.16	Positive	
1	2	Classroom 202	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	Classroom 202	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	Classroom 202	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	Classroom 202	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	Classroom 202	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	Classroom 202	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	Office 202A	W1	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 202A	W2	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 202A	W3	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 202A	W4	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 202A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Office 202A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Office 202B	W1	Concrete	Beige / Green	None	0	N/A	N/A	
1	2	Office 202B	W2	Concrete	Beige / Green	None	0	N/A	N/A	
1	2	Office 202B	W3	Concrete	Beige / Green	None	0	N/A	N/A	
1	2	Office 202B	W4	Concrete	Beige / Green	None	0	N/A	N/A	
1	2	Office 202B	Ceiling	Concrete	Beige	None	0	N/A	N/A	
1	2	Office 202B	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 201	W1	Concrete	Beige	None	0	N/A	N/A	
1	2	Classroom 201	W2	Sheetrock	Beige	None	0	N/A	N/A	
1	2	Classroom 201	W3	Concrete	Beige	Chipping	1	5	Positive	
1	2	Classroom 201	W4	Concrete/Brick	Beige	None	0	N/A	N/A	
1	2	Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 201	Radiator	Metal	Silver	Chipping	10	0.01	Negative	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Girl's Restroom across from Classroom 200	W1	Concrete/Brick	Beige / Yellow	Chipping	1	0	Negative
1	2	Girl's Restroom across from Classroom 200	W2	Brick	Beige / Yellow	Chipping	2	2.66	Positive
1	2	Girl's Restroom across from Classroom 200	W3	Concrete/Brick	Beige	Chipping	2	1.94	Positive
1	2	Girl's Restroom across from Classroom 200	W4	Concrete/Brick	Beige	Chipping	1	4.4	Positive
1	2	Girl's Restroom across from Classroom 200	Ceiling	Concrete	Beige	Chipping	1	No Access	No Access
1	2	Girl's Restroom across from Classroom 200	Floor	Concrete	Gray	None	0	0.02	Negative
1	2	Classroom 200	W1	Concrete	Beige	None	0	N/A	N/A
1	2	Classroom 200	W2	Concrete/Brick	Beige	Chipping	1	4.13	Positive
1	2	Classroom 200	W3	Sheetrock	Blue	None	0	0	Negative
1	2	Classroom 200	W4	Concrete	Beige	None	0	N/A	N/A
1	2	Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	Window Sill	Concrete	Tan	Chipping	12	3.44	Positive
1	2	Classroom 203A	W1	Concrete	Blue/Beige	None	0	0	Negative
1	2	Classroom 203A	W2	Sheetrock	Beige	None	0	N/A	N/A
1	2	Classroom 203A	W3	Brick	Beige	None	0	N/A	N/A
1	2	Classroom 203A	W4	Sheetrock	Beige	None	0	0	Negative
1	2	Classroom 203A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203A	Window Sill	Concrete	Tan	None	0	5	Positive
1	2	Classroom 203	Window Sill	Concrete	Tan	Chipping	12	5	Positive
1	2	Classroom 203	Column	Concrete	Beige / Green	Friction	1	1	Positive
1	2	Classroom 203	W1	Concrete	Beige	None	0	N/A	N/A
1	2	Classroom 203	W2	Brick	Beige	Chipping	2	1.25	Positive
1	2	Classroom 203	W3	Sheetrock	Beige	None	0	N/A	N/A
1	2	Classroom 203	W4	Sheetrock	Beige	None	0	N/A	N/A
1	2	Classroom 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	Radiator	Metal	Silver	Chipping	1	0.22	Negative
1	2	Classroom 209	Window Frame	Sheetrock	Tan	None	0	2.68	Positive
1	2	Classroom 209	W1	Sheetrock	Beige	Friction	10	0.7	Positive
1	2	Classroom 209	W2	Sheetrock	Beige	Friction	10	0.7	Positive
1	2	Classroom 209	W3	Brick	Beige	None	0	0.19	Negative
1	2	Classroom 209	W4	Concrete	Beige	None	0	N/A	N/A
1	2	Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W1	Sheetrock	Beige	None	0	N/A	N/A
1	2	Classroom 210	W2	Brick	Beige & Purple & Orange	None	0	2.73	Positive
1	2	Classroom 210	W3	Brick / Concrete	Beige	Chipping	2	1.47	Positive
1	2	Classroom 210	W4	Concrete / Sheetrock	Beige & Purple	Flaking	2	0	Negative
1	2	Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	Window Frame	Wood	Beige	Chipping	1	3.06	Positive
1	2	Machine Room 211	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Machine Room 211	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Machine Room 211	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Machine Room 211	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Machine Room 211	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Machine Room 211	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Fan Room 212	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Fan Room 212	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Fan Room 212	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Fan Room 212	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Fan Room 212	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Fan Room 212	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Cafeteria	W1	Concrete	Beige	Friction	5	0	Negative
1	2	Cafeteria	W2	Concrete	Beige / Red	Flaking	20	1.35	Positive
1	2	Cafeteria	W3	Sheetrock	Beige	None	0	0	Negative
1	2	Cafeteria	W4	Concrete	Beige	Friction	10	1.86	Positive
1	2	Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Cafeteria	Window Frame	Wood	Beige	None	0	2.41	Positive
1	2	Cafeteria	Column	Concrete	Yellow	Friction	2	0	Negative
1	2	Cafeteria	Railing	Metal	Beige	None	0	0.23	Negative
1	2	Girl's Restroom in Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Girl's Restroom in Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Girl's Restroom in Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Girl's Restroom in Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Girl's Restroom in Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Girl's Restroom in Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Cafeteria Storage near Entrance	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Cafeteria Storage near Entrance	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Cafeteria Storage near Entrance	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Cafeteria Storage near Entrance	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Cafeteria Storage near Entrance	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Cafeteria Storage near Entrance	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet in Cafeteria next to Boy's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet in Cafeteria next to Boy's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet in Cafeteria next to Boy's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet in Cafeteria next to Boy's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet in Cafeteria next to Boy's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet in Cafeteria next to Boy's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Boy's Restroom in Cafeteria	W1	Concrete	Green	None	0	N/A	N/A
1	2	Boy's Restroom in Cafeteria	W2	Concrete	Green	None	0	N/A	N/A
1	2	Boy's Restroom in Cafeteria	W3	Concrete	Green	None	0	N/A	N/A
1	2	Boy's Restroom in Cafeteria	W4	Concrete	Green	None	0	N/A	N/A
1	2	Boy's Restroom in Cafeteria	Ceiling	Fiberboard / Concrete	Beige	Chipping	30	No Access	No Access
1	2	Boy's Restroom in Cafeteria	Floor	Concrete	Brown / Red	Flaking	3	0	Negative
1	2	Boy's Restroom in Cafeteria	Window Frame	Wood	Green	Chipping	3	3.16	Positive
1	2	Boy's Restroom in Cafeteria	Radiator	Metal	Blue	Friction	1	0.7	Positive
1	2	Exit 7 Stairwell next to Cafeteria	W1	Concrete	Green / Blue / Beige	None	0	N/A	N/A
1	2	Exit 7 Stairwell next to Cafeteria	W2	Concrete	Green / Blue / Beige	Chipping	8	2.24	Positive
1	2	Exit 7 Stairwell next to Cafeteria	W3	Concrete / Brick	Green / Blue / Beige	Chipping	15	1.69	Positive
1	2	Exit 7 Stairwell next to Cafeteria	W4	Concrete	Green / Blue / Beige	Chipping	8	1.35	Positive
1	2	Exit 7 Stairwell next to Cafeteria	Ceiling	Fiberboard / Concrete	Beige	None	0	0	Negative
1	2	Exit 7 Stairwell next to Cafeteria	Floor	Concrete	Dark Grey	None	0	0	Negative
1	2	Exit 7 Stairwell next to Cafeteria	Stair Steps	Metal	Dark Grey	None	0	0	Negative
1	2	Exit 7 Stairwell next to Cafeteria	Stair Railing	Metal	Dark Grey	None	0	0.1	Negative

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Storage Room to Left of Kitchen	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room to Left of Kitchen	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room to Left of Kitchen	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room to Left of Kitchen	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room to Left of Kitchen	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room to Left of Kitchen	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Staff Locker Room next to Kitchen	Window Frame	Wood	Beige/Browm	Chipping	2	2.54	Positive
1	2	Staff Locker Room next to Kitchen	W1	Sheetrock	Beige	None	0	N/A	N/A
1	2	Staff Locker Room next to Kitchen	W2	Sheetrock	Beige	None	0	0	Negative
1	2	Staff Locker Room next to Kitchen	W3	Concrete	Beige	Chipping	5	1.08	Positive
1	2	Staff Locker Room next to Kitchen	W4	Sheetrock	Beige	None	0	N/A	N/A
1	2	Staff Locker Room next to Kitchen	Ceiling	Fiberboard / Concrete	Beige	None	0	N/A	N/A
1	2	Staff Locker Room next to Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Kitchen	W1	Sheetrock	Beige	None	0	N/A	N/A
1	2	Kitchen	W2	Sheetrock	Beige	None	0	N/A	N/A
1	2	Kitchen	W3	Concrete / Brick	Beige / Red	Chipping	20	1.69	Positive
1	2	Kitchen	W4	Concrete	Beige / Red	Chipping	10	1.87	Positive
1	2	Kitchen	Ceiling	Fiberboard / Concrete	Beige	Chipping	10	0	Negative
1	2	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Kitchen	Window Frame	Wood	Beige	None	0	2.45	Positive
1	2	Kitchen Office	W1	Sheetrock	Beige	None	0	N/A	N/A
1	2	Kitchen Office	W2	Sheetrock	Beige	None	0	N/A	N/A
1	2	Kitchen Office	W3	Concrete	Beige / Red	Chipping	5	2.01	Positive
1	2	Kitchen Office	W4	Concrete / Brick	Beige / Red	Chipping	10	2.01	Positive
1	2	Kitchen Office	Ceiling	Fiberboard / Concrete	Beige	Chipping	10	0	Negative
1	2	Kitchen Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	2nd Floor Hallways Leading to Cafeteria	W1	Concrete / Brick	Beige	None	0	N/A	N/A
1	2	2nd Floor Hallways Leading to Cafeteria	W2	Concrete / Brick	Beige	None	0	N/A	N/A
1	2	2nd Floor Hallways Leading to Cafeteria	W3	Concrete / Brick	Beige	None	0	N/A	N/A
1	2	2nd Floor Hallways Leading to Cafeteria	W4	Concrete / Brick	Beige	None	0	1.46	Positive
1	2	2nd Floor Hallways Leading to Cafeteria	Ceiling	Fiberboard / Concrete	Beige	None	0	N/A	N/A

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	2nd Floor Hallways Leading to Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	2nd Floor Hallways Leading to Cafeteria	Radiator	Metal	Beige	None	0	1.51	Positive
1	2	2nd Floor Hallways Leading to Cafeteria	Window Frame	Wood	Beige	None	0	2.33	Positive
1	2	2nd Floor Hallways	W1	Concrete	Beige	None	0	N/A	N/A
1	2	2nd Floor Hallways	W2	Concrete	Beige	None	0	N/A	N/A
1	2	2nd Floor Hallways	W3	Concrete / Brick	Beige	None	0	N/A	N/A
1	2	2nd Floor Hallways	W4	Concrete	Beige	None	0	N/A	N/A
1	2	2nd Floor Hallways	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	2nd Floor Hallways	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	2nd Floor Hallways	Radiator	Metal	Silver	Chipping	10	2.8	Positive
1	3	Stairwell Next to Staff Restroom and Boy's Room	W1	Brick	Beige	Friction	5	5	Positive
1	3	Stairwell Next to Staff Restroom and Boy's Room	W2	Brick	Beige	Flaking	5	5	Positive
1	3	Stairwell Next to Staff Restroom and Boy's Room	W3	Brick	Beige	Flaking	20	2.18	Positive
1	3	Stairwell Next to Staff Restroom and Boy's Room	W4	Brick	Beige/White/Green	Flaking	10	5	Positive
1	3	Stairwell Next to Staff Restroom and Boy's Room	Ceiling	Concrete	Beige	Moisture Damage	5	No Access	No Access
1	3	Stairwell Next to Staff Restroom and Boy's Room	Floor	Concrete	Dark Grey	None	0	5	Positive
1	3	Staff Restroom near Elevator	W1	Concrete	Beige	None	0	N/A	N/A
1	3	Staff Restroom near Elevator	W2	Brick	Beige	None	0	N/A	N/A
1	3	Staff Restroom near Elevator	W3	Concrete	Beige	None	0	N/A	N/A
1	3	Staff Restroom near Elevator	W4	Concrete	Beige	None	0	N/A	N/A
1	3	Staff Restroom near Elevator	Ceiling	Concrete	Beige	None	0	N/A	N/A
1	3	Staff Restroom near Elevator	Floor	Concrete	Dark Grey	None	0	0.02	Negative
1	3	Girl's Restroom near Classroom 301	W1	Brick	Beige	Flaking	5	0.7	Positive
1	3	Girl's Restroom near Classroom 301	W2	Brick	Beige	Flaking	5	0.7	Positive
1	3	Girl's Restroom near Classroom 301	W3	Brick	Beige	Flaking	5	0.7	Positive
1	3	Girl's Restroom near Classroom 301	W4	Brick	Beige	Flaking	5	0.7	Positive
1	3	Girl's Restroom near Classroom 301	Ceiling	Concrete	Beige	Chipping	5	No Access	No Access
1	3	Girl's Restroom near Classroom 301	Floor	Concrete	Grey	Friction	5	0	Negative
1	3	Staff Restroom near Elevator	Radiator	Metal	Silver	Chipping	2	0.08	Negative
1	3	Elevator near Boy's Restroom	W1	Concrete	Beige	Chipping	2	0	Negative
1	3	Elevator near Boy's Restroom	W2	Concrete	Beige	None	0	N/A	N/A
1	3	Boy's Restroom near Elevator	W3	Brick	Beige	Flaking	10	2.27	Positive
1	3	Boy's Restroom near Elevator	W4	Brick	Beige	Flaking	5	3.19	Positive
1	3	Elevator near Boy's Restroom	Ceiling	Concrete	Beige	Chipping	8	No Access	No Access

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Elevator near Boy's Restroom	Floor	Concrete	Grey	None	0	0.7	Positive
1	3	Stairwell Next to Staff Restroom and Boy's Room	Stair Risers	Concrete	Beige	None	0	2.92	Positive
1	3	Stairwell Next to Staff Restroom and Boy's Room	Railing	Metal	Black	None	0	0.22	Negative
1	3	Stairwell Next to Elevator	W1	Concrete	Green / Blue / Beige	Chipping	10	0	Negative
1	3	Stairwell Next to Elevator	W2	Concrete	Green / Blue / Beige	None	0	N/A	N/A
1	3	Stairwell Next to Elevator	W3	Concrete	Green / Blue / Beige / White	None	0	N/A	N/A
1	3	Stairwell Next to Elevator	W4	Concrete	Green / Blue / Beige / White	Cracking	5	0.03	Negative
1	3	Stairwell Next to Elevator	Ceiling	Concrete	Beige	None	0	N/A	N/A
1	3	Stairwell Next to Elevator	Floor	Concrete	Dark Grey	None	0	0	Negative
1	3	Stairwell Next to Elevator	Stair Risers	Metal	Black	None	0	0.03	Negative
1	3	Stairwell Next to Elevator	Railing	Metal	Black	Friction	20	0.04	Negative
1	2	"Exit 1" Stairwell near Girl's Restroom	Ceiling	Concrete	Beige	Friction	3	No Access	No Access
1	2	"Exit 1" Stairwell near Girl's Restroom	Railing	Metal	Black	Friction	20	0.12	Negative
1	2	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W1	Brick	Beige / White	None	0	0	Negative
1	2	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W2	Brick	Beige / White	None	0	0	Negative
1	2	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W3	Brick	Beige / White	None	0	N/A	N/A
1	2	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W4	Brick	Beige / White	Flaking	3	0.03	Negative
1	2	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	Ceiling	Concrete	White	Moisture Damage	5	No Access	No Access
1	2	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	Floor	Concrete	Grey	Friction	2	0.37	Negative
1	3	"Exit 1" Stairwell near Girl's Restroom	W1	Brick	Green / Blue / Beige	None	0	N/A	N/A
1	3	"Exit 1" Stairwell near Girl's Restroom	W2	Brick	Green / Blue / Beige	Flaking	5	0.32	Negative
1	3	"Exit 1" Stairwell near Girl's Restroom	W3	Brick	Green / Blue / Beige / White	Cracking	5	1	Positive
1	3	"Exit 1" Stairwell near Girl's Restroom	W4	Brick	Green / Blue / Beige	Flaking	3	0.34	Negative
1	3	"Exit 1" Stairwell near Girl's Restroom	Ceiling	Concrete	Beige	None	0	N/A	N/A
1	3	"Exit 1" Stairwell near Girl's Restroom	Floor	Concrete	Dark Grey	None	0	1	Positive
1	3	"Exit 1" Stairwell near Girl's Restroom	Stair Risers	Concrete	Beige	Friction	3	1	Positive
1	3	"Exit 1" Stairwell near Girl's Restroom	Railing	Metal	Black	Friction	20	0.13	Negative
1	3	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W1	Brick	Beige / White	None	0	0	Negative



		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W2	Brick	Beige / White	None	0	N/A	N/A
1	3	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W3	Brick	Beige / White	None	0	N/A	N/A
1	3	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	W4	Brick	Beige / White	Flaking	3	0	Negative
1	3	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	Ceiling	Concrete	White	Moisture Damage	5	No Access	No Access
1	3	"Exit 1" Stairwell near Girl's Restroom - Entry Vestibule	Floor	Concrete	Grey	Friction	2	1	Positive
1	3	3rd Floor Hallways	W1	Concrete	Grey	None	0	N/A	N/A
1	3	3rd Floor Hallways	W2	Concrete	Grey	None	0	N/A	N/A
1	3	3rd Floor Hallways	W3	Brick	Grey	None	0	1.18	Positive
1	3	3rd Floor Hallways	W4	Concrete	Grey	None	0	0	Negative
1	3	3rd Floor Hallways	W4	Wood	Grey	None	0	0	Negative
1	3	3rd Floor Hallways	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	3rd Floor Hallways	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	3rd Floor Hallways	Window Sill	Wood	Dark Grey	None	0	0.23	Negative
1	3	3rd Floor Hallways	Window Frame	Wood	Dark Grey	None	0	1.97	Positive
1	3	Classroom 309	W1	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 309	W2	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 309	W3	Concrete	Green / Teal	None	0	0	Negative
1	3	Classroom 309	W4	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 309	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 309	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 311	Window Sill	Wood	Dark Grey	None	0	N/A	N/A
1	3	Classroom 311	Window Frame	Wood	Dark Grey	None	0	5	Positive
1	3	Classroom 311	W1	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 311	W2	Brick	Grey	None	0	1.23	Positive
1	3	Classroom 311	W3	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 311	W4	Concrete	Green / Teal	None	0	N/A	N/A
1	3	Classroom 311	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 311	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 313	Window Sill	Wood	Dark Grey	None	0	N/A	N/A
1	3	Classroom 313	Window Frame	Wood	Dark Grey	None	0	N/A	N/A
1	3	Classroom 313	W1	Concrete	Green / Teal	None	0	N/A	N/A
1	3	Classroom 313	W2	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 313	W3	Brick	Grey	None	0	0.7	Positive
1	3	Classroom 313	W4	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 313	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	<b>School District of Philadelphia</b>							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	<b>Lead Safe Certification Assessment Report</b>							
		Inspection Company: REPSG	<b>Feltonville Intermediate School</b>							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	3	Classroom 313	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Office 309A	W1	Concrete	Beige	None	0	N/A	N/A	
1	3	Office 309A	W2	Concrete	Beige	None	0	N/A	N/A	
1	3	Office 309A	W3	Concrete	Beige	None	0	N/A	N/A	
1	3	Office 309A	W4	Concrete	Beige	None	0	N/A	N/A	
1	3	Office 309A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Office 309A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Office 307B	W1	Concrete	Beige	None	0	0.7	Positive	
1	3	Office 307B	W2	Concrete	Beige	None	0	N/A	N/A	
1	3	Office 307B	W3	Concrete	Beige	None	0	N/A	N/A	
1	3	Office 307B	W4	Concrete	Beige	None	0	N/A	N/A	
1	3	Office 307B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Office 307B	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Copy Room 307A	W1	Concrete	Beige	None	0	N/A	N/A	
1	3	Copy Room 307A	W2	Concrete	Beige	None	0	N/A	N/A	
1	3	Copy Room 307A	W3	Concrete	Beige	None	0	N/A	N/A	
1	3	Copy Room 307A	W4	Concrete	Beige	None	0	N/A	N/A	
1	3	Copy Room 307A	Ceiling	Concrete	Beige	Flaking	5	0.7	Positive	
1	3	Copy Room 307A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 307	Window Sill	Wood	Dark Grey	None	0	4.38	Positive	
1	3	Classroom 307	Window Frame	Wood	Dark Grey	None	0	N/A	N/A	
1	3	Classroom 307	Column	Concrete	Grey	None	0	1.18	Positive	
1	3	Classroom 307	W1	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 307	W2	Concrete	Grey	None	0	0	Negative	
1	3	Classroom 307	W3	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 307	W4	Concrete	Green / Teal	None	0	0	Negative	
1	3	Classroom 307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 307	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 306	Window Sill	Wood	Dark Grey	None	0	N/A	N/A	
1	3	Classroom 306	Window Frame	Wood	Dark Grey	None	0	N/A	N/A	
1	3	Classroom 306	W1	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 306	W2	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 306	W3	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 306	W4	Concrete	Green / Teal	None	0	N/A	N/A	
1	3	Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	<b>School District of Philadelphia</b>							
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	<b>Lead Safe Certification Assessment Report</b>							
		Inspection Company: REPSG	<b>Feltonville Intermediate School</b>							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	3	Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 304	Window Sill	Wood	Dark Grey	None	0	N/A	N/A	
1	3	Classroom 304	Window Frame	Wood	Dark Grey	None	0	N/A	N/A	
1	3	Classroom 304	W1	Concrete	Grey	None	0	0.7	Positive	
1	3	Classroom 304	W2	Sheetrock	Green / Teal	None	0	N/A	N/A	
1	3	Classroom 304	W3	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 304	W4	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 305	W1	Concrete	Green / Teal	None	0	0	Negative	
1	3	Classroom 305	W2	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 305	W3	Concrete	Grey	None	0	0	Negative	
1	3	Classroom 305	W4	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 315	Window Sill	Wood	Dark Grey	None	0	N/A	N/A	
1	3	Classroom 315	Window Frame	Wood	Dark Grey	None	0	N/A	N/A	
1	3	Classroom 315	W1	Concrete	Green / Teal	None	0	0.7	Positive	
1	3	Classroom 315	W2	Concrete	Grey	None	0	0	Negative	
1	3	Classroom 315	W3	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 315	W4	Sheetrock	Grey	None	0	0	Negative	
1	3	Classroom 315	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 315	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 303	Window Sill	Wood	Dark Grey	None	0	5	Positive	
1	3	Classroom 303	Window Frame	Wood	Dark Grey	None	0	1.85	Positive	
1	3	Classroom 303	Coat Rack	Wood	Dark Grey	None	0	0	Negative	
1	3	Classroom 303	W1	Sheetrock	Grey	None	0	0	Negative	
1	3	Classroom 303	W2	Concrete	Grey	None	0	N/A	N/A	
1	3	Classroom 303	W3	Concrete	Grey	None	0	1.31	Positive	
1	3	Classroom 303	W4	Sheetrock	Green / Teal	None	0	0	Negative	
1	3	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 302	Window Sill	Wood	Dark Grey	None	0	N/A	N/A	
1	3	Classroom 302	Window Frame	Wood	Dark Grey	None	0	1.77	Positive	
1	3	Classroom 302	W1	Concrete	Grey	None	0	N/A	N/A	

		Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021	School District of Philadelphia						
		Name of Inspector: Suzanne Shourds / Shalaunda Gourdine	Lead Safe Certification Assessment Report						
		Inspection Company: REPSG	Feltonville Intermediate School						
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 302	W2	Sheetrock	Green / Teal	None	0	0	Negative
1	3	Classroom 302	W3	Concrete	Grey	None	0	0.98	Positive
1	3	Classroom 302	W4	Sheetrock	Grey	None	0	N/A	N/A
1	3	Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 300	Window Sill	Wood	Dark Grey	None	0	0.49	Negative
1	3	Classroom 300	Window Frame	Wood	Dark Grey	None	0	1.21	Positive
1	3	Classroom 300	W1	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 300	W2	Concrete	Green / Teal	None	0	0	Negative
1	3	Classroom 300	W3	Concrete	Grey	None	0	0.7	Positive
1	3	Classroom 300	W4	Sheetrock	Grey	None	0	0	Negative
1	3	Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301	Window Sill	Wood	Dark Grey	Chipping	3	2.43	Positive
1	3	Classroom 301	Window Frame	Wood	Dark Grey	None	0	1.73	Positive
1	3	Classroom 301	W1	Concrete	Green / Teal	None	0	0.7	Positive
1	3	Classroom 301	W2	Sheetrock	Grey	None	0	N/A	N/A
1	3	Classroom 301	W3	Sheetrock	Grey	None	0	0	Negative
1	3	Classroom 301	W4	Concrete	Grey	None	0	1.42	Positive
1	3	Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet Next to Classroom 313	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Custodial Closet Next to Classroom 313	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Custodial Closet Next to Classroom 313	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Custodial Closet Next to Classroom 313	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Custodial Closet Next to Classroom 313	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Custodial Closet Next to Classroom 313	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	AT	Attic space in BE Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic space in BE Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic space in BE Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic space in BE Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic space in BE Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic space in BE Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space	W2	N/A	N/A	N/A	N/A	N/A	N/A

		<b>Inspection Dates: 8/30/2021, 8/31/2021, 9/3/2021, 9/9-10/2021</b>		<b>School District of Philadelphia</b>						
		<b>Name of Inspector: Suzanne Shourds / Shalaunda Gourdine</b>		<b>Lead Safe Certification Assessment Report</b>						
		<b>Inspection Company: REPSG</b>		<b>Feltonville Intermediate School</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>									
		<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>	
		1	CS	Crawl Space	W3	N/A	N/A	N/A	N/A	N/A
		1	CS	Crawl Space	W4	N/A	N/A	N/A	N/A	N/A
		1	CS	Crawl Space	Ceiling	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space	Floor	N/A	N/A	N/A	N/A	N/A		