

			School District of Philadelphia																							
			Lead Safe Certification Assessment Report																							
			Anderson Elementary School																							
			Name of Inspector: Ananth K. Vinjamuri		Inspection Dates: 5/4/20 through 5/8/20											ULCS# 1460										
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	P	PH1	Penthouse	no	W1	Cinderblock	Not Painted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	P	PH1	Penthouse	no	W2	Cinderblock	Not Painted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	P	PH1	Penthouse	no	W3	Cinderblock	Not Painted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	P	PH1	Penthouse	no	W4	Cinderblock	Not Painted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	P	PH1	Penthouse	no	Ceiling	Concrete	Not Painted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	P	PH1	Penthouse	no	Floor	Concrete	Not Painted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	P	PH1	Penthouse	no	Stair Railing	Metal	Grey	Chipping	10	0.3	Negative	No	0	No	No	No	No									
1	P	PH1	Penthouse	no	Stair Stringer	Metal	Grey	Chipping	3	0.6	Negative	No	0	No	No	No	No									
1	P	PH1	Penthouse	no	Stair Tread	Metal	Black	Chipping	5	0.01	Negative	No	0	No	No	No	No									
1	3	301A	Closet adjacent to Classrooms 300 and 301	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301A	Closet adjacent to Classrooms 300 and 301	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301A	Closet adjacent to Classrooms 300 and 301	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301A	Closet adjacent to Classrooms 300 and 301	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301A	Closet adjacent to Classrooms 300 and 301	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301A	Closet adjacent to Classrooms 300 and 301	yes	Floor	Concrete	Grey	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	W1	Cinderblock	Beige	Flaking	2	0.04	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	W1	Sheetrock	Beige	Flaking	2	0.01	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	Support pole at Coat Closet (W1)	Metal	Beige	Friction	4	0.8	Positive	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	Door Frame (W1)	Metal	Grey	Friction	5	0	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	Door Jamb (W1)	Metal	Grey	Friction	5	0	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	Door Stop (W1)	Metal	Grey	Friction	4	0	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	Interior Door Frame (W1)	Metal	Beige	Friction	4	0	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	W2	Cinderblock	Beige	Flaking	2	0	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	W3	Cinderblock	Beige	Flaking	5	0	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	W3 (Column)	Concrete	Beige	Chipping	2	0	Negative	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	Ceiling	Tile, Concrete	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	300	Classroom 300	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	W1	Sheetrock	Beige	Flaking	5	0	Negative	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	Column (W1)	Concrete	Beige	Chipping	2	0.02	Negative	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	3	0.7	Positive	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	Door Frame (W1)	Metal	Grey	Chipping	4	0	Negative	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	Door Jamb (W1)	Metal	Grey	Chipping	4	0	Negative	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	Door Stop (W1)	Metal	Grey	Chipping	4	0	Negative	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	Interior Door Frame (W1)	Metal	Beige	Chipping	4	0	Negative	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	W2	Cinderblock	Beige	Flaking	2	0	Negative	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	Ceiling	Tile, Concrete	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	301	Classroom 301	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	Support Pole at Coat Closet (W1)	Cinderblock	Blue	Chipping	2	0.5	Negative	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	Coat Hanger in Coat Closet (W1)	Metal	Blue	Chipping	8	0.3	Negative	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	Locker Door (W1)	Metal	Blue	Friction	2	0	Negative	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	Door Frame (W1)	Metal	Grey	Chipping	4	0	Negative	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	Door Jamb (W1)	Metal	Grey	Chipping	3	0	Negative	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	Door Stop (W1)	Metal	Grey	Chipping	4	0	Negative	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	Interior Door Frame (W1)	Metal	Beige	Chipping	4	0.01	Negative	No	0	No	No	No	No									
1	3	302	Classroom 302	yes	W2	Cinderblock	Blue	Flaking	3	0	Negative	No	0	No	No	No	No									

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Anderson Elementary School																
			Name of Inspector: Ananth K. Vinjamuri		Inspection Dates: 5/4/20 through 5/8/20														
			Inspection Company: Criterion Labs, Inc.		ULCS# 1460														
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	302	Classroom 302	yes	W3	Cinderblock	Blue	Flaking	3	0	Negative	No	0	No	No	No	No		
1	3	302	Classroom 302	yes	Column (W3)	Concrete	Blue	Chipping	3	0.01	Negative	No	0	No	No	No	No		
1	3	302	Classroom 302	yes	W4	Cinderblock	Blue	Flaking	2	0	Negative	No	0	No	No	No	No		
1	3	302	Classroom 302	yes	Ceiling	Concrete	White	Flaking	4	0.02	Negative	No	0	No	No	No	No		
1	3	302	Classroom 302	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Support Pole at Coat Closet (W1)	Metal	Blue	Chipping	4	0.3	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Door Frame (W1)	Metal	Grey	Friction	4	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Door Jamb (W1)	Metal	Grey	Friction	6	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Door Stop (W1)	Metal	Grey	Friction	4	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Interior Door Frame (W1)	Metal	Beige	Friction	10	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	W2	Cinderblock	Blue	Flaking	2	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Column (W2)	Concrete	Blue	Flaking	3	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Column (W3)	Concrete	Blue	Flaking	10	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Column (W4)	Concrete	Blue	Flaking	2	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Ceiling Beam (W4)	Concrete	Blue	Flaking	1	0	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Ceiling	Concrete	White	Flaking	4	0.09	Negative	No	0	No	No	No	No		
1	3	303	Classroom 303	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	W1	Cinderblock	Blue	Flaking	2	0	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Column (W1)	Concrete	Blue	Flaking	1	0	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Support Pole at Coat Closet (W1)	Metal	Blue	Chipping	3	0.5	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Interior Door Frame (W1)	Metal	Beige	Chipping	8	0.01	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	W2	Cinderblock	Blue	Flaking	2	0	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Column (W2)	Concrete	Blue	Flaking	2	0	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	W3	Cinderblock	Blue	Flaking	3	0	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Column (W3)	Concrete	Blue	Flaking	4	0	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Univentilator Cover (W3)	Metal	Brown	Chipping	3	0.01	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	W4	Cinderblock	Blue	Flaking	2	0	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Column (W4)	Concrete	Blue	Flaking	2	0	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Ceiling	Concrete	White	Flaking	5	0.03	Negative	No	0	No	No	No	No		
1	3	304	Classroom 304	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305	Office 305	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305	Office 305	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	3	0.01	Negative	No	0	No	No	No	No		
1	3	305	Office 305	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305	Office 305	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305	Office 305	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305	Office 305	yes	Ceiling	Concrete	White	Flaking	250	0.07	Negative	No	0	No	No	No	No		
1	3	305	Office 305	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305C	Office 305 Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305C	Office 305 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305C	Office 305 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305C	Office 305 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305C	Office 305 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	3	305C	Office 305 Closet	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305D	Office 305 Pipe Chase	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305D	Office 305 Pipe Chase	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305D	Office 305 Pipe Chase	no	Steam Pipe (W2)	Metal	Yellow	Flaking	5	0.04	Negative	No	0	No	No	No	No		
1	3	305D	Office 305 Pipe Chase	no	Drain Pipe (W2)	Metal	Yellow	Flaking	5	0.01	Negative	No	0	No	No	No	No		
1	3	305D	Office 305 Pipe Chase	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305D	Office 305 Pipe Chase	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305D	Office 305 Pipe Chase	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305D	Office 305 Pipe Chase	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	3	305A	Men's Restroom	yes	W1	Cinderblock	Beige	Flaking	3	0.06	Negative	No	0	No	No	No	No		

					School District of Philadelphia																
					Lead Safe Certification Assessment Report																
					Anderson Elementary School														Inspection Dates: 5/4/20 through 5/8/20		
			Name of Inspector: Ananth K. Vinjamuri									Inspection Company: Criterion Labs, Inc.			ULCS# 1460						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	3	305A	Men's Restroom	yes	W1 - Bottom Course	Cinderblock	Brown	Friction	3	0.06	Negative	No	0	No	No	No	No				
1	3	305A	Men's Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305A	Men's Restroom	yes	W2 - Bottom Course	Cinderblock	Brown	Friction	3	0.03	Negative	No	0	No	No	No	No				
1	3	305A	Men's Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305A	Men's Restroom	yes	W3 - Bottom Course	Cinderblock	Brown	Friction	3	0.04	Negative	No	0	No	No	No	No				
1	3	305A	Men's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305A	Men's Restroom	yes	W4 - Bottom Course	Cinderblock	Brown	None	4	0.04	Negative	No	0	No	No	No	No				
1	3	305A	Men's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305A	Men's Restroom	yes	Floor	Concrete	Grey	Friction	4	0	Negative	No	0	No	No	No	No				
1	3	305E	Custodial Closet between Men's and Women's Restrooms	no	W1	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305E	Custodial Closet between Men's and Women's Restrooms	no	W2	Cinderblock	Green	Flaking	2	0	Negative	No	0	No	No	No	No				
1	3	305E	Custodial Closet between Men's and Women's Restrooms	no	W3	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305E	Custodial Closet between Men's and Women's Restrooms	no	W4	Cinderblock	Green	Flaking	2	0	Negative	No	0	No	No	No	No				
1	3	305E	Custodial Closet between Men's and Women's Restrooms	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305E	Custodial Closet between Men's and Women's Restrooms	no	Floor	Concrete	Grey	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	W1	Cinderblock	Beige	Flaking	3	0	Negative	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	W1 - Bottom Course	Cinderblock	Brown	Friction	2	0.01	Negative	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	W2 - Bottom Course	Cinderblock	Brown	Friction	3	0.05	Negative	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	W3 - Bottom Course	Cinderblock	Brown	Friction	2	0.04	Negative	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	Negative	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	W4 - Bottom Course	Cinderblock	Brown	None	4	0.03	Negative	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305B	Women's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	305F	Women's Restroom Pipe Chase	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	305F	Women's Restroom Pipe Chase	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	305F	Women's Restroom Pipe Chase	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	305F	Women's Restroom Pipe Chase	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	305F	Women's Restroom Pipe Chase	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	305F	Women's Restroom Pipe Chase	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	W1	Cinderblock	Brown	Flaking	3	0.01	Negative	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	Door Frame (W1)	Metal	Grey	Chipping	4	0.01	Negative	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	W2	Cinderblock	Yellow/Brown	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	W3	Cinderblock	Yellow/Brown	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	Column (W3)	Concrete	Yellow	Flaking	3	0.06	Negative	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	W4	Cinderblock	Yellow/Brown	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	Ceiling	Concrete	Grey	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307A	Boy's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307B	Girl's Restroom	yes	W1	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307B	Girl's Restroom	yes	W1	Cinderblock	Green	Flaking	2	0	Negative	No	0	No	No	No	No				
1	3	307B	Girl's Restroom	yes	W2	Cinderblock	Purple/Green	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307B	Girl's Restroom	yes	W3	Cinderblock	Purple/Green	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307B	Girl's Restroom	yes	W4	Cinderblock	Purple/Green	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307B	Girl's Restroom	yes	Ceiling	Concrete	Grey	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307B	Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	No	0	No	No	No	No				
1	3	307C	Girl's Restroom Pipe Chase	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	307C	Girl's Restroom Pipe Chase	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	307C	Girl's Restroom Pipe Chase	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	307C	Girl's Restroom Pipe Chase	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	307C	Girl's Restroom Pipe Chase	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	3	307C	Girl's Restroom Pipe Chase	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				

					School District of Philadelphia																
					Lead Safe Certification Assessment Report																
			Name of Inspector: Ananth K. Vinjamuri		Anderson Elementary School														Inspection Dates: 5/4/20 through 5/8/20		
			Inspection Company: Criterion Labs, Inc.									ULCS# 1460									
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	3	306	Classroom 306	yes	W1	Cinderblock	Blue	Flaking	2	0	Negative	No	0	No	No	No	No				
1	3	306	Classroom 306	yes	Column (W1)	Concrete	Blue	Flaking	3	0	Negative	No	0	No	No	No	No				
				yes	Support pole at Coat Closet (W1)	Metal	Blue	Chipping													
1	3	306	Classroom 306						4	0.25	Negative	No		0	No	No	No				
1	3	306	Classroom 306	yes	Interior Door Frame (W1)	Metal	Blue	Chipping	4	0	Negative	No		0	No	No	No				
1	3	306	Classroom 306	yes	Exterior Door Frame (W1)	Metal	Blue	Chipping	4	0	Negative	No		0	No	No	No				
1	3	306	Classroom 306	yes	W2	Cinderblock	Blue	Flaking	2	0	Negative	No		0	No	No	No				
1	3	306	Classroom 306	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No		0	No	No	No				
1	3	306	Classroom 306	yes	Column (W3)	Concrete	Blue	Flaking	3	0	Negative	No		0	No	No	No				
1	3	306	Classroom 306	yes	W4	Cinderblock	Blue	Flaking	2	0	Negative	No		0	No	No	No				
1	3	306	Classroom 306	yes	Ceiling	Concrete	White	Flaking	5	0.06	Negative	No		0	No	No	No				
1	3	306	Classroom 306	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	W1	Sheetrock	Beige	Flaking	5	0	Negative	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	Column (W1)	Concrete	Beige	Flaking	4	0	Negative	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	Interior Door Frame (W1)	Metal	Yellow	Chipping	6	0	Negative	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	4	0	Negative	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	Door Jamb (W1)	Metal	Grey	Chipping	4	0	Negative	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	Door Stop (W1)	Metal	Grey	Chipping	4	0	Negative	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	Column (W3)	Concrete	Beige	Flaking	10	0	Negative	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	W4	Sheetrock	Beige	Flaking	4	0	Negative	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	307	Classroom 307/309	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No		0	No	No	No				
1	3	308	Classroom 308	yes	W1	Cinderblock	Beige	Flaking	1	0	Negative	No		0	No	No	No				
1	3	308	Classroom 308	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	3	0	Negative	No		0	No	No	No				
1	3	308	Classroom 308	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	3	0	Negative	No		0	No	No	No				
1	3	308	Classroom 308	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	308	Classroom 308	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	308	Classroom 308	yes	Column (W3)	Concrete	Beige	Flaking	4	0	Negative	No		0	No	No	No				
1	3	308	Classroom 308	yes	W4	Cinderblock	Beige	Flaking	4	0	Negative	No		0	No	No	No				
1	3	308	Classroom 308	yes	Ceiling	Concrete	Biege	Flaking	7	0.08	Negative	No		0	No	No	No				
1	3	308	Classroom 308	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No		0	No	No	No				
1	3	310	Classroom 310	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	No		0	No	No	No				
1	3	310	Classroom 310	yes	Column (W1)	Concrete	Blue	Flaking	2	0	Negative	No		0	No	No	No				
1	3	310	Classroom 310	yes	Support pole at Coat Closet (W1)	Metal	Blue	Chipping	4	0.06	Negative	No		0	No	No	No				
1	3	310	Classroom 310	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	3	0.01	Negative	No		0	No	No	No				
1	3	310	Classroom 310	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	3	0	Negative	No		0	No	No	No				
1	3	310	Classroom 310	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	No		0	No	No	No				
1	3	310	Classroom 310	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No		0	No	No	No				
1	3	310	Classroom 310	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	No		0	No	No	No				
1	3	310	Classroom 310	yes	Ceiling	Concrete	White	Flaking	2	0.04	Negative	No		0	No	No	No				
1	3	310	Classroom 310	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No		0	No	No	No				
1	3	309	Classroom 307/309 Closet	yes	W1	Sheetrock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	309	Classroom 307/309 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	309	Classroom 307/309 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	309	Classroom 307/309 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No		0	No	No	No				
1	3	309	Classroom 307/309 Closet	yes	Ceiling	Concrete	Biege	None	0	N/A	N/A	No		0	No	No	No				
1	3	309	Classroom 307/309 Closet	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No		0	No	No	No				
1	3	312	Classroom 312	yes	W1	Cinderblock	Beige	Flaking	3	0	Negative	No		0	No	No	No				
1	3	312	Classroom 312	yes	Column (W1)	Concrete	Beige	Flaking	2	0	Negative	No		0	No	No	No				
1	3	312	Classroom 312	yes	Support pole at Coat Closet (W1)	Metal	Beige	Chipping	4	0.6	Negative	No		0	No	No	No				

			School District of Philadelphia																					
			Lead Safe Certification Assessment Report																					
			Anderson Elementary School																					
			Inspection Dates: 5/4/20 through 5/8/20																					
			ULCS# 1460																					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes						
1	3	312	Classroom 312	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	3	0.01	Negative	No	0	No	No	No	No							
1	3	312	Classroom 312	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	3	0	Negative	No	0	No	No	No	No							
1	3	312	Classroom 312	yes	W2	Wood	Beige	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	312	Classroom 312	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	312	Classroom 312	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	312	Classroom 312	yes	Ceiling	Concrete	Biege	Flaking	12	0.06	Negative	No	0	No	No	No	No							
1	3	312	Classroom 312	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	W1	Cinderblock	Beige	Flaking	2	0	Negative	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	Column (W1)	Concrete	Beige	Flaking	8	0	Negative	No	0	No	No	No	No							
				yes	Support pole at Coat Closet (W1)																			
1	3	311	Classroom 311		Metal		Beige	Chipping	4	0.7	Positive	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	3	0.01	Negative	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	3	0.01	Negative	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	W2	Cinderblock	Beige	Flaking	2	0	Negative	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	W4	Cinderblock	Beige	Flaking	3	0	Negative	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	Ceiling	Concrete	Biege	Flaking	50	0.07	Negative	No	0	No	No	No	No							
1	3	311	Classroom 311	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	W1	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No							
				yes	Support pole at Coat Closet (W1)																			
1	3	313	Classroom 313		Metal		Green	Chipping	4	0.4	Negative	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	3	0.01	Negative	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	3	0	Negative	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	Exterior Door Jamb (W1)	Metal	Grey	Chipping	3	0	Negative	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	Exterior Door Stop (W1)	Metal	Grey	Chipping	3	0	Negative	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	W2	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	W3	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	W4	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	Ceiling	Concrete	White	Flaking	25	0.05	Negative	No	0	No	No	No	No							
1	3	313	Classroom 313	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	W1	Cinderblock	Beige	Chipping	2	0	Negative	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	Column (W1)	Concrete	Beige	Flaking	2	0	Negative	No	0	No	No	No	No							
				yes	Support pole at Coat Closet (W1)																			
1	3	314	Classroom 314		Metal		Beige	Chipping	6	0.7	Positive	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	3	0.01	Negative	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	3	0	Negative	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	W2	Cinderblock	Beige	Flaking	10	0	Negative	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	Column (W2)	Concrete	Beige	Flaking	4	0	Negative	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	Concrete Beam (W2)	Concrete	Beige	Flaking	10	0.06	Negative	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	Column (W3)	Concrete	Beige	Flaking	3	0	Negative	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	Column (W4)	Concrete	Beige	Flaking	3	0	Negative	No	0	No	No	No	No							
1	3	314	Classroom 314	yes	Ceiling	Concrete	Beige	Flaking	18	0.07	Negative	No	0	No	No	No	No	Includes Beam along the windows						
1	3	314	Classroom 314	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No							
1	3	S36	Stairwell C	yes	W1	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	S36	Stairwell C	yes	W2	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	S36	Stairwell C	yes	W3	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	S36	Stairwell C	yes	W4	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	S36	Stairwell C	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No							
1	3	S36	Stairwell C	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No							
1	3	S36	Stairwell C	yes	Stair Railing	Metal	Blue	Chipping	8	0.06	Negative	No	0	No	No	No	No							
1	3	S36	Stairwell C	yes	Stair Ringer	Metal	Blue	Chipping	3	0.04	Negative	No	0	No	No	No	No							
1	3	S31	Stairwell B	yes	W1	Cinderblock	Blue/White	None	0	N/A	N/A	No	0	No	No	No	No							

			School District of Philadelphia															
			Lead Safe Certification Assessment Report															
			Anderson Elementary School															
			Name of Inspector: Ananth K. Vinjamuri											Inspection Dates: 5/4/20 through 5/8/20				
			Inspection Company: Criterion Labs, Inc.											ULCS# 1460				
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	S31	Stairwell B	yes	Door (W1)	Metal	Blue	Chipping	2	0	Negative	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	Door Frame (W1)	Metal	Blue	Chipping	2	0.04	Negative	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	W2	Cinderblock	Blue/White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	W3	Cinderblock	Blue/White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	W4	Cinderblock	Blue/White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	Stair Railing	Metal	Blue	Chipping	10	0.05	Negative	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	Stair Ringer	Metal	Blue	Chipping	2	0.04	Negative	No	0	No	No	No	No	
1	3	S31	Stairwell B	yes	Stair Riser	Metal	Blue	Chipping	2	0.04	Negative	No	0	No	No	No	No	
1	3	H37	Hallway (from Room 300 to Room 314	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	H37	Hallway (from Room 300 to Room 314	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	H37	Hallway (from Room 300 to Room 314	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	H37	Hallway (from Room 300 to Room 314	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	H37	Hallway (from Room 300 to Room 314	yes	Ceiling	Concrete	White	Flaking	12	0.05	Negative	No	0	No	No	No	No	
1	3	H37	Hallway (from Room 300 to Room 314	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	3	S32	Stairwell A	yes	W1	Cinderblock	Blue/White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S32	Stairwell A	yes	W2	Cinderblock	Blue/White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S32	Stairwell A	yes	W3	Cinderblock	Blue/White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S32	Stairwell A	yes	W4	Cinderblock	Blue/White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S32	Stairwell A	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	3	S32	Stairwell A	yes	Floor	Concrete	Tan	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201	IMC 201	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201	IMC 201	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201	IMC 201	yes	W3	Cinderblock	Beige	Efflorescence	30	0.03	Negative	No	0	No	No	No	No	
1	2	201	IMC 201	yes	Column (W3)	Concrete	Beige	Flaking	4	0.02	Negative	No	0	No	No	No	No	
1	2	201	IMC 201	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201	IMC 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201	IMC 201	yes	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	201A	Closet adjacent to IMC 201 and Classroom 200	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201A	Closet adjacent to IMC 201 and Classroom 200	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201A	Closet adjacent to IMC 201 and Classroom 200	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201A	Closet adjacent to IMC 201 and Classroom 200	yes	Beam (W3)	Concrete	Beige	Flaking	1	0.09	Negative	No	0	No	No	No	No	Above the windows
1	2	201A	Closet adjacent to IMC 201 and Classroom 200	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201A	Closet adjacent to IMC 201 and Classroom 200	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	201A	Closet adjacent to IMC 201 and Classroom 200	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	W1	Cinderblock	Beige	Flaking	5	0	Negative	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	Column (W1)	Concrete	Beige	Flaking	2	0	Negative	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	4	0.7	Positive	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	6	0.02	Negative	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	Locker Door (W1)	Metal	Green	Chipping	3	0.06	Negative	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	W2	Cinderblock	Beige	Flaking	8	0	Negative	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	W3	Cinderblock	Beige	Flaking	3	0	Negative	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	W4	Cinderblock	Beige	Flaking	4	0	Negative	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	200	Classroom 200	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	W1	Cinderblock	Blue	Flaking	2	0	Negative	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	Column (W1)	Concrete	Blue	Flaking	5	0	Negative	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	Support Pole at Coat Closet (W1)	Metal	Blue	Chipping	3	0.8	Positive	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	8	0.13	Negative	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	Locker Door (W1)	Metal	Blue	Chipping	20	0	Negative	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	Column (W3)	Concrete	Blue	Flaking	4	0	Negative	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	W4	Cinderblock	Blue	Friction	10	0	Negative	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	202	Classroom 202	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	204	Classroom 204	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No	

			School District of Philadelphia																							
			Lead Safe Certification Assessment Report																							
			Anderson Elementary School																							
			Name of Inspector: Ananth K. Vinjamuri												Inspection Dates: 5/4/20 through 5/8/20											
			Inspection Company: Criterion Labs, Inc.												ULCS# 1460											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	2	204	Classroom 204	yes	Support Pole at Coat Closet (W1)	Metal	Green	Chipping	3	0.5	Negative	No	0	No	No	No	No									
1	2	204	Classroom 204	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	6	0.02	Negative	No	0	No	No	No	No									
1	2	204	Classroom 204	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	204	Classroom 204	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	204	Classroom 204	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	204	Classroom 204	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	204	Classroom 204	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	205	Teacher's Lounge 205	yes	W1	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	205	Teacher's Lounge 205	yes	W2	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	205	Teacher's Lounge 205	yes	W3	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	205	Teacher's Lounge 205	yes	W4	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	205	Teacher's Lounge 205	yes	Ceiling	Concrete	White	Flaking	15	0.04	Negative	No	0	No	No	No	No									
1	2	205	Teacher's Lounge 205	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	205A	Teacher's Lounge 205 Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	205A	Teacher's Lounge 205 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	205A	Teacher's Lounge 205 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	205A	Teacher's Lounge 205 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	205A	Teacher's Lounge 205 Closet	yes	Ceiling	Concrete	White	Flaking	2	0.03	Negative	No	0	No	No	No	No									
1	2	205A	Teacher's Lounge 205 Closet	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Men's Restroom	yes	W1	Cinderblock	Yellow/Brown	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Men's Restroom	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Men's Restroom	yes	W2	Cinderblock	Brown	Chipping	3	0.06	Negative	No	0	No	No	No	No									
1	2	207A	Men's Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Men's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Men's Restroom	yes	W4	Cinderblock	Brown	Chipping	2	0.06	Negative	No	0	No	No	No	No									
1	2	207A	Men's Restroom	yes	Ceiling	Concrete	White	Flaking	4	0.05	Negative	No	0	No	No	No	No									
1	2	207A	Men's Restroom	yes	Floor	Concrete	Brown	Friction	10	0	Negative	No	0	No	No	No	No									
1	2	207A	Women's Restroom	yes	W1	Cinderblock	Yellow/Brown	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Women's Restroom	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Women's Restroom	yes	W2	Cinderblock	Brown	Chipping	2	0.01	Negative	No	0	No	No	No	No									
1	2	207A	Women's Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Women's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Women's Restroom	yes	W4	Cinderblock	Brown	Chipping	2	0.02	Negative	No	0	No	No	No	No									
1	2	207A	Women's Restroom	yes	Ceiling	Concrete	White	Flaking	4	0.04	Negative	No	0	No	No	No	No									
1	2	207A	Women's Restroom	yes	Floor	Concrete	Grey	Friction	10	0	Negative	No	0	No	No	No	No									
1	2	207C	Boy's Restroom Pipe Chase	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207C	Boy's Restroom Pipe Chase	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207C	Boy's Restroom Pipe Chase	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207C	Boy's Restroom Pipe Chase	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207C	Boy's Restroom Pipe Chase	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207C	Boy's Restroom Pipe Chase	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Boy's Restroom	yes	W1	Cinderblock	Brown	Flaking	2	0.02	Negative	No	0	No	No	No	No									
1	2	207A	Boy's Restroom	yes	Interior Door Frame (W1)	Metal	Brown	Chipping	3	0.01	Negative	No	0	No	No	No	No									
1	2	207A	Boy's Restroom	yes	W2	Cinderblock	Brown	Flaking	10	0.01	Negative	No	0	No	No	No	No									
1	2	207A	Boy's Restroom	yes	W3	Cinderblock	Brown	Flaking	6	0.02	Negative	No	0	No	No	No	No									
1	2	207A	Boy's Restroom	yes	W4	Cinderblock	Brown	Flaking	12	0.02	Negative	No	0	No	No	No	No									
1	2	207A	Boy's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Boy's Restroom	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207D	Custodial Closet between Boy's and Girl's Restrooms	no	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207D	Custodial Closet between Boy's and Girl's Restrooms	no	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207D	Custodial Closet between Boy's and Girl's Restrooms	no	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207D	Custodial Closet between Boy's and Girl's Restrooms	no	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207D	Custodial Closet between Boy's and Girl's Restrooms	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207D	Custodial Closet between Boy's and Girl's Restrooms	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Girl's Restroom	yes	W1	Cinderblock	Brown	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Girl's Restroom	yes	Ductwork (W1)	Metal	Blue	Flaking	12	0.01	Negative	No	0	No	No	No	No									
1	2	207A	Girl's Restroom	yes	W2	Cinderblock	Brown	Flaking	4	0.02	Negative	No	0	No	No	No	No									
1	2	207A	Girl's Restroom	yes	W3	Cinderblock	Brown	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Girl's Restroom	yes	W4	Cinderblock	Brown	Flaking	4	0.02	Negative	No	0	No	No	No	No									
1	2	207A	Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	2	207A	Girl's Restroom	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	2	206	Classroom 206	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Anderson Elementary School																
			Name of Inspector: Ananth K. Vinjamuri												Inspection Dates: 5/4/20 through 5/8/20				
			Inspection Company: Criterion Labs, Inc.												ULCS# 1460				
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	206	Classroom 206	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	206	Classroom 206	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	206	Classroom 206	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	206	Classroom 206	yes	Ceiling	Concrete	White	Flaking	4	0.03	Negative	No	0	No	No	No	No		
1	2	206	Classroom 206	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	2	208	Classroom 208	yes	W1	Cinderblock	Beige	Flaking	2	0	Negative	No	0	No	No	No	No		
1	2	208	Classroom 208	yes	Column (W1)	Concrete	Beige	Flaking	2	0	Negative	No	0	No	No	No	No		
1	2	208	Classroom 208	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	3	0.3	Negative	No	0	No	No	No	No		
1	2	208	Classroom 208	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	208	Classroom 208	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	208	Classroom 208	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	208	Classroom 208	yes	Brace (W4)	Metal	Beige	Flaking	5	0.08	Negative	No	0	No	No	No	No	At Wall 1	
1	2	208	Classroom 208	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	208	Classroom 208	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	W1	Cinderblock	Beige	Flaking	2	0	Negative	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	4	0.5	Negative	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	8	0.01	Negative	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	W2	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Brace (W2)	Metal	Green	Chipping	4	0.06	Negative	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Brace (W2)	Metal	Beige	Chipping	4	0.4	Negative	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	W3	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Column (W3)	Concrete	Green	Flaking	1	0	Negative	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Column (W3)	Concrete	Beige	Flaking	3	0	Negative	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	W4	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Column (W4)	Concrete	Beige	Flaking	2	0	Negative	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	207	Classroom 207	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	Column (W1)	Concrete	Beige	Flaking	2	0	Negative	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	3	0.6	Negative	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	3	0	Negative	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	Column (W3)	Concrete	Beige	Flaking	3	0.01	Negative	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	210	Classroom 210	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	W1	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	W1	Cinderblock	Beige	Flaking	4	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Column (W1)	Concrete	Beige	Flaking	2	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	6	0.01	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	W2	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Column (W2)	Concrete	Green	Flaking	1	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Column (W2)	Concrete	Beige	Flaking	1	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	W3	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Column (W3)	Concrete	Green	Flaking	5	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Column (W3)	Concrete	Beige	Flaking	3	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	W4	Cinderblock	Green	None	2	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Column (W4)	Concrete	Green	Flaking	5	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Column (W4)	Concrete	Beige	Flaking	3	0	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Pipe Jacket (W4)	Metal	Beige	Chipping	4	0.13	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Ceiling	Concrete	White	Flaking	4	0.04	Negative	No	0	No	No	No	No		
1	2	209	Classroom 209	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	2	212	Classroom 212	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		

					School District of Philadelphia													
					Lead Safe Certification Assessment Report										Inspection Dates: 5/4/20 through 5/8/20			
					Anderson Elementary School										ULCS# 1460			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	212	Classroom 212	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	3	0.5	Negative	No	0	No	No	No	No	
1	2	212	Classroom 212	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	6	0.05	Negative	No	0	No	No	No	No	
1	2	212	Classroom 212	yes	W2	Wood	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	212	Classroom 212	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	212	Classroom 212	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	212	Classroom 212	yes	Ceiling	Concrete	White	Flaking	8	0.06	Negative	No	0	No	No	No	No	
1	2	212	Classroom 212	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	W1	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	W1	Cinderblock	Beige	Flaking	2	0	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Column (W1)	Concrete	Blue	Flaking	3	0	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	4	0.5	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Roof Drain Pipe (W1)	Metal	Tan	Chipping	4	0.11	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Hanger Flange (W1)	Metal	Beige	Chipping	4	0.6	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	6	0.01	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Exterior Door Frame (W1)	Metal	Grey	Chipping	5	0.01	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Column (W2)	Concrete	Green	Flaking	4	0	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Column (W2)	Concrete	Beige	Flaking	4	0	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Column (W3)	Concrete	Green	Flaking	3	0	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Column (W3)	Concrete	Beige	Flaking	4	0	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Column (W3)	Concrete	Blue	Flaking	2	0	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Ceiling	Concrete	White	Flaking	2	0.03	Negative	No	0	No	No	No	No	
1	2	211	Classroom 211	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	214	Classroom 214	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	214	Classroom 214	yes	Support Pole at Coat Closet (W1)	Cinderblock	Beige	Chipping	1	0.5	Negative	No	0	No	No	No	No	
1	2	214	Classroom 214	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	214	Classroom 214	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	214	Classroom 214	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	214	Classroom 214	yes	Ceiling	Concrete	White	Flaking	4	0.05	Negative	No	0	No	No	No	No	
1	2	214	Classroom 214	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	213	Classroom 213	yes	W1	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	213	Classroom 213	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	4	0	Negative	No	0	No	No	No	No	
1	2	213	Classroom 213	yes	W2	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	213	Classroom 213	yes	W3	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	213	Classroom 213	yes	W4	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	213	Classroom 213	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	213	Classroom 213	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	H26	Hallway (from Room 200 to Room 214	yes	W1	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	H26	Hallway (from Room 200 to Room 214	yes	W2	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	H26	Hallway (from Room 200 to Room 214	yes	W3	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	H26	Hallway (from Room 200 to Room 214	yes	W4	Cinderblock	Green/Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	H26	Hallway (from Room 200 to Room 214	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	H26	Hallway (from Room 200 to Room 214	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	W1	Cinderblock	White/Purple	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	Door (W1)	Metal	Blue	Chipping	3	0	Negative	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	Door Frame (W1)	Metal	Blue	Chipping	2	0	Negative	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	W2	Cinderblock	White/Purple	Chipping	2	0.3	Negative	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	W3	Cinderblock	White/Purple	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	W4	Cinderblock	White/Purple	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	Floor	Concrete	Tan	None	0	N/A	N/A	No	0	No	No	No	No	
1	2	S22	Stairwell A	yes	Stair Railing (W1)	Metal	Blue	Chipping	5	0.02	Negative	No	0	No	No	No	No	

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Anderson Elementary School																
			Name of Inspector: Ananth K. Vinjamuri		Inspection Dates: 5/4/20 through 5/8/20														
			Inspection Company: Criterion Labs, Inc.		ULCS# 1460														
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	S22	Stairwell A	yes	Stair Stringer (W1)	Metal	Blue	Chipping	2	0.11	Negative	No	0	No	No	No	No		
1	2	S22	Stairwell A	yes	Stair Riser (W1)	Metal	Blue	Chipping	2	0.13	Negative	No	0	No	No	No	No		
1	2	S21	Stairwell B	yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S21	Stairwell B	yes	Door Frame (W1)	Metal	Blue	Chipping	2	0.3	Negative	No	0	No	No	No	No		
1	2	S21	Stairwell B	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S21	Stairwell B	yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S21	Stairwell B	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S21	Stairwell B	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S21	Stairwell B	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	2	S26	Stairwell C	yes	W1	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S26	Stairwell C	yes	W2	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S26	Stairwell C	yes	W3	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S26	Stairwell C	yes	W4	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S26	Stairwell C	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	2	S26	Stairwell C	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110	Cafeteria/Gym	yes	W1	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110	Cafeteria/ Gym	yes	W2	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110	Cafeteria/ Gym	yes	W3	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110	Cafeteria/ Gym	yes	W4	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110	Cafeteria/ Gym	yes	Ceiling	Concrete/Metal Tru	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110	Cafeteria/ Gym	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110F	Gym Office	yes	W1	Cinderblock	Tan	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110F	Gym Office	yes	W2	Cinderblock	Tan	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110F	Gym Office	yes	W3	Cinderblock	Tan	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110F	Gym Office	yes	W4	Cinderblock	Tan	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110F	Gym Office	yes	Ceiling	Concrete	Tan	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110F	Gym Office	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110H	Gym Office Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110H	Gym Office Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110H	Gym Office Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110H	Gym Office Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110H	Gym Office Restroom	yes	Ceiling	Concrete	White	Flaking	4	0.02	Negative	No	0	No	No	No	No		
1	1	110H	Gym Office Restroom	yes	Floor	Concrete	Tan	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Gym Office Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Gym Office Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Gym Office Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Gym Office Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Gym Office Closet	yes	Ceiling	Concrete	White	Flaking	2	0.02	Negative	No	0	No	No	No	No		
1	1	110I	Gym Office Closet	yes	Floor	Concrete	Tan	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110E	Water Room between Gym Office and Gym Girl's Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110E	Water Room between Gym Office and Gym Girl's Restroom	yes	Interior Door Frame (W1)	Metal	Beige	Friction	2	0.01	Negative	No	0	No	No	No	No		
1	1	110E	Water Room between Gym Office and Gym Girl's Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110E	Water Room between Gym Office and Gym Girl's Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110E	Water Room between Gym Office and Gym Girl's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110E	Water Room between Gym Office and Gym Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110E	Water Room between Gym Office and Gym Girl's Restroom	yes	Ductwork at Ceiling	Metal	White	Flaking	1	0.01	Negative	No	0	No	No	No	No		
1	1	110E	Water Room between Gym Office and Gym Girl's Restroom	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110J	Fan Room above Gym Offices and Restrooms	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110J	Fan Room above Gym Offices and Restrooms	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110J	Fan Room above Gym Offices and Restrooms	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110J	Fan Room above Gym Offices and Restrooms	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110J	Fan Room above Gym Offices and Restrooms	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110J	Fan Room above Gym Offices and Restrooms	no	Ceiling Hatch	Metal	Black	Chipping	2	0.12	Negative	No	0	No	No	No	No		
1	1	110J	Fan Room above Gym Offices and Restrooms	no	Ductwork	Metal	Grey	Flaking	200	0.01	Negative	No	0	No	No	No	No		
1	1	110J	Fan Room above Gym Offices and Restrooms	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	W1	Cinderblock	White/Pink	None	0	N/A	N/A	No	0	No	No	No	No		

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Anderson Elementary School																
			Name of Inspector: Ananth K. Vinjamuri		Inspection Dates: 5/4/20 through 5/8/20														
			Inspection Company: Criterion Labs, Inc.		ULCS# 1460														
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	110A	Gym Girl's Restroom	yes	Exterior Door (W1)	Metal	Blue	Friction	3	0	Negative	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	Exterior Door Frame (W1)	Metal	Blue	Friction	3	0	Negative	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	Exterior Door Stop (W1)	Metal	Blue	Friction	3	0	Negative	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	W2	Cinderblock	Pink	Friction	2	0.03	Negative	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	W3	Cinderblock	Pink	Friction	6	0.05	Negative	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	W4	Cinderblock	White/Pink	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	Ceiling	Concrete	White	Flaking	5	0.03	Negative	No	0	No	No	No	No		
1	1	110A	Gym Girl's Restroom	yes	Floor	Concrete	Grey	Friction	3	0.01	Negative	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	W1	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	Interior Door Frame (W1)	Metal	Tan	Friction	2	0	Negative	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	Exterior Door (W1)	Metal	Blue	Friction	4	0	Negative	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	Exterior Door Frame (W1)	Metal	Blue	Friction	3	0	Negative	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	Exterior Door Stop (W1)	Metal	Blue	Friction	3	0	Negative	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	W2	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	W3	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	W4	Cinderblock	Green	Flaking	4	0	Negative	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	Ceiling	Concrete	White	Flaking	5	0.04	Negative	No	0	No	No	No	No		
1	1	110B	Gym Boy's Restroom	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110C	Kitchen Office	yes	W1	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110C	Kitchen Office	yes	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110C	Kitchen Office	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110C	Kitchen Office	yes	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110C	Kitchen Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110C	Kitchen Office	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110D	Kitchen	yes	W1	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110D	Kitchen	yes	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110D	Kitchen	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110D	Kitchen	yes	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110D	Kitchen	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110D	Kitchen	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110G	Kitchen Storage	yes	W1	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110G	Kitchen Storage	yes	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110G	Kitchen Storage	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110G	Kitchen Storage	yes	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110G	Kitchen Storage	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110G	Kitchen Storage	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Cafeteria/ Gym Entrance Area	yes	W1	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Cafeteria/ Gym Entrance Area	yes	W2	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Cafeteria/ Gym Entrance Area	yes	W3	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Cafeteria/ Gym Entrance Area	yes	W4	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Cafeteria/ Gym Entrance Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	110I	Cafeteria/ Gym Entrance Area	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	109	Auditorium	yes	W1	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	109	Auditorium	yes	W1	Cinderblock	Blue	Friction	1	0.01	Negative	No	0	No	No	No	No		
1	1	109	Auditorium	yes	Round column	Concrete	Blue	Friction	8	0	Negative	No	0	No	No	No	No		
1	1	109	Auditorium	yes	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	109	Auditorium	yes	W2	Cinderblock	Blue	Friction	2	0.05	Negative	No	0	No	No	No	No		
1	1	109	Auditorium	yes	W3	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	109	Auditorium	yes	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	109	Auditorium	yes	W4	Cinderblock	Blue	Friction	6	0.01	Negative	No	0	No	No	No	No		
1	1	109	Auditorium	yes	Upper Ceiling	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	109	Auditorium	yes	Lower Ceiling	Sheetrock	White	Flaking	3	0	Negative	No	0	No	No	No	No		
1	1	109	Auditorium	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No		
1	1	109 STAGE	Auditorium Stage	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	109 STAGE	Auditorium Stage	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	109 STAGE	Auditorium Stage	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		
1	1	109 STAGE	Auditorium Stage	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No		

			School District of Philadelphia																		
			Lead Safe Certification Assessment Report																		
			Anderson Elementary School																		
			Name of Inspector: Ananth K. Vinjamuri												Inspection Dates: 5/4/20 through 5/8/20						
			Inspection Company: Criterion Labs, Inc.												ULCS# 1460						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	1	109 STAGE	Auditorium Stage	yes	Ceiling	Concrete/Metal Truss	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	109 STAGE	Auditorium Stage	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	109A	Auditorium Stage Pipe Chase	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	109A	Auditorium Stage Pipe Chase	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	109A	Auditorium Stage Pipe Chase	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	109A	Auditorium Stage Pipe Chase	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	109A	Auditorium Stage Pipe Chase	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	109A	Auditorium Stage Pipe Chase	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	100A	Former Men's Restroom near Auditorium	no	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100A	Former Men's Restroom near Auditorium	no	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100A	Former Men's Restroom near Auditorium	no	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100A	Former Men's Restroom near Auditorium	no	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100A	Former Men's Restroom near Auditorium	no	Ceiling	Concrete	White	Flaking	1	0.04	Negative	No	0	No	No	No	No				
1	1	100A	Former Men's Restroom near Auditorium	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	100B	Former Women's Restroom and Former Security Office near Auditorium	no	W1	Cinderblock	Blue	Friction	1	0	Negative	No	0	No	No	No	No				
1	1	100B	Former Women's Restroom and Former Security Office near Auditorium	no	Interior Door Frame (W1)	Metal	Tan	Friction	2	0.01	Negative	No	0	No	No	No	No				
1	1	100B	Former Women's Restroom and Former Security Office near Auditorium	no	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100B	Former Women's Restroom and Former Security Office near Auditorium	no	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100B	Former Women's Restroom and Former Security Office near Auditorium	no	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100B	Former Women's Restroom and Former Security Office near Auditorium	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100B	Former Women's Restroom and Former Security Office near Auditorium	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	100M	Former Women's Restroom and Former Security Office near Auditorium Pipe Chase	no	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100M	Former Women's Restroom and Former Security Office near Auditorium Pipe Chase	no	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100M	Former Women's Restroom and Former Security Office near Auditorium Pipe Chase	no	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100M	Former Women's Restroom and Former Security Office near Auditorium Pipe Chase	no	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100M	Former Women's Restroom and Former Security Office near Auditorium Pipe Chase	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100M	Former Women's Restroom and Former Security Office near Auditorium Pipe Chase	no	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	W1	Cinderblock	Blue	Friction	2	0	Negative	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	Column (W1)	Concrete	Blue	Flaking	2	0	Negative	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	3	0.01	Negative	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	Column (W3)	Concrete	Blue	Flaking	4	0	Negative	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	Column (W4)	Concrete	Blue	Flaking	6	0	Negative	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	Ceiling	Concrete	White	Flaking	20	0.3	Negative	No	0	No	No	No	No				
1	1	100	Classroom 100	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	100D	Principal's Office	yes	W1	Purple	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100D	Principal's Office	yes	W2	Purple	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100D	Principal's Office	yes	W3	Purple	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100D	Principal's Office	yes	W4	Purple	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100D	Principal's Office	yes	Ceiling	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	100D	Principal's Office	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	100C	Principal's Office Restroom	yes	W1	Cinderblock	Red	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100C	Principal's Office Restroom	yes	W2	Cinderblock	Red	Flaking	4	0.05	Negative	No	0	No	No	No	No				
1	1	100C	Principal's Office Restroom	yes	W3	Cinderblock	Red	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100C	Principal's Office Restroom	yes	W4	Cinderblock	Red	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100C	Principal's Office Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100C	Principal's Office Restroom	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	1	100J	Principal's Office Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100J	Principal's Office Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100J	Principal's Office Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	1	100J	Principal's Office Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				

			School District of Philadelphia																						
			Lead Safe Certification Assessment Report																						
			Anderson Elementary School																						
			Name of Inspector: Ananth K. Vinjamuri		Inspection Dates: 5/4/20 through 5/8/20							ULCS# 1460													
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes							
1	1	100J	Principal's Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100J	Principal's Office Closet	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No								
1	1	100F	Main Office	yes	W1	Cinderblock	Purple	Friction	1	0	Negative	No	0	No	No	No	No								
1	1	100F	Main Office	yes	Window Sill (W1)	Metal	Beige	Chipping	2	0	Negative	No	0	No	No	No	No								
1	1	100F	Main Office	yes	W2	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100F	Main Office	yes	W3	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100F	Main Office	yes	W4	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100F	Main Office	yes	Ceiling	Tile/Concrete	White	Flaking	1	0.01	Negative	No	0	No	No	No	No								
1	1	100F	Main Office	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No								
1	1	100G	Main Office Conference Room	yes	W1	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100G	Main Office Conference Room	yes	Interior Door Frame (W1)	Metal	White	Chipping	1	0.01	Negative	No	0	No	No	No	No								
1	1	100G	Main Office Conference Room	yes	W2	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100G	Main Office Conference Room	yes	W3	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100G	Main Office Conference Room	yes	W4	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100G	Main Office Conference Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100G	Main Office Conference Room	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No								
1	1	100H	Office between Main Office Conference Room and Nurse's Office	yes	W1	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100H	Office between Main Office Conference Room and Nurse's Office	yes	W2	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100H	Office between Main Office Conference Room and Nurse's Office	yes	W3	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100H	Office between Main Office Conference Room and Nurse's Office	yes	Column (W3)	Concrete	Blue	Chipping	2	0.01	Negative	No	0	No	No	No	No								
1	1	100H	Office between Main Office Conference Room and Nurse's Office	yes	Pipe Jacket (W3)	Metal	Blue	Flaking	2	0.07	Negative	No	0	No	No	No	No								
1	1	100H	Office between Main Office Conference Room and Nurse's Office	yes	W4	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100H	Office between Main Office Conference Room and Nurse's Office	yes	Ceiling	Concrete	Tile/Concrete	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100H	Office between Main Office Conference Room and Nurse's Office	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No								
1	1	100I	Main Office Telecommunication Equipment Room	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100I	Main Office Telecommunication Equipment Room	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100I	Main Office Telecommunication Equipment Room	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100I	Main Office Telecommunication Equipment Room	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100I	Main Office Telecommunication Equipment Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100I	Main Office Telecommunication Equipment Room	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No								
1	1	100K	Storage Room between Main Office Telecommunication Equipment Room and Nurse's Office	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100K	Storage Room between Main Office Telecommunication Equipment Room and Nurse's Office	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100K	Storage Room between Main Office Telecommunication Equipment Room and Nurse's Office	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100K	Storage Room between Main Office Telecommunication Equipment Room and Nurse's Office	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100K	Storage Room between Main Office Telecommunication Equipment Room and Nurse's Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100K	Storage Room between Main Office Telecommunication Equipment Room and Nurse's Office	yes	Floor	Concrete	Grey	Friction	4	0.01	Negative	No	0	No	No	No	No								
1	1	100L	Main Office Hallway outside Main Office Conference Room leading to Nurse's Office	yes	W1	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100L	Main Office Hallway outside Main Office Conference Room leading to Nurse's Office	yes	W2	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100L	Main Office Hallway outside Main Office Conference Room leading to Nurse's Office	yes	W3	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100L	Main Office Hallway outside Main Office Conference Room leading to Nurse's Office	yes	W4	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No								
1	1	100L	Main Office Hallway outside Main Office Conference Room leading to Nurse's Office	yes	Ceiling	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No								
1	1	100L	Main Office Hallway outside Main Office Conference Room leading to Nurse's Office	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No								

			School District of Philadelphia																							
			Lead Safe Certification Assessment Report																							
			Anderson Elementary School																							
			Name of Inspector: Ananth K. Vinjamuri										Inspection Dates: 5/4/20 through 5/8/20													
			Inspection Company: Criterion Labs, Inc.										ULCS# 1460													
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	1	102A	Nurse's Office	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102A	Nurse's Office	yes	W2	Cinderblock	Blue	Friction	1	0	Negative	No	0	No	No	No	No									
1	1	102A	Nurse's Office	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102A	Nurse's Office	yes	W4	Cinderblock	Blue	Friction	2	0.01	Negative	No	0	No	No	No	No									
1	1	102A	Nurse's Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102A	Nurse's Office	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	102B	Nurse's Office Restroom	yes	W1	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102B	Nurse's Office Restroom	yes	W2	Cinderblock	White/Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102B	Nurse's Office Restroom	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102B	Nurse's Office Restroom	yes	W3	Cinderblock	Blue	Flaking	4	0.02	Negative	No	0	No	No	No	No									
1	1	102B	Nurse's Office Restroom	yes	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102B	Nurse's Office Restroom	yes	W4	Cinderblock	Blue	Flaking	4	0.06	Negative	No	0	No	No	No	No									
1	1	102B	Nurse's Office Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102B	Nurse's Office Restroom	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	102C	Nurse's Office Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102C	Nurse's Office Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102C	Nurse's Office Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102C	Nurse's Office Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102C	Nurse's Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	102C	Nurse's Office Closet	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	101A	Storage Room between Elevator and Women's Restroom	yes	W1	Cinderblock	Grey	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101A	Storage Room between Elevator and Women's Restroom	yes	Steam Pipe (W1)	Metal	White	Flaking	4	0.09	Negative	No	0	No	No	No	No									
1	1	101A	Storage Room between Elevator and Women's Restroom	yes	W2	Cinderblock	Grey	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101A	Storage Room between Elevator and Women's Restroom	yes	W3	Cinderblock	Grey	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101A	Storage Room between Elevator and Women's Restroom	yes	W4	Cinderblock	Grey	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101A	Storage Room between Elevator and Women's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101A	Storage Room between Elevator and Women's Restroom	yes	Floor	Concrete	Grey	Friction	10	0.05	Negative	No	0	No	No	No	No									
1	1	101C	Custodial Closet between Men's Restroom and Boy's Restroom	no	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101C	Custodial Closet between Men's Restroom and Boy's Restroom	no	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101C	Custodial Closet between Men's Restroom and Boy's Restroom	no	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101C	Custodial Closet between Men's Restroom and Boy's Restroom	no	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101C	Custodial Closet between Men's Restroom and Boy's Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101C	Custodial Closet between Men's Restroom and Boy's Restroom	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	W1	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	W1	Cinderblock	Green	Flaking	2	0.03	Negative	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	W2	Cinderblock	Green	Flaking	4	0.04	Negative	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	W3	Cinderblock	Green	Flaking	6	0.02	Negative	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	W4	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	Pipe Chase Door Frame (W4)	Metal	Tan	Flaking	8	0.03	Negative	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	Ceiling	Concrete	Grey	Flaking	30	0.03	Negative	No	0	No	No	No	No									
1	1	101E	Boy's Restroom	yes	Floor	Concrete	Grey	Friction	5	0	Negative	No	0	No	No	No	No									
1	1	101G	Boy's Restroom Pipe Chase adjacent to Girl's Restroom	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	101G	Boy's Restroom Pipe Chase adjacent to Girl's Restroom	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	101G	Boy's Restroom Pipe Chase adjacent to Girl's Restroom	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	101G	Boy's Restroom Pipe Chase adjacent to Girl's Restroom	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	101G	Boy's Restroom Pipe Chase adjacent to Girl's Restroom	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									

			School District of Philadelphia															
			Lead Safe Certification Assessment Report															
			Anderson Elementary School															
			Name of Inspector: Ananth K. Vinjamuri		Inspection Dates: 5/4/20 through 5/8/20													
			Inspection Company: Criterion Labs, Inc.		ULCS# 1460													
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	101G	Boy's Restroom Pipe Chase adjacent to Girl's Restroom	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	W1	Cinderblock	White	Flaking	2	0.04	Negative	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	W1	Cinderblock	Green	Flaking	2	0.04	Negative	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	W2	Cinderblock	Green	Flaking	6	0.03	Negative	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	W3	Cinderblock	Green	Flaking	8	0.01	Negative	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	W4	Cinderblock	Green	Flaking	4	0.01	Negative	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	Ceiling	Concrete	Grey	Flaking	20	0.03	Negative	No	0	No	No	No	No	
1	1	101F	Girl's Restroom	yes	Floor	Concrete	Grey	Friction	10	0	Negative	No	0	No	No	No	No	
1	1	101D	Men's Restroom	yes	W1	Cinderblock	White/Green	None	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101D	Men's Restroom	yes	W2	Cinderblock	White	Flaking	5	0.04	Negative	No	0	No	No	No	No	
1	1	101D	Men's Restroom	yes	W2	Cinderblock	Green	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101D	Men's Restroom	yes	W3	Cinderblock	White/Green	None	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101D	Men's Restroom	yes	W4	Cinderblock	White/Green	None	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101D	Men's Restroom	yes	Ceiling	Concrete	White	None	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101D	Men's Restroom	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101H	Boy's Restroom Pipe Chase adjacent to Men's and Women's Restrooms	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101H	Boy's Restroom Pipe Chase adjacent to Men's and Women's Restrooms	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101H	Boy's Restroom Pipe Chase adjacent to Men's and Women's Restrooms	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101H	Boy's Restroom Pipe Chase adjacent to Men's and Women's Restrooms	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101H	Boy's Restroom Pipe Chase adjacent to Men's and Women's Restrooms	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101H	Boy's Restroom Pipe Chase adjacent to Men's and Women's Restrooms	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101B	Women's Restroom	yes	W1	Cinderblock	White/Purple	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101B	Women's Restroom	yes	W2	Cinderblock	White/Purple	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101B	Women's Restroom	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101B	Women's Restroom	yes	W3	Cinderblock	Purple	Friction	3	0.01	Negative	No	0	No	No	No	No	
1	1	101B	Women's Restroom	yes	W4	Cinderblock	White	Flaking	3	0.03	Negative	No	0	No	No	No	No	
1	1	101B	Women's Restroom	yes	W4	Cinderblock	Purple	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101B	Women's Restroom	yes	Ceiling	Concrete	White	Flaking	10	0.02	Negative	No	0	No	No	No	No	
1	1	101B	Women's Restroom	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	102	Classroom 102	yes	W1	Cinderblock	Beige	Friction	1	0	Negative	No	0	No	No	No	No	
1	1	102	Classroom 102	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	2	0.7	Positive	No	0	No	No	No	No	
1	1	102	Classroom 102	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	6	0	Negative	No	0	No	No	No	No	
1	1	102	Classroom 102	yes	W2	Wood	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102	Classroom 102	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102	Classroom 102	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102	Classroom 102	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102	Classroom 102	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	W1	Cinderblock	Beige	Friction	2	0.01	Negative	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	Column (W1)	Concrete	Beige	Flaking	3	0	Negative	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	3	0.3	Negative	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	4	0	Negative	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	Univentilator Cover (W3)	Metal	Tan	Friction	3	0	Negative	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	Pipe Jacket (W3)	Cinderblock	Tan	Flaking	4	0.01	Negative	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	W4	Wood	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	Ceiling	Concrete	White	Flaking	3	0.05	Negative	No	0	No	No	No	No	
1	1	104	Classroom 104	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	W1	Cinderblock	Beige	Flaking	2	0.01	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Column (W1)	Concrete	Beige	Flaking	2	0.01	Negative	No	0	No	No	No	No	

			School District of Philadelphia															
			Lead Safe Certification Assessment Report															
			Anderson Elementary School															
			Name of Inspector: Ananth K. Vinjamuri											Inspection Dates: 5/4/20 through 5/8/20				
			Inspection Company: Criterion Labs, Inc.											ULCS# 1460				
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	101	Classroom 101	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	6	0.01	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Interior Door Jamb (W1)	Metal	Tan	Chipping	3	0	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Interior Door Stop (W1)	Metal	Tan	Chipping	3	0	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Exterior Door Frame (W1)	Metal	Blue	Chipping	3	0	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Support Post at Coat Closet (W1)	Metal	Beige	Chipping	3	0.4	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Expansion flange at floor (W2)	Metal	Beige	Friction	8	0.11	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Univentilator Cover (W3)	Metal	Blue	Chipping	4	0.6	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Column (W4)	Concrete	Beige	Flaking	1	0	Negative	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	101	Classroom 101	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	103	Office 103	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	103	Office 103	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	6	0	Negative	No	0	No	No	No	No	
1	1	103	Office 103	yes	Interior Door Stop (W1)	Metal	Tan	Chipping	4	0	Negative	No	0	No	No	No	No	
1	1	103	Office 103	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	103	Office 103	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	103	Office 103	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	103	Office 103	yes	Ceiling	Concrete	White	Efflorescence	3	0.05	Negative	No	0	No	No	No	No	
1	1	103	Office 103	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	Support Pole at Coat Closet (W1)	Metal	Beige	Chipping	2	0.6	Negative	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	6	0	Negative	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	Interior Door Jamb (W1)	Metal	Tan	Chipping	1	0	Negative	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	Interior Door Stop (W1)	Metal	Tan	Chipping	4	0	Negative	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	Column (W3)	Concrete	Beige	Flaking	1	0	Negative	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	Univentilator Cover (W3)	Metal	Blue	Friction	6	0.6	Negative	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	W4	Cinderblock	Beige	Friction	2	0	Negative	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	106	Classroom 106	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	105D	Storage Room between Stairwell B and Classroom 105	yes	W1	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105D	Storage Room between Stairwell B and Classroom 105	yes	W2	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105D	Storage Room between Stairwell B and Classroom 105	yes	W3	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105D	Storage Room between Stairwell B and Classroom 105	yes	W4	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105D	Storage Room between Stairwell B and Classroom 105	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105D	Storage Room between Stairwell B and Classroom 105	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	105	Classroom 105	yes	W1	Cinderblock	Beige	Flaking	1	0	Negative	No	0	No	No	No	No	
1	1	105	Classroom 105	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105	Classroom 105	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105	Classroom 105	yes	Column (W3)	Concrete	Beige	None	5	0.01	Negative	No	0	No	No	No	No	
1	1	105	Classroom 105	yes	W4	Cinderblock	Beige	Flaking	50	0	Negative	No	0	No	No	No	No	
1	1	105	Classroom 105	yes	Column (W4)	Concrete	Beige	Flaking	2	0.01	Negative	No	0	No	No	No	No	
1	1	105	Classroom 105	yes	Ceiling	Concrete	White	Water Stains	4	0.01	Negative	No	0	No	No	No	No	Transite ceiling at coat area

			School District of Philadelphia															
			Lead Safe Certification Assessment Report															
			Anderson Elementary School															
			Name of Inspector: Ananth K. Vinjamuri		Inspection Dates: 5/4/20 through 5/8/20													
			Inspection Company: Criterion Labs, Inc.		ULCS# 1460													
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	105	Classroom 105	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	105A	Classroom 105 Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105A	Classroom 105 Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105A	Classroom 105 Restroom	yes	W3	Cinderblock	Beige	Flaking, Efflorescence	10	0.06	Negative	No	0	No	No	No	No	
1	1	105A	Classroom 105 Restroom	yes	W4	Cinderblock	Beige	Friction	3	0.03	Negative	No	0	No	No	No	No	
1	1	105A	Classroom 105 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105A	Classroom 105 Restroom	yes	Floor	Concrete	Grey	Friction	10	0	Negative	No	0	No	No	No	No	
1	1	105B	Classroom 105 Storage Room adjacent to Restroom	yes	W1	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105B	Classroom 105 Storage Room adjacent to Restroom	yes	W2	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105B	Classroom 105 Storage Room adjacent to Restroom	yes	W3	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105B	Classroom 105 Storage Room adjacent to Restroom	yes	W4	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105B	Classroom 105 Storage Room adjacent to Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105B	Classroom 105 Storage Room adjacent to Restroom	yes	Floor	Concrete	No Paint	N/A	N/A	No Paint	N/A	No	0	No	No	No	No	
1	1	105E	Classroom 105 Storage Room behind Restroom and other Storage Room	yes	W1	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105E	Classroom 105 Storage Room behind Restroom and other Storage Room	yes	W2	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105E	Classroom 105 Storage Room behind Restroom and other Storage Room	yes	W3	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105E	Classroom 105 Storage Room behind Restroom and other Storage Room	yes	W4	Cinderblock	Green	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	105E	Classroom 105 Storage Room behind Restroom and other Storage Room	yes	Ceiling	Concrete	White	Flaking	3	0.03	Negative	No	0	No	No	No	No	
1	1	105E	Classroom 105 Storage Room behind Restroom and other Storage Room	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	108	Classroom 108	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108	Classroom 108	yes	Column (W1)	Concrete	Beige	Flaking	2	0	Negative	No	0	No	No	No	No	
1	1	108	Classroom 108	yes	Interior Door Frame (W1)	Metal	Tan	Chipping	6	0	Negative	No	0	No	No	No	No	
1	1	108	Classroom 108	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108	Classroom 108	yes	W3	Cinderblock	Beige	Flaking	2	0.01	Negative	No	0	No	No	No	No	
1	1	108	Classroom 108	yes	Univentilator Cover (W3)	Metal	Orange	Friction	5	0.5	Negative	No	0	No	No	No	No	
1	1	108	Classroom 108	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108	Classroom 108	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	Transite Ceiling at coat area
1	1	108	Classroom 108	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	108A	Classroom 108 Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108A	Classroom 108 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108A	Classroom 108 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108A	Classroom 108 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108A	Classroom 108 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108A	Classroom 108 Closet	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	108B	Classroom 108 Restroom	yes	W1	Cinderblock	Grey/Yellow	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108B	Classroom 108 Restroom	yes	W2	Cinderblock	Grey/Yellow	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108B	Classroom 108 Restroom	yes	W3	Cinderblock	Yellow	Efflorescence	4	0.01	Negative	No	0	No	No	No	No	
1	1	108B	Classroom 108 Restroom	yes	W3	Cinderblock	Grey	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108B	Classroom 108 Restroom	yes	W4	Cinderblock	Grey/Yellow	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108B	Classroom 108 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	108B	Classroom 108 Restroom	yes	Floor	Concrete	Grey	Friction	20	0.01	Negative	No	0	No	No	No	No	
1	1	102D	Closet adjacent to Hallway Entrance to Nurse's Office	yes	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102D	Closet adjacent to Hallway Entrance to Nurse's Office	yes	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102D	Closet adjacent to Hallway Entrance to Nurse's Office	yes	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102D	Closet adjacent to Hallway Entrance to Nurse's Office	yes	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102D	Closet adjacent to Hallway Entrance to Nurse's Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	102D	Closet adjacent to Hallway Entrance to Nurse's Office	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	H13	Hallway outside Main Office to Classroom 108	yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	H13	Hallway outside Main Office to Classroom 108	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	H13	Hallway outside Main Office to Classroom 108	yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	H13	Hallway outside Main Office to Classroom 108	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	H13	Hallway outside Main Office to Classroom 108	yes	Ceiling	Concrete	White	Flaking	2	0.01	Negative	No	0	No	No	No	No	
1	1	H13	Hallway outside Main Office to Classroom 108	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	S100	Main Entrance	yes	W1	Brick	No Paint	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	S100	Main Entrance	yes	W2	Brick	No Paint	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	S100	Main Entrance	yes	W3	Brick	No Paint	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	S100	Main Entrance	yes	W4	Brick	No Paint	None	0	N/A	N/A	No	0	No	No	No	No	
1	1	S100	Main Entrance	yes	Ceiling	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	1	S100	Main Entrance	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	

			School District of Philadelphia																							
			Lead Safe Certification Assessment Report																							
			Anderson Elementary School																							
			Name of Inspector: Ananth K. Vinjamuri		Inspection Dates: 5/4/20 through 5/8/20													ULCS# 1460								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	1	H15	Main Lobby	yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	H15	Main Lobby	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	H15	Main Lobby	yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	H15	Main Lobby	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	H15	Main Lobby	yes	Ceiling	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	H15	Main Lobby	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	H14	Hallway from Main Lobby to Cafeteria/Gym	yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	H14	Hallway from Main Lobby to Cafeteria/Gym	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	H14	Hallway from Main Lobby to Cafeteria/Gym	yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	H14	Hallway from Main Lobby to Cafeteria/Gym	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	H14	Hallway from Main Lobby to Cafeteria/Gym	yes	Ceiling	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	H14	Hallway from Main Lobby to Cafeteria/Gym	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	E1	Elevator	yes	W1	Metal	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	E1	Elevator	yes	W2	Metal	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	E1	Elevator	yes	W3	Metal	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	E1	Elevator	yes	W4	Metal	Beige	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	E1	Elevator	yes	Ceiling	Metal	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	E1	Elevator	yes	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	W1	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	Door (W1)	Metal	Blue	Chipping	1	0	Negative	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	Door Frame (W1)	Metal	Blue	Chipping	2	0	Negative	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	W2	Cinderblock	White	Chipping	2	0.03	Negative	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	Exit Door (W3)	Metal	Blue	Chipping	1	0	Negative	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	Exit Door Frame (W3)	Metal	Blue	Chipping	2	0	Negative	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	Floor	Concrete	Tan	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S12	Stairwell A	yes	Stair Railing towards the exit	Metal	Blue	Chipping	4	0.12	Negative	No	0	No	No	No	No									
1	1	S16	Stairwell C	yes	W1	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell C	yes	W2	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell C	yes	W3	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell C	yes	W4	Cinderblock	White/Green	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell C	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell C	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell B	yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell B	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell B	yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell B	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell B	yes	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell B	yes	Metal support at ceiling by Exit doors	Metal	Blue	Flaking	16	0.7	Positive	No	0	No	No	No	No									
1	1	S11	Stairwell B	yes	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	1	S11	Stairwell B	yes	Stair Riser	Concrete	Blue	Friction	4	0.01	Negative	No	0	No	No	No	No									
1	B	001A	Storage Room between Stairwell A and Elevator	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	B	001A	Storage Room between Stairwell A and Elevator	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	B	001A	Storage Room between Stairwell A and Elevator	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	B	001A	Storage Room between Stairwell A and Elevator	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	B	001A	Storage Room between Stairwell A and Elevator	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	B	001A	Storage Room between Stairwell A and Elevator	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No									
1	B	001B	Building Engineer's Office Restroom	no	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001B	Building Engineer's Office Restroom	no	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001B	Building Engineer's Office Restroom	no	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001B	Building Engineer's Office Restroom	no	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001B	Building Engineer's Office Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001B	Building Engineer's Office Restroom	no	Floor	Concrete	Red	Friction	4	0	Negative	No	0	No	No	No	No									
1	B	001C	Building Engineer's Office	no	W1	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001C	Building Engineer's Office	no	W2	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001C	Building Engineer's Office	no	W3	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001C	Building Engineer's Office	no	W4	Cinderblock	Blue	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001C	Building Engineer's Office	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No									
1	B	001C	Building Engineer's Office	no	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No									

			School District of Philadelphia																		
			Lead Safe Certification Assessment Report																		
			Inspection Dates: 5/4/20 through 5/8/20																		
			Name of Inspector: Ananth K. Vinjamuri		Anderson Elementary School											Inspection Company: Criterion Labs, Inc.			ULCS# 1460		
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	B	001D	Emergency Generator Room	no	W1	Cinderblock	White/Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001D	Emergency Generator Room	no	Column (W1)	Concrete	Beige	Flaking	2	0	Negative	No	0	No	No	No	No				
1	B	001D	Emergency Generator Room	no	Door (W1)	Metal	Grey	Flaking	4	0	Negative	No	0	No	No	No	No				
1	B	001D	Emergency Generator Room	no	W2	Cinderblock	White/Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001D	Emergency Generator Room	no	W3	Cinderblock	White/Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001D	Emergency Generator Room	no	W4	Cinderblock	White/Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001D	Emergency Generator Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001D	Emergency Generator Room	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	W1	Cinderblock	White/Grey	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	W2	Cinderblock	Grey	Flaking	20	0.01	Negative	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	W3	Cinderblock	Grey	Flaking	20	0.01	Negative	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	W4	Cinderblock	Grey	Flaking	30	0.01	Negative	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	H01	Hallway from Boiler Room to Stairwell B	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001E	Storage Room between Electrical Room and Emergency Generator Room	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001E	Storage Room between Electrical Room and Emergency Generator Room	no	Door Frame (W1)	Metal	Grey	Flaking	6	0.01	Negative	No	0	No	No	No	No				
1	B	001E	Storage Room between Electrical Room and Emergency Generator Room	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001E	Storage Room between Electrical Room and Emergency Generator Room	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001E	Storage Room between Electrical Room and Emergency Generator Room	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001E	Storage Room between Electrical Room and Emergency Generator Room	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001E	Storage Room between Electrical Room and Emergency Generator Room	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001F	Electrical Room	no	W1	Cinderblock	White/Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001F	Electrical Room	no	Door Frame (W1)	Metal	White/Beige	4	0.01	0.02	Negative	No	0	No	No	No	No				
1	B	001F	Electrical Room	no	W2	Cinderblock	White/Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001F	Electrical Room	no	W3	Cinderblock	White/Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001F	Electrical Room	no	W4	Cinderblock	White/Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001F	Electrical Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001F	Electrical Room	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	W1	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	W1	Cinderblock	Beige	Flaking	5	0.01	Negative	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	W2	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	W2	Cinderblock	Beige	Flaking	4	0.02	Negative	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	W3	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	W3	Cinderblock	Beige	Flaking	5	0.01	Negative	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	W4	Cinderblock	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	W4	Cinderblock	Beige	Flaking	6	0.01	Negative	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	Column (W4)	Concrete	White	Flaking	3	0.01	Negative	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	Column (W4)	Concrete	Beige	Flaking	3	0.01	Negative	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	001G	Boiler Room	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001H	Former Coal Room	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001H	Former Coal Room	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001H	Former Coal Room	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001H	Former Coal Room	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001H	Former Coal Room	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	001H	Former Coal Room	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	011J	Former Ash Room	no	W1	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	011J	Former Ash Room	no	W2	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	011J	Former Ash Room	no	W3	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	011J	Former Ash Room	no	W4	Cinderblock	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	011J	Former Ash Room	no	Ceiling	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	011J	Former Ash Room	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No				
1	B	H03	Hallway outside Elevator and Building Engineer's Office	no	W1	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				
1	B	H03	Hallway outside Elevator and Building Engineer's Office	no	W2	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No				

					School District of Philadelphia													
					Lead Safe Certification Assessment Report													
			Name of Inspector: Ananth K. Vinjamuri		Anderson Elementary School										Inspection Dates: 5/4/20 through 5/8/20			
			Inspection Company: Criterion Labs, Inc.									ULCS# 1460						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	B	H03	Hallway outside Elevator and Building Engineer's Office	no	W3	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	B	H03	Hallway outside Elevator and Building Engineer's Office	no	W4	Cinderblock	Beige	None	0	N/A	N/A	No	0	No	No	No	No	
1	B	H03	Hallway outside Elevator and Building Engineer's Office	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	B	H03	Hallway outside Elevator and Building Engineer's Office	no	Floor	Tile	N/A	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	B	S02	Stairwell A	no	W1	Cinderblock	Beige	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	B	S02	Stairwell A	no	W2	Cinderblock	Beige	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	B	S02	Stairwell A	no	W3	Cinderblock	Beige	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	B	S02	Stairwell A	no	W4	Cinderblock	Beige	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	B	S02	Stairwell A	no	Ceiling	Concrete	White	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	B	S02	Stairwell A	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	B	S01	Stairwell B	no	W1	Cinderblock	White/Beige	Flaking	4	0.01	Negative	No	0	No	No	No	No	
1	B	S01	Stairwell B	no	W2	Cinderblock	White/Beige	None	15	0.02	Negative	No	0	No	No	No	No	
1	B	S01	Stairwell B	no	W3	Cinderblock	White/Beige	None	20	0.01	Negative	No	0	No	No	No	No	
1	B	S01	Stairwell B	no	W4	Cinderblock	White/Beige	None	20	0.01	Negative	No	0	No	No	No	No	
1	B	S01	Stairwell B	no	Ceiling	Concrete	White	None	0	N/A	N/A	No	0	No	No	No	No	
1	B	S01	Stairwell B	no	Floor	Concrete	No Paint	N/A	N/A	N/A	N/A	No	0	No	No	No	No	
1	B	S01	Stairwell B	no	Stair	Metal	Blue	Flaking	5	0.7	Positive	No	0	No	No	No	No	