

Lead Safe Certification for Chester Arthur School																							
Element		Name of Inspector: Ananth K. Vinjamuri										Inspection Dates: 6/10-12, 14/19											
Fl oor		Inspection Company: Criterion Labs, Inc.										ULCS# 2480											
Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture	Plastering Needed (yes or no)	Comments/ Description/ Notes	
1	BS 011	Fuel Oil Tank and Fuel Oil Pump Room in Boiler Room	no	W1	Concrete	Grey/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 011	Fuel Oil Tank and Fuel Oil Pump Room in Boiler Room	no	W2	Concrete	Grey/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 011	Fuel Oil Tank and Fuel Oil Pump Room in Boiler Room	no	W3	Concrete	Grey	Flaking, Efflorescence	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 011	Fuel Oil Tank and Fuel Oil Pump Room in Boiler Room	no	W3	Concrete	White	Flaking, Efflorescence	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 011	Fuel Oil Tank and Fuel Oil Pump Room in Boiler Room	no	W4	Concrete	Grey/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 011	Fuel Oil Tank and Fuel Oil Pump Room in Boiler Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 011	Fuel Oil Tank and Fuel Oil Pump Room in Boiler Room	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 010	Storage Room next to Fuel Oil Tank Room	no	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 010	Storage Room next to Fuel Oil Tank Room	no	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 010	Storage Room next to Fuel Oil Tank Room	no	W3	Concrete	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 010	Storage Room next to Fuel Oil Tank Room	no	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 010	Storage Room next to Fuel Oil Tank Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 010	Storage Room next to Fuel Oil Tank Room	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 009	Boiler Room	no	W1	Cinderblock	Grey	Flaking	5	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 009	Boiler Room	no	W2	Concrete	Grey	Flaking	10	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 009	Boiler Room	no	W3	Concrete	Grey	Flaking	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 009	Boiler Room	no	W4	Concrete	Grey	Flaking	15	0.16	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 009	Boiler Room	no	W4	Concrete	White	Flaking	15	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 009	Boiler Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 009	Boiler Room	no	Floor	Concrete	Grey	Cracking	20	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 009	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Tank Support Pad	Concrete	Grey	Flaking	20	0.08	Negative	N/A	0	No	No	no	
1	BS 009	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Generator Support Pad	Concrete	Green	Flaking	10	0.14	Negative	N/A	0	No	No	no	
1	BS 008	Electrical Room	no	W1	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 008	Electrical Room	no	W2	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 008	Electrical Room	no	W3	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 008	Electrical Room	no	W4	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 008	Electrical Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 008	Electrical Room	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 001B	Gymnasium	yes	W1	Cinderblock	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 001B	Gymnasium	yes	W2	Cinderblock	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 001B	Gymnasium	yes	W3	Concrete	Blue	Flaking	5	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper wall	
1	BS 001B	Gymnasium	yes	W3	Concrete	White	Flaking	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower wall	
1	BS 001B	Gymnasium	yes	W4	Cinderblock	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 001B	Gymnasium	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 001B	Gymnasium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking	3	0.07	Negative	N/A	0	No	No	no	
1	BS 001B	Gymnasium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1	BS S03	Stairwell in Gym near Girl's Restroom	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S03	Stairwell in Gym near Girl's Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Brown	Flaking	4	0.02	Negative	N/A	0	No	No	no	
1	BS S03	Stairwell in Gym near Girl's Restroom	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S03	Stairwell in Gym near Girl's Restroom	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S03	Stairwell in Gym near Girl's Restroom	yes	W4	Concrete	Yellow	Friction	3	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S03	Stairwell in Gym near Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S03	Stairwell in Gym near Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 016	Girl's Restroom in Gym	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 016	Girl's Restroom in Gym	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 016	Girl's Restroom in Gym	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 016	Girl's Restroom in Gym	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 016	Girl's Restroom in Gym	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 016	Girl's Restroom in Gym	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 015	Boy's Restroom in Gym	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 015	Boy's Restroom in Gym	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 015	Boy's Restroom in Gym	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 015	Boy's Restroom in Gym	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 015	Boy's Restroom in Gym	yes	Ceiling	Plaster	White	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 015	Boy's Restroom in Gym	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 014	Former Kitchen/Storage Room in Gym	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 014	Former Kitchen/Storage Room in Gym	yes	W2	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 014	Former Kitchen/Storage Room in Gym	yes	W3	Concrete	White	Flaking, Efflorescence	10	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 014	Former Kitchen/Storage Room in Gym	yes	W4	Concrete	White	Flaking, Efflorescence	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 014	Former Kitchen/Storage Room in Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 014	Former Kitchen/Storage Room in Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	BS S02	Stairs near Kitchen from Gym to Hallway	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S02	Stairs near Kitchen from Gym to Hallway	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S02	Stairs near Kitchen from Gym to Hallway	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S02	Stairs near Kitchen from Gym to Hallway	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S02	Stairs near Kitchen from Gym to Hallway	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS S02	Stairs near Kitchen from Gym to Hallway	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 002	Gym Storage Room in Far Corner	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 002	Gym Storage Room in Far Corner	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 002	Gym Storage Room in Far Corner	yes	W3	Cinderblock	Yellow	Friction	3	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 002	Gym Storage Room in Far Corner	yes	W3	Cinderblock	Brown	Flaking	4	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Bottom Course	
1	BS 002	Gym Storage Room in Far Corner	yes	W4	Cinderblock	Brown	Flaking	15	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 002	Gym Storage Room in Far Corner	yes	W4	Cinderblock	Brown	Flaking	6	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Bottom course	
1	BS 002	Gym Storage Room in Far Corner	yes	Ceiling	Plaster	White	Cracking	6	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 002	Gym Storage Room in Far Corner	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1	BS 003	Gym Coat Room	yes	W1	Cinderblock	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 003	Gym Coat Room	yes	W2	Cinderblock	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 003	Gym Coat Room	yes	W3	Concrete	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	BS 003	Gym Coat Room	yes	W3	Concrete																		

Lead Safe Certification for Chester Arthur School																								
Name of Inspector: Ananth K. Vinjamuri																								
Inspection Dates: 6/10-12, 14/19																								
Inspection Company: Criterion Labs, Inc.																								
ULCS# 2480																								
Element	File #	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	BS	004	Gym Storage Room near Gym Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	004	Gym Storage Room near Gym Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	004	Gym Storage Room near Gym Office	yes	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	004	Gym Storage Room near Gym Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	004	Gym Storage Room near Gym Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	004	Gym Storage Room near Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	BS	005	Restroom and Shower located in Gym Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005	Restroom and Shower located in Gym Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005	Restroom and Shower located in Gym Office	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005	Restroom and Shower located in Gym Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005	Restroom and Shower located in Gym Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005	Restroom and Shower located in Gym Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005A	Gym Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005A	Gym Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005A	Gym Office	yes	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005A	Gym Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005A	Gym Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005A	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	BS	005B	Gym Office Closet	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005B	Gym Office Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005B	Gym Office Closet	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005B	Gym Office Closet	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005B	Gym Office Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	005B	Gym Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	BS	016A	Fan Room located over Gym Girl's and Boy's Restrooms and the Former Kitchen	no	W1	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1	BS	016A	Fan Room located over Gym Girl's and Boy's Restrooms and the Former Kitchen	no	W2	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1	BS	016A	Fan Room located over Gym Girl's and Boy's Restrooms and the Former Kitchen	no	W3	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1	BS	016A	Fan Room located over Gym Girl's and Boy's Restrooms and the Former Kitchen	no	W4	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1	BS	016A	Fan Room located over Gym Girl's and Boy's Restrooms and the Former Kitchen	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1	BS	016A	Fan Room located over Gym Girl's and Boy's Restrooms and the Former Kitchen	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1	BS	006A	Stairwell near Gym Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006A	Stairwell near Gym Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006A	Stairwell near Gym Office	yes	W3	Cinderblock	Yellow	Flaking, Efflorescence	20	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006A	Stairwell near Gym Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006A	Stairwell near Gym Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006A	Stairwell near Gym Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H02	Hallway near Gym Office to Main Basement Hallway	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H02	Hallway near Gym Office to Main Basement Hallway	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H02	Hallway near Gym Office to Main Basement Hallway	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H02	Hallway near Gym Office to Main Basement Hallway	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H02	Hallway near Gym Office to Main Basement Hallway	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H02	Hallway near Gym Office to Main Basement Hallway	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006B	Custodial Closet in Hallway near Gym Office	no	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006B	Custodial Closet in Hallway near Gym Office	no	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006B	Custodial Closet in Hallway near Gym Office	no	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006B	Custodial Closet in Hallway near Gym Office	no	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006B	Custodial Closet in Hallway near Gym Office	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	006B	Custodial Closet in Hallway near Gym Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	BS	006	Storage Room at end of Main Hallway	no	W1	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	006	Storage Room at end of Main Hallway	no	W2	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	006	Storage Room at end of Main Hallway	no	W3	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	006	Storage Room at end of Main Hallway	no	W4	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	006	Storage Room at end of Main Hallway	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	006	Storage Room at end of Main Hallway	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	007	Storage Room at end of Main Hallway near Boiler Room Door	no	W1	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	007	Storage Room at end of Main Hallway near Boiler Room Door	no	W2	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	007	Storage Room at end of Main Hallway near Boiler Room Door	no	W3	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	007	Storage Room at end of Main Hallway near Boiler Room Door	no	W4	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	007	Storage Room at end of Main Hallway near Boiler Room Door	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	007	Storage Room at end of Main Hallway near Boiler Room Door	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1	BS	012	Building Engineer's Office	no	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

		Lead Safe Certification for Chester Arthur School																						
		Name of Inspector: Ananth K. Vinjamuri										Inspection Dates: 6/10-12, 14/19												
		Inspection Company: Criterion Labs, Inc.										ULCS# 2480												
Element	Fl oor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	BS	012	Building Engineer's Office	no	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	012	Building Engineer's Office	no	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	012	Building Engineer's Office	no	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	012	Building Engineer's Office	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	012	Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	BS	012A	Building Engineer's Office Restroom and Shower	no	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	012A	Building Engineer's Office Restroom and Shower	no	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	012A	Building Engineer's Office Restroom and Shower	no	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	012A	Building Engineer's Office Restroom and Shower	no	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	012A	Building Engineer's Office Restroom and Shower	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No ceiling - Open to the B.E. Office Ceiling
1	BS	012A	Building Engineer's Office Restroom and Shower	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	BS	H01	Hallway from Health Room to Storage Rooms and along Building Engineer's Office	yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H01	Hallway from Health Room to Storage Rooms and along Building Engineer's Office	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H01	Hallway from Health Room to Storage Rooms and along Building Engineer's Office	yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H01	Hallway from Health Room to Storage Rooms and along Building Engineer's Office	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H01	Hallway from Health Room to Storage Rooms and along Building Engineer's Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H01	Hallway from Health Room to Storage Rooms and along Building Engineer's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	BS	H03	Hallway from Stairs near Health Room to Elevator	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H03	Hallway from Stairs near Health Room to Elevator	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H03	Hallway from Stairs near Health Room to Elevator	yes	W3	Cinderblock	White	Flaking	4	0.28	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall
1	BS	H03	Hallway from Stairs near Health Room to Elevator	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H03	Hallway from Stairs near Health Room to Elevator	yes	Ceiling	Concrete	White	Flaking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	H03	Hallway from Stairs near Health Room to Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	BS	013	Health Room across from Building Engineer's Office	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	013	Health Room across from Building Engineer's Office	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	013	Health Room across from Building Engineer's Office	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	013	Health Room across from Building Engineer's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	3	0.07	Negative	N/A	0	No	No	no	
1	BS	013	Health Room across from Building Engineer's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Blue	Flaking	2	0.11	Negative	N/A	0	No	No	no	
1	BS	013	Health Room across from Building Engineer's Office	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	BS	013	Health Room across from Building Engineer's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
1	BS	013	Health Room across from Building Engineer's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	1	111A	Room 108 School Store Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111A	Room 108 School Store Office	yes	W2	Cinderblock	Yellow	Flaking	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111A	Room 108 School Store Office	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111A	Room 108 School Store Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111A	Room 108 School Store Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
1	1	111A	Room 108 School Store Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	1	111B	Room 107 Security Surveillance Room	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111B	Room 107 Security Surveillance Room	yes	W2	Cinderblock	Yellow	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111B	Room 107 Security Surveillance Room	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111B	Room 107 Security Surveillance Room	yes	W4	Cinderblock	Yellow	Flaking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111B	Room 107 Security Surveillance Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
1	1	111B	Room 107 Security Surveillance Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	1	111	Auditorium	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111	Auditorium	yes	W1	N/A	N/A	N/A	0	N/A	N/A	Columns	Concrete	Yellow	Cracking	3	0.04	Negative	N/A	0	No	No	no	
1	1	111	Auditorium	yes	W1	N/A	N/A	N/A	0	N/A	N/A	Columns	Concrete	Brown	Cracking	3	0.1	Negative	N/A	0	No	No	no	Bottom
1	1	111	Auditorium	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111	Auditorium	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111	Auditorium	yes	W4	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111	Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
1	1	111	Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	1	111 STAGE	Auditorium Stage	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111 STAGE	Auditorium Stage	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111 STAGE	Auditorium Stage	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	1	111 STAGE	Auditorium Stage	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

Lead Safe Certification for Chester Arthur School																							
Element		File #		Name of Inspector: Ananth K. Vinjamuri										Inspection Dates: 6/10-12, 14/19									
				Inspection Company: Criterion Labs, Inc.										ULCS# 2480									
Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes	
1	1	111 STAGE	Auditorium Stage	yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	111 STAGE	Auditorium Stage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1	1	S13	Stairwell next to Stage Area	yes	W1	Cinderblock	Green	Flaking	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S13	Stairwell next to Stage Area	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S13	Stairwell next to Stage Area	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S13	Stairwell next to Stage Area	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S13	Stairwell next to Stage Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S13	Stairwell next to Stage Area	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S16	Stairwell No. 4 near rear Auditorium and Main Entrance to School Building	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S16	Stairwell No. 4 near rear Auditorium and Main Entrance to School Building	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S16	Stairwell No. 4 near rear Auditorium and Main Entrance to School Building	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S16	Stairwell No. 4 near rear Auditorium and Main Entrance to School Building	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S16	Stairwell No. 4 near rear Auditorium and Main Entrance to School Building	yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S16	Stairwell No. 4 near rear Auditorium and Main Entrance to School Building	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	H12	Hallway between Auditorium and Main Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	H12	Hallway between Auditorium and Main Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	H12	Hallway between Auditorium and Main Office	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	H12	Hallway between Auditorium and Main Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	H12	Hallway between Auditorium and Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile	
1	1	H12	Hallway between Auditorium and Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1	1	112	Women's Restroom between Auditorium and Main Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	112	Women's Restroom between Auditorium and Main Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	112	Women's Restroom between Auditorium and Main Office	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	112	Women's Restroom between Auditorium and Main Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	112	Women's Restroom between Auditorium and Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile	
1	1	112	Women's Restroom between Auditorium and Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	112A	Men's Restroom between Auditorium and Main Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	112A	Men's Restroom between Auditorium and Main Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	112A	Men's Restroom between Auditorium and Main Office	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	112A	Men's Restroom between Auditorium and Main Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	112A	Men's Restroom between Auditorium and Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile	
1	1	112A	Men's Restroom between Auditorium and Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	S12	Stairwell No. 3 by Rear Door of School Building	yes	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S12	Stairwell No. 3 by Rear Door of School Building	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Green	Flaking	1	0.04	Negative	N/A	0	No	no	
1	1	S12	Stairwell No. 3 by Rear Door of School Building	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S12	Stairwell No. 3 by Rear Door of School Building	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Concrete	Green	Flaking	2	0.02	Negative	N/A	0	No	no	
1	1	S12	Stairwell No. 3 by Rear Door of School Building	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S12	Stairwell No. 3 by Rear Door of School Building	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S12	Stairwell No. 3 by Rear Door of School Building	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	S12	Stairwell No. 3 by Rear Door of School Building	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	100	Classroom 100	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	100	Classroom 100	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	4	0.13	Negative	N/A	0	No	no	
1	1	100	Classroom 100	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Locker Door	Metal	Brown	Scratched	4	0.13	Negative	N/A	0	No	no	
1	1	100	Classroom 100	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	100	Classroom 100	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.01	Negative	N/A	0	No	no	
1	1	100	Classroom 100	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	100	Classroom 100	yes	W4	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	100	Classroom 100	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Beam	Concrete	White	Cracking	3	0.02	Negative	N/A	0	No	no	
1	1	100	Classroom 100	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	100	Classroom 100	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	102	Classroom 102	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	102	Classroom 102	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Brown	Scratched	2	0	Negative	N/A	0	No	no	
1	1	102	Classroom 102	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	2	0.01	Negative	N/A	0	No	no	
1	1	102	Classroom 102	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	102	Classroom 102	yes	W3	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	102	Classroom 102	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	102	Classroom 102	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.01	Negative	N/A	0	No	no	

Lead Safe Certification for Chester Arthur School																							
Element		Name of Inspector: Ananth K. Vinjamuri										Inspection Dates: 6/10-12, 14/19											
Floor		Inspection Company: Criterion Labs, Inc.										ULCS# 2480											
Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes	
1	1	105	IMC/Library	yes	W2	Cinderblock	Yellow	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	105	IMC/Library	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Flaking	1	0.03	Negative	N/A	0	No	No	no		
1	1	105	IMC/Library	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	105	IMC/Library	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	105	IMC/Library	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	105	IMC/Library	yes	Ceiling	Concrete	White	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Pipe penetration by W2 windows	
1	1	105	IMC/Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	109E	Main Office Secured Storage Room	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109E	Main Office Secured Storage Room	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109E	Main Office Secured Storage Room	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109E	Main Office Secured Storage Room	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109E	Main Office Secured Storage Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109E	Main Office Secured Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1	1	109I	Main Office Closet	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109I	Main Office Closet	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109I	Main Office Closet	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109I	Main Office Closet	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109I	Main Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109I	Main Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1	1	109A	Lead Teacher's Office in Main Office Area	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109A	Lead Teacher's Office in Main Office Area	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109A	Lead Teacher's Office in Main Office Area	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109A	Lead Teacher's Office in Main Office Area	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109A	Lead Teacher's Office in Main Office Area	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile	
1	1	109A	Lead Teacher's Office in Main Office Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	109AA	Lead Teacher's Office Closet	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109AA	Lead Teacher's Office Closet	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109AA	Lead Teacher's Office Closet	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109AA	Lead Teacher's Office Closet	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109AA	Lead Teacher's Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109AA	Lead Teacher's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1	1	109B	Principal's Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109B	Principal's Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109B	Principal's Office	yes	W3	Cinderblock	Yellow	Friction	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109B	Principal's Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109B	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile	
1	1	109B	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Carpet	
1	1	109F	Principal's Office Restroom	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109F	Principal's Office Restroom	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109F	Principal's Office Restroom	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109F	Principal's Office Restroom	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109F	Principal's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile	
1	1	109F	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	109J	Principal's Office Closet	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109J	Principal's Office Closet	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109J	Principal's Office Closet	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109J	Principal's Office Closet	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109J	Principal's Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile	
1	1	109J	Principal's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	109	Main Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109	Main Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109	Main Office	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109	Main Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Cracking	1	0.02	Negative	N/A	0	No	no	
1	1	109	Main Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile	
1	1	109	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	109D	Community Partnership Coordinator's Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109D	Community Partnership Coordinator's Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109D	Community Partnership Coordinator's Office	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109D	Community Partnership Coordinator's Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109D	Community Partnership Coordinator's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile	
1	1	109D	Community Partnership Coordinator's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	109G	Nurse's Office Exam Room	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109G	Nurse's Office Exam Room	yes	W2	Cinderblock	Blue	Friction	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109G	Nurse's Office Exam Room	yes	W3	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109G	Nurse's Office Exam Room	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	109G	Nurse's Office Exam Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile	
1	1	109G	Nurse's Office Exam Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	110A	Nurse's Office Restroom	yes	W1	Cinderblock	Blue	Friction	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	110A	Nurse's Office Restroom	yes	W2	Cinderblock	Blue	Friction	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	110A	Nurse's Office Restroom	yes	W3	Cinderblock	Blue	Friction	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	110A	Nurse's Office Restroom	yes	W4	Cinderblock	Blue	Friction	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	110A	Nurse's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile	
1	1	110A	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1	1	110	Nurse's Office	yes	W1	Cinderblock	Blue	Friction	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	110	Nurse's Office	yes	W2	Cinderblock	Blue	Friction	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	110	Nurse's Office	yes	W3	Cinderblock	Blue	Friction	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	110	Nurse's Office	yes	W4	Cinderblock	Blue	Friction	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1	1	110	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile	
1	1	110	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	

		Lead Safe Certification for Chester Arthur School																						
		Name of Inspector: Ananth K. Vinjamuri				Inspection Dates: 6/10-12, 14/19																		
		Inspection Company: Criterion Labs, Inc.				ULCS# 2480																		
Element	Fl oor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	210A	Women's Restroom across from Classroom 202	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	210A	Women's Restroom across from Classroom 202	yes	Ceiling	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	210A	Women's Restroom across from Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1	2	202	Classroom 202	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	202	Classroom 202	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	7	0.02	Negative	N/A	0	No	No	no	
1	2	202	Classroom 202	yes	W2	Sheetrock	Yellow	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	202	Classroom 202	yes	W2	Concrete	Yellow	Cracking	3	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Beam
1	2	202	Classroom 202	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	202	Classroom 202	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	202	Classroom 202	yes	Ceiling	Concrete	White	Cracking	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	202	Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	2	H28	Hallway to Classroom 207	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	H28	Hallway to Classroom 207	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	H28	Hallway to Classroom 207	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	H28	Hallway to Classroom 207	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	H28	Hallway to Classroom 207	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	H28	Hallway to Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	2	207	Classroom 207	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207	Classroom 207	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207	Classroom 207	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207	Classroom 207	yes	W4	Cinderblock	Yellow	Flaking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207	Classroom 207	yes	W4	Cinderblock	Yellow	Flaking	15	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207	Classroom 207	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.03	Negative	N/A	0	No	No	no	
1	2	207	Classroom 207	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Jacket	Metal	Yellow	Flaking	5	0.03	Negative	N/A	0	No	No	no	
1	2	207	Classroom 207	yes	Ceiling	Concrete	Yellow	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207	Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	2	207A	Girl's Restroom across from Classroom 204	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207A	Girl's Restroom across from Classroom 204	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207A	Girl's Restroom across from Classroom 204	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207A	Girl's Restroom across from Classroom 204	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207A	Girl's Restroom across from Classroom 204	yes	Ceiling	Concrete	White	Cracking	3	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	207A	Girl's Restroom across from Classroom 204	yes	Floor	Concrete	Grey	Scratched	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209A	Boy's Restroom across from Classroom 206	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209A	Boy's Restroom across from Classroom 206	yes	W2	Cinderblock	Yellow	Flaking	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	At the urinals
1	2	209A	Boy's Restroom across from Classroom 206	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209A	Boy's Restroom across from Classroom 206	yes	W4	Cinderblock	Yellow	Flaking	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	At the toilets
1	2	209A	Boy's Restroom across from Classroom 206	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209A	Boy's Restroom across from Classroom 206	yes	Floor	Concrete	Grey	Scratched	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209B	Book Closet across from Classroom 206	yes	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209B	Book Closet across from Classroom 206	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Limited Assessment - Cabinets in the way
1	2	209B	Book Closet across from Classroom 206	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209B	Book Closet across from Classroom 206	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209B	Book Closet across from Classroom 206	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	209B	Book Closet across from Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	2	204	Classroom 204	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	204	Classroom 204	yes	W2	Cinderblock	Yellow	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	204	Classroom 204	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Cracking	1	0.03	Negative	N/A	0	No	No	no	
1	2	204	Classroom 204	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	204	Classroom 204	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	204	Classroom 204	yes	Ceiling	Concrete	White	Flaking/Cracking	5	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Flaking in coat area (3 SF)
1	2	204	Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	2	206	Classroom 206	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	206	Classroom 206	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	206	Classroom 206	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	206	Classroom 206	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	206	Classroom 206	yes	Ceiling	Concrete	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	206	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	2	S24	Stairwell No. 1 near Classroom 206	yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	S24	Stairwell No. 1 near Classroom 206	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	S24	Stairwell No. 1 near Classroom 206	yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	S24	Stairwell No. 1 near Classroom 206	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	2	S24	Stairwell No. 1 near Classroom 206	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1																								

Lead Safe Certification for Chester Arthur School																							
Element		Name of Inspector: Ananth K. Vinjamuri										Inspection Dates: 6/10-12, 14/19											
Floor		Inspection Company: Criterion Labs, Inc.										ULCS# 2480											
Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes	
1 2	H27	Hallway to Classroom 209	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H27	Hallway to Classroom 209	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H27	Hallway to Classroom 209	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H27	Hallway to Classroom 209	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H27	Hallway to Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1 2	209	Classroom 209	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	209	Classroom 209	yes	W1	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	1	0.03	Negative	N/A	0	No	No	no		
1 2	209	Classroom 209	yes	W2	Cinderblock	Yellow	Flaking	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Near the top of the radiator	
1 2	209	Classroom 209	yes	W2	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Cracking	2	1.1	Positive	N/A	0	No	No	no		
1 2	209	Classroom 209	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	209	Classroom 209	yes	W4	Cinderblock	Yellow	Cracking	7	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Below blackboard	
1 2	209	Classroom 209	yes	Ceiling	Concrete	White	Flaking, Cracking	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Mostly in the Coat Area	
1 2	209	Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1 2	H26	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H26	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H26	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H26	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H26	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	H26	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1 2	203A	Custodial Closet near Classroom 203	no	W1	Cinderblock	Brown/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	203A	Custodial Closet near Classroom 203	no	W2	Cinderblock	Brown	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower Wall	
1 2	203A	Custodial Closet near Classroom 203	no	W2	Cinderblock	Yellow	Flaking	2	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall	
1 2	203A	Custodial Closet near Classroom 203	no	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall	
1 2	203A	Custodial Closet near Classroom 203	no	W3	Cinderblock	Brown	None	4	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower Wall	
1 2	203A	Custodial Closet near Classroom 203	no	W3	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	3	1.3	Positive	N/A	0	No	No	no	Upper	
1 2	203A	Custodial Closet near Classroom 203	no	W3	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Brown	Flaking	1	0.02	Negative	N/A	0	No	No	no	Lower	
1 2	203A	Custodial Closet near Classroom 203	no	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall	
1 2	203A	Custodial Closet near Classroom 203	no	W4	Cinderblock	Brown	Flaking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower Wall	
1 2	203A	Custodial Closet near Classroom 203	no	Ceiling	Concrete	Yellow	Flaking	12	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	203A	Custodial Closet near Classroom 203	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	203B	Storage Room next to Classroom 203	no	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	203B	Storage Room next to Classroom 203	no	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	203B	Storage Room next to Classroom 203	no	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	203B	Storage Room next to Classroom 203	no	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	203B	Storage Room next to Classroom 203	no	W4	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Green	Flaking	4	0.26	Negative	N/A	0	No	No	no		
1 2	203B	Storage Room next to Classroom 203	no	Ceiling	Concrete	Yellow	Flaking	30	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	203B	Storage Room next to Classroom 203	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1 2	210	Room 207-A	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	210	Room 207-A	yes	W1	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	0.2	Negative	N/A	0	No	No	no	Both doors	
1 2	210	Room 207-A	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	210	Room 207-A	yes	W3	Cinderblock	Yellow	Flaking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	210	Room 207-A	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 2	210	Room 207-A	yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Concrete only at windows. Rest of the ceiling is 1' x 1' ceiling tile	
1 2	210	Room 207-A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1 3	Elevator	Elevator	yes	W1	Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	Elevator	Elevator	yes	W2	Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	Elevator	Elevator	yes	W3	Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	Elevator	Elevator	yes	W4	Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	Elevator	Elevator	yes	Ceiling	Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	Elevator	Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile	
1 3	309	Classroom 309	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	309	Classroom 309	yes	W1	N/A	N/A	N/A	N/A	N/A	Door	Wood	Brown	Scratched	3	0	Negative	N/A	0	No	No	no		
1 3	309	Classroom 309	yes	W1	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	5	0.11	Negative	N/A	0	No	No	no		
1 3	309	Classroom 309	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	309	Classroom 309	yes	W2	N/A	N/A	N/A	N/A	N/A	Beam	Concrete	White	Cracking	2	1.1	Positive	N/A	0	No	No	no	Horizontal Beam above windows	
1 3	309	Classroom 309	yes	W2	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Scratched	3	0.07	Negative	N/A	0	No	No	no		
1 3	309	Classroom 309	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Far right corner	
1 3	309	Classroom 309	yes	W4	Cinderblock	Yellow	Cracking	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	309	Classroom 309	yes	Concrete	Concrete	White	Cracking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Beam above blackboard	
1 3	309	Classroom 309	yes	Ceiling	Concrete	White	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	309	Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1 3	S35	Stairwell No. 2 near Classroom 309	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Along beam and by window	
1 3	S35	Stairwell No. 2 near Classroom 309	yes	W2	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	S35	Stairwell No. 2 near Classroom 309	yes	W3	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	S35	Stairwell No. 2 near Classroom 309	yes	W4	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	S35	Stairwell No. 2 near Classroom 309	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	S35	Stairwell No. 2 near Classroom 309	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	306A	Book Closet near Classroom 309	yes	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	306A	Book Closet near Classroom 309	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	306A	Book Closet near Classroom 309	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	306A	Book Closet near Classroom 309	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	306A	Book Closet near Classroom 309	yes	Ceiling	Concrete	White	Flaking	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Spread Out	
1 3	306A	Book Closet near Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile	
1 3	S34	Stairwell No. 1 near Classroom 306	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	S34	Stairwell No. 1 near Classroom 306	yes	W2	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	S34	Stairwell No. 1 near Classroom 306	yes	W3	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no		
1 3	S34	Stairwell No. 1 near Classroom 306	yes	W3	N/A	N/A																	

Lead Safe Certification for Chester Arthur School																								
Element		Filior		Name of Inspector: Ananth K. Vinjamuri										Inspection Dates: 6/10-12, 14/19										
				Inspection Company: Criterion Labs, Inc.										ULCS# 2480										
Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes		
1	3	S34	Stairwell No. 1 near Classroom 306	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	S34	Stairwell No. 1 near Classroom 306	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H311	Hallway to Classroom 309	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H311	Hallway to Classroom 309	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H311	Hallway to Classroom 309	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Wall		
1	3	H311	Hallway to Classroom 309	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H311	Hallway to Classroom 309	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H311	Hallway to Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile		
1	3	307A	Book Closet across from Classroom 306	yes	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307A	Book Closet across from Classroom 306	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	5	0.06	Negative	N/A	0	No	no	Limited access - Misc materials in the way	
1	3	307A	Book Closet across from Classroom 306	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Limited access - Cabinets against the wall		
1	3	307A	Book Closet across from Classroom 306	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307A	Book Closet across from Classroom 306	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307A	Book Closet across from Classroom 306	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307A	Book Closet across from Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile		
1	3	307C	Boy's Restroom across from Classroom 306	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307C	Boy's Restroom across from Classroom 306	yes	W1	N/A	N/A	N/A	0	N/A	N/A	Door Frame	Metal	Grey	Scratched	5	0.07	Negative	N/A	0	No	no		
1	3	307C	Boy's Restroom across from Classroom 306	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307C	Boy's Restroom across from Classroom 306	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307C	Boy's Restroom across from Classroom 306	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307C	Boy's Restroom across from Classroom 306	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307C	Boy's Restroom across from Classroom 306	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307B	Girl's Restroom across from Classroom 304	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307B	Girl's Restroom across from Classroom 304	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Brown	Scratched	2	0	Negative	N/A	0	No	no		
1	3	307B	Girl's Restroom across from Classroom 304	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	5	0.05	Negative	N/A	0	No	no		
1	3	307B	Girl's Restroom across from Classroom 304	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307B	Girl's Restroom across from Classroom 304	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307B	Girl's Restroom across from Classroom 304	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307B	Girl's Restroom across from Classroom 304	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307B	Girl's Restroom across from Classroom 304	yes	Floor	Concrete	Grey	Cracking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	306	Classroom 306	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	306	Classroom 306	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Yellow	Flaking	2	0.21	Negative	N/A	0	No	no		
1	3	306	Classroom 306	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	6	0.02	Negative	N/A	0	No	no		
1	3	306	Classroom 306	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	306	Classroom 306	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Crack along the perimeter seam and by right corner		
1	3	306	Classroom 306	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	306	Classroom 306	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Cracking	2	0.01	Negative	N/A	0	No	no		
1	3	306	Classroom 306	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	306	Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile		
1	3	304	Classroom 304	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	304	Classroom 304	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	5	0.03	Negative	N/A	0	No	no		
1	3	304	Classroom 304	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	304	Classroom 304	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	304	Classroom 304	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	304	Classroom 304	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	304	Classroom 304	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile		
1	3	307	Classroom 307	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307	Classroom 307	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	10	0.12	Negative	N/A	0	No	no		
1	3	307	Classroom 307	yes	W2	Cinderblock	Yellow	Cracking	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307	Classroom 307	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307	Classroom 307	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307	Classroom 307	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.05	Negative	on top of radiator vent at middle column	1	No	no		
1	3	307	Classroom 307	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	307	Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile		
1	3	H312	Hallway to Classroom 307	yes	W1	Cinderblock	Yellow/Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H312	Hallway to Classroom 307	yes	W2	Cinderblock	Yellow/Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H312	Hallway to Classroom 307	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Wall		
1	3	H312	Hallway to Classroom 307	yes	W4	Cinderblock	Yellow/Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H312	Hallway to Classroom 307	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	H312	Hallway to Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile		
1	3	308	Classroom 307-A	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	308	Classroom 307-A	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	3	0.05	Negative	N/A	0	No	no	Left Door	
1	3	308	Classroom 307-A	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	3	0.15	Negative	N/A	0	No	no	Right Door	
1	3	308	Classroom 307-A	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	308	Classroom 307-A	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	308	Classroom 307-A	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	308	Classroom 307-A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x 1' Spline Ceiling Tiles		
1	3	308	Classroom 307-A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile		
1	3	302	Classrooms 300 and 302	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no			
1	3	302	Classrooms 300 and 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	4	0.02	Negative	N/A	0	No	no	Right side door	

Lead Safe Certification for Chester Arthur School																								
		Name of Inspector: Ananth K. Vinjamuri										Inspection Dates: 6/10-12, 14/19												
		Inspection Company: Criterion Labs, Inc.										ULCS# 2480												
Element	Fl oor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	3	302	Classrooms 300 and 302	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302	Classrooms 300 and 302	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Beam	Concrete	White	Flaking	1	0.03	Negative	N/A	0	No	No	no	
1	3	302	Classrooms 300 and 302	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302	Classrooms 300 and 302	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302	Classrooms 300 and 302	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.02	Negative	N/A	0	No	No	no	
1	3	302	Classrooms 300 and 302	yes	Ceiling	Concrete	White	Flaking, Cracking	40	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Spread out. Including middle beam
1	3	302	Classrooms 300 and 302	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1	3	302B	Classrooms 300 and 302 Restricted Storage Room	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302B	Classrooms 300 and 302 Restricted Storage Room	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302B	Classrooms 300 and 302 Restricted Storage Room	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302B	Classrooms 300 and 302 Restricted Storage Room	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302B	Classrooms 300 and 302 Restricted Storage Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302B	Classrooms 300 and 302 Restricted Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1	3	302A	Classrooms 300 and 302 Storage Room	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302A	Classrooms 300 and 302 Storage Room	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302A	Classrooms 300 and 302 Storage Room	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302A	Classrooms 300 and 302 Storage Room	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	302A	Classrooms 300 and 302 Storage Room	yes	Ceiling	Concrete	White	Flaking, Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Spread out. Includes beam
1	3	302A	Classrooms 300 and 302 Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1	3	S32	Stairwell No. 3 near Classroom 301	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	S32	Stairwell No. 3 near Classroom 301	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	S32	Stairwell No. 3 near Classroom 301	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	S32	Stairwell No. 3 near Classroom 301	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	S32	Stairwell No. 3 near Classroom 301	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	S32	Stairwell No. 3 near Classroom 301	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	301	Classroom 301	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	301	Classroom 301	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scatched	3	0.07	Negative	N/A	0	No	No	no	
1	3	301	Classroom 301	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	301	Classroom 301	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Crack in wall by coat area
1	3	301	Classroom 301	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	301	Classroom 301	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	301	Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	3	305A	Women's Restroom across from Classroom 302	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305A	Women's Restroom across from Classroom 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Flaking/Scatched	3	0.02	Negative	N/A	0	No	No	no	
1	3	305A	Women's Restroom across from Classroom 302	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305A	Women's Restroom across from Classroom 302	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305A	Women's Restroom across from Classroom 302	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305A	Women's Restroom across from Classroom 302	yes	Ceiling	Concrete	Beige	Flaking, Cracking	3	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	3 SF is cracking/flaking. Another 10 SF appears to have been scraped but needs to be re-painted
1	3	305A	Women's Restroom across from Classroom 302	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1	3	305B	Men's Restroom across from Classroom 302	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305B	Men's Restroom across from Classroom 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Flaking/Scatched	3	0.05	Negative	N/A	0	No	No	no	
1	3	305B	Men's Restroom across from Classroom 302	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305B	Men's Restroom across from Classroom 302	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305B	Men's Restroom across from Classroom 302	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305B	Men's Restroom across from Classroom 302	yes	Ceiling	Concrete	Beige	Flaking, Cracking	2	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305B	Men's Restroom across from Classroom 302	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1	3	305	Classroom 305	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305	Classroom 305	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scatched	3	0.01	Negative	N/A	0	No	No	no	
1	3	305	Classroom 305	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	305	Classroom 305	yes	W2	Cinderblock	Yellow	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking and Efflorescence	2	0.07	Negative	Window Sill, radiator	1	No	Unknown	no	Column side facing the window
1	3	305	Classroom 305	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	no	
1	3	305	Classroom 305	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	no	
1	3	305	Classroom 305	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	no	
1	3	305	Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	1	No	Unknown	no	by window
1	3	303	Classroom 303	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303	Classroom 303	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scatched	3	0.07	Negative	N/A	0	No	No	no	
1	3	303	Classroom 303	yes	W2	Cinderblock	Yellow	Cracking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	on the Beam
1	3	303	Classroom 303	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303	Classroom 303	yes	W4	Cinderblock	Yellow	Cracking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303	Classroom 303	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Efflorescence	2	0.03	Negative	N/A	0	No	No	no	
1	3	303	Classroom 303	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303	Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	3	H313	Hallway to Classrooms 303 and 305	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H313	Hallway to Classrooms 303 and 305	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H313	Hallway to Classrooms 303 and 305	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H313	Hallway to Classrooms 303 and 305	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H313	Hallway to Classrooms 303 and 305	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

Lead Safe Certification for Chester Arthur School																								
Name of Inspector: Ananth K. Vinjamuri																								
Inspection Company: Criterion Labs, Inc.																								
Inspection Dates: 6/10-12, 14/19																								
ULCS# 2480																								
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	3	H313	Hallway to Classrooms 303 and 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	3	303B	Custodial Staff Office and Storage next to Classroom 303	no	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303B	Custodial Staff Office and Storage next to Classroom 303	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	10	0.08	Negative	N/A	0	No	No	no	
1	3	303B	Custodial Staff Office and Storage next to Classroom 303	no	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303B	Custodial Staff Office and Storage next to Classroom 303	no	W3	Cinderblock	Yellow	Cracking	4	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303B	Custodial Staff Office and Storage next to Classroom 303	no	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303B	Custodial Staff Office and Storage next to Classroom 303	no	Ceiling	Concrete	Yellow	Flaking	200	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Severe Flaking Paint
1	3	303B	Custodial Staff Office and Storage next to Classroom 303	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	3	303A	Custodial Closet near Classroom 303	no	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303A	Custodial Closet near Classroom 303	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	7	0.07	Negative	N/A	0	No	No	no	
1	3	303A	Custodial Closet near Classroom 303	no	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303A	Custodial Closet near Classroom 303	no	W3	Cinderblock	Brown	Cracking	10	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower Wall
1	3	303A	Custodial Closet near Classroom 303	no	W4	Cinderblock	Yellow	Efflorescence	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall
1	3	303A	Custodial Closet near Classroom 303	no	Ceiling	Concrete	Yellow	Cracking	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	303A	Custodial Closet near Classroom 303	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H310	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H310	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H310	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H310	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H310	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1	3	H310	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile