

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Bart McMahon 060103	Patterson Elementary School							
		Inspection Company: Synertech	7000 Buist Ave, Philadelphia, PA 19142							
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Main Office	W1	Plaster	Tan	Flaking	3	7.9	Positive	
1	1	Main Office	W2	Plaster	Tan	Flaking	4	10.9	Positive	
1	1	Main Office	W3	Plaster	Blue	Flaking	12	8.1	Positive	
1	1	Main Office	Radiator	Metal	White	None	0	1	Positive	
1	1	Main Office	W4	Plaster	Tan	Flaking	5	9.6	Positive	
1	1	Main Office	Baseboard	Wood	Brown	None	0	0.1	Negative	
1	1	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Main Office	Ceiling	Plaster	White	Flaking	400	9.4	Positive	
1	1	Principal's Office	W1	Plaster	Tan	None	0	9.7	Positive	
1	1	Principal's Office	W2	Sheetrock	Tan	None	0	0.1	Negative	
1	1	Principal's Office	W3	Plaster	Tan	Cracking	3	10.1	Positive	
1	1	Principal's Office	Radiator	Metal	White	None	0	0.4	Negative	
1	1	Principal's Office	W4	Plaster	Tan	Flaking	3	7.9	Positive	
1	1	Principal's Office	Radiator	Metal	White	None	0	0.5	Negative	
1	1	Principal's Office	Baseboard	Wood	Brown	None	0	0.1	Negative	
1	1	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Principal's Office	Ceiling	Plaster	White	Flaking	175	11.1	Positive	
1	1	Principal's Office Restroom	W1	Sheetrock	White	None	0	0	Negative	
1	1	Principal's Office Restroom	Door Frame	Metal	Brown	None	0	0.1	Negative	
1	1	Principal's Office Restroom	W2	Sheetrock	White	None	0	0	Negative	
1	1	Principal's Office Restroom	W3	Sheetrock	White	None	0	0	Negative	
1	1	Principal's Office Restroom	W4	Sheetrock	White	None	0	0	Negative	
1	1	Principal's Office Restroom	Radiator Cover	Metal	White	None	0	0	Negative	
1	1	Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Principal's Office Restroom	Ceiling	Plaster	White	Flaking	4	2.8	Positive	
1	1	Principal's Conference Room	W1	Plaster	White	None	0	6.8	Positive	
1	1	Principal's Conference Room	W2	Plaster	White	None	0	8.9	Positive	
1	1	Principal's Conference Room	W3	Sheetrock	Tan	None	0	0.2	Negative	
1	1	Principal's Conference Room	Door Frame	Metal	Brown	Chipping	2	0	Negative	
1	1	Principal's Conference Room	W4	Plaster	White	None	0	9.5	Positive	
1	1	Principal's Conference Room	Baseboard	Wood	Brown	None	0	0	Negative	
1	1	Principal's Conference Room	Floor	Wood	N/A	N/A	N/A	N/A	N/A	

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Principal's Conference Room	Ceiling	Plaster	White	None	0	9.8	Positive
1	1	Classroom 101	W1	Plaster	Tan	Flaking	1	8.8	Positive
1	1	Classroom 101	W1	Plaster	Yellow	None	0	7.8	Positive
1	1	Classroom 101	W2	Plaster	Tan	Flaking	10	8.6	Positive
1	1	Classroom 101	W3	Plaster	Tan	Flaking	4	6.7	Positive
1	1	Classroom 101	W4	Plaster	Tan	Flaking	1	7.7	Positive
1	1	Classroom 101	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	Ceiling	Plaster	White	Flaking	520	9.8	Positive
1	1	Classroom 101 Storage	W1	Plaster	Tan	None	0	8.1	Positive
1	1	Classroom 101 Storage	W2	Plaster	Tan	None	0	7.9	Positive
1	1	Classroom 101 Storage	W3	Sheetrock	Tan	None	0	0	Negative
1	1	Classroom 101 Storage	W4	Plaster	Tan	None	0	6.9	Positive
1	1	Classroom 101 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Storage	Ceiling	Plaster	Tan	Flaking	1	7.9	Positive
1	1	Classroom 101 Restroom	W1	Sheetrock	Tan	None	0	0	Negative
1	1	Classroom 101 Restroom	W2	Plaster	Tan	None	0	7.6	Positive
1	1	Classroom 101 Restroom	W3	Plaster	Tan	Cracking	1	7.7	Positive
1	1	Classroom 101 Restroom	W4	Plaster	Tan	Chipping	2	7.4	Positive
1	1	Classroom 101 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	Ceiling	Plaster	Tan	None	0	8.9	Positive
1	1	Back Foyer	Ceiling	Plaster	Tan	None	0	8.6	Positive
1	1	Back Foyer	W1	Plaster	Tan	Flaking	1	1	Positive
1	1	Back Foyer	Door	Metal	Brown	Chipping	2	0	Negative
1	1	Back Foyer	Door Frame	Metal	Brown	Chipping	2	0	Negative
1	1	Back Foyer	W2	Plaster	Tan	None	0	7.8	Positive
1	1	Back Foyer	W3	Plaster	Tan	None	0	6.3	Positive
1	1	Back Foyer	Conduit	Metal	White	None	0	0.4	Negative
1	1	Back Foyer	W4	Plaster	Tan	None	0	5.1	Positive
1	1	Back Foyer	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Staff Restroom outside Classroom 101	W1	Plaster	Tan	None	0	3.9	Positive
1	1	Staff Restroom outside Classroom 101	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	1	Staff Restroom outside Classroom 101	W2	Plaster	Tan	None	0	4.3	Positive
1	1	Staff Restroom outside Classroom 101	W3	Plaster	Tan	Chipping	2	4.4	Positive
1	1	Staff Restroom outside Classroom 101	Toilet Partition	Metal	Brown	None	0	0.09	negative
1	1	Staff Restroom outside Classroom 101	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Staff Restroom outside Classroom 101	W4	Plaster	Tan	None	0	3.7	Positive
1	1	Staff Restroom outside Classroom 101	Floor	Concrete	Brown	Chipping	2	6.1	Positive
1	1	Staff Restroom outside Classroom 101	Ceiling	Plaster	White	Cracking	2	4.6	Positive
1	1	Classroom 102	W1	Plaster	Tan	Flaking	1	8.3	Positive
1	1	Classroom 102	W1	Plaster	Yellow	Flaking	2	5.7	Positive
1	1	Classroom 102	W2	Plaster	Tan	None	0	8.8	Positive
1	1	Classroom 102	W3	Plaster	Tan	Flaking	8	9.1	Positive
1	1	Classroom 102	Radiator Cover	Metal	White	None	0	0	Positive
1	1	Classroom 102	W4	Plaster	Tan	Flaking	2	9.1	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Classroom 102	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	Ceiling	Plaster	White	Flaking	450	10.5	Positive
1	1	Classroom 102 Restroom	W1	Plaster	Tan	None	0	6.7	Positive
1	1	Classroom 102 Restroom	W2	Plaster	Tan	None	0	4.1	Positive
1	1	Classroom 102 Restroom	W3	Sheetrock	Tan	None	0	5.2	Positive
1	1	Classroom 102 Restroom	W4	Plaster	Tan	Flaking	1	8.4	Positive
1	1	Classroom 102 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102 Restroom	Ceiling	Plaster	Tan	None	0	7.7	Positive
1	1	Classroom 102 Storage	W1	Sheetrock	Tan	None	0	0	Negative
1	1	Classroom 102 Storage	W2	Plaster	Tan	None	0	0.8	Positive
1	1	Classroom 102 Storage	W3	Plaster	Tan	None	0	7.5	Positive
1	1	Classroom 102 Storage	W4	Plaster	Tan	None	0	1	Positive
1	1	Classroom 102 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102 Storage	Ceiling	Plaster	Tan	None	0	6.7	Positive
1	1	Classroom 103	W1	Plaster	White	Cracking	2	9.4	Positive
1	1	Classroom 103	W1	Plaster	Yellow	Flaking	2	7.8	Positive
1	1	Classroom 103	W2	Plaster	White	Flaking	1	9	Positive
1	1	Classroom 103	W3	Plaster	White	Flaking	40	5.7	Positive
1	1	Classroom 103	Radiator Cover	Metal	White	Flaking	1	0.3	Negative
1	1	Classroom 103	W4	Plaster	Tan	Flaking	22	6.3	Positive
1	1	Classroom 103	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	Ceiling	Plaster	White	Flaking	480	7.2	Positive
1	1	Classroom 103 Storage	W1	Plaster	Tan	None	0	0.1	Negative
1	1	Classroom 103 Storage	W2	Plaster	Tan	None	0	8.1	Positive
1	1	Classroom 103 Storage	W3	Plaster	Tan	None	0	8.6	Positive
1	1	Classroom 103 Storage	W4	Plaster	Tan	None	0	8.9	Positive
1	1	Classroom 103 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Storage	Ceiling	Plaster	Tan	None	0	6.6	Positive
1	1	Classroom 103 Restroom	W1	Plaster	Tan	Flaking	2	5.9	Positive
1	1	Classroom 103 Restroom	W2	Plaster	Tan	None	0	4.9	Positive
1	1	Classroom 103 Restroom	Radiator (W2)	Metal	White	None	0	0.1	Negative
1	1	Classroom 103 Restroom	W3	Sheetrock	Tan	None	0	0.1	Negative
1	1	Classroom 103 Restroom	W4	Plaster	Tan	Flaking	1	4.6	Positive
1	1	Classroom 103 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Restroom	Ceiling	Plaster	Tan	None	0	7.1	Positive
1	1	Hallway at Main Office	Ceiling	Plaster	White	Flaking	350	8.7	Positive
1	1	Hallway at Main Office	W1	Plaster	Tan	Flaking	20	7	Positive
1	1	Hallway at Main Office	W2	Plaster	Tan	Flaking	12	8.4	Positive
1	1	Hallway at Main Office	Baseboard	Concrete	Brown	None	0	2.3	Positive
1	1	Classroom 104	W1	Plaster	Tan	None	0	3.3	Positive
1	1	Classroom 104	W1	Plaster	Yellow	None	0	4	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Classroom 104	W2	Sheetrock	Tan	None	0	0	Negative
1	1	Classroom 104	W3	Plaster	Tan	Flaking	8	8.2	Positive
1	1	Classroom 104	Radiator (W3)	Metal	White	None	0	0	Negative
1	1	Classroom 104	W4	Plaster	Tan	Flaking	2	6.9	Positive
1	1	Classroom 104	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 104	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	Ceiling	Plaster	White	Flaking	400	9.7	Positive
1	1	Classroom 104 Storage	W1	Plaster	Tan	None	0	9.3	Positive
1	1	Classroom 104 Storage	W2	Plaster	Tan	None	0	9.4	Positive
1	1	Classroom 104 Storage	W3	Plaster	Tan	None	0	9.2	Positive
1	1	Classroom 104 Storage	W4	Plaster	Tan	None	0	8.2	Positive
1	1	Classroom 104 Storage	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 104 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104 Storage	Ceiling	Plaster	Tan	None	0	9.1	Positive
1	1	Girl's Restroom next to Classroom 104	W1	Plaster	White	None	0	6.1	Positive
1	1	Girl's Restroom next to Classroom 104	Radiator	Metal	Brown	None	0	0	Negative
1	1	Girl's Restroom next to Classroom 104	W2	Plaster	White	Flaking	2	5.6	Positive
1	1	Girl's Restroom next to Classroom 104	W3	Plaster	White	Cracking	1	5.5	Positive
1	1	Girl's Restroom next to Classroom 104	Radiator (W3)	Metal	Black	None	0	0.3	Negative
1	1	Girl's Restroom next to Classroom 104	W4	Sheetrock	White	None	0	0	Negative
1	1	Girl's Restroom next to Classroom 104	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Girl's Restroom next to Classroom 104	Floor	Concrete	Grey	None	0	0.1	Negative
1	1	Girl's Restroom next to Classroom 104	Ceiling	Concrete	White	Flaking	3	0.03	Negative
1	1	Girl's Restroom next to Classroom 104	Horizontal Pipe (Ceiling)	Metal	White	Flaking	3	0.9	Positive
1	1	Girl's Restroom next to Classroom 104	Ductwork	Metal	White	None	0	0	Negative
1	1	Classroom 105	W1	Plaster	Tan	None	0	7.7	Positive
1	1	Classroom 105	W1	Plaster	Yellow	Flaking	4	4.8	Positive
1	1	Classroom 105	W2	Sheetrock	Tan	None	0	0	Negative
1	1	Classroom 105	W3	Plaster	Tan	Chipping	4	2.2	Positive
1	1	Classroom 105	Radiator (W3)	Metal	White	None	0	0.4	Negative
1	1	Classroom 105	W4	Sheetrock	Tan	None	0	0	Negative
1	1	Classroom 105	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 105	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	Ceiling	Plaster	White	Flaking	400	11.1	Positive
1	1	Classroom 105 Storage	W1	Plaster	Tan	None	0	7.2	Positive
1	1	Classroom 105 Storage	W2	Plaster	Tan	None	0	5.8	Positive
1	1	Classroom 105 Storage	W3	Plaster	Tan	None	0	7.1	Positive
1	1	Classroom 105 Storage	W4	Plaster	Tan	None	0	6.9	Positive
1	1	Classroom 105 Storage	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 105 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Storage	Ceiling	Plaster	Tan	None	0	8.2	Positive
1	1	Classroom 106	W1	Plaster	Tan	Chipping	2	4.3	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Classroom 106	W1	Plaster	Yellow	Cracking	6	8	Positive
1	1	Classroom 106	W2	Sheetrock	Tan	None	0	0	Negative
1	1	Classroom 106	W3	Plaster	Tan	Flaking	11	5.7	Positive
1	1	Classroom 106	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Classroom 106	W4	Sheetrock	Tan	None	0	0	Negative
1	1	Classroom 106	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 106	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	Ceiling	Plaster	White	Flaking	250	11.1	Positive
1	1	Classroom 106 Storage	W1	Plaster	Tan	None	0	6.3	Positive
1	1	Classroom 106 Storage	W2	Plaster	Tan	None	0	8.6	Positive
1	1	Classroom 106 Storage	W3	Plaster	Tan	None	0	5.4	Positive
1	1	Classroom 106 Storage	W4	Plaster	Tan	None	0	3.6	Positive
1	1	Classroom 106 Storage	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 106 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106 Storage	Ceiling	Plaster	White	Cracking	2	5.8	Positive
1	1	Classroom 107	W1	Plaster	Tan	Flaking	2	7.8	Positive
1	1	Classroom 107	W2	Plaster	Yellow	Chipping	2	7.5	Positive
1	1	Classroom 107	W3	Plaster	Tan	Flaking	8	5.6	Positive
1	1	Classroom 107	Radiator	Metal	White	None	0	0	Negative
1	1	Classroom 107	W4	Sheetrock	Tan	None	0	0.1	Negative
1	1	Classroom 107	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 107	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	Ceiling	Plaster	White	Flaking	195	10.9	Positive
1	1	Classroom 107 Storage	W1	Plaster	Tan	Flaking	1	7.9	Positive
1	1	Classroom 107 Storage	W2	Plaster	Tan	None	0	8.6	Positive
1	1	Classroom 107 Storage	W3	Plaster	Tan	None	0	7.5	Positive
1	1	Classroom 107 Storage	W4	Plaster	Tan	None	0	4.6	Positive
1	1	Classroom 107 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Storage	Ceiling	Plaster	Tan	None	0	8.8	Positive
1	1	Boy's Restroom next to Classroom 107	W1	Plaster	White	Cracking	3	4.4	Positive
1	1	Boy's Restroom next to Classroom 107	W2	Sheetrock	White	Cracking	1	0	Negative
1	1	Boy's Restroom next to Classroom 107	W2	Concrete	White	Flaking	1	0	Negative
1	1	Boy's Restroom next to Classroom 107	W3	Plaster	White	Flaking	1	4.3	Positive
1	1	Boy's Restroom next to Classroom 107	Vertical Pipe (W3)	Metal	White	Flaking	2	4.2	Positive
1	1	Boy's Restroom next to Classroom 107	W4	Plaster	White	None	0	3.5	Positive
1	1	Boy's Restroom next to Classroom 107	Radiator Cover	Metal	Brown	None	0	0	Negative
1	1	Boy's Restroom next to Classroom 107	Floor	Concrete	Grey	None	0	0	Negative
1	1	Boy's Restroom next to Classroom 107	Ceiling	Concrete	White	Cracking	4	0	Negative
1	1	Boy's Restroom next to Classroom 107	Ductwork	Metal	White	None	0	0	Negative
1	1	Hallway at Classrooms 105 to 107	Ceiling	Plaster	White	Flaking	250	11.4	Positive
1	1	Hallway at Classrooms 105 to 107	W1	Plaster	Tan	Flaking	40	8.2	Positive
1	1	Hallway at Classrooms 105 to 107	Electrical Panel	Metal	Brown	Chipping	2	0.4	Negative

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Hallway at Classrooms 105 to 107	Baseboard	Concrete	Brown	None	0	3.1	Positive
1	1	Hallway at Classrooms 105 to 107	W2	Plaster	Tan	Flaking	35	8	Positive
1	1	Hallway at Classrooms 105 to 107	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Auditorium Foyer Near 105	W1	Plaster	Tan	None	0	8.3	Positive
1	1	Auditorium Foyer Near 105	Moulding	Wood	Tan	Chipping	2	3.8	Positive
1	1	Auditorium Foyer Near 105	Door Frame	Wood	Brown	Chipping	6	6.3	Positive
1	1	Auditorium Foyer Near 105	Door	Wood	Brown	Chipping	2	8.3	Positive
1	1	Auditorium Foyer Near 105	W2	Plaster	Tan	None	0	2.9	Positive
1	1	Auditorium Foyer Near 105	Moulding	Wood	Tan	Chipping	32	5.1	Positive
1	1	Auditorium Foyer Near 105	Stringer	Wood	Brown	Cracking	7	4.8	Positive
1	1	Auditorium Foyer Near 105	W3	Plaster	Tan	None	0	8.7	Positive
1	1	Auditorium Foyer Near 105	Moulding	Wood	Tan	Cracking	1	4.6	Positive
1	1	Auditorium Foyer Near 105	Door Frame	Wood	Brown	Cracking	10	5.7	Positive
1	1	Auditorium Foyer Near 105	Door	Wood	Brown	Cracking	1	5.8	Positive
1	1	Auditorium Foyer Near 105	W4	Plaster	Tan	Cracking	2	3.1	Positive
1	1	Auditorium Foyer Near 105	Moulding	Wood	Tan	Flaking	32	6.8	Positive
1	1	Auditorium Foyer Near 105	Stringer	Wood	Brown	Cracking	2	8.6	Positive
1	1	Auditorium Foyer Near 105	Ceiling	Plaster	White	Cracking	3	7.6	Positive
1	1	Auditorium Foyer Between 106-109	W1	Plaster	Tan	None	0	9.7	Positive
1	1	Auditorium Foyer Between 106-109	Moulding	Wood	Tan	None	0	4.8	Positive
1	1	Auditorium Foyer Between 106-109	Door Frame	Wood	Brown	Chipping	3	4.6	Positive
1	1	Auditorium Foyer Between 106-109	Door	Wood	Brown	Chipping	2	6.4	Positive
1	1	Auditorium Foyer Between 106-109	W2	Plaster	Tan	Chipping	8	10.3	Positive
1	1	Auditorium Foyer Between 106-109	Moulding	Wood	Tan	Flaking	24	5.5	Positive
1	1	Auditorium Foyer Between 106-109	Stringer	Wood	Brown	None	0	6.8	Positive
1	1	Auditorium Foyer Between 106-109	W3	Plaster	Tan	Cracking	1	9.2	Positive
1	1	Auditorium Foyer Between 106-109	Moulding	Wood	Tan	None	0	5.4	Positive
1	1	Auditorium Foyer Between 106-109	Door Frame	Wood	Tan	Chipping	2	5.9	Positive
1	1	Auditorium Foyer Between 106-109	Door	Wood	Brown	Cracking	2	8	Positive
1	1	Auditorium Foyer Between 106-109	W4	Plaster	Tan	None	0	8.5	Positive
1	1	Auditorium Foyer Between 106-109	Moulding	Wood	Tan	Flaking	16	6	Positive
1	1	Auditorium Foyer Between 106-109	Stringer	Wood	Brown	None	0	6.4	Positive
1	1	Auditorium Foyer Between 106-109	Ceiling	Plaster	White	Cracking	3	10.5	Positive
1	1	Storage in Hallway by Auditorium Entrance	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A
1	1	Storage in Hallway by Auditorium Entrance	W2	Plaster	Tan	Partially Inaccessible	0	3.2	Positive
1	1	Storage in Hallway by Auditorium Entrance	W3	Plaster	Tan	Partially Inaccessible	0	4.6	Positive
1	1	Storage in Hallway by Auditorium Entrance	W4	Plaster	Tan	Partially Inaccessible	0	7.6	Positive
1	1	Storage in Hallway by Auditorium Entrance	Floor	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	1	Storage in Hallway by Auditorium Entrance	Ceiling	Plaster	Tan	Partially Inaccessible	0	5.4	Positive
1	1	Custodial Closet in Hallway by Auditorium Entrance	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A
1	1	Custodial Closet in Hallway by Auditorium Entrance	W2	Plaster	Tan	Partially Inaccessible	0	4.7	Positive
1	1	Custodial Closet in Hallway by Auditorium Entrance	W3	Plaster	Tan	Partially Inaccessible	0	6.6	Positive
1	1	Custodial Closet in Hallway by Auditorium Entrance	W4	Plaster	Tan	Partially Inaccessible	0	6.7	Positive
1	1	Custodial Closet in Hallway by Auditorium Entrance	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Custodial Closet in Hallway by Auditorium Entrance	Ceiling	Plaster	Tan	Cracking	2	8.9	Positive
1	1	Classroom 108	W1	Plaster	Tan	None	0	9	Positive
1	1	Classroom 108	W2	Plaster	Tan	Flaking	4	7.2	Positive
1	1	Classroom 108	W3	Plaster	Tan	Cracking	2	7.7	Positive
1	1	Classroom 108	Radiator Cover (W3)	Metal	White	None	0	0.1	Negative
1	1	Classroom 108	W4	Plaster	Yellow	Flaking	1	2.8	Positive
1	1	Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Ceiling	Plaster	White	Flaking	225	10.6	Positive
1	1	Classroom 108 Storage	W1	Plaster	Tan	None	0	5.6	Positive
1	1	Classroom 108 Storage	W2	Plaster	Tan	Flaking	1	7.6	Positive
1	1	Classroom 108 Storage	W3	Plaster	Tan	None	0	7.2	Positive
1	1	Classroom 108 Storage	W4	Plaster	Tan	None	0	7.6	Positive
1	1	Classroom 108 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Storage	Ceiling	Plaster	Tan	None	0	9.9	Positive
1	1	Classroom 108 Restroom	W1	Plaster	Tan	None	0	8	Positive
1	1	Classroom 108 Restroom	W2	Plaster	Tan	Cracking	1	5.2	Positive
1	1	Classroom 108 Restroom	W3	Plaster	Tan	None	0	8.4	Positive
1	1	Classroom 108 Restroom	W4	Plaster	Tan	None	0	7.4	Positive
1	1	Classroom 108 Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Restroom	Ceiling	Plaster	Tan	Flaking	2	8.5	Positive
1	1	Classroom 109	W1	Plaster	Tan	Cracking	2	3.9	Positive
1	1	Classroom 109	W2	Plaster	Yellow	Flaking	1	7.3	Positive
1	1	Classroom 109	W3	Plaster	Tan	Flaking	8	3.1	Positive
1	1	Classroom 109	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Classroom 109	W4	Plaster	Tan	Cracking	2	8.6	Positive
1	1	Classroom 109	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109	Ceiling	Plaster	White	Flaking	180	10.8	Positive
1	1	Classroom 109 Storage	W1	Plaster	Tan	None	0	8.2	Positive
1	1	Classroom 109 Storage	W2	Plaster	Tan	None	0	4.7	Positive
1	1	Classroom 109 Storage	W3	Sheetrock	Tan	None	0	0.1	Negative
1	1	Classroom 109 Storage	W4	Plaster	Tan	None	0	8.2	Positive
1	1	Classroom 109 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109 Storage	Ceiling	Plaster	White	None	0	9.6	Positive
1	1	Classroom 109 Restroom	W1	Plaster	White	None	0	7	Positive
1	1	Classroom 109 Restroom	W2	Sheetrock	White	None	0	0	Negative
1	1	Classroom 109 Restroom	W3	Plaster	White	Flaking	1	7.9	Positive
1	1	Classroom 109 Restroom	W4	Plaster	White	None	0	8.4	Positive
1	1	Classroom 109 Restroom	Floor	Concrete	Grey	None	0	0.1	Negative
1	1	Classroom 109 Restroom	Ceiling	Plaster	White	Flaking	1	7.9	Positive
1	1	Classroom 110	W1	Plaster	Yellow	Flaking	2	3.5	Positive
1	1	Classroom 110	W1	Plaster	Tan	Flaking	1	4.1	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Classroom 110	W2	Plaster	Tan	Cracking	8	8.8	Positive
1	1	Classroom 110	Radiator Cover	Metal	White	Flaking	6	0.3	Negative
1	1	Classroom 110	W3	Plaster	Yellow	None	0	3.3	Positive
1	1	Classroom 110	Radiator Cover	Metal	White	Chipping	6	0.2	Negative
1	1	Classroom 110	W4	Plaster	Tan	None	0	2.8	Positive
1	1	Classroom 110	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 110	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110	Ceiling	Plaster	White	Flaking	300	11.2	Positive
1	1	Classroom 110 Storage	W1	Plaster	Tan	None	0	7.6	Positive
1	1	Classroom 110 Storage	W2	Plaster	Tan	None	0	8	Positive
1	1	Classroom 110 Storage	W3	Plaster	Tan	None	0	7.3	Positive
1	1	Classroom 110 Storage	W4	Plaster	Tan	None	0	9.5	Positive
1	1	Classroom 110 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110 Storage	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	1	Classroom 110 Storage	Ceiling	Plaster	White	None	0	9.5	Positive
1	1	Classroom 110 Restroom	W1	Plaster	White	None	0	7.1	Positive
1	1	Classroom 110 Restroom	W2	Plaster	White	None	0	7.7	Positive
1	1	Classroom 110 Restroom	W3	Plaster	White	Cracking	3	7.4	Positive
1	1	Classroom 110 Restroom	W4	Plaster	White	None	0	8.1	Positive
1	1	Classroom 110 Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110 Restroom	Ceiling	Plaster	White	Cracking	2	5.7	Positive
1	1	Classroom 111	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 111	Ceiling	Plaster	White	Flaking	150	7.1	Positive
1	1	Classroom 111	W1	Plaster	Tan	None	0	5.7	Positive
1	1	Classroom 111	W2	Plaster	Tan	Flaking	2	7.3	Positive
1	1	Classroom 111	Blackboard Ledge	Wood	Tan	None	0	6.9	Positive
1	1	Classroom 111	W3	Plaster	Tan	Flaking	4	9	Positive
1	1	Classroom 111	Radiator Cover	Metal	Tan	None	0	0	Negative
1	1	Classroom 111	W4	Plaster	Tan	None	0	7.8	Positive
1	1	Classroom 111	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Front Foyer	Ceiling	Plaster	Tan	None	0	8.9	Positive
1	1	Front Foyer	W1	Plaster	Tan	None	0	2.5	Positive
1	1	Front Foyer	Conduit	Metal	White	None	0	0	Negative
1	1	Front Foyer	Door	Metal	Brown	None	0	0	Negative
1	1	Front Foyer	Door Frame	Metal	Brown	None	0	0	Negative
1	1	Front Foyer	W2	Plaster	Tan	None	0	8.5	Positive
1	1	Front Foyer	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Front Foyer	W3	Plaster	Tan	Cracking	10	3.3	Positive
1	1	Front Foyer	W4	Plaster	Tan	Flaking	1	10.5	Positive
1	1	Front Foyer	Floor	Concrete	Brown	Flaking	6	0	Negative
1	1	Stairwell Next to Classroom 111	Ceiling	Plaster	Tan	None	0	7.6	Positive
1	1	Stairwell Next to Classroom 111	W1	Plaster	Tan	None	0	8.8	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Stairwell Next to Classroom 111	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	1	Stairwell Next to Classroom 111	Door	Metal	Brown	Chipping	2	0.1	Negative
1	1	Stairwell Next to Classroom 111	W2	Plaster	Tan	None	0	8.4	Positive
1	1	Stairwell Next to Classroom 111	Stringer	Concrete	Brown	Flaking	2	1.4	Positive
1	1	Stairwell Next to Classroom 111	Step	Concrete	Brown	None	0	0.1	Negative
1	1	Stairwell Next to Classroom 111	Riser	Concrete	Brown	Flaking	1	5.1	Positive
1	1	Stairwell Next to Classroom 111	W3	Plaster	Tan	None	0	2.5	Positive
1	1	Stairwell Next to Classroom 111	Baseboard	Concrete	Brown	None	0	2.2	Positive
1	1	Classroom 111 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 111 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 111 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 111 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 111 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 111 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Auditorium	W1	Plaster	Tan	Cracking	8	5.2	Positive
1	1	Auditorium	Moulding	Wood	White	Flaking	26	2.3	Positive
1	1	Auditorium	W2	Plaster	Tan	Cracking	10	1.6	Positive
1	1	Auditorium	Moulding	Wood	White	Cracking	5	4.5	Positive
1	1	Auditorium	Vent	Metal	White	Cracking	6	4.9	Positive
1	1	Auditorium	Moulding	Wood	White	Cracking	4	1.4	Positive
1	1	Auditorium	Door Frame	Metal	Brown	Chipping	2	0	Negative
1	1	Auditorium	Door	Metal	Brown	None	0	0	Negative
1	1	Auditorium	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Auditorium	W3	Plaster	Tan	Cracking	3	2.3	Positive
1	1	Auditorium	W3	Plaster	White	None	0	1.7	Positive
1	1	Auditorium	Moulding	Wood	Brown	Cracking	4	5.4	Positive
1	1	Auditorium	Vent	Metal	White	Cracking	1	1.3	Positive
1	1	Auditorium	W4	Plaster	Tan	Efflorescence	105	3.8	Positive
1	1	Auditorium	Moulding	Wood	Brown	Flaking	2	6.7	Positive
1	1	Auditorium	Vent	Metal	Tan	Cracking	6	6.1	Positive
1	1	Auditorium	Moulding	Wood	White	Cracking	5	6.5	Positive
1	1	Auditorium	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	1	Auditorium	Door	Metal	Brown	None	0	0	Negative
1	1	Auditorium	Ceiling	Plaster	White	Flaking	260	6.8	Positive
1	1	Auditorium	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Hallway at Classrooms 108 to 111	Ceiling	Plaster	White	Flaking	83	10.3	Positive
1	1	Hallway at Classrooms 108 to 111	W1	Plaster	Tan	Cracking	9	8.2	Positive
1	1	Hallway at Classrooms 108 to 111	Vertical Pipe	Metal	White	Cracking	2	7.3	Positive
1	1	Hallway at Classrooms 108 to 111	Vertical Pipe	Metal	Brown	Cracking	2	6.4	Positive
1	1	Hallway at Classrooms 108 to 111	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Hallway at Classrooms 108 to 111	W2	Plaster	Tan	Flaking	6	7.7	Positive
1	1	Hallway at Classrooms 108 to 111	Baseboard	Concrete	Brown	None	0	1.1	Positive
1	1	Utility Closet in Hallway to the left of Auditorium Entrance	W1	Plaster	White	Partially Inaccessible	0	12.4	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Utility Closet in Hallway to the left of Auditorium Entrance	W2	Plaster	White	Partially Inaccessible	0	9.3	Positive
1	1	Utility Closet in Hallway to the left of Auditorium Entrance	W3	Plaster	White	Partially Inaccessible	0	10.5	Positive
1	1	Utility Closet in Hallway to the left of Auditorium Entrance	W4	Plaster	White	Partially Inaccessible	0	10.3	Positive
1	1	Utility Closet in Hallway to the left of Auditorium Entrance	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	1	Utility Closet in Hallway to the left of Auditorium Entrance	Ceiling	Plaster	White	Partially Inaccessible	0	16.8	Positive
1	1	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	Ceiling	Plaster	Tan	None	0	6.7	Positive
1	1	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	W1	Plaster	Tan	None	0	6	Positive
1	1	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	Door Frame	Metal	Brown	Chipping	1	0.3	Negative
1	1	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	Door	Metal	Brown	None	0	0.3	Negative
1	1	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	W2	Plaster	Tan	None	0	5.4	Positive
1	1	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	W3	Plaster	Tan	Cracking	1	6.8	Positive
1	1	Lantern Room - Storage in Hallway by Auditorium Entrance (includes 3 small rooms)	W4	Plaster	Tan	None	0	4.5	Positive
1	1	Wardrobe Room in the Hallway to the right of Auditorium Entrance	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A
1	1	Wardrobe Room in the Hallway to the right of Auditorium Entrance	W2	Plaster	Tan	Partially Inaccessible	0	11.5	Positive
1	1	Wardrobe Room in the Hallway to the right of Auditorium Entrance	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A
1	1	Wardrobe Room in the Hallway to the right of Auditorium Entrance	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A
1	1	Wardrobe Room in the Hallway to the right of Auditorium Entrance	Floor	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	1	Wardrobe Room in the Hallway to the right of Auditorium Entrance	Ceiling	Plaster	Tan	Partially Inaccessible	0	10.2	Positive
1	1	Stage	Apron	Wood	Tan	Flaking	1	7.7	Positive
1	1	Stage	Apron Vent	Metal	Tan	Cracking	5	5.9	Positive
1	1	Stage	Apron Baseboard	Wood	Brown	Cracking	1	6.2	Positive
1	1	Stage	W2	Plaster	Black	Cracking	5	3.4	Positive
1	1	Stage	Moulding	Wood	Brown	Cracking	2	7.5	Positive
1	1	Stage	Door Frame	Wood	Brown	Chipping	1	5.3	Positive
1	1	Stage	Door	Wood	Brown	Cracking	2	6.6	Positive
1	1	Stage	W3	Plaster	Black	Cracking	9	1.4	Positive
1	1	Stage	Baseboard	Wood	Black	None	0	3.4	Positive
1	1	Stage	Radiator	Metal	Brown	None	0	0.2	Negative
1	1	Stage	W4	Plaster	Black	Cracking	6	5.9	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Stage	Moulding	Wood	Black	Cracking	2	5.7	Positive
1	1	Stage	Door Frame	Wood	Black	Chipping	1	2.7	Positive
1	1	Storage to the Right of Stage	W1	Plaster	Tan	None	0	0.2	Negative
1	1	Storage to the Right of Stage	Door Frame	Wood	Brown	Chipping	3	6.7	Positive
1	1	Storage to the Right of Stage	Door	Wood	Brown	Chipping	2	6.2	Positive
1	1	Storage to the Right of Stage	W2	Plaster	Tan	Cracking	1	5.5	Positive
1	1	Storage to the Right of Stage	Electrical Panel	Metal	Brown	Cracking	2	0.1	Negative
1	1	Storage to the Right of Stage	W3	Plaster	Tan	None	0	4.1	Positive
1	1	Storage to the Right of Stage	Window Sill	Wood	Brown	Chipping	1	2.6	Positive
1	1	Storage to the Right of Stage	Window Frame	Wood	Brown	Chipping	1	1.3	Positive
1	1	Storage to the Right of Stage	W4	Plaster	Tan	None	0	0	Negative
1	1	Storage to the Right of Stage	Ceiling	Plaster	White	Cracking	3	0.6	Negative
1	1	Storage to the Right of Stage	Access Panel	Wood	Brown	Cracking	4	6.9	Positive
1	1	Storage to the Left of Stage	W1	Plaster	White	None	0	4.7	Positive
1	1	Storage to the Left of Stage	Door Frame	Wood	Brown	Chipping	2	6.8	Positive
1	1	Storage to the Left of Stage	Door	Wood	Brown	Cracking	1	7.7	Positive
1	1	Storage to the Left of Stage	W2	Plaster	White	None	0	3.9	Positive
1	1	Storage to the Left of Stage	W3	Plaster	White	None	0	4.5	Positive
1	1	Storage to the Left of Stage	Window Sill	Wood	Brown	Cracking	1	2.3	Positive
1	1	Storage to the Left of Stage	Window Frame	Wood	Brown	None	0	1.1	Positive
1	1	Storage to the Left of Stage	Radiator	Metal	Brown	None	0	0	Positive
1	1	Storage to the Left of Stage	W4	Plaster	White	Cracking	2	1.6	Positive
1	1	Storage to the Left of Stage	Ceiling	Plaster	White	None	0	1.4	Positive
1	1	Stairwell on the Girl's Restroom Side	Ceiling	Plaster	White	Cracking	8	9.7	Positive
1	1	Stairwell on the Girl's Restroom Side	Door	Metal	Brown	Chipping	1	0.1	Negative
1	1	Stairwell on the Girl's Restroom Side	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	1	Stairwell on the Girl's Restroom Side	W2	Plaster	Tan	None	0	7.1	Positive
1	1	Stairwell on the Girl's Restroom Side	Stringer	Concrete	Brown	Flaking	1	5	Positive
1	1	Stairwell on the Girl's Restroom Side	Step	Concrete	Brown	Chipping	2	1.6	Positive
1	1	Stairwell on the Girl's Restroom Side	Riser	Concrete	Brown	None	0	4.9	Positive
1	1	Stairwell on the Girl's Restroom Side	W3	Plaster	Tan	None	0	7.7	Positive
1	1	Stairwell on the Girl's Restroom Side	Newel Post	Metal	Brown	None	0	5.1	Positive
1	1	Stairwell on the Girl's Restroom Side	Door	Metal	Brown	Chipping	1	0.1	Negative
1	1	Stairwell on the Girl's Restroom Side	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	1	Stairwell on the Girl's Restroom Side	W4	Plaster	Tan	Cracking	2	2.4	Positive
1	1	Stairwell on the Boy's Restroom Side	Ceiling	Plaster	White	None	0	10.1	Positive
1	1	Stairwell on the Boy's Restroom Side	Door	Metal	Brown	Chipping	1	0.1	Negative
1	1	Stairwell on the Boy's Restroom Side	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	1	Stairwell on the Boy's Restroom Side	W2	Plaster	Tan	None	0	9.6	Positive
1	1	Stairwell on the Boy's Restroom Side	Stringer	Concrete	Brown	None	0	5.8	Positive
1	1	Stairwell on the Boy's Restroom Side	Step	Concrete	Brown	Flaking	1	1.3	Positive
1	1	Stairwell on the Boy's Restroom Side	Riser	Concrete	Brown	Chipping	3	5.4	Positive
1	1	Stairwell on the Boy's Restroom Side	Newel Post	Metal	Brown	Flaking	4	3.3	Positive
1	1	Stairwell on the Boy's Restroom Side	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Stairwell on the Boy's Restroom Side	W3	Plaster	Tan	None	0	2.8	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	1	Stairwell on the Boy's Restroom Side	Pipe Riser Jacket	Metal	Brown	None	0	0	Negative
1	1	Stairwell on the Boy's Restroom Side	Window Frame	Wood	Brown	None	0	0.2	Negative
1	1	Stairwell on the Boy's Restroom Side	W4	Plaster	Tan	Cracking	2	8.1	Positive
1	1	Front Foyer	Ceiling	Plaster	Tan	None	0	7.2	Positive
1	1	Front Foyer	W1	Plaster	Tan	Cracking	2	2.8	Positive
1	1	Front Foyer	W3	Plaster	Tan	None	0	6.6	Positive
1	1	Front Foyer	W4	Plaster	Tan	None	0	5.4	Positive
1	1	Front Foyer	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Front Foyer	Door	Metal	Brown	None	0	0	Negative
1	1	Front Foyer	Door Frame	Metal	Brown	None	0	0	Negative
1	1	Back Foyer	Ceiling	Plaster	Tan	None	0	7.9	Positive
1	1	Back Foyer	W1	Plaster	Tan	None	0	7	Positive
1	1	Back Foyer	Door	Metal	Brown	None	0	0	Negative
1	1	Back Foyer	Door Frame	Metal	Brown	None	0	0	Negative
1	1	Back Foyer	Pipe Riser Jacket	Metal	White	None	0	0.9	Positive
1	1	Back Foyer	Pipe Riser Turn	Metal	Brown	None	0	0.4	Negative
1	1	Back Foyer	W2	Plaster	Tan	Cracking	1	7.3	Positive
1	1	Back Foyer	Radiator Cover	Metal	White	None	0	0.1	Negative
1	1	Back Foyer	W3	Plaster	Tan	None	0	8.8	Positive
1	1	Back Foyer	W4	Plaster	Tan	None	0	5.9	Positive
1	2	Classroom 200	W1	Plaster	Orange	Flaking	6	6.9	Positive
1	2	Classroom 200	Vertical Pipe	Metal	White	Flaking	2	0.8	Positive
1	2	Classroom 200	W2	Plaster	Tan	Flaking	4	5.3	Positive
1	2	Classroom 200	Radiator Cover	Metal	White	None	0	0.1	Negative
1	2	Classroom 200	W3	Plaster	Tan	Flaking	14	7.2	Positive
1	2	Classroom 200	Radiator Cover	Metal	White	None	0	0.2	Negative
1	2	Classroom 200	W4	Plaster	Tan	Flaking	6	7.8	Positive
1	2	Classroom 200	Baseboard	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 200	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	Ceiling	Plaster	White	Flaking	250	9.7	Positive
1	2	Classroom 200 Storage	W1	Plaster	Tan	None	0	7.6	Positive
1	2	Classroom 200 Storage	Vertical Pipe	Metal	White	Flaking	2	6.4	Positive
1	2	Classroom 200 Storage	W2	Plaster	Tan	Cracking	1	8.1	Positive
1	2	Classroom 200 Storage	W3	Plaster	Tan	Flaking	3	8.5	Positive
1	2	Classroom 200 Storage	W4	Plaster	Tan	Flaking	1	9.4	Positive
1	2	Classroom 200 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200 Storage	Ceiling	Plaster	Tan	Flaking	4	9.6	Positive
1	2	Office at the end of the Hallway by Classroom 200	W1	Plaster	Tan	None	0	4.1	Positive
1	2	Office at the end of the Hallway by Classroom 200	W2	Plaster	Tan	Cracking	2	5.5	Positive
1	2	Office at the end of the Hallway by Classroom 200	W3	Plaster	Tan	Flaking	3	3.7	Positive
1	2	Office at the end of the Hallway by Classroom 200	Radiator	Metal	White	Flaking	1	0.2	Negative
1	2	Office at the end of the Hallway by Classroom 200	W4	Plaster	Tan	None	0	6.5	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	2	Office at the end of the Hallway by Classroom 200	Baseboard	Wood	Brown	None	0	0.1	Negative
1	2	Office at the end of the Hallway by Classroom 200	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Office at the end of the Hallway by Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Office at the end of the Hallway by Classroom 200	Ceiling	Plaster	White	Flaking	150	9.2	Positive
1	2	Classroom 201	W1	Plaster	Tan	None	0	9.5	Positive
1	2	Classroom 201	W1	Plaster	Orange	Flaking	3	10.9	Positive
1	2	Classroom 201	W2	Plaster	Tan	Flaking	14	8.6	Positive
1	2	Classroom 201	Radiator	Metal	White	Flaking	1	0.1	Negative
1	2	Classroom 201	Window Sill	Wood	Brown	None	0	0.3	Positive
1	2	Classroom 201	W3	Plaster	Tan	Flaking	8	8.2	Positive
1	2	Classroom 201	Radiator	Metal	White	Flaking	1	0.1	Negative
1	2	Classroom 201	W4	Plaster	Blue	Flaking	2	9.4	Positive
1	2	Classroom 201	Radiator	Metal	White	Chipping	1	0.2	Negative
1	2	Classroom 201	Baseboard	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 201	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201	Ceiling	Plaster	White	Flaking	350	8.6	Positive
1	2	Classroom 201 Storage	W1	Plaster	Tan	None	0	9.5	Positive
1	2	Classroom 201 Storage	W2	Plaster	Tan	None	0	9.9	Positive
1	2	Classroom 201 Storage	W3	Plaster	Tan	None	0	7.6	Positive
1	2	Classroom 201 Storage	W4	Plaster	Tan	None	0	9.4	Positive
1	2	Classroom 201 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201 Storage	Ceiling	Plaster	Tan	None	0	9.1	Positive
1	2	Classroom 202	W1	Plaster	Tan	None	0	9.6	Positive
1	2	Classroom 202	W2	Plaster	Tan	Flaking	5	8.9	Positive
1	2	Classroom 202	W3	Plaster	Tan	Flaking	8	7.7	Positive
1	2	Classroom 202	Radiator	Metal	White	None	0	0.3	Negative
1	2	Classroom 202	W4	Plaster	Orange	Chipping	1	9.3	Positive
1	2	Classroom 202	Baseboard	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 202	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	Ceiling	Plaster	White	Flaking	450	10.6	Positive
1	2	Classroom 202 Storage	W1	Plaster	Tan	None	0	8.9	Positive
1	2	Classroom 202 Storage	W2	Plaster	Tan	None	0	8.8	Positive
1	2	Classroom 202 Storage	W3	Plaster	Tan	Cracking	1	10.1	Positive
1	2	Classroom 202 Storage	W4	Plaster	Tan	None	0	9.2	Positive
1	2	Classroom 202 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202 Storage	Ceiling	Plaster	Tan	Flaking	1	9.4	Positive
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 203 Storage	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 204	W1	Plaster	Tan	Cracking	3	8.2	Positive
1	2	Classroom 204	W2	Sheetrock	Tan	None	0	0	Negative
1	2	Classroom 204	W3	Plaster	Tan	Cracking	12	7.9	Positive
1	2	Classroom 204	Radiator Cover	Metal	White	None	0	0.2	Negative
1	2	Classroom 204	W4	Plaster	Orange	Cracking	2	7.5	Positive
1	2	Classroom 204	Baseboard	Wood	Brown	None	0	0	Negative
1	2	Classroom 204	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204	Ceiling	Plaster	White	Flaking	480	11	Positive
1	2	Classroom 204 Storage	W1	Plaster	Tan	None	0	7.4	Positive
1	2	Classroom 204 Storage	W2	Plaster	Tan	None	0	10.1	Positive
1	2	Classroom 204 Storage	W3	Plaster	Tan	Cracking	1	9.1	Positive
1	2	Classroom 204 Storage	Vertical Pipe	Metal	Tan	Flaking	2	1.1	Positive
1	2	Classroom 204 Storage	W4	Plaster	Tan	None	0	4.4	Positive
1	2	Classroom 204 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204 Storage	Ceiling	Plaster	Tan	None	0	10	Positive
1	2	Girl's Restroom next to Classroom 204	W1	Plaster	White	Cracking	1	6.6	Positive
1	2	Girl's Restroom next to Classroom 204	Door	Wood	Brown	Chipping	1	0	Negative
1	2	Girl's Restroom next to Classroom 204	Door Frame	Wood	Brown	Cracking	1	0	Negative
1	2	Girl's Restroom next to Classroom 204	W2	Plaster	White	None	0	6.7	Positive
1	2	Girl's Restroom next to Classroom 204	W3	Plaster	White	Cracking	2	5.9	Positive
1	2	Girl's Restroom next to Classroom 204	Vertical Pipe	Metal	White	Flaking	6	4.8	Positive
1	2	Girl's Restroom next to Classroom 204	W4	Plaster	White	None	0	6.1	Positive
1	2	Girl's Restroom next to Classroom 204	Window Frame	Wood	Brown	Flaking	4	0.1	Negative
1	2	Girl's Restroom next to Classroom 204	Radiator	Metal	Brown	None	0	0	Negative
1	2	Girl's Restroom next to Classroom 204	Floor	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	2	Girl's Restroom next to Classroom 204	Ceiling	Plaster	Tan	None	0	4.2	Positive
1	2	Stairwell next to Girl's Restroom	Ceiling	Plaster	White	None	0	7.9	Positive
1	2	Stairwell next to Girl's Restroom	Door	Metal	Brown	Chipping	1	0.1	Negative
1	2	Stairwell next to Girl's Restroom	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	2	Stairwell next to Girl's Restroom	W2	Plaster	Tan	None	0	8.4	Positive
1	2	Stairwell next to Girl's Restroom	Stringer	Concrete	Brown	None	0	4.9	Positive
1	2	Stairwell next to Girl's Restroom	Step	Concrete	Brown	Flaking	2	0.1	Negative
1	2	Stairwell next to Girl's Restroom	Riser	Concrete	Brown	None	0	4.4	Positive
1	2	Stairwell next to Girl's Restroom	Newel Post	Metal	Brown	None	0	8.8	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	2	Stairwell next to Girl's Restroom	W3	Plaster	Tan	None	0	5.6	Positive
1	2	Stairwell next to Girl's Restroom	Window Frame	Wood	Brown	None	0	0.3	Negative
1	2	Stairwell next to Girl's Restroom	W4	Plaster	White	None	0	0	Negative
1	2	Stairwell next to Girl's Restroom	Radiator Cover	Metal	Tan	None	0	8	Positive
1	2	Classroom 205	W1	Plaster	Tan	None	0	9	Positive
1	2	Classroom 205	W1	Plaster	Orange	Cracking	3	8.2	Positive
1	2	Classroom 205	W2	Sheetrock	Tan	None	0	0	Negative
1	2	Classroom 205	W3	Plaster	Tan	Flaking	8	10.1	Positive
1	2	Classroom 205	Radiator	Metal	White	None	0	0.2	Negative
1	2	Classroom 205	W4	Sheetrock	Tan	None	0	0.1	Negative
1	2	Classroom 205	Baseboard	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 205	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	Ceiling	Plaster	White	Flaking	150	10.7	Positive
1	2	Classroom 205 Storage	W1	Plaster	Tan	None	0	6.7	Positive
1	2	Classroom 205 Storage	Door Frame	Wood	Brown	Chipping	1	0	Negative
1	2	Classroom 205 Storage	W2	Plaster	Tan	None	0	10.1	Positive
1	2	Classroom 205 Storage	W3	Plaster	Tan	Flaking	1	9.6	Positive
1	2	Classroom 205 Storage	W4	Plaster	Tan	None	0	5.4	Positive
1	2	Classroom 205 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205 Storage	Ceiling	Plaster	Tan	Flaking	1	9.8	Positive
1	2	Classroom 206	W1	Plaster	Tan	None	0	8.6	Positive
1	2	Classroom 206	W1	Plaster	Orange	Flaking	4	9.5	Positive
1	2	Classroom 206	W2	Sheetrock	Tan	None	0	0	Negative
1	2	Classroom 206	W3	Plaster	Tan	Flaking	10	7.4	Positive
1	2	Classroom 206	Radiator	Metal	White	None	0	0.3	Negative
1	2	Classroom 206	W4	Sheetrock	Tan	None	0	0	Negative
1	2	Classroom 206	Baseboard	Wood	Brown	None	0	0	Negative
1	2	Classroom 206	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	Ceiling	Plaster	White	Flaking	450	10.2	Positive
1	2	Classroom 206 Storage	W1	Plaster	Tan	None	0	9.4	Positive
1	2	Classroom 206 Storage	W2	Plaster	Tan	None	0	8.8	Positive
1	2	Classroom 206 Storage	W3	Plaster	Tan	None	0	8.4	Positive
1	2	Classroom 206 Storage	W4	Plaster	Tan	None	0	9.7	Positive
1	2	Classroom 206 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206 Storage	Ceiling	Plaster	Tan	None	0	9.9	Positive
1	2	Classroom 207	W1	Plaster	Tan	Cracking	2	10.1	Positive
1	2	Classroom 207	W2	Plaster	Orange	None	0	9.6	Positive
1	2	Classroom 207	W3	Plaster	Tan	Flaking	8	8.2	Positive
1	2	Classroom 207	Radiator Cover	Metal	White	None	0	0.1	Negative
1	2	Classroom 207	W4	Sheetrock	Tan	None	0	0	Negative
1	2	Classroom 207	Baseboard	Wood	Brown	None	0	0	Negative
1	2	Classroom 207	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	2	Classroom 207	Ceiling	Plaster	White	Cracking	100	9.2	Positive
1	2	Classroom 207 Storage	W1	Plaster	Tan	None	0	8.9	Positive
1	2	Classroom 207 Storage	W2	Plaster	Tan	None	0	10.5	Positive
1	2	Classroom 207 Storage	W3	Plaster	Tan	Cracking	1	8.5	Positive
1	2	Classroom 207 Storage	W4	Plaster	Tan	None	0	8.9	Positive
1	2	Classroom 207 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 207 Storage	Ceiling	Plaster	Tan	None	0	10.2	Positive
1	2	Boy's Restroom next to Classroom 207	W1	Plaster	Tan	Cracking	2	7.1	Positive
1	2	Boy's Restroom next to Classroom 207	Door	Wood	Brown	Chipping	1	0	Negative
1	2	Boy's Restroom next to Classroom 207	Door Frame	Wood	Brown	Cracking	1	0	Negative
1	2	Boy's Restroom next to Classroom 207	W2	Plaster	Tan	None	0	6.8	Positive
1	2	Boy's Restroom next to Classroom 207	Radiator	Metal	Brown	None	0	0.1	Negative
1	2	Boy's Restroom next to Classroom 207	W3	Sheetrock	Tan	None	0	0	Negative
1	2	Boy's Restroom next to Classroom 207	Vertical Pipe	Metal	White	Flaking	5	4.3	Positive
1	2	Boy's Restroom next to Classroom 207	W4	Plaster	Tan	None	0	7.3	Positive
1	2	Boy's Restroom next to Classroom 207	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom next to Classroom 207	Ceiling	Concrete	White	Chipping	4	6.5	Positive
1	2	Stairwel Next to Boy's Restroom	Ceiling	Plaster	White	None	0	8.7	Positive
1	2	Stairwel Next to Boy's Restroom	Door	Metal	Brown	Chipping	1	0.1	Negative
1	2	Stairwel Next to Boy's Restroom	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	2	Stairwel Next to Boy's Restroom	W2	Plaster	Tan	None	0	6.4	Positive
1	2	Stairwel Next to Boy's Restroom	Stringer	Concrete	Brown	None	0	6.2	Positive
1	2	Stairwel Next to Boy's Restroom	Step	Concrete	Brown	Chipping	2	0.8	Positive
1	2	Stairwel Next to Boy's Restroom	Riser	Concrete	Brown	Flaking	1	3.3	Positive
1	2	Stairwel Next to Boy's Restroom	Radiator Cover	Metal	White	None	0	0	Negative
1	2	Stairwel Next to Boy's Restroom	W3	Plaster	Tan	Flaking	6	4.3	Positive
1	2	Stairwel Next to Boy's Restroom	Window Frame	Wood	Brown	Flaking	1	0	Negative
1	2	Stairwel Next to Boy's Restroom	W4	Plaster	Tan	Cracking	2	4.5	Positive
1	2	Classroom 208	W1	Plaster	Tan	Cracking	2	10.6	Positive
1	2	Classroom 208	W2	Plaster	Tan	Flaking	12	8.6	Positive
1	2	Classroom 208	Radiator	Metal	White	Flaking	1	0.1	Negative
1	2	Classroom 208	W3	Plaster	Tan	Flaking	6	8.8	Positive
1	2	Classroom 208	Radiator	Metal	White	None	0	0	Negative
1	2	Classroom 208	W4	Plaster	Orange	Cracking	1	8.6	Positive
1	2	Classroom 208	Baseboard	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 208	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	Ceiling	Plaster	White	Flaking	225	9.7	Positive
1	2	Classroom 208A Storage	W1	Plaster	Tan	Flaking	3	7.9	Positive
1	2	Classroom 208A Storage	Radiator	Metal	White	Chipping	1	0.2	Negative
1	2	Classroom 208A Storage	W2	Plaster	Tan	Cracking	3	9.3	Positive
1	2	Classroom 208A Storage	Vertical Pipe	Metal	White	Flaking	2	5.1	Positive
1	2	Classroom 208A Storage	W3	Plaster	Tan	None	0	8	Positive
1	2	Classroom 208A Storage	W4	Plaster	Tan	None	0	9.6	Positive
1	2	Classroom 208A Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	2	Classroom 208A Storage	Ceiling	Plaster	Tan	Cracking	4	8.9	Positive
1	2	Classroom 209	W1	Plaster	Tan	Flaking	3	9.1	Positive
1	2	Classroom 209	W2	Plaster	Tan	Flaking	2	8.6	Positive
1	2	Classroom 209	W3	Plaster	Tan	Flaking	18	10.1	Positive
1	2	Classroom 209	Radiator Cover	Metal	White	None	0	0	Negative
1	2	Classroom 209	W4	Plaster	Orange	None	0	8.9	Positive
1	2	Classroom 209	Baseboard	Wood	Brown	None	0	0	Negative
1	2	Classroom 209	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	Ceiling	Plaster	White	Flaking	275	10.6	Positive
1	2	Classroom 209A Storage	W1	Plaster	Tan	None	0	7.9	Positive
1	2	Classroom 209A Storage	W2	Plaster	Tan	Cracking	2	2.6	Positive
1	2	Classroom 209A Storage	W3	Plaster	Tan	None	0	8.7	Positive
1	2	Classroom 209A Storage	W4	Plaster	Tan	None	0	10.4	Positive
1	2	Classroom 209A Storage	Floor Storage	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209A Storage	Ceiling	Plaster	Tan	None	0	9.8	Positive
1	2	Faculty Lounge	W1	Plaster	Tan	Cracking	3	3.5	Positive
1	2	Faculty Lounge	W2	Plaster	Tan	Cracking	1	2.8	Positive
1	2	Faculty Lounge	W3	Plaster	Tan	Flaking	16	8.8	Positive
1	2	Faculty Lounge	Radiator	Metal	Brown	None	0	0	Negative
1	2	Faculty Lounge	Window Sill	Wood	Brown	None	0	0	Negative
1	2	Faculty Lounge	Window Sill	Wood	Brown	Flaking	1	0.2	Negative
1	2	Faculty Lounge	W4	Plaster	Tan	Flaking	3	9.8	Positive
1	2	Faculty Lounge	Baseboard	Wood	Brown	None	0	0	Negative
1	2	Faculty Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Faculty Lounge	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Faculty Lounge	Ceiling	Plaster	White	Flaking	500	10.1	Positive
1	2	Faculty Lounge Restroom	W1	Sheetrock	White	None	0	0	Negative
1	2	Faculty Lounge Restroom	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	2	Faculty Lounge Restroom	W2	Sheetrock	White	None	0	0	Negative
1	2	Faculty Lounge Restroom	W3	Sheetrock	White	Cracking	4	0	Negative
1	2	Faculty Lounge Restroom	W4	Sheetrock	White	Cracking	3	0	Negative
1	2	Faculty Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Faculty Lounge Restroom	Ceiling	Plaster	Tan	Cracking	1	11.1	Positive
1	2	Nurse's Office next to Classroom 210	Door Frame (W1)	Metal	Brown	Flaking	3	3.8	Positive
1	2	Nurse's Office next to Classroom 210	Door	Wood	Brown	Flaking	2	4.1	Positive
1	2	Nurse's Office next to Classroom 210	Radiator	Metal	Silver	Chipping	3	0.1	Negative
1	2	Nurse's Office next to Classroom 210	Window Frame (W2)	Wood	Brown	Cracking	2	5.3	Positive
1	2	Nurse's Office next to Classroom 210	Radiator	Metal	Silver	None	0	0	Negative
1	2	Nurse's Office next to Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Nurse's Office next to Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Nurse's Office next to Classroom 210	Ceiling	Plaster	White	Flaking	320	9.4	Positive
1	2	Nurse's Office Restroom	W1	Plaster	White	Cracking	1	3.1	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	2	Nurse's Office Restroom	W2	Plaster	White	None	0	6.8	Positive
1	2	Nurse's Office Restroom	Vertical Pipe	Metal	Tan	Flaking	3	7.9	Positive
1	2	Nurse's Office Restroom	W3	Plaster	White	Cracking	2	1.6	Positive
1	2	Nurse's Office Restroom	W4	Plaster	White	None	0	1.1	Positive
1	2	Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Nurse's Office Restroom	Ceiling	Plaster	White	Cracking	1	6.8	Positive
1	2	Hallway at Classrooms 200 to 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway at Classrooms 200 to 203	Ceiling	Plaster	White	Flaking	175	8	Positive
1	2	Hallway at Classrooms 200 to 203	W1	Plaster	Tan	Flaking	9	9.6	Positive
1	2	Hallway at Classrooms 200 to 203	W2	Plaster	Tan	Flaking	6	6.3	Positive
1	2	Hallway at Classrooms 200 to 203	Baseboard	Concrete	Brown	None	0	4.5	Positive
1	2	Hallway at Classrooms 204 to 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway at Classrooms 204 to 207	Ceiling	Plaster	White	Flaking	375	9.4	Positive
1	2	Hallway at Classrooms 204 to 207	W1	Plaster	Tan	Flaking	125	8.9	Positive
1	2	Hallway at Classrooms 204 to 207	Electrical Panel	Metal	Brown	Chipping	1	0.5	Negative
1	2	Hallway at Classrooms 204 to 207	W2	Plaster	Tan	Flaking	42	5.6	Positive
1	2	Hallway at Classrooms 204 to 207	Baseboard	Concrete	Brown	None	0	1.4	Positive
1	2	Hallway at Classrooms 204 to 207	Radiator Cover	Metal	White	None	0	0	Negative
1	2	Hallway at Classrooms 208 to 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway at Classrooms 208 to 210	Ceiling	Plaster	White	Flaking	215	8.9	Positive
1	2	Hallway at Classrooms 208 to 210	W1	Plaster	Tan	Cracking	3	9.1	Positive
1	2	Hallway at Classrooms 208 to 210	W2	Plaster	Tan	Flaking	6	9.2	Positive
1	2	Hallway at Classrooms 208 to 210	Vertical Pipe	Metal	White	Chipping	1	8.7	Positive
1	2	Hallway at Classrooms 208 to 210	Vertical Pipe	Metal	Brown	Chipping	1	7.5	Positive
1	2	Hallway at Classrooms 208 to 210	Baseboard	Concrete	Brown	None	0	4.3	Positive
1	2	Hallway at Classrooms 208 to 210	Radiator Cover	Metal	White	None	0	0	Negative
1	3	Classroom 300	W1	Plaster	Blue	Flaking	9	8.8	Positive
1	3	Classroom 300	Conduit	Metal	Blue	None	0	0	Negative
1	3	Classroom 300	W2	Plaster	Tan	Flaking	7	6.3	Positive
1	3	Classroom 300	Conduit	Metal	Tan	None	0	0.4	Negative
1	3	Classroom 300	Radiator	Metal	White	None	0	0.1	Negative
1	3	Classroom 300	W3	Plaster	Tan	Flaking	12	4.8	Positive
1	3	Classroom 300	Radiator	Metal	White	None	0	0	Negative
1	3	Classroom 300	W4	Plaster	Tan	Flaking	10	7.4	Positive
1	3	Classroom 300	Baseboard	Wood	Brown	None	0	0	Negative
1	3	Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 300	Ceiling	Plaster	White	Flaking	600	9.4	Positive
1	3	Classroom 300 Storage	W1	Plaster	Tan	Flaking	6	1	Positive
1	3	Classroom 300 Storage	W2	Plaster	Tan	Cracking	2	8	Positive
1	3	Classroom 300 Storage	W3	Plaster	Tan	Flaking	3	10	Positive
1	3	Classroom 300 Storage	W4	Plaster	White	Flaking	8	7.3	Positive
1	3	Classroom 300 Storage	Radiator	Metal	White	Chipping	1	0.1	Negative
1	3	Classroom 300 Storage	Vertical Pipe	Metal	White	Cracking	2	7	Positive
1	3	Classroom 300 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	3	Classroom 300 Storage	Ceiling	Plaster	Tan	Efflorescence	18	6.5	Positive
1	3	Classroom 300 Restroom	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 300 Restroom	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 300 Restroom	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 300 Restroom	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 300 Restroom	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 300 Restroom	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Staff Restroom outside Classroom 300	Window Frame (W4)	Wood	Brown	Chipping	1	0.1	Negative
1	3	Staff Restroom outside Classroom 300	Radiator (W4)	Metal	White	None	0	0	Negative
1	3	Staff Restroom outside Classroom 300	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	3	Staff Restroom outside Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Staff Restroom outside Classroom 300	Ceiling	Plaster	Green	Flaking	50	8.4	Positive
1	3	Classroom 301	W1	Plaster	Tan	Flaking	16	9.3	Positive
1	3	Classroom 301	Conduit	Metal	Tan	None	0	9.2	Positive
1	3	Classroom 301	W2	Plaster	Tan	Flaking	25	5.6	Positive
1	3	Classroom 301	Radiator	Metal	White	None	0	0.1	Negative
1	3	Classroom 301	W3	Plaster	Tan	Flaking	12	7.6	Positive
1	3	Classroom 301	Radiator	Metal	White	None	0	0.2	Negative
1	3	Classroom 301	W4	Plaster	Blue	Flaking	6	7.7	Positive
1	3	Classroom 301	Conduit	Metal	Blue	None	0	0.1	Negative
1	3	Classroom 301	Baseboard	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 301	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301	Ceiling	Plaster	White	Flaking	375	9.3	Positive
1	3	Classroom 301 Storage	W1	Plaster	Tan	None	0	4.5	Positive
1	3	Classroom 301 Storage	W2	Plaster	Tan	None	0	6.2	Positive
1	3	Classroom 301 Storage	W3	Plaster	Tan	None	0	3.9	Positive
1	3	Classroom 301 Storage	W4	Plaster	Tan	None	0	5.4	Positive
1	3	Classroom 301 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301 Storage	Ceiling	Plaster	Tan	None	0	8.4	Positive
1	3	Classroom 302	W1	Plaster	Tan	None	0	10.3	Positive
1	3	Classroom 302	W1	Plaster	Blue	Flaking	4	7.5	Positive
1	3	Classroom 302	Conduit	Metal	Tan	None	0	8.8	Positive
1	3	Classroom 302	Conduit	Metal	Blue	None	0	0.1	Negative
1	3	Classroom 302	W2	Plaster	Tan	Flaking	2	7.6	Positive
1	3	Classroom 302	W3	Plaster	Tan	Flaking	6	8.1	Positive
1	3	Classroom 302	Radiator	Metal	White	None	0	0	Negative
1	3	Classroom 302	W4	Plaster	Tan	Flaking	2	9.5	Positive
1	3	Classroom 302	Baseboard	Wood	Brown	None	0	0	Negative
1	3	Classroom 302	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 302	Ceiling	Plaster	White	Flaking	225	9.4	Positive
1	3	Classroom 302 Storage	W1	Plaster	Tan	None	0	9	Positive
1	3	Classroom 302 Storage	W2	Plaster	Tan	None	0	7.6	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	3	Classroom 302 Storage	W3	Plaster	Tan	None	0	8.4	Positive
1	3	Classroom 302 Storage	W4	Plaster	Tan	None	0	8.6	Positive
1	3	Classroom 302 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 302 Storage	Ceiling	Plaster	Tan	None	0	9.3	Positive
1	3	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 303	Ceiling	Plaster	White	Flaking	200	8.4	Positive
1	3	Classroom 303	W1	Plaster	Tan	None	0	10	Positive
1	3	Classroom 303	W1	Plaster	Blue	Flaking	4	10.6	Positive
1	3	Classroom 303	Blackboard Ledge	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 303	W2	Plaster	Tan	Flaking	6	4.5	Positive
1	3	Classroom 303	Radiator	Metal	White	Flaking	2	0.2	Negative
1	3	Classroom 303	W3	Plaster	Tan	Flaking	8	8.2	Positive
1	3	Classroom 303	Radiator	Metal	White	Flaking	2	0.6	Negative
1	3	Classroom 303	Window Sill	Brick	Brown	None	0	0	Negative
1	3	Classroom 303	W4	Plaster	Tan	Flaking	1	9.5	Positive
1	3	Classroom 303	Vertical Pipe	Metal	White	None	0	9	Positive
1	3	Classroom 303	Conduit	Metal	White	None	0	0	Negative
1	3	Classroom 303	Conduit	Metal	Blue	None	0	0	Negative
1	3	Classroom 303	Baseboard	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 303 Storage	Ceiling	Plaster	Tan	Cracking	3	10.2	Positive
1	3	Classroom 303 Storage	W1	Plaster	Tan	None	0	9.2	Positive
1	3	Classroom 303 Storage	W2	Plaster	Tan	Cracking	2	7.9	Positive
1	3	Classroom 303 Storage	W3	Plaster	Tan	None	0	9.9	Positive
1	3	Classroom 303 Storage	Window Frame	Wood	Brown	Cracking	1	0.2	Negative
1	3	Classroom 303 Storage	Radiator	Metal	White	None	0	0.1	Negative
1	3	Classroom 303 Storage	Vertical Pipe	Metal	White	None	0	0.2	Negative
1	3	Classroom 303 Storage	W4	Plaster	Tan	None	0	9.2	Positive
1	3	Classroom 304	W1	Plaster	Tan	Flaking	6	7.2	Positive
1	3	Classroom 304	Conduit	Metal	Tan	None	0	0.1	Negative
1	3	Classroom 304	W2	Sheetrock	Tan	Flaking	4	0	Negative
1	3	Classroom 304	W3	Plaster	Tan	Flaking	30	3.3	Positive
1	3	Classroom 304	Radiator	Metal	White	None	0	0.1	Negative
1	3	Classroom 304	W4	Plaster	Blue	Flaking	12	10.3	Positive
1	3	Classroom 304	Baseboard	Wood	Brown	None	0	0	Negative
1	3	Classroom 304	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 304	Ceiling	Plaster	White	Flaking	500	7	Positive
1	3	Classroom 304 Storage	W1	Plaster	Tan	Cracking	5	6.9	Positive
1	3	Classroom 304 Storage	W2	Plaster	Tan	None	0	9.1	Positive
1	3	Classroom 304 Storage	W3	Plaster	Tan	None	0	7.8	Positive
1	3	Classroom 304 Storage	W4	Plaster	Tan	None	0	8	Positive
1	3	Classroom 304 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 304 Storage	Ceiling	Plaster	Tan	None	0	8.9	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	3	Girl's Restroom next to Classroom 304	W1	Sheetrock	White	None	0	0	Negative
1	3	Girl's Restroom next to Classroom 304	W2	Sheetrock	White	None	0	0	Negative
1	3	Girl's Restroom next to Classroom 304	W3	Sheetrock	White	None	0	0	Negative
1	3	Girl's Restroom next to Classroom 304	Vertical Pipe	Metal	White	Flaking	3	0.4	Negative
1	3	Girl's Restroom next to Classroom 304	W4	Sheetrock	White	None	0	14.3	Positive
1	3	Girl's Restroom next to Classroom 304	Window Trim	Wood	Brown	None	0	0	Negative
1	3	Girl's Restroom next to Classroom 304	Radiator	Metal	Brown	None	0	0	Negative
1	3	Girl's Restroom next to Classroom 304	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	3	Girl's Restroom next to Classroom 304	Ceiling	Plaster	White	None	0	5.2	Positive
1	3	Stairwell next to Girl's Restroom	Ceiling	Plaster	White	None	0	8.9	Positive
1	3	Stairwell next to Girl's Restroom	Door	Metal	Brown	Chipping	1	0.1	Negative
1	3	Stairwell next to Girl's Restroom	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	3	Stairwell next to Girl's Restroom	W2	Plaster	Tan	None	0	6.9	Positive
1	3	Stairwell next to Girl's Restroom	Stringer	Concrete	Brown	Chipping	1	7	Positive
1	3	Stairwell next to Girl's Restroom	Step	Concrete	Brown	None	0	0.2	Negative
1	3	Stairwell next to Girl's Restroom	Riser	Concrete	Brown	None	0	4.4	Positive
1	3	Stairwell next to Girl's Restroom	Newel Post	Metal	Brown	Flaking	1	3.6	Positive
1	3	Stairwell next to Girl's Restroom	W3	Plaster	Tan	Flaking	1	4.1	Positive
1	3	Stairwell next to Girl's Restroom	Window Frame	Wood	Brown	None	0	0.2	Negative
1	3	Stairwell next to Girl's Restroom	W4	Plaster	Tan	None	0	7.5	Positive
1	3	Stairwell next to Girl's Restroom	Radiator Cover	Metal	White	None	0	0.6	Positive
1	3	Classroom 305	W1	Plaster	Tan	Flaking	4	8.7	Positive
1	3	Classroom 305	Conduit	Metal	Tan	None	0	0.2	Negative
1	3	Classroom 305	W1	Plaster	Blue	Flaking	8	9.6	Positive
1	3	Classroom 305	Conduit	Metal	Blue	Chipping	2	0	Negative
1	3	Classroom 305	W2	Sheetrock	Tan	Flaking	9	0	Negative
1	3	Classroom 305	W3	Plaster	Tan	Flaking	18	2.2	Positive
1	3	Classroom 305	Radiator Cover	Metal	White	None	0	0.3	Negative
1	3	Classroom 305	W4	Sheetrock	Tan	Flaking	5	0	Negative
1	3	Classroom 305	Baseboard	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 305	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 305	Ceiling	Plaster	White	Flaking	600	7.1	Positive
1	3	Classroom 305 Storage	W1	Plaster	Tan	None	0	9.6	Positive
1	3	Classroom 305 Storage	W2	Plaster	Tan	Flaking	1	9.1	Positive
1	3	Classroom 305 Storage	W3	Plaster	Tan	None	0	9.9	Positive
1	3	Classroom 305 Storage	W4	Plaster	Tan	None	0	8.9	Positive
1	3	Classroom 305 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 305 Storage	Ceiling	Plaster	White	Cracking	1	9.9	Positive
1	3	Classroom 306	W1	Plaster	Tan	Cracking	3	9.7	Positive
1	3	Classroom 306	Conduit	Metal	Tan	None	0	0.1	Negative
1	3	Classroom 306	W1	Plaster	Blue	Flaking	5	5.2	Positive
1	3	Classroom 306	Conduit	Metal	Blue	None	0	0	Negative
1	3	Classroom 306	W2	Wood	White	Flaking	2	0	Negative
1	3	Classroom 306	W3	Plaster	Tan	Flaking	16	16	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	3	Classroom 306	Radiator	Metal	White	None	0	0	Negative
1	3	Classroom 306	Window Frame	Wood	Brown	None	0	0.3	Negative
1	3	Classroom 306	W4	Sheetrock	Tan	Flaking	4	0	Negative
1	3	Classroom 306	Baseboard	Wood	Brown	None	0	0.2	Negative
1	3	Classroom 306	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 306	Ceiling	Plaster	White	Flaking	250	8.3	Positive
1	3	Classroom 306 Storage	W1	Plaster	Tan	None	0	8.7	Positive
1	3	Classroom 306 Storage	W2	Plaster	Tan	None	0	8.7	Positive
1	3	Classroom 306 Storage	W3	Plaster	Tan	None	0	9.2	Positive
1	3	Classroom 306 Storage	W4	Plaster	Tan	None	0	8.4	Positive
1	3	Classroom 306 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 306 Storage	Ceiling	Plaster	White	None	0	8.9	Positive
1	3	Classroom 307	W1	Plaster	Tan	Flaking	2	6.3	Positive
1	3	Classroom 307	Conduit	Metal	Tan	None	0	0	Negative
1	3	Classroom 307	W2	Plaster	Blue	None	0	6.6	Positive
1	3	Classroom 307	Conduit	Metal	Blue	None	0	0	Negative
1	3	Classroom 307	W3	Plaster	Tan	Flaking	8	2.1	Positive
1	3	Classroom 307	Radiator	Metal	White	None	0	0.2	Negative
1	3	Classroom 307	W4	Wood	White	None	0	0	Negative
1	3	Classroom 307	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 307	Ceiling	Plaster	White	Flaking	100	7.9	Positive
1	3	Classroom 307 Storage	W1	Plaster	Tan	None	0	7.2	Positive
1	3	Classroom 307 Storage	W2	Plaster	Tan	None	0	13.4	Positive
1	3	Classroom 307 Storage	W3	Plaster	Tan	Cracking	1	8.3	Positive
1	3	Classroom 307 Storage	W4	Plaster	Tan	None	0	12.1	Positive
1	3	Classroom 307 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 307 Storage	Ceiling	Plaster	White	Flaking	100	7.9	Positive
1	3	Boy's Restroom next to Classroom 307	W1	Plaster	White	None	0	5.4	Positive
1	3	Boy's Restroom next to Classroom 307	W2	Plaster	White	None	0	4.9	Positive
1	3	Boy's Restroom next to Classroom 307	W3	Plaster	White	None	0	5.2	Positive
1	3	Boy's Restroom next to Classroom 307	Vertical Pipe	Metal	White	Chipping	2	3.1	Positive
1	3	Boy's Restroom next to Classroom 307	W4	Plaster	Tan	None	0	5	Positive
1	3	Boy's Restroom next to Classroom 307	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom next to Classroom 307	Ceiling	Plaster	White	Flaking	2	4.1	Positive
1	3	Stairwell next to Boy's Restroom	Ceiling	Plaster	White	Cracking	5	6.9	Positive
1	3	Stairwell next to Boy's Restroom	Door	Metal	Brown	Chipping	1	0.1	Negative
1	3	Stairwell next to Boy's Restroom	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	3	Stairwell next to Boy's Restroom	W2	Plaster	Tan	None	0	7.2	Positive
1	3	Stairwell next to Boy's Restroom	Newel Post	Metal	Brown	None	0	7.7	Positive
1	3	Stairwell next to Boy's Restroom	W4	Plaster	Tan	None	0	7.3	Positive
1	3	Custodial Closet in Hallway outside Boy's Restroom	W1	Sheetrock	Tan	Cracking	2	0.1	Negative
1	3	Custodial Closet in Hallway outside Boy's Restroom	W2	Sheetrock	Tan	None	0	0.1	Negative
1	3	Custodial Closet in Hallway outside Boy's Restroom	W3	Sheetrock	Tan	None	0	0.1	Negative

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	3	Custodial Closet in Hallway outside Boy's Restroom	W4	Sheetrock	Tan	None	0	0.1	Negative
1	3	Custodial Closet in Hallway outside Boy's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet in Hallway outside Boy's Restroom	Ceiling	Plaster	White	Flaking	8	4.1	Positive
1	3	Classroom 308	W1	Plaster	Tan	Cracking	7	9.5	Positive
1	3	Classroom 308	Conduit	Metal	Tan	None	0	0.1	Negative
1	3	Classroom 308	W2	Plaster	Tan	Cracking	35	8.9	Positive
1	3	Classroom 308	Radiator	Metal	Grey	None	0	0.1	Negative
1	3	Classroom 308	Vertical Pipe	Metal	Tan	Cracking	1	0.7	Positive
1	3	Classroom 308	W3	Plaster	Tan	Flaking	12	8.5	Positive
1	3	Classroom 308	W4	Plaster	Blue	Flaking	9	8.2	Positive
1	3	Classroom 308	Baseboard	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 308	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 308	Ceiling	Plaster	White	Flaking	275	10.2	Positive
1	3	Classroom 308 Storage	W1	Plaster	Tan	Cracking	1	9.2	Positive
1	3	Classroom 308 Storage	Vertical Pipe	Metal	Tan	None	0	0.8	Positive
1	3	Classroom 308 Storage	Radiator	Metal	White	Chipping	1	1.1	Positive
1	3	Classroom 308 Storage	W2	Plaster	Tan	None	0	9.2	Positive
1	3	Classroom 308 Storage	W3	Plaster	Tan	None	0	9.4	Positive
1	3	Classroom 308 Storage	W4	Plaster	Tan	Cracking	1	10.2	Positive
1	3	Classroom 308 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 308 Storage	Ceiling	Plaster	Tan	None	0	8.5	Positive
1	3	Classroom 309	W1	Plaster	Tan	Cracking	1	8.6	Positive
1	3	Classroom 309	W1	Plaster	Blue	Cracking	2	8.5	Positive
1	3	Classroom 309	W2	Plaster	Tan	Cracking	1	7.9	Positive
1	3	Classroom 309	W3	Plaster	Tan	Flaking	24	7.9	Positive
1	3	Classroom 309	Radiator Cover	Metal	White	None	0	0	Negative
1	3	Classroom 309	W4	Plaster	Tan	Flaking	3	8.6	Positive
1	3	Classroom 309	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 309	Baseboard	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 309	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 309	Ceiling	Plaster	White	Flaking	125	9.8	Positive
1	3	Classroom 309 Storage	W1	Plaster	Tan	None	0	8.1	Positive
1	3	Classroom 309 Storage	W2	Plaster	Tan	None	0	8.8	Positive
1	3	Classroom 309 Storage	W3	Plaster	Tan	None	0	8.7	Positive
1	3	Classroom 309 Storage	Vertical Pipe	Metal	White	None	0	0.4	Negative
1	3	Classroom 309 Storage	W4	Plaster	Tan	None	0	8.9	Positive
1	3	Classroom 309 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 309 Storage	Ceiling	Plaster	Tan	None	0	8.7	Positive
1	3	Classroom 310	W1	Plaster	Tan	Flaking	5	3	Positive
1	3	Classroom 310	W2	Plaster	Tan	Flaking	12	7.2	Positive
1	3	Classroom 310	Radiator	Metal	White	None	0	0	Negative
1	3	Classroom 310	W3	Plaster	Tan	Flaking	8	6.9	Positive
1	3	Classroom 310	Radiator	Metal	White	Chipping	2	0.2	Positive
1	3	Classroom 310	W4	Plaster	Blue	Flaking	6	9.2	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	3	Classroom 310	Baseboard	Wood	Brown	None	0	0	Negative
1	3	Classroom 310	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 310	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 310	Ceiling	Plaster	White	Flaking	600	9.3	Positive
1	3	Classroom 310 Storage	W1	Plaster	Tan	None	0	10.1	Positive
1	3	Classroom 310 Storage	W2	Plaster	Tan	None	0	9.9	Positive
1	3	Classroom 310 Storage	Vertical Pipe	Metal	White	Flaking	4	2.6	Positive
1	3	Classroom 310 Storage	W3	Plaster	Tan	Flaking	2	8.6	Positive
1	3	Classroom 310 Storage	Radiator	Metal	White	Chipping	1	2.7	Positive
1	3	Classroom 310 Storage	W4	Plaster	Tan	None	0	9.2	Positive
1	3	Classroom 310 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 310 Storage	Ceiling	Plaster	White	Flaking	1	9.5	Positive
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Office next to Classroom 310 (used as Book Room)	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Hallway at Classrooms 300 to 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway at Classrooms 300 to 303	Ceiling	Plaster	White	Flaking	210	9.1	Positive
1	3	Hallway at Classrooms 304 to 307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway at Classrooms 304 to 307	Ceiling	Plaster	White	Flaking	197	8.1	Positive
1	3	Hallway at Classrooms 304 to 307	W1	Plaster	Tan	None	0	8	Positive
1	3	Hallway at Classrooms 304 to 307	Conduit	Metal	Tan	None	0	0	Negative
1	3	Hallway at Classrooms 304 to 307	Electrical Panel	Metal	Brown	None	0	0.7	Positive
1	3	Hallway at Classrooms 304 to 307	W2	Plaster	Tan	Cracking	3	5.4	Positive
1	3	Hallway at Classrooms 304 to 307	Radiator Cover	Metal	White	None	0	0	Negative
1	3	Hallway at Classrooms 304 to 307	Baseboard	Concrete	Brown	None	0	2.4	Positive
1	3	Fire Tower near Hallway H32	Ceiling	Concrete	White	Cracking	12	0.6	Negative
1	3	Fire Tower near Hallway H32	W1	Brick	White	Flaking	1	7.1	Positive
1	3	Fire Tower near Hallway H32	Baseboard	Concrete	Brown	None	0	0.2	Negative
1	3	Fire Tower near Hallway H32	Door	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H32	Door Frame	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H32	W2	Brick	White	Flaking	7	7.6	Positive
1	3	Fire Tower near Hallway H32	Handrail	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H32	W3	Brick	White	None	0	5.2	Positive
1	3	Fire Tower near Hallway H32	Window Frame	Metal	Brown	Chipping	2	5.7	Positive
1	3	Fire Tower near Hallway H32	W4	Brick	White	None	0	2.2	Positive
1	3	Fire Tower near Hallway H32	Vertical Pipe	Metal	White	Flaking	6	6.8	Positive
1	3	Fire Tower near Hallway H32	Vertical Pipe	Metal	Brown	None	0	0.2	Negative
1	3	Fire Tower near Hallway H32	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower near Hallway H32	Step	Metal	Brown	Cracking	1	0	Negative

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	3	Fire Tower near Hallway H32	Riser	Concrete	Brown	Flaking	2	1.1	Positive
1	3	Fire Tower near Hallway H23	Ceiling	Concrete	White	Flaking	3	1.1	Positive
1	3	Fire Tower near Hallway H23	W1	Brick	White	Flaking	6	7.1	Positive
1	3	Fire Tower near Hallway H23	Baseboard	Concrete	Brown	None	0	0.2	Negative
1	3	Fire Tower near Hallway H23	Door	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H23	Door Frame	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H23	W2	Brick	White	Flaking	7	7.6	Positive
1	3	Fire Tower near Hallway H23	Handrail	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H23	W3	Brick	White	None	0	5.2	Positive
1	3	Fire Tower near Hallway H23	Window Frame	Metal	Brown	Chipping	2	5.4	Positive
1	3	Fire Tower near Hallway H23	W4	Brick	White	None	0	2.2	Positive
1	3	Fire Tower near Hallway H23	Vertical Pipe	Metal	White	Flaking	6	6.8	Positive
1	3	Fire Tower near Hallway H23	Vertical Pipe	Metal	Brown	None	0	0.2	Negative
1	3	Fire Tower near Hallway H23	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower near Hallway H23	Step	Metal	Brown	Cracking	1	0	Negative
1	3	Fire Tower near Hallway H23	Riser	Concrete	Brown	Flaking	2	1.1	Positive
1	3	Fire Tower near Hallway H12	Ceiling	Concrete	White	Cracking	5	1.1	Positive
1	3	Fire Tower near Hallway H12	W1	Brick	White	Flaking	1	7.1	Positive
1	3	Fire Tower near Hallway H12	Baseboard	Concrete	Brown	None	0	0.2	Negative
1	3	Fire Tower near Hallway H12	Door	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H12	Door Frame	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H12	W2	Brick	White	Flaking	7	7.6	Positive
1	3	Fire Tower near Hallway H12	Handrail	Metal	Brown	None	0	0	Negative
1	3	Fire Tower near Hallway H12	W3	Brick	White	None	0	5.2	Positive
1	3	Fire Tower near Hallway H12	Window Frame	Metal	Brown	Chipping	2	5.6	Positive
1	3	Fire Tower near Hallway H12	W4	Brick	White	None	0	2.2	Positive
1	3	Fire Tower near Hallway H12	Vertical Pipe	Metal	White	Flaking	6	6.8	Positive
1	3	Fire Tower near Hallway H12	Vertical Pipe	Metal	Brown	None	0	0.2	Negative
1	3	Fire Tower near Hallway H12	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower near Hallway H12	Step	Metal	Brown	Cracking	1	0	Negative
1	3	Fire Tower near Hallway H12	Riser	Concrete	Brown	Flaking	2	1.1	Positive
1	3	Hallway at Classrooms 308 to 311	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway at Classrooms 308 to 311	Ceiling	Plaster	White	Flaking	55	8.7	Positive
1	3	Hallway at Classrooms 308 to 311	W1	Plaster	Tan	Cracking	2	3.7	Positive
1	3	Hallway at Classrooms 308 to 311	W2	Plaster	Tan	Flaking	8	8.2	Positive
1	3	Hallway at Classrooms 308 to 311	Vertical Pipe	Metal	White	Chipping	1	8.5	Positive
1	3	Hallway at Classrooms 308 to 311	Vertical Pipe	Metal	Brown	Chipping	1	7.6	Positive
1	3	Hallway at Classrooms 308 to 311	Baseboard	Concrete	Brown	None	0	2.4	Positive
1	3	Hallway at Classrooms 308 to 311	Radiator Cover	Metal	White	None	0	0	Negative
1	B	Boiler Room	Ceiling	Concrete	White	Flaking	1050	0	Negative
1	B	Boiler Room	Column	Concrete	White	Flaking	400	0	Negative
1	B	Boiler Room	W1	Brick	White	Flaking	325	4.8	Positive
1	B	Boiler Room	W1	Concrete	Grey	Flaking	175	2.5	Positive
1	B	Boiler Room	W1	Brick	Grey	Flaking	60	2.4	Positive
1	B	Boiler Room	Door Frame	Metal	Brown	Chipping	1	0	Negative

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Boiler Room	Door	Metal	Brown	Cracking	4	0	Negative
1	B	Boiler Room	Handrail	Metal	Black	Chipping	1	0.1	Negative
1	B	Boiler Room	Stringer	Metal	Brown	Flaking	6	5	Positive
1	B	Boiler Room	Step	Metal	Brown	Chipping	10	0.1	Negative
1	B	Boiler Room	W2	Brick	White	Flaking	352	9.5	Positive
1	B	Boiler Room	W2	Concrete	Grey	Flaking	120	8.3	Positive
1	B	Boiler Room	Window Frame	Metal	Grey	Flaking	25	6	Positive
1	B	Boiler Room	W3	Brick	White	Flaking	285	2.7	Positive
1	B	Boiler Room	W3	Concrete	Grey	Flaking	140	6.3	Positive
1	B	Boiler Room	Window Frame	Wood	Grey	Flaking	25	2	Positive
1	B	Boiler Room	W4	Brick	White	Flaking	576	10.8	Positive
1	B	Boiler Room	W4	Brick	Grey	Flaking	85	10.3	Positive
1	B	Boiler Room	Window Frame	Metal	Grey	Flaking	16	4	Positive
1	B	Boiler Room	Slider Door	Metal	Grey	Flaking	100	5.3	Positive
1	B	Boiler Room	Ductwork	Metal	White	Flaking	425	4.1	Positive
1	B	Boiler Room	Column	Concrete	White	Flaking	150	9.8	Positive
1	B	Boiler Room	Column	Concrete	White	Flaking	75	9.8	Positive
1	B	Boiler Room	Floor Pad	Concrete	Grey	Flaking	400	0.1	Negative
1	B	Fan Room	W1	Brick	White	Flaking	120	0.4	Negative
1	B	Fan Room	W1	Brick	Grey	Flaking	120	8.7	Positive
1	B	Fan Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Fan Room	Ductwork	Metal	White	Flaking	108	11.1	Positive
1	B	Fan Room	Ductwork	Metal	Grey	Flaking	85	10.5	Positive
1	B	Fan Room	Ductwork	Metal	Silver	Flaking	100	11.3	Positive
1	B	Fan Room	W3	Brick	White	Flaking	175	1.7	Positive
1	B	Fan Room	W3	Brick	Grey	Flaking	50	8.1	Positive
1	B	Fan Room	Slider Door	Metal	Grey	Flaking	100	11	Positive
1	B	Fan Room	W4	Brick	White	Flaking	185	6.3	Positive
1	B	Fan Room	W4	Brick	Grey	Flaking	125	7.8	Positive
1	B	Fan Room	Electrical Panel	Metal	Grey	Flaking	72	0.2	Negative
1	B	Fan Room	Ductwork	Metal	White	Flaking	200	3.9	Positive
1	B	Fan Room	Ceiling	Concrete	White	Flaking	500	0	Negative
1	B	Fan Room	Column	Concrete	White	Flaking	75	0	Negative
1	B	Fan Room	Floor	Concrete	Grey	Flaking	400	0.1	Negative
1	B	Gym Equipment Storage	Ceiling	Concrete	White	Flaking	220	4.5	Positive
1	B	Gym Equipment Storage	W1	Brick	White	None	0	4.3	Positive
1	B	Gym Equipment Storage	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Gym Equipment Storage	Door	Metal	Brown	None	0	0	Negative
1	B	Gym Equipment Storage	W2	Brick	White	Flaking	50	5.3	Positive
1	B	Gym Equipment Storage	Chair Rail	Wood	White	Flaking	25	0.1	Negative
1	B	Gym Equipment Storage	W3	Brick	White	Cracking	6	6.1	Positive
1	B	Gym Equipment Storage	Radiator	Metal	White	Chipping	1	0.9	Positive
1	B	Gym Equipment Storage	Window Frame	Wood	White	Flaking	4	0.4	Negative
1	B	Gym Equipment Storage	W4	Brick	White	Flaking	35	0.8	Positive
1	B	Gym Equipment Storage	Chair Rail	Wood	White	Flaking	6	0.2	Negative

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Gym Equipment Storage	Ductwork	Metal	White	Flaking	30	9.6	Positive
1	B	Hallway next to Fan Room	W1	Brick	White	Flaking	128	0.8	Positive
1	B	Hallway next to Fan Room	W1	Brick	Grey	Flaking	90	10.7	Positive
1	B	Hallway next to Fan Room	Slider Door	Metal	Grey	Flaking	100	10.9	Positive
1	B	Hallway next to Fan Room	W2	Brick	White	Flaking	155	7.1	Positive
1	B	Hallway next to Fan Room	W2	Brick	Grey	Flaking	75	8.3	Positive
1	B	Hallway next to Fan Room	W3	Brick	White	Flaking	36	1.3	Positive
1	B	Hallway next to Fan Room	W3	Brick	Grey	Flaking	10	8.6	Positive
1	B	Hallway next to Fan Room	W4	Brick	White	Flaking	136	4.1	Positive
1	B	Hallway next to Fan Room	W4	Brick	Grey	Flaking	80	8.8	Positive
1	B	Hallway next to Fan Room	Sink	Metal	Grey	Flaking	6	8.2	Positive
1	B	Hallway next to Fan Room	Ceiling	Concrete	White	Flaking	275	3.2	Positive
1	B	Hallway next to Fan Room	Column	Concrete	White	Flaking	40	0.8	Positive
1	B	Hallway next to Fan Room	Ductwork	Metal	White	Flaking	190	11.3	Positive
1	B	Custodial storage room next to Fan Room	W1	Brick	White	Flaking	95	4.3	Positive
1	B	Custodial storage room next to Fan Room	W1	Brick	Grey	Flaking	75	6.4	Positive
1	B	Custodial storage room next to Fan Room	Door Frame	Metal	Brown	Chipping	2	0	Negative
1	B	Custodial storage room next to Fan Room	Door	Metal	Brown	Chipping	4	0	Negative
1	B	Custodial storage room next to Fan Room	W2	Brick	White	Flaking	238	4.1	Positive
1	B	Custodial storage room next to Fan Room	W2	Concrete	Grey	Flaking	170	0.8	Positive
1	B	Custodial storage room next to Fan Room	Window Frame	Wood	Brown	Flaking	12	4.2	Positive
1	B	Custodial storage room next to Fan Room	W3	Brick	White	Flaking	130	3.6	Positive
1	B	Custodial storage room next to Fan Room	W3	Concrete	Grey	Flaking	85	0.9	Positive
1	B	Custodial storage room next to Fan Room	W3	Concrete	Grey	Flaking	12	0.4	Negative
1	B	Custodial storage room next to Fan Room	W4	Brick	White	Flaking	250	3.5	Positive
1	B	Custodial storage room next to Fan Room	W4	Brick	Grey	Flaking	125	0.7	Positive
1	B	Custodial storage room next to Fan Room	Ceiling	Concrete	White	Flaking	570	0	Negative
1	B	Custodial storage room next to Fan Room	Column	Concrete	White	Flaking	25	0	Negative
1	B	Custodial storage room next to Fan Room	Ductwork	Metal	White	Flaking	210	11	Positive
1	B	Custodial storage room next to Fan Room	Floor	Concrete	Grey	Flaking	500	0.4	Negative
1	B	Boiler Room Storage	W1	Brick	White	Flaking	210	0.1	Negative
1	B	Boiler Room Storage	W1	Brick	Grey	Flaking	190	0.2	Negative
1	B	Boiler Room Storage	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Boiler Room Storage	Door	Metal	Brown	Chipping	6	0	Negative
1	B	Boiler Room Storage	W2	Brick	White	Flaking	215	0.3	Negative
1	B	Boiler Room Storage	Window Frame	Wood	Grey	Flaking	6	0.9	Positive
1	B	Boiler Room Storage	W3	Brick	White	Flaking	275	0.1	Negative
1	B	Boiler Room Storage	W3	Concrete	Grey	Flaking	275	0	Negative
1	B	Boiler Room Storage	Window Frame	Wood	Brown	Flaking	6	0.8	Positive
1	B	Boiler Room Storage	W4	Brick	White	Flaking	150	0	Negative
1	B	Boiler Room Storage	W4	Brick	Grey	Flaking	120	0.1	Negative
1	B	Boiler Room Storage	Ductwork	Metal	White	Flaking	740	10.9	Positive
1	B	Boiler Room Storage	Column	Concrete	White	Cracking	4	0	Negative
1	B	Boiler Room Storage	Column	Concrete	Grey	Cracking	6	4.8	Positive
1	B	Gym	Ceiling	Plaster	Tan	Efflorescence	16	9.5	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Gym	Column	Plaster	Tan	Cracking	7	8.5	Positive
1	B	Gym	Ductwork	Metal	White	Flaking	18	5.2	Positive
1	B	Gym	W1	Brick	Tan	None	0	5.7	Positive
1	B	Gym	Radiator Cover	Metal	White	Chipping	3	0.1	Negative
1	B	Gym	Window Frame	Wood	Brown	None	0	0	Negative
1	B	Gym	Pipe Jacket	Metal	Brown	Chipping	2	0	Negative
1	B	Gym	W2	Brick	Tan	Cracking	1	5.6	Positive
1	B	Gym	Vertical Pipe	Metal	White	Chipping	1	2.7	Positive
1	B	Gym	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Gym	Door	Metal	Brown	None	0	0	Negative
1	B	Gym	W3	Brick	Tan	Cracking	6	5	Positive
1	B	Gym	Pipe Jacket	Metal	Brown	Chipping	1	3.5	Positive
1	B	Gym	W4	Brick	Tan	Cracking	1	2.5	Positive
1	B	Gym	Baseboard	Concrete	Brown	None	0	0.2	Negative
1	B	Gym	Vertical Pipe	Metal	White	Chipping	1	6	Positive
1	B	Gym	Column	Plaster	Tan	None	0	4.3	Positive
1	B	Gym	Tread Plate	Metal	Brown	Chipping	2	0.1	Negative
1	B	Gym Office	W1	Brick	White	None	0	5.1	Positive
1	B	Gym Office	Door	Metal	Brown	None	0	0	Negative
1	B	Gym Office	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Gym Office	W2	Brick	White	Cracking	2	4.3	Positive
1	B	Gym Office	W3	Brick	White	Efflorescence	4	3.5	Positive
1	B	Gym Office	Window Frame	Wood	Brown	Cracking	1	0.6	Negative
1	B	Gym Office	Radiator	Metal	White	Chipping	1	1.1	Positive
1	B	Gym Office	W4	Brick	White	Flaking	2	5.2	Positive
1	B	Gym Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gym Office	Ductwork	Metal	White	Chipping	8	7.8	Positive
1	B	Gym Office	Ceiling	Concrete	White	Flaking	6	5.3	Positive
1	B	Gym Storage	W1	Brick	White	None	0	5.1	Positive
1	B	Gym Storage	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Gym Storage	Door	Metal	Brown	None	0	0	Negative
1	B	Gym Storage	W2	Brick	White	Cracking	2	4.3	Positive
1	B	Gym Storage	W3	Brick	White	Efflorescence	4	3.5	Positive
1	B	Gym Storage	Window Frame	Wood	Brown	Cracking	1	0.6	Negative
1	B	Gym Storage	Radiator	Metal	White	Chipping	1	1.1	Positive
1	B	Gym Storage	W4	Brick	White	Flaking	2	5.2	Positive
1	B	Gym Storage	Ceiling	Concrete	White	Flaking	10	4.1	Positive
1	B	Gym Storage	Ductwork	Metal	White	Flaking	8	7.8	Positive
1	B	Hallway by Cafeteria and Girl's Restroom	W1	Brick	White	Flaking	2	0.8	Positive
1	B	Hallway by Cafeteria and Girl's Restroom	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Hallway by Cafeteria and Girl's Restroom	Door	Metal	Brown	Chipping	1	0	Negative
1	B	Hallway by Cafeteria and Girl's Restroom	W2	Brick	White	Flaking	3	2.5	Positive
1	B	Hallway by Cafeteria and Girl's Restroom	W3	Brick	White	Cracking	1	3.2	Positive
1	B	Hallway by Cafeteria and Girl's Restroom	W4	Brick	White	Cracking	1	1.5	Positive
1	B	Hallway by Cafeteria and Girl's Restroom	Ceiling	Concrete	White	Flaking	12	3.7	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Hallway by Cafeteria and Girl's Restroom	Ductwork	Metal	White	Flaking	5	2.8	Positive
1	B	Gym Closet	Ceiling	Concrete	White	Flaking	7	12.3	Positive
1	B	Gym Closet	W1	Brick	White	Flaking	3	11.1	Positive
1	B	Gym Closet	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Gym Closet	Door	Metal	Brown	Chipping	1	0	Negative
1	B	Gym Closet	W2	Brick	White	Cracking	1	11	Positive
1	B	Gym Closet	W3	Brick	White	None	0	12	Positive
1	B	Gym Closet	Shelf	Wood	White	Flaking	2	0	Negative
1	B	Gym Closet	W4	Brick	White	None	0	10.8	Positive
1	B	Gym Closet	Ceiling	Concrete	White	Cracking	2	9.3	Positive
1	B	Gym Closet	W1	Brick	White	None	0	10.6	Positive
1	B	Gym Closet	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Gym Closet	Door	Metal	Brown	None	0	0	Negative
1	B	Gym Closet	W2	Brick	White	Flaking	2	11.8	Positive
1	B	Gym Closet	W3	Brick	White	Flaking	4	10.1	Positive
1	B	Gym Closet	W4	Brick	White	Cracking	2	11.2	Positive
1	B	Gym Closet	Vertical Pipe	Metal	White	Flaking	6	9.3	Positive
1	B	Stairwell Next to Gym Closet	Ceiling	Plaster	Tan	Chipping	6	8.8	Positive
1	B	Stairwell Next to Gym Closet	W1	Plaster	Tan	None	0	8.9	Positive
1	B	Stairwell Next to Gym Closet	Door	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell Next to Gym Closet	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell Next to Gym Closet	Strand	Concrete	Brown	None	0	9.5	Positive
1	B	Stairwell Next to Gym Closet	W2	Plaster	Tan	None	0	9.1	Positive
1	B	Stairwell Next to Gym Closet	Stringer	Concrete	Brown	Flaking	1	9	Positive
1	B	Stairwell Next to Gym Closet	Step	Concrete	Brown	Chipping	1	0.7	Positive
1	B	Stairwell Next to Gym Closet	Riser	Concrete	Brown	Chipping	1	4.7	Positive
1	B	Stairwell Next to Gym Closet	W3	Plaster	Tan	None	0	7.9	Positive
1	B	Stairwell Next to Gym Closet	Door	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell Next to Gym Closet	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell Next to Gym Closet	W4	Plaster	Tan	Flaking	2	4.1	Positive
1	B	Hallway by Music Room and Boy's Restroom	Ceiling	Concrete	White	Flaking	270	8.2	Positive
1	B	Hallway by Music Room and Boy's Restroom	Ductwork	Metal	White	Flaking	25	7	Positive
1	B	Hallway by Music Room and Boy's Restroom	W2	Brick	White	None	0	5.1	Positive
1	B	Hallway by Music Room and Boy's Restroom	W3	Brick	White	Flaking	1	6.3	Positive
1	B	Hallway by Music Room and Boy's Restroom	W4	Brick	White	Cracking	2	5.4	Positive
1	B	Hallway by Music Room and Boy's Restroom	Baseboard	Concrete	Brown	None	0	1.5	Positive
1	B	Hallway by Music Room and Boy's Restroom	Tread Plate	Metal	Brown	Chipping	1	0.4	Negative
1	B	Music Room Office	Ceiling	Plaster	White	Flaking	240	9.7	Positive
1	B	Music Room Office	W1	Plaster	Tan	Flaking	2	8.1	Positive
1	B	Music Room Office	Window Frame	Wood	Brown	None	0	0.1	Negative
1	B	Music Room Office	Ductwork	Metal	White	Flaking	2	9.8	Positive
1	B	Music Room Office	Radiator	Metal	White	Flaking	6	1.1	Positive
1	B	Music Room Office	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Music Room Office	Door	Metal	Brown	None	0	0	Negative
1	B	Music Room Office	W2	Plaster	Blue	Flaking	4	7.7	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Music Room Office	Baseboard	Concrete	Brown	Chipping	1	4.2	Positive
1	B	Music Room Office	W3	Plaster	Tan	Flaking	12	3.3	Positive
1	B	Music Room Office	Window Frame	Wood	Brown	Chipping	2	0.1	Negative
1	B	Music Room Office	Pipe Riser Jacket	Metal	Brown	Flaking	1	1	Positive
1	B	Music Room Office	W4	Plaster	Tan	Flaking	5	2.5	Positive
1	B	Music Room Office	Window Frame	Wood	Brown	None	0	0.1	Negative
1	B	Music Room	Ceiling	Plaster	White	Flaking	175	10.6	Positive
1	B	Music Room	Ductwork	Metal	White	Flaking	6	9.5	Positive
1	B	Music Room	Radiator	Metal	Brown	Flaking	12	8.8	Positive
1	B	Music Room	W1	Plaster	Tan	None	0	4.5	Positive
1	B	Music Room	Door Frame	Metal	Brown	Chipping	1	0.2	Negative
1	B	Music Room	Door	Metal	Brown	None	0	0	Negative
1	B	Music Room	W2	Plaster	Tan	Cracking	2	8.4	Positive
1	B	Music Room	Baseboard	Concrete	Brown	None	0	3.2	Positive
1	B	Music Room	W3	Plaster	Tan	None	0	7.5	Positive
1	B	Music Room	Window Frame	Wood	Brown	Chipping	2	0.1	Negative
1	B	Music Room	Pipe Riser Jacket	Metal	Brown	Chipping	2	5.7	Positive
1	B	Music Room	W4	Plaster	Blue	Cracking	4	4.6	Positive
1	B	Music Room	W4	Plaster	Tan	Flaking	3	8.8	Positive
1	B	Music Room	Pipe Riser Jacket	Metal	Brown	Chipping	1	2.9	Positive
1	B	Music Room	Window Frame	Wood	Brown	None	0	0.1	Negative
1	B	Music Room Storage	W1	Brick	White	Cracking	1	9.1	Positive
1	B	Music Room Storage	Door Frame	Metal	Brown	Chipping	1	0.3	Negative
1	B	Music Room Storage	W2	Brick	White	Flaking	3	11	Positive
1	B	Music Room Storage	W3	Brick	White	None	0	10.4	Positive
1	B	Music Room Storage	W4	Brick	White	Cracking	2	10.7	Positive
1	B	Music Room Storage	Ceiling	Plaster	White	Flaking	2	10.3	Positive
1	B	Music Office Closet	Ceiling	Plaster	Tan	Flaking	6	6.7	Positive
1	B	Music Office Closet	W1	Brick	White	None	0	1.9	Positive
1	B	Music Office Closet	Door Frame	Metal	Brown	Chipping	1	0.3	Negative
1	B	Music Office Closet	W2	Brick	White	Efflorescence	3	10.9	Positive
1	B	Music Office Closet	W3	Brick	White	Flaking	8	3.6	Positive
1	B	Music Office Closet	W4	Brick	White	None	0	10.5	Positive
1	B	Art Room	W1	Plaster	Blue	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W1	Brick	N/A	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W1	Plaster	White	Partially Inaccessible	0	12.5	Positive
1	B	Art Room	W2	Plaster	Blue	Partially Inaccessible	0	17.8	Positive
1	B	Art Room	W2	Brick	N/A	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W3	Plaster	Blue	Partially Inaccessible	0	13.4	Positive
1	B	Art Room	W3	Brick	N/A	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W4	Plaster	Blue	Partially Inaccessible	0	14.4	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Art Room	W4	Brick	N/A	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W4	Wood	Black	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	W4	Sheetrock	White	Partially Inaccessible	0	N/A	N/A
1	B	Art Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Art Room	Ceiling	Plaster	White	Partially Inaccessible	0	7.9	Positive
1	B	Art Room Storage	W1	Brick	White	Partially Inaccessible	0	10.2	Positive
1	B	Art Room Storage	W2	Brick	White	Partially Inaccessible	0	N/A	N/A
1	B	Art Room Storage	W2	Plaster	White	Partially Inaccessible	0	7.8	Positive
1	B	Art Room Storage	W3	Brick	White	Partially Inaccessible	0	N/A	N/A
1	B	Art Room Storage	W4	Brick	White	Partially Inaccessible	0	12.4	Positive
1	B	Art Room Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Art Room Storage	Ceiling	Plaster	White	Partially Inaccessible	0	9.9	Positive
1	B	Boy's Restroom	Ceiling	Plaster	White	Flaking	60	1	Positive
1	B	Boy's Restroom	Ductwork	Metal	White	None	0	0	Negative
1	B	Boy's Restroom	W1	Concrete	White	None	0	0	Negative
1	B	Boy's Restroom	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Boy's Restroom	Door	Metal	Brown	Chipping	1	0	Negative
1	B	Boy's Restroom	W2	Concrete	White	None	0	0	Negative
1	B	Boy's Restroom	W3	Concrete	White	None	0	0	Negative
1	B	Boy's Restroom	W4	Concrete	White	Cracking	1	2	Positive
1	B	Boy's Restroom	Window Frame	Wood	Brown	Flaking	6	5.7	Positive
1	B	Boy's Restroom	Radiator	Metal	Brown	None	0	0	Negative
1	B	Boy's Restroom	W4	Concrete	White	None	0	0.6	Negative
1	B	Stairwell	W1	Brick	White	None	0	6.6	Positive
1	B	Stairwell	W2	Brick	White	None	0	7.7	Positive
1	B	Stairwell	Stringer	Concrete	Brown	Flaking	1	7.5	Positive
1	B	Stairwell	Step	Concrete	Brown	Chipping	1	0.8	Positive
1	B	Stairwell	Riser	Concrete	Brown	Chipping	2	1.9	Positive
1	B	Stairwell	W4	Brick	White	None	0	5.5	Positive
1	B	Stairwell	Stringer	Concrete	Brown	None	0	4.2	Positive
1	B	Storage next to Boy's Restroom	W1	Brick	White	None	0	0.3	Negative
1	B	Storage next to Boy's Restroom	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Storage next to Boy's Restroom	Door	Metal	Brown	None	0	0	Negative
1	B	Storage next to Boy's Restroom	W2	Brick	White	Flaking	3	0.5	Negative
1	B	Storage next to Boy's Restroom	Vertical Pipe	Metal	White	Chipping	2	0.1	Negative
1	B	Storage next to Boy's Restroom	Window Frame	Wood	Brown	Chipping	3	0	Negative
1	B	Storage next to Boy's Restroom	W3	Brick	White	None	0	0	Negative
1	B	Storage next to Boy's Restroom	W4	Brick	White	None	0	0	Negative
1	B	Storage next to Boy's Restroom	Ceiling	Concrete	White	Cracking	2	0	Negative
1	B	Storage next to Boy's Restroom	Radiator	Metal	White	None	0	0	Negative
1	B	Storage next to Boy's Restroom	Ductwork	Metal	White	Flaking	8	7.6	Positive
1	3	Hallway at Classrooms 300 to 303	W1	Plaster	Tan	Cracking	2	8	Positive
1	3	Hallway at Classrooms 300 to 303	W1	Plaster	Tan	Cracking	2	8	Positive
1	3	Hallway at Classrooms 300 to 303	W2	Plaster	Tan	Cracking	5	9.3	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	3	Hallway at Classrooms 300 to 303	W2	Plaster	Tan	Cracking	5	9.3	Positive
1	B	Hallway outside Kitchen	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Kitchen	W2	Brick	White	None	0	15.5	Positive
1	B	Hallway outside Kitchen	Electrical Panel	Metal	Brown	None	0	0.02	Negative
1	B	Hallway outside Kitchen	Cabinet	Wood	Brown	Chipping	2	1.2	Positive
1	B	Hallway outside Kitchen	W3	Brick	White	Cracking	5	4.4	Positive
1	B	Hallway outside Kitchen	W4	Brick	White	Flaking	12	8.8	Positive
1	B	Hallway outside Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Kitchen	Baseboard	Concrete	Brown	Chipping	15	3.6	Positive
1	B	Hallway outside Kitchen	Ceiling	Plaster	White	Flaking	150	6.7	Positive
1	B	Kitchen	Ceiling	Plaster	Tan	Flaking	500	8.4	Positive
1	B	Kitchen	W1	Plaster	Tan	Flaking	9	7.4	Positive
1	B	Kitchen	Chair Rail	Wood	White	Flaking	4	0	Negative
1	B	Kitchen	Baseboard	Wood	Brown	None	0	0	Negative
1	B	Kitchen	W1	Brick	Tan	Cracking	1	5.1	Positive
1	B	Kitchen	W2	Plaster	Tan	Flaking	5	6.6	Positive
1	B	Kitchen	W2	Brick	Tan	Flaking	14	3.2	Positive
1	B	Kitchen	W3	Brick	Tan	Flaking	6	3.6	Positive
1	B	Kitchen	W3	Plaster	Tan	Flaking	8	7.6	Positive
1	B	Kitchen	W4	Plaster	Tan	Flaking	20	6.7	Positive
1	B	Kitchen	Floor	Concrete	Brown	Flaking	20	0.1	Negative
1	B	Kitchen	Trench Plate	Metal	Brown	None	0	0.1	Negative
1	B	Kitchen Storage	Ceiling	Plaster	Tan	None	0	7.3	Positive
1	B	Kitchen Storage	W1	Plaster	Tan	None	0	7.9	Positive
1	B	Kitchen Storage	Door	Metal	Brown	Chipping	1	0	Negative
1	B	Kitchen Storage	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Kitchen Storage	W2	Plaster	Tan	None	0	7.4	Positive
1	B	Kitchen Storage	W3	Plaster	Tan	None	0	8.1	Positive
1	B	Kitchen Storage	W4	Plaster	Tan	None	0	3.7	Positive
1	B	Kitchen Storage	Floor	Concrete	Brown	Chipping	6	0.1	Negative
1	B	Kitchen Storage Closet	Ceiling	Plaster	Tan	Flaking	7	9.3	Positive
1	B	Kitchen Storage Closet	Ductwork	Metal	White	Flaking	4	9.8	Positive
1	B	Kitchen Storage Closet	W1	Plaster	Tan	Chipping	2	9.2	Positive
1	B	Kitchen Storage Closet	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Kitchen Storage Closet	Door	Metal	Brown	None	0	0	Negative
1	B	Kitchen Storage Closet	W2	Plaster	Tan	None	0	8.7	Positive
1	B	Kitchen Storage Closet	W3	Plaster	Tan	None	0	9.1	Positive
1	B	Kitchen Storage Closet	W4	Plaster	Tan	None	0	8.4	Positive
1	B	Kitchen Storage Closet	Ceiling	Plaster	Tan	None	0	3.4	Positive
1	B	Kitchen Storage Closet	W1	Plaster	Tan	None	0	4.1	Positive
1	B	Kitchen Storage Closet	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Kitchen Storage Closet	Door	Metal	Brown	None	0	0	Negative
1	B	Kitchen Storage Closet	W2	Plaster	Tan	None	0	4.9	Positive
1	B	Kitchen Storage Closet	Shelf	Wood	Brown	None	0	0	Negative
1	B	Kitchen Storage Closet	W3	Plaster	Tan	Cracking	9	5.5	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Kitchen Storage Closet	W4	Plaster	Tan	None	0	4.8	Positive
1	B	Kitchen Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway behind Gym	W1	Brick	White	Cracking	2	8.2	Positive
1	B	Hallway behind Gym	Window Frame	Wood	White	Cracking	1	5.3	Positive
1	B	Hallway behind Gym	Window Sill	Wood	White	Flaking	5	5.5	Positive
1	B	Hallway behind Gym	W2	Brick	White	None	0	7.5	Positive
1	B	Hallway behind Gym	W3	Brick	White	Cracking	3	2.7	Positive
1	B	Hallway behind Gym	W4	Brick	White	None	0	7.3	Positive
1	B	Hallway behind Gym	Baseboard	Concrete	Brown	Chipping	6	0.1	Negative
1	B	Hallway behind Gym	Tread Plate	Metal	Brown	Chipping	8	0.4	Negative
1	B	Hallway behind Gym	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	Hallway behind Gym	Ductwork	Metal	Tan	Flaking	14	7.8	Positive
1	B	Hallway behind Gym	Ceiling	Plaster	White	Flaking	40	6	Positive
1	B	Stairwell next to Cafeteria	Ceiling	Plaster	Tan	None	0	8.8	Positive
1	B	Stairwell next to Cafeteria	Door	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell next to Cafeteria	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell next to Cafeteria	W2	Plaster	Tan	Cracking	2	7.6	Positive
1	B	Stairwell next to Cafeteria	Stringer	Concrete	Brown	Flaking	2	4.1	Positive
1	B	Stairwell next to Cafeteria	Step	Concrete	Brown	Flaking	1	2.7	Positive
1	B	Stairwell next to Cafeteria	Riser	Concrete	Brown	None	0	3.3	Positive
1	B	Stairwell next to Cafeteria	W4	Plaster	Tan	Flaking	2	8.7	Positive
1	B	Cafeteria	W1	Plaster	Tan	Efflorescence	22	3.8	Positive
1	B	Cafeteria	Column	Plaster	Tan	Efflorescence	16	3.6	Positive
1	B	Cafeteria	Vertical Pipe	Metal	Tan	Flaking	1	4	Positive
1	B	Cafeteria	Door Frame (W1)	Metal	Brown	Chipping	6	0	Negative
1	B	Cafeteria	W2	Plaster	Tan	Efflorescence	11	3.1	Positive
1	B	Cafeteria	Radiator	Metal	Brown	Chipping	1	5.4	Positive
1	B	Cafeteria	Radiator Pad	Concrete	Brown	None	0	0.7	Positive
1	B	Cafeteria	Window Frame	Wood	Brown	Cracking	2	0.2	Negative
1	B	Cafeteria	W3	Plaster	Tan	Efflorescence	30	6.1	Positive
1	B	Cafeteria	Window Frame	Wood	Brown	Chipping	2	0.3	Negative
1	B	Cafeteria	Metal Cage	Metal	Brown	None	0	0.1	Negative
1	B	Cafeteria	W4	Plaster	Tan	Cracking	8	2.7	Positive
1	B	Cafeteria	Door Frame	Wood	Brown	None	0	0.1	Negative
1	B	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria	Ceiling	Concrete	White	Flaking	100	0.3	Negative
1	B	Cafeteria	Ceiling	Plaster	White	Cracking	290	7.5	Positive
1	B	Restroom in Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Restroom in Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Restroom in Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Restroom in Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Restroom in Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Restroom in Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Cafeteria Storage	W1	Plaster	Tan	Cracking	1	9.4	Positive
1	B	Cafeteria Storage	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Cafeteria Storage	Door	Metal	Brown	Chipping	3	0	Negative
1	B	Cafeteria Storage	W2	Plaster	Tan	Cracking	2	10.1	Positive
1	B	Cafeteria Storage	W3	Plaster	Tan	Cracking	1	9.5	Positive
1	B	Cafeteria Storage	W4	Plaster	Tan	None	0	6.8	Positive
1	B	Cafeteria Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria Storage	Ceiling	Plaster	White	Flaking	40	9.7	Positive
1	B	Building Engineer's Office	W1	Plaster	Tan	Cracking	2	8.7	Positive
1	B	Building Engineer's Office	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Building Engineer's Office	Door	Metal	Brown	None	0	0	Negative
1	B	Building Engineer's Office	W2	Plaster	Tan	Cracking	4	10.2	Positive
1	B	Building Engineer's Office	Electrical Panel	Metal	Tan	Cracking	1	10.7	Positive
1	B	Building Engineer's Office	W3	Plaster	Tan	Cracking	2	10.7	Positive
1	B	Building Engineer's Office	Shelf	Wood	Tan	None	0	0	Negative
1	B	Building Engineer's Office	W4	Plaster	Tan	Flaking	7	11.7	Positive
1	B	Building Engineer's Office	Baseboard	Wood	Brown	None	0	0	Negative
1	B	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	Ceiling	Plaster	White	Flaking	15	10.5	Positive
1	B	Building Engineer's Office	Radiator	Metal	White	Flaking	1	2.9	Positive
1	B	Girl's Restroom	W1	Brick	White	Flaking	10	4.7	Positive
1	B	Girl's Restroom	W1	Brick	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Door Frame	Metal	Brown	None	0	0.1	Negative
1	B	Girl's Restroom	W2	Brick	White	None	0	5.3	Positive
1	B	Girl's Restroom	W2	Brick	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Toilet Partition	Metal	Brown	None	0	0.7	Positive
1	B	Girl's Restroom	W3	Brick	White	Cracking	3	4.4	Positive
1	B	Girl's Restroom	W3	Brick	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Pipe Jacket	Metal	Brown	None	0	0.1	Negative
1	B	Girl's Restroom	Pipe Jacket	Metal	White	None	0	0	Negative
1	B	Girl's Restroom	W4	Brick	White	Efflorescence	6	2.7	Positive
1	B	Girl's Restroom	W4	Brick	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Pipe Jacket	Metal	Brown	Chipping	1	3.6	Positive
1	B	Girl's Restroom	Pipe Jacket	Metal	White	Chipping	1	3.1	Positive
1	B	Cafeteria	Baseboard	Concrete	Brown	Cracking	2	1.9	Positive
1	B	Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Ceiling	Plaster	White	Flaking	25	3.2	Positive
1	B	Girl's Restroom	Ductwork	Metal	White	Chipping	6	0	Negative
1	B	Girl's Restroom	Radiator	Metal	White	Flaking	10	0.2	Negative
1	B	Storage outside of Girl's Restroom	Ceiling	Concrete	White	Cracking	6	6.1	Positive
1	B	Storage outside of Girl's Restroom	Ductwork	Metal	White	Cracking	3	2.2	Positive
1	B	Storage outside of Girl's Restroom	Radiator	Metal	White	Flaking	4	3.8	Positive
1	B	Storage outside of Girl's Restroom	W1	Brick	White	None	0	5.2	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
1	B	Storage outside of Girl's Restroom	W1	Brick	Brown	Cracking	1	5.9	Positive
1	B	Storage outside of Girl's Restroom	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	Storage outside of Girl's Restroom	Door	Metal	Brown	Cracking	2	0	Negative
1	B	Storage outside of Girl's Restroom	W2	Brick	White	None	0	5.6	Positive
1	B	Storage outside of Girl's Restroom	W2	Brick	Brown	None	0	5.5	Positive
1	B	Storage outside of Girl's Restroom	W3	Brick	White	Cracking	3	5.8	Positive
1	B	Storage outside of Girl's Restroom	Column	Concrete	White	None	0	4	Positive
1	B	Storage outside of Girl's Restroom	Column	Concrete	Brown	Efflorescence	4	6.6	Positive
1	B	Storage outside of Girl's Restroom	Vertical Pipe	Metal	White	Chipping	2	2	Positive
1	B	Storage outside of Girl's Restroom	Toilet Partition	Wood	Brown	None	0	8.2	Positive
1	B	Storage outside of Girl's Restroom	W4	Brick	Tan	Cracking	3	1.2	Positive
1	B	Storage outside of Girl's Restroom	W4	Brick	Brown	Flaking	1	5.4	Positive
1	B	Storage outside of Girl's Restroom	Window Frame	Wood	White	None	0	0	Negative
1	B	Storage outside of Girl's Restroom	Vertical Pipe	Metal	White	Flaking	9	3.3	Positive
1	B	Storage outside of Girl's Restroom	Ceiling	Concrete	Brown	Chipping	1	10.1	Positive
1	B	Storage outside of Girl's Restroom	W1	Metal	Brown	None	0	0.9	Positive
1	B	Storage outside of Girl's Restroom	W2	Brick	Brown	None	0	8.5	Positive
1	B	Storage outside of Girl's Restroom	Door Frame	Metal	Brown	Chipping	1	3.2	Positive
1	B	Storage outside of Girl's Restroom	W3	Concrete	Brown	None	0	11.4	Positive
1	B	Storage outside of Girl's Restroom	W4	Brick	Brown	None	0	10.8	Positive
1	B	Stairwell outside of Girl's Restroom	Ceiling	Plaster	Tan	Flaking	1	9.2	Positive
1	B	Stairwell outside of Girl's Restroom	W1	Plaster	Tan	None	0	6.7	Positive
1	B	Stairwell outside of Girl's Restroom	Door	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell outside of Girl's Restroom	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell outside of Girl's Restroom	W2	Plaster	Tan	None	0	7.3	Positive
1	B	Stairwell outside of Girl's Restroom	Baseboard	Concrete	Brown	None	0	2.4	Positive
1	B	Stairwell outside of Girl's Restroom	Stringer	Concrete	Brown	Flaking	6	5.5	Positive
1	B	Stairwell outside of Girl's Restroom	Step	Concrete	Brown	Flaking	1	1.1	Positive
1	B	Stairwell outside of Girl's Restroom	Riser	Concrete	Brown	None	0	4.6	Positive
1	B	Stairwell outside of Girl's Restroom	Newel Post	Metal	Brown	Flaking	10	6.6	Positive
1	B	Stairwell outside of Girl's Restroom	W4	Plaster	Tan	None	0	8.1	Positive
2	1	Classroom A1	W1	Sheetrock	Tan	None	0	0	Negative
2	1	Classroom A1	Shelving	Wood	White	None	0	0	Positive
2	1	Classroom A1	Door Frame	Metal	Blue	Chipping	2	0.1	Negative
2	1	Classroom A1	W2	Sheetrock	Tan	None	0	0	Negative
2	1	Classroom A1	W3	Brick	Tan	Cracking	2	1.9	Positive
2	1	Classroom A1	Window Sill	Wood	White	Flaking	1	0.2	Negative
2	1	Classroom A1	Radiator Cover	Metal	White	None	0	0	Negative
2	1	Classroom A1	W4	Sheetrock	Yellow	None	0	0.1	Negative
2	1	Classroom A1	Door	Metal	Brown	Chipping	1	0	Negative
2	1	Classroom A1	Door Frame	Metal	Brown	Chipping	2	0.1	Negative
2	1	Classroom A1	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A2	W1	Sheetrock	Tan	None	0	0.1	Negative

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
2	1	Classroom A2	Shelving	Wood	White	None	0	0	Negative
2	1	Classroom A2	Door Frame	Metal	Brown	Chipping	1	0.01	Negative
2	1	Classroom A2	W2	Sheetrock	Tan	None	0	0	Negative
2	1	Classroom A2	W3	Brick	White	Cracking	4	5.1	Positive
2	1	Classroom A2	Window Sill	Wood	White	Cracking	1	0.2	Negative
2	1	Classroom A2	Radiator Cover	Metal	White	None	0	0	Negative
2	1	Classroom A2	W4	Sheetrock	Tan	None	0	0.2	Negative
2	1	Classroom A2	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A3	W1	Sheetrock	Tan	None	0	0	Negative
2	1	Classroom A3	Door Frame	Metal	Black	Chipping	2	0.1	Negative
2	1	Classroom A3	Shelving	Wood	White	None	0	0	Negative
2	1	Classroom A3	W2	Sheetrock	Tan	None	0	0	Negative
2	1	Classroom A3	W3	Brick	White	Cracking	4	1.7	Positive
2	1	Classroom A3	Window Sill	Wood	White	None	0	0	Negative
2	1	Classroom A3	Radiator Cover	Metal	White	None	0	0.1	Negative
2	1	Classroom A3	W4	Sheetrock	Tan	None	0	0	Negative
2	1	Classroom A3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A4	W1	Sheetrock	Tan	None	0	0	Negative
2	1	Classroom A4	Door Frame	Metal	Blue	Chipping	2	0.1	Negative
2	1	Classroom A4	Shelving	Wood	White	None	0	0	Negative
2	1	Classroom A4	W2	Sheetrock	Tan	Cracking	3	0.1	Negative
2	1	Classroom A4	W3	Brick	White	Cracking	5	3.4	Positive
2	1	Classroom A4	Window Sill	Wood	White	Chipping	1	0.1	Negative
2	1	Classroom A4	Radiator Cover	Metal	White	None	0	0	Negative
2	1	Classroom A4	W4	Sheetrock	Tan	None	0	0	Negative
2	1	Classroom A4	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A4	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Classroom A4	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Storage Room in Rear Corridor	W1	Sheetrock	Tan	None	0	0	Negative
2	1	Storage Room in Rear Corridor	Door Frame (W1)	Metal	Blue	Chipping	1	0	Negative
2	1	Storage Room in Rear Corridor	W2	Sheetrock	Tan	None	0	0	Negative
2	1	Storage Room in Rear Corridor	W3	Brick	Tan	Cracking	1	4.9	Positive
2	1	Storage Room in Rear Corridor	W4	Brick	Tan	Cracking	3	1.3	Positive
2	1	Storage Room in Rear Corridor	Window Sill	Wood	Tan	None	0	0	Negative
2	1	Storage Room in Rear Corridor	Radiator Cover	Metal	White	None	0	0	Negative
2	1	Storage Room in Rear Corridor	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Hallway Rear Corridor	W2	Sheetrock	White	None	0	0	Negative
2	1	Hallway Rear Corridor	Chair Rail	Wood	Tan	None	0	0	Negative
2	1	Hallway Rear Corridor	W2	Sheetrock	Tan	None	0	0	Negative

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
2	1	Hallway Rear Corridor	W3	Sheetrock	White	None	0	0	Negative
2	1	Hallway Rear Corridor	W4	Brick	White	Flaking	2	5	Positive
2	1	Hallway Rear Corridor	Door Frame	Metal	Brown	Chipping	1	0	Negative
2	1	Hallway Rear Corridor	Door	Metal	Brown	None	0	0	Negative
2	1	Hallway Rear Corridor	Radiator Cover	Metal	Tan	None	0	0	Negative
2	1	Hallway Rear Corridor	Window Sill	Wood	White	None	0	0	Negative
2	1	Hallway Rear Corridor	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	Hallway Rear Corridor	Ceiling	Sheetrock	White	None	0	0	Negative
2	1	Hallway between Classrooms A1 & A4	W1	Brick	White	Cracking	12	5.8	Positive
2	1	Hallway between Classrooms A1 & A4	W1	Brick	Tan	Cracking	2	1.1	Positive
2	1	Hallway between Classrooms A1 & A4	Window Sill	Wood	White	None	0	0	Negative
2	1	Hallway between Classrooms A1 & A4	Radiator Cover	Metal	Tan	None	0	0	Negative
2	1	Hallway between Classrooms A1 & A4	Door Frame	Metal	Brown	Chipping	1	0	Negative
2	1	Hallway between Classrooms A1 & A4	Door	Metal	Brown	None	0	0	Negative
2	1	Hallway between Classrooms A1 & A4	W2	Sheetrock	White	None	0	0	Negative
2	1	Hallway between Classrooms A1 & A4	Chair Rail	Wood	Tan	Flaking	2	0	Negative
2	1	Hallway between Classrooms A1 & A4	W2	Sheetrock	Tan	Flaking	5	0	Negative
2	1	Hallway in front of Boys Restroom	Ceiling	Sheetrock	White	Cracking	8	0	Negative
2	1	Hallway in front of Boys Restroom	W1	Sheetrock	White	None	0	0	Negative
2	1	Hallway in front of Boys Restroom	Chair Rail	Wood	Tan	None	0	0	Negative
2	1	Hallway in front of Boys Restroom	W1	Sheetrock	Tan	None	0	0	Negative
2	1	Hallway in front of Boys Restroom	W2	Sheetrock	Tan	None	0	0	Negative
2	1	Hallway near Administrative Office	Ceiling	Sheetrock	White	None	0	4.5	Positive
2	1	Hallway near Administrative Office	W1	Brick	White	None	0	0	Negative
2	1	Hallway near Administrative Office	Door Frame	Metal	Brown	Chipping	1	0	Negative
2	1	Hallway near Administrative Office	Door	Metal	Grey	None	0	0	Negative
2	1	Hallway near Administrative Office	W2	Sheetrock	White	None	0	0	Negative
2	1	Hallway near Administrative Office	W2	Sheetrock	Tan	None	0	0	Negative
2	1	Hallway near Administrative Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway near Administrative Office	W4	Sheetrock	White	None	0	0	Negative
2	1	Hallway near Administrative Office	Chair Rail	Wood	Brown	None	0	0	Negative
2	1	Hallway near Administrative Office	W4	Sheetrock	Tan	None	0	0	Negative
2	1	Slop Sink Room at the End of the Hallway	W1	Sheetrock	Tan	Flaking	3	0	Negative
2	1	Slop Sink Room at the End of the Hallway	Door Frame (W1)	Metal	Blue	Chipping	1	0	Negative
2	1	Slop Sink Room at the End of the Hallway	W2	Brick	Tan	Cracking	5	4	Positive
2	1	Slop Sink Room at the End of the Hallway	W3	Brick	Tan	Cracking	1	0.3	Negative
2	1	Slop Sink Room at the End of the Hallway	Window Sill	Wood	White	None	0	0	Negative
2	1	Slop Sink Room at the End of the Hallway	Radiator Cover	Metal	Tan	None	0	0	Negative
2	1	Slop Sink Room at the End of the Hallway	W4	Sheetrock	Tan	Cracking	1	0	Negative
2	1	Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Office	W1	Sheetrock	Tan	Cracking	10	0	Negative
2	1	Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Office	W2	Brick	White	None	0	1	Positive

		Inspection Dates: 01/03/2023-01/16/2023	Lead-Safe Certification Assessment Report						
2	1	Office	Radiator	Metal	White	None	0	0	Negative
2	1	Office	W3	Sheetrock	Tan	None	0	0	Negative
2	1	Office	Door Frame	Metal	Blue	None	0	0	Negative
2	1	Office	W4	Sheetrock	Tan	None	0	0	Negative
2	1	Staff Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Staff Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Staff Restroom	W1	Sheetrock	Tan	None	0	0	Negative
2	1	Staff Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Staff Restroom	W2	Sheetrock	Tan	None	0	0	Negative
2	1	Staff Restroom	W3	Sheetrock	Tan	None	0	0	Negative
2	1	Staff Restroom	W4	Sheetrock	Tan	None	0	0	Negative
2	1	Mechanical Room behind Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Mechanical Room behind Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Mechanical Room behind Office	W1	Sheetrock	Tan	Flaking	5	0	Negative
2	1	Mechanical Room behind Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Mechanical Room behind Office	W2	Sheetrock	Tan	Flaking	6	0	Negative
2	1	Mechanical Room behind Office	W3	Brick	White	None	0	0.9	Positive
2	1	Mechanical Room behind Office	Radiator	Metal	White	None	0	0	Negative
2	1	Mechanical Room behind Office	W4	Brick	White	Flaking	2	6.5	Positive
2	1	Mechanical Room behind Office	Window Sill	Wood	White	None	0	0.1	Negative
2	1	Kitchen Next to Staff Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Kitchen Next to Staff Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Kitchen Next to Staff Restroom	W1	Sheetrock	Tan	None	0	0	Negative
2	1	Kitchen Next to Staff Restroom	Door Frame	Metal	Black	Chipping	2	0	Negative
2	1	Kitchen Next to Staff Restroom	W2	Sheetrock	Tan	Chipping	1	0	Negative
2	1	Kitchen Next to Staff Restroom	W3	Sheetrock	Tan	Flaking	1	0	Negative
2	1	Kitchen Next to Staff Restroom	W3	Brick	White	Flaking	4	6	Positive
2	1	Kitchen Next to Staff Restroom	Window Sill	Wood	White	Flaking	1	0	Negative
2	1	Kitchen Next to Staff Restroom	Radiator	Metal	White	None	0	0	Negative
2	1	Kitchen Next to Staff Restroom	W4	Sheetrock	Tan	Flaking	1	0	Negative
2	1	Attic- 3rd - near SE Stairs/Rm 304	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Attic- 3rd - near SE Stairs/Rm 304	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Attic- 3rd - near SE Stairs/Rm 304	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	AT	Attic- 3rd - near SE Stairs/Rm 304	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	AT	Attic- 3rd - near SE Stairs/Rm 304	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	AT	Attic- 3rd - near SE Stairs/Rm 304	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	CS	Crawl Space	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	CS	Crawl Space	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	CS	Crawl Space	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	CS	Crawl Space	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Lead-Safe Certification Assessment Report						
Inspection Dates: 01/03/2023-01/16/2023									
1	CS	Crawl Space	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	CS	Crawl Space	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access