

Lead Safe Certification for H. A. Brown School

Name of Inspector: Melissa Billingsley

Inspection Dates: June 10, 11 and 12, 2019

Inspection Company: Criterion Laboratories,

ULCS# 5210

Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	2	212	Boy's Restroom across from Classroom 213	W1	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Boy's Restroom across from Classroom 213	W2	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Boy's Restroom across from Classroom 213	W3	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Boy's Restroom across from Classroom 213	W4	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Boy's Restroom across from Classroom 213	Ceiling	Plaster	White	Chipping	1	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Boy's Restroom across from Classroom 213	Floor	Concrete	Grey	Chipping	1	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 213	W1	Sheetrock	White	Friction	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 213	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 213	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0	Negative
1	2	203	Classroom 213	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 213	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Chipping	1	0.02	Negative
1	2	203	Classroom 213	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 213	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0	Negative
1	2	203	Classroom 213	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Girl's Restroom adjacent to Classroom 213	W1	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Girl's Restroom adjacent to Classroom 213	W2	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Girl's Restroom adjacent to Classroom 213	W3	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Girl's Restroom adjacent to Classroom 213	W4	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Girl's Restroom adjacent to Classroom 213	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Girl's Restroom adjacent to Classroom 213	Floor	Concrete	Brown	Chipping	1	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 206	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 206	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 206	W3	Concrete	White	Friction	1	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 206	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Friction	1	0.02	Negative
1	2	208	Classroom 206	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	Staff Restroom next to Classroom 206	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	Staff Restroom next to Classroom 206	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	Staff Restroom next to Classroom 206	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	Staff Restroom next to Classroom 206	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	Staff Restroom next to Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	Staff Restroom next to Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Storage next to Data Closet 204	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Storage next to Data Closet 204	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Gray	Friction	1	0.09	Negative
1	2	214	Storage next to Data Closet 204	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Storage next to Data Closet 204	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Storage next to Data Closet 204	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Storage next to Data Closet 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Storage next to Data Closet 204	Floor	Concrete	Gray	Friction	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Data Server Room 204	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	213	Data Server Room 204	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	213	Data Server Room 204	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	213	Data Server Room 204	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	213	Data Server Room 204	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	213	Data Server Room 204	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	205	Classroom 214	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 214	W1	Sheetrock	White	Friction	1	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 214	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 214	W2	N/A	N/A	N/A	n/a	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0.04	Negative
1	2	205	Classroom 214	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0.02	Negative
1	2	205	Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Wall	Sheetrock	White	Friction	1	0.01	Negative
1	2	205	Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Brown	Friction	1	0.04	Negative
1	2	205	Classroom 214	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 214	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0.02	Negative
1	2	205	Classroom 214	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 209	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 209	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 209	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 209	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	2	0.01	Negative

Lead Safe Certification for H. A. Brown School

		Name of Inspector: Melissa Billingsley											Inspection Dates: June 10, 11 and 12, 2019				
		Inspection Company: Criterion Laboratories,											ULCS# 5210				
Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	2	202	Classroom 209	W3	Concrete	White	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Chipping	1	0.01	Negative
1	2	202	Classroom 209	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 209	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	2	0.01	Negative
1	2	202	Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Closet in Classroom 209	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Closet in Classroom 209	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Closet in Classroom 209	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Closet in Classroom 209	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Closet in Classroom 209	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Closet in Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Telecom Room 208	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Telecom Room 208	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Telecom Room 208	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Telecom Room 208	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Telecom Room 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Telecom Room 208	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 212	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 212	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 212	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 212	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 212	W3	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Brown	Friction	1	0.01	Negative
1	2	201	Classroom 212	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Chipping	1	0.01	Negative
1	2	201	Classroom 212	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 212	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Far left closet in Classroom 212	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Far left closet in Classroom 212	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Far left closet in Classroom 212	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Far left closet in Classroom 212	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Far left closet in Classroom 212	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Far left closet in Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Left closet in Classroom 212	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Left closet in Classroom 212	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Left closet in Classroom 212	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Left closet in Classroom 212	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Left closet in Classroom 212	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Left closet in Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 200	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 200	W1	Sheetrock	White	Friction	1	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 200	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0.02	Negative
1	2	207	Classroom 200	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Brown	Friction	3	0.03	Negative
1	2	207	Classroom 200	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 200	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0.02	Negative
1	2	207	Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 201	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 201	W1	Sheetrock	White	Friction	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 201	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 201	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0.02	Negative
1	2	206	Classroom 201	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Brown	Friction	3	0.04	Negative
1	2	206	Classroom 201	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 201	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	1	0.01	Negative
1	2	206	Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classrooms 200 to 212	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classrooms 200 to 212	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classrooms 200 to 212	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classrooms 200 to 212	W3	Concrete	White	Cracking	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for H. A. Brown School

Name of Inspector: **Melissa Billingsley**

Inspection Dates: **June 10, 11 and 12, 2019**

Inspection Company: **Criterion Laboratories,**

ULCS# **5210**

Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	2	H25	Hallway from Classrooms 200 to 212	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classrooms 200 to 212	W4	Concrete	Brown	Chipping	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classrooms 200 to 212	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classrooms 200 to 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Storage to Left of Gym	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Storage to Left of Gym	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Storage to Left of Gym	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Storage to Left of Gym	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Storage to Left of Gym	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	Storage to Left of Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13B	Kitchen Storage Room 112	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13B	Kitchen Storage Room 112	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13B	Kitchen Storage Room 112	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13B	Kitchen Storage Room 112	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13B	Kitchen Storage Room 112	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13B	Kitchen Storage Room 112	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Classroom 113	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Classroom 113	W1	Sheetrock	White	Friction	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Classroom 113	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Classroom 113	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Classroom 113	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Chipping	1	0.02	Negative
1	1	100	Classroom 113	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Classroom 113	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Classroom 113	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Boy's Restroom across from Classroom 114	W1	Concrete	Brown, white	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Boy's Restroom across from Classroom 114	W2	Concrete	Brown, white	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Boy's Restroom across from Classroom 114	W3	Concrete	Brown, white	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Boy's Restroom across from Classroom 114	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	1	0.11	Negative
1	1	101	Boy's Restroom across from Classroom 114	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	1	0.09	Negative
1	1	110	Boy's Restroom across from Classroom 114	W4	Concrete	Brown, white	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Boy's Restroom across from Classroom 114	W4	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Brown	Friction	1	0.02	Negative
1	1	110	Boy's Restroom across from Classroom 114	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Boy's Restroom across from Classroom 114	Floor	Concrete	Brown	Chipping	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Girl's Restroom Across from Classroom 114	W1	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Girl's Restroom Across from Classroom 114	W2	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Girl's Restroom Across from Classroom 114	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Girl's Restroom Across from Classroom 114	W3	Concrete	Brown	Efflorescence	1	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Girl's Restroom Across from Classroom 114	W4	Concrete	Brown/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Girl's Restroom Across from Classroom 114	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Girl's Restroom Across from Classroom 114	Floor	Concrete	Brown	Chipping	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114B	Storage Closet next to Classroom 119 Right side	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114B	Storage Closet next to Classroom 119 Right side	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114B	Storage Closet next to Classroom 119 Right side	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114B	Storage Closet next to Classroom 119 Right side	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114B	Storage Closet next to Classroom 119 Right side	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114B	Storage Closet next to Classroom 119 Right side	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Storage Closet next to Classroom 119 Left Side	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Storage Closet next to Classroom 119 Left Side	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Storage Closet next to Classroom 119 Left Side	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Storage Closet next to Classroom 119 Left Side	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Storage Closet next to Classroom 119 Left Side	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Storage Closet next to Classroom 119 Left Side	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	119	Classroom 119	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	119	Classroom 119	W1	Sheetrock	White	Friction	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for H. A. Brown School

Name of Inspector: Melissa Billingsley

Inspection Dates: June 10, 11 and 12, 2019

Inspection Company: Criterion Laboratories,

ULCS# 5210

Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	1	119	Classroom 119	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	119	Classroom 119	W3	Sheetrock	White	Friction	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	119	Classroom 119	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	119	Classroom 119	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	119	Classroom 119	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114C	Classroom 119 Storage and Former Exit door	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114C	Classroom 119 Storage and Former Exit door	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114C	Classroom 119 Storage and Former Exit door	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114C	Classroom 119 Storage and Former Exit door	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114C	Classroom 119 Storage and Former Exit door	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114C	Classroom 119 Storage and Former Exit door	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A	Classroom 119 Storage Closet	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A	Classroom 119 Storage Closet	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A	Classroom 119 Storage Closet	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A	Classroom 119 Storage Closet	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A	Classroom 119 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A	Classroom 119 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112	Gymnasium	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112	Gymnasium	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112	Gymnasium	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112	Gymnasium	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112	Gymnasium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112	Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112E	Gym Teacher's Office	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112E	Gym Teacher's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Brown	Chipping	1	0.02	Negative
1	1	112E	Gym Teacher's Office	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112E	Gym Teacher's Office	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112E	Gym Teacher's Office	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112E	Gym Teacher's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112E	Gym Teacher's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Teacher's Lounge	W1	Concrete	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Teacher's Lounge	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Teacher's Lounge	W3	Concrete	Green/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Teacher's Lounge	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Tan	Moisture Damage	1	0.03	Negative
1	1	102	Teacher's Lounge	W4	Concrete	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Teacher's Lounge	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Teacher's Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1004A	Home and School Office 122	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1004A	Home and School Office 122	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1004A	Home and School Office 122	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1004A	Home and School Office 122	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1004A	Home and School Office 122	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1004A	Home and School Office 122	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Men's Restroom next to Home and School Office 122	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Men's Restroom next to Home and School Office 122	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Men's Restroom next to Home and School Office 122	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Men's Restroom next to Home and School Office 122	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Men's Restroom next to Home and School Office 122	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Men's Restroom next to Home and School Office 122	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Custodial Closet next to Women's Staff Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Custodial Closet next to Women's Staff Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Custodial Closet next to Women's Staff Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Custodial Closet next to Women's Staff Restroom	W3	N/A	N/A	N/A	n/a	N/A	N/A	Window trim	Wood	White	Chipping	2	0.02	Negative

Lead Safe Certification for H. A. Brown School

Name of Inspector: Melissa Billingsley

Inspection Dates: June 10, 11 and 12, 2019

Inspection Company: Criterion Laboratories,

ULCS# 5210

Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	1	114	Classroom 14	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	3	0.05	Negative
1	1	114	Classroom 114	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114	Classroom 114	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Chipping	3	0.04	Negative
1	1	114	Classroom 114	W3	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Brown	Friction	1	0.11	Negative
1	1	114	Classroom 114	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114	Classroom 114	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Metal	Brown	Friction	3	0.1	Negative
1	1	114	Classroom 114	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114	Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S114	Stairwell next to Classroom 114	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S114	Stairwell next to Classroom 114	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S114	Stairwell next to Classroom 114	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S114	Stairwell next to Classroom 114	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S114	Stairwell next to Classroom 114	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Red	Friction	5	0.03	Negative
1	1	S114	Stairwell next to Classroom 114	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S114	Stairwell next to Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage to Right of Cafetorium (103)	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage to Right of Cafetorium (103)	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage to Right of Cafetorium (103)	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage to Right of Cafetorium (103)	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage to Right of Cafetorium (103)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage to Right of Cafetorium (103)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 101	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 101	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 101	W3	Concrete	Blue	Chipping	1	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 101	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Classroom 100	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Classroom 100	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Classroom 100	W3	Concrete	Blue	Chipping	1	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Classroom 100	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Classroom 100	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Classroom 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113A	Server Room across from Classroom 100	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113A	Server Room across from Classroom 100	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113A	Server Room across from Classroom 100	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113A	Server Room across from Classroom 100	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113A	Server Room across from Classroom 100	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113A	Server Room across from Classroom 100	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom 100 to Cafeteria	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom 100 to Cafeteria	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom 100 to Cafeteria	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom 100 to Cafeteria	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom 100 to Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom 100 to Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classrooms 108 to 113	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classrooms 108 to 113	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classrooms 108 to 113	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classrooms 108 to 113	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classrooms 108 to 113	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classrooms 108 to 113	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	W1	Concrete	White	Chipping, Flaking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	W1	Concrete	Gray	Chipping, Flaking	10	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	W2	Concrete	White	Chipping, Flaking	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	W2	Concrete	Gray	Chipping, Flaking	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	W3	Concrete	White	Chipping, Flaking	10	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	W3	Concrete	Gray	Chipping, Flaking	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

