

Lead Safe Certification for J. H. Brown School																	
Name of Inspector: Charles Rhodes									Inspection Dates: 6-10 through 6-14-19								
Inspection Company: Batta Environmental									ULCS# 8210								
Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional mponent XRF (positive/negative)
1	3	305	Classroom 305	W1	Plaster	Blue	Friction	18	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	W2	Plaster	Blue	Friction	24	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	W2	N/A	N/A	None	N/A	N/A	N/A	Radiator	Metal	Blue	Chipping	2	11.2	Negative
1	3	305	Classroom 305	W3	Plaster	Blue	Friction	36	9.9	Positive	N/A	N/A	N/A	None	N/A	N/A	N/A
1	3	305	Classroom 305	W4	Plaster	Blue	Friction	40	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S39	Stairwell adjacent to Classrooms 304 and 305	W1	Plaster	White	Chipping	1	12	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S39	Stairwell adjacent to Classrooms 304 and 305	W2	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
1	3	S39	Stairwell adjacent to Classrooms 304 and 305	W2	N/A	N/A	None	N/A	N/A	N/A	Newel posts	Metal	Green	Chipping	1	9.2	Positive
1	3	S39	Stairwell adjacent to Classrooms 304 and 305	W3	Plaster	White	None	1	11.3	Positive	N/A	N/A	N/A	None	N/A	N/A	N/A
1	3	S39	Stairwell adjacent to Classrooms 304 and 305	W3	N/A	N/A	None	N/A	N/A	N/A	Hand rails	Metal	Grey	Chipping	N/A	N/A	Positive
1	3	S39	Stairwell adjacent to Classrooms 304 and 305	W4	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S39	Stairwell adjacent to Classrooms 304 and 305	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S39	Stairwell adjacent to Classrooms 304 and 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	W1	Plaster	Blue	Chipping	4	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	W2	Plaster	Blue	Chipping	2	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	W3	Plaster	Blue	Alligatoring	4	13.1	Positive	N/A	N/A	N/A	None	N/A	N/A	N/A
1	3	304	Classroom 304	W3	N/A	N/A	None	N/A	N/A	N/A	Radiator	Metal	Blue	Chipping	1	12.4	Positive
1	3	304	Classroom 304	W4	Plaster	Blue	Chipping	4	8.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	W1	Plaster	Tan	Chipping	4	4.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	W3	Plaster	Tan	Chipping	1	9.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	W3	N/A	N/A	None	N/A	N/A	N/A	Baseboard	Wood	Tan	Flaking	4	-0.1	Negative
1	3	306	Classroom 306	W4	Plaster	Tan	Chipping	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306C	Classroom 306 Closet	W1	Plaster	Tan	Cracking	1	4.3	Positive	N/A	N/A	N/A	None	N/A	N/A	N/A
1	3	306C	Classroom 306 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	3	-0.1	Negative
1	3	306C	Classroom 306 Closet	W2	Plaster	Tan	Chipping	1	3.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306C	Classroom 306 Closet	W3	Plaster	Tan	Cracking	1	3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306C	Classroom 306 Closet	W4	Plaster	Tan	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306C	Classroom 306 Closet	Ceiling	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306C	Classroom 306 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306D	Classroom 306 Closet at Entrance	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306D	Classroom 306 Closet at Entrance	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306D	Classroom 306 Closet at Entrance	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306D	Classroom 306 Closet at Entrance	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306D	Classroom 306 Closet at Entrance	Ceiling	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306D	Classroom 306 Closet at Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	W1	Plaster	Blue	Cracking	2	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	W2	Plaster	Blue	Chipping	1	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	W3	Plaster	Blue	Alligatoring	6	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A	Electrical fixtures	Metal	Blue	Chipping	1	10.3	Positive
1	3	303	Classroom 303	W4	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	Floor	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	W1	Plaster	Tan	Chipping	2	5.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	W2	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	W3	Plaster	Tan	Friction	4	9.3	Positive	N/A	N/A	N/A	None	N/A	N/A	N/A
1	3	302	Classroom 302	W3	N/A	N/A	None	N/A	N/A	N/A	Radiator	Metal	Tan	Cracking	1	11.4	Positive
1	3	302	Classroom 302	W4	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	Floor	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Boy's Restroom	W1	Plaster	Tan	None	n/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Boy's Restroom	W2	Plaster	Tan	Flaking	14	14.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Boy's Restroom	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Metal	Tan	Cracking	30	2.6	Positive
1	3	S37	Stairwell next to Boy's Restroom	W3	N/A	N/A	None	N/A	N/A	N/A	Radiator	Metal	Tan	Cracking	10	7.1	Positive
1	3	S37	Stairwell next to Boy's Restroom	W4	Plaster	Tan	Cracking	22	10.2	Positive	N/A	N/A	Red	N/A	N/A	N/A	N/A
1	3	S37	Stairwell next to Boy's Restroom	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for J. H. Brown School																	
Name of Inspector: Charles Rhodes										Inspection Dates: 6-10 through 6-14-19							
Inspection Company: Batta Environmental										ULCS# 8210							
Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	3	S37	Stairwell next to Boy's Restroom	Floor	Concrete	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306A	W1	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306A	W2	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306A	W3	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306A	W4	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306A	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	W1	Plaster	White	Cracking	10	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	W2	Sheetrock	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	W3	Plaster	White	Cracking	12	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	W4	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway from Classroom from 301 to 304	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway from Classroom from 301 to 304	W2	Plaster	Tan	Cracking	86	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway from Classroom from 301 to 304	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway from Classroom from 301 to 304	W4	Plaster	Tan	Cracking	29	9.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway from Classroom from 301 to 304	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway from Classroom from 301 to 304	Floor	Concrete	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300A	Psychologist's Office 300	W1	Plaster	Blue	Cracking	17	9.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300A	Psychologist's Office 300	W2	Plaster	Blue	Chipping	6	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300A	Psychologist's Office 300	W3	Plaster	Blue	Cracking	14	5.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300A	Psychologist's Office 300	W4	Plaster	Blue	Cracking	14	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300A	Psychologist's Office 300	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300A	Psychologist's Office 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	W1	Plaster	Blue	Cracking	4	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	W2	Plaster	Blue	Cracking	4	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	W3	Plaster	Blue	Cracking	17	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Blue	Chipping	3	14.1	Positive
1	3	307	Classroom 307	W4	Plaster	Blue	Cracking	12	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Office 308	W1	Plaster	Blue	Chipping	12	11.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Office 308	W2	Plaster	Blue	Chipping	10	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Office 308	W3	Plaster	Blue	Chipping	8	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Office 308	W4	Plaster	Blue	Chipping	27	11.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Office 308	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Office 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H37	Hallway from Classroom from 300 to 308	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H37	Hallway from Classroom from 300 to 308	W2	Plaster	Tan	Chipping	9	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H37	Hallway from Classroom from 300 to 308	W3	Plaster	Tan	Cracking	17	9.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H37	Hallway from Classroom from 300 to 308	W4	Plaster	Tan	Chipping	25	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H37	Hallway from Classroom from 300 to 308	Ceiling	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H37	Hallway from Classroom from 300 to 308	Floor	Concrete	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	W1	Plaster	Blue	Flaking	3	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	W2	Plaster	Blue	Flaking	1	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	W3	Plaster	Blue	Flaking	3	7.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	W4	Plaster	Blue	Chipping	10	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	Ceiling	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classrooms 209 and 210	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classrooms 209 and 210	W2	Plaster	Tan	Cracking	14	14.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classrooms 209 and 210	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classrooms 209 and 210	W4	Plaster	Tan	Cracking	6	15.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classrooms 209 and 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell adjacent to Classrooms 209 and 210	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	W1	Plaster	Grey	Friction	1	7.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	W2	Plaster	Grey	Friction	1	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	W3	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	W4	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	W1	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for J. H. Brown School																	
Name of Inspector: Charles Rhodes									Inspection Dates: 6-10 through 6-14-19								
Inspection Company: Batta Environmental									ULCS# 8210								
Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	2	211	Classroom 211	W2	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	W3	Plaster	Grey	Chipping	1	8.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	W4	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	W1	Plaster	Blue	Flaking	8	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	W2	Plaster	Blue	Cracking	16	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	W3	Plaster	Blue	Chipping	14	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A	pipng	Metal	Blue	Chipping	3	1	Positive
1	2	208	Classroom 208	W4	Plaster	Blue	Flaking	20	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	W1	Plaster	Blue	Chipping	3	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	W2	Plaster	Blue	Chipping	6	8.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	W3	Plaster	Blue	Chipping	4	6.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	W4	Plaster	Blue	Chipping	5	7.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Room 207A Office	W1	Plaster	Blue	Friction	1	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Room 207A Office	W2	Plaster	Blue	Chipping	7	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Room 207A Office	W3	Plaster	Blue	Cracking	9	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Room 207A Office	W4	Plaster	Blue	Friction	6	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Room 207A Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Room 207A Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classroom from Staff Lunch Room 200 to Classroom 210	W1	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classroom from Staff Lunch Room 200 to Classroom 210	W2	Plaster	Blue	Flaking	26	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classroom from Staff Lunch Room 200 to Classroom 210	W3	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classroom from Staff Lunch Room 200 to Classroom 210	W4	Plaster	Tan	Cracking	28	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classroom from Staff Lunch Room 200 to Classroom 210	W4	N/A	Tan	N/A	N/A	N/A	N/A	pipng	Metal	Tan	Chipping	3	14	Positive
1	2	H25	Hallway from Classroom from Staff Lunch Room 200 to Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H25	Hallway from Classroom from Staff Lunch Room 200 to Classroom 210	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Staff Lunch Room 200	W1	Plaster	Tan	Efflorescence	15	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Staff Lunch Room 200	W2	Plaster	Tan	Flaking	40	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Staff Lunch Room 200	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Staff Lunch Room 200	W3	N/A	N/A	N/A	N/A	N/A	N/A	pipng	Metal	Tan	Cracking	8	11.5	Positive
1	2	200	Staff Lunch Room 200	W4	Plaster	Tan	Flaking	15	13.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Staff Lunch Room 200	Ceiling	Plaster	Tan	Efflorescence	25	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Staff Lunch Room 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Staff Lunch Room 200 Kitchen	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Staff Lunch Room 200 Kitchen	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Staff Lunch Room 200 Kitchen	W3	Plaster	Tan	Chipping	6	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Staff Lunch Room 200 Kitchen	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Staff Lunch Room 200 Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Staff Lunch Room 200 Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W1	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W2	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W3	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W4	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206B	Classroom 206A	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206B	Classroom 206A	W2	Plaster	Tan	Chipping	3	4.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for J. H. Brown School																	
Name of Inspector: Charles Rhodes										Inspection Dates: 6-10 through 6-14-19							
Inspection Company: Batta Environmental										ULCS# 8210							
Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional mponent XRF (positive/negative)
1	2	206B	Classroom 206A	W3	Plaster	Tan	Flaking	12	2.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206B	Classroom 206A	W4	Plaster	Tan	Chipping	3	3.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206B	Classroom 206A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206B	Classroom 206A	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Boy's Restroom	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Boy's Restroom	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Boy's Restroom	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Boy's Restroom	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Boy's Restroom	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W1	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W2	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W3	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W4	Plaster	Grey	Chipping	1	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	W1	Plaster	Tan	Chipping	3	7.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	W2	Plaster	Tan	Cracking	4	7.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	W3	Plaster	Tan	Chipping	3	11.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	W3	Plaster	N/A	N/A	N/A	N/A	N/A	pipng	Metal	Tan	Cracking	14	11.9	Positive
1	2	206	Classroom 206	W4	Plaster	Tan	Flaking	6	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205 Computer Lab	W1	Plaster	Green	Chipping	36	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205 Computer Lab	W2	Plaster	Green	Chipping	25	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205 Computer Lab	W3	Plaster	Green	Flaking	35	9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205 Computer Lab	W3	Plaster	Green	Flaking	N/A	N/A	N/A	pipng	Metal	Green	Cracking	20	11.8	Positive
1	2	205	Classroom 205 Computer Lab	W4	Plaster	Green	Cracking	21	6.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205 Computer Lab	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205 Computer Lab	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	W1	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	W2	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	W3	Plaster	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	W4	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204A	Closet 204A	W2	Plaster	Green	Flaking	20	6.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell adjacent to Classrooms 204 and 205	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell adjacent to Classrooms 204 and 205	W2	Plaster	Tan	Flaking	25	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell adjacent to Classrooms 204 and 205	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell adjacent to Classrooms 204 and 205	W4	Plaster	Tan	Friction	10	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell adjacent to Classrooms 204 and 205	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairwell adjacent to Classrooms 204 and 205	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H26	Hallway from Classroom from 201 to 204	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H26	Hallway from Classroom from 201 to 204	W2	Plaster	Tan	Chipping	32	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H26	Hallway from Classroom from 201 to 204	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H26	Hallway from Classroom from 201 to 204	W4	Plaster	Tan	Cracking	18	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H26	Hallway from Classroom from 201 to 204	W4	N/A	N/A	N/A	N/A	N/A	N/A	pipng	Metal	Tan	Cracking	28	11.4	Positive
1	2	H26	Hallway from Classroom from 201 to 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H26	Hallway from Classroom from 201 to 204	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	Stairwell adjacent to Classrooms 103 and 104	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	Stairwell adjacent to Classrooms 103 and 104	W2	Plaster	Tan	Friction	1	12.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	Stairwell adjacent to Classrooms 103 and 104	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	Stairwell adjacent to Classrooms 103 and 104	W4	Plaster	Tan	Friction	1	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	Stairwell adjacent to Classrooms 103 and 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	Stairwell adjacent to Classrooms 103 and 104	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	W3	Plaster	Tan	Cracking	1	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

			Lead Safe Certification for J. H. Brown School															
			Name of Inspector: Charles Rhodes						Inspection Dates: 6-10 through 6-14-19									
			Inspection Company: Batta Environmental						ULCS# 8210									
Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	
1	1	104	Classroom 104	W3	Plaster	Tan	Chipping	1	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	104	Classroom 104	W4	Plaster	Orange	Chipping	1	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	104	Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	104	Classroom 104	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105	Room 105 Kindergarten	W1	Plaster	Tan	Chipping	25	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105	Room 105 Kindergarten	W2	Plaster	Tan	Cracking	8	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105	Room 105 Kindergarten	W3	Plaster	Tan	Flaking	24	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105	Room 105 Kindergarten	W3	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Tan	Chipping	25	0	Negative	
1	1	105	Room 105 Kindergarten	W4	Plaster	Tan	Chipping	5	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105	Room 105 Kindergarten	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105	Room 105 Kindergarten	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	102	Classroom 102	W1	Plaster	Grey	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	102	Classroom 102	W2	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	102	Classroom 102	W3	Plaster	Tan	Cracking	1	14.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	102	Classroom 102	W4	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	102	Classroom 102	Ceiling	N/A	Grey	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	102	Classroom 102	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	101	Classroom 101	W1	Plaster	Grey	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	101	Classroom 101	W2	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	101	Classroom 101	W3	Plaster	Grey	Flaking	11	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	101	Classroom 101	W4	Plaster	Grey	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	101	Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	101	Classroom 101	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairwell next to Library	W1	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairwell next to Library	W2	Plaster	Tan	Flaking	22	13.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairwell next to Library	W3	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairwell next to Library	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Tan	Cracking	22	11.1	Positive
1	1	S11	Stairwell next to Library	W4	Plaster	Tan	Chipping	4	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairwell next to Library	Ceiling	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairwell next to Library	Floor	Concrete	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100A	Main Office	W1	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100A	Main Office	W2	Plaster	Tan	Chipping	8	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100A	Main Office	W3	Plaster	Tan	Chipping	1	12.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100A	Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Tan	Cracking	10	8.9	Positive	
1	1	100A	Main Office	W4	Plaster	Tan	Friction	5	12.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100A	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100A	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	W1	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	W2	Plaster	Tan	Spalling	2	13.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	W2	Plaster	Grey	Cracking	6	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	W2	Plaster	Blue	Cracking	8	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	W3	Plaster	Blue	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Grey	Cracking	6	6.3	Positive	
1	1	100B	Principal's Office	W4	Plaster	Grey	Chipping	8	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	W4	Plaster	Blue	Chipping	6	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	W4	Plaster	Tan	Chipping	10	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	Ceiling	Plaster	Tan	Flaking	4	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	100B	Principal's Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105A	Classroom 105A	W1	Plaster	Tan	Chipping	6	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105A	Classroom 105A	W2	Plaster	Tan	Chipping	5	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105A	Classroom 105A	W3	Plaster	Tan	Spalling	18	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105A	Classroom 105A	W4	Plaster	Tan	Chipping	14	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105A	Classroom 105A	Ceiling	Plaster	Tan	Flaking	24	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	105A	Classroom 105A	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H14	Hallway from Classroom from 103 to the Main Office	W1	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H14	Hallway from Classroom from 103 to the Main Office	W2	Plaster	Tan	Chipping	16	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H14	Hallway from Classroom from 103 to the Main Office	W3	Plaster	Tan	Chipping	1	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H14	Hallway from Classroom from 103 to the Main Office	W4	Plaster	Tan	Chipping	24	14	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H14	Hallway from Classroom from 103 to the Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Tan	Cracking	16	18.8	Positive	
1	1	H14	Hallway from Classroom from 103 to the Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Tan	Flaking	4	6	Positive	

			Lead Safe Certification for J. H. Brown School														
			Name of Inspector: Charles Rhodes						Inspection Dates: 6-10 through 6-14-19								
			Inspection Company: Batta Environmental						ULCS# 8210								
Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	1	H14	Hallway from Classroom from 103 to the Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classroom from 103 to the Main Office	Floor	Concrete	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S16	Main Entrance Vestabule and Stairs	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S16	Main Entrance Vestabule and Stairs	W2	Plaster	Tan	Chipping	4	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S16	Main Entrance Vestabule and Stairs	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S16	Main Entrance Vestabule and Stairs	W4	Plaster	Tan	Chipping	1	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S16	Main Entrance Vestabule and Stairs	Ceiling	Plaster	Tan	Flaking	6	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S16	Main Entrance Vestabule and Stairs	Floor	Concrete	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	W1	Plaster	Tan	Chipping	1	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	W2	Plaster	Tan	Chipping	1	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	W3	Plaster	Tan	Chipping	1	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	W4	Plaster	Blue	Chipping	1	12.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Classroom 106 Closet (Hallway Side)	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Classroom 106 Closet (Hallway Side)	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Classroom 106 Closet (Hallway Side)	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Classroom 106 Closet (Hallway Side)	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Classroom 106 Closet (Hallway Side)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Classroom 106 Closet (Hallway Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Classroom 106 Closet (Back of Classroom)	W1	No Access	Tan	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Classroom 106 Closet (Back of Classroom)	W2	No Access	Tan	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Classroom 106 Closet (Back of Classroom)	W3	No Access	Tan	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Classroom 106 Closet (Back of Classroom)	W4	No Access	Tan	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Classroom 106 Closet (Back of Classroom)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Classroom 106 Closet (Back of Classroom)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	W1	Plaster	Tan	Chipping	2	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	W2	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	W3	Plaster	Tan	Chipping	1	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	W4	Plaster	Blue	Chipping	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Closet (Hallway Side)	W1	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Closet (Hallway Side)	W2	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Closet (Hallway Side)	W3	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Closet (Hallway Side)	W4	Plaster	Blue	Cracking	10	6.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Closet (Hallway Side)	Ceiling	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Closet (Hallway Side)	Floor	Wood	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell adjacent to Classrooms 107 and 108	W1	Plaster	Tan	Cracking	2	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell adjacent to Classrooms 107 and 108	W1	N/A	N/A	None	N/A	N/A	N/A	Door	Metal	Brown	Flaking	13	0.4	Negative
1	1	S15	Stairwell adjacent to Classrooms 107 and 108	W2	Plaster	Tan	Friction	3	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell adjacent to Classrooms 107 and 108	W3	Plaster	Tan	Cracking	6	12.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell adjacent to Classrooms 107 and 108	W3	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Tan	Flaking	14	10.6	Positive
1	1	S15	Stairwell adjacent to Classrooms 107 and 108	W4	Plaster	Tan	Friction	4	15	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell adjacent to Classrooms 107 and 108	Ceiling	Plaster	Tan	Cracking	8	10.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairwell adjacent to Classrooms 107 and 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	W1	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	W2	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	W3	Plaster	Tan	Cracking	2	13.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	W4	Plaster	Orange	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Office109	W1	Plaster	Green	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Office109	W2	Plaster	Green	Chipping	10	15	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Office109	W3	Plaster	Green	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Office109	W3	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Green	Cracking	8	15.8	Positive
1	1	109	Office109	W4	Plaster	Green	Cracking	27	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Office109	Ceiling	Plaster	Green	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Office109	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Nurse's Office 110	W1	Plaster	Tan	Chipping	1	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Nurse's Office 110	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	5.9	Positive
1	1	110	Nurse's Office 110	W2	Plaster	Tan	Chipping	8	10.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for J. H. Brown School																	
			Name of Inspector: Charles Rhodes						Inspection Dates: 6-10 through 6-14-19								
			Inspection Company: Batta Environmental						ULCS# 8210								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	110	Nurse's Office 110	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	14	5	Positive
1	1	110	Nurse's Office 110	W3	Plaster	Tan	Chipping	2	12.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Nurse's Office 110	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	2	3.3	Positive
1	1	110	Nurse's Office 110	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Chipping	1	4.7	Positive
1	1	110	Nurse's Office 110	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Tan	Chipping	1	10.3	Positive
1	1	110	Nurse's Office 110	W3	N/A	N/A	N/A	N/A	N/A	N/A	pipeing	Metal	Tan	Chipping	3	12.8	Positive
1	1	110	Nurse's Office 110	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	13	7.1	Positive
1	1	110	Nurse's Office 110	W4	Plaster	Tan	Flaking	8	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Nurse's Office 110	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	2	4	Positive
1	1	110	Nurse's Office 110	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	24	7.4	Positive
1	1	110	Nurse's Office 110	Ceiling	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Nurse's Office 110	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Office 111	W1	Plaster	Tan	Chipping	5	14.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Office 111	W2	Plaster	Tan	Chipping	1	13.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Office 111	W3	Plaster	Tan	Chipping	2	15.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Office 111	W4	Plaster	Tan	Chipping	2	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Office 111	Ceiling	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Office 111	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Auditorium	W1	Plaster	Tan	Chipping	1	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	4.5	Positive
1	1	100	Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	5	Positive
1	1	100	Auditorium	W2	Plaster	Tan	Chipping	85	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Chipping	22	4.6	Positive
1	1	100	Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Trim	Wood	Tan	Chipping	4	4.2	Positive
1	1	100	Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	2	3.5	Positive
1	1	100	Auditorium	W3	Plaster	Tan	Chipping	35	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Auditorium	W4	Plaster	Tan	Chipping	20	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	3	5	Positive
1	1	100	Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	3.4	Positive
1	1	100	Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Trim	Wood	Tan	Chipping	3	3.3	Positive
1	1	100	Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Auditorium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom from 108 to the Auditorium	W1	Plaster	Tan	Chipping	1	13.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom from 108 to the Auditorium	W2	Plaster	Tan	Chipping	6	15.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom from 108 to the Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A	pipeing	Metal	Tan	Chipping	15	10.5	Positive
1	1	H13	Hallway from Classroom from 108 to the Auditorium	W3	Plaster	Tan	Chipping	3	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom from 108 to the Auditorium	W4	Plaster	Tan	Chipping	18	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom from 108 to the Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A	pipeing	Metal	Tan	Chipping	12	15.8	Positive
1	1	H13	Hallway from Classroom from 108 to the Auditorium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway from Classroom from 108 to the Auditorium	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	1	Generator Room	W1	Concrete	White	N/A	N/A	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	1	Generator Room	W2	Concrete	White	N/A	N/A	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	1	Generator Room	W3	Concrete	White	N/A	N/A	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	1	Generator Room	W4	Concrete	White	N/A	N/A	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	1	Generator Room	Ceiling	Concrete	White	N/A	N/A	not accessed	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	1	Generator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	2	Storage Room adjacent to Boiler Room	W1	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	2	Storage Room adjacent to Boiler Room	W2	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	2	Storage Room adjacent to Boiler Room	W3	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	2	Storage Room adjacent to Boiler Room	W4	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	2	Storage Room adjacent to Boiler Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	2	Storage Room adjacent to Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	3	Boiler Room	W1	Brick	White	Spalling	400	0.6	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	3	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	pipeing	Metal	Tan	Chipping	96	1.2	Positive
1	BS	3	Boiler Room	W2	Concrete	White	Spalling	450	4.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	3	Boiler Room	W3	Concrete	White	Spalling	380	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for J. H. Brown School																	
Name of Inspector: Charles Rhodes										Inspection Dates: 6-10 through 6-14-19							
Inspection Company: Batta Environmental										ULCS# 8210							
Element	Floor	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	BS	3	Boiler Room	W4	Concrete	White	Spalling	350	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	3	Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	3	Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	003A	Fan Room	W1	Concrete	Black	Chipping	150	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	003A	Fan Room	W1	Brick	White	Chipping	75	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	003A	Fan Room	W2	Brick	White	Flaking	8	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	003A	Fan Room	W3	Brick	White	Flaking	15	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	003A	Fan Room	W4	Concrete	White	Flaking	8	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	003A	Fan Room	W4	Concrete	Black	Spalling	150	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	003A	Fan Room	Ceiling	Concrete	White	Flaking	50	not accessed	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	003A	Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	5	Building Engineer's Office	W1	Concrete	Tan	Flaking	36	11.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	5	Building Engineer's Office	W2	Concrete	Tan	Chipping	4	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	5	Building Engineer's Office	W3	Plaster	Tan	Moisture Damage	30	11.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	5	Building Engineer's Office	W4	Plaster	Tan	Moisture Damage	24	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	5	Building Engineer's Office	Ceiling	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	5	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005A	Building Engineer's Storage Room	W1	Plaster	Tan	Chipping	18	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005A	Building Engineer's Storage Room	W2	Plaster	Tan	Chipping	24	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005A	Building Engineer's Storage Room	W3	Plaster	Tan	Chipping	10	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005A	Building Engineer's Storage Room	W4	Plaster	Tan	Spalling	40	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005A	Building Engineer's Storage Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005A	Building Engineer's Storage Room	Floor	Concrete	Grey	Cracking	30	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005B	Building Engineer's Restroom	W1	Plaster	Tan	Chipping	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005B	Building Engineer's Restroom	W2	Plaster	Tan	Chipping	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005B	Building Engineer's Restroom	W3	Plaster	Tan	Chipping	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005B	Building Engineer's Restroom	W4	Plaster	Tan	Spalling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005B	Building Engineer's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	005B	Building Engineer's Restroom	Floor	Concrete	Grey	Cracking	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	6	Boy's Restroom adjacent to Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	6	Boy's Restroom adjacent to Boiler Room	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	6	Boy's Restroom adjacent to Boiler Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	6	Boy's Restroom adjacent to Boiler Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	6	Boy's Restroom adjacent to Boiler Room	Ceiling	Concrete	Tan	Cracking	45	not Accessible	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	6	Boy's Restroom adjacent to Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Tan	Chipping	1	not Accessible	Positive
1	BS	6	Boy's Restroom adjacent to Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Flaking	15	Accessible	Positive
1	BS	6	Boy's Restroom adjacent to Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	H01	Hallway from Electrical Room to Boiler Room	W1	Plaster	Tan	Chipping	2	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	H01	Hallway from Electrical Room to Boiler Room	W2	Plaster	Tan	Chipping	6	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	H01	Hallway from Electrical Room to Boiler Room	W3	Plaster	Tan	Chipping	3	22	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	H01	Hallway from Electrical Room to Boiler Room	W4	Plaster	Tan	Chipping	4	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	H01	Hallway from Electrical Room to Boiler Room	Ceiling	Plaster	Tan	Moisture Damage	80	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	H01	Hallway from Electrical Room to Boiler Room	Floor	Concrete	Grey	Friction	10	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	8	Electrical Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	8	Electrical Room	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	8	Electrical Room	W2	N/A	N/A	N/A	N/A	N/A	N/A	piping	Metal	Tan	Flaking	30	1.3	Positive
1	BS	8	Electrical Room	W3	Concrete	Black	Chipping	3	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	8	Electrical Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	8	Electrical Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	8	Electrical Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	4	Storage Room adjacent to Electrical Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	4	Storage Room adjacent to Electrical Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	4	Storage Room adjacent to Electrical Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	4	Storage Room adjacent to Electrical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	4	Storage Room adjacent to Electrical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	4	Storage Room adjacent to Electrical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	7	Classroom adjacent to Janitor's Closet	W1	Plaster	Tan	Chipping	2	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	7	Classroom adjacent to Janitor's Closet	W2	Plaster	Tan	Cracking	8	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for J. H. Brown School																	
Name of Inspector: Charles Rhodes								Inspection Dates: 6-10 through 6-14-19									
Inspection Company: Batta Environmental								ULCS# 8210									
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	BS	7	Classroom adjacent to Janitor's Closet	W3	Plaster	Tan	Moisture Damage	25	4.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	7	Classroom adjacent to Janitor's Closet	W4	Plaster	Tan	Efflorescence	20	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	7	Classroom adjacent to Janitor's Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	0.8	Positive
1	BS	7	Classroom adjacent to Janitor's Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Grey	Chipping	60	0.2	Negative
1	BS	7	Classroom adjacent to Janitor's Closet	Ceiling	Plaster	Tan	Cracking	40	no access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	7	Classroom adjacent to Janitor's Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	007A	Custodial Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	007A	Custodial Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	007A	Custodial Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	007A	Custodial Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	007A	Custodial Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	007A	Custodial Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	S01	Middle Stairwell next to Girl's Restroom	W1	Plaster	Tan	Chipping	2	14.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	S01	Middle Stairwell next to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Flaking	8	0.4	Negative
1	BS	S01	Middle Stairwell next to Girl's Restroom	W2	Plaster	Tan	Chipping	6	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	S01	Middle Stairwell next to Girl's Restroom	W3	Plaster	Tan	Chipping	2	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	S01	Middle Stairwell next to Girl's Restroom	W4	Plaster	Tan	Cracking	8	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	S01	Middle Stairwell next to Girl's Restroom	Ceiling	Plaster	Tan	Flaking	3	9.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	S01	Middle Stairwell next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	10	Girl's Restroom adjacent to Gym	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	10	Girl's Restroom adjacent to Gym	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	10	Girl's Restroom adjacent to Gym	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	10	Girl's Restroom adjacent to Gym	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	10	Girl's Restroom adjacent to Gym	Ceiling	Plaster	Tan	Moisture Damage	60	no access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	10	Girl's Restroom adjacent to Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	11	Gymnasium	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	11	Gymnasium	W2	Concrete	Tan	Chipping	2	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	11	Gymnasium	W2	N/A	N/A	N/A	N/A	N/A	N/A	pipng	Metal	Tan	Flaking	36	5.3	Positive
1	BS	11	Gymnasium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Concrete	Tan	Chipping	10	0.3	Negative
1	BS	11	Gymnasium	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	11	Gymnasium	W4	Concrete	White	Chipping	10	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	11	Gymnasium	W4	N/A	N/A	N/A	N/A	N/A	N/A	pipng	Metal	Tan	Flaking	34	10	Positive
1	BS	11	Gymnasium	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Metal	Brown	Chipping	10	0.2	Negative
1	BS	11	Gymnasium	Ceiling	Concrete	Tan	Cracking	72	Not Accessible	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	11	Gymnasium	Floor	Wood	Brown	Friction	250	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	11	Gymnasium	Floor	Metal	Grey	Friction	34	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	12	Gymnasium Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	12	Gymnasium Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	12	Gymnasium Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	12	Gymnasium Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	12	Gymnasium Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	12	Gymnasium Office	Floor	Concrete	Grey	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	9	Cafeteria	W1	Brick	Tan	Chipping	2	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	9	Cafeteria	W2	Brick	Tan	Chipping	1	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	9	Cafeteria	W3	Brick	Tan	Chipping	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	9	Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A	pipng	Metal	Tan	Chipping	28	5.7	Positive
1	BS	9	Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Metal	Brown	Chipping	1	10	Positive
1	BS	9	Cafeteria	W4	Brick	Tan	Chipping	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	9	Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	9	Cafeteria	Floor	Concrete	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	9	Cafeteria	Floor	Metal	Grey	Friction	34	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009A	Kitchen Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009A	Kitchen Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009A	Kitchen Storage	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009A	Kitchen Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009A	Kitchen Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009A	Kitchen Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009B	Kitchen	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009B	Kitchen	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009B	Kitchen	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009B	Kitchen	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	009B	Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

			Lead Safe Certification for J. H. Brown School																
			Name of Inspector: Charles Rhodes						Inspection Dates: 6-10 through 6-14-19										
			Inspection Company: Batta Environmental						ULCS# 8210										
Element Floor																			