

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P aster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	1	100	Copier Room in Principal's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100	Copier Room in Principal's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100	Copier Room in Principal's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100	Copier Room in Principal's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100	Copier Room in Principal's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100	Copier Room in Principal's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100	Copier Room in Principal's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100A	Principal's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100A	Principal's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100A	Principal's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100A	Principal's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100A	Principal's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100A	Principal's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100A	Principal's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100B	Vice Principal's Office	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100B	Vice Principal's Office	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100B	Vice Principal's Office	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100B	Vice Principal's Office	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100B	Vice Principal's Office	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100C	Principal's Office Restroom	Floor	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100C	Principal's Office Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100C	Principal's Office Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100C	Principal's Office Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100C	Principal's Office Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100C	Principal's Office Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100C	Principal's Office Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	1	100F	Stairwell B by Main Office	W1	Plaster	White	Chipping	10	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Stairwell B by Main Office	W2	Plaster	White	Cracking	12	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Stairwell B by Main Office	W3	Plaster	White	Chipping	10	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Stairwell B by Main Office	W4	Plaster	White	Chipping	8	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Stairwell B by Main Office	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Stairwell B by Main Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100G	Restroom outside Principal's Office	W1	Plaster	White	Flaking	6	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100G	Restroom outside Principal's Office	W2	Plaster	White	Flaking	40	37.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100G	Restroom outside Principal's Office	W3	Sheetrock	White	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100G	Restroom outside Principal's Office	W4	Sheetrock	White	Flaking	40	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100G	Restroom outside Principal's Office	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100G	Restroom outside Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101	Classroom 101	W1	Plaster	Tan	Chipping	3	14.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101	Classroom 101	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.24	Negative
1230	1	1	101	Classroom 101	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Green	Chipping	1	0.3	Negative
1230	1	1	101	Classroom 101	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101	Classroom 101	W2	Plaster	Tan	Flaking	6	24.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101	Classroom 101	W3	Plaster	Tan	Flaking	7	34.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101	Classroom 101	W4	Plaster	Tan	Cracking	4	36.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101	Classroom 101	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101	Classroom 101	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	3	0.35	Negative
1230	1	1	101A	Storage 101 Restroom	W1	Plaster	Tan	Chipping	1	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	101A	Storage 101 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	2	0.26	Negative
1230	1	1	101A	Storage 101 Restroom	W2	Plaster	Tan	Cracking	4	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																			
Lead Safe Certification Assessment Report																			
Bryant Promise Academy Elementary School #1230																			
				Inspection Company: Synertech, Inc.															
				Name of Inspector: Bart McMahon/Ryan Hutsell															
				Inspection Dates: 06/17-06/27/2019															
ULC S#	E l e m e n t	Flo r	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P ster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	
1230	1	1	101A	Storage 101 Restroom	W3	Plaster	Tan	Cracking	1	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101A	Storage 101 Restroom	W4	Plaster	Tan	Cracking	7	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101A	Storage 101 Restroom	Ceiling	Plaster	White	Flaking	2	4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101A	Storage 101 Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101B	Storage 101 Storage Room	W1	Plaster	Tan	Partially Inaccessible/Chipping	1	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101B	Storage 101 Storage Room	W2	Plaster	Tan	Partially Inaccessible/ Cracking	3	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101B	Storage 101 Storage Room	W3	Plaster	Tan	Partially Inaccessible/ Chipping	6	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101B	Storage 101 Storage Room	W4	Plaster	Tan	Partially Inaccessible/ Chipping	2	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101B	Storage 101 Storage Room	Ceiling	Plaster	White	Cracking	1	12.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	101B	Storage 101 Storage Room	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102	Classroom 102	W1	Plaster	Tan	Cracking	2	22.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102	Classroom 102	W2	Plaster	Tan	Chipping	1	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102	Classroom 102	W3	Plaster	Tan	Flaking	7	35.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102	Classroom 102	W4	Plaster	Tan	Flaking	4	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102	Classroom 102	Ceiling	Plaster	White	Cracking	3	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102	Classroom 102	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102A	Classroom 102 Storage	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102A	Classroom 102 Storage	W2	Plaster	Tan	Cracking	4	22.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102A	Classroom 102 Storage	W3	Plaster	Tan	Cracking	4	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102A	Classroom 102 Storage	W4	Plaster	Tan	Cracking	7	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102A	Classroom 102 Storage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102A	Classroom 102 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102B	Classroom 102 Restroom	W1	Plaster	Tan	Chipping	2	22.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102B	Classroom 102 Restroom	W2	Plaster	Tan	Chipping	4	31.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102B	Classroom 102 Restroom	W3	Plaster	Tan	Flaking	3	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102B	Classroom 102 Restroom	W4	Plaster	Tan	Flaking	2	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102B	Classroom 102 Restroom	Ceiling	Plaster	White	Cracking	1	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102B	Classroom 102 Restroom	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102B	Classroom 102 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	1	0.33	Negative	
1230	1	1	102C	Classroom 102 Storage	W1	Plaster	Tan	Partially Inaccessible			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102C	Classroom 102 Storage	W2	Plaster	Tan	Partially Inaccessible/ Cracking	10	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102C	Classroom 102 Storage	W3	Plaster	Tan	Partially Inaccessible/ Cracking	3	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102C	Classroom 102 Storage	W4	Plaster	Tan	Partially Inaccessible/ Cracking	7	36.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102C	Classroom 102 Storage	Ceiling	Plaster	White	Flaking	3	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	102C	Classroom 102 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	103	Classroom 103	W1	Plaster	Tan	Chipping	2	35.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	103	Classroom 103	W2	Plaster	Tan	Efflorescence	6	34.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	103	Classroom 103	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	2	5.9	Positive	
1230	1	1	103	Classroom 103	W3	Plaster	Tan	Flaking	6	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	103	Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	2	6.1	Positive	
1230	1	1	103	Classroom 103	W4	Plaster	Tan	Chipping	2	29.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	103	Classroom 103	Ceiling	Plaster	White	Flaking	6	15.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P aster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	1	103	Classroom 103	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103A	Classroom 103 Restroom	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103A	Classroom 103 Restroom	W2	Plaster	Tan	Flaking	3	24.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103A	Classroom 103 Restroom	W3	Plaster	Tan	Flaking	3	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103A	Classroom 103 Restroom	W4	Plaster	Tan	Flaking	1	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103A	Classroom 103 Restroom	Ceiling	Concrete	White	Cracking	3	15.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103A	Classroom 103 Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103B	Classroom 103 Storage	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103B	Classroom 103 Storage	W2	Plaster	Tan	Flaking	9	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103B	Classroom 103 Storage	W3	Plaster	Tan	Cracking	2	41.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103B	Classroom 103 Storage	W4	Plaster	Tan	Cracking	6	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103B	Classroom 103 Storage	Ceiling	Concrete	White	Cracking	1	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	103B	Classroom 103 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104A	Classroom 104 Storage	W1	Plaster	Tan	Chipping	1	35.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104A	Classroom 104 Storage	W2	Plaster	Tan	Chipping	1	41	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104A	Classroom 104 Storage	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104A	Classroom 104 Storage	W4	Plaster	Tan	Chipping	6	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104A	Classroom 104 Storage	Ceiling	Plaster	White	Cracking	1	5.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104A	Classroom 104 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104	Classroom 104	W1	Plaster	Tan	Cracking	3	22.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104	Classroom 104	W2	Plaster	Tan	Cracking	1	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104	Classroom 104	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	2	5.6	Positive
1230	1	1	104	Classroom 104	W3	Plaster	Tan	Chipping	3	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104	Classroom 104	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	1	7.1	Positive
1230	1	1	104	Classroom 104	W4	Plaster	Tan	Efflorescence	4	31.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104	Classroom 104	Ceiling	Plaster	White	Flaking	7	4.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	104	Classroom 104	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105	Classroom 105	W1	Plaster	Tan	Chipping	2	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105	Classroom 105	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.16	Negative
1230	1	1	105	Classroom 105	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	2	0.32	Negative
1230	1	1	105	Classroom 105	W2	Plaster	Tan	Chipping	2	31.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105	Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Cracking	1	6.2	Positive
1230	1	1	105	Classroom 105	W3	Plaster	Tan	Cracking	8	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105	Classroom 105	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	1	0.25	Negative
1230	1	1	105	Classroom 105	W4	Plaster	Tan	Chipping	2	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105	Classroom 105	Ceiling	Plaster	Tan	Flaking	3	9.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105	Classroom 105	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105A	Classroom 105 Storage	W1	Plaster	Tan	Chipping	1	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105A	Classroom 105 Storage	W2	Plaster	Tan	Cracking	12	31.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105A	Classroom 105 Storage	W3	Plaster	Tan	Cracking	2	18.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105A	Classroom 105 Storage	W4	Plaster	Tan	Chipping	9	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105A	Classroom 105 Storage	Ceiling	Plaster	Tan	Cracking	4	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	105A	Classroom 105 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106	Classroom 106	W1	Plaster	Tan	Chipping	4	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106	Classroom 106	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	2	0.3	Negative
1230	1	1	106	Classroom 106	W2	Plaster	Tan	Chipping	3	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106	Classroom 106	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	2	0.45	Negative
1230	1	1	106	Classroom 106	W3	Plaster	Tan	Flaking	9	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106	Classroom 106	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	1	5.2	Positive
1230	1	1	106	Classroom 106	W4	Plaster	Tan	Chipping	1	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106	Classroom 106	Ceiling	Plaster	Tan	Cracking	3	12.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106	Classroom 106	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Paster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	1	1	106A	Classroom 106 Storage	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106A	Classroom 106 Storage	W2	Plaster	Tan	Cracking	11	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106A	Classroom 106 Storage	W3	Plaster	Tan	Chipping	4	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106A	Classroom 106 Storage	W4	Plaster	Tan	Flaking	16	33.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106A	Classroom 106 Storage	Ceiling	Plaster	Tan	Flaking	3	8.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	106A	Classroom 106 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107	Classroom 107	W1	Plaster	Tan	Chipping	8	38	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107	Classroom 107	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.22	Negative
1230	1	1	107	Classroom 107	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	1	0.24	Negative
1230	1	1	107	Classroom 107	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	1	7.1	Positive
1230	1	1	107	Classroom 107	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0.32	Negative
1230	1	1	107	Classroom 107	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	1	8.2	Positive
1230	1	1	107	Classroom 107	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Brown	Chipping	4	0.25	Negative
1230	1	1	107	Classroom 107	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107	Classroom 107	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107	Classroom 107	Ceiling	Metal	White	Flaking	400	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107	Classroom 107	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107A	Classroom 107 Storage	W1	Plaster	Tan	Chipping	1	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107A	Classroom 107 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.32	Negative
1230	1	1	107A	Classroom 107 Storage	W2	Plaster	Tan	Cracking	19	18.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107A	Classroom 107 Storage	W3	Plaster	Tan	Cracking	9	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107A	Classroom 107 Storage	W4	Plaster	Tan	Flaking	10	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107A	Classroom 107 Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.18	Negative
1230	1	1	107A	Classroom 107 Storage	Ceiling	Metal	White	Flaking	120	5.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	107A	Classroom 107 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108	Classroom 108	W1	Plaster	Blue	Chipping	8	31.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108	Classroom 108	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	wood	brown	Chipping	1	0.4	Negative
1230	1	1	108	Classroom 108	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	wood	brown	Chipping	2	0.25	Negative
1230	1	1	108	Classroom 108	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108	Classroom 108	W3	Plaster	Blue	Chipping	12	36.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108	Classroom 108	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	metal	silver	Chipping	1	5.7	Positive
1230	1	1	108	Classroom 108	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	wood	brown	Chipping	2	0.3	Negative
1230	1	1	108	Classroom 108	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	N/A	white	Flaking	1	0.34	Negative
1230	1	1	108	Classroom 108	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108	Classroom 108	Ceiling	Metal	White	Flaking	400	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108	Classroom 108	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108A	Classroom 108 Storage	W1	Plaster	Blue	Chipping	10	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108A	Classroom 108 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	wood	brown	Chipping	1	0.4	Negative
1230	1	1	108A	Classroom 108 Storage	W2	Plaster	Blue	Cracking	2	29.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108A	Classroom 108 Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	wood	brown	Chipping	1	0.26	Negative
1230	1	1	108A	Classroom 108 Storage	W3	Plaster	Blue	Cracking	100	16.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108A	Classroom 108 Storage	W4	Wood	Blue	Chipping	10	34.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108A	Classroom 108 Storage	Ceiling	Metal	White	Flaking	120	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	108A	Classroom 108 Storage	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	109	Main Office	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	109	Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	2	0.31	Negative
1230	1	1	109	Main Office	W2	Sheetrock	White	Chipping	3	0.18	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	109	Main Office	W3	Plaster	White	Partially Inaccessible/ Cracking	6	33.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	109	Main Office	W4	Plaster	White	Partially Inaccessible/ Flaking	8	30.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																				
Lead Safe Certification Assessment Report																				
Bryant Promise Academy Elementary School #1230																				
						Inspection Company: Synertech, Inc.														
						Name of Inspector: Bart McMahon/Ryan Hutsell														
						Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)		
1230	1	1	109	Main Office	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	109	Main Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	109A	Storage/Telephone/Control Room in Main Office	W1	Plaster	White	Flaking	26	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	109A	Storage/Telephone/Control Room in Main Office	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	109A	Storage/Telephone/Control Room in Main Office	W3	Plaster	White	Cracking	25	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	109A	Storage/Telephone/Control Room in Main Office	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	109A	Storage/Telephone/Control Room in Main Office	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	109A	Storage/Telephone/Control Room in Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.39	Negative		
1230	1	1	109A	Storage/Telephone/Control Room in Main Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110	Nurse's Suite - Rear Office	W1	Plaster	White	Chipping	5	32.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110	Nurse's Suite - Rear Office	W2	Plaster	White	Flaking	12	29.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110	Nurse's Suite - Rear Office	W3	Plaster	White	Flaking	10	31.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110	Nurse's Suite - Rear Office	W4	Plaster	White	Flaking	4	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110	Nurse's Suite - Rear Office	Ceiling	Plaster	White	Flaking	4	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110	Nurse's Suite - Rear Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110A	Nurse's Office	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110A	Nurse's Office	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110A	Nurse's Office	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110A	Nurse's Office	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110A	Nurse's Office	Ceiling	Plaster	White	Flaking	2	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110A	Nurse's Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110B	Nurse's Office Restroom	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110B	Nurse's Office Restroom	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110B	Nurse's Office Restroom	W3	Plaster	White	Flaking	12	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110B	Nurse's Office Restroom	W4	Plaster	White	Cracking	6	27.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110B	Nurse's Office Restroom	Ceiling	Plaster	White	Flaking	2	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110B	Nurse's Office Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110C	Office in Small Hallway next to Nurse's Office	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110C	Office in Small Hallway next to Nurse's Office	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110C	Office in Small Hallway next to Nurse's Office	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110C	Office in Small Hallway next to Nurse's Office	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110C	Office in Small Hallway next to Nurse's Office	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110C	Office in Small Hallway next to Nurse's Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110D	Boy's Restroom in Small Hallway next to Nurse's Office	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110D	Boy's Restroom in Small Hallway next to Nurse's Office	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110D	Boy's Restroom in Small Hallway next to Nurse's Office	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110D	Boy's Restroom in Small Hallway next to Nurse's Office	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110D	Boy's Restroom in Small Hallway next to Nurse's Office	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	110D	Boy's Restroom in Small Hallway next to Nurse's Office	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	1	110E	Girl's Restroom in Small Hallway next to Nurse's Office	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110E	Girl's Restroom in Small Hallway next to Nurse's Office	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110E	Girl's Restroom in Small Hallway next to Nurse's Office	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110E	Girl's Restroom in Small Hallway next to Nurse's Office	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110E	Girl's Restroom in Small Hallway next to Nurse's Office	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110E	Girl's Restroom in Small Hallway next to Nurse's Office	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110F	Small Hallway next to Nurse's Office	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110F	Small Hallway next to Nurse's Office	W2	Plaster	White	Flaking	15	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110F	Small Hallway next to Nurse's Office	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110F	Small Hallway next to Nurse's Office	W4	Plaster	White	Flaking	20	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110F	Small Hallway next to Nurse's Office	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110F	Small Hallway next to Nurse's Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	111	Classroom 111	W1	Plaster	Tan	Chipping	2	20.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	111	Classroom 111	W2	Plaster	Tan	Chipping	2	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	111	Classroom 111	W3	Plaster	Tan	Efflorescence	12	40.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	111	Classroom 111	W4	Plaster	Tan	Chipping	3	35.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	111	Classroom 111	Ceiling	Plaster	White	Cracking	1	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	111	Classroom 111	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112	Classroom 112	W1	Plaster	Grey	Chipping	2	27.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112	Classroom 112	W2	Plaster	Grey	Chipping	2	33.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112	Classroom 112	W3	Plaster	Grey	Cracking	7	34.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112	Classroom 112	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Cracking	1	7.3	Positive
1230	1	1	112	Classroom 112	W4	Plaster	Grey	Chipping	2	29.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112	Classroom 112	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112	Classroom 112	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112B	Classroom 112 Storage	W1	Plaster	Tan	Chipping	1	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112B	Classroom 112 Storage	W2	Plaster	Tan	Efflorescence	8	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112B	Classroom 112 Storage	W3	Plaster	Tan	Flaking	6	28.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112B	Classroom 112 Storage	W4	Plaster	Tan	Flaking	12	30.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112B	Classroom 112 Storage	Ceiling	Plaster	Tan	Cracking	9	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	112B	Classroom 112 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113	Classroom 113	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.31	Negative
1230	1	1	113	Classroom 113	W1	Plaster	Tan	Chipping	3	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113	Classroom 113	W2	N/A	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113	Classroom 113	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113	Classroom 113	W3	Plaster	Tan	Chipping	1	22.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113	Classroom 113	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113	Classroom 113	Ceiling	Plaster	Tan	Cracking	12	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113	Classroom 113	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113A	Classroom 113 Storage	W1	Plaster	Tan	Chipping	1	29.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113A	Classroom 113 Storage	W2	Plaster	Tan	Chipping	2	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113A	Classroom 113 Storage	W3	Plaster	Tan	Cracking	6	22.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113A	Classroom 113 Storage	W4	Plaster	Tan	Chipping	1	25.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113A	Classroom 113 Storage	Ceiling	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	113A	Classroom 113 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114	Classroom 114	W1	Plaster	Blue	Cracking	7	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114	Classroom 114	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Blue	Chipping	2	0.16	Negative
1230	1	1	114	Classroom 114	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Blue	Chipping	1	0.19	Negative
1230	1	1	114	Classroom 114	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	brown	Chipping	1	0.24	Negative

School District of Philadelphia Lead Safe Certification Assessment Report Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	1	114	Classroom 114	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114	Classroom 114	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	1	6.9	Positive
1230	1	1	114	Classroom 114	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Blue	Chipping	2	0.3	Negative
1230	1	1	114	Classroom 114	W3	Plaster	Blue	Flaking	16	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114	Classroom 114	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Blue	Chipping	2	0.26	Negative
1230	1	1	114	Classroom 114	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Blue	Chipping	1	0.12	Negative
1230	1	1	114	Classroom 114	W4	Plaster	Blue	Cracking	4	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114	Classroom 114	Ceiling	Metal	White	Flaking	400	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114	Classroom 114	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114B	Classroom 114 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Blue	Chipping	2	0.23	Negative
1230	1	1	114B	Classroom 114 Storage	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114B	Classroom 114 Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	brown	Chipping	1	0.18	Negative
1230	1	1	114B	Classroom 114 Storage	W3	Plaster	Blue	Cracking	7	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114B	Classroom 114 Storage	W4	Plaster	Blue	Flaking	9	31.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114B	Classroom 114 Storage	Ceiling	Metal	White	Flaking	12	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114B	Classroom 114 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114A	Boy's Restroom across from Classroom 106	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114A	Boy's Restroom across from Classroom 106	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114A	Boy's Restroom across from Classroom 106	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114A	Boy's Restroom across from Classroom 106	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114A	Boy's Restroom across from Classroom 106	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114A	Boy's Restroom across from Classroom 106	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114C	Custodial Storage in the Hallway by Boys Restroom	W1	Plaster	Blue	Cracking	3	36.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114C	Custodial Storage in the Hallway by Boys Restroom	W2	Plaster	Blue	Chipping	2	31.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	114C	Custodial Storage in the Hallway by Boys Restroom	W3	Plaster	Blue	Chipping	2	28.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110JC	Custodial Storage in the Hallway by Nurse's Office	W4	Plaster	Blue	Chipping	1	22.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110JC	Custodial Storage in the Hallway by Nurse's Office	Ceiling	Plaster	Blue	Chipping	3	11.5	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	110JC	Custodial Storage in the Hallway by Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H11	Hallway at Classrooms 112 to 114	W1	Plaster	White	Chipping	10	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H11	Hallway at Classrooms 112 to 114	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.24	Negative
1230	1	1	H11	Hallway at Classrooms 112 to 114	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H11	Hallway at Classrooms 112 to 114	W3	Plaster	White	Chipping	10	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H11	Hallway at Classrooms 112 to 114	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	5	0.31	Negative
1230	1	1	H11	Hallway at Classrooms 112 to 114	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H11	Hallway at Classrooms 112 to 114	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H11	Hallway at Classrooms 112 to 114	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H12	Main Hallway at Classroom 103 to Main Office	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H12	Main Hallway at Classroom 103 to Main Office	W2	Plaster	White	Chipping	30	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H12	Main Hallway at Classroom 103 to Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	2	0.28	Negative
1230	1	1	H12	Main Hallway at Classroom 103 to Main Office	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H12	Main Hallway at Classroom 103 to Main Office	W4	Plaster	White	Chipping	45	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H12	Main Hallway at Classroom 103 to Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.34	Negative
1230	1	1	H12	Main Hallway at Classroom 103 to Main Office	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P aster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	1	H12	Main Hallway at Classroom 103 to Main Office	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H13	Hallway at Classroom 102	W1	Plaster	White	Chipping	16	28.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H13	Hallway at Classroom 102	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	5	0.32	Negative
1230	1	1	H13	Hallway at Classroom 102	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H13	Hallway at Classroom 102	W3	Plaster	White	Flaking	6	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H13	Hallway at Classroom 102	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	3	0.35	Negative
1230	1	1	H13	Hallway at Classroom 102	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	H13	Hallway at Classroom 102	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	W1	Plaster	White	Chipping	4	28.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	W2	Plaster	White	Chipping	12	38.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	W3	Plaster	White	Chipping	6	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	W4	Plaster	White	Chipping	15	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S12	Stairwell B at Main Office	W1	Plaster	White	Cracking	4	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S12	Stairwell B at Main Office	W2	Plaster	White	Chipping	14	35.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S12	Stairwell B at Main Office	W3	Plaster	White	Chipping	10	36.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S12	Stairwell B at Main Office	W4	Plaster	White	Cracking	8	18.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S12	Stairwell B at Main Office	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S12	Stairwell B at Main Office	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S12	Stairwell B at Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	4	1	Positive
1230	1	1	S13	Stairwell C at Classroom 103	W1	Plaster	White	Chipping	8	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S13	Stairwell C at Classroom 103	W2	Plaster	White	Chipping	6	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S13	Stairwell C at Classroom 103	W3	Plaster	White	Chipping	12	7.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S13	Stairwell C at Classroom 103	W4	Plaster	White	Chipping	6	33.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S13	Stairwell C at Classroom 103	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S13	Stairwell C at Classroom 103	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200	Teacher's Lounge	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200	Teacher's Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	3	0.04	Negative
1230	1	2	200	Teacher's Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	3	0.16	Negative
1230	1	2	200	Teacher's Lounge	W2	Plaster	Tan	Flaking	8	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200	Teacher's Lounge	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	2	0.32	Negative
1230	1	2	200	Teacher's Lounge	W3	Plaster	Tan	Chipping	20	32.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200	Teacher's Lounge	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	6	0.26	Negative
1230	1	2	200	Teacher's Lounge	W4	Plaster	Tan	Cracking	4	20.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200	Teacher's Lounge	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200	Teacher's Lounge	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200A	Teacher's Lounge Restroom	W1	Plaster	Tan	Chipping	1	39.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200A	Teacher's Lounge Restroom	W2	Plaster	Tan	Chipping	8	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200A	Teacher's Lounge Restroom	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200A	Teacher's Lounge Restroom	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200A	Teacher's Lounge Restroom	Ceiling	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200A	Teacher's Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200B	Girl's Restroom next to Teacher's Lounge	W1	Plaster	Tan	Cracking	1	18.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200B	Girl's Restroom next to Teacher's Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	0.14	Negative
1230	1	2	200B	Girl's Restroom next to Teacher's Lounge	W2	Plaster	Tan	Cracking	1	33.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200B	Girl's Restroom next to Teacher's Lounge	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200B	Girl's Restroom next to Teacher's Lounge	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	1	0.2	Negative
1230	1	2	200B	Girl's Restroom next to Teacher's Lounge	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200B	Girl's Restroom next to Teacher's Lounge	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200B	Girl's Restroom next to Teacher's Lounge	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200C5	Teacher's Lounge Restroom	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200C5	Teacher's Lounge Restroom	W2	Plaster	Tan	Chipping	10	35.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	200C5	Teacher's Lounge Restroom	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																				
Lead Safe Certification Assessment Report																				
Bryant Promise Academy Elementary School #1230																				
					Inspection Company: Synertech, Inc.															
					Name of Inspector: Bart McMahon/Ryan Hutsell															
					Inspection Dates: 06/17-06/27/2019															
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Paster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)		
1230	1	2	200C5	Teacher's Lounge Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	4	0.16	Negative		
1230	1	2	200C6	Teacher's Lounge Restroom	W4	Plaster	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	200C5	Teacher's Lounge Restroom	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	200C5	Teacher's Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	200D	Custodial Storage outside Teachers Lounge Room 200	W1	Plaster	White	Cracking	8	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	200D	Custodial Storage outside Teachers Lounge Room 201	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	3	0.12	Negative		
1230	1	2	200D	Custodial Storage outside Teachers Lounge Room 201	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Tan	Chipping	20	0.37	Negative		
1230	1	2	200D	Custodial Storage outside Teachers Lounge Room 200	W2	Plaster	White	Cracking	10	39.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	200D	Custodial Storage outside Teachers Lounge Room 200	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	200D	Custodial Storage outside Teachers Lounge Room 200	W4	Plaster	White	Cracking	6	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	200D	Custodial Storage outside Teachers Lounge Room 200	Ceiling	Metal	White	Chipping	10	13.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	200D	Custodial Storage outside Teachers Lounge Room 200	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	201	Classroom 201	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	201	Classroom 201	W2	Plaster	Tan	Partially Inaccessible/ Chipping	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	201	Classroom 202	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	6	5.4	Positive		
1230	1	2	201	Classroom 201	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	201	Classroom 201	W4	Plaster	Tan	Efflorescence	4	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	201	Classroom 201	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	201	Classroom 201	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	201A	Classroom 201 Storage near window wall	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201A	Classroom 201 Storage near window wall	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201A	Classroom 201 Storage near window wall	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201A	Classroom 201 Storage near window wall	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201A	Classroom 201 Storage near window wall	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201A	Classroom 201 Storage near window wall	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201B	Classroom 201 Storage next to doorway	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201B	Classroom 201 Storage next to doorway	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201B	Classroom 201 Storage next to doorway	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201B	Classroom 201 Storage next to doorway	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201B	Classroom 201 Storage next to doorway	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201B	Classroom 201 Storage next to doorway	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201C	Custodial Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201C	Custodial Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201C	Custodial Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201C	Custodial Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201C	Custodial Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	201C	Custodial Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		
1230	1	2	202	Classroom 202	W1	Plaster	Tan	Chipping	8	31.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	202	Classroom 202	W2	Plaster	Tan	Efflorescence	2	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	202	Classroom 202	W3	Plaster	Tan	Efflorescence	10	39.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	202	Classroom 202	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	10	6.2	Positive		
1230	1	2	202	Classroom 202	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	202	Classroom 202	Ceiling	Plaster	White	Efflorescence	3	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	202	Classroom 202	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	2	202A	Classroom 202 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		

School District of Philadelphia																			
Lead Safe Certification Assessment Report																			
Bryant Promise Academy Elementary School #1230																			
				Inspection Company: Synertech, Inc.															
				Name of Inspector: Bart McMahon/Ryan Hutsell															
				Inspection Dates: 06/17-06/27/2019															
ULC #	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	
1230	1	2	202A	Classroom 202 Storage	W2	Plaster	White	Chipping	20	36.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202A	Classroom 202 Storage	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202A	Classroom 202 Storage	W4	Plaster	White	Chipping	20	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202A	Classroom 202 Storage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202A	Classroom 202 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	W2	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	Ceiling	Plaster	Tan	Chipping	30	9.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203	Classroom 203	W1	Plaster	Tan	Chipping	4	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203	Classroom 203	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	15	0.1	Negative	
1230	1	2	203	Classroom 203	W2	Plaster	Tan	Chipping	6	26.9	Positive	Door Frame	Wood	Brown	Chipping	5	0.1	Negative	
1230	1	2	203	Classroom 203	W3	Plaster	Tan	Efflorescence	8	38.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203	Classroom 203	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203	Classroom 203	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203	Classroom 203	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203A	Classroom 203 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203A	Classroom 203 Storage	W2	Plaster	White	Chipping	20	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203A	Classroom 203 Storage	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203A	Classroom 203 Storage	W4	Plaster	White	Chipping	20	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203A	Classroom 203 Storage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	203A	Classroom 203 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204	Classroom 204	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204	Classroom 204	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	4	0.21	Negative	
1230	1	2	204	Classroom 204	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	7	0.18	Negative	
1230	1	2	204	Classroom 204	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204	Classroom 204	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	4	0.21	Negative	
1230	1	2	204	Classroom 204	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	2	0.08	Negative	
1230	1	2	204	Classroom 204	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204	Classroom 204	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204	Classroom 204	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	10	0.12	Negative	
1230	1	2	204	Classroom 204	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204	Classroom 204	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204A	Classroom 204 Storage	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204A	Classroom 204 Storage	W2	Plaster	White	Chipping	20	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204A	Classroom 204 Storage	W3	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204A	Classroom 204 Storage	W4	Plaster	White	Chipping	20	25.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204A	Classroom 204 Storage	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	204A	Classroom 204 Storage	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	205	Classroom 205	W1	Plaster	Tan	Chipping	3	38.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	205	Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.25	Negative	
1230	1	2	205	Classroom 205	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	6	0.16	Negative	
1230	1	2	205	Classroom 205	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	8	0.12	Negative	

School District of Philadelphia Lead Safe Certification Assessment Report Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	F l o o r	S p a c e #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Primer Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	1	2	205	Classroom 205	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205	Classroom 205	W3	Concrete	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	3	0.27	Negative
1230	1	2	205	Classroom 205	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	6	0.32	Negative
1230	1	2	205	Classroom 205	W3	Plaster	Tan	Efflorescence	6	22.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205	Classroom 205	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205	Classroom 205	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	3	0.14	Negative
1230	1	2	205	Classroom 205	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205	Classroom 205	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205A	Classroom 205 Storage	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205A	Classroom 205 Storage	W2	Plaster	White	Chipping	20	39.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205A	Classroom 205 Storage	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205A	Classroom 205 Storage	W4	Plaster	White	Chipping	20	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205A	Classroom 205 Storage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	205A	Classroom 205 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206	Classroom 206	W1	Plaster	Tan	Chipping	10	19.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206	Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	2	0.23	Negative
1230	1	2	206	Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	3	0.26	Negative
1230	1	2	206	Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	2	0.15	Negative
1230	1	2	206	Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	5	0.13	Negative
1230	1	2	206	Classroom 206	W2	Plaster	Tan	Chipping	1	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206	Classroom 206	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	4	0.27	Negative
1230	1	2	206	Classroom 206	W3	Plaster	Tan	Chipping	16	20.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206	Classroom 206	W4	Plaster	Tan	Chipping	1	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206	Classroom 206	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	5	0.19	Negative
1230	1	2	206	Classroom 206	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206	Classroom 206	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206A	Classroom 206 Storage	W1	Plaster	White	Cracking	1	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206A	Classroom 206 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Cracking	1	0.25	Negative
1230	1	2	206A	Classroom 206 Storage	W2	Plaster	White	Cracking	20	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206A	Classroom 206 Storage	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206A	Classroom 206 Storage	W4	Plaster	White	Cracking	20	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206A	Classroom 206 Storage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206A	Classroom 206 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214A	Boy's Restroom across from Classroom 206	W1	Plaster	Tan	Cracking	3	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214A	Boy's Restroom across from Classroom 206	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214A	Boy's Restroom across from Classroom 206	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214A	Boy's Restroom across from Classroom 206	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214A	Boy's Restroom across from Classroom 206	Ceiling	Plaster	White	Flaking	3	4.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214A	Boy's Restroom across from Classroom 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	5	0.41	Negative
1230	1	2	214A	Boy's Restroom across from Classroom 206	Floor	Concrete	Gray	Cracking	5	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	207	Classroom 207	W1	Plaster	Purple	Chipping	6	27.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	207	Classroom 207	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	20	0.26	Negative
1230	1	2	207	Classroom 207	W2	Plaster	Purple	Chipping	4	17.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	207	Classroom 207	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	20	7.1	Positive
1230	1	2	207	Classroom 207	W3	Plaster	Purple	Chipping	40	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	207	Classroom 207	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	207	Classroom 207	Ceiling	Metal	White	Flaking	400	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	207	Classroom 207	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	207A	Classroom 207 Storage	W1	Plaster	White	Chipping	1	36.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																			
Lead Safe Certification Assessment Report																			
Bryant Promise Academy Elementary School #1230																			
				Inspection Company: Synertech, Inc.															
				Name of Inspector: Bart McMahon/Ryan Hutsell															
				Inspection Dates: 06/17-06/27/2019															
ULC #	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	
1230	1	2	207A	Classroom 207 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	3	0.26	Negative	
1230	1	2	207A	Classroom 207 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	White	Chipping	3	0.21	Negative	
1230	1	2	207A	Classroom 207 Storage	W2	Plaster	White	Chipping	30	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	207A	Classroom 207 Storage	W3	Plaster	White	Chipping	15	18.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	207A	Classroom 207 Storage	W4	Plaster	White	Chipping	20	18.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	207A	Classroom 207 Storage	Ceiling	Metal	White	Flaking	200	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	207A	Classroom 207 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208	Classroom 208	W1	Plaster	Tan	Chipping	5	34.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208	Classroom 208	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208	Classroom 208	W3	Plaster	Tan	Chipping	10	27	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208	Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	3	0.02	Negative	
1230	1	2	208	Classroom 208	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208	Classroom 208	Ceiling	Metal	White	Flaking	400	15.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208	Classroom 208	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208A	Classroom 208 Storage	W1	Plaster	Yellow	Flaking	10	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208A	Classroom 208 Storage	W2	Plaster	Yellow	Chipping	5	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208A	Classroom 208 Storage	W3	Plaster	Yellow	Chipping	20	31.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208A	Classroom 208 Storage	W4	Plaster	Yellow	Chipping	1	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208A	Classroom 208 Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	1	0.19	Negative	
1230	1	2	208A	Classroom 208 Storage	Ceiling	Metal	White	Flaking	40	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	208A	Classroom 208 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209	Classroom 209	W1	Plaster	Tan	Chipping	10	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209	Classroom 209	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	6	0.27	Negative	
1230	1	2	209	Classroom 209	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209	Classroom 209	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209	Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Flaking	3	0.25	Negative	
1230	1	2	209	Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	10	4.1	Positive	
1230	1	2	209	Classroom 209	W4	Plaster	Tan	Flaking	15	35.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209	Classroom 209	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	6	5.4	Positive	
1230	1	2	209	Classroom 209	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Tan	Chipping	1	0.28	Negative	
1230	1	2	209	Classroom 210	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	1	0.15	Negative	
1230	1	2	209	Classroom 209	Ceiling	Metal	White	Flaking	400	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209	Classroom 209	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209A	Classroom 209 Storage	W1	Plaster	White	Chipping	15	36.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209A	Classroom 209 Storage	W2	Plaster	White	Chipping	18	24.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209A	Classroom 209 Storage	W3	Plaster	White	Chipping	20	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209A	Classroom 209 Storage	W4	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209A	Classroom 209 Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	1	0.19	Negative	
1230	1	2	209A	Classroom 209 Storage	Ceiling	Metal	White	Chipping	40	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	209A	Classroom 209 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	210	Classroom 210	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	210	Classroom 210	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Partially Inaccessible/Chip ping	10	0.2	Negative	
1230	1	2	210	Classroom 210	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	210	Classroom 210	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	6	0.13	Negative	
1230	1	2	210	Classroom 210	W3	Plaster	White	Efflorescence	6	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	210	Classroom 210	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	13	3.9	Positive	
1230	1	2	210A	Classroom 210	W4	Plaster	White	Chipping	4	16	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	210A	Classroom 210	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	210A	Classroom 210	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	210A	Classroom 210 Closet	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	2	210A	Classroom 210 Closet	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	210A	Classroom 210 Closet	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	210A	Classroom 210 Closet	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	210A	Classroom 210 Closet	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	210A	Classroom 210 Closet	Floor	Wood	Brown	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211	Classroom 211	W1	Plaster	Tan	Chipping	3	22	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211	Classroom 211	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	12	0.22	Negative
1230	1	2	211	Classroom 211	W2	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211	Classroom 211	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	10	0.18	Negative
1230	1	2	211	Classroom 211	W3	Plaster	Tan	Cracking	2	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211	Classroom 211	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	40	5.1	Positive
1230	1	2	211	Classroom 211	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211	Classroom 211	Ceiling	Plaster	White	Chipping	1	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211	Classroom 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	3	0.34	Negative
1230	1	2	211	Classroom 211	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211A	Classroom 211 Storage	W1	Plaster	White	Chipping	1	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211A	Classroom 211 Storage	W2	Plaster	White	Chipping	3	28.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211A	Classroom 211 Storage	W3	Plaster	White	Chipping	1	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211A	Classroom 211 Storage	W4	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211A	Classroom 211 Storage	Ceiling	N/A	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211A	Classroom 211 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211A	Classroom 211 Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	7	0.21	Negative
1230	1	2	212	Classroom 212	W1	Plaster	Tan	Chipping	6	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212	Classroom 212	W2	Plaster	Tan	Chipping	2	17.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212	Classroom 212	W3	Plaster	Tan	Chipping	10	31.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212	Classroom 212	W4	Wood	Tan	Chipping	3	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212	Classroom 212	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212	Classroom 212	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212A	Classroom 212 Storage	W1	Plaster	White	Chipping	2	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212A	Classroom 212 Storage	W2	Plaster	White	Chipping	10	20.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212A	Classroom 212 Storage	W3	Plaster	White	Chipping	1	17.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212A	Classroom 212 Storage	W4	Plaster	White	Chipping	10	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212A	Classroom 212 Storage	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	212A	Classroom 212 Storage	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213	Classroom 213	W1	Plaster	Tan	Chipping	2	30.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213	Classroom 213	W2	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213	Classroom 213	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213	Classroom 213	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Flaking	20	6.2	Positive
1230	1	2	213	Classroom 213	W4	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213	Classroom 213	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213	Classroom 213	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213A	Classroom 213 Storage	W1	Plaster	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213A	Classroom 213 Storage	W2	Plaster	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213A	Classroom 213 Storage	W3	Plaster	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213A	Classroom 213 Storage	W4	Plaster	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia Lead Safe Certification Assessment Report Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Paster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	1	2	213A	Classroom 213 Storage	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213A	Classroom 213 Storage	Floor	Wood	Brown	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214	Classroom 214	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214	Classroom 214	W2	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214	Classroom 214	W3	Plaster	Tan	Chipping	3	29.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214	Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	20	3.9	Positive
1230	1	2	214	Classroom 214	W4	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214	Classroom 214	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214	Classroom 214	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214B	Classroom 214 Storage	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214B	Classroom 214 Storage	W2	Plaster	White	Chipping	15	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214B	Classroom 214 Storage	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214B	Classroom 214 Storage	W4	Plaster	White	Chipping	15	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214B	Classroom 214 Storage	Ceiling	Plaster	White	Chipping	20	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214B	Classroom 214 Storage	Floor	Wood	Brown	Partially Inaccessible			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H21	Hallway at Classrooms 210 to 214	W1	Plaster	White	Chipping	8	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H21	Hallway at Classrooms 210 to 214	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.28	Negative
1230	1	2	H21	Hallway at Classrooms 210 to 214	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H21	Hallway at Classrooms 210 to 214	W3	Plaster	White	Chipping	12	34.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H21	Hallway at Classrooms 210 to 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.28	Negative
1230	1	2	H21	Hallway at Classrooms 210 to 214	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H21	Hallway at Classrooms 210 to 214	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H21	Hallway at Classrooms 210 to 214	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H22	Main Hallway at Classroom 203 to 209	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H22	Main Hallway at Classroom 203 to 209	W2	Plaster	White	Chipping	14	29.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H22	Main Hallway at Classroom 203 to 209	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	5	0.19	Negative
1230	1	2	H22	Main Hallway at Classroom 203 to 209	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H22	Main Hallway at Classroom 203 to 209	W4	Plaster	White	Flaking	18	34.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H22	Main Hallway at Classroom 203 to 209	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.34	Negative
1230	1	2	H22	Main Hallway at Classroom 203 to 209	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H22	Main Hallway at Classroom 203 to 209	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H23	Hallway at Classroom 202	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H23	Hallway at Classroom 202	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H23	Hallway at Classroom 202	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H23	Hallway at Classroom 202	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H23	Hallway at Classroom 202	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	H23	Hallway at Classroom 202	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S21	Stairwell A at Classroom 210	W1	Plaster	White	Chipping	3	29.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S21	Stairwell A at Classroom 210	W2	Plaster	White	Chipping	16	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S21	Stairwell A at Classroom 210	W3	Plaster	White	Chipping	4	27.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S21	Stairwell A at Classroom 210	W4	Plaster	White	Chipping	12	28.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S21	Stairwell A at Classroom 210	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S21	Stairwell A at Classroom 210	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S22	Stairwell B at Classroom 209	W1	Plaster	White	Chipping	4	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S22	Stairwell B at Classroom 209	W2	Plaster	White	Chipping	10	29.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S22	Stairwell B at Classroom 209	W3	Plaster	White	Chipping	6	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S22	Stairwell B at Classroom 209	W4	Plaster	White	Chipping	6	30.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S22	Stairwell B at Classroom 209	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S22	Stairwell B at Classroom 209	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S22	Stairwell B at Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	3	0.9	Positive
1230	1	2	S23	Stairwell C at Classroom 203	W1	Plaster	White	Chipping	12	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S23	Stairwell C at Classroom 203	W2	Plaster	White	Chipping	10	17.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S23	Stairwell C at Classroom 203	W3	Plaster	White	Chipping	10	18.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																			
Lead Safe Certification Assessment Report																			
Bryant Promise Academy Elementary School #1230																			
				Inspection Company: Synertech, Inc.															
				Name of Inspector: Bart McMahon/Ryan Hutsell															
				Inspection Dates: 06/17-06/27/2019															
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P aster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	
1230	1	2	S23	Stairwell C at Classroom 203	W4	Plaster	White	Chipping	8	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	S23	Stairwell C at Classroom 203	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	S23	Stairwell C at Classroom 203	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300	School Police Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	2	0.41	Negative	
1230	1	3	300	School Police Office	W1	Plaster	Tan	Chipping	19	32.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300	School Police Office	W2	Plaster	Tan	Chipping	12	37.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300	School Police Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	1	5.3	Positive	
1230	1	3	300	School Police Office	W3	Plaster	Tan	Partially Inaccessible/ Chipping	21	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300	School Police Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	1	6.1	Positive	
1230	1	3	300	School Police Office	W4	Plaster	Tan	Partially Inaccessible/Cr acking	9	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300	School Police Office	Ceiling	Plaster	Tan	Partially Inaccessible/Cr acking	12	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300	School Police Office	Floor	N/A	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300A	School Police Office Restroom	W1	Plaster	Tan	Flaking	6	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300A	School Police Office Restroom	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300A	School Police Office Restroom	W3	Plaster	Tan	Flaking	60	36.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300A	School Police Office Restroom	W4	Plaster	Tan	Chipping	1	29.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300A	School Police Office Restroom	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300A	School Police Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300B	Girl's Restroom near School Police Office	W1	Plaster	Tan	Chipping	3	24.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300B	Girl's Restroom near School Police Office	W2	Plaster	Tan	Flaking	12	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300B	Girl's Restroom near School Police Office	W3	Plaster	Tan	Flaking	3	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300B	Girl's Restroom near School Police Office	W4	Plaster	Tan	Efflorescence	3	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300B	Girl's Restroom near School Police Office	Ceiling	Plaster	White	Cracking	6	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300B	Girl's Restroom near School Police Office	Floor	Concrete	Brown	Chipping	9	2.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300C	School Police Office Restroom	W1	Plaster	Tan	Chipping	1	31.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300C	School Police Office Restroom	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300C	School Police Office Restroom	W3	Plaster	Tan	Cracking	55	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300C	School Police Office Restroom	W4	Plaster	Tan	Chipping	40	24.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300C	School Police Office Restroom	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300C	School Police Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300D	Custodial Storage outside School Police Office	W1	Plaster	Tan	Chipping	3	22.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300D	Custodial Storage outside School Police Office	W2	Plaster	Tan	Flaking	12	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300D	Custodial Storage outside School Police Office	W3	Plaster	Tan	Cracking	6	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300D	Custodial Storage outside School Police Office	W4	Plaster	Tan	Chipping	3	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300D	Custodial Storage outside School Police Office	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	300D	Custodial Storage outside School Police Office	Floor	Concrete	N/A	Chipping	2	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301	Computer Room	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301	Computer Room	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	1	4.8	Positive	
1230	1	3	301	Computer Room	W2	Plaster	Tan	Flaking	3	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301	Computer Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	2	5.2	Positive	
1230	1	3	301	Computer Room	W3	Plaster	Tan	Flaking	9	30.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301	Computer Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	Stage	Wood	Brown	Chipping	1	0.1	Negative	
1230	1	3	301	Computer Room	W4	Plaster	Tan	Cracking	2	32.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301	Computer Room	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301	Computer Room	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

School District of Philadelphia																			
Lead Safe Certification Assessment Report																			
Bryant Promise Academy Elementary School #1230																			
				Inspection Company: Synertech, Inc.															
				Name of Inspector: Bart McMahon/Ryan Hutsell															
				Inspection Dates: 06/17-06/27/2019															
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	
1230	1	3	301A	Computer Room Storage by Window Wall	W1	Plaster	Blue	Cracking	1	37.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301A	Computer Room Storage by Window Wall	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301A	Computer Room Storage by Window Wall	W3	Plaster	Blue	Cracking	4	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301A	Computer Room Storage by Window Wall	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301A	Computer Room Storage by Window Wall	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301A	Computer Room Storage by Window Wall	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301B	Computer Room Storage by Doorway	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1230	1	3	301B	Computer Room Storage by Doorway	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1230	1	3	301B	Computer Room Storage by Doorway	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1230	1	3	301B	Computer Room Storage by Doorway	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1230	1	3	301B	Computer Room Storage by Doorway	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1230	1	3	301B	Computer Room Storage by Doorway	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1230	1	3	301C	Custodial Storage	W1	Plaster	White	Cracking	4	31.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301C	Custodial Storage	W2	Plaster	White	Flaking	8	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301C	Custodial Storage	W3	Plaster	White	Flaking	8	16.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301C	Custodial Storage	W4	Plaster	White	Flaking	5	31.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301C	Custodial Storage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	301C	Custodial Storage	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302	Classroom 302	W1	Plaster	Tan	Chipping	3	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302	Classroom 302	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.26	Negative	
1230	1	3	302	Classroom 302	W2	Plaster	Tan	Efflorescence	24	18.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302	Classroom 302	W3	Plaster	Tan	Efflorescence	16	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302	Classroom 302	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Brown	Chipping	4	0.31	Negative	
1230	1	3	302	Classroom 302	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302	Classroom 302	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Cracking	4	0.22	Negative	
1230	1	3	302	Classroom 302	Ceiling	Plaster	White	Efflorescence	16	31.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302	Classroom 302	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302A	Classroom 302 Storage	W1	Plaster	Tan	Cracking	1	36.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302A	Classroom 302 Storage	W2	Plaster	Tan	Flaking	1	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302A	Classroom 302 Storage	W3	Plaster	Tan	Cracking	1	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302A	Classroom 302 Storage	W4	Plaster	Tan	Flaking	6	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302A	Classroom 302 Storage	Ceiling	Plaster	White	Flaking	2	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302A	Classroom 302 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302B	Storage outside Classroom 302 by Stairwell C	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302B	Storage outside Classroom 302 by Stairwell C	W2	Plaster	Tan	Cracking	12	29.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302B	Storage outside Classroom 302 by Stairwell C	W3	Plaster	Tan	Cracking	1	32.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302B	Storage outside Classroom 302 by Stairwell C	W4	Plaster	Tan	Cracking	15	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302B	Storage outside Classroom 302 by Stairwell C	Ceiling	Plaster	Tan	Flaking	22	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	302B	Storage outside Classroom 302 by Stairwell C	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	303	Classroom 303	W1	Plaster	Tan	Cracking	3	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	303	Classroom 303	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	1	0.17	Negative	
1230	1	3	303	Classroom 303	W2	Plaster	Tan	Efflorescence	6	37.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	303	Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	1	0.18	Negative	
1230	1	3	303	Classroom 303	W3	Plaster	Tan	Flaking	7	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	303	Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	silver	Cracking	2	6.2	Positive	
1230	1	3	303	Classroom 303	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	303	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	303	Classroom 303	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	303A	Classroom 303 Storage	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC #	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Paster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	1	3	303A	Classroom 303 Storage	W2	Plaster	Tan	Cracking	4	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	303A	Classroom 303 Storage	W3	Plaster	Tan	Cracking	2	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	303A	Classroom 303 Storage	W4	Plaster	Tan	Flaking	1	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	303A	Classroom 303 Storage	Ceiling	Plaster	Tan	Flaking	3	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	303A	Classroom 303 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304	Classroom 304	W1	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304	Classroom 304	W2	Plaster	Green	Cracking	1	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304	Classroom 304	W3	Plaster	Green	Cracking	2	24.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304	Classroom 304	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	silver	Chipping	1	7	Positive
1230	1	3	304	Classroom 304	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304	Classroom 304	Ceiling	Plaster	White	Cracking	12	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304	Classroom 304	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304A	Classroom 304 Storage	W1	Plaster	Green	Cracking	1	29.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304A	Classroom 304 Storage	W2	Plaster	Green	Cracking	2	34.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304A	Classroom 304 Storage	W3	Plaster	Green	Cracking	4	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304A	Classroom 304 Storage	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304A	Classroom 304 Storage	Ceiling	Plaster	White	Cracking	1	15.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	304A	Classroom 304 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305	Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	2	0.26	Negative
1230	1	3	305	Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	1	0.16	Negative
1230	1	3	305	Classroom 305	W1	Plaster	Tan	Flaking	3	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305	Classroom 305	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	2	0.19	Negative
1230	1	3	305	Classroom 305	W2	Plaster	Tan	Cracking	3	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305	Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	1	4.2	Positive
1230	1	3	305	Classroom 305	W3	Plaster	Tan	Flaking	9	32.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305	Classroom 305	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	1	0.34	Negative
1230	1	3	305	Classroom 305	W4	Plaster	Tan	Chipping	2	37	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305	Classroom 305	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305	Classroom 305	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305A	Classroom 305 Storage	W1	Plaster	Tan	Chipping	1	31.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305A	Classroom 305 Storage	W2	Plaster	Tan	Chipping	9	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305A	Classroom 305 Storage	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305A	Classroom 305 Storage	W4	Plaster	Tan	Chipping	2	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305A	Classroom 305 Storage	Ceiling	Plaster	Tan	Flaking	12	19.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	305A	Classroom 305 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306	Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.39	Negative
1230	1	3	306	Classroom 306	W1	Plaster	Tan	Cracking	6	30.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306	Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	2	0.25	Negative
1230	1	3	306	Classroom 306	W2	Plaster	Tan	Chipping	3	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306	Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	2	5.9	Positive
1230	1	3	306	Classroom 306	W3	Plaster	Tan	Flaking	16	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306	Classroom 306	W4	Plaster	Tan	Chipping	1	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306	Classroom 306	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306	Classroom 306	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306A	Classroom 306 Storage	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306A	Classroom 306 Storage	W2	Plaster	Tan	Chipping	2	8.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306A	Classroom 306 Storage	W3	Plaster	Tan	Chipping	2	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306A	Classroom 306 Storage	W4	Plaster	Tan	Chipping	2	8.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306A	Classroom 306 Storage	Ceiling	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	306A	Classroom 306 Storage	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314A	Boy's Restroom across from Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	N/A	White	Flaking	1	0.37	Negative
1230	1	3	314A	Boy's Restroom across from Classroom 306	W1	Plaster	Tan	Flaking	2	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P r i m a r y D a m a g e (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	3	314A	Boy's Restroom across from Classroom 306	W2	Plaster	Tan	Flaking	2	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314A	Boy's Restroom across from Classroom 306	W3	Plaster	Tan	Efflorescence	6	6.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314A	Boy's Restroom across from Classroom 306	W4	Plaster	Tan	Flaking	3	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314A	Boy's Restroom across from Classroom 306	Ceiling	Concrete	White	Cracking	6	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314A	Boy's Restroom across from Classroom 306	Floor	Concrete	Blue	Chipping	50	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307	Classroom 307	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Brown	Chipping	2	0.25	Negative
1230	1	3	307	Classroom 307	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	2	0.21	Negative
1230	1	3	307	Classroom 307	W1	Plaster	Tan	Cracking	11	13.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307	Classroom 307	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	1	5.1	Positive
1230	1	3	307	Classroom 307	W2	Plaster	Tan	Cracking	12	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307	Classroom 307	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	1	6.7	Positive
1230	1	3	307	Classroom 307	W3	Plaster	Tan	Cracking	7	37.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307	Classroom 307	W4	Plaster	Tan	Cracking	9	32.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307	Classroom 307	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307	Classroom 307	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307A	Classroom 307 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	1	0.19	Negative
1230	1	3	307A	Classroom 307 Storage	W1	Plaster	Tan	Chipping	2	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307A	Classroom 307 Storage	W2	Plaster	Tan	Flaking	30	28	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307A	Classroom 307 Storage	W3	Plaster	Tan	Flaking	18	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307A	Classroom 307 Storage	W4	Plaster	Tan	Flaking	60	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307A	Classroom 307 Storage	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	307A	Classroom 307 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308	Classroom 308	W1	Plaster	Tan	Cracking	4	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308	Classroom 308	W2	Plaster	Tan	Cracking	9	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308	Classroom 308	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	2	5.7	Positive
1230	1	3	308	Classroom 308	W3	Plaster	Tan	Cracking	11	18.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308	Classroom 308	W4	Plaster	Tan	Flaking	6	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308	Classroom 308	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308	Classroom 308	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308A	Classroom 308 Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	308A	Classroom 308 Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	308A	Classroom 308 Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	308A	Classroom 308 Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	308A	Classroom 308 Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	308A	Classroom 308 Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	309	Classroom 309	W1	Plaster	Tan	Cracking	4	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309	Classroom 309	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309	Classroom 309	W3	Plaster	Tan	Cracking	2	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309	Classroom 309	W4	Plaster	Tan	Cracking	8	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309	Classroom 309	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309	Classroom 309	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309A	Classroom 309 Storage	W1	Plaster	Tan	Cracking	4	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309A	Classroom 309 Storage	W2	Plaster	Tan	Cracking	10	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309A	Classroom 309 Storage	W3	Plaster	Tan	Chipping	6	27.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309A	Classroom 309 Storage	W4	Plaster	Tan	Cracking	12	29.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309A	Classroom 309 Storage	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	309A	Classroom 309 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310	Classroom 310	W1	Plaster	Tan	Chipping	4	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310	Classroom 310	W2	Plaster	Tan	Cracking	10	33.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310	Classroom 310	W3	Plaster	Tan	Cracking	12	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310	Classroom 310	W4	Plaster	Tan	Cracking	3	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310	Classroom 310	Ceiling	Plaster	White	Flaking	21	34.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310	Classroom 310	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310A	Classroom 310 Storage	W1	Plaster	Tan	Chipping	1	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	3	310A	Classroom 310 Storage	W2	Plaster	Tan	Chipping	1	28.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310A	Classroom 310 Storage	W3	Plaster	Tan	Cracking	3	29.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310A	Classroom 310 Storage	W4	Plaster	Tan	Cracking	1	24.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310A	Classroom 310 Storage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	310A	Classroom 310 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311	Classroom 311	W1	Plaster	Tan	Cracking	6	34.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311	Classroom 311	W2	Plaster	Tan	Cracking	16	33.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311	Classroom 311	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Cracking	1	7.2	Positive
1230	1	3	311	Classroom 311	W3	Plaster	Tan	Cracking	21	36.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311	Classroom 311	W4	Plaster	Tan	Flaking	14	36.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311	Classroom 311	Ceiling	Plaster	White	Cracking	6	27.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311	Classroom 311	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311A	Classroom 311 Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311A	Classroom 311 Storage	W2	Plaster	Tan	Chipping	2	18.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311A	Classroom 311 Storage	W3	Plaster	Tan	Cracking	11	29.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311A	Classroom 311 Storage	W4	Plaster	Tan	Cracking	4	36.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311A	Classroom 311 Storage	Ceiling	Plaster	White	Cracking	1	33.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	311A	Classroom 311 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312	Classroom 312	W1	Plaster	Tan	Chipping	1	31.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312	Classroom 312	W2	Plaster	Tan	Chipping	3	36.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312	Classroom 312	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Cracking	1	3.9	Positive
1230	1	3	312	Classroom 312	W3	Plaster	Tan	Cracking	27	33.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312	Classroom 312	W4	Plaster	Tan	Cracking	4	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312	Classroom 312	Ceiling	Plaster	White	Cracking	9	28	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312	Classroom 312	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312A	Classroom 312 Storage	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312A	Classroom 312 Storage	W2	Plaster	Tan	Flaking	17	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312A	Classroom 312 Storage	W3	Plaster	Tan	Cracking	6	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312A	Classroom 312 Storage	W4	Plaster	Tan	Cracking	19	24.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312A	Classroom 312 Storage	Ceiling	Plaster	Tan	Cracking	1	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	312A	Classroom 312 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	313	Classroom 313	W1	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	White	Cracking	4	0.35	Negative
1230	1	3	313	Classroom 313	W1	Plaster	Tan	Flaking	5	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	313	Classroom 313	W2	Plaster	Tan	Flaking	12	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	313	Classroom 313	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Cracking	1	6.5	Positive
1230	1	3	313	Classroom 313	W3	Plaster	Tan	Flaking	36	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	313	Classroom 313	W4	Plaster	Tan	Cracking	16	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	313	Classroom 313	Ceiling	Plaster	White	Cracking	22	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	313	Classroom 313	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	313A	Classroom 313 Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	313A	Classroom 313 Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	313A	Classroom 313 Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	313A	Classroom 313 Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	313A	Classroom 313 Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	313A	Classroom 313 Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	3	314	Classroom 314	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	0.29	Negative
1230	1	3	314	Classroom 314	W1	Plaster	Tan	Chipping	4	22.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314	Classroom 314	W2	Plaster	Tan	Chipping	7	27.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314	Classroom 314	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Cracking	1	5.8	Positive
1230	1	3	314	Classroom 314	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Brown	Chipping	2	0.22	Negative
1230	1	3	314	Classroom 314	W3	Plaster	Tan	Chipping	11	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314	Classroom 314	W4	Plaster	Tan	Chipping	5	31.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314	Classroom 314	Ceiling	Plaster	Tan	Cracking	2	33.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314	Classroom 314	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314B	Classroom 314 Storage	W1	Plaster	Tan	Chipping	2	37.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Paster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	1	3	314B	Classroom 314 Storage	W2	Plaster	Tan	Chipping	9	34.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314B	Classroom 314 Storage	W3	Plaster	Tan	Chipping	3	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314B	Classroom 314 Storage	W4	Plaster	Tan	Flaking	11	22.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314B	Classroom 314 Storage	Ceiling	Metal	White	Flaking	13	24.96	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	314B	Classroom 314 Storage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H31	Hallway at Classrooms 310 to 314	W1	Plaster	White	Flaking	12	35.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H31	Hallway at Classrooms 310 to 314	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	2	0.33	Negative
1230	1	3	H31	Hallway at Classrooms 310 to 314	W2	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H31	Hallway at Classrooms 310 to 314	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H31	Hallway at Classrooms 310 to 314	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.28	Negative
1230	1	3	H31	Hallway at Classrooms 310 to 314	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H31	Hallway at Classrooms 310 to 314	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H31	Hallway at Classrooms 310 to 314	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H32	Main Hallway at Classroom 303 to 309	W1	Plaster	White	Flaking	70	33.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H32	Main Hallway at Classroom 303 to 309	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	3	0.26	Negative
1230	1	3	H32	Main Hallway at Classroom 303 to 309	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H32	Main Hallway at Classroom 303 to 309	W3	Plaster	White	Chipping	15	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H32	Main Hallway at Classroom 303 to 309	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	2	0.27	Negative
1230	1	3	H32	Main Hallway at Classroom 303 to 309	W4	Plaster	White	Chipping	4	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H32	Main Hallway at Classroom 303 to 309	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H32	Main Hallway at Classroom 303 to 309	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H33	Hallway at Classroom 302	W1	Plaster	White	Holes	4	28.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H33	Hallway at Classroom 302	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	3	0.29	Negative
1230	1	3	H33	Hallway at Classroom 302	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H33	Hallway at Classroom 302	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H33	Hallway at Classroom 302	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H33	Hallway at Classroom 302	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	H33	Hallway at Classroom 302	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S31	Stairwell A at Classroom 310	W1	Plaster	White	Cracking	12	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S31	Stairwell A at Classroom 310	W2	Plaster	White	Chipping	8	31.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S31	Stairwell A at Classroom 310	W3	Plaster	White	Chipping	8	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S21	Stairwell A at Classroom 310	W4	Plaster	White	Chipping	10	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S31	Stairwell A at Classroom 310	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S21	Stairwell A at Classroom 310	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S21	Stairwell A at Classroom 310	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	2	0.35	Negative
1230	1	3	S32	Stairwell B at Classroom 309	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S32	Stairwell B at Classroom 309	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	3	0.04	Negative
1230	1	3	S32	Stairwell B at Classroom 309	W2	Plaster	White	Cracking	6	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S32	Stairwell B at Classroom 309	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S32	Stairwell B at Classroom 309	W4	Plaster	White	Chipping	6	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S32	Stairwell B at Classroom 309	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S32	Stairwell B at Classroom 309	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S33	Stairwell C at Classroom 303	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S33	Stairwell C at Classroom 303	W2	Plaster	White	Cracking	12	14.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S33	Stairwell C at Classroom 303	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S33	Stairwell C at Classroom 303	W4	Plaster	White	Chipping	10	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S33	Stairwell C at Classroom 303	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S33	Stairwell C at Classroom 303	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001B	Classroom by Stairwell C and used as Storage	W1	Plaster	White	Flaking	50	16.5	Positive	Door Frame	Wood	Broan	Chipping	1	7.9	Positive
1230	1	B	001B	Classroom by Stairwell C and used as Storage	W2	Plaster	White	Flaking	35	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001B	Classroom by Stairwell C and used as Storage	W3	Plaster	White	Flaking	60	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001B	Classroom by Stairwell C and used as Storage	W4	Plaster	White	Flaking	120	14.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Primer Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	1	B	001B	Classroom by Stairwell C and used as Storage	Ceiling	Plaster	White	Flaking	999	11.9	Positive	Radiator	Metal	Silver	Flaking	40	20.1	Positive
1230	1	B	001B	Classroom by Stairwell C and used as Storage	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BA	Storage #1 in Room 001B	W1	Plaster	White	Chipping	1	15.4	Positive	Door Frame	Wood	Brown	Chipping	1	0.3	Negative
1230	1	B	001BA	Storage #1 in Room 001B	W2	Plaster	White	Flaking	1	23.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BA	Storage #1 in Room 001B	W3	Plaster	White	Flaking	20	19.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BA	Storage #1 in Room 001B	W4	Plaster	White	Flaking	1	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BA	Storage #1 in Room 001B	Ceiling	Plaster	White	Flaking	30	12	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BA	Storage #1 in Room 001B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	10	0.27	Negative
1230	1	B	001BA	Storage #1 in Room 001B	Floor	Concrete	Gray	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BB	Storage #2 in Room 001B	W1	Plaster	Yellow	Flaking	10	32.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BB	Storage #2 in Room 001B	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	6.3	Positive
1230	1	B	001BB	Storage #2 in Room 001B	W2	Plaster	Yellow	Flaking	25	28.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BB	Storage #2 in Room 001B	W3	Plaster	Yellow	Flaking	35	29.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BB	Storage #2 in Room 001B	W4	Plaster	Yellow	Flaking	10	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BB	Storage #2 in Room 001B	Ceiling	Plaster	White	Efflorescence	0	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	001BB	Storage #2 in Room 001B	Floor	Concrete	Gray	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	002B	Storage	W1	Concrete	Tan	None	0	11.1	Positive	Door Frame	Wood	Tan	Chipping	2	0.3	Negative
1230	1	B	002B	Storage	W2	Concrete	Tan	Flaking	10	8.6	Positive	Door Frame	Wood	Tan	Chipping	2	8.7	Positive
1230	1	B	002B	Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	2	0.1	Negative
1230	1	B	002B	Storage	W3	Brick	Tan	Flaking	40	10.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	002B	Storage	W4	Wood	Tan	Flaking	20	27.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	002B	Storage	Ceiling	Plaster	Tan	Flaking	20	21.8	Positive	Radiator	Metal	Silver	Chipping	10	7.4	Positive
1230	1	B	002B	Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	1	B	003B	Classroom by Stairwell B - used as Storage	W1	Wood	White	Chipping	20	15.9	Positive	Door Frame	Wood	Tan	Chipping	2	0.3	Negative
1230	1	B	003B	Classroom by Stairwell B - used as Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.25	Negative
1230	1	B	003B	Classroom by Stairwell B - used as Storage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	White	Chipping	6	0.17	Negative
1230	1	B	003B	Classroom by Stairwell B - used as Storage	W2	Sheetrock	White	Chipping	20	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	003B	Classroom by Stairwell B - used as Storage	W3	Wood	White	Flaking	125	39.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	003B	Classroom by Stairwell B - used as Storage	W4	Wood	White	Flaking	60	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	003B	Classroom by Stairwell B - used as Storage	Ceiling	Wood	White	Flaking	150	18.6	Positive	Radiator	Metal	Silver	Chipping	10	14	Positive
1230	1	B	003B	Classroom by Stairwell B - used as Storage	Floor	12"x12" Floor Tile	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	004B	Storage	W1	Brick	Tan	None	0	5.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	004B	Storage	W2	Brick	Tan	None	0	5.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	004B	Storage	W3	Brick	Tan	None	0	5.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	004B	Storage	W4	Concrete	Tan	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	004B	Storage	Ceiling	Concrete	Tan	Chipping	5	5.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	004B	Storage	Floor	Concrete	Grey	Chipping	40	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	005B/006B	Storage	W1	Sheetrock	White	Chipping	8	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	005B/006B	Storage	W2	Wood	White	Chipping	6	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	005B/006B	Storage	W3	Wood	White	Chipping	4	27.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	005B/006B	Storage	W4	Wood	White	Flaking	30	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	005B/006B	Storage	Ceiling	Wood	White	Chipping	18	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	005B/006B	Storage	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007B	Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007B	Restroom	W2	Brick	White	Flaking	85	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007B	Restroom	W3	Concrete	White	Flaking	35	36.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007B	Restroom	W4	Concrete	White	Flaking	50	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	B	007B	Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	3	0.33	Negative
1230	1	B	007B	Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Chipping	3	5.5	Positive
1230	1	B	007B	Restroom	Ceiling	Concrete	White	Flaking	32	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007B	Restroom	Floor	12"x12" Floor Tile	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007C	Custodial Storage	W1	CMU	Tan	None	0	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007C	Custodial Storage	W2	Concrete	Tan	Flaking	7	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007C	Custodial Storage	W3	Concrete	Tan	Flaking	11	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007C	Custodial Storage	W4	Brick	Tan	Flaking	24	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007C	Custodial Storage	Ceiling	Plaster	Tan	Flaking	36	27.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	007C	Custodial Storage	Floor	12"x12" Floor Tile	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	008B	Girl's Restroom in Main Hallway	W1	Brick	Tan	Flaking	12	13.3	Positive	Door Frame	Metal	Black	Flaking	2	25.2	Positive
1230	1	B	008B	Girl's Restroom in Main Hallway	W2	Concrete	Tan	Flaking	25	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	008B	Girl's Restroom in Main Hallway	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	2	0.37	Negative
1230	1	B	008B	Girl's Restroom in Main Hallway	W3	Concrete	White	Flaking	18	14.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	008B	Girl's Restroom in Main Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Chipping	6	0.14	Negative
1230	1	B	008B	Girl's Restroom in Main Hallway	W4	Concrete	Tan	Flaking	30	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	008B	Girl's Restroom in Main Hallway	Ceiling	Concrete	White	Flaking	50	16.5	Positive	Radiator	Metal	Tan	Chipping	75	0	Negative
1230	1	B	008B	Girl's Restroom in Main Hallway	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Chipping	15	0.19	Negative
1230	1	B	008B	Girl's Restroom in Main Hallway	Floor	Concrete	Gray	Chipping	75	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	009B	Boiler Room Storage	W1	Brick	White	Flaking	300	10.8	Positive	Door Frame	Wood	Tan	Chipping	1	0.2	Negative
1230	1	B	009B	Boiler Room Storage	W2	Brick	White	Flaking	300	19.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	009B	Boiler Room Storage	W3	Concrete	White	Flaking	300	28.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	009B	Boiler Room Storage	W4	Concrete	White	Flaking	300	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	009B	Boiler Room Storage	Ceiling	Concrete	White	Flaking	600	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	009B	Boiler Room Storage	Floor	Concrete	Gray	Hole	10	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B	Boiler Room	W1	Concrete	White	Flaking	250	9.5	Positive	Door Frame	Wood	Tan/Blue	Chipping	1	38	Positive
1230	1	B	010B	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan/Blue	Chipping	15	28	Positive
1230	1	B	010B	Boiler Room	W2	Concrete	White	Flaking	100	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B	Boiler Room	W3	Concrete	White	Flaking	250	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B	Boiler Room	W4	Concrete	White	Flaking	250	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B	Boiler Room	Ceiling	Concrete	White	Flaking	300	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B	Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-1	Pump Room in Boiler Room	W1	Concrete	White	Flaking	100	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-1	Pump Room in Boiler Room	W2	Concrete	White	Flaking	150	14.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-1	Pump Room in Boiler Room	W3	Concrete	White	Flaking	60	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-1	Pump Room in Boiler Room	W4	Concrete	White	Flaking	125	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-1	Pump Room in Boiler Room	Ceiling	Concrete	White	Flaking	85	14.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-1	Pump Room in Boiler Room	Floor	Concrete	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-2	Water Meter Room in Boiler Room	W1	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-2	Water Meter Room in Boiler Room	W2	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-2	Water Meter Room in Boiler Room	W3	Brick	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-2	Water Meter Room in Boiler Room	W4	Brick	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-2	Water Meter Room in Boiler Room	Ceiling	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	010B-2	Water Meter Room in Boiler Room	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	011B	Fan Room 1 next to Boy's Restroom	W1	Brick	White	Flaking	250	36.2	Positive	Door Frame	Wood	Tan/Blue	Chipping	1	29.2	Positive
1230	1	B	011B	Fan Room 1 next to Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan/Blue	Chipping	15	31	Positive
1230	1	B	011B	Fan Room 1 next to Boy's Restroom	W2	Brick	White	Flaking	200	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	011B	Fan Room 1 next to Boy's Restroom	W3	Brick	White	Flaking	250	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	011B	Fan Room 1 next to Boy's Restroom	W4	Brick	White	Flaking	220	31.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	011B	Fan Room 1 next to Boy's Restroom	Ceiling	Concrete	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	011B	Fan Room 1 next to Boy's Restroom	Floor	Concrete	Gray	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	012B	Boy's Restroom across from Boiler Room	W1	Brick	White	Flaking	12	34.8	Positive	Door	Wood	Blue	Chipping	2	0.1	Negative
1230	1	B	012B	Boy's Restroom across from Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Blue	Chipping	1	5.2	Positive

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P aster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	B	012B	Boy's Restroom across from Boiler Room	W2	Concrete	White	Flaking	6	31.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	012B	Boy's Restroom across from Boiler Room	W2	Brick	White	Flaking	6	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	012B	Boy's Restroom across from Boiler Room	W3	Concrete	White	Flaking	18	22.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	012B	Boy's Restroom across from Boiler Room	W3	Brick	White	Flaking	20	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	012B	Boy's Restroom across from Boiler Room	W4	Brick	White	Flaking	20	24.6	Positive	Wall Base	Concrete	Black	Flaking	15	0.2	Negative
1230	1	B	012B	Boy's Restroom across from Boiler Room	Ceiling	Concrete	White	Flaking	75	18.9	Positive	Radiator	Metal	Tan	Chipping	40	0	Negative
1230	1	B	012B	Boy's Restroom across from Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	20	0.52	Negative
1230	1	B	012B	Boy's Restroom across from Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	Tan	Flaking	50	4	Positive
1230	1	B	012B	Boy's Restroom across from Boiler Room	Floor	Concrete	Gray	Chipping	75	0.4	Negative	Column	Metal	Black	Chipping	1	1.4	Positive
1230	1	B	013B	Building Engineer's Office	W1	Concrete	White	Flaking	5	27.5	Positive	Door	Wood	Blue/Tan	Chipping	2	0.1	Negative
1230	1	B	013B	Building Engineer's Office	W1	Brick	White	Flaking	25	35.2	Positive	Door Frame	Wood	Blue/Tan	Chipping	2	21.8	Positive
1230	1	B	013B	Building Engineer's Office	W2	Brick	White	Flaking	125	30.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	013B	Building Engineer's Office	W3	Concrete	White	Flaking	75	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	013B	Building Engineer's Office	W4	Brick	White	Flaking	60	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	013B	Building Engineer's Office	Ceiling	Concrete	White	Flaking	225	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	013B	Building Engineer's Office	Floor	Concrete	Gray	Chipping	75	0.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014B	Classroom 014B by Stairwell C	W1	Plaster	Yellow	Flaking	80	32.4	Positive	Door Frame	Wood	Brown	Chipping	1	11	Positive
1230	1	B	014B	Classroom 014B by Stairwell C	W2	Plaster	Yellow	Flaking	125	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014B	Classroom 014B by Stairwell C	W3	Plaster	Yellow	Flaking	140	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014B	Classroom 014B by Stairwell C	W4	Plaster	Yellow	Flaking	30	36.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014B	Classroom 014B by Stairwell C	Ceiling	Plaster	White	Flaking	75	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014B	Classroom 014B by Stairwell C	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	40	20.1	Positive
1230	1	B	014B	Classroom 014B by Stairwell C	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014C	Classroom 014B Storage by Window Wall	W1	Plaster	Yellow	Flaking	1	26.8	Positive	Door Frame	Wood	Brown	Chipping	1	6.8	Positive
1230	1	B	014C	Classroom 014B Storage by Window Wall	W2	Plaster	Yellow	Flaking	1	23.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014C	Classroom 014B Storage by Window Wall	W3	Plaster	Yellow	Flaking	1	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014C	Classroom 014B Storage by Window Wall	W4	Plaster	Yellow	Flaking	1	28.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014C	Classroom 014B Storage by Window Wall	Ceiling	Plaster	White	None	0	30.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014C	Classroom 014B Storage by Window Wall	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014D	Classroom 014B Storage by Doorway	W1	Plaster	Yellow	None	0	21.4	Positive	Door Frame	Wood	Brown	Chipping	1	8.6	Positive
1230	1	B	014D	Classroom 014B Storage by Doorway	W2	Plaster	Yellow	None	0	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014D	Classroom 014B Storage by Doorway	W3	Plaster	Yellow	None	0	28	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014D	Classroom 014B Storage by Doorway	W4	Plaster	Yellow	None	0	27.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014D	Classroom 014B Storage by Doorway	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014D	Classroom 014B Storage by Doorway	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014F	Storage next to Stairwell C	W1	Plaster	White	Chipping	4	30.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014F	Storage next to Stairwell C	W2	Plaster	White	Flaking	12	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014F	Storage next to Stairwell C	W3	Plaster	White	Cracking	3	22.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014F	Storage next to Stairwell C	W4	Plaster	White	Flaking	12	31.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014F	Storage next to Stairwell C	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	014F	Storage next to Stairwell C	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	015B	Fan Room 2	W1	Concrete	White	None	0	20.8	Positive	Door	Wood	Brown	None	0	0.1	Negative
1230	1	B	015B	Fan Room 2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	9.7	Positive
1230	1	B	015B	Fan Room 2	W2	Concrete	White	None	0	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	015B	Fan Room 2	W3	Concrete	White	None	0	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	015B	Fan Room 2	W4	Concrete	White	None	0	29.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	015B	Fan Room 2	Ceiling	Concrete	White	None	0	33.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	015B	Fan Room 2	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	016B-1	Gym Closet #1	W1	Brick	White	Chipping	1	8.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	016B-1	Gym Closet #1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0	Negative
1230	1	B	016B-1	Gym Closet #1	W3	Brick	White	Chipping	1	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	016B-1	Gym Closet #1	Ceiling	Concrete	White	None	0	0.6	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	016B-1	Gym Closet #1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Chipping	1	11.7	Positive
1230	1	B	016B-2	Gym Closet #2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	None	0	9.5	Positive
1230	1	B	016B-2	Gym Closet #2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	12.5	Positive

School District of Philadelphia																			
Lead Safe Certification Assessment Report																			
Bryant Promise Academy Elementary School #1230																			
					Inspection Company: Synertech, Inc.														
					Name of Inspector: Bart McMahon/Ryan Hutsell														
					Inspection Dates: 06/17-06/27/2019														
ULC S#	E	l	Flo	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Primer Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	1	B		016B-2	Gym Closet #2	W2	Brick	White	None	0	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-2	Gym Closet #2	W3	Brick	White	None	0	9.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-2	Gym Closet #2	W4	Brick	White	None	0	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-2	Gym Closet #2	Ceiling	Concrete	White	None	0	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-2	Gym Closet #2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	None	0	9	Positive
1230	1	B		016B-3	Gym Closet #3	W1	Brick	White	None	0	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-3	Gym Closet #3	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.1	Negative
1230	1	B		016B-3	Gym Closet #3	W2	Brick	White	None	0	8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-3	Gym Closet #3	W3	Brick	White	None	0	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-3	Gym Closet #3	W4	Brick	White	None	0	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-3	Gym Closet #3	Ceiling	Concrete	White	Flaking	2	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-3	Gym Closet #3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	None	0	17.6	Positive
1230	1	B		016B-EV1	Gym Exit Vestibule #1	W1	Brick	White	Chipping	2	5.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-EV1	Gym Exit Vestibule #1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	1	0	Negative
1230	1	B		016B-EV1	Gym Exit Vestibule #1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1230	1	B		016B-EV1	Gym Exit Vestibule #1	W2	Brick	White	Flaking	50	7.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-EV1	Gym Exit Vestibule #1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	1	0	Negative
1230	1	B		016B-EV1	Gym Exit Vestibule #1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1230	1	B		016B-EV1	Gym Exit Vestibule #1	W3	Brick	White	Flaking	30	6.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-EV1	Gym Exit Vestibule #1	W4	Brick	White	Flaking	30	7.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-EV1	Gym Exit Vestibule #1	Ceiling	Concrete	White	Flaking	50	5.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-4	Gym Closet #4	W1	Brick	White	None	0	5.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-4	Gym Closet #4	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	1	0.1	Negative
1230	1	B		016B-4	Gym Closet #4	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1230	1	B		016B-4	Gym Closet #4	W2	Brick	White	Flaking	20	5.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-4	Gym Closet #4	W3	Brick	White	Flaking	10	4.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-4	Gym Closet #4	W4	Brick	White	None	0	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B-4	Gym Closet #4	Ceiling	Concrete	White	Flaking	30	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B	Gym	W1	Brick	Blue	Flaking	20	31.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B	Gym	W2	Brick	Blue	Flaking	75	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B	Gym	W3	Brick	Blue	Flaking	125	27.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B	Gym	W4	Brick	Blue	Flaking	60	35.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B	Gym	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	8	1.8	Positive
1230	1	B		016B	Gym	Ceiling	Concrete	White	Flaking	525	33.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		016B	Gym	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking	225	23.5	Positive
1230	1	B		016B	Gym	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	120	7.1	Positive
1230	1	B		016B	Gym	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Column	Concrete	White/Brown	Flaking	25	15.8	Positive
1230	1	B		016B	Gym	Floor	12"x12" Floor Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		017B	Staff Restroom by Gym in Main Hallway	W1	Brick	White	Chipping	2	21.1	Positive	Door Frame	Wood	Brown	Chipping	1	7.7	Positive
1230	1	B		017B	Staff Restroom by Gym in Main Hallway	W2	Brick	White	Efflorescence	5	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		017B	Staff Restroom by Gym in Main Hallway	W3	Brick	White	Flaking	20	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		017B	Staff Restroom by Gym in Main Hallway	W4	Brick	White	Flaking	10	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		017B	Staff Restroom by Gym in Main Hallway	Ceiling	Concrete	White	Flaking	60	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		017B	Staff Restroom by Gym in Main Hallway	Floor	Concrete	Gray	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		018B	Custodial Storage in Main Hallway	W1	Brick	White	Chipping	3	13.8	Positive	Door Frame	Wood	Brown	Chipping	1	0.2	Negative
1230	1	B		018B	Custodial Storage in Main Hallway	W2	Brick	White	Chipping	2	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		018B	Custodial Storage in Main Hallway	W3	Brick	White	Chipping	2	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		018B	Custodial Storage in Main Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Chipping	2	0.41	Negative
1230	1	B		018B	Custodial Storage in Main Hallway	W4	Brick	White	Efflorescence	2	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		018B	Custodial Storage in Main Hallway	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		018B	Custodial Storage in Main Hallway	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Chipping	1	0.28	Negative
1230	1	B		018B	Custodial Storage in Main Hallway	Floor	Concrete	Gray	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B		H1B	Hallway by Mechanical Rooms	W1	Brick	White	Chipping	6	21.1	Positive	Wall Base	Concrete	Grey	Chipping	2	22.7	Positive
1230	1	B		H1B	Hallway by Mechanical Rooms	W2	Brick	White	Chipping	20	26.8	Positive	Wall Base	Concrete	Grey	Flaking	15	19.1	Positive

School District of Philadelphia Lead Safe Certification Assessment Report Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	1	B	H1B	Hallway by Mechanical Rooms	W3	Brick	White	Chipping	10	34.5	Positive	Plenum Door	Wood	Blue	Chipping	2	29.5	Positive
1230	1	B	H1B	Hallway by Mechanical Rooms	W4	Brick	White	Flaking	125	2.7	Positive	Wall Base	Concrete	Grey	Flaking	15	28.1	Positive
1230	1	B	H1B	Hallway by Mechanical Rooms	Ceiling/ Plaster	Concrete	White	Flaking	275	35.4	Positive	Ductwork	Metal	Tan	Chipping	125	12.5	Positive
1230	1	B	H1B	Hallway by Mechanical Rooms	Floor	Concrete	Brown	Chipping	275	0.3	Negative	Stair Risers	Concrete	Brown	Flaking	15	0.2	Negative
1230	1	B	H2B	Main Hallway	W1	Concrete	White	Flaking	1800	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	H2B	Main Hallway	W2	Brick	White	Flaking	0	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	H2B	Main Hallway	W3	Brick	White	Flaking	1800	33.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	H2B	Main Hallway	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	B	H2B	Main Hallway	Ceiling	Concrete/ Plaster	White	Flaking	1000	18.9	Positive	Ductwork	Metal	White	Flaking	275	9.8	Positive
1230	1	B	H2B	Main Hallway	Floor	Concrete	Brown	Chipping	1500	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	100D	Mechanical Room in Stairwell connecting Elements 1 & 2	W1	Concrete	White	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	100D	Mechanical Room in Stairwell connecting Elements 1 & 2	W2	Concrete	White	Chipping	1	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	100D	Mechanical Room in Stairwell connecting Elements 1 & 2	W3	Concrete	White	Chipping	1	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	100D	Mechanical Room in Stairwell connecting Elements 1 & 2	W4	Concrete	White	Chipping	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	100D	Mechanical Room in Stairwell connecting Elements 1 & 2	Ceiling	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	100D	Mechanical Room in Stairwell connecting Elements 1 & 2	Floor	Concrete	Gray	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	101	Lobby	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	101	Lobby	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	101	Lobby	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	101	Lobby	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	101	Lobby	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	101	Lobby	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	102	Women's Restroom in Lobby	W1	Concrete	White	Chipping	4	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	102	Women's Restroom in Lobby	W2	Concrete	White	Chipping	6	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	102	Women's Restroom in Lobby	W3	Concrete	White	Flaking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	102	Women's Restroom in Lobby	W4	Concrete	White	Flaking	16	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	102	Women's Restroom in Lobby	Ceiling	Plaster	White	Flaking	4	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	102	Women's Restroom in Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	103	Men's Restroom in Lobby	W1	Concrete	White	Chipping	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	103	Men's Restroom in Lobby	W2	Concrete	White	Chipping	2	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	103	Men's Restroom in Lobby	W3	Concrete	White	Flaking	12	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	103	Men's Restroom in Lobby	W4	Concrete	White	Flaking	12	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	103	Men's Restroom in Lobby	Ceiling	Plaster	White	Flaking	6	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	103	Men's Restroom in Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	W1	Brick	Yellow	Cracking	2	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Yellow	Chipping	6	0.12	Negative
1230	2	1	107	Home & School Office next to Girl's Restroom	W2	Brick	Yellow	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	W3	Brick	Yellow	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	W4	Brick	Yellow	Cracking	8	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	Ceiling	Plaster	White	Cracking	4	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	108	Girl's Restroom in Cafetorium	W1	Brick	Brown	Chipping	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	108	Girl's Restroom in Cafetorium	W2	Brick	Brown	Chipping	2	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																									
Lead Safe Certification Assessment Report																									
Bryant Promise Academy Elementary School #1230																									
					Inspection Company: Synertech, Inc.																				
					Name of Inspector: Bart McMahon/Ryan Hutsell																				
					Inspection Dates: 06/17-06/27/2019																				
ULC S#	E	l	e	m	e	n	t	Flo	or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	2	1						108			Girl's Restroom in Cafetorium	W3	Brick	Brown	Chipping	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1						108			Girl's Restroom in Cafetorium	W4	Brick	Brown	Flaking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1						108			Girl's Restroom in Cafetorium	Ceiling	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1						108			Girl's Restroom in Cafetorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					107A			Room 107	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					107A			Room 107	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					107A			Room 107	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					107A			Room 107	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					107A			Room 107	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					107A			Room 107	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					119			Walkway @ Wall by Food Services	W1	Brick	Yellow	Chipping	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					119			Walkway @ Wall by Food Services	W2	Brick	Yellow	Chipping	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					119			Walkway @ Wall by Food Services	W3	Brick	Yellow	Chipping	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					119			Walkway @ Wall by Food Services	W4	Brick	Yellow	Chipping	1	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					119			Walkway @ Wall by Food Services	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					119			Walkway @ Wall by Food Services	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					109			Boy's Restroom (9-A) in Cafetorium	W1	Brick	Brown	Chipping	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					109			Boy's Restroom (9-A) in Cafetorium	W2	Brick	Brown	Chipping	12	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					109			Boy's Restroom (9-A) in Cafetorium	W3	Brick	Brown	Chipping	5	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					109			Boy's Restroom (9-A) in Cafetorium	W4	Brick	Brown	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					109			Boy's Restroom (9-A) in Cafetorium	Ceiling	Plaster	White	Flaking	2	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					109			Boy's Restroom (9-A) in Cafetorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					110			Storage 3 (10-A) next to Boy's Restroom in Cafetorium	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	2	2	1					110			Storage 3 (10-A) next to Boy's Restroom in Cafetorium	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	2	2	1					110			Storage 3 (10-A) next to Boy's Restroom in Cafetorium	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	2	2	1					110			Storage 3 (10-A) next to Boy's Restroom in Cafetorium	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	2	2	1					110			Storage 3 (10-A) next to Boy's Restroom in Cafetorium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	2	2	1					110			Storage 3 (10-A) next to Boy's Restroom in Cafetorium	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1230	2	2	1					112			Electrical Room (12-A) next to Boy's Restroom in Cafetorium	W1	Brick	Green	Chipping	4	0.14	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					112			Electrical Room (12-A) next to Boy's Restroom in Cafetorium	W2	Brick	Green	Flaking	2	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					112			Electrical Room (12-A) next to Boy's Restroom in Cafetorium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Green	Chipping	10	0.05	Negative
1230	2	2	1					112			Electrical Room (12-A) next to Boy's Restroom in Cafetorium	W3	Brick	Green	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					112			Electrical Room (12-A) next to Boy's Restroom in Cafetorium	W4	Brick	Green	Chipping	1	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					112			Electrical Room (12-A) next to Boy's Restroom in Cafetorium	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					112			Electrical Room (12-A) next to Boy's Restroom in Cafetorium	Floor	Concrete	Gray	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					114			Cafetorium	W1	Concrete	White	Flaking	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					114			Cafetorium	W2	Concrete	White	Flaking	16	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					114			Cafetorium	W3	Concrete	White	Flaking	32	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					114			Cafetorium	W4	Concrete	White	Flaking	40	0.14	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					114			Cafetorium	Ceiling	Plaster	White	Cracking	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					114			Cafetorium	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					124			Stage	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					124			Stage	W2	Concrete	White	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	1					124			Stage	W3	Concrete	White	Flaking	24	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Paster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	2	1	124	Stage	W4	Concrete	White	Flaking	6	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	124	Stage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	124	Stage	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	115	Freezer Room	W1	Brick	Yellow	Flaking	100	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	115	Freezer Room	W2	Brick	Yellow	Flaking	20	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	115	Freezer Room	W3	Brick	Yellow	Flaking	200	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	115	Freezer Room	W4	Brick	Yellow	Flaking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	115	Freezer Room	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	115	Freezer Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	116	Kitchen	W1	Brick	Yellow	Flaking	12	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	116	Kitchen	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Yellow	Chipping	6	0.52	Negative
1230	2	1	116	Kitchen	W2	Brick	Yellow	Flaking	6	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	116	Kitchen	W3	Brick	Yellow	Efflorescence	200	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	116	Kitchen	W4	Brick	Yellow	Flaking	10	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	116	Kitchen	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	116	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	117/118	Kitchen Service Line Area	W1	Brick	Yellow	Chipping	2	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	117/118	Kitchen Service Line Area	W2	Brick	Yellow	Chipping	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	117/118	Kitchen Service Line Area	W3	Brick	Yellow	Chipping	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	117/118	Kitchen Service Line Area	W4	Brick	Yellow	Chipping	15	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	117/118	Kitchen Service Line Area	Ceiling	Plaster	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	117/118	Kitchen Service Line Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	119	Exit Walkway through Kitchen Area	W1	Brick	Yellow	Chipping	2	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	119	Exit Walkway through Kitchen Area	W2	Brick	Yellow	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	119	Exit Walkway through Kitchen Area	W3	Brick	Yellow	Chipping	3	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	119	Exit Walkway through Kitchen Area	W4	Brick	Yellow	Chipping	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	119	Exit Walkway through Kitchen Area	Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	119	Exit Walkway through Kitchen Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	120	Kitchen Office	W1	Concrete	Tan	Cracking	1	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	120	Kitchen Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.04	Negative
1230	2	1	120	Kitchen Office	W2	Concrete	Tan	Cracking	2	0.04	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	120	Kitchen Office	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	120	Kitchen Office	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	120	Kitchen Office	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	120	Restroom by Kitchen Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	121	Restroom by Kitchen Office	W1	Plaster	White	Chipping	1	0.04	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	121	Restroom by Kitchen Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.5	Negative
1230	2	1	121	Restroom by Kitchen Office	W2	Plaster	White	Flaking	10	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	121	Restroom by Kitchen Office	W3	Plaster	White	Flaking	3	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	121	Restroom by Kitchen Office	W4	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	121	Restroom by Kitchen Office	Ceiling	Plaster	White	Efflorescence	30	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	121	Restroom by Kitchen Office	Floor	Concrete	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	122	Storage 2 next to Storage 3 by Stage	W1	Concrete	White	Flaking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	122	Storage 2 next to Storage 3 by Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	1	0.45	Negative
1230	2	1	122	Storage 2 next to Storage 3 by Stage	W2	Concrete	White	Flaking	4	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	122	Storage 2 next to Storage 3 by Stage	W3	Concrete	White	Flaking	6	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	122	Storage 2 next to Storage 3 by Stage	W4	Concrete	White	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	122	Storage 2 next to Storage 3 by Stage	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	122	Storage 2 next to Storage 3 by Stage	Floor	Concrete	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	123	Storage 3 next to Stage	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	123	Storage 3 next to Stage	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	123	Storage 3 next to Stage	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	123	Storage 3 next to Stage	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	123	Storage 3 next to Stage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	123	Storage 3 next to Stage	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																									
Lead Safe Certification Assessment Report																									
Bryant Promise Academy Elementary School #1230																									
										Inspection Company: Synertech, Inc.															
										Name of Inspector: Bart McMahon/Ryan Hutsell															
										Inspection Dates: 06/17-06/27/2019															
ULC #	E	l	e	m	e	n	t	Flo	or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1230	2	2	2	200	Foyer						W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	200	Foyer						W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	200	Foyer						W3	Plaster	Tan	Flaking	75	0.18	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	200	Foyer						W4	Plaster	Tan	Flaking	2	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	200	Foyer						W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	0.35	Negative
1230	2	2	2	200	Foyer						Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	200	Foyer						Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	201	Women's Restroom in Foyer						W1	Concrete	White	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	201	Women's Restroom in Foyer						W2	Concrete	White	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	201	Women's Restroom in Foyer						W3	Concrete	White	Chipping	1	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	201	Women's Restroom in Foyer						W4	Concrete	White	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	201	Women's Restroom in Foyer						Ceiling	Plaster	White	Flaking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	201	Women's Restroom in Foyer						Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	202	Men's Restroom in Foyer						W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	202	Men's Restroom in Foyer						W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	202	Men's Restroom in Foyer						W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	202	Men's Restroom in Foyer						W4	Concrete	White	Chipping	1	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	202	Men's Restroom in Foyer						Ceiling	Plaster	White	Flaking	9	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	202	Men's Restroom in Foyer						Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	203	Book Storage in Foyer						W1	Concrete	Green	Partially Inaccessible/Chipping	1	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	203	Book Storage in Foyer						W2	Concrete	Green	Partially Inaccessible/Flaking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	203	Book Storage in Foyer						W3	Concrete	Green	Partially Inaccessible/Flaking	6	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	203	Book Storage in Foyer						W4	Concrete	Green	Partially Inaccessible/Flaking	3	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	203	Book Storage in Foyer						Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	203	Book Storage in Foyer						Floor	N/A	N/A	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	204	Library Center Office behind Restrooms						W1	Concrete	White	Chipping	4	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	204	Library Center Office behind Restrooms						W2	Concrete	White	Flaking	3	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	204	Library Center Office behind Restrooms						W3	Concrete	White	Flaking	9	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	204	Library Center Office behind Restrooms						W4	Concrete	White	Flaking	13	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	204	Library Center Office behind Restrooms						Ceiling	Plaster	White	Cracking	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	204	Library Center Office behind Restrooms						Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	205	Office across from Library Center Office						W1	Concrete	White	Flaking	8	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	205	Office across from Library Center Office						W2	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	205	Office across from Library Center Office						W3	Concrete	White	Cracking	12	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	205	Office across from Library Center Office						W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	White	Chipping	2	0.02	Negative
1230	2	2	2	205	Office across from Library Center Office						W4	Concrete	White	Flaking	2	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	205	Office across from Library Center Office						Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	205	Office across from Library Center Office						Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	206	Audio Visual Review Room						W1	Brick	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	206	Audio Visual Review Room						W2	Brick	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	206	Audio Visual Review Room						W3	Brick	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	206	Audio Visual Review Room						W4	Brick	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	2	206	Audio Visual Review Room						Ceiling	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																					
Lead Safe Certification Assessment Report																					
Bryant Promise Academy Elementary School #1230																					
						Inspection Company: Synertech, Inc.															
						Name of Inspector: Bart McMahon/Ryan Hutsell															
						Inspection Dates: 06/17-06/27/2019															
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Paster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)			
1230	2	2	206	Audio Visual Review Room	Floor	N/A	N/A		0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	207	Library	W1	Brick	Tan	Cracking	3	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	207	Library	W1	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Tan	Chipping	24	0.02	Negative	N/A		
1230	2	2	207	Library	W2	Brick	Tan	Cracking	2	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	207	Library	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Tan	Chipping	6	0.2	Negative	N/A		
1230	2	2	207	Library	W3	Brick	Tan	Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	207	Library	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Tan	Chipping	16	0.04	Negative	N/A		
1230	2	2	207	Library	W4	Brick	Tan	Efflorescence	16	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	207	Library	Ceiling	Plaster	White	Flaking	60	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	207	Library	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	208	Kitchen in Library	W1	Brick	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	208	Kitchen in Library	W1	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Brown	Chipping	12	0.4	Negative	N/A		
1230	2	2	208	Kitchen in Library	W2	Brick	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	208	Kitchen in Library	W3	Brick	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	208	Kitchen in Library	W4	Brick	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	208	Kitchen in Library	Ceiling	Plaster	White	Chipping	2	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	208	Kitchen in Library	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	209	Mechanical Room along back wall of Library	W1	Brick	Green	Chipping	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	209	Mechanical Room along back wall of Library	W2	Brick	Green	Chipping	6	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	209	Mechanical Room along back wall of Library	W3	Brick	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	209	Mechanical Room along back wall of Library	W4	Brick	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	209	Mechanical Room along back wall of Library	Ceiling	Concrete	Green	Flaking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	209	Mechanical Room along back wall of Library	Floor	Concrete	Gray	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	210	Rear Stairwell next to Mechanical Room	W1	Brick	Tan	Flaking	15	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	210	Rear Stairwell next to Mechanical Room	W2	Brick	Tan	Flaking	15	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	210	Rear Stairwell next to Mechanical Room	W3	Brick	Tan	Flaking	12	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	210	Rear Stairwell next to Mechanical Room	W4	Brick	Tan	Cracking	10	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	210	Rear Stairwell next to Mechanical Room	Ceiling	Plaster	White	Cracking	60	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	210	Rear Stairwell next to Mechanical Room	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	200	IMC Hallway	W1	Concrete	White	Chipping	1	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	200	IMC Hallway	W2	Concrete	White	Cracking	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	200	IMC Hallway	W3	Concrete	White	Chipping	2	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	200	IMC Hallway	W4	Concrete	White	Chipping	6	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	200	IMC Hallway	Ceiling	Concrete	White	Chipping	2	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	2	2	200	IMC Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100	Copier Room in Principal's Office	W1	Plaster	Green	Cracking	3	29.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100	Copier Room in Principal's Office	W1	Plaster	Beige	Cracking	2	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100	Copier Room in Principal's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	4	0.3	Negative	N/A		
1230	1	1	100	Copier Room in Principal's Office	W2	Plaster	Green	Cracking	2	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100	Copier Room in Principal's Office	W2	Plaster	Beige	Cracking	2	17.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100	Copier Room in Principal's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	3	0.2	Negative	N/A		
1230	1	1	100	Copier Room in Principal's Office	W3	Plaster	Green	Cracking	3	32.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100	Copier Room in Principal's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	5	4.3	Positive	N/A		
1230	1	1	100	Copier Room in Principal's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	3	0.26	Negative	N/A		
1230	1	1	100	Copier Room in Principal's Office	W4	Plaster	Green	Cracking	3	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100	Copier Room in Principal's Office	W4	Plaster	Beige	Cracking	4	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100	Copier Room in Principal's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	8	4.5	Positive	N/A		
1230	1	1	100	Copier Room in Principal's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	4	0.3	Negative	N/A		
1230	1	1	100	Copier Room in Principal's Office	Ceiling	Plaster	White	Flaking	1	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
1230	1	1	100A	Principal's Office	W1	Plaster	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Black	Chipping	5	0.11	Negative	N/A		

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	1	100A	Principal's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Black	Chipping	3	0.17	Negative
1230	1	1	100A	Principal's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Cracking	3	5.5	Positive
1230	1	1	100A	Principal's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Black	Cracking	3	0.3	Negative
1230	1	1	100A	Principal's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Black	Cracking	10	0.28	Negative
1230	1	1	100B	Vice Principal's Office (Now used as storage room)	W1	Plaster	White	None	0	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100B	Vice Principal's Office (Now used as storage room)	W2	Plaster	White	None	0	38.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100B	Vice Principal's Office (Now used as storage room)	W3	Plaster	White	None	0	34.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100B	Vice Principal's Office (Now used as storage room)	W4	Plaster	White	None	0	38.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100C	Principal's Office Restroom	W1	Plaster	Blue	Cracking	1	22.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100C	Principal's Office Restroom	W2	Plaster	Blue	Cracking	3	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100C	Principal's Office Restroom	W3	Plaster	Blue	Cracking	3	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100C	Principal's Office Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Cracking	4	2.6	Positive
1230	1	1	100C	Principal's Office Restroom	W4	Plaster	Blue	Cracking	3	24	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100C	Principal's Office Restroom	Ceiling	Drywall	Blue	Cracking	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Principal's Office Restroom Foyer	W1	Plaster	Blue	Cracking	2	23.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Principal's Office Restroom Foyer	W3	Sheetrock	Blue	Flaking, Effloracence	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Principal's Office Restroom Foyer	W4	Plaster	Blue	Cracking	2	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	100F	Principal's Office Restroom Foyer	Ceiling	Drywall	Blue	Cracking	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	102C	Classroom 102 Storage	W1	Plaster	Tan	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	109	Main Office	W1	Plaster	White	None	0	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	109A	Storage/Telephone/Control Room in Main Office	W2	Plaster	White	None	0	33.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201	Classroom 201	W1	Plaster	Tan	None	0	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201	Classroom 201	W3	Plaster	Tan	None	0	18.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201A	Classroom 201 Storage near window wall	W1	Plaster	Yellow	Cracking	6	2.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201A	Classroom 201 Storage near window wall	W2	Plaster	Yellow	Flaking	20	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201A	Classroom 201 Storage near window wall	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Tan	Flaking	10	0	Negative
1230	1	2	201A	Classroom 201 Storage near window wall	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	10	1.5	Positive
1230	1	2	201A	Classroom 201 Storage near window wall	W3	Plaster	Yellow	None	0	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201A	Classroom 201 Storage near window wall	W4	Plaster	Yellow	None	0	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201A	Classroom 201 Storage near window wall	Ceiling	Plaster	White	Flaking, Cracking	6	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201B	Classroom 201 Storage next to doorway	W1	Plaster	Yellow	None	0	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201B	Classroom 201 Storage next to doorway	W2	Plaster	Yellow	None	0	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201B	Classroom 201 Storage next to doorway	W3	Plaster	Yellow	None	0	18.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201B	Classroom 201 Storage next to doorway	W4	Plaster	Yellow	None	0	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	201B	Classroom 201 Storage next to doorway	Ceiling	Plaster	White	None	0	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	W1	Plaster	Tan	Cracking	5	8.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	W2	Plaster	Tan	Cracking	5	8.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	W3	Plaster	Tan	Cracking	5	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	W4	Plaster	Tan	Cracking	5	9.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	206A	Classroom 206 Storage	W3	Plaster	White	None	0	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	210	Classroom 210	W2	Plaster	White	None	0	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	210A	Classroom 210 Closet	W1	Wood	Brown	N/A	N/A	N/A	N/A	Door	Wood	White	Chipping	5	0.07	Negative
1230	1	2	211	Classroom 211	W2	Plaster	Tan	None	0	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211	Classroom 211	W4	Plaster	Blue	Chipping	10	27.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	211	Classroom 211	W3	Plaster	Blue	Chipping	10	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213A	Classroom 213 Storage	W2	Plaster	White	N/A	0	33.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	2	213A	Classroom 213 Storage	W3	Plaster	White	N/A	0	39.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	213A	Classroom 213 Storage	W4	Plaster	White	N/A	0	32.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	214	Classroom 214	W2	Wood	Tan	None	0	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	301B	Computer Room Storage by Doorway	W1	Plaster	Green	Friction	3	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	301B	Computer Room Storage by Doorway	W2	Plaster	Green	N/A	0	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	301B	Computer Room Storage by Doorway	W3	Plaster	Green	N/A	0	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	301B	Computer Room Storage by Doorway	W4	Plaster	Green	Friction	4	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	301B	Computer Room Storage by Doorway	Ceiling	Plaster	White	N/A	0	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308A	Classroom 308 Storage	W1	Plaster	White	None	0	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308A	Classroom 308 Storage	W2	Plaster	White	Cracking	10	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308A	Classroom 308 Storage	W3	Plaster	White	None	2	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	308A	Classroom 308 Storage	W4	Wood	White	None	0	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	W2	Block	Yellow	None	0	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	W3	Block	Yellow	None	0	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	W1	Block	Yellow	None	0	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	1	107	Home & School Office next to Girl's Restroom	W4	Block	Yellow	None	0	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	205	Office across from Library Center Office	W2	Block	Tan	None	0	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	206	Audio Visual Review Room	W1	Block	Green	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	206	Audio Visual Review Room	W2	Block	Green	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	206	Audio Visual Review Room	W3	Block	Green	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	206	Audio Visual Review Room	W4	Block	Green	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	208	Kitchen in Library	W1	Block	Tan	None	0	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	208	Kitchen in Library	W2	Block	Tan	None	0	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	208	Kitchen in Library	W3	Block	Tan	None	0	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	2	2	208	Kitchen in Library	W4	Block	Tan	None	0	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Friction, Flaking	4	0.01	Negative
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	6	0	Negative
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Brown	Chipping	10	6.6	Positive
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Concrete	Black	Chipping	15	6.1	Positive
1230	1	1	S11	Stairwell A at Classrooms 112 to 114	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	25	4.7	Positive
1230	1	2	S21	Stairwell A at Classroom 210	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Chipping	7	0	Negative
1230	1	2	S21	Stairwell A at Classroom 210	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	8	0	Negative
1230	1	2	S21	Stairwell A at Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Brown	Chipping	10	5.1	Positive
1230	1	2	S21	Stairwell A at Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Concrete	Brown	Chipping	5	0.24	Negative
1230	1	2	S21	Stairwell A at Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	6	6.2	Positive
1230	1	3	S31	Stairwell A at Classroom 310	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Brown	Chipping	10	6.4	Positive
1230	1	3	S31	Stairwell A at Classroom 310	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	4	6.4	Positive
1230	1	3	S31	Stairwell A at Classroom 310	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	3	11.8	Positive
1230	1	3	S31	Stairwell A at Classroom 310	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Friction, Flaking	8	0.02	Negative
1230	1	3	S31	Stairwell A at Classroom 310	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	6	0	Negative
1230	1	3	S31	Stairwell A at Classroom 310	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Metal Stair	Metal	Brown	Chipping	2	12.6	Positive
1230	1	3	S31	Stairwell A at Classroom 310	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Railing	Wood	Brown	Chipping	6	0.29	Negative
1230	1	3	S32	Stairwell B at Classroom 309	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Friction, Flaking	6	0	Negative
1230	1	3	S32	Stairwell B at Classroom 309	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Friction, Flaking	10	0.16	Negative
1230	1	3	S32	Stairwell B at Classroom 309	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Wood	Gray	Chipping	10	0.28	Negative
1230	1	2	S22	Stairwell B at Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Wood	Gray	Chipping	10	0.23	Negative
1230	1	3	S32	Stairwell B at Classroom 309	W2	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Wood	Brown	Chipping	20	0.24	Negative
1230	1	2	S22	Stairwell B at Classroom 209	W2	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Wood	Brown	Chipping	20	0.2	Negative
1230	1	2	S22	Stairwell B at Classroom 209	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Friction, Flaking	10	0	Negative
1230	1	2	S22	Stairwell B at Classroom 209	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	6	0.4	Negative
1230	1	1	S12	Stairwell B at Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Wood	Brown	Chipping	20	0.3	Negative
1230	1	1	S12	Stairwell B at Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Chipping	10	0	Negative

School District of Philadelphia																		
Lead Safe Certification Assessment Report																		
Bryant Promise Academy Elementary School #1230																		
				Inspection Company: Synertech, Inc.														
				Name of Inspector: Bart McMahon/Ryan Hutsell														
				Inspection Dates: 06/17-06/27/2019														
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P a s t e r D a m a g e (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1230	1	1	S12	Stairwell B at Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	10	0.02	Negative
1230	1	1	S13	Stairwell C at Classroom 103	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Chipping	10	0	Negative
1230	1	1	S13	Stairwell C at Classroom 103	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	4	0	Negative
1230	1	3	S33	Stairwell C at Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Chipping	10	0.1	Negative
1230	1	3	S33	Stairwell C at Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	4	0	Negative
1230	1	3	S33	Stairwell C at Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	3	3	Positive
1230	1	3	S33	Stairwell C at Classroom 303	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	6	4.4	Positive
1230	1	3	S33	Stairwell C at Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Brown	Chipping	10	0.19	Negative
1230	1	3	S33	Stairwell C at Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	20	1	Positive
1230	1	3	S33	Stairwell C at Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	5	5.6	Positive
1230	1	3	S33	Stairwell C at Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Concrete	Brown	Chipping	14	5.1	Positive
1230	1	3	S33	Stairwell C at Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Concrete	Brown	Chipping	7	6.8	Positive
1230	1	3	S33	Stairwell C at Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Tread	Concrete	Brown	Chipping	2	0.9	Positive
1230	1	3	S33	Stairwell C at Classroom 303	Ceiling	Plaster	White	Flaking, Efflorescence, Spalling	12	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S23	Stairwell C at Classroom 203	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Chipping	8	0	Negative
1230	1	2	S23	Stairwell C at Classroom 203	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	4	0	Negative
1230	1	2	S23	Stairwell C at Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Brown	Chipping	10	0.27	Negative
1230	1	2	S23	Stairwell C at Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Stringer	Concrete	Brown	Chipping	8	5.5	Positive
1230	1	2	S23	Stairwell C at Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Tread	Concrete	Brown	Chipping	12	6.7	Positive
1230	1	2	S23	Stairwell C at Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Concrete	Brown	Chipping	2	7.6	Positive
1230	1	2	S23	Stairwell C at Classroom 203	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	20	0.01	Negative
1230	1	1	S13	Stairwell C at Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Treads	Concrete	Brown	Chipping	30	6.9	Positive
1230	1	1	S13	Stairwell C at Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Concrete	Brown	Chipping	4	12.5	Positive
1230	1	1	S13	Stairwell C at Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Brown	Chipping	10	0.3	Negative
1230	1	1	S13	Stairwell C at Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	8	0.21	Negative
1230	1	1	S13	Stairwell C at Classroom 103	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	8	17.2	Positive
1230	1	1	S13	Stairwell C at Classroom 103	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	6	0.01	Negative
1230	1	1	S13	Stairwell C at Classroom 103	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	12	0.07	Negative
1230	1	1	S13	Stairwell C at Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	8	14.4	Positive
1230	1	3	S34	Firetower across from Classroom 308	W1	Brick	White	Flaking	40	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S34	Firetower across from Classroom 308	W2	Brick	White	Flaking	150	4.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S34	Firetower across from Classroom 308	W3	Brick	White	Flaking	175	24.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S34	Firetower across from Classroom 308	W4	Brick	White	Flaking	110	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S34	Firetower across from Classroom 308	Floor	Concrete	Gray	Flaking	40	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	3	S34	Firetower across from Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Gray	Flaking	20	0.4	Negative
1230	1	2	S24	Firetower across from Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Concrete	Gray	Flaking	80	1.5	Positive
1230	1	3	S34	Firetower across from Classroom 308	Ceiling	Concrete	White	Flaking	150	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S24	Firetower across from Classroom 208	W1	Brick	White	Flaking	40	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S24	Firetower across from Classroom 208	W2	Brick	White	Flaking	150	2.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S24	Firetower across from Classroom 208	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window Frame	Wood	Brown	Flaking	10	19.1	Positive
1230	1	2	S24	Firetower across from Classroom 208	W3	Brick	White	Flaking	100	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S24	Firetower across from Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window Frame	Wood	Brown	Flaking	2	22.5	Positive
1230	1	2	S24	Firetower across from Classroom 208	W4	Brick	White	Flaking	120	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S24	Firetower across from Classroom 208	Floor	Concrete	Gray	Flaking	40	1.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	2	S24	Firetower across from Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Gray	Flaking	20	0.4	Negative
1230	1	2	S24	Firetower across from Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Riser	Concrete	Gray	Flaking	80	1.2	Positive
1230	1	2	S24	Firetower across from Classroom 208	Ceiling	Concrete	White	Flaking	200	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S14	Firetower across from Classroom 108	W1	Brick	White	Flaking	70	35.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S14	Firetower across from Classroom 108	W2	Brick	White	Flaking	80	9.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1230	1	1	S14	Firetower across from Classroom 108	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window Frame	Wood	Brown	Flaking	5	8.2	Positive
1230	1	1	S14	Firetower across from Classroom 108	W3	Brick	White	Flaking	50	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia																					
Lead Safe Certification Assessment Report																					
Bryant Promise Academy Elementary School #1230																					
				Inspection Company: Synertech, Inc.																	
				Name of Inspector: Bart McMahon/Ryan Hutsell																	
				Inspection Dates: 06/17-06/27/2019																	
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Pester Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)			
1230	1	1	S14	Firetower across from Classroom 108	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Flaking	4	0.14	Negative			
1230	1	1	S14	Firetower across from Classroom 108	W4	Brick	White	Flaking	70	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	S14	Firetower across from Classroom 108	Floor	Concrete	Gray	Flaking	40	2.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	S14	Firetower across from Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Gray	Flaking	20	0.4	Negative			
1230	1	1	S14	Firetower across from Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Gray	Flaking	80	1.3	Positive			
1230	1	1	S14	Firetower across from Classroom 108	Ceiling	Concrete	White	Flaking	200	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	S35	Firetower next to Classroom 302	W1	Brick	White	Cracking	20	3.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	S35	Firetower next to Classroom 302	W2	Brick	White	Cracking, Flaking	80	3.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	S35	Firetower next to Classroom 302	W3	Brick	White	Flaking, Efflorescence	15	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	S35	Firetower next to Classroom 302	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window Frame	Wood	Brown	Flaking	4	0.12	Negative			
1230	1	3	S35	Firetower next to Classroom 302	W4	Brick	White	Flaking	6	3.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	S35	Firetower next to Classroom 302	Floor	Concrete	Gray	Flaking	20	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	S35	Firetower next to Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Gray	Flaking	15	0.3	Negative			
1230	1	3	S35	Firetower next to Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Gray	Flaking	80	1.2	Positive			
1230	1	3	S35	Firetower next to Classroom 302	Ceiling	Concrete	White	Flaking	15	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	S25	Firetower next to Classroom 202	W1	Brick	White	Cracking	25	3.2	Positive	Door Frame	Metal	Brown	Flaking	3	0.13	Negative			
1230	1	2	S25	Firetower next to Classroom 202	W2	Brick	White	Flaking, Efflorescence	100	2.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	S25	Firetower next to Classroom 202	W3	Brick	White	Flaking	30	6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	S25	Firetower next to Classroom 202	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window Frame	Wood	Brown	Flaking	6	2	Positive			
1230	1	2	S25	Firetower next to Classroom 202	W4	Brick	White	Cracking	2	6.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	S25	Firetower next to Classroom 202	Floor	Concrete	Gray	Flaking	4	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	S25	Firetower next to Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Gray	Flaking	15	0.3	Negative			
1230	1	2	S25	Firetower next to Classroom 202	Ceiling	Concrete	White	Flaking	30	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	S15	Firetower next to Classroom 102	W1	Brick	White	Cracking	2	5.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	S15	Firetower next to Classroom 102	W2	Brick	White	Cracking	10	6.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	S15	Firetower next to Classroom 102	W3	Brick	White	Efflorescence, Flaking	25	4.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	S15	Firetower next to Classroom 102	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Flaking, Cracking	8	0.27	Negative			
1230	1	1	S15	Firetower next to Classroom 102	W4	Brick	White	Cracking	2	6.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	S15	Firetower next to Classroom 102	Floor	Concrete	Gray	Flaking	10	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	S15	Firetower next to Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Gray	Flaking	30	0.01	Negative			
1230	1	1	S15	Firetower next to Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Strair riser	Concrete	Gray	Flaking	12	3.1	Positive			
1230	1	1	S15	Firetower next to Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Treads	Concrete	Gray	Flaking	10	0.08	Negative			
1230	1	1	S15	Firetower next to Classroom 102	Ceiling	Concrete	White	Flaking	5	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	H32	Main Hallway at Classroom 303 to 309	Ceiling	Plaster	White	Efflorescence	40	15.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	100B	Vice Principal's Office	Ceiling	Plaster	White	Cracking	4	28.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	202B	Storage outside Classroom 202 by Stairwell C	Ceiling	Plaster	Tan	Chipping	30	9.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	302B	Storage outside Classroom 302 by Stairwell C	Ceiling	Plaster	Tan	Chipping	5	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	1	110B	Nurse's Office Restroom	W3	Plaster	White	Chipping	20	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	309A	Classroom 309 Storage	W2	Plaster	Tan	Cracking	10	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	311	Classroom 311	W1	Plaster	Tan	Cracking	5	34.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	210	Classroom 210	W3	Plaster	White	Cracking	20	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	302A	Classroom 302 Storage	W1	Plaster	Tan	Cracking	1	36.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	302A	Classroom 302 Storage	W2	Plaster	Tan	Flaking	1	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	302A	Classroom 302 Storage	W3	Plaster	Tan	Cracking	1	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	302A	Classroom 302 Storage	W4	Plaster	Tan	Flaking	1	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	306A	Classroom 306 Storage	W2	Plaster	Tan	Chipping	5	8.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	3	306	Classroom 306	W1	Plaster	Tan	Cracking	5	30.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	209A	Classroom 209 Storage	W2	Plaster	White	Chipping	20	24.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	209A	Classroom 209 Storage	W4	Plaster	White	Chipping	20	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			
1230	1	2	208A	Classroom 208 Storage	W2	Plaster	Yellow	Chipping	20	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A			

School District of Philadelphia																			
Lead Safe Certification Assessment Report																			
Bryant Promise Academy Elementary School #1230																			
				Inspection Company: Synertech, Inc.															
				Name of Inspector: Bart McMahon/Ryan Hutsell															
				Inspection Dates: 06/17-06/27/2019															
ULC S#	E l e m e n t	Flo or	Space #	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and P aster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	
1230	1	2	208A	Classroom 208 Storage	W4	Plaster	Yellow	Chipping	20	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	214B	Classroom 214 Storage	W2	Plaster	White	Chipping	10	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	214B	Classroom 214 Storage	Ceiling	Plaster	White	Flaking	20	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	H32	Main Hallway at Classroom 303 to 309	W1	Plaster	Tan	ng, Chipping, F	36	33.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	H32	Main Hallway at Classroom 303 to 309	W3	Plaster	Tan	ng, Chipping, F	12	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	H31	Hallway at Classrooms 310 to 314	W1	Plaster	Tan	ng, Chipping, F	40	35.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	3	H31	Hallway at Classrooms 310 to 314	W3	Plaster	Tan	ng, Chipping, F	20	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	3	307	Classroom 307	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	1	5.1	Positive	
NEW	1	3	307	Classroom 307	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Flaking	1	6.7	Positive	
NEW	1	2	210	Classroom 210	W1	Plaster	Tan	Flaking	6	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	210	Classroom 210	W3	Plaster	Tan	Flaking/Efflores cence	20	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	210	Classroom 210	W3	Plaster	White	Cracking	10	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	210	Classroom 210	Radiator (W3)	Metal	Tan	Friction	3	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	210	Classroom 210	W4 (soap dispenser)	Plaster	Tan	Holes	1		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	210	Classroom 210	Ceiling	Plaster	White	Moisture Damage	2		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	211	Classroom 211	W2	Plaster	Tan	Chipping	6	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	211	Classroom 211	W2	Plaster	Tan	ap Dispenser Hol	1	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	211	Classroom 211	W3	Plaster	Tan	Flaking	10	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	211	Classroom 211	W3	Plaster	Tan	Efflorescence	2	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	211	Classroom 211	W4	Plaster	Tan	Flaking	15	N/A	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	212	Classroom 212	W1 (soap dispenser)	Plaster	Tan	Holes	1		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	212	Classroom 212	W3	Plaster	Tan	Flaking/Efflores cence	15		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	212	Classroom 212	W3 (Radiator)	Metal	Silver	Chipping	8		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	212A	Classroom 212 Storage	W1	Plaster	White	Chipping	2	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	212A	Classroom 212 Storage	W2	Plaster	White	Flaking	10	20.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	212A	Classroom 212 Storage	W3	Plaster	White	Flaking	8	17.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	212A	Classroom 212 Storage	W4	Plaster	White	Flaking	10	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	213	Classroom 213	W1 (soap dispenser)	Plaster	Tan	Holes	1		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	214	Classroom 214	W1 (soap dispenser)	Plaster	Tan	Holes	1		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	214B	Classroom 214 Storage	W2	Plaster	White	Chipping	10	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	214B	Classroom 214 Storage	Ceiling	Plaster	White	Flaking	20	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NEW	1	2	214B	Classroom 214 Storage	W3	Plaster	White	Flaking	8	17.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	200	Teacher's Lounge	W1	Plaster	Tan	Flaking	5		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	200	Teacher's Lounge	W2	Plaster	Tan	Flaking	10	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	200	Teacher's Lounge	W3	Plaster	Tan	Chipping	20	32.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	200	Teacher's Lounge	W4	Plaster	Tan	Cracking	6	20.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	200	Teacher's Lounge	Ceiling	Plaster	White	Flaking	1		Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	200A	Teacher's Lounge Restroom	W1	Plaster	Tan	Chipping	1	39.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	2	200A	Teacher's Lounge Restroom	W2	Plaster	Tan	Chipping	8	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	110A	Nurse's Office	Ceiling	Plaster	White	Flaking	6	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1230	1	1	110	Nurse's Suite - Rear Office	Ceiling	Plaster	White	Flaking	1	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	