

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	Classroom 100	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	W1	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	W3	Plaster	Tan	Flaking	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 100	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Friction	5	0.02	Negative
1	1	Classroom 101	W2	Plaster	White	Chipping	3	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	W4	Plaster	White	Chipping	3	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office/Classroom 102	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office/Classroom 102	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office/Classroom 102	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office/Classroom 102	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office/Classroom 102	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office/Classroom 102	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office/Classroom 102	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office/Classroom 102	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W1	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W2	Plaster	Tan	Chipping	5	0.14	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W4	Plaster	Tan	Chipping	2	0.13	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W4	Concrete	White	None	0	N/A	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W4	Concrete	Tan	None	0	N/A	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	2	0.23	Negative
1	1	Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W2	Concrete	Brown	Friction	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W4	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W4	Plaster	Tan	Chipping	2	0.21	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Friction	5	0.22	Negative
1	1	Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W1	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W2	Plaster	Tan	Chipping	2	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W2	Wood	Tan	Friction	5	0.23	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W4	Concrete	Brown	Friction	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	Classroom 106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge Restroom	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge Restroom	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge Restroom	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge Restroom	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W1	Concrete	Red	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W1	Concrete	Orange	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W2	Concrete	Red	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W2	Concrete	Orange	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Friction	10	12.4	Positive
1	1	Hallway from Classrooms 103-106	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W3	Concrete	Red	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W3	Concrete	Orange	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W3	Plaster	Yellow	Chipping	2	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W4	Concrete	Red	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W4	Concrete	Orange	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W4	Plaster	Yellow	Chipping	2	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Friction	10	18.6	Positive
1	1	Hallway from Classrooms 103-106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 103-106	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W1	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W3	Plaster	Green	Friction	10	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W4	Plaster	Green	Friction	5	0.21	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	W4	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Friction	10	5.9	Positive
1	1	Stairwell #4	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #4	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W3	Plaster	Blue	Chipping	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W4	Plaster	Blue	Chipping	10	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	W4	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Friction	10	12.2	Positive

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	Stairwell #3	W4	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Brown	Friction	5	0.11	Negative
1	1	Stairwell #3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell #3	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway to Exterior Entrance between Classrooms 100 and 101	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway to Exterior Entrance between Classrooms 100 and 101	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway to Exterior Entrance between Classrooms 100 and 101	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway to Exterior Entrance between Classrooms 100 and 101	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway to Exterior Entrance between Classrooms 100 and 101	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway to Exterior Entrance between Classrooms 100 and 101	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway to Exterior Entrance between Classrooms 100 and 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway to Exterior Entrance between Classrooms 100 and 101	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Vestibule at Exterior Entrance between Classrooms 100 and 101	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Vestibule at Exterior Entrance between Classrooms 100 and 101	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Vestibule at Exterior Entrance between Classrooms 100 and 101	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Vestibule at Exterior Entrance between Classrooms 100 and 101	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Vestibule at Exterior Entrance between Classrooms 100 and 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Vestibule at Exterior Entrance between Classrooms 100 and 101	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	3	0	Negative
2	1	Auditorium	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	3	0.02	Negative
2	1	Auditorium	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	3	0.02	Negative
2	1	Auditorium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stairs to Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stairs to Stage	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stairs to Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stairs to Stage	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stairs to Stage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stairs to Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office	W1	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office	W2	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office	W3	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office	W4	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Restroom	W1	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Restroom	W2	Concrete	Gray	Chipping	2	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Restroom	W3	Concrete	Gray	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Restroom	W4	Concrete	Gray	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Closet	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Closet	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Closet	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019																
Name of Inspector: Melissa Billingsley																
Inspection Company: Criterion Labs., Inc																
E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
2	1	Principal's Office Closet	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Principal's Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	W1	Concrete	Brown	Chipping	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	W2	Concrete	Brown	Chipping	3	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	W3	Concrete	Brown	Chipping	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	W4	Concrete	Brown	Chipping	3	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Telecommunication Equipment Room	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Telecommunication Equipment Room	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Telecommunication Equipment Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Telecommunication Equipment Room	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Telecommunication Equipment Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Telecommunication Equipment Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Assistant Principal's Office	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Assistant Principal's Office	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Assistant Principal's Office	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Assistant Principal's Office	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Assistant Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Assistant Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Office adjacent to Principal's Office	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Office adjacent to Principal's Office	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Office adjacent to Principal's Office	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Office adjacent to Principal's Office	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Office adjacent to Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Office adjacent to Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Closet	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Closet	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Closet	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Closet	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Closet	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Closet	W2	Concrete	White	Partially Inaccessible	0	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Closet	W3	Concrete	White	Partially Inaccessible	0	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Closet	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Nurse's Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Conference Room 6	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Conference Room 6	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Conference Room 6	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Conference Room 6	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
2	1	Conference Room 6	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Conference Room 6	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Men's Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Men's Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Men's Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Men's Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Men's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Men's Restroom	Floor	Concrete	Gray	Friction	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Women's Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Women's Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Women's Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Women's Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Women's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Women's Restroom	Floor	Concrete	Gray	Friction	5	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Elevator	W1	Elevator	Green	Friction	5	3.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Elevator	W2	Elevator	Green	Friction	5	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Elevator	W3	Elevator	Green	Friction	5	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Elevator	W4	Elevator	Green	Friction	5	0.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Elevator	Ceiling	Metal	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Right of Stage	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Right of Stage	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Right of Stage	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Right of Stage	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Right of Stage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Right of Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Left of Stage	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Left of Stage	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Left of Stage	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Left of Stage	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Left of Stage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Auditorium Stage Storage Room to Left of Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	S.C.C. Office	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	S.C.C. Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	5	0.03	Negative
2	1	S.C.C. Office	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	S.C.C. Office	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	S.C.C. Office	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	S.C.C. Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	S.C.C. Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Electrical Room	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Electrical Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	3	0.03	Negative
2	1	Electrical Room	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Electrical Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Electrical Room	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Electrical Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	B	Elevator Mechanical Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Elevator Mechanical Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Elevator Mechanical Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Elevator Mechanical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Elevator Mechanical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Elevator Mechanical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Custodial Storage Room adjacent to Electrical Room	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Custodial Storage Room adjacent to Electrical Room	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Custodial Storage Room adjacent to Electrical Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Custodial Storage Room adjacent to Electrical Room	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Custodial Storage Room adjacent to Electrical Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Custodial Storage Room adjacent to Electrical Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Lobby to Stairwell #2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Lobby to Stairwell #2	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Lobby to Stairwell #2	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

Element	Floor	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
2	1	Hallway from Lobby to Stairwell #2	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Lobby to Stairwell #2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Lobby to Stairwell #2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Lobby between Element 1 and Element 2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Lobby between Element 1 and Element 2	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Lobby between Element 1 and Element 2	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Lobby between Element 1 and Element 2	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Lobby between Element 1 and Element 2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Lobby between Element 1 and Element 2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Entrance Lobby	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Entrance Lobby	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Entrance Lobby	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Entrance Lobby	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Entrance Lobby	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Main Entrance Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Center Aisle	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Center Aisle	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Center Aisle	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Center Aisle	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Center Aisle	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Center Aisle	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Left Aisle	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Left Aisle	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Left Aisle	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Left Aisle	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Left Aisle	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway to Auditorium Left Aisle	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Stairwell #1 to Stairwell #2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Stairwell #1 to Stairwell #2	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Stairwell #1 to Stairwell #2	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Stairwell #1 to Stairwell #2	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Stairwell #1 to Stairwell #2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Stairwell #1 to Stairwell #2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Main Entrance to Gymateria	W1	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Main Entrance to Gymateria	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Main Entrance to Gymateria	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Main Entrance to Gymateria	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Main Entrance to Gymateria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Main Entrance to Gymateria	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	W1	Concrete	Brown	Friction	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	W2	Concrete	Brown	Friction	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.05	Negative
2	1	Entrance adjacent to Stairwell #2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.03	Negative
2	1	Entrance adjacent to Stairwell #2	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	W3	Concrete	Brown	Friction	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	W4	Concrete	Brown	Friction	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Entrance adjacent to Stairwell #2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
2	1	Stairwell #2 Exterior Entrance	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 Exterior Entrance	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.4	Negative
2	1	Stairwell #2 Exterior Entrance	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 Exterior Entrance	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 Exterior Entrance	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 Exterior Entrance	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	10	0.03	Negative
2	1	Stairwell #2 Exterior Entrance	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.02	Negative
2	1	Stairwell #2 Exterior Entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 Exterior Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 Exterior Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Brown	Friction	10	0.04	Negative
2	1	Stairwell #2 from Landing at 1st Floor to next Landing Up	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 from Landing at 1st Floor to next Landing Up	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 from Landing at 1st Floor to next Landing Up	W3	Concrete	White	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 from Landing at 1st Floor to next Landing Up	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 from Landing at 1st Floor to next Landing Up	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairwell #2 from Landing at 1st Floor to next Landing Up	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Teacher Lounge/Dining	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Teacher Lounge/Dining	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Teacher Lounge/Dining	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	3	0.04	Negative
2	1	Teacher Lounge/Dining	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Teacher Lounge/Dining	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Teacher Lounge/Dining	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Teacher Lounge/Dining	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Kitchen	W1	Concrete	White	Friction	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Kitchen	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	3	0.04	Negative
2	1	Gymateria Kitchen	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Kitchen	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Kitchen	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Kitchen	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	3	0.01	Negative
2	1	Gymateria Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria (Cafeteria / Gymnasium)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Storage Room adjacent to Kitchen	W1	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Storage Room adjacent to Kitchen	W2	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Storage Room adjacent to Kitchen	W3	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Storage Room adjacent to Kitchen	W4	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Storage Room adjacent to Kitchen	Ceiling	Concrete	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Storage Room adjacent to Kitchen	Floor	Concrete	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Corner Storage Room Kitchen Side	W1	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Corner Storage Room Kitchen Side	W2	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
2	1	Gymateria Corner Storage Room Kitchen Side	W3	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Corner Storage Room Kitchen Side	W4	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Corner Storage Room Kitchen Side	Ceiling	Concrete	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Corner Storage Room Kitchen Side	Floor	Concrete	N/A	No Access	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office	W3	Concrete	White	Flaking	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office	W4	Concrete	White	Flaking	5	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymnasium Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Former Girl's Dressing Room	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Former Girl's Dressing Room	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Former Girl's Dressing Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Former Girl's Dressing Room	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Former Girl's Dressing Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Former Girl's Dressing Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Girl's Restroom	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Gymateria Boy's Restroom	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	GymateriaFormer Boy's Dressing Room	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	GymateriaFormer Boy's Dressing Room	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	GymateriaFormer Boy's Dressing Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	GymateriaFormer Boy's Dressing Room	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	GymateriaFormer Boy's Dressing Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	GymateriaFormer Boy's Dressing Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1	W1	Concrete	White	Chipping	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1	W2	Concrete	White	Chipping	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1	W3	Concrete	White	Chipping	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1	W4	Wood	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to entrance	W1	Concrete	White	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to entrance	W2	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to entrance	W3	Concrete	White	Chipping	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to entrance	W4	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Restroom	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Restroom	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Restroom	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Restroom	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report
Comegys Elementary School
5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019
Name of Inspector: Melissa Billingsley
Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
3	1	Classroom K1 Restroom	Floor	Concrete	Gray	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to restroom	W3	Concrete	White	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to restroom	W4	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to restroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to partition wall	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to partition wall	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to partition wall	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to partition wall	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to partition wall	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K1 Closet adjacent to partition wall	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to entrance	W1	Concrete	White	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to entrance	W2	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to entrance	W3	Concrete	White	Chipping	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to entrance	W4	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	W1	Concrete	White	Chipping	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	W1	Concrete	Tan	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	W2	Wood	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	W3	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	W3	Concrete	Tan	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	W4	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	W4	Concrete	Tan	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Restroom	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Restroom	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Restroom	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Restroom	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Restroom	Floor	Concrete	Gray	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to restroom	W3	Concrete	White	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to restroom	W4	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to restroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to partition wall	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to partition wall	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to partition wall	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to partition wall	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to partition wall	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Classroom K2 Closet adjacent to partition wall	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Circular Storage Room near Classroom K2	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
3	1	Circular Storage Room near Classroom K2	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
3	1	Circular Storage Room near Classroom K2	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
3	1	Circular Storage Room near Classroom K2	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
3	1	Circular Storage Room near Classroom K2	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
3	1	Circular Storage Room near Classroom K2	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
3	1	Hallway outside Classrooms K1 and K2	W1	Concrete	Red	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W1	Concrete	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W2	Concrete	Green	Chipping	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W2	Concrete	Blue	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W2	Concrete	Yellow	Chipping	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W2	Concrete	White	Chipping	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report
Comegys Elementary School
5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

Element	Floor	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
3	1	Hallway outside Classrooms K1 and K2	W3	Concrete	Green	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W3	Concrete	Blue	Chipping	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W3	Concrete	Yellow	Chipping	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W3	Concrete	White	Chipping	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	W4	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway outside Classrooms K1 and K2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Entrance Lobby	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Entrance Lobby	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Entrance Lobby	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Entrance Lobby	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Entrance Lobby	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Entrance Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway between Element 1 and Element 3	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway between Element 1 and Element 3	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway between Element 1 and Element 3	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway between Element 1 and Element 3	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway between Element 1 and Element 3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Hallway between Element 1 and Element 3	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W1	Plaster	Yellow	Chipping	10	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	3	0.03	Negative
1	2	Classroom 200	W2	Plaster	Yellow	Chipping	10	0.21	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	5	0.11	Negative
1	2	Classroom 200	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W3	Concrete	Yellow	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W3	Concrete	Brown	Friction	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	5	0.2	Negative
1	2	Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Yellow	Friction	5	0.01	Negative
1	2	Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Brown	Chipping	2	0.4	Negative
1	2	Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Wood	Yellow	Chipping	10	0.32	Negative
1	2	Classroom 200	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	5	0.13	Negative
1	2	Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Clinical Services	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Clinical Services	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Clinical Services	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Clinical Services	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Clinical Services	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Clinical Services	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Yellow	Friction	5	0.22	Negative
1	2	Classroom 202	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W4	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Friction	2	0.03	Negative
1	2	Classroom 203	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W2	Plaster	Yellow	Moisture Damage	5	0.22	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Friction	5	0.03	Negative
1	2	Classroom 203	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	Classroom 203	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W4	Plaster	Yellow	Chipping	1	0.21	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC/Library 204	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC/Library 204	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC/Library 204	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC/Library 204	W4	Wood	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC/Library 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC/Library 204	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	W2	Plaster	White	Chipping	1	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	W2	Wood	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	W2	Concrete	Brown	Friction	5	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Friction	5	0.11	Negative
1	2	Classroom 206	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 206	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge 202 1/2	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge 202 1/2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge 202 1/2	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge 202 1/2	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge 202 1/2	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge 202 1/2	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge 202 1/2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge 202 1/2	Floor	Concrete	Gray	Friction	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge Restroom	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge Restroom	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 SETSS Room	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 Restroom	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 Restroom	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 Restroom	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 Restroom	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 199 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 203 to 206	W1	Concrete	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	Hallway from Classrooms 203 to 206	W2	Concrete	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 203 to 206	W2	Plaster	Purple	Chipping	2	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 203 to 206	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	5	0.15	Negative
1	2	Hallway from Classrooms 203 to 206	W3	Concrete	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 203 to 206	W4	Plaster	White	Chipping	20	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 203 to 206	W4	Plaster	Purple	Chipping	10	0.18	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 203 to 206	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Brown	Chipping	5	0.11	Negative
1	2	Hallway from Classrooms 203 to 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 203 to 206	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W2	Plaster	Green	Chipping	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W3	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W4	Plaster	Green	Chipping	5	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	W4	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Friction	10	12.5	Positive
1	2	Stairwell #4	W4	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Brown	Friction	5	0.11	Negative
1	2	Stairwell #4	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #4	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W2	Plaster	Blue	Friction	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W4	Plaster	Blue	Friction	2	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	W4	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Friction	10	13.4	Positive
1	2	Stairwell #3	W4	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindle	Metal	Green	Friction	10	0.04	Negative
1	2	Stairwell #3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell #3	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Brown	Friction	10	0.12	Negative
1	AT	Stairwell #3 to Attic and Roof	W1	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Stairwell #3 to Attic and Roof	W2	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Stairwell #3 to Attic and Roof	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Wood	Green	Friction	5	0.04	Negative
1	AT	Stairwell #3 to Attic and Roof	W3	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Stairwell #3 to Attic and Roof	W4	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Stairwell #3 to Attic and Roof	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Stairwell #3 to Attic and Roof	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Stairwell #3 to Attic and Roof	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Green	Friction	5	0.9	Positive
1	AT	Stairwell #3 to Attic and Roof	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Concrete	Green	Friction	5	0.7	Positive
2	2	Classroom 207	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 207	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 207	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 207	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 208	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 208	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 208	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 208	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 214	W1	Concrete	White	Chipping	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 214	W2	Concrete	White	Chipping	5	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 214	W3	Concrete	White	Chipping	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 214	W4	Concrete	White	Chipping	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
2	2	Classroom 214	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W1	Concrete	Yellow	Chipping	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W1	Concrete	Tan	Chipping	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W2	Concrete	Tan	Chipping	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W3	Concrete	Yellow	Chipping	3	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W3	Concrete	Green	Chipping	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W3	Concrete	Blue	Chipping	3	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W4	Concrete	Yellow	Chipping	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	W4	Concrete	Tan	Chipping	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 212	W1	Concrete	Blue	Chipping	5	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 212	W1	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 212	W2	Concrete	Purple	Chipping	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 212	W3	Concrete	Blue	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 212	W4	Concrete	Blue	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 212	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 211	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 211	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	3	0	Negative
2	2	Classroom 211	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 211	W3	Concrete	White	Chipping	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 211	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 211	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 209	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 209	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 209	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 209	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 210	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 210	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 210	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 210	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Book 2 adjacent to Classroom 210	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Book 2 adjacent to Classroom 210	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Book 2 adjacent to Classroom 210	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Book 2 adjacent to Classroom 210	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Book 2 adjacent to Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Book 2 adjacent to Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Boy's Restroom across from Classroom 213	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Boy's Restroom across from Classroom 213	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.04	Negative
2	2	Boy's Restroom across from Classroom 213	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Boy's Restroom across from Classroom 213	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Boy's Restroom across from Classroom 213	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Boy's Restroom across from Classroom 213	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Boy's Restroom across from Classroom 213	Floor	Concrete	Gray	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Girl's Restroom across from Classroom 213	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Girl's Restroom across from Classroom 213	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.11	Negative
2	2	Girl's Restroom across from Classroom 213	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Girl's Restroom across from Classroom 213	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Girl's Restroom across from Classroom 213	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Girl's Restroom across from Classroom 213	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Girl's Restroom across from Classroom 213	Floor	Concrete	Gray	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Custodial Closet adjacent to Girl's Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Custodial Closet adjacent to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.03	Negative

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

Element	Floor	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
2	2	Custodial Closet adjacent to Girl's Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Custodial Closet adjacent to Girl's Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Custodial Closet adjacent to Girl's Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Custodial Closet adjacent to Girl's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Custodial Closet adjacent to Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	W1	Concrete	Green	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	W2	Concrete	Green	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	W3	Concrete	Green	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	W4	Concrete	Green	Chipping	5	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 211-214	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	W1	Concrete	Green	Chipping	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	W2	Concrete	Green	Chipping	5	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	W3	Concrete	Green	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	W4	Concrete	Green	Chipping	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 207-208	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	W1	Concrete	Green	Chipping	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	W2	Concrete	Green	Chipping	5	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	W3	Concrete	Green	Chipping	5	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	W4	Concrete	Green	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway outside Classrooms 209-210	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway connector between Element 1 and Element 2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway connector between Element 1 and Element 2	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway connector between Element 1 and Element 2	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway connector between Element 1 and Element 2	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway connector between Element 1 and Element 2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Hallway connector between Element 1 and Element 2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 2nd Floor to 1st Landing	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 2nd Floor to 1st Landing	W2	Concrete	White	Chipping	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 2nd Floor to 1st Landing	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 2nd Floor to 1st Landing	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 2nd Floor to 1st Landing	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 2nd Floor to 1st Landing	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 1st landing to 2nd landing	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 1st landing to 2nd landing	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 1st landing to 2nd landing	W3	Concrete	White	Chipping	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 1st landing to 2nd landing	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 1st landing to 2nd landing	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #2 from 1st landing to 2nd landing	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	W2	Concrete	Blue	Chipping	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	W3	Concrete	Blue	Friction	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

Element	Floor	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
2	2	Stairwell #1	W4	Concrete	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairwell #1	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 304	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 304	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.05	Negative
2	3	Classroom 304	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.03	Negative
2	3	Classroom 304	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 304	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 304	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 304	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 304	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 303	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 303	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 303	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 303	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Book 3 adjacent to Classroom 303	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Book 3 adjacent to Classroom 303	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Book 3 adjacent to Classroom 303	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Book 3 adjacent to Classroom 303	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Book 3 adjacent to Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Book 3 adjacent to Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 302	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 302	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 302	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 302	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 305	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 305	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 305	W3	Concrete	White	Friction	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 305	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 306	W1	Concrete	White	Chipping	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.03	Negative
2	3	Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.01	Negative
2	3	Classroom 306	W2	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 306	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 306	W3	Concrete	White	Chipping	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 306	W4	Concrete	White	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 301	W1	Concrete	White	Friction	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 301	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.03	Negative
2	3	Classroom 301	W2	Concrete	Purple	Friction	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 301	W3	Concrete	Green	Friction	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 301	W3	Concrete	White	Friction	3	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 301	W4	Concrete	Blue	Friction	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 300	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 300	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 300	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 300	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

Element	Floor	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
2	3	Classroom 307	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 307	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 307	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 307	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Classroom 307	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage next to Classroom 300	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage next to Classroom 300	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage next to Classroom 300	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage next to Classroom 300	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage next to Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage next to Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Boy's Restroom across from Classroom 306	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Boy's Restroom across from Classroom 306	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Boy's Restroom across from Classroom 306	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Boy's Restroom across from Classroom 306	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Boy's Restroom across from Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Boy's Restroom across from Classroom 306	Floor	Concrete	Gray	Friction	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from Classroom 305	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from Classroom 305	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from Classroom 305	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from Classroom 305	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from Classroom 305	Floor	Concrete	Gray	Friction	5	0.23	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Custodial Closet adjacent to Girl's Restroom	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Custodial Closet adjacent to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.03	Negative
2	3	Custodial Closet adjacent to Girl's Restroom	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Custodial Closet adjacent to Girl's Restroom	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Custodial Closet adjacent to Girl's Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Custodial Closet adjacent to Girl's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Custodial Closet adjacent to Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	W1	Concrete	Blue	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	W2	Concrete	Blue	Friction	10	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	W3	Concrete	Blue	Friction	10	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	W4	Concrete	Blue	Friction	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 304 to 307	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	W1	Concrete	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	W2	Concrete	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	W3	Concrete	Blue	Friction	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	W4	Concrete	Blue	Friction	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 300 to 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	W1	Concrete	Blue	Friction	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	W2	Concrete	Blue	Friction	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	W3	Concrete	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	W4	Concrete	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway outside Classrooms 302 to 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

Element	Floor	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
2	3	Hallway Connector between Element 1 and Element 2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway Connector between Element 1 and Element 2	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway Connector between Element 1 and Element 2	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway Connector between Element 1 and Element 2	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway Connector between Element 1 and Element 2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Hallway Connector between Element 1 and Element 2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #2	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #2	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #2	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #2	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W1	Concrete	Brown	Friction	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W2	Concrete	Brown	Friction	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W3	Concrete	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W3	Concrete	Brown	Friction	3	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	W4	Concrete	Brown	Friction	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairwell #1	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Pump Room	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Pump Room	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Pump Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Pump Room	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Pump Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Pump Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Compressor Room	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Compressor Room	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Compressor Room	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Compressor Room	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Compressor Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Compressor Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Time Clock Room adjacent to Building Engineer's Office	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Time Clock Room adjacent to Building Engineer's Office	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Time Clock Room adjacent to Building Engineer's Office	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Time Clock Room adjacent to Building Engineer's Office	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Time Clock Room adjacent to Building Engineer's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Time Clock Room adjacent to Building Engineer's Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Storage next to Building Engineer's Office	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Storage next to Building Engineer's Office	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Storage next to Building Engineer's Office	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Storage next to Building Engineer's Office	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Storage next to Building Engineer's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

E l e m e n t	F l o o r	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	Storage next to Building Engineer's Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Art Room	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Art Room	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Art Room	W3	Plaster	White	Moisture Damage	30	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Art Room	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Art Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Art Room	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W1	Metal	Brown	Friction	10	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W4	Metal	Brown	Friction	10	20.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Floor	Concrete	Brown	Friction	10	0.13	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom Closet	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom Closet	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom Closet	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom Closet	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom Closet	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	Floor	Concrete	Brown	Friction	10	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Mower Storage Room	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Mower Storage Room	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Mower Storage Room	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Mower Storage Room	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Mower Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Mower Storage Room	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Closet adjacent to Mower Storage Room	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Closet adjacent to Mower Storage Room	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Closet adjacent to Mower Storage Room	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Closet adjacent to Mower Storage Room	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Closet adjacent to Mower Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Closet adjacent to Mower Storage Room	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Men's Restroom	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Men's Restroom	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Men's Restroom	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Men's Restroom	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Men's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Men's Restroom	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	W1	Concrete	White	Chipping	30	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	W1	Concrete	Gray	Chipping	30	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	W2	Concrete	White	Chipping	30	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	W2	Concrete	Gray	Chipping	30	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	W3	Concrete	White	Moisture Damage	30	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	W3	Concrete	Gray	Moisture Damage	30	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	W4	Concrete	White	Chipping	30	0.13	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	W4	Concrete	Gray	Chipping	30	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	Ceiling	Concrete	White	Flaking	30	0.23	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Electrical Room	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Stairwell	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Stairwell	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Stairwell	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Stairwell	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Stairwell	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom Stairwell	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report

Comegys Elementary School

5100 Greenway Ave, Philadelphia, PA 19143

Inspection Dates: 7/19-7/31/2019

Name of Inspector: Melissa Billingsley

Inspection Company: Criterion Labs., Inc

Element	Floor	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
1	B	Storage outside Boy's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage outside Boy's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage outside Boy's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage outside Boy's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage outside Boy's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage outside Boy's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway outside Electrical Room	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Electrical Room	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Electrical Room	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Electrical Room	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Electrical Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Electrical Room	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway by Boy's Restroom	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway by Boy's Restroom	W2	Brick	White	Chipping	10	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway by Boy's Restroom	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway by Boy's Restroom	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway by Boy's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway by Boy's Restroom	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Art Room	W1	Brick	White	Chipping	5	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Art Room	W2	Brick	White	Chipping	5	1.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Art Room	W3	Brick	White	Chipping	5	2.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Art Room	W4	Brick	White	Chipping	5	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Art Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Art Room	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway between Pump Room and Stairwell #4	W1	Brick	White	Chipping	5	4.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway between Pump Room and Stairwell #4	W2	Brick	White	Chipping	5	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway between Pump Room and Stairwell #4	W3	Brick	White	Chipping	5	3.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway between Pump Room and Stairwell #4	W4	Brick	White	Chipping	5	2.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway between Pump Room and Stairwell #4	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway between Pump Room and Stairwell #4	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Girl's Restroom	W1	Brick	White	Chipping	5	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Girl's Restroom	W2	Brick	White	Chipping	5	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Girl's Restroom	W3	Brick	White	Chipping	5	2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Girl's Restroom	W4	Brick	White	Chipping	5	3.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Girl's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway outside Girl's Restroom	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #4	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	W1	Plaster	Blue	Chipping	5	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	W2	Plaster	Blue	Chipping	5	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	W3	Plaster	Blue	Chipping	5	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	W4	Plaster	Blue	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell #3	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs to Boiler Room	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs to Boiler Room	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs to Boiler Room	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs to Boiler Room	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs to Boiler Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Inspection Dates: 7/19-7/31/2019
Name of Inspector: Melissa Billingsley
Inspection Company: Criterion Labs., Inc

20