

Element Floor Space #					School District of Philadelphia													On-going Moisture Intrusion  Plastering Needed (yes or no)  Asbestos Abatement Needed (yes or no)  Comments/ Description/ Notes							
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21											
			Inspection Company: Synertech, Inc.		Cook-Wissahickon ES School									ULCS# 6410											
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved								
1	1	100	Health Suite - Nurse's Office	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	100	Health Suite - Nurse's Office	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	100	Health Suite - Nurse's Office	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	100	Health Suite - Nurse's Office	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	100	Health Suite - Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	N/A	No	no	no	Ceiling Tiles				
1	1	100	Health Suite - Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no	9" x 9" Floor Tiles				
1	1	100A	Counselor's Office next to Health Suite	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	100A	Counselor's Office next to Health Suite	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	100A	Counselor's Office next to Health Suite	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	100A	Counselor's Office next to Health Suite	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	100A	Counselor's Office next to Health Suite	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	100A	Counselor's Office next to Health Suite	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	101	Classroom 101	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	101	Classroom 101	yes	Door Frame	Metal	Grey	Chipping	4	N/A	N/A		0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	101	Classroom 101	yes	W2	CMU	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	101	Classroom 101	yes	W3	Concrete	White	Chipping	6	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	101	Classroom 101	yes	W3	CMU	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	101	Classroom 101	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A		0.35	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	101	Classroom 101	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	101	Classroom 101	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	101	Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	101A	Classroom 101 Closet	yes	W1	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	101A	Classroom 101 Closet	yes	W2	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	101A	Classroom 101 Closet	yes	Coat Rack	Wood	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	101A	Classroom 101 Closet	yes	W3	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	101A	Classroom 101 Closet	yes	W4	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	101A	Classroom 101 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	101A	Classroom 101 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102	Classroom 102	yes	W1	CMU	White	Cracking	4	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	102	Classroom 102	yes	Door Frame	Metal	Grey	Chipping	3	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	102	Classroom 102	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102	Classroom 102	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102	Classroom 102	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A		0.29	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	102	Classroom 102	yes	W4	Concrete	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	102	Classroom 102	yes	Pipe	Metal	White	Chipping	4	N/A	N/A		0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	102	Classroom 102	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102	Classroom 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102A	Classroom 102 Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102A	Classroom 102 Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102A	Classroom 102 Closet	yes	Coat Rack	Wood	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	102A	Classroom 102 Closet	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102A	Classroom 102 Closet	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102A	Classroom 102 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	102A	Classroom 102 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	103/103B	Classroom 103	yes	W1	CMU	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	103/103B	Classroom 103	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A		0.08	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	103/103B	Classroom 103	yes	W2	CMU	White	Chipping	4	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	103/103B	Classroom 103	yes	W3	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	103/103B	Classroom 103	yes	W3	Concrete	White	Chipping	2	N/A	N/A		0.04	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	103/103B	Classroom 103	yes	W4	CMU	White	Chipping	4	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	103/103B	Classroom 103	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles				
1	1	103/103B	Classroom 103	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles				
1	1	103A	Classroom 103 Storage	yes	W1	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	103A	Classroom 103 Storage	yes	W2	CMU	White	None	0	N/A	N/A		0.04	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	103A	Classroom 103 Storage	yes	W3	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	103A	Classroom 103 Storage	yes	W4	CMU	White	None	0	N/A	N/A		0.1	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	103A	Classroom 103 Storage	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	103A	Classroom 103 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	104	IMC Library	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	104	IMC Library	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	104	IMC Library	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	104	IMC Library	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	104	IMC Library	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	104	IMC Library	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	104	IMC Library	yes	Handrail	Metal	Tan	Friction	4	N/A	N/A		0.17	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	104	IMC Library	yes	Newel Post	Metal	Tan	Chipping	2	N/A	N/A		0.25	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	104	IMC Library	yes	Risers	Metal	Tan	Chipping	6	N/A	N/A		0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	S111	IMC Stairwell to 2nd Floor	yes	W1	CMU	Blue	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	S111	IMC Stairwell to 2nd Floor	yes	Door Frame	Metal	Red	Chipping	2	N/A	N/A		0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	1	S111	IMC Stairwell to 2nd Floor	yes	W2	CMU	Blue	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	1	S111	IMC Stairwell to 2nd Floor	yes	Door Frame	Metal	Red	Chipping	2	N/A	N/A		0.06	Negative	None	N/A	Negative	Prior to Repair	No	no	no				

					School District of Philadelphia																
					Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21							
					Cook-Wissahickon ES School									ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	S111	IMC Stairwell to 2nd Floor	yes	W3	CMU	Blue	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	S111	IMC Stairwell to 2nd Floor	yes	Door Frame	Metal	Red	Chipping	2	N/A	N/A	0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	S111	IMC Stairwell to 2nd Floor	yes	W4	CMU	Blue	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	S111	IMC Stairwell to 2nd Floor	yes	Door Frame	Metal	Red	Chipping	2	N/A	N/A	0.11	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	S111	IMC Stairwell to 2nd Floor	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles
1	1	S111	IMC Stairwell to 2nd Floor	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Carpet
1	1	104A	IMC Library Office	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104A	IMC Library Office	yes	W2	CMU	White	None	0	N/A	N/A	0.02	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104A	IMC Library Office	yes	W3	CMU	White	None	0	N/A	N/A	0.06	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104A	IMC Library Office	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104A	IMC Library Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	104A	IMC Library Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	104B	IMC Library - Teachers Lounge (Former Material Prep Room)	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104B	IMC Library - Teachers Lounge (Former Material Prep Room)	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104B	IMC Library - Teachers Lounge (Former Material Prep Room)	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104B	IMC Library - Teachers Lounge (Former Material Prep Room)	yes	W4	CMU	White	None	0	N/A	N/A	0.04	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104B	IMC Library - Teachers Lounge (Former Material Prep Room)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	104B	IMC Library - Teachers Lounge (Former Material Prep Room)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	104C	IMC Library Locker Room	yes	W1	CMU	White	None	0	N/A	N/A	0.1	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104C	IMC Library Locker Room	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104C	IMC Library Locker Room	yes	W3	CMU	White	None	0	N/A	N/A	0.05	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104C	IMC Library Locker Room	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104C	IMC Library Locker Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	104C	IMC Library Locker Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	104D	IMC Library Storeroom near Front Desk	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104D	IMC Library Storeroom near Front Desk	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104D	IMC Library Storeroom near Front Desk	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104D	IMC Library Storeroom near Front Desk	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	104D	IMC Library Storeroom near Front Desk	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	104D	IMC Library Storeroom near Front Desk	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	105	Classroom 105	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	105	Classroom 105	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.11	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	105	Classroom 105	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	105	Classroom 105	yes	W3	Concrete	Grey	Chipping	4	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	105	Classroom 105	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A	0.27	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	105	Classroom 105	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	105	Classroom 105	yes	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	105	Classroom 105	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	1	105A	Classroom 105 Closet	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	1	105A	Classroom 105 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	1	105A	Classroom 105 Closet	yes	Coat Rack	Wood	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	105A	Classroom 105 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	1	105A	Classroom 105 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	1	105A	Classroom 105 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	105A	Classroom 105 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	106	Classroom 106	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	106	Classroom 106	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.13	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	106	Classroom 106	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	106	Classroom 106	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	106	Classroom 106	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A	0.25	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	106	Classroom 106	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	1	106	Classroom 106	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	1	106	Classroom 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles
1	1	106	Classroom 106	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles
1	1	106A	Classroom 106 Closet	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	106A	Classroom 106 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	106A	Classroom 106 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	106A	Classroom 106 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	1	106A	Classroom 106 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles
1	1	106A	Classroom 106 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles
1	1	107	Classroom 107	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	

Element Floor Space #				School District of Philadelphia										On-going Moisture Intrusion  Plastering Needed (yes or no)  Asbestos Abatement Needed (yes or no)  Comments/ Description/ Notes											
				Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report							Inspection Dates: 04/20-5/03/21												
				Inspection Company: Synertech, Inc.		Cook-Wissahickon ES School																			
Element	Floor	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)					Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	107	Classroom 107	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	107	Classroom 107	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	107	Classroom 107	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	107	Classroom 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	107	Classroom 107	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108	Classroom 108 - Computer Room	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108	Classroom 108 - Computer Room	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	108	Classroom 108 - Computer Room	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108	Classroom 108 - Computer Room	yes	W3	Concrete	White	Chipping	2	N/A	N/A	0.11	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	108	Classroom 108 - Computer Room	yes	W4	Sheetrock	White	Chipping	12	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	108	Classroom 108 - Computer Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108	Classroom 108 - Computer Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108A	Classroom 108 Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108A	Classroom 108 Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108A	Classroom 108 Closet	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108A	Classroom 108 Closet	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108A	Classroom 108 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	108A	Classroom 108 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109	Classroom 109	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109	Classroom 109	yes	Door Frame	Metal	Grey	Chipping	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109	Classroom 109	yes	Pipe	Metal	White	Chipping	2	N/A	N/A	0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	109	Classroom 109	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109	Classroom 109	yes	Coat Rack	Wood	White	Chipping	6	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	109	Classroom 109	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109	Classroom 109	yes	W4	Sheetrock	White	Chipping	12	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	109	Classroom 109	yes	Ceiling	Concrete	White	Chipping	12	N/A	N/A	N/A	N/A	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	109	Classroom 109	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109A	Classroom 109 Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109A	Classroom 109 Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109A	Classroom 109 Closet	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109A	Classroom 109 Closet	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109A	Classroom 109 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	109A	Classroom 109 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	110	Classroom 110	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0.19	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	110	Classroom 110	yes	W2	Sheetrock	White	Chipping	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	110	Classroom 110	yes	W2	Sheetrock	Green	Chipping	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	110	Classroom 110	yes	W3	Concrete	White	Chipping	2	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	110	Classroom 110	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	1	110A	Classroom 110 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0.08	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	111	Classroom 111	yes	W2	Sheetrock	White	Chipping	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	111	Classroom 111	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A	0.3	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	111	Classroom 111	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No								

					School District of Philadelphia																	
					Lead Safe Certification Assessment Report										Inspection Dates: 04/20-5/03/21							
					Cook-Wissahickon ES School										ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	113	Main Office	yes	W1	CMU	Tan	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113	Main Office	yes	Door Frame	Metal	Tan	Chipping	4	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113	Main Office	yes	W2	CMU	Tan	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	113	Main Office	yes	W3	Concrete	Tan	Chipping	2	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113	Main Office	yes	Door Frame	Metal	Tan	Chipping	2	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113	Main Office	yes	Window Frame	Metal	Tan	Chipping	2	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113	Main Office	yes	W4	Concrete	Tan	Chipping	4	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	113	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles	
1	1	113	Main Office	yes	Front Desk	Wood	White	Chipping	5	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	W1	CMU	Tan	Chipping	2	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	W2	CMU	Tan	Chipping	5	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	W3	CMU	Tan	Chipping	6	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	W4	CMU	Tan	Chipping	4	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113B	Main Office Mailroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	113B	Main Office Mailroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles	
1	1	113A	Mailroom Restroom	yes	W1	CMU	Tan	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113A	Mailroom Restroom	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0.1 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113A	Mailroom Restroom	yes	W2	CMU	Tan	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113A	Mailroom Restroom	yes	W3	CMU	Tan	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113A	Mailroom Restroom	yes	W4	CMU	Tan	Flaking	2	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	113A	Mailroom Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	113A	Mailroom Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles	
1	1	113C	Principal's Office Restroom	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113C	Principal's Office Restroom	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113C	Principal's Office Restroom	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113C	Principal's Office Restroom	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113C	Principal's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	113C	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles	
1	1	113D	Principal's Office	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113D	Principal's Office	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113D	Principal's Office	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113D	Principal's Office	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113D	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	113D	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	113E	Principal's Office Server Closet	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113E	Principal's Office Server Closet	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113E	Principal's Office Server Closet	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113E	Principal's Office Server Closet	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113E	Principal's Office Server Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113E	Principal's Office Server Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles	
1	1	113D1	Principal's Office Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113D1	Principal's Office Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113D1	Principal's Office Closet	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113D1	Principal's Office Closet	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	113D1	Principal's Office Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	113D1	Principal's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles	
1	1	114	Office next to Storeroom	yes	W1	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	114	Office next to Storeroom	yes	W2	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	114	Office next to Storeroom	yes	W3	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	114	Office next to Storeroom	yes	W4	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	114	Office next to Storeroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	114	Office next to Storeroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	115	Storeroom next to After School Office	yes	W1	CMU	White	None	None	N/A	N/A	N/A	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	115	Storeroom next to After School Office	yes	W2	CMU	White	None	None	N/A	N/A	N/A	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	115	Storeroom next to After School Office	yes	W3	CMU	White	None	None	N/A	N/A	N/A	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	115	Storeroom next to After School Office	yes	W4	CMU	White	None	None	N/A	N/A	N/A	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	115	Storeroom next to After School Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	115	Storeroom next to After School Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	116	After School Program Office	yes	W1	CMU	White	None	None	N/A	N/A	N/A	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	116	After School Program Office	yes	W2	CMU	White	None	None	N/A	N/A	N/A	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	116	After School Program Office	yes	W3	CMU	White	None	None	N/A	N/A	N/A	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	116	After School Program Office	yes	W4	CMU	White	None	None	N/A	N/A	N/A	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	116	After School Program Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	116	After School Program Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	117	Home & School Program Office	yes	W1	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	117	Home & School Program Office	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	117	Home & School Program Office	yes	W2	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		

					School District of Philadelphia																	
					Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21								
					Cook-Wissahickon ES School									ULCS# 6410								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	117	Home & School Program Office	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	117	Home & School Program Office	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	117	Home & School Program Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	117	Home & School Program Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	118	Health Suite - Storeroom next to Restroom	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	118	Health Suite - Storeroom next to Restroom	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	118	Health Suite - Storeroom next to Restroom	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	118	Health Suite - Storeroom next to Restroom	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	118	Health Suite - Storeroom next to Restroom	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	118	Health Suite - Storeroom next to Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	118	Health Suite - Storeroom next to Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	119	Health Suite - Treatment Room next to suite door	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	119	Health Suite - Treatment Room next to suite door	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	119	Health Suite - Treatment Room next to suite door	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	119	Health Suite - Treatment Room next to suite door	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	119	Health Suite - Treatment Room next to suite door	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	119	Health Suite - Treatment Room next to suite door	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	119	Health Suite - Treatment Room next to suite door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	119A	Nurse's Office Restroom	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	119A	Nurse's Office Restroom	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0.09	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	119A	Nurse's Office Restroom	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	119A	Nurse's Office Restroom	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	119A	Nurse's Office Restroom	yes	W4	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	119A	Nurse's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	119A	Nurse's Office Restroom	yes	Floor	Concrete	Grey	Chipping	2	N/A	N/A	0.08	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	120	Health Suite - Storeroom with Sink	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	120	Health Suite - Storeroom with Sink	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	120	Health Suite - Storeroom with Sink	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	120	Health Suite - Storeroom with Sink	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	120	Health Suite - Storeroom with Sink	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	120	Health Suite - Storeroom with Sink	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	120	Health Suite - Storeroom with Sink	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	122	Health Suite - Counselor's Office	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	122	Health Suite - Counselor's Office	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	122	Health Suite - Counselor's Office	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	122	Health Suite - Counselor's Office	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	122	Health Suite - Counselor's Office	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	122	Health Suite - Counselor's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	122	Health Suite - Counselor's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	124	Storeroom next to Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	124	Storeroom next to Boy's Restroom	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0.05	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	124	Storeroom next to Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	124	Storeroom next to Boy's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	124	Storeroom next to Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no		
1	1	124	Storeroom next to Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles	
1	1	124	Storeroom next to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	9" x 9" Floor Tiles	
1	1	125	Boy's Restroom by Stairwell #2	yes	W1	CMU	Green	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	125	Boy's Restroom by Stairwell #2	yes	Pipe	Metal	Blue	Chipping	2	N/A	N/A	0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	125	Boy's Restroom by Stairwell #2	yes	W2	CMU	Green	Flaking	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	125	Boy's Restroom by Stairwell #2	yes	W3	CMU	Green	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	125	Boy's Restroom by Stairwell #2	yes	Stall Dividers	Metal	Blue	Chipping	2	N/A	N/A	0.15	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	125	Boy's Restroom by Stairwell #2	yes	W4	CMU	Green	Flaking	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	125	Boy's Restroom by Stairwell #2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	125	Boy's Restroom by Stairwell #2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	126	Girl's Restroom by Stairwell #2	yes	W1	CMU	Green	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	126	Girl's Restroom by Stairwell #2	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	126	Girl's Restroom by Stairwell #2	yes	W2	CMU	Green	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	126	Girl's Restroom by Stairwell #2	yes	W3	Concrete	Green	Flaking	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	126	Girl's Restroom by Stairwell #2	yes	W4	CMU	Green	Chipping	6	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	126	Girl's Restroom by Stairwell #2	yes	Radiator	Metal	Blue	Chipping	2	N/A	N/A	0.15	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	126	Girl's Restroom by Stairwell #2	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	126	Girl's Restroom by Stairwell #2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no		
1	1	127	Custodial Closet next to Girl's Restroom	no	W1	CMU	White	Flaking	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	127	Custodial Closet next to Girl's Restroom	no	W2	CMU	White	Flaking	3	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	127	Custodial Closet next to Girl's Restroom	no	W3	CMU	White	Flaking	6	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no		
1	1	127	Custodial Closet next to Girl's Restroom	no	Pipe	Metal	White	Flaking	2	N/A	N/A	0.23	Negative	None	N/A	Negative	Prior to Repair	No	no	no		

					School District of Philadelphia																		
					Lead Safe Certification Assessment Report												Inspection Dates: 04/20-5/03/21						
					Cook-Wissahickon ES School												ULCS# 6410						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	127	Custodial Closet next to Girl's Restroom	no	Sink	Porcelain	Grey	Flaking	2	N/A	N/A	0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	127	Custodial Closet next to Girl's Restroom	no	W4	CMU	White	Flaking	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	127	Custodial Closet next to Girl's Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	127	Custodial Closet next to Girl's Restroom	no	Floor	Concrete	Grey	Chipping	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H11	Hallway at Stairwell #3	yes	W1	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Positive	No	No	no	no			
1	1	H11	Hallway at Stairwell #3	yes	W2	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrlvrQMukMZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrlvrQMukMZGjLQ9JX/view?usp=sharing</a>		
1	1	H11	Hallway at Stairwell #3	yes	W3	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Positive	No	No	no	no			
1	1	H11	Hallway at Stairwell #3	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A	0.16	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H11	Hallway at Stairwell #3	yes	Door	Metal	Blue	Chipping	2	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H11	Hallway at Stairwell #3	yes	W4	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrlvrQMukMZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrlvrQMukMZGjLQ9JX/view?usp=sharing</a>		
1	1	H11	Hallway at Stairwell #3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H11	Hallway at Stairwell #3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H11	Hallway at Stairwell #3	yes	Baseboard	Terracotta	Red	Chipping	6	N/A	N/A	0.06	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	W1	CMU	Grey	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	W1	Concrete	Grey	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	W2	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	W3	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	W3	Concrete	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	Door	Metal	Blue	Chipping	2	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A	0.15	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	W4	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H12	Hallway at Classrooms 105 & 106	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H13	Hallway at Classrooms 102 & 103	yes	W1	CMU	Grey	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Positive	No	No	no	no			
1	1	H13	Hallway at Classrooms 102 & 103	yes	W2	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrlvrQMukMZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrlvrQMukMZGjLQ9JX/view?usp=sharing</a>		
1	1	H13	Hallway at Classrooms 102 & 103	yes	W3	CMU	Grey	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Positive	No	No	no	no			
1	1	H13	Hallway at Classrooms 102 & 103	yes	W4	CMU	Grey	Chipping	44	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrlvrQMukMZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrlvrQMukMZGjLQ9JX/view?usp=sharing</a>		
1	1	H13	Hallway at Classrooms 102 & 103	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H13	Hallway at Classrooms 102 & 103	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H13	Hallway at Classrooms 102 & 103	yes	Door Frames	Metal	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H14	Hallway at IMC	yes	W1	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H14	Hallway at IMC	yes	Elevator Door Frame	Metal	Red	Chipping	1	N/A	N/A	0.28	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H14	Hallway at IMC	yes	Elevator Door	Metal	Red	Chipping	1	N/A	N/A	0.23	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H14	Hallway at IMC	yes	W2	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H14	Hallway at IMC	yes	W3	Concrete	Grey	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H14	Hallway at IMC	yes	W3	Concrete	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H14	Hallway at IMC	yes	W4	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H14	Hallway at IMC	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H14	Hallway at IMC	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	W1	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	W1	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	W2	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	W3	CMU	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	W3	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no			
1	1	H15	Hallway at Stairwell #4	yes	W4	CMU	White	Chipping	4	N/A	N/A	0	Negative										

					School District of Philadelphia												Inspection Dates: 04/20-5/03/21									
					Lead Safe Certification Assessment Report												Cook-Wissahickon ES School									
					Cook-Wissahickon ES School												ULCS# 6410									
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm^2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes					
1	1	H110	Hallway at Main Entrance	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	H110	Hallway at Main Entrance	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	H110	Hallway at Main Entrance	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	H110	Hallway at Main Entrance	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	H110	Hallway at Main Entrance	yes	W4	Wood	White	Chipping	2	N/A	N/A		0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	H110	Hallway at Main Entrance	yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	H110	Hallway at Main Entrance	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	H110	Hallway at Main Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S11	Stairwell #3	yes	W1	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S11	Stairwell #3	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A		0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S11	Stairwell #3	yes	Door	Metal	Blue	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S11	Stairwell #3	yes	W2	CMU	Blue	Chipping	6	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S11	Stairwell #3	yes	W3	Concrete	Blue	Flaking	5	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S11	Stairwell #3	yes	W4	Concrete	Blue	Flaking	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S11	Stairwell #3	yes	Ceiling	Concrete	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S11	Stairwell #3	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S11	Stairwell #3	yes	Risers	Concrete	Blue	Chipping	12	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S16	Stairwell #4	yes	W1	CMU	Blue	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S16	Stairwell #4	yes	W2	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S16	Stairwell #4	yes	W3	CMU	Blue	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S16	Stairwell #4	yes	W4	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S16	Stairwell #4	yes	Ceiling	Concrete	White	Chipping	2	N/A	N/A		0.15	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S16	Stairwell #4	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S16	Stairwell #4	yes	Risers	Concrete	Blue	Chipping	20	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S17	Stairwell #1	yes	W1	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S17	Stairwell #1	yes	W2	CMU	Blue	Chipping	10	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S17	Stairwell #1	yes	W3	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S17	Stairwell #1	yes	W4	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S17	Stairwell #1	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A		0	N/A	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S17	Stairwell #1	yes	Door	Metal	Blue	Chipping	2	N/A	N/A		0	N/A	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S17	Stairwell #1	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S17	Stairwell #1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S17	Stairwell #1	yes	Risers	Concrete	Black	Chipping	10	N/A	N/A		0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S18	Stairwell #2	yes	W1	CMU	Blue	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S18	Stairwell #2	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S18	Stairwell #2	yes	Door	Metal	Blue	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S18	Stairwell #2	yes	W2	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S18	Stairwell #2	yes	W3	Concrete	Blue	Flaking	4	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S18	Stairwell #2	yes	W4	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S18	Stairwell #2	yes	Ceiling	Concrete	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	S18	Stairwell #2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	S18	Stairwell #2	yes	Risers	Concrete	Blue	Chipping	12	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	1	EX1	Loading Dock	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	EX1	Loading Dock	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	EX1	Loading Dock	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	EX1	Loading Dock	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	EX1	Loading Dock	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	1	EX1	Loading Dock	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	2	200	Classroom 200	yes	W1	CMU	White	Chipping	6	N/A	N/A	N/A	N/A	None	N/A	Negative	Prior to Repair	No	no	no						
1	2	200	Classroom 200	yes	W2	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	2	200	Classroom 200	yes	W3	CMU	White	Chipping	4	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	2	200	Classroom 200	yes	W4	CMU	White</																			

					School District of Philadelphia																
					Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21							
					Cook-Wissahickon ES School									ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	215	Storeroom next to Classroom 200A	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	215	Storeroom next to Classroom 200A	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	215	Storeroom next to Classroom 200A	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	215	Storeroom next to Classroom 200A	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	215	Storeroom next to Classroom 200A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	201	Classroom 201	yes	W1	CMU	White	Chipping	40	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	201	Classroom 201	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	201	Classroom 201	yes	W2	CMU	White	None	0	N/A	N/A	0.06	Negative	None	N/A	Negative	No	No	no	no	
1	2	201	Classroom 201	yes	W3	Concrete	White	Chipping	5	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	201	Classroom 201	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A	0.26	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	201	Classroom 201	yes	W4	Sheetrock	White	Chipping	36	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	201	Classroom 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A	0.09	Negative	None	N/A	Negative	No	No	no	no	
1	2	201	Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	201A	Classroom 201 Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	201A	Classroom 201 Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	201A	Classroom 201 Closet	yes	W3	CMU	White	Chipping	6	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	201A	Classroom 201 Closet	yes	W4	CMU	White	Chipping	6	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	201A	Classroom 201 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	201A	Classroom 201 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	202	Classroom 202	yes	W1	CMU	White	Chipping	6	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	W1	Concrete	Grey	Chipping	2	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	W2	Sheetrock	White	Chipping	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A	0.18	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	W4	Sheetrock	White	Chipping	3	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	202	Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	202A	Classroom 202 Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	202A	Classroom 202 Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	202A	Classroom 202 Closet	yes	Coat Rack	Wood	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	202A	Classroom 202 Closet	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	202A	Classroom 202 Closet	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	202A	Classroom 202 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	202A	Classroom 202 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203	Classroom 203	yes	W1	CMU	White	Chipping	15	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	203	Classroom 203	yes	W1	CMU	Yellow	Chipping	20	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	203	Classroom 203	yes	W2	Sheetrock	White	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	203	Classroom 203	yes	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	203	Classroom 203	yes	W3	Concrete	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	203	Classroom 203	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203	Classroom 203	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203	Classroom 203	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203A	Classroom 203 Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203A	Classroom 203 Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203A	Classroom 203 Closet	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203A	Classroom 203 Closet	yes	Duct	Metal	White	Flaking	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	203A	Classroom 203 Closet	yes	Duct	Metal	Brown	Flaking	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	203A	Classroom 203 Closet	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203A	Classroom 203 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203A	Classroom 203 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	203A	Classroom 203 Closet	yes	Bookcase	Metal	Tan	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	Newel Post	Metal	Tan	Chipping	3	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	Stringer	Metal	Tan	Chipping	10	N/A	N/A	0.16	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	Risers	Metal	Tan	Chipping	10	N/A	N/A	0.22	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	S29	Stairs across from Classroom 203	yes	Handrail	Metal	Tan	Chipping	8	N/A	N/A	0.23	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204	Classroom 204	yes	W1	CMU	Blue	Chipping	20	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204	Classroom 204	yes	W2	Sheetrock	Blue	Chipping	30	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204	Classroom 204	yes	W3	CMU	Blue	Chipping	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204	Classroom 204	yes	Univent	Metal	Grey	Chipping	10	N/A	N/A	0.4	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204	Classroom 204	yes	W4	CMU	Blue	Chipping	32	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204	Classroom 204	yes	Ceiling	Concrete	Blue	Flaking	12	N/A	N/A	0.13	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204	Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	204A	Classroom 204 Closet	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	204A	Classroom 204 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	204A	Classroom 204 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	204A	Classroom 204 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	204A	Classroom 204 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	204A	Classroom 204 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	N/A	No	no	no	
1	2	204B	Custodial Closet by Classroom 204	no	W1	CMU	Blue	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204B	Custodial Closet by Classroom 204	no	W2	CMU	Blue	Chipping	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204B	Custodial Closet by Classroom 204	no	W3	CMU	Blue	Chipping	12	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	



					School District of Philadelphia																
					Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21							
					Cook-Wissahickon ES School									ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	204B	Custodial Closet by Classroom 204	no	W4	CMU	Blue	Chipping	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	204B	Custodial Closet by Classroom 204	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	204B	Custodial Closet by Classroom 204	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	205	Classroom 205	yes	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	205	Classroom 205	yes	Door Frame	Metal	Brown	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	205	Classroom 205	yes	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	205	Classroom 205	yes	W3	CMU	White	Chipping	3	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	205	Classroom 205	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A	0.24	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	205	Classroom 205	yes	W4	Sheetrock	White	Chipping	24	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	205	Classroom 205	yes	Ceiling	Concrete	White	Flaking	50	N/A	N/A	0.11	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	205	Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	205A	Classroom 205 Closet	yes	W1	CMU	White	None	0	N/A	N/A	0.04	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	205A	Classroom 205 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	205A	Classroom 205 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0.06	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	205A	Classroom 205 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0.05	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	205A	Classroom 205 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	205A	Classroom 205 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	206	Classroom 206	yes	W1	CMU	White	Chipping	12	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	206	Classroom 206	yes	W1	Concrete	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	206	Classroom 206	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	206	Classroom 206	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	206	Classroom 206	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A	0.41	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	206	Classroom 206	yes	W4	CMU	White	Chipping	6	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	206	Classroom 206	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	206	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	206A	Classroom 206 Closet	yes	W1	CMU	N/A	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	206A	Classroom 206 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	206A	Classroom 206 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	206A	Classroom 206 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	206A	Classroom 206 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	0.08	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	206A	Classroom 206 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	207	Classroom 207	yes	W1	CMU	White	Chipping	2	N/A	N/A	0	N/A	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	207	Classroom 207	yes	W1	Concrete	Grey	Chipping	1	N/A	N/A	0.04	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	207	Classroom 207	yes	W2	CMU	White	Chipping	2	N/A	N/A	0	N/A	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	207	Classroom 207	yes	W2	Concrete	Grey	Chipping	2	N/A	N/A	0	N/A	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	207	Classroom 207	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	207	Classroom 207	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	207	Classroom 207	yes	Ceiling	Concrete	White	Chipping	1	N/A	N/A	0.08	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	207	Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	208	Classroom 208	yes	W1	Concrete	White	Chipping	3	N/A	N/A	0	N/A	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	208	Classroom 208	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.13	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	208	Classroom 208	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	208	Classroom 208	yes	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	208	Classroom 208	yes	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	208	Classroom 208	yes	Univent	Metal	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	208	Classroom 208	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	208	Classroom 208	yes	Ceiling	Concrete	White	Flaking	6	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	208	Classroom 208	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	208A	Classroom 208 Closet	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	208A	Classroom 208 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	208A	Classroom 208 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	208A	Classroom 208 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	208A	Classroom 208 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	0.09	Negative	None	N/A	Negative	No	No	no	no	
1	2	208A	Classroom 208 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	W1	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	209	Classroom 209	yes	W1	Concrete	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	209	Classroom 209	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.18	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	209	Classroom 209	yes	Pipe	Metal	Blue	Flaking	2	N/A	N/A	0.26	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	209	Classroom 209	yes	W2	Sheetrock	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	209	Classroom 209	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Univent	Metal	Grey	Chipping	6	N/A	N/A	0.3	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	209	Classroom 209	yes	W4	Sheetrock	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	209	Classroom 209	yes	Ceiling	Concrete	White	Flaking	6	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	209	Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	

					School District of Philadelphia																
					Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21							
					Cook-Wissahickon ES School									ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm^2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	209A	Classroom 209 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	209A	Classroom 209 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	210	Classroom 210	yes	W1	CMU	Blue	Chipping	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	W1	Concrete	Blue	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	210	Classroom 210	yes	W3	CMU	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	W3	Concrete	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	Univent	Metal	Grey	Chipping	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	W4	CMU	Blue	Chipping	46	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	Coat Rack	Wood	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	Ceiling	Concrete	White	Flaking	30	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	210	Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	2	210A	Classroom 210 Closet	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	210A	Classroom 210 Closet	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	210A	Classroom 210 Closet	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	210A	Classroom 210 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	210A	Classroom 210 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	210A	Classroom 210 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	211	Classroom 211	yes	W1	CMU	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	Mirror Frame	Wood	Blue	Chipping	1	N/A	N/A	0.08	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	Door Frame	Metal	Grey	Chipping	4	N/A	N/A	0.06	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	W2	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	211	Classroom 211	yes	W3	CMU	Blue	Flaking	12	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	Univent	Metal	Grey	Chipping	24	N/A	N/A	0.32	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	W4	CMU	Blue	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	211	Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	211	Classroom 211	yes	Desk	Metal	Blue	Chipping	5	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	211A	Classroom 211 Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	211A	Classroom 211 Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	211A	Classroom 211 Closet	yes	W3	CMU	Blue	Flaking	12	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	211A	Classroom 211 Closet	yes	W4	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	211A	Classroom 211 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	211A	Classroom 211 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212	Classroom 212	yes	W1	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	212	Classroom 212	yes	Pipe	Metal	White	Chipping	1	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	212	Classroom 212	yes	W2	CMU	White	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	212	Classroom 212	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212	Classroom 212	yes	W4	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	212	Classroom 212	yes	Ceiling	Concrete	White	Flaking	20	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	212	Classroom 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212A	Classroom 212 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212A	Classroom 212 Restroom	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212A	Classroom 212 Restroom	yes	Radiator	Metal	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	212A	Classroom 212 Restroom	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212A	Classroom 212 Restroom	yes	W4	CMU	White	Flaking	16	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	212A	Classroom 212 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212A	Classroom 212 Restroom	yes	Floor	Concrete	Grey	Flaking	8	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	212B	Classroom 212 Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212B	Classroom 212 Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212B	Classroom 212 Closet	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212B	Classroom 212 Closet	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212B	Classroom 212 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	212B	Classroom 212 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	214	Men's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	214	Men's Restroom	yes	Ladder	Metal	Brown	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	214	Men's Restroom	yes	Pipe	Metal	White	Flaking	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	214	Men's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	214	Men's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	214	Men's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	214	Men's Restroom	yes	Ceiling	Concrete	White	Flaking	4	N/A	N/A	0.08	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	214	Men's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	2	216	Book Storeroom next to Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	216	Book Storeroom next to Boy's Restroom	yes	Ladder	Metal	Black	Chipping	3	N/A	N/A	0.2	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	216	Book Storeroom next to Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	216	Book Storeroom next to Boy's Restroom	yes	Pipe	Metal	White	Flaking	2	N/A	N/A	0.17	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	216	Book Storeroom next to Boy's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	216	Book Storeroom next to Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	216	Book Storeroom next to Boy's Restroom	yes	Ceiling	Concrete	White	Flaking	12	N/A	N/A	0.06	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	216	Book Storeroom next to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	219	Storeroom next to Classroom 207	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	

					School District of Philadelphia													Inspection Dates: 04/20-5/03/21			
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report																
			Inspection Company: Synertech, Inc.		Cook-Wissahickon ES School									ULCS# 6410							
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm^2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	219	Storeroom next to Classroom 207	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	219	Storeroom next to Classroom 207	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	219	Storeroom next to Classroom 207	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	219	Storeroom next to Classroom 207	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	219	Storeroom next to Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	220	Men's Restroom next to Classroom 212	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	220	Men's Restroom next to Classroom 212	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	220	Men's Restroom next to Classroom 212	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	220	Men's Restroom next to Classroom 212	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	220	Men's Restroom next to Classroom 212	yes	Stall Dividers	Metal	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	220	Men's Restroom next to Classroom 212	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	220	Men's Restroom next to Classroom 212	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	220	Men's Restroom next to Classroom 212	yes	Floor	Concrete	Grey	Chipping	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	Door Frame	Metal	Blue	Chipping	0	N/A	N/A	0.21	Negative	None	N/A	Negative	No	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	Stall Dividers	Metal	Green	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	Stall Dividers	Metal	White	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	221	Women's Restroom near Elevator	yes	Floor	Concrete	Grey	Chipping	12	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	223	Speech Room 213 next to Elevator	yes	W1	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	223	Speech Room 213 next to Elevator	yes	W2	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	223	Speech Room 213 next to Elevator	yes	W3	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	223	Speech Room 213 next to Elevator	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	2	223	Speech Room 213 next to Elevator	yes	Ceiling	Concrete	White	Flaking	32	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	223	Speech Room 213 next to Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	223A	Storeroom next to Women's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	223A	Storeroom next to Women's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	223A	Storeroom next to Women's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	223A	Storeroom next to Women's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	223A	Storeroom next to Women's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	223A	Storeroom next to Women's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	224	Fan Room across from Classroom 202	no	W1	CMU	N/A	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	No paint
1	2	224	Fan Room across from Classroom 202	no	W2	CMU	N/A	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	No paint
1	2	224	Fan Room across from Classroom 202	no	W3	CMU	N/A	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	No paint
1	2	224	Fan Room across from Classroom 202	no	W4	CMU	N/A	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	No paint
1	2	224	Fan Room across from Classroom 202	no	Ceiling	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	No paint
1	2	224	Fan Room across from Classroom 202	no	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	No paint
1	2	225	Classroom 213	yes	W1	Concrete	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	225	Classroom 213	yes	Pipe	Metal	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	225	Classroom 213	yes	W2	CMU	White	Flaking	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	225	Classroom 213	yes	W3	CMU	White	Flaking	15	N/A	N/A	0.04	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	225	Classroom 213	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	225	Classroom 213	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles
1	2	225	Classroom 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles
1	2	H21	Hallway outside Classroom 207	yes	W1	CMU	White	None	0	N/A	N/A	0.04	Negative	None	N/A	Negative	No	No	no	no	
1	2	H21	Hallway outside Classroom 207	yes	W2	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H21	Hallway outside Classroom 207	yes	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H21	Hallway outside Classroom 207	yes	Door Frame	Metal	Blue	Chipping													

					School District of Philadelphia																
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21							
			Inspection Company: Synertech, Inc.		Cook-Wissahickon ES School									ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm^2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	H23	Hallway at Classrooms 202 & 203	yes	Door Frames	Metal	Blue	Chipping	6	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H23	Hallway at Classrooms 202 & 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	2	H23	Hallway at Classrooms 202 & 203	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	0	Negative	None	N/A	Negative	No	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	W1	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Positive	No	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Elevator Door Frame	Metal	Red	Chipping	2	N/A	N/A	0.32	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Elevator Door	Metal	Red	Chipping	1	N/A	N/A	0.4	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	W2	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	W2	CMU	White	Chipping	8	N/A	N/A	0	N/A	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Radiator	Metal	Grey	Chipping	2	N/A	N/A	0.02	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Door Frames	Metal	Red	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Door Frames	Metal	Blue	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H25	Hallway between Classrooms 211 & 212	yes	W1	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Positive	No	No	no	no	
1	2	H25	Hallway between Classrooms 211 & 212	yes	W2	Concrete	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H25	Hallway between Classrooms 211 & 212	yes	W2	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H25	Hallway between Classrooms 211 & 212	yes	Door Frames	Metal	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H25	Hallway between Classrooms 211 & 212	yes	Doors	Metal	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H25	Hallway between Classrooms 211 & 212	yes	Baseboard	Terracotta	Red	Flaking	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	Glazed terracotta is 1.2 ug/cm^2, red paint is 0.0 ug/cm^2
1	2	H25	Hallway between Classrooms 211 & 212	yes	W3	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H25	Hallway between Classrooms 211 & 212	yes	W3	Concrete	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H25	Hallway between Classrooms 211 & 212	yes	W4	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H25	Hallway between Classrooms 211 & 212	yes	Door Frames	Metal	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H25	Hallway between Classrooms 211 & 212	yes	Baseboard	Terracotta	Red	Flaking	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	Glazed terracotta is 1.2 ug/cm^2, red paint is 0.0 ug/cm^2
1	2	H25	Hallway between Classrooms 211 & 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H25	Hallway between Classrooms 211 & 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H26	Hallway outside Classroom 201	yes	W1	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Positive	No	No	no	no	
1	2	H26	Hallway outside Classroom 201	yes	W2	CMU	Grey	Chipping	6	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H26	Hallway outside Classroom 201	yes	Door Frames	Metal	Blue	Chipping	2	N/A	N/A	0.15	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H26	Hallway outside Classroom 201	yes	W3	CMU	Grey	Chipping	32	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H26	Hallway outside Classroom 201	yes	W3	CMU	White	Chipping	32	N/A	N/A	0.08	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H26	Hallway outside Classroom 201	yes	W4	CMU	Grey	Chipping	16	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H26	Hallway outside Classroom 201	yes	Door Frames	Metal	Blue	Chipping	2	N/A	N/A	0.11	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H26	Hallway outside Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H26	Hallway outside Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H26	Hallway outside Classroom 201	yes	Baseboard	Terracotta	Red	Flaking	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Elevator Door	Metal	Blue	Chipping	2	N/A	N/A	0.25	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Elevator Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0.19	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	W3	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Positive	No	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	W4	CMU	Grey	Chipping	12	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	yes	<a href="https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing">https://drive.google.com/file/d/1WHIXPegY-HppZFrOlvrQMUKmZGjLQ9JX/view?usp=sharing</a>
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H24	Hallway from Men's Restroom to Classroom 200	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	W2	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	W2	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	W2	Concrete	Grey	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	W4	CMU	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	Radiator	Metal	Red	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	2	H29	Hallway at Classrooms 209 & 210	yes	Baseboard	Terracotta	Red	Chipping	20	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	2	H27	Hallway outside Classroom 204	yes	W1																

					School District of Philadelphia												Inspection Dates: 04/20-5/03/21									
					Lead Safe Certification Assessment Report												ULCS# 6410									
					Cook-Wissahickon ES School																					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm^2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes					
1	B	1	Classroom K-1	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	1	Classroom K-1	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	1	Classroom K-1	yes	Sink Cabinet	Wood	White	Flaking	4	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	1	Classroom K-1	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	1	Classroom K-1	yes	W3	CMU	White	Chipping	4	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	1	Classroom K-1	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A		0.4	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	1	Classroom K-1	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	1	Classroom K-1	yes	W4	CMU	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	1	Classroom K-1	yes	W4	Sheetrock	White	Chipping	24	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	1	Classroom K-1	yes	Ceiling	Concrete	White	Chipping	500	N/A	N/A		0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	1	Classroom K-1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001B	Classroom K-1 Coat Area	yes	W1	CMU	White	None	0	N/A	N/A		0	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	001B	Classroom K-1 Coat Area	yes	W2	CMU	White	None	0	N/A	N/A		0	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	001B	Classroom K-1 Coat Area	yes	W3	CMU	White	None	0	N/A	N/A		0	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	001B	Classroom K-1 Coat Area	yes	W4	CMU	White	None	0	N/A	N/A		0	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	001B	Classroom K-1 Coat Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001B	Classroom K-1 Coat Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001A	Classroom -1 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001A	Classroom -1 Restroom	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001A	Classroom -1 Restroom	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001A	Classroom -1 Restroom	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001A	Classroom -1 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001A	Classroom -1 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001C	Classroom K-1 Closet	yes	W1	CMU	White	None	0	N/A	N/A		0	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	001C	Classroom K-1 Closet	yes	W2	CMU	White	None	0	N/A	N/A		0	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	001C	Classroom K-1 Closet	yes	W3	CMU	White	None	0	N/A	N/A		0	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	001C	Classroom K-1 Closet	yes	W4	CMU	White	None	0	N/A	N/A		0	N/A	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	001C	Classroom K-1 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	001C	Classroom K-1 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	2	Classroom K-2	yes	W1	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	2	Classroom K-2	yes	Door Frame	Metal	Grey	Chipping	1	N/A	N/A		0.13	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	2	Classroom K-2	yes	W2	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	2	Classroom K-2	yes	W3	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	2	Classroom K-2	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A		0.36	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	2	Classroom K-2	yes	W4	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no					
1	B	2	Classroom K-2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles					
1	B	2	Classroom K-2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	002A	Classroom K-2 Restroom	yes	W1	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	002A	Classroom K-2 Restroom	yes	W2	CMU	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	002A	Classroom K-2 Restroom	yes	W3	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	002A	Classroom K-2 Restroom	yes	W4	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	12" x 12" Floor Tiles				
1	B	002A	Classroom K-2 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles					
1	B	002A	Classroom K-2 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles					
1	B	002B	Classroom K-2 Coat Area	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	002B	Classroom K-2 Coat Area	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	002B	Classroom K-2 Coat Area	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	002B	Classroom K-2 Coat Area	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	002B	Classroom K-2 Coat Area	yes	Coat Rack	Wood	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no					
1	B	002B	Classroom K-2 Coat Area	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no						
1	B	002B	Classroom K-2 Coat Area	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles					
1	B	002B	Classroom K-2 Coat Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles					
1	B	002C	Classroom K-2 Closet next to hall door	yes	W1	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	No	No	no	no					
1	B	002C	Classroom K-2 Closet next to hall door	yes	W2	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	No	No	no	no					
1	B	002C	Classroom K-2 Closet next to hall door	yes	W3	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	No	No	no	no					
1	B	002C	Classroom K-2 Closet next to hall door	yes	W4	CMU	White	None	0	N/A	N/A		0	Negative	None	N/A	Negative	No	No	no	no					
1	B	002C	Classroom K-2 Closet next to hall door	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	Ceiling Tiles					
1	B	002C	Classroom K-2 Closet next to hall door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	12" x 12" Floor Tiles					
1	B	3	Classroom K-3	yes	W1	CMU	White	Chipping																		

					School District of Philadelphia																
					Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21							
					Cook-Wissahickon ES School									ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	B	003A	Classroom K-3 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	003B	Classroom K-3 Coat Area	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	003B	Classroom K-3 Coat Area	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	003B	Classroom K-3 Coat Area	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	003B	Classroom K-3 Coat Area	yes	Coat Rack	Wood	White	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	003B	Classroom K-3 Coat Area	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	003B	Classroom K-3 Coat Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	003B	Classroom K-3 Coat Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	003C	Closet between Classrooms K-2 & K-3	yes	W1	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003C	Closet between Classrooms K-2 & K-3	yes	W2	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003C	Closet between Classrooms K-2 & K-3	yes	W3	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003C	Closet between Classrooms K-2 & K-3	yes	W4	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003C	Closet between Classrooms K-2 & K-3	yes	Ceiling	Concrete	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003C	Closet between Classrooms K-2 & K-3	yes	Pipe	Metal	White	Chipping	4	N/A	N/A		0.2 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003C	Closet between Classrooms K-2 & K-3	yes	Duct	Metal	White	Chipping	2	N/A	N/A		0.21 Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	003C	Closet between Classrooms K-2 & K-3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	003D	Classroom K-3 Closet by entrance	yes	W1	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003D	Classroom K-3 Closet by entrance	yes	W2	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003D	Classroom K-3 Closet by entrance	yes	W3	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003D	Classroom K-3 Closet by entrance	yes	W4	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003D	Classroom K-3 Closet by entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	003D	Classroom K-3 Closet by entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	4	Small Music Room next to Music Room 005	yes	W1	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	4	Small Music Room next to Music Room 005	yes	W2	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	4	Small Music Room next to Music Room 005	yes	W3	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	4	Small Music Room next to Music Room 005	yes	W4	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	4	Small Music Room next to Music Room 005	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	4	Small Music Room next to Music Room 005	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	5	Music Room 005	yes	W1	CMU	White	Chipping	2	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	5	Music Room 005	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A		0.17 Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	5	Music Room 005	yes	W2	CMU	White	Holes	1	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	5	Music Room 005	yes	W3	Concrete	White	Chipping	20	N/A	N/A		0 Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	5	Music Room 005	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	5	Music Room 005	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	5	Music Room 005	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	W1	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	W2	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	W3	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	Window Frame	Metal	Grey	Flaking	3	N/A	N/A	0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	W4	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	W1	CMU	White	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	005B	Music Room Storeroom (Practice Room B)	yes	Window Frame	Metal	Grey	Chipping	2	N/A	N/A		0.18 Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	005A	Storeroom next to Music Room (Practice Room A)	yes	W2	CMU	White	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	005A	Storeroom next to Music Room (Practice Room A)	yes	Window Frame	Metal	Grey	Chipping	2	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	005A	Storeroom next to Music Room (Practice Room A)	yes	W3	CMU	White	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	005A	Storeroom next to Music Room (Practice Room A)	yes	W4	CMU	White	Chipping	1	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	005A	Storeroom next to Music Room (Practice Room A)	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	005A	Storeroom next to Music Room (Practice Room A)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	6	Art Room K-6	yes	W1	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	6	Art Room K-6	yes	W2	CMU	White	None	0	N/A	N/A	0.05	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	6	Art Room K-6	yes	W3	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	6	Art Room K-6	yes	Univent	Metal	Grey	Chipping	12	N/A	N/A	0.45	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	6	Art Room K-6	yes	W4	CMU	White	None	0	N/A	N/A		0.1 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	6	Art Room K-6	yes	Ceiling	Concrete	White	Chipping	2	N/A	N/A		0.1 Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	6	Art Room K-6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	006A/006B	Classroom K-6 Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	006A/006B	Classroom K-6 Closet	yes	W2	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	
1	B	006A/006B	Classroom K-6 Closet	yes	W3	CMU	White	None	0	N/A	N/A		0 Negative	None	N/A	Negative	Partially Inaccessible	No	no	no	

					School District of Philadelphia																			
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report												Inspection Dates: 04/20-5/03/21							
			Inspection Company: Synertech, Inc.		Cook-Wissahickon ES School												ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	B	006A/006B	Classroom K-6 Closet	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	006A/006B	Classroom K-6 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	006A/006B	Classroom K-6 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	7	Girl's Locker Area	yes	W1	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	7	Girl's Locker Area	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A	0.15	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	7	Girl's Locker Area	yes	W2	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	7	Girl's Locker Area	yes	W3	CMU	Blue	Flaking	20	N/A	N/A	0	N/A	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	7	Girl's Locker Area	yes	W3	Concrete	Blue	Flaking	2	N/A	N/A	0	N/A	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	7	Girl's Locker Area	yes	W4	CMU	Blue	Flaking	30	N/A	N/A	0	N/A	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	7	Girl's Locker Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	7	Girl's Locker Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	8	Boy's Locker Area	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	8	Boy's Locker Area	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0.08	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	8	Boy's Locker Area	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	8	Boy's Locker Area	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	8	Boy's Locker Area	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	8	Boy's Locker Area	yes	Door	Metal	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	8	Boy's Locker Area	yes	W4	CMU	White	Flaking	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	8	Boy's Locker Area	yes	W4	Concrete	White	Flaking	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	8	Boy's Locker Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	8	Boy's Locker Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	9	Gym Office	yes	W1	CMU	Grey	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	9	Gym Office	yes	W2	CMU	Grey	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	9	Gym Office	yes	W3	CMU	Grey	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	9	Gym Office	yes	W4	CMU	Grey	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	9	Gym Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	9	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	009A	Gym Office Restroom	yes	W1	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	009A	Gym Office Restroom	yes	W2	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	009A	Gym Office Restroom	yes	W3	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	009A	Gym Office Restroom	yes	W4	CMU	Grey	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	009A	Gym Office Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	009A	Gym Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	10	Gym Left Storeroom on the Girl's side	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	10	Gym Left Storeroom on the Girl's side	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	10	Gym Left Storeroom on the Girl's side	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	10	Gym Left Storeroom on the Girl's side	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	10	Gym Left Storeroom on the Girl's side	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	10	Gym Left Storeroom on the Girl's side	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	11	Gym Right Storeroom on the Boy's side	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	11	Gym Right Storeroom on the Boy's side	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	11	Gym Right Storeroom on the Boy's side	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	11	Gym Right Storeroom on the Boy's side	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	11	Gym Right Storeroom on the Boy's side	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	11	Gym Right Storeroom on the Boy's side	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	12	Gym	yes	W1	CMU	Grey	Chipping	200	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
1	B	12	Gym	yes	W1	CMU	White	Chipping	200	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
1	B	12	Gym	yes	W1	Concrete	Grey	Chipping	10	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
1	B	12	Gym	yes	W2	CMU	Grey	Chipping	100	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
1	B	12	Gym	yes	W2	CMU	White	Chipping	100	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
1	B	12	Gym	yes	W2	Concrete	Grey	Chipping	10	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
1	B	12	Gym	yes	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	12	Gym	yes	Door	Metal	Brown	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	12	Gym	yes	W3	CMU	Grey	Chipping	200	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
1	B	12	Gym	yes	W3	CMU	White	Chipping	200	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
1	B	12	Gym	yes	W3	Concrete	Grey	Chipping	10	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top latex layer peeling			
</																								



					School District of Philadelphia														Inspection Dates: 04/20-5/03/21						
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report														Cook-Wissahickon ES School						
			Inspection Company: Synertech, Inc.																ULCS# 6410						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm^2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	B	15	Kitchen Prep/Freezer Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	15	Kitchen Prep/Freezer Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16	Kitchen	no	W1	CMU	White	Chipping	5	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	16	Kitchen	no	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16	Kitchen	no	W3	CMU	White	Chipping	10	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	16	Kitchen	no	W3	Concrete	White	Chipping	20	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	16	Kitchen	no	Door Frame	Metal	Grey	Chipping	2	N/A	N/A		0.23	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	16	Kitchen	no	Doors	Metal	Grey	Chipping	2	N/A	N/A		0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	16	Kitchen	no	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16	Kitchen	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16	Kitchen	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16A	Kitchen Storeroom	no	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16A	Kitchen Storeroom	no	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16A	Kitchen Storeroom	no	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16A	Kitchen Storeroom	no	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16A	Kitchen Storeroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16A	Kitchen Storeroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16B	Kitchen Restroom	no	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16B	Kitchen Restroom	no	Door Frame	Metal	Green	Chipping	2	N/A	N/A		0.11	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	16B	Kitchen Restroom	no	W2	CMU	White	Chipping	1	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	16B	Kitchen Restroom	no	W3	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	16B	Kitchen Restroom	no	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16B	Kitchen Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16B	Kitchen Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16C	Kitchen Locker	no	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16C	Kitchen Locker	no	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16C	Kitchen Locker	no	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16C	Kitchen Locker	no	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16C	Kitchen Locker	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	16C	Kitchen Locker	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	17	Lawn Mower Storage next to Kitchen	no	W1	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	17	Lawn Mower Storage next to Kitchen	no	W2	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	17	Lawn Mower Storage next to Kitchen	no	W3	CMU	White	Chipping	4	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	17	Lawn Mower Storage next to Kitchen	no	W4	CMU	White	Chipping	2	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	17	Lawn Mower Storage next to Kitchen	no	Ceiling	Concrete	White	Cracking	5	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	17	Lawn Mower Storage next to Kitchen	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no					
1	B	18	Boiler Room	no	W1	CMU	White	Flaking	60	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W1	CMU	Grey	Flaking	60	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W1	Concrete	White	Flaking	30	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W1	Concrete	Grey	Flaking	30	N/A	N/A		0.02	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W2	CMU	White	Flaking	20	N/A	N/A		0.02	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W2	CMU	Grey	Flaking	20	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W2	Concrete	White	Flaking	10	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W2	Concrete	Grey	Flaking	10	N/A	N/A		0.06	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W3	CMU	White	Flaking	80	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W3	CMU	Grey	Flaking	80	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W3	Concrete	White	Flaking	30	N/A	N/A		0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W3	Concrete	Grey	Flaking	30	N/A	N/A		0.08	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W4	CMU	White	Flaking	120	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W4	CMU	Grey	Flaking	120	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W4	Concrete	White	Flaking	20	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	W4	Concrete	Grey	Flaking	20	N/A	N/A		0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	18	Boiler Room	no	Ceiling	Concrete																			



					School District of Philadelphia																			
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report												Inspection Dates: 04/20-5/03/21							
			Inspection Company: Synertech, Inc.		Cook-Wissahickon ES School												ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	B	21A	Custodial Closet between Staff Restrooms	yes	W4	CMU	White	None	0	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	21A	Custodial Closet between Staff Restrooms	yes	Ceiling	Concrete	White	Cracking	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	21A	Custodial Closet between Staff Restrooms	yes	Floor	Concrete	Grey	Chipping	3	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	22	Men's Restroom next to Building Engineer's Office	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	22	Men's Restroom next to Building Engineer's Office	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	22	Men's Restroom next to Building Engineer's Office	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	22	Men's Restroom next to Building Engineer's Office	yes	Pipe	Metal	White	Chipping	1	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	22	Men's Restroom next to Building Engineer's Office	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	22	Men's Restroom next to Building Engineer's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	22	Men's Restroom next to Building Engineer's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	23	Building Engineer's Storeroom (Former Janitorial Locker Room)	no	W1	CMU	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	23	Building Engineer's Storeroom (Former Janitorial Locker Room)	no	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	23	Building Engineer's Storeroom (Former Janitorial Locker Room)	no	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	23	Building Engineer's Storeroom (Former Janitorial Locker Room)	no	W4	CMU	White	Chipping	1	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	23	Building Engineer's Storeroom (Former Janitorial Locker Room)	no	Ceiling	Concrete	White	Cracking	2	N/A	N/A	0	Negative	None	N/A	Negative	Partially Inaccessible	No	no	no				
1	B	23	Building Engineer's Storeroom (Former Janitorial Locker Room)	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	23A	Building Engineer's Storeroom Restroom	no	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	23A	Building Engineer's Storeroom Restroom	no	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	23A	Building Engineer's Storeroom Restroom	no	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	23A	Building Engineer's Storeroom Restroom	no	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	23A	Building Engineer's Storeroom Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	23A	Building Engineer's Storeroom Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	24	Elevator Meter Room next to Elevator	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	24	Elevator Meter Room next to Elevator	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	24	Elevator Meter Room next to Elevator	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	24	Elevator Meter Room next to Elevator	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	24	Elevator Meter Room next to Elevator	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	24	Elevator Meter Room next to Elevator	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	25	Pump Room/Storage	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	25	Pump Room/Storage	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	25	Pump Room/Storage	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	25	Pump Room/Storage	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	25	Pump Room/Storage	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	25	Pump Room/Storage	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	W1	CMU	Grey	Chipping	60	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no	Top layer latex peeling			
1	B	26	Auditorium/Cafeteria	yes	W2	CMU	Grey	Chipping	10	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	Door Frames	Metal	Grey	Chipping	5	N/A	N/A	0.15	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	Stage	Wood	Red	Chipping	40	N/A	N/A	0.29	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	W3	CMU	Grey	Chipping	30	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	W4	CMU	Grey	Chipping	80	N/A	N/A	0	Negative	None	N/A	Positive	Prior to Repair	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	Columns	Concrete	Grey	Chipping	20	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	26	Auditorium/Cafeteria	yes	Risers	Concrete	Black	Chipping	20	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no				
1	B	26A	Cleaner's Break Room on Stage Left	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26A	Cleaner's Break Room on Stage Left	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26A	Cleaner's Break Room on Stage Left	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26A	Cleaner's Break Room on Stage Left	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26A	Cleaner's Break Room on Stage Left	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26A	Cleaner's Break Room on Stage Left	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26B	Cafetorium Storeroom on Stage Right	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26B	Cafetorium Storeroom on Stage Right	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26B	Cafetorium Storeroom on Stage Right	yes	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26B	Cafetorium Storeroom on Stage Right	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26B	Cafetorium Storeroom on Stage Right	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no				
1	B	26B	Cafetorium Storeroom on Stage Right	yes	Floor	N/A	N/A	N/A																

					School District of Philadelphia																
					Lead Safe Certification Assessment Report									Inspection Dates: 04/20-5/03/21							
					Cook-Wissahickon ES School									ULCS# 6410							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Results (ug/cm*2)	XRF Results (Positive/Negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	B	H03	Hallway at Classrooms 002 & 003	yes	Door Frames	Metal	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H03	Hallway at Classrooms 002 & 003	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H03	Hallway at Classrooms 002 & 003	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H03	Hallway at Classrooms 002 & 003	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H04	Hallway at Elevator	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H04	Hallway at Elevator	yes	W2	CMU	Grey	Chipping	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H04	Hallway at Elevator	yes	Door Frames	Metal	Grey	Chipping	2	N/A	N/A	0.09	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H04	Hallway at Elevator	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H04	Hallway at Elevator	yes	W4	CMU	Grey	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H04	Hallway at Elevator	yes	Door Frames	Metal	Grey	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H04	Hallway at Elevator	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H04	Hallway at Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H08	Hallway to Gym	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H08	Hallway to Gym	yes	W2	CMU	Grey	Chipping	4	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H08	Hallway to Gym	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.16	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H08	Hallway to Gym	yes	Door Frames	Metal	Grey	Chipping	2	N/A	N/A	0.16	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H08	Hallway to Gym	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H08	Hallway to Gym	yes	W4	CMU	Grey	Chipping	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H08	Hallway to Gym	yes	Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H08	Hallway to Gym	yes	Door Frames	Metal	Grey	Chipping	2	N/A	N/A	0.11	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	H08	Hallway to Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	H08	Hallway to Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	Door	Metal	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	W3	Concrete	White	Chipping	4	N/A	N/A	N/A	N/A	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	Door Frame	Metal	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	Door	Metal	Blue	Chipping	2	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01A	Stairwell #3 Boy's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	W1	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	N/A	N/A	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Door	Metal	Blue	Chipping	1	N/A	N/A	0.09	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	W2	CMU	Blue	Chipping	20	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	W2	Concrete	Blue	Chipping	20	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	W3	CMU	Blue	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0.16	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Door	Metal	Blue	Chipping	1	N/A	N/A	0.12	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	W4	CMU	Blue	Chipping	8	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Vent	Metal	Blue	Chipping	1	N/A	N/A	0.16	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Door Frame	Metal	Blue	Chipping	1	N/A	N/A	0.1	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	Negative	No	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Stringer	Concrete	Blue	Chipping	10	N/A	N/A	0	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	B	S01C	Stairwell #3 Girl's Restroom	yes	Risers	Concrete	Blue	Chipping	30	N/A	N/A	0.14	Negative	None	N/A	Negative	Prior to Repair	No	no	no	
1	EX	EX2	Building Exterior Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX2	Building Exterior Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX2	Building Exterior Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX2	Building Exterior Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX2	Building Exterior Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX2	Building Exterior Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX3	Exterior Door	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX3	Exterior Door	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX3	Exterior Door	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX3	Exterior Door	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX3	Exterior Door	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	EX	EX3	Exterior Door	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	R	EX4	Roof	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	R	EX4	Roof	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	R	EX4	Roof	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	R	EX4	Roof	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	R	EX4	Roof	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	
1	R	EX4	Roof	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative	No	No	no	no	