

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r											
		Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	H115	Main Entrance Lobby	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	H115	Main Entrance Lobby	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	H115	Main Entrance Lobby	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.1	Negative
1	1	H115	Main Entrance Lobby	Door	Wood	Grey	Chipping	2	N/A	N/A	0.12	Negative
1	1	H115	Main Entrance Lobby	Radiator	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	1	H115	Main Entrance Lobby	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	H115	Main Entrance Lobby	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	H115	Main Entrance Lobby	Door Frame	Metal	Black	Metal	2	N/A	N/A	0.17	Negative
1	1	H115	Main Entrance Lobby	Door	Wood	Grey	Chipping	2	N/A	N/A	0.21	Negative
1	1	H115	Main Entrance Lobby	Radiator	Metal	Black	Metal	1	N/A	N/A	0	Negative
1	1	H115	Main Entrance Lobby	Ceiling	Concrete	White	Cracking	8	N/A	N/A	0	Negative
1	1	H115	Main Entrance Lobby	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	H115	Main Entrance Lobby	Stair Risers	Concrete	Grey	Chipping	1	N/A	N/A	0	Negative
1	1	106D	Main Lobby Men's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106D	Main Lobby Men's Restroom	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	1	106D	Main Lobby Men's Restroom	Door	Wood	Yellow	Chipping	1	N/A	N/A	0.12	Negative
1	1	106D	Main Lobby Men's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106D	Main Lobby Men's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106D	Main Lobby Men's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106D	Main Lobby Men's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	106D	Main Lobby Men's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	1	106E	Main Lobby Custodial Closet	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	106E	Main Lobby Custodial Closet	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	106E	Main Lobby Custodial Closet	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	106E	Main Lobby Custodial Closet	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	106E	Main Lobby Custodial Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	106E	Main Lobby Custodial Closet	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	1	106B	Main Lobby Women's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Main Lobby Women's Restroom	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	1	106B	Main Lobby Women's Restroom	Door	Wood	Yellow	Chipping	1	N/A	N/A	0.12	Negative
1	1	106B	Main Lobby Women's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Main Lobby Women's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Main Lobby Women's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Main Lobby Women's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Main Lobby Women's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	1	115	Auditorium	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	1	115	Auditorium	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	115	Auditorium	Door	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	115	Auditorium	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	115	Auditorium	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	115	Auditorium	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0.4	Negative
1	1	115	Auditorium	Door	Metal	Brown	Chipping	2	N/A	N/A	0.3	Negative
1	1	115	Auditorium	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	115	Auditorium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115	Auditorium	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115	Auditorium	Chairs	Metal	Green	Chipping	20	N/A	N/A	0	Negative
1	1	115A	Stage	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	115A	Stage	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	115A	Stage	Door Frame	Metal	White	Chipping	2	N/A	N/A	0.12	Negative
1	1	115A	Stage	Door	Metal	White	Chipping	2	N/A	N/A	0.08	Negative
1	1	115A	Stage	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	115A	Stage	Pipe	Metal	White	Flaking	4	N/A	N/A	0.17	Negative
1	1	115A	Stage	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	115A	Stage	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.1	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r											
		Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm*2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	115A	Stage	Door	Metal	Yellow	Chipping	2	N/A	N/A	0.15	Negative
1	1	115A	Stage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	115A	Stage	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115D	Stage Entrance/Stairs (audience right)	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	115D	Stage Entrance/Stairs (audience right)	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	115D	Stage Entrance/Stairs (audience right)	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	115D	Stage Entrance/Stairs (audience right)	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	115D	Stage Entrance/Stairs (audience right)	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	115D	Stage Entrance/Stairs (audience right)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115B	Stage Fan Room	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	1	115B	Stage Fan Room	Door Frame	Metal	White	Chipping	2	N/A	N/A	0.2	Negative
1	1	115B	Stage Fan Room	Door	Metal	White	Chipping	2	N/A	N/A	0.2	Negative
1	1	115B	Stage Fan Room	W2	CMU	White	Chipping	6	N/A	N/A	0	Negative
1	1	115B	Stage Fan Room	W3	CMU	White	Chipping	12	N/A	N/A	0	Negative
1	1	115B	Stage Fan Room	Pipe	Metal	White	Flaking	12	N/A	N/A	0.18	Negative
1	1	115B	Stage Fan Room	W4	CMU	White	Chipping	6	N/A	N/A	0	Negative
1	1	115B	Stage Fan Room	Ceiling	Plaster	White	Flaking	4	N/A	N/A	0.08	Negative
1	1	115B	Stage Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115B	Stage Fan Room	Fan Unit	Metal	Green	Chipping	4	N/A	N/A	0	Negative
1	1	115C	Stage Storeroom (audience left)	W1	CMU	Green	Cracking	12	N/A	N/A	0	Negative
1	1	115C	Stage Storeroom (audience left)	Door Frame	Metal	Green	Chipping	2	N/A	N/A	0.16	Negative
1	1	115C	Stage Storeroom (audience left)	Door	Metal	Green	Chipping	2	N/A	N/A	0.1	Negative
1	1	115C	Stage Storeroom (audience left)	W2	CMU	Green	Cracking	12	N/A	N/A	0	Negative
1	1	115C	Stage Storeroom (audience left)	W3	CMU	Green	Cracking	12	N/A	N/A	0	Negative
1	1	115C	Stage Storeroom (audience left)	W4	CMU	Green	Cracking	12	N/A	N/A	0	Negative
1	1	115C	Stage Storeroom (audience left)	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	115C	Stage Storeroom (audience left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101	Classroom 101	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	101	Classroom 101	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.1	Negative
1	1	101	Classroom 101	Door	Metal	Yellow	Chipping	2	N/A	N/A	0	Negative
1	1	101	Classroom 101	Sink Cabinet	Wood	Yellow	Chipping	12	N/A	N/A	0	Negative
1	1	101	Classroom 101	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	101	Classroom 101	Door Frame	Metal	Brown	Chipping	4	N/A	N/A	0	Negative
1	1	101	Classroom 101	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	101	Classroom 101	Univent	Metal	Tan	Chipping	4	N/A	N/A	0.17	Negative
1	1	101	Classroom 101	Pipes	Metal	Tan	Chipping	2	N/A	N/A	0.13	Negative
1	1	101	Classroom 101	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	101	Classroom 101	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	101	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101B	Classroom 101 Closet	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	101B	Classroom 101 Closet	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	101B	Classroom 101 Closet	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	101B	Classroom 101 Closet	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	101B	Classroom 101 Closet	Ceiling	Concrete	Green	None	0	N/A	N/A	N/A	N/A
1	1	101B	Classroom 101 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	117	Classroom 101 Coat Closet	W1	CMU	Green	None	0	N/A	N/A	N/A	N/A
1	1	117	Classroom 101 Coat Closet	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	117	Classroom 101 Coat Closet	W3	CMU	Green	None	0	N/A	N/A	N/A	N/A
1	1	117	Classroom 101 Coat Closet	Door Frame	Metal	Brown	Chipping	1	N/A	N/A	0	Negative
1	1	117	Classroom 101 Coat Closet	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	117	Classroom 101 Coat Closet	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	117	Classroom 101 Coat Closet	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	117	Classroom 101 Coat Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	117	Classroom 101 Coat Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	117	Classroom 101 Coat Closet	Ceiling	Concrete	Green	None	0	N/A	N/A	N/A	N/A
1	1	117	Classroom 101 Coat Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	Classroom 101 Restroom	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	Door	Wood	Yellow	Chipping	2	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	Door	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	Cabinet	Wood	White	Chipping	4	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	Pipe	Metal	Brown	Flaking	5	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	W3	CMU	White	Chipping	6	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	W3	Concrete	White	Chipping	6	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	Univent	Metal	White	Chipping	4	N/A	N/A	0.22	Negative
1	1	101A	Classroom 101 Restroom	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	Ceiling	Concrete	White	Chipping	4	N/A	N/A	0	Negative
1	1	101A	Classroom 101 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	Classroom 101 Restroom	Baseboards	Terracotta	Black	Chipping	2	N/A	N/A	0	Negative
1	1	102	Classroom 102	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	102	Classroom 102	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	1	102	Classroom 102	Door	Wood	Yellow	Chipping	2	N/A	N/A	0	Negative
1	1	102	Classroom 102	Cabinet	Wood	Brown	Chipping	6	N/A	N/A	0	Negative
1	1	102	Classroom 102	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	102	Classroom 102	W3	CMU	White	None	6	N/A	N/A	0	Negative
1	1	102	Classroom 102	W3	Concrete	White	Chipping	4	N/A	N/A	0	Negative
1	1	102	Classroom 102	Univent	Metal	Brown	Chipping	5	N/A	N/A	0.2	Negative
1	1	102	Classroom 102	Shelves	Metal	Brown	Chipping	5	N/A	N/A	0.18	Negative
1	1	102	Classroom 102	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	102	Classroom 102	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	102	Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102A	Classroom 102 Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	102A	Classroom 102 Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	102A	Classroom 102 Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	102A	Classroom 102 Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	102A	Classroom 102 Restroom	Ceiling	Concrete	White	Flaking	3	N/A	N/A	0.1	Negative
1	1	102A	Classroom 102 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	116	Classroom 102 Coat Closet	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	116	Classroom 102 Coat Closet	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	116	Classroom 102 Coat Closet	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	116	Classroom 102 Coat Closet	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	116	Classroom 102 Coat Closet	Ceiling	Ceiling	Green	None	0	N/A	N/A	N/A	N/A
1	1	116	Classroom 102 Coat Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102B	Exit Hallway next to Classroom 102	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	116	Classroom 102 Coat Closet	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	1	116	Classroom 102 Coat Closet	Door	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	1	102B	Exit Hallway next to Classroom 102	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	102B	Exit Hallway next to Classroom 102	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	102B	Exit Hallway next to Classroom 102	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	102B	Exit Hallway next to Classroom 102	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	102B	Exit Hallway next to Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Nurse's Office Waiting Room	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103	Nurse's Office Waiting Room	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103	Nurse's Office Waiting Room	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103	Nurse's Office Waiting Room	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103	Nurse's Office Waiting Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	103	Nurse's Office Waiting Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	103B	Nurse's Office	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	103B	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103C	Nurse's Office Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103C	Nurse's Office Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103C	Nurse's Office Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103C	Nurse's Office Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	103C	Nurse's Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	103C	Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H116	Exit Hall next to Nurse's Office	W1	CMU	Tan	None	0	N/A	N/A	N/A	N/A
1	1	H116	Exit Hall next to Nurse's Office	W2	CMU	Tan	None	0	N/A	N/A	N/A	N/A
1	1	116	Classroom 102 Coat Closet	W3	CMU	Tan	Flaking	20	N/A	N/A	0	Negative
1	1	H116	Exit Hall next to Nurse's Office	W4	CMU	Tan	None	0	N/A	N/A	N/A	N/A
1	1	116	Classroom 102 Coat Closet	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.18	Negative
1	1	116	Classroom 102 Coat Closet	Door	Metal	Grey	Chipping	2	N/A	N/A	0.26	Negative
1	1	H116	Exit Hall next to Nurse's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	H116	Exit Hall next to Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	W1	CMU	White	Chipping	1	N/A	N/A	0	Negative
1	1	104	Classroom 104	W2	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	1	104	Classroom 104	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	1	104	Classroom 104	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	104	Classroom 104	Door	Wood	Yellow	Chipping	2	N/A	N/A	0.13	Negative
1	1	104	Classroom 104	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	1	104	Classroom 104	Univent	Metal	Tan	Chipping	6	N/A	N/A	0.18	Negative
1	1	104	Classroom 104	Pipes	Metal	Tan	Chipping	2	N/A	N/A	0.1	Negative
1	1	104	Classroom 104	W4	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	1	104	Classroom 104	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Storage Closet to the Left	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	104A	Classroom 104 Storage Closet to the Left	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	104A	Classroom 104 Storage Closet to the Left	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	104A	Classroom 104 Storage Closet to the Left	Pipe	Metal	Green	Chipping	3	N/A	N/A	0.12	Negative
1	1	104A	Classroom 104 Storage Closet to the Left	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	104A	Classroom 104 Storage Closet to the Left	Ceiling	Concrete	Green	None	0	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Storage Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104B	Classroom 104 Storage Closet to the Right	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	104B	Classroom 104 Storage Closet to the Right	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	104B	Classroom 104 Storage Closet to the Right	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	104B	Classroom 104 Storage Closet to the Right	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	104B	Classroom 104 Storage Closet to the Right	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	1	104B	Classroom 104 Storage Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S101	Stainwell 1	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S101	Stainwell 1	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S101	Stainwell 1	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S101	Stainwell 1	W4	CMU	White	None	0	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	S101	Stairwell 1	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	S101	Stairwell 1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H114	Hallway from Stair 1 to Classroom 101	W1	CMU	White	Chipping	12	N/A	N/A	0	0
1	1	H114	Hallway from Stair 1 to Classroom 101	Door Frame	Metal	Black	Chipping	6	N/A	N/A	0.1	Negative
1	1	H114	Hallway from Stair 1 to Classroom 101	Doors	Wood	Yellow	Chipping	6	N/A	N/A	0.08	Negative
1	1	H114	Hallway from Stair 1 to Classroom 101	Doors	Wood	Black	Chipping	6	N/A	N/A	0.16	Negative
1	1	H114	Hallway from Stair 1 to Classroom 101	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	H114	Hallway from Stair 1 to Classroom 101	W3	CMU	White	Chipping	12	N/A	N/A	0	0
1	1	H114	Hallway from Stair 1 to Classroom 101	Door Frame	Metal	Brown	Friction	2	N/A	N/A	0.14	Negative
1	1	H114	Hallway from Stair 1 to Classroom 101	Door	Metal	Brown	Friction	2	N/A	N/A	0.1	Negative
1	1	H114	Hallway from Stair 1 to Classroom 101	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	H114	Hallway from Stair 1 to Classroom 101	Radiator	Metal	Grey	Chipping	2	N/A	N/A	0.2	Negative
1	1	H114	Hallway from Stair 1 to Classroom 101	Ceiling	Concrete	White	Chipping	2	N/A	N/A	0.1	Negative
1	1	H114	Hallway from Stair 1 to Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H114	Hallway from Stair 1 to Classroom 101	Handrail	Metal	Brown	Friction	4	N/A	N/A	0	Negative
1	1	106	Office across from Main Office	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	106	Office across from Main Office	Door Frame	Metal	Brown	Chipping	1	N/A	N/A	0	Negative
1	1	106	Office across from Main Office	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	106	Office across from Main Office	Door Frame	Metal	Brown	Chipping	1	N/A	N/A	0	Negative
1	1	106	Office across from Main Office	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	1	106	Office across from Main Office	Radiator	Metal	Brown	Chipping	2	N/A	N/A	0.16	Negative
1	1	106	Office across from Main Office	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	106	Office across from Main Office	Ceiling	Concrete	White	Chipping	1	N/A	N/A	0	Negative
1	1	106	Office across from Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Office Closet on Hallway side	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106A	Office Closet on Hallway side	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106A	Office Closet on Hallway side	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106A	Office Closet on Hallway side	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106A	Office Closet on Hallway side	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	106A	Office Closet on Hallway side	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Office Closet on windows side	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Office Closet on windows side	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	1	106B	Office Closet on windows side	Door	Wood	Yellow	Chipping	1	N/A	N/A	0.23	Negative
1	1	106B	Office Closet on windows side	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Office Closet on windows side	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Office Closet on windows side	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Office Closet on windows side	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	106B	Office Closet on windows side	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105	Main Office	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105	Main Office	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.12	Negative
1	1	105	Main Office	Door	Wood	White	Chipping	2	N/A	N/A	0.04	Negative
1	1	105	Main Office	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105	Main Office	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105	Main Office	Univent	Metal	Black	Chipping	4	N/A	N/A	0.17	Negative
1	1	105	Main Office	Door	Wood	White	Chipping	1	N/A	N/A	0	Negative
1	1	105	Main Office	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105	Main Office	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.1	Negative
1	1	105	Main Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	105	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Main Office Closet next to Principal's Office	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	105B	Main Office Closet next to Principal's Office	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	105B	Main Office Closet next to Principal's Office	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	105B	Main Office Closet next to Principal's Office	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	105B	Main Office Closet next to Principal's Office	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	105B	Main Office Closet next to Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105C	Main Office Closet by counter	W1	CMU	White	Cracking	0	N/A	N/A	0	Negative
1	1	105C	Main Office Closet by counter	W2	CMU	White	Cracking	0	N/A	N/A	0	Negative
1	1	105C	Main Office Closet by counter	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	105C	Main Office Closet by counter	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	105C	Main Office Closet by counter	Ceiling	Concrete	White	Cracking	0	N/A	N/A	0	Negative
1	1	105C	Main Office Closet by counter	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105A	Principal's Office	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105A	Principal's Office	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	1	105A	Principal's Office	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105A	Principal's Office	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105A	Principal's Office	Radiator Diffuser	Metal	Black	Chipping	4	N/A	N/A	0.2	Negative
1	1	105A	Principal's Office	W4	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	1	105A	Principal's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	105A	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105A	Principal's Office	Baseboards	Terracotta	N/A	None	2	N/A	N/A	0	Negative
1	1	105D	Principal's Office Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105D	Principal's Office Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105D	Principal's Office Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105D	Principal's Office Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	105D	Principal's Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	105D	Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Vice Principal's Office	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	108	Vice Principal's Office	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	108	Vice Principal's Office	Door	Wood	Yellow	Chipping	2	N/A	N/A	0	Negative
1	1	108	Vice Principal's Office	Door	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	1	108	Vice Principal's Office	Cabinets	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	1	108	Vice Principal's Office	Pipes	Metal	Brown	Flaking	1	N/A	N/A	0.1	Negative
1	1	108	Vice Principal's Office	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	108	Vice Principal's Office	W3	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	1	108	Vice Principal's Office	W3	Concrete	White	Chipping	6	N/A	N/A	0	Negative
1	1	108	Vice Principal's Office	Univent	Metal	White	Chipping	4	N/A	N/A	0.14	Negative
1	1	108	Vice Principal's Office	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	108	Vice Principal's Office	Ceiling	Concrete	White	Chipping	4	N/A	N/A	0	Negative
1	1	108	Vice Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Room 108 Closet to the Left	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	1	108A	Room 108 Closet to the Left	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	1	108A	Room 108 Closet to the Left	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	1	108A	Room 108 Closet to the Left	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	1	108A	Room 108 Closet to the Left	Ceiling	Concrete	Blue	None	0	N/A	N/A	N/A	N/A
1	1	108A	Room 108 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Room 108 Closet to the Right	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	1	108B	Room 108 Closet to the Right	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	1	108B	Room 108 Closet to the Right	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	1	108B	Room 108 Closet to the Right	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	1	108B	Room 108 Closet to the Right	Ceiling	Concrete	Blue	None	0	N/A	N/A	N/A	N/A
1	1	108B	Room 108 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	107	Classroom 107	Door	Wood	Yellow	Chipping	2	N/A	N/A	0	Negative
1	1	107	Classroom 107	Door	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	1	107	Classroom 107	Cabinets	Wood	White	Chipping	4	N/A	N/A	0	Negative
1	1	107	Classroom 107	Pipes	Metal	Brown	Flaking	4	N/A	N/A	0.12	Negative
1	1	107	Classroom 107	W2	CMU	White	None	0	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	107	Classroom 107	W3	CMU	White	Chipping	6	N/A	N/A	0	Negative
1	1	107	Classroom 107	W3	Concrete	White	Chipping	6	N/A	N/A	0	Negative
1	1	107	Classroom 107	Univent	Metal	White	Chipping	4	N/A	N/A	0.18	Negative
1	1	107	Classroom 107	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	Ceiling	Concrete	White	Chipping	4	N/A	N/A	0	Negative
1	1	107	Classroom 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Closet to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	107A	Classroom 107 Closet to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	107A	Classroom 107 Closet to the Left	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	107A	Classroom 107 Closet to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	107A	Classroom 107 Closet to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	1	107A	Classroom 107 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107B	Classroom 107 Closet to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	107B	Classroom 107 Closet to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	107B	Classroom 107 Closet to the Right	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	107B	Classroom 107 Closet to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	107B	Classroom 107 Closet to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	1	107B	Classroom 107 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S102	Stairwell 2 next to Vice Principal's Office	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S102	Stairwell 2 next to Vice Principal's Office	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S102	Stairwell 2 next to Vice Principal's Office	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S102	Stairwell 2 next to Vice Principal's Office	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S102	Stairwell 2 next to Vice Principal's Office	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.1	Negative
1	1	S102	Stairwell 2 next to Vice Principal's Office	Door	Metal	Grey	Chipping	2	N/A	N/A	0.14	Negative
1	1	S102	Stairwell 2 next to Vice Principal's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	S102	Stairwell 2 next to Vice Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	109	Classroom 109	Door	Wood	Yellow	Chipping	2	N/A	N/A	0	Negative
1	1	109	Classroom 109	Door	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	1	109	Classroom 109	Cabinets	Wood	White	Chipping	4	N/A	N/A	0	Negative
1	1	109	Classroom 109	Pipes	Metal	Brown	Flaking	4	N/A	N/A	0	Negative
1	1	109	Classroom 109	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	W3	CMU	White	Chipping	6	N/A	N/A	0	Negative
1	1	109	Classroom 109	W3	Concrete	White	Chipping	6	N/A	N/A	0	Negative
1	1	109	Classroom 109	Univent	Metal	White	Chipping	4	N/A	N/A	0.1	Negative
1	1	109	Classroom 109	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	Ceiling	Concrete	White	Chipping	4	N/A	N/A	0	Negative
1	1	109	Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109A	Classroom 109 Closet to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	109A	Classroom 109 Closet to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	109A	Classroom 109 Closet to the Left	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	109A	Classroom 109 Closet to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	109A	Classroom 109 Closet to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	1	109A	Classroom 109 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109B	Classroom 109 Closet to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	109B	Classroom 109 Closet to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	109B	Classroom 109 Closet to the Right	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	109B	Classroom 109 Closet to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	1	109B	Classroom 109 Closet to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	1	109B	Classroom 109 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	1st Floor Boy's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	110	1st Floor Boy's Restroom	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	1	110	1st Floor Boy's Restroom	Door	Metal	Grey	Chipping	1	N/A	N/A	0.1	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	110	1st Floor Boy's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	110	1st Floor Boy's Restroom	Stall Divider	Metal	Black	Chipping	3	N/A	N/A	0	Negative
1	1	110	1st Floor Boy's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	110	1st Floor Boy's Restroom	Door Frame	Metal	Red	Chipping	2	N/A	N/A	0.3	Negative
1	1	110	1st Floor Boy's Restroom	Door	Metal	Red	Chipping	2	N/A	N/A	0.3	Negative
1	1	110	1st Floor Boy's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	110	1st Floor Boy's Restroom	Ceiling	Concrete	White	Flaking	100	N/A	N/A	0	Negative
1	1	110	1st Floor Boy's Restroom	Duct	Metal	White	Flaking	5	N/A	N/A	0.15	Negative
1	1	110	1st Floor Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110A	1st Floor Girl's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	110A	1st Floor Girl's Restroom	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	1	110A	1st Floor Girl's Restroom	Door	Metal	Grey	Chipping	1	N/A	N/A	0.08	Negative
1	1	110A	1st Floor Girl's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	110A	1st Floor Girl's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	110A	1st Floor Girl's Restroom	Door Frame	Metal	Red	Chipping	2	N/A	N/A	0.3	Negative
1	1	110A	1st Floor Girl's Restroom	Door	Metal	Red	Chipping	2	N/A	N/A	0.28	Negative
1	1	110A	1st Floor Girl's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	110A	1st Floor Girl's Restroom	Ceiling	Concrete	White	Flaking	200	N/A	N/A	0.1	Negative
1	1	110A	1st Floor Girl's Restroom	Duct	Metal	White	Flaking	5	N/A	N/A	0.15	Negative
1	1	110A	1st Floor Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110B	Teacher's Lounge & Restroom across from Classroom 111	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	110B	Teacher's Lounge & Restroom across from Classroom 111	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	110B	Teacher's Lounge & Restroom across from Classroom 111	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	110B	Teacher's Lounge & Restroom across from Classroom 111	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	110B	Teacher's Lounge & Restroom across from Classroom 111	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	110B	Teacher's Lounge & Restroom across from Classroom 111	Ceiling	Concrete	White	Flaking	8	N/A	N/A	0	Negative
1	1	110B	Teacher's Lounge & Restroom across from Classroom 111	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Classroom 111	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	1	111	Classroom 111	W1	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	1	111	Classroom 111	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	1	111	Classroom 111	Door	Metal	Brown	Chipping	1	N/A	N/A	0	Negative
1	1	111	Classroom 111	Door Frame	Metal	Brown	Chipping	1	N/A	N/A	0	Negative
1	1	111	Classroom 111	Door	Metal	Yellow	Chipping	1	N/A	N/A	0	Negative
1	1	111	Classroom 111	Pipes	Metal	White	Chipping	2	N/A	N/A	0	Negative
1	1	111	Classroom 111	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	1	111	Classroom 111	W2	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	1	111	Classroom 111	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	1	111	Classroom 111	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	1	111	Classroom 111	Univent	Metal	White	Chipping	6	N/A	N/A	0	Negative
1	1	111	Classroom 111	Pipes	Metal	White	Chipping	1	N/A	N/A	0	Negative
1	1	111	Classroom 111	W4	CMU	White	Chipping	6	N/A	N/A	0	Negative
1	1	111	Classroom 111	W4	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	1	111	Classroom 111	Ceiling	Concrete	White	Chipping	5	N/A	N/A	0	Negative
1	1	111	Classroom 111	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111A	Classroom 111 Closet to the Left	W1	CMU	Yellow	None	0	N/A	N/A	0	Negative
1	1	111A	Classroom 111 Closet to the Left	W2	CMU	Yellow	None	0	N/A	N/A	0	Negative
1	1	111A	Classroom 111 Closet to the Left	W3	CMU	Yellow	None	0	N/A	N/A	0	Negative
1	1	111A	Classroom 111 Closet to the Left	W4	CMU	Yellow	None	0	N/A	N/A	0	Negative



			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	111A	Classroom 111 Closet to the Left	Ceiling	Concrete	Yellow	None	0	N/A	N/A	0	Negative
1	1	111A	Classroom 111 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111B	Classroom 111 Closet to the Right	W1	CMU	Yellow	None	0	N/A	N/A	0	Negative
1	1	111B	Classroom 111 Closet to the Right	W2	CMU	Yellow	None	0	N/A	N/A	0	Negative
1	1	111B	Classroom 111 Closet to the Right	W3	CMU	Yellow	None	0	N/A	N/A	0	Negative
1	1	111B	Classroom 111 Closet to the Right	W4	CMU	Yellow	None	0	N/A	N/A	0	Negative
1	1	111B	Classroom 111 Closet to the Right	Ceiling	Concrete	Yellow	None	0	N/A	N/A	0	Negative
1	1	111B	Classroom 111 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112	Classroom 112	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	112	Classroom 112	Door	Metal	Black	Chipping	1	N/A	N/A	0.15	Negative
1	1	112	Classroom 112	Door	Metal	Yellow	Chipping	2	N/A	N/A	0.09	Negative
1	1	112	Classroom 112	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	112	Classroom 112	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	112	Classroom 112	Univent	Metal	White	Chipping	4	N/A	N/A	0.2	Negative
1	1	112	Classroom 112	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	112	Classroom 112	Ceiling	Concrete	White	Chipping	24	N/A	N/A	0.08	Negative
1	1	112	Classroom 112	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112A	Classroom 112 Closet	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	112A	Classroom 112 Closet	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	112A	Classroom 112 Closet	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	112A	Classroom 112 Closet	Pipe	Metal	Green	Chipping	4	N/A	N/A	0.18	Negative
1	1	112A	Classroom 112 Closet	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	1	112A	Classroom 112 Closet	Ceiling	Concrete	Green	None	0	N/A	N/A	N/A	N/A
1	1	112A	Classroom 112 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S103	Stairwell 3 adjacent to Classroom 112	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S103	Stairwell 3 adjacent to Classroom 112	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S103	Stairwell 3 adjacent to Classroom 112	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S103	Stairwell 3 adjacent to Classroom 112	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	S103	Stairwell 3 adjacent to Classroom 112	Door	Metal	Blue	Chipping	2	N/A	N/A	0.3	Negative
1	1	S103	Stairwell 3 adjacent to Classroom 112	Door	Metal	Brown	Chipping	2	N/A	N/A	0.24	Negative
1	1	S103	Stairwell 3 adjacent to Classroom 112	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	S103	Stairwell 3 adjacent to Classroom 112	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S104	Exit Hallway next to Classroom 111	W1	CMU	White	Flaking	20	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	W1	Concrete	White	Flaking	12	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.1	Negative
1	1	S104	Exit Hallway next to Classroom 111	Door	Metal	Black	Chipping	2	N/A	N/A	0.1	Negative
1	1	S104	Exit Hallway next to Classroom 111	W2	CMU	White	Flaking	250	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	W2	Concrete	White	Flaking	15	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	Handrail	Metal	Brown	Friction	6	N/A	N/A	0.3	Negative
1	1	S104	Exit Hallway next to Classroom 111	Radiator	Metal	White	Chipping	4	N/A	N/A	0.15	Negative
1	1	S104	Exit Hallway next to Classroom 111	W3	CMU	White	Flaking	30	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	W3	Concrete	White	Flaking	20	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	Door	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	W4	CMU	White	Flaking	250	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	W4	Concrete	White	Flaking	20	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	Ceiling	Concrete	White	Flaking	2	N/A	N/A	0	Negative
1	1	S104	Exit Hallway next to Classroom 111	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H113	Hallway from Gymnasium to Main Lobby	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.06	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	Doors	Wood	Grey	Chipping	4	N/A	N/A	0.04	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	Elevator Door Frame	Metal	Grey	Chipping	2	N/A	N/A	0.21	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	Elevator Door	Metal	Grey	Chipping	2	N/A	N/A	0.16	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	H113	Hallway from Gymnasium to Main Lobby	Radiators	Metal	Grey	Chipping	4	N/A	N/A	0.1	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	Pipes	Metal	Tan	Chipping	1	N/A	N/A	0.12	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	H113	Hallway from Gymnasium to Main Lobby	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	Doors	Wood	Grey	Chipping	4	N/A	N/A	0	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	1	H113	Hallway from Gymnasium to Main Lobby	Ceiling	Concrete	White	Chipping	5	N/A	N/A	0	Negative
1	1	H113	Hallway from Gymnasium to Main Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113	Gymnasium	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113	Gymnasium	Backboard	Wood	White	Chipping	8	N/A	N/A	0.15	Negative
1	1	113	Gymnasium	Door Frame	Metal	Black	Friction	2	N/A	N/A	0	Negative
1	1	113	Gymnasium	Door	Wood	Yellow	Chipping	2	N/A	N/A	0	Negative
1	1	113	Gymnasium	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	113	Gymnasium	Door	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	113	Gymnasium	W2	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	1	113	Gymnasium	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	1	113	Gymnasium	Backboard	Wood	White	Chipping	8	N/A	N/A	0	Negative
1	1	113	Gymnasium	W4	CMU	White	Chipping	6	N/A	N/A	0	Negative
1	1	113	Gymnasium	Radiator	Metal	White	Chipping	1	N/A	N/A	0.16	Negative
1	1	113	Gymnasium	Ceiling	Concrete	White	Flaking	10	N/A	N/A	0	Negative
1	1	113	Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113	Gymnasium	Baseboards	Metal	Brown	Chipping	20	N/A	N/A	0	Negative
1	1	113A	Gymnasium Storeroom (former Boy's Locker Room)	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113A	Gymnasium Storeroom (former Boy's Locker Room)	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113A	Gymnasium Storeroom (former Boy's Locker Room)	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113A	Gymnasium Storeroom (former Boy's Locker Room)	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113A	Gymnasium Storeroom (former Boy's Locker Room)	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	113A	Gymnasium Storeroom (former Boy's Locker Room)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113B	Gym Office	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113B	Gym Office	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	1	113B	Gym Office	Switch Panel	Metal	Brown	Chipping	1	N/A	N/A	0.14	Negative
1	1	113B	Gym Office	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113B	Gym Office	Radiator	Metal	Brown	Chipping	2	N/A	N/A	0.18	Negative
1	1	113B	Gym Office	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113B	Gym Office	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113B	Gym Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	113B	Gym Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113B	Gym Office	Baseboards	Concrete	Black	Chipping	5	N/A	N/A	0.1	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	W3	CMU	White	Flaking	12	N/A	N/A	0	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	Ceiling	Concrete	White	Flaking	6	N/A	N/A	0	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	Floor	Concrete	Grey	Chipping	10	N/A	N/A	0.1	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	Handrail	Metal	Grey	Friction	8	N/A	N/A	0	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	Risers	Metal	Grey	Chipping	4	N/A	N/A	0	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r											
		Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	Treads	Concrete	Grey	Chipping	12	N/A	N/A	0	Negative
			Gymnasium Upstairs Storeroom (former Girl's Locker Room)	Stringer	Metal	Grey	Chipping	6	N/A	N/A	0.14	Negative
1	1	113C	Gymnasium Upstairs Storeroom (former Girl's Locker Room)	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	2	200	Counselor's Office 200	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.14	Negative
1	2	200	Counselor's Office 200	W2	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	200	Counselor's Office 200	W3	CMU	White	Chipping	6	N/A	N/A	0.04	Negative
1	2	200	Counselor's Office 200	W4	CMU	White	Chipping	40	N/A	N/A	0	Negative
1	2	200	Counselor's Office 200	Ceiling	Concrete	White	Chipping	8	N/A	N/A	0.08	Negative
1	2	200	Counselor's Office 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	Univent	Metal	Brown	Chipping	6	N/A	N/A	0.17	Negative
1	2	201	Classroom 201	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Classroom 201 Storage Closet to the Left	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	201A	Classroom 201 Storage Closet to the Left	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	201A	Classroom 201 Storage Closet to the Left	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	201A	Classroom 201 Storage Closet to the Left	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	201A	Classroom 201 Storage Closet to the Left	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	2	201A	Classroom 201 Storage Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Classroom 201 Storage Closet to the Right	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	201B	Classroom 201 Storage Closet to the Right	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	201B	Classroom 201 Storage Closet to the Right	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	201B	Classroom 201 Storage Closet to the Right	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	201B	Classroom 201 Storage Closet to the Right	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	2	201B	Classroom 201 Storage Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	Univent	Metal	Brown	Chipping	6	N/A	N/A	0.17	Negative
1	2	202	Classroom 202	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Classroom 202 Storage Closet to the Left	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	202A	Classroom 202 Storage Closet to the Left	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	202A	Classroom 202 Storage Closet to the Left	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	202A	Classroom 202 Storage Closet to the Left	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	202A	Classroom 202 Storage Closet to the Left	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative
1	2	202A	Classroom 202 Storage Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202B	Classroom 202 Storage Closet to the Right	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	202B	Classroom 202 Storage Closet to the Right	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	202B	Classroom 202 Storage Closet to the Right	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	202B	Classroom 202 Storage Closet to the Right	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	202B	Classroom 202 Storage Closet to the Right	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative
1	2	202B	Classroom 202 Storage Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.06	Negative
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	Door	Wood	Yellow	Chipping	2	N/A	N/A	0.1	Negative
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	Panel Door	Metal	White	Chipping	3	N/A	N/A	0.17	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.1	Negative
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	Ceiling	Concrete	White	Flaking	6	N/A	N/A	0	Negative
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	Pipes	Metal	White	Flaking	2	N/A	N/A	0	Negative
1	2	202A	Storeroom/Staff Lounge next to Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202B	2nd Floor Staff Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202B	2nd Floor Staff Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202B	2nd Floor Staff Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202B	2nd Floor Staff Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	202B	2nd Floor Staff Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	202B	2nd Floor Staff Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	2	203	Classroom 203	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.12	Negative
1	2	203	Classroom 203	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	2	203	Classroom 203	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	2	203	Classroom 203	Univent	Metal	Brown	Chipping	4	N/A	N/A	0.18	Negative
1	2	203	Classroom 203	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	2	203	Classroom 203	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203A	Classroom 203 Closet to the Left	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	203A	Classroom 203 Closet to the Left	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	203A	Classroom 203 Closet to the Left	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	203A	Classroom 203 Closet to the Left	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	203A	Classroom 203 Closet to the Left	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	2	203A	Classroom 203 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203B	Classroom 203 Closet to the Right	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	203B	Classroom 203 Closet to the Right	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	203B	Classroom 203 Closet to the Right	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	203B	Classroom 203 Closet to the Right	W4	CMU	Green	Flaking	4	N/A	N/A	0	Negative
1	2	203B	Classroom 203 Closet to the Right	Pipe	Metal	Green	Flaking	12	N/A	N/A	0.18	Negative
1	2	203B	Classroom 203 Closet to the Right	Ceiling	Concrete	Green	None	0	N/A	N/A	N/A	N/A
1	2	203B	Classroom 203 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204	Classroom 204	Door Frame	Metal	Green	Chipping	2	N/A	N/A	0	Negative
1	2	204	Classroom 204	Door	Wood	Green	Chipping	2	N/A	N/A	0	Negative
1	2	204	Classroom 204	Cubbies	Wood	Green	Friction	4	N/A	N/A	0	Negative
1	2	204	Classroom 204	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204	Classroom 204	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204	Classroom 204	Univent/Built-in Shelves	Metal	Green	Chipping	10	N/A	N/A	0.1	Negative
1	2	204	Classroom 204	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204	Classroom 204	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204A	Classroom 204 Closet to the Left	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204A	Classroom 204 Closet to the Left	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204A	Classroom 204 Closet to the Left	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204A	Classroom 204 Closet to the Left	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204A	Classroom 204 Closet to the Left	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	2	204A	Classroom 204 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	Classroom 204 Closet to the Right	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204B	Classroom 204 Closet to the Right	W2	CMU	Green	None	0	N/A	N/A	0	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	2	204B	Classroom 204 Closet to the Right	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204B	Classroom 204 Closet to the Right	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	2	204B	Classroom 204 Closet to the Right	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	2	204B	Classroom 204 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S201	Stairwell 1 next to Classroom 204	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	S201	Stairwell 1 next to Classroom 204	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	S201	Stairwell 1 next to Classroom 204	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	S201	Stairwell 1 next to Classroom 204	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	S201	Stairwell 1 next to Classroom 204	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	S201	Stairwell 1 next to Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S201	Stairwell 1 next to Classroom 204	Stair Soffit	Metal	Brown	Chipping	4	N/A	N/A	0.23	Negative
1	2	S201	Stairwell 1 next to Classroom 204	Handrail	Metal	Brown	Friction	6	N/A	N/A	0.17	Negative
1	2	S201	Stairwell 1 next to Classroom 204	Newel Post	Metal	Brown	Friction	2	N/A	N/A	0.12	Negative
1	2	204A	Book Storage next to Stair 1	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	2	204A	Book Storage next to Stair 1	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	2	204A	Book Storage next to Stair 1	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	2	204A	Book Storage next to Stair 1	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	2	204A	Book Storage next to Stair 1	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	2	204A	Book Storage next to Stair 1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	Supply Closet across from Classroom 205	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	2	204B	Supply Closet across from Classroom 205	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	2	204B	Supply Closet across from Classroom 205	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	2	204B	Supply Closet across from Classroom 205	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	2	204B	Supply Closet across from Classroom 205	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	2	204B	Supply Closet across from Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H214	Hallway from Office 200 to Supply Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	H214	Hallway from Office 200 to Supply Closet	Door Frame	Metal	Black	Chipping	6	N/A	N/A	0.06	Negative
1	2	H214	Hallway from Office 200 to Supply Closet	Doors	Wood	Yellow	Chipping	6	N/A	N/A	0	Negative
1	2	H214	Hallway from Office 200 to Supply Closet	Pipes	Metal	White	Chipping	2	N/A	N/A	0.17	Negative
1	2	H214	Hallway from Office 200 to Supply Closet	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	H214	Hallway from Office 200 to Supply Closet	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	H214	Hallway from Office 200 to Supply Closet	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	H214	Hallway from Office 200 to Supply Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	H214	Hallway from Office 200 to Supply Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H214	Hallway from Office 200 to Supply Closet	Baseboards	Terracotta	N/A	N/A	N/A	N/A	N/A	0.02	Negative
1	2	205	Classroom 205	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	2	205	Classroom 205	Door Frame	Metal	Black	Friction	2	N/A	N/A	0.1	Negative
1	2	205	Classroom 205	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	2	205	Classroom 205	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	2	205	Classroom 205	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	2	205	Classroom 205	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	Classroom 205 Storage Closet	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	205A	Classroom 205 Storage Closet	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	205A	Classroom 205 Storage Closet	Pipe	Metal	Brown	Chipping	2	N/A	N/A	0.25	Negative
1	2	205A	Classroom 205 Storage Closet	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	205A	Classroom 205 Storage Closet	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	205A	Classroom 205 Storage Closet	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	2	205A	Classroom 205 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Staff Restroom next to Elevator	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206	Staff Restroom next to Elevator	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206	Staff Restroom next to Elevator	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206	Staff Restroom next to Elevator	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206	Staff Restroom next to Elevator	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	2	206	Staff Restroom next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206A	Office 206	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	2	206A	Office 206	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	2	206A	Office 206	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	2	206A	Office 206	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	2	206A	Office 206	Ceiling	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	206A	Office 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206B	Office 206 Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206B	Office 206 Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206B	Office 206 Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206B	Office 206 Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206B	Office 206 Restroom	Ceiling	Concrete	White	Chipping	4	N/A	N/A	0.08	Negative
1	2	206B	Office 206 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206C	Office 206 Server Room	W1	Drywall	White	Flaking	4	N/A	N/A	0	Negative
1	2	206C	Office 206 Server Room	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206C	Office 206 Server Room	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206C	Office 206 Server Room	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	206C	Office 206 Server Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	206C	Office 206 Server Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	207	Classroom 207	W1	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	207	Classroom 207	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.12	Negative
1	2	207	Classroom 207	Doors	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	2	207	Classroom 207	W2	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	207	Classroom 207	W2	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	207	Classroom 207	W3	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	207	Classroom 207	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	207	Classroom 207	Univent	Metal	Brown	Chipping	6	N/A	N/A	0.1	Negative
1	2	207	Classroom 207	W4	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	207	Classroom 207	W4	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	207	Classroom 207	Ceiling	Concrete	White	Flaking	10	N/A	N/A	0	Negative
1	2	207	Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Classroom 207 Closet to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	207A	Classroom 207 Closet to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	207A	Classroom 207 Closet to the Left	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	207A	Classroom 207 Closet to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	207A	Classroom 207 Closet to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	N/A	N/A
1	2	207A	Classroom 207 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207B	Classroom 207 Closet to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	207B	Classroom 207 Closet to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	207B	Classroom 207 Closet to the Right	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	207B	Classroom 207 Closet to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	207B	Classroom 207 Closet to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	N/A	N/A
1	2	207B	Classroom 207 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Computer Lab 208	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	W1	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.12	Negative
1	2	208	Computer Lab 208	Doors	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	W2	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	W2	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	W3	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	Univent	Metal	Brown	Chipping	6	N/A	N/A	0.1	Negative
1	2	208	Computer Lab 208	W4	CMU	White	Chipping	4	N/A	N/A	0	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	2	208	Computer Lab 208	W4	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	Ceiling	Concrete	White	Flaking	10	N/A	N/A	0	Negative
1	2	208	Computer Lab 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208A	Classroom 208 Closet to the Left	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	208A	Classroom 208 Closet to the Left	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	208A	Classroom 208 Closet to the Left	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	208A	Classroom 208 Closet to the Left	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	208A	Classroom 208 Closet to the Left	Ceiling	Concrete	Blue	None	0	N/A	N/A	N/A	N/A
1	2	208A	Classroom 208 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208B	Classroom 208 Closet to the Right	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	208B	Classroom 208 Closet to the Right	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	208B	Classroom 208 Closet to the Right	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	208B	Classroom 208 Closet to the Right	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	208B	Classroom 208 Closet to the Right	Ceiling	Concrete	Blue	None	0	N/A	N/A	N/A	N/A
1	2	208B	Classroom 208 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S202	Stairwell 2 across from Classroom 209	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	S202	Stairwell 2 across from Classroom 209	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	S202	Stairwell 2 across from Classroom 209	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	S202	Stairwell 2 across from Classroom 209	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	S202	Stairwell 2 across from Classroom 209	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	S202	Stairwell 2 across from Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S202	Stairwell 2 across from Classroom 209	Handrail	Metal	Black	Friction	12	N/A	N/A	0.2	Negative
1	2	S202	Stairwell 2 across from Classroom 209	Baluster	Metal	Black	Chipping	2	N/A	N/A	0.14	Negative
1	2	209	Classroom 209	W1	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	209	Classroom 209	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	2	209	Classroom 209	Doors	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	2	209	Classroom 209	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	2	209	Classroom 209	W2	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	209	Classroom 209	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	2	209	Classroom 209	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	209	Classroom 209	Univent	Metal	Brown	Chipping	6	N/A	N/A	0.21	Negative
1	2	209	Classroom 209	W4	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	209	Classroom 209	W4	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	209	Classroom 209	Ceiling	Concrete	White	Flaking	4	N/A	N/A	0	Negative
1	2	209	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209A	Classroom 209 Closet to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	209A	Classroom 209 Closet to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	209A	Classroom 209 Closet to the Left	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	209A	Classroom 209 Closet to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	209A	Classroom 209 Closet to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	2	209A	Classroom 209 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209B	Classroom 209 Closet to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	209B	Classroom 209 Closet to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	209B	Classroom 209 Closet to the Right	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	209B	Classroom 209 Closet to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	209B	Classroom 209 Closet to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	2	209B	Classroom 209 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	2nd Floor Girl's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	210	2nd Floor Girl's Restroom	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	2	210	2nd Floor Girl's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	210	2nd Floor Girl's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	210	2nd Floor Girl's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	210	2nd Floor Girl's Restroom	Ceiling	Concrete	White	Flaking	12	N/A	N/A	0	Negative
1	2	210	2nd Floor Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	2	210A	2nd Floor Boy's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	210A	2nd Floor Boy's Restroom	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.08	Negative
1	2	210A	2nd Floor Boy's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	210A	2nd Floor Boy's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	210A	2nd Floor Boy's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	210A	2nd Floor Boy's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	210A	2nd Floor Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210B	Custodial Closet between student restrooms	W1	CMU	White	Flaking	5	N/A	N/A	0	Negative
1	2	210B	Custodial Closet between student restrooms	W2	CMU	White	Flaking	5	N/A	N/A	0	Negative
1	2	210B	Custodial Closet between student restrooms	W3	CMU	White	Flaking	5	N/A	N/A	0	Negative
1	2	210B	Custodial Closet between student restrooms	W4	CMU	White	Flaking	5	N/A	N/A	0	Negative
1	2	210B	Custodial Closet between student restrooms	Ceiling	Concrete	White	Cracking	2	N/A	N/A	0	Negative
1	2	210B	Custodial Closet between student restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	211	Classroom 211	Door Frame	Metal	Black	Friction	1	N/A	N/A	0	Negative
1	2	211	Classroom 211	Shelf Brackets	Metal	White	Chipping	2	N/A	N/A	0.15	Negative
1	2	211	Classroom 211	W2	CMU	White	Chipping	5	N/A	N/A	0	Negative
1	2	211	Classroom 211	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	211	Classroom 211	Univent	Metal	Brown	Chipping	5	N/A	N/A	0.25	Negative
1	2	211	Classroom 211	W4	CMU	White	Chipping	5	N/A	N/A	0	Negative
1	2	211	Classroom 211	Ceiling	Concrete	White	Chipping	1	N/A	N/A	0	Negative
1	2	211	Classroom 211	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211A	Classroom 211 Closet to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	211A	Classroom 211 Closet to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	211A	Classroom 211 Closet to the Left	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	211A	Classroom 211 Closet to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	211A	Classroom 211 Closet to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	2	211A	Classroom 211 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211B	Classroom 211 Closet to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	211B	Classroom 211 Closet to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	211B	Classroom 211 Closet to the Right	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	211B	Classroom 211 Closet to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	211B	Classroom 211 Closet to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	2	211B	Classroom 211 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Classroom 212	W1	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	2	212	Classroom 212	Door Frame	Metal	Brown	Chipping	6	N/A	N/A	0.15	Negative
1	2	212	Classroom 212	Door	Wood	Yellow	Chipping	4	N/A	N/A	0	Negative
1	2	212	Classroom 212	W2	CMU	White	Chipping	1	N/A	N/A	0	Negative
1	2	212	Classroom 212	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	2	212	Classroom 212	Univent	Metal	White	Chipping	30	N/A	N/A	0.18	Negative
1	2	212	Classroom 212	Bookshelf	Metal	White	Chipping	20	N/A	N/A	0.12	Negative
1	2	212	Classroom 212	W4	CMU	White	Chipping	1	N/A	N/A	0	Negative
1	2	212	Classroom 212	Ceiling	Concrete	White	Flaking	4	N/A	N/A	0	Negative
1	2	212	Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A	Classroom 212 Closet to the Left	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	212A	Classroom 212 Closet to the Left	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	212A	Classroom 212 Closet to the Left	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	212A	Classroom 212 Closet to the Left	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	212A	Classroom 212 Closet to the Left	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative
1	2	212A	Classroom 212 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212B	Classroom 212 Closet to the Right	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	212B	Classroom 212 Closet to the Right	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	212B	Classroom 212 Closet to the Right	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	212B	Classroom 212 Closet to the Right	W4	CMU	Blue	None	0	N/A	N/A	0	Negative



			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm*2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	2	212B	Classroom 212 Closet to the Right	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative
1	2	212B	Classroom 212 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Classroom 213	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	213	Classroom 213	Door Frame	Metal	Black	Friction	1	N/A	N/A	0	Negative
1	2	213	Classroom 213	Shelf	Wood	White	Friction	2	N/A	N/A	0	Negative
1	2	213	Classroom 213	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	2	213	Classroom 213	W3	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	2	213	Classroom 213	Univent	Metal	White	Chipping	40	N/A	N/A	0.2	Negative
1	2	213	Classroom 213	Bookshelf	Metal	White	Chipping	40	N/A	N/A	0.17	Negative
1	2	213	Classroom 213	W4	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	2	213	Classroom 213	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	213	Classroom 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213A	Classroom 213 Storage to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	213A	Classroom 213 Storage to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	213A	Classroom 213 Storage to the Left	W3	CMU	Brown	Chipping	2	N/A	N/A	0	Negative
1	2	213A	Classroom 213 Storage to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	213A	Classroom 213 Storage to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	N/A	N/A
1	2	213A	Classroom 213 Storage to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213B	Classroom 213 Storage to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	213B	Classroom 213 Storage to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	213B	Classroom 213 Storage to the Right	W3	CMU	Brown	Chipping	4	N/A	N/A	0	Negative
1	2	213B	Classroom 213 Storage to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	2	213B	Classroom 213 Storage to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	N/A	N/A
1	2	213B	Classroom 213 Storage to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Classroom 214	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	2	214	Classroom 214	Door Frame	Metal	Brown	Chipping	1	N/A	N/A	0.1	Negative
1	2	214	Classroom 214	Door	Wood	Brown	Chipping	1	N/A	N/A	0	Negative
1	2	214	Classroom 214	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.04	Negative
1	2	214	Classroom 214	Door	Wood	Yellow	Chipping	1	N/A	N/A	0.12	Negative
1	2	214	Classroom 214	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	2	214	Classroom 214	W3	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	2	214	Classroom 214	Univent	Metal	Brown	Chipping	40	N/A	N/A	0.24	Negative
1	2	214	Classroom 214	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	2	214	Classroom 214	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	214	Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Classroom 214 Closet to the Left	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	214A	Classroom 214 Closet to the Left	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	214A	Classroom 214 Closet to the Left	Pipe	Metal	Blue	Chipping	2	N/A	N/A	0.2	Negative
1	2	214A	Classroom 214 Closet to the Left	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	214A	Classroom 214 Closet to the Left	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	214A	Classroom 214 Closet to the Left	Ceiling	Concrete	Blue	None	0	N/A	N/A	N/A	N/A
1	2	214A	Classroom 214 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214B	Classroom 214 Closet to the Right	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	214B	Classroom 214 Closet to the Right	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	214B	Classroom 214 Closet to the Right	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	214B	Classroom 214 Closet to the Right	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	2	214B	Classroom 214 Closet to the Right	Ceiling	Concrete	Blue	None	0	N/A	N/A	N/A	N/A
1	2	214B	Classroom 214 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S203	Stairwell 3 next to Classroom 214	W1	Terracotta	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S203	Stairwell 3 next to Classroom 214	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	2	S203	Stairwell 3 next to Classroom 214	W2	Terracotta	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S203	Stairwell 3 next to Classroom 214	W3	Terracotta	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S203	Stairwell 3 next to Classroom 214	W4	Terracotta	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S203	Stairwell 3 next to Classroom 214	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	2	S203	Stairwell 3 next to Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H213	Hallway from Classroom 205 to Classroom 213	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	H213	Hallway from Classroom 205 to Classroom 213	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	2	H213	Hallway from Classroom 205 to Classroom 213	Doors	Wood	Yellow	Chipping	4	N/A	N/A	0	Negative
1	2	H213	Hallway from Classroom 205 to Classroom 213	Pipes	Metal	White	Chipping	2	N/A	N/A	0.12	Negative
1	2	H213	Hallway from Classroom 205 to Classroom 213	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	H213	Hallway from Classroom 205 to Classroom 213	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	H213	Hallway from Classroom 205 to Classroom 213	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	2	H213	Hallway from Classroom 205 to Classroom 213	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	H213	Hallway from Classroom 205 to Classroom 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H213	Hallway from Classroom 205 to Classroom 213	Baseboards	Terracotta	N/A	N/A	N/A	N/A	N/A	0.02	Negative
1	3	300	Office 300	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	300	Office 300	W2	CMU	White	Flaking	6	N/A	N/A	0	Negative
1	3	300	Office 300	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	300	Office 300	Radiator	Metal	White	Chipping	4	N/A	N/A	0.14	Negative
1	3	300	Office 300	W4	CMU	White	Flaking	12	N/A	N/A	0	Negative
1	3	300	Office 300	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	3	300	Office 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	301	Classroom 301	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.1	Negative
1	3	301	Classroom 301	Coat Rack	Metal	Green	Friction	4	N/A	N/A	0	Negative
1	3	301	Classroom 301	Brackets	Metal	Tan	Chipping	2	N/A	N/A	0.18	Negative
1	3	301	Classroom 301	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	301	Classroom 301	Door	Wood	White	Chipping	1	N/A	N/A	0	Negative
1	3	301	Classroom 301	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	301	Classroom 301	Univent	Metal	Brown	Chipping	4	N/A	N/A	0.24	Negative
1	3	301	Classroom 301	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	301	Classroom 301	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301A	Classroom 301 Closet to the Left	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	301A	Classroom 301 Closet to the Left	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	301A	Classroom 301 Closet to the Left	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	301A	Classroom 301 Closet to the Left	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	301A	Classroom 301 Closet to the Left	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	3	301A	Classroom 301 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301B	Classroom 301 Closet to the Right	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	301B	Classroom 301 Closet to the Right	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	301B	Classroom 301 Closet to the Right	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	301B	Classroom 301 Closet to the Right	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	301B	Classroom 301 Closet to the Right	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	3	301B	Classroom 301 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302	Classroom 302	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	3	302	Classroom 302	Door	Wood	White	Chipping	2	N/A	N/A	0	Negative
1	3	302	Classroom 302	Door	Wood	Yellow	Chipping	2	N/A	N/A	0	Negative
1	3	302	Classroom 302	Coat Rack	Metal	White	Chipping	5	N/A	N/A	0.08	Negative
1	3	302	Classroom 302	Brackets	Metal	White	Chipping	1	N/A	N/A	0.15	Negative
1	3	302	Classroom 302	Shelf	Wood	White	Chipping	20	N/A	N/A	0	Negative
1	3	302	Classroom 302	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302	Classroom 302	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302	Classroom 302	Univent	Metal	White	Chipping	4	N/A	N/A	0.21	Negative
1	3	302	Classroom 302	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302	Classroom 302	Ceiling	Concrete	White	Cracking	2	N/A	N/A	0	Negative
1	3	302	Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	3	302A	Classroom 302 Closet to the Left	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302A	Classroom 302 Closet to the Left	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302A	Classroom 302 Closet to the Left	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302A	Classroom 302 Closet to the Left	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302A	Classroom 302 Closet to the Left	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	3	302A	Classroom 302 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302B	Classroom 302 Closet to the Right	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302B	Classroom 302 Closet to the Left	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302B	Classroom 302 Closet to the Left	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302B	Classroom 302 Closet to the Left	Shelf	Wood	White	Friction	2	N/A	N/A	0	Negative
1	3	302B	Classroom 302 Closet to the Left	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	302B	Classroom 302 Closet to the Left	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	3	302B	Classroom 302 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302B	Storeroom/Staff Lounge next to Classroom 302	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	302B	Storeroom/Staff Lounge next to Classroom 302	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	302B	Storeroom/Staff Lounge next to Classroom 302	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	302B	Storeroom/Staff Lounge next to Classroom 302	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	302B	Storeroom/Staff Lounge next to Classroom 302	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	302B	Storeroom/Staff Lounge next to Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302C	3rd Floor Staff Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	302C	3rd Floor Staff Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	302C	3rd Floor Staff Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	302C	3rd Floor Staff Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	302C	3rd Floor Staff Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	302C	3rd Floor Staff Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	3	303	Library 303	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	303	Library 303	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	303	Library 303	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	303	Library 303	Univent	Metal	White	Chipping	2	N/A	N/A	0.18	Negative
1	3	303	Library 303	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	303	Library 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Library 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303A	Library Closet	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	303A	Library Closet	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	303A	Library Closet	Brackets	Wood	White	Chipping	1	N/A	N/A	0	Negative
1	3	303A	Library Closet	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	303A	Library Closet	Pipe	Metal	White	Chipping	2	N/A	N/A	0.17	Negative
1	3	303A	Library Closet	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	303A	Library Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	303A	Library Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304	Classroom 304	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	3	304	Classroom 304	Door	Wood	White	Chipping	1	N/A	N/A	0	Negative
1	3	304	Classroom 304	Door	Wood	Yellow	Chipping	1	N/A	N/A	0	Negative
1	3	304	Classroom 304	Cabinets	Wood	Black	Chipping	4	N/A	N/A	0	Negative
1	3	304	Classroom 304	Brackets	Metal	Green	Chipping	1	N/A	N/A	0.2	Negative
1	3	304	Classroom 304	Brackets	Metal	Tan	Chipping	1	N/A	N/A	0.1	Negative
1	3	304	Classroom 304	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304	Classroom 304	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304	Classroom 304	Univent	Metal	Brown	Chipping	4	N/A	N/A	0.23	Negative
1	3	304	Classroom 304	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304	Classroom 304	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304C	Classroom 304 Closet to the Left	W1	CMU	Green	None	0	N/A	N/A	0	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	3	304C	Classroom 304 Closet to the Left	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	304C	Classroom 304 Closet to the Left	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	304C	Classroom 304 Closet to the Left	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	304C	Classroom 304 Closet to the Left	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	3	304C	Classroom 304 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304D	Classroom 304 Closet to the Right	W1	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	304D	Classroom 304 Closet to the Right	W2	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	304D	Classroom 304 Closet to the Right	W3	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	304D	Classroom 304 Closet to the Right	W4	CMU	Green	None	0	N/A	N/A	0	Negative
1	3	304D	Classroom 304 Closet to the Right	Ceiling	Concrete	Green	None	0	N/A	N/A	0	Negative
1	3	304D	Classroom 304 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304A	Book Closet next to Stair 1	W1	CMU	White	None	0	N/A	N/A	0	N/A
1	3	304A	Book Closet next to Stair 1	Door Frame	Metal	White	Chipping	1	N/A	N/A	0.15	Negative
1	3	304A	Book Closet next to Stair 1	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304A	Book Closet next to Stair 1	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304A	Book Closet next to Stair 1	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304A	Book Closet next to Stair 1	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	3	304A	Book Closet next to Stair 1	Floor	N/A	White	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304A	Book Closet next to Stair 1	Door Frame	Metal	White	Chipping	1	N/A	N/A	0.12	Negative
1	3	304B	Supply Closet next to Book Closet	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304B	Supply Closet next to Book Closet	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304B	Supply Closet next to Book Closet	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304B	Supply Closet next to Book Closet	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	304B	Supply Closet next to Book Closet	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	3	304B	Supply Closet next to Book Closet	Floor	N/A	White	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S301	Stairwell 1 next to Classroom 304	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	S301	Stairwell 1 next to Classroom 304	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	S301	Stairwell 1 next to Classroom 304	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0.1	Negative
1	3	S301	Stairwell 1 next to Classroom 304	Door	Metal	Brown	Chipping	4	N/A	N/A	0	Negative
1	3	S301	Stairwell 1 next to Classroom 304	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	S301	Stairwell 1 next to Classroom 304	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	S301	Stairwell 1 next to Classroom 304	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	S301	Stairwell 1 next to Classroom 304	Floor	N/A	White	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H314	Hallway between Office 300 to Supply Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	H314	Hallway between Office 300 to Supply Closet	W2	CMU	White	Chipping	20	N/A	N/A	0	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Door Frames	Metal	Black	Chipping	6	N/A	N/A	0.12	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Doors	Wood	Yellow	Chipping	12	N/A	N/A	0.05	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Radiators	Metal	Grey	Chipping	6	N/A	N/A	0.2	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Conduit	Metal	White	Chipping	4	N/A	N/A	0.25	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Pipes	Metal	White	Chipping	10	N/A	N/A	0.11	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0.15	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Door	Metal	Brown	Chipping	4	N/A	N/A	0.08	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	W4	CMU	White	Chipping	20	N/A	N/A	0	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Door Frames	Metal	Black	Chipping	6	N/A	N/A	0.09	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Doors	Wood	Yellow	Chipping	12	N/A	N/A	0.12	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Radiators	Metal	Grey	Chipping	6	N/A	N/A	0.08	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Conduit	Metal	White	Chipping	1	N/A	N/A	0.2	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Pipes	Metal	White	Chipping	1	N/A	N/A	0.1	Negative
1	3	H314	Hallway between Office 300 to Supply Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	H314	Hallway between Office 300 to Supply Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	305	Classroom 305	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	305	Classroom 305	W3	CMU	White	None	0	N/A	N/A	0	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	3	305	Classroom 305	Univent	Metal	White	Chipping	4	N/A	N/A	0.19	Negative
1	3	305	Classroom 305	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	305	Classroom 305	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Book Closet next to Elevator	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	306A	Book Closet next to Elevator	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	306A	Book Closet next to Elevator	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	306A	Book Closet next to Elevator	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	306A	Book Closet next to Elevator	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	306A	Book Closet next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Storeroom/Faculty Men's Lounge	W1	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	3	306	Storeroom/Faculty Men's Lounge	Door Frame	Metal	Black	Metal	1	N/A	N/A	0.16	Negative
1	3	306	Storeroom/Faculty Men's Lounge	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	3	306	Storeroom/Faculty Men's Lounge	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0	Negative
1	3	306	Storeroom/Faculty Men's Lounge	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	306	Storeroom/Faculty Men's Lounge	Radiator	Metal	White	Chipping	4	N/A	N/A	0.22	Negative
1	3	306	Storeroom/Faculty Men's Lounge	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	306	Storeroom/Faculty Men's Lounge	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Storeroom/Faculty Men's Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306B	Faculty Men's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	306B	Faculty Men's Restroom	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.1	Negative
1	3	306B	Faculty Men's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	306B	Faculty Men's Restroom	Pipe Chase Door	Metal	White	Chipping	2	N/A	N/A	0.21	Negative
1	3	306B	Faculty Men's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	306B	Faculty Men's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	306B	Faculty Men's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	306B	Faculty Men's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307	Classroom 307	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0.16	Negative
1	3	307	Classroom 307	Doors	Wood	White	Chipping	4	N/A	N/A	0.06	Negative
1	3	307	Classroom 307	Panel	Metal	White	Chipping	1	N/A	N/A	0.22	Negative
1	3	307	Classroom 307	Shelf Brackets	Metal	White	Chipping	2	N/A	N/A	0.1	Negative
1	3	307	Classroom 307	Coat Rack	Metal	White	Chipping	2	N/A	N/A	0	Negative
1	3	307	Classroom 307	Shelves	Wood	White	Friction	5	N/A	N/A	0	Negative
1	3	307	Classroom 307	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307	Classroom 307	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307	Classroom 307	Univent	Metal	White	Chipping	2	N/A	N/A	0	Negative
1	3	307	Classroom 307	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307	Classroom 307	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307A	Classroom 307 Closet to the Left	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307A	Classroom 307 Closet to the Left	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307A	Classroom 307 Closet to the Left	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307A	Classroom 307 Closet to the Left	Shelf	Wood	White	Friction	2	N/A	N/A	0	Negative
1	3	307A	Classroom 307 Closet to the Left	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307A	Classroom 307 Closet to the Left	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	3	307A	Classroom 307 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307B	Classroom 307 Closet to the Right	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307B	Classroom 307 Closet to the Right	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307B	Classroom 307 Closet to the Right	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307B	Classroom 307 Closet to the Right	Shelf	Wood	White	Friction	2	N/A	N/A	0	Negative
1	3	307B	Classroom 307 Closet to the Right	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	307B	Classroom 307 Closet to the Right	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	3	307B	Classroom 307 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21		Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell		William Dick Elementary School								
			Inspection Company: Synertech		2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	
1	3	308	Classroom 308	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative	
1	3	308	Classroom 308	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative	
1	3	308	Classroom 308	Doors	Wood	White	Chipping	2	N/A	N/A	0	Negative	
1	3	308	Classroom 308	Air Vent	Metal	Blue	Chipping	1	N/A	N/A	0.1	Negative	
1	3	308	Classroom 308	Brackets	Metal	Tan	Chipping	1	N/A	N/A	0.08	Negative	
1	3	308	Classroom 308	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative	
1	3	308	Classroom 308	W3	CMU	White	Chipping	5	N/A	N/A	0	Negative	
1	3	308	Classroom 308	Univent	Metal	Brown	Chipping	4	N/A	N/A	0.19	Negative	
1	3	308	Classroom 308	W4	CMU	White	Chipping	2	N/A	N/A	0	Negative	
1	3	308	Classroom 308	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative	
1	3	308	Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	308A	Classroom 308 Closet to the Left	W1	CMU	Blue	None	0	N/A	N/A	0	Negative	
1	3	308A	Classroom 308 Closet to the Left	W2	CMU	Blue	None	0	N/A	N/A	0	Negative	
1	3	308A	Classroom 308 Closet to the Left	W3	CMU	Blue	None	0	N/A	N/A	0	Negative	
1	3	308A	Classroom 308 Closet to the Left	W4	CMU	Blue	None	0	N/A	N/A	0	Negative	
1	3	308A	Classroom 308 Closet to the Left	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative	
1	3	308A	Classroom 308 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	308B	Classroom 308 Closet to the Right	W1	CMU	Blue	None	0	N/A	N/A	0	Negative	
1	3	308B	Classroom 308 Closet to the Right	W2	CMU	Blue	None	0	N/A	N/A	0	Negative	
1	3	308B	Classroom 308 Closet to the Right	W3	CMU	Blue	None	0	N/A	N/A	0	Negative	
1	3	308B	Classroom 308 Closet to the Right	W4	CMU	Blue	None	0	N/A	N/A	0	Negative	
1	3	308B	Classroom 308 Closet to the Right	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative	
1	3	308B	Classroom 308 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	S302	Stairwell 2 next to Classroom 308	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	
1	3	S302	Stairwell 2 next to Classroom 308	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	
1	3	S302	Stairwell 2 next to Classroom 308	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	
1	3	S302	Stairwell 2 next to Classroom 308	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	
1	3	S302	Stairwell 2 next to Classroom 308	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	
1	3	S302	Stairwell 2 next to Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	S302	Stairwell 2 next to Classroom 308	Handrail	Metal	Black	Friction	12	N/A	N/A	0.2	Negative	
1	3	S302	Stairwell 2 next to Classroom 308	Baluster	Metal	Black	Chipping	2	N/A	N/A	0.14	Negative	
1	3	309	Classroom 309	W1	CMU	White	None	0	N/A	N/A	0	Negative	
1	3	309	Classroom 309	W2	CMU	White	None	0	N/A	N/A	0	Negative	
1	3	309	Classroom 309	W3	CMU	White	Chipping	12	N/A	N/A	0	Negative	
1	3	309	Classroom 309	Univent	Metal	White	Chipping	4	N/A	N/A	0.1	Negative	
1	3	309	Classroom 309	W4	CMU	White	None	0	N/A	N/A	0	Negative	
1	3	309	Classroom 309	Ceiling	Concrete	White	Chipping	12	N/A	N/A	0	Negative	
1	3	309	Classroom 309	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	309A	Classroom 309 Closet to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative	
1	3	309A	Classroom 309 Closet to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative	
1	3	309A	Classroom 309 Closet to the Left	W3	CMU	Brown	None	0	N/A	N/A	0	Negative	
1	3	309A	Classroom 309 Closet to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative	
1	3	309A	Classroom 309 Closet to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative	
1	3	309A	Classroom 309 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	309B	Classroom 309 Closet to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative	
1	3	309B	Classroom 309 Closet to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative	
1	3	309B	Classroom 309 Closet to the Right	W3	CMU	Brown	None	0	N/A	N/A	0	Negative	
1	3	309B	Classroom 309 Closet to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative	
1	3	309B	Classroom 309 Closet to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative	
1	3	309B	Classroom 309 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	310	3rd Floor Boy's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	
1	3	310	3rd Floor Boy's Restroom	Door	Metal	Grey	Chipping	1	N/A	N/A	0	Negative	
1	3	310	3rd Floor Boy's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	
1	3	310	3rd Floor Boy's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	3	310	3rd Floor Boy's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	310	3rd Floor Boy's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	310	3rd Floor Boy's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	3	310	3rd Floor Boy's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	310A	3rd Floor Girl's Restroom	Door	Metal	Black	Chipping	1	N/A	N/A	0.12	Negative
1	3	310A	3rd Floor Girl's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	310A	3rd Floor Girl's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	310A	3rd Floor Girl's Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	310A	3rd Floor Girl's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	310A	3rd Floor Girl's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	3	311	Classroom 311	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	311	Classroom 311	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	311	Classroom 311	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	311	Classroom 311	Radiator	Metal	Brown	Chipping	4	N/A	N/A	0.12	Negative
1	3	311	Classroom 311	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	311	Classroom 311	Ceiling	Concrete	White	Chipping	6	N/A	N/A	0	Negative
1	3	311	Classroom 311	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	311A	Classroom 311 Closet to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	311A	Classroom 311 Closet to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	311A	Classroom 311 Closet to the Left	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	311A	Classroom 311 Closet to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	311A	Classroom 311 Closet to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	3	311A	Classroom 311 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	311B	Classroom 311 Closet to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	311B	Classroom 311 Closet to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	311B	Classroom 311 Closet to the Right	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	311B	Classroom 311 Closet to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	311B	Classroom 311 Closet to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	3	311B	Classroom 311 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312	Classroom 312	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	312	Classroom 312	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	312	Classroom 312	W3	CMU	White	Chipping	12	N/A	N/A	0	Negative
1	3	312	Classroom 312	Univent	Metal	Brown	Chipping	6	N/A	N/A	0.18	Negative
1	3	312	Classroom 312	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	312	Classroom 312	Ceiling	Concrete	White	Chipping	12	N/A	N/A	0.1	Negative
1	3	312	Classroom 312	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312A	Classroom 312 Closet to the Left	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	312A	Classroom 312 Closet to the Left	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	312A	Classroom 312 Closet to the Left	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	312A	Classroom 312 Closet to the Left	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	312A	Classroom 312 Closet to the Left	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative
1	3	312A	Classroom 312 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	312B	Classroom 312 Closet to the Right	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	312B	Classroom 312 Closet to the Right	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	312B	Classroom 312 Closet to the Right	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	312B	Classroom 312 Closet to the Right	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	312B	Classroom 312 Closet to the Right	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative
1	3	312B	Classroom 312 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	313	Classroom 313	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	313	Classroom 313	Air Vent	Metal	Blue	Chipping	1	N/A	N/A	0.4	Negative
1	3	313	Classroom 313	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	313	Classroom 313	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	313	Classroom 313	Univent	Metal	Brown	Chipping	4	N/A	N/A	0.2	Negative
1	3	313	Classroom 313	W4	CMU	White	None	0	N/A	N/A	0	Negative

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	3	313	Classroom 313	Ceiling	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	3	313	Classroom 313	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	313A	Classroom 313 Closet to the Left	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	313A	Classroom 313 Closet to the Left	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	313A	Classroom 313 Closet to the Left	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	313A	Classroom 313 Closet to the Left	Pipe	Metal	Blue	Chipping	4	N/A	N/A	0.2	Negative
1	3	313A	Classroom 313 Closet to the Left	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	313A	Classroom 313 Closet to the Left	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative
1	3	313A	Classroom 313 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	313B	Classroom 313 Closet to the Right	W1	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	313B	Classroom 313 Closet to the Right	W2	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	313B	Classroom 313 Closet to the Right	W3	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	313B	Classroom 313 Closet to the Right	W4	CMU	Blue	None	0	N/A	N/A	0	Negative
1	3	313B	Classroom 313 Closet to the Right	Ceiling	Concrete	Blue	None	0	N/A	N/A	0	Negative
1	3	313B	Classroom 313 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	314	Classroom 314	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	3	314	Classroom 314	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	3	314	Classroom 314	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	3	314	Classroom 314	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	3	314	Classroom 314	Ceiling	Concrete	White	Chipping	0	N/A	N/A	0	Negative
1	3	314	Classroom 314	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	314A	Classroom 314 Closet to the Left	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	314A	Classroom 314 Closet to the Left	Door Frame	Metal	Black	Chipping	1	N/A	N/A	0.13	Negative
1	3	314A	Classroom 314 Closet to the Left	Door	Wood	White	Chipping	2	N/A	N/A	0.06	Negative
1	3	314A	Classroom 314 Closet to the Left	Air Vent	Metal	Brown	Chipping	1	N/A	N/A	0.3	Negative
1	3	314A	Classroom 314 Closet to the Left	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	314A	Classroom 314 Closet to the Left	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	314A	Classroom 314 Closet to the Left	Univent/Shelves	Metal	Brown	Chipping	12	N/A	N/A	0.16	Negative
1	3	314A	Classroom 314 Closet to the Left	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	314A	Classroom 314 Closet to the Left	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	3	314A	Classroom 314 Closet to the Left	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	314B	Classroom 314 Closet to the Right	W1	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	314B	Classroom 314 Closet to the Right	W2	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	314B	Classroom 314 Closet to the Right	W3	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	314B	Classroom 314 Closet to the Right	W4	CMU	Brown	None	0	N/A	N/A	0	Negative
1	3	314B	Classroom 314 Closet to the Right	Ceiling	Concrete	Brown	None	0	N/A	N/A	0	Negative
1	3	314B	Classroom 314 Closet to the Right	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S303	Stairwell 3 next to Classroom 314	W1	Terracotta	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S303	Stairwell 3 next to Classroom 314	Door Frame	Metal	Black	Chipping	2	N/A	N/A	0	Negative
1	3	S303	Stairwell 3 next to Classroom 314	W2	Terracotta	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S303	Stairwell 3 next to Classroom 314	W3	Terracotta	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S303	Stairwell 3 next to Classroom 314	W4	Terracotta	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S303	Stairwell 3 next to Classroom 314	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	S303	Stairwell 3 next to Classroom 314	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H313	Hallway from Classroom 305 to Classroom 313	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	3	H313	Hallway from Classroom 305 to Classroom 313	Door Frames	Metal	Black	Chipping	6	N/A	N/A	0.1	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Doors	Wood	Yellow	Chipping	12	N/A	N/A	0	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Radiators	Metal	Grey	Chipping	6	N/A	N/A	0.16	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Conduit	Metal	White	Chipping	4	N/A	N/A	0.2	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Pipes	Metal	White	Chipping	10	N/A	N/A	0.15	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	W2	CMU	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H313	Hallway from Classroom 305 to Classroom 313	W3	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Radiators	Metal	Grey	Chipping	6	N/A	N/A	0.1	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Conduit	Metal	White	Chipping	1	N/A	N/A	0.2	Negative



			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	3	H313	Hallway from Classroom 305 to Classroom 313	Pipes	Metal	White	Chipping	1	N/A	N/A	0.1	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Door	Metal	Brown	Chipping	4	N/A	N/A	0.1	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	W4	CMU	White	Chipping	20	N/A	N/A	0	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Door Frames	Metal	Black	Chipping	6	N/A	N/A	0	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Doors	Wood	Yellow	Chipping	12	N/A	N/A	0.1	Negative
1	3	H313	Hallway from Classroom 305 to Classroom 313	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	3	H313	Hallway from Classroom 305 to Classroom 313	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	4	Boiler Room	W1	CMU	White	Flaking	400	N/A	N/A	0.9	Positive
1	B	4	Boiler Room	W1	CMU	Green	Flaking	200	N/A	N/A	3.1	Positive
1	B	4	Boiler Room	W1	Concrete	White	Flaking	120	N/A	N/A	2.2	Positive
1	B	4	Boiler Room	W1	Concrete	Green	Flaking	120	N/A	N/A	2.5	Positive
1	B	4	Boiler Room	Door Frame	Metal	Blue	Flaking	6	N/A	N/A	0.2	Negative
1	B	4	Boiler Room	Door	Wood	Blue	Flaking	6	N/A	N/A	0.15	Negative
1	B	4	Boiler Room	Electric Panel	Metal	Grey	Flaking	20	N/A	N/A	0.32	Negative
1	B	4	Boiler Room	Crawl Space Access Door	Metal	Grey	Flaking	4	N/A	N/A	0.17	Negative
1	B	4	Boiler Room	Conduit	Metal	Grey	Flaking	10	N/A	N/A	0.26	Negative
1	B	4	Boiler Room	Stair Stringer	Metal	Grey	Flaking	8	N/A	N/A	1.7	Positive
1	B	4	Boiler Room	Handrail	Metal	Grey	Flaking	12	N/A	N/A	1.4	Positive
1	B	4	Boiler Room	W2	CMU	White	Flaking	200	N/A	N/A	2.6	Positive
1	B	4	Boiler Room	W2	CMU	Green	Flaking	150	N/A	N/A	4.2	Positive
1	B	4	Boiler Room	W2	Concrete	White	Flaking	100	N/A	N/A	1.9	Positive
1	B	4	Boiler Room	W2	Concrete	Green	Flaking	50	N/A	N/A	2.8	Positive
1	B	4	Boiler Room	Electric Panel	Metal	Grey	Flaking	20	N/A	N/A	0.22	Negative
1	B	4	Boiler Room	Furnace Door	Metal	Grey	Flaking	2	N/A	N/A	3.1	Positive
1	B	4	Boiler Room	W3	CMU	White	Flaking	100	N/A	N/A	2.6	Positive
1	B	4	Boiler Room	W3	CMU	Green	Flaking	150	N/A	N/A	1.9	Positive
1	B	4	Boiler Room	W3	Concrete	White	Flaking	50	N/A	N/A	4	Positive
1	B	4	Boiler Room	W3	Concrete	Green	Flaking	100	N/A	N/A	3.1	Positive
1	B	4	Boiler Room	Stairs	Metal	Grey	Flaking	20	N/A	N/A	2.1	Positive
1	B	4	Boiler Room	W4	CMU	White	Flaking	100	N/A	N/A	1.5	Positive
1	B	4	Boiler Room	W4	CMU	Green	Flaking	200	N/A	N/A	2.9	Positive
1	B	4	Boiler Room	W4	Concrete	White	Flaking	100	N/A	N/A	1.6	Positive
1	B	4	Boiler Room	W4	Concrete	Green	Flaking	200	N/A	N/A	3.2	Positive
1	B	4	Boiler Room	Ceiling	Concrete	White	Flaking	800	N/A	N/A	1.2	Positive
1	B	4	Boiler Room	Pipes	Metal	White	Flaking	100	N/A	N/A	0.4	Negative
1	B	4	Boiler Room	Floor	Concrete	Grey	Flaking	200	N/A	N/A	0.36	Negative
1	B	2	Former Coal Room	W1	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	2	Former Coal Room	W2	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	2	Former Coal Room	W3	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	2	Former Coal Room	W4	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	2	Former Coal Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	2	Former Coal Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Pump Room	W1	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Pump Room	W2	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Pump Room	W3	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Pump Room	W4	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Pump Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Pump Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	3	Boiler Room Office (Former Building Engineer's Office)	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Door Frame	Metal	White	Chipping	4	N/A	N/A	0.2	Negative
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Door	Wood	White	Chipping	4	N/A	N/A	0.1	Negative
1	B	3	Boiler Room Office (Former Building Engineer's Office)	W2	Concrete	White	Flaking	18	N/A	N/A	1.9	Positive

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm*2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Radiator	Metal	White	Flaking	2	N/A	N/A	0.31	Negative
1	B	3	Boiler Room Office (Former Building Engineer's Office)	W3	Concrete	White	Flaking	18	N/A	N/A	2.1	Positive
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Conduit	Metal	White	Chipping	2	N/A	N/A	0.19	Negative
1	B	3	Boiler Room Office (Former Building Engineer's Office)	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Door Frame	Metal	White	Chipping	2	N/A	N/A	0.16	Negative
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Door	Wood	White	Chipping	2	N/A	N/A	0.2	Negative
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Ceiling	Concrete	White	Flaking	90	N/A	N/A	0.45	Negative
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Pipes	Metal	White	Flaking	30	N/A	N/A	0.26	Negative
1	B	3	Boiler Room Office (Former Building Engineer's Office)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	3A	Boiler Room Restroom	W1	Brick	White	None	0	N/A	N/A	N/A	N/A
1	B	3A	Boiler Room Restroom	Door Frame	Metal	White	Friction	4	N/A	N/A	0.17	Negative
1	B	3A	Boiler Room Restroom	W2	Brick	White	Flaking	1	N/A	N/A	0.1	Negative
1	B	3A	Boiler Room Restroom	W3	Brick	White	Flaking	12	N/A	N/A	0.2	Negative
1	B	3A	Boiler Room Restroom	W4	Brick	White	Chipping	2	N/A	N/A	0.2	Negative
1	B	3A	Boiler Room Restroom	Ceiling	Concrete	White	Flaking	12	N/A	N/A	0.25	Negative
1	B	3A	Boiler Room Restroom	Pipe	Metal	White	Flaking	6	N/A	N/A	0.23	Negative
1	B	3A	Boiler Room Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	B	H02	Hallway from Boiler Room to Electrical Room	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	H02	Hallway from Boiler Room to Electrical Room	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	H02	Hallway from Boiler Room to Electrical Room	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	H02	Hallway from Boiler Room to Electrical Room	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	H02	Hallway from Boiler Room to Electrical Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H02	Hallway from Boiler Room to Electrical Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	7	Storage Cage	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	7	Storage Cage	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	7	Storage Cage	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	7	Storage Cage	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	7	Storage Cage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	7	Storage Cage	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Custodial Closet	W1	CMU	Green	Chipping	6	N/A	N/A	0	Negative
1	B	8	Custodial Closet	W2	CMU	Green	Chipping	12	N/A	N/A	0	Negative
1	B	8	Custodial Closet	W3	CMU	Green	Chipping	6	N/A	N/A	0	Negative
1	B	8	Custodial Closet	W4	CMU	Green	Chipping	12	N/A	N/A	0	Negative
1	B	8	Custodial Closet	Ceiling	Concrete	White	Cracking	1	N/A	N/A	0	Negative
1	B	8	Custodial Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	13	Electrical Room next to Building Engineer's Office	W1	Brick	White	Flaking	20	N/A	N/A	0	Negative
1	B	13	Electrical Room next to Building Engineer's Office	W1	Brick	Green	Flaking	20	N/A	N/A	0	Negative
1	B	13	Electrical Room next to Building Engineer's Office	Door Frame	Metal	Green	Chipping	2	N/A	N/A	0.1	Negative
1	B	13	Electrical Room next to Building Engineer's Office	Door	Metal	Green	Chipping	2	N/A	N/A	0.1	Negative
1	B	13	Electrical Room next to Building Engineer's Office	W2	Brick	White	Flaking	4	N/A	N/A	0	Negative
1	B	13	Electrical Room next to Building Engineer's Office	W2	Brick	Green	Flaking	4	N/A	N/A	0	Negative
1	B	13	Electrical Room next to Building Engineer's Office	W3	Brick	White	Chipping	4	N/A	N/A	0	Negative
1	B	13	Electrical Room next to Building Engineer's Office	W3	Brick	Green	Chipping	4	N/A	N/A	0	Negative
1	B	13	Electrical Room next to Building Engineer's Office	W4	Brick	White	Chipping	4	N/A	N/A	0	Negative
1	B	13	Electrical Room next to Building Engineer's Office	W4	Brick	Green	Chipping	4	N/A	N/A	0	Negative
1	B	13	Electrical Room next to Building Engineer's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	B	13	Electrical Room next to Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	12	Building Engineer's Office	W1	CMU	White	Flaking	2	N/A	N/A	0	Negative
1	B	12	Building Engineer's Office	Door Frame	Metal	White	Chipping	2	N/A	N/A	0.1	Negative
1	B	12	Building Engineer's Office	Door	Metal	White	Chipping	2	N/A	N/A	0.12	Negative
1	B	12	Building Engineer's Office	Pipe	Metal	White	Chipping	2	N/A	N/A	0.27	Negative
1	B	12	Building Engineer's Office	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	12	Building Engineer's Office	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	12	Building Engineer's Office	W4	CMU	White	None	0	N/A	N/A	N/A	N/A

			Inspection Dates: 6/30/21	Lead-Safe Certification Assessment Report								
			Name of Inspector: Ryan Hutsell	William Dick Elementary School								
			Inspection Company: Synertech	2498 W Diamond St, Philadelphia, PA 19121								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Lead Concentration ug/cm^2	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)
1	B	12	Building Engineer's Office	Ceiling	Concrete	White	Flaking	1	N/A	N/A	0	Negative
1	B	12	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	008B	Storeroom across from Building Engineer's Office	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	B	008B	Storeroom across from Building Engineer's Office	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	B	008B	Storeroom across from Building Engineer's Office	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	B	008B	Storeroom across from Building Engineer's Office	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	B	008B	Storeroom across from Building Engineer's Office	Ceiling	Concrete	White	None	0	N/A	N/A	0	Negative
1	B	008B	Storeroom across from Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	10	Kitchen	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	B	10	Kitchen	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0.1	Negative
1	B	10	Kitchen	Door	Metal	Brown	Chipping	2	N/A	N/A	0.2	Negative
1	B	10	Kitchen	W2	CMU	White	Chipping	2	N/A	N/A	0	Negative
1	B	10	Kitchen	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0.1	Negative
1	B	10	Kitchen	Door	Metal	Brown	Chipping	2	N/A	N/A	0.2	Negative
1	B	10	Kitchen	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	10	Kitchen	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	10	Kitchen	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	B	10	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010A	Kitchen Storeroom on exterior wall	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	010A	Kitchen Storeroom on exterior wall	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	010A	Kitchen Storeroom on exterior wall	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	010A	Kitchen Storeroom on exterior wall	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	010A	Kitchen Storeroom on exterior wall	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	B	010A	Kitchen Storeroom on exterior wall	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	Kitchen Storeroom on Cafeteria side	W1	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	010B	Kitchen Storeroom on Cafeteria side	W2	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	010B	Kitchen Storeroom on Cafeteria side	W3	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	010B	Kitchen Storeroom on Cafeteria side	W4	CMU	White	None	0	N/A	N/A	N/A	N/A
1	B	010B	Kitchen Storeroom on Cafeteria side	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	B	010B	Kitchen Storeroom on Cafeteria side	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	012A	Cafeteria	W1	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	B	012A	Cafeteria	Pipe	Metal	White	Chipping	4	N/A	N/A	0	Negative
1	B	012A	Cafeteria	Vent Grille	Metal	Green	Chipping	1	N/A	N/A	0	Negative
1	B	012A	Cafeteria	Bench	Metal	White	Chipping	54	N/A	N/A	0.56	Negative
1	B	012A	Cafeteria	W2	CMU	White	Chipping	4	N/A	N/A	0	Negative
1	B	012A	Cafeteria	Door Frame	Metal	Brown	Chipping	2	N/A	N/A	0.1	Negative
1	B	012A	Cafeteria	Door	Metal	Brown	Chipping	2	N/A	N/A	0.14	Negative
1	B	012A	Cafeteria	Vent Grille	Metal	Brown	Chipping	2	N/A	N/A	0.26	Negative
1	B	012A	Cafeteria	W3	CMU	White	Chipping	5	N/A	N/A	0	Negative
1	B	012A	Cafeteria	W4	CMU	White	Chipping	6	N/A	N/A	0	Negative
1	B	012A	Cafeteria	Bench	Metal	White	Chipping	54	N/A	N/A	0.5	Negative
1	B	012A	Cafeteria	Ceiling	Concrete	White	Flaking	200	N/A	N/A	0.04	Negative
1	B	012A	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01	Hallway from Elevator to Cafeteria	W1	CMU	White	None	0	N/A	N/A	0	Negative
1	B	H01	Hallway from Elevator to Cafeteria	W2	CMU	White	None	0	N/A	N/A	0	Negative
1	B	H01	Hallway from Elevator to Cafeteria	W3	CMU	White	None	0	N/A	N/A	0	Negative
1	B	H01	Hallway from Elevator to Cafeteria	W4	CMU	White	None	0	N/A	N/A	0	Negative
1	B	H01	Hallway from Elevator to Cafeteria	Ceiling	Concrete	White	Chipping	2	N/A	N/A	0	Negative
1	B	H01	Hallway from Elevator to Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A