

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	G	Boiler Room	W1	Concrete	White/Gray	Flaking	65	0.1	Negative
1	G	Boiler Room	W1	Metal	Blue	None	0	N/A	N/A
1	G	Boiler Room	W2	Concrete	White/Gray	Flaking	70	-0.3	Negative
1	G	Boiler Room	W3	Concrete	White/Gray	Flaking	115	0	Negative
1	G	Boiler Room	W4	Concrete	White/Gray	Flaking	100	-0.4	Negative
1	G	Boiler Room	Ceiling	Concrete	Gray	None	0	N/A	N/A
1	G	Boiler Room	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Back Stairwell in Boiler Room	W1	Concrete	Green/White	None	0	N/A	N/A
1	G	Back Stairwell in Boiler Room	W2	Concrete	Green/White	None	0	N/A	N/A
1	G	Back Stairwell in Boiler Room	W2	Metal	Blue	None	0	N/A	N/A
1	G	Back Stairwell in Boiler Room	W3	Concrete	Green/White	Flaking	60	0.1	Negative
1	G	Back Stairwell in Boiler Room	W4	Concrete	Green/White	Flaking	130	0.1	Negative
1	G	Back Stairwell in Boiler Room	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Back Stairwell in Boiler Room	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Hallway from Cafeteria to Boiler Room	W1	Concrete	White	None	0	N/A	N/A
1	G	Hallway from Cafeteria to Boiler Room	W1	Metal	Gray/Blue	None	0	N/A	N/A
1	G	Hallway from Cafeteria to Boiler Room	W2	Concrete	White	None	0	N/A	N/A
1	G	Hallway from Cafeteria to Boiler Room	W3	Concrete	White	None	0	N/A	N/A
1	G	Hallway from Cafeteria to Boiler Room	W4	Concrete	White	Flaking	10	-0.3	Negative
1	G	Hallway from Cafeteria to Boiler Room	Ceiling	Concrete	White	Flaking	25	0.1	Negative
1	G	Hallway from Cafeteria to Boiler Room	Floor	Concrete	Black	None	0	N/A	N/A
1	G	Gymnasium	W1	Concrete	White	None	0	N/A	N/A
1	G	Gymnasium	W1	Metal	Brown/Gray	None	0	N/A	N/A
1	G	Gymnasium	W2	Concrete	White	None	0	N/A	N/A
1	G	Gymnasium	W3	Concrete	White	Flaking	15	-0.4	Negative
1	G	Gymnasium	W4	Concrete	White	None	0	N/A	N/A
1	G	Gymnasium	Ceiling	Wood	White	None	0	N/A	N/A
1	G	Gymnasium	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	G	"Girl's Dressing" Room in Gym	W1	Concrete	Green	None	0	N/A	N/A
1	G	"Girl's Dressing" Room in Gym	W1	Metal	White	None	0	N/A	N/A
1	G	"Girl's Dressing" Room in Gym	W2	Concrete	Green	None	0	N/A	N/A
1	G	"Girl's Dressing" Room in Gym	W3	Concrete	Green	None	0	N/A	N/A
1	G	"Girl's Dressing" Room in Gym	W4	Concrete	Green	None	0	N/A	N/A
1	G	"Girl's Dressing" Room in Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	"Girl's Dressing" Room in Gym	Floor	9 x 9 Tile	White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	G	Storage Room in Gym next to Girl's Dressing Room	W1	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room in Gym next to Girl's Dressing Room	W1	Metal	White	None	0	N/A	N/A
1	G	Storage Room in Gym next to Girl's Dressing Room	W2	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room in Gym next to Girl's Dressing Room	W3	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room in Gym next to Girl's Dressing Room	W4	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room in Gym next to Girl's Dressing Room	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Storage Room in Gym next to Girl's Dressing Room	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	G	Gym Office	W1	Concrete	White	None	0	N/A	N/A
1	G	Gym Office	W1	Metal	Gray	None	0	N/A	N/A
1	G	Gym Office	W2	Concrete	White	None	0	N/A	N/A
1	G	Gym Office	W3	Concrete	White	None	0	N/A	N/A
1	G	Gym Office	W4	Concrete	White	None	0	N/A	N/A
1	G	Gym Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Gym Office	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	G	Gym Office Restroom	W1	Concrete	White	None	0	N/A	N/A
1	G	Gym Office Restroom	W1	Metal	Gray/Blue	None	0	N/A	N/A
1	G	Gym Office Restroom	W2	Concrete	White	None	0	N/A	N/A
1	G	Gym Office Restroom	W3	Concrete	White	Flaking	4	-0.7	Negative
1	G	Gym Office Restroom	W4	Concrete	White	None	0	N/A	N/A
1	G	Gym Office Restroom	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	G	Gym Office Restroom	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	G	Boy's Restroom in Gym	W1	Concrete	White	Flaking	8	-0.4	Negative
1	G	Boy's Restroom in Gym	W1	Metal	Gray	None	0	N/A	N/A
1	G	Boy's Restroom in Gym	W2	Concrete	White	None	0	N/A	N/A
1	G	Boy's Restroom in Gym	W3	Concrete	White	None	0	N/A	N/A
1	G	Boy's Restroom in Gym	W4	Concrete	White	None	0	N/A	N/A
1	G	Boy's Restroom in Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Boy's Restroom in Gym	Ceiling	Metal	White	Flaking	4	0	Negative
1	G	Boy's Restroom in Gym	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Storage Room next to Boy's Restroom in Gym	W1	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room next to Boy's Restroom in Gym	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	G	Storage Room next to Boy's Restroom in Gym	W2	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room next to Boy's Restroom in Gym	W3	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room next to Boy's Restroom in Gym	W4	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room next to Boy's Restroom in Gym	Ceiling	Concrete	White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	G	Storage Room next to Boy's Restroom in Gym	Ceiling	Metal	White	Flaking	4	0	Negative
1	G	Storage Room next to Boy's Restroom in Gym	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Storage Room behind the Storage Room next to Boy's Restroom in Gym	W1	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room behind the Storage Room next to Boy's Restroom in Gym	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	G	Storage Room behind the Storage Room next to Boy's Restroom in Gym	W2	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room behind the Storage Room next to Boy's Restroom in Gym	W3	Concrete	Green	Flaking	3	-0.2	Negative
1	G	Storage Room behind the Storage Room next to Boy's Restroom in Gym	W4	Concrete	Green	None	0	N/A	N/A
1	G	Storage Room behind the Storage Room next to Boy's Restroom in Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Storage Room behind the Storage Room next to Boy's Restroom in Gym	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Girl's Restroom in Gym	W1	Concrete	White	Flaking	15	-0.4	Negative
1	G	Girl's Restroom in Gym	W1	Metal	Gray	None	0	N/A	N/A
1	G	Girl's Restroom in Gym	W2	Concrete	White	Flaking	25	-0.6	Negative
1	G	Girl's Restroom in Gym	W3	Concrete	White	Flaking	15	-0.4	Negative
1	G	Girl's Restroom in Gym	W4	Concrete	White	Flaking	30	-0.4	Negative
1	G	Girl's Restroom in Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Girl's Restroom in Gym	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Stairwell between Girl's Restroom and Gym	W1	Concrete	Yellow/White	None	0	N/A	N/A
1	G	Stairwell between Girl's Restroom and Gym	W2	Concrete	Yellow/White	None	0	N/A	N/A
1	G	Stairwell between Girl's Restroom and Gym	W3	Concrete	Yellow/White	None	0	N/A	N/A
1	G	Stairwell between Girl's Restroom and Gym	W4	Concrete	Yellow/White	None	0	N/A	N/A
1	G	Stairwell between Girl's Restroom and Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Stairwell between Girl's Restroom and Gym	Floor	9 x 9 Tile	Green	None	0	N/A	N/A
1	G	Hallway from Hall near Gym to Pantry	W1	Concrete	Green/White	Flaking	3	-0.4	Negative
1	G	Hallway from Hall near Gym to Pantry	W2	Concrete	Green/White	Flaking	35	-0.5	Negative
1	G	Hallway from Hall near Gym to Pantry	W3	Concrete	Green/White	Flaking	9	-0.3	Negative
1	G	Hallway from Hall near Gym to Pantry	W4	Concrete	Green/White	Flaking	35	-0.5	Negative
1	G	Hallway from Hall near Gym to Pantry	W4	Metal	Green	None	0	N/A	N/A
1	G	Hallway from Hall near Gym to Pantry	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Hallway from Hall near Gym to Pantry	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	G	Hallway from Cafeteria to Gym	W1	Concrete	Green/White	Flaking	8	0.2	Negative
1	G	Hallway from Cafeteria to Gym	W2	Concrete	Green/White	None	0	N/A	N/A
1	G	Hallway from Cafeteria to Gym	W3	Concrete	Green/White	None	0	N/A	N/A
1	G	Hallway from Cafeteria to Gym	W4	Concrete	Green/White	Flaking	15	-0.6	Negative
1	G	Hallway from Cafeteria to Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Hallway from Cafeteria to Gym	Ceiling	Metal	White	Flaking	5	0	Negative
1	G	Hallway from Cafeteria to Gym	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
1	G	Girl's Restroom near Kitchen	W1	Concrete	Purple/White	None	0	N/A	N/A
1	G	Girl's Restroom near Kitchen	W1	Metal	Gray	None	0	N/A	N/A
1	G	Girl's Restroom near Kitchen	W2	Concrete	Purple/White	Flaking	10	-0.3	Negative
1	G	Girl's Restroom near Kitchen	W3	Concrete	Purple/White	None	0	N/A	N/A
1	G	Girl's Restroom near Kitchen	W3	Metal	Purple	None	0	N/A	N/A
1	G	Girl's Restroom near Kitchen	W4	Concrete	Purple/White	Flaking	5	-0.5	Negative
1	G	Girl's Restroom near Kitchen	Ceiling	Concrete	White	Flaking	10	0.2	Negative
1	G	Girl's Restroom near Kitchen	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Custodial Closet next to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Custodial Closet next to Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Custodial Closet next to Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Custodial Closet next to Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Custodial Closet next to Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Custodial Closet next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Staff Restroom across from Kitchen	W1	Concrete	Purple/White	None	0	N/A	N/A
1	G	Staff Restroom across from Kitchen	W1	Metal	Gray	None	0	N/A	N/A
1	G	Staff Restroom across from Kitchen	W2	Concrete	Purple/White	None	0	N/A	N/A
1	G	Staff Restroom across from Kitchen	W3	Concrete	Purple/White	None	0	N/A	N/A
1	G	Staff Restroom across from Kitchen	W4	Concrete	Purple/White	Flaking	3	-0.3	Negative
1	G	Staff Restroom across from Kitchen	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Staff Restroom across from Kitchen	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Boy's Restroom near Cafeteria	W1	Concrete	Purple/White	None	0	N/A	N/A
1	G	Boy's Restroom near Cafeteria	W1	Metal	Gray	None	0	N/A	N/A
1	G	Boy's Restroom near Cafeteria	W2	Concrete	Purple/White	None	0	N/A	N/A
1	G	Boy's Restroom near Cafeteria	W3	Concrete	Purple/White	None	0	N/A	N/A
1	G	Boy's Restroom near Cafeteria	W3	Metal	Purple	None	0	N/A	N/A
1	G	Boy's Restroom near Cafeteria	W4	Concrete	Purple/White	Flaking	15	0.3	Negative
1	G	Boy's Restroom near Cafeteria	Ceiling	Concrete	White	Flaking	5	-0.4	Negative

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	G	Boy's Restroom near Cafeteria	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Pipe Chase in Boy's Restroom near Cafeteria	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Pipe Chase in Boy's Restroom near Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Pipe Chase in Boy's Restroom near Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Pipe Chase in Boy's Restroom near Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Pipe Chase in Boy's Restroom near Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Pipe Chase in Boy's Restroom near Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Kitchen	W1	Concrete	White	Flaking	115	-0.6	Negative
1	G	Kitchen	W1	Metal	Purple/Gray	None	0	N/A	N/A
1	G	Kitchen	W2	Concrete	White	Flaking	85	0.3	Negative
1	G	Kitchen	W2	Metal	White	Flaking	3	-0.3	Negative
1	G	Kitchen	W3	Concrete	White	Flaking	50	0.4	Negative
1	G	Kitchen	W3	Metal	Purple	None	0	N/A	N/A
1	G	Kitchen	W4	Metal	Gray	None	0	N/A	N/A
1	G	Kitchen	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Kitchen	Floor	9 x 9 Tile	Green	None	0	N/A	N/A
1	G	Kitchen Office and Pantry	W1	Concrete	White	None	0	N/A	N/A
1	G	Kitchen Office and Pantry	W1	Metal	Purple	None	0	N/A	N/A
1	G	Kitchen Office and Pantry	W2	Concrete	White	None	0	N/A	N/A
1	G	Kitchen Office and Pantry	W3	Concrete	White	None	0	N/A	N/A
1	G	Kitchen Office and Pantry	W4	Concrete	White	None	0	N/A	N/A
1	G	Kitchen Office and Pantry	W4	Metal	Purple	None	0	N/A	N/A
1	G	Kitchen Office and Pantry	Ceiling	Concrete	White	Flaking	20	-0.3	Negative
1	G	Kitchen Office and Pantry	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A
1	G	Cafeteria	W1	Concrete	Blue/White	Flaking	220	-0.5	Negative
1	G	Cafeteria	W1	Metal	Blue	None	0	N/A	N/A
1	G	Cafeteria	W2	Concrete	Blue/White	Flaking	520	-0.4	Negative
1	G	Cafeteria	W3	Concrete	Blue/White	Flaking	50	-0.5	Negative
1	G	Cafeteria	W3	Metal	Blue	None	0	N/A	N/A
1	G	Cafeteria	W4	Concrete	Blue/White	Flaking	10	0.1	Negative
1	G	Cafeteria	Ceiling	Concrete	White	None	0	N/A	N/A
1	G	Cafeteria	Floor	12 x 12 Tile	Green	None	0	N/A	N/A
1	G	Stairwell in Cafeteria near Cage	W1	Concrete	Green/White	None	0	N/A	N/A
1	G	Stairwell in Cafeteria near Cage	W2	Concrete	Green/White	None	0	N/A	N/A
1	G	Stairwell in Cafeteria near Cage	W3	Concrete	Green/White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	G	Stairwell in Cafeteria near Cage	W4	Concrete	Green/White	None	0	N/A	N/A
1	G	Stairwell in Cafeteria near Cage	Ceiling	Concrete	White	Flaking	5	0.4	Negative
1	G	Stairwell in Cafeteria near Cage	Floor	Concrete	Gray	None	0	N/A	N/A
1	G	Maintenance Supply and Equipment Storage Room in Cafeteria	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Supply and Equipment Storage Room in Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Supply and Equipment Storage Room in Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Supply and Equipment Storage Room in Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Supply and Equipment Storage Room in Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Supply and Equipment Storage Room in Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Staff Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Staff Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Staff Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Staff Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Staff Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Maintenance Staff Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Restroom in Maintenance Staff Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Restroom in Maintenance Staff Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Restroom in Maintenance Staff Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Restroom in Maintenance Staff Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Restroom in Maintenance Staff Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Restroom in Maintenance Staff Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	G	Elevator	W1	Metal	Blue	None	0	N/A	N/A
1	G	Elevator	W2	Metal	Blue	Flaking	1	0	Negative
1	G	Elevator	W3	Metal	Blue	None	0	N/A	N/A
1	G	Elevator	W4	Metal	Blue	Flaking	2	0	Negative
1	G	Elevator	Ceiling	Metal	White	None	0	N/A	N/A
1	G	Elevator	Floor	12 x 12 Tile	Brown	None	0	N/A	N/A
1	G	Throughout Ground Floor	W1	-	-	-	-	-	-
1	G	Throughout Ground Floor	W2	-	-	-	-	-	-
1	G	Throughout Ground Floor	W3	-	-	-	-	-	-

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	G	Throughout Ground Floor	W4	-	-	-	-	-	-
1	G	Throughout Ground Floor	Ceiling	-	-	-	-	-	-
1	G	Throughout Ground Floor	Floor	-	-	-	-	-	-
1	1	Stairwell 3 across from Classroom 100	W1	Concrete	Blue/White	Flaking	12	0.2	Negative
1	1	Stairwell 3 across from Classroom 100	W2	Concrete	Blue/White	Cracking/Flaking	20	-0.6	Negative
1	1	Stairwell 3 across from Classroom 100	W2	Metal	Gray	None	0	N/A	N/A
1	1	Stairwell 3 across from Classroom 100	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Stairwell 3 across from Classroom 100	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Stairwell 3 across from Classroom 100	Ceiling	Concrete	White	Flaking	15	0	Negative
1	1	Stairwell 3 across from Classroom 100	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Classroom 100	W1	Concrete	Blue	None	0	N/A	N/A
1	1	Classroom 100	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom 100	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 100	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 100	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 100	W4	Concrete	Pink	None	0	N/A	N/A
1	1	Classroom 100	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom 100	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Girl's Restroom across from Classroom 100	W1	Concrete	Yellow/White	Flaking	30	-0.4	Negative
1	1	Girl's Restroom across from Classroom 100	W1	Metal	Gray	None	0	N/A	N/A
1	1	Girl's Restroom across from Classroom 100	W2	Concrete	Yellow/White	Flaking	20	-0.5	Negative
1	1	Girl's Restroom across from Classroom 100	W3	Concrete	Yellow/White	Flaking	5	-0.4	Negative
1	1	Girl's Restroom across from Classroom 100	W4	Concrete	Yellow/White	Flaking	3	-0.5	Negative
1	1	Girl's Restroom across from Classroom 100	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Girl's Restroom across from Classroom 100	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Boy's Restroom across from Classroom 102	W1	Concrete	Blue/White	Flaking	5	-0.5	Negative
1	1	Boy's Restroom across from Classroom 102	W1	Metal	Gray	None	0	N/A	N/A
1	1	Boy's Restroom across from Classroom 102	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Boy's Restroom across from Classroom 102	W2	Metal	Gray	Flaking	6	-0.2	Negative
1	1	Boy's Restroom across from Classroom 102	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Boy's Restroom across from Classroom 102	W4	Concrete	Blue/White	Flaking	7	-0.7	Negative
1	1	Boy's Restroom across from Classroom 102	Ceiling	Concrete	White	Flaking	4	0	Negative
1	1	Boy's Restroom across from Classroom 102	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Custordial closet between boys and girls restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custordial closet between boys and girls restrooms	W2	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Custodial closet between boys and girls restrooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between boys and girls restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom across from Classroom 102	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom across from Classroom 102	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom across from Classroom 102	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom across from Classroom 102	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom across from Classroom 102	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom across from Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 102	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom 102	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 102	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 102	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 102	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 102	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom 102	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Classroom 101	W1	Concrete	Blue	None	0	N/A	N/A
1	1	Classroom 101	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom 101	W2	Concrete	Blue	None	0	N/A	N/A
1	1	Classroom 101	W3	Concrete	Blue	None	0	N/A	N/A
1	1	Classroom 101	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 101	W4	Concrete	Blue	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Classroom 101	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom 101	Floor	9 x 9 Tile	Blue	None	0	N/A	N/A
1	1	Classroom 104	W1	Concrete	Blue	None	0	N/A	N/A
1	1	Classroom 104	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom 104	W2	Concrete	Blue	None	0	N/A	N/A
1	1	Classroom 104	W3	Concrete	Blue	None	0	N/A	N/A
1	1	Classroom 104	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 104	W4	Concrete	Blue	None	0	N/A	N/A
1	1	Classroom 104	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom 104	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Classroom 103	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 103	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom 103	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 103	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 103	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 103	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 103	Ceiling	Concrete	White	Flaking	1	-0.1	Negative
1	1	Classroom 103	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	1	Classroom 105	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 105	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom 105	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 105	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 105	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 105	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom 105	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	1	Stairwell No. 2 near Classroom 105	W1	Concrete	Green/White	None	0	N/A	N/A
1	1	Stairwell No. 2 near Classroom 105	W2	Concrete	Green/White	Cracking	15	-0.3	Negative
1	1	Stairwell No. 2 near Classroom 105	W3	Concrete	Green/White	None	0	N/A	N/A
1	1	Stairwell No. 2 near Classroom 105	W4	Concrete	Green/White	Flaking	1	-0.3	Negative
1	1	Stairwell No. 2 near Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Stairwell No. 2 near Classroom 105	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	W2	Concrete	Blue/White	Flaking	55	-0.6	Negative

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	1	Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	W3	Concrete	Blue/White	Flaking	20	-0.6	Negative
1	1	Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	W4	Concrete	Blue/White	Flaking	100	0	Negative
1	1	Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Ceiling	Concrete	White	Flaking	125	0	Negative
1	1	Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Floor	9 x 9 Tile	Brown	None	0	N/A	N/A
1	1	Classroom K-1	W1	Concrete	White/Blue	Flaking	4	-0.4	Negative
1	1	Classroom K-1	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom K-1	W2	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-1	W3	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-1	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom K-1	W4	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-1	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-1	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A
1	1	Classroom K-1 Coat Room	W1	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-1 Coat Room	W2	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-1 Coat Room	W3	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-1 Coat Room	W4	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-1 Coat Room	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-1 Coat Room	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A
1	1	Classroom K-1 Storage Room	W1	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-1 Storage Room	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom K-1 Storage Room	W2	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-1 Storage Room	W3	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-1 Storage Room	W4	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-1 Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-1 Storage Room	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	1	Classroom K-1 Restroom	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom K-1 Restroom	W1	Metal	Blue	None	0	N/A	N/A
1	1	Classroom K-1 Restroom	W2	Concrete	Blue/White	Flaking	7	-0.5	Negative
1	1	Classroom K-1 Restroom	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom K-1 Restroom	W4	Concrete	Blue/White	Flaking	16	-0.4	Negative
1	1	Classroom K-1 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Pipe Chase in Classroom K-1 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Pipe Chase in Classroom K-1 Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Classroom K-1 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Classroom K-1 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Classroom K-1 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Classroom K-1 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K-1 Restroom	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
1	1	Back Hallway from Classroom K-1 to Classroom K-2	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Back Hallway from Classroom K-1 to Classroom K-2	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Back Hallway from Classroom K-1 to Classroom K-2	W2	Metal	Blue	None	0	N/A	N/A
1	1	Back Hallway from Classroom K-1 to Classroom K-2	W3	Concrete	Blue/White	Flaking	6	-0.2	Negative
1	1	Back Hallway from Classroom K-1 to Classroom K-2	W4	Concrete	Blue/White	Flaking	4	0	Negative
1	1	Back Hallway from Classroom K-1 to Classroom K-2	W4	Metal	Gray	Flaking	5	0	Negative
1	1	Back Hallway from Classroom K-1 to Classroom K-2	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Back Hallway from Classroom K-1 to Classroom K-2	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
1	1	Classroom K-2	W1	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-2	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom K-2	W2	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-2	W3	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-2	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom K-2	W4	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-2	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-2	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A
1	1	Classroom K-2 Coat Room	W1	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-2 Coat Room	W2	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-2 Coat Room	W3	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-2 Coat Room	W4	Concrete	White/Blue	None	0	N/A	N/A
1	1	Classroom K-2 Coat Room	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-2 Coat Room	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A
1	1	Classroom K-2 Storage Room	W1	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-2 Storage Room	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom K-2 Storage Room	W2	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-2 Storage Room	W3	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-2 Storage Room	W4	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-2 Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom K-2 Storage Room	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom K-2 Restroom	W1	Concrete	White	Flaking	2	-0.5	Negative
1	1	Classroom K-2 Restroom	W1	Metal	Gray	None	0	N/A	N/A
1	1	Classroom K-2 Restroom	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom K-2 Restroom	W3	Concrete	Blue/White	Flaking	6	-0.4	Negative
1	1	Classroom K-2 Restroom	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom K-2 Restroom	Ceiling	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom K-2 Restroom	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
1	1	Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	W2	Concrete	Blue/White	Flaking	100	-0.5	Negative
1	1	Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	W2	Metal	Gray	None	0	N/A	N/A
1	1	Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	W4	Concrete	Blue/White	Flaking	35	-0.6	Negative
1	1	Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	Floor	9 x 9 Tile	Brown	None	0	N/A	N/A
1	1	Women's Restroom next to Elevator	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Women's Restroom next to Elevator	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Women's Restroom next to Elevator	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Women's Restroom next to Elevator	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Women's Restroom next to Elevator	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Women's Restroom next to Elevator	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Women's Restroom next to Elevator	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	Men's Restroom near Room 106	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Men's Restroom near Room 106	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Men's Restroom near Room 106	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Men's Restroom near Room 106	W3	Concrete	Blue/White	Flaking	20	-0.3	Negative
1	1	Men's Restroom near Room 106	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Men's Restroom near Room 106	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Men's Restroom near Room 106	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Pipe Chase outside Men's Restroom near Room 106	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase outside Men's Restroom near Room 106	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase outside Men's Restroom near Room 106	W3	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Pipe Chase outside Men's Restroom near Room 106	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase outside Men's Restroom near Room 106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase outside Men's Restroom near Room 106	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	W1	Concrete	Purple/White	None	0	N/A	N/A
1	1	Classroom 107	W1	Metal	Purple/Gray	None	0	N/A	N/A
1	1	Classroom 107	W2	Concrete	Purple/White	Flaking	5	-0.4	Negative
1	1	Classroom 107	W3	Concrete	Purple/White	None	0	N/A	N/A
1	1	Classroom 107	W3	Metal	Purple	None	0	N/A	N/A
1	1	Classroom 107	W4	Sheetrock	Purple/White	None	0	N/A	N/A
1	1	Classroom 107	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom 107	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A
1	1	Classroom 107 Storage Area	W1	Concrete	Purple/White	None	0	N/A	N/A
1	1	Classroom 107 Storage Area	W1	Metal	Purple/Gray	None	0	N/A	N/A
1	1	Classroom 107 Storage Area	W2	Concrete	Purple/White	None	0	N/A	N/A
1	1	Classroom 107 Storage Area	W3	Concrete	Purple/White	None	0	N/A	N/A
1	1	Classroom 107 Storage Area	W4	Concrete	Purple/White	Flaking	4	-0.4	Negative
1	1	Classroom 107 Storage Area	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom 107 Storage Area	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A
1	1	Classroom 107 Restroom	W1	Concrete	Green/White	None	0	N/A	N/A
1	1	Classroom 107 Restroom	W1	Metal	Gray	None	0	N/A	N/A
1	1	Classroom 107 Restroom	W2	Concrete	Green/White	None	0	N/A	N/A
1	1	Classroom 107 Restroom	W3	Concrete	Green/White	None	0	N/A	N/A
1	1	Classroom 107 Restroom	W4	Concrete	Green/White	None	0	N/A	N/A
1	1	Classroom 107 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Classroom 107 Restroom	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Classroom 108	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom 108 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 110	W1	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 110	W2	Sheetrock	Blue/White	Flaking	5	0	Negative
1	1	Classroom 110	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 110	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 110	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 110	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Classroom 110	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Teacher's Lounge	W1	Concrete	Blue / White	None	0	N/A	N/A
1	1	Teacher's Lounge	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Teacher's Lounge	W2	Concrete	Blue / White	None	0	N/A	N/A
1	1	Teacher's Lounge	W3	Concrete	Blue / White	None	0	N/A	N/A
1	1	Teacher's Lounge	W3	Metal	Blue	None	0	N/A	N/A
1	1	Teacher's Lounge	W4	Sheetrock	Blue / White	Flaking	4	-0.1	Negative
1	1	Teacher's Lounge	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Teacher's Lounge	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	1	Classroom 109	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 109	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Classroom 109	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 109	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 109	W3	Metal	Blue	None	0	N/A	N/A
1	1	Classroom 109	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 109	Ceiling	Concrete	Blue/White	None	0	N/A	N/A
1	1	Classroom 109	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Boy's Restroom next to Room 109	W1	Concrete	Blue/White	Flaking	2	-0.1	Negative
1	1	Boy's Restroom next to Room 109	W1	Metal	Gray	None	0	N/A	N/A
1	1	Boy's Restroom next to Room 109	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Boy's Restroom next to Room 109	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Boy's Restroom next to Room 109	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Boy's Restroom next to Room 109	Ceiling	Concrete	White	Flaking	1	0	Negative
1	1	Boy's Restroom next to Room 109	Floor	Concrete	Brown	None	0	N/A	N/A
1	1	Pipe Chase in Boy's Restroom next to Room 109	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom next to Room 109	W2	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Pipe Chase in Boy's Restroom next to Room 109	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom next to Room 109	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom next to Room 109	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Boy's Restroom next to Room 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom near Room 109	W1	Concrete	Purple/White	None	0	N/A	N/A
1	1	Girl's Restroom near Room 109	W1	Metal	Purple/Gray	None	0	N/A	N/A
1	1	Girl's Restroom near Room 109	W2	Concrete	Purple/White	None	0	N/A	N/A
1	1	Girl's Restroom near Room 109	W3	Concrete	Purple/White	None	0	N/A	N/A
1	1	Girl's Restroom near Room 109	W4	Concrete	Purple/White	Flaking	3	-0.6	Negative
1	1	Girl's Restroom near Room 109	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Girl's Restroom near Room 109	Floor	Concrete	Brown	None	0	N/A	N/A
1	1	Stairwell No. 1 near Building Engineer's Office	W1	Concrete	Yellow/White	None	0	N/A	N/A
1	1	Stairwell No. 1 near Building Engineer's Office	W2	Concrete	Yellow/White	Flaking	3	-0.2	Negative
1	1	Stairwell No. 1 near Building Engineer's Office	W2	Metal	Gray	None	0	N/A	N/A
1	1	Stairwell No. 1 near Building Engineer's Office	W3	Concrete	Yellow/White	None	0	N/A	N/A
1	1	Stairwell No. 1 near Building Engineer's Office	W4	Concrete	Yellow/White	None	0	N/A	N/A
1	1	Stairwell No. 1 near Building Engineer's Office	Ceiling	Concrete	White	Flaking	1	0.2	Negative
1	1	Stairwell No. 1 near Building Engineer's Office	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	W1	Concrete	Yellow	None	0	N/A	N/A
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	W1	Metal	Yellow/Brown	None	0	N/A	N/A
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	W2	Concrete	Yellow	None	0	N/A	N/A
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	W2	Metal	Gray	None	0	N/A	N/A
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	W3	Concrete	Yellow	None	0	N/A	N/A
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	W4	Concrete	Yellow	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	W4	Metal	Gray	None	0	N/A	N/A
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
2	1	Hallway from Stairwell near Building Engineer's Office to IMC/Library	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
2	1	Library/IMC	W1	Concrete	Tan	None	0	N/A	N/A
2	1	Library/IMC	W1	Metal	Tan	Flaking	4	0.1	Negative
2	1	Library/IMC	W1	Metal	Brown	None	0	N/A	N/A
2	1	Library/IMC	W1	Metal	Tan	None	0	N/A	N/A
2	1	Library/IMC	W2	Concrete	Tan	None	0	N/A	N/A
2	1	Library/IMC	W3	Concrete	Tan	None	0	N/A	N/A
2	1	Library/IMC	W1	Metal	Brown	None	0	N/A	N/A
2	1	Library/IMC	W3	Metal	Tan	None	0	N/A	N/A
2	1	Library/IMC	W3	Metal	Tan	Flaking	4	0.3	Negative
2	1	Library/IMC	W4	Concrete	Tan	None	0	N/A	N/A
2	1	Library/IMC	Ceiling	Drop Ceiling	Tan	None	0	N/A	N/A
2	1	Library/IMC	Floor	Carpet	Multi	None	0	N/A	N/A
1	1	Hallway from Building Engineer's Office to Elevator	W1	Concrete	Multi	Flaking	100	-0.5	Negative
1	1	Hallway from Building Engineer's Office to Elevator	W3	Concrete	Multi	Flaking	110	-0.5	Negative
1	1	Hallway from Building Engineer's Office to Elevator	W4	Concrete	Multi	None	0	N/A	N/A
1	1	Hallway from Building Engineer's Office to Elevator	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Hallway from Building Engineer's Office to Elevator	Floor	Floor Tile	Multi	None	0	N/A	N/A
1	1	Auditorium	W1	Concrete	Blue	None	0	N/A	N/A
1	1	Auditorium	W2	Concrete	Blue	None	0	N/A	N/A
1	1	Auditorium	W2	Metal	Blue	None	0	N/A	N/A
1	1	Auditorium	W4	Concrete	Blue	None	0	N/A	N/A
1	1	Auditorium	W4	Metal	Blue	None	0	N/A	N/A
1	1	Auditorium	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Auditorium	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	1	Auditorium Stage	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Auditorium Stage	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Auditorium Stage	W3	Metal	Blue	None	0	N/A	N/A
1	1	Auditorium Stage	W3	Concrete	Black/White	None	0	N/A	N/A
1	1	Auditorium Stage	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Auditorium Stage	W3	Metal	Blue	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Auditorium Stage	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	1	Fan Room on Auditorium Stage	W1	Concrete	White	None	0	N/A	N/A
1	1	Fan Room on Auditorium Stage	W2	Concrete	White	None	0	N/A	N/A
1	1	Fan Room on Auditorium Stage	W3	Concrete	White	None	0	N/A	N/A
1	1	Fan Room on Auditorium Stage	W4	Concrete	White	None	0	N/A	N/A
1	1	Fan Room on Auditorium Stage	Floor	Concrete	Gray	None	0	N/A	N/A
1	1	Hallway/Lobby between Auditorium and Main Office	W1	Concrete	Yellow	None	0	N/A	N/A
1	1	Hallway/Lobby between Auditorium and Main Office	W2	Concrete	Multi	None	0	N/A	N/A
1	1	Hallway/Lobby between Auditorium and Main Office	W3	Concrete	Multi	None	0	N/A	N/A
1	1	Hallway/Lobby between Auditorium and Main Office	W4	Concrete	Multi	None	0	N/A	N/A
1	1	Hallway/Lobby between Auditorium and Main Office	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Hallway/Lobby between Auditorium and Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Hallway/Lobby between Auditorium and Main Office	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Main Entrance Door Way	W1	Concrete	Blue/White	Flaking	15	0.1	Negative
1	1	Main Entrance Door Way	W1	Metal	Gray	None	0	N/A	N/A
1	1	Main Entrance Door Way	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Main Entrance Door Way	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Main Entrance Door Way	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Main Entrance Door Way	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Main Entrance Door Way	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Main Entrance Door Way	Floor	9 x 9 Tile	Multi	None	0	N/A	N/A
1	1	Principal's Office	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Principal's Office	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Principal's Office	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Principal's Office	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Principal's Office	W3	Metal	Blue	None	0	N/A	N/A
1	1	Principal's Office	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Principal's Office	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Principal's Office	Floor	Carpet	Blue	None	0	N/A	N/A
1	1	Principal's Office Restroom	W1	Concrete	White/Red	Flaking	2	-0.7	Negative
1	1	Principal's Office Restroom	W1	Metal	Red/Blue	None	0	N/A	N/A
1	1	Principal's Office Restroom	W2	Concrete	White/Red	None	0	N/A	N/A
1	1	Principal's Office Restroom	W3	Concrete	White/Red	None	0	N/A	N/A
1	1	Principal's Office Restroom	W4	Concrete	White/Red	Flaking	5	-0.5	Negative
1	1	Principal's Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Principal's Office Restroom	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	1	Principal's Office Closet	W1	Concrete	White	None	0	N/A	N/A
1	1	Principal's Office Closet	W1	Metal	Blue	None	0	N/A	N/A
1	1	Principal's Office Closet	W2	Concrete	White	None	0	N/A	N/A
1	1	Principal's Office Closet	W3	Concrete	White	None	0	N/A	N/A
1	1	Principal's Office Closet	W4	Concrete	White	None	0	N/A	N/A
1	1	Principal's Office Closet	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Principal's Office Closet	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Closet in Main Office next to Principal's Office	W1	Concrete	White	None	0	N/A	N/A
1	1	Closet in Main Office next to Principal's Office	W1	Metal	Blue	None	0	N/A	N/A
1	1	Closet in Main Office next to Principal's Office	W2	Concrete	White	None	0	N/A	N/A
1	1	Closet in Main Office next to Principal's Office	W3	Concrete	White	None	0	N/A	N/A
1	1	Closet in Main Office next to Principal's Office	W4	Concrete	White	None	0	N/A	N/A
1	1	Closet in Main Office next to Principal's Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Closet in Main Office next to Principal's Office	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Main Office	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Main Office	W1	Metal	Gray	None	0	N/A	N/A
1	1	Main Office	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Main Office	W3	Concrete	Blue/White	Flaking	2	-0.2	Negative
1	1	Main Office	W3	Metal	Blue	None	0	N/A	N/A
1	1	Main Office	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Main Office	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Main Office	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Hallway in Main Office to Nurse's Office	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Hallway in Main Office to Nurse's Office	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Hallway in Main Office to Nurse's Office	W4	Sheetrock	Blue/White	None	0	N/A	N/A
1	1	Hallway in Main Office to Nurse's Office	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Hallway in Main Office to Nurse's Office	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Main Office Storage Room across from Counselor B Office	W1	Concrete	White	None	0	N/A	N/A
1	1	Main Office Storage Room across from Counselor B Office	W1	Metal	Blue	None	0	N/A	N/A
1	1	Main Office Storage Room across from Counselor B Office	W2	Concrete	White	None	0	N/A	N/A
1	1	Main Office Storage Room across from Counselor B Office	W3	Concrete	White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Main Office Storage Room across from Counselor B Office	W4	Concrete	White	None	0	N/A	N/A
1	1	Main Office Storage Room across from Counselor B Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Main Office Storage Room across from Counselor B Office	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Nurse's Office 106	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Nurse's Office 106	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Nurse's Office 106	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Nurse's Office 106	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Nurse's Office 106	W3	Metal	Blue	None	0	N/A	N/A
1	1	Nurse's Office 106	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Nurse's Office 106	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Nurse's Office 106	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Nurse's Office Storage Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Storage Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Storage Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Storage Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Storage Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Storage Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Restroom	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Nurse's Office Restroom	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Nurse's Office Restroom	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Nurse's Office Restroom	W3	Concrete	Blue/White	Cracking	3	-0.6	Negative
1	1	Nurse's Office Restroom	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Nurse's Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Nurse's Office Restroom	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	1	Assistant Principal's Office in Main Office Area	W1	Concrete	Blue/White	None	0	N/A	N/A
1	1	Assistant Principal's Office in Main Office Area	W1	Metal	Blue	None	0	N/A	N/A
1	1	Assistant Principal's Office in Main Office Area	W2	Concrete	Blue/White	None	0	N/A	N/A
1	1	Assistant Principal's Office in Main Office Area	W3	Concrete	Blue/White	None	0	N/A	N/A
1	1	Assistant Principal's Office in Main Office Area	W3	Metal	Blue	None	0	N/A	N/A
1	1	Assistant Principal's Office in Main Office Area	W4	Concrete	Blue/White	None	0	N/A	N/A
1	1	Assistant Principal's Office in Main Office Area	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Assistant Principal's Office in Main Office Area	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Dean's Office in Main Office Area	W1	Concrete	White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Dean's Office in Main Office Area	W1	Metal	Blue/White	None	0	N/A	N/A
1	1	Dean's Office in Main Office Area	W2	Concrete	White	None	0	N/A	N/A
1	1	Dean's Office in Main Office Area	W3	Concrete	White	None	0	N/A	N/A
1	1	Dean's Office in Main Office Area	W3	Metal	White	None	0	N/A	N/A
1	1	Dean's Office in Main Office Area	W4	Concrete	White	None	0	N/A	N/A
1	1	Dean's Office in Main Office Area	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Dean's Office in Main Office Area	Floor	Concrete	White	None	0	N/A	N/A
1	1	Computer Server Room next to Nurse's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Computer Server Room next to Nurse's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Computer Server Room next to Nurse's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Computer Server Room next to Nurse's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Computer Server Room next to Nurse's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Computer Server Room next to Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	"Visual Aids" Storage Room across from Classroom 105	W1	Concrete	White	None	0	N/A	N/A
1	1	"Visual Aids" Storage Room across from Classroom 105	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	"Visual Aids" Storage Room across from Classroom 105	W2	Concrete	White	None	0	N/A	N/A
1	1	"Visual Aids" Storage Room across from Classroom 105	W3	Concrete	White	Flaking	15	-0.5	Negative
1	1	"Visual Aids" Storage Room across from Classroom 105	W4	Concrete	White	None	0	N/A	N/A
1	1	"Visual Aids" Storage Room across from Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	"Visual Aids" Storage Room across from Classroom 105	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	1	Books B-1 Storage Room near Classrooms 103 and 105	W1	Concrete	Blue	None	0	N/A	N/A
1	1	Books B-1 Storage Room near Classrooms 103 and 105	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	1	Books B-1 Storage Room near Classrooms 103 and 105	W2	Concrete	Blue	None	0	N/A	N/A
1	1	Books B-1 Storage Room near Classrooms 103 and 105	W3	Concrete	Blue	None	0	N/A	N/A
1	1	Books B-1 Storage Room near Classrooms 103 and 105	W4	Concrete	Blue	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Books B-1 Storage Room near Classrooms 103 and 105	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Books B-1 Storage Room near Classrooms 103 and 105	Floor	9 x 9 Tile	Brown	None	0	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toys" printed on Door	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Speech Office next to Teacher's Lounge	W1	Concrete	Pink/White	None	0	N/A	N/A
1	1	Speech Office next to Teacher's Lounge	W1	Metal	Pink/Gray	None	0	N/A	N/A
1	1	Speech Office next to Teacher's Lounge	W2	Concrete	Pink/White	None	0	N/A	N/A
1	1	Speech Office next to Teacher's Lounge	W3	Concrete	Pink/White	None	0	N/A	N/A
1	1	Speech Office next to Teacher's Lounge	W3	Metal	Pink	None	0	N/A	N/A
1	1	Speech Office next to Teacher's Lounge	W4	Concrete	Pink/White	None	0	N/A	N/A
1	1	Speech Office next to Teacher's Lounge	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	1	Speech Office next to Teacher's Lounge	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	1	Throughout 1st Floor	W1	-	-	-	-	-	-
1	1	Throughout 1st Floor	W2	-	-	-	-	-	-

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Throughout 1st Floor	W3	-	-	-	-	-	-
1	1	Throughout 1st Floor	W4	-	-	-	-	-	-
1	1	Throughout 1st Floor	Ceiling	-	-	-	-	-	-
1	1	Throughout 1st Floor	Floor	-	-	-	-	-	-
1	2	Classroom 200	W1	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 200	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Classroom 200	W2	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 200	W3	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 200	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 200	W4	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 200	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 200	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Stairwell No. 3 across from Classroom 200	W1	Concrete	Blue/White	Alligatoring	6	-0.5	Negative
1	2	Stairwell No. 3 across from Classroom 200	W2	Concrete	Blue/White	Cracking/Flaking	30	-0.5	Negative
1	2	Stairwell No. 3 across from Classroom 200	W3	Concrete	Blue/White	Flaking	15	-0.3	Negative
1	2	Stairwell No. 3 across from Classroom 200	W3	Metal	Gray	None	0	N/A	N/A
1	2	Stairwell No. 3 across from Classroom 200	W4	Concrete	Blue/White	Flaking	15	-0.4	Negative
1	2	Stairwell No. 3 across from Classroom 200	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Stairwell No. 3 across from Classroom 200	Floor	Concrete	Gray	None	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	W1	Concrete	Purple/White	None	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	W1	Metal	Pink/Purple	None	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	W2	Concrete	Purple/White	None	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	W3	Concrete	Purple/White	None	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	W3	Metal	Purple	None	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	W4	Concrete	Purple/White	None	0	N/A	N/A
1	2	Girl's Restroom across from Classroom 200	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	2	Girl's Restroom across from Classroom 200	Floor	Concrete	Gray	None	0	N/A	N/A
1	2	Custodial Closet across from Classroom 200	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 200	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Books B-2 Storage Room near Classrooms 200 and 202	W1	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Books B-2 Storage Room near Classrooms 200 and 202	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Books B-2 Storage Room near Classrooms 200 and 202	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Books B-2 Storage Room near Classrooms 200 and 202	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Books B-2 Storage Room near Classrooms 200 and 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Books B-2 Storage Room near Classrooms 200 and 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	W1	Concrete	Blue/White	Flaking	3	-0.3	Negative
1	2	Boy's Restroom across from Classroom 202	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	W2	Concrete	Blue/White	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	W3	Concrete	Blue/White	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	W3	Metal	Blue	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	W4	Concrete	Blue/White	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	Ceiling	Concrete	White	Flaking	3	0.2	Negative
1	2	Boy's Restroom across from Classroom 202	Floor	Concrete	Gray	None	0	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 202	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 202	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 202	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W1	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 202	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Classroom 202	W2	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 202	W3	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 202	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 202	W4	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 202	Ceiling	Concrete	White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Classroom 202	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Classroom 201	W1	Concrete	Blue/Green	None	0	N/A	N/A
1	2	Classroom 201	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Classroom 201	W2	Concrete	Blue/Green	None	0	N/A	N/A
1	2	Classroom 201	W3	Concrete	Blue/Green	None	0	N/A	N/A
1	2	Classroom 201	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 201	W4	Concrete	Blue/Green	None	0	N/A	N/A
1	2	Classroom 201	Ceiling	Concrete	White	Flaking	25	0.2	Negative
1	2	Classroom 201	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Classroom 204	W1	Concrete	White/Blue	None	0	N/A	N/A
1	2	Classroom 204	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Classroom 204	W2	Concrete	White/Blue	None	0	N/A	N/A
1	2	Classroom 204	W3	Concrete	White/Blue	None	0	N/A	N/A
1	2	Classroom 204	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 204	W4	Concrete	White/Blue	None	0	N/A	N/A
1	2	Classroom 204	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 204	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	2	Classroom 203	W1	Concrete	Blue/Green	None	0	N/A	N/A
1	2	Classroom 203	W1	Metal	Blue/Green	None	0	N/A	N/A
1	2	Classroom 203	W2	Concrete	Blue/Green	None	0	N/A	N/A
1	2	Classroom 203	W3	Concrete	Blue/Green	None	0	N/A	N/A
1	2	Classroom 203	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 203	W4	Concrete	Blue/Green	None	0	N/A	N/A
1	2	Classroom 203	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 203	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Classroom 206	W1	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 206	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Classroom 206	W2	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 206	W3	Concrete	Blue/White	Flaking	5	0.3	Negative
1	2	Classroom 206	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 206	W4	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 206	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 206	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Classroom 205	W1	Concrete	Purple/Blue	None	0	N/A	N/A
1	2	Classroom 205	W1	Metal	Blue	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Classroom 205	W2	Concrete	Purple/Blue	None	0	N/A	N/A
1	2	Classroom 205	W3	Concrete	Purple/Blue	None	0	N/A	N/A
1	2	Classroom 205	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 205	W4	Concrete	Purple/Blue	None	0	N/A	N/A
1	2	Classroom 205	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 205	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Classroom 208	W1	Concrete	Green/Blue	None	0	N/A	N/A
1	2	Classroom 208	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Classroom 208	W2	Concrete	Green/Blue	None	0	N/A	N/A
1	2	Classroom 208	W3	Concrete	Green/Blue	None	0	N/A	N/A
1	2	Classroom 208	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 208	W4	Concrete	Green/Blue	None	0	N/A	N/A
1	2	Classroom 208	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 208	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Stairwell No. 2 across from Classroom 208	W1	Concrete	Green/White	None	0	N/A	N/A
1	2	Stairwell No. 2 across from Classroom 208	W2	Concrete	Green/White	None	0	N/A	N/A
1	2	Stairwell No. 2 across from Classroom 208	W3	Concrete	Green/White	None	0	N/A	N/A
1	2	Stairwell No. 2 across from Classroom 208	W4	Concrete	Green/White	Flaking	5	-0.4	Negative
1	2	Stairwell No. 2 across from Classroom 208	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Stairwell No. 2 across from Classroom 208	Floor	Concrete	Gray	None	0	N/A	N/A
1	2	Classroom 210	W1	Concrete	White	None	0	N/A	N/A
1	2	Classroom 210	W1	Metal	White	None	0	N/A	N/A
1	2	Classroom 210	W1	Metal	White	Flaking	6	0	Negative
1	2	Classroom 210	W2	Concrete	White	None	0	N/A	N/A
1	2	Classroom 210	W3	Concrete	White	None	0	N/A	N/A
1	2	Classroom 210	W3	Metal	White	None	0	N/A	N/A
1	2	Classroom 210	W4	Concrete	White	None	0	N/A	N/A
1	2	Classroom 210	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 210	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Classroom 212	W1	Concrete	Green/White	None	0	N/A	N/A
1	2	Classroom 212	W1	Metal	Green/Gray	None	0	N/A	N/A
1	2	Classroom 212	W2	Concrete	Green/White	None	0	N/A	N/A
1	2	Classroom 212	W3	Concrete	Green/White	None	0	N/A	N/A
1	2	Classroom 212	W3	Metal	Green	None	0	N/A	N/A
1	2	Classroom 212	W4	Concrete	Green/White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Classroom 212	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 212	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Women's Restroom across from Classroom 214	W1	Concrete	White/Blue	None	0	N/A	N/A
1	2	Women's Restroom across from Classroom 214	W1	Metal	Pink/Gray	None	0	N/A	N/A
1	2	Women's Restroom across from Classroom 214	W2	Concrete	White/Blue	None	0	N/A	N/A
1	2	Women's Restroom across from Classroom 214	W3	Concrete	White/Blue	None	0	N/A	N/A
1	2	Women's Restroom across from Classroom 214	W4	Concrete	White/Blue	None	0	N/A	N/A
1	2	Women's Restroom across from Classroom 214	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Women's Restroom across from Classroom 214	Floor	Concrete	Gray	None	0	N/A	N/A
1	2	Pipe Chase in Hall next to Women's Restroom across from Classroom 214	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Hall next to Women's Restroom across from Classroom 214	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Hall next to Women's Restroom across from Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Hall next to Women's Restroom across from Classroom 214	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Hall next to Women's Restroom across from Classroom 214	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Hall next to Women's Restroom across from Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 217 Science	W1	Metal	Brown	None	0	N/A	N/A
1	2	Classroom 217 Science	W2	Concrete	Tan	Flaking	10	-0.2	Negative
1	2	Classroom 217 Science	W3	Concrete	Tan	None	0	N/A	N/A
1	2	Classroom 217 Science	W3	Metal	Black	None	0	N/A	N/A
1	2	Classroom 217 Science	W4	Concrete	Tan	Flaking	10	-0.7	Negative
1	2	Classroom 217 Science	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	2	Classroom 217 Science	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
1	2	Classroom 217 Lab Prep	W1	Concrete	Tan	None	0	N/A	N/A
1	2	Classroom 217 Lab Prep	W1	Metal	Brown	None	0	N/A	N/A
1	2	Classroom 217 Lab Prep	W2	Concrete	Tan	None	0	N/A	N/A
1	2	Classroom 217 Lab Prep	W3	Concrete	Tan	None	0	N/A	N/A
1	2	Classroom 217 Lab Prep	W3	Metal	Tan	None	0	N/A	N/A
1	2	Classroom 217 Lab Prep	W4	Concrete	Tan	None	0	N/A	N/A
1	2	Classroom 217 Lab Prep	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
1	2	Classroom 217 Lab Prep	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Lab Prep Classroom 217	W1	Concrete	Tan	None	0	N/A	N/A
1	2	Room 214 Learning Support	W1	Concrete	White/Blue	None	0	N/A	N/A
1	2	Room 214 Learning Support	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Room 214 Learning Support	W2	Concrete	White	None	0	N/A	N/A
1	2	Room 214 Learning Support	W3	Concrete	White/Blue	None	0	N/A	N/A
1	2	Room 214 Learning Support	W3	Metal	Blue	None	0	N/A	N/A
1	2	Room 214 Learning Support	W4	Concrete	White/Blue	None	0	N/A	N/A
1	2	Room 214 Learning Support	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Room 214 Learning Support	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	2	Classroom 216/218 Art	W1	Concrete	Multi	None	0	N/A	N/A
1	2	Classroom 216/218 Art	W1	Metal	Black/Gray	None	0	N/A	N/A
1	2	Classroom 216/218 Art	W2	Concrete	Multi	None	0	N/A	N/A
1	2	Classroom 216/218 Art	W3	Concrete	Multi	None	0	N/A	N/A
1	2	Classroom 216/218 Art	W3	Metal	Black	None	0	N/A	N/A
1	2	Classroom 216/218 Art	W4	Concrete	Multi	None	0	N/A	N/A
1	2	Classroom 216/218 Art	Ceiling	Concrete	White	Flaking	20	0.2	Negative
1	2	Classroom 216/218 Art	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	2	Classroom 219	W1	Concrete	Blue / White	None	0	N/A	N/A
1	2	Classroom 219	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Classroom 219	W2	Concrete	Blue / White	None	0	N/A	N/A
1	2	Classroom 219	W3	Concrete	Blue / White	None	0	N/A	N/A
1	2	Classroom 219	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 219	W4	Concrete	Blue / White	None	0	N/A	N/A
1	2	Classroom 219	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 219	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	2	Classroom 220 Music	W1	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 220 Music	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Classroom 220 Music	W2	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 220 Music	W3	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 220 Music	W3	Metal	Blue	None	0	N/A	N/A
1	2	Classroom 220 Music	W4	Concrete	Blue/White	None	0	N/A	N/A
1	2	Classroom 220 Music	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Classroom 220 Music	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 220	W1	Concrete	Blue/White	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 220	W1	Metal	Gray/Blue	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Boy's Restroom across from Classroom 220	W2	Concrete	Blue/White	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 220	W3	Concrete	Blue/White	Flaking	4	-0.3	Negative
1	2	Boy's Restroom across from Classroom 220	W3	Metal	Blue	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 220	W4	Concrete	Blue/White	None	0	N/A	N/A
1	2	Boy's Restroom across from Classroom 220	Ceiling	Concrete	White	Flaking	15	0.4	Negative
1	2	Boy's Restroom across from Classroom 220	Floor	Concrete	Cement	None	0	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 220	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 220	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 220	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 220	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 220	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Restroom across from Classroom 220	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom near Classroom 220	W1	Concrete	Purple/White	None	0	N/A	N/A
1	2	Girl's Restroom near Classroom 220	W1	Metal	Purple/Gray	None	0	N/A	N/A
1	2	Girl's Restroom near Classroom 220	W2	Concrete	Purple/White	None	0	N/A	N/A
1	2	Girl's Restroom near Classroom 220	W3	Concrete	Purple/White	None	0	N/A	N/A
1	2	Girl's Restroom near Classroom 220	W3	Metal	Purple	None	0	N/A	N/A
1	2	Girl's Restroom near Classroom 220	W4	Concrete	Purple/White	None	0	N/A	N/A
1	2	Girl's Restroom near Classroom 220	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Girl's Restroom near Classroom 220	Floor	Concrete	Gray	None	0	N/A	N/A
1	2	Stairwell No. 1 near Classroom 220	W1	Concrete	Yellow/White	None	0	N/A	N/A
1	2	Stairwell No. 1 near Classroom 220	W2	Concrete	Yellow/White	None	0	N/A	N/A
1	2	Stairwell No. 1 near Classroom 220	W3	Concrete	Yellow/White	None	0	N/A	N/A
1	2	Stairwell No. 1 near Classroom 220	W3	Metal	Gray	None	0	N/A	N/A
1	2	Stairwell No. 1 near Classroom 220	W4	Concrete	Yellow/White	Flaking	20	-0.5	Negative
1	2	Stairwell No. 1 near Classroom 220	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Stairwell No. 1 near Classroom 220	Floor	Concrete	White	None	0	N/A	N/A
1	2	Custodial Closet across from Classroom 220	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 220	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 220	W3	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Custodial Closet across from Classroom 220	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 220	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet across from Classroom 220	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Men's Restroom across from Classroom 220	W1	Concrete	Blue	Flaking	1	-0.6	Negative
1	2	Men's Restroom across from Classroom 220	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	2	Men's Restroom across from Classroom 220	W2	Concrete	Blue	None	0	N/A	N/A
1	2	Men's Restroom across from Classroom 220	W3	Concrete	Blue	None	0	N/A	N/A
1	2	Men's Restroom across from Classroom 220	W4	Concrete	Blue	None	0	N/A	N/A
1	2	Men's Restroom across from Classroom 220	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Men's Restroom across from Classroom 220	Floor	Concrete	Gray	None	0	N/A	N/A
1	2	Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	W1	Concrete	Multi	Flaking	80	-0.6	Negative
1	2	Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	W3	Concrete	Multi	Flaking	45	-0.1	Negative
1	2	Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	W4	Concrete	Blue	Flaking	12	-0.5	Negative
1	2	Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	Floor	9 x 9 Tile	Brown	None	0	N/A	N/A
1	2	Hallway from Classroom 200 to Classroom 210	W1	Concrete	Blue/White	None	0	N/A	N/A
1	2	Hallway from Classroom 200 to Classroom 210	W2	Concrete	Blue/White	Flaking	75	-0.5	Negative
1	2	Hallway from Classroom 200 to Classroom 210	W3	Concrete	Blue/White	Flaking	4	-0.5	Negative
1	2	Hallway from Classroom 200 to Classroom 210	W4	Concrete	Blue/White	Flaking	30	0.1	Negative
1	2	Hallway from Classroom 200 to Classroom 210	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Hallway from Classroom 200 to Classroom 210	Floor	9 x 9 Tile	Brown	None	0	N/A	N/A
1	2	Throughout 2nd Floor	W1	-	-	-	-	-	-
1	2	Throughout 2nd Floor	W2	-	-	-	-	-	-
1	2	Throughout 2nd Floor	W3	-	-	-	-	-	-
1	2	Throughout 2nd Floor	W4	-	-	-	-	-	-
1	2	Throughout 2nd Floor	Ceiling	-	-	-	-	-	-
1	2	Throughout 2nd Floor	Floor	-	-	-	-	-	-
1	3	Stairwell across from Classroom 300	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Stairwell across from Classroom 300	W2	Concrete	Blue/White	Flaking	50	-0.5	Negative
1	3	Stairwell across from Classroom 300	W3	Concrete	Blue/White	Flaking	20	-0.4	Negative
1	3	Stairwell across from Classroom 300	W3	Metal	Gray	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Stairwell across from Classroom 300	W4	Concrete	Blue/White	Flaking	15	-0.2	Negative
1	3	Stairwell across from Classroom 300	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Stairwell across from Classroom 300	Floor	Concrete	Gray	None	0	N/A	N/A
1	3	Classroom 300	W1	Concrete	Purple/White	None	0	N/A	N/A
1	3	Classroom 300	W1	Metal	Purple/Gray	None	0	N/A	N/A
1	3	Classroom 300	W1	Transite	Purple	Flaking	5	0.1	Negative
1	3	Classroom 300	W2	Concrete	Purple/White	None	0	N/A	N/A
1	3	Classroom 300	W3	Concrete	Purple/White	Flaking	5	-0.1	Negative
1	3	Classroom 300	W3	Metal	Purple	None	0	N/A	N/A
1	3	Classroom 300	W4	Concrete	Purple/White	None	0	N/A	N/A
1	3	Classroom 300	Ceiling	Concrete	Purple/White	None	0	N/A	N/A
1	3	Classroom 300	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Girl's Restroom across from Classroom 300	W1	Concrete	Pink/White	None	0	N/A	N/A
1	3	Girl's Restroom across from Classroom 300	W1	Metal	Pink	None	0	N/A	N/A
1	3	Girl's Restroom across from Classroom 300	W2	Concrete	Pink/White	None	0	N/A	N/A
1	3	Girl's Restroom across from Classroom 300	W3	Concrete	Pink/White	Alligatoring	10	-0.5	Negative
1	3	Girl's Restroom across from Classroom 300	W3	Metal	Pink	None	0	N/A	N/A
1	3	Girl's Restroom across from Classroom 300	W4	Concrete	Pink/White	None	0	N/A	N/A
1	3	Girl's Restroom across from Classroom 300	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Girl's Restroom across from Classroom 300	Floor	Concrete	Gray	None	0	N/A	N/A
1	3	Custodial Closet across from Classroom 300	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet across from Classroom 300	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet across from Classroom 300	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet across from Classroom 300	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet across from Classroom 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet across from Classroom 300	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books B-3 Storage Room near Classroom 302	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books B-3 Storage Room near Classroom 302	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books B-3 Storage Room near Classroom 302	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books B-3 Storage Room near Classroom 302	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books B-3 Storage Room near Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books B-3 Storage Room near Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	W1	Concrete	Blue/White	Flaking	2	-0.3	Negative
1	3	Boy's Restroom across from Classroom 302	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	W2	Concrete	Blue/White	Flaking	40	-0.2	Negative

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Boy's Restroom across from Classroom 302	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	W3	Metal	Blue	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	W4	Concrete	Blue/White	Flaking	40	-0.4	Negative
1	3	Boy's Restroom across from Classroom 302	Ceiling	Concrete	White	Alligatoring	10	0.2	Negative
1	3	Boy's Restroom across from Classroom 302	Floor	Concrete	Gray	None	0	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 302	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 302	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 302	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 302	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 302	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 302	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 302	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 302	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 302	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 302	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 302	Ceiling	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 302	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Classroom 301	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 301	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 301	W1	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 301	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 301	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 301	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 301	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 301	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 301	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	3	Classroom 304	W1	Concrete	Blue/White	Flaking	4	0.2	Negative
1	3	Classroom 304	W1	Metal	Blue/Gray	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	3	Classroom 304	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 304	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 304	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 304	W4	Concrete	Blue/White	Flaking	3	0	Negative
1	3	Classroom 304	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 304	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	3	Classroom 303	W1	Concrete	Pink/White	None	0	N/A	N/A
1	3	Classroom 303	W1	Metal	Pink/Gray	None	0	N/A	N/A
1	3	Classroom 303	W2	Concrete	Pink/White	None	0	N/A	N/A
1	3	Classroom 303	W3	Concrete	Pink/White	None	0	N/A	N/A
1	3	Classroom 303	W3	Metal	Pink	None	0	N/A	N/A
1	3	Classroom 303	W4	Concrete	Pink/White	None	0	N/A	N/A
1	3	Classroom 303	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 303	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Classroom 306	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 306	W1	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 306	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 306	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 306	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 306	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 306	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 306	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Classroom 305	W1	Concrete	Gray	None	0	N/A	N/A
1	3	Classroom 305	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 305	W2	Concrete	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 305	W3	Concrete	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 305	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 305	W4	Concrete	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 305	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 305	Floor	9 x 9 Tile	Grey	None	0	N/A	N/A
1	3	Stairwell No. 2 across from Classroom 308	W1	Concrete	Green/White	None	0	N/A	N/A
1	3	Stairwell No. 2 across from Classroom 308	W2	Concrete	Green/White	None	0	N/A	N/A
1	3	Stairwell No. 2 across from Classroom 308	W3	Concrete	Green/White	Flaking	3	-0.2	Negative
1	3	Stairwell No. 2 across from Classroom 308	W4	Concrete	Green/White	Flaking	10	-0.5	Negative
1	3	Stairwell No. 2 across from Classroom 308	Ceiling	Concrete	White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	3	Stairwell No. 2 across from Classroom 308	Floor	Concrete	Gray	None	0	N/A	N/A
1	3	Classroom 308	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 308	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 308	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 308	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 308	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 308	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 308	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 308	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 308	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 308	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Classroom 310	W1	Concrete	Green/White	None	0	N/A	N/A
1	3	Classroom 310	W1	Metal	White	Flaking	3	-0.1	Negative
1	3	Classroom 310	W2	Concrete	Green/White	None	0	N/A	N/A
1	3	Classroom 310	W3	Concrete	Green/White	None	0	N/A	N/A
1	3	Classroom 310	W3	Metal	Green	None	0	N/A	N/A
1	3	Classroom 310	W4	Concrete	Green/White	None	0	N/A	N/A
1	3	Classroom 310	Ceiling	Concrete	White	Alligating	15	0.3	Negative
1	3	Classroom 310	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Classroom 312	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 312	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 312	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 312	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 312	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 312	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 312	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 312	Floor	9 x 9 Tile	White	None	0	N/A	N/A
1	3	Women's Restroom across from Classroom 314	W1	Concrete	Multi	None	0	N/A	N/A
1	3	Women's Restroom across from Classroom 314	W1	Metal	Gray	None	0	N/A	N/A
1	3	Women's Restroom across from Classroom 314	W2	Concrete	Multi	None	0	N/A	N/A
1	3	Women's Restroom across from Classroom 314	W3	Concrete	Multi	None	0	N/A	N/A
1	3	Women's Restroom across from Classroom 314	W4	Concrete	Multi	None	0	N/A	N/A
1	3	Women's Restroom across from Classroom 314	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Women's Restroom across from Classroom 314	Floor	Concrete	Gray	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Pipe Chase in Hall by Women's Restroom across from Classroom 314	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hall by Women's Restroom across from Classroom 314	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hall by Women's Restroom across from Classroom 314	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hall by Women's Restroom across from Classroom 314	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hall by Women's Restroom across from Classroom 314	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hall by Women's Restroom across from Classroom 314	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books A-3 Storage Room across from Classroom 314	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books A-3 Storage Room across from Classroom 314	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books A-3 Storage Room across from Classroom 314	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books A-3 Storage Room across from Classroom 314	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books A-3 Storage Room across from Classroom 314	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Books A-3 Storage Room across from Classroom 314	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Computer Lab 316	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Computer Lab 316	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Computer Lab 316	W1	Metal	Black	None	0	N/A	N/A
1	3	Computer Lab 316	W2	Wood	Brown	None	0	N/A	N/A
1	3	Computer Lab 316	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Computer Lab 316	W3	Metal	Blue	None	0	N/A	N/A
1	3	Computer Lab 316	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Computer Lab 316	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Computer Lab 316	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Classroom 317	W1	Concrete	Pink/White	None	0	N/A	N/A
1	3	Classroom 317	W1	Metal	Pink/Gray	None	0	N/A	N/A
1	3	Classroom 317	W2	Concrete	Pink/White	None	0	N/A	N/A
1	3	Classroom 317	W3	Concrete	Pink/White	None	0	N/A	N/A
1	3	Classroom 317	W3	Metal	Pink	None	0	N/A	N/A
1	3	Classroom 317	W4	Concrete	Pink/White	None	0	N/A	N/A
1	3	Classroom 317	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 317	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Classroom 318	W1	Concrete	Blue / White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	3	Classroom 318	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 318	W2	Concrete	Blue / White	None	0	N/A	N/A
1	3	Classroom 318	W3	Concrete	Blue / White	None	0	N/A	N/A
1	3	Classroom 318	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 318	W4	Concrete	Blue / White	Flaking	2	0.1	Negative
1	3	Classroom 318	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 318	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Classroom 319	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 319	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 319	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 319	W3	Concrete	Blue/White	Flaking	4	-0.3	Negative
1	3	Classroom 319	W3	Metal	Blue	None	0	N/A	N/A
1	3	Classroom 319	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 319	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 319	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	3	Classroom 320	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 320	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Classroom 320	W2	Concrete	Blue/White	Flaking	3	-0.5	Negative
1	3	Classroom 320	W3	Concrete	Blue/White	Flaking	10	-0.1	Negative
1	3	Classroom 320	W3	Metal	Blue/White	None	0	N/A	N/A
1	3	Classroom 320	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Classroom 320	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Classroom 320	Floor	9 x 9 Tile	Tan	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 320	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 320	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 320	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 320	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 320	W3	Metal	Blue	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 320	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 320	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Boy's Restroom across from Classroom 320	Floor	Concrete	Concrete	None	0	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 320	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 320	W2	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Pipe Chase in Boy's Restroom across from Classroom 320	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 320	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 320	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Boy's Restroom across from Classroom 320	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Men's Restroom across from Classroom 320	W1	Concrete	Purple	None	0	N/A	N/A
1	3	Men's Restroom across from Classroom 320	W1	Metal	Purple/Gray	None	0	N/A	N/A
1	3	Men's Restroom across from Classroom 320	W2	Concrete	Purple	None	0	N/A	N/A
1	3	Men's Restroom across from Classroom 320	W3	Concrete	Purple	None	0	N/A	N/A
1	3	Men's Restroom across from Classroom 320	W4	Concrete	Purple	None	0	N/A	N/A
1	3	Men's Restroom across from Classroom 320	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Men's Restroom across from Classroom 320	Floor	Concrete	Gray	None	0	N/A	N/A
1	3	Custodial Closet near Classroom 320	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet near Classroom 320	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet near Classroom 320	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet near Classroom 320	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet near Classroom 320	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet near Classroom 320	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Girl's Restroom near Classroom 320	W1	Concrete	Purple/White	Flaking	4	-0.3	Negative
1	3	Girl's Restroom near Classroom 320	W1	Metal	Purple/Pink	None	0	N/A	N/A
1	3	Girl's Restroom near Classroom 320	W2	Concrete	Purple/White	Flaking	10	-0.4	Negative
1	3	Girl's Restroom near Classroom 320	W3	Concrete	Purple/White	Flaking	3	-0.3	Negative
1	3	Girl's Restroom near Classroom 320	W3	Metal	White	None	0	N/A	N/A
1	3	Girl's Restroom near Classroom 320	W4	Concrete	Purple/White	None	0	N/A	N/A
1	3	Girl's Restroom near Classroom 320	Ceiling	Concrete	White	Flaking	25	0.4	Negative
1	3	Girl's Restroom near Classroom 320	Floor	Concrete	Gray	None	0	N/A	N/A
1	3	Stairwell No. 1 near Classroom 320	W1	Concrete	Yellow/White	Flaking	20	-0.5	Negative
1	3	Stairwell No. 1 near Classroom 320	W2	Concrete	Yellow/White	Flaking	30	-0.2	Negative
1	3	Stairwell No. 1 near Classroom 320	W3	Concrete	Yellow/White	Flaking	10	-0.4	Negative
1	3	Stairwell No. 1 near Classroom 320	W3	Metal	Gray	None	0	N/A	N/A
1	3	Stairwell No. 1 near Classroom 320	W4	Concrete	Yellow/White	Flaking	8	-0.3	Negative
1	3	Stairwell No. 1 near Classroom 320	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Stairwell No. 1 near Classroom 320	Floor	Concrete	Gray	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	3	Hallway from Stairwell No. 1 near Classroom 320 to Elevator and Classroom 312	W1	Concrete	Green/White	None	0	N/A	N/A
1	3	Hallway from Stairwell No. 1 near Classroom 320 to Elevator and Classroom 312	W2	Concrete	Green/White	None	0	N/A	N/A
1	3	Hallway from Stairwell No. 1 near Classroom 320 to Elevator and Classroom 312	W3	Concrete	Green/White	None	0	N/A	N/A
1	3	Hallway from Stairwell No. 1 near Classroom 320 to Elevator and Classroom 312	W4	Concrete	Green/White	None	0	N/A	N/A
1	3	Hallway from Stairwell No. 1 near Classroom 320 to Elevator and Classroom 312	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Hallway from Stairwell No. 1 near Classroom 320 to Elevator and Classroom 312	Floor	9 x 9 Tile	Brown	None	0	N/A	N/A
1	3	Hallway from Classroom 300 to Classroom 310	W1	Concrete	Green/White	None	0	N/A	N/A
1	3	Hallway from Classroom 300 to Classroom 310	W2	Concrete	Green/White	None	0	N/A	N/A
1	3	Hallway from Classroom 300 to Classroom 310	W3	Concrete	Green/White	None	0	N/A	N/A
1	3	Hallway from Classroom 300 to Classroom 310	W4	Concrete	Green/White	None	0	N/A	N/A
1	3	Hallway from Classroom 300 to Classroom 310	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Hallway from Classroom 300 to Classroom 310	Floor	9 x 9 Tile	Brown	None	0	N/A	N/A
1	3	Room 314 Teacher Office	W1	Concrete	Blue/White	None	0	N/A	N/A
1	3	Room 314 Teacher Office	W1	Metal	Blue/Gray	None	0	N/A	N/A
1	3	Room 314 Teacher Office	W2	Concrete	Blue/White	None	0	N/A	N/A
1	3	Room 314 Teacher Office	W3	Concrete	Blue/White	None	0	N/A	N/A
1	3	Room 314 Teacher Office	W3	Metal	Blue	None	0	N/A	N/A
1	3	Room 314 Teacher Office	W4	Concrete	Blue/White	None	0	N/A	N/A
1	3	Room 314 Teacher Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	Room 314 Teacher Office	Floor	9 x 9 Tile	Gray	None	0	N/A	N/A
1	4	Elevator machine room - entrance through S37-3	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	4	Elevator machine room - entrance through S37-3	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	4	Elevator machine room - entrance through S37-3	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	4	Elevator machine room - entrance through S37-3	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	4	Elevator machine room - entrance through S37-3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	Elevator machine room - entrance through S37-3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Throughout 3rd Floor	W1	-	-	-	-	-	-
1	3	Throughout 3rd Floor	W2	-	-	-	-	-	-
1	3	Throughout 3rd Floor	W3	-	-	-	-	-	-
1	3	Throughout 3rd Floor	W4	-	-	-	-	-	-

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Throughout 3rd Floor	Ceiling	-	-	-	-	-	-
1	3	Throughout 3rd Floor	Floor	-	-	-	-	-	-
3	1	School Psychologist and Band Practice Room	W1	Concrete	White	Flaking	15	0.1	Negative
3	1	School Psychologist and Band Practice Room	W1	Metal	Blue	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room	W2	Sheetrock	White	Flaking	5	-0.1	Negative
3	1	School Psychologist and Band Practice Room	W3	Concrete	White	Flaking	10	-0.1	Negative
3	1	School Psychologist and Band Practice Room	W3	Metal	blue	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room	W4	Concrete	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Closet	W1	Sheetrock	White	Flaking	7	0	Negative
3	1	School Psychologist and Band Practice Room Closet	W1	Metal	Blue	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Closet	W2	Sheetrock	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Closet	W3	Concrete	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Closet	W4	Concrete	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Closet	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Closet	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Storage between Restroom and Closet	W2	Sheetrock	White	Flaking	2	-0.1	Negative
3	1	School Psychologist and Band Practice Room Storage between Restroom and Closet	W3	Concrete	White	Flaking	2	0.2	Negative
3	1	School Psychologist and Band Practice Room Storage between Restroom and Closet	W4	Sheetrock	White	Flaking	3	0	Negative
3	1	School Psychologist and Band Practice Room Storage between Restroom and Closet	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Storage between Restroom and Closet	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Restroom	W1	Sheetrock	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Restroom	W1	Metal	Blue	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Restroom	W2	Sheetrock	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Restroom	W3	Concrete	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Restroom	W4	Sheetrock	White	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
3	1	School Psychologist and Band Practice Room Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	School Psychologist and Band Practice Room Restroom	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	ESOL Room	W1	Concrete	White	Flaking	40	0.4	Negative
3	1	ESOL Room	W1	Metal	Blue	None	0	N/A	N/A
3	1	ESOL Room	W2	Sheetrock	White	None	0	N/A	N/A
3	1	ESOL Room	W3	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room	W3	Metal	Blue	None	0	N/A	N/A
3	1	ESOL Room	W4	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	ESOL Room Storage and Meter Room	W1	Sheetrock	White	None	0	N/A	N/A
3	1	ESOL Room Storage and Meter Room	W1	Metal	Blue	None	0	N/A	N/A
3	1	ESOL Room Storage and Meter Room	W2	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room Storage and Meter Room	W3	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room Storage and Meter Room	W4	Sheetrock	White	None	0	N/A	N/A
3	1	ESOL Room Storage and Meter Room	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room Storage and Meter Room	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	ESOL Room Storage between Restroom and Meter Room	W2	Sheetrock	White	None	0	N/A	N/A
3	1	ESOL Room Storage between Restroom and Meter Room	W3	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room Storage between Restroom and Meter Room	W4	Sheetrock	White	None	0	N/A	N/A
3	1	ESOL Room Storage between Restroom and Meter Room	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room Storage between Restroom and Meter Room	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	ESOL Room Restroom	W1	Sheetrock	White	None	0	N/A	N/A
3	1	ESOL Room Restroom	W1	Metal	Blue	None	0	N/A	N/A
3	1	ESOL Room Restroom	W2	Sheetrock	White	None	0	N/A	N/A
3	1	ESOL Room Restroom	W3	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room Restroom	W4	Sheetrock	White	None	0	N/A	N/A
3	1	ESOL Room Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	ESOL Room Restroom	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
3	1	ESOL Room Entrance Area	W1	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	W2	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	W3	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	W4	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	Ceiling	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	Floor	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	W1	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	W2	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	W3	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	W4	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	Ceiling	-	-	-	-	-	-
3	1	ESOL Room Entrance Area	Floor	-	-	-	-	-	-
3	1	Home and School Office	W1	Concrete	Yellow	None	0	N/A	N/A
3	1	Home and School Office	W1	Metal	Blue	None	0	N/A	N/A
3	1	Home and School Office	W2	Concrete	Blue	None	0	N/A	N/A
3	1	Home and School Office	W3	Concrete	Yellow	None	0	N/A	N/A
3	1	Home and School Office	W3	Metal	Blue	None	0	N/A	N/A
3	1	Home and School Office	W4	Sheetrock	Yellow/Blue	None	0	N/A	N/A
3	1	Home and School Office	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
3	1	Home and School Office	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	Home and School Office Restroom	W1	Sheetrock	White	None	0	N/A	N/A
3	1	Home and School Office Restroom	W2	Sheetrock	White	None	0	N/A	N/A
3	1	Home and School Office Restroom	W3	Sheetrock	White	None	0	N/A	N/A
3	1	Home and School Office Restroom	W4	Sheetrock	White	None	0	N/A	N/A
3	1	Home and School Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	Home and School Office Restroom	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	Home and School Office Storage next to Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Storage next to Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Storage next to Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Storage next to Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Storage next to Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Storage next to Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
3	1	Home and School Office Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Home and School Rear Office Area	W1	-	-	-	-	-	-
3	1	Home and School Rear Office Area	W2	-	-	-	-	-	-
3	1	Home and School Rear Office Area	W3	-	-	-	-	-	-
3	1	Home and School Rear Office Area	W4	-	-	-	-	-	-
3	1	Home and School Rear Office Area	Ceiling	-	-	-	-	-	-
3	1	Home and School Rear Office Area	Floor	-	-	-	-	-	-
3	1	Hallway from Classroom A14 to ESOL Room	W1	Concrete	White	None	0	N/A	N/A
3	1	Hallway from Classroom A14 to ESOL Room	W2	Concrete	White	None	0	N/A	N/A
3	1	Hallway from Classroom A14 to ESOL Room	W2	Metal	Blue	None	0	N/A	N/A
3	1	Hallway from Classroom A14 to ESOL Room	W3	Concrete	White	None	0	N/A	N/A
3	1	Hallway from Classroom A14 to ESOL Room	W4	Concrete	White	None	0	N/A	N/A
3	1	Hallway from Classroom A14 to ESOL Room	W4	Metal	blue	None	0	N/A	N/A
3	1	Hallway from Classroom A14 to ESOL Room	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	Hallway from Classroom A14 to ESOL Room	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	Counseling Office	W1	Concrete	White/Blue	None	0	N/A	N/A
3	1	Counseling Office	W1	Metal	Blue	None	0	N/A	N/A
3	1	Counseling Office	W2	Concrete	White/Blue	None	0	N/A	N/A
3	1	Counseling Office	W3	Concrete	Blue	None	0	N/A	N/A
3	1	Counseling Office	W3	Metal	Blue	None	0	N/A	N/A
3	1	Counseling Office	W4	Sheetrock	Blue	None	0	N/A	N/A
3	1	Counseling Office	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
3	1	Counseling Office	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	Counseling Office Closet	W1	Sheetrock	White	None	0	N/A	N/A
3	1	Counseling Office Closet	W1	Metal	Blue	None	0	N/A	N/A
3	1	Counseling Office Closet	W2	Sheetrock	White	None	0	N/A	N/A
3	1	Counseling Office Closet	W3	Concrete	White	None	0	N/A	N/A
3	1	Counseling Office Closet	W4	Concrete	White	None	0	N/A	N/A
3	1	Counseling Office Closet	Ceiling	Concrete	White	Flaking	1	0.1	Negative
3	1	Counseling Office Closet	Floor	12 x 12 Tile	Gray	None	0	N/A	N/A
3	1	Counseling Office Storage next to Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Counseling Office Storage next to Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Counseling Office Storage next to Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
3	1	Counseling Office Storage next to Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Counseling Office Storage next to Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Counseling Office Storage next to Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Counseling Office Restroom	W1	Sheetrock	White	None	0	N/A	N/A
3	1	Counseling Office Restroom	W1	Metal	Blue	None	0	N/A	N/A
3	1	Counseling Office Restroom	W2	Sheetrock	White	None	0	N/A	N/A
3	1	Counseling Office Restroom	W3	Concrete	White	Flaking	3	0.5	Negative
3	1	Counseling Office Restroom	W4	Sheetrock	White	None	0	N/A	N/A
3	1	Counseling Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
3	1	Counseling Office Restroom	Floor	12 x 12 Tile	Gray	None	0	N/A	N/A
3	1	Smaller Counselling Office in Counseling Office	W1	Sheetrock	Blue	None	0	N/A	N/A
3	1	Smaller Counselling Office in Counseling Office	W1	Metal	White	None	0	N/A	N/A
3	1	Smaller Counselling Office in Counseling Office	W2	Concrete	Blue	None	0	N/A	N/A
3	1	Smaller Counselling Office in Counseling Office	W3	Sheetrock	Blue	None	0	N/A	N/A
3	1	Smaller Counselling Office in Counseling Office	W4	Concrete	Blue	None	0	N/A	N/A
3	1	Smaller Counselling Office in Counseling Office	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
3	1	Smaller Counselling Office in Counseling Office	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
3	1	Counseling Office Entrance Area	W1	-	-	-	-	-	-
3	1	Counseling Office Entrance Area	W2	-	-	-	-	-	-
3	1	Counseling Office Entrance Area	W3	-	-	-	-	-	-
3	1	Counseling Office Entrance Area	W4	-	-	-	-	-	-
3	1	Counseling Office Entrance Area	Ceiling	-	-	-	-	-	-
3	1	Counseling Office Entrance Area	Floor	-	-	-	-	-	-
4	1	Classroom A2	W1	Concrete	White	None	0	N/A	N/A
4	1	Classroom A2	W1	Metal	White/Blue	None	0	N/A	N/A
4	1	Classroom A2	W2	Concrete	White	None	0	N/A	N/A
4	1	Classroom A2	W3	Concrete	White	Efflorescence	175	-0.1	Negative
4	1	Classroom A2	W3	Metal	White	None	0	N/A	N/A
4	1	Classroom A2	W4	Concrete	White	None	0	N/A	N/A
4	1	Classroom A2	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A2	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Classroom A1	W1	Concrete	White/Tan	None	0	N/A	N/A
4	1	Classroom A1	W1	Metal	Brown/Blue	None	0	N/A	N/A
4	1	Classroom A1	W2	Concrete	White/Tan	None	0	N/A	N/A
4	1	Classroom A1	W3	Concrete	White/Tan	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
4	1	Classroom A1	W4	Concrete	White/Tan	None	0	N/A	N/A
4	1	Classroom A1	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A1	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Classroom A4	W1	Concrete	White	None	0	N/A	N/A
4	1	Classroom A4	W1	Metal	White/Blue	None	0	N/A	N/A
4	1	Classroom A4	W2	Concrete	White	None	0	N/A	N/A
4	1	Classroom A4	W3	Concrete	Blue	Efflorescence	100	0	Negative
4	1	Classroom A4	W3	Metal	White	None	0	N/A	N/A
4	1	Classroom A4	W4	Concrete	Blue	None	0	N/A	N/A
4	1	Classroom A4	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A4	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Classroom A3	W1	Concrete	White/Blue	None	0	N/A	N/A
4	1	Classroom A3	W1	Metal	Gray	None	0	N/A	N/A
4	1	Classroom A3	W2	Concrete	White/Blue	None	0	N/A	N/A
4	1	Classroom A3	W3	Concrete	White/Blue	None	0	N/A	N/A
4	1	Classroom A3	W3	Metal	Gray	None	0	N/A	N/A
4	1	Classroom A3	W4	Concrete	White	None	0	N/A	N/A
4	1	Classroom A3	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A3	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Classroom A6	W1	Concrete	White/Blue	None	0	N/A	N/A
4	1	Classroom A6	W1	Metal	Blue	None	0	N/A	N/A
4	1	Classroom A6	W2	Concrete	White/Blue	None	0	N/A	N/A
4	1	Classroom A6	W3	Concrete	White/Blue	None	0	N/A	N/A
4	1	Classroom A6	W3	Metal	Blue	None	0	N/A	N/A
4	1	Classroom A6	W4	Concrete	White	None	0	N/A	N/A
4	1	Classroom A6	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A6	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Classroom A5	W1	Concrete	White/Blue	None	0	N/A	N/A
4	1	Classroom A5	W1	Metal	Brown/Blue	None	0	N/A	N/A
4	1	Classroom A5	W2	Concrete	White/Blue	None	0	N/A	N/A
4	1	Classroom A5	W3	Concrete	White	None	0	N/A	N/A
4	1	Classroom A5	W3	Metal	Brown	None	0	N/A	N/A
4	1	Classroom A5	W4	Concrete	White	None	0	N/A	N/A
4	1	Classroom A5	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A5	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4	1	Boy's Restroom	W1	Concrete	Brown/White	None	0	N/A	N/A
4	1	Boy's Restroom	W1	Metal	Blue	None	0	N/A	N/A
4	1	Boy's Restroom	W2	Concrete	Brown/White	None	0	N/A	N/A
4	1	Boy's Restroom	W3	Concrete	Brown/White	None	0	N/A	N/A
4	1	Boy's Restroom	W4	Concrete	Brown/White	None	0	N/A	N/A
4	1	Boy's Restroom	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Boy's Restroom	Floor	Ceramic Tile	Blue/White	None	0	N/A	N/A
4	1	Pipe Chase inside Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase inside Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase inside Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase inside Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase inside Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase inside Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase outside Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase outside Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase outside Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase outside Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase outside Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Pipe Chase outside Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Girl's Restroom	W1	Concrete	Brown/White	None	0	N/A	N/A
4	1	Girl's Restroom	W1	Metal	Blue	None	0	N/A	N/A
4	1	Girl's Restroom	W2	Concrete	Brown/White	None	0	N/A	N/A
4	1	Girl's Restroom	W3	Concrete	Brown/White	None	0	N/A	N/A
4	1	Girl's Restroom	W4	Concrete	Brown/White	None	0	N/A	N/A
4	1	Girl's Restroom	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Girl's Restroom	Floor	Ceramic Tile	Brown/White	None	0	N/A	N/A
4	1	Teacher's Lounge by Classroom A8	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Teacher's Lounge by Classroom A8	W1	Metal	Blue	None	0	N/A	N/A
4	1	Teacher's Lounge by Classroom A8	W2	Concrete	Blue/White	None	0	N/A	N/A
4	1	Teacher's Lounge by Classroom A8	W3	Concrete	Blue/White	None	0	N/A	N/A
4	1	Teacher's Lounge by Classroom A8	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Teacher's Lounge by Classroom A8	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Teacher's Lounge by Classroom A8	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Staff Restroom next to Boy's Restroom	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Staff Restroom next to Boy's Restroom	W1	Metal	Blue/Gray	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4	1	Staff Restroom next to Boy's Restroom	W2	Concrete	Blue/White	None	0	N/A	N/A
4	1	Staff Restroom next to Boy's Restroom	W3	Concrete	Blue/White	None	0	N/A	N/A
4	1	Staff Restroom next to Boy's Restroom	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Staff Restroom next to Boy's Restroom	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Staff Restroom next to Boy's Restroom	Floor	Ceramic Tile	Brown	None	0	N/A	N/A
4	1	Staff Restroom next to Teacher's Closet	W1	Concrete	Pink/White	None	0	N/A	N/A
4	1	Staff Restroom next to Teacher's Closet	W1	Metal	Blue/Gray	None	0	N/A	N/A
4	1	Staff Restroom next to Teacher's Closet	W2	Concrete	Pink/White	None	0	N/A	N/A
4	1	Staff Restroom next to Teacher's Closet	W3	Concrete	Pink/White	None	0	N/A	N/A
4	1	Staff Restroom next to Teacher's Closet	W4	Concrete	Pink/White	None	0	N/A	N/A
4	1	Staff Restroom next to Teacher's Closet	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Staff Restroom next to Teacher's Closet	Floor	Ceramic Tile	Brown	None	0	N/A	N/A
4	1	Teacher's Closet next to Classroom A7	W1	Concrete	White	None	0	N/A	N/A
4	1	Teacher's Closet next to Classroom A7	W1	Metal	Blue/Gray	None	0	N/A	N/A
4	1	Teacher's Closet next to Classroom A7	W2	Concrete	White	None	0	N/A	N/A
4	1	Teacher's Closet next to Classroom A7	W3	Concrete	White	None	0	N/A	N/A
4	1	Teacher's Closet next to Classroom A7	W4	Concrete	White	None	0	N/A	N/A
4	1	Teacher's Closet next to Classroom A7	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Teacher's Closet next to Classroom A7	Floor	Cement	N/A	None	0	N/A	N/A
4	1	Classroom A7	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A7	W1	Metal	Blue	None	0	N/A	N/A
4	1	Classroom A7	W2	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A7	W3	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A7	W3	Metal	Blue	None	0	N/A	N/A
4	1	Classroom A7	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A7	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A7	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Classroom A8	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A8	W1	Metal	Blue	None	0	N/A	N/A
4	1	Classroom A8	W2	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A8	W3	Concrete	Blue/White	Efflorescence	20	0	Negative
4	1	Classroom A8	W3	Metal	Blue	None	0	N/A	N/A
4	1	Classroom A8	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A8	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A8	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	<b>Lead-Safe Certification Assessment Report</b>						
		Name of Inspector: Justine James	<b>Decatur School</b>						
		Inspection Company: Batta Environmental	<b>3500 Academy Rd, Philadelphia, PA 19154</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
4	1	Classroom A9	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A9	W1	Metal	Blue	None	0	N/A	N/A
4	1	Classroom A9	W2	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A9	W3	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A9	W3	Metal	Blue	None	0	N/A	N/A
4	1	Classroom A9	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Classroom A9	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A9	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Classroom A10	W1	Concrete	White	None	0	N/A	N/A
4	1	Classroom A10	W1	Metal	Blue/White	None	0	N/A	N/A
4	1	Classroom A10	W2	Concrete	White	None	0	N/A	N/A
4	1	Classroom A10	W3	Concrete	White	None	0	N/A	N/A
4	1	Classroom A10	W3	Metal	White	None	0	N/A	N/A
4	1	Classroom A10	W4	Concrete	White	None	0	N/A	N/A
4	1	Classroom A10	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Classroom A10	Floor	12 x 12 Tile	Tan	None	0	N/A	N/A
4	1	Hallway from near Classroom A8 to Exit Doors	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from near Classroom A8 to Exit Doors	W3	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from near Classroom A8 to Exit Doors	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from near Classroom A8 to Exit Doors	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Hallway from near Classroom A8 to Exit Doors	Floor	Concrete	Gray	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	W2	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	W3	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	W2	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	W3	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Hallway from Classroom A8 to Girl's Restroom	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
4	1	Mechanical Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Mechanical Room	W2	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 4/12/2021-4/15/2021	Lead-Safe Certification Assessment Report						
		Name of Inspector: Justine James	Decatur School						
		Inspection Company: Batta Environmental	3500 Academy Rd, Philadelphia, PA 19154						
E l e m e n t	F l o o r	On Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
4	1	Mechanical Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Mechanical Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Mechanical Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Mechanical Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4	1	Hallway from Classroom A1 to Classroom A5	W1	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A1 to Classroom A5	W2	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A1 to Classroom A5	W3	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A1 to Classroom A5	W4	Concrete	Blue/White	None	0	N/A	N/A
4	1	Hallway from Classroom A1 to Classroom A5	Ceiling	Drop Ceiling	White	None	0	N/A	N/A
4	1	Hallway from Classroom A1 to Classroom A5	Floor	12 x 12 Tile	Multi	None	0	N/A	N/A
1	C	Crawl Space accessible near Basement Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Basement Boiler Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Basement Boiler Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Basement Boiler Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Basement Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Basement Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Floor Hatch	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Floor Hatch	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Floor Hatch	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Floor Hatch	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Floor Hatch	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Floor Hatch	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Class rooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Class rooms	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Class rooms	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Class rooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Class rooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	C	Crawl Space accessible near Class rooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	A	Attic	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	A	Attic	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	A	Attic	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	A	Attic	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	A	Attic	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	A	Attic	Floor	N/A	N/A	N/A	N/A	N/A	N/A