

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	B4	Classroom B4 (Art Room)	W1	Concrete	Blue	None	0	N/A	N/A
1	B	B4	Classroom B4 (Art Room)	W2	Concrete	Tan	Efflorescence	6	5	Positive
1	B	B4	Classroom B4 (Art Room)	W3	Concrete	Tan	Efflorescence	16	0	Negative
1	B	B4	Classroom B4 (Art Room)	W4	Concrete	Tan	Efflorescence	2	1	Positive
1	B	B4	Classroom B4 (Art Room)	Ceiling	Concrete	White	None	0	5	Positive
1	B	B4	Classroom B4 (Art Room)	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	B4	Classroom B4 (Art Room)	Ventilator Shaft	Metal	Tan	Chipping	N/A	0.6	Negative
1	B	B4	Classroom B4 (Art Room)	Ventilator Unit	Metal	White	Friction	1	0	Negative
1	B	001B	Classroom B4 Storage (Art Room)	W1	Brick	Beige & Exposed Brick	None	0	N/A	N/A
1	B	001B	Classroom B4 Storage (Art Room)	W2	Brick	Beige & Exposed Brick	None	0	N/A	N/A
1	B	001B	Classroom B4 Storage (Art Room)	W3	Brick	Beige & Exposed Brick	None	0	N/A	N/A
1	B	001B	Classroom B4 Storage (Art Room)	W4	Brick	Beige & Exposed Brick	None	0	N/A	N/A
1	B	001B	Classroom B4 Storage (Art Room)	Ceiling	Concrete	Beige	None	0	N/A	N/A
1	B	001B	Classroom B4 Storage (Art Room)	Floor	Concrete	Brown	None	0	N/A	N/A
1	B	13	Prop Closet across from Classroom B4 Art Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	13	Prop Closet across from Classroom B4 Art Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	13	Prop Closet across from Classroom B4 Art Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	13	Prop Closet across from Classroom B4 Art Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	13	Prop Closet across from Classroom B4 Art Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	13	Prop Closet across from Classroom B4 Art Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	14	Storage Room in Basement Stairs next to Classroom B4 Art Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	14	Storage Room in Basement Stairs next to Classroom B4 Art Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	14	Storage Room in Basement Stairs next to Classroom B4 Art Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	14	Storage Room in Basement Stairs next to Classroom B4 Art Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	14	Storage Room in Basement Stairs next to Classroom B4 Art Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	14	Storage Room in Basement Stairs next to Classroom B4 Art Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	16	Gas Meter Room	W1	Brick	White & Teal	Chipping	20	1	Positive

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	16	Gas Meter Room	W2	Brick	White & Teal	Chipping	30	1	Positive
1	B	16	Gas Meter Room	W3	Brick	White & Teal	Chipping	40	1	Positive
1	B	16	Gas Meter Room	W4	Brick	White & Teal	Chipping	20	1	Positive
1	B	16	Gas Meter Room	Ceiling	Concrete	White	Chipping	190	1	Positive
1	B	16	Gas Meter Room	Floor	Concrete	Brown	None	0	N/A	N/A
1	B	1A	Girl's Restroom next to Classroom B4	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	B	1A	Girl's Restroom next to Classroom B4	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	B	1A	Girl's Restroom next to Classroom B4	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	B	1A	Girl's Restroom next to Classroom B4	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	B	1A	Girl's Restroom next to Classroom B4	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	1A	Girl's Restroom next to Classroom B4	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	B	1A PC	Girl's Restroom next to Classroom B4: Pipe Chase	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1A PC	Girl's Restroom next to Classroom B4: Pipe Chase	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1A PC	Girl's Restroom next to Classroom B4: Pipe Chase	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1A PC	Girl's Restroom next to Classroom B4: Pipe Chase	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1A PC	Girl's Restroom next to Classroom B4: Pipe Chase	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1A PC	Girl's Restroom next to Classroom B4: Pipe Chase	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1C	Boys Restroom next to Classroom B4	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	B	1C	Boys Restroom next to Classroom B4	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	B	1C	Boys Restroom next to Classroom B4	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	B	1C	Boys Restroom next to Classroom B4	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	B	1C	Boys Restroom next to Classroom B4	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	1C	Boys Restroom next to Classroom B4	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	B	1D	Service Closet Next to Basement Boy's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1D	Service Closet Next to Basement Boy's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1D	Service Closet Next to Basement Boy's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1D	Service Closet Next to Basement Boy's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1D	Service Closet Next to Basement Boy's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	1D	Service Closet Next to Basement Boy's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4	Boiler Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4	Boiler Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4	Boiler Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4	Boiler Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4	Boiler Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4	Boiler Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4A	Storage Room next to Boiler Room Rear	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4A	Storage Room next to Boiler Room Rear	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4A	Storage Room next to Boiler Room Rear	W3	No Access	No Access	No Access	No Access	No Access	No Access

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	4A	Storage Room next to Boiler Room Rear	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4A	Storage Room next to Boiler Room Rear	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4A	Storage Room next to Boiler Room Rear	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	4B	Building Engineer's Office next to Boiler Room	W1	Brick	White & Dark Grey	Chipping	10	0.06	Negative
1	B	4B	Building Engineer's Office next to Boiler Room	W2	Brick	White & Dark Grey	Chipping	20	1	Positive
1	B	4B	Building Engineer's Office next to Boiler Room	W3	Brick	White & Dark Grey	Chipping	20	1	Positive
1	B	4B	Building Engineer's Office next to Boiler Room	W4	Brick	White & Dark Grey	Chipping	20	1	Positive
1	B	4B	Building Engineer's Office next to Boiler Room	Ceiling	Concrete	White	Chipping	800	1	Positive
1	B	4B	Building Engineer's Office next to Boiler Room	Floor	Concrete	Grey	Friction	50	0	Negative
1	B	B3A	Office to Left rear of Cafeteria	W1	Concrete	Tan	None	0	N/A	N/A
1	B	B3A	Office to Left rear of Cafeteria	W2	Concrete	Tan	None	0	N/A	N/A
1	B	B3A	Office to Left rear of Cafeteria	W3	Concrete	Tan	None	0	N/A	N/A
1	B	B3A	Office to Left rear of Cafeteria	W4	Concrete	Tan	None	0	N/A	N/A
1	B	B3A	Office to Left rear of Cafeteria	Ceiling	Concrete	Tan	Moisture Damage	6	No Access	No Access
1	B	B3A	Office to Left rear of Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B3	Custodial Lounge next to Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B3	Custodial Lounge next to Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B3	Custodial Lounge next to Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B3	Custodial Lounge next to Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B3	Custodial Lounge next to Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B3	Custodial Lounge next to Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	12	Cafeteria	W1	Brick	Tan	None	0	0.11	Negative
1	B	12	Cafeteria	W2	Concrete	Tan	None	0	N/A	N/A
1	B	12	Cafeteria	W3	Brick	Tan	None	0	N/A	N/A
1	B	12	Cafeteria	W4	Concrete	Tan	None	0	N/A	N/A
1	B	12	Cafeteria	Ceiling	Drop Ceiling Tiles	N/A	None	0	N/A	N/A
1	B	12	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	12	Cafeteria	Trim	Concrete	Grey	Friction	1	0.12	Negative
1	B	H01	Hallway near Classroom B4 and Cafeteria areas	W1	Brick	White & Off White	None	0	N/A	N/A
1	B	H01	Hallway near Classroom B4 and Cafeteria areas	W2	Brick	White & Off White	None	0	N/A	N/A
1	B	H01	Hallway near Classroom B4 and Cafeteria areas	W3	Brick	White & Off White	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	H01	Hallway near Classroom B4 and Cafeteria areas	W4	Brick	White & Off White	None	0	N/A	N/A
1	B	H01	Hallway near Classroom B4 and Cafeteria areas	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	H01	Hallway near Classroom B4 and Cafeteria areas	Floor	Concrete	Brown	None	0	N/A	N/A
1	B	B5A	Storage Room next to Classroom B5	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B5A	Storage Room next to Classroom B5	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B5A	Storage Room next to Classroom B5	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B5A	Storage Room next to Classroom B5	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B5A	Storage Room next to Classroom B5	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B5A	Storage Room next to Classroom B5	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B5A	Storage Room next to Classroom B5	W1	Brick	Beige & Exposed Brick	None	0	N/A	N/A
1	B	B5A	Storage Room next to Classroom B5	W2	Brick	Beige & Exposed Brick	None	0	N/A	N/A
1	B	B5A	Storage Room next to Classroom B5	W3	Brick	Beige & Exposed Brick	None	0	N/A	N/A
1	B	B5A	Storage Room next to Classroom B5	W4	Brick	Beige & Exposed Brick	None	0	N/A	N/A
1	B	B5A	Storage Room next to Classroom B5	Ceiling	Concrete	Beige	None	0	N/A	N/A
1	B	B5A	Storage Room next to Classroom B5	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	B5	Classroom B5 Sensory Room	W1	Concrete	Tan	Friction	3	5	Positive
1	B	B5	Classroom B5 Sensory Room	W2	Concrete	Tan	Efflorescence	7	5	Positive
1	B	B5	Classroom B5 Sensory Room	W3	Concrete	Blue	Efflorescence	11	0	Negative
1	B	B5	Classroom B5 Sensory Room	W4	Concrete	Tan	Efflorescence	6	0	Negative
1	B	B5	Classroom B5 Sensory Room	Ceiling	Concrete	White	Flaking	7	0	Negative
1	B	B5	Classroom B5 Sensory Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B5	Classroom B5 Sensory Room	Door Frame	Wood	Grey	Chipping	3	0.21	Negative
1	B	B5	Classroom B5 Sensory Room	Ventilator Shaft	Metal	Tan	Chipping	1	0.04	Negative
1	B	B5	Classroom B5 Sensory Room	Ventilator Unit	Metal	White	Friction	1	0	Negative
1	B	B5	Classroom B5 Sensory Room	Ventilator Trim	Metal	Grey	Friction	1	0.15	Negative
1	B	11	Storage Closet/Electrical Room in Stair to Right of Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	11	Storage Closet/Electrical Room in Stair to Right of Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	11	Storage Closet/Electrical Room in Stair to Right of Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	11	Storage Closet/Electrical Room in Stair to Right of Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	11	Storage Closet/Electrical Room in Stair to Right of Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	11	Storage Closet/Electrical Room in Stair to Right of Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	S01	Stairs Next to Cafeteria in Basement	W1	Concrete	Tan	None	0	N/A	N/A
1	B	S01	Stairs Next to Cafeteria in Basement	W2	Brick	Tan	None	0	N/A	N/A
1	B	S01	Stairs Next to Cafeteria in Basement	W3	Concrete	Tan	None	0	N/A	N/A
1	B	S01	Stairs Next to Cafeteria in Basement	W4	Concrete	Tan	None	0	N/A	N/A
1	B	S01	Stairs Next to Cafeteria in Basement	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	S01	Stairs Next to Cafeteria in Basement	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5A	Home and School Storage Closet next to Gymnasium	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	5A	Home and School Storage Closet next to Gymnasium	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	5A	Home and School Storage Closet next to Gymnasium	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	5A	Home and School Storage Closet next to Gymnasium	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	5A	Home and School Storage Closet next to Gymnasium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	5A	Home and School Storage Closet next to Gymnasium	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	10	Custodial Closet across from Kitchen	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	10	Custodial Closet across from Kitchen	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	10	Custodial Closet across from Kitchen	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	10	Custodial Closet across from Kitchen	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	10	Custodial Closet across from Kitchen	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	10	Custodial Closet across from Kitchen	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	6A	Kitchen	W1	Concrete	Tan	None	0	N/A	N/A
1	B	6A	Kitchen	W2	Sheetrock	Tan	None	0	N/A	N/A
1	B	6A	Kitchen	W3	Concrete	Tan	None	0	N/A	N/A
1	B	6A	Kitchen	W4	Concrete	Tan	None	0	0.11	Negative
1	B	6A	Kitchen	Ceiling	Concrete	Tan	None	0	N/A	N/A
1	B	6A	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Gymnasium	W1	Concrete	Gray/White	None	0	N/A	N/A
1	B	8	Gymnasium	W2	Concrete	Gray/White	Chipping	2	0.13	Negative
1	B	8	Gymnasium	W3	Concrete	Gray/White	None	0	N/A	N/A
1	B	8	Gymnasium	W4	Concrete	Gray/White	None	0	N/A	N/A
1	B	8	Gymnasium	Ceiling	Concrete	White	Cracking	10	0	Negative
1	B	8	Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S05	Stairs leading to Entrance of Gym	W1	Concrete	Tan	None	0	N/A	N/A
1	B	S05	Stairs leading to Entrance of Gym	W2	Concrete	Tan	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	S05	Stairs leading to Entrance of Gym	W3	Concrete	Tan	None	0	N/A	N/A
1	B	S05	Stairs leading to Entrance of Gym	W4	Concrete	Tan	None	0	N/A	N/A
1	B	S05	Stairs leading to Entrance of Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	S05	Stairs leading to Entrance of Gym	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	8A	Gym Teacher's Office in Gym	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8A	Gym Teacher's Office in Gym	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8A	Gym Teacher's Office in Gym	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8A	Gym Teacher's Office in Gym	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8A	Gym Teacher's Office in Gym	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8A	Gym Teacher's Office in Gym	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8T	Gym Teacher's Office Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8T	Gym Teacher's Office Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8T	Gym Teacher's Office Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8T	Gym Teacher's Office Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8T	Gym Teacher's Office Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8T	Gym Teacher's Office Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	S06	Stairs in front of Gym to exterior	W1	Concrete	Tan	None	0	N/A	N/A
1	B	S06	Stairs in front of Gym to exterior	W2	Concrete	Tan	None	0	N/A	N/A
1	B	S06	Stairs in front of Gym to exterior	W3	Concrete	Tan	None	0	N/A	N/A
1	B	S06	Stairs in front of Gym to exterior	W4	Concrete	Tan	None	0	N/A	N/A
1	B	S06	Stairs in front of Gym to exterior	Ceiling	Concrete	Tan	None	0	N/A	N/A
1	B	S06	Stairs in front of Gym to exterior	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	S08	Stairs in Gym adjacent to Gym Office	W1	Concrete	Tan	None	0	N/A	N/A
1	B	S08	Stairs in Gym adjacent to Gym Office	W2	Concrete	Tan	None	0	N/A	N/A
1	B	S08	Stairs in Gym adjacent to Gym Office	W3	Concrete	Tan	None	0	N/A	N/A
1	B	S08	Stairs in Gym adjacent to Gym Office	W4	Concrete	Tan	None	0	N/A	N/A
1	B	S08	Stairs in Gym adjacent to Gym Office	Ceiling	Concrete	Tan	None	0	N/A	N/A
1	B	S08	Stairs in Gym adjacent to Gym Office	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	6	Classroom B6 Music Room	W1	Concrete	Tan	None	0	N/A	N/A
1	B	6	Classroom B6 Music Room	W2	Concrete	Tan w/Green	Chipping	1	0	Negative
1	B	6	Classroom B6 Music Room	W3	Concrete	Concrete	None	0	N/A	N/A
1	B	6	Classroom B6 Music Room	W4	Sheetrock	Blue	None	0	N/A	N/A
1	B	6	Classroom B6 Music Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	6	Classroom B6 Music Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H2	Hallway next to Music Classroom and Gym	W1	Concrete	Tan	None	0	N/A	N/A
1	B	H2	Hallway next to Music Classroom and Gym	W2	Concrete	Tan	Chipping	5	0	Negative
1	B	H2	Hallway next to Music Classroom and Gym	W3	Concrete	Tan	None	0	N/A	N/A
1	B	H2	Hallway next to Music Classroom and Gym	W4	Concrete	Tan	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	H2	Hallway next to Music Classroom and Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	H2	Hallway next to Music Classroom and Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S07	Stairs to Left of Classroom B6 near rear of Gym	W1	Concrete	Tan	None	0	N/A	N/A
1	B	S07	Stairs to Left of Classroom B6 near rear of Gym	W2	Concrete	Tan	None	0	N/A	N/A
1	B	S07	Stairs to Left of Classroom B6 near rear of Gym	W3	Concrete	Tan	None	0	N/A	N/A
1	B	S07	Stairs to Left of Classroom B6 near rear of Gym	W4	Concrete	Tan/Green	Chipping	2	5	Positive
1	B	S07	Stairs to Left of Classroom B6 near rear of Gym	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	S07	Stairs to Left of Classroom B6 near rear of Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W1	Concrete	Tan	None	0	0.01	Negative
1	2	201	Classroom 201	W2	Concrete	Tan	None	0	N/A	N/A
1	2	201	Classroom 201	W3	Concrete	Tan	None	0	0.07	Negative
1	2	201	Classroom 201	W4	Concrete	Orange	None	0	N/A	N/A
1	2	201	Classroom 201	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	201	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Classroom 201 Left Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201A	Classroom 201 Left Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201A	Classroom 201 Left Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201A	Classroom 201 Left Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201A	Classroom 201 Left Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201A	Classroom 201 Left Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201B	Classroom 201 Right Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201B	Classroom 201 Right Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201B	Classroom 201 Right Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201B	Classroom 201 Right Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201B	Classroom 201 Right Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	201B	Classroom 201 Right Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	202	Classroom 202	W1	Concrete	Tan	None	0	0	Negative
1	2	202	Classroom 202	W2	Concrete	Tan	None	0	N/A	N/A
1	2	202	Classroom 202	W3	Concrete	Tan	None	0	N/A	N/A
1	2	202	Classroom 202	W4	Concrete	Orange	None	0	0.01	Negative
1	2	202	Classroom 202	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	202	Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Classroom 202 Left Closet	W1	Concrete	Tan	None	0	N/A	N/A
1	2	202A	Classroom 202 Left Closet	W2	Concrete	Tan	None	0	N/A	N/A
1	2	202A	Classroom 202 Left Closet	W3	Concrete	Tan	None	0	N/A	N/A
1	2	202A	Classroom 202 Left Closet	W4	Concrete	Tan	None	0	N/A	N/A
1	2	202A	Classroom 202 Left Closet	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	202A	Classroom 202 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	202B	Classroom 202 Right Closet	W1	Concrete	Tan	None	0	N/A	N/A
1	2	202B	Classroom 202 Right Closet	W2	Concrete	Tan	None	0	N/A	N/A
1	2	202B	Classroom 202 Right Closet	W3	Concrete	Tan	None	0	N/A	N/A
1	2	202B	Classroom 202 Right Closet	W4	Concrete	Tan	None	0	N/A	N/A
1	2	202B	Classroom 202 Right Closet	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	202B	Classroom 202 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203	Classroom 203	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203	Classroom 203	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203	Classroom 203	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203	Classroom 203	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203	Classroom 203	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203B	Classroom 203 Left Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203B	Classroom 203 Left Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203B	Classroom 203 Left Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203B	Classroom 203 Left Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203B	Classroom 203 Left Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203B	Classroom 203 Left Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203C	Classroom 203 Right Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203C	Classroom 203 Right Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203C	Classroom 203 Right Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203C	Classroom 203 Right Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203C	Classroom 203 Right Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203C	Classroom 203 Right Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Building Engineers Office across from Classroom 203	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Building Engineers Office across from Classroom 203	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Building Engineers Office across from Classroom 203	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Building Engineers Office across from Classroom 203	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Building Engineers Office across from Classroom 203	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Building Engineers Office across from Classroom 203	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	2H2	Hallway next to Classrooms 201 through 203	W1	Concrete	Tan	None	0	N/A	N/A
1	2	2H2	Hallway next to Classrooms 201 through 203	W2	Concrete	Tan	None	0	1	Positive
1	2	2H2	Hallway next to Classrooms 201 through 203	W3	Concrete	Tan	None	0	N/A	N/A
1	2	2H2	Hallway next to Classrooms 201 through 203	W4	Concrete	Tan	None	0	0.22	Negative
1	2	2H2	Hallway next to Classrooms 201 through 203	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	2H2	Hallway next to Classrooms 201 through 203	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	S26	Stairs Next to Classroom 201	W1	Concrete	Tan	None	0	N/A	N/A
1	2	S26	Stairs Next to Classroom 201	W2	Concrete	Tan	Cracking	10	0.09	Negative

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S26	Stairs Next to Classroom 201	W3	Concrete	Tan	None	0	N/A	N/A
1	2	S26	Stairs Next to Classroom 201	W4	Concrete	Tan	Cracking	10	1	Positive
1	2	S26	Stairs Next to Classroom 201	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S26	Stairs Next to Classroom 201	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	203A	Storage Closet outside Classroom 203	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Storage Closet outside Classroom 203	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Storage Closet outside Classroom 203	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Storage Closet outside Classroom 203	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Storage Closet outside Classroom 203	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203A	Storage Closet outside Classroom 203	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204	Classroom 204	W1	Concrete	Yellow	None	0	0	Negative
1	2	204	Classroom 204	W2	Plaster	Tan	None	0	N/A	N/A
1	2	204	Classroom 204	W3	Concrete	Tan	None	0	0	Negative
1	2	204	Classroom 204	W4	Plaster	Tan	None	0	N/A	N/A
1	2	204	Classroom 204	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204	Classroom 204	Floor	Wood	Brown	None	0	N/A	N/A
1	2	204A	Classroom 204 Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	2	204A	Classroom 204 Closet	W2	Plaster	Tan	None	0	N/A	N/A
1	2	204A	Classroom 204 Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	2	204A	Classroom 204 Closet	W4	Plaster	Tan	None	0	N/A	N/A
1	2	204A	Classroom 204 Closet	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204A	Classroom 204 Closet	Floor	Wood	Brown	None	0	N/A	N/A
1	2	210	Classroom 210	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	210	Classroom 210	W2	Plaster	Tan	None	0	N/A	N/A
1	2	210	Classroom 210	W3	Concrete	Tan	Chipping	1	5	Positive
1	2	210	Classroom 210	W4	Plaster	Tan	None	0	0	Negative
1	2	210	Classroom 210	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	210	Classroom 210	Floor	Wood	Brown	None	0	N/A	N/A
1	2	209	Classroom 209	W1	Plaster	Tan	None	0	5	Positive
1	2	209	Classroom 209	W2	Plaster	Tan	None	0	N/A	N/A
1	2	209	Classroom 209	W3	Concrete	Tan	None	0	5	Positive
1	2	209	Classroom 209	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	209	Classroom 209	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	209	Classroom 209	Floor	Wood	Brown	None	0	N/A	N/A
1	2	209	Classroom 209	Radiator	Metal	Grey	Chipping	1	0.07	Negative
1	2	205	Teacher's Lounge Next to Classroom 204	W1	Concrete	Tan	None	0	0.11	Negative
1	2	205	Teacher's Lounge Next to Classroom 204	W2	Concrete	Tan	None	0	N/A	N/A
1	2	205	Teacher's Lounge Next to Classroom 204	W3	Sheetrock	Tan	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	205	Teacher's Lounge Next to Classroom 204	W4	Concrete	Tan	None	0	0.08	Negative
1	2	205	Teacher's Lounge Next to Classroom 204	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	205	Teacher's Lounge Next to Classroom 204	Floor	N/A	N/A	Friction	N/A	N/A	N/A
1	2	205A	Staff Restroom in 2nd Floor Teacher's Lounge next to Classroom 204	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	205A	Staff Restroom in 2nd Floor Teacher's Lounge next to Classroom 204	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	205A	Staff Restroom in 2nd Floor Teacher's Lounge next to Classroom 204	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	205A	Staff Restroom in 2nd Floor Teacher's Lounge next to Classroom 204	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	205A	Staff Restroom in 2nd Floor Teacher's Lounge next to Classroom 204	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	205A	Staff Restroom in 2nd Floor Teacher's Lounge next to Classroom 204	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	2	205B	Teachers Lounge Storage	W1	Plaster	Tan	None	0	N/A	N/A
1	2	205B	Teachers Lounge Storage	W2	Plaster	Tan	None	0	N/A	N/A
1	2	205B	Teachers Lounge Storage	W3	Plaster	Tan	None	0	N/A	N/A
1	2	205B	Teachers Lounge Storage	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	205B	Teachers Lounge Storage	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	205B	Teachers Lounge Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	W1	Plaster	Tan	None	0	0	Negative
1	2	206	Classroom 206	W2	Plaster	Tan	None	0	N/A	N/A
1	2	206	Classroom 206	W3	Plaster	Tan	None	0	0.04	Negative
1	2	206	Classroom 206	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	206	Classroom 206	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	206	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206A	Classroom 206 Left Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Classroom 206 Left Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Classroom 206 Left Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Classroom 206 Left Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Classroom 206 Left Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Classroom 206 Left Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206B	Classroom 206 Right Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206B	Classroom 206 Right Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206B	Classroom 206 Right Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206B	Classroom 206 Right Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206B	Classroom 206 Right Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206B	Classroom 206 Right Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	200	Boy's Restroom across from Classroom 208	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200	Boy's Restroom across from Classroom 208	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200	Boy's Restroom across from Classroom 208	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200	Boy's Restroom across from Classroom 208	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200	Boy's Restroom across from Classroom 208	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200	Boy's Restroom across from Classroom 208	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200PC	Boy's Restroom across from Classroom 208: Pipe Chase	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200PC	Boy's Restroom across from Classroom 208: Pipe Chase	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200PC	Boy's Restroom across from Classroom 208: Pipe Chase	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200PC	Boy's Restroom across from Classroom 208: Pipe Chase	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200PC	Boy's Restroom across from Classroom 208: Pipe Chase	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200PC	Boy's Restroom across from Classroom 208: Pipe Chase	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	200A	Girl's Restroom Across from Classroom 208	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	200A	Girl's Restroom Across from Classroom 208	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	200A	Girl's Restroom Across from Classroom 208	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	200A	Girl's Restroom Across from Classroom 208	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	200A	Girl's Restroom Across from Classroom 208	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	200A	Girl's Restroom Across from Classroom 208	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	2	208	Classroom 208	W1	Plaster	Yellow	None	0	5	Positive
1	2	208	Classroom 208	W2	Plaster	Tan	None	0	5	Positive
1	2	208	Classroom 208	W3	Plaster	Tan	Chipping	1	5	Positive
1	2	208	Classroom 208	W4	Plaster	Tan	None	0	N/A	N/A
1	2	208	Classroom 208	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	208	Classroom 208	Floor	Wood	Brown	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	W1	Plaster	Tan	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	W2	Plaster	Tan	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	W3	Plaster	Tan	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	W4	Plaster	Tan	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	Floor	Wood	Brown	None	0	N/A	N/A
1	2	207	Classroom 207	W1	Plaster	Yellow	None	0	5	Positive
1	2	207	Classroom 207	W2	Plaster	Tan/Green	Chipping	1	2.4	Positive
1	2	207	Classroom 207	W3	Plaster	Tan	None	0	0.15	Negative

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	207	Classroom 207	W4	Plaster	Tan	None	0	N/A	N/A
1	2	207	Classroom 207	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	207	Classroom 207	Floor	Wood	Brown	None	0	N/A	N/A
1	2	207A	Classroom 207 Storage	W1	Plaster	Tan	None	0	N/A	N/A
1	2	207A	Classroom 207 Storage	W2	Plaster	Tan	None	0	N/A	N/A
1	2	207A	Classroom 207 Storage	W3	Plaster	Tan	None	0	N/A	N/A
1	2	207A	Classroom 207 Storage	W4	Plaster	Tan	None	0	N/A	N/A
1	2	207A	Classroom 207 Storage	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	207A	Classroom 207 Storage	Floor	Wood	Brown	None	0	N/A	N/A
1	2	S21	Stairs Next to Classroom 204	W1	Concrete	Tan	None	0	3.96	Positive
1	2	S21	Stairs Next to Classroom 204	W2	Concrete	Tan	None	0	N/A	N/A
1	2	S21	Stairs Next to Classroom 204	W3	Concrete	Tan	None	0	N/A	N/A
1	2	S21	Stairs Next to Classroom 204	W4	Plaster	Tan	None	0	N/A	N/A
1	2	S21	Stairs Next to Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairs Next to Classroom 204	Floor	Concrete	Black/Red	None	0	N/A	N/A
1	2	H21	Hallway next to Classrooms 204 through 207	W1	Plaster	Tan	None	0	N/A	N/A
1	2	H21	Hallway next to Classrooms 204 through 207	W2	Plaster	Tan	None	0	1	Positive
1	2	H21	Hallway next to Classrooms 204 through 207	W3	Plaster	Tan	None	0	N/A	N/A
1	2	H21	Hallway next to Classrooms 204 through 207	W4	Plaster	Tan	Moisture Damage	15	1	Positive
1	2	H21	Hallway next to Classrooms 204 through 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H21	Hallway next to Classrooms 204 through 207	Floor	Concrete	Black/Red	None	0	N/A	N/A
1	2	222	Office 207A	W1	Concrete	Tan	None	0	5	Positive
1	2	222	Office 207A	W2	Concrete	Tan	None	0	0.21	Negative
1	2	222	Office 207A	W3	Concrete	Tan	None	0	N/A	N/A
1	2	222	Office 207A	W4	Concrete	Tan	None	0	N/A	N/A
1	2	222	Office 207A	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	222	Office 207A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	222	Office 207A	Radiator	Metal	Blue	None	0	0.42	Negative
1	2	212	Unisex Restroom next to Office 207A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	212	Unisex Restroom next to Office 207A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	212	Unisex Restroom next to Office 207A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	212	Unisex Restroom next to Office 207A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	212	Unisex Restroom next to Office 207A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	212	Unisex Restroom next to Office 207A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	S24	Stairs Next to Classroom 208	W1	Concrete	Tan	None	0	N/A	N/A
1	2	S24	Stairs Next to Classroom 208	W2	Concrete	Tan	None	0	0.01	Negative
1	2	S24	Stairs Next to Classroom 208	W3	Concrete	Tan	None	0	N/A	N/A
1	2	S24	Stairs Next to Classroom 208	W4	Plaster	Tan	None	0	1	Positive

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S24	Stairs Next to Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairs Next to Classroom 208	Floor	Concrete	Black/Red	None	0	N/A	N/A
1	2	220	Girl's Restroom Across from Classroom 217	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	220	Girl's Restroom Across from Classroom 217	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	220	Girl's Restroom Across from Classroom 217	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	220	Girl's Restroom Across from Classroom 217	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	220	Girl's Restroom Across from Classroom 217	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	220	Girl's Restroom Across from Classroom 217	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	2	219 PC	Girls/ Boy's Restroom across from Classroom 217 Pipe Chase	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	219 PC	Girls/ Boy's Restroom across from Classroom 217 Pipe Chase	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	219 PC	Girls/ Boy's Restroom across from Classroom 217 Pipe Chase	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	219 PC	Girls/ Boy's Restroom across from Classroom 217 Pipe Chase	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	219 PC	Girls/ Boy's Restroom across from Classroom 217 Pipe Chase	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	219 PC	Girls/ Boy's Restroom across from Classroom 217 Pipe Chase	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	219	Boy's Restroom across from Classroom 217	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	219	Boy's Restroom across from Classroom 217	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	219	Boy's Restroom across from Classroom 217	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	219	Boy's Restroom across from Classroom 217	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	2	219	Boy's Restroom across from Classroom 217	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	219	Boy's Restroom across from Classroom 217	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	2	216	Classroom 216	W1	Concrete	Grey	None	0	N/A	N/A
1	2	216	Classroom 216	W2	Concrete	Grey	None	0	N/A	N/A
1	2	216	Classroom 216	W3	Sheetrock	Orange	None	0	0	Negative
1	2	216	Classroom 216	W4	Concrete	Grey	None	0	2.03	Positive
1	2	216	Classroom 216	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	216	Classroom 216	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	216A	Office 216A	W1	Concrete	Blue	None	0	0.01	Negative
1	2	216A	Office 216A	W2	Concrete	Blue	None	0	N/A	N/A
1	2	216A	Office 216A	W3	Brick	Blue	None	0	0.01	Negative
1	2	216A	Office 216A	W4	Concrete	Blue	None	0	N/A	N/A
1	2	216A	Office 216A	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	216A	Office 216A	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	217	Classroom 217	W1	Concrete	Grey	None	0	0.01	Negative

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	217	Classroom 217	W2	Concrete	Grey	None	0	0.01	Negative
1	2	217	Classroom 217	W3	Sheetrock	Orange	None	0	N/A	N/A
1	2	217	Classroom 217	W4	Concrete	Grey	None	0	0.06	Negative
1	2	217	Classroom 217	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	217	Classroom 217	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	Classroom 215	W1	Concrete	Grey	None	0	N/A	N/A
1	2	215	Classroom 215	W2	Concrete	Grey	None	0	4.54	Positive
1	2	215	Classroom 215	W3	Sheetrock	Orange	None	0	N/A	N/A
1	2	215	Classroom 215	W4	Concrete	Grey	None	0	0.07	Negative
1	2	215	Classroom 215	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	215	Classroom 215	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Classroom 214	W1	Concrete	Blue	None	0	N/A	N/A
1	2	214	Classroom 214	W2	Concrete	Grey	None	0	N/A	N/A
1	2	214	Classroom 214	W3	Concrete	Grey	None	0	N/A	N/A
1	2	214	Classroom 214	W4	Concrete	Grey	None	0	N/A	N/A
1	2	214	Classroom 214	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	214	Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	218	Classroom 218	W1	Concrete	Orange	None	0	0.02	Negative
1	2	218	Classroom 218	W2	Concrete	Grey	None	0	N/A	N/A
1	2	218	Classroom 218	W3	Sheetrock	Grey	None	0	N/A	N/A
1	2	218	Classroom 218	W4	Concrete	Grey	None	0	0.08	Negative
1	2	218	Classroom 218	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	218	Classroom 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S27	Stairs Next to Classroom 215	W1	Concrete	Tan	None	0	N/A	N/A
1	2	S27	Stairs Next to Classroom 215	W2	Concrete	Tan	None	0	0.06	Negative
1	2	S27	Stairs Next to Classroom 215	W3	Concrete	Tan	None	0	N/A	N/A
1	2	S27	Stairs Next to Classroom 215	W4	Concrete	Tan	None	0	0.04	Negative
1	2	S27	Stairs Next to Classroom 215	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S27	Stairs Next to Classroom 215	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	3H2	Hallway next to Classrooms 214 through 217	W1	Concrete	Grey	None	0	0.1	Negative
1	2	3H2	Hallway next to Classrooms 214 through 217	W2	Concrete	Grey	None	0	0.06	Negative
1	2	3H2	Hallway next to Classrooms 214 through 217	W3	Concrete	Grey	None	0	0.06	Negative
1	2	3H2	Hallway next to Classrooms 214 through 217	W4	Concrete	Grey	None	0	0.06	Negative
1	2	3H2	Hallway next to Classrooms 214 through 217	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	3H2	Hallway next to Classrooms 214 through 217	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Office 108-A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108A	Office 108-A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108A	Office 108-A	W3	No Access	No Access	No Access	No Access	No Access	No Access

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	108A	Office 108-A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108A	Office 108-A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108A	Office 108-A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117	Girl's Restroom next to Office 108A	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	117	Girl's Restroom next to Office 108A	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	117	Girl's Restroom next to Office 108A	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	117	Girl's Restroom next to Office 108A	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	117	Girl's Restroom next to Office 108A	Ceiling	Concrete	Tan	Cracking	3	0	Negative
1	1	117	Girl's Restroom next to Office 108A	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	109A	Boy's Restroom 109A near Office 108A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109A	Boy's Restroom 109A near Office 108A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109A	Boy's Restroom 109A near Office 108A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109A	Boy's Restroom 109A near Office 108A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109A	Boy's Restroom 109A near Office 108A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109A	Boy's Restroom 109A near Office 108A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Service Closet Next to Boy's Restroom near Office 108A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Service Closet Next to Boy's Restroom near Office 108A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Service Closet Next to Boy's Restroom near Office 108A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Service Closet Next to Boy's Restroom near Office 108A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Service Closet Next to Boy's Restroom near Office 108A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Service Closet Next to Boy's Restroom near Office 108A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Office 110A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Office 110A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Office 110A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Office 110A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Office 110A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110A	Office 110A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110	Classroom 110	W1	Concrete	Grey	None	0	N/A	N/A
1	1	110	Classroom 110	W2	Concrete	Grey	None	0	0.02	Negative
1	1	110	Classroom 110	W3	Concrete	Grey	None	0	N/A	N/A
1	1	110	Classroom 110	W4	Concrete	Teal	None	0	0	Negative
1	1	110	Classroom 110	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	110	Classroom 110	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	110B	Storage Closet in Classroom 110	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Storage Closet in Classroom 110	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Storage Closet in Classroom 110	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Storage Closet in Classroom 110	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Storage Closet in Classroom 110	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110B	Storage Closet in Classroom 110	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113B	Classroom 110 Restroom	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	113B	Classroom 110 Restroom	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	113B	Classroom 110 Restroom	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	113B	Classroom 110 Restroom	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	113B	Classroom 110 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113B	Classroom 110 Restroom	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	108	Classroom 108	W1	Concrete	Grey	None	0	0.04	Negative
1	1	108	Classroom 108	W2	Concrete	Teal	None	0	N/A	N/A
1	1	108	Classroom 108	W3	Concrete	Grey	None	0	N/A	N/A
1	1	108	Classroom 108	W4	Concrete	Grey	None	0	N/A	N/A
1	1	108	Classroom 108	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	108	Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage Closet in Classroom 108	W1	Concrete	Grey	None	0	N/A	N/A
1	1	108B	Storage Closet in Classroom 108	W2	Concrete	Grey	None	0	N/A	N/A
1	1	108B	Storage Closet in Classroom 108	W3	Concrete	Grey	None	0	N/A	N/A
1	1	108B	Storage Closet in Classroom 108	W4	Concrete	Grey	None	0	N/A	N/A
1	1	108B	Storage Closet in Classroom 108	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage Closet in Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111B	Classroom 108 Restroom	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	111B	Classroom 108 Restroom	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	111B	Classroom 108 Restroom	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	111B	Classroom 108 Restroom	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	111B	Classroom 108 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111B	Classroom 108 Restroom	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	109	Classroom 109	W1	Concrete	Grey	None	0	N/A	N/A
1	1	109	Classroom 109	W2	Concrete	Teal	None	0	N/A	N/A
1	1	109	Classroom 109	W3	Concrete	Grey	None	0	0.05	Negative
1	1	109	Classroom 109	W4	Concrete	Grey	None	0	N/A	N/A
1	1	109	Classroom 109	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	109	Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112A	Storage Closet in Classroom 109	W1	Concrete	Grey	None	0	N/A	N/A
1	1	112A	Storage Closet in Classroom 109	W2	Concrete	Grey	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	112A	Storage Closet in Classroom 109	W3	Concrete	Grey	None	0	N/A	N/A
1	1	112A	Storage Closet in Classroom 109	W4	Concrete	Grey	None	0	N/A	N/A
1	1	112A	Storage Closet in Classroom 109	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112A	Storage Closet in Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112B	Classroom 109 Restroom	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	112B	Classroom 109 Restroom	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	112B	Classroom 109 Restroom	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	112B	Classroom 109 Restroom	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	112B	Classroom 109 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	112B	Classroom 109 Restroom	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	S112	Stairs Next to Classroom 109	W1	Concrete	Tan	None	0	N/A	N/A
1	1	S112	Stairs Next to Classroom 109	W2	Concrete	Tan	None	0	N/A	N/A
1	1	S112	Stairs Next to Classroom 109	W3	Concrete	Tan	None	0	N/A	N/A
1	1	S112	Stairs Next to Classroom 109	W4	Concrete	Tan	None	0	N/A	N/A
1	1	S112	Stairs Next to Classroom 109	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S112	Stairs Next to Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	3H1	Hallway near Classroom 109 through Office 108A	W1	Concrete	Grey	None	0	N/A	N/A
1	1	3H1	Hallway near Classroom 109 through Office 108A	W2	Concrete	Grey	None	0	0.03	Negative
1	1	3H1	Hallway near Classroom 109 through Office 108A	W3	Concrete	Grey	None	0	N/A	N/A
1	1	3H1	Hallway near Classroom 109 through Office 108A	W4	Concrete	Grey	None	0	0.03	Negative
1	1	3H1	Hallway near Classroom 109 through Office 108A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	3H1	Hallway near Classroom 109 through Office 108A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S18	Stairs Next to Auditorium	W1	Concrete	Tan	None	0	N/A	N/A
1	1	S18	Stairs Next to Auditorium	W2	Concrete	Tan/Green	Chipping	2	5	Positive
1	1	S18	Stairs Next to Auditorium	W3	Concrete	Tan	None	0	N/A	N/A
1	1	S18	Stairs Next to Auditorium	W4	Concrete	Tan	None	0	N/A	N/A
1	1	S18	Stairs Next to Auditorium	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S18	Stairs Next to Auditorium	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101	Classroom 101	W1	Concrete	Teal	None	0	N/A	N/A
1	1	101	Classroom 101	W2	Concrete	Grey	None	0	0	Negative
1	1	101	Classroom 101	W3	Concrete	Grey	None	0	0	Negative
1	1	101	Classroom 101	W4	Concrete	Grey	None	0	N/A	N/A
1	1	101	Classroom 101	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	101	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101	Classroom 101	Radiator	Metal	Grey	None	0	0.4	Negative
1	1	101T	Classroom 101 Restroom	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	101T	Classroom 101 Restroom	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	101T	Classroom 101 Restroom	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	101T	Classroom 101 Restroom	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	101T	Classroom 101 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	101T	Classroom 101 Restroom	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	101C	Classroom 101 Coat Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101C	Classroom 101 Coat Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101C	Classroom 101 Coat Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101C	Classroom 101 Coat Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101C	Classroom 101 Coat Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101C	Classroom 101 Coat Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102A	Storage Closet between Classrooms 102 and 101	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102A	Storage Closet between Classrooms 102 and 101	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102A	Storage Closet between Classrooms 102 and 101	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102A	Storage Closet between Classrooms 102 and 101	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102A	Storage Closet between Classrooms 102 and 101	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102A	Storage Closet between Classrooms 102 and 101	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102	Classroom 102	W1	Concrete	Grey	None	0	0.06	Negative
1	1	102	Classroom 102	W2	Concrete	Grey	None	0	N/A	N/A
1	1	102	Classroom 102	W3	Concrete	Grey	None	0	0.06	Negative
1	1	102	Classroom 102	W4	Concrete	Teal	None	0	N/A	N/A
1	1	102	Classroom 102	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	102	Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Classroom 102	Radiator	Metal	Grey	None	0	0.06	Negative
1	1	102T	Classroom 102 Restroom	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	102T	Classroom 102 Restroom	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	102T	Classroom 102 Restroom	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	102T	Classroom 102 Restroom	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	102T	Classroom 102 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	102T	Classroom 102 Restroom	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	102B	Classroom 102 Closet to left of entry door	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102B	Classroom 102 Closet to left of entry door	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102B	Classroom 102 Closet to left of entry door	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102B	Classroom 102 Closet to left of entry door	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102B	Classroom 102 Closet to left of entry door	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102B	Classroom 102 Closet to left of entry door	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102C	Classroom 102 Closet to right of entry door	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102C	Classroom 102 Closet to right of entry door	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102C	Classroom 102 Closet to right of entry door	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102C	Classroom 102 Closet to right of entry door	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	102C	Classroom 102 Closet to right of entry door	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102C	Classroom 102 Closet to right of entry door	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102Z	Classroom 102 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102Z	Classroom 102 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102Z	Classroom 102 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102Z	Classroom 102 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102Z	Classroom 102 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102Z	Classroom 102 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Server Room Across from Classroom 102	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Server Room Across from Classroom 102	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Server Room Across from Classroom 102	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Server Room Across from Classroom 102	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Server Room Across from Classroom 102	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107C	Server Room Across from Classroom 102	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	1H2	Hallway between Auditorium and Classroom 102	W1	Concrete	Tan	None	0	N/A	N/A
1	1	1H2	Hallway between Auditorium and Classroom 102	W2	Concrete	Tan	Chipping	1	0.09	Negative
1	1	1H2	Hallway between Auditorium and Classroom 102	W3	Concrete	Tan	None	0	N/A	N/A
1	1	1H2	Hallway between Auditorium and Classroom 102	W4	Concrete	Tan	None	0	0.16	Negative
1	1	1H2	Hallway between Auditorium and Classroom 102	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	1H2	Hallway between Auditorium and Classroom 102	Floor	Concrete	Black/Red	None	0	N/A	N/A
1	1	103C	Auditorium	W1	Concrete	Tan	None	0	N/A	N/A
1	1	103C	Auditorium	W2	Concrete	Grey	Cracking	2	0	Negative
1	1	103C	Auditorium	W3	Concrete	Tan	Cracking	1	0.35	Negative
1	1	103C	Auditorium	W4	Concrete	Tan	None	0	N/A	N/A
1	1	103C	Auditorium	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	103C	Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103C PC	Auditorium Pipe Chase	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C PC	Auditorium Pipe Chase	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C PC	Auditorium Pipe Chase	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C PC	Auditorium Pipe Chase	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C PC	Auditorium Pipe Chase	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C PC	Auditorium Pipe Chase	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103ST	Auditorium Stage	W1	Concrete	Black	None	0	N/A	N/A
1	1	103ST	Auditorium Stage	W2	Concrete	Black	None	0	N/A	N/A
1	1	103ST	Auditorium Stage	W3	Concrete	Black	None	0	N/A	N/A
1	1	103ST	Auditorium Stage	W4	Concrete	Black	None	0	N/A	N/A
1	1	103ST	Auditorium Stage	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	103ST	Auditorium Stage	Floor	Wood	Black	None	0	0	Negative

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S19	Stairs in Auditorium to Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S19	Stairs in Auditorium to Stage	W2	Concrete	Black	None	0	0	Negative
1	1	S19	Stairs in Auditorium to Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S19	Stairs in Auditorium to Stage	W4	Concrete	Black	None	0	0	Negative
1	1	S19	Stairs in Auditorium to Stage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S19	Stairs in Auditorium to Stage	Floor	Concrete	Grey	None	0	0	Negative
1	1	103T	Student Restroom in Auditorium	W1	Ceramic tile	Tan & Green	None	0	N/A	N/A
1	1	103T	Student Restroom in Auditorium	W2	Ceramic tile	Tan & Green	None	0	N/A	N/A
1	1	103T	Student Restroom in Auditorium	W3	Ceramic tile	Tan & Green	None	0	N/A	N/A
1	1	103T	Student Restroom in Auditorium	W4	Ceramic tile	Tan & Green	None	0	N/A	N/A
1	1	103T	Student Restroom in Auditorium	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	103T	Student Restroom in Auditorium	Floor	Ceramic tile	Brown & Grey	None	0	N/A	N/A
1	1	103X	Women's Restroom next to Auditorium	W1	Ceramic tile	Tan & Green	None	0	N/A	N/A
1	1	103X	Women's Restroom next to Auditorium	W2	Ceramic tile	Tan & Green	None	0	N/A	N/A
1	1	103X	Women's Restroom next to Auditorium	W3	Ceramic tile	Tan & Green	None	0	N/A	N/A
1	1	103X	Women's Restroom next to Auditorium	W4	Ceramic tile	Tan & Green	None	0	N/A	N/A
1	1	103X	Women's Restroom next to Auditorium	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	103X	Women's Restroom next to Auditorium	Floor	Ceramic tile	Brown & Grey	None	0	N/A	N/A
1	1	S110	Stairs to Left of Auditorium	W1	Concrete	Tan	None	0	N/A	N/A
1	1	S110	Stairs to Left of Auditorium	W2	Concrete	Tan	None	0	N/A	N/A
1	1	S110	Stairs to Left of Auditorium	W3	Concrete	Tan	None	0	N/A	N/A
1	1	S110	Stairs to Left of Auditorium	W4	Concrete	Tan	None	0	N/A	N/A
1	1	S110	Stairs to Left of Auditorium	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S110	Stairs to Left of Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Main Office	W1	Concrete	Tan	None	0	0	Negative
1	1	107	Main Office	W2	Concrete	Tan	None	0	0.05	Negative
1	1	107	Main Office	W3	Concrete	Tan	None	0	5	Positive
1	1	107	Main Office	W4	Concrete	Tan	None	0	N/A	N/A
1	1	107	Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	107	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107T	Principal's Office	W1	Concrete	Tan	None	0	N/A	N/A
1	1	107T	Principal's Office	W2	Concrete	Tan	None	0	N/A	N/A
1	1	107T	Principal's Office	W3	Concrete	Tan	None	0	5	Positive
1	1	107T	Principal's Office	W4	Concrete	Tan	None	0	N/A	N/A
1	1	107T	Principal's Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	107T	Principal's Office	Floor	Wood	Brown	None	0	N/A	N/A
1	1	107B	Principal's Office Restroom	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	107B	Principal's Office Restroom	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	107B	Principal's Office Restroom	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	107B	Principal's Office Restroom	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	107B	Principal's Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	107B	Principal's Office Restroom	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	107A	Principal's Office Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Principal's Office Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Principal's Office Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Principal's Office Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Principal's Office Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	107A	Principal's Office Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S11	Stairs /Foyer at Visitor Entrance	W1	Concrete	Tan	None	0	N/A	N/A
1	1	S11	Stairs /Foyer at Visitor Entrance	W2	Concrete	Tan	None	0	N/A	N/A
1	1	S11	Stairs /Foyer at Visitor Entrance	W3	Concrete	Tan	None	0	N/A	N/A
1	1	S11	Stairs /Foyer at Visitor Entrance	W4	Concrete	Tan	None	0	N/A	N/A
1	1	S11	Stairs /Foyer at Visitor Entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairs /Foyer at Visitor Entrance	Floor	Concrete	Black/Red	None	0	N/A	N/A
1	1	103	Classroom 103	W1	Concrete	Tan	None	0	0.09	Negative
1	1	103	Classroom 103	W2	Concrete	Tan	None	0	5	Positive
1	1	103	Classroom 103	W3	Concrete	Tan	None	0	0.07	Negative
1	1	103	Classroom 103	W4	Concrete	Orange	None	0	0	Negative
1	1	103	Classroom 103	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	103	Classroom 103	Floor	Wood	Brown	None	0	N/A	N/A
1	1	103C	Classroom 103 Coat Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C	Classroom 103 Coat Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C	Classroom 103 Coat Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C	Classroom 103 Coat Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C	Classroom 103 Coat Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103C	Classroom 103 Coat Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	103A	Nurse's Front Office	W1	Concrete	Tan	None	0	N/A	N/A
1	1	103A	Nurse's Front Office	W2	Concrete	Tan	None	0	N/A	N/A
1	1	103A	Nurse's Front Office	W3	Concrete	Tan	None	0	0.11	Negative
1	1	103A	Nurse's Front Office	W4	Concrete	Tan	None	0	0.17	Negative
1	1	103A	Nurse's Front Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	103A	Nurse's Front Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Rear Nurse's Office with Windows	W1	Concrete	Tan	None	0	N/A	N/A
1	1	104	Rear Nurse's Office with Windows	W2	Concrete	Tan	None	0	N/A	N/A
1	1	104	Rear Nurse's Office with Windows	W3	Concrete	Tan	None	0	0	Negative
1	1	104	Rear Nurse's Office with Windows	W4	Concrete	Tan	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	104	Rear Nurse's Office with Windows	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	104	Rear Nurse's Office with Windows	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104A	Nurse's Office Restroom	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	104A	Nurse's Office Restroom	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	104A	Nurse's Office Restroom	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	104A	Nurse's Office Restroom	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	104A	Nurse's Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	104A	Nurse's Office Restroom	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	105A	Nurse's Office Right Storage Room	W1	Plaster	Tan	None	0	N/A	N/A
1	1	105A	Nurse's Office Right Storage Room	W2	Plaster	Tan	None	0	N/A	N/A
1	1	105A	Nurse's Office Right Storage Room	W3	Plaster	Tan	None	0	N/A	N/A
1	1	105A	Nurse's Office Right Storage Room	W4	Plaster	Tan	None	0	N/A	N/A
1	1	105A	Nurse's Office Right Storage Room	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	105A	Nurse's Office Right Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105AB	Nurse's Office Left Storage Room	W1	Plaster	Tan	None	0	N/A	N/A
1	1	105AB	Nurse's Office Left Storage Room	W2	Plaster	Tan	None	0	N/A	N/A
1	1	105AB	Nurse's Office Left Storage Room	W3	Plaster	Tan	None	0	N/A	N/A
1	1	105AB	Nurse's Office Left Storage Room	W4	Plaster	Tan	None	0	N/A	N/A
1	1	105AB	Nurse's Office Left Storage Room	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	105AB	Nurse's Office Left Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105L	1st Floor Teacher's Lounge next to Nurse's office	W1	Concrete	Tan	None	0	N/A	N/A
1	1	105L	1st Floor Teacher's Lounge next to Nurse's office	W2	Concrete	Tan	None	0	N/A	N/A
1	1	105L	1st Floor Teacher's Lounge next to Nurse's office	W3	Concrete	Tan	None	0	N/A	N/A
1	1	105L	1st Floor Teacher's Lounge next to Nurse's office	W4	Concrete	Tan	None	0	N/A	N/A
1	1	105L	1st Floor Teacher's Lounge next to Nurse's office	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	105L	1st Floor Teacher's Lounge next to Nurse's office	Floor	Wood	Brown	None	0	N/A	N/A
1	1	105L PC	1st Floor Teacher's Lounge next to Nurse's office-Pipe Chase	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105L PC	1st Floor Teacher's Lounge next to Nurse's office-Pipe Chase	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105L PC	1st Floor Teacher's Lounge next to Nurse's office-Pipe Chase	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105L PC	1st Floor Teacher's Lounge next to Nurse's office-Pipe Chase	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105L PC	1st Floor Teacher's Lounge next to Nurse's office-Pipe Chase	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105L PC	1st Floor Teacher's Lounge next to Nurse's office-Pipe Chase	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112Z	Staff Restroom in 1st Floor Teacher's Lounge	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	112Z	Staff Restroom in 1st Floor Teacher's Lounge	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	112Z	Staff Restroom in 1st Floor Teacher's Lounge	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	112Z	Staff Restroom in 1st Floor Teacher's Lounge	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	112Z	Staff Restroom in 1st Floor Teacher's Lounge	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	112Z	Staff Restroom in 1st Floor Teacher's Lounge	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	103B	Counselor's Office across from Classroom 106	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	103B	Counselor's Office across from Classroom 106	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	103B	Counselor's Office across from Classroom 106	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	103B	Counselor's Office across from Classroom 106	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	103B	Counselor's Office across from Classroom 106	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	103B	Counselor's Office across from Classroom 106	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	103D	Counselor's Office across from Classroom 106 Closet	W1	Concrete	Tan	None	0	N/A	N/A
1	1	103D	Counselor's Office across from Classroom 106 Closet	W2	Concrete	Tan	None	0	N/A	N/A
1	1	103D	Counselor's Office across from Classroom 106 Closet	W3	Concrete	Tan	None	0	N/A	N/A
1	1	103D	Counselor's Office across from Classroom 106 Closet	W4	Concrete	Tan	None	0	N/A	N/A
1	1	103D	Counselor's Office across from Classroom 106 Closet	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	103D	Counselor's Office across from Classroom 106 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Lobby outside of 1st Floor Counselor's Office	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	105B	Lobby outside of 1st Floor Counselor's Office	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	105B	Lobby outside of 1st Floor Counselor's Office	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	105B	Lobby outside of 1st Floor Counselor's Office	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	105B	Lobby outside of 1st Floor Counselor's Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	105B	Lobby outside of 1st Floor Counselor's Office	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	100	Boy's Restroom across from Classroom 105	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	100	Boy's Restroom across from Classroom 105	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	100	Boy's Restroom across from Classroom 105	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	100	Boy's Restroom across from Classroom 105	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	100	Boy's Restroom across from Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	100	Boy's Restroom across from Classroom 105	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	100A	Girl's Restroom Across from Classroom 105	W1	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	100A	Girl's Restroom Across from Classroom 105	W2	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	100A	Girl's Restroom Across from Classroom 105	W3	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	100A	Girl's Restroom Across from Classroom 105	W4	Ceramic Tile	Tan & Green	None	0	N/A	N/A
1	1	100A	Girl's Restroom Across from Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	100A	Girl's Restroom Across from Classroom 105	Floor	Ceramic Tile	Brown & Grey	None	0	N/A	N/A
1	1	104	Classroom 104	W1	Concrete	Tan	None	0	N/A	N/A
1	1	104	Classroom 104	W2	Concrete	Tan	None	0	N/A	N/A
1	1	104	Classroom 104	W3	Concrete	Tan	None	0	0.13	Negative

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	104	Classroom 104	W4	Concrete	Orange	None	0	N/A	N/A
1	1	104	Classroom 104	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	104	Classroom 104	Floor	Wood	Brown	None	0	N/A	N/A
1	1	104	Classroom 104	Radiator	Metal	Grey	None	0	0.12	Negative
1	1	104A	Classroom 104 Coat Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104A	Classroom 104 Coat Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104A	Classroom 104 Coat Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104A	Classroom 104 Coat Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104A	Classroom 104 Coat Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104A	Classroom 104 Coat Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	105	Classroom 105	W1	Concrete	Tan	None	0	5	Positive
1	1	105	Classroom 105	W2	Concrete	Blue	None	0	5	Positive
1	1	105	Classroom 105	W3	Concrete	Tan	None	0	0.13	Negative
1	1	105	Classroom 105	W4	Concrete	Tan	None	0	N/A	N/A
1	1	105	Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	105	Classroom 105	Floor	Wood	Brown	None	0	N/A	N/A
1	1	105A	Classroom 105 Closet	W1	Concrete	Tan	None	0	N/A	N/A
1	1	105A	Classroom 105 Closet	W2	Concrete	Tan	None	0	N/A	N/A
1	1	105A	Classroom 105 Closet	W3	Concrete	Tan	None	0	N/A	N/A
1	1	105A	Classroom 105 Closet	W4	Concrete	Tan	None	0	N/A	N/A
1	1	105A	Classroom 105 Closet	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	105A	Classroom 105 Closet	Floor	Wood	Brown	None	0	N/A	N/A
1	1	S14	Stairs Next to Classroom 105	W1	Concrete	Tan	None	0	N/A	N/A
1	1	S14	Stairs Next to Classroom 105	W2	Concrete	Tan	None	0	N/A	N/A
1	1	S14	Stairs Next to Classroom 105	W3	Concrete	Tan	None	0	N/A	N/A
1	1	S14	Stairs Next to Classroom 105	W4	Concrete	Tan	None	0	N/A	N/A
1	1	S14	Stairs Next to Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	Stairs Next to Classroom 105	Floor	Concrete	Black/Red	None	0	N/A	N/A
1	1	113	Office in Stairwell next to Classroom 104	W1	Plaster	Tan	None	0	0	Negative
1	1	113	Office in Stairwell next to Classroom 104	W2	Plaster	Tan	None	0	0.02	Negative
1	1	113	Office in Stairwell next to Classroom 104	W3	Plaster	Tan	None	0	N/A	N/A
1	1	113	Office in Stairwell next to Classroom 104	W4	Plaster	Tan	None	0	N/A	N/A
1	1	113	Office in Stairwell next to Classroom 104	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	113	Office in Stairwell next to Classroom 104	Floor	Wood	Brown	None	0	N/A	N/A
1	1	113T	Men's Restroom in Stairwell near Classroom 104	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113T	Men's Restroom in Stairwell near Classroom 104	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113T	Men's Restroom in Stairwell near Classroom 104	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113T	Men's Restroom in Stairwell near Classroom 104	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	113T	Men's Restroom in Stairwell near Classroom 104	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	113T	Men's Restroom in Stairwell near Classroom 104	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	W1	Plaster	Tan	None	0	N/A	N/A
1	1	114	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	W2	Plaster	White	Chipping	2	0	Negative
1	1	114	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	W3	Plaster	Tan	Moisture Damage	5	3.4	Positive
1	1	114	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	W4	Plaster	Tan	None	0	N/A	N/A
1	1	114	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	114	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	Floor	Concrete	Black/Red	None	0	N/A	N/A
1	1	114	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	Radiator	Metal	Grey	Chipping	1	0.08	Negative
1	1	106	Classroom 106	W1	Concrete	Tan	None	0	5	Positive
1	1	106	Classroom 106	W2	Concrete	Tan	None	0	N/A	N/A
1	1	106	Classroom 106	W3	Concrete	Tan	None	0	0.05	Negative
1	1	106	Classroom 106	W4	Concrete	Blue	None	0	N/A	N/A
1	1	106	Classroom 106	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	106	Classroom 106	Floor	Wood	Brown	None	0	N/A	N/A
1	1	106A	Classroom 106 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	106A	Classroom 106 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	106A	Classroom 106 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	106A	Classroom 106 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	106A	Classroom 106 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	106A	Classroom 106 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11	1st Floor Hallways next to Classrooms 103 through 105	W1	Concrete	Tan	None	0	1	Positive
1	1	H11	1st Floor Hallways next to Classrooms 103 through 105	W2	Concrete	Tan	None	0	1	Positive
1	1	H11	1st Floor Hallways next to Classrooms 103 through 105	W3	Concrete	Tan	None	0	1	Positive
1	1	H11	1st Floor Hallways next to Classrooms 103 through 105	W4	Concrete	Tan	None	0	5	Positive
1	1	H11	1st Floor Hallways next to Classrooms 103 through 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H11	1st Floor Hallways next to Classrooms 103 through 105	Floor	Concrete	Black/Red	None	0	N/A	N/A

			Inspection Dates: July 9, 15, & 16, 2021	School District of Philadelphia						
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine	Capital Project Lead-Based Paint Assessment Report						
			Inspection Company: React	C.W. Henry School						
E l e m e n t	F l o o r	Space #	On Site Space Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	H2	Rear Exit Foyer	W1	Concrete	Grey	None	0	N/A	N/A
1	1	H2	Rear Exit Foyer	W2	Concrete	Grey	None	0	N/A	N/A
1	1	H2	Rear Exit Foyer	W3	Concrete	Grey	None	0	N/A	N/A
1	1	H2	Rear Exit Foyer	W4	Concrete	Grey	None	0	N/A	N/A
1	1	H2	Rear Exit Foyer	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H2	Rear Exit Foyer	Floor	Concrete	N/A	N/A	N/A	N/A	N/A