

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	2	1	Exterior Steps adjacent to Classroom 61	W1	Concrete/Stone	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 61	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 61	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 61	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 61	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 61	Floor	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway from Classrooms 61 to 66	W1	Stone	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway from Classrooms 61 to 66	W1	N/A	N/A	N/A	0	N/A	N/A	Door	Metal	Brown	Moisture Damage	10	0	Negative
8270	2	1	Hallway from Classrooms 61 to 66	W1	N/A	N/A	N/A	0	N/A	N/A	Door Frame	Metal	Brown	Moisture Damage	10	0	Negative
8270	2	1	Hallway from Classrooms 61 to 66	W2	Stone	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway from Classrooms 61 to 66	W2	N/A	N/A	N/A	0	N/A	N/A	Door Frame	Metal	Beige	Chipping	10	0	Negative
8270	2	1	Hallway from Classrooms 61 to 66	W3	Stone	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway from Classrooms 61 to 66	W3	N/A	N/A	N/A	0	N/A	N/A	Door	Metal	Brown	Moisture Damage	10	0	Negative
8270	2	1	Hallway from Classrooms 61 to 66	W3	N/A	N/A	N/A	0	N/A	N/A	Door Frame	Metal	Brown	Moisture Damage	10	0	Negative
8270	2	1	Hallway from Classrooms 61 to 66	W4	Stone	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway from Classrooms 61 to 66	W4	N/A	N/A	N/A	0	N/A	N/A	Door Frame	Metal	Beige	Chipping	10	0	Negative
8270	2	1	Hallway from Classrooms 61 to 66	W4	N/A	N/A	N/A	0	N/A	N/A	Door	Metal	Brown	Chipping	10	0	Negative
8270	2	1	Hallway from Classrooms 61 to 66	W4	N/A	N/A	N/A	0	N/A	N/A	Radiator cover	Metal	Brown	Flaking	2	0	Negative
8270	2	1	Hallway from Classrooms 61 to 66	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway from Classrooms 61 to 66	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64	W1	N/A	N/A	N/A	0	N/A	N/A	Door	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 64	W1	N/A	N/A	N/A	0	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 64	W2	Concrete	Beige	Chipping	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64	W3	Concrete	Beige	Flaking	4	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 64	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 64	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Restroom	W1	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 64 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 64 Restroom	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Restroom	W3	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Restroom	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Closet	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Closet	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Closet	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Closet	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Closet	Ceiling	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 64 Closet	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61	W1	Concrete	Beige	Flaking	2	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 61	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 61	W2	Sheetrock	Beige	Flaking	6	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 61	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 61	W3	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Restroom	W1	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 61 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 61 Restroom	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Restroom	W3	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Restroom	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Closet	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Closet	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Closet	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Closet	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Closet	Ceiling	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 61 Closet	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	2	1	Hallway between Classrooms 61 and 62	W1	Stone	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway between Classrooms 61 and 62	W1	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Brown	Flaking	2	0	Negative
8270	2	1	Hallway between Classrooms 61 and 62	W2	Stone	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway between Classrooms 61 and 62	W3	Stone	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway between Classrooms 61 and 62	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Brown	Flaking	2	0.03	Negative
8270	2	1	Hallway between Classrooms 61 and 62	W4	Stone	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway between Classrooms 61 and 62	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Hallway between Classrooms 61 and 62	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Utility Room	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Utility Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Utility Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Utility Room	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Utility Room	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Utility Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	Duct	Metal	Green	Flaking	3	0.04	Negative
8270	2	1	Utility Room	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Utility Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	5	0.02	Negative
8270	2	1	Utility Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Utility Room	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Staff Bathroom within Utility Room	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Staff Bathroom within Utility Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Flaking	2	0.01	Negative
8270	2	1	Staff Bathroom within Utility Room	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Staff Bathroom within Utility Room	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Staff Bathroom within Utility Room	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Staff Bathroom within Utility Room	Ceiling	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Staff Bathroom within Utility Room	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 65	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 65	W2	Sheetrock	Beige	Moisture Damage	6	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 65	W3	Concrete	Beige	Flaking	6	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Beige	Flaking	15	0.04	Negative
8270	2	1	Classroom 65	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Restroom	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 65 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 65 Restroom	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Restroom	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Restroom	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Closet	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Closet	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Closet	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Closet	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Closet	Ceiling	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 65 Closet	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room 62	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room 62	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Truancy Room 62	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.03	Negative
8270	2	1	Truancy Room 62	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room 62	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	2	0	Negative
8270	2	1	Truancy Room 62	W3	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room 62	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room 62	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	3	0.05	Negative
8270	2	1	Truancy Room 62	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	3	0.01	Negative
8270	2	1	Truancy Room 62	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room 62	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Courtroom 62B	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Courtroom 62B	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Courtroom 62B	W3	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Courtroom 62B	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Courtroom 62B	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Courtroom 62B	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Restroom	W1	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	3	0.01	Negative

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component Damage Quantity (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	2	1	Truancy Room Restroom	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Restroom	W3	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Restroom	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Center Storage Closet	W1	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Center Storage Closet	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Center Storage Closet	W3	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Center Storage Closet	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Center Storage Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Center Storage Closet	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Window Storage Closet	W1	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Window Storage Closet	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Window Storage Closet	W3	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Window Storage Closet	W4	Sheetrock	Beige	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Window Storage Closet	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Window Storage Closet	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66	W1	Concrete	Beige	Flaking	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 66	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0.02	Negative
8270	2	1	Classroom 66	W2	Sheetrock	Beige	Flaking	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66	W3	Concrete	Beige	Flaking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66	W3	Sheetrock	Beige	Moisture Damage	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Beige	Chipping	15	0.3	Negative
8270	2	1	Classroom 66	W3	N/A	N/A	N/A	N/A	N/A	N/A	Book Shelve	Metal	Beige	Chipping	15	0.03	Negative
8270	2	1	Classroom 66	W4	Sheetrock	Beige	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66	W4	Concrete	Beige	Flaking	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.01	Negative
8270	2	1	Classroom 66	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 66	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Restroom	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Restroom	W2	Sheetrock	Tan	Moisture Damage	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Restroom	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 66 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.03	Negative
8270	2	1	Classroom 66 Restroom	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Restroom	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Closet	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Closet	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Closet	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Closet	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Closet	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 66 Closet	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.01	Negative
8270	2	1	Classroom 63	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 63	W2	Sheetrock	Beige	Flaking	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.01	Negative
8270	2	1	Classroom 63	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 63	W3	Concrete	Beige	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Flaking	15	0	Negative
8270	2	1	Classroom 63	W3	N/A	N/A	N/A	N/A	N/A	N/A	Book Shelve	Metal	Tan	Flaking	10	0	Negative
8270	2	1	Classroom 63	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Restroom	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Restroom	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Restroom	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	5	0.02	Negative
8270	2	1	Classroom 63 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.03	Negative
8270	2	1	Classroom 63 Restroom	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Restroom	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Coat Room	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Coat Room	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Coat Room	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	Element	Room	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	2	1	Classroom 63 Coat Room	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Coat Room	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Classroom 63 Coat Room	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 63	W1	Concrete/Stone	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 63	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 63	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 63	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 63	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Classroom 63	Floor	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Utility Room	W1	Concrete/Stone	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Utility Room	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Utility Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Utility Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Utility Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Exterior Steps adjacent to Utility Room	Floor	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 204	W1	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 204	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.02	Negative
8270	1	2	Classroom 204	W2	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 204	W3	Concrete	Off-White	Cracking	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 204	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	beige	Alligating	30	0.05	Negative
8270	1	2	Classroom 204	W4	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 204	Ceiling	Concrete	White	Cracking, Flaking	150	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 204	Floor	Concrete	N/A	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 203	W1	Concrete	Off-White	Flaking	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 203	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.01	Negative
8270	1	2	Classroom 203	W2	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 203	W3	Concrete	Off-White	Spalling	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 203	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	beige	Alligating	30	0.05	Negative
8270	1	2	Classroom 203	W4	CMU	Off-White	Cracking, Flaking	60	0	Negative	N/A	N/A	N/A	N/A	N/A	0	Negative
8270	1	2	Classroom 203	Ceiling	Concrete	White	Cracking, Flaking	30	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 203	Floor	Concrete	N/A	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W1	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	beige	Friction	4	0	Negative
8270	1	2	Girl's Restroom	W2	CMU	Off-White	Flaking, Spalling	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A	Bathroom Stalls	Transite	Brown	Friction	4	0	Negative
8270	1	2	Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	2	0.01	Negative
8270	1	2	Girl's Restroom	W3	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W4	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	Ceiling	Concrete	White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	Floor	Concrete	N/A	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet adjacent to Restrooms	W1	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet adjacent to Restrooms	W2	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet adjacent to Restrooms	W3	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet adjacent to Restrooms	W4	CMU	Off-White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet adjacent to Restrooms	Ceiling	Concrete	White	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet adjacent to Restrooms	Floor	Concrete	N/A	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms	W1	CMU	Off-White	Partially Inaccessible	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms	W2	CMU	Off-White	Partially Inaccessible	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms	W3	CMU	Off-White	Partially Inaccessible	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms	W4	CMU	Off-White	Partially Inaccessible	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms	Ceiling	Concrete	White	Partially Inaccessible	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Duct	Metal	White	Chipping	2	0.13	Negative
8270	1	2	Storage Closet adjacent to Restrooms	Floor	Concrete	N/A	None	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms Pipe Chase	W1	CMU	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms Pipe Chase	W2	CMU	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms Pipe Chase	W3	CMU	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms Pipe Chase	W4	CMU	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms Pipe Chase	Ceiling	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Closet adjacent to Restrooms Pipe Chase	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	2	0.02	Negative
8270	1	2	Boy's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	1	2	Boy's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Cracking	2	0.01	Negative
8270	1	2	Boy's Restroom	Ceiling	Concrete	White	Flaking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 202	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Friction	4	0	Negative
8270	1	2	Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	White	Chipping	2	0.01	Negative
8270	1	2	Classroom 202	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 202	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 202	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Alligatoring	30	0.25	Negative
8270	1	2	Classroom 202	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 202	Ceiling	Concrete	White	Cracking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 202	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 202	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 202	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 202	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 202	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	5	0.05	Negative
8270	1	2	Stairwell adjacent to Classroom 202	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 202	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 202	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 202	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Green	Friction	5	2.13	Positive
8270	1	2	Stairwell adjacent to Classroom 202	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Green	Cracking	2	1.2	Positive
8270	1	2	Stairwell adjacent to Classroom 202	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Green	Friction	5	0	Negative
8270	1	2	Stairwell adjacent to Classroom 202	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	Metal	Green	Cracking	1	2.7	Positive
8270	1	2	Classroom 201	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 201	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	15	0.07	Negative
8270	1	2	Classroom 201	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 201	W3	Concrete	Off-White	None	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	beige	flaking	15	0.25	Negative
8270	1	2	Classroom 201	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 201	Ceiling	Concrete	White	Moisture Damage	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 201	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 201 to 205	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 201 to 205	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	200	0.08	Negative
8270	1	2	Hallway from Classrooms 201 to 205	W1	N/A	N/A	N/A	N/A	N/A	N/A	Electrical Panel	Metal	red/white	Friction	1	0.01	Negative
8270	1	2	Hallway from Classrooms 201 to 205	W1	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	off white	Chipping	1	0.01	Negative
8270	1	2	Hallway from Classrooms 201 to 205	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 201 to 205	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 201 to 205	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 201 to 205	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.06	Negative
8270	1	2	Hallway from Classrooms 201 to 205	W3	N/A	N/A	N/A	N/A	N/A	N/A	Electrical Panel	Metal	Red	Chipping	1	0	Negative
8270	1	2	Hallway from Classrooms 201 to 205	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 201 to 205	Ceiling	Concrete	White	Flaking	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 201 to 205	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 205	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0	Negative
8270	1	2	Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	White	Friction	5	0.07	Negative
8270	1	2	Classroom 205	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 205	W3	Concrete	Off-White	Cracking	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 205	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 205	W3	CMU	Off-White	None	N/A	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 205	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	tan	Cracking	30	0.05	Negative
8270	1	2	Classroom 205	Ceiling	Concrete	White	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 205	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 205	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	wood	green	Friction	2	0.03	Negative
8270	1	2	Stairwell adjacent to Classroom 205	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	metal	Green	Friction	2	0.03	Negative
8270	1	2	Stairwell adjacent to Classroom 205	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 205	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 205	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 205	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 205	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 205	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Green	Friction	10	0.8	Positive
8270	1	2	Stairwell adjacent to Classroom 205	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Green	chipping	5	3	Positive
8270	1	2	Stairwell adjacent to Classroom 205	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Green	Friction	15	0	Negative
8270	1	2	Stairwell adjacent to Classroom 205	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	Metal	Green	Chipping	5	4.5	Positive

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	Element	Room	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	1	2	Classroom 206	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 206	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	metal	tan	Friction	20	0	Negative
8270	1	2	Classroom 206	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 206	W3	Concrete	Off-White	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 206	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	tan	Alligating	30	0.3	Negative
8270	1	2	Classroom 206	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 206	Ceiling	Concrete	White	Cracking	15	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 206	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 207	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 207	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	tan	Friction	20	0.05	Negative
8270	1	2	Classroom 207	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 207	W3	Concrete	Beige	Flaking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 207	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Alligating	30	0.25	Negative
8270	1	2	Classroom 207	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Alligating	30	0.25	Negative
8270	1	2	Classroom 207	Ceiling	Concrete	White	Flaking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 207	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room/Roof Access	W1	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room/Roof Access	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Green	Flaking	6	0.15	Negative
8270	1	2	Storage Room/Roof Access	W2	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room/Roof Access	W2	N/A	N/A	N/A	N/A	N/A	N/A	Roof Access Ladder	Metal	Green	Friction	10	5	Positive
8270	1	2	Storage Room/Roof Access	W3	Concrete	Green	Cracking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room/Roof Access	W4	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room/Roof Access	Ceiling	Concrete	White	Moisture Damage	30	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room/Roof Access	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classroom 201	W1	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classroom 201	W2	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classroom 201	W3	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classroom 201	W4	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classroom 201	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classroom 201	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom Entrance	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom Entrance	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	1	0.04	Negative
8270	1	2	Women's Restroom Entrance	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom Entrance	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom Entrance	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	1	0.05	Negative
8270	1	2	Women's Restroom Entrance	W4	Concrete	Off-White	Chipping	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom Entrance	Ceiling	Concrete	White	Cracking	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom Entrance	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	1	0.07	Negative
8270	1	2	Women's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	4	0.15	Negative
8270	1	2	Women's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Women's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 216	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 216	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.05	Negative
8270	1	2	Classroom 216	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 216	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 216	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	beige	Chipping	15	0.25	Negative
8270	1	2	Classroom 216	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 216	Ceiling	Concrete	White	Cracking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 216	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway From Classrooms 215 to 216	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway From Classrooms 215 to 216	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	10	0.06	Negative
8270	1	2	Hallway From Classrooms 215 to 216	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway From Classrooms 215 to 216	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	10	0.06	Negative
8270	1	2	Hallway From Classrooms 215 to 216	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway From Classrooms 215 to 216	W3	N/A	N/A	N/A	N/A	N/A	N/A	Electrical Panel	Metal	Yellow	Friction	1	0.01	Negative
8270	1	2	Hallway From Classrooms 215 to 216	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway From Classrooms 215 to 216	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	10	0.05	Negative
8270	1	2	Hallway From Classrooms 215 to 216	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway From Classrooms 215 to 216	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classrooms 215 and 216	W1	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classrooms 215 and 216	W2	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classrooms 215 and 216	W3	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classrooms 215 and 216	W4	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	Element	Room	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	1	2	Storage across from Classrooms 215 and 216	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage across from Classrooms 215 and 216	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 215	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 215	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	tan	Friction	20	0.07	Negative
8270	1	2	Classroom 215	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 215	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 215	w3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Alligating	30	0.27	Negative
8270	1	2	Classroom 215	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 215	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 215	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom Entrance	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom Entrance	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	tan	Friction	2	0.06	Negative
8270	1	2	Men's Restroom Entrance	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom Entrance	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom Entrance	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	tan	Friction	2	0.06	Negative
8270	1	2	Men's Restroom Entrance	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom Entrance	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	peeling	4	0.17	Negative
8270	1	2	Men's Restroom Entrance	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom Entrance	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	metal	Tan	Friction	2	0.06	Negative
8270	1	2	Men's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom	W3	CMU	Off-White	Flaking	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Moisture Damage	3	0.16	Negative
8270	1	2	Men's Restroom	Ceiling	Concrete	White	Moisture Damage	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Men's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 214	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 214	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	22	0.1	Negative
8270	1	2	Classroom 214	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 214	W3	CMU	Off-White	Chipping	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Cracking	15	0.26	Negative
8270	1	2	Classroom 214	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 214	Ceiling	concrete	White	Flaking	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 214	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 213	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 213	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Green	Friction	10	0.04	Negative
8270	1	2	Stairwell adjacent to Classroom 213	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Green	Friction	10	0.03	Negative
8270	1	2	Stairwell adjacent to Classroom 213	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 213	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 213	W4	CMU	Off-White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 213	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 213	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 213	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	metal	green	Friction	10	4.7	Positive
8270	1	2	Stairwell adjacent to Classroom 213	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	metal	Green	Chipping	5	2.4	Positive
8270	1	2	Stairwell adjacent to Classroom 213	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	metal	green	Friction	15	0	Negative
8270	1	2	Stairwell adjacent to Classroom 213	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	metal	green	chipping	5	3.5	Positive
8270	1	2	Classroom 213	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 213	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	tan	friction	20	0.07	Negative
8270	1	2	Classroom 213	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 213	W3	CMU	Off-White	Flaking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 213	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 213	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Beige	Friction	15	0.7	Positive
8270	1	2	Classroom 213	Ceiling	Concrete	White	Flaking	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 213	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	3	0.06	Negative
8270	1	2	Boy's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Moisture Damage	2	0.04	Negative
8270	1	2	Boy's Restroom	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Boy's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room across from Classroom 208	W1	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room across from Classroom 208	W2	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room across from Classroom 208	W3	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room across from Classroom 208	W4	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room across from Classroom 208	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component Damage Quantity (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	1	2	Storage Room across from Classroom 208	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet across from Classroom 208	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet across from Classroom 208	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet across from Classroom 208	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet across from Classroom 208	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet across from Classroom 208	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Custodial Closet across from Classroom 208	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	2	0.04	Negative
8270	1	2	Girl's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	Bathroom Stalls	Wood	Brown	Friction	2	0	Negative
8270	1	2	Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Cracking	3	0.02	Negative
8270	1	2	Girl's Restroom	Ceiling	Concrete	White	Cracking	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Girl's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 212	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 212	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	tan	Friction	20	0.06	Negative
8270	1	2	Classroom 212	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 212	W3	Concrete	White	Flaking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 212	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Beige	Friction	15	0.61	Negative
8270	1	2	Classroom 212	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 212	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 212	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 211	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 211	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.08	Negative
8270	1	2	Classroom 211	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 211	W3	Concrete	White	Flaking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 211	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Beige	Chipping	15	0.19	Negative
8270	1	2	Classroom 211	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 211	Ceiling	Concrete	White	Flaking	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 211	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 210	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 210	W1	N/A	N/A	N/A	N/A	N/A	N/A	Gate	Metal	Black	Friction	5	0	Negative
8270	1	2	Classroom 210	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.06	Negative
8270	1	2	Classroom 210	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 210	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 210	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Beige	Friction	20	0.02	Negative
8270	1	2	Classroom 210	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 210	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 210	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 210	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 210	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 210	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 210	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 210	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 210	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Stairwell adjacent to Classroom 210	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	metal	Green	Friction	20	2.7	Positive
8270	1	2	Stairwell adjacent to Classroom 210	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Green	Friction	40	0	Negative
8270	1	2	Stairwell adjacent to Classroom 210	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Green	Chipping	10	3.7	Positive
8270	1	2	Stairwell adjacent to Classroom 210	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	Metal	Green	Chipping	5	5	Positive
8270	1	2	Stairwell adjacent to Classroom 210	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	2	0.2	Negative
8270	1	2	Classroom 209	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 209	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 209	W3	CMU	Off-White	Moisture Damage	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 209	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 209	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 209	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 209	W1	N/A	N/A	N/A	N/A	N/A	N/A	Sink Cabinet	Metal	Purple	Peeling	4	0	Negative
8270	1	2	Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Peeling	30	0.17	Negative
8270	1	2	Classroom 208	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.08	Negative
8270	1	2	Classroom 208	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 208	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 208	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 208	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 208	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Classroom 208	W1	N/A	N/A	N/A	N/A	N/A	N/A	Closet Shelf	wood	green	Chipping	20	0.14	Negative
8270	1	2	Classroom 208	W1	N/A	N/A	N/A	N/A	N/A	N/A	Sink Cabinet	Metal	Purple	Peeling	4	0	Negative

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	1	2	Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Peeling	30	0.19	Negative
8270	1	2	Hallway from Classrooms 210 to 214	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.07	Negative
8270	1	2	Hallway from Classrooms 210 to 214	W1	CMU	Blue	Flaking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 210 to 214	W1	CMU	Yellow	Flaking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 210 to 214	W1	N/A	N/A	N/A	N/A	N/A	N/A	Stairwell Door Frame	Metal	Tan	Friction	2	0.02	Negative
8270	1	2	Hallway from Classrooms 210 to 214	W2	N/A	N/A	N/A	N/A	N/A	N/A	Stairwell Door	Metal	Tan	Friction	4	0.05	Negative
8270	1	2	Hallway from Classrooms 210 to 214	W2	CMU	White/blue/ yellow	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 210 to 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.07	Negative
8270	1	2	Hallway from Classrooms 210 to 214	W3	CMU	Blue	Flaking	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 210 to 214	W3	CMU	Yellow	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 210 to 214	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	metal	tan	flaking	6	0.04	Negative
8270	1	2	Hallway from Classrooms 210 to 214	Ceiling	Concrete	White	Moisture Damage	6 SF	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 210 to 214	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Hallway from Classrooms 210 to 214	W1	N/A	N/A	N/A	N/A	N/A	N/A	Electrical Panel	Metal	Yellow	Friction	2	0.01	Negative
8270	1	2	Hallway from Classrooms 210 to 214	W1	N/A	N/A	N/A	N/A	N/A	N/A	Electrical Panel	Metal	Blue	Friction	2	0.01	Negative
8270	1	2	Hallway from Classrooms 210 to 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Stairwell Door	Metal	Tan	Chipping	3	0.05	Negative
8270	1	2	Hallway from Classrooms 210 to 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Stairwell door frame	Metal	Tan	Chipping	3	0.04	Negative
8270	1	2	Speech/OT/ESL	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Speech/OT/ESL	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	20	0.06	Negative
8270	1	2	Speech/OT/ESL	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Speech/OT/ESL	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Speech/OT/ESL	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Speech/OT/ESL	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Flaking	1	0.07	Negative
8270	1	2	Speech/OT/ESL	W3	CMU	Off-White	Moisture Damage	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Speech/OT/ESL	W4	CMU	Off-White	Flaking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Speech/OT/ESL	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	20	0.12	Negative
8270	1	2	Speech/OT/ESL	Ceiling	Concrete	White	Flaking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Speech/OT/ESL	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	W1	CMU	Blue	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	2	0.06	Negative
8270	1	2	Storage Room adjacent to Teacher's Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A	Duct	Metal	Beige	Flaking	3	0.02	Negative
8270	1	2	Storage Room adjacent to Teacher's Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A	Electrical fixtures	Metal	Blue	Flaking	1	0.26	Negative
8270	1	2	Storage Room adjacent to Teacher's Lounge	W2	CMU	Blue	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	W3	CMU	Blue	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	W4	CMU	Blue	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 112	W1	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 112	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Green	Friction	5	0.02	Negative
8270	1	1	Stairwell adjacent to Classroom 112	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	5	0.02	Negative
8270	1	1	Stairwell adjacent to Classroom 112	W2	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 112	W3	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 112	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Green	Friction	5	0.02	Negative
8270	1	1	Stairwell adjacent to Classroom 112	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	5	0.02	Negative
8270	1	1	Stairwell adjacent to Classroom 112	W4	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 112	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 112	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 112	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Green	Friction	20	3.2	Positive
8270	1	1	Stairwell adjacent to Classroom 112	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Green	Friction	40	0	Negative
8270	1	1	Stairwell adjacent to Classroom 112	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Green	Chipping	10	1.5	Positive
8270	1	1	Stairwell adjacent to Classroom 112	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	Metal	Green	Chipping	5	2.4	Positive
8270	1	1	Stairwell adjacent to Classroom 112	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Under Carriage	Metal	White	Chipping	2	15	Negative
8270	1	1	Stairwell adjacent to Classroom 112	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	I-Beam	Metal	White	Chipping	2	2.7	Positive
8270	1	1	Stairwell adjacent to Classroom 112	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Green	Chipping	10	1.5	Positive
8270	1	1	Classroom 112	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 112	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.05	Negative
8270	1	1	Classroom 112	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 112	W3	CMU	Off-White	Flaking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 112	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Cover	Metal	White	Flaking	2	1.1	Negative
8270	1	1	Classroom 112	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Alligatoring	20	0.3	Negative
8270	1	1	Classroom 112	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 112	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Hanger	metal	White	Flaking	1	0.03	Negative
8270	1	1	Classroom 112	Ceiling	Concrete	White	Moisture Damage	2	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 112	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 111	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 111	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 111	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	Element	Room	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	1	1	Boy's Restroom next to 111	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 111	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 111	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W1	CMU	Off-White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W2	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W3	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W4	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 111	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 111	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.07	Negative
8270	1	1	Classroom 111	W1	N/A	N/A	N/A	N/A	N/A	N/A	Closet Shelf	Wood	Green	Flaking	15	0.15	Negative
8270	1	1	Classroom 111	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 111	W3	CMU	Off-White	Flaking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	0	Negative
8270	1	1	Classroom 111	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Alligatoring	30	0.59	Negative
8270	1	1	Classroom 111	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Casing	Metal	White	Flaking	2	0.1	Negative
8270	1	1	Classroom 111	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 111	Ceiling	Concrete	White	Moisture Damage	2	0.14	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 111	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Insulation	Asbestos	White	Moisture Damage	3	0.01	Negative
8270	1	1	Classroom 111	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 110	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 110	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.07	Negative
8270	1	1	Classroom 110	W1	N/A	N/A	N/A	N/A	N/A	N/A	Closet Shelf	Wood	Green	Chipping	15	0.07	Negative
8270	1	1	Classroom 110	W2	CMU	Off-White	Chipping	5	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 110	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 110	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Alligatoring	30	0.3	Negative
8270	1	1	Classroom 110	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 110	Ceiling	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 110	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 109	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 109	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	20	0.12	Negative
8270	1	1	Classroom 109	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 109	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 109	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Alligatoring	30	0.45	Negative
8270	1	1	Classroom 109	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Cover	Metal	White	Flaking	2	0.03	Negative
8270	1	1	Classroom 109	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 109	Ceiling	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 109	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 109	W1	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 109	W2	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 109	W3	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 109	W4	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 109	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 109	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 109	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Green	Friction	20	3.2	Positive
8270	1	1	Stairwell adjacent to Classroom 109	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Green	Friction	40	0	Negative
8270	1	1	Stairwell adjacent to Classroom 109	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Green	Chipping	10	1.5	Positive
8270	1	1	Stairwell adjacent to Classroom 109	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	Metal	Green	Chipping	5	2.4	Positive
8270	1	1	Stairwell adjacent to Classroom 109	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Under Carriage	Metal	White	Chipping	2	15	Negative
8270	1	1	Stairwell adjacent to Classroom 109	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	I-Beam	Metal	White	Chipping	2	2.7	Positive
8270	1	1	Stairwell adjacent to Classroom 109	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Green	Chipping	10	1.5	Positive
8270	1	1	Hallway from Classrooms 109 to 113	W1	CMU	White	Flaking	12	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 109 to 113	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	30	0.05	Negative
8270	1	1	Hallway from Classrooms 109 to 113	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 109 to 113	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	30	0.05	Negative
8270	1	1	Hallway from Classrooms 109 to 113	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Green	Friction	5	0.01	Negative

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component Damage Quantity (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	1	1	Hallway from Classrooms 109 to 113	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 109 to 113	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 109 to 113	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	30	0.01	Negative
8270	1	1	Hallway from Classrooms 109 to 113	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 109 to 113	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway at Main Entrance	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway at Main Entrance	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway at Main Entrance	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway at Main Entrance	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway at Main Entrance	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway at Main Entrance	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 101 to 105	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 101 to 105	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	30	0.04	Negative
8270	1	1	Hallway from Classrooms 101 to 105	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 101 to 105	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	30	0.06	Negative
8270	1	1	Hallway from Classrooms 101 to 105	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Friction	5	0.04	Negative
8270	1	1	Hallway from Classrooms 101 to 105	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 101 to 105	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 101 to 105	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	30	0.02	Negative
8270	1	1	Hallway from Classrooms 101 to 105	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Hallway from Classrooms 101 to 105	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	18	0.06	Negative
8270	1	1	Auditorium	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Wall Panell	Wood	Varnish	Flaking	10	0.07	Negative
8270	1	1	Auditorium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	18	0.08	Negative
8270	1	1	Auditorium	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	18	0.03	Negative
8270	1	1	Auditorium	W3	N/A	N/A	N/A	N/A	N/A	N/A	Wall Panell	Wood	Varnish	Flaking	10	0.06	Negative
8270	1	1	Auditorium	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	18	0.05	Negative
8270	1	1	Auditorium	Ceiling	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium	Floor	Wood	Varnish	Chipping	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium	Center	N/A	N/A	N/A	N/A	N/A	N/A	Auditorium Chairs	Wood	Varnish	Chipping	100	0.01	Negative
8270	1	1	Auditorium	Center	N/A	N/A	N/A	N/A	N/A	N/A	Auditorium Chairs	Metal	Brown	Chipping	100	0.03	Negative
8270	1	1	Storage Room across from Classroom 112	W1	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	W2	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	W3	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	W4	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	W1	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	W2	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	W3	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	W4	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0	Negative
8270	1	1	Dean of Students Office	W2	CMU	White	Flaking	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office Bathroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office Bathroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office Bathroom	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.04	Negative
8270	1	1	Dean of Students Office Bathroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office Bathroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office Bathroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Dean of Students Office Bathroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 113	W1	CMU	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 113	W1	N/A	N/A	N/A	N/A	N/A	N/A	metal pipe	Concrete	Green	Chipping	5	0.2	Negative
8270	1	1	Storage Room across from Classroom 113	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	10	0.06	Negative
8270	1	1	Storage Room across from Classroom 113	W2	CMU	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 113	W3	CMU	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 113	W3	N/A	N/A	N/A	N/A	N/A	N/A	electrical panel	Metal	Tan	Friction	10	0.1	Negative
8270	1	1	Storage Room across from Classroom 113	W4	CMU	Green	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

	E	F															
	l	l															
	e	e															
	m	m															
	e	e															
	n	n															
	t	t															

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	Element	Room	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	1	1	Special Education Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.09	Negative
8270	1	1	Special Education Office	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Special Education Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	2	0.03	Negative
8270	1	1	Special Education Office	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Special Education Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Special Education Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Entrance/Exit Foyer	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Entrance/Exit Foyer	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Entrance/Exit Foyer	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Entrance/Exit Foyer	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Entrance/Exit Foyer	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Entrance/Exit Foyer	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.18	Negative
8270	1	1	Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Electrical fixtures	Metal	Beige	Flaking	1	0	Negative
8270	1	1	Main Office	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Beige	Flaking	2	0.16	Negative
8270	1	1	Main Office	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.07	Negative
8270	1	1	Main Office	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Building Engineer's Restroom	W1	Concrete	White	Moisture Damage	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Building Engineer's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	3	0.01	Negative
8270	1	1	Building Engineer's Restroom	W2	Concrete	White	Moisture Damage	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Building Engineer's Restroom	W3	Concrete	White	Moisture Damage	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Building Engineer's Restroom	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Building Engineer's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Building Engineer's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.18	Negative
8270	1	1	Office 125	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	2	0.29	Negative
8270	1	1	Office 125	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	1	0.01	Negative
8270	1	1	Office 125	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125 Closet	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	1	0.08	Negative
8270	1	1	Office 125 Closet	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125 Closet	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125 Closet	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125 Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Office 125 Closet	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office Closet	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office Closet	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office Closet	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Main Office Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Men's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Men's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Men's Restroom	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Men's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Men's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Men's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 101	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 101	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 101	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 101	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 101	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	1	1	Classroom 101	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 101	W1	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 101	W2	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 101	W3	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 101	W4	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 101	Ceiling	Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 101	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 101	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Green	Friction	20	3.2	Positive
8270	1	1	Stairwell adjacent to Classroom 101	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Green	Friction	40	0	Negative
8270	1	1	Stairwell adjacent to Classroom 101	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Green	Chipping	10	1.5	Positive
8270	1	1	Stairwell adjacent to Classroom 101	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	Metal	Green	Chipping	5	2.4	Positive
8270	1	1	Stairwell adjacent to Classroom 101	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Under Carriage	Metal	White	Chipping	2	15	Negative
8270	1	1	Stairwell adjacent to Classroom 101	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	I-Beam	Metal	White	Chipping	2	2.7	Positive
8270	1	1	Stairwell adjacent to Classroom 101	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Green	Chipping	10	1.5	Positive
8270	1	1	Classroom 102	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 102	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 102	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 102	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 102	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 102	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 102	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 102	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.19	Negative
8270	1	1	Boy's Restroom next to 102	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 102	W2	N/A	N/A	N/A	N/A	N/A	N/A	Bathroom Stall	Wood	White	Flaking	3	0	Negative
8270	1	1	Boy's Restroom next to 102	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 102	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 102	Ceiling	Concrete	White	Moisture Damage	3	0.24	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Boy's Restroom next to 102	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	6	0.09	Negative
8270	1	1	Boy's Restroom next to 102	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Girl's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Janitor Closet	Floor	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W1	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W2	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W3	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W4	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 103	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 103	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 103	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 103	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 103	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 103	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 104	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 104	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 104	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 104	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 104	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 104	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 105	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 105	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 105	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 105	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 105	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 105	W1	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 105	W2	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 105	W3	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	1	1	Stairwell adjacent to Classroom 105	W4	CMU	Ceramic Tile	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 105	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stairwell adjacent to Classroom 105	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Green	Friction	20	3.2	Positive
8270	1	1	Stairwell adjacent to Classroom 105	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Green	Friction	40	0	Negative
8270	1	1	Stairwell adjacent to Classroom 105	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Green	Chipping	10	1.5	Positive
8270	1	1	Stairwell adjacent to Classroom 105	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	Metal	Green	Chipping	5	2.4	Positive
8270	1	1	Stairwell adjacent to Classroom 105	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Under Carriage	Metal	White	Chipping	2	15	Negative
8270	1	1	Stairwell adjacent to Classroom 105	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	I-Beam	Metal	White	Chipping	2	2.7	Positive
8270	1	1	Stairwell adjacent to Classroom 105	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Green	Chipping	10	1.5	Positive
8270	1	1	Classroom 106	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 106	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 106	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 106	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 106	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 106	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 107	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 107	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 107	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 107	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 107	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Classroom 107	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Book Closet adjacent to Classroom 107	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Book Closet adjacent to Classroom 107	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.05	Negative
8270	1	1	Book Closet adjacent to Classroom 107	W2	Concrete	Grey	Moisture Damage	2	0.15	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Book Closet adjacent to Classroom 107	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Book Closet adjacent to Classroom 107	W3	N/A	N/A	N/A	N/A	N/A	N/A	Duct	Metal	Grey	Chipping	2	1	Positive
8270	1	1	Book Closet adjacent to Classroom 107	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Book Closet adjacent to Classroom 107	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Grey	Flaking	2	0.18	Negative
8270	1	1	Book Closet adjacent to Classroom 107	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Book Closet adjacent to Classroom 107	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	School Police	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	School Police	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	5	0	Negative
8270	1	1	School Police	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	School Police	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	School Police	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	School Police	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	School Police	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stage	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.04	Negative
8270	1	1	Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Access Panel	Metal	Green	Chipping	12	0.04	Negative
8270	1	1	Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A	Electrical Panel	Metal	Green	Friction	4	0.02	Negative
8270	1	1	Stage	W2	CMU	White	Flaking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stage	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.04	Negative
8270	1	1	Stage	W3	CMU	White	Flaking	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.04	Negative
8270	1	1	Stage	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stage	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.04	Negative
8270	1	1	Stage	Ceiling	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Stage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium Stairs	W1	CMU	White	Flaking	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium Stairs	W2	CMU	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium Stairs	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	2	0.01	Negative
8270	1	1	Auditorium Stairs	W3	CMU	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium Stairs	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	2	0.04	Negative
8270	1	1	Auditorium Stairs	W4	Concrete	White	Flaking	4	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium Stairs	Ceiling	Concrete	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Auditorium Stairs	Floor	Concrete	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	W1	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	W2	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	W3	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	W4	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Classroom 4 to Classroom 5	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Classroom 4 to Classroom 5	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	20	0.01	Negative
8270	1	B	Hallway from Classroom 4 to Classroom 5	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Classroom 4 to Classroom 5	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	20	0.01	Negative

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	Element	Room	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	1	B	Hallway from Classroom 4 to Classroom 5	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Classroom 4 to Classroom 5	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	20	0.01	Negative
8270	1	B	Hallway from Classroom 4 to Classroom 5	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Classroom 4 to Classroom 5	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	20	0.01	Negative
8270	1	B	Hallway from Classroom 4 to Classroom 5	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Classroom 4 to Classroom 5	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4 Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4 Closet	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4 Closet	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4 Closet	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4 Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 4 Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	W1	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	W2	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	W3	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	W4	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Coat Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Coat Closet	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Coat Closet	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Coat Closet	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Coat Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Coat Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	W1	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	W2	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	W3	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	W4	CMU	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Boy's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Boy's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Boy's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Boy's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Boy's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boy's Restroom	W1	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	6	0.29	Negative
8270	1	B	Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Chase Door Frame	Metal	Tan	Flaking	6	1	Positive
8270	1	B	Boy's Restroom	W2	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boy's Restroom	W3	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Green	Friction / Moisture	8	0.01	Negative
8270	1	B	Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction / Moisture	8	0.06	Negative
8270	1	B	Boy's Restroom	W4	CMU	Off-White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boy's Restroom	Ceiling	Concrete	White	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Girl's Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Girl's Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Girl's Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Girl's Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Girl's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway to Library	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway to Library	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

	ULCS#	Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
	8270	1	B	Hallway to Library	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Hallway to Library	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Hallway to Library	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Hallway to Library	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Exterior Exit/Entrance Steps	W1	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Exterior Exit/Entrance Steps	W2	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Exterior Exit/Entrance Steps	W3	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Exterior Exit/Entrance Steps	W4	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Exterior Exit/Entrance Steps	Ceiling	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Exterior Exit/Entrance Steps	Floor	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 1	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 1	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 1	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 1	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 1	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 2	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 2	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 2	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 2	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 2	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Restroom 2	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Utility Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Utility Closet	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Utility Closet	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Utility Closet	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Utility Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Library Utility Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W1	Brick	White	Flaking	300	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction	10	0.01	Negative
	8270	1	B	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	10	0.01	Negative
	8270	1	B	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	80	0	Negative
	8270	1	B	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Flaking	50	0.03	Negative
	8270	1	B	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Grey	Flaking	50	0.03	Negative
	8270	1	B	Boiler Room	W2	CMU	White	Flaking	300	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W2	CMU	Grey	Flaking	300	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W2	Brick	White	Flaking	300	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W2	N/A	N/A	N/A	N/A	N/A	N/A	Electrical Panel	Metal	White	Flaking	10	0.06	Negative
	8270	1	B	Boiler Room	W3	Concrete	White	Flaking	200	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W3	Concrete	Grey	Flaking	250	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W3	Brick	White	Flaking	50	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Beige	Friction	10	0	Negative
	8270	1	B	Boiler Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Beige	Friction	10	0.05	Negative
	8270	1	B	Boiler Room	W4	Concrete	White	Flaking	300	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W4	Concrete	Grey	Flaking	250	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W4	Brick	White	Flaking	250	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Beige	Friction	10	0.05	Negative
	8270	1	B	Boiler Room	Ceiling	Concrete	White	Flaking	1500	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Boiler Room	Floor	Concrete	N/A	n/a	n/a	n/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	W4	CMU	White	Flaking	30	0.03	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	Ceiling	Concrete	White	Flaking	45	0.01	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	Floor	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Blue	Chipping	30	4.3	Positive
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Metal	Yellow	Chipping	30	4.6	Positive
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Blue	Chipping	30	8.7	Positive
	8270	1	B	Metal Boiler Room Exit/Entrance Stairs	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Support	Metal	Grey	Chipping	30	10.1	Positive
	8270	1	B	Tank Room	W1	CMU	White	Flaking	30	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Tank Room	W2	CMU	White	Flaking	30	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	8270	1	B	Tank Room	W3	CMU	White	Flaking	30	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	Element	Room	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	1	B	Tank Room	W4	CMU	White	Flaking	30	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Tank Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Chipping	20	0.7	Positive
8270	1	B	Tank Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Tank Room	Floor	Concrete	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boiler Room Tank Storage	W1	Concrete	White	flaking / Water Damage	30	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boiler Room Tank Storage	W2	Concrete	White	flaking / Water Damage	30	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boiler Room Tank Storage	W3	Concrete	White	flaking / Water Damage	30	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boiler Room Tank Storage	W4	Concrete	White	flaking / Water Damage	30	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boiler Room Tank Storage	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Flaking	20	0.7	Positive
8270	1	B	Boiler Room Tank Storage	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boiler Room Tank Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Boiler Room Entrance Stairs	Center	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Yellow	Friction	12	1.4	Positive
8270	1	B	Boiler Room Entrance Stairs	Center	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Yellow	Friction	20	7.1	Positive
8270	1	B	Boiler Room Entrance Stairs	Center	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Friction	10	7.5	Positive
8270	1	B	Building Engineer's Office	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction	10	0.05	Negative
8270	1	B	Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	10	0.06	Negative
8270	1	B	Building Engineer's Office	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Building Engineer's Office	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Building Engineer's Office	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Building Engineer's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	10	0.06	Negative
8270	1	B	Building Engineer's Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Building Engineer's Office	Floor	Concrete	Grey	Flaking	20	0.15	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Kitchen	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Kitchen	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Kitchen	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Kitchen	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Kitchen	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Entrance/Exit Hallway	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Entrance/Exit Hallway	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Entrance/Exit Hallway	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Entrance/Exit Hallway	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Entrance/Exit Hallway	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Entrance/Exit Hallway	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Staff Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Staff Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Staff Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Staff Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Staff Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Staff Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Closet	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Closet	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Closet	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 1 Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway connecting Classroom 1 and 2	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway connecting Classroom 1 and 2	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway connecting Classroom 1 and 2	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component Damage (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	1	B	Hallway connecting Classroom 1 and 2	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway connecting Classroom 1 and 2	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway connecting Classroom 1 and 2	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Coat Room	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Coat Room	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Coat Room	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Coat Room	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Coat Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Coat Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Closet	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Closet	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Closet	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Closet	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Closet	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Restroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Restroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Restroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Restroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Restroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 2 Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3 Bathroom	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3 Bathroom	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3 Bathroom	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3 Bathroom	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3 Bathroom	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 3 Bathroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Classroom 3	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Classroom 3	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Classroom 3	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Classroom 3	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Classroom 3	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Classroom 3	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Stairwell adjacent to Classroom 3	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Green	Friction	20	3.2	Positive
8270	1	B	Stairwell adjacent to Classroom 3	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Green	Friction	40	0	Negative
8270	1	B	Stairwell adjacent to Classroom 3	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Green	Chipping	10	1.5	Positive
8270	1	B	Stairwell adjacent to Classroom 3	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Ballast	Metal	Green	Chipping	5	2.4	Positive
8270	1	B	Stairwell adjacent to Classroom 3	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Under Carriage	Metal	White	Chipping	2	15	Negative
8270	1	B	Stairwell adjacent to Classroom 3	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	I-Beam	Metal	White	Chipping	2	2.7	Positive
8270	1	B	Stairwell adjacent to Classroom 3	Center/Stairs	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Green	Chipping	10	1.5	Positive
8270	1	B	Hallway between Classrooms 2 and 3	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway between Classrooms 2 and 3	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway between Classrooms 2 and 3	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway between Classrooms 2 and 3	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway between Classrooms 2 and 3	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway between Classrooms 2 and 3	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Boiler Room to Classroom 1	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Boiler Room to Classroom 1	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Boiler Room to Classroom 1	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Boiler Room to Classroom 1	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell

Inspection Dates: 6/10 - 6/14/2019

Inspection Company: VERTEX

ULCS# 8270

ULCS#	Element	Room	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)
8270	1	B	Hallway from Boiler Room to Classroom 1	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Hallway from Boiler Room to Classroom 1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Head Start Kitchen	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Head Start Kitchen	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Head Start Kitchen	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Head Start Kitchen	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Head Start Kitchen	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Head Start Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Cafeteria	W1	CMU	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Cafeteria	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	30	0.06	Negative
8270	1	B	Cafeteria	W2	CMU	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Flaking	15	0.01	Negative
8270	1	B	Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Green	Friction	10	0	Negative
8270	1	B	Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Green	Friction	10	0.15	Negative
8270	1	B	Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	5	0.06	Negative
8270	1	B	Cafeteria	W3	CMU	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	5	0.03	Negative
8270	1	B	Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A	Dividing Wall	Wood	Tan	Friction / Flaking	6	0.01	Negative
8270	1	B	Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A	Dividing Wall Door Frame	Metal	Tan	Friction / Flaking	6	0	Negative
8270	1	B	Cafeteria	W4	CMU	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A	Electrical Panel	Metal	Tan	Flaking	3	0.07	Negative
8270	1	B	Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Friction	4	0.19	Negative
8270	1	B	Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	White	Friction	10	0.18	Negative
8270	1	B	Cafeteria	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	18	0.09	Negative
8270	1	B	Cafeteria	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	White	Flaking	5	0.08	Negative
8270	1	B	Gymnasium	W1	CMU	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium	W2	CMU	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium	W3	CMU	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium	W4	CMU	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium Office	W1	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium Office	W2	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium Office	W3	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium Office	W4	CMU	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium Office	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Gymnasium Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Window Storage Closet	W4	Sheetrock	Beige	None	0	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	2	1	Truancy Room Window Storage Closet	Ceiling	Concrete	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	W1	CMU	Blue	None	0	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	W2	CMU	Blue	None	0	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	W3	CMU	Blue	None	0	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	W4	CMU	Blue	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	2	Storage Room adjacent to Teacher's Lounge	Ceiling	Concrete	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W1	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W2	CMU	White	None	0	0.21	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W3	CMU	White	None	0	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W4	CMU	White	None	0	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	Ceiling	Concrete	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	W1	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	W2	CMU	White	None	0	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	W3	CMU	White	None	0	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	W4	CMU	White	None	0	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 112	Ceiling	Concrete	White	None	0	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	W1	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	W2	CMU	White	None	0	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	W3	CMU	White	None	0	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	W4	CMU	White	None	0	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 111	Ceiling	Concrete	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification for Thomas Holme School

Name of Inspector: Jessica Sewell
Inspection Company: VERTEX

Inspection Dates: 6/10 - 6/14/2019
ULCS# 8270

ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage terms (see	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component Damage Quantity (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
8270	1	1	Storage Room across from Classroom 113	W1	CMU	Green	None	0	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 113	W2	CMU	Green	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 113	W3	CMU	Green	None	0	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage Room across from Classroom 113	Ceiling	Concrete	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W1	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W2	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W3	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	W4	CMU	White	None	0	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	W1	CMU	White	None	0	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	W2	CMU	White	None	0	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	W3	CMU	White	None	0	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	W4	CMU	White	None	0	0.14	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Storage across from Classroom 101	Ceiling	Concrete	White	None	0	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	W1	CMU	White	None	0	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	W2	CMU	White	None	0	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	W3	CMU	White	None	0	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	W4	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Classroom 5 Storage Room	Ceiling	Concrete	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	W1	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	W2	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	W3	CMU	White	None	0	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	W4	CMU	White	None	0	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room across from Classroom 5	Ceiling	Concrete	White	None	0	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	W1	CMU	White	None	0	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	W2	CMU	White	None	0	0.14	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	W3	CMU	White	None	0	0.19	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	W4	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	Ceiling	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	1	Back Office	Floor	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	W1	CMU	White	None	0	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	W2	CMU	White	None	0	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	W3	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	W4	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	Ceiling	CMU	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Back Office Restroom	Floor	CMU	White	None	0	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	W1	CMU	Yellow	None	0	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	W2	CMU	Yellow	None	0	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	W3	CMU	Yellow	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	W4	CMU	Yellow	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	Ceiling	CMU	Yellow	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage adjacent to Head Start Kitchen	Floor	CMU	Yellow	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	W1	CMU	Green	None	0	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	W2	CMU	Green	None	0	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	W3	CMU	Green	None	0	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	W4	CMU	Green	None	0	0.19	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	Ceiling	CMU	Green	None	0	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8270	1	B	Storage Room adjacent to Classroom 1	Floor	CMU	Green	None	0	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A