

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	S2	Faculty Office S2/ Classroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	S2	Faculty Office S2/ Classroom	yes	W2	Sheetrock	Beige	Cracking/Friction	10	0	Negative
1	B	S2	Faculty Office S2/ Classroom	yes	W3	Plaster/CMU	Beige	None	0	N/A	N/A
1	B	S2	Faculty Office S2/ Classroom	yes	Radiator	Metal	Silver	Alligating	20	0.17	Negative
1	B	S2	Faculty Office S2/ Classroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	B	S2	Faculty Office S2/ Classroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	B	S2	Faculty Office S2/ Classroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S1	Classroom S2	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	S1	Classroom S2	yes	W2	Sheetrock	Beige	Cracking/Friction	10	0	Negative
1	B	S1	Classroom S2	yes	W3	Plaster/CMU	Beige	None	0	N/A	N/A
1	B	S1	Classroom S2	yes	Radiator	Metal	Silver	Alligating	20	0.17	Negative
1	B	S1	Classroom S2	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	B	S1	Classroom S2	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	B	S1	Classroom S2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	001	Classroom S1 (Music Room)	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	001	Classroom S1	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	B	001	Classroom S1	yes	W3	Plaster	Beige	Flaking/Cracking	40	13.7	Positive
1	B	001	Classroom S1	yes	Radiator	Metal	Silver	Alligating	40	0.04	Negative
1	B	001	Classroom S1	yes	W4	Sheetrock	Multi	Alligating	300	0	Negative
1	B	001	Classroom S1	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	B	001	Classroom S1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	001A	Classroom S1 Closet	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	001A	Classroom S1 Closet	yes	W2	Plaster	White	Chipping/Flaking	100	15.8	Positive
1	B	001A	Classroom S1 Closet	yes	W3	Plaster	White	Cracking	40	10.3	Positive
1	B	001A	Classroom S1 Closet	yes	W4	Plaster	White	Cracking/Flaking	100	12.8	Positive
1	B	001A	Classroom S1 Closet	yes	Ceiling	Plaster	White	Cracking	60	15.9	Positive
1	B	001A	Classroom S1 Closet	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	H01	Hallway from Classroom S1 to Faculty Office	yes	W1	Brick	Blue	Flaking/Chipping	100	2.4	Positive
1	B	H01	Hallway from Classroom S1 to Faculty Office	yes	W2	Brick	Blue	Flaking/Chipping	100	2.8	Positive
1	B	H01	Hallway from Classroom S1 to Faculty Office	yes	W3	Plaster	Blue	Flaking/Chipping	100	5.2	Positive
1	B	H01	Hallway from Classroom S1 to Faculty Office	yes	W4	Brick	Blue	Flaking/Chipping	100	5.9	Positive
1	B	H01	Hallway from Classroom S1 to Faculty Office	yes	Ceiling	Plaster	White	Flaking/Chipping	100	1.7	Positive
1	B	H01	Hallway from Classroom S1 to Faculty Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S04	Stairwell next to Classroom S1	yes	W1	Brick	Blue	Flaking/Chipping	100	9.4	Positive
1	B	S04	Stairwell next to Classroom S1	yes	W2	Brick	Blue	Flaking/Chipping	100	5.7	Positive
1	B	S04	Stairwell next to Classroom S1	yes	W3	Plaster	Blue	Flaking/Chipping	100	3.7	Positive
1	B	S04	Stairwell next to Classroom S1	yes	W4	Brick	Blue	Flaking/Chipping	100	4	Positive
1	B	S04	Stairwell next to Classroom S1	yes	Ceiling	Plaster	White	Flaking/Chipping	100	15.4	Positive
1	B	S04	Stairwell next to Classroom S1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S04	Stairwell next to Classroom S1	yes	Tread	Concrete	Grey	Friction	30	5.1	Positive
1	B	S04	Stairwell next to Classroom S1	yes	Stringer	Concrete	Grey	Friction	10	12.1	Positive
1	B	S04	Stairwell next to Classroom S1	yes	Riser	Concrete	Grey	Friction	30	8.5	Positive
1	B	S04	Stairwell next to Classroom S1	yes	Newel Post	Concrete	Grey	Friction	10	1.5	Positive
1	B	S04	Stairwell next to Classroom S1	yes	Handrail	Metal	Grey	Friction	5	6.5	Positive
1	B	S04	Stairwell next to Classroom S1	yes	Ballast	Metal	Grey	Friction	15	0.3	Negative
1	B	005	Cafetorium	yes	W1	Brick	Pink	Holes	10	5.6	Positive
1	B	005	Cafetorium	yes	W2	Brick	Pink	None	0	N/A	N/A
1	B	005	Cafetorium	yes	Stair Tread	Concrete	Brown	Friction	20	0.06	Negative
1	B	005	Cafetorium	yes	Stair Riser	Concrete	Brown	Friction	20	2.2	Positive
1	B	005	Cafetorium	yes	W3	Brick	Pink	None	0	N/A	N/A
1	B	005	Cafetorium	yes	Pipe	Metal	Brown	Chipping	6	0.22	Negative

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	005	Cafetorium	yes	W4	Brick	Pink	None	0	N/A	N/A
1	B	005	Cafetorium	yes	Stair Tread	Concrete	Brown	Friction	20	0.06	Negative
1	B	005	Cafetorium	yes	Stair Riser	Concrete	Brown	Friction	20	2.2	Positive
1	B	005	Cafetorium	yes	Ceiling	Plaster	White	Cracking/Chipping	50	24.4	Positive
1	B	005	Cafetorium	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	003	Cafetorium Storage	yes	W1	Brick	Blue	Chipping	40	4.2	Positive
1	B	003	Cafetorium Storage	yes	W2	Brick	Blue	Chipping	20	3.1	Positive
1	B	003	Cafetorium Storage	yes	Pipe	Metal	Pink	Chipping	6	0.25	Negative
1	B	003	Cafetorium Storage	yes	W3	Brick	Blue	Chipping/Cracking	50	1.5	Positive
1	B	003	Cafetorium Storage	yes	W4	Brick	Blue	Chipping/Cracking	50	2.8	Positive
1	B	003	Cafetorium Storage	yes	Ceiling	Plaster	White	Efflorescence/Flaking	20	15.4	Positive
1	B	003	Cafetorium Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	004	Physical Education Office	yes	W1	Brick	White	None	0	N/A	N/A
1	B	004	Physical Education Office	yes	W2	Brick	White	Chipping	10	4.5	Positive
1	B	004	Physical Education Office	yes	W3	Brick	White	None	0	N/A	N/A
1	B	004	Physical Education Office	yes	W4	Brick	White	None	0	N/A	N/A
1	B	004	Physical Education Office	yes	Ceiling	Plaster	White	Cracking	10	12.5	Positive
1	B	004	Physical Education Office	yes	Pipe	Metal	White	Chipping	50	6.9	Positive
1	B	004	Physical Education Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	H05	Cafeteria Exterior Exit Hallway	yes	W1	Brick	White	Alligatoring	30	5.1	Positive
1	B	H05	Cafeteria Exterior Exit Hallway	yes	W2	Brick	White	Alligatoring	20	8.4	Positive
1	B	H05	Cafeteria Exterior Exit Hallway	yes	Window Frame	Wood	White	Alligatoring	30	0.06	Negative
1	B	H05	Cafeteria Exterior Exit Hallway	yes	W3	Brick	White	Flaking/Chipping	40	1.8	Positive
1	B	H05	Cafeteria Exterior Exit Hallway	yes	W4	Brick	White	None	0	N/A	N/A
1	B	H05	Cafeteria Exterior Exit Hallway	yes	Pipe	Metal	Pink	Flaking/Chipping	20	0.16	Negative
1	B	H05	Cafeteria Exterior Exit Hallway	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	H05	Cafeteria Exterior Exit Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	H02	Hallway outside Kitchen and Boiler Room	yes	W1	Brick	Blue	None	0	N/A	N/A
1	B	H02	Hallway outside Kitchen and Boiler Room	yes	W2	Brick	Blue	None	0	N/A	N/A
1	B	H02	Hallway outside Kitchen and Boiler Room	yes	W3	Brick	Blue	None	0	N/A	N/A
1	B	H02	Hallway outside Kitchen and Boiler Room	yes	W4	Brick	Blue	None	0	N/A	N/A
1	B	H02	Hallway outside Kitchen and Boiler Room	yes	Ceiling	Plaster	White	Flaking	100	13.3	Positive
1	B	H02	Hallway outside Kitchen and Boiler Room	yes	Duct	Metal	White	Chipping/Flaking	100	16.4	Positive
1	B	H02	Hallway outside Kitchen and Boiler Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	011	Boiler Room	no	W1	Brick	White	Flaking	500	23.4	Positive
1	B	011	Boiler Room	no	W2	Brick	White	Flaking	500	16.6	Positive
1	B	011	Boiler Room	no	W3	Brick	White	Flaking	500	17.6	Positive
1	B	011	Boiler Room	no	W4	Brick	White	Flaking	500	21.5	Positive
1	B	011	Boiler Room	no	Ceiling	Concrete	White	Flaking	2000	26.5	Positive
1	B	011	Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	012	Fan Room	no	W1	Brick	Blue	Flaking	200	16.4	Positive
1	B	012	Fan Room	no	W2	Brick	Blue	Flaking	100	29.4	Positive
1	B	012	Fan Room	no	Pipe	Metal	Blue	Flaking	10	6.3	Positive
1	B	012	Fan Room	no	W3	Brick	Blue	Flaking	300	29.3	Positive
1	B	012	Fan Room	no	W4	Brick	Blue	Flaking	200	21.3	Positive
1	B	012	Fan Room	no	Ceiling	Concrete	White	Flaking	500	20	Positive
1	B	012	Fan Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	014	Building Engineer's Office	no	W1	Concrete	Pink	Flaking/Efflorescence	500	19.3	Positive
1	B	014	Building Engineer's Office	no	W2	Concrete	Pink	Flaking/Efflorescence	500	10.5	Positive
1	B	014	Building Engineer's Office	no	W3	Concrete	Pink	Flaking/Efflorescence	500	21.6	Positive
1	B	014	Building Engineer's Office	no	W4	Concrete	Pink	Flaking/Efflorescence	500	22	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	014	Building Engineer's Office	no	Ceiling	Concrete	White	Flaking/Efflorescence	1000	20	Positive
1	B	014	Building Engineer's Office	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	013	Oil Tank Room	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
1	B	013	Oil Tank Room	no	W2	Brick	N/A	N/A	N/A	N/A	N/A
1	B	013	Oil Tank Room	no	W3	Brick	N/A	N/A	N/A	N/A	N/A
1	B	013	Oil Tank Room	no	W4	Brick	N/A	N/A	N/A	N/A	N/A
1	B	013	Oil Tank Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	013	Oil Tank Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	007	Kitchen	yes	W1	Brick	White	None	0	N/A	N/A
1	B	007	Kitchen	yes	W2	Brick	White	Cracking	5	1.5	Positive
1	B	007	Kitchen	yes	W3	Brick	White	None	0	N/A	N/A
1	B	007	Kitchen	yes	W4	Brick	White	None	0	N/A	N/A
1	B	007	Kitchen	yes	Ceiling	Plaster	White	Flaking/Cracking/Moist ure	40	4.9	Positive
1	B	007	Kitchen	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	007A	Kitchen Office	yes	W1	Brick	White	None	0	N/A	N/A
1	B	007A	Kitchen Office	yes	W2	Brick	White	None	0	N/A	N/A
1	B	007A	Kitchen Office	yes	W3	Brick	White	None	0	N/A	N/A
1	B	007A	Kitchen Office	yes	W4	Brick	White	None	0	N/A	N/A
1	B	007A	Kitchen Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	007A	Kitchen Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	B2	Classroom B2 (Art Room)	yes	W1	Plaster	White	Chipping/Cracking	20	14.3	Positive
1	B	B2	Classroom B2 (Art Room)	yes	W2	Sheetrock	White	Holes/Moisture Damage	20	0	Negative
1	B	B2	Classroom B2 (Art Room)	yes	W3	Plaster	White	Chipping/Flaking	30	1.5	Positive
1	B	B2	Classroom B2 (Art Room)	yes	Radiator	Metal	Silver	Alligatoring	20	0.03	Negative
1	B	B2	Classroom B2 (Art Room)	yes	W4	Plaster	White	Cracking	10	15.3	Positive
1	B	B2	Classroom B2 (Art Room)	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	B	B2	Classroom B2 (Art Room)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B2A	Classroom B2 Coat Room	yes	W1	Plaster	Yellow	Cracking	100	15.3	Positive
1	B	B2A	Classroom B2 Coat Room	yes	W2	Plaster	Yellow	Cracking	20	4.3	Positive
1	B	B2A	Classroom B2 Coat Room	yes	W3	Plaster	Yellow	Cracking	200	7.1	Positive
1	B	B2A	Classroom B2 Coat Room	yes	W4	Plaster	Yellow	Cracking	20	10.3	Positive
1	B	B2A	Classroom B2 Coat Room	yes	Ceiling	Plaster	Yellow	Cracking	300	19.5	Positive
1	B	B2A	Classroom B2 Coat Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B2B	Classroom B2 Closet	yes	W1	Plaster	Yellow	Cracking/Flaking	100	10.4	Positive
1	B	B2B	Classroom B2 Closet	yes	W2	Plaster	Yellow	Cracking/Flaking	60	9.5	Positive
1	B	B2B	Classroom B2 Closet	yes	W3	Plaster	Yellow	Cracking/Flaking	150	9.6	Positive
1	B	B2B	Classroom B2 Closet	yes	W4	Plaster	Yellow	Cracking/Flaking/Spalli ng	80	9.6	Positive
1	B	B2B	Classroom B2 Closet	yes	Ceiling	Plaster	Yellow	Cracking/Flaking	200	10.3	Positive
1	B	B2B	Classroom B2 Closet	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	009	Classroom B1 (ESOL)	yes	W1	Plaster	White	Chippinh/Cracking	20	16.4	Positive
1	B	009	Classroom B1 (ESOL)	yes	W2	Sheetrock	White	Peeling/Staple Holes	10	9.4	Positive
1	B	009	Classroom B1 (ESOL)	yes	W3	Plaster	White	Efflorescence/Flaking/ Chipping	60	13.2	Positive
1	B	009	Classroom B1 (ESOL)	yes	W4	Sheetrock	White	Peeling/Staple Holes	30	1.3	Positive
1	B	009	Classroom B1 (ESOL)	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	B	009	Classroom B1 (ESOL)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	010	Classroom B1 Closet (Rear of Classroom)	yes	W1	Plaster	Beige	Efflorescence/Flaking	200	15.3	Positive
1	B	010	Classroom B1 Closet (Rear of Classroom)	yes	W2	Plaster	Beige	Efflorescence/Flaking	120	19.5	Positive
1	B	010	Classroom B1 Closet (Rear of Classroom)	yes	W3	Plaster	Beige	Cracking/Efflorescence	100	10.4	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	010	Classroom B1 Closet (Rear of Classroom)	yes	W4	Plaster	Beige	FlakingCracking/Efflorescence	130	4.5	Positive
1	B	010	Classroom B1 Closet (Rear of Classroom)	yes	Ceiling	Plaster	Beige	FlakingCracking/Efflorescence	130	15.3	Positive
1	B	010	Classroom B1 Closet (Adjacent to Entrance)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	011	Classroom B1 Closet (Adjacent to Entrance)	yes	W1	Plaster	Beige	Cracking.Chipping	30	10.4	Positive
1	B	011	Classroom B1 Closet (Adjacent to Entrance)	yes	W2	Plaster	Beige	Flaking/Cracking	50	15.3	Positive
1	B	011	Classroom B1 Closet (Adjacent to Entrance)	yes	W3	Plaster	Beige	Cracking	20	19.6	Positive
1	B	011	Classroom B1 Closet (Adjacent to Entrance)	yes	W4	Plaster	Beige	Cracking	30	18.4	Positive
1	B	011	Classroom B1 Closet (Adjacent to Entrance)	yes	Pipe	Metal	Beige	Chipping	6	1.6	Positive
1	B	011	Classroom B1 Closet (Adjacent to Entrance)	yes	Ceiling	Plaster	Beige	N/A	N/A	N/A	N/A
1	B	011	Classroom B1 Closet (Adjacent to Entrance)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S03	Stairwell next to Classroom B1	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	S03	Stairwell next to Classroom B1	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	B	S03	Stairwell next to Classroom B1	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	B	S03	Stairwell next to Classroom B1	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	B	S03	Stairwell next to Classroom B1	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	S03	Stairwell next to Classroom B1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S03	Stairwell next to Classroom B1	yes	Tread	Concrete	Grey	Friction	30	5.1	Positive
1	B	S03	Stairwell next to Classroom B1	yes	Stringer	Concrete	Grey	Friction	10	12.1	Positive
1	B	S03	Stairwell next to Classroom B1	yes	Riser	Concrete	Grey	Friction	30	8.5	Positive
1	B	S03	Stairwell next to Classroom B1	yes	Newel Post	Concrete	Grey	Friction	10	1.5	Positive
1	B	S03	Stairwell next to Classroom B1	yes	Handrail	Metal	Grey	Friction	5	6.5	Positive
1	B	S03	Stairwell next to Classroom B1	yes	Ballast	Metal	Grey	Friction	15	0.3	Negative
1	B	H03	Hallway outside Classrooms B1 and B2	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	B	H03	Hallway outside Classrooms B1 and B2	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	B	H03	Hallway outside Classrooms B1 and B2	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	B	H03	Hallway outside Classrooms B1 and B2	yes	Tread	Concrete	Grey	Friction	30	5.1	Positive
1	B	H03	Hallway outside Classrooms B1 and B2	yes	Riser	Concrete	Grey	Friction	30	12.1	Positive
1	B	H03	Hallway outside Classrooms B1 and B2	yes	Handrail	Metal	Grey	Friction	10	8.5	Positive
1	B	H03	Hallway outside Classrooms B1 and B2	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	B	H03	Hallway outside Classrooms B1 and B2	yes	Ceiling	Plaster	White	Flaking/Holes/Efflorescence	80	2.6	Positive
1	B	H03	Hallway outside Classrooms B1 and B2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	113	Main Office	yes	W1	Plaster	White	Cracking	5	11.4	Positive
1	1	113	Main Office	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	113	Main Office	yes	W3	Plaster	White	Flaking	40	16.4	Positive
1	1	113	Main Office	yes	W4	Plaster	White	Cracking	5	9	Positive
1	1	113	Main Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	113	Main Office	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	113A	Main Office Closet	yes	W1	Plaster	Yellow	Flaking/Cracking/Chipping	150	5.4	Positive
1	1	113A	Main Office Closet	yes	Pipe	Metal	Yellow	Chipping	30	12	Positive
1	1	113A	Main Office Closet	yes	W2	Plaster	Yellow	Cracking	50	9.5	Positive
1	1	113A	Main Office Closet	yes	W3	Plaster	Yellow	Holes/Cracking	50	6.6	Positive
1	1	113A	Main Office Closet	yes	W4	Plaster	Yellow	Flaking	100	4	Positive
1	1	113A	Main Office Closet	yes	Ceiling	Plaster	Yellow	Flaking/Efflorescence/ Moisture Damage	100	11.6	Positive
1	1	113A	Main Office Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	114	Principal's Office	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	114	Principal's Office	yes	W2	Plaster	White	Cracking	20	21.5	Positive
1	1	114	Principal's Office	yes	W3	Plaster	White	Flaking	20	5	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	114	Principal's Office	yes	W4	Plaster	White	Cracking	20	23.7	Positive
1	1	114	Principal's Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	114	Principal's Office	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	114A	Principal's Closet	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	1	114A	Principal's Closet	yes	W2	Plaster	Yellow	Cracking/Chipping	20	14.7	Positive
1	1	114A	Principal's Closet	yes	W3	Plaster	Yellow	Cracking	10	20	Positive
1	1	114A	Principal's Closet	yes	W4	Plaster	Yellow	Cracking	20	21	Positive
1	1	114A	Principal's Closet	yes	Ceiling	Plaster	Yellow	Flaking/Hole	150	16	Positive
1	1	114A	Principal's Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	114C	Principal's Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	114C	Principal's Restroom	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	114C	Principal's Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	114C	Principal's Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	114C	Principal's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	114C	Principal's Restroom	yes	Floor	Concrete	Blue	None	0	N/A	N/A
1	1	H114	Principal's Hallway	yes	W1	Plaster	Blue	Cracking/Flaking	5	11.5	Positive
1	1	H114	Principal's Hallway	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	H114	Principal's Hallway	yes	W3	Plaster	Blue	Cracking	5	10	Positive
1	1	H114	Principal's Hallway	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	H114	Principal's Hallway	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	H114	Principal's Hallway	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	S13	Stairwell outside Classroom 101	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	S13	Stairwell outside Classroom 101	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	S13	Stairwell outside Classroom 101	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	S13	Stairwell outside Classroom 101	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	S13	Stairwell outside Classroom 101	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	S13	Stairwell outside Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S13	Stairwell outside Classroom 101	yes	Tread	Concrete	Grey	Friction	20	0.03	Negative
1	1	S13	Stairwell outside Classroom 101	yes	Riser	Concrete	Grey	Friction	10	2.6	Positive
1	1	S13	Stairwell outside Classroom 101	yes	Stringer	Concrete	Grey	Friction	10	20	Positive
1	1	S13	Stairwell outside Classroom 101	yes	Ballast	Metal	Brown	Friction	10	0.3	Negative
1	1	S13	Stairwell outside Classroom 101	yes	Newel Post	Metal	Brown	Friction	6	2.6	Positive
1	1	100	Women's Restroom next to Classroom 101	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	100	Women's Restroom next to Classroom 101	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	100	Women's Restroom next to Classroom 101	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	100	Women's Restroom next to Classroom 101	yes	Radiator	Metal	Silver	Alligating	10	0.03	Negative
1	1	100	Women's Restroom next to Classroom 101	yes	Pipe	Metal	Beige	Flaking	10	0.04	Negative
1	1	100	Women's Restroom next to Classroom 101	yes	W4	Plaster	Beige	Efflorescence	5	6.7	Positive
1	1	100	Women's Restroom next to Classroom 101	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	100	Women's Restroom next to Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101	Classroom 101	yes	W1	Plaster	Beige	Chipping	30	23.6	Positive
1	1	101	Classroom 101	yes	W2	Plaster	Beige	Chipping/Cracking	20	10.5	Positive
1	1	101	Classroom 101	yes	W3	Plaster	Beige	Flaking/Efflorescence/ Cracking	60	11.6	Positive
1	1	101	Classroom 101	yes	W4	Plaster	Beige	Cracking/Chipping	40	9.5	Positive
1	1	101	Classroom 101	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	101	Classroom 101	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	101A	Classroom 101 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	101A	Classroom 101 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	101A	Classroom 101 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	101A	Classroom 101 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	101A	Classroom 101 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	101A	Classroom 101 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	101B	Classroom 101 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	101B	Classroom 101 Restroom	yes	W2	Plaster	Beige	Cracking	10	23	Positive
1	1	101B	Classroom 101 Restroom	yes	W3	Plaster	Beige	Hole/Cracking	20	15.5	Positive
1	1	101B	Classroom 101 Restroom	yes	Radiator	Metal	Silver	Alligatoring	10	0.05	Negative
1	1	101B	Classroom 101 Restroom	yes	W4	Plaster	Beige	Cracking	60	21	Positive
1	1	101B	Classroom 101 Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	101B	Classroom 101 Restroom	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	102	Classroom 102	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	102	Classroom 102	yes	W2	Plaster	Beige	Holes/Chipping	10	10	Positive
1	1	102	Classroom 102	yes	W3	Plaster	Beige	Staple Holes/Flaking/Chipping	40	6.7	Positive
1	1	102	Classroom 102	yes	W4	Plaster	Beige	Staple Holes	10	23.6	Positive
1	1	102	Classroom 102	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	102	Classroom 102	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	102A	Classroom 102 Coat Room	yes	W1	Plaster	Blue	Cracking	1	10.5	Positive
1	1	102A	Classroom 102 Coat Room	yes	W2	Plaster	Blue	Cracking/Chipping	30	11.6	Positive
1	1	102A	Classroom 102 Coat Room	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	1	102A	Classroom 102 Coat Room	yes	W4	Plaster	Blue	Cracking	20	9.5	Positive
1	1	102A	Classroom 102 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	102A	Classroom 102 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	yes	W1	Plaster	Beige	Chipping/Cracking	30	23	Positive
1	1	103	Classroom 103	yes	W2	Plaster	Beige	Cracking/Flaking	10	15.5	Positive
1	1	103	Classroom 103	yes	W3	Plaster	Beige	Flaking/Chipping/Crack ing	40	21	Positive
1	1	103	Classroom 103	yes	Radiator	Metal	Silver	Alligatoring	20	0.07	Negative
1	1	103	Classroom 103	yes	W4	Plaster	Beige	Chipping	10	10	Positive
1	1	103	Classroom 103	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	103A	Classroom 103 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	103A	Classroom 103 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	103A	Classroom 103 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	103A	Classroom 103 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	103A	Classroom 103 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	103A	Classroom 103 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	103B	Classroom 103 Storage Closet	yes	W1	Plaster	Beige	Efflorescence/Flaking	100	14	Positive
1	1	103B	Classroom 103 Storage Closet	yes	Radiator	Metal	Silver	Alligatoring	15	0.04	Negative
1	1	103B	Classroom 103 Storage Closet	yes	W2	Plaster	Beige	Efflorescence/Flaking/ Cracking	100	11	Positive
1	1	103B	Classroom 103 Storage Closet	yes	W3	Plaster	Beige	Chipping/Cracking	80	9.5	Positive
1	1	103B	Classroom 103 Storage Closet	yes	W4	Plaster	Beige	Cracking	60	10	Positive
1	1	103B	Classroom 103 Storage Closet	yes	Ceiling	Plaster	White	Flaking	60	21	Positive
1	1	103B	Classroom 103 Storage Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	S12	Stairwell outside Classroom 103	yes	W1	Plaster	White	Flaking	10	25.4	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Door	Metal	Brown	Friction	20	2.5	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Door Frame	Metal	Brown	Friction	20	9.3	Positive
1	1	S12	Stairwell outside Classroom 103	yes	W2	Plaster	White	Flaking/Cracking	40	12.6	Positive
1	1	S12	Stairwell outside Classroom 103	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	S12	Stairwell outside Classroom 103	yes	Door	Metal	Brown	Friction	20	12.4	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Door Frame	Metal	Brown	Friction	20	11	Positive
1	1	S12	Stairwell outside Classroom 103	yes	W4	Plaster	White	Moisture	10	14.4	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	S12	Stairwell outside Classroom 103	yes	Ceiling	Plaster	White	Cracking	20	12.5	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	S12	Stairwell outside Classroom 103	yes	Tread	Concrete	Grey	Friction	30	5.1	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Stringer	Concrete	Grey	Friction	10	12.1	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Riser	Concrete	Grey	Friction	30	8.5	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Newel Post	Concrete	Grey	Friction	10	1.5	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Handrail	Metal	Grey	Friction	5	6.5	Positive
1	1	S12	Stairwell outside Classroom 103	yes	Ballast	Metal	Grey	Friction	15	0.3	Negative
1	1	H14	Hallway from Classrooms 101 to 103	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	H14	Hallway from Classrooms 101 to 103	yes	Door	Metal	Brown	Friction	20	2.7	Positive
1	1	H14	Hallway from Classrooms 101 to 103	yes	Door Frame	Metal	Brown	Friction	20	4.2	Positive
1	1	H14	Hallway from Classrooms 101 to 103	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	H14	Hallway from Classrooms 101 to 103	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	H14	Hallway from Classrooms 101 to 103	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	H14	Hallway from Classrooms 101 to 103	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classrooms 101 to 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	103B	Girl's Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	103B	Girl's Restroom	yes	W2	Plaster	Beige	Chipping	20	12.5	Positive
1	1	103B	Girl's Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	103B	Girl's Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	103B	Girl's Restroom	yes	Ceiling	Plaster	White	Efflorescence/Moisture	50	23.5	Positive
1	1	103B	Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	104	Classroom 104	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	104	Classroom 104	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
1	1	104	Classroom 104	yes	W3	Plaster	White	Flaking	10	9.5	Positive
1	1	104	Classroom 104	yes	Radiator	Metal	Silver	Alligating	10	0.04	Negative
1	1	104	Classroom 104	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	104	Classroom 104	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Coat Room	yes	W1	Plaster	White	Chipping/Cracking	30	9.2	Positive
1	1	104A	Classroom 104 Coat Room	yes	W2	Plaster	White	Cracking	20	5	Positive
1	1	104A	Classroom 104 Coat Room	yes	W3	Plaster	White	Chipping/Cracking	10	12.4	Positive
1	1	104A	Classroom 104 Coat Room	yes	W4	Plaster	White	Cracking	5	4.5	Positive
1	1	104A	Classroom 104 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	105	Classroom 105	yes	W1	Plaster	Beige	Chipping/Cracking	40	10.2	Positive
1	1	105	Classroom 105	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
1	1	105	Classroom 105	yes	W3	Plaster	Beige	Chipping/Cracking/Flaking	60	5.7	Positive
1	1	105	Classroom 105	yes	Radiator	Metal	Silver	Alligating	15	0.07	Negative
1	1	105	Classroom 105	yes	W4	Sheetrock	Beige	Chipping/Staple Holes	20	6	Positive
1	1	105	Classroom 105	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	105	Classroom 105	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105A	Classroom 105 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	105A	Classroom 105 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	105A	Classroom 105 Coat Room	yes	W3	Plaster	Beige	Chipping/Holes	60	10.4	Positive
1	1	105A	Classroom 105 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	105A	Classroom 105 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	105A	Classroom 105 Coat Room	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	S15A	Auditorium Entrance Staircase across from Classroom 105	yes	W1	Plaster	Beige	None	0	N/A	N/A

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	S15A	Auditorium Entrance Staircase across from Classroom 105	yes	W2	Plaster	Beige	Cracking	30	12.3	Positive
1	1	S15A	Auditorium Entrance Staircase across from Classroom 105	yes	W3	Plaster	Beige	Cracking	30	22.3	Positive
1	1	S15A	Auditorium Entrance Staircase across from Classroom 105	yes	W4	Plaster	Beige	Cracking	30	10	Positive
1	1	S15A	Auditorium Entrance Staircase across from Classroom 105	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S15A	Auditorium Entrance Staircase across from Classroom 105	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S15B	Auditorium Entrance Staircase across from Classroom 106	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	S15B	Auditorium Entrance Staircase across from Classroom 106	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	S15B	Auditorium Entrance Staircase across from Classroom 106	yes	W3	Plaster	Beige	Cracking	30	9.6	Positive
1	1	S15B	Auditorium Entrance Staircase across from Classroom 106	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	S15B	Auditorium Entrance Staircase across from Classroom 106	yes	Ceiling	Plaster	White	Flaking	10	10.4	Positive
1	1	S15B	Auditorium Entrance Staircase across from Classroom 106	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	112	Auditorium	yes	W1	Plaster	Tan	Cracking	15	9.5	Positive
1	1	112	Auditorium	yes	W2	Plaster	Tan	Chipping/Cracking	30	7.5	Positive
1	1	112	Auditorium	yes	Door	Metal	Brown	Friction	20	0.07	Negative
1	1	112	Auditorium	yes	Door Frame	Metal	Brown	Friction	20	0.08	Negative
1	1	112	Auditorium	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	112	Auditorium	yes	W4	Plaster	Tan	Chipping	10	19.3	Positive
1	1	112	Auditorium	yes	Door	Metal	Brown	Friction	20	0.05	Negative
1	1	112	Auditorium	yes	Door Frame	Metal	Brown	Friction	20	0.02	Negative
1	1	112	Auditorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	112	Auditorium	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	112A	Stage	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	112A	Stage	yes	W2	Plaster	White	Chipping/Holes	20	19.4	Positive
1	1	112A	Stage	yes	W3	Plaster	White	Chipping/Cracking	40	10.3	Positive
1	1	112A	Stage	yes	W4	Plaster	White	Chipping/Cracking	40	19.3	Positive
1	1	112A	Stage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	112A	Stage	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	112B	Stage Left Storage Room (Main Office Side)	yes	W1	Plaster	White	Chipping	5	9.5	Positive
1	1	112B	Stage Left Storage Room (Main Office Side)	yes	W2	Plaster	White	Flaking	3	12.4	Positive
1	1	112B	Stage Left Storage Room (Main Office Side)	yes	W3	Plaster	White	Moisture Damage/Efflorescence	20	21.3	Positive
1	1	112B	Stage Left Storage Room (Main Office Side)	yes	W4	Plaster	White	Efflorescence	20	17.6	Positive
1	1	112B	Stage Left Storage Room (Main Office Side)	yes	Ceiling	Plaster	White	Efflorescence	3	18.4	Positive
1	1	112B	Stage Left Storage Room (Main Office Side)	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	112C	Stage Right Storage Room (Classroom 110 Side)	yes	W1	Plaster	White	Cracking/Flaking	10	12.3	Positive
1	1	112C	Stage Right Storage Room (Classroom 110 Side)	yes	W2	Plaster	White	Flaking/Cracking/Efflorescence	50	19.4	Positive
1	1	112C	Stage Right Storage Room (Classroom 110 Side)	yes	W3	Plaster	White	Flaking/Cracking/Efflorescence	50	17.5	Positive
1	1	112C	Stage Right Storage Room (Classroom 110 Side)	yes	W4	Plaster	White	Efflorescence	5	10.3	Positive



## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	112C	Stage Right Storage Room (Classroom 110 Side)	yes	Ceiling	Plaster	White	Flaking/Cacking	30	11	Positive
1	1	112C	Stage Right Storage Room (Classroom 110 Side)	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	112D	Office 107A	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112D	Office 107A	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112D	Office 107A	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112D	Office 107A	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112D	Office 107A	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112D	Office 107A	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	106	Classroom 106	yes	W1	Plaster	Beige	Chipping/Cracking/Staple Holes	50	21.3	Positive
1	1	106	Classroom 106	yes	W2	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	yes	W3	Plaster	Beige	Cracking/Chipping/Flaking	30	26.5	Positive
1	1	106	Classroom 106	yes	W4	Sheetrock	Beige	Staple Holes	10	20.4	Positive
1	1	106	Classroom 106	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	106A	Classroom 106 Coat Room	yes	W1	Plaster	Yellow	Cracking/Chipping	50	29.4	Positive
1	1	106A	Classroom 106 Coat Room	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	106A	Classroom 106 Coat Room	yes	W3	Plaster	Yellow	Cracking	10	12.4	Positive
1	1	106A	Classroom 106 Coat Room	yes	W4	Plaster	Yellow	Cracking/Chipping	20	10.4	Positive
1	1	106A	Classroom 106 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	106A	Classroom 106 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	yes	W1	Plaster	Blue/Green	Chipping/cracking/Staple Holes/Flaking	50	9.5	Positive
1	1	107	Classroom 107	yes	W2	Plaster	Blue/Green	Flaking/Cracking/Chipping	60	7.9	Positive
1	1	107	Classroom 107	yes	W3	Plaster	Blue/Green	Efflorescence/Flaking/Chipping/Cracking	60	10.4	Positive
1	1	107	Classroom 107	yes	Radiator	Metal	Silver	Alligatoring	20	0.04	Negative
1	1	107	Classroom 107	yes	W4	Plaster	Blue/Green	Flaking	10	16.8	Positive
1	1	107	Classroom 107	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Coat Room	yes	W1	Plaster	Blue/Green	Chipping	40	17.8	Positive
1	1	107A	Classroom 107 Coat Room	yes	W2	Plaster	Blue/Green	None	0	N/A	N/A
1	1	107A	Classroom 107 Coat Room	yes	W3	Plaster	Blue/Green	Chipping	40	7.9	Positive
1	1	107A	Classroom 107 Coat Room	yes	W4	Plaster	Blue/Green	Chipping	40	3.9	Positive
1	1	107A	Classroom 107 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	S14	Fire Tower across from Classroom 107	yes	W1	Brick	White	Flaking	500	21.8	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	Door	Metal	Green	Flaking	20	26.7	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	Door Frame	Metal	Green	Flaking	20	29	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	W2	Brick	White	Flaking	500	17.9	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	Pipe	Metal	White	Flaking	20	2.1	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	W3	Brick	White	Flaking	500	26.9	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	Door	Metal	Grey	Flaking	20	10	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	Door Frame	Metal	Grey	Flaking	20	7.9	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	W4	Brick	White	Flaking	500	18.8	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	Window Safety Bars	Metal	Black	Flaking	120	26	Positive
1	1	S14	Fire Tower across from Classroom 107	yes	Ceiling	Concrete	White	Flaking	1000	18.9	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	S14	Fire Tower across from Classroom 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	107B	Boy's Restroom	yes	W1	Plaster	Blue	Efflorescence	5	5.8	Positive
1	1	107B	Boy's Restroom	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	107B	Boy's Restroom	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	1	107B	Boy's Restroom	yes	W4	Plaster	Blue	Cracking/Flaking	50	16.7	Positive
1	1	107B	Boy's Restroom	yes	Ceiling	Plaster	White	Moisture Damage	30	17.6	Positive
1	1	107B	Boy's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	H15	Hallway from Classrooms 104 to 107	yes	W1	Plaster	Beige	Flaking/Efflorescence/ Cracking	50	17.8	Positive
1	1	H15	Hallway from Classrooms 104 to 107	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	H15	Hallway from Classrooms 104 to 107	yes	W3	Plaster	Beige	Cracking	30	18	Positive
1	1	H15	Hallway from Classrooms 104 to 107	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	H15	Hallway from Classrooms 104 to 107	yes	Door	Metal	Brown	Friction	10	6.6	Positive
1	1	H15	Hallway from Classrooms 104 to 107	yes	Door Frame	Metal	Brown	Friction	10	6.1	Positive
1	1	H15	Hallway from Classrooms 104 to 107	yes	Radiator	Metal	Silver	Alligatoring	30	0.05	Negative
1	1	H15	Hallway from Classrooms 104 to 107	yes	Pipe	Metal	Brown	Chipping	24	13.3	Negative
1	1	H15	Hallway from Classrooms 104 to 107	yes	Electrical Panel	Metal	Brown	Chloioing	5	0.26	Negative
1	1	H15	Hallway from Classrooms 104 to 107	yes	W4	Plaster	Beige	Cracking	40	15.9	Positive
1	1	H15	Hallway from Classrooms 104 to 107	yes	Ceiling	Plaster	White	Flaking	20	14.8	Positive
1	1	H15	Hallway from Classrooms 104 to 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairwell next to Classroom 108	yes	W1	Plaster	White	Flaking	10	15.8	Positive
1	1	S11	Stairwell next to Classroom 108	yes	Door	Metal	Brown	Friction	20	0	Negative
1	1	S11	Stairwell next to Classroom 108	yes	Door Frame	Metal	Brown	Friction	20	0	Negative
1	1	S11	Stairwell next to Classroom 108	yes	W2	Plaster	White	Flaking/Cracking	40	14.9	Positive
1	1	S11	Stairwell next to Classroom 108	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	S11	Stairwell next to Classroom 108	yes	Door	Metal	Brown	Friction	20	6.9	Positive
1	1	S11	Stairwell next to Classroom 108	yes	Door Frame	Metal	Brown	Friction	20	6.7	Positive
1	1	S11	Stairwell next to Classroom 108	yes	W4	Plaster	White	Moisture	10	16.8	Positive
1	1	S11	Stairwell next to Classroom 108	yes	Ceiling	Plaster	White	Cracking	20	24.9	Positive
1	1	S11	Stairwell next to Classroom 108	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	S11	Stairwell next to Classroom 108	yes	Tread	Concrete	Grey	Friction	20	3.9	Positive
1	1	S11	Stairwell next to Classroom 108	yes	Stringer	Concrete	Grey	Friction	10	0.25	Negative
1	1	S11	Stairwell next to Classroom 108	yes	Riser	Concrete	Grey	Friction	10	14.7	Positive
1	1	S11	Stairwell next to Classroom 108	yes	Ballast	Metal	Brown	Friction	20	0.4	Negative
1	1	S11	Stairwell next to Classroom 108	yes	Newel Post	Metal	Grey	Friction	20	11.4	Positive
1	1	S11	Stairwell next to Classroom 108	yes	Handrail	Metal	Brown	Friction	10	0.18	Negative
1	1	108	Classroom 108	yes	W1	Plaster	Beige	Chipping/Cracking	20	14.8	Positive
1	1	108	Classroom 108	yes	W2	Plaster	Beige	Chipping/Cracking	20	9.7	Positive
1	1	108	Classroom 108	yes	W3	Plaster	Beige	Chipping/Cracking/Flak ing	40	5.8	Positive
1	1	108	Classroom 108	yes	W4	Plaster	Beige	Chipping/Flaking	50	16.9	Positive
1	1	108	Classroom 108	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	108B	Classroom 108 Restroom	yes	W1	Plaster	White	Cracking/Flaking	10	11.1	Positive
1	1	108B	Classroom 108 Restroom	yes	W2	Plaster	White	Efflorescence/Moisture Damage	15	9.8	Positive
1	1	108B	Classroom 108 Restroom	yes	Pipe	Metal	White	Chipping	5	0.02	Negative
1	1	108B	Classroom 108 Restroom	yes	Radiator	Metal	Silver	Alligatoring	10	0.08	Negative
1	1	108B	Classroom 108 Restroom	yes	W3	Plaster	White	Flaking/Chipping	20	15	Positive
1	1	108B	Classroom 108 Restroom	yes	W4	Sheetrock	White	Moisture Damage/Cracking	10	0	Negative
1	1	108B	Classroom 108 Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	108B	Classroom 108 Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	1	108A	Classroom 108 Coat Room	yes	W1	Plaster	Yellow	Cracking	20	16.8	Positive
1	1	108A	Classroom 108 Coat Room	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	108A	Classroom 108 Coat Room	yes	W3	Plaster	Yellow	Cracking	20	9.6	Positive
1	1	108A	Classroom 108 Coat Room	yes	W4	Plaster	Yellow	Cracking	20	4.8	Positive
1	1	108A	Classroom 108 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	108A	Classroom 108 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	yes	W1	Plaster	Beige	Cracking/Holes	40	12.9	Positive
1	1	109	Classroom 109	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	109	Classroom 109	yes	W3	Plaster	Beige	Flaking/Chipping/Crack ing	50	18.9	Positive
1	1	109	Classroom 109	yes	Radiator	Metal	Silver	Alligatoring	30	0.08	Negative
1	1	109	Classroom 109	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	109	Classroom 109	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	109A	Classroom 109 Coat Room	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	1	109A	Classroom 109 Coat Room	yes	W2	Plaster	Blue	Cracking/Chipping	40	15.8	Positive
1	1	109A	Classroom 109 Coat Room	yes	W3	Plaster	Blue	Cracking	10	14.9	Positive
1	1	109A	Classroom 109 Coat Room	yes	W4	Plaster	Blue	Cracking/Chipping	30	19.9	Positive
1	1	109A	Classroom 109 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	109A	Classroom 109 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	110	Classroom 110	yes	W1	Plaster	Beige	Chipping/Cracking	40	6.9	Positive
1	1	110	Classroom 110	yes	W2	Plaster	Beige	Chipping	30	4	Positive
1	1	110	Classroom 110	yes	W3	Plaster	Beige	Flaking/Chipping/Crack ing	60	17.9	Positive
1	1	110	Classroom 110	yes	W4	Plaster	Beige	Hole/Cracking	20	9.7	Positive
1	1	110	Classroom 110	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	110	Classroom 110	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	110A	Classroom 110 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	110A	Classroom 110 Coat Room	yes	W2	Plaster	Beige	Flaking/Chipping	50	16.8	Positive
1	1	110A	Classroom 110 Coat Room	yes	W3	Plaster	Beige	Flaking/Chipping/Crack ing	50	16.9	Positive
1	1	110A	Classroom 110 Coat Room	yes	W4	Plaster	Beige	Chipping	5	9.3	Positive
1	1	110A	Classroom 110 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	110A	Classroom 110 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	111	Men's Restroom	yes	W1	Plaster	Beige	Cracking	20	10.6	Positive
1	1	111	Men's Restroom	yes	W2	Plaster	Beige	Cracking	20	13.9	Positive
1	1	111	Men's Restroom	yes	W3	Plaster	Beige	Cracking	20	11.9	Positive
1	1	111	Men's Restroom	yes	W4	Plaster	Beige	Cracking	20	15	Positive
1	1	111	Men's Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	111	Men's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H16	Hallway from Classrooms 108 to 110	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	H16	Hallway from Classrooms 108 to 110	yes	Door	Metal	Brown	Friction	20	6.9	Positive
1	1	H16	Hallway from Classrooms 108 to 110	yes	Door Frame	Metal	Brown	Friction	20	4.8	Positive
1	1	H16	Hallway from Classrooms 108 to 110	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	H16	Hallway from Classrooms 108 to 110	yes	Pipe	Metal	Brown	Chipping/Flaking	8	8.2	Positive
1	1	H16	Hallway from Classrooms 108 to 110	yes	Radiator	Metal	Silver	Alligatoring	10	0	Negative
1	1	H16	Hallway from Classrooms 108 to 110	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	H16	Hallway from Classrooms 108 to 110	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	H16	Hallway from Classrooms 108 to 110	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	H16	Hallway from Classrooms 108 to 110	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S17	Stairwell outside Classroom 110	yes	W1	Plaster	Beige	None	0	N/A	N/A

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	S17	Stairwell outside Classroom 110	yes	W2	Plaster	Beige	Cracking/Flaking	20	28.9	Positive
1	1	S17	Stairwell outside Classroom 110	yes	W3	Plaster	Beige	Cracking/Flaking	20	26	Positive
1	1	S17	Stairwell outside Classroom 110	yes	W4	Plaster	Beige	Cracking/Flaking	5	16.5	Positive
1	1	S17	Stairwell outside Classroom 110	yes	Ceiling	Plaster	Beige	N/A	N/A	N/A	N/A
1	1	S17	Stairwell outside Classroom 110	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S17	Stairwell outside Classroom 110	yes	Tread	Concrete	Grey	Friction	20	0.03	Negative
1	1	S17	Stairwell outside Classroom 110	yes	Riser	Concrete	Grey	Friction	10	2.6	Positive
1	1	S17	Stairwell outside Classroom 110	yes	Stringer	Concrete	Grey	Friction	10	20	Positive
1	1	S17	Stairwell outside Classroom 110	yes	Ballast	Metal	Brown	Friction	10	0.3	Negative
1	1	S17	Stairwell outside Classroom 110	yes	Newel Post	Metal	Brown	Friction	6	2.6	Positive
1	2	213	Teacher's Lounge	yes	W1	Plaster	Green	Friction	20	18	Positive
1	2	213	Teacher's Lounge	yes	Door	Wood	Brown	Friction	10	0.06	Negative
1	2	213	Teacher's Lounge	yes	Door Frame	Wood	Brown	Friction	10	0.03	Negative
1	2	213	Teacher's Lounge	yes	W2	Plaster	Green	Holes	5	17.8	Positive
1	2	213	Teacher's Lounge	yes	door	Wood	Brown	Friction	10	0.03	Negative
1	2	213	Teacher's Lounge	yes	door frame	Wood	Brown	Friction	10	0.04	Negative
1	2	213	Teacher's Lounge	yes	W3	Plaster	Green	Efflorescence	10	16.5	Positive
1	2	213	Teacher's Lounge	yes	window sill	Wood	Brown	Friction	10	1.5	Positive
1	2	213	Teacher's Lounge	yes	W4	Plaster	Green	None	0	N/A	N/A
1	2	213	Teacher's Lounge	yes	door frame	Wood	Brown	Friction	10	0.03	Negative
1	2	213	Teacher's Lounge	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	213	Teacher's Lounge	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	213A	Teacher's Lounge Closet	no	W1	Plaster	Green	Flaking	60	16.7	Positive
1	2	213A	Teacher's Lounge Closet	no	W2	Plaster	Green	None	0	N/A	N/A
1	2	213A	Teacher's Lounge Closet	no	Door Frame	Wood	Brown	Friction	10	0.02	Negative
1	2	213A	Teacher's Lounge Closet	no	W3	Plaster	Green	Flaking	40	11	Positive
1	2	213A	Teacher's Lounge Closet	no	W4	Plaster	Green	Flaking	80	19.8	Positive
1	2	213A	Teacher's Lounge Closet	no	Ceiling	Plaster	White	Flaking	100	10.9	Positive
1	2	213A	Teacher's Lounge Closet	no	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	214A	Women's Restroom adjacent to Teacher's Lounge	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	214A	Women's Restroom adjacent to Teacher's Lounge	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	214A	Women's Restroom adjacent to Teacher's Lounge	yes	pipe	Metal	Yellow	Moisture Damage, flaking	5	11.2	Positive
1	2	214A	Women's Restroom adjacent to Teacher's Lounge	yes	Stall Doors	Wood	Brown	Friction	20	11.8	Positive
1	2	214A	Women's Restroom adjacent to Teacher's Lounge	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	214A	Women's Restroom adjacent to Teacher's Lounge	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	214A	Women's Restroom adjacent to Teacher's Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	214A	Women's Restroom adjacent to Teacher's Lounge	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	214	Counselor's Office 214	yes	W1	Plaster	Yellow	Chipping	20	12.5	Positive
1	2	214	Counselor's Office 214	yes	door	Wood	Brown	Friction	5	11.7	Positive
1	2	214	Counselor's Office 214	yes	door frame	Wood	Brown	Friction	5	9.8	Positive
1	2	214	Counselor's Office 214	yes	W2	Plaster	Yellow	Efflorescence, flaking	40	10	Positive
1	2	214	Counselor's Office 214	yes	hutch	Wood	Yellow	Friction, chipping	20	3.7	Positive
1	2	214	Counselor's Office 214	yes	W3	Plaster	Yellow	Chipping	20	16.6	Positive
1	2	214	Counselor's Office 214	yes	W4	Plaster	Yellow	None	0	N/A	N/A

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	214	Counselor's Office 214	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	214	Counselor's Office 214	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	2	200	Nurse's Office	yes	W1	Plaster	Green	chipping, cracking	5	17.8	Positive
1	2	200	Nurse's Office	yes	door	Wood	Brown	Friction	10	20.6	Positive
1	2	200	Nurse's Office	yes	door frame	Wood	Brown	Friction	10	7.8	Positive
1	2	200	Nurse's Office	yes	W2	Plaster	Green	chipping, flaking	100	13.9	Positive
1	2	200	Nurse's Office	yes	door	Wood	Brown	Friction	10	10.9	Positive
1	2	200	Nurse's Office	yes	door frame	Wood	Brown	Friction	10	11.7	Positive
1	2	200	Nurse's Office	yes	Hutch	Wood	Brown	Friction	20	11.8	Positive
1	2	200	Nurse's Office	yes	W3	Plaster	Green	Efflorescence, spalling, flaking	60	14.8	Positive
1	2	200	Nurse's Office	yes	W4	Plaster	Green	Flaking	100	17.9	Positive
1	2	200	Nurse's Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	200	Nurse's Office	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	2	200A	Nurse's Restroom	yes	W1	Plaster	Green	None	0	N/A	N/A
1	2	200A	Nurse's Restroom	yes	W2	Plaster	Green	Efflorescence, flaking	40	7.8	Positive
1	2	200A	Nurse's Restroom	yes	W3	Plaster	Green	Efflorescence	10	9.2	Positive
1	2	200A	Nurse's Restroom	yes	W4	Plaster	Green	None	0	N/A	N/A
1	2	200A	Nurse's Restroom	yes	Ceiling	Plaster	Green	Efflorescence	5	8.6	Positive
1	2	200A	Nurse's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	yes	W1	Plaster	Beige	cracking, chipping	20	23.6	Positive
1	2	201	Classroom 201	yes	W2	Plaster	Beige	chipping, holes	10	20	Positive
1	2	201	Classroom 201	yes	W3	Plaster	Beige	chipping, flaking,	100	10.6	Positive
1	2	201	Classroom 201	yes	W4	Plaster	Beige	Efflorescence, flaking	100	10	Positive
1	2	201	Classroom 201	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	201A	Classroom 201 Coat Room	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	2	201A	Classroom 201 Coat Room	yes	W2	Plaster	Blue	flaking, chipping	200	2.7	Positive
1	2	201A	Classroom 201 Coat Room	yes	W3	Plaster	Blue	Flaking	100	12.6	Positive
1	2	201A	Classroom 201 Coat Room	yes	radiator	Metal	silver	Flaking	30	0.02	Negative
1	2	201A	Classroom 201 Coat Room	yes	W4	Plaster	Blue	flaking, cracking	100	12.5	Positive
1	2	201A	Classroom 201 Coat Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Classroom 201 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	yes	W1	Plaster	Beige	chipping, holes	30	20.4	Positive
1	2	202	Classroom 202	yes	W2	Plaster	Beige	holes, cracking	30	17.6	Positive
1	2	202	Classroom 202	yes	W3	Plaster	Beige	Spalling	20	21.2	Positive
1	2	202	Classroom 202	yes	radiator	Metal	Silver	Alligatoring	30	0.03	Negative
1	2	202	Classroom 202	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	202	Classroom 202	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	2	202A	Classroom 202 Coat Room	yes	W1	Plaster	Blue	Chipping	10	20.3	Positive
1	2	202A	Classroom 202 Coat Room	yes	W2	Plaster	Blue	holes, chipping	50	19.6	Positive
1	2	202A	Classroom 202 Coat Room	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	2	202A	Classroom 202 Coat Room	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	202A	Classroom 202 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	202A	Classroom 202 Coat Room	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	yes	W1	Plaster	Beige	chipping, holes	30	14.5	Positive
1	2	203	Classroom 203	yes	W2	Plaster	Beige	Holes, flaking, cracking	60	15	Positive
1	2	203	Classroom 203	yes	W3	Plaster	Beige	Holes, flaking	30	15.7	Positive
1	2	203	Classroom 203	yes	W4	Plaster	Beige	Holes	50	14.3	Positive
1	2	203	Classroom 203	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	203	Classroom 203	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	2	203A	Classroom 203 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	2	203A	Classroom 203 Storage	yes	W2	Plaster	Blue	Cracking	30	19.5	Positive
1	2	203A	Classroom 203 Storage	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	2	203A	Classroom 203 Storage	yes	W4	Plaster	Blue	Cracking	30	11.5	Positive
1	2	203A	Classroom 203 Storage	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	203A	Classroom 203 Storage	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	2	S22	Stairwell next to Classroom 203	yes	W1	Plaster	White	Flaking	20	10.3	Positive
1	2	S22	Stairwell next to Classroom 203	yes	W2	Plaster	White	Chipping	10	24.5	Positive
1	2	S22	Stairwell next to Classroom 203	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	S22	Stairwell next to Classroom 203	yes	Door	Metal	Brown	Friction	10	1.8	Positive
1	2	S22	Stairwell next to Classroom 203	yes	Door Frame	Metal	Brown	Friction	10	3.9	Positive
1	2	S22	Stairwell next to Classroom 203	yes	W4	Plaster	White	Cracking	20	14.4	Positive
1	2	S22	Stairwell next to Classroom 203	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S22	Stairwell next to Classroom 203	yes	Floor	Concrete	Grey	Friction	100	0.23	Negative
1	2	S22	Stairwell next to Classroom 203	yes	Newel Posts	Metal	Grey	Friction	20	2.8	Positive
1	2	S22	Stairwell next to Classroom 203	yes	Ballast	Metal	Grey	Friction	40	0.24	Negative
1	2	S22	Stairwell next to Classroom 203	yes	Handrail	Metal	Grey	Friction	10	0.2	Negative
1	2	H29	Hallway from Classroom 201 to 203	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	H29	Hallway from Classroom 201 to 203	yes	door	Metal	Brown	Friction	20	1.9	Positive
1	2	H29	Hallway from Classroom 201 to 203	yes	door frame	Metal	Brown	Friction	20	2.8	Positive
1	2	H29	Hallway from Classroom 201 to 203	yes	W2	Plaster	Beige	Chipping	20	14.9	Positive
1	2	H29	Hallway from Classroom 201 to 203	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	H29	Hallway from Classroom 201 to 203	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	H29	Hallway from Classroom 201 to 203	yes	Ceiling	Plaster	N/a	None	0	N/A	N/A
1	2	H29	Hallway from Classroom 201 to 203	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	203B	Girl's Restroom	yes	W1	Plaster	Pink	None	0	N/A	N/A
1	2	203B	Girl's Restroom	yes	W2	Plaster	Pink	None	0	N/A	N/A
1	2	203B	Girl's Restroom	yes	Pipe	Metal	Pink	Friction	5	6.8	Positive
1	2	203B	Girl's Restroom	yes	W3	Plaster	Pink	Chipping	5	7.7	Positive
1	2	203B	Girl's Restroom	yes	W4	Plaster	Pink	None	0	N/A	N/A
1	2	203B	Girl's Restroom	yes	Ceiling	Plaster	White	Moisture Damage, Flaking	10	10	Positive
1	2	203B	Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	204	Classroom 204	yes	W1	Plaster	Beige	Chipping/Staple Holes	30	23.7	Positive
1	2	204	Classroom 204	yes	W2	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	yes	W3	Plaster	Beige	Moisture Damage/Cracking/Stap le Holes	50	26.8	Positive
1	2	204	Classroom 204	yes	W4	Plaster	Beige	Chipping	20	20	Positive
1	2	204	Classroom 204	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	204A	Classroom 204 Coat Room	yes	W1	Plaster	Beige	Cracking	20	7.8	Positive
1	2	204A	Classroom 204 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	204A	Classroom 204 Coat Room	yes	W3	Plaster	Beige	Spalling	20	4.9	Positive
1	2	204A	Classroom 204 Coat Room	yes	W4	Plaster	Beige	Cracking	20	2.8	Positive
1	2	204A	Classroom 204 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	204A	Classroom 204 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	yes	W1	Plaster	Beige	Holes/Chipping	40	19.8	Positive
1	2	205	Classroom 205	yes	W2	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	yes	W3	Plaster	Beige	Flaking/Chipping	20	11.9	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	205	Classroom 205	yes	Radiator	Metal	Silver	Alligatoring	20	0.01	Negative
1	2	205	Classroom 205	yes	W4	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	205A	Classroom 205 Coat Room	yes	W1	Plaster	Beige	Chipping	5	8.2	Positive
1	2	205A	Classroom 205 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	205A	Classroom 205 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	205A	Classroom 205 Coat Room	yes	W4	Plaster	Beige	Cracking	10	12.3	Positive
1	2	205A	Classroom 205 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	205A	Classroom 205 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	yes	W1	Plaster	Beige	Chipping	20	19.3	Positive
1	2	206	Classroom 206	yes	W2	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	yes	W3	Plaster	Beige	Chipping/Flaking	30	20	Positive
1	2	206	Classroom 206	yes	Radiator	Metal	Silver	Alligatoring	20	0.05	Negative
1	2	206	Classroom 206	yes	W4	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	206A	Classroom 206 Coat Room	yes	W1	Plaster	Yellow	Chipping/Cracking	30	9.5	Positive
1	2	206A	Classroom 206 Coat Room	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	206A	Classroom 206 Coat Room	yes	W3	Plaster	Yellow	Spalling	10	5.9	Positive
1	2	206A	Classroom 206 Coat Room	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	206A	Classroom 206 Coat Room	yes	Ceiling	Plaster	White	Flaking	15	10	Positive
1	2	206A	Classroom 206 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	yes	W1	Plaster	Beige	Chipping/Cracking/Holes	50	20	Positive
1	2	207	Classroom 207	yes	W2	Plaster	Beige	Moisture Damage/Flaking/Staple Holes	50	23.7	Positive
1	2	207	Classroom 207	yes	W3	Plaster	Beige	Flaking/Chipping/Efflorescence	35	21	Positive
1	2	207	Classroom 207	yes	Radiator	Metal	Silver	Alligatoring	10	0.08	Negative
1	2	207	Classroom 207	yes	W4	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	207A	Classroom 207 Coat Room	yes	W1	Plaster	Green	Cracking/Chipping/Hole	60	12	Positive
1	2	207A	Classroom 207 Coat Room	yes	W2	Plaster	Green	None	0	N/A	N/A
1	2	207A	Classroom 207 Coat Room	yes	W3	Plaster	Green	Cracking/Flaking	40	11.4	Positive
1	2	207A	Classroom 207 Coat Room	yes	Pipe	Metal	Green	Flaking	12	0.11	Negative
1	2	207A	Classroom 207 Coat Room	yes	W4	Plaster	Green	Cracking/Flaking	40	9.3	Positive
1	2	207A	Classroom 207 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	207A	Classroom 207 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	211	Telephone Room 211	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	211	Telephone Room 211	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	211	Telephone Room 211	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	211	Telephone Room 211	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	211	Telephone Room 211	no	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	211	Telephone Room 211	no	Floor	Concrete	Varnish	N/A	N/A	N/A	N/A
1	2	S24	Fire Tower across from Classroom 207	no	W1	Brick	White	Flaking	500	7.8	Positive
1	2	S24	Fire Tower across from Classroom 207	yes	Door	Metal	Green	Flaking	20	7	Positive
1	2	S24	Fire Tower across from Classroom 207	no	Door Frame	Metal	Green	Flaking	20	8	Positive
1	2	S24	Fire Tower across from Classroom 207	yes	W2	Brick	White	Flaking	500	15.8	Positive
1	2	S24	Fire Tower across from Classroom 207	yes	Pipe	Metal	White	Flaking	20	0.25	Negative

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	S24	Fire Tower across from Classroom 207	no	W3	Brick	White	Flaking	500	8.9	Positive
1	2	S24	Fire Tower across from Classroom 207	no	Door	Metal	Grey	Flaking	20	10	Positive
1	2	S24	Fire Tower across from Classroom 207	no	Door Frame	Metal	Grey	Flaking	20	13	Positive
1	2	S24	Fire Tower across from Classroom 207	yes	W4	Brick	White	Flaking	500	10.9	Positive
1	2	S24	Fire Tower across from Classroom 207	yes	Window Safety Bars	Metal	Black	Flaking	120	21	Positive
1	2	S24	Fire Tower across from Classroom 207	yes	Ceiling	Concrete	White	Flaking	1000	24	Positive
1	2	S24	Fire Tower across from Classroom 207	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	207B	Boy's Restroom	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	2	207B	Boy's Restroom	yes	W2	Plaster	Blue	Holes	5	15.8	Positive
1	2	207B	Boy's Restroom	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	2	207B	Boy's Restroom	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	207B	Boy's Restroom	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	207B	Boy's Restroom	yes	Floor	Concrete	Varnish	N/A	N/A	N/A	N/A
1	2	H28	Hallway from Classrooms 204 to 207	yes	W1	Plaster	Beige	Staple Holes/ Cracking	20	13.8	Positive
1	2	H28	Hallway from Classrooms 204 to 207	yes	Electrical Panel	Metal	Brown	Chipping	10	0.4	Negative
1	2	H28	Hallway from Classrooms 204 to 207	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	H28	Hallway from Classrooms 204 to 207	yes	W3	Plaster	Beige	Cracking/Staple Holes/Chipping	60	20.1	Positive
1	2	H28	Hallway from Classrooms 204 to 207	yes	Electrical Panel	Metal	Brown	Chipping	10	0.28	Negative
1	2	H28	Hallway from Classrooms 204 to 207	yes	Radiator	Metal	Silver	Alligatoring	40	0.13	Negative
1	2	H28	Hallway from Classrooms 204 to 207	yes	Pipe	Metal	Brown	Chipping	16	19.3	Positive
1	2	H28	Hallway from Classrooms 204 to 207	yes	Door	Metal	Brown	Friction	10	0.11	Negative
1	2	H28	Hallway from Classrooms 204 to 207	yes	Door Frame	Metal	Brown	Friction	10	0.1	Negative
1	2	H28	Hallway from Classrooms 204 to 207	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	H28	Hallway from Classrooms 204 to 207	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	H28	Hallway from Classrooms 204 to 207	yes	Floor	Concrete	Varnish	N/A	N/A	N/A	N/A
1	2	S21	Stairwell outside Classroom 208	yes	W1	Plaster	White	Flaking	10	21.6	Positive
1	2	S21	Stairwell outside Classroom 208	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	S21	Stairwell outside Classroom 208	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	S21	Stairwell outside Classroom 208	yes	Door	Metal	Brown	Friction	10	5	Positive
1	2	S21	Stairwell outside Classroom 208	yes	Door Frame	Metal	Brown	Friction	10	4.3	Positive
1	2	S21	Stairwell outside Classroom 208	yes	W4	Plaster	White	Chipping	5	13.8	Positive
1	2	S21	Stairwell outside Classroom 208	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S21	Stairwell outside Classroom 208	yes	Floor	Concrete	Grey	Friction	200	0.03	Negative
1	2	S21	Stairwell outside Classroom 208	yes	Newel Posts	Metal	Grey	Friction	20	10.6	Positive
1	2	S21	Stairwell outside Classroom 208	yes	Ballast	Metal	Grey	Friction	40	0.26	Negative
1	2	S21	Stairwell outside Classroom 208	yes	Handrail	Metal	Grey	Friction	10	1.9	Positive
1	2	S21	Stairwell outside Classroom 208	yes	Tread	Concrete	Grey	Friction	50	0.01	Negative
1	2	S21	Stairwell outside Classroom 208	yes	Stringer	Concrete	Grey	Friction	40	12.3	Positive
1	2	208	Classroom 208	yes	W1	Plaster	Beige	Chipping/Holes	15	12.3	Positive
1	2	208	Classroom 208	yes	W2	Plaster	Beige	Chipping/Cracking	20	12.4	Positive
1	2	208	Classroom 208	yes	W3	Plaster	Beige	Chipping/Flaking/Crack ing	40	20	Positive
1	2	208	Classroom 208	yes	Radiator	Metal	Silver	Alligatoring	30	0.03	Negative
1	2	208	Classroom 208	yes	W4	Plaster	Beige	Flaking/Cracking	30	11	Positive
1	2	208	Classroom 208	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	208A	Classroom 208 Coat Room	yes	W1	Plaster	Beige	Efflorescence/Flaking	30	10.4	Positive
1	2	208A	Classroom 208 Coat Room	yes	W2	Plaster	Beige	Flaking/Cracking	60	12	Positive
1	2	208A	Classroom 208 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	208A	Classroom 208 Coat Room	yes	W4	Plaster	Beige	Flaking	30	9.1	Positive



## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	208A	Classroom 208 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	208A	Classroom 208 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	yes	W1	Plaster	Beige	Chipping/Cracking	30	13	Positive
1	2	209	Classroom 209	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	209	Classroom 209	yes	W3	Plaster	Beige	Flaking/Chipping/Crack ing	50	15	Positive
1	2	209	Classroom 209	yes	W4	Plaster	Beige	Cracking/Holes/	30	28.8	Positive
1	2	209	Classroom 209	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	209A	Classroom 209 Coat Room	yes	W1	Plaster	Green	None	0	N/A	N/A
1	2	209A	Classroom 209 Coat Room	yes	W2	Plaster	Green	Cracking	30	3.7	Positive
1	2	209A	Classroom 209 Coat Room	yes	W3	Plaster	Green	Cracking	30	5.6	Positive
1	2	209A	Classroom 209 Coat Room	yes	W4	Plaster	Green	Cracking/Chipping	30	8	Positive
1	2	209A	Classroom 209 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	209A	Classroom 209 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	yes	W1	Plaster	Beige	Chipping/Cracking/Hole s	30	7.1	Positive
1	2	210	Classroom 210	yes	W2	Plaster	Beige	Efflorescence/Flaking/ Cracking	50	12.4	Positive
1	2	210	Classroom 210	yes	Pipe	Metal	Beige	Chipping	5	22.1	Positive
1	2	210	Classroom 210	yes	W3	Plaster	Beige	Chipping/Flaking/Efflor escence	60	11.5	Positive
1	2	210	Classroom 210	yes	Radiator	Metal	Silver	Alligatoring	30	0.04	Negative
1	2	210	Classroom 210	yes	W4	Plaster	Beige	Staple Holes	20	5.5	Positive
1	2	210	Classroom 210	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	210B	Classroom 210 Coat Room	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	2	210B	Classroom 210 Coat Room	yes	W2	Plaster	Blue	Cracking	30	12.5	Positive
1	2	210B	Classroom 210 Coat Room	yes	W3	Plaster	Blue	Flaking/Chipping/Holes	60	7.9	Positive
1	2	210B	Classroom 210 Coat Room	yes	Radiator	Metal	Silver	Alligatoring	10	0.08	Negative
1	2	210B	Classroom 210 Coat Room	yes	W4	Plaster	Blue	Chipping/Cracking	50	3.6	Positive
1	2	210B	Classroom 210 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	210B	Classroom 210 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	210A	Office adjacent to Classroom 210	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	210A	Office adjacent to Classroom 210	yes	W2	Plaster	Yellow	Chipping/Cracking/Flak ing	100	5.1	Positive
1	2	210A	Office adjacent to Classroom 210	yes	W3	Plaster	Yellow	Flaking/Cracking/Efflor escence	120	12.7	Positive
1	2	210A	Office adjacent to Classroom 210	yes	Radiator	Metal	Silver	Alligatoring	20	0.03	Negative
1	2	210A	Office adjacent to Classroom 210	yes	W4	Plaster	Yellow	Staple Holes/Cracking/Chippin g	60	19.5	Positive
1	2	210A	Office adjacent to Classroom 210	yes	Ceiling	Plaster	White	Flaking	50	12.4	Positive
1	2	210A	Office adjacent to Classroom 210	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	H27	Hallway from Classrooms 208 to 210	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	H27	Hallway from Classrooms 208 to 210	yes	Door	Metal	Brown	Friction	20	5.2	Positive
1	2	H27	Hallway from Classrooms 208 to 210	yes	Door Frame	Metal	Brown	Friction	20	6.3	Positive
1	2	H27	Hallway from Classrooms 208 to 210	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	H27	Hallway from Classrooms 208 to 210	yes	Pipe	Metal	Brown	Chipping	6	22.7	Positive
1	2	H27	Hallway from Classrooms 208 to 210	yes	Radiator	Metal	Silver	Chipping	10	0.3	Negative
1	2	H27	Hallway from Classrooms 208 to 210	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	H27	Hallway from Classrooms 208 to 210	yes	W4	Plaster	Beige	None	5	6	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	H27	Hallway from Classrooms 208 to 210	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	H27	Hallway from Classrooms 208 to 210	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	300	Counselor's Office 300	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	300	Counselor's Office 300	yes	W2	Plaster	Green	Chipping	20	11.2	Positive
1	3	300	Counselor's Office 300	yes	W3	Plaster	Green	Flaking/Chipping/Crack ing	40	16	Positive
1	3	300	Counselor's Office 300	yes	W4	Plaster	Green	Flaking/cracking	60	13.6	Positive
1	3	300	Counselor's Office 300	yes	Radiator	Metal	Silver	Chipping	30	0.02	Negative
1	3	300	Counselor's Office 300	yes	Ceiling	Plaster	N/A	N/A	0	N/A	N/A
1	3	300	Counselor's Office 300	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	300A	Staff Restroom at Counselor's Office	yes	W1	Plaster	Green	Flaking/cracking	50	6.8	Positive
1	3	300A	Staff Restroom at Counselor's Office	yes	W2	Plaster	Green	Cracking	60	5.9	Positive
1	3	300A	Staff Restroom at Counselor's Office	yes	Pipe	Metal	Green	Flaking	20	7.9	Positive
1	3	300A	Staff Restroom at Counselor's Office	yes	W3	Plaster	Green	Flaking/cracking	100	7.9	Positive
1	3	300A	Staff Restroom at Counselor's Office	yes	Pipe	Metal	Green	Flaking	5	5.8	Positive
1	3	300A	Staff Restroom at Counselor's Office	yes	Radiator	Metal	Silver	Chipping	20	0.02	Negative
1	3	300A	Staff Restroom at Counselor's Office	yes	W4	Plaster	Green	Flaking/cracking	120	9.8	Positive
1	3	300A	Staff Restroom at Counselor's Office	yes	Ceiling	Plaster	White	N/A	N/A	N/A	N/A
1	3	300A	Staff Restroom at Counselor's Office	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	301	Classroom 301	yes	W1	Plaster	Beige	Chipping/cracking	50	13.4	Positive
1	3	301	Classroom 301	yes	W2	Plaster	Beige	Efflorescence/chipping	20	15.2	Positive
1	3	301	Classroom 301	yes	W3	Plaster	Beige	Cracking/chipping	30	17.6	Positive
1	3	301	Classroom 301	yes	Radiator	Metal	Silver	Chipping	10	0.01	Negative
1	3	301	Classroom 301	yes	W4	Plaster	Beige	Efflorescence/holes	50	11.4	Positive
1	3	301	Classroom 301	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	yes	Floor	Wood	Varnish	None	0	n/a	n/a
1	3	301A	Classroom 301 Coat Room	yes	W1	Plaster	Beige	Chipping/cracking	40	12.4	Positive
1	3	301A	Classroom 301 Coat Room	yes	W2	Plaster	Beige	Efflorescence	20	17.7	Positive
1	3	301A	Classroom 301 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	301A	Classroom 301 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	301A	Classroom 301 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	301A	Classroom 301 Coat Room	yes	Floor	Wood	Varnish	None	0	n/a	n/a
1	3	302	Classroom 302	yes	W1	Plaster	Beige	Cracking/chipping	40	11.6	Positive
1	3	302	Classroom 302	yes	W2	Plaster	Beige	Holes/chipping	60	18.7	Positive
1	3	302	Classroom 302	yes	W3	Plaster	Beige	Cracking/chipping	30	15.9	Positive
1	3	302	Classroom 302	yes	Radiator	Metal	Silver	Chipping	20	0.02	Negative
1	3	302	Classroom 302	yes	W4	Plaster	Beige	Holes/chipping	50	17.7	Positive
1	3	302	Classroom 302	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	302A	Classroom 302 Coat Room	yes	W1	Plaster	Beige	chipping/cracking	20	15.7	Positive
1	3	302A	Classroom 302 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Classroom 302 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Classroom 302 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Classroom 302 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	302A	Classroom 302 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	303	Classroom 311	yes	W1	Plaster	Beige	holes/chipping	20	16.7	Positive
1	3	303	Classroom 311	yes	W2	Plaster	Beige	Chipping/cracking/holes	60	15.9	Positive
1	3	303	Classroom 311	yes	W3	Plaster	Beige	Efflorescence/chipping/ flaking	80	19	Positive
1	3	303	Classroom 311	yes	Radiator	Metal	Silver	Chipping	40	0.02	Negative
1	3	303	Classroom 311	yes	W4	Plaster	Beige	None	0	N/A	N/A

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	303	Classroom 311	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 311	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	303A	Classroom 311 Closet	yes	W1	Plaster	Green	Flaking	300	17.9	Positive
1	3	303A	Classroom 311 Closet	yes	pipe	Metal	Green	Flaking	12	11.2	Positive
1	3	303A	Classroom 311 Closet	yes	W2	Plaster	Green	Flaking	100	10	Positive
1	3	303A	Classroom 311 Closet	yes	W3	Plaster	Green	Flaking	100	9.8	Positive
1	3	303A	Classroom 311 Closet	yes	W4	Plaster	Green	Flaking	100	10.9	Positive
1	3	303A	Classroom 311 Closet	yes	pipe	Metal	Green	Flaking	12	3.8	Positive
1	3	303A	Classroom 311 Closet	yes	Ceiling	Plaster	White	Moisture Damage/flaking	500	19.9	Positive
1	3	303A	Classroom 311 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	311	Classroom 303	yes	W1	Plaster	Beige	Efflorescence/moisture	60	20.9	Positive
1	3	311	Classroom 303	yes	W2	Plaster	Beige	Cracking	30	17.7	Positive
1	3	311	Classroom 303	yes	W3	Plaster	Beige	Efflorescence/flaking	80	19.5	Positive
1	3	311	Classroom 303	yes	W4	Plaster	Beige	cracking/chipping	50	20.9	Positive
1	3	311	Classroom 303	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	311	Classroom 303	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	311A	Classroom 303 Closet	yes	W1	Plaster	Beige	Cracking	40	11.7	Positive
1	3	311A	Classroom 303 Closet	yes	W2	Plaster	Beige	Cracking	200	12.8	Positive
1	3	311A	Classroom 303 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	311A	Classroom 303 Closet	yes	W4	Plaster	Beige	Efflorescence/Flaking/ Cracking	400	19.8	Positive
1	3	311A	Classroom 303 Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	311A	Classroom 303 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell outside Classroom 303	yes	W1	Plaster	Beige	Flaking	20	11.7	Positive
1	3	S32	Stairwell outside Classroom 303	yes	Radiator	Metal	Silver	Alligatoring	20	1.7	Positive
1	3	S32	Stairwell outside Classroom 303	yes	W2	Plaster	Beige	chipping/flaking	200	17.7	Positive
1	3	S32	Stairwell outside Classroom 303	yes	Door	Wood	Brown	Friction	5	0.03	Negative
1	3	S32	Stairwell outside Classroom 303	yes	Door Frame	Wood	Brown	Friction	5	0.02	Negative
1	3	S32	Stairwell outside Classroom 303	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	S32	Stairwell outside Classroom 303	yes	Door	Metal	Brown	Friction	10	5	Positive
1	3	S32	Stairwell outside Classroom 303	yes	Door Frame	Metal	Brown	Friction	10	4.8	Positive
1	3	S32	Stairwell outside Classroom 303	yes	W4	Plaster	Beige	cracking/flaking	200	18	Positive
1	3	S32	Stairwell outside Classroom 303	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S32	Stairwell outside Classroom 303	yes	Floor	Concrete	Grey	Chipping	40	0.15	Negative
1	3	S32	Stairwell outside Classroom 303	yes	Newel Post	Metal	Grey	Friction	5	7.7	Positive
1	3	S32	Stairwell outside Classroom 303	yes	Ballast	Metal	Grey	Friction	10	0.19	Negative
1	3	S32	Stairwell outside Classroom 303	yes	Handrail	Wood	Grey	Friction	15	0.12	Negative
1	3	H310	Hallway from Classrooms 301 to 303	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	H310	Hallway from Classrooms 301 to 303	yes	Door	Metal	Brown	Friction	20	4.7	Positive
1	3	H310	Hallway from Classrooms 301 to 303	yes	Door Frame	Metal	Brown	Friction	20	6	Positive
1	3	H310	Hallway from Classrooms 301 to 303	yes	W2	Plaster	Beige	holes/chipping	100	14	Positive
1	3	H310	Hallway from Classrooms 301 to 303	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	H310	Hallway from Classrooms 301 to 303	yes	W4	Plaster	Beige	holes/chipping	40	17.8	Positive
1	3	H310	Hallway from Classrooms 301 to 303	yes	Pipe	Metal	Brown	Chipping	6	0.12	Negative
1	3	H310	Hallway from Classrooms 301 to 303	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	H310	Hallway from Classrooms 301 to 303	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	303B	Girl's Restroom	yes	W1	Plaster	Pink	Efflorescence/cracking	20	6.9	Positive
1	3	303B	Girl's Restroom	yes	W2	Plaster	Pink	cracking/chipping	50	3.9	Positive
1	3	303B	Girl's Restroom	yes	W3	Plaster	Pink	Moisture Damage/cracking	10	6.4	Positive
1	3	303B	Girl's Restroom	yes	W4	Plaster	Pink	Cracking	20	8.9	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	303B	Girl's Restroom	yes	pipe	Metal	Pink	Chipping	5	13.1	Positive
1	3	303B	Girl's Restroom	yes	Ceiling	Plaster	White	Flaking/cracking	100	27.8	Positive
1	3	303B	Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	304	Classroom 304	yes	W1	Plaster	Beige	chipping/cracking	40	12.5	Positive
1	3	304	Classroom 304	yes	W2	Sheetrock	Beige	holes	5	15.6	Positive
1	3	304	Classroom 304	yes	W3	Plaster	Beige	chipping/flaking/crackin g	120	16	Positive
1	3	304	Classroom 304	yes	radiator	Metal	silver	Chipping	10	0.09	Negative
1	3	304	Classroom 304	yes	W4	Plaster	Beige	flaking/holes	20	9.4	Positive
1	3	304	Classroom 304	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	304A	Classroom 304 Coat Room	yes	W1	Plaster	Beige	Cracking	30	23.5	Positive
1	3	304A	Classroom 304 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	304A	Classroom 304 Coat Room	yes	W3	Plaster	Beige	Spalling	20	20	Positive
1	3	304A	Classroom 304 Coat Room	yes	W4	Plaster	Beige	Cracking	40	29.3	Positive
1	3	304A	Classroom 304 Coat Room	yes	Ceiling	Plaster	N/A	None	0	N/A	N/A
1	3	304A	Classroom 304 Coat Room	yes	Floor	Wood	Varnish	None	0	n/a	n/a
1	3	305	Classroom 305	yes	W1	Plaster	Beige	Cracking/chipping/hole s	100	12	Positive
1	3	305	Classroom 305	yes	W2	Sheetrock	Beige	holes	40	0	Negative
1	3	305	Classroom 305	yes	W3	Plaster	Beige	Cracking/chipping	20	11.5	Positive
1	3	305	Classroom 305	yes	W4	Sheetrock	Beige	Chipping	10	0	Negative
1	3	305	Classroom 305	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	305A	Classroom 305 Coat Room	yes	W1	Plaster	Beige	Chipping	20	15.4	Positive
1	3	305A	Classroom 305 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	305A	Classroom 305 Coat Room	yes	W3	Plaster	Beige	Spalling	5	11	Positive
1	3	305A	Classroom 305 Coat Room	yes	W4	Plaster	Beige	Chipping	10	9.6	Positive
1	3	305A	Classroom 305 Coat Room	yes	Ceiling	Plaster	N/A	None	0	N/A	N/A
1	3	305A	Classroom 305 Coat Room	yes	Floor	Wood	Varnish	None	0	n/a	n/a
1	3	306	Classroom 306	yes	W1	Plaster	Beige	Chipping/holes	10	10.3	Positive
1	3	306	Classroom 306	yes	W2	Sheetrock	Beige	peeling/holes	30	0	Negative
1	3	306	Classroom 306	yes	W3	Plaster	Beige	flaking/chipping	40	17.2	Positive
1	3	306	Classroom 306	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
1	3	306	Classroom 306	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306 Coat Room	yes	W1	Plaster	Beige	Cracking	20	14.3	Positive
1	3	306A	Classroom 306 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	306A	Classroom 306 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	306A	Classroom 306 Coat Room	yes	W4	Plaster	Beige	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	306A	Classroom 306 Coat Room	yes	Floor	Wood	Varnish	None	0	n/a	n/a
1	3	306B	Classroom 306 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	306B	Classroom 306 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	306B	Classroom 306 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	306B	Classroom 306 Closet	yes	W4	Plaster	Beige	Flaking	5	11.5	Positive
1	3	306B	Classroom 306 Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	306B	Classroom 306 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	yes	W1	Plaster	Beige	flaking/cracking	20	17.5	Positive
1	3	307	Classroom 307	yes	W2	Plaster	Beige	cracking/flaking	60	20.3	Positive
1	3	307	Classroom 307	yes	W3	Plaster	Beige	Efflorescence/flaking	40	12	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	307	Classroom 307	yes	W4	Sheetrock	Beige	Holes/Peeling	40	0	Negative
1	3	307	Classroom 307	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	yes	Divider (wall)	Sheetrock	Beige	Friction	50	0	Negative
1	3	307A	Classroom 307 Coat Room	yes	W1	Plaster	Beige	Cracking	30	23	Positive
1	3	307A	Classroom 307 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	307A	Classroom 307 Coat Room	yes	W3	Plaster	Beige	holes	2	29.7	Positive
1	3	307A	Classroom 307 Coat Room	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
1	3	307A	Classroom 307 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	307A	Classroom 307 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	310C	Office 307A	yes	W1	Plaster	White	flaking/chipping	20	9.6	Positive
1	3	310C	Office 307A	yes	W2	Plaster	White	Chipping	5	8.9	Positive
1	3	310C	Office 307A	yes	radiator	Metal	silver	Alligatoring	10	0.03	Negative
1	3	310C	Office 307A	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	310C	Office 307A	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	310C	Office 307A	yes	Ceiling	Plaster	Beige	Flaking/cracking/moisture damage	12	15.8	Positive
1	3	310C	Office 307A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S34	Fire Tower across from Classroom 307	no	W1	Brick	White	Flaking	500	7.8	Positive
1	3	S34	Fire Tower across from Classroom 307	no	door	Metal	Green	Flaking	20	7	Positive
1	3	S34	Fire Tower across from Classroom 307	no	door frame	Metal	Green	Flaking	20	8	Positive
1	3	S34	Fire Tower across from Classroom 307	no	W2	Brick	White	Flaking	500	15.8	Positive
1	3	S34	Fire Tower across from Classroom 307	no	pipe	Metal	White	Flaking	20	0.25	Negative
1	3	S34	Fire Tower across from Classroom 307	no	W3	Brick	White	Flaking	500	8.9	Positive
1	3	S34	Fire Tower across from Classroom 307	no	door	Metal	Grey	Flaking	20	10	Positive
1	3	S34	Fire Tower across from Classroom 307	no	door frame	Metal	Grey	Flaking	20	13	Positive
1	3	S34	Fire Tower across from Classroom 307	no	W4	Brick	White	Flaking	500	10.9	Positive
1	3	S34	Fire Tower across from Classroom 307	no	window safety bars	Metal	Black	Flaking	120	21	Positive
1	3	S34	Fire Tower across from Classroom 307	no	Ceiling	Concrete	White	Flaking	1000	24	Positive
1	3	S34	Fire Tower across from Classroom 307	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	307B	Boy's Restroom	yes	W1	Plaster	Blue	Cracking	100	12.4	Positive
1	3	307B	Boy's Restroom	yes	W2	Plaster	Blue	Cracking	100	11.7	Positive
1	3	307B	Boy's Restroom	yes	W3	Plaster	Blue	Cracking	100	10.4	Positive
1	3	307B	Boy's Restroom	yes	W4	Plaster	Blue	Cracking	100	10	Positive
1	3	307B	Boy's Restroom	yes	Ceiling	Plaster	White	Cracking/Chipping	100	23.5	Positive
1	3	307B	Boy's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	H311	Hallway from Classrooms 303 to 307	yes	W1	Plaster	beige	cracking/holes	100	25.4	Positive
1	3	H311	Hallway from Classrooms 303 to 307	yes	electrical panel	Metal	Brown	Chipping	5	0.26	Negative
1	3	H311	Hallway from Classrooms 303 to 307	yes	W2	Plaster	beige	None	0	N/A	N/A
1	3	H311	Hallway from Classrooms 303 to 307	yes	W3	Plaster	beige	Efflorescence/flaking	200	16.3	Positive
1	3	H311	Hallway from Classrooms 303 to 307	yes	pipe	Metal	Black	Chipping	15	5.4	Positive
1	3	H311	Hallway from Classrooms 303 to 307	yes	electrical panel	Metal	Brown	Chipping	10	0.27	Negative
1	3	H311	Hallway from Classrooms 303 to 307	yes	door frame	Metal	Brown	Friction	10	3.7	Positive
1	3	H311	Hallway from Classrooms 303 to 307	yes	door	Metal	Brown	Friction	20	4.4	Positive
1	3	H311	Hallway from Classrooms 303 to 307	yes	W4	Plaster	beige	None	0	N/A	N/A
1	3	H311	Hallway from Classrooms 303 to 307	yes	radiator	Metal	Silver	Alligatoring	20	0.03	Negative
1	3	H311	Hallway from Classrooms 303 to 307	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	H311	Hallway from Classrooms 303 to 307	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell outside Classroom 308	yes	W1	Plaster	beige	Moisture Damage/Cracking	60	16	Positive
1	3	S31	Stairwell outside Classroom 308	yes	W2	Plaster	Beige	Cracking	80	17.4	Positive

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	S31	Stairwell outside Classroom 308	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	S31	Stairwell outside Classroom 308	yes	door	Metal	Brown	Friction	10	9.8	Positive
1	3	S31	Stairwell outside Classroom 308	yes	door frame	Metal	Brown	Friction	10	4	Positive
1	3	S31	Stairwell outside Classroom 308	yes	W4	Plaster	Beige	Efflorescence, Cracking	40	14.8	Positive
1	3	S31	Stairwell outside Classroom 308	yes	Ceiling	Plaster	White	Efflorescence, Cracking	100	26.9	Positive
1	3	S31	Stairwell outside Classroom 308	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell outside Classroom 308	yes	ballast	Metal	Brown	Friction	25	0.26	Negative
1	3	S31	Stairwell outside Classroom 308	yes	newel post	Metal	Brown	Friction	15	7.6	Positive
1	3	S31	Stairwell outside Classroom 308	yes	handrail	Metal	Brown	Friction	5	0.4	Negative
1	3	308	Classroom 308	yes	W1	Plaster	beige	Efflorescence, chipping, holes	20	16.5	Positive
1	3	308	Classroom 308	yes	W2	Plaster	beige	chipping, holes, cracking	40	20.9	Positive
1	3	308	Classroom 308	yes	W3	Plaster	beige	chipping, flaking, cracking	100	23	Positive
1	3	308	Classroom 308	yes	W4	Plaster	beige	Efflorescence, flaking	100	22.6	Positive
1	3	308	Classroom 308	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	308	Classroom 308	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	308A	Classroom 308 Closet	yes	W1	Plaster	Beige	Flaking	300	10.5	Positive
1	3	308A	Classroom 308 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	308A	Classroom 308 Closet	yes	W3	Plaster	Beige	flaking, cracking	300	25.7	Positive
1	3	308A	Classroom 308 Closet	yes	W4	Plaster	Beige	cracking, flaking	100	20.4	Positive
1	3	308A	Classroom 308 Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	308A	Classroom 308 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	309	Classroom 309	yes	W1	Plaster	Beige	chipping, holes	60	21	Positive
1	3	309	Classroom 309	yes	W2	Plaster	Beige	chipping, holes	60	24.6	Positive
1	3	309	Classroom 309	yes	W3	Plaster	Beige	cracking, chipping, efflorescence	100	23	Positive
1	3	309	Classroom 309	yes	radiator	Metal	silver	Chipping	30	0.06	Negative
1	3	309	Classroom 309	yes	W4	Plaster	Beige	chipping, holes	60	23.8	Positive
1	3	309	Classroom 309	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	309	Classroom 309	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	3	309A	Classroom 309 Coat Room	yes	W1	Plaster	Beige	Cracking	10	29	Positive
1	3	309A	Classroom 309 Coat Room	yes	W2	Plaster	Beige	chipping, cracking	60	10.4	Positive
1	3	309A	Classroom 309 Coat Room	yes	W3	Plaster	Beige	Cracking	30	15.3	Positive
1	3	309A	Classroom 309 Coat Room	yes	W4	Plaster	Beige	Cracking	60	12.5	Positive
1	3	309A	Classroom 309 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	309A	Classroom 309 Coat Room	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	3	310	Classroom 310	yes	W1	Plaster	Beige	chipping, cracking	20	12.2	Positive
1	3	310	Classroom 310	yes	W2	Plaster	Beige	Moisture Damage, flaking	80	11	Positive
1	3	310	Classroom 310	yes	W3	Plaster	Beige	Efflorescence, cracking, flaking	100	10.6	Positive
1	3	310	Classroom 310	yes	radiator	Metal	silver	Alligatoring	30	0.02	Negative
1	3	310	Classroom 310	yes	W4	Plaster	Beige	holes, chipping	40	16	Positive
1	3	310	Classroom 310	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	310	Classroom 310	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	3	310B	Classroom 310 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	310B	Classroom 310 Coat Room	yes	W2	Plaster	Beige	Spalling, chipping	20	11	Positive
1	3	310B	Classroom 310 Coat Room	yes	W3	Plaster	Beige	Cracking	30	10.3	Positive
1	3	310B	Classroom 310 Coat Room	yes	W4	Plaster	Beige	holes, chipping	40	10.4	Positive
1	3	310B	Classroom 310 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A

## Hopkinson

E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	310B	Classroom 310 Coat Room	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A
1	3	310A	Classroom 310A	yes	W1	Plaster	Yellow	chipping, cracking	30	15.4	Positive
1	3	310A	Classroom 310A	yes	W2	Plaster	Yellow	spalling, cracking	60	11.3	Positive
1	3	310A	Classroom 310A	yes	W3	Plaster	Yellow	Efflorescence, flaking	100	20.4	Positive
1	3	310A	Classroom 310A	yes	radiator	Metal	silver	Alligatoring	30	0.03	Negative
1	3	310A	Classroom 310A	yes	W4	Plaster	Yellow	holes, chipping, cracking	50	1.4	Positive
1	3	310A	Classroom 310A	yes	Ceiling	Plaster	beige	N/A	N/A	N/A	N/A
1	3	310A	Classroom 310A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	H312	Hallway from Classrooms 308 to 310	yes	W1	Plaster	beige	None	0	N/A	N/A
1	3	H312	Hallway from Classrooms 308 to 310	yes	door	Metal	Brown	Friction	5	5.7	Positive
1	3	H312	Hallway from Classrooms 308 to 310	yes	door frame	Metal	Brown	Friction	5	9.3	Positive
1	3	H312	Hallway from Classrooms 308 to 310	yes	W2	Plaster	beige	chipping, flaking	80	11.2	Positive
1	3	H312	Hallway from Classrooms 308 to 310	yes	W3	Plaster	beige	None	0	N/A	N/A
1	3	H312	Hallway from Classrooms 308 to 310	yes	W4	Plaster	beige	holes, chipping	30	10.4	Positive
1	3	H312	Hallway from Classrooms 308 to 310	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	H312	Hallway from Classrooms 308 to 310	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	001	Classroom 1	yes	W1	Concrete	Blue	None	0	N/A	N/A
2	1	001	Classroom 1	yes	W2	Concrete	Blue	None	0	N/A	N/A
2	1	001	Classroom 1	yes	W3	Concrete	Blue	None	0	N/A	N/A
2	1	001	Classroom 1	yes	W4	Concrete	Blue	None	0	N/A	N/A
2	1	001	Classroom 1	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	001	Classroom 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	001B	Classroom 1 Restroom	yes	W1	Concrete	Blue	None	0	N/A	N/A
2	1	001B	Classroom 1 Restroom	yes	W2	Concrete	Blue	None	0	N/A	N/A
2	1	001B	Classroom 1 Restroom	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	1	001B	Classroom 1 Restroom	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	1	001B	Classroom 1 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	001B	Classroom 1 Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	002	Classroom 2	yes	W1	Concrete	Blue	None	0	N/A	N/A
2	1	002	Classroom 2	yes	W2	Concrete	Blue	None	0	N/A	N/A
2	1	002	Classroom 2	yes	W3	Concrete	Blue	None	0	N/A	N/A
2	1	002	Classroom 2	yes	W4	Concrete	Blue	None	0	N/A	N/A
2	1	002	Classroom 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	002	Classroom 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	003	Office P3	yes	W1	Concrete	Blue	None	0	N/A	N/A
2	1	003	Office P3	yes	W2	Concrete	Blue	None	0	N/A	N/A
2	1	003	Office P3	yes	W3	Concrete	Blue	None	0	N/A	N/A
2	1	003	Office P3	yes	W4	Concrete	Blue	None	0	N/A	N/A
2	1	003	Office P3	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	003	Office P3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	003B	Classroom 2 Restroom	yes	W1	Concrete	Blue	None	0	N/A	N/A
2	1	003B	Classroom 2 Restroom	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	1	003B	Classroom 2 Restroom	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	1	003B	Classroom 2 Restroom	yes	W4	Concrete	Blue	None	0	N/A	N/A
2	1	003B	Classroom 2 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	003B	Classroom 2 Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	H04	Entrance/Center Hallway	yes	W1	Concrete	Blue	None	0	N/A	N/A

# Hopkinson

<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Student/ Teacher Occupied (yes/no)</b>	<b>Primary Component</b>	<b>Substrate Material</b>	<b>Color</b>	<b>Description of Primary Damage</b>	<b>Primary Component Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>Primary Component XRF (positive/ negative)</b>
2	1	H04	Entrance/Center Hallway	yes	W2	Concrete	Blue	None	0	N/A	N/A
2	1	H04	Entrance/Center Hallway	yes	W3	Concrete	Blue	None	0	N/A	N/A
2	1	H04	Entrance/Center Hallway	yes	W4	Concrete	Blue	None	0	N/A	N/A
2	1	H04	Entrance/Center Hallway	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	H04	Entrance/Center Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A