



Howe Academics Plus School
5800 North 13th Street
Philadelphia, Pennsylvania

Paint and Plaster Stabilization Project Final Report

NOVEMBER 9, 2019

PREPARED FOR:

School District of Philadelphia
440 North Broad Street, Room 3053
Philadelphia, Pennsylvania
Attention: Mr. Brian Joseph

PREPARED BY:

The Vertex Companies, Inc.
700 Turner Industrial Way
Aston, Pennsylvania 19014
PHONE 610.558.8902

CONTROL NUMBER:

2018255009

WORK ORDER NUMBER:

1709065

ENCUMBRANCE NUMBER:

588472

VERTEX Project No: 56950

TABLE OF CONTENTS

- I. Introduction
- II. Methods Executive Summary
 - A. Preliminary Steps
 - i. Parent and Staff Notifications
 - ii. Decluttering
 - iii. Wall Hangings
 - iv. Swing Space
 - v. Facilities Building Cleaning Staff Training
 - B. Pre-Cleaning
 - C. Paint and Plaster Stabilization Procedures
 - i. Work Practices
 - ii. Oversight
 - D. Cleanup and Completion of Stabilization Work
 - i. Cleanup
 - ii. Testing
- III. Oversight
 - A. Scope of Work
 - B. EPA Checklist
 - C. Oversight
 - D. Sample Results

Appendix A. Scope of Work Table

Appendix B. EPA Checklist Table

Appendix C. Oversight Table

Appendix D. FAAS Sample Results Table

Appendix E. Photographs

Appendix F. Environmental Firm Certificates

Appendix G. Paint Contractor Certifications

Appendix H. Documentation of Parent and Staff Notifications

I. Introduction

The School District of Philadelphia (SDP) developed a Paint and Plaster Stabilization Project Plan and Procedures jointly with the District's Office of Environmental Management and Services (OEMS) and the Philadelphia Federation of Teacher's Health and Welfare Fund and Union's Director of Environmental Science and Occupational Safety and Health. The purpose of this work is to minimize the risk of children's exposure to lead-based paint while at school. Designated schools were inspected on a room-by-room basis to develop a Scope of Work for each school.

The Vertex Companies, Inc. (VERTEX) was contracted by OEMS to perform oversight and clearance testing during the paint and plaster stabilization project that was conducted at the Howe Academics Plus School located at 5800 North 13th Street in Philadelphia, PA. The project began on May 6, 2019 and was completed on July 26, 2019. Workers certified under the US Environmental Protection Agency (EPA) Lead Renovation, Repair, and Painting Rule (RRP) performed the removal of loose, peeling, flaking, and damaged/deteriorated paint and plaster as delineated in the Scope of Work. This work was overseen by a VERTEX certified environmental technician who verified workers were following RRP rules/procedures. The environmental technician also performed lead in dust wipe sampling in areas designated by the stabilization plan.

II. Methods Executive Summary

A. Preliminary Steps

i. Parent and Staff Notifications

An initial communication titled Paint and Plaster Stabilization: Project Start, along with a Questions and Answers sheet was mailed to staff and parents several weeks prior to the commencement of work. Parents of children in grades Pre-Kindergarten to First Grade also received the EPA Lead RRP pamphlet in this mailing. Additionally, prior to the start of the project, parent and staff meetings were held by SDP OEMS, Maintenance, and Operations to explain the process of the paint and plaster project and to field any questions or concerns.

ii. Decluttering

Classrooms, closets, and other storage areas were decluttered prior to the commencement of stabilization work. Coordination of decluttering activities was made between teachers and facilities staff to ensure that outdated and unneeded materials were discarded. Facilities staff assisted teachers in moving large and heavy materials to dumpsters.

iii. Wall Hangings

Posters, bulletin boards, framed art, and any other wall hangings present were removed prior to the commencement of paint and plaster stabilization activities. This was coordinated with teachers by the SDP Operations Division at the kick-off meeting and during the phasing of the project, with the help of the Principal. Teachers were instructed to use bulletin boards or mounting putty to hang materials in the future. The use of staples or any kind of tape to hang materials moving forward is no longer permitted.

iv. Swing Space

Swing space was identified prior to the commencement of the stabilization work to ensure that classrooms were available during the school year. A plan was created on a school-by-school basis to relocate students and teachers from classrooms during the course of this work. Each work area was scheduled for cleaning by facilities staff after the paint stabilization work was completed by the painting contractor.

v. Facilities Building Cleaning Staff Training

Cleaning staff were provided with information about this project and expectations for post-cleaning. Post-cleaning activities included high efficiency particulate air (HEPA) vacuuming and wet wiping all horizontal surfaces and polishing floors.

B. Pre-Cleaning

SDP Maintenance Environmental Staff performed HEPA vacuuming and wet wiping in areas that had significant paint chips or plaster debris on stored materials that needed to be moved prior to stabilization.

C. Paint and Plaster Stabilization Procedures

i. Work Practices

Prior to the commencement of the paint and plaster stabilization activities, facilities staff moved stored materials and furniture in each space into either the center of the room or into the hallway. Any remaining objects in each space were covered with plastic sheeting. All windows, non-entrance doors, and HVAC system openings were also sealed with plastic sheeting. The entrance to the space was covered with plastic sheeting and a plastic flap and had a lead warning sign attached as per EPA Lead RRP. A tacky walk-off pad was placed outside the entrance to limit the spread of dust from the work area. Any visible paint chips and dust were promptly HEPA vacuumed. Plastic floor coverings extended six feet out from the vertical surfaces being stabilized, where physically possible.

All workers performing paint and plaster stabilization were certified as Lead RRP workers. Workers wore disposable clothing, foot coverings, and applicable respiratory protection inside each work area when performing paint and plaster stabilization. Stabilization work was performed in compliance with the EPA Lead RRP rules and guidelines. When stabilization work was completed, paint chips and debris were misted and folded up inside plastic floor coverings and disposed of in heavy duty plastic waste bags. Waste bags were tied with a “gooseneck” knot and sealed with tape. Waste was disposed of off-site as construction debris.

ii. Oversight

An environmental technician was on-site each day that any prep, stabilization, or painting was performed by the contractor. The overall responsibility of the technician was to ensure compliance with lead safe work practices. The technician maintained an oversight spreadsheet completing the date each space was pre-cleaned, the contents were moved, the space was prepped, and the surfaces were stabilized. The technician also collected colorimetric wipes where necessary and recorded the number of RRP wipes, colorimetric wipes, and the results of any wipes submitted for flame atomic absorption spectrophotometry (FAAS) on the spreadsheet. RRP wipes collected by the painting contractor were verified as clean or passing by the technician.

In addition, the technician also completed an EPA Checklist spreadsheet. This spreadsheet confirmed that for each work area that warning signs were posted at the entrance, the work area was contained to prevent the spread of dust and debris, all objects in the work area were removed or covered, HVAC ducts were closed and covered, windows were closed, doors were closed and sealed, doors that must be used for passage were covered to prevent the spread of dust, floors were covered with taped down plastic, waste was contained on-site and while being transported off site, the work area was properly cleaned after renovation, all chips and debris were picked up, the protective sheeting was misted, folded dirty side inward, and taped for removal, light lenses were inspected, surfaces above light fixtures were inspected, and that surfaces were HEPA vacuumed or wiped with wet cloths.

D. Cleanup and Completion of Stabilization Work

The following cleanup and completion procedures were performed for each work area after the completion of the stabilization work:

i. Cleanup

Cleanup began once the contractor and environmental technician agreed that there were no signs of loose, peeling, flaking, bubbling, or crumbling paint or plaster on walls, ceilings, or any other painted surfaces. The protective sheeting was misted, folded dirty side inward, taped, and bagged in heavy duty bags. Workers used HEPA vacuums and wet cloths to clean floors, windowsills, and any other horizontal surfaces. The environmental technician then performed a visual inspection to ensure there were no visible signs of paint chips, debris, or dust of any kind on surfaces in the work area or outside the contained and isolated work area.

ii. Testing

Testing performed in each work area was a combination of EPA RRP cleaning verification wipes, Colorimetric Wipe SKC, Inc. Full Disclosure Instant Wipes for instant detection of lead in dust, and laboratory analysis via flame atomic absorption spectrophotometry. Laboratory analysis was performed by EMSL Analytical, Inc. of Cinnaminson, New Jersey. Once each work area was stabilized, plastic coverings removed, and surfaces cleaned, the environmental technician performed a visual inspection. Upon passing the visual inspection, the contractor performed EPA RRP verification wipes as required by EPA Lead RRP. The contractor and technician had to agree that each wipe passed the cleanliness standard. If either the contractor or technician failed a wipe, the space was recleaned and retested until the wipes passed. For many spaces, passing EPA RRP verification wipes were the only tests required.

In "Child-occupied area" spaces, at least one colorimetric wipe per space was collected. "Child-occupied areas" include but are not limited to classrooms, restrooms, cafeterias, gymnasiums, IMCs, and auditoriums that are routinely used by children in pre-kindergarten, kindergarten, and first grade. Common areas that these children only pass through, such as hallways and stairwells are not included. "Child-occupied areas" were identified by the Principal. The colorimetric wipes have a detection limit of 18 micrograms (μg) of lead. If the wipe changes from a yellow or orange color to a pink or red color, it indicates that there is a concentration of lead greater than 18 μg and the wipe fails. If a colorimetric wipe failed, the space was recleaned until both passing EPA RRP verification wipes and colorimetric wipes were obtained.

Approximately ten percent of colorimetric wipes collected or at least one from each child occupied area were sent to EMSL Analytical, Inc. for flame atomic absorption spectrophotometry. The School District of Philadelphia has chosen to use a standard of 20 µg of lead for passing floor samples. If laboratory results were greater than 20 µg, the space was recleaned and retested with EPA RRP verification wipes, colorimetric wipes, and flame atomic absorption until the results were less than 20 µg.

III. Oversight

A. Scope of Work

A Scope of Work for the Howe Academics Plus School was developed following a room-by-room inspection of the school. The assessor looked for cracking, chipping, gouging, holes, flaking, spalling, efflorescence, and significant moisture damage on walls and ceilings throughout the school. The assessor also recorded any observed paint chips or plaster debris on floors, windowsills, furniture, and stored materials. The observed damage for each space became the Scope of Work for this project. Additional areas of damage found behind wall hangings and inside decluttered closets were added to the scope of work as they were observed. A copy of the Scope of Work can be found in Appendix A.

B. EPA Checklist

The on-site environmental technician completed an EPA Checklist spreadsheet. This spreadsheet confirmed that for each work area that warning signs were posted at the entrance, the work area was contained to prevent the spread of dust and debris, all objects in the work area were removed or covered, HVAC ducts were closed and covered, windows were closed, doors were closed and sealed, doors that must be used for passage were covered to prevent the spread of dust, floors were covered with taped down plastic, waste was contained on-site and while being transported off site, the work area was properly cleaned after renovation, all chips and debris were picked up, protective sheeting was misted, folded dirty side inward, and taped for removal, and that surfaces were HEPA vacuumed or wiped with wet clothes. The technician also confirmed that a certified renovator performed post renovation cleaning verification and signed off that each of the previously listed requirements had occurred for each work area. A copy of the EPA Checklist can be found in Appendix B.

C. Oversight

An environmental technician was on-site each day that any prep, stabilization, or painting was performed by the contractor. The overall responsibility of the technician was to ensure compliance with lead safe work practices. Each technician was a certified renovator and lead dust sampling technician. The technician maintained an oversight spreadsheet completing the date each space was pre-cleaned, the contents were moved, the space was prepped, and the surfaces were stabilized. The technician also collected colorimetric wipes where necessary and recorded the number of RRP wipes, colorimetric wipes, and the results of any wipes submitted for flame atomic absorption spectrophotometry on this spreadsheet. A copy of the Oversight spreadsheet can be found in Appendix C.

D. Sample Results

Summary of Sample Results for the Howe Academics Plus School		
Number of RRP Wipes	Number of Colorimetric Wipes	Number of FAAS Wipes
1,002	53	22

Specific locations for the RRP verification wipes and colorimetric wipes can be found in Appendix C. Specific results of flame atomic absorption spectrophotometry samples can be found in Appendix D.

Refer to Appendix E for Photographs of the project. Refer to Appendix F for Environmental Firm Certifications, Appendix G for Paint Contractor Certifications or Documentation of Training, and Appendix H for Documentation of Parent and Staff Notifications.

Appendix A. Scope of Work Table

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Ceiling	Cracking, holes	13	No	No	N/A	N/A	Yes	
2	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Floor	N/A	N/A	No	No	N/A	Stored materials	No	Limited Inspection
3	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W1	Cracking, chipping wall and gate, holes	15	No	No	N/A	N/A	Yes	
4	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W2	Cracking, chipping, holes	16	No	No	N/A	N/A	Yes	
5	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W3	Cracking	3	No	No	N/A	N/A	No	
6	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W4	N/A	N/A	No	No	N/A	Stored materials	No	Limited Inspection
7	7320	1	3	316		Classroom 16	Ceiling	Flaking windows	4	No	No	N/A	N/A	No	
8	7320	1	3	316		Classroom 16	Floor	Debris	N/A	No	Debris on floor by windows	5	N/A	No	
9	7320	1	3	316		Classroom 16	W1	Cracking, chipping, holes	20	No	No	N/A	N/A	Yes	
10	7320	1	3	316		Classroom 16	W2	Cracking	3	No	No	N/A	N/A	No	
11	7320	1	3	316		Classroom 16	W3	Chipping, Flaking wall and radiator, efflorescence	39	Yes	No	N/A	N/A	Yes	
12	7320	1	3	316		Classroom 16	W4	Flaking	3	No	No	N/A	N/A	No	
13	7320	1	3	316C		Classroom 16 Coat Closet	Ceiling	Flaking	3	No	No	N/A	N/A	No	
14	7320	1	3	316C		Classroom 16 Coat Closet	Floor	Debris	N/A	No	Debris on floor	6	N/A	No	
15	7320	1	3	316C		Classroom 16 Coat Closet	W3	Cracking, chipping, flaking	35	No	No	N/A	N/A	No	
16	7320	1	3	316C		Classroom 16 Coat Closet	W4	Flaking	4	No	No	N/A	N/A	No	
17	7320	1	3	317		Classroom 17	Ceiling	Flaking by windows	11	No	No	N/A	N/A	No	
18	7320	1	3	317		Classroom 17	W1	Chipping, staples holes, holes, flaking	16	No	No	N/A	N/A	Yes	
19	7320	1	3	317		Classroom 17	W2	Chipping	2	No	No	N/A	N/A	No	
20	7320	1	3	317		Classroom 17	W3	Chipping, holes, flaking, flaking radiators spalling	52	Yes	No	N/A	N/A	Yes	
21	7320	1	3	317		Classroom 17	W4	Cracking, staple holes	18	No	No	N/A	N/A	Yes	
22	7320	1	3	317B		Classroom 17 Coat Closet	W3	Cracking, chipping	6	No	No	N/A	N/A	No	
23	7320	1	3	318		Classroom 18	Ceiling	Flaking by windows	24	No	No	N/A	N/A	No	
24	7320	1	3	318		Classroom 18	Floor	Debris	N/A	No	Debris on floor under windows	8	N/A	No	
25	7320	1	3	318		Classroom 18	W1	Chipping door frame	4	no	no	NA	no	No	
26	7320	1	3	318		Classroom 18	W2	Efflorescence by partition pocket	2	yes	yes	2	cabinet	Yes	
27	7320	1	3	318		Classroom 18	W3	Chipping radiator, holes, spalling	7	Yes	Debris on floor under radiators	4	N/A	Yes	
28	7320	1	3	318		Classroom 18	W4	Cracking	6	No	No	N/A	N/A	No	
29	7320	1	3	318C		Classroom 18 Coat Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
30	7320	1	3	318C		Classroom 18 Coat Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
31	7320	1	3	318C		Classroom 18 Coat Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
32	7320	1	3	318C		Classroom 18 Coat Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
33	7320	1	3	318C		Classroom 18 Coat Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
34	7320	1	3	318C		Classroom 18 Coat Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
35	7320	1	3	318A		Classroom 18 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
36	7320	1	3	318B		Classroom 18 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
37	7320	1	3	318A		Classroom 18 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
38	7320	1	3	318A		Classroom 18 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
39	7320	1	3	318A		Classroom 18 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
40	7320	1	3	318A		Classroom 18 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
41	7320	1	3	319		Classroom 19	Ceiling	Flaking by windows	14	No	No	N/A	N/A	No	
42	7320	1	3	319		Classroom 19	Floor	Debris	N/A	No	Debris on floor by windows	4	N/A	No	
43	7320	1	3	319		Classroom 19	W1	Flaking	8	No	No	N/A	N/A	No	
44	7320	1	3	319		Classroom 19	W3	Cracking, staple holes, flaking	7	No	No	N/A	N/A	Yes	
45	7320	1	3	319		Classroom 19	W4	Cracking, flaking	6	No	No	N/A	N/A	No	
46	7320	1	3	319B		Classroom 19 Coat Closet	W3	Cracking	3	No	No	N/A	N/A	No	
47	7320	1	3	319B		Classroom 19 Coat Closet	W4	Cracking	1	No	No	N/A	N/A	No	
48	7320	1	3	320		Classroom 20	Ceiling	Holes, flaking	11	No	No	N/A	N/A	Yes	
49	7320	1	3	320		Classroom 20	Floor	Debris	N/A	No	Debris on floor under radiators	8	N/A	No	
50	7320	1	3	320		Classroom 20	W1	Gouges, flaking	6	No	No	N/A	N/A	Yes	
51	7320	1	3	320		Classroom 20	W3	Chipping, holes by radiators, flaking	10	No	No	N/A	N/A	Yes	
52	7320	1	3	320B		Classroom 20 Coat Closet	W3	Cracking	2	No	No	N/A	N/A	No	
53	7320	1	3	321		Classroom 21	Ceiling	Holes, flaking	12	No	No	N/A	N/A	Yes	
54	7320	1	3	321		Classroom 21	Floor	Debris	N/A	No	Debris on floor by windows	3	N/A	No	
55	7320	1	3	321		Classroom 21	W1	Chipping, flaking	10	No	No	N/A	N/A	No	
56	7320	1	3	321		Classroom 21	W3	Chipping radiators, flaking, efflorescence	6	Yes	No	N/A	N/A	Yes	
57	7320	1	3	321		Classroom 21	W4	Holes, flaking	7	No	No	N/A	N/A	Yes	
58	7320	1	3	321B		Classroom 21 Coat Closet	W3	Cracking	2	No	No	N/A	N/A	No	
59	7320	1	3	321A		Classroom 21 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
60	7320	1	3	321A		Classroom 21 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
61	7320	1	3	321A		Classroom 21 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
62	7320	1	3	321A		Classroom 21 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
63	7320	1	3	321A		Classroom 21 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
64	7320	1	3	321A		Classroom 21 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
65	7320	1	3	322		Classroom 22	Ceiling	Holes, flaking by windows	10	No	No	N/A	N/A	Yes	
66	7320	1	3	322		Classroom 22	Floor	Debris	N/A	No	Debris under radiators	6	N/A	No	
67	7320	1	3	322		Classroom 22	W1	Cracking, chipping, staple holes	7	No	No	N/A	N/A	Yes	
68	7320	1	3	322		Classroom 22	W2	Spalling, efflorescence	3	Yes	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
69	7320	1	3	322		Classroom 22	W3	Holes, spalling, efflorescence	11	Yes	No	N/A	N/A	Yes	
70	7320	1	3	322C		Classroom 22 Coat Closet	W2	Cracking	2	No	No	N/A	N/A	No	
71	7320	1	3	322C		Classroom 22 Coat Closet	W3	Cracking, chipping	5	No	No	N/A	N/A	No	
72	7320	1	3	325		Classroom 23	Ceiling	Flaking by windows	4	No	No	N/A	N/A	No	
73	7320	1	3	325		Classroom 23	Floor	Debris	N/A	No	Debris under radiators	5	N/A	No	
74	7320	1	3	325		Classroom 23	W1	Chipping, holes	5	No	No	N/A	N/A	Yes	
75	7320	1	3	325		Classroom 23	W3	Chipping radiators, flaking, holes above radiators	23	No	No	N/A	N/A	Yes	
76	7320	1	3	325C		Classroom 23 Coat Closet	Ceiling	Holes	1	No	No	N/A	N/A	Yes	
77	7320	1	3	325C		Classroom 23 Coat Closet	W3	Cracking, chipping, flaking	4	No	No	N/A	N/A	No	
78	7320	1	3	323		Classroom 24	Floor	Debris	N/A	No	Debris by windows	6	N/A	No	
79	7320	1	3	323		Classroom 24	W1	Chipping, Hole, Flaking	10	No	No	N/A	N/A	No	
80	7320	1	3	323		Classroom 24	W2	Chipping, Flaking	7	No	No	N/A	N/A	No	
81	7320	1	3	323		Classroom 24	W3	Cracking, flaking	18	No	No	N/A	N/A	No	
82	7320	1	3	323		Classroom 24	W4	Flaking wall, radiator, efflorescence	13	Yes	No	N/A	N/A	Yes	
83	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W2	Chipping, flaking	2	No	No	N/A	N/A	No	
84	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W3	Chipping radiators	3	No	No	N/A	N/A	No	
85	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W4	Cracking, flaking	5	No	No	N/A	N/A	No	
86	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W3	Chipping	2	No	No	N/A	N/A	No	
87	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W4	Chipping, flaking	3	No	No	N/A	N/A	No	
88	7320	1	3	316A		Men and Women's Staff Restroom	W2	Cracking, holes	6	No	No	N/A	N/A	Yes	
89	7320	1	3	316A		Men and Women's Staff Restroom	W4	Cracking, holes, flaking	3	No	No	N/A	N/A	Yes	
90	7320	1	3	323A		Office Next to Classroom 23	Ceiling	Cracking, flaking	8	No	No	N/A	N/A	No	
91	7320	1	3	323A		Office Next to Classroom 23	Floor	Debris	N/A	No	Debris under radiators	1	N/A	No	
92	7320	1	3	323A		Office Next to Classroom 23	W1	Cracking, holes	5	No	No	N/A	N/A	Yes	
93	7320	1	3	323A		Office Next to Classroom 23	W2	Cracking, flaking	9	No	No	N/A	N/A	No	
94	7320	1	3	323A		Office Next to Classroom 23	W3	Cracking, chipping radiators, holes	7	No	No	N/A	N/A	Yes	
95	7320	1	3	323A		Office Next to Classroom 23	W4	Flaking	3	No	No	N/A	N/A	No	
96	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	Floor	Chipping stair face	60	No	No	N/A	N/A	No	
97	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	W3	Chipping, flaking	26	No	No	N/A	N/A	No	
98	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	Floor	Debris	N/A	No	Debris on sill and floor under windows	6	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
99	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W1	Holes	1	No	No	N/A	N/A	Yes	
100	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W2	Cracking, holes	10	No	No	N/A	N/A	Yes	
101	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W3	Chipping radiators, holes by windows	4	No	No	N/A	N/A	Yes	
102	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W4	Cracking, spalling	6	Yes	No	N/A	N/A	Yes	
103	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W1	Chipping door	6	No	No	N/A	N/A	No	
104	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W3	Flaking iron bars	30	No	No	N/A	N/A	No	
105	7320	1	3	H313		Third Floor Main Hallway	W1	Chipping, holes, flaking radiators	6	No	No	N/A	N/A	Yes	
106	7320	1	3	H313		Third Floor Main Hallway	W3	g wall and radiators, holes, staple holes,	10	No	No	N/A	N/A	Yes	
107	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W3	Chipping door	3	No	No	N/A	N/A	No	
108	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W4	Flaking window frame	14	No	No	N/A	N/A	No	
109	7320	1	3	324A		Women's Staff Restroom	W1	Chipping	1	No	No	N/A	N/A	No	
110	7320	1	3	324A		Women's Staff Restroom	W2	Flaking	10	No	No	N/A	N/A	No	
111	7320	1	3	324A		Women's Staff Restroom	W4	Cracking, flaking	27	No	No	N/A	N/A	No	
112	7320	1	2	210		Classroom 10	Ceiling	Holes, flaking	8	No	No	N/A	N/A	Yes	
113	7320	1	2	210		Classroom 10	Floor	Debris	N/A	No	Debris under radiators by windows	3	N/A	No	
114	7320	1	2	210		Classroom 10	W1	Cracking, chipping, staple holes, flaking	12	No	No	N/A	N/A	Yes	
115	7320	1	2	210		Classroom 10	W3	ipping radiators, holes, flaking, efflorescence	31	Yes	No	N/A	N/A	Yes	
116	7320	1	2	210		Classroom 10	W4	Cracking, holes, flaking	29	No	No	N/A	N/A	Yes	
117	7320	1	2	210C		Classroom 10 Coat Closet	W3	Cracking, chipping, flaking	11	No	No	N/A	N/A	No	
118	7320	1	2	211		Classroom 11	Ceiling	Holes, flaking	7	No	No	N/A	N/A	Yes	
119	7320	1	2	211		Classroom 11	W1	Cracking, chipping, holes, flaking	9	No	No	N/A	N/A	Yes	
120	7320	1	2	211		Classroom 11	W3	g, chipping wall, radiator and pipe, holes,	32	No	No	N/A	N/A	Yes	
121	7320	1	2	211		Classroom 11	W4	Chipping	4	No	No	N/A	N/A	No	
122	7320	1	2	211B		Classroom 11 Coat Closet	W3	Cracking, gouges	4	No	No	N/A	N/A	Yes	
123	7320	1	2	212		Classroom 12	Ceiling	Flaking	7	No	No	N/A	N/A	No	
124	7320	1	2	212		Classroom 12	Floor	Debris	N/A	No	Debris on floor by radiators	6	N/A	No	
125	7320	1	2	212		Classroom 12	W1	Cracking, chipping, holes, flaking	19	No	No	N/A	N/A	Yes	
126	7320	1	2	212		Classroom 12	W3	ipping radiator and pipe, flaking, efflorescence	22	Yes	No	N/A	N/A	Yes	
127	7320	1	2	212		Classroom 12	W4	Flaking	5	No	No	N/A	N/A	No	
128	7320	1	2	212B		Classroom 12 Coat Closet	W3	Cracking, flaking	12	No	No	N/A	N/A	No	
129	7320	1	2	15		Classroom 15	Ceiling	Flaking	9	No	No	N/A	N/A	No	
130	7320	1	2	15		Classroom 15	Floor	Debris	N/A	No	Debris on floor by windows	5	N/A	No	
131	7320	1	2	15		Classroom 15	W1	Cracking, chipping, staple holes, flaking	44	No	No	N/A	N/A	Yes	
132	7320	1	2	15		Classroom 15	W2	Cracking, staple holes	21	No	No	N/A	N/A	Yes	
133	7320	1	2	15		Classroom 15	W3	ipping raditors, holes, flaking, efflorescence	32	Yes	No	N/A	N/A	Yes	
134	7320	1	2	15		Classroom 15	W4	Gouges, staple holes	21	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
135	7320	1	2	15B		Classroom 15 Coat Closet	W2	Cracking	1	No	No	N/A	N/A	No	
136	7320	1	2	15B		Classroom 15 Coat Closet	W3	Cracking, holes, flaking	20	No	No	N/A	N/A	Yes	
137	7320	1	2	208		Classroom 8	Floor	Debris	N/A	No	Debris under radiators	2	N/A	No	
138	7320	1	2	208		Classroom 8	W1	Cracking, chipping, holes	12	No	No	N/A	N/A	Yes	
139	7320	1	2	208		Classroom 8	W2	Chipping, staples holes	7	No	No	N/A	N/A	Yes	
140	7320	1	2	208		Classroom 8	W3	Chipping pipe and radiator, holes, flaking	22	No	No	N/A	N/A	Yes	
141	7320	1	2	208		Classroom 8	W4	Flaking	8	No	No	N/A	N/A	No	
142	7320	1	2	208B		Classroom 8 Coat Closet	W2	Chipping, flaking	3	No	No	N/A	N/A	No	
143	7320	1	2	208B		Classroom 8 Coat Closet	W3	Chipping	2	No	No	N/A	N/A	No	
144	7320	1	2	206		Classroom 9	Ceiling	Chipping, flaking	5	No	No	N/A	N/A	No	
145	7320	1	2	206		Classroom 9	Floor	Debris	N/A	No	Debris on floor by radiators	5	N/A	No	
146	7320	1	2	206		Classroom 9	W1	Chipping, holes, staple holes, flaking	46	No	No	N/A	N/A	Yes	
147	7320	1	2	206		Classroom 9	W2	Staple holes	40	No	No	N/A	N/A	Yes	
148	7320	1	2	206		Classroom 9	W3	chipping wall and pipe, holes, flaking, effl	49	Yes	No	N/A	N/A	Yes	
149	7320	1	2	206		Classroom 9	W4	Chipping, staples holes, flaking	18	No	No	N/A	N/A	Yes	
150	7320	1	2	206B		Classroom 9 Coat Closet	W3	Cracking	4	No	No	N/A	N/A	No	
151	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W2	Holes, staple holes, flaking	23	No	No	N/A	N/A	Yes	
152	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W3	Chipping	1	No	No	N/A	N/A	No	
153	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W4	Staple holes	6	No	No	N/A	N/A	Yes	
154	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Ceiling	Cracking, flaking	4	No	No	N/A	N/A	No	
155	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Floor	Debris	N/A	No	Debris on floor by wall	5	N/A	No	
156	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W2	Cracking, chipping, holes, flaking	11	No	No	N/A	N/A	Yes	
157	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W3	ing radiator, flaking pipe, flaking, efflores	10	Yes	No	N/A	N/A	Yes	
158	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W4	Cracking	4	No	No	N/A	N/A	No	
159	7320	1	2	213		IMC Library	Ceiling	Holes, flaking	14	No	No	N/A	N/A	Yes	
160	7320	1	2	213		IMC Library	Floor	Debris	N/A	No	Debris on floor by radiators	12	N/A	No	
161	7320	1	2	213		IMC Library	W1	Cracking, chipping, holes, flaking	39	No	No	N/A	N/A	Yes	
162	7320	1	2	213		IMC Library	W2	Cracking, flaking	11	No	No	N/A	N/A	No	
163	7320	1	2	213		IMC Library	W3	pping radiators, holes, spalling, effloresce	23	Yes	No	N/A	N/A	Yes	
164	7320	1	2	213		IMC Library	W4	Chipping	2	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
165	7320	1	2	213B		IMC Library Book Storage Closet	W3	Cracking	2	No	No	N/A	N/A	No	
166	7320	1	2	213C		IMC Library Book Storage Closet	W4	N/A	N/A	No	No	N/A	Stored materials on shelves	No	Limited Inspection
167	7320	1	2	214B		Men's Staff Restroom	W4	Flaking	3	No	No	N/A	N/A	No	
168	7320	1	2	215C		Room within Teacher's Lounge	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
169	7320	1	2	215C		Room within Teacher's Lounge	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
170	7320	1	2	215C		Room within Teacher's Lounge	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
171	7320	1	2	215C		Room within Teacher's Lounge	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
172	7320	1	2	215C		Room within Teacher's Lounge	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
173	7320	1	2	215C		Room within Teacher's Lounge	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
174	7320	1	2	H29		Second Floor Main Hallway	W1	Chipping metal pipe, staple holes, flaking	18	No	No	N/A	N/A	Yes	
175	7320	1	2	H29		Second Floor Main Hallway	W3	g, chipping wall and radiator, holes, staple	26	No	No	N/A	N/A	Yes	
176	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W3	Chipping door and bars	92	No	No	N/A	N/A	No	
177	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W4	Chipping windows	12	No	No	N/A	N/A	No	
178	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
179	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
180	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
181	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
182	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
183	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
184	7320	1	2	215A		Teacher's Lounge	Floor	Debris	N/A	No	Debris on floor	2	N/A	No	
185	7320	1	2	215A		Teacher's Lounge	W1	Chipping	2	No	No	N/A	N/A	No	
186	7320	1	2	215A		Teacher's Lounge	W2	Cracking	4	No	No	N/A	N/A	No	
187	7320	1	2	215A		Teacher's Lounge	W3	Cracking, flaking	7	No	No	N/A	N/A	No	
188	7320	1	2	215A		Teacher's Lounge	W4	Chipping radiators, flaking	5	No	No	N/A	N/A	No	
189	7320	1	2	215D		Teacher's Lounge Kitchen	W1	built-in shelves, chipping baseboard, holes	7	No	No	N/A	N/A	Yes	
190	7320	1	2	215D		Teacher's Lounge Kitchen	W2	Cracking, chipping baseboard, holes	4	No	No	N/A	N/A	Yes	
191	7320	1	2	215D		Teacher's Lounge Kitchen	W3	Chipping baseboard	4	No	No	N/A	N/A	No	
192	7320	1	2	215D		Teacher's Lounge Kitchen	W4	Chipping baseboard	4	No	No	N/A	N/A	No	
193	7320	1	2	214A		Women's Staff Restroom	W1	Chipping	1	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
194	7320	1	2	214A		Women's Staff Restroom	W2	Holes	1	No	No	N/A	N/A	Yes	
195	7320	1	2	214A		Women's Staff Restroom	W3	Chipping metal pipe	2	No	No	N/A	N/A	No	
196	7320	2	1	101C		Cafeteria	Ceiling	Flaking, efflorescence	5	Yes	No	N/A	N/A	Yes	
197	7320	2	1	101C		Cafeteria	W1	Cracking, chipping wall and door, flaking	29	No	No	N/A	N/A	No	
198	7320	2	1	101C		Cafeteria	W2	Cracking	30	No	No	N/A	N/A	No	
199	7320	2	1	101C		Cafeteria	W3	Chipping door	10	No	No	N/A	N/A	No	
200	7320	2	1	101C		Cafeteria	W4	Cracking	30	No	No	N/A	N/A	No	
201	7320	1	1	101		Classroom 1	Ceiling	Flaking	1	No	No	N/A	N/A	No	
202	7320	1	1	101		Classroom 1	W1	Cracking, chipping, chipping door, holes	21	No	No	N/A	N/A	Yes	
203	7320	1	1	101		Classroom 1	W2	Chipping	3	No	No	N/A	N/A	No	
204	7320	1	1	101		Classroom 1	W3	Chipping metal pipe, chipping, holes and efflorescence	19	Yes	No	N/A	N/A	Yes	
205	7320	1	1	101		Classroom 1	W4	Cracking and chipping	6	No	No	N/A	N/A	No	
206	7320	1	1	101D		Classroom 1 Coat Closet	W2	Chipping	3	No	No	N/A	N/A	No	
207	7320	1	1	101D		Classroom 1 Coat Closet	W3	Cracking and chipping	15	No	No	N/A	N/A	No	
208	7320	1	1	101A		Classroom 1 Restroom	W2	Flaking	2	No	No	N/A	N/A	No	
209	7320	1	1	101A		Classroom 1 Restroom	W4	Chipping wall and radiator	7	No	No	N/A	N/A	No	
210	7320	1	1	102		Classroom 2	W1	Cracking, chipping, holes, flaking	28	No	No	N/A	N/A	Yes	
211	7320	1	1	102		Classroom 2	W3	Chipping pipe and radiator, holes and efflorescence	18	Yes	No	N/A	N/A	Yes	
212	7320	1	1	102B		Classroom 2 Coat Closet	W3	Cracking and holes	12	No	No	N/A	N/A	Yes	
213	7320	1	1	103		Classroom 3	Ceiling	Flaking	2	No	No	N/A	N/A	No	
214	7320	1	1	103		Classroom 3	W1	Cracking, chipping door, flaking	20	No	No	N/A	N/A	No	
215	7320	1	1	103		Classroom 3	W2	Chipping and flaking	5	No	No	N/A	N/A	No	
216	7320	1	1	103		Classroom 3	W3	Cracking, chipping, chipping radiator, flaking	15	No	No	N/A	N/A	No	
217	7320	1	1	103		Classroom 3	W4	Chipping wall and metal pipe	4	No	No	N/A	N/A	No	
218	7320	1	1	103C		Classroom 3 Coat Closet	Ceiling	Chipping	1	No	No	N/A	N/A	No	
219	7320	1	1	103C		Classroom 3 Coat Closet	Floor	Debris	N/A	No	Debris on floor	2	N/A	No	
220	7320	1	1	103C		Classroom 3 Coat Closet	W3	Cracking, chipping, gouge, flaking	18	No	No	N/A	N/A	Yes	
221	7320	1	1	103C		Classroom 3 Coat Closet	W4	Chipping	1	No	No	N/A	N/A	No	
222	7320	1	1	103B		Classroom 3 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
223	7320	1	1	103B		Classroom 3 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
224	7320	1	1	103A		Classroom 3 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
225	7320	1	1	103A		Classroom 3 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
226	7320	1	1	103A		Classroom 3 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
227	7320	1	1	103B		Classroom 3 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
228	7320	1	1	104		Classroom 4	Ceiling	Holes, flaking	9	No	No	N/A	N/A	Yes	
229	7320	1	1	104		Classroom 4	Floor	Debris	N/A	No	Debris on floor by radiators	1	N/A	No	
230	7320	1	1	104		Classroom 4	W1	Cracking, chipping	11	No	No	N/A	N/A	No	
231	7320	1	1	104		Classroom 4	W2	Cracking, chipping, holes, chipping metal pipe	13	No	No	N/A	N/A	Yes	
232	7320	1	1	104		Classroom 4	W3	Cracking, chipping, holes, chipping radiator	15	No	No	N/A	N/A	Yes	
233	7320	1	1	104		Classroom 4	W4	Cracking, holes, flaking	16	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
234	7320	1	1	104E		Classroom 4 Coat Closet	W1	N/A	N/A	No	No	N/A	Stored materials	No	Limited Inspection
235	7320	1	1	104E		Classroom 4 Coat Closet	W2	Chipping	1	No	No	N/A	N/A	No	
236	7320	1	1	104E		Classroom 4 Coat Closet	W3	Cracking	12	No	No	N/A	N/A	No	
237	7320	1	1	104E		Classroom 4 Coat Closet	W4	Chipping	1	No	No	N/A	N/A	No	
238	7320	1	1	106		Classroom 6	Ceiling	Flaking	8	No	No	N/A	N/A	No	
239	7320	1	1	106		Classroom 6	W1	Chipping, flaking, chipping door	18	No	No	N/A	N/A	No	
240	7320	1	1	106		Classroom 6	W2	Chipping	2	No	No	N/A	N/A	No	
241	7320	1	1	106		Classroom 6	W3	Chipping wall, radiator, pipe and flaking	17	No	No	N/A	N/A	No	
242	7320	1	1	106		Classroom 6	W4	Staple holes	8	No	No	N/A	N/A	Yes	
243	7320	1	1	106C		Classroom 6 Coat Closet	W1	N/A	N/A	No	No	N/A	Shelves and stored materials	No	Limited Inspection
244	7320	1	1	106B		Classroom 6 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
245	7320	1	1	106B		Classroom 6 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
246	7320	1	1	106A		Classroom 6 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Computer desk blocking door. This space will need to be inspected
247	7320	1	1	106A		Classroom 6 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
248	7320	1	1	106A		Classroom 6 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
249	7320	1	1	106B		Classroom 6 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
250	7320	1	1	107E		Classroom 7	Ceiling	Holes, flaking	6	No	No	N/A	N/A	Yes	
251	7320	1	1	107E		Classroom 7	W1	Chipping, holes, staple holes, chipping door	26	No	No	N/A	N/A	Yes	
252	7320	1	1	107E		Classroom 7	W2	Cracking, chipping, holes, flaking	24	No	No	N/A	N/A	Yes	
253	7320	1	1	107E		Classroom 7	W3	Chipping, holes, flaking, spalling, chipping radiator	30	Yes	No	N/A	N/A	Yes	
254	7320	1	1	107E		Classroom 7	W4	Cracking, chipping, flaking, chipping cabinet	31	No	No	N/A	N/A	No	
255	7320	1	1	107D		Classroom 7 Coat Closet	W2	Flaking	3	No	No	N/A	N/A	No	
256	7320	1	1	107D		Classroom 7 Coat Closet	W3	Cracking, flaking	29	No	No	N/A	N/A	No	
257	7320	1	1	107C		Classroom 7 Restroom	W2	Chipping radiators	4	No	No	N/A	N/A	No	
258	7320	1	1	107F		Classroom 7 Storage Closet	Floor	Debris	N/A	No	Debris on floor	16	N/A	No	
259	7320	1	1	107F		Classroom 7 Storage Closet	W1	flaking	100	No	No	N/A	N/A	No	
260	7320	1	1	107B		Classroom 7 Storage Closet	W2	Cracking	3	No	No	N/A	N/A	No	
261	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W1	Chipping	4	No	No	N/A	N/A	No	
262	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W2	Chipping	7	No	No	N/A	N/A	No	
263	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W3	Chipping, holes	14	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
264	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W4	Chipping	2	No	No	N/A	N/A	No	
265	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W1	Chipping	3	No	No	N/A	N/A	No	
266	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W2	Chipping	4	No	No	N/A	N/A	No	
267	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W3	Chipping	3	No	No	N/A	N/A	No	
268	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W4	Chipping	4	No	No	N/A	N/A	No	
269	7320	1	1	105A		Counselor's Office	Floor	Debris	N/A	No	Debris on floor by window	2	N/A	No	
270	7320	1	1	105A		Counselor's Office	W1	Chipping door	4	No	No	N/A	N/A	No	
271	7320	1	1	105A		Counselor's Office	W2	Chipping	5	No	No	N/A	N/A	No	
272	7320	1	1	105A		Counselor's Office	W3	Chipping radiator, flaking	13	No	No	N/A	N/A	No	
273	7320	1	1	105A		Counselor's Office	W4	Cracking, chipping	14	No	No	N/A	N/A	No	
274	7320	1	1	H19		First Floor Main Hallway	W1	Chipping wall and pipe, holes, flaking	26	No	No	N/A	N/A	Yes	
275	7320	1	1	H19		First Floor Main Hallway	W3	Chipping, chipping wall, metal pipe, radiator, flaking	56	No	No	N/A	N/A	No	
276	7320	1	1	S17		First Floor Stairwell Grange Avenue	Ceiling	Flaking	14	No	No	N/A	N/A	No	
277	7320	1	1	S17		First Floor Stairwell Grange Avenue	Floor	Chipping wall and rail	42	No	No	N/A	N/A	No	
278	7320	1	1	S17		First Floor Stairwell Grange Avenue	W1	Chipping, flaking, holes	35	No	No	N/A	N/A	Yes	
279	7320	1	1	S17		First Floor Stairwell Grange Avenue	W2	Chipping wall, radiator and pipe	9	No	No	N/A	N/A	No	
280	7320	1	1	S17		First Floor Stairwell Grange Avenue	W3	Chipping, holes, flaking	32	No	No	N/A	N/A	Yes	
281	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	23	No	No	N/A	N/A	No	
282	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W1	Chipping wall and pipe	6	No	No	N/A	N/A	No	
283	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W3	Chipping, holes, flaking	26	No	No	N/A	N/A	Yes	
284	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W4	Cracking, chipping radiators, flaking	17	No	No	N/A	N/A	No	
285	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Ceiling	Cracking, flaking	6	No	No	N/A	N/A	No	
286	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Floor	Debris	N/A	No	Debris on floor by wall	3	N/A	No	
287	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W2	Chipping, chipping metal pipe, holes, flaking	37	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
288	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W3	Chipping radiator, holes, flaking	8	No	No	N/A	N/A	Yes	
289	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W4	Cracking, flaking	12	No	No	N/A	N/A	No	
290	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W2	Cracking, holes, flaking	14	No	No	N/A	N/A	Yes	
291	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W3	Chipping, cracking, holes	11	No	No	N/A	N/A	Yes	
292	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W4	Cracking, chipping radiator, holes, flaking	36	No	No	N/A	N/A	Yes	
293	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W1	Chipping door and radiator	26	No	No	N/A	N/A	No	
294	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W2	Chipping radiator, door and metal pipe	13	No	No	N/A	N/A	No	
295	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W3	Cracking, chipping door and radiator, flaking	46	No	No	N/A	N/A	No	
296	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W4	Chipping metal pipe	2	No	No	N/A	N/A	No	
297	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W1	Cracking	1	No	No	N/A	N/A	No	
298	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W3	Cracking, chipping, holes	32	No	No	N/A	N/A	Yes	
299	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W4	Chipping, holes	6	No	No	N/A	N/A	Yes	
300	7320	1	1	S19		Main Entrance Stairwell	W1	Cracking, chipping wall and door, flaking	26	No	No	N/A	N/A	No	
301	7320	1	1	107		Main Office	Ceiling	Holes, flaking	4	No	No	N/A	N/A	Yes	
302	7320	1	1	107		Main Office	W1	Chipping	7	No	No	N/A	N/A	No	
303	7320	1	1	107		Main Office	W2	Holes, flaking, spalling, efflorescence, chipping	27	Yes	No	N/A	N/A	Yes	
304	7320	1	1	107		Main Office	W3	Chipping, holes, chipping door	8	No	No	N/A	N/A	Yes	
305	7320	1	1	107		Main Office	W4	Chipping	6	No	No	N/A	N/A	No	
306	7320	1	1	105D		Nurse's Office	W1	Chipping, chipping door	7	No	No	N/A	N/A	No	
307	7320	1	1	105D		Nurse's Office	W2	Cracking, chipping, flaking	17	No	No	N/A	N/A	No	
308	7320	1	1	105D		Nurse's Office	W3	Chipping radiator, flaking	12	No	No	N/A	N/A	No	
309	7320	1	1	105D		Nurse's Office	W4	Chipping	10	No	No	N/A	N/A	No	
310	7320	1	1	107A		Principal's Office	W1	Cracking, chipping, chipping door	8	No	No	N/A	N/A	No	
311	7320	1	1	107A		Principal's Office	W4	Holes	4	No	No	N/A	N/A	Yes	
312	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W1	Chipping door	10	No	No	N/A	N/A	No	
313	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W2	Cracking and flaking	6	No	No	N/A	N/A	No	
314	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W4	Cracking	3	No	No	N/A	N/A	No	
315	7320	1	1	S27		Second Floor Stairwell Grange Avenue	Floor	Chipping stairs and rails	22	No	No	N/A	N/A	No	
316	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W1	Cracking, chipping, staple holes, flaking	31	No	No	N/A	N/A	Yes	
317	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W2	Chipping, flaking	3	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
318	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W3	Cracking, flaking	24	No	No	N/A	N/A	No	
319	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W4	Flaking	7	No	No	N/A	N/A	No	
320	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Ceiling	Cracking, flaking	4	No	No	N/A	N/A	No	
321	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	23	No	No	N/A	N/A	No	
322	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W1	Cracking, chipping, holes, staple holes	11	No	No	N/A	N/A	Yes	
323	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W2	Chipping door	4	No	No	N/A	N/A	No	
324	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W3	Chipping, flaking	9	No	No	N/A	N/A	No	
325	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W4	Flaking, spalling	4	Yes	No	N/A	N/A	Yes	
326	7320	1	1	105C		Special Education Office	Ceiling	Flaking	2	No	No	N/A	N/A	No	
327	7320	1	1	105C		Special Education Office	W2	Chipping	2	No	No	N/A	N/A	No	
328	7320	1	1	105C		Special Education Office	W3	Flaking	6	No	No	N/A	N/A	No	
329	7320	1	1	105B		Speech Office	W1	Cracking, flaking, holes, spalling	29	Yes	No	N/A	N/A	Yes	
330	7320	1	1	105B		Speech Office	W2	Cracking, chipping, gouges, holes	17	No	No	N/A	N/A	Yes	
331	7320	1	1	105B		Speech Office	W4	Chipping	4	No	No	N/A	N/A	No	
332	7320	1	1	S110		Stairwell next to Classroom 2	Floor	Chipping hand rail	20	No	No	N/A	N/A	No	
333	7320	1	1	S110		Stairwell next to Classroom 2	W1	Chipping door	8	No	No	N/A	N/A	No	
334	7320	1	1	S110		Stairwell next to Classroom 2	W3	Chipping door, flaking iron bars	30	No	No	N/A	N/A	No	
335	7320	1	1	S110		Stairwell next to Classroom 2	W4	Chipping door	14	No	No	N/A	N/A	No	
336	7320	1	1	S111		Stairwell next to Main Office	W1	Chipping door	10	No	No	N/A	N/A	No	
337	7320	1	1	S111		Stairwell next to Main Office	W2	Chipping door	6	No	No	N/A	N/A	No	
338	7320	1	1	S111		Stairwell next to Main Office	W3	Chipping door, flaking door, flaking iron bars	26	No	No	N/A	N/A	No	
339	7320	1	1	S111		Stairwell next to Main Office	W4	Flaking iron bars	90	No	No	N/A	N/A	No	
340	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	Ceiling	Cracking	5	No	No	N/A	N/A	No	
341	7320	1	1	104A		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W2	Cracking	4	No	No	N/A	N/A	No	
342	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W3	Cracking, chipping pipe	8	No	No	N/A	N/A	No	
343	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W4	Cracking, holes	16	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
344	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Ceiling	Cracking, holes, flaking	16	No	No	N/A	N/A	Yes	
345	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Floor	Debris	N/A	No	Debris on floor	4	N/A	No	
346	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W1	Flaking	20	No	No	N/A	N/A	No	
347	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W2	Cracking, holes, flaking	30	No	No	N/A	N/A	Yes	
348	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W3	Flaking on wall and asbestos pipe	70	No	No	N/A	N/A	No	
349	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W4	Flaking	5	No	No	N/A	N/A	No	
350	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Ceiling	Holes	10	No	No	N/A	N/A	Yes	
351	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Floor	Debris	N/A	No	Debris throughout	25	N/A	No	
352	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W1	Cracking, chipping wall and rails, flaking	55	No	No	N/A	N/A	No	
353	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W2	Flaking	7	No	No	N/A	N/A	No	
354	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W3	Cracking, holes, flaking	18	No	No	N/A	N/A	Yes	
355	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W4	Cracking, holes, flaking	16	No	No	N/A	N/A	Yes	
356	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	Floor	Chipping rail and flaking	13	No	No	N/A	N/A	No	
357	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W1	Chipping and flaking	3	No	No	N/A	N/A	No	
358	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W2	Chipping door	2	No	No	N/A	N/A	No	
359	7320	1	0	008B		Basement Boy's Restroom	Ceiling	Cracking, holes, flaking in concrete	36	No	No	N/A	N/A	Yes	
360	7320	1	0	008B		Basement Boy's Restroom	W1	Flaking	53	No	No	N/A	N/A	No	
361	7320	1	0	008B		Basement Boy's Restroom	W2	Flaking	51	No	No	N/A	N/A	No	
362	7320	1	0	008B		Basement Boy's Restroom	W3	Flaking	42	No	No	N/A	N/A	No	
363	7320	1	0	008B		Basement Boy's Restroom	W4	Flaking	47	No	No	N/A	N/A	No	
364	7320	1	0	003B		Basement Girl's Restroom	W1	Flaking duct and wall	30	No	No	N/A	N/A	No	
365	7320	1	0	003B		Basement Girl's Restroom	W2	Chipping pipe flaking wall	50	No	No	N/A	N/A	No	
366	7320	1	0	003B		Basement Girl's Restroom	W3	Cracked and flaking brick wall	59	No	No	N/A	N/A	No	
367	7320	1	0	003B		Basement Girl's Restroom	W4	Chipped pipe flaking wall	65	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
368	7320	1	0	H01		Basement Main Hallway	Ceiling	Flaking ceiling and duct	258	No	No	N/A	N/A	No	
369	7320	1	0	H01		Basement Main Hallway	Floor	Chipping floor grate	140	No	No	N/A	N/A	No	
370	7320	1	0	H01		Basement Main Hallway	W1	Chipping baseboard, flaking wall	130	No	No	N/A	N/A	No	
371	7320	1	0	H01		Basement Main Hallway	W2	Chipping, flaking	11	No	No	N/A	N/A	No	
372	7320	1	0	H01		Basement Main Hallway	W3	Chipping baseboard, flaking wall	70	No	No	N/A	N/A	No	
373	7320	1	0	H01		Basement Main Hallway	W4	Chipping baseboard, flaking wall	48	No	No	N/A	N/A	No	
374	7320	1	0	S09		Basement Stairwell Grange Avenue	Floor	Chipping stair and rails	58	No	No	N/A	N/A	No	
375	7320	1	0	S09		Basement Stairwell Grange Avenue	W1	Cracking, chipping wall and radiator, flaking	26	No	No	N/A	N/A	No	
376	7320	1	0	S09		Basement Stairwell Grange Avenue	W2	Cracking, chipping, chipping door, holes	37	No	No	N/A	N/A	Yes	
377	7320	1	0	S09		Basement Stairwell Grange Avenue	W3	Cracking, chipping radiators, staple holes	27	No	No	N/A	N/A	Yes	
378	7320	1	0	S09		Basement Stairwell Grange Avenue	W4	Chipping door	8	No	No	N/A	N/A	No	
379	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Ceiling	Flaking	25	No	No	N/A	N/A	No	
380	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	55	No	No	N/A	N/A	No	
381	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W1	Cracking, chipping, flaking	47	No	No	N/A	N/A	No	
382	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W2	Chipping door frame	10	No	No	N/A	N/A	No	
383	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W3	Chipping	14	No	No	N/A	N/A	No	
384	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W4	Chipping door and pipe, holes and flaking	39	No	No	N/A	N/A	Yes	
385	7320	1	0	001B		Classroom B-1	Ceiling	Chipping, flaking	9	No	No	N/A	N/A	No	
386	7320	1	0	001B		Classroom B-1	Floor	Chipping radiators	20	No	No	N/A	N/A	No	
387	7320	1	0	001B		Classroom B-1	W1	Cracking, chipping, chipping door	36	No	No	N/A	N/A	No	
388	7320	1	0	001B		Classroom B-1	W2	Cracking, flaking	11	No	No	N/A	N/A	No	
389	7320	1	0	001B		Classroom B-1	W3	Cracking, holes, flaking	7	No	No	N/A	N/A	Yes	
390	7320	1	0	001B		Classroom B-1	W4	Chipping fiberglass pipe	5	No	No	N/A	N/A	No	
391	7320	1	0	002B		Gymnasium	W1	Chipping on door, duct, pipe and backboard	75	No	No	N/A	N/A	No	
392	7320	1	0	002B		Gymnasium	W2	Chipping on door and backboard	30	No	No	N/A	N/A	No	
393	7320	1	0	002B		Gymnasium	W3	Cracking brick, chipping radiators	43	No	No	N/A	N/A	No	
394	7320	1	0	002B		Gymnasium	W4	Chipping radiator, pipe and door	41	No	No	N/A	N/A	No	
395	7320	1	0	002C		Gymnasium Storage Closet	W3	Chipping wall and shelf	30	No	No	N/A	Stored materials	No	
396	7320	1	0	H02		Hallway from Classroom B-1 to Basement Main Hallway	W2	Chipping brick wall	3	No	No	N/A	N/A	No	
397	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Ceiling	Flaking ceiling and duct	225	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
398	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Floor	Debris	N/A	No	Debris at wall	4	N/A	No	
399	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W2	Chipping baseboard, flaking brick	100	No	No	N/A	N/A	No	
400	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W3	Chipping baseboard, flaking brick	10	No	No	N/A	N/A	No	
401	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W4	Chipping baseboard, flaking brick	29	No	No	N/A	N/A	No	
402	7320	1	0	S04		Stairwell adjacent to Classroom B-1	Ceiling	Flaking duct and ceiling	70	No	No	N/A	N/A	No	
403	7320	1	0	S04		Stairwell adjacent to Classroom B-1	Floor	Chipping hand rail	20	No	No	N/A	N/A	No	
404	7320	1	0	S04		Stairwell adjacent to Classroom B-1	W1	Chipping door, flaking wall	13	No	No	N/A	N/A	No	
405	7320	1	0	S04		Stairwell adjacent to Classroom B-1	W3	Chipping door	22	No	No	N/A	N/A	No	
406	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	Ceiling	Chipping door	10	No	No	N/A	N/A	No	
407	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	Floor	Chipping baseboard, stair face and hand rail	43	No	No	N/A	N/A	No	
408	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	W3	Chipping door	20	No	No	N/A	N/A	No	
409	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	W4	Chipping door	6	No	No	N/A	N/A	No	
410	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
411	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
412	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
413	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
414	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
415	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
416	7320	1	0	009B		Store Room #1	Ceiling	Flaking	20	No	No	N/A	Stored materials on shelves	No	
417	7320	1	0	009B		Store Room #1	Floor	N/A	N/A	No	No	N/A	Stored materials on shelves	No	Limited Inspection
418	7320	1	0	009B		Store Room #1	W1	N/A	N/A	No	No	N/A	Stored materials on shelves	No	Limited Inspection
419	7320	1	0	009B		Store Room #1	W2	Flaking metal pipe and wall	50	No	No	N/A	Stored materials on shelves	No	

Howe -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
420	7320	1	0	009B		Store Room #1	W3	Flaking	10	No	No	N/A	Stored materials on shelves	No	
421	7320	1	0	009B		Store Room #1	W4	N/A	N/A	No	No	N/A	Stored materials on shelves	No	Limited Inspection

Appendix B. EPA Checklist Table

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
1	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Ceiling	Cracking, holes	yes	yes	yes	yes	yes	yes	yes	yes
2	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Floor	N/A	yes	yes	yes	yes	yes	yes	yes	yes
3	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W1	Cracking, chipping wall and gate, holes	yes	yes	yes	yes	yes	yes	yes	yes
4	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W2	Cracking, chipping, holes	yes	yes	yes	yes	yes	yes	yes	yes
5	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W3	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
6	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W4	N/A	yes	yes	yes	yes	yes	yes	yes	yes
7	7320	1	3	316		Classroom 16	Ceiling	Flaking windows	yes	yes	yes	yes	yes	yes	yes	yes
8	7320	1	3	316		Classroom 16	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
9	7320	1	3	316		Classroom 16	W1	Cracking, chipping, holes	yes	yes	yes	yes	yes	yes	yes	yes
10	7320	1	3	316		Classroom 16	W2	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
11	7320	1	3	316		Classroom 16	W3	Cracking, Flaking wall and radiator, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
12	7320	1	3	316		Classroom 16	W4	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
13	7320	1	3	316C		Classroom 16 Coat Closet	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
14	7320	1	3	316C		Classroom 16 Coat Closet	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
15	7320	1	3	316C		Classroom 16 Coat Closet	W3	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
16	7320	1	3	316C		Classroom 16 Coat Closet	W4	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
17	7320	1	3	317		Classroom 17	Ceiling	Flaking by windows	yes	yes	yes	yes	yes	yes	yes	yes
18	7320	1	3	317		Classroom 17	W1	Chipping, staples holes, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
19	7320	1	3	317		Classroom 17	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
20	7320	1	3	317		Classroom 17	W3	Cracking, holes, flaking, flaking radiators spalling	yes	yes	yes	yes	yes	yes	yes	yes
21	7320	1	3	317		Classroom 17	W4	Cracking, staple holes	yes	yes	yes	yes	yes	yes	yes	yes
22	7320	1	3	317B		Classroom 17 Coat Closet	W3	Cracking, chipping	yes	yes	yes	yes	yes	yes	yes	yes
23	7320	1	3	318		Classroom 18	Ceiling	Flaking by windows	yes	yes	yes	yes	yes	yes	yes	yes
24	7320	1	3	318		Classroom 18	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
25	7320	1	3	318		Classroom 18	W1	Chipping door frame	yes	yes	yes	yes	yes	yes	yes	yes
26	7320	1	3	318		Classroom 18	W2	Efflorescence by partition pocket	yes	yes	yes	yes	yes	yes	yes	yes
27	7320	1	3	318		Classroom 18	W3	Chipping radiator, holes, spalling	yes	yes	yes	yes	yes	yes	yes	yes
28	7320	1	3	318		Classroom 18	W4	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
29	7320	1	3	318C		Classroom 18 Coat Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
30	7320	1	3	318C		Classroom 18 Coat Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes	yes
31	7320	1	3	318C		Classroom 18 Coat Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes	yes
32	7320	1	3	318C		Classroom 18 Coat Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes	yes
33	7320	1	3	318C		Classroom 18 Coat Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes	yes
34	7320	1	3	318C		Classroom 18 Coat Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes	yes
35	7320	1	3	318A		Classroom 18 Storage Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes	yes
36	7320	1	3	318B		Classroom 18 Storage Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes	yes
37	7320	1	3	318A		Classroom 18 Storage Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes	yes
38	7320	1	3	318A		Classroom 18 Storage Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes	yes
39	7320	1	3	318A		Classroom 18 Storage Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes	yes
40	7320	1	3	318A		Classroom 18 Storage Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes	yes
41	7320	1	3	319		Classroom 19	Ceiling	Flaking by windows	yes	yes	yes	yes	yes	yes	yes	yes
42	7320	1	3	319		Classroom 19	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
43	7320	1	3	319		Classroom 19	W1	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
44	7320	1	3	319		Classroom 19	W3	Cracking, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
45	7320	1	3	319		Classroom 19	W4	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
46	7320	1	3	319B		Classroom 19 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
47	7320	1	3	319B		Classroom 19 Coat Closet	W4	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
48	7320	1	3	320		Classroom 20	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
49	7320	1	3	320		Classroom 20	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
50	7320	1	3	320		Classroom 20	W1	Gouges, flaking	yes	yes	yes	yes	yes	yes	yes	yes
51	7320	1	3	320		Classroom 20	W3	Chipping, holes by radiators, flaking	yes	yes	yes	yes	yes	yes	yes	yes
52	7320	1	3	320B		Classroom 20 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
53	7320	1	3	321		Classroom 21	Ceiling	Holes, flaking	YES	YES	YES	YES	YES	YES	YES	yes
54	7320	1	3	321		Classroom 21	Floor	Debris	YES	YES	YES	YES	YES	YES	YES	yes
55	7320	1	3	321		Classroom 21	W1	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
56	7320	1	3	321		Classroom 21	W3	Chipping radiators, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
57	7320	1	3	321		Classroom 21	W4	Holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
58	7320	1	3	321B		Classroom 21 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
59	7320	1	3	321A		Classroom 21 Storage Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes	yes
60	7320	1	3	321A		Classroom 21 Storage Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes	yes
61	7320	1	3	321A		Classroom 21 Storage Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes	yes
62	7320	1	3	321A		Classroom 21 Storage Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes	yes
63	7320	1	3	321A		Classroom 21 Storage Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
64	7320	1	3	321A		Classroom 21 Storage Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes	yes
65	7320	1	3	322		Classroom 22	Ceiling	Holes, flaking by windows	yes	yes	yes	yes	yes	yes	yes	yes
66	7320	1	3	322		Classroom 22	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
67	7320	1	3	322		Classroom 22	W1	Cracking, chipping, staple holes	yes	yes	yes	yes	yes	yes	yes	yes
68	7320	1	3	322		Classroom 22	W2	Spalling, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
69	7320	1	3	322		Classroom 22	W3	Holes, spalling, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
70	7320	1	3	322C		Classroom 22 Coat Closet	W2	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
71	7320	1	3	322C		Classroom 22 Coat Closet	W3	Cracking, chipping	yes	yes	yes	yes	yes	yes	yes	yes
72	7320	1	3	325		Classroom 23	Ceiling	Flaking by windows	yes	yes	yes	yes	yes	yes	yes	yes
73	7320	1	3	325		Classroom 23	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
74	7320	1	3	325		Classroom 23	W1	Chipping, holes	yes	yes	yes	yes	yes	yes	yes	yes
75	7320	1	3	325		Classroom 23	W3	Chipping radiators, flaking, holes above radiators	yes	yes	yes	yes	yes	yes	yes	yes
76	7320	1	3	325C		Classroom 23 Coat Closet	Ceiling	Holes	yes	yes	yes	yes	yes	yes	yes	yes
77	7320	1	3	325C		Classroom 23 Coat Closet	W3	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
78	7320	1	3	323		Classroom 24	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
79	7320	1	3	323		Classroom 24	W1	Chipping, Hole, Flaking	yes	yes	yes	yes	yes	yes	yes	yes
80	7320	1	3	323		Classroom 24	W2	Chipping, Flaking	yes	yes	yes	yes	yes	yes	yes	yes
81	7320	1	3	323		Classroom 24	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
82	7320	1	3	323		Classroom 24	W4	Flaking wall, radiator, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
83	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W2	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
84	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W3	Chipping radiators	yes	yes	yes	yes	yes	yes	yes	yes
85	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W4	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
86	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W3	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
87	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W4	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
88	7320	1	3	316A		Men and Women's Staff Restroom	W2	Cracking, holes	yes	yes	yes	yes	yes	yes	yes	yes
89	7320	1	3	316A		Men and Women's Staff Restroom	W4	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
90	7320	1	3	323A		Office Next to Classroom 23	Ceiling	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
91	7320	1	3	323A		Office Next to Classroom 23	Floor	Debris	YES	YES	YES	YES	YES	YES	YES	yes
92	7320	1	3	323A		Office Next to Classroom 23	W1	Cracking, holes	YES	YES	YES	YES	YES	YES	YES	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
93	7320	1	3	323A		Office Next to Classroom 23	W2	Cracking, flaking	YES	YES	YES	YES	YES	YES	YES	yes
94	7320	1	3	323A		Office Next to Classroom 23	W3	Cracking, chipping radiators, holes	YES	YES	YES	YES	YES	YES	YES	yes
95	7320	1	3	323A		Office Next to Classroom 23	W4	Flaking	YES	YES	YES	YES	YES	YES	YES	yes
96	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	Floor	Chipping stair face	yes	yes	yes	yes	yes	yes	yes	yes
97	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	W3	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
98	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
99	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W1	Holes	yes	yes	yes	yes	yes	yes	yes	yes
100	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W2	Cracking, holes	yes	yes	yes	yes	yes	yes	yes	yes
101	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W3	Chipping radiators, holes by windows	yes	yes	yes	yes	yes	yes	yes	yes
102	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W4	Cracking, spalling	yes	yes	yes	yes	yes	yes	yes	yes
103	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
104	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W3	Flaking iron bars	yes	yes	yes	yes	yes	yes	yes	yes
105	7320	1	3	H313		Third Floor Main Hallway	W1	Chipping, holes, flaking radiators	yes	yes	yes	yes	yes	yes	yes	yes
106	7320	1	3	H313		Third Floor Main Hallway	W3	Chipping wall and radiators, holes, staple holes, flaking,	yes	yes	yes	yes	yes	yes	yes	yes
107	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W3	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
108	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W4	Flaking window frame	yes	yes	yes	yes	yes	yes	yes	yes
109	7320	1	3	324A		Women's Staff Restroom	W1	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
110	7320	1	3	324A		Women's Staff Restroom	W2	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
111	7320	1	3	324A		Women's Staff Restroom	W4	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
112	7320	1	2	210		Classroom 10	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
113	7320	1	2	210		Classroom 10	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
114	7320	1	2	210		Classroom 10	W1	Cracking, chipping, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
115	7320	1	2	210		Classroom 10	W3	Chipping radiators, holes, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
116	7320	1	2	210		Classroom 10	W4	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
117	7320	1	2	210C		Classroom 10 Coat Closet	W3	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
118	7320	1	2	211		Classroom 11	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
119	7320	1	2	211		Classroom 11	W1	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
120	7320	1	2	211		Classroom 11	W3	Cracking, chipping wall, radiator and pipe, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
121	7320	1	2	211		Classroom 11	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
122	7320	1	2	211B		Classroom 11 Coat Closet	W3	Cracking, gouges	yes	yes	yes	yes	yes	yes	yes	yes
123	7320	1	2	212		Classroom 12	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
124	7320	1	2	212		Classroom 12	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
125	7320	1	2	212		Classroom 12	W1	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
126	7320	1	2	212		Classroom 12	W3	Chipping radiator and pipe, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
127	7320	1	2	212		Classroom 12	W4	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
128	7320	1	2	212B		Classroom 12 Coat Closet	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
129	7320	1	2	15		Classroom 15	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
130	7320	1	2	15		Classroom 15	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
131	7320	1	2	15		Classroom 15	W1	Cracking, chipping, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
132	7320	1	2	15		Classroom 15	W2	Cracking, staple holes	yes	yes	yes	yes	yes	yes	yes	yes
133	7320	1	2	15		Classroom 15	W3	Chipping raditors, holes, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
134	7320	1	2	15		Classroom 15	W4	Gouges, staple holes	yes	yes	yes	yes	yes	yes	yes	yes
135	7320	1	2	15B		Classroom 15 Coat Closet	W2	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
136	7320	1	2	15B		Classroom 15 Coat Closet	W3	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
137	7320	1	2	208		Classroom 8	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
138	7320	1	2	208		Classroom 8	W1	Cracking, chipping, holes	yes	yes	yes	yes	yes	yes	yes	yes
139	7320	1	2	208		Classroom 8	W2	Chipping, staples holes	yes	yes	yes	yes	yes	yes	yes	yes
140	7320	1	2	208		Classroom 8	W3	Chipping pipe and radiator, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
141	7320	1	2	208		Classroom 8	W4	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
142	7320	1	2	208B		Classroom 8 Coat Closet	W2	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
143	7320	1	2	208B		Classroom 8 Coat Closet	W3	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
144	7320	1	2	206		Classroom 9	Ceiling	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
145	7320	1	2	206		Classroom 9	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
146	7320	1	2	206		Classroom 9	W1	Chipping, holes, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
147	7320	1	2	206		Classroom 9	W2	Staple holes	yes	yes	yes	yes	yes	yes	yes	yes
148	7320	1	2	206		Classroom 9	W3	Cracking, chipping wall and pipe, holes, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
149	7320	1	2	206		Classroom 9	W4	Chipping, staples holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
150	7320	1	2	206B		Classroom 9 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
151	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W2	Holes, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
152	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W3	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
153	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W4	Staple holes	yes	yes	yes	yes	yes	yes	yes	yes
154	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Ceiling	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
155	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
156	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W2	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
157	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W3	Chipping radiator, flaking pipe, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
158	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W4	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
159	7320	1	2	213		IMC Library	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
160	7320	1	2	213		IMC Library	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
161	7320	1	2	213		IMC Library	W1	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
162	7320	1	2	213		IMC Library	W2	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
163	7320	1	2	213		IMC Library	W3	Chipping radiators, holes, spalling, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
164	7320	1	2	213		IMC Library	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
165	7320	1	2	213B		IMC Library Book Storage Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
166	7320	1	2	213C		IMC Library Book Storage Closet	W4	N/A	yes	yes	yes	yes	yes	yes	yes	yes
167	7320	1	2	214B		Men's Staff Restroom	W4	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
168	7320	1	2	215C		Room within Teacher's Lounge	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes	yes
169	7320	1	2	215C		Room within Teacher's Lounge	Floor	No Access	yes	yes	yes	yes	yes	yes	yes	yes
170	7320	1	2	215C		Room within Teacher's Lounge	W1	No Access	yes	yes	yes	yes	yes	yes	yes	yes
171	7320	1	2	215C		Room within Teacher's Lounge	W2	No Access	yes	yes	yes	yes	yes	yes	yes	yes
172	7320	1	2	215C		Room within Teacher's Lounge	W3	No Access	yes	yes	yes	yes	yes	yes	yes	yes
173	7320	1	2	215C		Room within Teacher's Lounge	W4	No Access	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
174	7320	1	2	H29		Second Floor Main Hallway	W1	Chipping metal pipe, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
175	7320	1	2	H29		Second Floor Main Hallway	W3	Cracking, chipping wall and radiator, holes, staple holes	yes	yes	yes	yes	yes	yes	yes	yes
176	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W3	Chipping door and bars	yes	yes	yes	yes	yes	yes	yes	yes
177	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W4	Chipping windows	yes	yes	yes	yes	yes	yes	yes	yes
178	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes	yes
179	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Floor	No Access	yes	yes	yes	yes	yes	yes	yes	yes
180	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W1	No Access	yes	yes	yes	yes	yes	yes	yes	yes
181	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W2	No Access	yes	yes	yes	yes	yes	yes	yes	yes
182	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W3	No Access	yes	yes	yes	yes	yes	yes	yes	yes
183	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W4	No Access	yes	yes	yes	yes	yes	yes	yes	yes
184	7320	1	2	215A		Teacher's Lounge	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
185	7320	1	2	215A		Teacher's Lounge	W1	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
186	7320	1	2	215A		Teacher's Lounge	W2	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
187	7320	1	2	215A		Teacher's Lounge	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
188	7320	1	2	215A		Teacher's Lounge	W4	Chipping radiators, flaking	yes	yes	yes	yes	yes	yes	yes	yes
189	7320	1	2	215D		Teacher's Lounge Kitchen	W1	Chipping built-in shelves, chipping baseboard, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
190	7320	1	2	215D		Teacher's Lounge Kitchen	W2	Cracking, chipping baseboard, holes	yes	yes	yes	yes	yes	yes	yes	yes
191	7320	1	2	215D		Teacher's Lounge Kitchen	W3	Chipping baseboard	yes	yes	yes	yes	yes	yes	yes	yes
192	7320	1	2	215D		Teacher's Lounge Kitchen	W4	Chipping baseboard	yes	yes	yes	yes	yes	yes	yes	yes
193	7320	1	2	214A		Women's Staff Restroom	W1	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
194	7320	1	2	214A		Women's Staff Restroom	W2	Holes	yes	yes	yes	yes	yes	yes	yes	yes
195	7320	1	2	214A		Women's Staff Restroom	W3	Chipping metal pipe	yes	yes	yes	yes	yes	yes	yes	yes
196	7320	2	1	101C		Cafeteria	Ceiling	Flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
197	7320	2	1	101C		Cafeteria	W1	Cracking, chipping wall and door, flaking	yes	yes	yes	yes	yes	yes	yes	yes
198	7320	2	1	101C		Cafeteria	W2	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
199	7320	2	1	101C		Cafeteria	W3	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
200	7320	2	1	101C		Cafeteria	W4	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
201	7320	1	1	101		Classroom 1	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
202	7320	1	1	101		Classroom 1	W1	Cracking, chipping, chipping door, holes	yes	yes	yes	yes	yes	yes	yes	yes
203	7320	1	1	101		Classroom 1	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
204	7320	1	1	101		Classroom 1	W3	Chipping metal pipe, chipping, holes and efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
205	7320	1	1	101		Classroom 1	W4	Cracking and chipping	yes	yes	yes	yes	yes	yes	yes	yes
206	7320	1	1	101D		Classroom 1 Coat Closet	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
207	7320	1	1	101D		Classroom 1 Coat Closet	W3	Cracking and chipping	yes	yes	yes	yes	yes	yes	yes	yes
208	7320	1	1	101A		Classroom 1 Restroom	W2	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
209	7320	1	1	101A		Classroom 1 Restroom	W4	Chipping wall and radiator	yes	yes	yes	yes	yes	yes	yes	yes
210	7320	1	1	102		Classroom 2	W1	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
211	7320	1	1	102		Classroom 2	W3	Chipping pipe and radiator, holes and efflorescence	yes	yes	yes	yes	yes	yes	yes	yes
212	7320	1	1	102B		Classroom 2 Coat Closet	W3	Cracking and holes	yes	yes	yes	yes	yes	yes	yes	yes
213	7320	1	1	103		Classroom 3	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
214	7320	1	1	103		Classroom 3	W1	Cracking, chipping door, flaking	yes	yes	yes	yes	yes	yes	yes	yes
215	7320	1	1	103		Classroom 3	W2	Chipping and flaking	yes	yes	yes	yes	yes	yes	yes	yes
216	7320	1	1	103		Classroom 3	W3	Cracking, chipping, chipping radiator, flaking	yes	yes	yes	yes	yes	yes	yes	yes
217	7320	1	1	103		Classroom 3	W4	Chipping wall and metal pipe	yes	yes	yes	yes	yes	yes	yes	yes
218	7320	1	1	103C		Classroom 3 Coat Closet	Ceiling	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
219	7320	1	1	103C		Classroom 3 Coat Closet	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
220	7320	1	1	103C		Classroom 3 Coat Closet	W3	Cracking, chipping, gouge, flaking	yes	yes	yes	yes	yes	yes	yes	yes
221	7320	1	1	103C		Classroom 3 Coat Closet	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
222	7320	1	1	103B		Classroom 3 Storage Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes	yes
223	7320	1	1	103B		Classroom 3 Storage Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes	yes
224	7320	1	1	103A		Classroom 3 Storage Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes	yes
225	7320	1	1	103A		Classroom 3 Storage Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes	yes
226	7320	1	1	103A		Classroom 3 Storage Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes	yes
227	7320	1	1	103B		Classroom 3 Storage Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes	yes
228	7320	1	1	104		Classroom 4	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
229	7320	1	1	104		Classroom 4	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
230	7320	1	1	104		Classroom 4	W1	Cracking, chipping	yes	yes	yes	yes	yes	yes	yes	yes
231	7320	1	1	104		Classroom 4	W2	Cracking, chipping, holes, chipping metal pipe	yes	yes	yes	yes	yes	yes	yes	yes
232	7320	1	1	104		Classroom 4	W3	cracking, chipping, holes, chipping radiator	yes	yes	yes	yes	yes	yes	yes	yes
233	7320	1	1	104		Classroom 4	W4	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
234	7320	1	1	104E		Classroom 4 Coat Closet	W1	N/A	yes	yes	yes	yes	yes	yes	yes	yes
235	7320	1	1	104E		Classroom 4 Coat Closet	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
236	7320	1	1	104E		Classroom 4 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
237	7320	1	1	104E		Classroom 4 Coat Closet	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
238	7320	1	1	106		Classroom 6	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
239	7320	1	1	106		Classroom 6	W1	Chipping, flaking, chipping door	yes	yes	yes	yes	yes	yes	yes	yes
240	7320	1	1	106		Classroom 6	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
241	7320	1	1	106		Classroom 6	W3	Chipping wall, radiator, pipe and flaking	yes	yes	yes	yes	yes	yes	yes	yes
242	7320	1	1	106		Classroom 6	W4	Staple holes	yes	yes	yes	yes	yes	yes	yes	yes
243	7320	1	1	106C		Classroom 6 Coat Closet	W1	N/A	yes	yes	yes	yes	yes	yes	yes	yes
244	7320	1	1	106B		Classroom 6 Storage Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes	yes
245	7320	1	1	106B		Classroom 6 Storage Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes	yes
246	7320	1	1	106A		Classroom 6 Storage Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes	yes
247	7320	1	1	106A		Classroom 6 Storage Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes	yes
248	7320	1	1	106A		Classroom 6 Storage Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes	yes
249	7320	1	1	106B		Classroom 6 Storage Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes	yes
250	7320	1	1	107E		Classroom 7	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
251	7320	1	1	107E		Classroom 7	W1	Chipping, holes, staple holes, chipping door	yes	yes	yes	yes	yes	yes	yes	yes
252	7320	1	1	107E		Classroom 7	W2	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
253	7320	1	1	107E		Classroom 7	W3	Chipping, holes, flaking, spalling, chipping radiator	yes	yes	yes	yes	yes	yes	yes	yes
254	7320	1	1	107E		Classroom 7	W4	Cracking, chipping, flaking, chipping cabinets	yes	yes	yes	yes	yes	yes	yes	yes
255	7320	1	1	107D		Classroom 7 Coat Closet	W2	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
256	7320	1	1	107D		Classroom 7 Coat Closet	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
257	7320	1	1	107C		Classroom 7 Restroom	W2	Chipping radiators	yes	yes	yes	yes	yes	yes	yes	yes
258	7320	1	1	107F		Classroom 7 Storage Closet	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
259	7320	1	1	107F		Classroom 7 Storage Closet	W1	flaking	yes	yes	yes	yes	yes	yes	yes	yes
260	7320	1	1	107B		Classroom 7 Storage Closet	W2	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
261	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W1	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
262	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorsence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
263	7320	1	1	105		Common Area for Conselor, Nurse, Special Education and Speech Offices	W3	Chipping, holes	yes	yes	yes	yes	yes	yes	yes	yes
264	7320	1	1	105		Common Area for Conselor, Nurse, Special Education and Speech Offices	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
265	7320	1	1	105E		Common Area for Conselor, Nurse, Special Education and Speech Offices Storage Closet	W1	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
266	7320	1	1	105E		Common Area for Conselor, Nurse, Special Education and Speech Offices Storage Closet	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
267	7320	1	1	105E		Common Area for Conselor, Nurse, Special Education and Speech Offices Storage Closet	W3	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
268	7320	1	1	105E		Common Area for Conselor, Nurse, Special Education and Speech Offices Storage Closet	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
269	7320	1	1	105A		Counselor's Office	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
270	7320	1	1	105A		Counselor's Office	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
271	7320	1	1	105A		Counselor's Office	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
272	7320	1	1	105A		Counselor's Office	W3	Chipping radiator, flaking	yes	yes	yes	yes	yes	yes	yes	yes
273	7320	1	1	105A		Counselor's Office	W4	Cracking, chipping	yes	yes	yes	yes	yes	yes	yes	yes
274	7320	1	1	H19		First Floor Main Hallway	W1	Chipping wall and pipe, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
275	7320	1	1	H19		First Floor Main Hallway	W3	Cracking, chipping wall, metal pipe, radiator, flaking	yes	yes	yes	yes	yes	yes	yes	yes
276	7320	1	1	S17		First Floor Stairwell Grange Avenue	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
277	7320	1	1	S17		First Floor Stairwell Grange Avenue	Floor	Chipping wall and rail	yes	yes	yes	yes	yes	yes	yes	yes
278	7320	1	1	S17		First Floor Stairwell Grange Avenue	W1	Chipping, flaking, holes	yes	yes	yes	yes	yes	yes	yes	yes
279	7320	1	1	S17		First Floor Stairwell Grange Avenue	W2	Chipping wall, radiator and pipe	yes	yes	yes	yes	yes	yes	yes	yes
280	7320	1	1	S17		First Floor Stairwell Grange Avenue	W3	Chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
281	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	yes	yes	yes	yes	yes	yes	yes	yes
282	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W1	Chipping wall and pipe	yes	yes	yes	yes	yes	yes	yes	yes
283	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W3	Chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
284	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W4	Cracking, chipping radiators, flaking	yes	yes	yes	yes	yes	yes	yes	yes
285	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Ceiling	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
286	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
287	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W2	Cracking, chipping, chipping metal pipe, holes, flaking,	yes	yes	yes	yes	yes	yes	yes	yes
288	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W3	Chipping radiator, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
289	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W4	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
290	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W2	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
291	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W3	Chipping, cracking, holes	yes	yes	yes	yes	yes	yes	yes	yes
292	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W4	Cracking, chipping radiator, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
293	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W1	Chipping door and radiator	yes	yes	yes	yes	yes	yes	yes	yes
294	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W2	Chipping radiator, door and metal pipe	yes	yes	yes	yes	yes	yes	yes	yes
295	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W3	Cracking, chipping door and radiator, flaking	yes	yes	yes	yes	yes	yes	yes	yes
296	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W4	Chipping metal pipe	yes	yes	yes	yes	yes	yes	yes	yes
297	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W1	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
298	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W3	Cracking, chipping, holes	yes	yes	yes	yes	yes	yes	yes	yes
299	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W4	Chipping, holes	yes	yes	yes	yes	yes	yes	yes	yes
300	7320	1	1	S19		Main Entrance Stairwell	W1	Cracking, chipping wall and door, flaking	yes	yes	yes	yes	yes	yes	yes	yes
301	7320	1	1	107		Main Office	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
302	7320	1	1	107		Main Office	W1	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
303	7320	1	1	107		Main Office	W2	Chipping, holes, flaking, spalling, efflorescence, chipping radiator	yes	yes	yes	yes	yes	yes	yes	yes
304	7320	1	1	107		Main Office	W3	Chipping, holes, chipping door	yes	yes	yes	yes	yes	yes	yes	yes
305	7320	1	1	107		Main Office	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
306	7320	1	1	105D		Nurse's Office	W1	Chipping, chipping door	yes	yes	yes	yes	yes	yes	yes	yes
307	7320	1	1	105D		Nurse's Office	W2	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
308	7320	1	1	105D		Nurse's Office	W3	Chipping radiator, flaking	yes	yes	yes	yes	yes	yes	yes	yes
309	7320	1	1	105D		Nurse's Office	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
310	7320	1	1	107A		Principal's Office	W1	Cracking, chipping, chipping door	yes	yes	yes	yes	yes	yes	yes	yes
311	7320	1	1	107A		Principal's Office	W4	Holes	yes	yes	yes	yes	yes	yes	yes	yes
312	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
313	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W2	Cracking and flaking	yes	yes	yes	yes	yes	yes	yes	yes
314	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W4	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
315	7320	1	1	S27		Second Floor Stairwell Grange Avenue	Floor	Chipping stairs and rails	yes	yes	yes	yes	yes	yes	yes	yes
316	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W1	Cracking, chipping, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
317	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W2	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
318	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
319	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W4	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
320	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Ceiling	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
321	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	yes	yes	yes	yes	yes	yes	yes	yes
322	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W1	Cracking, chipping, holes, staple holes	yes	yes	yes	yes	yes	yes	yes	yes
323	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W2	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
324	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W3	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
325	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W4	Flaking, spalling	yes	yes	yes	yes	yes	yes	yes	yes
326	7320	1	1	105C		Special Education Office	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
327	7320	1	1	105C		Special Education Office	W2	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
328	7320	1	1	105C		Special Education Office	W3	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
329	7320	1	1	105B		Speech Office	W1	Cracking, flaking, holes, spalling	yes	yes	yes	yes	yes	yes	yes	yes
330	7320	1	1	105B		Speech Office	W2	Cracking, chipping, gouges, holes	yes	yes	yes	yes	yes	yes	yes	yes
331	7320	1	1	105B		Speech Office	W4	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
332	7320	1	1	S110		Stairwell next to Classroom 2	Floor	Chipping hand rail	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorsence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
333	7320	1	1	S110		Stairwell next to Classroom 2	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
334	7320	1	1	S110		Stairwell next to Classroom 2	W3	Chipping door, flaking iron bars	yes	yes	yes	yes	yes	yes	yes	yes
335	7320	1	1	S110		Stairwell next to Classroom 2	W4	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
336	7320	1	1	S111		Stairwell next to Main Office	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
337	7320	1	1	S111		Stairwell next to Main Office	W2	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
338	7320	1	1	S111		Stairwell next to Main Office	W3	Chipping door, flaking door, flaking iron bars	yes	yes	yes	yes	yes	yes	yes	yes
339	7320	1	1	S111		Stairwell next to Main Office	W4	Flaking iron bars	yes	yes	yes	yes	yes	yes	yes	yes
340	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	Ceiling	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
341	7320	1	1	104A		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W2	Cracking	yes	yes	yes	yes	yes	yes	yes	yes
342	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W3	Cracking, chipping pipe	yes	yes	yes	yes	yes	yes	yes	yes
343	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W4	Cracking, holes	yes	yes	yes	yes	yes	yes	yes	yes
344	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Ceiling	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
345	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
346	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W1	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
347	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W2	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
348	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W3	Flaking on wall and asbestos pipe	yes	yes	yes	yes	yes	yes	yes	yes
349	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W4	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
350	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Ceiling	Holes	yes	yes	yes	yes	yes	yes	yes	yes
351	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
352	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W1	Cracking, chipping wall and rails, flaking	yes	yes	yes	yes	yes	yes	yes	yes
353	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W2	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
354	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W3	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
355	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W4	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
356	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	Floor	Chipping rail and flaking	yes	yes	yes	yes	yes	yes	yes	yes
357	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W1	Chipping and flaking	yes	yes	yes	yes	yes	yes	yes	yes
358	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W2	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes
359	7320	1	0	008B		Basement Boy's Restroom	Ceiling	Cracking, holes, flaking in concrete	yes	yes	yes	yes	yes	yes	yes	yes
360	7320	1	0	008B		Basement Boy's Restroom	W1	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
361	7320	1	0	008B		Basement Boy's Restroom	W2	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
362	7320	1	0	008B		Basement Boy's Restroom	W3	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
363	7320	1	0	008B		Basement Boy's Restroom	W4	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
364	7320	1	0	003B		Basement Girl's Restroom	W1	Flaking duct and wall	yes	yes	yes	yes	yes	yes	yes	yes
365	7320	1	0	003B		Basement Girl's Restroom	W2	Chipping pipe flaking wall	yes	yes	yes	yes	yes	yes	yes	yes
366	7320	1	0	003B		Basement Girl's Restroom	W3	Cracked and flaking brick wall	yes	yes	yes	yes	yes	yes	yes	yes
367	7320	1	0	003B		Basement Girl's Restroom	W4	Chipped pipe flaking wall	yes	yes	yes	yes	yes	yes	yes	yes
368	7320	1	0	H01		Basement Main Hallway	Ceiling	Flaking ceiling and duct	yes	yes	yes	yes	yes	yes	yes	yes
369	7320	1	0	H01		Basement Main Hallway	Floor	Chipping floor grate	yes	yes	yes	yes	yes	yes	yes	yes
370	7320	1	0	H01		Basement Main Hallway	W1	Chipping baseboard, flaking wall	yes	yes	yes	yes	yes	yes	yes	yes
371	7320	1	0	H01		Basement Main Hallway	W2	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
372	7320	1	0	H01		Basement Main Hallway	W3	Chipping baseboard, flaking wall	yes	yes	yes	yes	yes	yes	yes	yes
373	7320	1	0	H01		Basement Main Hallway	W4	Chipping baseboard, flaking wall	yes	yes	yes	yes	yes	yes	yes	yes
374	7320	1	0	S09		Basement Stairwell Grange Avenue	Floor	Chipping stair and rails	yes	yes	yes	yes	yes	yes	yes	yes
375	7320	1	0	S09		Basement Stairwell Grange Avenue	W1	Cracking, chipping wall and radiator, flaking	yes	yes	yes	yes	yes	yes	yes	yes
376	7320	1	0	S09		Basement Stairwell Grange Avenue	W2	Cracking, chipping, chipping door, holes	yes	yes	yes	yes	yes	yes	yes	yes
377	7320	1	0	S09		Basement Stairwell Grange Avenue	W3	Cracking, chipping radiators, staple holes	yes	yes	yes	yes	yes	yes	yes	yes
378	7320	1	0	S09		Basement Stairwell Grange Avenue	W4	Chipping door	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)
379	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes	yes
380	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	yes	yes	yes	yes	yes	yes	yes	yes
381	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W1	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
382	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W2	Chipping door frame	yes	yes	yes	yes	yes	yes	yes	yes
383	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W3	Chipping	yes	yes	yes	yes	yes	yes	yes	yes
384	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W4	Chipping door and pipe, holes and flaking	yes	yes	yes	yes	yes	yes	yes	yes
385	7320	1	0	001B		Classroom B-1	Ceiling	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes	yes
386	7320	1	0	001B		Classroom B-1	Floor	Chipping radiators	yes	yes	yes	yes	yes	yes	yes	yes
387	7320	1	0	001B		Classroom B-1	W1	Cracking, chipping, chipping door	yes	yes	yes	yes	yes	yes	yes	yes
388	7320	1	0	001B		Classroom B-1	W2	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes	yes
389	7320	1	0	001B		Classroom B-1	W3	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes	yes
390	7320	1	0	001B		Classroom B-1	W4	Chipping fiberglass pipe	yes	yes	yes	yes	yes	yes	yes	yes
391	7320	1	0	002B		Gymnasium	W1	Chipping on door, duct, pipe and backboard	yes	yes	yes	yes	yes	yes	yes	yes
392	7320	1	0	002B		Gymnasium	W2	Chipping on door and backboard	yes	yes	yes	yes	yes	yes	yes	yes
393	7320	1	0	002B		Gymnasium	W3	Cracking brick, chipping radiators	yes	yes	yes	yes	yes	yes	yes	yes
394	7320	1	0	002B		Gymnasium	W4	Chipping radiator, pipe and door	yes	yes	yes	yes	yes	yes	yes	yes
395	7320	1	0	002C		Gymnasium Storage Closet	W3	Chipping wall and shelf	yes	yes	yes	yes	yes	yes	yes	yes
396	7320	1	0	H02		Hallway from Classroom B-1 to Basement Main Hallway	W2	Chipping brick wall	yes	yes	yes	yes	yes	yes	yes	yes
397	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Ceiling	Flaking ceiling and duct	yes	yes	yes	yes	yes	yes	yes	yes
398	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Floor	Debris	yes	yes	yes	yes	yes	yes	yes	yes
399	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W2	Chipping baseboard, flaking brick	yes	yes	yes	yes	yes	yes	yes	yes
400	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W3	Chipping baseboard, flaking brick	yes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

[illegible]

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
1	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Ceiling	Cracking, holes	yes	yes	yes	yes	yes	yes	yes
2	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Floor	N/A	yes	yes	yes	yes	yes	yes	yes
3	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W1	Cracking, chipping wall and gate, holes	yes	yes	yes	yes	yes	yes	yes
4	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W2	Cracking, chipping, holes	yes	yes	yes	yes	yes	yes	yes
5	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W3	Cracking	yes	yes	yes	yes	yes	yes	yes
6	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W4	N/A	yes	yes	yes	yes	yes	yes	yes
7	7320	1	3	316		Classroom 16	Ceiling	Flaking windows	yes	yes	yes	yes	yes	yes	yes
8	7320	1	3	316		Classroom 16	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
9	7320	1	3	316		Classroom 16	W1	Cracking, chipping, holes	yes	yes	yes	yes	yes	yes	yes
10	7320	1	3	316		Classroom 16	W2	Cracking	yes	yes	yes	yes	yes	yes	yes
11	7320	1	3	316		Classroom 16	W3	Cracking, Flaking wall and radiator, efflorescence	yes	yes	yes	yes	yes	yes	yes
12	7320	1	3	316		Classroom 16	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
13	7320	1	3	316C		Classroom 16 Coat Closet	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
14	7320	1	3	316C		Classroom 16 Coat Closet	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
15	7320	1	3	316C		Classroom 16 Coat Closet	W3	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes
16	7320	1	3	316C		Classroom 16 Coat Closet	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
17	7320	1	3	317		Classroom 17	Ceiling	Flaking by windows	yes	yes	yes	yes	yes	yes	yes
18	7320	1	3	317		Classroom 17	W1	Chipping, staples holes, holes, flaking	yes	yes	yes	yes	yes	yes	yes
19	7320	1	3	317		Classroom 17	W2	Chipping	yes	yes	yes	yes	yes	yes	yes
20	7320	1	3	317		Classroom 17	W3	Cracking, holes, flaking, flaking radiators spalling	yes	yes	yes	yes	yes	yes	yes
21	7320	1	3	317		Classroom 17	W4	Cracking, staple holes	yes	yes	yes	yes	yes	yes	yes
22	7320	1	3	317B		Classroom 17 Coat Closet	W3	Cracking, chipping	yes	yes	yes	yes	yes	yes	yes
23	7320	1	3	318		Classroom 18	Ceiling	Flaking by windows	yes	yes	yes	yes	yes	yes	yes
24	7320	1	3	318		Classroom 18	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
25	7320	1	3	318		Classroom 18	W1	Chipping door frame	yes	yes	yes	yes	yes	yes	yes
26	7320	1	3	318		Classroom 18	W2	Efflorescence by partition pocket	yes	yes	yes	yes	yes	yes	yes
27	7320	1	3	318		Classroom 18	W3	Chipping radiator, holes, spalling	yes	yes	yes	yes	yes	yes	yes
28	7320	1	3	318		Classroom 18	W4	Cracking	yes	yes	yes	yes	yes	yes	yes
29	7320	1	3	318C		Classroom 18 Coat Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
30	7320	1	3	318C		Classroom 18 Coat Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes
31	7320	1	3	318C		Classroom 18 Coat Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes
32	7320	1	3	318C		Classroom 18 Coat Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes
33	7320	1	3	318C		Classroom 18 Coat Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes
34	7320	1	3	318C		Classroom 18 Coat Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes
35	7320	1	3	318A		Classroom 18 Storage Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes
36	7320	1	3	318B		Classroom 18 Storage Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes
37	7320	1	3	318A		Classroom 18 Storage Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes
38	7320	1	3	318A		Classroom 18 Storage Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes
39	7320	1	3	318A		Classroom 18 Storage Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes
40	7320	1	3	318A		Classroom 18 Storage Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes
41	7320	1	3	319		Classroom 19	Ceiling	Flaking by windows	yes	yes	yes	yes	yes	yes	yes
42	7320	1	3	319		Classroom 19	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
43	7320	1	3	319		Classroom 19	W1	Flaking	yes	yes	yes	yes	yes	yes	yes
44	7320	1	3	319		Classroom 19	W3	Cracking, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes
45	7320	1	3	319		Classroom 19	W4	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
46	7320	1	3	319B		Classroom 19 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes
47	7320	1	3	319B		Classroom 19 Coat Closet	W4	Cracking	yes	yes	yes	yes	yes	yes	yes
48	7320	1	3	320		Classroom 20	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
49	7320	1	3	320		Classroom 20	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
50	7320	1	3	320		Classroom 20	W1	Gouges, flaking	yes	yes	yes	yes	yes	yes	yes
51	7320	1	3	320		Classroom 20	W3	Chipping, holes by radiators, flaking	yes	yes	yes	yes	yes	yes	yes
52	7320	1	3	320B		Classroom 20 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes
53	7320	1	3	321		Classroom 21	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
54	7320	1	3	321		Classroom 21	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
55	7320	1	3	321		Classroom 21	W1	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
56	7320	1	3	321		Classroom 21	W3	Chipping radiators, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes
57	7320	1	3	321		Classroom 21	W4	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
58	7320	1	3	321B		Classroom 21 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes
59	7320	1	3	321A		Classroom 21 Storage Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes
60	7320	1	3	321A		Classroom 21 Storage Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes
61	7320	1	3	321A		Classroom 21 Storage Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes
62	7320	1	3	321A		Classroom 21 Storage Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes
63	7320	1	3	321A		Classroom 21 Storage Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
64	7320	1	3	321A		Classroom 21 Storage Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes
65	7320	1	3	322		Classroom 22	Ceiling	Holes, flaking by windows	yes	yes	yes	yes	yes	yes	yes
66	7320	1	3	322		Classroom 22	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
67	7320	1	3	322		Classroom 22	W1	Cracking, chipping, staple holes	yes	yes	yes	yes	yes	yes	yes
68	7320	1	3	322		Classroom 22	W2	Spalling, efflorescence	yes	yes	yes	yes	yes	yes	yes
69	7320	1	3	322		Classroom 22	W3	Holes, spalling, efflorescence	yes	yes	yes	yes	yes	yes	yes
70	7320	1	3	322C		Classroom 22 Coat Closet	W2	Cracking	yes	yes	yes	yes	yes	yes	yes
71	7320	1	3	322C		Classroom 22 Coat Closet	W3	Cracking, chipping	yes	yes	yes	yes	yes	yes	yes
72	7320	1	3	325		Classroom 23	Ceiling	Flaking by windows	yes	yes	yes	yes	yes	yes	yes
73	7320	1	3	325		Classroom 23	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
74	7320	1	3	325		Classroom 23	W1	Chipping, holes	yes	yes	yes	yes	yes	yes	yes
75	7320	1	3	325		Classroom 23	W3	Chipping radiators, flaking, holes above radiators	yes	yes	yes	yes	yes	yes	yes
76	7320	1	3	325C		Classroom 23 Coat Closet	Ceiling	Holes	yes	yes	yes	yes	yes	yes	yes
77	7320	1	3	325C		Classroom 23 Coat Closet	W3	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes
78	7320	1	3	323		Classroom 24	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
79	7320	1	3	323		Classroom 24	W1	Chipping, Hole, Flaking	yes	yes	yes	yes	yes	yes	yes
80	7320	1	3	323		Classroom 24	W2	Chipping, Flaking	yes	yes	yes	yes	yes	yes	yes
81	7320	1	3	323		Classroom 24	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
82	7320	1	3	323		Classroom 24	W4	Flaking wall, radiator, efflorescence	yes	yes	yes	yes	yes	yes	yes
83	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W2	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
84	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W3	Chipping radiators	yes	yes	yes	yes	yes	yes	yes
85	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W4	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
86	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W3	Chipping	yes	yes	yes	yes	yes	yes	yes
87	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W4	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
88	7320	1	3	316A		Men and Women's Staff Restroom	W2	Cracking, holes	yes	yes	yes	yes	yes	yes	yes
89	7320	1	3	316A		Men and Women's Staff Restroom	W4	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
90	7320	1	3	323A		Office Next to Classroom 23	Ceiling	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
91	7320	1	3	323A		Office Next to Classroom 23	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
92	7320	1	3	323A		Office Next to Classroom 23	W1	Cracking, holes	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
93	7320	1	3	323A		Office Next to Classroom 23	W2	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
94	7320	1	3	323A		Office Next to Classroom 23	W3	Cracking, chipping radiators, holes	yes	yes	yes	yes	yes	yes	yes
95	7320	1	3	323A		Office Next to Classroom 23	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
96	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	Floor	Chipping stair face	yes	yes	yes	yes	yes	yes	yes
97	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	W3	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
98	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
99	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W1	Holes	yes	yes	yes	yes	yes	yes	yes
100	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W2	Cracking, holes	yes	yes	yes	yes	yes	yes	yes
101	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W3	Chipping radiators, holes by windows	yes	yes	yes	yes	yes	yes	yes
102	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W4	Cracking, spalling	yes	yes	yes	yes	yes	yes	yes
103	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes
104	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W3	Flaking iron bars	yes	yes	yes	yes	yes	yes	yes
105	7320	1	3	H313		Third Floor Main Hallway	W1	Chipping, holes, flaking radiators	yes	yes	yes	yes	yes	yes	yes
106	7320	1	3	H313		Third Floor Main Hallway	W3	Chipping wall and radiators, holes, staple holes, flaking,	yes	yes	yes	yes	yes	yes	yes
107	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W3	Chipping door	yes	yes	yes	yes	yes	yes	yes
108	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W4	Flaking window frame	yes	yes	yes	yes	yes	yes	yes
109	7320	1	3	324A		Women's Staff Restroom	W1	Chipping	yes	yes	yes	yes	yes	yes	yes
110	7320	1	3	324A		Women's Staff Restroom	W2	Flaking	yes	yes	yes	yes	yes	yes	yes
111	7320	1	3	324A		Women's Staff Restroom	W4	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
112	7320	1	2	210		Classroom 10	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
113	7320	1	2	210		Classroom 10	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
114	7320	1	2	210		Classroom 10	W1	Cracking, chipping, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
115	7320	1	2	210		Classroom 10	W3	Chipping radiators, holes, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes
116	7320	1	2	210		Classroom 10	W4	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
117	7320	1	2	210C		Classroom 10 Coat Closet	W3	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes
118	7320	1	2	211		Classroom 11	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
119	7320	1	2	211		Classroom 11	W1	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes
120	7320	1	2	211		Classroom 11	W3	Cracking, chipping wall, radiator and pipe, holes, flaking	yes	yes	yes	yes	yes	yes	yes
121	7320	1	2	211		Classroom 11	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
122	7320	1	2	211B		Classroom 11 Coat Closet	W3	Cracking, gouges	yes	yes	yes	yes	yes	yes	yes
123	7320	1	2	212		Classroom 12	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
124	7320	1	2	212		Classroom 12	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
125	7320	1	2	212		Classroom 12	W1	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes
126	7320	1	2	212		Classroom 12	W3	Chipping radiator and pipe, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes
127	7320	1	2	212		Classroom 12	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
128	7320	1	2	212B		Classroom 12 Coat Closet	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
129	7320	1	2	15		Classroom 15	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
130	7320	1	2	15		Classroom 15	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
131	7320	1	2	15		Classroom 15	W1	Cracking, chipping, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes
132	7320	1	2	15		Classroom 15	W2	Cracking, staple holes	yes	yes	yes	yes	yes	yes	yes
133	7320	1	2	15		Classroom 15	W3	Chipping raditors, holes, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes
134	7320	1	2	15		Classroom 15	W4	Gouges, staple holes	yes	yes	yes	yes	yes	yes	yes
135	7320	1	2	15B		Classroom 15 Coat Closet	W2	Cracking	yes	yes	yes	yes	yes	yes	yes
136	7320	1	2	15B		Classroom 15 Coat Closet	W3	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
137	7320	1	2	208		Classroom 8	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
138	7320	1	2	208		Classroom 8	W1	Cracking, chipping, holes	yes	yes	yes	yes	yes	yes	yes
139	7320	1	2	208		Classroom 8	W2	Chipping, staples holes	yes	yes	yes	yes	yes	yes	yes
140	7320	1	2	208		Classroom 8	W3	Chipping pipe and radiator, holes, flaking	yes	yes	yes	yes	yes	yes	yes
141	7320	1	2	208		Classroom 8	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
142	7320	1	2	208B		Classroom 8 Coat Closet	W2	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
143	7320	1	2	208B		Classroom 8 Coat Closet	W3	Chipping	yes	yes	yes	yes	yes	yes	yes
144	7320	1	2	206		Classroom 9	Ceiling	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
145	7320	1	2	206		Classroom 9	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
146	7320	1	2	206		Classroom 9	W1	Chipping, holes, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes
147	7320	1	2	206		Classroom 9	W2	Staple holes	yes	yes	yes	yes	yes	yes	yes
148	7320	1	2	206		Classroom 9	W3	Cracking, chipping wall and pipe, holes, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes
149	7320	1	2	206		Classroom 9	W4	Chipping, staples holes, flaking	yes	yes	yes	yes	yes	yes	yes
150	7320	1	2	206B		Classroom 9 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
151	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W2	Holes, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes
152	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W3	Chipping	yes	yes	yes	yes	yes	yes	yes
153	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W4	Staple holes	yes	yes	yes	yes	yes	yes	yes
154	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Ceiling	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
155	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
156	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W2	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes
157	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W3	Chipping radiator, flaking pipe, flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes
158	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W4	Cracking	yes	yes	yes	yes	yes	yes	yes
159	7320	1	2	213		IMC Library	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
160	7320	1	2	213		IMC Library	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
161	7320	1	2	213		IMC Library	W1	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes
162	7320	1	2	213		IMC Library	W2	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
163	7320	1	2	213		IMC Library	W3	Chipping radiators, holes, spalling, efflorescence	yes	yes	yes	yes	yes	yes	yes
164	7320	1	2	213		IMC Library	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
165	7320	1	2	213B		IMC Library Book Storage Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes
166	7320	1	2	213C		IMC Library Book Storage Closet	W4	N/A	yes	yes	yes	yes	yes	yes	yes
167	7320	1	2	214B		Men's Staff Restroom	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
168	7320	1	2	215C		Room within Teacher's Lounge	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes
169	7320	1	2	215C		Room within Teacher's Lounge	Floor	No Access	yes	yes	yes	yes	yes	yes	yes
170	7320	1	2	215C		Room within Teacher's Lounge	W1	No Access	yes	yes	yes	yes	yes	yes	yes
171	7320	1	2	215C		Room within Teacher's Lounge	W2	No Access	yes	yes	yes	yes	yes	yes	yes
172	7320	1	2	215C		Room within Teacher's Lounge	W3	No Access	yes	yes	yes	yes	yes	yes	yes
173	7320	1	2	215C		Room within Teacher's Lounge	W4	No Access	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
174	7320	1	2	H29		Second Floor Main Hallway	W1	Chipping metal pipe, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes
175	7320	1	2	H29		Second Floor Main Hallway	W3	Cracking, chipping wall and radiator, holes, staple holes	yes	yes	yes	yes	yes	yes	yes
176	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W3	Chipping door and bars	yes	yes	yes	yes	yes	yes	yes
177	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W4	Chipping windows	yes	yes	yes	yes	yes	yes	yes
178	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes
179	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Floor	No Access	yes	yes	yes	yes	yes	yes	yes
180	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W1	No Access	yes	yes	yes	yes	yes	yes	yes
181	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W2	No Access	yes	yes	yes	yes	yes	yes	yes
182	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W3	No Access	yes	yes	yes	yes	yes	yes	yes
183	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W4	No Access	yes	yes	yes	yes	yes	yes	yes
184	7320	1	2	215A		Teacher's Lounge	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
185	7320	1	2	215A		Teacher's Lounge	W1	Chipping	yes	yes	yes	yes	yes	yes	yes
186	7320	1	2	215A		Teacher's Lounge	W2	Cracking	yes	yes	yes	yes	yes	yes	yes
187	7320	1	2	215A		Teacher's Lounge	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
188	7320	1	2	215A		Teacher's Lounge	W4	Chipping radiators, flaking	yes	yes	yes	yes	yes	yes	yes
189	7320	1	2	215D		Teacher's Lounge Kitchen	W1	Chipping built-in shelves, chipping baseboard, holes, flaking	yes	yes	yes	yes	yes	yes	yes
190	7320	1	2	215D		Teacher's Lounge Kitchen	W2	Cracking, chipping baseboard, holes	yes	yes	yes	yes	yes	yes	yes
191	7320	1	2	215D		Teacher's Lounge Kitchen	W3	Chipping baseboard	yes	yes	yes	yes	yes	yes	yes
192	7320	1	2	215D		Teacher's Lounge Kitchen	W4	Chipping baseboard	yes	yes	yes	yes	yes	yes	yes
193	7320	1	2	214A		Women's Staff Restroom	W1	Chipping	yes	yes	yes	yes	yes	yes	yes
194	7320	1	2	214A		Women's Staff Restroom	W2	Holes	yes	yes	yes	yes	yes	yes	yes
195	7320	1	2	214A		Women's Staff Restroom	W3	Chipping metal pipe	yes	yes	yes	yes	yes	yes	yes
196	7320	2	1	101C		Cafeteria	Ceiling	Flaking, efflorescence	yes	yes	yes	yes	yes	yes	yes
197	7320	2	1	101C		Cafeteria	W1	Cracking, chipping wall and door, flaking	yes	yes	yes	yes	yes	yes	yes
198	7320	2	1	101C		Cafeteria	W2	Cracking	yes	yes	yes	yes	yes	yes	yes
199	7320	2	1	101C		Cafeteria	W3	Chipping door	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
200	7320	2	1	101C		Cafeteria	W4	Cracking	yes	yes	yes	yes	yes	yes	yes
201	7320	1	1	101		Classroom 1	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
202	7320	1	1	101		Classroom 1	W1	Cracking, chipping, chipping door, holes	yes	yes	yes	yes	yes	yes	yes
203	7320	1	1	101		Classroom 1	W2	Chipping	yes	yes	yes	yes	yes	yes	yes
204	7320	1	1	101		Classroom 1	W3	Chipping metal pipe, chipping, holes and efflorescence	yes	yes	yes	yes	yes	yes	yes
205	7320	1	1	101		Classroom 1	W4	Cracking and chipping	yes	yes	yes	yes	yes	yes	yes
206	7320	1	1	101D		Classroom 1 Coat Closet	W2	Chipping	yes	yes	yes	yes	yes	yes	yes
207	7320	1	1	101D		Classroom 1 Coat Closet	W3	Cracking and chipping	yes	yes	yes	yes	yes	yes	yes
208	7320	1	1	101A		Classroom 1 Restroom	W2	Flaking	yes	yes	yes	yes	yes	yes	yes
209	7320	1	1	101A		Classroom 1 Restroom	W4	Chipping wall and radiator	yes	yes	yes	yes	yes	yes	yes
210	7320	1	1	102		Classroom 2	W1	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes
211	7320	1	1	102		Classroom 2	W3	Chipping pipe and radiator, holes and efflorescence	yes	yes	yes	yes	yes	yes	yes
212	7320	1	1	102B		Classroom 2 Coat Closet	W3	Cracking and holes	yes	yes	yes	yes	yes	yes	yes
213	7320	1	1	103		Classroom 3	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
214	7320	1	1	103		Classroom 3	W1	Cracking, chipping door, flaking	yes	yes	yes	yes	yes	yes	yes
215	7320	1	1	103		Classroom 3	W2	Chipping and flaking	yes	yes	yes	yes	yes	yes	yes
216	7320	1	1	103		Classroom 3	W3	Cracking, chipping, chipping radiator, flaking	yes	yes	yes	yes	yes	yes	yes
217	7320	1	1	103		Classroom 3	W4	Chipping wall and metal pipe	yes	yes	yes	yes	yes	yes	yes
218	7320	1	1	103C		Classroom 3 Coat Closet	Ceiling	Chipping	yes	yes	yes	yes	yes	yes	yes
219	7320	1	1	103C		Classroom 3 Coat Closet	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
220	7320	1	1	103C		Classroom 3 Coat Closet	W3	Cracking, chipping, gouge, flaking	yes	yes	yes	yes	yes	yes	yes
221	7320	1	1	103C		Classroom 3 Coat Closet	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
222	7320	1	1	103B		Classroom 3 Storage Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes
223	7320	1	1	103B		Classroom 3 Storage Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes
224	7320	1	1	103A		Classroom 3 Storage Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes
225	7320	1	1	103A		Classroom 3 Storage Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes
226	7320	1	1	103A		Classroom 3 Storage Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes
227	7320	1	1	103B		Classroom 3 Storage Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes
228	7320	1	1	104		Classroom 4	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
229	7320	1	1	104		Classroom 4	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
230	7320	1	1	104		Classroom 4	W1	Cracking, chipping	yes	yes	yes	yes	yes	yes	yes
231	7320	1	1	104		Classroom 4	W2	Cracking, chipping, holes, chipping metal pipe	yes	yes	yes	yes	yes	yes	yes
232	7320	1	1	104		Classroom 4	W3	cracking, chipping, holes, chipping radiator	yes	yes	yes	yes	yes	yes	yes
233	7320	1	1	104		Classroom 4	W4	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
234	7320	1	1	104E		Classroom 4 Coat Closet	W1	N/A	yes	yes	yes	yes	yes	yes	yes
235	7320	1	1	104E		Classroom 4 Coat Closet	W2	Chipping	yes	yes	yes	yes	yes	yes	yes
236	7320	1	1	104E		Classroom 4 Coat Closet	W3	Cracking	yes	yes	yes	yes	yes	yes	yes
237	7320	1	1	104E		Classroom 4 Coat Closet	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
238	7320	1	1	106		Classroom 6	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
239	7320	1	1	106		Classroom 6	W1	Chipping, flaking, chipping door	yes	yes	yes	yes	yes	yes	yes
240	7320	1	1	106		Classroom 6	W2	Chipping	yes	yes	yes	yes	yes	yes	yes
241	7320	1	1	106		Classroom 6	W3	Chipping wall, radiator, pipe and flaking	yes	yes	yes	yes	yes	yes	yes
242	7320	1	1	106		Classroom 6	W4	Staple holes	yes	yes	yes	yes	yes	yes	yes
243	7320	1	1	106C		Classroom 6 Coat Closet	W1	N/A	yes	yes	yes	yes	yes	yes	yes
244	7320	1	1	106B		Classroom 6 Storage Closet	Ceiling	No Access	yes	yes	yes	yes	yes	yes	yes
245	7320	1	1	106B		Classroom 6 Storage Closet	Floor	No Access	yes	yes	yes	yes	yes	yes	yes
246	7320	1	1	106A		Classroom 6 Storage Closet	W1	No Access	yes	yes	yes	yes	yes	yes	yes
247	7320	1	1	106A		Classroom 6 Storage Closet	W2	No Access	yes	yes	yes	yes	yes	yes	yes
248	7320	1	1	106A		Classroom 6 Storage Closet	W3	No Access	yes	yes	yes	yes	yes	yes	yes
249	7320	1	1	106B		Classroom 6 Storage Closet	W4	No Access	yes	yes	yes	yes	yes	yes	yes
250	7320	1	1	107E		Classroom 7	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
251	7320	1	1	107E		Classroom 7	W1	Chipping, holes, staple holes, chipping door	yes	yes	yes	yes	yes	yes	yes
252	7320	1	1	107E		Classroom 7	W2	Cracking, chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes
253	7320	1	1	107E		Classroom 7	W3	Chipping, holes, flaking, spalling, chipping radiator	yes	yes	yes	yes	yes	yes	yes
254	7320	1	1	107E		Classroom 7	W4	Cracking, chipping, flaking, chipping cabinets	yes	yes	yes	yes	yes	yes	yes
255	7320	1	1	107D		Classroom 7 Coat Closet	W2	Flaking	yes	yes	yes	yes	yes	yes	yes
256	7320	1	1	107D		Classroom 7 Coat Closet	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
257	7320	1	1	107C		Classroom 7 Restroom	W2	Chipping radiators	yes	yes	yes	yes	yes	yes	yes
258	7320	1	1	107F		Classroom 7 Storage Closet	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
259	7320	1	1	107F		Classroom 7 Storage Closet	W1	flaking	yes	yes	yes	yes	yes	yes	yes
260	7320	1	1	107B		Classroom 7 Storage Closet	W2	Cracking	yes	yes	yes	yes	yes	yes	yes
261	7320	1	1	105		Common Area for Conselor, Nurse, Special Education and Speech Offices	W1	Chipping	yes	yes	yes	yes	yes	yes	yes
262	7320	1	1	105		Common Area for Conselor, Nurse, Special Education and Speech Offices	W2	Chipping	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
263	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W3	Chipping, holes	yes	yes	yes	yes	yes	yes	yes
264	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
265	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W1	Chipping	yes	yes	yes	yes	yes	yes	yes
266	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W2	Chipping	yes	yes	yes	yes	yes	yes	yes
267	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W3	Chipping	yes	yes	yes	yes	yes	yes	yes
268	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
269	7320	1	1	105A		Counselor's Office	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
270	7320	1	1	105A		Counselor's Office	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes
271	7320	1	1	105A		Counselor's Office	W2	Chipping	yes	yes	yes	yes	yes	yes	yes
272	7320	1	1	105A		Counselor's Office	W3	Chipping radiator, flaking	yes	yes	yes	yes	yes	yes	yes
273	7320	1	1	105A		Counselor's Office	W4	Cracking, chipping	yes	yes	yes	yes	yes	yes	yes
274	7320	1	1	H19		First Floor Main Hallway	W1	Chipping wall and pipe, holes, flaking	yes	yes	yes	yes	yes	yes	yes
275	7320	1	1	H19		First Floor Main Hallway	W3	Cracking, chipping wall, metal pipe, radiator, flaking	yes	yes	yes	yes	yes	yes	yes
276	7320	1	1	S17		First Floor Stairwell Grange Avenue	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
277	7320	1	1	S17		First Floor Stairwell Grange Avenue	Floor	Chipping wall and rail	yes	yes	yes	yes	yes	yes	yes
278	7320	1	1	S17		First Floor Stairwell Grange Avenue	W1	Chipping, flaking, holes	yes	yes	yes	yes	yes	yes	yes
279	7320	1	1	S17		First Floor Stairwell Grange Avenue	W2	Chipping wall, radiator and pipe	yes	yes	yes	yes	yes	yes	yes
280	7320	1	1	S17		First Floor Stairwell Grange Avenue	W3	Chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes
281	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	yes	yes	yes	yes	yes	yes	yes
282	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W1	Chipping wall and pipe	yes	yes	yes	yes	yes	yes	yes
283	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W3	Chipping, holes, flaking	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
284	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W4	Cracking, chipping radiators, flaking	yes	yes	yes	yes	yes	yes	yes
285	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Ceiling	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
286	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
287	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W2	Cracking, chipping, chipping metal pipe, holes, flaking,	yes	yes	yes	yes	yes	yes	yes
288	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W3	Chipping radiator, holes, flaking	yes	yes	yes	yes	yes	yes	yes
289	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W4	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
290	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W2	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
291	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W3	Chipping, cracking, holes	yes	yes	yes	yes	yes	yes	yes
292	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W4	Cracking, chipping radiator, holes, flaking	yes	yes	yes	yes	yes	yes	yes
293	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W1	Chipping door and radiator	yes	yes	yes	yes	yes	yes	yes
294	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W2	Chipping radiator, door and metal pipe	yes	yes	yes	yes	yes	yes	yes
295	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W3	Cracking, chipping door and radiator, flaking	yes	yes	yes	yes	yes	yes	yes
296	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W4	Chipping metal pipe	yes	yes	yes	yes	yes	yes	yes
297	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W1	Cracking	yes	yes	yes	yes	yes	yes	yes
298	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W3	Cracking, chipping, holes	yes	yes	yes	yes	yes	yes	yes
299	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W4	Chipping, holes	yes	yes	yes	yes	yes	yes	yes
300	7320	1	1	S19		Main Entrance Stairwell	W1	Cracking, chipping wall and door, flaking	yes	yes	yes	yes	yes	yes	yes
301	7320	1	1	107		Main Office	Ceiling	Holes, flaking	yes	yes	yes	yes	yes	yes	yes
302	7320	1	1	107		Main Office	W1	Chipping	yes	yes	yes	yes	yes	yes	yes
303	7320	1	1	107		Main Office	W2	Chipping, holes, flaking, spalling, efflorescence, chipping radiator	yes	yes	yes	yes	yes	yes	yes
304	7320	1	1	107		Main Office	W3	Chipping, holes, chipping door	yes	yes	yes	yes	yes	yes	yes
305	7320	1	1	107		Main Office	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
306	7320	1	1	105D		Nurse's Office	W1	Chipping, chipping door	yes	yes	yes	yes	yes	yes	yes
307	7320	1	1	105D		Nurse's Office	W2	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
308	7320	1	1	105D		Nurse's Office	W3	Chipping radiator, flaking	yes	yes	yes	yes	yes	yes	yes
309	7320	1	1	105D		Nurse's Office	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
310	7320	1	1	107A		Principal's Office	W1	Cracking, chipping, chipping door	yes	yes	yes	yes	yes	yes	yes
311	7320	1	1	107A		Principal's Office	W4	Holes	yes	yes	yes	yes	yes	yes	yes
312	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes
313	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W2	Cracking and flaking	yes	yes	yes	yes	yes	yes	yes
314	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W4	Cracking	yes	yes	yes	yes	yes	yes	yes
315	7320	1	1	S27		Second Floor Stairwell Grange Avenue	Floor	Chipping stairs and rails	yes	yes	yes	yes	yes	yes	yes
316	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W1	Cracking, chipping, staple holes, flaking	yes	yes	yes	yes	yes	yes	yes
317	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W2	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
318	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W3	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
319	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
320	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Ceiling	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
321	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	yes	yes	yes	yes	yes	yes	yes
322	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W1	Cracking, chipping, holes, staple holes	yes	yes	yes	yes	yes	yes	yes
323	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W2	Chipping door	yes	yes	yes	yes	yes	yes	yes
324	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W3	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
325	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W4	Flaking, spalling	yes	yes	yes	yes	yes	yes	yes
326	7320	1	1	105C		Special Education Office	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
327	7320	1	1	105C		Special Education Office	W2	Chipping	yes	yes	yes	yes	yes	yes	yes
328	7320	1	1	105C		Special Education Office	W3	Flaking	yes	yes	yes	yes	yes	yes	yes
329	7320	1	1	105B		Speech Office	W1	Cracking, flaking, holes, spalling	yes	yes	yes	yes	yes	yes	yes
330	7320	1	1	105B		Speech Office	W2	Cracking, chipping, gouges, holes	yes	yes	yes	yes	yes	yes	yes
331	7320	1	1	105B		Speech Office	W4	Chipping	yes	yes	yes	yes	yes	yes	yes
332	7320	1	1	S110		Stairwell next to Classroom 2	Floor	Chipping hand rail	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
333	7320	1	1	S110		Stairwell next to Classroom 2	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes
334	7320	1	1	S110		Stairwell next to Classroom 2	W3	Chipping door, flaking iron bars	yes	yes	yes	yes	yes	yes	yes
335	7320	1	1	S110		Stairwell next to Classroom 2	W4	Chipping door	yes	yes	yes	yes	yes	yes	yes
336	7320	1	1	S111		Stairwell next to Main Office	W1	Chipping door	yes	yes	yes	yes	yes	yes	yes
337	7320	1	1	S111		Stairwell next to Main Office	W2	Chipping door	yes	yes	yes	yes	yes	yes	yes
338	7320	1	1	S111		Stairwell next to Main Office	W3	Chipping door, flaking door, flaking iron bars	yes	yes	yes	yes	yes	yes	yes
339	7320	1	1	S111		Stairwell next to Main Office	W4	Flaking iron bars	yes	yes	yes	yes	yes	yes	yes
340	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	Ceiling	Cracking	yes	yes	yes	yes	yes	yes	yes
341	7320	1	1	104A		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W2	Cracking	yes	yes	yes	yes	yes	yes	yes
342	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W3	Cracking, chipping pipe	yes	yes	yes	yes	yes	yes	yes
343	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W4	Cracking, holes	yes	yes	yes	yes	yes	yes	yes
344	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Ceiling	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
345	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
346	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W1	Flaking	yes	yes	yes	yes	yes	yes	yes
347	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W2	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
348	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W3	Flaking on wall and asbestos pipe	yes	yes	yes	yes	yes	yes	yes
349	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
350	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Ceiling	Holes	yes	yes	yes	yes	yes	yes	yes
351	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Floor	Debris	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
352	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W1	Cracking, chipping wall and rails, flaking	yes	yes	yes	yes	yes	yes	yes
353	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W2	Flaking	yes	yes	yes	yes	yes	yes	yes
354	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W3	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
355	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W4	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
356	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	Floor	Chipping rail and flaking	yes	yes	yes	yes	yes	yes	yes
357	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W1	Chipping and flaking	yes	yes	yes	yes	yes	yes	yes
358	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W2	Chipping door	yes	yes	yes	yes	yes	yes	yes
359	7320	1	0	008B		Basement Boy's Restroom	Ceiling	Cracking, holes, flaking in concrete	yes	yes	yes	yes	yes	yes	yes
360	7320	1	0	008B		Basement Boy's Restroom	W1	Flaking	yes	yes	yes	yes	yes	yes	yes
361	7320	1	0	008B		Basement Boy's Restroom	W2	Flaking	yes	yes	yes	yes	yes	yes	yes
362	7320	1	0	008B		Basement Boy's Restroom	W3	Flaking	yes	yes	yes	yes	yes	yes	yes
363	7320	1	0	008B		Basement Boy's Restroom	W4	Flaking	yes	yes	yes	yes	yes	yes	yes
364	7320	1	0	003B		Basement Girl's Restroom	W1	Flaking duct and wall	yes	yes	yes	yes	yes	yes	yes
365	7320	1	0	003B		Basement Girl's Restroom	W2	Chipping pipe flaking wall	yes	yes	yes	yes	yes	yes	yes
366	7320	1	0	003B		Basement Girl's Restroom	W3	Cracked and flaking brick wall	yes	yes	yes	yes	yes	yes	yes
367	7320	1	0	003B		Basement Girl's Restroom	W4	Chipped pipe flaking wall	yes	yes	yes	yes	yes	yes	yes
368	7320	1	0	H01		Basement Main Hallway	Ceiling	Flaking ceiling and duct	yes	yes	yes	yes	yes	yes	yes
369	7320	1	0	H01		Basement Main Hallway	Floor	Chipping floor grate	yes	yes	yes	yes	yes	yes	yes
370	7320	1	0	H01		Basement Main Hallway	W1	Chipping baseboard, flaking wall	yes	yes	yes	yes	yes	yes	yes
371	7320	1	0	H01		Basement Main Hallway	W2	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
372	7320	1	0	H01		Basement Main Hallway	W3	Chipping baseboard, flaking wall	yes	yes	yes	yes	yes	yes	yes
373	7320	1	0	H01		Basement Main Hallway	W4	Chipping baseboard, flaking wall	yes	yes	yes	yes	yes	yes	yes
374	7320	1	0	S09		Basement Stairwell Grange Avenue	Floor	Chipping stair and rails	yes	yes	yes	yes	yes	yes	yes
375	7320	1	0	S09		Basement Stairwell Grange Avenue	W1	Cracking, chipping wall and radiator, flaking	yes	yes	yes	yes	yes	yes	yes
376	7320	1	0	S09		Basement Stairwell Grange Avenue	W2	Cracking, chipping, chipping door, holes	yes	yes	yes	yes	yes	yes	yes
377	7320	1	0	S09		Basement Stairwell Grange Avenue	W3	Cracking, chipping radiators, staple holes	yes	yes	yes	yes	yes	yes	yes
378	7320	1	0	S09		Basement Stairwell Grange Avenue	W4	Chipping door	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorsence, significant mositure damage)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification
379	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Ceiling	Flaking	yes	yes	yes	yes	yes	yes	yes
380	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	yes	yes	yes	yes	yes	yes	yes
381	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W1	Cracking, chipping, flaking	yes	yes	yes	yes	yes	yes	yes
382	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W2	Chipping door frame	yes	yes	yes	yes	yes	yes	yes
383	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W3	Chipping	yes	yes	yes	yes	yes	yes	yes
384	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W4	Chipping door and pipe, holes and flaking	yes	yes	yes	yes	yes	yes	yes
385	7320	1	0	001B		Classroom B-1	Ceiling	Chipping, flaking	yes	yes	yes	yes	yes	yes	yes
386	7320	1	0	001B		Classroom B-1	Floor	Chipping radiators	yes	yes	yes	yes	yes	yes	yes
387	7320	1	0	001B		Classroom B-1	W1	Cracking, chipping, chipping door	yes	yes	yes	yes	yes	yes	yes
388	7320	1	0	001B		Classroom B-1	W2	Cracking, flaking	yes	yes	yes	yes	yes	yes	yes
389	7320	1	0	001B		Classroom B-1	W3	Cracking, holes, flaking	yes	yes	yes	yes	yes	yes	yes
390	7320	1	0	001B		Classroom B-1	W4	Chipping fiberglass pipe	yes	yes	yes	yes	yes	yes	yes
391	7320	1	0	002B		Gymnasium	W1	Chipping on door, duct, pipe and backboard	yes	yes	yes	yes	yes	yes	yes
392	7320	1	0	002B		Gymnasium	W2	Chipping on door and backboard	yes	yes	yes	yes	yes	yes	yes
393	7320	1	0	002B		Gymnasium	W3	Cracking brick, chipping radiators	yes	yes	yes	yes	yes	yes	yes
394	7320	1	0	002B		Gymnasium	W4	Chipping radiator, pipe and door	yes	yes	yes	yes	yes	yes	yes
395	7320	1	0	002C		Gymnasium Storage Closet	W3	Chipping wall and shelf	yes	yes	yes	yes	yes	yes	yes
396	7320	1	0	H02		Hallway from Classroom B-1 to Basement Main Hallway	W2	Chipping brick wall	yes	yes	yes	yes	yes	yes	yes
397	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Ceiling	Flaking ceiling and duct	yes	yes	yes	yes	yes	yes	yes
398	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Floor	Debris	yes	yes	yes	yes	yes	yes	yes
399	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W2	Chipping baseboard, flaking brick	yes	yes	yes	yes	yes	yes	yes
400	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W3	Chipping baseboard, flaking brick	yes	yes	yes	yes	yes	yes	yes

Howe Elementary School

[illegible]

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
1	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Ceiling	Cracking, holes	Included Below		William Klinger, Field Technician	6-28-19
2	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Floor	N/A	Included Below		William Klinger, Field Technician	6-28-19
3	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W1	Cracking, chipping wall and gate, holes	RRP 5		William Klinger, Field Technician	6-28-19
4	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W2	Cracking, chipping, holes	RRP 5		William Klinger, Field Technician	6-28-19
5	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W3	Cracking	RRP 5		William Klinger, Field Technician	6-28-19
6	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W4	N/A	RRP 5		William Klinger, Field Technician	6-28-19
7	7320	1	3	316		Classroom 16	Ceiling	Flaking windows	Included with Wall 3		William Klinger, Field Technician	6-28-19
8	7320	1	3	316		Classroom 16	Floor	Debris	Included with Wall 3		William Klinger, Field Technician	6-28-19
9	7320	1	3	316		Classroom 16	W1	Cracking, chipping, holes	RRP-5; Colormetric-1		William Klinger, Field Technician	6-28-19
10	7320	1	3	316		Classroom 16	W2	Cracking	RRP 4		William Klinger, Field Technician	6-28-19
11	7320	1	3	316		Classroom 16	W3	Cracking, Flaking wall and radiator, efflorescence	RRP-10; Colormetric-2; and FAAS-2	37 ug/ft2 and < 10 ug/ft2	William Klinger, Field Technician	6-28-19
12	7320	1	3	316		Classroom 16	W4	Flaking	RRP 4		William Klinger, Field Technician	6-28-19
13	7320	1	3	316C		Classroom 16 Coat Closet	Ceiling	Flaking	RRP-2; Colormetric-1		William Klinger, Field Technician	6-28-19
14	7320	1	3	316C		Classroom 16 Coat Closet	Floor	Debris	Included with Ceiling Area		William Klinger, Field Technician	6-28-19
15	7320	1	3	316C		Classroom 16 Coat Closet	W3	Cracking, chipping, flaking	Included with Ceiling Area		William Klinger, Field Technician	6-28-19
16	7320	1	3	316C		Classroom 16 Coat Closet	W4	Flaking	Included with Ceiling Area		William Klinger, Field Technician	6-28-19
17	7320	1	3	317		Classroom 17	Ceiling	Flaking by windows	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-28-19
18	7320	1	3	317		Classroom 17	W1	Chipping, staples holes, holes, flaking	RRP 5		Lou DiMichele, Industrial Hygienist	5-28-19
19	7320	1	3	317		Classroom 17	W2	Chipping	RRP 4		Lou DiMichele, Industrial Hygienist	5-28-19
20	7320	1	3	317		Classroom 17	W3	Cracking, holes, flaking, flaking radiators spalling	RRP 5		Lou DiMichele, Industrial Hygienist	5-28-19
21	7320	1	3	317		Classroom 17	W4	Cracking, staple holes	RRP 4		Lou DiMichele, Industrial Hygienist	5-28-19
22	7320	1	3	317B		Classroom 17 Coat Closet	W3	Cracking, chipping	RRP 1		Lou DiMichele, Industrial Hygienist	5-28-19
23	7320	1	3	318		Classroom 18	Ceiling	Flaking by windows	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-28-19
24	7320	1	3	318		Classroom 18	Floor	Debris	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-28-19
25	7320	1	3	318		Classroom 18	W1	Chipping door frame	RRP 4		Lou DiMichele, Industrial Hygienist	5-28-19
26	7320	1	3	318		Classroom 18	W2	Efflorescence by partition pocket	RRP 4		Lou DiMichele, Industrial Hygienist	5-28-19
27	7320	1	3	318		Classroom 18	W3	Chipping radiator, holes, spalling	RRP 4		Lou DiMichele, Industrial Hygienist	5-28-19
28	7320	1	3	318		Classroom 18	W4	Cracking	RRP 4		Lou DiMichele, Industrial Hygienist	5-28-19
29	7320	1	3	318C		Classroom 18 Coat Closet	Ceiling	No Access	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5-28-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
30	7320	1	3	318C		Classroom 18 Coat Closet	Floor	No Access	RRP 2		Lou DiMichele, Industrial Hygienist	5-28-19
31	7320	1	3	318C		Classroom 18 Coat Closet	W1	No Access	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5-28-19
32	7320	1	3	318C		Classroom 18 Coat Closet	W2	No Access	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5-28-19
33	7320	1	3	318C		Classroom 18 Coat Closet	W3	No Access	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5-28-19
34	7320	1	3	318C		Classroom 18 Coat Closet	W4	No Access	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5-28-19
35	7320	1	3	318A		Classroom 18 Storage Closet	Ceiling	No Access	RRP 1		Lou DiMichele, Industrial Hygienist	5-28-19
36	7320	1	3	318B		Classroom 18 Storage Closet	Floor	No Access	RRP 1		Lou DiMichele, Industrial Hygienist	5-28-19
37	7320	1	3	318A		Classroom 18 Storage Closet	W1	No Access	Included with Ceiling Area		William Klinger, Field Technician	5-28-19
38	7320	1	3	318A		Classroom 18 Storage Closet	W2	No Access	Included with Ceiling Area		William Klinger, Field Technician	5-28-19
39	7320	1	3	318A		Classroom 18 Storage Closet	W3	No Access	Included with Ceiling Area		William Klinger, Field Technician	5-28-19
40	7320	1	3	318A		Classroom 18 Storage Closet	W4	No Access	Included with Ceiling Area		William Klinger, Field Technician	5-28-19
41	7320	1	3	319		Classroom 19	Ceiling	Flaking by windows	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-28-19
42	7320	1	3	319		Classroom 19	Floor	Debris	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-28-19
43	7320	1	3	319		Classroom 19	W1	Flaking	RRP 5		Lou DiMichele, Industrial Hygienist	5-28-19
44	7320	1	3	319		Classroom 19	W3	Cracking, staple holes, flaking	RRP 5		Lou DiMichele, Industrial Hygienist	5-28-19
45	7320	1	3	319		Classroom 19	W4	Cracking, flaking	RRP 4		Lou DiMichele, Industrial Hygienist	5-28-19
46	7320	1	3	319B		Classroom 19 Coat Closet	W3	Cracking	RRP 1		Lou DiMichele, Industrial Hygienist	5-28-19
47	7320	1	3	319B		Classroom 19 Coat Closet	W4	Cracking	RRP 1		Lou DiMichele, Industrial Hygienist	5-28-19
48	7320	1	3	320		Classroom 20	Ceiling	Holes, flaking	Included with Wall 3		William Klinger, Field Technician	6-17-19
49	7320	1	3	320		Classroom 20	Floor	Debris	Included with Wall 3		William Klinger, Field Technician	6-17-19
50	7320	1	3	320		Classroom 20	W1	Gouges, flaking	RRP 5		William Klinger, Field Technician	6-17-19
51	7320	1	3	320		Classroom 20	W3	Chipping, holes by radiators, flaking	RRP 5		William Klinger, Field Technician	6-17-19
52	7320	1	3	320B		Classroom 20 Coat Closet	W3	Cracking	RRP 1		William Klinger, Field Technician	6-17-19
53	7320	1	3	321		Classroom 21	Ceiling	Holes, flaking	Included with Wall 3	N/A	Lou DiMichele, Industrial Hygienist	5-13-19
54	7320	1	3	321		Classroom 21	Floor	Debris	Included with Wall 3	N/A	Lou DiMichele, Industrial Hygienist	5-13-19
55	7320	1	3	321		Classroom 21	W1	Chipping, flaking	RRP-8, Colorimetric-2, and FAAS-2	42 ug/ft2 and < 10 ug/ft2	Lou DiMichele, Industrial Hygienist	5-13-19
56	7320	1	3	321		Classroom 21	W3	Chipping radiators, flaking, efflorescence	RRP 4		Lou DiMichele, Industrial Hygienist	5-13-19
57	7320	1	3	321		Classroom 21	W4	Holes, flaking	RRP-4 and Colorimetric-1		Lou DiMichele, Industrial Hygienist	5-13-19
58	7320	1	3	321B		Classroom 21 Coat Closet	W3	Cracking	RRP-1 and Colorimetric-1		Lou DiMichele, Industrial Hygienist	5-13-19
59	7320	1	3	321A		Classroom 21 Storage Closet	Ceiling	No Access	N/A No Paint/All Wood		Lou DiMichele, Industrial Hygienist	5-13-19
60	7320	1	3	321A		Classroom 21 Storage Closet	Floor	No Access	N/A No Paint/All Wood		Lou DiMichele, Industrial Hygienist	5-13-19
61	7320	1	3	321A		Classroom 21 Storage Closet	W1	No Access	N/A No Paint/All Wood		Lou DiMichele, Industrial Hygienist	5-13-19
62	7320	1	3	321A		Classroom 21 Storage Closet	W2	No Access	N/A No Paint/All Wood		Lou DiMichele, Industrial Hygienist	5-13-19
63	7320	1	3	321A		Classroom 21 Storage Closet	W3	No Access	N/A No Paint/All Wood		Lou DiMichele, Industrial Hygienist	5-13-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
64	7320	1	3	321A		Classroom 21 Storage Closet	W4	No Access	N/A No Paint/All Wood		Lou DiMichele, Industrial Hygienist	5-13-19
65	7320	1	3	322		Classroom 22	Ceiling	Holes, flaking by windows	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-20-19
66	7320	1	3	322		Classroom 22	Floor	Debris	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-20-19
67	7320	1	3	322		Classroom 22	W1	Cracking, chipping, staple holes	RRP 4		Lou DiMichele, Industrial Hygienist	5-20-19
68	7320	1	3	322		Classroom 22	W2	Spalling, efflorescence	RRP 4		Lou DiMichele, Industrial Hygienist	5-20-19
69	7320	1	3	322		Classroom 22	W3	Holes, spalling, efflorescence	RRP 4		Lou DiMichele, Industrial Hygienist	5-20-19
70	7320	1	3	322C		Classroom 22 Coat Closet	W2	Cracking	RRP 1		Lou DiMichele, Industrial Hygienist	5-20-19
71	7320	1	3	322C		Classroom 22 Coat Closet	W3	Cracking, chipping	RRP 1		Lou DiMichele, Industrial Hygienist	5-20-19
72	7320	1	3	325		Classroom 23	Ceiling	Flaking by windows	Included with Wall 3		Lou DiMichele, Industrial Hygienist	
73	7320	1	3	325		Classroom 23	Floor	Debris	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-20-19
74	7320	1	3	325		Classroom 23	W1	Chipping, holes	RRP 5		Lou DiMichele, Industrial Hygienist	5-20-19
75	7320	1	3	325		Classroom 23	W3	Chipping radiators, flaking, holes above radiators	RRP 5		Lou DiMichele, Industrial Hygienist	5-20-19
76	7320	1	3	325C		Classroom 23 Coat Closet	Ceiling	Holes	RRP 1		Lou DiMichele, Industrial Hygienist	5-20-19
77	7320	1	3	325C		Classroom 23 Coat Closet	W3	Cracking, chipping, flaking	RRP 1		Lou DiMichele, Industrial Hygienist	5-20-19
78	7320	1	3	323		Classroom 24	Floor	Debris	Included Below		Lou DiMichele, Industrial Hygienist	5-20-19
79	7320	1	3	323		Classroom 24	W1	Chipping, Hole, Flaking	RRP-4 and Colorimetric-1		Lou DiMichele, Industrial Hygienist	5-20-19
80	7320	1	3	323		Classroom 24	W2	Chipping, Flaking	RRP 2		Lou DiMichele, Industrial Hygienist	5-20-19
81	7320	1	3	323		Classroom 24	W3	Cracking, flaking	RRP-4, Colorimetric-1, and FAAS-1	<10 ug/ft2	Lou DiMichele, Industrial Hygienist	5-20-19
82	7320	1	3	323		Classroom 24	W4	Flaking wall, radiator, efflorescence	RRP 2		Lou DiMichele, Industrial Hygienist	5-20-19
83	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W2	Chipping, flaking	RRP 3		William Klinger, Field Technician	7-3-19
84	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W3	Chipping radiators	RRP 3		William Klinger, Field Technician	7-3-19
85	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W4	Cracking, flaking	RRP 3		William Klinger, Field Technician	7-3-19
86	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W3	Chipping	RRP 2		William Klinger, Field Technician	7-3-19
87	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W4	Chipping, flaking	RRP 2		William Klinger, Field Technician	7-3-19
88	7320	1	3	316A		Men and Women's Staff Restroom	W2	Cracking, holes	RRP 2		William Klinger, Field Technician	7-1-19
89	7320	1	3	316A		Men and Women's Staff Restroom	W4	Cracking, holes, flaking	RRP 2		William Klinger, Field Technician	7-1-19
90	7320	1	3	323A		Office Next to Classroom 23	Ceiling	Cracking, flaking	Included Below		William Klinger, Field Technician	5-20-19
91	7320	1	3	323A		Office Next to Classroom 23	Floor	Debris	RRP 2		Lou DiMichele, Industrial Hygienist	5/20/19
92	7320	1	3	323A		Office Next to Classroom 23	W1	Cracking, holes	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5/20/19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
93	7320	1	3	323A		Office Next to Classroom 23	W2	Cracking, flaking	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5/20/19
94	7320	1	3	323A		Office Next to Classroom 23	W3	Cracking, chipping radiators, holes	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5/20/19
95	7320	1	3	323A		Office Next to Classroom 23	W4	Flaking	Included with Floor Area		Lou DiMichele, Industrial Hygienist	5/20/19
96	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	Floor	Chipping stair face	RRP 1		William Klinger, Field Technician	6-27-19
97	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	W3	Chipping, flaking	RRP 2		William Klinger, Field Technician	6-27-19
98	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	Floor	Debris	RRP 5		William Klinger, Field Technician	6-25-19
99	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W1	Holes	Included with Floor Area		William Klinger, Field Technician	6-25-19
100	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W2	Cracking, holes	Included with Floor Area		William Klinger, Field Technician	6-25-19
101	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W3	Chipping radiators, holes by windows	Included with Floor Area		William Klinger, Field Technician	6-25-19
102	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W4	Cracking, spalling	Included with Floor Area		William Klinger, Field Technician	6-25-19
103	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W1	Chipping door	RRP 3		William Klinger, Field Technician	6-25-19
104	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W3	Flaking iron bars	RRP 3		William Klinger, Field Technician	6-25-19
105	7320	1	3	H313		Third Floor Main Hallway	W1	Chipping, holes, flaking radiators	RRP 8		William Klinger, Field Technician	6-25-19
106	7320	1	3	H313		Third Floor Main Hallway	W3	Chipping wall and radiators, holes, staple holes, flaking,	RRP 8		William Klinger, Field Technician	6-25-19
107	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W3	Chipping door	RRP 4		William Klinger, Field Technician	6-25-19
108	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W4	Flaking window frame	RRP 4		William Klinger, Field Technician	6-25-19
109	7320	1	3	324A		Women's Staff Restroom	W1	Chipping	RRP 3		William Klinger, Field Technician	6-26-19
110	7320	1	3	324A		Women's Staff Restroom	W2	Flaking	RRP 3		William Klinger, Field Technician	6-26-19
111	7320	1	3	324A		Women's Staff Restroom	W4	Cracking, flaking	RRP 3		William Klinger, Field Technician	6-26-19
112	7320	1	2	210		Classroom 10	Ceiling	Holes, flaking	Included with Wall 3		William Klinger, Field Technician	6-24-19
113	7320	1	2	210		Classroom 10	Floor	Debris	Included with Wall 3		William Klinger, Field Technician	6-24-19
114	7320	1	2	210		Classroom 10	W1	Cracking, chipping, staple holes, flaking	RRP 5		William Klinger, Field Technician	6-24-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
115	7320	1	2	210		Classroom 10	W3	Chipping radiators, holes, flaking, efflorescence	RRP 5		William Klinger, Field Technician	6-24-19
116	7320	1	2	210		Classroom 10	W4	Cracking, holes, flaking	RRP 4		William Klinger, Field Technician	6-24-19
117	7320	1	2	210C		Classroom 10 Coat Closet	W3	Cracking, chipping, flaking	RRP 1		William Klinger, Field Technician	6-24-19
118	7320	1	2	211		Classroom 11	Ceiling	Holes, flaking	Included with Wall 3		Nicholas Volpe, Field Technician	6-7-19
119	7320	1	2	211		Classroom 11	W1	Cracking, chipping, holes, flaking	RRP 5		Nicholas Volpe, Field Technician	6-7-19
120	7320	1	2	211		Classroom 11	W3	Cracking, chipping wall, radiator and pipe, holes, flaking	RRP 5		Nicholas Volpe, Field Technician	6-7-19
121	7320	1	2	211		Classroom 11	W4	Chipping	RRP 4		Nicholas Volpe, Field Technician	6-7-19
122	7320	1	2	211B		Classroom 11 Coat Closet	W3	Cracking, gouges	RRP 1		Nicholas Volpe, Field Technician	6-7-19
123	7320	1	2	212		Classroom 12	Ceiling	Flaking	Included with Wall 3		Nicholas Volpe, Field Technician	6-7-19
124	7320	1	2	212		Classroom 12	Floor	Debris	Included with Wall 3		Nicholas Volpe, Field Technician	6-7-19
125	7320	1	2	212		Classroom 12	W1	Cracking, chipping, holes, flaking	RRP-5 and Colorimetric-1		Nicholas Volpe, Field Technician	6-7-19
126	7320	1	2	212		Classroom 12	W3	Chipping radiator and pipe, flaking, efflorescence	RRP-5, Colorimetric-1, and FAAS-1	<10 ug/ft2	Nicholas Volpe, Field Technician	6-7-19
127	7320	1	2	212		Classroom 12	W4	Flaking	RRP 4		Nicholas Volpe, Field Technician	6-7-19
128	7320	1	2	212B		Classroom 12 Coat Closet	W3	Cracking, flaking	RRP 1		Nicholas Volpe, Field Technician	6-7-19
129	7320	1	2	15		Classroom 15	Ceiling	Flaking	Included with Wall 3		Nicholas Volpe, Field Technician	5-31-19
130	7320	1	2	15		Classroom 15	Floor	Debris	Included with Wall 3		Nicholas Volpe, Field Technician	5-31-19
131	7320	1	2	15		Classroom 15	W1	Cracking, chipping, staple holes, flaking	RRP 5		Nicholas Volpe, Field Technician	5-31-19
132	7320	1	2	15		Classroom 15	W2	Cracking, staple holes	RRP 4		Nicholas Volpe, Field Technician	5-31-19
133	7320	1	2	15		Classroom 15	W3	Chipping raditors, holes, flaking, efflorescence	RRP 5		Nicholas Volpe, Field Technician	5-31-19
134	7320	1	2	15		Classroom 15	W4	Gouges, staple holes	RRP 4		Nicholas Volpe, Field Technician	5-31-19
135	7320	1	2	15B		Classroom 15 Coat Closet	W2	Cracking	RRP 1		Nicholas Volpe, Field Technician	5-31-19
136	7320	1	2	15B		Classroom 15 Coat Closet	W3	Cracking, holes, flaking	RRP 1		Nicholas Volpe, Field Technician	5-31-19
137	7320	1	2	208		Classroom 8	Floor	Debris	Included with Wall 3		Nicholas Volpe, Field Technician	5-31-19
138	7320	1	2	208		Classroom 8	W1	Cracking, chipping, holes	RRP-5 and Colorimetric-1		Nicholas Volpe, Field Technician	5-31-19
139	7320	1	2	208		Classroom 8	W2	Chipping, staples holes	RRP 4		Nicholas Volpe, Field Technician	5-31-19
140	7320	1	2	208		Classroom 8	W3	Chipping pipe and radiator, holes, flaking	RRP-10, Colorimetric-2, and FAAS-2	35 ug/ft2 and < 10 ug/ft2	Nicholas Volpe, Field Technician	5-31-19
141	7320	1	2	208		Classroom 8	W4	Flaking	RRP 4		Nicholas Volpe, Field Technician	5-31-19
142	7320	1	2	208B		Classroom 8 Coat Closet	W2	Chipping, flaking	RRP-1 and Colorimetric-1		Nicholas Volpe, Field Technician	5-31-19
143	7320	1	2	208B		Classroom 8 Coat Closet	W3	Chipping	RRP 1		Nicholas Volpe, Field Technician	5-31-19
144	7320	1	2	206		Classroom 9	Ceiling	Chipping, flaking	Included with Wall 3		Nicholas Volpe, Field Technician	5-31-19
145	7320	1	2	206		Classroom 9	Floor	Debris	Included with Wall 3		Nicholas Volpe, Field Technician	5-31-19
146	7320	1	2	206		Classroom 9	W1	Chipping, holes, staple holes, flaking	RRP 5		Nicholas Volpe, Field Technician	5-31-19
147	7320	1	2	206		Classroom 9	W2	Staple holes	RRP 4		Nicholas Volpe, Field Technician	5-31-19
148	7320	1	2	206		Classroom 9	W3	Cracking, chipping wall and pipe, holes, flaking, efflorescence	RRP 5		Nicholas Volpe, Field Technician	5-31-19
149	7320	1	2	206		Classroom 9	W4	Chipping, staples holes, flaking	RRP 4		Nicholas Volpe, Field Technician	5-31-19
150	7320	1	2	206B		Classroom 9 Coat Closet	W3	Cracking	RRP 1		Nicholas Volpe, Field Technician	5-31-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
151	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W2	Holes, staple holes, flaking	RRP 4		Nicholas Volpe, Field Technician	5-31-19
152	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W3	Chipping	RRP 4		Nicholas Volpe, Field Technician	6-7-19
153	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W4	Staple holes	RRP 4		Nicholas Volpe, Field Technician	6-7-19
154	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Ceiling	Cracking, flaking	Included with Walls		Nicholas Volpe, Field Technician	6-7-19
155	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Floor	Debris	Included with Walls		Nicholas Volpe, Field Technician	6-7-19
156	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W2	Cracking, chipping, holes, flaking	RRP 4		Nicholas Volpe, Field Technician	6-7-19
157	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W3	Chipping radiator, flaking pipe, flaking, efflorescence	RRP 1		Nicholas Volpe, Field Technician	6-7-19
158	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W4	Cracking	RRP 4		Nicholas Volpe, Field Technician	6-7-19
159	7320	1	2	213		IMC Library	Ceiling	Holes, flaking	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-8-19
160	7320	1	2	213		IMC Library	Floor	Debris	Included with Wall 3		Lou DiMichele, Industrial Hygienist	5-8-19
161	7320	1	2	213		IMC Library	W1	Cracking, chipping, holes, flaking	RRP-8 and Colorimetric-1		Lou DiMichele, Industrial Hygienist	5-8-19
162	7320	1	2	213		IMC Library	W2	Cracking, flaking	RRP 4		Lou DiMichele, Industrial Hygienist	5-8-19
163	7320	1	2	213		IMC Library	W3	Chipping radiators, holes, spalling, efflorescence	RRP-8, Colorimetric-1, and FAAS-1	11 ug/ft2	Lou DiMichele, Industrial Hygienist	5-8-19
164	7320	1	2	213		IMC Library	W4	Chipping	RRP 4		Lou DiMichele, Industrial Hygienist	5-8-19
165	7320	1	2	213B		IMC Library Book Storage Closet	W3	Cracking	RRP 4		Lou DiMichele, Industrial Hygienist	5-8-19
166	7320	1	2	213C		IMC Library Book Storage Closet	W4	N/A	RRP 1		Lou DiMichele, Industrial Hygienist	5-8-19
167	7320	1	2	214B		Men's Staff Restroom	W4	Flaking	RRP 4		William Klinger, Field Technician	6-21-19
168	7320	1	2	215C		Room within Teacher's Lounge	Ceiling	No Access	Included Below		William Klinger, Field Technician	6-22-19
169	7320	1	2	215C		Room within Teacher's Lounge	Floor	No Access	Included Below		William Klinger, Field Technician	6-22-19
170	7320	1	2	215C		Room within Teacher's Lounge	W1	No Access	RRP 1		William Klinger, Field Technician	6-22-19
171	7320	1	2	215C		Room within Teacher's Lounge	W2	No Access	RRP 1		William Klinger, Field Technician	6-22-19
172	7320	1	2	215C		Room within Teacher's Lounge	W3	No Access	RRP 1		William Klinger, Field Technician	6-22-19
173	7320	1	2	215C		Room within Teacher's Lounge	W4	No Access	RRP 1		William Klinger, Field Technician	6-22-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
174	7320	1	2	H29		Second Floor Main Hallway	W1	Chipping metal pipe, staple holes, flaking	RRP 15		William Klinger, Field Technician	6-20-19
175	7320	1	2	H29		Second Floor Main Hallway	W3	Cracking, chipping wall and radiator, holes, staple holes	RRP 15		William Klinger, Field Technician	6-20-19
176	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W3	Chipping door and bars	RRP 9		William Klinger, Field Technician	6-20-19
177	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W4	Chipping windows	RRP 9		William Klinger, Field Technician	6-20-19
178	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Ceiling	No Access	Included Below		William Klinger, Field Technician	6-20-19
179	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Floor	No Access	Included Below		William Klinger, Field Technician	6-20-19
180	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W1	No Access	RRP 1		William Klinger, Field Technician	6-20-19
181	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W2	No Access	RRP 1		William Klinger, Field Technician	6-20-19
182	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W3	No Access	RRP 1		William Klinger, Field Technician	6-20-19
183	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W4	No Access	RRP 1		William Klinger, Field Technician	6-20-19
184	7320	1	2	215A		Teacher's Lounge	Floor	Debris	Included Below		William Klinger, Field Technician	6-20-19
185	7320	1	2	215A		Teacher's Lounge	W1	Chipping	RRP 2		William Klinger, Field Technician	6-20-19
186	7320	1	2	215A		Teacher's Lounge	W2	Cracking	RRP 2		William Klinger, Field Technician	6-20-19
187	7320	1	2	215A		Teacher's Lounge	W3	Cracking, flaking	RRP 2		William Klinger, Field Technician	6-20-19
188	7320	1	2	215A		Teacher's Lounge	W4	Chipping radiators, flaking	RRP 2		William Klinger, Field Technician	6-20-19
189	7320	1	2	215D		Teacher's Lounge Kitchen	W1	Chipping built-in shelves, chipping baseboard, holes, flaking	RRP 2		William Klinger, Field Technician	6-20-19
190	7320	1	2	215D		Teacher's Lounge Kitchen	W2	Cracking, chipping baseboard, holes	RRP 2		William Klinger, Field Technician	6-20-19
191	7320	1	2	215D		Teacher's Lounge Kitchen	W3	Chipping baseboard	RRP 2		William Klinger, Field Technician	6-20-19
192	7320	1	2	215D		Teacher's Lounge Kitchen	W4	Chipping baseboard	RRP 2		William Klinger, Field Technician	6-20-19
193	7320	1	2	214A		Women's Staff Restroom	W1	Chipping	RRP 3		William Klinger, Field Technician	6-20-19
194	7320	1	2	214A		Women's Staff Restroom	W2	Holes	RRP 3		William Klinger, Field Technician	6-20-19
195	7320	1	2	214A		Women's Staff Restroom	W3	Chipping metal pipe	RRP 3		William Klinger, Field Technician	6-20-19
196	7320	2	1	101C		Cafeteria	Ceiling	Flaking, efflorescence	Included Below		William Klinger, Field Technician	6-20-19
197	7320	2	1	101C		Cafeteria	W1	Cracking, chipping wall and door, flaking	RRP-8, Colorimetric-1, and FAAS-1	13 ug/ft2	William Klinger, Field Technician	7-12-19
198	7320	2	1	101C		Cafeteria	W2	Cracking	RRP 8		William Klinger, Field Technician	7-12-19
199	7320	2	1	101C		Cafeteria	W3	Chipping door	RRP-8 and Colorimetric-1		William Klinger, Field Technician	7-12-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
200	7320	2	1	101C		Cafeteria	W4	Cracking	RRP-8 and Colorimetric-1		William Klinger, Field Technician	7-12-19
201	7320	1	1	101		Classroom 1	Ceiling	Flaking	Included Below		William Klinger, Field Technician	6-17-19
202	7320	1	1	101		Classroom 1	W1	Cracking, chipping, chipping door, holes	RRP 5		William Klinger, Field Technician	6-17-19
203	7320	1	1	101		Classroom 1	W2	Chipping	RRP-4, Colorimetric-1, and FAAS-1	< 10 ug/ft2	William Klinger, Field Technician	6-17-19
204	7320	1	1	101		Classroom 1	W3	Chipping metal pipe, chipping, holes and efflorescence	RRP 5		William Klinger, Field Technician	6-17-19
205	7320	1	1	101		Classroom 1	W4	Cracking and chipping	RRP-4 and Colorimetric-1		William Klinger, Field Technician	6-17-19
206	7320	1	1	101D		Classroom 1 Coat Closet	W2	Chipping	RRP-1 and Colorimetric-1		William Klinger, Field Technician	6-17-19
207	7320	1	1	101D		Classroom 1 Coat Closet	W3	Cracking and chipping	RRP 1		William Klinger, Field Technician	6-17-19
208	7320	1	1	101A		Classroom 1 Restroom	W2	Flaking	RRP-1 and Colorimetric-1		William Klinger, Field Technician	6-17-19
209	7320	1	1	101A		Classroom 1 Restroom	W4	Chipping wall and radiator	RRP 1		William Klinger, Field Technician	6-17-19
210	7320	1	1	102		Classroom 2	W1	Cracking, chipping, holes, flaking	RRP-5, Colorimetric-1, and FAAS-1	< 10 ug/ft2	William Klinger, Field Technician	6-18-19
211	7320	1	1	102		Classroom 2	W3	Chipping pipe and radiator, holes and efflorescence	RRP-5 and Colorimetric-1		William Klinger, Field Technician	6-18-19
212	7320	1	1	102B		Classroom 2 Coat Closet	W3	Cracking and holes	RRP-1 and Colorimetric-1		William Klinger, Field Technician	6-18-19
213	7320	1	1	103		Classroom 3	Ceiling	Flaking	Included with Wall 3		William Klinger, Field Technician	6-20-19
214	7320	1	1	103		Classroom 3	W1	Cracking, chipping door, flaking	RRP 5		William Klinger, Field Technician	6-20-19
215	7320	1	1	103		Classroom 3	W2	Chipping and flaking	RRP-4 and Colorimetric-1		William Klinger, Field Technician	6-20-19
216	7320	1	1	103		Classroom 3	W3	Cracking, chipping, chipping radiator, flaking	RRP 5		William Klinger, Field Technician	6-20-19
217	7320	1	1	103		Classroom 3	W4	Chipping wall and metal pipe	RRP-4, Colorimetric-1, and FAAS-1	< 10 ug/ft2	William Klinger, Field Technician	6-20-19
218	7320	1	1	103C		Classroom 3 Coat Closet	Ceiling	Chipping	Included with Wall 3		William Klinger, Field Technician	6-20-19
219	7320	1	1	103C		Classroom 3 Coat Closet	Floor	Debris	Included with Wall 3		William Klinger, Field Technician	6-20-19
220	7320	1	1	103C		Classroom 3 Coat Closet	W3	Cracking, chipping, gouge, flaking	RRP-1 and Colorimetric-1		William Klinger, Field Technician	6-20-19
221	7320	1	1	103C		Classroom 3 Coat Closet	W4	Chipping	RRP 1		William Klinger, Field Technician	6-20-19
222	7320	1	1	103B		Classroom 3 Storage Closet	Ceiling	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-20-19
223	7320	1	1	103B		Classroom 3 Storage Closet	Floor	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-20-19
224	7320	1	1	103A		Classroom 3 Storage Closet	W1	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-20-19
225	7320	1	1	103A		Classroom 3 Storage Closet	W2	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-20-19
226	7320	1	1	103A		Classroom 3 Storage Closet	W3	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-20-19
227	7320	1	1	103B		Classroom 3 Storage Closet	W4	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-20-19
228	7320	1	1	104		Classroom 4	Ceiling	Holes, flaking	Included with Wall 3		William Klinger, Field Technician	6-20-19
229	7320	1	1	104		Classroom 4	Floor	Debris	Included with Wall 3		William Klinger, Field Technician	6-20-19
230	7320	1	1	104		Classroom 4	W1	Cracking, chipping	RRP 5		William Klinger, Field Technician	6-20-19
231	7320	1	1	104		Classroom 4	W2	Cracking, chipping, holes, chipping metal pipe	RRP 4		William Klinger, Field Technician	6-20-19
232	7320	1	1	104		Classroom 4	W3	cracking, chipping, holes, chipping radiator	RRP 5		William Klinger, Field Technician	6-20-19
233	7320	1	1	104		Classroom 4	W4	Cracking, holes, flaking	RRP 4		William Klinger, Field Technician	6-20-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorsence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
234	7320	1	1	104E		Classroom 4 Coat Closet	W1	N/A	RRP 1		William Klinger, Field Technician	6-20-19
235	7320	1	1	104E		Classroom 4 Coat Closet	W2	Chipping	RRP 1		William Klinger, Field Technician	6-20-19
236	7320	1	1	104E		Classroom 4 Coat Closet	W3	Cracking	RRP 1		William Klinger, Field Technician	6-20-19
237	7320	1	1	104E		Classroom 4 Coat Closet	W4	Chipping	RRP 1		William Klinger, Field Technician	6-20-19
238	7320	1	1	106		Classroom 6	Ceiling	Flaking	Included with Wall 3		William Klinger, Field Technician	6-21-19
239	7320	1	1	106		Classroom 6	W1	Chipping, flaking, chipping door	RRP-5 and Colorimetric-1		William Klinger, Field Technician	6-21-19
240	7320	1	1	106		Classroom 6	W2	Chipping	RRP 4		William Klinger, Field Technician	6-21-19
241	7320	1	1	106		Classroom 6	W3	Chipping wall, radiator, pipe and flaking	RRP-5, Colorimetric-1, and FAAS-1	< 10 ug/ft2	William Klinger, Field Technician	6-21-19
242	7320	1	1	106		Classroom 6	W4	Staple holes	RRP 4		William Klinger, Field Technician	6-21-19
243	7320	1	1	106C		Classroom 6 Coat Closet	W1	N/A	RRP 1		William Klinger, Field Technician	6-21-19
244	7320	1	1	106B		Classroom 6 Storage Closet	Ceiling	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-21-19
245	7320	1	1	106B		Classroom 6 Storage Closet	Floor	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-21-19
246	7320	1	1	106A		Classroom 6 Storage Closet	W1	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-21-19
247	7320	1	1	106A		Classroom 6 Storage Closet	W2	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-21-19
248	7320	1	1	106A		Classroom 6 Storage Closet	W3	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-21-19
249	7320	1	1	106B		Classroom 6 Storage Closet	W4	No Access	N/A No Paint/All Wood		William Klinger, Field Technician	6-21-19
250	7320	1	1	107E		Classroom 7	Ceiling	Holes, flaking	Included with Wall 3		William Klinger, Field Technician	6-21-19
251	7320	1	1	107E		Classroom 7	W1	Chipping, holes, staple holes, chipping door	RRP-5, Colorimetric-1, and FAAS-1	< 10 ug/ft2	William Klinger, Field Technician	6-19-19
252	7320	1	1	107E		Classroom 7	W2	Cracking, chipping, holes, flaking	RRP-4 and Colorimetric-1		William Klinger, Field Technician	6-19-19
253	7320	1	1	107E		Classroom 7	W3	Chipping, holes, flaking, spalling, chipping radiator	RRP 5		William Klinger, Field Technician	6-19-19
254	7320	1	1	107E		Classroom 7	W4	Cracking, chipping, flaking, chipping cabinets	RRP 4		William Klinger, Field Technician	6-19-19
255	7320	1	1	107D		Classroom 7 Coat Closet	W2	Flaking	RRP 1		William Klinger, Field Technician	6-19-19
256	7320	1	1	107D		Classroom 7 Coat Closet	W3	Cracking, flaking	RRP-1 and Colorimetric-1		William Klinger, Field Technician	6-19-19
257	7320	1	1	107C		Classroom 7 Restroom	W2	Chipping radiators	RRP-2, Colorimetric-1, and FAAS-1	12 ug/ft2	William Klinger, Field Technician	6-19-19
258	7320	1	1	107F		Classroom 7 Storage Closet	Floor	Debris	Included Below		William Klinger, Field Technician	6-19-19
259	7320	1	1	107F		Classroom 7 Storage Closet	W1	flaking	RRP 1		William Klinger, Field Technician	6-19-19
260	7320	1	1	107B		Classroom 7 Storage Closet	W2	Cracking	RRP 1		William Klinger, Field Technician	6-19-19
261	7320	1	1	105		Common Area for Conselor, Nurse, Special Education and Speech Offices	W1	Chipping	RRP 1		William Klinger, Field Technician	6-19-19
262	7320	1	1	105		Common Area for Conselor, Nurse, Special Education and Speech Offices	W2	Chipping	RRP 1		William Klinger, Field Technician	6-25-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
263	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W3	Chipping, holes	RRP 1		William Klinger, Field Technician	6-25-19
264	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W4	Chipping	RRP 1		William Klinger, Field Technician	6-25-19
265	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W1	Chipping	N/A No Paint/All Wood		William Klinger, Field Technician	6-25-19
266	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W2	Chipping	N/A No Paint/All Wood		William Klinger, Field Technician	6-25-19
267	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W3	Chipping	N/A No Paint/All Wood		William Klinger, Field Technician	6-25-19
268	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W4	Chipping	N/A No Paint/All Wood		William Klinger, Field Technician	6-25-19
269	7320	1	1	105A		Counselor's Office	Floor	Debris	Included Below		William Klinger, Field Technician	6-25-19
270	7320	1	1	105A		Counselor's Office	W1	Chipping door	RRP 2		William Klinger, Field Technician	6-25-19
271	7320	1	1	105A		Counselor's Office	W2	Chipping	RRP 2		William Klinger, Field Technician	6-25-19
272	7320	1	1	105A		Counselor's Office	W3	Chipping radiator, flaking	RRP 2		William Klinger, Field Technician	6-25-19
273	7320	1	1	105A		Counselor's Office	W4	Cracking, chipping	RRP 2		William Klinger, Field Technician	6-25-19
274	7320	1	1	H19		First Floor Main Hallway	W1	Chipping wall and pipe, holes, flaking	RRP 7		William Klinger, Field Technician	7-24-19
275	7320	1	1	H19		First Floor Main Hallway	W3	Cracking, chipping wall, metal pipe, radiator, flaking	RRP 7		William Klinger, Field Technician	7-24-19
276	7320	1	1	S17		First Floor Stairwell Grange Avenue	Ceiling	Flaking	Included Below		William Klinger, Field Technician	7-24-19
277	7320	1	1	S17		First Floor Stairwell Grange Avenue	Floor	Chipping wall and rail	Included Below		William Klinger, Field Technician	7-24-19
278	7320	1	1	S17		First Floor Stairwell Grange Avenue	W1	Chipping, flaking, holes	RRP 6		William Klinger, Field Technician	7-24-19
279	7320	1	1	S17		First Floor Stairwell Grange Avenue	W2	Chipping wall, radiator and pipe	RRP 6		William Klinger, Field Technician	7-24-19
280	7320	1	1	S17		First Floor Stairwell Grange Avenue	W3	Chipping, holes, flaking	RRP 6		William Klinger, Field Technician	7-24-19
281	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	Included Below		William Klinger, Field Technician	7-24-19
282	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W1	Chipping wall and pipe	RRP 6		William Klinger, Field Technician	7-24-19
283	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W3	Chipping, holes, flaking	RRP 6		William Klinger, Field Technician	7-24-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
284	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W4	Cracking, chipping radiators, flaking	RRP 6		William Klinger, Field Technician	7-24-19
285	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Ceiling	Cracking, flaking	Included with Walls		William Klinger, Field Technician	7-24-19
286	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Floor	Debris	Included with Walls		William Klinger, Field Technician	7-24-19
287	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W2	Cracking, chipping, chipping metal pipe, holes, flaking,	RRP 4		William Klinger, Field Technician	7-24-19
288	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W3	Chipping radiator, holes, flaking	RRP 4		William Klinger, Field Technician	7-24-19
289	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W4	Cracking, flaking	RRP 4		William Klinger, Field Technician	7-8-19
290	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W2	Cracking, holes, flaking	RRP 4		William Klinger, Field Technician	7-8-19
291	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W3	Chipping, cracking, holes	RRP 4		William Klinger, Field Technician	7-8-19
292	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W4	Cracking, chipping radiator, holes, flaking	RRP 4		William Klinger, Field Technician	7-8-19
293	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W1	Chipping door and radiator	RRP 5		William Klinger, Field Technician	7-8-19
294	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W2	Chipping radiator, door and metal pipe	RRP 5		William Klinger, Field Technician	7-8-19
295	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W3	Cracking, chipping door and radiator, flaking	RRP 5		William Klinger, Field Technician	7-8-19
296	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W4	Chipping metal pipe	RRP 5		William Klinger, Field Technician	7-8-19
297	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W1	Cracking	RRP 2		William Klinger, Field Technician	6-26-19
298	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W3	Cracking, chipping, holes	RRP 2		William Klinger, Field Technician	6-26-19
299	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W4	Chipping, holes	RRP 2		William Klinger, Field Technician	6-26-19
300	7320	1	1	S19		Main Entrance Stairwell	W1	Cracking, chipping wall and door, flaking	RRP 2		William Klinger, Field Technician	6-26-19
301	7320	1	1	107		Main Office	Ceiling	Holes, flaking	Included Below		William Klinger, Field Technician	6-26-19
302	7320	1	1	107		Main Office	W1	Chipping	RRP-1, Colorimetric-1, and FAAS-1	<10 ug/ft2	William Klinger, Field Technician	6-26-19
303	7320	1	1	107		Main Office	W2	Chipping, holes, flaking, spalling, efflorescence, chipping radiator	RRP 1		William Klinger, Field Technician	6-26-19
304	7320	1	1	107		Main Office	W3	Chipping, holes, chipping door	RRP 1		William Klinger, Field Technician	6-26-19
305	7320	1	1	107		Main Office	W4	Chipping	RRP-1 and Colorimetric-1		William Klinger, Field Technician	6-26-19
306	7320	1	1	105D		Nurse's Office	W1	Chipping, chipping door	RRP-2 and Colorimetric-1		William Klinger, Field Technician	6-26-19
307	7320	1	1	105D		Nurse's Office	W2	Cracking, chipping, flaking	RRP 2		William Klinger, Field Technician	6-7-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
308	7320	1	1	105D		Nurse's Office	W3	Chipping radiator, flaking	RRP-2, Colorimetric-1, and FAAS-1	12 ug/ft2	William Klinger, Field Technician	6-7-19
309	7320	1	1	105D		Nurse's Office	W4	Chipping	RRP 2		William Klinger, Field Technician	6-7-19
310	7320	1	1	107A		Principal's Office	W1	Cracking, chipping, chipping door	RRP 2		William Klinger, Field Technician	6-7-19
311	7320	1	1	107A		Principal's Office	W4	Holes	RRP 2		William Klinger, Field Technician	6-7-19
312	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W1	Chipping door	RRP 1		William Klinger, Field Technician	6-7-19
313	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W2	Cracking and flaking	RRP 1		William Klinger, Field Technician	6-7-19
314	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W4	Cracking	RRP 1		William Klinger, Field Technician	6-7-19
315	7320	1	1	S27		Second Floor Stairwell Grange Avenue	Floor	Chipping stairs and rails	Included Below		Nicholas Volpe, Field Technician	6-7-19
316	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W1	Cracking, chipping, staple holes, flaking	RRP 3		Nicholas Volpe, Field Technician	6-7-19
317	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W2	Chipping, flaking	RRP 3		Nicholas Volpe, Field Technician	6-7-19
318	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W3	Cracking, flaking	RRP 3		Nicholas Volpe, Field Technician	6-7-19
319	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W4	Flaking	RRP 3		Nicholas Volpe, Field Technician	6-7-19
320	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Ceiling	Cracking, flaking	Included Below		Nicholas Volpe, Field Technician	6-7-19
321	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	Included Below		Nicholas Volpe, Field Technician	6-7-19
322	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W1	Cracking, chipping, holes, staple holes	RRP 3		Nicholas Volpe, Field Technician	6-7-19
323	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W2	Chipping door	RRP 3		Nicholas Volpe, Field Technician	6-7-19
324	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W3	Chipping, flaking	RRP 3		Nicholas Volpe, Field Technician	6-7-19
325	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W4	Flaking, spalling	RRP 3		William Klinger, Field Technician	6-21-19
326	7320	1	1	105C		Special Education Office	Ceiling	Flaking	Included with Wall 3		William Klinger, Field Technician	6-21-19
327	7320	1	1	105C		Special Education Office	W2	Chipping	RRP 2		William Klinger, Field Technician	6-21-19
328	7320	1	1	105C		Special Education Office	W3	Flaking	RRP 2		William Klinger, Field Technician	6-21-19
329	7320	1	1	105B		Speech Office	W1	Cracking, flaking, holes, spalling	RRP 2		William Klinger, Field Technician	6-21-19
330	7320	1	1	105B		Speech Office	W2	Cracking, chipping, gouges, holes	RRP 2		William Klinger, Field Technician	6-21-19
331	7320	1	1	105B		Speech Office	W4	Chipping	RRP 2		William Klinger, Field Technician	6-21-19
332	7320	1	1	S110		Stairwell next to Classroom 2	Floor	Chipping hand rail	Included Below		William Klinger, Field Technician	6-21-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
333	7320	1	1	S110		Stairwell next to Classroom 2	W1	Chipping door	RRP 3		William Klinger, Field Technician	6-21-19
334	7320	1	1	S110		Stairwell next to Classroom 2	W3	Chipping door, flaking iron bars	RRP 3		William Klinger, Field Technician	6-21-19
335	7320	1	1	S110		Stairwell next to Classroom 2	W4	Chipping door	RRP 3		William Klinger, Field Technician	6-21-19
336	7320	1	1	S111		Stairwell next to Main Office	W1	Chipping door	RRP 3		William Klinger, Field Technician	6-21-19
337	7320	1	1	S111		Stairwell next to Main Office	W2	Chipping door	RRP 3		William Klinger, Field Technician	6-21-19
338	7320	1	1	S111		Stairwell next to Main Office	W3	Chipping door, flaking door, flaking iron bars	RRP 3		William Klinger, Field Technician	6-21-19
339	7320	1	1	S111		Stairwell next to Main Office	W4	Flaking iron bars	RRP 3		William Klinger, Field Technician	6-21-19
340	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	Ceiling	Cracking	Included Below		William Klinger, Field Technician	6-20-19
341	7320	1	1	104A		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W2	Cracking	RRP 2		William Klinger, Field Technician	6-20-19
342	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W3	Cracking, chipping pipe	RRP 2		William Klinger, Field Technician	6-20-19
343	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W4	Cracking, holes	RRP 2		William Klinger, Field Technician	6-20-19
344	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Ceiling	Cracking, holes, flaking	Included Below		William Klinger, Field Technician	6-20-19
345	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Floor	Debris	Included Below		William Klinger, Field Technician	6-20-19
346	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W1	Flaking	RRP 2		William Klinger, Field Technician	6-20-19
347	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W2	Cracking, holes, flaking	RRP 2		William Klinger, Field Technician	6-20-19
348	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W3	Flaking on wall and asbestos pipe	RRP 2		William Klinger, Field Technician	6-20-19
349	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W4	Flaking	RRP 2		William Klinger, Field Technician	6-20-19
350	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Ceiling	Holes	Included Below		William Klinger, Field Technician	6-20-19
351	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Floor	Debris	Included Below		William Klinger, Field Technician	6-20-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
352	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W1	Cracking, chipping wall and rails, flaking	RRP 2		William Klinger, Field Technician	6-20-19
353	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W2	Flaking	RRP 2		William Klinger, Field Technician	6-20-19
354	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W3	Cracking, holes, flaking	RRP 2		William Klinger, Field Technician	6-20-19
355	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W4	Cracking, holes, flaking	RRP 2		William Klinger, Field Technician	6-20-19
356	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	Floor	Chipping rail and flaking	Included Below		William Klinger, Field Technician	6-20-19
357	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W1	Chipping and flaking	RRP 3		William Klinger, Field Technician	6-20-19
358	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W2	Chipping door	RRP 3		William Klinger, Field Technician	6-20-19
359	7320	1	0	008B		Basement Boy's Restroom	Ceiling	Cracking, holes, flaking in concrete	Included Below		William Klinger, Field Technician	7-15-19
360	7320	1	0	008B		Basement Boy's Restroom	W1	Flaking	RRP-6, Colorimetric-1, and FAAS-1	<10 ug/ft2	William Klinger, Field Technician	7-15-19
361	7320	1	0	008B		Basement Boy's Restroom	W2	Flaking	RRP 6		William Klinger, Field Technician	7-15-19
362	7320	1	0	008B		Basement Boy's Restroom	W3	Flaking	RRP 6		William Klinger, Field Technician	7-15-19
363	7320	1	0	008B		Basement Boy's Restroom	W4	Flaking	RRP-6 and Colorimetric-1		William Klinger, Field Technician	7-15-19
364	7320	1	0	003B		Basement Girl's Restroom	W1	Flaking duct and wall	RRP 6		William Klinger, Field Technician	7-15-19
365	7320	1	0	003B		Basement Girl's Restroom	W2	Chipping pipe flaking wall	RRP 6		William Klinger, Field Technician	7-15-19
366	7320	1	0	003B		Basement Girl's Restroom	W3	Cracked and flaking brick wall	RRP-6 and Colorimetric-1		William Klinger, Field Technician	7-15-19
367	7320	1	0	003B		Basement Girl's Restroom	W4	Chipped pipe flaking wall	RRP-6, Colorimetric-1, and FAAS-1	<10 ug/ft2	William Klinger, Field Technician	7-15-19
368	7320	1	0	H01		Basement Main Hallway	Ceiling	Flaking ceiling and duct	Included Below		William Klinger, Field Technician	7-26-16
369	7320	1	0	H01		Basement Main Hallway	Floor	Chipping floor grate	Included Below		William Klinger, Field Technician	7-26-16
370	7320	1	0	H01		Basement Main Hallway	W1	Chipping baseboard, flaking wall	RRP 6		William Klinger, Field Technician	7-26-16
371	7320	1	0	H01		Basement Main Hallway	W2	Chipping, flaking	RRP 6		William Klinger, Field Technician	7-26-16
372	7320	1	0	H01		Basement Main Hallway	W3	Chipping baseboard, flaking wall	RRP 6		William Klinger, Field Technician	7-26-16
373	7320	1	0	H01		Basement Main Hallway	W4	Chipping baseboard, flaking wall	RRP 6		William Klinger, Field Technician	7-26-16
374	7320	1	0	S09		Basement Stairwell Grange Avenue	Floor	Chipping stair and rails	Included Below		William Klinger, Field Technician	7-9-19
375	7320	1	0	S09		Basement Stairwell Grange Avenue	W1	Cracking, chipping wall and radiator, flaking	RRP 2		William Klinger, Field Technician	7-9-19
376	7320	1	0	S09		Basement Stairwell Grange Avenue	W2	Cracking, chipping, chipping door, holes	RRP 2		William Klinger, Field Technician	7-9-19
377	7320	1	0	S09		Basement Stairwell Grange Avenue	W3	Cracking, chipping radiators, staple holes	RRP 2		William Klinger, Field Technician	7-9-19
378	7320	1	0	S09		Basement Stairwell Grange Avenue	W4	Chipping door	RRP 2		William Klinger, Field Technician	7-9-19

Howe Elementary School

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant mositure damage)	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
379	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Ceiling	Flaking	Included Below		William Klinger, Field Technician	7-9-19
380	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	Included Below		William Klinger, Field Technician	7-9-19
381	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W1	Cracking, chipping, flaking	RRP 2		William Klinger, Field Technician	7-9-19
382	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W2	Chipping door frame	RRP 2		William Klinger, Field Technician	7-9-19
383	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W3	Chipping	RRP 2		William Klinger, Field Technician	7-9-19
384	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W4	Chipping door and pipe, holes and flaking	RRP 2		William Klinger, Field Technician	7-19-19
385	7320	1	0	001B		Classroom B-1	Ceiling	Chipping, flaking	Included Below		William Klinger, Field Technician	7-19-19
386	7320	1	0	001B		Classroom B-1	Floor	Chipping radiators	Included Below		William Klinger, Field Technician	7-19-19
387	7320	1	0	001B		Classroom B-1	W1	Cracking, chipping, chipping door	RRP-5 and Colorimetric-1		William Klinger, Field Technician	7-19-19
388	7320	1	0	001B		Classroom B-1	W2	Cracking, flaking	RRP 5		William Klinger, Field Technician	7-19-19
389	7320	1	0	001B		Classroom B-1	W3	Cracking, holes, flaking	RRP-10, Colorimetric-2, and FAAS-2	27 ug/ft2 and	William Klinger, Field Technician	7-19-19
390	7320	1	0	001B		Classroom B-1	W4	Chipping fiberglass pipe	RRP 5		William Klinger, Field Technician	7-19-19
391	7320	1	0	002B		Gymnasium	W1	Chipping on door, duct, pipe and backboard	RRP-8, Colorimetric-1, and FAAS-1	<10 ug/ft2	William Klinger, Field Technician	7-16-19
392	7320	1	0	002B		Gymnasium	W2	Chipping on door and backboard	RRP 8		William Klinger, Field Technician	7-16-19
393	7320	1	0	002B		Gymnasium	W3	Cracking brick, chipping radiators	RRP-8 and Colorimetric-1		William Klinger, Field Technician	7-16-19
394	7320	1	0	002B		Gymnasium	W4	Chipping radiator, pipe and door	RRP-8 and Colorimetric-1		William Klinger, Field Technician	7-16-19
395	7320	1	0	002C		Gymnasium Storage Closet	W3	Chipping wall and shelf	RRP 1		William Klinger, Field Technician	7-16-19
396	7320	1	0	H02		Hallway from Classroom B-1 to Basement Main Hallway	W2	Chipping brick wall	RRP 4		William Klinger, Field Technician	7-26-19
397	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Ceiling	Flaking ceiling and duct	Included Below		William Klinger, Field Technician	7-26-19
398	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Floor	Debris	Included Below		William Klinger, Field Technician	7-26-19
399	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W2	Chipping baseboard, flaking brick	RRP 2		William Klinger, Field Technician	7-26-19
400	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W3	Chipping baseboard, flaking brick	RRP 2		William Klinger, Field Technician	7-26-19

Howe Elementary School

[illegible]

Appendix C. Oversight Table

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
1	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Ceiling	Cracking, holes					6-21-19	6-21-19	6-24-19	6-26-19	6-28-19	6-28-19	Included Below	Included Below	Included Below	Included Below	Included Below	
2	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Floor	N/A					6-21-19	6-21-19	6-24-19	6-26-19	6-28-19	6-28-19	Included Below	Included Below	Included Below	Included Below	Included Below	
3	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W1	Cracking, chipping wall and gate, holes					6-21-19	6-21-19	6-24-19	6-26-19	6-28-19	6-28-19	188	5	0	No	N/A	
4	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W2	Cracking, chipping, holes					6-21-19	6-21-19	6-24-19	6-26-19	6-28-19	6-28-19	188	5	0	No	N/A	
5	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W3	Cracking					6-21-19	6-21-19	6-24-19	6-26-19	6-28-19	6-28-19	188	5	0	No	N/A	
6	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W4	N/A					6-21-19	6-21-19	6-24-19	6-26-19	6-28-19	6-28-19	188	5	0	No	N/A	
7	7320	1	3	316		Classroom 16	Ceiling	Flaking windows					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
8	7320	1	3	316		Classroom 16	Floor	Debris					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
9	7320	1	3	316		Classroom 16	W1	Cracking, chipping, holes					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	180	5	1	No	N/A	
10	7320	1	3	316		Classroom 16	W2	Cracking					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	144	4	0	No	N/A	
11	7320	1	3	316		Classroom 16	W3	Cracking, Flaking wall and radiator, efflorescence					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	180	5	2	YES	37 and < 10	1st Wipe Sample failed/Recleaned/Resampled - Passed
12	7320	1	3	316		Classroom 16	W4	Flaking					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	144	4	0	No	N/A	
13	7320	1	3	316C		Classroom 16 Coat Closet	Ceiling	Flaking					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	80	2	1	No	N/A	
14	7320	1	3	316C		Classroom 16 Coat Closet	Floor	Debris					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	
15	7320	1	3	316C		Classroom 16 Coat Closet	W3	Cracking, chipping, flaking					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	
16	7320	1	3	316C		Classroom 16 Coat Closet	W4	Flaking					6-21-19	6-21-19	6-24-19	6-25-19	6-28-19	6-28-19	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	
17	7320	1	3	317		Classroom 17	Ceiling	Flaking by windows					5-17-19	5-17-19	5-20-19	5-23-19	5-28-19	5-28-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
18	7320	1	3	317		Classroom 17	W1	Chipping, staples holes, holes, flaking					5-17-19	5-17-19	5-20-19	5-23-19	5-28-19	5-28-19	180	5	0	No	N/A	
19	7320	1	3	317		Classroom 17	W2	Chipping					5-17-19	5-17-19	5-20-19	5-23-19	5-28-19	5-28-19	144	4	0	No	N/A	
20	7320	1	3	317		Classroom 17	W3	Cracking, holes, flaking, flaking radiators spalling					5-17-19	5-17-19	5-20-19	5-23-19	5-28-19	5-28-19	180	5	0	No	N/A	
21	7320	1	3	317		Classroom 17	W4	Cracking, staple holes					5-17-19	5-17-19	5-20-19	5-23-19	5-28-19	5-28-19	144	4	0	No	N/A	
22	7320	1	3	317B		Classroom 17 Coat Closet	W3	Cracking, chipping					5-17-19	5-17-19	5-20-19	5-23-19	5-28-19	5-28-19	30	1	0	No	N/A	
23	7320	1	3	318		Classroom 18	Ceiling	Flaking by windows					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
24	7320	1	3	318		Classroom 18	Floor	Debris					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
25	7320	1	3	318		Classroom 18	W1	Chipping door frame					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	168	4	0	No	N/A	
26	7320	1	3	318		Classroom 18	W2	Efflorescence by partition pocket					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	144	4	0	No	N/A	
27	7320	1	3	318		Classroom 18	W3	Chipping radiator, holes, spalling					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	168	4	0	No	N/A	
28	7320	1	3	318		Classroom 18	W4	Cracking					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	144	4	0	No	N/A	
29	7320	1	3	318C		Classroom 18 Coat Closet	Ceiling	No Access					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
30	7320	1	3	318C		Classroom 18 Coat Closet	Floor	No Access					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	80	2	0	No	N/A	
31	7320	1	3	318C		Classroom 18 Coat Closet	W1	No Access					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
32	7320	1	3	318C		Classroom 18 Coat Closet	W2	No Access					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
33	7320	1	3	318C		Classroom 18 Coat Closet	W3	No Access					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
34	7320	1	3	318C		Classroom 18 Coat Closet	W4	No Access					5-17-19	5-17-19	5-20-19	5-22-19	5-28-19	5-28-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
35	7320	1	3	318A		Classroom 18 Storage Closet	Ceiling	No Access					5-17-19	5-17-19	5-20-19	5-22-19	5-20-19	5-20-19	24	1	0	No	N/A	
36	7320	1	3	318B		Classroom 18 Storage Closet	Floor	No Access					5-17-19	5-17-19	5-20-19	5-20-19	5-20-19	5-20-19	24	1	0	No	N/A	
37	7320	1	3	318A		Classroom 18 Storage Closet	W1	No Access					5-17-19	5-17-19	5-20-19	5-20-19	5-20-19	5-20-19	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	
38	7320	1	3	318A		Classroom 18 Storage Closet	W2	No Access					5-17-19	5-17-19	5-20-19	5-20-19	5-20-19	5-20-19	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	
39	7320	1	3	318A		Classroom 18 Storage Closet	W3	No Access					5-17-19	5-17-19	5-20-19	5-20-19	5-20-19	5-20-19	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	
40	7320	1	3	318A		Classroom 18 Storage Closet	W4	No Access					5-17-19	5-17-19	5-20-19	5-20-19	5-20-19	5-20-19	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	Included with Ceiling Area	
41	7320	1	3	319		Classroom 19	Ceiling	Flaking by windows			Missing Ceiling Tile, Stained Ceiling Tile		5-17-19	5-17-19	5-17-19	5-20-19	5-28-19	5-28-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
42	7320	1	3	319		Classroom 19	Floor	Debris					5-17-19	5-17-19	5-17-19	5-20-19	5-28-19	5-28-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
43	7320	1	3	319		Classroom 19	W1	Flaking					5-17-19	5-17-19	5-17-19	5-20-19	5-28-19	5-28-19	180	5	0	No	N/A	
44	7320	1	3	319		Classroom 19	W3	Cracking, staple holes, flaking					5-17-19	5-17-19	5-17-19	5-20-19	5-28-19	5-28-19	180	5	0	No	N/A	
45	7320	1	3	319		Classroom 19	W4	Cracking, flaking					5-17-19	5-17-19	5-17-19	5-20-19	5-28-19	5-28-19	144	4	0	No	N/A	
46	7320	1	3	319B		Classroom 19 Coat Closet	W3	Cracking					5-17-19	5-17-19	5-17-19	5-20-19	5-28-19	5-28-19	40	1	0	No	N/A	
47	7320	1	3	319B		Classroom 19 Coat Closet	W4	Cracking					5-17-19	5-17-19	5-17-19	5-20-19	5-28-19	5-28-19	40	1	0	No	N/A	
48	7320	1	3	320		Classroom 20	Ceiling	Holes, flaking					6-7-19	6-7-19	6-7-19	6-11-19	6-17-19	6-17-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
49	7320	1	3	320		Classroom 20	Floor	Debris					6-7-19	6-7-19	6-7-19	6-11-19	6-17-19	6-17-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
50	7320	1	3	320		Classroom 20	W1	Gouges, flaking					6-7-19	6-7-19	6-7-19	6-11-19	6-17-19	6-17-19	180	5	0	No	N/A	
51	7320	1	3	320		Classroom 20	W3	Chipping, holes by radiators, flaking					6-7-19	6-7-19	6-7-19	6-11-19	6-17-19	6-17-19	180	5	0	No	N/A	
52	7320	1	3	320B		Classroom 20 Coat Closet	W3	Cracking					6-7-19	6-7-19	6-7-19	6-11-19	6-17-19	6-17-19	40	1	0	No	N/A	
53	7320	1	3	321		Classroom 21	Ceiling	Holes, flaking			Stained ceiling tile		5-7-19	5-6-19	5-7-19	5-9-19	5-11-19	5-13-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	3 stained ceiling tiles
54	7320	1	3	321		Classroom 21	Floor	Debris					5-7-19	5-6-19	5-7-19	5-9-19	5-11-19	5-13-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
55	7320	1	3	321		Classroom 21	W1	Chipping, flaking					5-7-19	5-6-19	5-7-19	5-9-19	5-11-19	5-13-19	156	4	2	YES	#2 and < 10	1st Wipe Sample failed/Recleaned/Resampled - Passed AAS Retest 5-10-19
56	7320	1	3	321		Classroom 21	W3	Chipping radiators, flaking, efflorescence					5-7-19	5-6-19	5-7-19	5-9-19	5-11-19	5-13-19	156	4	0	No	N/A	
57	7320	1	3	321		Classroom 21	W4	Holes, flaking					5-7-19	5-6-19	5-7-19	5-9-19	5-11-19	5-13-19	150	4	1	No	N/A	
58	7320	1	3	321B		Classroom 21 Coat Closet	W3	Cracking					5-10-19	5-10-19	5-10-19	5-10-19	5-11-19	5-13-19	40	1	1	No	N/A	
59	7320	1	3	321A		Classroom 21 Storage Closet	Ceiling	No Access					5-10-19	5-10-19	5-10-19	5-10-19	5-11-19	5-14-19	N/A	N/A	N/A	N/A	N/A	All Wood - No Paint
60	7320	1	3	321A		Classroom 21 Storage Closet	Floor	No Access					5-10-19	5-10-19	5-10-19	5-10-19	5-11-19	5-14-19	N/A	N/A	N/A	N/A	N/A	All Wood - No Paint

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
61	7320	1	3	321A		Classroom 21 Storage Closet	W1	No Access					5-10-19	5-10-19	5-10-19	5-10-19	5-11-19	5-14-19	N/A	N/A	N/A	N/A	N/A	All Wood - No Paint
62	7320	1	3	321A		Classroom 21 Storage Closet	W2	No Access					5-10-19	5-10-19	5-10-19	5-10-19	5-11-19	5-14-19	N/A	N/A	N/A	N/A	N/A	All Wood - No Paint
63	7320	1	3	321A		Classroom 21 Storage Closet	W3	No Access					5-10-19	5-10-19	5-10-19	5-10-19	5-11-19	5-14-19	N/A	N/A	N/A	N/A	N/A	All Wood - No Paint
64	7320	1	3	321A		Classroom 21 Storage Closet	W4	No Access					5-10-19	5-10-19	5-10-19	5-10-19	5-11-19	5-14-19	N/A	N/A	N/A	N/A	N/A	All Wood - No Paint
65	7320	1	3	322		Classroom 22	Ceiling	Holes, flaking by windows			Stained ceiling tile		5-10-19	5-10-19	5-13-19	5-13-19	5-20-19	5-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Stained ceiling tile
66	7320	1	3	322		Classroom 22	Floor	Debris					5-10-19	5-10-19	5-13-19	5-13-19	5-20-19	5-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	N/A
67	7320	1	3	322		Classroom 22	W1	Cracking, chipping, staple holes					5-10-19	5-10-19	5-13-19	5-13-19	5-20-19	5-20-19	168	4	0	No	N/A	
68	7320	1	3	322		Classroom 22	W2	Spalling, efflorescence					5-10-19	5-10-19	5-13-19	5-13-19	5-20-19	5-20-19	144	4	0	No	N/A	
69	7320	1	3	322		Classroom 22	W3	Holes, spalling, efflorescence					5-10-19	5-10-19	5-13-19	5-13-19	5-20-19	5-20-19	168	4	0	No	N/A	
70	7320	1	3	322C		Classroom 22 Coat Closet	W2	Cracking					5-10-19	5-10-19	5-13-19	5-13-19	5-20-19	5-20-19	40	1	0	No	N/A	
71	7320	1	3	322C		Classroom 22 Coat Closet	W3	Cracking, chipping					5-10-19	5-10-19	5-13-19	5-13-19	5-20-19	5-20-19	40	1	0	No	N/A	
72	7320	1	3	325		Classroom 23	Ceiling	Flaking by windows					5-10-19	5-10-19	5-13-19	5-14-19	5-20-19	5-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
73	7320	1	3	325		Classroom 23	Floor	Debris					5-10-19	5-10-19	5-13-19	5-14-19	5-20-19	5-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
74	7320	1	3	325		Classroom 23	W1	Chipping, holes					5-10-19	5-10-19	5-13-19	5-14-19	5-20-19	5-20-19	192	5	0	No	N/A	
75	7320	1	3	325		Classroom 23	W3	Chipping radiators, flaking, holes above radiators					5-10-19	5-10-19	5-13-19	5-14-19	5-20-19	5-20-19	192	5	0	No	N/A	
76	7320	1	3	325C		Classroom 23 Coat Closet	Ceiling	Holes					5-10-19	5-10-19	5-13-19	5-14-19	5-20-19	5-20-19	40	1	0	No	N/A	
77	7320	1	3	325C		Classroom 23 Coat Closet	W3	Cracking, chipping, flaking					5-10-19	5-10-19	5-13-19	5-14-19	5-20-19	5-20-19	40	1	0	No	N/A	
78	7320	1	3	323		Classroom 24	Floor	Debris					5-10-19	5-10-19	5-13-19	5-16-19	5-20-19	5-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
79	7320	1	3	323		Classroom 24	W1	Chipping, Hole, Flaking			Stained ceiling tile		5-10-19	5-10-19	5-13-19	5-16-19	5-20-19	5-20-19	150	4	1	No	N/A	Stained Ceiling Tile
80	7320	1	3	323		Classroom 24	W2	Chipping, Flaking					5-10-19	5-10-19	5-13-19	5-16-19	5-20-19	5-20-19	84	2	0	No	N/A	
81	7320	1	3	323		Classroom 24	W3	Cracking, flaking					5-10-19	5-10-19	5-13-19	5-16-19	5-20-19	5-20-19	150	4	1	Yes	<10	
82	7320	1	3	323		Classroom 24	W4	Flaking wall, radiator, efflorescence					5-10-19	5-10-19	5-13-19	5-16-19	5-20-19	5-20-19	84	2	0	No	N/A	
83	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W2	Chipping, flaking					6-24-19	6-24-19	6-25-19	6-26-19	7-3-19	7-3-19	120	3	0	No	N/A	
84	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W3	Chipping radiators					6-24-19	6-24-19	6-25-19	6-26-19	7-3-19	7-3-19	120	3	0	No	N/A	
85	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W4	Cracking, flaking					6-24-19	6-24-19	6-26-19	6-26-19	7-3-19	7-3-19	120	3	0	No	N/A	
86	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W3	Chipping					5-9-19	N/A	5-9-19	6-24-19	7-3-19	7-3-19	80	2	0	No	N/A	
87	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W4	Chipping, flaking					5-9-19	N/A	5-9-19	6-24-19	7-3-19	7-3-19	80	2	0	No	N/A	
88	7320	1	3	316A		Men and Women's Staff Restroom	W2	Cracking, holes					N/A	N/A	6-26-19	6-28-19	7-3-19	7-3-19	80	2	0	No	N/A	
89	7320	1	3	316A		Men and Women's Staff Restroom	W4	Cracking, holes, flaking					N/A	N/A	6-26-19	6-28-19	7-1-19	7-1-19	80	2	0	No	N/A	
90	7320	1	3	323A		Office Next to Classroom 23	Ceiling	Cracking, flaking					5-10-19	5-10-19	5-14-19	5-16-19	5-20-19	5-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
91	7320	1	3	323A		Office Next to Classroom 23	Floor	Debris					5-10-19	5-10-19	5-14-19	5-16-19	5-20-19	5-20-19	84	2	0	No	N/A	
92	7320	1	3	323A		Office Next to Classroom 23	W1	Cracking, holes					5-10-19	5-10-19	5-14-19	5-16-19	5-20-19	5-20-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/t2)	Other Notes or Comments
93	7320	1	3	323A		Office Next to Classroom 23	W2	Cracking, flaking					5-10-19	5-10-19	5-14-19	5-16-19	5-20-19	5-20-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
94	7320	1	3	323A		Office Next to Classroom 23	W3	Cracking, chipping radiators, holes					5-10-19	5-10-19	5-14-19	5-16-19	5-20-19	5-20-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
95	7320	1	3	323A		Office Next to Classroom 23	W4	Flaking					5-10-19	5-10-19	5-14-19	5-16-19	5-20-19	5-20-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
96	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	Floor	Chipping stair face					5-12-19	N/A	5-16-19	6-26-19	6-26-19	6-27-19	28	1	0	No	N/A	
97	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	W3	Chipping, flaking					5-12-19	N/A	5-16-19	6-26-19	6-26-19	6-27-19	64	2	0	No	N/A	
98	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	Floor	Debris					6-7-19	6-7-19	6-7-19	6-11-19	6-24-19	6-25-19	192	5	0	No	N/A	
99	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W1	Holes					6-7-19	6-7-19	6-7-19	6-11-19	6-20-19	6-25-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
100	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W2	Cracking, holes					6-7-19	6-7-19	6-7-19	6-11-19	6-24-19	6-25-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
101	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W3	Chipping radiators, holes by windows					6-7-19	6-7-19	6-7-19	6-11-19	6-24-19	6-25-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
102	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W4	Cracking, spalling					6-7-19	6-7-19	6-7-19	6-11-19	6-24-19	6-25-19	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	Included with Floor Area	
103	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W1	Chipping door					5-9-19	N/A	5-9-19	6-20-19	6-24-19	6-25-19	95	3	0	No	N/A	
104	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W3	Flaking iron bars					5-9-19	N/A	5-9-19	6-20-19	6-24-19	6-25-19	95	3	0	No	N/A	
105	7320	1	3	H313		Third Floor Main Hallway	W1	Chipping, holes, flaking radiators					5-9-19	N/A	5-9-19	6-24-19	6-24-19	6-24-19	312	8	0	No	N/A	
106	7320	1	3	H313		Third Floor Main Hallway	W3	Chipping wall and radiators, holes, staple holes, flaking,					5-9-19	N/A	5-9-19	6-24-19	6-24-19	6-24-19	312	8	0	No	N/A	
107	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W3	Chipping door					6-10-19	6-10-19	6-12-19	6-26-19	6-26-19	6-26-19	156	4	0	No	N/A	
108	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W4	Flaking window frame					6-10-19	6-10-19	6-12-19	6-21-19	6-26-19	6-26-19	156	4	0	No	N/A	
109	7320	1	3	324A		Women's Staff Restroom	W1	Chipping					6-17-19	6-17-19	6-18-19	6-25-19	6-26-19	6-26-19	116	3	0	No	N/A	
110	7320	1	3	324A		Women's Staff Restroom	W2	Flaking					6-17-19	6-17-19	6-18-19	6-25-19	6-26-19	6-26-19	116	3	0	No	N/A	
111	7320	1	3	324A		Women's Staff Restroom	W4	Cracking, flaking					6-17-19	6-17-19	6-17-19	6-25-19	6-26-19	6-26-19	116	3	0	No	N/A	
112	7320	1	2	210		Classroom 10	Ceiling	Holes, flaking					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-24-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
113	7320	1	2	210		Classroom 10	Floor	Debris					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-24-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
114	7320	1	2	210		Classroom 10	W1	Cracking, chipping, staple holes, flaking					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-24-19	180	5	0	No	N/A	
115	7320	1	2	210		Classroom 10	W3	Chipping radiators, holes, flaking, efflorescence					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-24-19	180	5	0	No	N/A	
116	7320	1	2	210		Classroom 10	W4	Cracking, holes, flaking					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-24-19	144	4	0	No	N/A	
117	7320	1	2	210C		Classroom 10 Coat Closet	W3	Cracking, chipping, flaking					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-24-19	40	1	0	No	N/A	

Task ID	ULCS#	Element	Factor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/f2)	Other Notes or Comments
118	7320	1	2	211		Classroom 11	Ceiling	Holes, flaking					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
119	7320	1	2	211		Classroom 11	W1	Cracking, chipping, holes, flaking					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	180	5	0	No	N/A	
120	7320	1	2	211		Classroom 11	W3	Cracking, chipping wall, radiator and pipe, holes, flaking					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	180	5	0	No	N/A	
121	7320	1	2	211		Classroom 11	W4	Chipping					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	144	4	0	No	N/A	
122	7320	1	2	211B		Classroom 11 Coat Closet	W3	Cracking, gouges					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	40	1	0	No	N/A	
123	7320	1	2	212		Classroom 12	Ceiling	Flaking					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
124	7320	1	2	212		Classroom 12	Floor	Debris					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
125	7320	1	2	212		Classroom 12	W1	Cracking, chipping, holes, flaking					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	180	5	1	No	N/A	
126	7320	1	2	212		Classroom 12	W3	Chipping radiator and pipe, flaking, efflorescence					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	180	5	1	Yes	<10	
127	7320	1	2	212		Classroom 12	W4	Flaking					5-31-19	5-31-19	6-3-19	6-5	6-8-19	6-7-19	144	4	0	No	N/A	
128	7320	1	2	212B		Classroom 12 Coat Closet	W3	Cracking, flaking					5-31-19	5-31-19	6-3-19	6-5-19	6-8-19	6-7-19	40	1	1	No	N/A	
129	7320	1	2	15		Classroom 15	Ceiling	Flaking					5-24-19	5-24-19	5-24-19	5-26-19	6-1-19	6-7-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
130	7320	1	2	15		Classroom 15	Floor	Debris					5-24-19	5-24-19	5-24-19	5-26-19	6-1-19	6-7-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
131	7320	1	2	15		Classroom 15	W1	Cracking, chipping, staple holes, flaking					5-24-19	5-25-19	5-28-19	5-29-19	6-1-19	5-31-19	180	5	0	No	N/A	
132	7320	1	2	15		Classroom 15	W2	Cracking, staple holes					5-24-19	5-25-19	5-28-19	5-29-19	6-1-19	5-31-19	144	4	0	No	N/A	
133	7320	1	2	15		Classroom 15	W3	Chipping raditors, holes, flaking, efflorescence					5-24-19	5-25-19	5-28-19	5-29-19	6-1-19	5-31-19	180	5	0	No	N/A	
134	7320	1	2	15		Classroom 15	W4	Gouges, staple holes					5-24-19	5-25-19	5-28-19	5-29-19	6-1-19	5-31-19	144	4	0	No	N/A	
135	7320	1	2	15B		Classroom 15 Coat Closet	W2	Cracking					5-24-19	5-25-19	5-28-19	5-29-19	6-1-19	5-31-19	40	1	0	No	N/A	
136	7320	1	2	15B		Classroom 15 Coat Closet	W3	Cracking, holes, flaking					5-24-19	5-25-19	5-28-19	5-29-19	6-1-19	5-31-19	40	1	0	No	N/A	
137	7320	1	2	208		Classroom 8	Floor	Debris					5-24-19	5-25-19	5-28-19	5-28-19	5-30-19	5-31-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
138	7320	1	2	208		Classroom 8	W1	Cracking, chipping, holes					5-24-19	5-25-19	5-28-19	5-28-19	5-30-19	5-31-19	180	5	1	No	N/A	
139	7320	1	2	208		Classroom 8	W2	Chipping, staples holes					5-24-19	5-25-19	5-28-19	5-28-19	5-30-19	5-31-19	144	4	0	No	N/A	
140	7320	1	2	208		Classroom 8	W3	Chipping pipe and radiator, holes, flaking					5-24-19	5-25-19	5-28-19	5-28-19	5-30-19	5-31-19	180	5	2	Yes	35 and <10	1st Wipe Sample failed/Recleaned/Resampled - Passed
141	7320	1	2	208		Classroom 8	W4	Flaking					5-24-19	5-25-19	5-28-19	5-28-19	5-30-19	5-31-19	144	4	0	No	N/A	
142	7320	1	2	208B		Classroom 8 Coat Closet	W2	Chipping, flaking					5-24-19	5-25-19	5-28-19	5-28-19	5-30-19	5-31-19	40	1	1	No	N/A	
143	7320	1	2	208B		Classroom 8 Coat Closet	W3	Chipping					5-24-19	5-25-19	5-28-19	5-28-19	5-30-19	5-31-19	40	1	0	No	N/A	
144	7320	1	2	206		Classroom 9	Ceiling	Chipping, flaking					5-25-19	5-25-19	5-28-19	5-29-19	5-31-19	5-30-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
145	7320	1	2	206		Classroom 9	Floor	Debris					5-25-19	5-25-19	5-28-19	5-29-19	5-31-19	5-30-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
146	7320	1	2	206		Classroom 9	W1	Chipping, holes, staple holes, flaking					5-25-19	5-25-19	5-28-19	5-29-19	5-31-19	5-30-19	180	5	0	No	N/A	
147	7320	1	2	206		Classroom 9	W2	Staple holes					5-25-19	5-25-19	5-28-19	5-29-19	5-31-19	5-30-19	144	4	0	No	N/A	
148	7320	1	2	206		Classroom 9	W3	Cracking, chipping wall and pipe, holes, flaking, efflorescence					5-25-19	5-25-19	5-28-19	5-29-19	5-31-19	5-30-19	180	5	0	No	N/A	
149	7320	1	2	206		Classroom 9	W4	Chipping, staples holes, flaking					5-25-19	5-25-19	5-28-19	5-29-19	5-31-19	5-30-19	144	4	0	No	N/A	
150	7320	1	2	206B		Classroom 9 Coat Closet	W3	Cracking					5-25-19	5-25-19	5-28-19	5-29-19	5-31-19	5-30-19	40	1	0	No	N/A	
151	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W2	Holes, staple holes, flaking					5-7-19	N/A	5-7-19	5-10-19	6-21-19	6-21-19	156	4	0	No	N/A	
152	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W3	Chipping					5-7-19	N/A	5-7-19	5-10-19	6-21-19	6-21-19	156	4	0	No	N/A	
153	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W4	Staple holes					5-7-19	N/A	5-8-19	5-10-19	6-21-19	6-21-19	156	4	0	No	N/A	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
154	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Ceiling	Cracking, flaking					5-8-19	N/A	5-8-19	5-10-19	6-21-19	6-21-19	Included with Walls	Included with Walls	Included with Walls	Included with Walls	Included with Walls	
155	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Floor	Debris					5-8-19	N/A	5-8-19	5-10-19	6-21-19	6-21-19	Included with Walls	Included with Walls	Included with Walls	Included with Walls	Included with Walls	
156	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W2	Cracking, chipping, holes, flaking					5-8-19	N/A	5-8-19	5-10-19	6-21-19	6-21-19	156	4	0	No	N/A	
157	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W3	Chipping radiator, flaking pipe, flaking, efflorescence					5-8-19	N/A	5-8-19	5-10-19	6-26-19	6-26-19	42	1	0	No	N/A	
158	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W4	Cracking					5-8-19	N/A	5-8-19	5-10-19	6-26-19	6-26-19	156	4	0	No	N/A	
159	7320	1	2	213		IMC Library	Ceiling	Holes, flaking					5-6-19	5-6-19	5-6-19	5-8-19	5-11-19	5-13-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Bent ceiling track ADJ to clock
160	7320	1	2	213		IMC Library	Floor	Debris					5-6-19	5-6-19	5-6-19	5-8-19	5-11-19	5-13-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
161	7320	1	2	213		IMC Library	W1	Cracking, chipping, holes, flaking					5-6-19	5-6-19	5-6-19	5-8-19	5-11-19	5-13-19	336	8	1	No	N/A	
162	7320	1	2	213		IMC Library	W2	Cracking, flaking					5-6-19	5-6-19	5-6-19	5-8-19	5-11-19	5-13-19	144	4	0	No	N/A	
163	7320	1	2	213		IMC Library	W3	Chipping radiators, holes, spalling, efflorescence					5-6-19	5-6-19	5-6-19	5-8-19	5-11-19	5-13-19	336	8	1	Yes	11	Stained ceiling tile
164	7320	1	2	213		IMC Library	W4	Chipping					5-6-19	5-6-19	5-6-19	5-8-19	5-11-19	5-13-19	144	4	0	No	N/A	
165	7320	1	2	213B		IMC Library Book Storage Closet	W3	Cracking					6-25-19	6-25-19	6-25-19	6-25-19	6-25-19	6-25-19	144	4	0	No	N/A	
166	7320	1	2	213C		IMC Library Book Storage Closet	W4	N/A					6-25-19	6-25-19	6-25-19	6-25-19	6-25-19	6-25-19	144	4	1	No	N/A	
167	7320	1	2	214B		Men's Staff Restroom	W4	Flaking					6-10-19	6-10-19	6-14-19	6-18-19	6-21-19	6-21-19	150	4	0	No	N/A	
168	7320	1	2	215C		Room within Teacher's Lounge	Ceiling	No Access					6-10-19	6-10-19	6-10-19	6-11-19	6-21-19	6-22-19	Included Below	Included Below	Included Below	Included Below	Included Below	
169	7320	1	2	215C		Room within Teacher's Lounge	Floor	No Access					6-10-19	6-10-19	6-10-19	6-11-19	6-21-19	6-22-19	Included Below	Included Below	Included Below	Included Below	Included Below	
170	7320	1	2	215C		Room within Teacher's Lounge	W1	No Access					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	30	1	0	No	N/A	Stained Ceiling tiles
171	7320	1	2	215C		Room within Teacher's Lounge	W2	No Access					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	30	1	0	No	N/A	
172	7320	1	2	215C		Room within Teacher's Lounge	W3	No Access					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	30	1	0	No	N/A	
173	7320	1	2	215C		Room within Teacher's Lounge	W4	No Access					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	30	1	0	No	N/A	
174	7320	1	2	H29		Second Floor Main Hallway	W1	Chipping metal pipe, staple holes, flaking					5-7-19	N/A	5-7-19	5-10-19	6-20-19	6-20-19	600	15	0	No	N/A	
175	7320	1	2	H29		Second Floor Main Hallway	W3	Cracking, chipping wall and radiator, holes, staple holes					5-7-19	N/A	5-7-19	5-10-19	6-20-19	6-20-19	600	15	0	No	N/A	
176	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W3	Chipping door and bars					6-23-19	N/A	6-24-19	6-26-19	6-20-19	6-20-19	351	9	0	No	N/A	
177	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W4	Chipping windows					6-23-19	N/A	6-24-19	6-26-19	6-20-19	6-20-19	351	9	0	No	N/A	
178	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Ceiling	No Access					6-15-19	6-15-19	6-17-19	6-19-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
179	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Floor	No Access					6-15-19	6-15-19	6-17-19	6-19-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
180	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W1	No Access					6-15-19	6-15-19	6-17-19	6-19-19	6-20-19	6-20-19	25	1	0	No	N/A	

Task ID	ULCS#	Element	Factor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
181	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W2	No Access					6-15-19	6-15-19	6-17-19	6-19-19	6-20-19	6-20-19	25	1	0	No	N/A	
182	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W3	No Access					6-15-19	6-15-19	6-17-19	6-19-19	6-20-19	6-20-19	25	1	0	No	N/A	
183	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W4	No Access					6-15-19	6-15-19	6-19-19	6-19-19	6-20-19	6-20-19	25	1	0	No	N/A	Stain water ceiling tile
184	7320	1	2	215A		Teacher's Lounge	Floor	Debris					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
185	7320	1	2	215A		Teacher's Lounge	W1	Chipping					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	52	2	0	No	N/A	
186	7320	1	2	215A		Teacher's Lounge	W2	Cracking					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	52	2	0	No	N/A	
187	7320	1	2	215A		Teacher's Lounge	W3	Cracking, flaking					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	52	2	0	No	N/A	
188	7320	1	2	215A		Teacher's Lounge	W4	Chipping radiators, flaking					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	52	2	0	No	N/A	
189	7320	1	2	215D		Teacher's Lounge Kitchen	W1	Chipping built-in shelves, chipping baseboard, holes, flaking					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	52	2	0	No	N/A	
190	7320	1	2	215D		Teacher's Lounge Kitchen	W2	Cracking, chipping baseboard, holes					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	52	2	0	No	N/A	
191	7320	1	2	215D		Teacher's Lounge Kitchen	W3	Chipping baseboard					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	52	2	0	No	N/A	
192	7320	1	2	215D		Teacher's Lounge Kitchen	W4	Chipping baseboard					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	52	2	0	No	N/A	
193	7320	1	2	214A		Women's Staff Restroom	W1	Chipping					6-10-19	6-10-19	6-10-19	6-11-19	6-20-19	6-20-19	120	3	0	No	N/A	
194	7320	1	2	214A		Women's Staff Restroom	W2	Holes					6-10-19	6-11-19	6-19-19	6-21-19	6-20-19	6-21-19	120	3	0	No	N/A	
195	7320	1	2	214A		Women's Staff Restroom	W3	Chipping metal pipe					6-10-19	6-11-19	6-19-19	6-21-19	6-20-19	6-21-19	120	3	0	No	N/A	
196	7320	2	1	101C		Cafeteria	Ceiling	Flaking, efflorescence					7-5-19	7-5-19	7-8-19	7-11-19	7-12-19	7-12-19	Included Below	Included Below	Included Below	Included Below	Included Below	Damaged ceiling tile
197	7320	2	1	101C		Cafeteria	W1	Cracking, chipping wall and door, flaking					7-5-19	7-5-19	7-8-19	7-11-19	7-12-19	7-12-19	300	8	1	Yes	13	
198	7320	2	1	101C		Cafeteria	W2	Cracking					7-5-19	7-5-19	7-8-19	7-11-19	7-12-19	7-12-19	300	8	0	No	N/A	
199	7320	2	1	101C		Cafeteria	W3	Chipping door					7-5-19	7-5-19	7-8-19	7-11-19	7-12-19	7-12-19	300	8	1	No	N/A	
200	7320	2	1	101C		Cafeteria	W4	Cracking					7-5-19	7-5-19	7-8-19	7-11-19	7-12-19	7-12-19	300	8	1	No	N/A	
201	7320	1	1	101		Classroom 1	Ceiling	Flaking					6-10-19	6-10-19	6-11-19	6-12-19	6-12-19	6-12-19	Included Below	Included Below	Included Below	Included Below	Included Below	
202	7320	1	1	101		Classroom 1	W1	Cracking, chipping, chipping door, holes					6-10-19	6-10-19	6-11-19	6-12-19	6-17-19	6-17-19	180	5	0	No	N/A	
203	7320	1	1	101		Classroom 1	W2	Chipping					6-10-19	6-10-19	6-11-19	6-12-19	6-17-19	6-17-19	144	4	1	Yes	<10	
204	7320	1	1	101		Classroom 1	W3	Chipping metal pipe, chipping, holes and efflorescence					6-10-19	6-10-19	6-11-19	6-12-19	6-17-19	6-17-19	180	5	0	No	N/A	
205	7320	1	1	101		Classroom 1	W4	Cracking and chipping					6-10-19	6-10-19	6-11-19	6-12-19	6-17-19	6-17-19	144	4	1	No	N/A	
206	7320	1	1	101D		Classroom 1 Coat Closet	W2	Chipping					6-10-19	6-10-19	6-11-19	6-12-19	6-17-19	6-17-19	40	1	1	No	N/A	
207	7320	1	1	101D		Classroom 1 Coat Closet	W3	Cracking and chipping					6-10-19	6-10-19	6-11-19	6-12-19	6-17-19	6-17-19	40	1	0	No	N/A	
208	7320	1	1	101A		Classroom 1 Restroom	W2	Flaking					6-10-19	6-10-19	6-11-19	6-12-19	6-17-19	6-17-19	33	1	1	No	N/A	
209	7320	1	1	101A		Classroom 1 Restroom	W4	Chipping wall and radiator					6-10-19	6-10-19	6-11-19	6-12-19	6-17-19	6-17-19	33	1	0	No	N/A	
210	7320	1	1	102		Classroom 2	W1	Cracking, chipping, holes, flaking					6-10-19	6-10-19	6-11-19	6-13-19	6-18-19	6-18-19	180	5	1	Yes	<10	
211	7320	1	1	102		Classroom 2	W3	Chipping pipe and radiator, holes and efflorescence					6-10-19	6-10-19	6-11-19	6-13-19	6-18-19	6-18-19	180	5	1	No	N/A	
212	7320	1	1	102B		Classroom 2 Coat Closet	W3	Cracking and holes					6-10-19	6-10-19	6-11-19	6-13-19	6-18-19	6-18-19	40	1	1	No	N/A	
213	7320	1	1	103		Classroom 3	Ceiling	Flaking					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
214	7320	1	1	103		Classroom 3	W1	Cracking, chipping door, flaking					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	180	5	0	No	N/A	
215	7320	1	1	103		Classroom 3	W2	Chipping and flaking					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	144	4	1	No	N/A	
216	7320	1	1	103		Classroom 3	W3	Cracking, chipping, chipping radiator, flaking					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	180	5	0	No	N/A	
217	7320	1	1	103		Classroom 3	W4	Chipping wall and metal pipe					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	144	4	1	Yes	<10	
218	7320	1	1	103C		Classroom 3 Coat Closet	Ceiling	Chipping					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/f2)	Other Notes or Comments
219	7320	1	1	103C		Classroom 3 Coat Closet	Floor	Debris					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
220	7320	1	1	103C		Classroom 3 Coat Closet	W3	Cracking, chipping, gouge, flaking					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	40	1	1	No	N/A	
221	7320	1	1	103C		Classroom 3 Coat Closet	W4	Chipping					6-11-19	6-11-19	6-12-19	6-14-19	6-20-19	6-20-19	40	1	0	No	N/A	
222	7320	1	1	103B		Classroom 3 Storage Closet	Ceiling	No Access					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
223	7320	1	1	103B		Classroom 3 Storage Closet	Floor	No Access					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
224	7320	1	1	103A		Classroom 3 Storage Closet	W1	No Access					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
225	7320	1	1	103A		Classroom 3 Storage Closet	W2	No Access					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
226	7320	1	1	103A		Classroom 3 Storage Closet	W3	No Access					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
227	7320	1	1	103B		Classroom 3 Storage Closet	W4	No Access					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
228	7320	1	1	104		Classroom 4	Ceiling	Holes, flaking					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
229	7320	1	1	104		Classroom 4	Floor	Debris					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
230	7320	1	1	104		Classroom 4	W1	Cracking, chipping					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	180	5	0	No	N/A	
231	7320	1	1	104		Classroom 4	W2	Cracking, chipping, holes, chipping metal pipe					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	144	4	0	No	N/A	
232	7320	1	1	104		Classroom 4	W3	cracking, chipping, holes, chipping radiator					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	180	5	0	No	N/A	
233	7320	1	1	104		Classroom 4	W4	Cracking, holes, flaking					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	144	4	0	No	N/A	
234	7320	1	1	104E		Classroom 4 Coat Closet	W1	N/A					6-11-19	6-11-19	6-12-19	6-12-19	6-20-19	6-20-19	20	1	0	No	N/A	
235	7320	1	1	104E		Classroom 4 Coat Closet	W2	Chipping					6-11-19	6-11-19	6-12-19	6-18-19	6-20-19	6-20-19	20	1	0	No	N/A	
236	7320	1	1	104E		Classroom 4 Coat Closet	W3	Cracking					6-11-19	6-11-19	6-12-19	6-18-19	6-20-19	6-20-19	20	1	0	No	N/A	
237	7320	1	1	104E		Classroom 4 Coat Closet	W4	Chipping					6-11-19	6-11-19	6-12-19	6-18-19	6-20-19	6-20-19	20	1	0	No	N/A	
238	7320	1	1	106		Classroom 6	Ceiling	Flaking					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
239	7320	1	1	106		Classroom 6	W1	Chipping, flaking, chipping door					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	180	5	1	No	N/A	
240	7320	1	1	106		Classroom 6	W2	Chipping					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	144	4	0	No	N/A	
241	7320	1	1	106		Classroom 6	W3	Chipping wall, radiator, pipe and flaking					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	180	5	1	Yes	<10	
242	7320	1	1	106		Classroom 6	W4	Staple holes					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	144	4	0	No	N/A	
243	7320	1	1	106C		Classroom 6 Coat Closet	W1	N/A					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	20	1	0	No	N/A	
244	7320	1	1	106B		Classroom 6 Storage Closet	Ceiling	No Access					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
245	7320	1	1	106B		Classroom 6 Storage Closet	Floor	No Access					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
246	7320	1	1	106A		Classroom 6 Storage Closet	W1	No Access					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
247	7320	1	1	106A		Classroom 6 Storage Closet	W2	No Access					6-12-19	6-12-19	6-13-19	6-20-19	6-21-19	6-21-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
248	7320	1	1	106A		Classroom 6 Storage Closet	W3	No Access					6-12-19	6-12-19	6-12-19	6-18-19	6-20-19	6-19-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
249	7320	1	1	106B		Classroom 6 Storage Closet	W4	No Access					6-12-19	6-12-19	6-12-19	6-18-19	6-20-19	6-19-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
250	7320	1	1	107E		Classroom 7	Ceiling	Holes, flaking					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
251	7320	1	1	107E		Classroom 7	W1	Chipping, holes, staple holes, chipping door					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	180	5	1	Yes	<10	
252	7320	1	1	107E		Classroom 7	W2	Cracking, chipping, holes, flaking					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	144	4	1	No	N/A	
253	7320	1	1	107E		Classroom 7	W3	Chipping, holes, flaking, spalling, chipping radiator					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	180	5	0	No	N/A	
254	7320	1	1	107E		Classroom 7	W4	Cracking, chipping, flaking, chipping cabinets					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	144	4	0	No	N/A	
255	7320	1	1	107D		Classroom 7 Coat Closet	W2	Flaking					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	40	1	0	No	N/A	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
256	7320	1	1	107D		Classroom 7 Coat Closet	W3	Cracking, flaking					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	40	1	1	No	N/A	
257	7320	1	1	107C		Classroom 7 Restroom	W2	Chipping radiators					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	80	2	1	Yes	12	
258	7320	1	1	107F		Classroom 7 Storage Closet	Floor	Debris					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	Included Below	Included Below	Included Below	Included Below	Included Below	
259	7320	1	1	107F		Classroom 7 Storage Closet	W1	flaking					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	40	1	0	No	N/A	
260	7320	1	1	107B		Classroom 7 Storage Closet	W2	Cracking					6-10-19	6-10-19	6-12-19	6-13-19	6-18-19	6-19-19	40	1	0	No	N/A	
261	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W1	Chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	40	1	0	No	N/A	
262	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W2	Chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	40	1	0	No	N/A	
263	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W3	Chipping, holes					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	40	1	0	No	N/A	
264	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W4	Chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	40	1	0	No	N/A	
265	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W1	Chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
266	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W2	Chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
267	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W3	Chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
268	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W4	Chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	N/A	N/A	N/A	N/A	N/A	No Paint/All Wood
269	7320	1	1	105A		Counselor's Office	Floor	Debris					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	Included Below	Included Below	Included Below	Included Below	Included Below	
270	7320	1	1	105A		Counselor's Office	W1	Chipping door					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	50	2	0	No	N/A	
271	7320	1	1	105A		Counselor's Office	W2	Chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	50	2	0	No	N/A	
272	7320	1	1	105A		Counselor's Office	W3	Chipping radiator, flaking					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	50	2	0	No	N/A	
273	7320	1	1	105A		Counselor's Office	W4	Cracking, chipping					6-14-19	6-14-19	6-18-19	6-20-19	6-25-19	6-25-19	50	2	0	No	N/A	
274	7320	1	1	H19		First Floor Main Hallway	W1	Chipping wall and pipe, holes, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	252	7	0	No	N/A	
275	7320	1	1	H19		First Floor Main Hallway	W3	Cracking, chipping wall, metal pipe, radiator, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	252	7	0	No	N/A	
276	7320	1	1	S17		First Floor Stairwell Grange Avenue	Ceiling	Flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	Included Below	Included Below	Included Below	Included Below	Included Below	
277	7320	1	1	S17		First Floor Stairwell Grange Avenue	Floor	Chipping wall and rail					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	Included Below	Included Below	Included Below	Included Below	Included Below	

Task ID	ULCS#	Element	Factor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
278	7320	1	1	S17		First Floor Stairwell Grange Avenue	W1	Chipping, flaking, holes					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	220	6	0	No	N/A	
279	7320	1	1	S17		First Floor Stairwell Grange Avenue	W2	Chipping wall, radiator and pipe					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	220	6	0	No	N/A	
280	7320	1	1	S17		First Floor Stairwell Grange Avenue	W3	Chipping, holes, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	220	6	0	No	N/A	
281	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	Included Below	Included Below	Included Below	Included Below	Included Below	
282	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W1	Chipping wall and pipe					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	220	6	0	No	N/A	
283	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W3	Chipping, holes, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	220	6	0	No	N/A	
284	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W4	Cracking, chipping radiators, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	220	6	0	No	N/A	
285	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Ceiling	Cracking, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	Included with Walls	Included with Walls	Included with Walls	Included with Walls	Included with Walls	
286	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Floor	Debris					6-25-19	6-25-19	6-26-19	6-28-19	7-2-19	7-2-19	Included with Walls	Included with Walls	Included with Walls	Included with Walls	Included with Walls	
287	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W2	Cracking, chipping, chipping metal pipe, holes, flaking,					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	150	4	0	No	N/A	
288	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W3	Chipping radiator, holes, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	150	4	0	No	N/A	
289	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W4	Cracking, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	150	4	0	No	N/A	
290	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W2	Cracking, holes, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	150	4	0	No	N/A	
291	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W3	Chipping, cracking, holes					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	150	4	0	No	N/A	
292	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W4	Cracking, chipping radiator, holes, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	150	4	0	No	N/A	
293	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W1	Chipping door and radiator					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	200	5	0	No	N/A	
294	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W2	Chipping radiator, door and metal pipe					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	200	5	0	No	N/A	
295	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W3	Cracking, chipping door and radiator, flaking					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	200	5	0	No	N/A	
296	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W4	Chipping metal pipe					6-25-19	6-25-19	6-26-19	6-28-19	7-1-19	7-1-19	200	5	0	No	N/A	
297	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W1	Cracking					6-24-19	6-24-19	6-25-19	6-25-19	6-26-19	6-26-19	75	2	0	No	N/A	

Task ID	ULCS#	Element	Factor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
298	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W3	Cracking, chipping, holes					6-24-19	6-24-19	6-25-19	6-25-19	6-26-19	6-26-19	75	2	0	No	N/A	
299	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W4	Chipping, holes					6-24-19	6-24-19	6-25-19	6-25-19	6-26-19	6-26-19	75	2	0	No	N/A	
300	7320	1	1	S19		Main Entrance Stairwell	W1	Cracking, chipping wall and door, flaking					6-23-19	6-23-19	6-24-19	6-25-19	6-26-19	6-26-19	80	2	0	No	N/A	
301	7320	1	1	107		Main Office	Ceiling	Holes, flaking					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	Included Below	Included Below	Included Below	Included Below	Included Below	
302	7320	1	1	107		Main Office	W1	Chipping					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	40	1	1	Yes	<10	
303	7320	1	1	107		Main Office	W2	Chipping, holes, flaking, spalling, efflorescence, chipping radiator					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	40	1	0	No	N/A	
304	7320	1	1	107		Main Office	W3	Chipping, holes, chipping door					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	40	1	0	No	N/A	
305	7320	1	1	107		Main Office	W4	Chipping					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	40	1	1	No	N/A	
306	7320	1	1	105D		Nurse's Office	W1	Chipping, chipping door					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	60	2	1	No	N/A	
307	7320	1	1	105D		Nurse's Office	W2	Cracking, chipping, flaking					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	60	2	0	No	N/A	
308	7320	1	1	105D		Nurse's Office	W3	Chipping radiator, flaking					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	60	2	1	Yes	12	
309	7320	1	1	105D		Nurse's Office	W4	Chipping					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	60	2	0	No	N/A	
310	7320	1	1	107A		Principal's Office	W1	Cracking, chipping, chipping door					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	50	2	0	No	N/A	
311	7320	1	1	107A		Principal's Office	W4	Holes					6-14-19	6-14-19	6-18-19	6-24-19	6-26-19	6-26-19	50	2	0	No	N/A	
312	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W1	Chipping door					6-14-19	6-14-19	6-18-19	6-25-19	6-26-19	6-26-19	40	1	0	No	N/A	
313	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W2	Cracking and flaking					6-14-19	6-18-19	6-25-19	6-25-19	6-26-19	6-26-19	40	1	0	No	N/A	
314	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W4	Cracking					6-14-19	6-18-19	6-25-19	6-25-19	6-26-19	6-26-19	40	1	0	No	N/A	
315	7320	1	1	S27		Second Floor Stairwell Grange Avenue	Floor	Chipping stairs and rails					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	Included Below	Included Below	Included Below	Included Below	Included Below	
316	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W1	Cracking, chipping, staple holes, flaking					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	90	3	0	No	N/A	
317	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W2	Chipping, flaking					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	90	3	0	No	N/A	
318	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W3	Cracking, flaking					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	90	3	0	No	N/A	
319	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W4	Flaking					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	90	3	0	No	N/A	
320	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Ceiling	Cracking, flaking					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	Included Below	Included Below	Included Below	Included Below	Included Below	
321	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	Included Below	Included Below	Included Below	Included Below	Included Below	
322	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W1	Cracking, chipping, holes, staple holes					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	90	3	0	No	N/A	
323	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W2	Chipping door					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	90	3	0	No	N/A	
324	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W3	Chipping, flaking					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	90	3	0	No	N/A	
325	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W4	Flaking, spalling					6-4-19	N/A	6-4-19	6-5-19	6-5-19	7-8-19	90	3	0	No	N/A	
326	7320	1	1	105C		Special Education Office	Ceiling	Flaking					6-13-19	6-13-19	6-15-19	6-20-19	6-20-19	6-21-19	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	Included with Wall 3	
327	7320	1	1	105C		Special Education Office	W2	Chipping					6-13-19	6-13-19	6-15-19	6-20-19	6-20-19	6-21-19	5	2	0	No	N/A	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
328	7320	1	1	105C		Special Education Office	W3	Flaking					6-13-19	6-13-19	6-15-19	6-20-19	6-20-19	6-21-19	50	2	0	No	N/A	
329	7320	1	1	105B		Speech Office	W1	Cracking, flaking, holes, spalling					6-13-19	6-13-19	6-15-19	6-20-19	6-20-19	6-21-19	50	2	0	No	N/A	
330	7320	1	1	105B		Speech Office	W2	Cracking, chipping, gouges, holes					6-13-19	6-13-19	6-15-19	6-20-19	6-20-19	6-21-19	50	2	0	No	N/A	
331	7320	1	1	105B		Speech Office	W4	Chipping					6-13-19	6-13-19	6-15-19	6-20-19	6-20-19	6-21-19	50	2	0	No	N/A	
332	7320	1	1	S110		Stairwell next to Classroom 2	Floor	Chipping hand rail					6-10-19	6-16-19	6-17-19	6-20-19	6-20-19	6-21-19	Included Below	Included Below	Included Below	Included Below	Included Below	
333	7320	1	1	S110		Stairwell next to Classroom 2	W1	Chipping door					6-10-19	6-16-19	6-17-19	6-20-19	6-20-19	6-21-19	120	3	0	No	N/A	
334	7320	1	1	S110		Stairwell next to Classroom 2	W3	Chipping door, flaking iron bars					6-10-19	6-16-19	6-17-19	6-20-19	6-20-19	6-21-19	120	3	0	No	N/A	
335	7320	1	1	S110		Stairwell next to Classroom 2	W4	Chipping door					6-10-19	6-16-19	6-17-19	6-20-19	6-20-19	6-21-19	120	3	0	No	N/A	
336	7320	1	1	S111		Stairwell next to Main Office	W1	Chipping door					6-10-19	6-16-19	6-17-19	6-20-19	6-20-19	6-21-19	120	3	0	No	N/A	
337	7320	1	1	S111		Stairwell next to Main Office	W2	Chipping door					6-10-19	6-16-19	6-17-19	6-20-19	6-20-19	6-21-19	120	3	0	No	N/A	
338	7320	1	1	S111		Stairwell next to Main Office	W3	Chipping door, flaking door, flaking iron bars					6-10-19	6-16-19	6-17-19	6-20-19	6-20-19	6-21-19	120	3	0	No	N/A	
339	7320	1	1	S111		Stairwell next to Main Office	W4	Flaking iron bars					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	120	3	0	No	N/A	
340	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	Ceiling	Cracking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
341	7320	1	1	104A		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W2	Cracking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	70	2	0	No	N/A	
342	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W3	Cracking, chipping pipe					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	70	2	0	No	N/A	
343	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W4	Cracking, holes					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	70	2	0	No	N/A	
344	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Ceiling	Cracking, holes, flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
345	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Floor	Debris					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
346	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W1	Flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	75	2	0	No	N/A	
347	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W2	Cracking, holes, flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	75	2	0	No	N/A	
348	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W3	Flaking on wall and asbestos pipe					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	75	2	0	No	N/A	
349	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W4	Flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	75	2	0	No	N/A	
350	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Ceiling	Holes					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
351	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Floor	Debris					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	

Task ID	ULCS#	Element	Factor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
352	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W1	Cracking, chipping wall and rails, flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	80	2	0	No	N/A	
353	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W2	Flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	80	2	0	No	N/A	
354	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W3	Cracking, holes, flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	80	2	0	No	N/A	
355	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W4	Cracking, holes, flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	80	2	0	No	N/A	
356	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	Floor	Chipping rail and flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	Included Below	Included Below	Included Below	Included Below	Included Below	
357	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W1	Chipping and flaking					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	100	3	0	No	N/A	
358	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W2	Chipping door					6-10-19	6-10-19	6-17-19	6-20-19	6-20-19	6-20-19	100	3	0	No	N/A	
359	7320	1	0	008B		Basement Boy's Restroom	Ceiling	Cracking, holes, flaking in concrete					7-1-19	7-1-19	7-3-19	7-5-19	7-6-19	7-15-19	Included Below	Included Below	Included Below	Included Below	Included Below	
360	7320	1	0	008B		Basement Boy's Restroom	W1	Flaking					7-1-19	7-1-19	7-3-19	7-5-19	7-6-19	7-15-19	225	6	1	Yes	<10	
361	7320	1	0	008B		Basement Boy's Restroom	W2	Flaking					7-1-19	7-1-19	7-3-19	7-5-19	7-6-19	7-15-19	225	6	0	No	N/A	
362	7320	1	0	008B		Basement Boy's Restroom	W3	Flaking					7-1-19	7-1-19	7-3-19	7-5-19	7-6-19	7-15-19	225	6	0	No	N/A	
363	7320	1	0	008B		Basement Boy's Restroom	W4	Flaking					7-1-19	7-1-19	7-3-19	7-5-19	7-6-19	7-15-19	225	6	1	No	N/A	
364	7320	1	0	003B		Basement Girl's Restroom	W1	Flaking duct and wall					7-1-19	7-1-19	7-3-19	7-5-19	7-6-19	7-15-19	225	6	0	No	N/A	
365	7320	1	0	003B		Basement Girl's Restroom	W2	Chipping pipe flaking wall					7-8-19	7-8-19	7-9-19	7-10-19	7-16-19	7-15-19	225	6	0	No	N/A	
366	7320	1	0	003B		Basement Girl's Restroom	W3	Cracked and flaking brick wall					7-8-19	7-8-19	7-9-19	7-10-19	7-16-19	7-15-19	225	6	1	No	N/A	
367	7320	1	0	003B		Basement Girl's Restroom	W4	Chipped pipe flaking wall					7-12-19	7-12-19	7-13-19	7-16-19	7-16-19	7-16-19	225	6	1	Yes	<10	
368	7320	1	0	H01		Basement Main Hallway	Ceiling	Flaking ceiling and duct					7-12-19	7-12-19	7-13-19	7-16-19	7-16-19	7-16-19	Included Below	Included Below	Included Below	Included Below	Included Below	
369	7320	1	0	H01		Basement Main Hallway	Floor	Chipping floor grate					7-12-19	7-12-19	7-13-19	7-16-19	7-16-19	7-16-19	Included Below	Included Below	Included Below	Included Below	Included Below	
370	7320	1	0	H01		Basement Main Hallway	W1	Chipping baseboard, flaking wall					7-12-19	7-12-19	7-13-19	7-16-19	7-16-19	7-16-19	240	6	0	No	N/A	
371	7320	1	0	H01		Basement Main Hallway	W2	Chipping, flaking					7-12-19	7-12-19	7-13-19	7-16-19	7-16-19	7-16-19	240	6	0	No	N/A	
372	7320	1	0	H01		Basement Main Hallway	W3	Chipping baseboard, flaking wall					7-12-19	7-12-19	7-13-19	7-16-19	7-16-19	7-16-19	240	6	0	No	N/A	
373	7320	1	0	H01		Basement Main Hallway	W4	Chipping baseboard, flaking wall					7-12-19	7-12-19	7-13-19	7-16-19	7-16-19	7-16-19	240	6	0	No	N/A	
374	7320	1	0	S09		Basement Stairwell Grange Avenue	Floor	Chipping stair and rails					7-12-19	7-12-19	7-13-19	7-16-19	7-16-19	7-16-19	Included Below	Included Below	Included Below	Included Below	Included Below	
375	7320	1	0	S09		Basement Stairwell Grange Avenue	W1	Cracking, chipping wall and radiator, flaking					7-1-19	7-1-19	7-5-19	7-9-19	7-9-19	7-9-19	52	2	0	No	N/A	
376	7320	1	0	S09		Basement Stairwell Grange Avenue	W2	Cracking, chipping, chipping door, holes					7-1-19	7-1-19	7-5-19	7-9-19	7-9-19	7-9-19	52	2	0	No	N/A	
377	7320	1	0	S09		Basement Stairwell Grange Avenue	W3	Cracking, chipping radiators, staple holes					7-1-19	7-1-19	7-5-19	7-8-19	7-9-19	7-9-19	52	2	0	No	N/A	
378	7320	1	0	S09		Basement Stairwell Grange Avenue	W4	Chipping door					7-1-19	7-1-19	7-5-19	7-9-19	7-9-19	7-9-19	52	2	0	No	N/A	
379	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Ceiling	Flaking					7-1-19	7-1-19	7-8-19	7-9-19	7-9-19	7-9-19	Included Below	Included Below	Included Below	Included Below	Included Below	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/ft2)	Other Notes or Comments
380	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails					7-1-19	7-1-19	7-8-19	7-9-19	7-9-19	7-9-19	Included Below	Included Below	Included Below	Included Below	Included Below	
381	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W1	Cracking, chipping, flaking					7-1-19	7-1-19	7-8-19	7-9-19	7-9-19	7-9-19	52	2	0	No	N/A	
382	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W2	Chipping door frame					7-1-19	7-1-19	7-8-19	7-9-19	7-9-19	7-9-19	52	2	0	No	N/A	
383	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W3	Chipping					7-1-19	7-1-19	7-8-19	7-9-19	7-9-19	7-9-19	52	2	0	No	N/A	
384	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W4	Chipping door and pipe, holes and flaking					7-1-19	7-1-19	7-8-19	7-9-19	7-9-19	7-9-19	52	2	0	No	N/A	
385	7320	1	0	001B		Classroom B-1	Ceiling	Chipping, flaking					7-15-19	7-15-19	7-16-19	7-16-19	7-19-19	7-19-19	Included Below	Included Below	Included Below	Included Below	Included Below	Stain Ceiling Tiles
386	7320	1	0	001B		Classroom B-1	Floor	Chipping radiators					7-15-19	7-15-19	7-16-19	7-16-19	7-19-19	7-19-19	Included Below	Included Below	Included Below	Included Below	Included Below	
387	7320	1	0	001B		Classroom B-1	W1	Cracking, chipping, chipping door					7-15-19	7-15-19	7-16-19	7-16-19	7-19-19	7-19-19	170	5	1	No	N/A	
388	7320	1	0	001B		Classroom B-1	W2	Cracking, flaking					7-15-19	7-15-19	7-16-19	7-16-19	7-19-19	7-19-19	170	5	0	No	N/A	
389	7320	1	0	001B		Classroom B-1	W3	Cracking, holes, flaking					7-15-19	7-15-19	7-16-19	7-16-19	7-19-19	7-19-19	170	5	1	Yes	27 and	1st Wipe Sample failed/Recleaned/Resampled -
390	7320	1	0	001B		Classroom B-1	W4	Chipping fiberglass pipe					7-15-19	7-15-19	7-16-19	7-16-19	7-19-19	7-19-19	170	5	0	No	N/A	
391	7320	1	0	002B		Gymnasium	W1	Chipping on door, duct, pipe and backboard					7-1-19	7-2-19	7-3-19	7-16-19	7-16-19	7-16-19	295	8	1	Yes	<10	
392	7320	1	0	002B		Gymnasium	W2	Chipping on door and backboard					7-1-19	7-2-19	7-3-19	7-16-19	7-16-19	7-16-19	295	8	0	No	N/A	
393	7320	1	0	002B		Gymnasium	W3	Cracking brick, chipping radiators					7-1-19	7-2-19	7-3-19	7-16-19	7-16-19	7-16-19	295	8	1	No	N/A	
394	7320	1	0	002B		Gymnasium	W4	Chipping radiator, pipe and door					7-1-19	7-2-19	7-3-19	7-16-19	7-16-19	7-16-19	295	8	1	No	N/A	
395	7320	1	0	002C		Gymnasium Storage Closet	W3	Chipping wall and shelf					7-1-19	7-2-19	7-3-19	7-16-19	7-16-19	7-16-19	40	1	1	No	N/A	
396	7320	1	0	H02		Hallway from Classroom B-1 to Basement Main Hallway	W2	Chipping brick wall					7-15-19	7-15-19	7-15-19	7-16-19	7-19-19	7-26-19	160	4	0	No	N/A	
397	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Ceiling	Flaking ceiling and duct					7-15-19	7-15-19	7-15-19	7-16-19	7-19-19	7-26-19	Included Below	Included Below	Included Below	Included Below	Included Below	
398	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Floor	Debris					7-15-19	7-15-19	7-15-19	7-16-19	7-19-19	7-26-19	Included Below	Included Below	Included Below	Included Below	Included Below	
399	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W2	Chipping baseboard, flaking brick					7-15-19	7-15-19	7-15-19	7-16-19	7-19-19	7-26-19	80	2	0	No	N/A	
400	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W3	Chipping baseboard, flaking brick					7-15-19	7-15-19	7-15-19	7-16-19	7-19-19	7-26-19	80	2	0	No	N/A	
401	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W4	Chipping baseboard, flaking brick					7-15-19	7-15-19	7-15-19	7-16-19	7-19-19	7-26-19	80	2	0	No	N/A	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results (ug/t2)	Other Notes or Comments
402	7320	1	0	S04		Stairwell adjacent to Classroom B-1	Ceiling	Flaking duct and ceiling					7-15-19	7-15-19	7-15-19	7-16-19	7-19-19	7-26-19	Included Below	Included Below	Included Below	Included Below	Included Below	
403	7320	1	0	S04		Stairwell adjacent to Classroom B-1	Floor	Chipping hand rail					7-15-19	7-15-19	7-15-19	7-16-19	7-19-19	7-26-19	Included Below	Included Below	Included Below	Included Below	Included Below	
404	7320	1	0	S04		Stairwell adjacent to Classroom B-1	W1	Chipping door, flaking wall					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	80	2	0	No	N/A	
405	7320	1	0	S04		Stairwell adjacent to Classroom B-1	W3	Chipping door					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	80	2	0	No	N/A	
406	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	Ceiling	Chipping door					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	Included Below	Included Below	Included Below	Included Below	Included Below	
407	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	Floor	Chipping baseboard, stair face and hand rail					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	Included Below	Included Below	Included Below	Included Below	Included Below	
408	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	W3	Chipping door					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	80	2	0	No	N/A	
409	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	W4	Chipping door					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	80	2	0	No	N/A	
410	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	Ceiling	No Access					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	Included Below	Included Below	Included Below	Included Below	Included Below	
411	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	Floor	No Access					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	Included Below	Included Below	Included Below	Included Below	Included Below	
412	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W1	No Access					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	40	1	0	No	N/A	
413	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W2	No Access					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	40	1	0	No	N/A	
414	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W3	No Access					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	40	1	0	No	N/A	
415	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W4	No Access					7-1-19	7-1-19	7-2-19	7-3-19	7-5-19	7-5-19	40	1	0	No	N/A	
416	7320	1	0	009B		Store Room #1	Ceiling	Flaking					7-12-19	7-12-19	7-12-19	7-15-19	7-16-19	7-16-19	Included Below	Included Below	Included Below	Included Below	Included Below	
417	7320	1	0	009B		Store Room #1	Floor	N/A					7-12-19	7-12-19	7-12-19	7-16-19	7-16-19	7-16-19	Included Below	Included Below	Included Below	Included Below	Included Below	
418	7320	1	0	009B		Store Room #1	W1	N/A					7-12-19	7-12-19	7-12-19	7-16-19	7-16-19	7-16-19	52	2	0	No	N/A	
419	7320	1	0	009B		Store Room #1	W2	Flaking metal pipe and wall					7-12-19	7-12-19	7-12-19	7-16-19	7-16-19	7-16-19	52	2	0	No	N/A	
420	7320	1	0	009B		Store Room #1	W3	Flaking					7-12-19	7-12-19	7-12-19	7-16-19	7-16-19	7-16-19	52	2	0	No	N/A	
421	7320	1	0	009B		Store Room #1	W4	N/A					7-12-19	7-12-19	7-12-19	7-16-19	7-16-19	7-16-19	52	2	0	No	N/A	

Appendix D. FAAS Sample Results Table

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201904647

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **BJ Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/09/19 3:10 PM
Collected: 5/9/2019

Project: **P.S.O. - Howe / #****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201904647-0001	5/9/2019	5/10/2019	N/A	11 µg/wipe
Site: IMC Room					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. $\mu\text{g/wipe} = \mu\text{g}/\text{ft}^2 \times \text{area sampled in ft}^2$. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, AZLA 2845.01

Initial report from 05/14/2019 11:30:21

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201904669

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **BJ Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/10/19 9:00 AM
Collected: 5/9/2019

Project: **P.S.D. Howe / #56950****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201904669-0001	5/9/2019	5/11/2019	N/A	42 µg/wipe
Site: Room #21					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/13/2019 16:27:22

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061909149

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **BJ Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/15/19 10:20 AM
Collected: 5/13/2019

Project: **PSD-Hone/56950****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
#2	061909149-0001	5/13/2019	5/15/2019	N/A	<10 µg/wipe
Site: Classroom #21					

Alger Liang, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Carle Place, NY Lab ID 102344 is accredited by the AIHA LAP, LLC in the Environmental Lead accred. program for Lead in Dust, CT PH-0249, NYS ELAP 11469, CA 2339

Initial report from 05/15/2019 16:29:11

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201904891

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Don Heim**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/18/19 9:00 AM
Collected: 5/16/2019

Project: **56950****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
051619-01	201904891-0001	5/16/2019	5/18/2019	144 in ²	<10 µg/ft ²
Site: Room #24					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/20/2019 09:14:55

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201905210

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **BJ Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/30/19 9:00 AM
Collected: 5/29/2019

Project: **P.S.D. - Home / # 56950****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201905210-0001	5/29/2019	5/30/2019	144 in ²	35 µg/ft ²
Site: Room # 8					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/31/2019 08:15:20

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201905357

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Don Heim**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/01/19 9:00 AM
Collected: 5/31/2019

Project: **Howe E.S. / 56950 / 5800 N. 13th Street****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
H-531-01	201905357-0001	5/31/2019	6/1/2019	144 in ²	<10 µg/ft ²
Site: Classroom #8 W-3 Center of Wall 3' Out					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/03/2019 10:57:41

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201905499

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Don Heim**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/05/19 9:00 AM
Collected: 6/4/2019

Project: **Howe E.S. / Job #56950****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
H-604-01	201905499-0001	6/4/2019	6/5/2019	144 in ²	<10 µg/ft ²
Site: Classroom #12 - W-3 - 2' Out From Wall					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. $\mu\text{g}/\text{ft}^2 = \mu\text{g}/\text{wipe} \times \text{area sampled in ft}^2$. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ. NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845 01

Initial report from 06/06/2019 14:51:30

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201905880

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Bernard Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/13/19 3:05 PM
Collected: 6/13/2019

Project: P.S.D Home # 56950

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
01	201905880-0001	6/13/2019	6/14/2019	144 in ²	<10 µg/ft ²
Site: class rm # 7					
02	201905880-0002	6/13/2019	6/14/2019	144 in ²	12 µg/ft ²
Site: bathroom #7					
03	201905880-0003	6/13/2019	6/14/2019	144 in ²	<10 µg/ft ²
Site: classroom # 1					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/mpe. ug/mpe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845 01

Initial report from 06/14/2019 15:29:23

Test Report ChmSnglePrrm/nQC-7.32.3 Printed: 6/14/2019 3:29:23 PM

Page 1 of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201906218

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Bernard Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/24/19 12:40 PM
Collected: 6/24/2019

Project: Howe ES / 56950

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
01	201906218-0001	6/24/2019	6/25/2019	144 in ²	12 µg/ft ²
Site: nurse office by windows					

Philip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036 NY 10872 PA 68-00367, AIHA-LAP, LLC ELLAP 100194, AZLA 2845 01

Initial report from 06/25/2019 15:20:04

Test Report ChmSnglePrm/nQC-7.32.3 Printed: 6/25/2019 3:20:04 PM

Page 1 of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201906344

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Bernard Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/26/19 12:40 PM
Collected: 6/26/2019

Project: **Howe School #56950****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
-01	201906344-0001	6/26/2019	6/27/2019	144 in ²	37 µg/ft ²
Site: 3rd Floor Room 16 Computer Lab					
-02	201906344-0002	6/26/2019	6/27/2019	144 in ²	<10 µg/ft ²
Site: 1st Floor Main Office					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. µg/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ. NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/27/2019 15:09:29

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminson@emsl.com

EMSL Order: 201906478

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Bernard Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/28/19 12:45 PM
Collected:

Project: Howe School 56590

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
-01	201906478-0001 Site: Room-16	6/28/2019	N/A		<10 µg/wipe
-02	201906478-0002 Site: Room-6	6/28/2019	N/A		<10 µg/wipe
-03	201906478-0003 Site: Room #3	6/28/2019	N/A		<10 µg/wipe
-04	201906478-0004 Site: Room #2	6/28/2019	N/A		<10 µg/wipe

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. µg/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ. NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845 01

Initial report from 06/29/2019 16:17:19

Test Report ChmSnglePrm/nQC-7.32.3 Printed: 6/29/2019 4:17:19 PM

Page 1 of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907021

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Bernard Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 07/12/19 12:30 PM
Collected: 7/12/2019

Project: **Howe School # 56950****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201907021-0001	7/12/2019	7/13/2019	N/A	<10 µg/wipe
Site: basement boys room					
2	201907021-0002	7/12/2019	7/13/2019	N/A	<10 µg/wipe
Site: basement girls room					
3	201907021-0003	7/12/2019	7/13/2019	N/A	13 µg/wipe
Site: basement cafeteria					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. µg/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845 01

Initial report from 07/13/2019 14:50:29

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907358

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Bernard Brunner**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 07/19/19 12:35 PM
Collected: 7/19/2019

Project: Howee School #56950

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201907358-0001	7/19/2019	7/19/2019	N/A	<10 µg/wipe
Site: gym basement					
2	201907358-0002	7/19/2019	7/19/2019	N/A	27 µg/wipe
Site: art room #(B.1) basement					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. µg/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/20/2019 13:10:38

Appendix E. Photographs

Appendix F. Environmental Firm Certifications

United States Environmental Protection Agency

This is to certify that



The Vertex Companies, Inc.

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint renovation, repair, and painting activities pursuant to 40 CFR Part 745.89

In the Jurisdiction of:

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires March 20, 2024

NAT-F199670-1

Certification #

March 06, 2019

Issued On



Michelle Price

Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
WASHINGTON, D.C. 20460

March 07, 2019

Marc Fiore
The Vertex Companies, Inc.
400 Libbey Parkway
Weymouth, MA 02364

OFFICE OF CHEMICAL SAFETY
AND POLLUTION PREVENTION

Dear Marc Fiore:

Thank you for applying to the U.S. Environmental Protection Agency (EPA) for certification to conduct Renovation, Repair and Painting Activities in target housing and child-occupied facilities. I am pleased to inform you that, pursuant to 40 CFR Part 745, Subpart E, your renovation, repair and painting firm is certified. Your certificate is enclosed.

This certification expires on **March 20, 2024** and is valid in **All EPA Administered States, Tribes, and Territories**. However, if a State in which you are certified obtains program authorization during the term of this certification, the scope of your certification will be diminished to exclude the affected area.

Your EPA firm certification is subject to the following restrictions:

- 1) Individual states and Indian tribes, whether authorized or not, are not required to accept EPA certification and may accept or reject it under its own authority. Please be aware that your EPA certification does not relieve you of any obligations you may have to any State or Indian tribe regarding renovation, repair and painting activities.
- 2) EPA certification is specific and limited as described above. If you wish to obtain certification in other lead-based paint disciplines, you must apply separately.
- 3) In advertising the EPA certification, firms must indicate clearly that the firm is certified only for purposes of Section 402 of TSCA. Failure to accurately state EPA certification conditions could result in EPA suspending or withdrawing certification.
- 4) EPA may conduct audits and/or inspections to ensure continued compliance with regulatory standards, and may revoke or suspend its certification if subsequent alterations or deviations result with the firm no longer meeting the standards found at 40 CFR Part 745, Subpart E.

If you have questions about the renovation, repair and painting rule or need assistance, please contact the Regional Lead Coordinator, Amanda R. Brylski, of the EPA Region 1 staff at 617-918-1758. If you have any questions about your firm certification, please contact the National Lead Information Center at 1-800-424-LEAD and refer to **Application ID number R620658**. Congratulations, and thank you for your interest in being a certified renovation, repair and painting firm.

Sincerely,

A handwritten signature in black ink, appearing to read "Michelle Price", is written over the typed name.

Michelle Price, Chief
Lead, Heavy Metals, and Inorganics Branch

Enclosures

School District of Philadelphia
Paint and Plaster Stabilization Project
Name of School

	A	B	C	D	E	F	G	H
1	Name of Certified Contractor	Worker Name	US EPA RRP Training Provider (Firm/Individual)	US EPA RRP Certification Number	US EPA RRP Certification Expiration Date	Worker Trained on site (Yes/No)	Training Date	Comments
2	The Vertex Companies, Inc.	Nicholas Volpe	Access Training Services/Mark Schlager	R-I-18846-18-00107	12/7/2023	No	12/7/2018	
3	The Vertex Companies, Inc.	Louis DiMichele	Access Training Services/Mark Schlager	R-I-18846-18-00044	5/25/2023	No	5/25/2018	
4	The Vertex Companies, Inc.	William Klinger	Access Training Services/Mark Schlager	R-I-18846-18-000333	4/20/2023	No	4/20/2018	
5	The Vertex Companies, Inc.	Nicholas Volpe	Access Training Services/Mark Schlager	D-I-18846-18-00056	11/14/2023	No	11/14/2018	Lead Dust Sampling Technician
6	The Vertex Companies, Inc.	Louis DiMichele	Access Training Services/Mark Schlager	D-I-18846-18-00014	3/23/2023	No	3/23/2018	Lead Dust Sampling Technician
7	The Vertex Companies, Inc.	William Klinger	Criterion Laboratories, Inc./James A. Weltz	D-I-19014-18-746939	8/3/2023	No	8/3/2018	Lead Dust Sampling Technician

Appendix G. Paint Contractor Certifications

United States Environmental Protection Agency

This is to certify that



Buttonwood Co., Inc.

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint renovation, repair, and painting activities pursuant to 40 CFR Part 745.89

In the Jurisdiction of:

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires March 10, 2021

NAT-86266-2

Certification #

February 24, 2016

Issued On



A handwritten signature in black ink that reads "Michelle Price".

Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch

School District of Philadelphia
Paint and Plaster Stabilization Project
Name of School

	A	B	C	D	E	F	G	H
1	Name of Certified Contractor	Worker Name	US EPA RRP Training Provider (Firm/Individual)	US EPA RRP Certification Number	US EPA RRP Certification Expiration Date	Worker Trained on site (Yes/No)	Training Date	Comments
2	Buttonwood Co., Inc.	Jim Volpe	Finishing Trades Institute of the Mid-Atlantic Region/Martin McNulty	R-I-21936-12-00242	12/11/2023	No	12/11/2018	
3	Buttonwood Co., Inc.	Angelo Chambers	Finishing Trades Institute of the Mid-Atlantic Region/Martin McNulty	R-I-21936-12-00301	1/22/2024	No	1/22/2019	

Appendix H. Documentation of Parent and Staff Notifications



**Julia Ward Howe School
5800 N. 13th Street
Philadelphia, Pa. 19141**

**Dana Singletary
Principal**

Telephone: 215-400-3650

Paint and Plaster Stabilization: Project Start

Dear School Families,

The School District of Philadelphia works daily to ensure that our students and staff have a safe, healthy environment in which to learn and work. On behalf of the School District, I am writing to share information with you about plans for renovation to remove loose and peeling paint in our school building. The goal of the work is to enhance classroom environments and remove the risk of lead exposure to children in our school community.

The School District has begun paint and plaster stabilization work in school buildings constructed prior to 1978 that are likely to contain lead-based paint. Paint stabilization involves removing loose, peeling, flaking and crumbling paint and plaster under controlled conditions. Our school has been selected for this work because paint damage was documented in occupied spaces such as classrooms and classroom closets, administrative offices, cafeteria, auditorium, bathrooms, kitchen, hallways, and emergency exit stairways.

The work is being completed by individuals who are trained and certified in United States Environmental Protection Agency (EPA) lead-based paint renovation, repair and painting work practices. These work practices ensure that classrooms and other areas are free of paint chips, dust and debris. Each space will be assessed after the work is completed in each area to ensure that the spaces are ready for students and staff to safely occupy. Building staff will also look for signs of paint and plaster damage and clean paint and plaster dust and debris using a HEPA vacuum before, during, and after the project.

Details about the project including the environmental consultant's assessment report, project schedule and frequently asked questions are available in the school's main office or by visiting www.philasd.org/facilities. Copies will also be provided to the School Advisory Council and Home and School Association in the near future.

We understand that you likely will have additional questions, and we will work to address those promptly. The School District will host a meeting for families to share an overview of the repairs and to answer questions on **Wednesday, April 10, 2019 at 8:30 AM** in our school.

Sincerely,
Dana Singletary
Principal