



May 30, 2023

Ms. Victoria Flemming
Office of Environmental
School District of Philadelphia
440 North Broad Street
Philadelphia, Pa 19130-4015

BEA#: 543523AF
OEP#: EP2023-0603-4290

**RE: Lead Safe Assessment
Universal Bluford Charter School
5720 Media Street., Philadelphia, PA 19131**

Dear Ms. Flemming,

The purpose of this lead safe inspection was to determine the existence and condition of lead-based paint at the Universal Bluford Charter School using an x-ray fluorescence (XRF) analyzer. Lead-Based Paint (LBP) is defined by The City of Philadelphia Department of Health to contain equal or greater than 0.70 mg/cm² lead via XRF. LBP is defined by the Federal Department of Housing and Urban Development (HUD) and Environmental Protection Agency (EPA) to contain equal or greater than 1.00 mg/cm² lead via XRF.

The inspection of the subject property was performed by Timothy Smith of Batta Environmental Associates, Inc., a Pennsylvania licensed lead-inspector.

From March 13th – 22nd, 2023, BATTAs completed Lead-Based Paint (LBP) XRF Inspection at the following property:

- **Universal Bluford Charter School – 5720 Media Street., Philadelphia, PA 19131**

Results

Results of the XRF readings can be found in the School District of Philadelphia Google Drive in the Excel File titled: "Universal Institute Charter School @ Bluford Lead Sheet". The survey and testing were performed to locate any damaged Lead-Based Paint (LBP) that may be present throughout the interior of the building prior to planned stabilization. At the time of the assessment from 3/13 – 3/22/23, **no damaged LBP was identified in student or teacher occupied areas.**



Batta Environmental Associates, Inc. is pleased to provide the School District of Philadelphia with our professional environmental services. If you should have any questions regarding the information or data provided in this correspondence, please contact our office at (302)-737-3376.

Sincerely,

A handwritten signature in dark purple ink, appearing to read "Alyssa M. Cartagena".

Alyssa M. Cartagena

Project Manager

BATTA Environmental Associates, Inc.

Consulting | Laboratories | Products | Training

(O) 302.737.3376 | (C) 267.467.2774 | alyssa.cartagena@battaenv.com





Philadelphia Department of Public Health Certification of School Lead Safe Status

By signing this certificate, I confirm that I have done a visual inspection of the areas where children have access, including contact surfaces where children store their equipment or materials, and confirm these areas do not have deteriorated lead-based paint. A certified risk assessor or lead dust sampling technician completed verification wipe tests in accordance with the EPA's RRP guidelines and confirms they meet the EPA's cleanliness standard. A certified risk assessor or lead dust sampling technician collected interior dust wipe samples in compliance with EPA regulations in work areas and confirms they did not contain lead contaminated dust in excess of EPA dust lead standards in Pre-K, Kindergarten, and 1st Grade classrooms as well as the restrooms, offices, cafeterias, gymnasiums, and auditoriums these children routinely occupy. This certificate is valid for 4 years from date of verification.

UNIVERSAL BLUFORD CHARTER SCHOOL - 5720 MEDIA STREET, PHILADELPHIA, PA 19131

School Name

Street Address

Batta Environmental

057662

Certifying Company (print)

Risk Assessor, Lead Inspector PA Lic. #, EPA Firm Certification or Lead Dust Sampling Technician

Certification #

Timothy Smith *T.S.-it*

3/22/2023

Inspector/Risk Assessor or Dust Wipe Sampling Technician Name (Signature)

Date of Verification

Victoria Flemming, 215-400-5768, vflemming@delucaadvisory.com

School Official Name, Telephone and E-mail Address

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	W1	CMU	Yellow	None	0	0	Negative
4290	2	B429001	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	W3	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	W4	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
4290	2	B429001	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	100A	Women's Staff Restroom across from Cafetorium	W1	CMU	White	None	0	0	Negative
4290	2	B429001	1	100A	Women's Staff Restroom across from Cafetorium	Doorframe	Metal	Blue	Friction	1	0.5	Negative
4290	2	B429001	1	100A	Women's Staff Restroom across from Cafetorium	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	100A	Women's Staff Restroom across from Cafetorium	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	100A	Women's Staff Restroom across from Cafetorium	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	100A	Women's Staff Restroom across from Cafetorium	Ceiling	Drywall	White	None	0	0.1	Negative
4290	2	B429001	1	100A	Women's Staff Restroom across from Cafetorium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	100B	Men's Staff Restroom across from Cafetorium	W1	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	100B	Men's Staff Restroom across from Cafetorium	Doorframe	Metal	Blue	None	0	0.4	Negative
4290	2	B429001	1	100B	Men's Staff Restroom across from Cafetorium	W2	CMU	White	None	0	0	Negative
4290	2	B429001	1	100B	Men's Staff Restroom across from Cafetorium	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	100B	Men's Staff Restroom across from Cafetorium	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	100B	Men's Staff Restroom across from Cafetorium	Ceiling	Drywall	White	None	0	0.3	Negative
4290	2	B429001	1	100B	Men's Staff Restroom across from Cafetorium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATT Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	W1	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	Doorframe	Metal	Blue	None	0	0.5	Negative
4290	2	B429001	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	Conduit	Metal	White	None	0	0.2	Negative
4290	2	B429001	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	W3	CMU	White	None	0	0	Negative
4290	2	B429001	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	Ceiling	Drywall	White	None	0	0.2	Negative
4290	2	B429001	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	Floor	Concrete	Grey	None	0	0	Negative
4290	2	B429001	1	101	Front Entrance Vestibule	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	101	Front Entrance Vestibule	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	101	Front Entrance Vestibule	W3	Drywall	White	None	0	0	Negative
4290	2	B429001	1	101	Front Entrance Vestibule	Door	Metal	Purple	None	0	0.1	Negative
4290	2	B429001	1	101	Front Entrance Vestibule	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	101	Front Entrance Vestibule	Ceiling	Drywall	White	None	0	0	Negative
4290	2	B429001	1	101	Front Entrance Vestibule	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	102	Front Entrance Reception/Waiting Area	W1	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	102	Front Entrance Reception/Waiting Area	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	102	Front Entrance Reception/Waiting Area	Conduit	Metal	Yellow	None	0	0.2	Negative
4290	2	B429001	1	102	Front Entrance Reception/Waiting Area	W3	CMU	Yellow	None	0	0.2	Negative
4290	2	B429001	1	102	Front Entrance Reception/Waiting Area	Column	Metal	Multi	None	0	0.3	Negative
4290	2	B429001	1	102	Front Entrance Reception/Waiting Area	W4	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	102	Front Entrance Reception/Waiting Area	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	102	Front Entrance Reception/Waiting Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103	Main Office	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103	Main Office	W1	CMU	Brown	None	0	0.1	Negative
4290	2	B429001	1	103	Main Office	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103	Main Office	W3	CMU	White	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	103	Main Office	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103	Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103	Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103A	Telecomm Room inside Main Office	W1	Wood	White	None	0	0.1	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	W2	Wood	White	None	0	0.1	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	W3	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	Metal Panel	Metal	White	None	0	0.1	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	Conduit	Metal	White	None	0	0.2	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	Ceiling	Metal	White	None	0	0.1	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	Insulation	Fiberglass	White	None	0	0.2	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	Support Beam	Metal	White	None	0	0.5	Negative
4290	2	B429001	1	103A	Telecomm Room inside Main Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103B	Conference Room 103B inside Main Office	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103B	Conference Room 103B inside Main Office	Doorframe	Metal	Blue	Chipping	4	0.1	Negative
4290	2	B429001	1	103B	Conference Room 103B inside Main Office	Windowframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	1	103B	Conference Room 103B inside Main Office	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103B	Conference Room 103B inside Main Office	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103B	Conference Room 103B inside Main Office	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	103B	Conference Room 103B inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103B	Conference Room 103B inside Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103C	Work Room 103C inside Main Office	W1	CMU	Brown	None	0	0.2	Negative
4290	2	B429001	1	103C	Work Room 103C inside Main Office	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103C	Work Room 103C inside Main Office	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103C	Work Room 103C inside Main Office	Doorframe	Metal	Blue	Chipping	1	0.2	Negative
4290	2	B429001	1	103C	Work Room 103C inside Main Office	W4	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103C	Work Room 103C inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103C	Work Room 103C inside Main Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103D	Counselor's Office 103D inside Main Office	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103D	Counselor's Office 103D inside Main Office	Doorframe	Metal	Blue	Chipping	2	0.1	Negative
4290	2	B429001	1	103D	Counselor's Office 103D inside Main Office	W2	CMU	White	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	103D	Counselor's Office 103D inside Main Office	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103D	Counselor's Office 103D inside Main Office	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	103D	Counselor's Office 103D inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103D	Counselor's Office 103D inside Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103E	Counselor's Office 103E inside Main Office	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103E	Counselor's Office 103E inside Main Office	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	2	B429001	1	103E	Counselor's Office 103E inside Main Office	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103E	Counselor's Office 103E inside Main Office	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103E	Counselor's Office 103E inside Main Office	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	103E	Counselor's Office 103E inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103E	Counselor's Office 103E inside Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103F	Principal's Office 103F inside Main Office	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103F	Principal's Office 103F inside Main Office	Conduit	Metal	White	None	0	0.2	Negative
4290	2	B429001	1	103F	Principal's Office 103F inside Main Office	Doorframe	Metal	Blue	Friction	3	0.2	Negative
4290	2	B429001	1	103F	Principal's Office 103F inside Main Office	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103F	Principal's Office 103F inside Main Office	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103F	Principal's Office 103F inside Main Office	W4	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103F	Principal's Office 103F inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103F	Principal's Office 103F inside Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103G	Principal's Office Closet	W1	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103G	Principal's Office Closet	Doorframe	Metal	White	None	0	0.4	Negative
4290	2	B429001	1	103G	Principal's Office Closet	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	103G	Principal's Office Closet	Insulation	Fiberglass	White	None	0	0.1	Negative
4290	2	B429001	1	103G	Principal's Office Closet	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103G	Principal's Office Closet	Shelf	Wood	White	None	0	0.3	Negative
4290	2	B429001	1	103G	Principal's Office Closet	W4	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	103G	Principal's Office Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103G	Principal's Office Closet	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	103H	Principal's Office Bathroom	W1	CMU	White	None	0	0.4	Negative
4290	2	B429001	1	103H	Principal's Office Bathroom	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	1	103H	Principal's Office Bathroom	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	103H	Principal's Office Bathroom	Insulation	Fiberglass	White	None	0	0.2	Negative
4290	2	B429001	1	103H	Principal's Office Bathroom	W3	CMU	White	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	103H	Principal's Office Bathroom	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	103H	Principal's Office Bathroom	Ceiling	Drywall	White	None	0	0.1	Negative
4290	2	B429001	1	103H	Principal's Office Bathroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	104	Girl's Student Restroom across from Cafetorium	W1	CMU	Yellow	None	0	0.1	Negative
4290	2	B429001	1	104	Girl's Student Restroom across from Cafetorium	W2	CMU	Yellow	None	0	0.2	Negative
4290	2	B429001	1	104	Girl's Student Restroom across from Cafetorium	W3	CMU	Yellow	None	0	0.2	Negative
4290	2	B429001	1	104	Girl's Student Restroom across from Cafetorium	W4	CMU	Yellow	None	0	0.1	Negative
4290	2	B429001	1	104	Girl's Student Restroom across from Cafetorium	Pipe	Metal	White	None	0	0.2	Negative
4290	2	B429001	1	104	Girl's Student Restroom across from Cafetorium	Ceiling	Drywall	White	None	0	0.1	Negative
4290	2	B429001	1	104	Girl's Student Restroom across from Cafetorium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	105	Boy's Student Restroom across from Cafetorium	W1	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	105	Boy's Student Restroom across from Cafetorium	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	105	Boy's Student Restroom across from Cafetorium	W3	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	105	Boy's Student Restroom across from Cafetorium	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	105	Boy's Student Restroom across from Cafetorium	Ceiling	Drywall	White	None	0	0.2	Negative
4290	2	B429001	1	105	Boy's Student Restroom across from Cafetorium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	106	Family Student Resource Center across from Cafetorium	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	106	Family Student Resource Center across from Cafetorium	Doorframe	Metal	Blue	Chipping	4	0.1	Negative
4290	2	B429001	1	106	Family Student Resource Center across from Cafetorium	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	106	Family Student Resource Center across from Cafetorium	W3	CMU	White	None	0	0	Negative
4290	2	B429001	1	106	Family Student Resource Center across from Cafetorium	W4	CMU	White	None	0	0	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	106	Family Student Resource Center across from Cafetorium	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	106	Family Student Resource Center across from Cafetorium	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	106A	Family Student Resource Center Restroom	W1	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	106A	Family Student Resource Center Restroom	Doorframe	Metal	Blue	None	0	0	Negative
4290	2	B429001	1	106A	Family Student Resource Center Restroom	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	106A	Family Student Resource Center Restroom	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	106A	Family Student Resource Center Restroom	Pipe	Metal	White	None	0	0.3	Negative
4290	2	B429001	1	106A	Family Student Resource Center Restroom	W4	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	106A	Family Student Resource Center Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
4290	2	B429001	1	106A	Family Student Resource Center Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	107	Nurse's Office	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	107	Nurse's Office	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	2	B429001	1	107	Nurse's Office	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	107	Nurse's Office	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	107	Nurse's Office	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	107	Nurse's Office	Ceiling	Drywall	White	None	0	0.1	Negative
4290	2	B429001	1	107	Nurse's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	107A	Nurse's Office Restroom	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	107A	Nurse's Office Restroom	Doorframe	Metal	Blue	Friction	4	0.2	Negative
4290	2	B429001	1	107A	Nurse's Office Restroom	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	107A	Nurse's Office Restroom	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	107A	Nurse's Office Restroom	Pipe	Metal	White	None	0	0.3	Negative
4290	2	B429001	1	107A	Nurse's Office Restroom	W4	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	107A	Nurse's Office Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	107A	Nurse's Office Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	108	Gym Teacher's Office	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	108	Gym Teacher's Office	Doorframe	Metal	Blue	None	0	0	Negative
4290	2	B429001	1	108	Gym Teacher's Office	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	108	Gym Teacher's Office	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	108	Gym Teacher's Office	Metal Panel	Metal	White	None	0	0.2	Negative
4290	2	B429001	1	108	Gym Teacher's Office	W4	CMU	White	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	108	Gym Teacher's Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	108	Gym Teacher's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	108A	Gym Teacher's Office Restroom	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	108A	Gym Teacher's Office Restroom	Doorframe	Metal	Blue	None	0	0.5	Negative
4290	2	B429001	1	108A	Gym Teacher's Office Restroom	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	108A	Gym Teacher's Office Restroom	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	108A	Gym Teacher's Office Restroom	W4	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	108A	Gym Teacher's Office Restroom	Insulation	Fiberglass	White	None	0	0.2	Negative
4290	2	B429001	1	108A	Gym Teacher's Office Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
4290	2	B429001	1	108A	Gym Teacher's Office Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	109	Gymnasium	W1	CMU	White	Efflorescence	70	0.1	Negative
4290	2	B429001	1	109	Gymnasium	Doorframe	Metal	Blue	Chipping	4	0.1	Negative
4290	2	B429001	1	109	Gymnasium	Duct	Metal	White	Cracking	10	0.1	Negative
4290	2	B429001	1	109	Gymnasium	W2	CMU	White	Flaking	4	0.1	Negative
4290	2	B429001	1	109	Gymnasium	Pipe	Metal	White	None	0	0.3	Negative
4290	2	B429001	1	109	Gymnasium	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	109	Gymnasium	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	109	Gymnasium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
4290	2	B429001	1	109	Gymnasium	Floor	Rubber	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	109A	Gymnasium Girl's Restroom	W1	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	109A	Gymnasium Girl's Restroom	Conduit	Metal	White	None	0	0.1	Negative
4290	2	B429001	1	109A	Gymnasium Girl's Restroom	Doorframe	Metal	Blue	None	0	0	Negative
4290	2	B429001	1	109A	Gymnasium Girl's Restroom	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	109A	Gymnasium Girl's Restroom	W3	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	109A	Gymnasium Girl's Restroom	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	109A	Gymnasium Girl's Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
4290	2	B429001	1	109A	Gymnasium Girl's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	109B	Gymnasium Boy's Restroom	W1	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	109B	Gymnasium Boy's Restroom	Conduit	Metal	White	None	0	0.1	Negative
4290	2	B429001	1	109B	Gymnasium Boy's Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	2	B429001	1	109B	Gymnasium Boy's Restroom	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	109B	Gymnasium Boy's Restroom	W3	CMU	White	None	0	0	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report							
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford							
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131							
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
4290	2	B429001	1	109B	Gymnasium Boy's Restroom	W4	CMU	White	None	0	0.1	Negative	
4290	2	B429001	1	109B	Gymnasium Boy's Restroom	Ceiling	Drywall	White	None	0	0	Negative	
4290	2	B429001	1	109B	Gymnasium Boy's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
4290	2	B429001	1	109C	Gym Equipment Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	
4290	2	B429001	1	109C	Gym Equipment Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	
4290	2	B429001	1	109C	Gym Equipment Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	
4290	2	B429001	1	109C	Gym Equipment Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	
4290	2	B429001	1	109C	Gym Equipment Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
4290	2	B429001	1	109C	Gym Equipment Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	W1	CMU	White	None	0	0.1	Negative	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	Conduit	Metal	White	None	0	0.1	Negative	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	Doorframe	Metal	Blue	Friction	5	0.1	Negative	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	W2	CMU	White	None	0	0.2	Negative	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	Insulation	Fiberglass	White	None	0	0.2	Negative	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	W3	CMU	White	None	0	0.1	Negative	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	W4	CMU	White	None	0	0.4	Negative	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	Ceiling	Metal	White	None	0	0.2	Negative	
4290	2	B429001	1	110	Shipping/Receiving Room next to Kitchen	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A	
4290	2	B429001	1	110A	Shipping/Receiving Room Restroom	W1	CMU	White	None	0	0.2	Negative	
4290	2	B429001	1	110A	Shipping/Receiving Room Restroom	Doorframe	Metal	Blue	None	0	0.4	Negative	
4290	2	B429001	1	110A	Shipping/Receiving Room Restroom	W2	CMU	White	None	0	0	Negative	
4290	2	B429001	1	110A	Shipping/Receiving Room Restroom	W3	CMU	White	None	0	0	Negative	
4290	2	B429001	1	110A	Shipping/Receiving Room Restroom	W4	CMU	White	None	0	0.2	Negative	
4290	2	B429001	1	110A	Shipping/Receiving Room Restroom	Ceiling	Drywall	White	None	0	0.1	Negative	
4290	2	B429001	1	110A	Shipping/Receiving Room Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A	
4290	2	B429001	1	110B	Building Engineer's Office	W1	CMU	White	None	0	0.1	Negative	
4290	2	B429001	1	110B	Building Engineer's Office	Doorframe	Metal	Blue	Friction	2	0.4	Negative	
4290	2	B429001	1	110B	Building Engineer's Office	W2	CMU	White	None	0	0	Negative	
4290	2	B429001	1	110B	Building Engineer's Office	W3	CMU	White	None	0	0.1	Negative	
4290	2	B429001	1	110B	Building Engineer's Office	W4	CMU	White	None	0	0.1	Negative	
4290	2	B429001	1	110B	Building Engineer's Office	Insulation	Fiberglass	White	None	0	0.2	Negative	
4290	2	B429001	1	110B	Building Engineer's Office	Ceiling	Metal	White	None	0	0.2	Negative	
4290	2	B429001	1	110B	Building Engineer's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A	

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	111	Kitchen 111	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111	Kitchen 111	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	2	B429001	1	111	Kitchen 111	W2	CMU	White	None	0	0	Negative
4290	2	B429001	1	111	Kitchen 111	pipe	Metal	White	Chipping	4	0.2	Negative
4290	2	B429001	1	111	Kitchen 111	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111	Kitchen 111	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111	Kitchen 111	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	111	Kitchen 111	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	111A	Kitchen Storage Closet	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111A	Kitchen Storage Closet	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	2	B429001	1	111A	Kitchen Storage Closet	W2	CMU	White	None	0	0	Negative
4290	2	B429001	1	111A	Kitchen Storage Closet	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111A	Kitchen Storage Closet	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	111A	Kitchen Storage Closet	Conduit	Plastic	White	None	0	0.1	Negative
4290	2	B429001	1	111A	Kitchen Storage Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	111A	Kitchen Storage Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	111B	Kitchen Office	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111B	Kitchen Office	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	2	B429001	1	111B	Kitchen Office	door	Metal	Blue	None	0	0.2	Negative
4290	2	B429001	1	111B	Kitchen Office	W2	CMU	White	None	0	0	Negative
4290	2	B429001	1	111B	Kitchen Office	W3	CMU	White	None	0	0	Negative
4290	2	B429001	1	111B	Kitchen Office	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111B	Kitchen Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	111B	Kitchen Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	111C	Kitchen Office Restroom	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111C	Kitchen Office Restroom	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	2	B429001	1	111C	Kitchen Office Restroom	W2	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	111C	Kitchen Office Restroom	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	111C	Kitchen Office Restroom	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	111C	Kitchen Office Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	111C	Kitchen Office Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	112	Cafeteria Serving Line	W1	Drywall	White	None	0	0.2	Negative
4290	2	B429001	1	112	Cafeteria Serving Line	door	Metal	Blue	Friction	1	0.3	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	112	Cafeteria Serving Line	Doorframe	Metal	Blue	Friction	3	0	Negative
4290	2	B429001	1	112	Cafeteria Serving Line	W2	CMU	Green	None	0	0	Negative
4290	2	B429001	1	112	Cafeteria Serving Line	W3	CMU	Green	None	0	0.2	Negative
4290	2	B429001	1	112	Cafeteria Serving Line	W4	CMU	Green	None	0	0	Negative
4290	2	B429001	1	112	Cafeteria Serving Line	Ceiling	Drywall	Green	None	0	0.2	Negative
4290	2	B429001	1	112	Cafeteria Serving Line	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	113	Cafeteria	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	113	Cafeteria	Doorframe	Metal	Blue	Friction	4	0	Negative
4290	2	B429001	1	113	Cafeteria	W2	CMU	Green	None	0	0.1	Negative
4290	2	B429001	1	113	Cafeteria	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	113	Cafeteria	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	113	Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
4290	2	B429001	1	113	Cafeteria	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	113A	Cafeteria Storage Room	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	113A	Cafeteria Storage Room	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	2	B429001	1	113A	Cafeteria Storage Room	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	113A	Cafeteria Storage Room	W3	CMU	White	None	0	0.2	Negative
4290	2	B429001	1	113A	Cafeteria Storage Room	pipe	Metal	White	None	0	0.2	Negative
4290	2	B429001	1	113A	Cafeteria Storage Room	W4	CMU	White	None	0	0	Negative
4290	2	B429001	1	113A	Cafeteria Storage Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	113A	Cafeteria Storage Room	Floor	Concrete	Blue	Friction	10	0.5	Negative
4290	2	B429001	1	114	Auditorium	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	114	Auditorium	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	114	Auditorium	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	114	Auditorium	Conduit	Plaster	White	None	0	0.1	Negative
4290	2	B429001	1	114	Auditorium	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	114	Auditorium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
4290	2	B429001	1	114	Auditorium	Floor	Concrete	Blue	None	0	0.1	Negative
4290	2	B429001	1	115	Auditorium Stage	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	115	Auditorium Stage	Conduit	Metal	White	None	0	0	Negative
4290	2	B429001	1	115	Auditorium Stage	W2	CMU	Black	None	0	0.2	Negative
4290	2	B429001	1	115	Auditorium Stage	W3	CMU	Black	None	0	0	Negative
4290	2	B429001	1	115	Auditorium Stage	pipe	Metal	Black	None	0	0.2	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	115	Auditorium Stage	W4	CMU	Black	None	0	0.2	Negative
4290	2	B429001	1	115	Auditorium Stage	Ceiling	Drywall	White	None	0	0.1	Negative
4290	2	B429001	1	115	Auditorium Stage	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Doorframe	Metal	Blue	Friction	3	0.2	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	pipe	Metal	Red	None	0	0.2	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Pan	Metal	White	None	0	0.1	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Post	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Railing	Metal	Blue	None	0	0.2	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Stringer	Metal	White	None	0	1.1	Positive
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Ceiling	Metal	White	None	0	0.4	Negative
4290	2	B429001	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	W1	CMU	White	None	0	0	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	W3	CMU	White	None	0	0.3	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	pipe	Metal	Red	None	0	0.1	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Post	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Railing	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Stringer	Metal	White	None	0	0.3	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Ceiling	Metal	White	None	0	0.1	Negative
4290	2	B429001	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	200 A-1	Hallway outside of Library 202	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	200 A-1	Hallway outside of Library 202	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	2	200 A-1	Hallway outside of Library 202	W2	CMU	Blue	None	0	0.1	Negative
4290	2	B429001	2	200 A-1	Hallway outside of Library 202	Windowframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	2	200 A-1	Hallway outside of Library 202	W3	CMU	Blue	None	0	0	Negative
4290	2	B429001	2	200 A-1	Hallway outside of Library 202	W4	CMU	White	None	0	0	Negative
4290	2	B429001	2	200 A-1	Hallway outside of Library 202	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	200 A-1	Hallway outside of Library 202	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	201	Conference Room 201	W1	CMU	White	None	0	0.4	Negative
4290	2	B429001	2	201	Conference Room 202	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	2	201	Conference Room 201	W2	CMU	White	None	0	0	Negative
4290	2	B429001	2	201	Conference Room 201	W3	CMU	White	None	0	0	Negative
4290	2	B429001	2	201	Conference Room 201	W4	CMU	White	None	0	0.4	Negative
4290	2	B429001	2	201	Conference Room 202	Column	CMU	White	None	0	0	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	2	201	Conference Room 201	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	201	Conference Room 201	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	202	Library	W1	CMU	Yellow	None	0	0.1	Negative
4290	2	B429001	2	202	Library	Doorframe	Metal	Blue	Chipping	4	0.4	Negative
4290	2	B429001	2	202	Library	W2	CMU	Yellow	None	0	0.2	Negative
4290	2	B429001	2	202	Library	Conduit	Metal	Yellow	None	0	0.1	Negative
4290	2	B429001	2	202	Library	Windowframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	2	202	Library	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	202	Library	W4	CMU	Yellow	None	0	0.2	Negative
4290	2	B429001	2	202	Library	Column	CMU	Blue	None	0	0.1	Negative
4290	2	B429001	2	202	Library	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	202	Library	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	202A	Library Storage Room	W1	CMU	White	None	0	0	Negative
4290	2	B429001	2	202A	Library Storage Room	Doorframe	Metal	Blue	None	0	0.5	Negative
4290	2	B429001	2	202A	Library Storage Room	Windowframe	Metal	Blue	None	0	0	Negative
4290	2	B429001	2	202A	Library Storage Room	W2	CMU	White	None	0	0	Negative
4290	2	B429001	2	202A	Library Storage Room	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	202A	Library Storage Room	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	202A	Library Storage Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	202A	Library Storage Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	203	Computer Classroom 203	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	203	Computer Classroom 203	Doorframe	Metal	Blue	Chipping	3	0.4	Negative
4290	2	B429001	2	203	Computer Classroom 203	Conduit	Metal	White	None	0	0.2	Negative
4290	2	B429001	2	203	Computer Classroom 203	W2	CMU	Green	None	0	0	Negative
4290	2	B429001	2	203	Computer Classroom 203	W3	CMU	White	None	0	0	Negative
4290	2	B429001	2	203	Computer Classroom 203	W4	CMU	White	None	0	0	Negative
4290	2	B429001	2	203	Computer Classroom 203	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	203	Computer Classroom 203	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	203B	Electrical Room 203B	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	203B	Electrical Room 203B	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	2	203B	Electrical Room 203B	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	203B	Electrical Room 203B	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	203B	Electrical Room 203B	Conduit	Metal	White	None	0	0.2	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	2	B429001	2	203B	Electrical Room 203B	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	203B	Electrical Room 203B	Stairs	Wood	Grey	Chipping	2	0.3	Negative
4290	2	B429001	2	203B	Electrical Room 203B	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	203B	Electrical Room 203B	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	W1	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	W2	CMU	White	None	0	0	Negative
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	Railing	Metal	Blue	None	0	0	Negative
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	Post	Metal	Blue	None	0	0	Negative
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	Stringer	Metal	White	None	0	0.3	Negative
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	Stair A-2	Stairwell A-2 next to Library 202	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	W1	CMU	White	None	0	0.2	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Doorframe	Metal	Blue	None	0	0	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Railing	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Post	Metal	Blue	None	0	0.1	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Stringer	Metal	White	None	0	0.3	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	W2	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	W3	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	W4	CMU	White	None	0	0.1	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Pipe	Metal	Red	None	0	0.2	Negative
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	2	B429001	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	W1	N/A	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	W3	CMU	Yellow	None	0	0.4	Negative
4290	3	B429001	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	W4	CMU	Yellow	None	0	0.2	Negative
4290	3	B429001	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	Doorframe	Metal	Blue	Friction	2	0	Negative
4290	3	B429001	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	W2	CMU	White	None	0	0.4	Negative
4290	3	B429001	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	W3	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-3	Hallway from Classrooms 124 - 126	W1	CMU	White	None	0	0	Negative
4290	3	B429001	1	100 B-3	Hallway from Classrooms 124 - 126	W2	CMU	Yellow	None	0	0	Negative
4290	3	B429001	1	100 B-3	Hallway from Classrooms 124 - 126	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	100 B-3	Hallway from Classrooms 124 - 126	W4	CMU	Yellow	None	0	0	Negative
4290	3	B429001	1	100 B-3	Hallway from Classrooms 124 - 126	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-3	Hallway from Classrooms 124 - 126	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	door	Metal	Blue	None	0	0	Negative
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	W2	CMU	White	None	0	0	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	W3	CMU	White	None	0	0.3	Negative
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Railing	Metal	Blue	Flaking	10	0.1	Negative
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Post	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Stringer	Metal	White	None	0	0	Negative
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	W1	CMU	White	None	0	0.3	Negative
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	Conduit	Metal	White	None	0	0.1	Negative
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	Ceiling	Metal	White	None	0	0.1	Negative
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	Duct	Metal	White	None	0	0.1	Negative
4290	3	B429001	1	100D	Elevator Machine Room next to Elevator 2	Floor	Concrete	Grey	None	0	0.4	Negative
4290	3	B429001	1	100E	Women's Restroom between Classrooms 125 and 126	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100E	Women's Restroom between Classrooms 125 and 126	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	1	100E	Women's Restroom between Classrooms 125 and 126	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	100E	Women's Restroom between Classrooms 125 and 126	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	100E	Women's Restroom between Classrooms 125 and 126	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100E	Women's Restroom between Classrooms 125 and 126	Ceiling	Drywall	White	None	0	0	Negative
4290	3	B429001	1	100E	Women's Restroom between Classrooms 125 and 126	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	100F	Men's Restroom next to Classroom 124	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100F	Men's Restroom next to Classroom 124	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	1	100F	Men's Restroom next to Classroom 124	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	100F	Men's Restroom next to Classroom 124	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	100F	Men's Restroom next to Classroom 124	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	100F	Men's Restroom next to Classroom 124	Ceiling	Drywall	White	None	0	0	Negative
4290	3	B429001	1	100F	Men's Restroom next to Classroom 124	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	116	Special Ed Classroom 116	W1	CMU	White	None	0	0.3	Negative
4290	3	B429001	1	116	Special Ed Classroom 116	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	1	116	Special Ed Classroom 116	W2	CMU	White	None	0	0	Negative
4290	3	B429001	1	116	Special Ed Classroom 116	W3	CMU	Yellow	None	0	0.1	Negative
4290	3	B429001	1	116	Special Ed Classroom 116	W4	CMU	White	None	0	0	Negative
4290	3	B429001	1	116	Special Ed Classroom 116	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	116	Special Ed Classroom 116	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	117	Office 117 between Classroom 116 and Music Room	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	117	Office 117 between Classroom 116 and Music Room	Doorframe	Metal	Blue	Chipping	2	0.2	Negative
4290	3	B429001	1	117	Office 117 between Classroom 116 and Music Room	W2	CMU	White	None	0	0	Negative
4290	3	B429001	1	117	Office 117 between Classroom 116 and Music Room	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	117	Office 117 between Classroom 116 and Music Room	W4	CMU	Blue	None	0	0	Negative
4290	3	B429001	1	117	Office 117 between Classroom 116 and Music Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	117	Office 117 between Classroom 116 and Music Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	118	Exit Vestibule between Classrooms 116 and 118	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	118	Exit Vestibule between Classrooms 116 and 118	Doorframe	Metal	Blue	None	0	0.6	Negative
4290	3	B429001	1	118	Exit Vestibule between Classrooms 116 and 118	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	118	Exit Vestibule between Classrooms 116 and 118	W3	CMU	White	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	118	Exit Vestibule between Classrooms 116 and 118	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	118	Exit Vestibule between Classrooms 116 and 118	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	118	Exit Vestibule between Classrooms 116 and 118	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	119	Music Room next to Boiler Room	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	119	Music Room next to Boiler Room	Doorframe	Metal	Blue	Friction	5	0.5	Negative
4290	3	B429001	1	119	Music Room next to Boiler Room	W2	CMU	White	None	0	0	Negative
4290	3	B429001	1	119	Music Room next to Boiler Room	W3	CMU	Yellow	None	0	0	Negative
4290	3	B429001	1	119	Music Room next to Boiler Room	W4	CMU	White	None	0	0	Negative
4290	3	B429001	1	119	Music Room next to Boiler Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	119	Music Room next to Boiler Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	119A	Music Room Closet	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	119A	Music Room Closet	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	1	119A	Music Room Closet	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	119A	Music Room Closet	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	119A	Music Room Closet	W4	CMU	White	None	0	0	Negative
4290	3	B429001	1	119A	Music Room Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	119A	Music Room Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	120	Boiler Room 120	W1	CMU	White	None	0	0	Negative
4290	3	B429001	1	120	Boiler Room 120	Doorframe	Metal	Blue	Friction	1	0.5	Negative
4290	3	B429001	1	120	Boiler Room 120	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	120	Boiler Room 120	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	120	Boiler Room 120	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	120	Boiler Room 120	Conduit	Metal	White	Chipping	4	0.3	Negative
4290	3	B429001	1	120	Boiler Room 120	Ceiling	Metal	White	None	0	0.1	Negative
4290	3	B429001	1	120	Boiler Room 120	Floor	Concrete	Grey	Friction	75	0.2	Negative
4290	3	B429001	1	121	Electrical Room 121	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	121	Electrical Room 121	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	1	121	Electrical Room 121	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	1	121	Electrical Room 121	W2	CMU	White	None	0	0	Negative
4290	3	B429001	1	121	Electrical Room 121	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	121	Electrical Room 121	W4	CMU	White	None	0	0	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	121	Electrical Room 121	Ceiling	Metal	White	None	0	0.1	Negative
4290	3	B429001	1	121	Electrical Room 121	pipe	Metal	Red	None	0	0.1	Negative
4290	3	B429001	1	121	Electrical Room 121	Conduit	Metal	White	None	0	0.1	Negative
4290	3	B429001	1	121	Electrical Room 121	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	122	Fire Pump Room 122	W1	CMU	White	None	0	0	Negative
4290	3	B429001	1	122	Fire Pump Room 122	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	122	Fire Pump Room 122	door	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	1	122	Fire Pump Room 122	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	122	Fire Pump Room 122	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	122	Fire Pump Room 122	pipe	Metal	White	None	0	0.1	Negative
4290	3	B429001	1	122	Fire Pump Room 122	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	122	Fire Pump Room 122	Ceiling	Metal	White	Flaking	2	0.2	Negative
4290	3	B429001	1	122	Fire Pump Room 122	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	123	Classroom 123	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	123	Classroom 123	Doorframe	Metal	Blue	Friction	1	0.2	Negative
4290	3	B429001	1	123	Classroom 123	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	123	Classroom 123	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	123	Classroom 123	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	123	Classroom 123	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	123	Classroom 123	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	123A	Classroom 123 Restroom	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	123A	Classroom 123 Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	1	123A	Classroom 123 Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	123A	Classroom 123 Restroom	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	123A	Classroom 123 Restroom	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	123A	Classroom 123 Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
4290	3	B429001	1	123A	Classroom 123 Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	124	Classroom 124	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	124	Classroom 124	Doorframe	Metal	Blue	Friction	2	0.4	Negative
4290	3	B429001	1	124	Classroom 124	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	124	Classroom 124	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	124	Classroom 124	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	124	Classroom 124	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	124	Classroom 124	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	124A	Classroom 124 Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	124A	Classroom 124 Restroom	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	124A	Classroom 124 Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	124A	Classroom 124 Restroom	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	124A	Classroom 124 Restroom	W4	CMU	White	None	0	0	Negative
4290	3	B429001	1	124A	Classroom 124 Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
4290	3	B429001	1	124A	Classroom 124 Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	125	Classroom 125	W1	CMU	White	None	0	0	Negative
4290	3	B429001	1	125	Classroom 125	Doorframe	Metal	Blue	Friction	4	0.2	Negative
4290	3	B429001	1	125	Classroom 125	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	125	Classroom 125	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	125	Classroom 125	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	125	Classroom 125	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	125	Classroom 125	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	125A	Classroom 125 Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	125A	Classroom 125 Restroom	Doorframe	Metal	Blue	Friction	1	0.4	Negative
4290	3	B429001	1	125A	Classroom 125 Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	125A	Classroom 125 Restroom	W3	CMU	White	None	0	0.3	Negative
4290	3	B429001	1	125A	Classroom 125 Restroom	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	125A	Classroom 125 Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
4290	3	B429001	1	125A	Classroom 125 Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	126	Classroom 126	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	126	Classroom 126	Doorframe	Metal	Blue	Friction	3	0.1	Negative
4290	3	B429001	1	126	Classroom 126	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	126	Classroom 126	W3	CMU	White	None	0	0.3	Negative
4290	3	B429001	1	126	Classroom 126	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	126	Classroom 126	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	126	Classroom 126	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	126A	Classroom 126 Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	126A	Classroom 126 Restroom	Doorframe	Metal	Blue	Friction	3	0.1	Negative
4290	3	B429001	1	126A	Classroom 126 Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	126A	Classroom 126 Restroom	W3	CMU	White	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATT Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	126A	Classroom 126 Restroom	W4	CMU	White	None	0	0	Negative
4290	3	B429001	1	126A	Classroom 126 Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
4290	3	B429001	1	126A	Classroom 126 Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	W3	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	129	Classroom 127	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	129	Classroom 127	Doorframe	Metal	Blue	Friction	2	0.1	Negative
4290	3	B429001	1	129	Classroom 127	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	129	Classroom 127	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	129	Classroom 127	W4	CMU	Yellow	None	0	0.2	Negative
4290	3	B429001	1	129	Classroom 127	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	129	Classroom 127	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	130	Office next to Classroom 127	W1	CMU	White	None	0	0	Negative
4290	3	B429001	1	130	Office next to Classroom 127	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	130	Office next to Classroom 127	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	130	Office next to Classroom 127	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	130	Office next to Classroom 127	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	130	Office next to Classroom 127	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	130	Office next to Classroom 127	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	131	Faculty Lounge next to Kindergarten Wing double doors	W1	CMU	White	None	0	0	Negative
4290	3	B429001	1	131	Faculty Lounge next to Kindergarten Wing double doors	Doorframe	Metal	Blue	Friction	1	0.3	Negative
4290	3	B429001	1	131	Faculty Lounge next to Kindergarten Wing double doors	W2	CMU	White	None	0	0	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	131	Faculty Lounge next to Kindergarten Wing double doors	W3	CMU	White	None	0	0	Negative
4290	3	B429001	1	131	Faculty Lounge next to Kindergarten Wing double doors	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	131	Faculty Lounge next to Kindergarten Wing double doors	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	131	Faculty Lounge next to Kindergarten Wing double doors	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	CAB2	Elevator 2 across from Classroom 116	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	CAB2	Elevator 2 across from Classroom 116	W2	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	CAB2	Elevator 2 across from Classroom 116	W3	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	CAB2	Elevator 2 across from Classroom 116	W4	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	CAB2	Elevator 2 across from Classroom 116	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	CAB2	Elevator 2 across from Classroom 116	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	W1	CMU	White	None	0	0	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Doorframe	Metal	Blue	None	0	0.5	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Railing	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Post	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Stringer	Metal	White	None	0	0.3	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Stair Pan	Metal	White	None	0	0.6	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	pipe	Metal	Red	None	0	0	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	W4	CMU	White	None	0	0	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Ceiling	Metal	White	None	0	0.2	Negative
4290	3	B429001	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATT Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Railing	Metal	Blue	Flaking	40	0.1	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Post	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Stringer	Metal	White	None	0	0.3	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Stair Pan	Metal	White	None	0	0.2	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	pipe	Metal	Red	None	0	0.1	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	W3	CMU	White	None	0	0.4	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Ceiling	Metal	White	None	0	0.2	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Duct Insulation	Fiberglass	White	None	0	0	Negative
4290	3	B429001	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-1	Hallway outside of Classrooms 204 -207	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-1	Hallway outside of Classrooms 204 -207	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	200 B-1	Hallway outside of Classrooms 204 -207	W3	CMU	Blue	None	0	0	Negative
4290	3	B429001	2	200 B-1	Hallway outside of Classrooms 204 -207	W4	CMU	Blue	None	0	0.2	Negative
4290	3	B429001	2	200 B-1	Hallway outside of Classrooms 204 -207	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-1	Hallway outside of Classrooms 204 -207	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-2	Hallway outside of Classrooms 208 -209	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-2	Hallway outside of Classrooms 208 -209	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200 B-2	Hallway outside of Classrooms 208 -209	W3	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-2	Hallway outside of Classrooms 208 -209	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200 B-2	Hallway outside of Classrooms 208 -209	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-2	Hallway outside of Classrooms 208 -209	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-3	Hallway outside of Classrooms 211 -215	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-3	Hallway outside of Classrooms 211 -215	W2	CMU	Blue	None	0	0.2	Negative
4290	3	B429001	2	200 B-3	Hallway outside of Classrooms 211 -215	W3	CMU	Blue	None	0	0	Negative
4290	3	B429001	2	200 B-3	Hallway outside of Classrooms 211 -215	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200 B-3	Hallway outside of Classrooms 211 -215	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-3	Hallway outside of Classrooms 211 -215	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-4	Hallway outside of Restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-4	Hallway outside of Restrooms	W2	CMU	Blue	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATT Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	2	200 B-4	Hallway outside of Restrooms	W3	CMU	White	None	0	0	Negative
4290	3	B429001	2	200 B-4	Hallway outside of Restrooms	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	200 B-4	Hallway outside of Restrooms	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200 B-4	Hallway outside of Restrooms	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200A	Hall Closet next to Women's Restroom	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	200A	Hall Closet next to Women's Restroom	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	2	200A	Hall Closet next to Women's Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200A	Hall Closet next to Women's Restroom	W3	no access	White	None	0	0.1	Negative
4290	3	B429001	2	200A	Hall Closet next to Women's Restroom	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200A	Hall Closet next to Women's Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200A	Hall Closet next to Women's Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200B	Women's Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200B	Women's Restroom	Doorframe	Metal	Blue	None	0	0.7	Positive
4290	3	B429001	2	200B	Women's Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200B	Women's Restroom	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	200B	Women's Restroom	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200B	Women's Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200B	Women's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200C	Custodial Closet	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200C	Custodial Closet	Doorframe	Metal	Blue	Friction	4	0.3	Negative
4290	3	B429001	2	200C	Custodial Closet	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200C	Custodial Closet	W3	CMU	White	None	0	0.4	Negative
4290	3	B429001	2	200C	Custodial Closet	Step	Concrete	Grey	None	0	0.1	Negative
4290	3	B429001	2	200C	Custodial Closet	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200C	Custodial Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200C	Custodial Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200D	Men's Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200D	Men's Restroom	Doorframe	Metal	Blue	None	0	0.7	Positive
4290	3	B429001	2	200D	Men's Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200D	Men's Restroom	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	200D	Men's Restroom	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200D	Men's Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	200D	Men's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	2	200E	Electrical Room next to Boy's Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200E	Electrical Room next to Boy's Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	2	200E	Electrical Room next to Boy's Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200E	Electrical Room next to Boy's Restroom	W3	CMU	White	None	0	0.3	Negative
4290	3	B429001	2	200E	Electrical Room next to Boy's Restroom	Duct	Metal	White	None	0	0.2	Negative
4290	3	B429001	2	200E	Electrical Room next to Boy's Restroom	W4	CMU	White	None	0	0	Negative
4290	3	B429001	2	200E	Electrical Room next to Boy's Restroom	Ceiling	Metal	No Access	No Access	No Access	No Access	No Access
4290	3	B429001	2	200E	Electrical Room next to Boy's Restroom	Floor	Concrete	Grey	Friction	6	0.3	Negative
4290	3	B429001	2	200F	Telecomm Room across from Classroom 204	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200F	Telecomm Room across from Classroom 204	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	2	200F	Telecomm Room across from Classroom 204	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	200F	Telecomm Room across from Classroom 204	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	200F	Telecomm Room across from Classroom 204	W4	CMU	White	None	0	0.5	Negative
4290	3	B429001	2	200F	Telecomm Room across from Classroom 204	Ceiling	Metal	No Access	No Access	No Access	No Access	No Access
4290	3	B429001	2	200F	Telecomm Room across from Classroom 204	Floor	Concrete	Grey	Friction	6	0.3	Negative
4290	3	B429001	2	204	Classroom 204	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	204	Classroom 204	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	2	204	Classroom 204	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	204	Classroom 204	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	204	Classroom 204	W4	CMU	White	None	0	0.5	Negative
4290	3	B429001	2	204	Classroom 204	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	204	Classroom 204	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	205	Classroom 205	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	205	Classroom 205	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	2	205	Classroom 205	W2	CMU	White	None	0	0	Negative
4290	3	B429001	2	205	Classroom 205	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	205	Classroom 205	W4	CMU	White	None	0	0	Negative
4290	3	B429001	2	205	Classroom 205	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	2	205	Classroom 205	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	206	Classroom 206	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	206	Classroom 206	Doorframe	Metal	Blue	None	0	0.5	Negative
4290	3	B429001	2	206	Classroom 206	W2	CMU	White	None	0	0	Negative
4290	3	B429001	2	206	Classroom 206	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	206	Classroom 206	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	206	Classroom 206	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	206	Classroom 206	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	207	Classroom 207	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	207	Classroom 207	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	2	207	Classroom 207	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	207	Classroom 207	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	207	Classroom 207	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	207	Classroom 207	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	207	Classroom 207	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	208	Classroom 208	W1	CMU	White	None	0	0.3	Negative
4290	3	B429001	2	208	Classroom 208	Doorframe	Metal	Blue	None	0	0	Negative
4290	3	B429001	2	208	Classroom 208	W2	CMU	White	None	0	0	Negative
4290	3	B429001	2	208	Classroom 208	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	208	Classroom 208	W4	CMU	Blue	None	0	0.1	Negative
4290	3	B429001	2	208	Classroom 208	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	208	Classroom 208	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	209	Classroom 209	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	209	Classroom 209	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	2	209	Classroom 209	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	209	Classroom 209	W3	CMU	Blue	None	0	0.1	Negative
4290	3	B429001	2	209	Classroom 209	W4	CMU	White	None	0	0.3	Negative
4290	3	B429001	2	209	Classroom 209	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	209	Classroom 209	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	210	Office 210	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	210	Office 210	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	2	210	Office 210	W2	CMU	White	None	0	0	Negative
4290	3	B429001	2	210	Office 210	W3	CMU	Blue	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	2	210	Office 210	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	210	Office 210	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	210	Office 210	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	211	Classroom 211	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	211	Classroom 211	Doorframe	Metal	Blue	Friction	4	0.3	Negative
4290	3	B429001	2	211	Classroom 211	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	211	Classroom 211	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	211	Classroom 211	W4	CMU	White	None	0	0	Negative
4290	3	B429001	2	211	Classroom 211	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	211	Classroom 211	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	212	Classroom 212	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	212	Classroom 212	Doorframe	Metal	Blue	Friction	1	0.3	Negative
4290	3	B429001	2	212	Classroom 212	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	212	Classroom 212	W3	CMU	White	None	0	0	Negative
4290	3	B429001	2	212	Classroom 212	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	212	Classroom 212	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	212	Classroom 212	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	213	Classroom 213	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	213	Classroom 213	Doorframe	Metal	Blue	Friction	3	0.1	Negative
4290	3	B429001	2	213	Classroom 213	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	213	Classroom 213	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	213	Classroom 213	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	213	Classroom 213	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	213	Classroom 213	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	214	Classroom 214	W1	CMU	White	None	0	0	Negative
4290	3	B429001	2	214	Classroom 214	Doorframe	Metal	Blue	Friction	6	0.2	Negative
4290	3	B429001	2	214	Classroom 214	W2	CMU	White	None	0	0	Negative
4290	3	B429001	2	214	Classroom 214	W3	CMU	White	None	0	0	Negative
4290	3	B429001	2	214	Classroom 214	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	214	Classroom 214	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	214	Classroom 214	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	215	Classroom 215	W1	CMU	White	None	0	0	Negative
4290	3	B429001	2	215	Classroom 215	Doorframe	Metal	Blue	Friction	4	0.5	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	2	215	Classroom 215	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	215	Classroom 215	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	215	Classroom 215	W4	CMU	White	None	0	0	Negative
4290	3	B429001	2	215	Classroom 215	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	215	Classroom 215	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	216	Classroom 216	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	216	Classroom 216	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	2	216	Classroom 216	W2	CMU	White	None	0	0	Negative
4290	3	B429001	2	216	Classroom 216	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	216	Classroom 216	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	216	Classroom 216	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	216	Classroom 216	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	217	Girl's Student Restroom	W1	CMU	Yellow	None	0	0.3	Negative
4290	3	B429001	2	217	Girl's Student Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	2	217	Girl's Student Restroom	W2	CMU	Yellow	None	0	0	Negative
4290	3	B429001	2	217	Girl's Student Restroom	W3	CMU	Yellow	None	0	0.1	Negative
4290	3	B429001	2	217	Girl's Student Restroom	W4	CMU	Yellow	None	0	0.2	Negative
4290	3	B429001	2	217	Girl's Student Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
4290	3	B429001	2	217	Girl's Student Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	218	Boy's Student Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	218	Boy's Student Restroom	Doorframe	Metal	Blue	Friction	1	0.4	Negative
4290	3	B429001	2	218	Boy's Student Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	218	Boy's Student Restroom	W3	Drywall	White	None	0	0	Negative
4290	3	B429001	2	218	Boy's Student Restroom	W4	CMU	White	None	0	0.3	Negative
4290	3	B429001	2	218	Boy's Student Restroom	Ceiling	Drywall	White	None	0	0	Negative
4290	3	B429001	2	218	Boy's Student Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	Doorframe	Metal	Blue	Friction	1	0.5	Negative
4290	3	B429001	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	W3	CMU	White	None	0	0.2	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	Duct	Metal	White	None	0	0	Negative
4290	3	B429001	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	W4	CMU	White	None	0	0	Negative
4290	3	B429001	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	Ceiling	Metal	No Access	No Access	No Access	No Access	No Access
4290	3	B429001	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	W1	CMU	White	None	0	0	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	Doorframe	Metal	Blue	None	0	0.4	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	Post	Metal	Blue	None	0	0	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	pan	Metal	White	None	0	0.7	Positive
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	Railing	Metal	Blue	Flaking	10	0.2	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	Stringer	Metal	White	Friction	14	0.2	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	W3	CMU	White	None	0	0	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	pipe	Metal	Red	None	0	0.3	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	Ceiling	Metal	White	None	0	0.1	Negative
4290	3	B429001	2	Stair C-2	Stairwell C-2 next to Classroom 215	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	Doorframe	Metal	Blue	None	0	0.5	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	Railing	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	Post	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	Stringer	Metal	White	None	0	0.3	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	pan	Metal	White	None	0	0	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	pipe	Metal	Red	Chipping	2	0.1	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	W3	CMU	White	None	0	0	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	W4	CMU	White	None	0	0	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	Ceiling	Metal	White	None	0	0	Negative
4290	3	B429001	2	Stair D-2	Stairwell D-2 next to Classroom 207	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-1	Hallway outside of Classrooms 301 - 304	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-1	Hallway outside of Classrooms 301 - 304	W2	CMU	White	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	3	300 B-1	Hallway outside of Classrooms 301 - 304	Mural	CMU	multi	None	0	0.1	Negative
4290	3	B429001	3	300 B-1	Hallway outside of Classrooms 301 - 304	W3	CMU	Green	None	0	0.1	Negative
4290	3	B429001	3	300 B-1	Hallway outside of Classrooms 301 - 304	W4	CMU	Green	None	0	0	Negative
4290	3	B429001	3	300 B-1	Hallway outside of Classrooms 301 - 304	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-1	Hallway outside of Classrooms 301 - 304	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-2	Hallway outside of Science Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-2	Hallway outside of Science Classroom 305	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300 B-2	Hallway outside of Science Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-2	Hallway outside of Science Classroom 305	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300 B-2	Hallway outside of Science Classroom 305	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-2	Hallway outside of Science Classroom 305	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-3	Hallway outside of Classrooms 307 - 311	W1	CMU	Green	None	0	0.2	Negative
4290	3	B429001	3	300 B-3	Hallway outside of Classrooms 307 - 311	W2	CMU	Green	None	0	0.1	Negative
4290	3	B429001	3	300 B-3	Hallway outside of Classrooms 307 - 311	W3	CMU	White	None	0	0.3	Negative
4290	3	B429001	3	300 B-3	Hallway outside of Classrooms 307 - 311	W4	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-3	Hallway outside of Classrooms 307 - 311	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-3	Hallway outside of Classrooms 307 - 311	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-4	Hallway outside of Restrooms	W1	CMU	Green	None	0	0.1	Negative
4290	3	B429001	3	300 B-4	Hallway outside of Restrooms	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300 B-4	Hallway outside of Restrooms	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300 B-4	Hallway outside of Restrooms	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	300 B-4	Hallway outside of Restrooms	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300 B-4	Hallway outside of Restrooms	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300A	Hall Closet next to Women's Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300A	Hall Closet next to Women's Restroom	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	3	300A	Hall Closet next to Women's Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300A	Hall Closet next to Women's Restroom	W3	CMU	White	No Access	No Access	No Access	No Access
4290	3	B429001	3	300A	Hall Closet next to Women's Restroom	W4	CMU	White	None	0	0	Negative
4290	3	B429001	3	300A	Hall Closet next to Women's Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300A	Hall Closet next to Women's Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300B	Women's Restroom	W1	CMU	White	None	0	0	Negative
4290	3	B429001	3	300B	Women's Restroom	Doorframe	Metal	Blue	Chipping	1	0.5	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	3	300B	Women's Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300B	Women's Restroom	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300B	Women's Restroom	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300B	Women's Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
4290	3	B429001	3	300B	Women's Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300C	Custodial Closet	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300C	Custodial Closet	Doorframe	Metal	Blue	Chipping	2	0.4	Negative
4290	3	B429001	3	300C	Custodial Closet	W2	CMU	White	None	0	0	Negative
4290	3	B429001	3	300C	Custodial Closet	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	300C	Custodial Closet	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	300C	Custodial Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300C	Custodial Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300D	Men's Restroom	W1	CMU	White	None	0	0	Negative
4290	3	B429001	3	300D	Men's Restroom	Doorframe	Metal	Blue	None	0	0.4	Negative
4290	3	B429001	3	300D	Men's Restroom	W2	CMU	White	None	0	0	Negative
4290	3	B429001	3	300D	Men's Restroom	W3	CMU	White	None	0	0	Negative
4290	3	B429001	3	300D	Men's Restroom	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	300D	Men's Restroom	Ceiling	Drywall	White	None	0	0.3	Negative
4290	3	B429001	3	300D	Men's Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	W3	CMU	White	None	0	0	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	W4	CMU	White	None	0	0.4	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	Conduit	Plastic	White	None	0	0.4	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	Ceiling	Metal	White	None	0	0.1	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	Conduit	Metal	White	None	0	0.3	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	Duct	Metal	White	None	0	0.3	Negative
4290	3	B429001	3	300E	Electrical Room next to Boy's Restroom	Floor	Floor Tile	Grey	none	0	0.2	Negative
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	W1	Wood	White	None	0	0.1	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	Doorframe	Metal	Blue	None	0	0.3	Negative
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	Conduit	Metal	White	None	0	0.2	Negative
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	W2	Wood	White	None	0	0	Negative
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	W3	Wood	White	None	0	0	Negative
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	Duct	Metal	White	None	0	0.2	Negative
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	W4	Wood	White	None	0	0.1	Negative
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
4290	3	B429001	3	300F	Telecomm Room across from Classroom 301	Floor	Concrete	Grey	None	0	0.2	Negative
4290	3	B429001	3	301	Classroom 301	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	301	Classroom 301	Doorframe	Metal	Blue	Friction	3	0.2	Negative
4290	3	B429001	3	301	Classroom 301	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	301	Classroom 301	W3	CMU	White	None	0	0	Negative
4290	3	B429001	3	301	Classroom 301	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	301	Classroom 301	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	301	Classroom 301	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	302	Classroom 302	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	302	Classroom 302	Doorframe	Metal	Blue	Friction	5	0.1	Negative
4290	3	B429001	3	302	Classroom 302	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	302	Classroom 302	W3	CMU	White	None	0	0.5	Negative
4290	3	B429001	3	302	Classroom 302	W4	CMU	White	None	0	0.4	Negative
4290	3	B429001	3	302	Classroom 302	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	302	Classroom 302	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	303	Classroom 303	W1	CMU	White	None	0	0	Negative
4290	3	B429001	3	303	Classroom 303	Doorframe	Metal	Blue	Friction	4	0.2	Negative
4290	3	B429001	3	303	Classroom 303	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	303	Classroom 303	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	303	Classroom 303	W4	CMU	White	None	0	0	Negative
4290	3	B429001	3	303	Classroom 303	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	3	303	Classroom 303	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	304	Classroom 304	W1	CMU	White	None	0	0	Negative
4290	3	B429001	3	304	Classroom 304	Doorframe	Metal	Blue	Friction	3	0.5	Negative
4290	3	B429001	3	304	Classroom 304	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	304	Classroom 304	W3	CMU	White	None	0	0	Negative
4290	3	B429001	3	304	Classroom 304	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	304	Classroom 304	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	304	Classroom 304	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	305	Science Classroom 305	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	305	Science Classroom 305	Doorframe	Metal	Blue	Friction	3	0.1	Negative
4290	3	B429001	3	305	Science Classroom 305	W2	CMU	White	None	0	0	Negative
4290	3	B429001	3	305	Science Classroom 305	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	305	Science Classroom 305	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	305	Science Classroom 305	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	305	Science Classroom 305	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	306	Office 306	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	306	Office 306	Doorframe	Metal	Blue	Friction	2	0.5	Negative
4290	3	B429001	3	306	Office 306	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	306	Office 306	W3	CMU	Green	None	0	0	Negative
4290	3	B429001	3	306	Office 306	W4	CMU	White	None	0	0	Negative
4290	3	B429001	3	306	Office 306	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	306	Office 306	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	307	Classroom 307	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	307	Classroom 307	Doorframe	Metal	Blue	Friction	4	0.1	Negative
4290	3	B429001	3	307	Classroom 307	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	307	Classroom 307	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	307	Classroom 307	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	307	Classroom 307	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	307	Classroom 307	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	308	Classroom 308	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	308	Classroom 308	Doorframe	Metal	Blue	Friction	2	0.1	Negative
4290	3	B429001	3	308	Classroom 308	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	308	Classroom 308	W3	CMU	White	None	0	0	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	3	308	Classroom 308	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	308	Classroom 308	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	308	Classroom 308	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	309	Classroom 309	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	309	Classroom 309	Doorframe	Metal	Blue	Friction	2	0.2	Negative
4290	3	B429001	3	309	Classroom 309	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	309	Classroom 309	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	309	Classroom 309	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	309	Classroom 309	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	309	Classroom 309	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	310	Classroom 310	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	310	Classroom 310	Doorframe	Metal	Blue	Friction	2	0.1	Negative
4290	3	B429001	3	310	Classroom 310	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	310	Classroom 310	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	310	Classroom 310	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	310	Classroom 310	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	310	Classroom 310	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	311	Classroom 311	W1	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	311	Classroom 311	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	3	311	Classroom 311	W2	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	311	Classroom 311	W3	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	311	Classroom 311	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	311	Classroom 311	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	311	Classroom 311	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	312	Classroom 312	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	312	Classroom 312	Doorframe	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	3	312	Classroom 312	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	312	Classroom 312	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	312	Classroom 312	W4	CMU	Green	None	0	0.2	Negative
4290	3	B429001	3	312	Classroom 312	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	312	Classroom 312	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	313	Girl's Student Restroom	W1	CMU	Yellow	None	0	0.2	Negative
4290	3	B429001	3	313	Girl's Student Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	3	313	Girl's Student Restroom	W2	CMU	Yellow	None	0	0	Negative
4290	3	B429001	3	313	Girl's Student Restroom	W3	CMU	Yellow	None	0	0	Negative
4290	3	B429001	3	313	Girl's Student Restroom	W4	CMU	Yellow	None	0	0.1	Negative
4290	3	B429001	3	313	Girl's Student Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
4290	3	B429001	3	313	Girl's Student Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	314	Boy's Student Restroom	W1	CMU	White	None	0	0	Negative
4290	3	B429001	3	314	Boy's Student Restroom	Doorframe	Metal	Blue	None	0	0.4	Negative
4290	3	B429001	3	314	Boy's Student Restroom	W2	CMU	White	None	0	0	Negative
4290	3	B429001	3	314	Boy's Student Restroom	W3	Drywall	White	None	0	0	Negative
4290	3	B429001	3	314	Boy's Student Restroom	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	314	Boy's Student Restroom	Ceiling	Drywall	White	None	0	0	Negative
4290	3	B429001	3	314	Boy's Student Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Doorframe	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	W2	CMU	White	None	0	0	Negative
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	W3	CMU	White	None	0	0	Negative
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Ladder	Metal	Blue	None	0	0.2	Negative
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Duct	Metal	White	None	0	0	Negative
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	W4	CMU	White	None	0	0.2	Negative
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Ceiling	Metal	White	None	0	0.1	Negative
4290	3	B429001	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Floor	Concrete	Grey	None	0	0	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	W1	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	Doorframe	Metal	Blue	None	0	0.6	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	W2	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	pipe	Metal	Red	None	0	0.1	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	Railing	Metal	Blue	Chipping	8	0.1	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	Post	Metal	Blue	None	0	0.2	Negative

					Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
					Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
					Inspection Company: BATA Environmental	5720 Media St, Philadelphia PA 19131						
ULCS#	Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	Stringer	Metal	White	Friction	3	0.3	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	pan	Metal	White	None	0	0.1	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	W3	CMU	White	None	0	0	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	Stair C-3	Stairwell C-3 next to Classroom 311	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	W1	CMU	White	None	0	0	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	Doorframe	Metal	Blue	None	0	0.5	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	W2	CMU	White	None	0	0	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	Railing	Metal	Blue	Chipping	1	0.1	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	Post	Metal	Blue	None	0	0.1	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	Stringer	Metal	White	None	0	0.3	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	pan	Metal	White	None	0	0.1	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	pipe	Metal	Red	None	0	0.1	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	W3	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	W4	CMU	White	None	0	0.1	Negative
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	3	Stair D-3	Stairwell D-3 next to Classroom 304	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	AT	AT	Attic - None	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	AT	AT	Attic - None	W2	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	AT	AT	Attic - None	W3	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	AT	AT	Attic - None	W4	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	AT	AT	Attic - None	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	AT	AT	Attic - None	Floor	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	CS	CS	Crawl Space - None	W1	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	CS	CS	Crawl Space - None	W2	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	CS	CS	Crawl Space - None	W3	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	CS	CS	Crawl Space - None	W4	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	CS	CS	Crawl Space - None	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
4290	3	B429001	CS	CS	Crawl Space - None	Floor	N/A	N/A	N/A	N/A	N/A	N/A

[1] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the comments. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.

[2] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."

[3] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.