

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Boiler Room	Door Casing	Metal	Blue	None	0	0.5	Negative
1	B	Boiler Room	Door	Metal	Blue	None	0	0	Negative
1	B	Boiler Room	sink	ceramic	Gray	Flaking	0	0.3	Negative
1	B	Boiler Room	Door	Metal	Blue	None	0	0	Negative
1	B	Boiler Room	Door Casing	Metal	Blue	None	0	0.4	Negative
1	B	Boiler Room	Pipe	Metal	Yellow	None	0	0.9	Positive
1	B	Boiler Room	Pipe	Metal	Red	None	0	0.3	Negative
1	B	Boiler Room Stairs to Exterior	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Stairs to Exterior	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Stairs to Exterior	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Stairs to Exterior	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Stairs to Exterior	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Stairs to Exterior	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Incinerator Room	W1	CMU	Gray	None	0	0.1	Negative
1	B	Incinerator Room	W2	Concrete	Gray	None	0	0.1	Negative
1	B	Incinerator Room	W4	CMU	Gray	None	0	0.1	Negative
1	B	Incinerator Room	Door	Metal	Purple	None	0	0	Negative
1	B	Incinerator Room	Door Casing	Metal	Purple	None	0	0.1	Negative
1	B	Hallway/Vestibule outside Boiler Room	Stairs - Railing	Metal	Brown	None	0	1.2	Positive
1	B	Hallway/Vestibule outside Boiler Room	Door Casing	Metal	Blue	None	0	0.2	Negative
1	B	Hallway/Vestibule outside Boiler Room	Door	Metal	Blue	None	0	0.1	Negative
1	B	Hallway/Vestibule outside Boiler Room	machine	Metal	Gray	None	0	0	Negative
1	B	Stairwell to 1st Floor next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell to 1st Floor next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell to 1st Floor next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell to 1st Floor next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell to 1st Floor next to Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell to 1st Floor next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Storage Room below Stairwell to 1st Floor next to Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room below Stairwell to 1st Floor next to Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room below Stairwell to 1st Floor next to Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Storage Room below Stairwell to 1st Floor next to Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room below Stairwell to 1st Floor next to Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Storage Room below Stairwell to 1st Floor next to Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Vestibule outside School Police Office	W1	CMU	Beige	None	0	0	Negative
1	B	Vestibule outside School Police Office	W2	CMU	Beige	None	0	0.5	Negative
1	B	Vestibule outside School Police Office	W3	CMU	Beige	None	0	0.2	Negative
1	B	Vestibule outside School Police Office	W4	CMU	Beige	None	0	0.2	Negative
1	B	Vestibule outside School Police Office	Door Casing	Metal	Beige	None	0	0.2	Negative
1	B	Vestibule outside School Police Office	Door	Metal	Beige	None	0	0	Negative
1	B	Vestibule outside School Police Office	Door	Metal	Blue	None	0	0.1	Negative
1	B	Vestibule outside School Police Office	Door Center Post	Metal	Blue	None	0	0.6	Negative
1	B	Vestibule outside School Police Office	Door Casing	Metal	Blue	None	0	0.3	Negative
1	1	Main Office	W1	CMU	Orange	None	0	0.2	Negative
1	1	Main Office	W2	CMU	White	None	0	0.1	Negative
1	1	Main Office	W4	CMU	Orange	None	0	0.1	Negative
1	1	Main Office	W3	CMU	White	None	0	0.2	Negative
1	1	Main Office	Door Casing	Metal	Brown	None	0	0.5	Negative
1	1	Main Office	Door Casing	Metal	Brown	None	0	0.2	Negative
1	1	Main Office	Door Casing	Metal	Brown	None	0	0.2	Negative
1	1	Main Office	Door Casing	Metal	Brown	None	0	0.3	Negative
1	1	Main Office	Door	Wood	Tan	None	0	0.1	Negative
1	1	Main Office	Door	Wood	Tan	None	0	0.1	Negative
1	1	Main Office	Door	Wood	Blue	None	0	0.1	Negative
1	1	Main Office Mail Room	W1	CMU	Beige	None	0	0.4	Negative
1	1	Main Office Mail Room	W2	CMU	Beige	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Main Office Mail Room	W3	CMU	Beige	None	0	0.2	Negative
1	1	Main Office Mail Room	W4	CMU	Beige	None	0	0	Negative
1	1	Main Office Mail Room	Door Casing	Metal	Beige	None	0	0.4	Negative
1	1	Main Office Mail Room	Door	Wood	Tan	None	0	0	Negative
1	1	Main Office Mail Room	Door Casing	Metal	Brown	None	0	0.4	Negative
1	1	Principal's Office	W1	CMU	White	None	0	0.2	Negative
1	1	Principal's Office	W2	CMU	White	None	0	0.2	Negative
1	1	Principal's Office	W3	CMU	White	None	0	0.1	Negative
1	1	Principal's Office	W4	CMU	White	None	0	0.1	Negative
1	1	Principal's Office	Door	Wood	Tan	None	0	0.1	Negative
1	1	Principal's Office	Door Casing	Metal	Brown	None	0	0.3	Negative
1	1	Principal's Office	Door Casing	Metal	Tan	None	0	0.4	Negative
1	1	Principal's Office	Door	Metal	Tan	None	0	0	Negative
1	1	Principal's Office Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	1	Principal's Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Conference Room	W1	CMU	Blue	None	0	0.1	Negative
1	1	Conference Room	W4	CMU	Blue	None	0	0.1	Negative
1	1	Conference Room	W3	CMU	Blue	None	0	0.1	Negative
1	1	Conference Room	W2	CMU	Blue	None	0	0.1	Negative
1	1	Conference Room	Door	Wood	Blue	None	0	0.1	Negative
1	1	Conference Room	Door Casing	Metal	Blue	None	0	0.5	Negative
1	1	Conference Room	Univent	Metal	Blue	None	0	0	Negative
1	1	Office next to Conference Room	W1	CMU	White	None	0	0.1	Negative
1	1	Office next to Conference Room	W4	CMU	White	None	0	0.1	Negative
1	1	Office next to Conference Room	W3	CMU	White	None	0	0.1	Negative
1	1	Office next to Conference Room	W2	CMU	White	None	0	0.1	Negative
1	1	Office next to Conference Room	Door	Wood	Tan	None	0	0	Negative
1	1	Office next to Conference Room	Door Casing	Metal	White	None	0	0.2	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Main Office Copy Room	W1	CMU	White	None	0	0.1	Negative
1	1	Main Office Copy Room	W2	CMU	White	None	0	0	Negative
1	1	Main Office Copy Room	W4	CMU	White	None	0	0.1	Negative
1	1	Main Office Copy Room	W3	CMU	White	None	0	0.1	Negative
1	1	Main Office Storage Closet	W1	CMU	Yellow	None	0	0.1	Negative
1	1	Main Office Storage Closet	W4	CMU	Yellow	None	0	0	Negative
1	1	Main Office Storage Closet	W3	CMU	Yellow	None	0	0	Negative
1	1	Main Office Storage Closet	W2	CMU	Yellow	None	0	0.1	Negative
1	1	Main Office Storage Closet	Door Casing	Metal	Brown	None	0	0.5	Negative
1	1	Main Office Storage Closet	Door	Wood	Tan	None	0	0	Negative
1	1	Hallway from Main Office to Nurse's Suite	W1	CMU	Green	None	0	0.1	Negative
1	1	Hallway from Main Office to Nurse's Suite	W3	CMU	Green	None	0	0	Negative
1	1	Hallway from Main Office to Nurse's Suite	W4	CMU	Beige	None	0	0.1	Negative
1	1	Hallway from Main Office to Nurse's Suite	W2	CMU	Beige	None	0	0.1	Negative
1	1	Hallway from Main Office to Nurse's Suite	Door Center POS	Metal	Blue	None	0	0	Negative
1	1	Hallway from Main Office to Nurse's Suite	Door	Metal	Blue	None	0	0.1	Negative
1	1	Hallway from Main Office to Nurse's Suite	Door Casing	Metal	Blue	None	0	0.1	Negative
1	1	Hallway from Main Office to Nurse's Suite	Door Casing	Metal	Beige	None	0	0.2	Negative
1	1	Hallway from Main Office to Nurse's Suite	Door	Metal	Beige	None	0	0	Negative
1	1	Hallway from Main Office to Nurse's Suite	Door Center POS	Metal	Black	None	0	0	Negative
1	1	Hallway from Main Office to Nurse's Suite	Door Casing	Metal	Beige	None	0	0.1	Negative
1	1	Hallway from Main Office to Nurse's Suite	Door	Wood	Beige	None	0	0.1	Negative
1	1	Hallway from Main Office to Nurse's Suite	Univent	Metal	Beige	None	0	0	Negative
1	1	Hallway from Main Office to 4 Administrative Offices	W1	CMU	Beige	None	0	0	Negative
1	1	Hallway from Main Office to 4 Administrative Offices	W4	CMU	Beige	None	0	0.1	Negative
1	1	Hallway from Main Office to 4 Administrative Offices	W3	CMU	Beige	None	0	0	Negative
1	1	Hallway from Main Office to 4 Administrative Offices	W2	CMU	Beige	None	0	0.1	Negative
1	1	Hallway from Main Office to 4 Administrative Offices	Door Casing	Metal	Blue	None	0	0.5	Negative
1	1	Hallway from Main Office to 4 Administrative Offices	Door	Wood	Blue	None	0	0.1	Negative
1	1	Hallway from Main Office to 4 Administrative Offices	Door	Wood	Blue	None	0	0.1	Negative
1	1	Hallway from Main Office to 4 Administrative Offices	Door Casing	Metal	Blue	None	0	0.4	Negative
1	1	1st Right Administrative Office in Main Office Suite	Door	Wood	Blue	None	0	0.1	Negative
1	1	1st Right Administrative Office in Main Office Suite	Door Casing	Metal	Blue	None	0	0.5	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	1st Right Administrative Office in Main Office Suite	W1	CMU	Beige	None	0	0.2	Negative
1	1	1st Right Administrative Office in Main Office Suite	W4	CMU	Beige	None	0	0.1	Negative
1	1	1st Right Administrative Office in Main Office Suite	W3	CMU	Beige	None	0	0.1	Negative
1	1	1st Right Administrative Office in Main Office Suite	W2	CMU	Beige	None	0	0.2	Negative
1	1	2nd Right Administrative Office in Main Office Suite	W1	CMU	Beige	None	0	0.1	Negative
1	1	2nd Right Administrative Office in Main Office Suite	W4	CMU	Beige	None	0	0.1	Negative
1	1	2nd Right Administrative Office in Main Office Suite	W3	CMU	Beige	None	0	0	Negative
1	1	2nd Right Administrative Office in Main Office Suite	W2	CMU	Beige	None	0	0	Negative
1	1	2nd Right Administrative Office in Main Office Suite	Door Casing	Metal	Blue	None	0	0.2	Negative
1	1	2nd Right Administrative Office in Main Office Suite	Door	Wood	Blue	None	0	0.1	Negative
1	1	2nd Right Administrative Office in Main Office Suite	Door	Wood	Blue	None	0	0.1	Negative
1	1	2nd Right Administrative Office in Main Office Suite	Door Casing	Metal	Blue	None	0	0.2	Negative
1	1	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	Door Casing	Metal	Blue	None	0	0.3	Negative
1	1	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	Door	Wood	Blue	None	0	0.1	Negative
1	1	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	W1	CMU	Beige	None	0	0.1	Negative
1	1	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	W2	CMU	Beige	None	0	0.1	Negative
1	1	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	W3	CMU	Beige	None	0	0.1	Negative
1	1	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	W4	CMU	Beige	None	0	0	Negative
1	1	1st Left Administrative Office in Main Office Suite	Door	Wood	Black	None	0	0.1	Negative
1	1	1st Left Administrative Office in Main Office Suite	Door Casing	Metal	Black	None	0	0.2	Negative
1	1	1st Left Administrative Office in Main Office Suite	W1	CMU	Beige	None	0	0.1	Negative
1	1	1st Left Administrative Office in Main Office Suite	W4	CMU	Beige	None	0	0	Negative
1	1	1st Left Administrative Office in Main Office Suite	W3	CMU	Beige	None	0	0.1	Negative
1	1	1st Left Administrative Office in Main Office Suite	W2	CMU	Beige	None	0	0	Negative
1	1	2nd Left Administrative Office in Main Office Suite	W1	CMU	Blue	None	0	0	Negative
1	1	2nd Left Administrative Office in Main Office Suite	W4	CMU	Blue	None	0	0	Negative
1	1	2nd Left Administrative Office in Main Office Suite	W3	CMU	Blue	None	0	0.1	Negative
1	1	2nd Left Administrative Office in Main Office Suite	W2	CMU	Blue	None	0	0.2	Negative
1	1	2nd Left Administrative Office in Main Office Suite	Door Casing	Metal	Blue	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia							
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report							
		Inspection Company: Acer Associates	E.W. Rhodes ES School							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	2nd Left Administrative Office in Main Office Suite	Door	Wood	Blue	None	0	0.1	Negative	
1	1	Nurse's Suite - Open Area next to Main Office	Door Casing	Metal	Blue	None	0	0.3	Negative	
1	1	Nurse's Suite - Open Area next to Main Office	Door	Wood	Blue	None	0	0.2	Negative	
1	1	Nurse's Suite - Open Area next to Main Office	W1	CMU	Beige	None	0	0.1	Negative	
1	1	Nurse's Suite - Open Area next to Main Office	W2	CMU	Beige	None	0	0.1	Negative	
1	1	Nurse's Suite - Open Area next to Main Office	W4	CMU	Beige	None	0	0.2	Negative	
1	1	Nurse's Suite - Open Area next to Main Office	W3	CMU	Beige	None	0	0.1	Negative	
1	1	Medical Supply Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Medical Supply Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Medical Supply Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Medical Supply Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Medical Supply Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Medical Supply Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Nurse's Office	W1	CMU	Yellow	None	0	0	Negative	
1	1	Nurse's Office	W2	CMU	Yellow	None	0	0	Negative	
1	1	Nurse's Office	W3	CMU	Yellow	None	0	0.1	Negative	
1	1	Nurse's Office	W4	CMU	Yellow	None	0	0	Negative	
1	1	Nurse's Office	Window Casing	Metal	Blue	None	0	0	Negative	
1	1	Nurse's Office	Window Casing	Metal	Blue	None	0	0.4	Negative	
1	1	Nurse's Office	Door Casing	Metal	Blue	None	0	0.1	Negative	
1	1	Nurse's Office	Door	Wood	Blue	None	0	0	Negative	
1	1	Nurse's Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Nurse's Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Nurse's Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Nurse's Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Nurse's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Nurse's Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Sound-Proof Room inside Nurse's Suite	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Sound-Proof Room inside Nurse's Suite	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Sound-Proof Room inside Nurse's Suite	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Sound-Proof Room inside Nurse's Suite	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Sound-Proof Room inside Nurse's Suite	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Sound-Proof Room inside Nurse's Suite	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Nurse's Suite Corner Exam Room	W1	CMU	Yellow	None	0	0	Negative	

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Nurse's Suite Corner Exam Room	W2	CMU	Yellow	None	0	0.1	Negative
1	1	Nurse's Suite Corner Exam Room	W3	CMU	Yellow	None	0	0.1	Negative
1	1	Nurse's Suite Corner Exam Room	W4	CMU	Yellow	None	0	0.1	Negative
1	1	Nurse's Suite Corner Exam Room	Door Casing	Metal	Blue	None	0	0.4	Negative
1	1	Nurse's Suite Corner Exam Room	Door	Wood	Blue	None	0	0	Negative
1	1	Nurse's Suite Corner Exam Room Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Corner Exam Room Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Corner Exam Room Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Corner Exam Room Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Corner Exam Room Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Corner Exam Room Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Corner Exam Room Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Corner Exam Room Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Corner Exam Room Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Corner Exam Room Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Corner Exam Room Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Corner Exam Room Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Middle Exam Room	Door	Wood	Blue	None	0	0.1	Negative
1	1	Nurse's Suite Middle Exam Room	Door Casing	Metal	Blue	None	0	0.4	Negative
1	1	Nurse's Suite Middle Exam Room	W4	CMU	Beige	None	0	0.1	Negative
1	1	Nurse's Suite Middle Exam Room	W3	CMU	Beige	None	0	0	Negative
1	1	Nurse's Suite Middle Exam Room	W2	CMU	Beige	None	0	0.1	Negative
1	1	Nurse's Suite Middle Exam Room Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Middle Exam Room Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Middle Exam Room Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Middle Exam Room Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Middle Exam Room Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Middle Exam Room Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Middle Exam Room Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Middle Exam Room Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Middle Exam Room Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Middle Exam Room Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Middle Exam Room Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Suite Middle Exam Room Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	HVAC/Mechanical Room in Nurse's Suite	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	HVAC/Mechanical Room in Nurse's Suite	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	HVAC/Mechanical Room in Nurse's Suite	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	HVAC/Mechanical Room in Nurse's Suite	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	HVAC/Mechanical Room in Nurse's Suite	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	HVAC/Mechanical Room in Nurse's Suite	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Nurse's Suite Waiting Room	W1	CMU	Beige	Flaking	3	0.1	Negative
1	1	Nurse's Suite Waiting Room	W2	CMU	Beige	Flaking	3	0	Negative
1	1	Nurse's Suite Waiting Room	W3	CMU	Beige	None	0	0	Negative
1	1	Nurse's Suite Waiting Room	W4	CMU	Beige	None	0	0	Negative
1	1	Nurse's Suite Waiting Room	Door Casing	Metal	Blue	None	0	0.4	Negative
1	1	Custodial Storage Room across from Nurse's Suite	W4	Drywall	Beige	None	0	0.1	Negative
1	1	Custodial Storage Room across from Nurse's Suite	Door Casing	Metal	Brown	None	0	0.1	Negative
1	1	Custodial Storage Room across from Nurse's Suite	Door Casing	Metal	Blue	None	0	0.2	Negative
1	1	Custodial Storage Room across from Nurse's Suite	Door	Wood	Blue	None	0	0.1	Negative
1	1	Hallway outside Main Office and Auditorium	W1	CMU	Blue	None	0	0.1	Negative
1	1	Hallway outside Main Office and Auditorium	W4	CMU	Blue	None	0	0.1	Negative
1	1	Hallway outside Main Office and Auditorium	W3	CMU	Beige	None	0	0.1	Negative
1	1	Hallway outside Main Office and Auditorium	W2	CMU	Beige	None	0	0.1	Negative
1	1	Hallway outside Main Office and Auditorium	Column	Concrete	Beige	None	0	0.3	Negative
1	1	Storage Room behind Auditorium toward Main Office Suite	W1	CMU	Beige	None	0	0.1	Negative
1	1	Storage Room behind Auditorium toward Main Office Suite	W2	CMU	Beige	None	0	0	Negative
1	1	Storage Room behind Auditorium toward Main Office Suite	W3	CMU	Beige	None	0	0.1	Negative
1	1	Storage Room behind Auditorium toward Main Office Suite	W4	Concrete	Beige	None	0	0.2	Negative
1	1	Storage Room behind Auditorium toward Main Office Suite	Column	Concrete	Beige	None	0	0	Negative
1	1	Storage Room behind Auditorium toward Main Office Suite	Ceiling	Concrete	Beige	None	0	0.1	Negative
1	1	Center Storage Room behind Auditorium	W1	CMU	Beige	None	0	0.2	Negative
1	1	Center Storage Room behind Auditorium	W2	CMU	Beige	None	0	0	Negative
1	1	Center Storage Room behind Auditorium	W3	CMU	Beige	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Center Storage Room behind Auditorium	W4	CMU	Beige	None	0	0	Negative
1	1	Center Storage Room behind Auditorium	Door Casing	Metal	Blue	None	0	0.3	Negative
1	1	Center Storage Room behind Auditorium	Door	Wood	Blue	None	0	0.1	Negative
1	1	Center Storage Room behind Auditorium	Ceiling	Concrete	Beige	None	0	0.3	Negative
1	1	Center Storage Room behind Auditorium	Column	Concrete	Beige	None	0	0.3	Negative
1	1	Storage Room behind Auditorium toward Building Engineer's Office	Ceiling	Concrete	Beige	None	0	0.1	Negative
1	1	Storage Room behind Auditorium toward Building Engineer's Office	Column	Concrete	Beige	None	0	0.1	Negative
1	1	Storage Room behind Auditorium toward Building Engineer's Office	W1	CMU	Beige	None	0	0.1	Negative
1	1	Storage Room behind Auditorium toward Building Engineer's Office	W4	CMU	Beige	None	0	0	Negative
1	1	Storage Room behind Auditorium toward Building Engineer's Office	W3	CMU	Beige	None	0	0	Negative
1	1	Storage Room behind Auditorium toward Building Engineer's Office	W2	Concrete	Beige	None	0	0.2	Negative
1	1	Storage Room inside Storage room 27	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Room inside Storage room 27	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Room inside Storage room 27	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Room inside Storage room 27	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Room inside Storage room 27	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Room inside Storage room 27	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Main Office to Art Classroom	W1	CMU	Green	Intact	0	0.1	Negative
1	1	Hallway from Main Office to Art Classroom	W3	CMU	Green	Intact	0	0	Negative
1	1	Hallway from Main Office to Art Classroom	W4	CMU	Beige	Intact	0	0.1	Negative
1	1	Hallway from Main Office to Art Classroom	W2	CMU	Beige	Intact	0	0.1	Negative
1	1	Hallway from Main Office to Art Classroom	Door Center POS	Metal	Blue	Intact	0	0	Negative
1	1	Hallway from Main Office to Art Classroom	Door	Metal	Blue	Intact	0	0.1	Negative
1	1	Hallway from Main Office to Art Classroom	Door Casing	Metal	Blue	Intact	0	0.1	Negative
1	1	Hallway from Main Office to Art Classroom	Door Casing	Metal	Beige	Intact	0	0.2	Negative
1	1	Hallway from Main Office to Art Classroom	Door	Metal	Beige	Intact	0	0	Negative
1	1	Hallway from Main Office to Art Classroom	Door Center POS	Metal	Black	Intact	0	0	Negative
1	1	Hallway from Main Office to Art Classroom	Door Casing	Metal	Beige	Intact	0	0.1	Negative
1	1	Hallway from Main Office to Art Classroom	Door	Wood	Beige	Intact	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Hallway from Main Office to Art Classroom	Univent	Metal	Beige	Intact	0	0	Negative
1	1	Stairwell outside Art Classroom	Door Casing	Metal	Beige	Intact	0	0.5	Negative
1	1	Stairwell outside Art Classroom	Door	Metal	Beige	Intact	0	0	Negative
1	1	Stairwell outside Art Classroom	W1	CMU	Beige	Intact	0	0.1	Negative
1	1	Stairwell outside Art Classroom	W2	CMU	Beige	Intact	0	0.1	Negative
1	1	Stairwell outside Art Classroom	W3	CMU	Beige	Intact	0	0.1	Negative
1	1	Stairwell outside Art Classroom	W4	CMU	Beige	Intact	0	0.1	Negative
1	1	Stairwell outside Art Classroom	Stairs - Railing	Metal	Beige	Intact	0	0.3	Negative
1	1	Stairwell outside Art Classroom	Stairs - Stringer	Metal	Beige	Intact	0	0.6	Negative
1	1	Stairwell outside Art Classroom	Stairs - Riser	Metal	Beige	Intact	0	0.7	Positive
1	1	Shaft on landing between first and second floor	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Shaft on landing between first and second floor	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Shaft on landing between first and second floor	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Shaft on landing between first and second floor	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Shaft on landing between first and second floor	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Shaft on landing between first and second floor	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Art Classroom	Door Casing	Metal	Blue	Intact	0	0.5	Negative
1	1	Art Classroom	Door	Wood	Blue	Intact	0	0	Negative
1	1	Art Classroom	W1	CMU	Brown	Intact	0	0.1	Negative
1	1	Art Classroom	W4	CMU	Brown	Intact	0	0	Negative
1	1	Art Classroom	W3	CMU	Brown	Intact	0	0.1	Negative
1	1	Art Classroom	W2	CMU	Brown	Intact	0	0.1	Negative
1	1	Art Classroom	Duct	Metal	Beige	Flaking	3	0.1	Negative
1	1	Stairwell inside Art Classroom to Upper HVAC/Mechanical Room	Stairs - Railing	Metal	Brown	Intact	0	0.4	Negative
1	1	Stairwell inside Art Classroom to Upper HVAC/Mechanical Room	Stairs - Stringer	Metal	Brown	Intact	0	1.6	Positive
1	1	Stairwell inside Art Classroom to Upper HVAC/Mechanical Room	Stairs - Riser	Metal	Brown	Intact	0	1.6	Positive
1	1	Art Classroom Storage - Closer to Entrance	W1	CMU	Yellow	Intact	0	0.1	Negative
1	1	Art Classroom Storage - Closer to Entrance	W2	CMU	Yellow	Intact	0	0.2	Negative
1	1	Art Classroom Storage - Closer to Entrance	Door Casing	Metal	Blue	Intact	0	0.4	Negative
1	1	Art Classroom Storage - Closer to Entrance	Door	Wood	Blue	Intact	0	0.1	Negative
1	1	Art Classroom Storage - Closer to Entrance	Duct	Metal	Brown	Intact	0	0.4	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Art Classroom Office	Door	Wood	Blue	Intact	0	0	Negative
1	1	Art Classroom Office	Door Casing	Metal	Blue	Intact	0	0.1	Negative
1	1	Art Classroom Office	W1	CMU	Brown	Intact	0	0.1	Negative
1	1	Art Classroom Office	W2	CMU	Brown	Intact	0	0	Negative
1	1	Art Classroom Office	W3	CMU	Brown	Intact	0	0	Negative
1	1	Art Classroom Office	W4	CMU	Brown	Intact	0	0.1	Negative
1	1	Storage inside Art Classroom Office	W1	CMU	Brown	Intact	0	0	Negative
1	1	Storage inside Art Classroom Office	Door Casing	Metal	Blue	Intact	0	0.1	Negative
1	1	Storage inside Art Classroom Office	Door	Wood	Blue	Intact	0	0	Negative
1	1	Storage inside Art Classroom Office	Duct	Metal	Brown	Intact	0	0.1	Negative
1	1	Drying room next to Art Classroom Office	Duct	Metal	Yellow	Intact	0	0.1	Negative
1	1	Drying room next to Art Classroom Office	W1	CMU	Yellow	Intact	0	0.1	Negative
1	1	Drying room next to Art Classroom Office	W4	CMU	Yellow	Intact	0	0.1	Negative
1	1	Drying room next to Art Classroom Office	W3	CMU	Yellow	Intact	0	0.1	Negative
1	1	Drying room next to Art Classroom Office	W2	CMU	Yellow	Intact	0	0.1	Negative
1	1	Drying room next to Art Classroom Office	Door Casing	Metal	Blue	Intact	0	0.4	Negative
1	1	Drying room next to Art Classroom Office	Door	Wood	Blue	Intact	0	0.1	Negative
1	1	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	W1	CMU	Brown	Intact	0	0	Negative
1	1	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	Door Casing	Metal	Blue	Intact	0	0.4	Negative
1	1	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	Door	Wood	Blue	Intact	0	0.1	Negative
1	1	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	W2	CMU	Brown	Intact	0	0.1	Negative
1	1	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	W3	CMU	Brown	Intact	0	0	Negative
1	1	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	W4	CMU	Brown	Intact	0	0.1	Negative
1	1	Backstage Area between Art Classroom and Auditorium	W1	CMU	Yellow	Intact	0	0.1	Negative
1	1	Backstage Area between Art Classroom and Auditorium	W4	CMU	Yellow	Intact	0	0.1	Negative
1	1	Backstage Area between Art Classroom and Auditorium	W3	CMU	Yellow	Intact	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Backstage Area between Art Classroom and Auditorium	W2	CMU	Yellow	Intact	0	0.1	Negative
1	1	Backstage Area between Art Classroom and Auditorium	Duct	Metal	White	Flaking	10	0.2	Negative
1	1	Backstage Area between Art Classroom and Auditorium	Door Casing	Metal	Blue	Intact	0	0.2	Negative
1	1	Backstage Area between Art Classroom and Auditorium	Door	Wood	Blue	Intact	0	0	Negative
1	1	Auditorium Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	W1	CMU	Brown	Intact	0	0.1	Negative
1	1	Auditorium	W2	CMU	Brown	Intact	0	0.1	Negative
1	1	Auditorium	Door Casing	Metal	Blue	Intact	0	0.2	Negative
1	1	Auditorium	W3	CMU	Brown	Intact	0	0.1	Negative
1	1	Auditorium	W3	Concrete	White	Flaking	10	0.1	Negative
1	1	Auditorium	W4	Concrete	White	Intact	0	0.3	Negative
1	1	Auditorium	W4	CMU	Brown	Intact	0	0.2	Negative
1	1	Auditorium	Door Casing	Metal	Blue	Intact	0	0.5	Negative
1	1	Auditorium	Door Casing	Metal	Blue	Intact	0	0.1	Negative
1	1	Auditorium	Door Center POS	Metal	Tan	Intact	0	0.1	Negative
1	1	Auditorium	Door	Wood	Blue	Intact	0	0.1	Negative
1	1	Hallway from Auditorium to Large Storage Area	W2	CMU	Beige	Intact	0	0	Negative
1	1	Hallway from Auditorium to Large Storage Area	W4	CMU	Beige	Intact	0	0.1	Negative
1	1	Hallway from Auditorium to Large Storage Area	W3	CMU	Beige	Intact	0	0.1	Negative
1	1	Hallway from Auditorium to Large Storage Area	Door	Wood	Beige	Intact	0	0.1	Negative
1	1	Hallway from Auditorium to Large Storage Area	Door Casing	Metal	Beige	Intact	0	0.3	Negative
1	1	Hallway from Auditorium to Large Storage Area	Column	Concrete	Beige	Intact	0	0.1	Negative
1	1	Stairwell outside Building Engineer's Office	W1	CMU	Beige	Intact	0	0	Negative
1	1	Stairwell outside Building Engineer's Office	W2	CMU	Beige	Intact	0	0.1	Negative
1	1	Stairwell outside Building Engineer's Office	W3	CMU	Beige	Intact	0	0.1	Negative
1	1	Stairwell outside Building Engineer's Office	W4	CMU	Beige	Intact	0	0.4	Negative
1	1	Stairwell outside Building Engineer's Office	Door Casing	Metal	Blue	Intact	0	0.3	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Stairwell outside Building Engineer's Office	Door	Metal	Blue	Intact	0	0	Negative
1	1	Stairwell outside Building Engineer's Office	Door	Metal	Blue	Intact	0	0.1	Negative
1	1	Stairwell outside Building Engineer's Office	Door Casing	Metal	Blue	Intact	0	0.4	Negative
1	1	Stairwell outside Building Engineer's Office	Column	Concrete	Beige	Intact	0	0.2	Negative
1	1	Stairwell outside Building Engineer's Office	Stairs - Stringer	Metal	Brown	Intact	0	0.8	Positive
1	1	Stairwell outside Building Engineer's Office	Stairs - Railing	Metal	Brown	Intact	0	0.1	Negative
1	1	Stairwell outside Building Engineer's Office	Stairs - Riser	Metal	Brown	Intact	0	1	Positive
1	1	Foyer outside Large Storage Area next to Art Classroom	W1	CMU	Beige	Intact	0	0	Negative
1	1	Foyer outside Large Storage Area next to Art Classroom	W2	Drywall	Beige	Intact	0	0.2	Negative
1	1	Foyer outside Large Storage Area next to Art Classroom	W3	Drywall	Beige	Intact	0	0	Negative
1	1	Foyer outside Large Storage Area next to Art Classroom	W4	CMU	Beige	Intact	0	0	Negative
1	1	Storage Room outside Large Storage Area next to Art Classroom	W1	CMU	Blue	Intact	0	0	Negative
1	1	Storage Room outside Large Storage Area next to Art Classroom	W2	CMU	Blue	Intact	0	0.2	Negative
1	1	Storage Room outside Large Storage Area next to Art Classroom	W3	CMU	Blue	Intact	0	0	Negative
1	1	Storage Room outside Large Storage Area next to Art Classroom	W4	CMU	Blue	Intact	0	0.1	Negative
1	1	Storage Room outside Large Storage Area next to Art Classroom	Floor	Concrete	Brown	Intact	0	0.3	Negative
1	1	Storage Room outside Large Storage Area next to Art Classroom	Door Casing	Metal	Blue	Intact	0	0.2	Negative
1	1	Storage Room outside Large Storage Area next to Art Classroom	Door	Wood	Blue	Intact	0	0.1	Negative
1	1	Large Storage Area Storage Room closer to Entrance	W1	CMU	Beige	Intact	0	0.2	Negative
1	1	Large Storage Area Storage Room closer to Entrance	W2	CMU	Beige	Intact	0	0.1	Negative
1	1	Large Storage Area Storage Room closer to Entrance	W3	CMU	Beige	Intact	0	0.2	Negative
1	1	Large Storage Area Storage Room closer to Entrance	Door	Wood	Blue	Intact	0	0	Negative
1	1	Large Storage Area Storage Room closer to Entrance	Door Casing	Metal	Blue	Intact	0	0	Negative
1	1	Large Storage Area Office toward Art Classroom	W1	CMU	Beige	Intact	0	0.2	Negative
1	1	Large Storage Area Office toward Art Classroom	W2	CMU	Beige	Intact	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Large Storage Area Office toward Art Classroom	W3	CMU	Beige	Intact	0	0.2	Negative
1	1	Large Storage Area Office toward Art Classroom	Door	Wood	Blue	Intact	0	0	Negative
1	1	Large Storage Area Office toward Art Classroom	Door Casing	Metal	Blue	Intact	0	0	Negative
1	1	Large Storage Area Office Closet toward Art Classroom	Door Casing	Metal	Blue	Intact	0	0.4	Negative
1	1	Large Storage Area next to Art Classroom	W1	Drywall	Beige	Intact	0	0.2	Negative
1	1	Large Storage Area next to Art Classroom	W1	CMU	Beige	Intact	0	0	Negative
1	1	Large Storage Area next to Art Classroom	W2	CMU	Beige	Intact	0	0.1	Negative
1	1	Large Storage Area next to Art Classroom	W3	CMU	Beige	Intact	0	0.1	Negative
1	1	Large Storage Area next to Art Classroom	W4	Drywall	Beige	Intact	0	0.1	Negative
1	1	Large Storage Area next to Art Classroom	W4	CMU	Beige	Intact	0	0.1	Negative
1	1	Large Storage Area next to Art Classroom	Column	Concrete	Beige	Intact	0	0.2	Negative
1	1	Large Storage Area next to Art Classroom	Fan Unit	Metal	Beige	Intact	0	0.1	Negative
1	1	Large Storage Area next to Art Classroom	Door Casing	Metal	Blue	Intact	0	0	Negative
1	1	Large Storage Area next to Art Classroom	Door	Metal	Blue	Intact	0	0.1	Negative
1	1	Large Storage Area next to Art Classroom	Door Center Post	Metal	Blue	Intact	0	0	Negative
1	1	Large Storage Area next to Art Classroom	Door Casing	Metal	Blue	Intact	0	0.4	Negative
1	1	Large Storage Area next to Art Classroom	Pipe	Metal	Beige	Intact	0	0.3	Negative
1	1	Large Storage Area next to Art Classroom	Duct	Metal	Beige	Intact	0	0.1	Negative
1	1	Front Entrance Vestibule Stairwell	Stairs - Railing	Metal	Brown	Intact	0	0.3	Negative
1	1	Front Entrance Vestibule Stairwell	Stairs - Riser	Metal	Brown	Intact	0	0.7	Positive
1	1	Front Entrance Vestibule Stairwell	Stairs - Stringer	Metal	Brown	Intact	0	0.4	Negative
1	1	Front Entrance Vestibule Stairwell	W1	CMU	Beige	Intact	0	0.2	Negative
1	1	Front Entrance Vestibule Stairwell	W3	CMU	Beige	Intact	0	0.1	Negative
1	1	Front Entrance Vestibule Stairwell	W2	CMU	Beige	Intact	0	0.1	Negative
1	1	Front Entrance Vestibule Stairwell	Column	Concrete	Beige	Intact	0	0.1	Negative
1	1	Men's Restroom next to Front Entrance	W1	CMU	Beige	Intact	0	0.1	Negative
1	1	Men's Restroom next to Front Entrance	W4	CMU	Beige	Intact	0	0	Negative
1	1	Men's Restroom next to Front Entrance	W2	CMU	Beige	Intact	0	0.1	Negative
1	1	Men's Restroom next to Front Entrance	Ceiling	Concrete	Beige	Intact	0	0.1	Negative
1	1	Men's Restroom next to Front Entrance	Door Casing	Metal	Blue	Intact	0	0.2	Negative
1	1	Men's Restroom next to Front Entrance	Door	Wood	Blue	Intact	0	0.1	Negative
1	1	Women's Restroom next to Front Entrance	W1	CMU	White	Intact	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia							
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report							
		Inspection Company: Acer Associates	E.W. Rhodes ES School							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Women's Restroom next to Front Entrance	W2	CMU	White	Intact	0	0.1	Negative	
1	1	Women's Restroom next to Front Entrance	W3	CMU	White	Intact	0	0	Negative	
1	1	Women's Restroom next to Front Entrance	Ceiling	Concrete	White	Intact	0	0	Negative	
1	1	Women's Restroom next to Front Entrance	Door Casing	Metal	Blue	Intact	0	0.4	Negative	
1	1	Women's Restroom next to Front Entrance	Door	Wood	Blue	Intact	0	0.1	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	W1	CMU	BEIGE	INTACT	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	W2	CMU	BEIGE	INTACT	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	DOOR CASING	Metal	BEIGE	INTACT	0	0.02	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	DOOR CENTER PC	METAL	BEIGE	INTACT	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	W3	CMU	YELLOW	INTACT	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	PIPE CHASE DOO	METAL	BEIGE	INTACT	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	FIREHOSE DOOR	METAL	WHITE	INTACT	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	DOOR CASING	METAL	BEIGE	INTACT	0	0.04	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	DOOR	METAL	BEIGE	INTACT	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	W1	CMU	Beige	Intact	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	W3	CMU	Yellow	Intact	0	0.1	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	W2	CMU	Beige	Intact	0	0.1	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	Door	Metal	Beige	Intact	0	0.2	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	Door Casing	Metal	Beige	Intact	0	0.2	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	Pipe chase door	Metal	Beige	Intact	0	0.2	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	Door	Wood	Beige	Intact	0	0	Negative	
1	1	Hallway between A and B Wings and Gymnasium/Pool	Door	Metal	Beige	Intact	0	0	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	W1	CMU	BEIGE	INTACT	0	0	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	W2	CMU	BEIGE	INTACT	0	0	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	W3	CMU	BEIGE	INTACT	0	0	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	W4	CMU	BEIGE	INTACT	0	0	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	DOOR	METAL	BLUE	INTACT	0	0	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	DOOR	WOOD	BLUE	INTACT	0	0.01	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	SOFFIT	Plaster	CLEAR	INTACT	0	0	Negative	
1	1	Hallway outside A Wing Classrooms A1 -A7	SOFFIT	Plaster	CLEAR	INTACT	0	0	Negative	

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Hallway outside A Wing Classrooms A1 -A7	SOFFIT	Plaster	CLEAR	INTACT	0	0	Negative
1	1	Custodial closet between Classrooms A7 and A6	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms A7 and A6	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms A7 and A6	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms A7 and A6	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms A7 and A6	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms A7 and A6	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway connecting A Wing and B Wing	W1	CMU	YELLOW	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	W4	CMU	YELLOW	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	W3	CMU	YELLOW	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	W2	CMU	YELLOW	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	DOOR	METAL	BLUE	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	DOOR	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Hallway connecting A Wing and B Wing	DOOR CASING	METAL	BLUE	INTACT	0	0.09	Negative
1	1	Hallway connecting A Wing and B Wing	DOOR CASING	METAL	BLUE	INTACT	0	0.12	Negative
1	1	Hallway connecting A Wing and B Wing	DOOR	METAL	BLUE	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	DOOR CENTER PANEL	METAL	BLUE	INTACT	0	0.11	Negative
1	1	Hallway connecting A Wing and B Wing	STAIRS RAILING	METAL	BROWN	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	STAIRS RISER	METAL	BROWN	INTACT	0	0.9	Positive
1	1	Hallway connecting A Wing and B Wing	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.9	Positive
1	1	Hallway connecting A Wing and B Wing	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	DOOR TOP PANEL	METAL	BLUE	INTACT	0	0	Negative
1	1	Hallway connecting A Wing and B Wing	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	W4	CMU	TAN	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	W3	CMU	TAN	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0.08	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	SOFFIT	Plaster	TAN	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	DOOR	METAL	BLUE	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0.04	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	VENT COVER	METAL	CLEAR	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	VENT COVER	METAL	CLEAR	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	DOOR	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	DOOR	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0.03	Negative
1	1	Custodial closet between Classrooms B6 and B7	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms B6 and B7	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms B6 and B7	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms B6 and B7	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms B6 and B7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial closet between Classrooms B6 and B7	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage closet in between boys and girls restroom in H012	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage closet in between boys and girls restroom in H012	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage closet in between boys and girls restroom in H012	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage closet in between boys and girls restroom in H012	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage closet in between boys and girls restroom in H012	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage closet in between boys and girls restroom in H012	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage closet in between boys and girls restroom in H012	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage closet in between boys and girls restroom in H012	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage closet in between boys and girls restroom in H012	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage closet in between boys and girls restroom in H012	W4	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Pipe Chase in Storage closet in between boys and girls restroom in H012	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage closet in between boys and girls restroom in H012	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	A Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative
1	1	A Wing Lunch Room	DOOR	METAL	BLUE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	W2	CMU	ORANGE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	W3	CMU	ORANGE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	WALL DIVIDER	FIBERBOARD	ORANGE	INTACT	0	0.13	Negative
1	1	A Wing Lunch Room	COLUMN	METAL	BEIGE	INTACT	0	0.05	Negative
1	1	A Wing Lunch Room	DIVIDER WALL	DRYWALL	BEIGE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative
1	1	A Wing Lunch Room	STAIRS RISER	METAL	BROWN	INTACT	0	1.3	Positive
1	1	A Wing Lunch Room	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.5	Negative
1	1	A Wing Lunch Room	STAIRS RAILING	METAL	BROWN	INTACT	0	0.13	Negative
1	1	Stairwell inside A Wing Lunch Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside A Wing Lunch Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside A Wing Lunch Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside A Wing Lunch Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside A Wing Lunch Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside A Wing Lunch Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	B Wing Lunch Room	W1	CMU	GREEN	INTACT	0	0.01	Negative
1	1	B Wing Lunch Room	W2	CMU	GREEN	INTACT	0	0.01	Negative
1	1	B Wing Lunch Room	COLUMN	CONCRETE	CLEAR	INTACT	0	0.02	Negative
1	1	B Wing Lunch Room	W2	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	B Wing Lunch Room	DOOR	WOOD	BLUE	INTACT	0	0	Negative
1	1	B Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative
1	1	B Wing Lunch Room	COLUMN	CONCRETE	BEIGE	Flaking	5	0	Negative
1	1	B Wing Lunch Room	W4	DRYWALL	BEIGE	INTACT	0	0	Negative
1	1	B Wing Lunch Room	W4	WOOD	BEIGE	INTACT	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	B Wing Lunch Room	COLUMN	METAL	BEIGE	INTACT	0	0.01	Negative
1	1	B Wing Lunch Room	VENT COVER	METAL	BEIGE	INTACT	0	0.01	Negative
1	1	B Wing Lunch Room	STAIRS RAILING	METAL	BROWN	INTACT	0	0.9	Positive
1	1	B Wing Lunch Room	STAIRS RISER	METAL	BROWN	INTACT	0	0.6	Negative
1	1	B Wing Lunch Room	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.5	Negative
1	1	B Wing Lunch Room	CEILING	CONCRETE	BEIGE		0	0	Negative
1	1	B Wing Lunch Room	DOOR CASING	PLASTER	BLUE	INTACT	0	0.01	Negative
1	1	B Wing Lunch Room	DOOR	METAL	BLUE	INTACT	0	0.04	Negative
1	1	B Wing Lunch Room	SOFFIT	METAL	BEIGE	INTACT	0	0	Negative
1	1	B Wing Lunch Room	SOFFIT	METAL	BEIGE	INTACT	0	0	Negative
1	1	B Wing Lunch Room	AIR RETURN COV	METAL	GREEN	INTACT	0	0	Negative
1	1	Stairwell inside B Wing Lunch Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside B Wing Lunch Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside B Wing Lunch Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside B Wing Lunch Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside B Wing Lunch Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside B Wing Lunch Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom A7	DIVIDER WALL	DRYWALL	WHITE	INTACT	0	0.01	Negative
1	1	Classroom A7	DIVIDER WALL TF	WOOD	BEIGE	INTACT	0	0.03	Negative
1	1	Classroom A7	W2	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	Classroom A7	W1	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	Classroom A7	COLUMN	CONCRETE	BEIGE	INTACT	0	0.01	Negative
1	1	Classroom A7	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative
1	1	Classroom A6	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Classroom A6	WALL BASEBOAR	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	Classroom A6	WALL BASEBOAR	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	Classroom A6	WALL BASEBOAR	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	Classroom A6	WALL BASEBOAR	CMU	GRAY	INTACT	0	0.01	Negative
1	1	Classroom A6	COLUMN	CONCRETE	BEIGE	INTACT	0	0.01	Negative
1	1	Classroom A6	Ceiling	CONCRETE	BEIGE	INTACT	0	0.01	Negative
1	1	Classroom A6	DIVIDER WALL TF	WOOD	BLUE	INTACT	0	0.01	Negative
1	1	Classroom A6	DIVIDER WALL	DRYWALL	BEIGE	INTACT	0	0	Negative
1	1	Classroom A5	COLUMN	CONCRETE	YELLOW	INTACT	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom A5	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom A5	W2	CMU	WHITE	INTACT	0	0.03	Negative
1	1	Classroom A5	W3	CMU	YELLOW	INTACT	0	0.01	Negative
1	1	Classroom A5	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom A5	DIVIDER WALL TF	WOOD	WHITE	INTACT	0	0.03	Negative
1	1	Classroom A5	DIVIDER WALL	DRYWALL	WHITE	INTACT	0	0.01	Negative
1	1	Classroom A5	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Classroom A5	DOOR	WOOD	BLUE	INTACT	0	0.01	Negative
1	1	Classroom A4	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative
1	1	Classroom A4	W1	CMU	WHITE	INTACT	0	0	Negative
1	1	Classroom A4	W4	CMU	WHITE	INTACT	0	0.02	Negative
1	1	Classroom A4	W4	CMU	YELLOW	INTACT	0	0	Negative
1	1	Classroom A4	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom A4	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom A4	COLUMN	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	Classroom A4	WALL DIVIDER TF	WOOD	WHITE	INTACT	0	0	Negative
1	1	Classroom A4	WALL DIVIDER	DRYWALL	WHITE	INTACT	0	0.01	Negative
1	1	Classroom A4	COLUMN	CONCRETE	YELLOW	INTACT	0	0.01	Negative
1	1	Classroom A3	DIVIDER WALL	DRYWALL	WHITE	INTACT	0	0	Negative
1	1	Classroom A3	DIVIDER WALL TF	WOOD	WHITE	INTACT	0	0	Negative
1	1	Classroom A3	W1	CMU	WHITE	INTACT	0	0.02	Negative
1	1	Classroom A3	W2	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom A3	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom A3	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom A3	WALL BASEBOARD	CMU	YELLOW	INTACT	0	0.03	Negative
1	1	Classroom A3	COLUMN	CONCRETE	YELLOW	INTACT	0	0	Negative
1	1	Classroom A3	DOOR CASING	METAL	BLUE	INTACT	0	0.05	Negative
1	1	Classroom A2	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom A2	W4	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom A2	W3	CMU	YELLOW	INTACT	0	0.01	Negative
1	1	Classroom A2	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom A2	DIVIDER WALL TF	WOOD	WHITE	INTACT	0	0	Negative
1	1	Classroom A2	DIVIDER WALL	DRYWALL	WHITE	INTACT	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom A1	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom A1	W2	CMU	WHITE	INTACT	0	0	Negative
1	1	Classroom A1	W4	CMU	WHITE	INTACT	0	0	Negative
1	1	Classroom A1	W3	CMU	YELLOW	INTACT	0	0	Negative
1	1	Classroom A1	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom A1	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom A1	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Classroom A1	DOOR	WOOD	BLUE	INTACT	0	0	Negative
1	1	A Wing Boy's Restroom	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative
1	1	A Wing Boy's Restroom	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Boy's Restroom	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Boy's Restroom	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Boy's Restroom	ceiling	Concrete	BEIGE	INTACT	0	0	Negative
1	1	A Wing Girl's Restroom	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Girl's Restroom	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Girl's Restroom	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Girl's Restroom	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	A Wing Girl's Restroom	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative
1	1	A Wing Girl's Restroom	DOOR CASING	METAL	BLUE	INTACT	0	0.03	Negative
1	1	Stairwell between A and B Wings	W1	CMU	YELLOW	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	W4	CMU	YELLOW	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	W3	CMU	YELLOW	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	W2	CMU	YELLOW	Flaking	15	0	Negative
1	1	Stairwell between A and B Wings	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	DOOR	METAL	BLUE	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	DOOR	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Stairwell between A and B Wings	DOOR CASING	METAL	BLUE	INTACT	0	0.09	Negative
1	1	Stairwell between A and B Wings	DOOR CASING	METAL	BLUE	INTACT	0	0.12	Negative
1	1	Stairwell between A and B Wings	DOOR	METAL	BLUE	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	DOOR CENTER PO	METAL	BLUE	INTACT	0	0.11	Negative
1	1	Stairwell between A and B Wings	STAIRS RAILING	METAL	BROWN	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	STAIRS RISER	METAL	BROWN	INTACT	0	0.9	Positive
1	1	Stairwell between A and B Wings	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.9	Positive

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Stairwell between A and B Wings	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	DOOR TOP PANE	METAL	BLUE	INTACT	0	0	Negative
1	1	Stairwell between A and B Wings	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative
1	1	B Wing Girl's Restroom	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	B Wing Girl's Restroom	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	B Wing Girl's Restroom	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	B Wing Girl's Restroom	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	B Wing Girl's Restroom	Ceiling	Wood	WHITE	INTACT	0	0	Negative
1	1	B Wing Girl's Restroom	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative
1	1	B Wing Boy's Restroom	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative
1	1	B Wing Boy's Restroom	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	B Wing Boy's Restroom	W2	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	B Wing Boy's Restroom	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	B Wing Boy's Restroom	PIPE CHASE DOO	METAL	BEIGE	INTACT	0	0	Negative
1	1	B Wing Boy's Restroom	Ceiling	CONCRETE	BEIGE	INTACT	0	0	Negative
1	1	B Wing Boy's Restroom	VENT COVER	METAL	BEIGE	INTACT	0	0	Negative
1	1	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W4	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell behind B Wing Classroom B7	W1	Brick	Beige	Intact	0	0.1	Negative
1	1	Stairwell behind B Wing Classroom B7	W2	Brick	Beige	Intact	0	0.1	Negative
1	1	Stairwell behind B Wing Classroom B7	W4	Brick	Beige	Intact	0	0.2	Negative
1	1	Stairwell behind B Wing Classroom B7	Stairs - Railing	Metal	Beige	Intact	0	0.2	Negative
1	1	Stairwell behind B Wing Classroom B7	Stairs - Riser	Metal	Beige	Intact	0	1	Positive
1	1	Stairwell behind B Wing Classroom B7	Stairs - Stringer	Metal	Beige	Intact	0	0.7	Positive
1	1	Stairwell behind B Wing Classroom B7	W2	Drywall	Beige	Intact	0	0	Negative
1	1	Classrooms B6 + B7	W1	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	Classrooms B6 + B7	W4	CMU	BEIGE	Efflorescence	7	0	Negative
1	1	Classrooms B6 + B7	W3	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	Classrooms B6 + B7	W2	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	Classrooms B6 + B7	DIVIDER WALL TF	WOOD	BEIGE	INTACT	0	0.02	Negative
1	1	Classrooms B6 + B7	DIVIDER WALL	WOOD	BLUE	INTACT	0	0	Negative
1	1	Classrooms B6 + B7	COLUMN	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	Classrooms B6 + B7	COLUMN	CONCRETE	BEIGE	INTACT	0	0.01	Negative
1	1	Classrooms B6 + B7	UNIVENT	METAL	BEIGE	INTACT	0	0.14	Negative
1	1	Classrooms B6 + B7	SOFFIT	Plaster	BEIGE	Efflorescence	10	0	Negative
1	1	Pipe Chase in Classrooms B6 + B7	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Chase in Classrooms B6 + B7	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Chase in Classrooms B6 + B7	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Chase in Classrooms B6 + B7	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Chase in Classrooms B6 + B7	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Chase in Classrooms B6 + B7	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom B5	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom B5	W2	CMU	WHITE	INTACT	0	0	Negative
1	1	Classroom B5	W3	CMU	ORANGE	Efflorescence	20	0.01	Negative
1	1	Classroom B5	SOFFIT	Plaster	WHITE	Efflorescence	10	0	Negative
1	1	Classroom B5	COLUMN	CONCRETE	ORANGE	INTACT	0	0	Negative
1	1	Classroom B5	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative
1	1	Classroom B5	DIVIDER WALL TF	WOOD	WHITE	INTACT	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom B5	DIVIDER WALL	WOOD	WHITE	INTACT	0	0	Negative
1	1	Classroom B5	CONDUIT	METAL	WHITE	INTACT	0	0.22	Negative
1	1	Classroom B4	WALL	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom B4	WALL	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom B4	W3	CMU	ORANGE	Flaking	10	0	Negative
1	1	Classroom B4	COLUMN	CONCRETE	ORANGE	INTACT	0	0	Negative
1	1	Classroom B4	COLUMN	CONCRETE	WHITE	INTACT	0	0.01	Negative
1	1	Classroom B4	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom B4	WALL DIVIDER TF	WOOD	WHITE	INTACT	0	0	Negative
1	1	Classroom B4	DOOR	WOOD	BLUE	INTACT	0	0	Negative
1	1	Classroom B3	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom B3	W4	CMU	WHITE	INTACT	0	0	Negative
1	1	Classroom B3	W3	CMU	ORANGE	INTACT	0	0.01	Negative
1	1	Classroom B3	SOFFIT	Plaster	WHITE	Efflorescence	12	0	Negative
1	1	Classroom B3	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom B3	WALL DIVIDER TF	WOOD	WHITE	INTACT	0	0.01	Negative
1	1	Classroom B3	WALL DIVIDER	DRYWALL	WHITE	INTACT	0	0	Negative
1	1	Classroom B3	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative
1	1	Classroom B2	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom B2	W2	CMU	WHITE	INTACT	0	0.02	Negative
1	1	Classroom B2	W3	CMU	ORANGE	INTACT	0	0.01	Negative
1	1	Classroom B2	SOFFIT	Plaster	WHITE	Efflorescence	2	0	Negative
1	1	Classroom B2	WALL DIVIDER TF	WOOD	WHITE	INTACT	0	0	Negative
1	1	Classroom B2	WALL DIVIDER	DRYWALL	WHITE	INTACT	0	0.03	Negative
1	1	Classroom B2	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative
1	1	Classroom B2	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Classroom B2	W2	CMU	BLUE	INTACT	0	0.01	Negative
1	1	Classroom B2	W3	CMU	ORANGE	INTACT	0	0	Negative
1	1	Classroom B2	W4	CMU	WHITE	INTACT	0	0	Negative
1	1	Classroom B1	SOFFIT 3	Plaster	WHITE	Efflorescence	2	0	Negative
1	1	Classroom B1	SOFFIT 2	Plaster	WHITE	Efflorescence	8	0	Negative
1	1	Classroom B1	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative
1	1	Classroom B1	COLUMN	CONCRETE	ORANGE	INTACT	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom B1	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Classroom B1	DOOR	WOOD	BLUE	INTACT	0	0	Negative
1	1	Electrical Room between A and B Wings	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Electrical Room between A and B Wings	W2	CMU	WHITE	INTACT	0	0.02	Negative
1	1	Electrical Room between A and B Wings	W3	CMU	WHITE	INTACT	0	0.02	Negative
1	1	Electrical Room between A and B Wings	W4	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Electrical Room between A and B Wings	DOOR CENTER PC	METAL	BLUE	INTACT	0	0	Negative
1	1	Electrical Room between A and B Wings	DOOR	METAL	BLUE	INTACT	0	0.02	Negative
1	1	Electrical Room between A and B Wings	COLUMN	CONCRETE	WHITE	INTACT	0	0.02	Negative
1	1	Electrical Room between A and B Wings	COLUMN	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to B Wing Lunch Room	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Special Education Classroom next to B Wing Lunch Room	W2	CMU	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to B Wing Lunch Room	W3	CMU	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to B Wing Lunch Room	W4	DRYWALL	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to B Wing Lunch Room	Ceiling	Concrete	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to B Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Special Education Classroom next to B Wing Lunch Room	DUCT	METAL	WHITE	INTACT	0	0	Negative
1	1	Restroom inside Special Education Classroom next to B Wing Lunch Room	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Restroom inside Special Education Classroom next to B Wing Lunch Room	W4	CMU	WHITE	INTACT	0	0	Negative
1	1	Restroom inside Special Education Classroom next to B Wing Lunch Room	W3	CMU	WHITE	INTACT	0	0	Negative
1	1	Restroom inside Special Education Classroom next to B Wing Lunch Room	W2	CMU	WHITE	INTACT	0	0	Negative
1	1	Restroom inside Special Education Classroom next to B Wing Lunch Room	CEILING	PLASTER	WHITE	INTACT	0	0	Negative
1	1	Restroom inside Special Education Classroom next to B Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Restroom inside Special Education Classroom next to B Wing Lunch Room	DOOR	WOOD	BLUE	INTACT	0	0	Negative
1	1	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W1	CMU	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W4	CMU	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W3	CMU	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W4	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W4	DRYWALL	WHITE	INTACT	0	0	Negative
1	1	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	CEILING	PLASTER	WHITE	INTACT	0	0	Negative
1	1	Book Storage Room next to A Wing Lunch Room	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Book Storage Room next to A Wing Lunch Room	W2	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Book Storage Room next to A Wing Lunch Room	W3	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Book Storage Room next to A Wing Lunch Room	W4	DRYWALL	WHITE	INTACT	0	0	Negative
1	1	Book Storage Room next to A Wing Lunch Room	WALL	DRYWALL	BLUE	INTACT	0	0	Negative
1	1	Book Storage Room next to A Wing Lunch Room	SOFFIT	Plaster	BLUE	INTACT	0	0.01	Negative
1	1	Book Storage Room next to A Wing Lunch Room	SOFFIT	Plaster	WHITE	Efflorescence	150	0.02	Negative
1	1	Book Storage Room next to A Wing Lunch Room	COLUMN	CONCRETE	BLUE	INTACT	0	0.01	Negative
1	1	Book Storage Room next to A Wing Lunch Room	COLUMN	CONCRETE	WHITE	INTACT	0	0.01	Negative
1	1	Book Storage Room next to A Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative
1	1	Hallway between C and D Wings and Gymnasium/Pool	W1	CMU	PURPLE	INTACT	0	0	Negative
1	1	Hallway between C and D Wings and Gymnasium/Pool	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	Hallway between C and D Wings and Gymnasium/Pool	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	Hallway between C and D Wings and Gymnasium/Pool	DOOR CASING	METAL	BEIGE	INTACT	0	0.01	Negative
1	1	Hallway between C and D Wings and Gymnasium/Pool	DOOR	METAL	BEIGE	INTACT	0	0	Negative
1	1	Hallway between C and D Wings and Gymnasium/Pool	DOOR CENTER PANEL	METAL	BROWN	INTACT	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Hallway between C and D Wings and Gymnasium/Pool	Pipe Chase Door	METAL	BEIGE	INTACT	0	0	Negative
1	1	Men's Staff Restroom in hallway between C and D Wings	DOOR CASING	METAL	BLUE	INTACT	0	0.5	Negative
1	1	Men's Staff Restroom in hallway between C and D Wings	W1	CMU	WHITE	INTACT	0	0	Negative
1	1	Men's Staff Restroom in hallway between C and D Wings	W4	CMU	WHITE	INTACT	0	0	Negative
1	1	Men's Staff Restroom in hallway between C and D Wings	W3	CMU	WHITE	INTACT	0	0	Negative
1	1	Men's Staff Restroom in hallway between C and D Wings	W2	CMU	WHITE	INTACT	0	0.01	Negative
1	1	Men's Staff Restroom in hallway between C and D Wings	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	Women's Staff Restroom in hallway between C and D Wings	W1	CMU	Purple	Intact	0	0.2	Negative
1	1	Women's Staff Restroom in hallway between C and D Wings	W2	CMU	Beige	Intact	0	0.1	Negative
1	1	Women's Staff Restroom in hallway between C and D Wings	W3	CMU	Beige	Intact	0	0.1	Negative
1	1	Women's Staff Restroom in hallway between C and D Wings	Door	Metal	Beige	Intact	0	0.1	Negative
1	1	Women's Staff Restroom in hallway between C and D Wings	Door Center POS	Metal	Brown	Intact	0	0	Negative
1	1	Women's Staff Restroom in hallway between C and D Wings	Door Casing	Metal	Beige	Intact	0	0.2	Negative
1	1	Women's Staff Restroom in hallway between C and D Wings	Door	Wood	White	Intact	0	0	Negative
1	1	Women's Staff Restroom in hallway between C and D Wings	Door Casing	Metal	White	Intact	0	0.2	Negative
1	1	Hallway outside D Wing Classrooms D1 - D7	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside D Wing Classrooms D1 - D7	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside D Wing Classrooms D1 - D7	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside D Wing Classrooms D1 - D7	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside D Wing Classrooms D1 - D7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside D Wing Classrooms D1 - D7	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway connecting C Wing and D Wing	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	Hallway connecting C Wing and D Wing	W4	CMU	BEIGE	INTACT	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Hallway connecting C Wing and D Wing	DOOR CASING	METAL	BLUE	INTACT	0	0.15	Negative
1	1	Hallway connecting C Wing and D Wing	DOOR	METAL	BLUE	INTACT	0	0	Negative
1	1	Hallway connecting C Wing and D Wing	DOOR CENTER PANEL	METAL	BLUE	INTACT	0	0.07	Negative
1	1	Hallway connecting C Wing and D Wing	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	Hallway connecting C Wing and D Wing	STAIRS RAILING	METAL	BROWN	INTACT	0	0	Negative
1	1	Hallway connecting C Wing and D Wing	STAIRS RISER	METAL	BROWN	INTACT	0	0.9	Positive
1	1	Hallway connecting C Wing and D Wing	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.8	Positive
1	1	Hallway outside C Wing Classrooms C1 - C7	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside C Wing Classrooms C1 - C7	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside C Wing Classrooms C1 - C7	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside C Wing Classrooms C1 - C7	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside C Wing Classrooms C1 - C7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway outside C Wing Classrooms C1 - C7	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet in H02 between classrooms C6 and C7	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet in H02 between classrooms C6 and C7	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet in H02 between classrooms C6 and C7	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet in H02 between classrooms C6 and C7	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet in H02 between classrooms C6 and C7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet in H02 between classrooms C6 and C7	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	D Wing Lunch Room	W1	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	D Wing Lunch Room	W2	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	D Wing Lunch Room	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	D Wing Lunch Room	W4	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	D Wing Lunch Room	COLUMN	CONCRETE	BEIGE	INTACT	0	0.02	Negative
1	1	D Wing Lunch Room	COLUMN	CONCRETE	BLUE	INTACT	0	0	Negative
1	1	D Wing Lunch Room	COLUMN	CONCRETE	BLUE	INTACT	0	0	Negative
1	1	D Wing Lunch Room	COLUMN	CONCRETE	BEIGE	INTACT	0	0.01	Negative
1	1	D Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.05	Negative
1	1	D Wing Lunch Room	DOOR	WOOD	BLUE	INTACT	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	D Wing Lunch Room	VENT COVER	METAL	BLUE	INTACT	0	0	Negative
1	1	D Wing Lunch Room	STAIRS RISER	METAL	BROWN	INTACT	0	0.7	Positive
1	1	D Wing Lunch Room	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.5	Negative
1	1	D Wing Lunch Room	STAIRS RAILING	METAL	BROWN	INTACT	0	1	Positive
1	1	D Wing Lunch Room	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	D Wing Lunch Room	SOFFIT	Plaster	BLUE	INTACT	0	0	Negative
1	1	D Wing Lunch Room	SOFFIT	Plaster	BLUE	INTACT	0	0	Negative
1	1	Storage Closet in D Wing Lunch Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in D Wing Lunch Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in D Wing Lunch Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in D Wing Lunch Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in D Wing Lunch Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in D Wing Lunch Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Stairwell inside D Wing Lunch Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside D Wing Lunch Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside D Wing Lunch Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside D Wing Lunch Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside D Wing Lunch Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside D Wing Lunch Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	C Wing Lunch Room	W1	CMU	BLUE	INTACT	0	0.01	Negative
1	1	C Wing Lunch Room	W2	CMU	BLUE	INTACT	0	0.01	Negative
1	1	C Wing Lunch Room	W3	CMU	BLUE	INTACT	0	0	Negative
1	1	C Wing Lunch Room	W4	CMU	BLUE	INTACT	0	0.01	Negative
1	1	C Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative
1	1	C Wing Lunch Room	DOOR	METAL	BLUE	INTACT	0	0.01	Negative
1	1	C Wing Lunch Room	SOFFIT	PLASTER	BEIGE	INTACT	0	0	Negative
1	1	C Wing Lunch Room	STAIRS RAILING	METAL	BROWN	INTACT	0	0.21	Negative
1	1	C Wing Lunch Room	STAIRS RISER	METAL	BROWN	INTACT	0	0.5	Negative
1	1	C Wing Lunch Room	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.8	Positive
1	1	C Wing Lunch Room	CEILING	CONCRETE	WHITE	Flaking	15	0.03	Negative
1	1	C Wing Lunch Room	SOFFIT	PLASTER	BEIGE	INTACT	0	0	Negative
1	1	C Wing Lunch Room	SOFFIT	PLASTER	BEIGE	INTACT	0	0	Negative
1	1	Stairwell inside C Wing Lunch Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell inside C Wing Lunch Room	W2	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia							
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report							
		Inspection Company: Acer Associates	E.W. Rhodes ES School							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Stairwell inside C Wing Lunch Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell inside C Wing Lunch Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell inside C Wing Lunch Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell inside C Wing Lunch Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom D6 and D7	W1	CMU	WHITE	None	0	0	Negative	
1	1	Classroom D6 and D7	W4	CMU	WHITE	None	0	0.01	Negative	
1	1	Classroom D6 and D7	W2	CMU	WHITE	None	0	0.01	Negative	
1	1	Classroom D6 and D7	W3	CMU	PURPLE	None	0	0	Negative	
1	1	Classroom D6 and D7	W3	CMU	WHITE	None	0	0.02	Negative	
1	1	Classroom D6 and D7	SOFFIT	Plaster	WHITE	None	0	0	Negative	
1	1	Classroom D6 and D7	SOFFIT	Plaster	WHITE	None	0	0	Negative	
1	1	Classroom D6 and D7	COLUMN	METAL	WHITE	None	0	0.01	Negative	
1	1	Classroom D6 and D7	WALL DIVIDER TR	WOOD	WHITE	None	0	0	Negative	
1	1	Classroom D6 and D7	CEILING COLUMN	CONCRETE	WHITE	None	0	0.01	Negative	
1	1	Classroom D6 and D7	DOOR CASING	METAL	BEIGE	None	0	0.01	Negative	
1	1	Classroom D6 and D7	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	
1	1	Classroom D5	DOOR CASING	METAL	BLUE	None	0	0	Negative	
1	1	Classroom D5	DOOR	WOOD	BLUE	None	0	0	Negative	
1	1	Classroom D5	W1	CMU	WHITE	None	0	0	Negative	
1	1	Classroom D5	W4	CMU	WHITE	None	0	0.03	Negative	
1	1	Classroom D5	W3	CMU	PURPLE	None	0	0.02	Negative	
1	1	Classroom D5	SOFFIT	Plaster	WHITE	None	0	0	Negative	
1	1	Classroom D5	COLUMN	CONCRETE	PURPLE	None	0	0.01	Negative	
1	1	Classroom D5	WALL DIVIDER TR	WOOD	WHITE	None	0	0	Negative	
1	1	Classroom D5	WALL DIVIDER	DRYWALL	WHITE	None	0	0	Negative	
1	1	Classroom D4	WALL DIVIDER	DRYWALL	WHITE	None	0	0	Negative	
1	1	Classroom D4	WALL DIVIDER TR	WOOD	WHITE	None	0	0	Negative	
1	1	Classroom D4	W1	CMU	WHITE	None	0	0.02	Negative	
1	1	Classroom D4	W2	CMU	WHITE	None	0	0.01	Negative	
1	1	Classroom D4	W3	CMU	WHITE	None	0	0.02	Negative	
1	1	Classroom D4	W3	CMU	PURPLE	None	0	0.05	Negative	
1	1	Classroom D4	COLUMN	CONCRETE	PURPLE	None	0	0.01	Negative	
1	1	Classroom D4	COLUMN	CONCRETE	WHITE	None	0	0	Negative	

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom D4	SOFFIT 3	Plaster	WHITE	Efflorescence	3	0	Negative
1	1	Classroom D4	SOFFIT	Plaster	WHITE	None	0	0.03	Negative
1	1	Classroom D4	COLUMN	CONCRETE	WHITE	None	0	0.05	Negative
1	1	Classroom D3	W3	CMU	WHITE	None	0	0.04	Negative
1	1	Classroom D3	W4	CMU	WHITE	None	0	0	Negative
1	1	Classroom D3	W2	CMU	PURPLE	None	0	0.01	Negative
1	1	Classroom D3	UNIVENT	METAL	BEIGE	None	0	0	Negative
1	1	Classroom D3	SOFFIT	Plaster	WHITE	None	0	0.01	Negative
1	1	Classroom D3	SOFFIT	Plaster	WHITE	None	0	0.02	Negative
1	1	Classroom D3	DIVIDER WALL TP	WOOD	WHITE	None	0	0.01	Negative
1	1	Classroom D3	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative
1	1	Classroom D3	DOOR CENTER PC	METAL	BEIGE	None	0	0.01	Negative
1	1	Classroom D2	DOOR CASING	METAL	BLACK	None	0	0.01	Negative
1	1	Classroom D2	W1	CMU	WHITE	None	0	0.03	Negative
1	1	Classroom D2	W2	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom D2	W3	CMU	GREEN	None	0	0.01	Negative
1	1	Classroom D2	W3	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom D2	SOFFIT	Plaster	WHITE	Efflorescence	6	0	Negative
1	1	Classroom D2	UNIVENT	Metal	WHITE	None	0	0	Negative
1	1	Classroom D2	COLUMN	CONCRETE	GREEN	None	0	0.02	Negative
1	1	Classroom D2	DIVIDER WALL TP	WOOD	WHITE	None	0	0.01	Negative
1	1	Classroom D2	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative
1	1	Classroom D1	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	1	Classroom D1	W1	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom D1	W2	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom D1	W4	CMU	WHITE	None	0	0.03	Negative
1	1	Classroom D1	W3	CMU	PURPLE	None	0	0.01	Negative
1	1	Classroom D1	COLUMN	METAL	PURPLE	None	0	0.01	Negative
1	1	Classroom D1	SOFFIT	Plaster	WHITE	None	0	0.02	Negative
1	1	Classroom D1	SOFFIT	Plaster	WHITE	None	0	0.03	Negative
1	1	Classroom D1	UNIVENT	METAL	WHITE	None	0	0	Negative
1	1	D Wing Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative
1	1	D Wing Boy's Restroom	W2	CMU	BEIGE	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	D Wing Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative
1	1	D Wing Boy's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative
1	1	D Wing Boy's Restroom	DOOR CASING	METAL	BLACK	None	0	0.11	Negative
1	1	Storage Closet in H02 between classrooms C6 and C7	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in H02 between classrooms C6 and C7	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in H02 between classrooms C6 and C7	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in H02 between classrooms C6 and C7	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in H02 between classrooms C6 and C7	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet in H02 between classrooms C6 and C7	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	D Wing Girl's Restroom	DOOR CASING	METAL	BLACK	None	0	0.3	Negative
1	1	D Wing Girl's Restroom	W1	CMU	BEIGE	None	0	0	Negative
1	1	D Wing Girl's Restroom	W2	CMU	BEIGE	None	0	0	Negative
1	1	D Wing Girl's Restroom	W3	CMU	BEIGE	None	0	0	Negative
1	1	D Wing Girl's Restroom	W4	CMU	BEIGE	None	0	0	Negative
1	1	D Wing Girl's Restroom	CEILING	Concrete	BEIGE	None	0	0	Negative
1	1	Stairwell between C and D Wings	W1	CMU	BEIGE	None	0	0	Negative
1	1	Stairwell between C and D Wings	W4	CMU	BEIGE	None	0	0	Negative
1	1	Stairwell between C and D Wings	DOOR CASING	METAL	BLUE	None	0	0.15	Negative
1	1	Stairwell between C and D Wings	DOOR	METAL	BLUE	None	0	0	Negative
1	1	Stairwell between C and D Wings	DOOR CENTER PANEL	METAL	BLUE	None	0	0.07	Negative
1	1	Stairwell between C and D Wings	W3	CMU	BEIGE	None	0	0	Negative
1	1	Stairwell between C and D Wings	STAIRS RAILING	METAL	BROWN	None	0	0	Negative
1	1	Stairwell between C and D Wings	STAIRS RISER	METAL	BROWN	None	0	0.9	Positive
1	1	Stairwell between C and D Wings	STAIRS STRINGER	METAL	BROWN	None	0	0.8	Positive
1	1	C Wing Girl's Restroom	DOOR CASING	METAL	BLACK	None	0	0.15	Negative
1	1	C Wing Girl's Restroom	W1	CMU	YELLOW	None	0	0	Negative
1	1	C Wing Girl's Restroom	W2	CMU	YELLOW	None	0	0	Negative
1	1	C Wing Girl's Restroom	W3	CMU	YELLOW	None	0	0	Negative
1	1	C Wing Girl's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative
1	1	C Wing Boy's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative
1	1	C Wing Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative
1	1	C Wing Boy's Restroom	W4	CMU	BEIGE	None	0	0	Negative
1	1	C Wing Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	C Wing Boy's Restroom	DOOR CASING	METAL	BLACK	None	0	0.21	Negative
1	1	Storage Closet between boy's and girl's restrooms in C wing	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet between boy's and girl's restrooms in C wing	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet between boy's and girl's restrooms in C wing	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet between boy's and girl's restrooms in C wing	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet between boy's and girl's restrooms in C wing	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet between boy's and girl's restrooms in C wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell behind C Wing Classroom C7	W1	BRICK	BEIGE	None	0	0.01	Negative
1	1	Stairwell behind C Wing Classroom C7	W2	BRICK	BEIGE	None	0	0.01	Negative
1	1	Stairwell behind C Wing Classroom C7	W4	BRICK	BEIGE	None	0	0.01	Negative
1	1	Stairwell behind C Wing Classroom C7	W3	BRICK	BEIGE	None	0	0.03	Negative
1	1	Stairwell behind C Wing Classroom C7	W3	DRYWALL	BEIGE	None	0	0	Negative
1	1	Stairwell behind C Wing Classroom C7	STAIRS RISER	METAL	BEIGE	None	0	0.6	Negative
1	1	Stairwell behind C Wing Classroom C7	STAIRS STRINGER	METAL	BEIGE	None	0	1.2	Positive
1	1	Stairwell behind C Wing Classroom C7	STAIRS RAILING	METAL	BEIGE	None	0	0.02	Negative
1	1	Stairwell behind C Wing Classroom C7	STAIRS HALF WALL	WOOD	BEIGE	None	0	0	Negative
1	1	Stairwell behind C Wing Classroom C7	W3	CMU	BEIGE	None	0	0	Negative
1	1	Stairwell behind C Wing Classroom C7	DOOR CASING	METAL	BEIGE	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Stairwell behind C Wing Classroom C7	DOOR	METAL	BEIGE	None	0	0	Negative
1	1	Stairwell behind C Wing Classroom C7	DOOR CENTER PANEL	METAL	BEIGE	None	0	0	Negative
1	1	Stairwell behind C Wing Classroom C7	UNIVENT	METAL	BEIGE	None	0	0.01	Negative
1	1	Stairwell behind C Wing Classroom C7	CEILING	CONCRETE	BEIGE	None	0	0.04	Negative
1	1	Classroom C7	DOOR CASING	METAL	BLUE	None	0	0.04	Negative
1	1	Classroom C7	DOOR	WOOD	BLUE	None	0	0	Negative
1	1	Classroom C7	W1	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C7	W2	CMU	WHITE	None	0	0.02	Negative
1	1	Classroom C7	W3	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C7	DIVIDER WALL TRIM	WOOD	WHITE	None	0	0	Negative
1	1	Classroom C7	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative
1	1	Classroom C6	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative
1	1	Classroom C6	DIVIDER WALL TRIM	WOOD	WHITE	None	0	0.01	Negative
1	1	Classroom C6	W1	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C6	W4	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C6	W2	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C6	W3	CMU	GREEN	None	0	0.02	Negative
1	1	Classroom C6	SOFFIT	PLASTER	WHITE	None	0	0.05	Negative
1	1	Classroom C6	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative
1	1	Classroom C6	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	1	Classroom C5	W1	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C5	W2	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C5	W3	CMU	WHITE	None	0	0	Negative
1	1	Classroom C5	SOFFIT	PLASTER	WHITE	None	0	0	Negative
1	1	Classroom C5	DIVIDER WALL TRIM	WOOD	WHITE	None	0	0.01	Negative
1	1	Classroom C5	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative
1	1	Classroom C4	SOFFIT	Plaster	WHITE	None	0	0.02	Negative
1	1	Classroom C4	SOFFIT	Plaster	WHITE	None	0	0.01	Negative
1	1	Classroom C4	W1	CMU	WHITE	None	0	0.02	Negative
1	1	Classroom C4	W4	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C4	W3	CMU	GREEN	None	0	0.01	Negative
1	1	Classroom C4	COLUMN	METAL	GREEN	None	0	0.01	Negative
1	1	Classroom C4	COLUMN	METAL	WHITE	None	0	0.01	Negative
1	1	Classroom C4	DIVIDER WALL TRIM	WOOD	WHITE	None	0	0.05	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom C4	DIVIDER WALL	DRYWALL	WHITE	None	0	0.02	Negative
1	1	Classroom C4	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	1	Classroom C4	DOOR	WOOD	BLUE	None	0	0	Negative
1	1	Classroom C3	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative
1	1	Classroom C3	DIVIDER WALL TR	WOOD	WHITE	None	0	0	Negative
1	1	Classroom C3	W1	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C3	W2	CMU	WHITE	None	0	0.03	Negative
1	1	Classroom C3	W3	CMU	GREEN	None	0	0.01	Negative
1	1	Classroom C3	SOFFIT	Plaster	WHITE	None	0	0.02	Negative
1	1	Classroom C3	SOFFIT	Plaster	WHITE	None	0	0.01	Negative
1	1	Classroom C2	SOFFIT	Plaster	WHITE	None	0	0.02	Negative
1	1	Classroom C2	W1	CMU	BEIGE	None	0	0.01	Negative
1	1	Classroom C2	DOOR CASING	METAL	BLUE	None	0	0.09	Negative
1	1	Classroom C2	W4	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C2	W3	CMU	GREEN	None	0	0.01	Negative
1	1	Classroom C2	SOFFIT	Plaster	WHITE	None	0	0.01	Negative
1	1	Classroom C2	DIVIDER WALL TR	WOOD	WHITE	None	0	0	Negative
1	1	Classroom C2	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative
1	1	Classroom C2	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative
1	1	Classroom C1	W1	CMU	WHITE	None	0	0.02	Negative
1	1	Classroom C1	W4	CMU	WHITE	None	0	0	Negative
1	1	Classroom C1	W3	CMU	WHITE	None	0	0.03	Negative
1	1	Classroom C1	W2	CMU	GREEN	None	0	0.01	Negative
1	1	Classroom C1	COLUMN	METAL	GREEN	None	0	0.02	Negative
1	1	Classroom C1	SOFFIT	Plaster	WHITE	None	0	0.02	Negative
1	1	Classroom C1	W2	CMU	WHITE	None	0	0.01	Negative
1	1	Classroom C1	SOFFIT	Plaster	WHITE	None	0	0.02	Negative
1	1	Kitchen	W1	CMU	BEIGE	None	0	0	Negative
1	1	Kitchen	W2	CMU	BEIGE	None	0	0.01	Negative
1	1	Kitchen	W3	CMU	BEIGE	None	0	0.02	Negative
1	1	Kitchen	W4	CMU	BEIGE	None	0	0.01	Negative
1	1	Kitchen	DOOR	WOOD	BLUE	None	0	0.03	Negative
1	1	Kitchen	DOOR CASING	METAL	BLUE	None	0	0.03	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Kitchen	COLUMN	METAL	BEIGE	None	0	0.01	Negative
1	1	Kitchen	W4	CMU	WHITE	None	0	0	Negative
1	1	Kitchen	DOOR CASING	METAL	BLUE	None	0	0.03	Negative
1	1	Kitchen	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	1	Kitchen Locker Room	DOOR	WOOD	BLUE	None	0	0.06	Negative
1	1	Kitchen Locker Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	1	Kitchen Locker Room	W1	CMU	YELLOW	None	0	0	Negative
1	1	Kitchen Locker Room	W2	CMU	YELLOW	None	0	0	Negative
1	1	Kitchen Locker Room	W4	CMU	YELLOW	None	0	0.04	Negative
1	1	Kitchen Locker Room	W3	CMU	YELLOW	None	0	0.01	Negative
1	1	Kitchen Custodial Closet near C Cafeteria	W1	CMU	BEIGE	None	0	0	Negative
1	1	Kitchen Custodial Closet near C Cafeteria	W1	DRYWALL	BEIGE	None	0	0	Negative
1	1	Kitchen Custodial Closet near C Cafeteria	DOOR CENTER PANEL	METAL	BLUE	None	0	0.09	Negative
1	1	Kitchen Custodial Closet near C Cafeteria	W2	CMU	BEIGE	None	0	0.01	Negative
1	1	Kitchen Custodial Closet near C Cafeteria	W3	CMU	BEIGE	None	0	0.02	Negative
1	1	Kitchen Custodial Closet near C Cafeteria	W4	CMU	BEIGE	None	0	0.03	Negative
1	1	Kitchen Lounge	DOOR	WOOD	BLUE	None	0	0.06	Negative
1	1	Kitchen Lounge	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	1	Kitchen Lounge	W1	CMU	YELLOW	None	0	0	Negative
1	1	Kitchen Lounge	W2	CMU	YELLOW	None	0	0	Negative
1	1	Kitchen Lounge	W4	CMU	YELLOW	None	0	0.04	Negative
1	1	Kitchen Lounge	W3	CMU	YELLOW	None	0	0.01	Negative
1	1	Kitchen Lounge Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Kitchen Lounge Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Kitchen Lounge Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Kitchen Lounge Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Kitchen Lounge Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Kitchen Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Dietician's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Dietician's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Dietician's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Dietician's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Dietician's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Dietician's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Storage Room next to C Wing Lunch Room	W1	CONCRETE	WHITE	None	0	0	Negative
1	1	Storage Room next to C Wing Lunch Room	W4	CMU	WHITE	None	0	0	Negative
1	1	Storage Room next to C Wing Lunch Room	W2	CMU	BEIGE	None	0	0	Negative
1	1	Storage Room next to C Wing Lunch Room	FLOOR	METAL	GRAY	None	0	0	Negative
1	1	Storage Room next to C Wing Lunch Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	1	Storage Room next to C Wing Lunch Room	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	1	Walk in Freezer Room	W1	CONCRETE	WHITE	None	0	0	Negative
1	1	Walk in Freezer Room	W4	CMU	WHITE	None	0	0	Negative
1	1	Walk in Freezer Room	W2	CMU	BEIGE	None	0	0	Negative
1	1	Walk in Freezer Room	FLOOR	METAL	GRAY	None	0	0	Negative
1	1	Walk in Freezer Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	1	Walk in Freezer Room	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	1	Food Storage Room next to D Wing Lunch Room	W1	CONCRETE	WHITE	None	0	0	Negative
1	1	Food Storage Room next to D Wing Lunch Room	W4	CMU	WHITE	None	0	0	Negative
1	1	Food Storage Room next to D Wing Lunch Room	W2	CMU	BEIGE	None	0	0	Negative
1	1	Food Storage Room next to D Wing Lunch Room	FLOOR	METAL	GRAY	None	0	0	Negative
1	1	Food Storage Room next to D Wing Lunch Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	1	Food Storage Room next to D Wing Lunch Room	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	1	Closet inside Food Storage Room next to D Wing Lunch Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Closet inside Food Storage Room next to D Wing Lunch Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Closet inside Food Storage Room next to D Wing Lunch Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Closet inside Food Storage Room next to D Wing Lunch Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Closet inside Food Storage Room next to D Wing Lunch Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Closet inside Food Storage Room next to D Wing Lunch Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Stairwell next to D Wing Classroom D7	W1	BRICK	BEIGE	None	0	0.01	Negative
1	1	Stairwell next to D Wing Classroom D7	W2	BRICK	BEIGE	None	0	0.01	Negative
1	1	Stairwell next to D Wing Classroom D7	W4	BRICK	BEIGE	None	0	0.01	Negative
1	1	Stairwell next to D Wing Classroom D7	W3	BRICK	BEIGE	None	0	0.03	Negative
1	1	Stairwell next to D Wing Classroom D7	W3	DRYWALL	BEIGE	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Stairwell next to D Wing Classroom D7	STAIRS RISER	METAL	BEIGE	None	0	0.6	Negative
1	1	Stairwell next to D Wing Classroom D7	STAIRS STRINGER	METAL	BEIGE	None	0	1.2	Positive
1	1	Stairwell next to D Wing Classroom D7	STAIRS RAILING	METAL	BEIGE	None	0	0.02	Negative
1	1	Stairwell next to D Wing Classroom D7	STAIRS HALF WALL	WOOD	BEIGE	None	0	0	Negative
1	1	Stairwell next to D Wing Classroom D7	W3	CMU	BEIGE	None	0	0	Negative
1	1	Stairwell next to D Wing Classroom D7	DOOR CASING	METAL	BEIGE	None	0	0	Negative
1	1	Stairwell next to D Wing Classroom D7	DOOR	METAL	BEIGE	None	0	0	Negative
1	1	Stairwell next to D Wing Classroom D7	DOOR CENTER PANEL	METAL	BEIGE	None	0	0	Negative
1	1	Stairwell next to D Wing Classroom D7	UNIVENT	METAL	BEIGE	None	0	0.01	Negative
1	1	Stairwell next to D Wing Classroom D7	CEILING	CONCRETE	BEIGE	None	0	0.04	Negative
1	1	Men's Restroom behind D Wing Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Men's Restroom behind D Wing Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Men's Restroom behind D Wing Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Men's Restroom behind D Wing Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Men's Restroom behind D Wing Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Men's Restroom behind D Wing Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Women's Restroom behind D Wing Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Women's Restroom behind D Wing Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Women's Restroom behind D Wing Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Women's Restroom behind D Wing Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Women's Restroom behind D Wing Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Women's Restroom behind D Wing Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pool Area (closed)	W1	CMU	Beige	None	0	0.2	Negative
1	1	Pool Area (closed)	W4	CMU	Beige	None	0	0.2	Negative
1	1	Pool Area (closed)	W3	CMU	Beige	None	0	0.1	Negative
1	1	Pool Area (closed)	W2	CMU	Beige	None	0	0.1	Negative
1	1	Pool Area (closed)	Door Casing	Metal	Brown	None	0	0	Negative
1	1	Pool Area (closed)	Door	Metal	Brown	None	0	0.1	Negative
1	1	Pool Area (closed)	Door	Metal	Brown	None	0	0.1	Negative
1	1	Pool Area (closed)	Door Casing	Metal	Brown	None	0	0.1	Negative
1	1	Pool Area (closed)	Door Casing	Metal	Brown	None	0	0.1	Negative
1	1	Pool Area (closed)	Door	Wood	Brown	None	0	0	Negative
1	1	Storage/Pool Pump Room	W2	CMU	Yellow	None	0	0.1	Negative
1	1	Storage/Pool Pump Room	W4	CMU	Yellow	None	0	0.2	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Storage/Pool Pump Room	W3	CMU	Yellow	None	0	0.3	Negative
1	1	Storage/Pool Pump Room	Column	Concrete	Yellow	None	0	0.2	Negative
1	1	Pool Equipment Storage Room	W1	CMU	Beige	None	0	0.1	Negative
1	1	Pool Equipment Storage Room	W2	CMU	Beige	None	0	0.1	Negative
1	1	Pool Office	W1	CMU	White	None	0	0.1	Negative
1	1	Pool Office	W4	CMU	White	None	0	0.1	Negative
1	1	Pool Office	W3	CMU	White	None	0	0	Negative
1	1	Pool Office	W2	CMU	White	None	0	0.1	Negative
1	1	Boy's Locker Room Restroom and Showers	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom and Showers	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom and Showers	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom and Showers	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom and Showers	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom and Showers	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Changing Booth	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Locker Room Changing Booth	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Locker Room Changing Booth	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Locker Room Changing Booth	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Locker Room Changing Booth	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Locker Room Changing Booth	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Locker Room Hallway	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Hallway	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Hallway	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Hallway	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room - Main Area	W1	CMU	Beige	None	0	0.1	Negative
1	1	Boy's Locker Room - Main Area	W2	CMU	Beige	None	0	0.1	Negative
1	1	Boy's Locker Room - Main Area	W3	CMU	Beige	None	0	0.1	Negative
1	1	Boy's Locker Room - Main Area	W4	CMU	Beige	None	0	0.2	Negative
1	1	Boy's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.7	Positive
1	1	Boy's Locker Room - Main Area	Door	Wood	Tan	None	0	0.1	Negative
1	1	Boy's Locker Room - Main Area	Door	Wood	Tan	None	0	0.1	Negative
1	1	Boy's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.7	Positive

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Boy's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.6	Negative
1	1	Boy's Locker Room Shower Area	W2	CMU	Beige	None	0	0	Negative
1	1	Boy's Locker Room Shower Area	W3	CMU	Beige	None	0	0.1	Negative
1	1	Boy's Locker Room Shower Area	W4	CMU	Beige	None	0	0.1	Negative
1	1	Storage Closet inside Boy's Locker Room Main Area	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet inside Boy's Locker Room Main Area	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet inside Boy's Locker Room Main Area	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet inside Boy's Locker Room Main Area	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet inside Boy's Locker Room Main Area	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage Closet inside Boy's Locker Room Main Area	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Restroom next to Locker Room Main Area	Door Casing	Metal	Blue	None	0	0.3	Negative
1	1	Boy's Restroom next to Locker Room Main Area	Door	Wood	Blue	None	0	0.1	Negative
1	1	Boy's Restroom next to Locker Room Main Area	W1	CMU	White	None	0	0.1	Negative
1	1	Boy's Restroom next to Locker Room Main Area	W2	CMU	White	None	0	0.1	Negative
1	1	Boy's Restroom next to Locker Room Main Area	W3	CMU	White	None	0	0	Negative
1	1	Boy's Restroom next to Locker Room Main Area	W4	CMU	White	None	0	0.1	Negative
1	1	Boy's Restroom next to Locker Room Main Area	Ceiling	Concrete	White	None	0	0.1	Negative
1	1	Custodial Closet next to Boy's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Boy's Gym Teacher's Restroom Gym Office	W1	CMU	Blue	None	0	0.1	Negative
1	1	Boy's Gym Teacher's Restroom Gym Office	W4	CMU	Blue	None	0	0.1	Negative
1	1	Boy's Gym Teacher's Restroom Gym Office	W3	CMU	Blue	None	0	0.2	Negative
1	1	Boy's Gym Teacher's Restroom Gym Office	W2	CMU	Blue	None	0	0.2	Negative
1	1	Boy's Gym Teacher's Office	W1	CMU	Beige	None	0	0.2	Negative
1	1	Boy's Gym Teacher's Office	W2	CMU	Beige	None	0	0.1	Negative
1	1	Boy's Gym Teacher's Office	W3	CMU	Beige	None	0	0.2	Negative
1	1	Boy's Gym Teacher's Office	W4	CMU	Beige	None	0	0.1	Negative
1	1	Boy's Gym Teacher's Office	Door Casing	Metal	Blue	None	0	0.7	Positive
1	1	Boy's Gym Teacher's Office	Door	Wood	Blue	None	0	0.1	Negative
1	1	Boy's Gym Teacher's Office	Door	Wood	Blue	None	0	0.1	Negative
1	1	Boy's Gym Teacher's Office	Door Casing	Metal	Blue	None	0	0.6	Negative
1	1	Boy's Gym Teacher's Office	Door Casing	Wood	Blue	None	0	0	Negative
1	1	Boy's Gym Teacher's Office	Door Casing	Metal	Blue	None	0	0.5	Negative
1	1	Boy's Gym Storage Room across from the Gym Teacher's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Storage Room across from the Gym Teacher's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Storage Room across from the Gym Teacher's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Storage Room across from the Gym Teacher's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boy's Gym Storage Room across from the Gym Teacher's Office	Duct	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage room across from boy's changing booths	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage room across from boy's changing booths	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage room across from boy's changing booths	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage room across from boy's changing booths	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage room across from boy's changing booths	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage room across from boy's changing booths	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Gymnasium	W1	CMU	Beige	None	0	0.2	Negative
1	1	Gymnasium	W2	CMU	Beige	None	0	0.1	Negative
1	1	Gymnasium	W3	CMU	Beige	None	0	0	Negative
1	1	Gymnasium	W4	CMU	Beige	None	0	0.1	Negative
1	1	Gymnasium	Door Casing	Metal	Blue	None	0	0.2	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Gymnasium	Door Center POS	Metal	Blue	None	0	0	Negative
1	1	Gymnasium	Door	Wood	Blue	None	0	0	Negative
1	1	Stairwell in Boy's Side Gymnasium to Upper Weight Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Boy's Side Gymnasium to Upper Weight Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Boy's Side Gymnasium to Upper Weight Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Boy's Side Gymnasium to Upper Weight Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Boy's Side Gymnasium to Upper Weight Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Boy's Side Gymnasium to Upper Weight Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Girl's Side Gymnasium to Upper Weight Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Girl's Side Gymnasium to Upper Weight Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Girl's Side Gymnasium to Upper Weight Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Girl's Side Gymnasium to Upper Weight Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Girl's Side Gymnasium to Upper Weight Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell in Girl's Side Gymnasium to Upper Weight Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Upper Weight Room above Locker Rooms	W1	CMU	Blue	None	0	0	Negative
1	2	Upper Weight Room above Locker Rooms	W4	CMU	Blue	None	0	0.1	Negative
1	2	Upper Weight Room above Locker Rooms	W3	CMU	Blue	None	0	0.1	Negative
1	2	Upper Weight Room above Locker Rooms	W2	CMU	Blue	None	0	0.1	Negative
1	2	Upper Weight Room above Locker Rooms	W2	CMU	Yellow	None	0	0.1	Negative
1	2	Upper Weight Room above Locker Rooms	W1	CMU	Yellow	None	0	0.1	Negative
1	2	Upper Weight Room above Locker Rooms	W3	CMU	Yellow	None	0	0	Negative
1	2	Upper Weight Room above Locker Rooms	W4	CMU	Yellow	None	0	0.2	Negative
1	2	Upper Weight Room above Locker Rooms	Door Casing	Metal	Blue	None	0	0.2	Negative
1	2	Upper Weight Room above Locker Rooms	Door	Wood	Blue	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Girl's Locker Room Restroom	W2	CMU	Beige	None	0	0.1	Negative
1	1	Girl's Locker Room Restroom	W3	CMU	Beige	None	0	0.1	Negative
1	1	Girl's Locker Room Restroom	W4	CMU	Beige	None	0	0.1	Negative
1	1	Girl's Locker Room Changing Booth	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Changing Booth	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Changing Booth	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Changing Booth	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Changing Booth	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Changing Booth	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room - Main Area	W1	CMU	Beige	None	0	0.1	Negative
1	1	Girl's Locker Room - Main Area	W4	CMU	Beige	None	0	0.1	Negative
1	1	Girl's Locker Room - Main Area	W2	CMU	Beige	None	0	0	Negative
1	1	Girl's Locker Room - Main Area	W3	CMU	Beige	None	0	0.1	Negative
1	1	Girl's Locker Room - Main Area	Door Casing	Metal	Beige	None	0	0.5	Negative
1	1	Girl's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.6	Negative
1	1	Girl's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.5	Negative
1	1	Girl's Locker Room Shower Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Shower Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Shower Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Shower Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Shower Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Shower Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Girl's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Girl's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Girl's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Girl's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Girl's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Girl's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom next to Locker Room Main Area	W1	CMU	White	None	0	0.1	Negative
1	1	Girl's Restroom next to Locker Room Main Area	W2	CMU	White	None	0	0	Negative
1	1	Girl's Restroom next to Locker Room Main Area	W3	CMU	White	None	0	0	Negative
1	1	Girl's Restroom next to Locker Room Main Area	W4	CMU	White	None	0	0.2	Negative
1	1	Girl's Restroom next to Locker Room Main Area	Ceiling	Concrete	White	None	0	0	Negative
1	1	Girl's Restroom next to Locker Room Main Area	Door Casing	Metal	Blue	None	0	0.7	Positive

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Girl's Restroom next to Locker Room Main Area	Door	Wood	Blue	None	0	0	Negative
1	1	Custodial Closet next to Girl's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Gym Teacher's Restroom Gym Office	W1	CMU	Yellow	None	0	0.1	Negative
1	1	Girl's Gym Teacher's Restroom Gym Office	W2	CMU	Yellow	None	0	0.1	Negative
1	1	Girl's Gym Teacher's Restroom Gym Office	W3	CMU	Yellow	None	0	0	Negative
1	1	Girl's Gym Teacher's Restroom Gym Office	W4	CMU	Yellow	None	0	0.4	Negative
1	1	Girl's Gym Teacher's Restroom Gym Office	Door Casing	Metal	Blue	None	0	0.5	Negative
1	1	Girl's Gym Teacher's Restroom Gym Office	Door	Wood	Blue	None	0	0	Negative
1	1	Girl's Gym Teacher's Office	W1	CMU	Beige	None	0	0	Negative
1	1	Girl's Gym Teacher's Office	W4	CMU	Beige	None	0	0.1	Negative
1	1	Girl's Gym Teacher's Office	W3	CMU	Beige	None	0	0.2	Negative
1	1	Girl's Gym Teacher's Office	W2	CMU	Beige	None	0	0.1	Negative
1	1	Girl's Gym Teacher's Office	Door Casing	Metal	Beige	None	0	0.7	Positive
1	1	Girl's Gym Teacher's Office	Door Casing	Metal	Beige	None	0	0.8	Positive
1	1	Girl's Gym Teacher's Office	Door	Wood	Beige	None	0	0.1	Negative
1	1	Girl's Gym Teacher's Office	Door Casing	Metal	Beige	None	0	0.6	Negative
1	1	Girl's Gym Storage Room across from the Gym Teacher's Office	W1	CMU	Brown	Flaking	60	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Girl's Gym Storage Room across from the Gym Teacher's Office	W2	CMU	Brown	None	0	0	Negative
1	1	Girl's Gym Storage Room across from the Gym Teacher's Office	W3	CMU	Brown	None	0	0.1	Negative
1	1	Girl's Gym Storage Room across from the Gym Teacher's Office	W4	CMU	Brown	None	0	0.2	Negative
1	1	Girl's Gym Storage Room across from the Gym Teacher's Office	Duct	Metal	Brown	None	0	0.1	Negative
1	1	Vestibule outside School Police Office	Stairs - Railing	Metal	Brown	None	0	0.3	Negative
1	1	Vestibule outside School Police Office	Stairs - Stringer	Metal	Brown	None	0	1.5	Positive
1	1	Vestibule outside School Police Office	Stairs - Riser	Metal	Brown	None	0	1.5	Positive
1	1	School Police Office	W1	CMU	Beige	None	0	0.1	Negative
1	1	School Police Office	W2	CMU	Beige	None	0	0.1	Negative
1	1	School Police Office	W3	CMU	Beige	None	0	0.1	Negative
1	1	School Police Office	W4	CMU	Beige	None	0	0.2	Negative
1	1	School Police Office	Soffit	Plaster	Beige	Efflorescence	31	0.1	Negative
1	1	School Police Office Holding Cell	W1	CMU	Beige	None	0	0.2	Negative
1	1	School Police Office Holding Cell	W2	CMU	Beige	None	0	0.2	Negative
1	1	School Police Office Holding Cell	W3	CMU	Beige	None	0	0.1	Negative
1	1	School Police Office Holding Cell	W4	CMU	Beige	None	0	0.1	Negative
1	1	School Police Office Holding Cell	Column	Concrete	Beige	None	0	0.1	Negative
1	1	School Police Office Holding Cell	Window Casing	Metal	Blue	None	0	0.2	Negative
1	1	School Police Office Holding Cell	Door Casing	Metal	Blue	None	0	0	Negative
1	1	School Police Office Holding Cell	Door	Wood	Blue	None	0	0	Negative
1	1	Principal's Storage Room next to School Police Office	W1	CMU	Beige	None	0	0.1	Negative
1	1	Principal's Storage Room next to School Police Office	W4	CMU	Beige	None	0	0.1	Negative
1	1	Principal's Storage Room next to School Police Office	W3	CMU	Beige	None	0	0	Negative
1	1	Principal's Storage Room next to School Police Office	W2	CMU	Blue	None	0	0	Negative
1	1	Principal's Storage Room next to School Police Office	Door Casing	Metal	Blue	None	0	0.4	Negative
1	1	Principal's Storage Room next to School Police Office	Door	Wood	Blue	None	0	0	Negative
1	1	Principal's Storage Room next to School Police Office	Door	Wood	Blue	None	0	0.1	Negative
1	1	Principal's Storage Room next to School Police Office	Door Casing	Metal	Blue	None	0	0	Negative
1	1	Principal's Storage Room next to School Police Office	Window Casing	Metal	Blue	None	0	0	Negative
1	1	Main Entrance Foyer	W1	CMU	Beige	None	0	0.2	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Main Entrance Foyer	W3	CMU	Beige	None	0	0.2	Negative
1	1	Main Entrance Foyer	W4	CMU	Beige	None	0	0.1	Negative
1	1	Main Entrance Foyer	Door Casing	Metal	Blue	None	0	0.4	Negative
1	1	Main Entrance Foyer	Door Center Post	Metal	Blue	None	0	0.3	Negative
1	1	Main Entrance Foyer	Door	Metal	Blue	None	0	0.1	Negative
1	1	Main Entrance Foyer	Door	Metal	Beige	None	0	0	Negative
1	1	Main Entrance Foyer	Door Casing	Metal	Beige	None	0	0.1	Negative
1	1	Storage Closet inside Principal's Storage Room next to School Police Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Principal's Storage Room next to School Police Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Principal's Storage Room next to School Police Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Principal's Storage Room next to School Police Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Principal's Storage Room next to School Police Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage Closet inside Principal's Storage Room next to School Police Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway/Loading Dock outside Building Engineer's Office	W1	CMU	Blue	None	0	0.1	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	W3	CMU	Blue	None	0	0.1	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	W4	CMU	Beige	None	0	0.1	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	Door Casing	Metal	Beige	None	0	0.4	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	Door	Wood	Beige	None	0	0.1	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	Column	Concrete	Beige	None	0	0.3	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	W2	CMU	Beige	None	0	0.1	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	W1	CMU	Brown	None	0	0.1	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	W2	CMU	Brown	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Hallway/Loading Dock outside Building Engineer's Office	W3	CMU	Brown	None	0	0.5	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	W4	CMU	Brown	None	0	0	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	Column	Concrete	Brown	None	0	0.3	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	Pipe	Metal	Brown	None	0	0.8	Positive
1	1	Hallway/Loading Dock outside Building Engineer's Office	Door	Wood	Brown	None	0	0.1	Negative
1	1	Hallway/Loading Dock outside Building Engineer's Office	Door	Wood	Blue	None	0	0	Negative
1	1	Men's Restroom next to Building Engineer's Office	W2	CMU	Beige	None	0	0	Negative
1	1	Men's Restroom next to Building Engineer's Office	W1	CMU	Beige	None	0	0	Negative
1	1	Men's Restroom next to Building Engineer's Office	W4	CMU	Beige	None	0	0.1	Negative
1	1	Men's Restroom next to Building Engineer's Office	W3	CMU	Beige	None	0	0.1	Negative
1	1	Men's Restroom next to Building Engineer's Office	Door Casing	Metal	Blue	None	0	0.5	Negative
1	1	Men's Restroom next to Building Engineer's Office	Door	Wood	Blue	None	0	0	Negative
1	1	Building Engineer's Office	W1	CMU	Beige	None	0	0.1	Negative
1	1	Building Engineer's Office	W2	CMU	Beige	None	0	0	Negative
1	1	Building Engineer's Office	W3	CMU	Beige	None	0	0.1	Negative
1	1	Building Engineer's Office	W4	CMU	Beige	None	0	0.1	Negative
1	1	Building Engineer's Office	Window Casing	Metal	Blue	None	0	0.1	Negative
1	1	Building Engineer's Office	Door Casing	Metal	Blue	None	0	0.3	Negative
1	1	Building Engineer's Office	Door	Wood	Blue	None	0	0.1	Negative
1	1	Pipe Chase in Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Building Engineer's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Building Engineer's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Building Engineer's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Office next to Building Engineer's Office	W1	CMU	Beige	None	0	0	Negative
1	1	Office next to Building Engineer's Office	W2	CMU	Beige	None	0	0	Negative
1	1	Office next to Building Engineer's Office	W3	CMU	Beige	None	0	0.1	Negative
1	1	Office next to Building Engineer's Office	W4	CMU	Beige	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Office next to Building Engineer's Office	Door Casing	Metal	Beige	None	0	0.2	Negative
1	1	Office next to Building Engineer's Office	Door	Wood	Beige	None	0	0.1	Negative
1	1	Pipe Chase in Office next to Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Office next to Building Engineer's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Office next to Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Office next to Building Engineer's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Office next to Building Engineer's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Pipe Chase in Office next to Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Restroom next to Building Engineer's Office	W1	CMU	Beige	None	0	0.1	Negative
1	1	Women's Restroom next to Building Engineer's Office	W2	CMU	Beige	None	0	0.1	Negative
1	1	Women's Restroom next to Building Engineer's Office	W3	CMU	Beige	None	0	0	Negative
1	1	Women's Restroom next to Building Engineer's Office	W4	CMU	Beige	None	0	0	Negative
1	1	Women's Restroom next to Building Engineer's Office	Door Casing	Metal	Blue	None	0	0.4	Negative
1	1	Women's Restroom next to Building Engineer's Office	Door	Wood	Blue	None	0	0	Negative
1	1	Storage Room next to Loading Dock Entrance	W1	CMU	Beige	None	0	0.1	Negative
1	1	Storage Room next to Loading Dock Entrance	W4	CMU	Beige	None	0	0.1	Negative
1	1	Storage Room next to Loading Dock Entrance	W3	CMU	Beige	None	0	0.1	Negative
1	1	Storage Room next to Loading Dock Entrance	W2	CMU	Black	None	0	0.1	Negative
1	1	Stairwell next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell next to Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell behind A Wing Classroom A106	W1	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell behind A Wing Classroom A106	W2	CMU	Beige	None	0	0	Negative
1	2	Stairwell behind A Wing Classroom A106	W4	CMU	Beige	None	0	0	Negative
1	2	Stairwell behind A Wing Classroom A106	Stairs - Railing	Metal	Brown	None	0	0	Negative
1	2	Stairwell behind A Wing Classroom A106	Stairs - Stringer	Metal	Brown	None	0	1.1	Positive
1	2	Stairwell behind A Wing Classroom A106	Stairs - Riser	Metal	Brown	None	0	0.9	Positive
1	2	Stairwell behind A Wing Classroom A106	Door Casing	Metal	Beige	None	0	0.7	Positive
1	2	Stairwell behind A Wing Classroom A106	Door	Metal	Beige	None	0	0	Negative
1	2	Classroom A106	W1	CMU	Blue	Flaking	15	0.1	Negative
1	2	Classroom A106	W2	CMU	Blue	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom A106	W3	CMU	Blue	None	0	0	Negative
1	2	Classroom A106	W4	Concrete	Blue	None	0	0.1	Negative
1	2	Classroom A106	Soffit	Plaster	Beige	None	0	0	Negative
1	2	Classroom A106	Door Casing	Metal	Blue	None	0	0.8	Positive
1	2	Classroom A106	Soffit	Plaster	Beige	None	0	0.3	Negative
1	2	Classroom A106	W1	CMU	Beige	None	0	0.1	Negative
1	2	Classroom A105	W1	CMU	White	None	0	0.1	Negative
1	2	Classroom A105	W2	CMU	White	None	0	0	Negative
1	2	Classroom A105	W3	CMU	Yellow	None	0	0	Negative
1	2	Classroom A105	Soffit	Plaster	White	Efflorescence	2	0.3	Negative
1	2	Classroom A105	Column	Concrete	White	None	0	0.2	Negative
1	2	Classroom A105	Divider Wall Trac	Wood	White	None	0	0.2	Negative
1	2	Classroom A105	Divider Wall	Drywall	White	None	0	0.2	Negative
1	2	Classroom A105	Door Casing	Metal	Blue	None	0	0.3	Negative
1	2	Classroom A105	Door	Wood	Blue	None	0	0.1	Negative
1	2	Classroom A104	Door	Wood	Blue	None	0	0	Negative
1	2	Classroom A104	Door Casing	Metal	Blue	None	0	0.4	Negative
1	2	Classroom A104	Divider Wall Trac	Wood	White	None	0	0.1	Negative
1	2	Classroom A104	Divider Wall Trac	Wood	White	None	0	0	Negative
1	2	Classroom A104	Divider Wall	Drywall	White	None	0	0.1	Negative
1	2	Classroom A104	Divider Wall	Drywall	White	None	0	0	Negative
1	2	Classroom A104	W3	Concrete	Yellow	None	0	0	Negative
1	2	Classroom A104	Soffit	Plaster	White	Efflorescence	10	0.1	Negative
1	2	Classroom A103	W1	Concrete	White	None	0	0.1	Negative
1	2	Classroom A103	W4	Concrete	White	None	0	0	Negative
1	2	Classroom A103	W3	Concrete	Yellow	None	0	0.1	Negative
1	2	Classroom A103	Soffit	Plaster	White	None	0	0.2	Negative
1	2	Classroom A103	Divider Wall Trac	Wood	White	None	0	0	Negative
1	2	Classroom A103	Divider Wall	Drywall	White	None	0	0.1	Negative
1	2	Classroom A103	Door Casing	Metal	Blue	None	0	0.1	Negative
1	2	Classroom A102	Door Casing	Metal	Blue	None	0	0.2	Negative
1	2	Classroom A102	W1	CMU	White	None	0	0.1	Negative
1	2	Classroom A102	W2	CMU	White	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom A102	W3	CMU	Yellow	None	0	0.1	Negative
1	2	Classroom A102	Soffit	Plaster	White	None	0	0.1	Negative
1	2	Classroom A102	Divider Wall Trac	Wood	White	None	0	0.1	Negative
1	2	Classroom A102	Divider Wall	Drywall	White	None	0	0	Negative
1	2	Classroom A101	W1	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom A101	W4	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom A101	W3	CMU	YELLOW	None	0	0.01	Negative
1	2	Classroom A101	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative
1	2	Classroom A101	DIVIDER WALL TR	WOOD	WHITE	None	0	0.01	Negative
1	2	Classroom A101	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative
1	2	Classroom A101	DOOR CASING	METAL	BLUE	None	0	0	Negative
1	2	Classroom A101	Divider Wall	Drywall	White	None	0	0.1	Negative
1	2	Classroom A101	Divider Wall Trac	Wood	White	None	0	0.1	Negative
1	2	Classroom A101	W1	CMU	White	None	0	0.1	Negative
1	2	Classroom A101	W4	CMU	White	None	0	0.1	Negative
1	2	Classroom A101	W3	CMU	Yellow	None	0	0.1	Negative
1	2	Classroom A101	Soffit	Plaster	White	None	0	0.1	Negative
1	2	A Wing Boy's Restroom	W1	CMU	Beige	None	0	0	Negative
1	2	A Wing Boy's Restroom	W4	CMU	Beige	None	0	0	Negative
1	2	A Wing Boy's Restroom	W3	CMU	Beige	None	0	0.1	Negative
1	2	A Wing Boy's Restroom	Door Casing	Metal	Blue	None	0	0.3	Negative
1	2	A Wing Boy's Restroom	Ceiling	Concrete	Beige	None	0	0.1	Negative
1	2	A Wing Men's Staff Restroom	Ceiling	Concrete	White	None	0	0.1	Negative
1	2	A Wing Men's Staff Restroom	Door Casing	Metal	Blue	None	0	0.4	Negative
1	2	A Wing Men's Staff Restroom	Door	Wood	Blue	None	0	0	Negative
1	2	A Wing Men's Staff Restroom	W1	CMU	White	None	0	0.1	Negative
1	2	A Wing Men's Staff Restroom	W4	CMU	White	None	0	0	Negative
1	2	A Wing Men's Staff Restroom	W3	CMU	White	None	0	0	Negative
1	2	A Wing Women's Staff Restroom	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	A Wing Women's Staff Restroom	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	A Wing Women's Staff Restroom	W1	CMU	BEIGE	None	0	0	Negative
1	2	A Wing Women's Staff Restroom	W2	CMU	BEIGE	None	0	0	Negative
1	2	A Wing Women's Staff Restroom	W3	CMU	BEIGE	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	A Wing Women's Staff Restroom	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	2	A Wing Women's Staff Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.03	Negative
1	2	A Wing Women's Staff Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.03	Negative
1	2	A Wing Women's Staff Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.08	Negative
1	2	A Wing Girl's Restroom	Door Casing	Metal	Blue	None	0	0.4	Negative
1	2	A Wing Girl's Restroom	W1	CMU	Pink	None	0	0	Negative
1	2	A Wing Girl's Restroom	W2	CMU	Pink	None	0	0.1	Negative
1	2	A Wing Girl's Restroom	W4	CMU	Pink	None	0	0.1	Negative
1	2	A Wing Girl's Restroom	Ceiling	Concrete	Beige	None	0	0	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	W1	CMU	Beige	None	0	0.1	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	W2	CMU	Beige	None	0	0	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	W2	CMU	Green	None	0	0	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	W4	CMU	Beige	None	0	0	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	W3	CMU	Brown	None	0	0.1	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	W1	CMU	Green	None	0	0	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Green	None	0	0.1	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Beige	None	0	0.4	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Beige	None	0	0.4	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Beige	None	0	0.5	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Brown	None	0	0.4	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	Soffit	Plaster	Brown	None	0	0	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	Soffit	Plaster	Beige	None	0	0	Negative
1	2	Hallway outside A Wing Classrooms A101 - A106	Soffit	Plaster	Beige	None	0	0	Negative
1	2	Custodial Closet Hallway between Classrooms 106A & 105A	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet Hallway between Classrooms 106A & 105A	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet Hallway between Classrooms 106A & 105A	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet Hallway between Classrooms 106A & 105A	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet Hallway between Classrooms 106A & 105A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet Hallway between Classrooms 106A & 105A	Floor	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Stairwell behind B Wing Classroom B106	W1	Brick	Beige	None	0	0.1	Negative
1	2	Stairwell behind B Wing Classroom B106	W2	Brick	Beige	None	0	0.1	Negative
1	2	Stairwell behind B Wing Classroom B106	W4	Brick	Beige	None	0	0.2	Negative
1	2	Stairwell behind B Wing Classroom B106	Stairs - Railing	Metal	Beige	None	0	0.2	Negative
1	2	Stairwell behind B Wing Classroom B106	Stairs - Riser	Metal	Beige	None	0	1	Positive
1	2	Stairwell behind B Wing Classroom B106	Stairs - Stringer	Metal	Beige	None	0	0.7	Positive
1	2	Stairwell behind B Wing Classroom B106	W2	Drywall	Beige	None	0	0	Negative
1	2	Classroom B106	Soffit	Plaster	White	None	0	0.1	Negative
1	2	Classroom B106	Soffit	Plaster	White	None	0	0	Negative
1	2	Classroom B106	Door Casing	Metal	Blue	None	0	0.7	Positive
1	2	Classroom B106	W1	CMU	White	None	0	0.1	Negative
1	2	Classroom B106	W2	CMU	White	None	0	0.1	Negative
1	2	Classroom B105	Divider Wall Trac	Wood	White	None	0	0.1	Negative
1	2	Classroom B105	Divider Wall	Drywall	White	None	0	0.1	Negative
1	2	Classroom B105	Door Casing	Metal	Blue	None	0	0.6	Negative
1	2	Classroom B105	W1	CMU	White	None	0	0.1	Negative
1	2	Classroom B105	W4	CMU	White	None	0	0	Negative
1	2	Classroom B105	W3	CMU	Orange	None	0	0.1	Negative
1	2	Classroom B105	Soffit	Plaster	White	None	0	0	Negative
1	2	Classroom B104	Door	Wood	Blue	None	0	0.1	Negative
1	2	Classroom B104	Door Casing	Metal	Blue	None	0	0.5	Negative
1	2	Classroom B104	W1	CMU	Beige	None	0	0.1	Negative
1	2	Classroom B104	W2	CMU	Beige	None	0	0.1	Negative
1	2	Classroom B104	W3	CMU	Beige	None	0	0	Negative
1	2	Classroom B104	Soffit	Plaster	White	None	0	0	Negative
1	2	Classroom B104	Divider Wall	Drywall	White	None	0	0.1	Negative
1	2	Classroom B104	Divider Wall Trac	Wood	White	None	0	0.1	Negative
1	2	Classroom B104	Divider Wall Trac	Wood	White	None	0	0.1	Negative
1	2	Classroom B103	Divider Wall Trac	Wood	White	None	0	0	Negative
1	2	Classroom B103	Divider Wall	Drywall	White	None	0	0.1	Negative
1	2	Classroom B103	W1	CMU	White	None	0	0.1	Negative
1	2	Classroom B103	W2	CMU	White	None	0	0.1	Negative
1	2	Classroom B103	W3	CMU	Orange	None	0	0.6	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom B103	Soffit	Plaster	White	None	0	0	Negative
1	2	Classroom B103	Door Casing	Metal	Blue	None	0	0.7	Positive
1	2	Classroom B103	Door	Wood	Blue	None	0	0.1	Negative
1	2	Classroom B102	Door Casing	Metal	Blue	None	0	0.4	Negative
1	2	Classroom B102	Door	Wood	Blue	None	0	0.1	Negative
1	2	Classroom B102	W1	CMU	White	None	0	0.2	Negative
1	2	Classroom B102	W4	CMU	White	None	0	0.1	Negative
1	2	Classroom B102	W3	CMU	Orange	None	0	0	Negative
1	2	Classroom B102	Soffit	Plaster	White	Efflorescence	3	0	Negative
1	2	Classroom B102	Divider Wall	Drywall	White	None	0	0.1	Negative
1	2	Classroom B102	Divider Wall Trac	Wood	White	None	0	0.1	Negative
1	2	Classroom B101	W1	Concrete	Beige	None	0	0.1	Negative
1	2	Classroom B101	W2	Concrete	Beige	Flaking	3	0.1	Negative
1	2	Classroom B101	W3	Concrete	Blue	None	0	0.1	Negative
1	2	Classroom B101	Soffit	Plaster	White	Efflorescence	1	0.1	Negative
1	2	Classroom B101	Divider Wall	Drywall	White	None	0	0.2	Negative
1	2	Classroom B101	Divider Wall Trac	Wood	White	None	0	0.1	Negative
1	2	Classroom B101	Door Casing	Metal	Blue	None	0	0.4	Negative
1	2	B Wing Boy's Restroom	Ceiling	CMU	Beige	None	0	0	Negative
1	2	B Wing Boy's Restroom	W1	CMU	Beige	None	0	0.1	Negative
1	2	B Wing Boy's Restroom	W2	CMU	Beige	None	0	0	Negative
1	2	B Wing Boy's Restroom	W3	CMU	Beige	None	0	0	Negative
1	2	B Wing Boy's Restroom	Floor	Tile	Gray	None	0	0.2	Negative
1	2	B Wing Boy's Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative
1	2	B Wing Boy's Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative
1	2	B Wing Boy's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.4	Negative
1	2	B Wing Boy's Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative
1	2	B Wing Men's Staff Restroom	Door Casing	Metal	Blue	None	0	0.6	Negative
1	2	B Wing Men's Staff Restroom	Door	Wood	Blue	None	0	0	Negative
1	2	B Wing Men's Staff Restroom	Door Casing	Metal	Blue	None	0	0.7	Positive
1	2	B Wing Men's Staff Restroom	Door Casing	Metal	Blue	None	0	0.5	Negative
1	2	B Wing Men's Staff Restroom	W1	CMU	Beige	None	0	0.1	Negative
1	2	B Wing Men's Staff Restroom	W2	CMU	Beige	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	B Wing Men's Staff Restroom	W3	CMU	Beige	None	0	0.1	Negative
1	2	B Wing Men's Staff Restroom	Floor	Tile	Gray	None	0	0.2	Negative
1	2	B Wing Men's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative
1	2	B Wing Men's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative
1	2	B Wing Men's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative
1	2	B Wing Men's Staff Restroom	Ceiling	Concrete	Beige	None	0	0.1	Negative
1	2	B Wing Women's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative
1	2	B Wing Women's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative
1	2	B Wing Women's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative
1	2	B Wing Women's Staff Restroom	Floor	Tile	Gray	None	0	0.3	Negative
1	2	B Wing Women's Staff Restroom	W1	CMU	Beige	None	0	0.1	Negative
1	2	B Wing Women's Staff Restroom	W2	CMU	Beige	None	0	0.2	Negative
1	2	B Wing Women's Staff Restroom	W3	CMU	Beige	None	0	0.6	Negative
1	2	B Wing Women's Staff Restroom	Ceiling	Concrete	Beige	None	0	0.1	Negative
1	2	B Wing Women's Staff Restroom	Door Casing	Metal	Blue	None	0	0.5	Negative
1	2	B Wing Women's Staff Restroom	Door	Wood	Blue	None	0	0	Negative
1	2	B Wing Girl's Restroom	Door Casing	Metal	Blue	None	0	0.5	Negative
1	2	B Wing Girl's Restroom	W2	CMU	Beige	None	0	0	Negative
1	2	B Wing Girl's Restroom	W1	CMU	Beige	None	0	0	Negative
1	2	B Wing Girl's Restroom	W3	CMU	Beige	None	0	0.1	Negative
1	2	B Wing Girl's Restroom	W4	CMU	Beige	None	0	0.1	Negative
1	2	B Wing Girl's Restroom	Ceiling	Concrete	Beige	None	0	0.1	Negative
1	2	B Wing Girl's Restroom	Floor	Tile	Gray	None	0	0.2	Negative
1	2	B Wing Girl's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative
1	2	B Wing Girl's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.5	Negative
1	2	B Wing Girl's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative
1	2	B Wing Girl's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.2	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	W1	CMU	Tan	None	0	0.1	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	W2	CMU	Tan	None	0	0.1	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	W3	CMU	Beige	None	0	0.1	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	W4	CMU	Green	None	0	0.1	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	Door Casing	Metal	Beige	None	0	0.4	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	Door	Wood	Beige	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Hallway outside B Wing Classrooms B101 - B106	Door	Metal	Beige	None	0	0	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	Door Casing	Metal	Beige	None	0	0.5	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	Soffit	Plaster	Beige	None	0	0.1	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	Soffit	Plaster	Beige	None	0	0	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	W3	CMU	Green	None	0	0	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	Soffit	Plaster	Beige	None	0	0.1	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	W4	CMU	Beige	None	0	0.1	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	Door Casing	Metal	Beige	None	0	0.4	Negative
1	2	Hallway outside B Wing Classrooms B101 - B106	Door	Metal	Blue	None	0	0	Negative
1	2	Custodial closet in hallway between 106B & 105B	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial closet in hallway between 106B & 105B	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial closet in hallway between 106B & 105B	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial closet in hallway between 106B & 105B	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial closet in hallway between 106B & 105B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial closet in hallway between 106B & 105B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Music Classrooms Hallway	W1	CMU	Beige	None	0	0.1	Negative
1	2	Music Classrooms Hallway	W3	CMU	Beige	None	0	0	Negative
1	2	Music Classrooms Hallway	W4	CMU	Beige	None	0	0.1	Negative
1	2	Music Classrooms Hallway	Door	Wood	Beige	None	0	0.1	Negative
1	2	Music Classrooms Hallway	Door Casing	Metal	Beige	None	0	0.1	Negative
1	2	Music Classrooms Hallway	Soffit	Plaster	Beige	None	0	0.1	Negative
1	2	Large Library Reading Area in A Wing	W1	CMU	GREEN	None	0	0.03	Negative
1	2	Large Library Reading Area in A Wing	W4	CMU	GREEN	None	0	0.01	Negative
1	2	Large Library Reading Area in A Wing	W3	CMU	GREEN	None	0	0.02	Negative
1	2	Large Library Reading Area in A Wing	W2	CMU	GREEN	None	0	0.01	Negative
1	2	Large Library Reading Area in A Wing	W2	CMU	LIGHT GREEN	None	0	0.02	Negative
1	2	Large Library Reading Area in A Wing	W1	CMU	LIGHT GREEN	Efflorescence	5	0.01	Negative
1	2	Large Library Reading Area in A Wing	W3	CMU	LIGHT GREEN	None	0	0.03	Negative
1	2	Large Library Reading Area in A Wing	W2	CMU	LIGHT GREEN	None	0	0.01	Negative
1	2	Large Library Reading Area in A Wing	COLUMN	CONCRETE	WHITE	Flaking	10	0	Negative
1	2	Large Library Reading Area in A Wing	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative
1	2	Large Library Reading Area in A Wing	DOOR CASING	METAL	BLUE	None	0	0.26	Negative
1	2	Large Library Reading Area in A Wing	DOOR CASING	METAL	BLUE	None	0	0.6	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Large Library Reading Area in A Wing	DOOR	WOOD	BLUE	None	0	0	Negative
1	2	Large Library Reading Area in A Wing	DOOR	WOOD	BLUE	None	0	0	Negative
1	2	A Wing Large Library Reading Area Stairwell	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	A Wing Large Library Reading Area Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	A Wing Large Library Reading Area Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	A Wing Large Library Reading Area Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	A Wing Large Library Reading Area Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	A Wing Large Library Reading Area Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell between A and B Wings	W2	Concrete	Yellow	None	0	0.2	Negative
1	2	Stairwell between A and B Wings	W3	Concrete	Beige	None	0	0.1	Negative
1	2	Stairwell between A and B Wings	W4	Concrete	Beige	None	0	0.1	Negative
1	2	Stairwell between A and B Wings	Door	Metal	Blue	None	0	0.1	Negative
1	2	Stairwell between A and B Wings	Door Casing	Metal	Beige	None	0	0.4	Negative
1	2	Stairwell between A and B Wings	Stairs - Railing	Metal	Brown	None	0	0.1	Negative
1	2	Stairwell between A and B Wings	Stairs - Riser	Metal	Brown	None	0	1.9	Positive
1	2	Stairwell between A and B Wings	Stairs - Stringer	Metal	Brown	None	0	1.2	Positive
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W2	CMU	YELLOW	None	0	0.01	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W1	CMU	YELLOW	None	0	0.02	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.3	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.3	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.23	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.4	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR	WOOD	BLUE	None	0	0.01	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR	WOOD	BLUE	None	0	0.02	Negative
1	2	Office behind A Wing Stairwell	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Office behind A Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.22	Negative
1	2	Office behind A Wing Stairwell	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Office behind A Wing Stairwell	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Office behind A Wing Stairwell	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Office behind A Wing Stairwell	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Office between 121A and A Wing Faculty Lounge	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Office between 121A and A Wing Faculty Lounge	DOOR CENTER PANEL	METAL	BLUE	None	0	0.25	Negative
1	2	Office between 121A and A Wing Faculty Lounge	DOOR CASING	METAL	BLUE	None	0	0.28	Negative
1	2	Office between 121A and A Wing Faculty Lounge	DOOR	WOOD	BLUE	None	0	0.02	Negative
1	2	Office between 121A and A Wing Faculty Lounge	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Office between 121A and A Wing Faculty Lounge	W4	CMU	BEIGE	None	0	0.03	Negative
1	2	Office between 121A and A Wing Faculty Lounge	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Office between 121A and A Wing Faculty Lounge	W2	CMU	BEIGE	None	0	0.03	Negative
1	2	Office next to A Wing Stairwell	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Office next to A Wing Stairwell	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Office next to A Wing Stairwell	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Office next to A Wing Stairwell	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Office next to A Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.4	Negative
1	2	Office next to A Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.26	Negative
1	2	Office across from Classroom A103	W4	CMU	BEIGE	None	0	0.02	Negative
1	2	Office across from Classroom A103	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Office across from Classroom A103	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Office across from Classroom A103	W1	CMU	BEIGE	None	0	0.02	Negative
1	2	Office across from Classroom A103	DOOR CASING	METAL	BLUE	None	0	0.5	Negative
1	2	Office across from Classroom A103	DOOR CASING	METAL	BLUE	None	0	0.25	Negative
1	2	Office across from Classroom A103	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Office across from Classroom A103	DOOR	WOOD	BLUE	None	0	0.02	Negative
1	2	A Wing Large Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	A Wing Large Storage Room	W2	CMU	BEIGE	None	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	A Wing Large Storage Room	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	A Wing Large Storage Room	W4	CMU	BEIGE	None	0	0.02	Negative
1	2	A Wing Large Storage Room	WINDOW CASING	METAL	BROWN	None	0	0.4	Negative
1	2	A Wing Large Storage Room	WINDOW CASING	METAL	BROWN	None	0	0.23	Negative
1	2	A Wing Large Storage Room	WINDOW CASING	METAL	BROWN	None	0	0.25	Negative
1	2	A Wing Large Storage Room	DOOR CASING	METAL	BROWN	None	0	0.4	Negative
1	2	A Wing Large Storage Room	DOOR	WOOD	BROWN	None	0	0.01	Negative
1	2	A Wing Large Storage Room	DOOR	WOOD	BROWN	None	0	0.01	Negative
1	2	A Wing Large Storage Room	DOOR CASING	METAL	BROWN	None	0	0.25	Negative
1	2	A Wing Large Storage Room	COLUMN	CONCRETE	BEIGE	None	0	0.04	Negative
1	2	A Wing Small Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	A Wing Small Storage Room	W2	CMU	BEIGE	None	0	0	Negative
1	2	A Wing Small Storage Room	W3	CMU	BEIGE	None	0	0.03	Negative
1	2	A Wing Small Storage Room	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	A Wing Small Storage Room	DOOR CASING	METAL	BLUE	None	0	0.18	Negative
1	2	A Wing Small Storage Room	DOOR	WOOD	BLUE	None	0	0.1	Negative
1	2	Small Office inside A Wing Large Library Reading Area	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Small Office inside A Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.4	Negative
1	2	Small Office inside A Wing Large Library Reading Area	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside A Wing Large Library Reading Area	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside A Wing Large Library Reading Area	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside A Wing Large Library Reading Area	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	A Wing Storage Room next to HVAC/Mechanical Room 1	W4	CMU	BEIGE	None	0	0.03	Negative
1	2	A Wing Storage Room next to HVAC/Mechanical Room 1	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	A Wing Storage Room next to HVAC/Mechanical Room 1	W2	CMU	BEIGE	None	0	0.02	Negative
1	2	A Wing Storage Room next to HVAC/Mechanical Room 1	W3	CMU	BEIGE	None	0	0.11	Negative
1	2	A Wing Storage Room next to HVAC/Mechanical Room 1	DOOR CASING	METAL	BLUE	None	0	0.25	Negative
1	2	A Wing Storage Room next to HVAC/Mechanical Room 1	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	HVAC/Mechanical Room 1 between A and B Wings	W1	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	HVAC/Mechanical Room 1 between A and B Wings	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room 1 between A and B Wings	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room 1 between A and B Wings	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room 1 between A and B Wings	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room 1 between A and B Wings	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Large Library Reading Area in B Wing	W1	CMU	BLUE	None	0	0.01	Negative
1	2	Large Library Reading Area in B Wing	W1	CMU	LIGHT BLUE	None	0	0.02	Negative
1	2	Large Library Reading Area in B Wing	W2	CMU	LIGHT BLUE	None	0	0.02	Negative
1	2	Large Library Reading Area in B Wing	W4	CMU	LIGHT BLUE	None	0	0.01	Negative
1	2	Large Library Reading Area in B Wing	W3	CMU	LIGHT BLUE	None	0	0.01	Negative
1	2	Large Library Reading Area in B Wing	W3	CMU	BLUE	None	0	0.01	Negative
1	2	Large Library Reading Area in B Wing	W4	CMU	BLUE	None	0	0.03	Negative
1	2	Large Library Reading Area in B Wing	W2	CMU	BLUE	None	0	0	Negative
1	2	Large Library Reading Area in B Wing	COLUMN	CONCRETE	BLUE	None	0	0	Negative
1	2	Large Library Reading Area in B Wing	W2	DRYWALL	WHITE	None	0	0	Negative
1	2	Large Library Reading Area in B Wing	SOFFIT	PLASTER	WHITE	None	0	0	Negative
1	2	Large Library Reading Area in B Wing	DOOR CASING	METAL	BEIGE	None	0	0.21	Negative
1	2	Large Library Reading Area in B Wing	DOOR	WOOD	BEIGE	None	0	0	Negative
1	2	Large Library Reading Area in B Wing	DOOR CENTER PANEL	WOOD	BEIGE	None	0	0	Negative
1	2	Large Library Reading Area in B Wing	DOOR CASING	METAL	BLUE	None	0	0.26	Negative
1	2	Large Library Reading Area in B Wing	DOOR	WOOD	BLUE	None	0	0	Negative
1	2	Large Library Reading Area in B Wing	DOOR	WOOD	BLACK	None	0	0.01	Negative
1	2	Large Library Reading Area in B Wing	DOOR CASING	METAL	BLACK	None	0	0.3	Negative
1	2	B Wing Large Library Reading Area Stairwell	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	B Wing Large Library Reading Area Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	B Wing Large Library Reading Area Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	B Wing Large Library Reading Area Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	B Wing Large Library Reading Area Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	B Wing Large Library Reading Area Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Lounge between B Wing Large Library Reading Area and B Wing Hallway	DOOR CASING	METAL	BLACK	None	0	0.24	Negative
1	2	Lounge between B Wing Large Library Reading Area and B Wing Hallway	DOOR	WOOD	BLACK	None	0	0	Negative
1	2	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W2	CMU	BEIGE	None	0	0.03	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W4	CMU	BEIGE	None	0	0.02	Negative
1	2	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W3	CMU	GREEN	None	0	0.02	Negative
1	2	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W2	CMU	GREEN	None	0	0.01	Negative
1	2	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W1	CMU	GREEN	None	0	0.01	Negative
1	2	Office behind B Wing Stairwell	DOOR	WOOD	BLACK	None	0	0.05	Negative
1	2	Office behind B Wing Stairwell	DOOR CASING	METAL	BLACK	None	0	0.4	Negative
1	2	Office behind B Wing Stairwell	DOOR CASING	METAL	BLACK	None	0	0.3	Negative
1	2	Office behind B Wing Stairwell	DOOR	WOOD	BLACK	None	0	0.01	Negative
1	2	Office behind B Wing Stairwell	W1	CMU	BEIGE	None	0	0.02	Negative
1	2	Office behind B Wing Stairwell	W2	CMU	BEIGE	None	0	0.07	Negative
1	2	Office behind B Wing Stairwell	W4	CMU	BEIGE	None	0	0.02	Negative
1	2	Office behind B Wing Stairwell	W3	CMU	BEIGE	Flaking	2	0.03	Negative
1	2	Office behind B Wing Stairwell	COLUMN	CONCRETE	BEIGE	None	0	0	Negative
1	2	Office between 121B and B Wing Faculty Lounge	W4	CMU	BEIGE	None	0	0.02	Negative
1	2	Office between 121B and B Wing Faculty Lounge	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Office between 121B and B Wing Faculty Lounge	W1	CMU	BEIGE	None	0	0.02	Negative
1	2	Office between 121B and B Wing Faculty Lounge	W2	CMU	BEIGE	None	0	0.02	Negative
1	2	Office between 121B and B Wing Faculty Lounge	DOOR CASING	METAL	BLACK	None	0	0.16	Negative
1	2	Office between 121B and B Wing Faculty Lounge	DOOR	WOOD	BLACK	None	0	0.01	Negative
1	2	Office next to B Wing Stairwell	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Office next to B Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.21	Negative
1	2	Office next to B Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.5	Negative
1	2	Office next to B Wing Stairwell	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Office next to B Wing Stairwell	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Office next to B Wing Stairwell	W2	CMU	BEIGE	Flaking	5	0.01	Negative
1	2	Office next to B Wing Stairwell	W3	CMU	BEIGE	None	0	0.02	Negative
1	2	Office next to B Wing Stairwell	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Office across from Classroom B103	W1	CMU	BEIGE	None	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Office across from Classroom B103	W2	CMU	BEIGE	None	0	0.06	Negative
1	2	Office across from Classroom B103	W3	CMU	BEIGE	None	0	0.02	Negative
1	2	Office across from Classroom B103	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Office across from Classroom B103	DOOR CASING	METAL	BLACK	None	0	0.3	Negative
1	2	Office across from Classroom B103	DOOR CASING	METAL	BLUE	None	0	0.28	Negative
1	2	Office across from Classroom B103	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Office across from Classroom B103	DOOR	WOOD	BLACK	None	0	0.01	Negative
1	2	B Wing Small Storage Room	DOOR CASING	METAL	BLUE	None	0	0.3	Negative
1	2	B Wing Small Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	B Wing Small Storage Room	W2	CMU	BEIGE	Flaking	3	0.02	Negative
1	2	B Wing Small Storage Room	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	B Wing Small Storage Room	W4	CMU	BEIGE	None	0	0.02	Negative
1	2	B Wing Small Storage Room	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative
1	2	Small Office inside B Wing Large Library Reading Area	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside B Wing Large Library Reading Area	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside B Wing Large Library Reading Area	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside B Wing Large Library Reading Area	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside B Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.26	Negative
1	2	Small Office inside B Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.3	Negative
1	2	Small Office inside B Wing Large Library Reading Area	Door	WOOD	BLUE	None	0	0.01	Negative
1	2	Small Office inside B Wing Large Library Reading Area	DOOR CASING	WOOD	BLUE	None	0	0.01	Negative
1	2	B Wing Storage Room next to HVAC/Mechanical Room 1	DOOR CASING	METAL	BLACK	None	0	0.01	Negative
1	2	B Wing Storage Room next to HVAC/Mechanical Room 1	DOOR	WOOD	BLACK	None	0	0.01	Negative
1	2	B Wing Storage Room next to HVAC/Mechanical Room 1	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	B Wing Storage Room next to HVAC/Mechanical Room 1	W4	CMU	BEIGE	None	0	0.02	Negative
1	2	B Wing Storage Room next to HVAC/Mechanical Room 1	W3	CMU	BEIGE	None	0	0.03	Negative
1	2	B Wing Storage Room next to HVAC/Mechanical Room 1	W2	CMU	BEIGE	None	0	0.04	Negative
1	2	Stairwell behind D Wing Classroom D106	W1	BRICK	BEIGE	None	0	0.01	Negative
1	2	Stairwell behind D Wing Classroom D106	W2	BRICK	BEIGE	None	0	0.01	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Stairwell behind D Wing Classroom D106	W4	BRICK	BEIGE	None	0	0.01	Negative
1	2	Stairwell behind D Wing Classroom D106	W3	BRICK	BEIGE	None	0	0.03	Negative
1	2	Stairwell behind D Wing Classroom D106	W3	DRYWALL	BEIGE	None	0	0	Negative
1	2	Stairwell behind D Wing Classroom D106	STAIRS RISER	METAL	BEIGE	None	0	0.6	Negative
1	2	Stairwell behind D Wing Classroom D106	STAIRS STRINGER	METAL	BEIGE	None	0	1.2	Positive
1	2	Stairwell behind D Wing Classroom D106	STAIRS RAILING	METAL	BEIGE	None	0	0.02	Negative
1	2	Stairwell behind D Wing Classroom D106	STAIRS HALF WALL	WOOD	BEIGE	None	0	0	Negative
1	2	Stairwell behind D Wing Classroom D106	W3	CMU	BEIGE	None	0	0	Negative
1	2	Stairwell behind D Wing Classroom D106	DOOR CASING	METAL	BEIGE	None	0	0	Negative
1	2	Stairwell behind D Wing Classroom D106	DOOR	METAL	BEIGE	None	0	0	Negative
1	2	Stairwell behind D Wing Classroom D106	DOOR CENTER PANEL	METAL	BEIGE	None	0	0	Negative
1	2	Stairwell behind D Wing Classroom D106	UNIVENT	METAL	BEIGE	None	0	0.01	Negative
1	2	Stairwell behind D Wing Classroom D106	CEILING	CONCRETE	BEIGE	None	0	0.04	Negative
1	2	Classroom D106	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Classroom D106	DOOR CASING	WOOD	BLUE	None	0	0	Negative
1	2	Classroom D106	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom D106	W2	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom D106	W4	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom D106	W3	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom D106	WALL	CMU	PURPLE	None	0	0.01	Negative
1	2	Classroom D106	CEILING	PLASTER	WHITE	None	0	0.01	Negative
1	2	Classroom D105	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom D105	W4	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom D105	W3	CMU	PURPLE	None	0	0.01	Negative
1	2	Classroom D105	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative
1	2	Classroom D105	DIVIDER WALL TOP	WOOD	WHITE	None	0	0	Negative
1	2	Classroom D105	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative
1	2	Classroom D104	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative
1	2	Classroom D104	DIVIDER WALL TOP	WOOD	WHITE	None	0	0	Negative
1	2	Classroom D104	W1	CMU	WHITE	None	0	0	Negative
1	2	Classroom D104	DIVIDER WALL TOP	WOOD	WHITE	None	0	0.03	Negative
1	2	Classroom D104	DIVIDER WALL	PLASTER	WHITE	None	0	0.01	Negative
1	2	Classroom D104	W2	CMU	WHITE	None	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom D104	W3	CMU	PURPLE	None	0	0.01	Negative
1	2	Classroom D104	COLUMN	CONCRETE	WHITE	None	0	0.01	Negative
1	2	Classroom D104	SOFFIT	PLASTER	WHITE	Efflorescence	2	0.01	Negative
1	2	Classroom D103	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative
1	2	Classroom D103	W3	CMU	PURPLE	None	0	0.02	Negative
1	2	Classroom D103	W2	CMU	WHITE	None	0	0	Negative
1	2	Classroom D103	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Classroom D103	DIVIDER WALL TF	WOOD	WHITE	None	0	0.02	Negative
1	2	Classroom D103	DIVIDER WALL	WOOD	WHITE	None	0	0.01	Negative
1	2	Classroom D102	DIVIDER WALL	WOOD	WHITE	None	0	0.02	Negative
1	2	Classroom D102	DIVIDER WALL TF	WOOD	WHITE	None	0	0.02	Negative
1	2	Classroom D102	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom D102	W4	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom D102	W3	CMU	PURPLE	None	0	0.01	Negative
1	2	Classroom D102	SOFFIT	PLASTER	WHITE	None	0	0	Negative
1	2	Classroom D101	SOFFIT	PLASTER	WHITE	None	0	0.04	Negative
1	2	Classroom D101	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom D101	W2	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom D101	W3	CMU	PURPLE	None	0	0	Negative
1	2	Classroom D101	DIVIDER WALL TF	WOOD	WHITE	None	0	0.01	Negative
1	2	Classroom D101	DIVIDER WALL	PLASTER	WHITE	None	0	0.02	Negative
1	2	D Wing Boy's Restroom	DOOR CASING	METAL	BLACK	None	0	0.03	Negative
1	2	D Wing Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Boy's Restroom	W2	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative
1	2	D Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative
1	2	D Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative
1	2	D Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative
1	2	D Wing Boy's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative
1	2	D Wing Men's Staff Restroom	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	2	D Wing Men's Staff Restroom	WALL BASEBOAR	CMU	BEIGE	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	D Wing Men's Staff Restroom	WALL BASEBOAR	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Men's Staff Restroom	WALL BASEBOAR	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Men's Staff Restroom	DOOR CASING	WOOD	BLUE	None	0	0.01	Negative
1	2	D Wing Men's Staff Restroom	DOOR	WOOD	BLUE	None	0	0.09	Negative
1	2	D Wing Women's Staff Restroom	DOOR CASING	METAL	BLUE	None	0	0.02	Negative
1	2	D Wing Women's Staff Restroom	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	D Wing Women's Staff Restroom	W1	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Women's Staff Restroom	W4	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Women's Staff Restroom	W3	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Women's Staff Restroom	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	2	D Wing Girl's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative
1	2	D Wing Girl's Restroom	FLOOR	CONCRETE	GRAY	None	0	0	Negative
1	2	D Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.03	Negative
1	2	D Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.02	Negative
1	2	D Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.01	Negative
1	2	D Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.02	Negative
1	2	D Wing Girl's Restroom	W3	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Girl's Restroom	W2	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Girl's Restroom	W1	CMU	BEIGE	None	0	0	Negative
1	2	D Wing Girl's Restroom	DOOR CASING	METAL	BLACK	None	0	0.05	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W1	CMU	BEIGE	None	0	0	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W4	CMU	BEIGE	None	0	0.05	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	DOOR CASING	METAL	BLACK	None	0	0.03	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	DOOR	METAL	BLUE	None	0	0	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	SOFFIT	Plaster	BEIGE	None	0	0	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	SOFFIT	Plaster	BEIGE	None	0	0	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W1	CMU	Blue	None	0	0.1	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W1	CMU	Green	None	0	0.2	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W3	CMU	Green	None	0	0	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W3	CMU	Blue	None	0	0.1	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W2	CMU	Blue	None	0	0.2	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Hallway outside D Wing Classrooms D101 - D106	W2	CMU	Green	None	0	0.1	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W4	CMU	Green	None	0	0.1	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	W4	CMU	Blue	None	0	0.1	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	Door	Wood	Beige	None	0	0.1	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	Door	Wood	Blue	None	0	0	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	Door Casing	Metal	Blue	None	0	0.4	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	Door	Wood	Beige	None	0	0.1	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	Door Casing	Metal	Beige	None	0	0.1	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	Soffit	Plaster	Beige	None	0	0.5	Negative
1	2	Hallway outside D Wing Classrooms D101 - D106	Soffit	Plaster	Beige	None	0	0.1	Negative
1	2	Custodial Closet in hallway between D106 & D105	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in hallway between D106 & D105	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in hallway between D106 & D105	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in hallway between D106 & D105	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in hallway between D106 & D105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in hallway between D106 & D105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell behind C Wing Classroom 106C	W1	BRICK	BEIGE	None	0	0.01	Negative
1	2	Stairwell behind C Wing Classroom 106C	W2	BRICK	BEIGE	None	0	0.01	Negative
1	2	Stairwell behind C Wing Classroom 106C	W4	BRICK	BEIGE	None	0	0.01	Negative
1	2	Stairwell behind C Wing Classroom 106C	W3	BRICK	BEIGE	None	0	0.03	Negative
1	2	Stairwell behind C Wing Classroom 106C	W3	DRYWALL	BEIGE	None	0	0	Negative
1	2	Stairwell behind C Wing Classroom 106C	STAIRS RISER	METAL	BEIGE	None	0	0.6	Negative
1	2	Stairwell behind C Wing Classroom 106C	STAIRS STRINGER	METAL	BEIGE	None	0	1.2	Positive
1	2	Stairwell behind C Wing Classroom 106C	STAIRS RAILING	METAL	BEIGE	None	0	0.02	Negative
1	2	Stairwell behind C Wing Classroom 106C	STAIRS HALFVAL	WOOD	BEIGE	None	0	0	Negative
1	2	Stairwell behind C Wing Classroom 106C	W3	CMU	BEIGE	None	0	0	Negative
1	2	Stairwell behind C Wing Classroom 106C	DOOR CASING	METAL	BEIGE	None	0	0	Negative
1	2	Stairwell behind C Wing Classroom 106C	DOOR	METAL	BEIGE	None	0	0	Negative
1	2	Stairwell behind C Wing Classroom 106C	DOOR CENTER PC	METAL	BEIGE	None	0	0	Negative
1	2	Stairwell behind C Wing Classroom 106C	UNIVENT	METAL	BEIGE	None	0	0.01	Negative
1	2	Stairwell behind C Wing Classroom 106C	CEILING	CONCRETE	BEIGE	None	0	0.04	Negative
1	2	Classroom C106	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom C106	W2	CMU	WHITE	None	0	0.01	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom C106	W3	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom C106	W3	CMU	GREEN	None	0	0.01	Negative
1	2	Classroom C106	W4	CMU	GREEN	None	0	0.01	Negative
1	2	Classroom C106	SOFFIT	PLASTER	WHITE	None	0	0	Negative
1	2	Classroom C106	SOFFIT	PLASTER	WHITE	None	0	0	Negative
1	2	Classroom C106	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Classroom C106	DOOR	WOOD	BLUE	None	0	0	Negative
1	2	Classroom C105	DOOR CASING	METAL	BLUE	None	0	0.06	Negative
1	2	Classroom C105	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom C105	W2	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom C105	W3	CMU	GREEN	None	0	0.01	Negative
1	2	Classroom C105	SOFFIT	PLASTER	WHITE	Efflorescence	4	0	Negative
1	2	Classroom C105	WALL DIVIDER TR	WOOD	WHITE	None	0	0	Negative
1	2	Classroom C105	WALL DIVIDER	DRYWALL	WHITE	None	0	0	Negative
1	2	Classroom C104	WALL DIVIDER	DRYWALL	WHITE	None	0	0.01	Negative
1	2	Classroom C104	WALL DIVIDER TR	WOOD	WHITE	None	0	0.02	Negative
1	2	Classroom C104	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom C104	W4	CMU	WHITE	None	0	0.04	Negative
1	2	Classroom C104	W3	CMU	GREEN	None	0	0.04	Negative
1	2	Classroom C104	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative
1	2	Classroom C104	DIVIDER WALL TR	WOOD	WHITE	None	0	0	Negative
1	2	Classroom C104	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative
1	2	Classroom C103	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative
1	2	Classroom C103	W1	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom C103	W4	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom C103	W3	CMU	GREEN	None	0	0.05	Negative
1	2	Classroom C103	W2	CMU	WHITE	None	0	0.02	Negative
1	2	Classroom C103	WALL DIVIDER TR	WOOD	WHITE	None	0	0.01	Negative
1	2	Classroom C103	WALL DIVIDER	DRYWALL	WHITE	None	0	0.01	Negative
1	2	Classroom C103	DOOR CASING	METAL	BLUE	None	0	0	Negative
1	2	Classroom C102	DOOR CASING	METAL	BLUE	None	0	0.02	Negative
1	2	Classroom C102	DOOR	WOOD	BLUE	None	0	0	Negative
1	2	Classroom C102	W1	CMU	WHITE	None	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom C102	W2	CMU	WHITE	None	0	0.01	Negative
1	2	Classroom C102	W3	CMU	GREEN	None	0	0.05	Negative
1	2	Classroom C102	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative
1	2	Classroom C102	WALL DIVIDER TP	WOOD	WHITE	None	0	0.01	Negative
1	2	Classroom C102	WALL DIVIDER	DRYWALL	WHITE	None	0	0.02	Negative
1	2	Classroom C102	COLUMN	CONCRETE	WHITE	None	0	0	Negative
1	2	Classroom C101	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Classroom C101	W1	CMU	WHITE	None	0	0.03	Negative
1	2	Classroom C101	W4	CMU	WHITE	None	0	0.05	Negative
1	2	Classroom C101	W3	CMU	GREEN	None	0	0.02	Negative
1	2	Classroom C101	SOFFIT	PLASTER	WHITE	None	0	0.02	Negative
1	2	Classroom C101	DIVIDER WALL TP	WOOD	WHITE	None	0	0.01	Negative
1	2	Classroom C101	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative
1	2	C Wing Boy's Restroom	DOOR CASING	METAL	BLACK	None	0	0.03	Negative
1	2	C Wing Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative
1	2	C Wing Boy's Restroom	W4	CMU	BEIGE	None	0	0	Negative
1	2	C Wing Boy's Restroom	W2	CMU	BEIGE	None	0	0	Negative
1	2	C Wing Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative
1	2	C Wing Boy's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative
1	2	C Wing Boy's Restroom	FLOOR	CONCRETE	GRAY	None	0	0	Negative
1	2	C Wing Boy's Restroom	WALL BASEBOARD	TILE	GRAY	None	0	0.02	Negative
1	2	C Wing Boy's Restroom	WALL BASEBOARD	TILE	GRAY	None	0	0.01	Negative
1	2	C Wing Boy's Restroom	WALL BASEBOARD	TILE	GRAY	None	0	0	Negative
1	2	C Wing Boy's Restroom	WALL BASEBOARD	TILE	GRAY	None	0	0.04	Negative
1	2	C Wing Men's Staff Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing Men's Staff Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing Men's Staff Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing Men's Staff Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing Men's Staff Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing Men's Staff Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing Women's Staff Restroom	W1	CMU	WHITE	None	0	0	Negative
1	2	C Wing Women's Staff Restroom	W4	CMU	WHITE	None	0	0	Negative
1	2	C Wing Women's Staff Restroom	W3	CMU	WHITE	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	C Wing Women's Staff Restroom	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	2	C Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.05	Negative
1	2	C Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.01	Negative
1	2	C Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.04	Negative
1	2	C Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.07	Negative
1	2	C Wing Girl's Restroom	W1	CMU	PINK	None	0	0	Negative
1	2	C Wing Girl's Restroom	W4	CMU	PINK	None	0	0	Negative
1	2	C Wing Girl's Restroom	W3	CMU	PINK	None	0	0	Negative
1	2	C Wing Girl's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative
1	2	C Wing Girl's Restroom	FLOOR	CONCRETE	GRAY	None	0	0	Negative
1	2	C Wing Girl's Restroom	DOOR CASING	METAL	BLACK	None	0	0.01	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	DOOR	METAL	BLUE	None	0	0	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	W2	CMU	PURPLE	None	0	0.04	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	W3	CMU	BEIGE	None	0	0	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	W1	CMU	PURPLE	None	0	0.01	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	DOOR CASING	METAL	BEIGE	None	0	0.01	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	DOOR CASING	METAL	BEIGE	None	0	0.06	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	SOFFIT	PLASTER	BEIGE	None	0	0.01	Negative
1	2	Hallway outside C Wing Classrooms C101 - C106	SOFFIT	PLASTER	BEIGE	None	0	0.01	Negative
1	2	Custodial Closet in H126 between classrooms C105 & C106	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in H126 between classrooms C105 & C106	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in H126 between classrooms C105 & C106	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in H126 between classrooms C105 & C106	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in H126 between classrooms C105 & C106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet in H126 between classrooms C105 & C106	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Large Library Reading Area in D Wing	W1	CMU	BLUE	None	0	0.01	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Large Library Reading Area in D Wing	W2	CMU	BEIGE	None	0	0.02	Negative
1	2	Large Library Reading Area in D Wing	W1	CMU	BEIGE	Flaking	25	0.03	Negative
1	2	Large Library Reading Area in D Wing	DOOR CASING	METAL	BLUE	None	0	0.15	Negative
1	2	Large Library Reading Area in D Wing	DOOR	METAL	BLUE	None	0	0.06	Negative
1	2	Large Library Reading Area in D Wing	W4	CMU	BLUE	None	0	0.01	Negative
1	2	Large Library Reading Area in D Wing	DOOR CASING	METAL	BLUE	None	0	0.28	Negative
1	2	Large Library Reading Area in D Wing	DOOR	METAL	BLUE	None	0	0	Negative
1	2	Large Library Reading Area in D Wing	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Large Library Reading Area in D Wing	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative
1	2	Large Library Reading Area in D Wing	CEILING	PLASTER	WHITE	None	0	0	Negative
1	2	D Wing Large Library Reading Area Stairwell	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	D Wing Large Library Reading Area Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	D Wing Large Library Reading Area Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	D Wing Large Library Reading Area Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	D Wing Large Library Reading Area Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	D Wing Large Library Reading Area Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Lounge between D Wing Large Library Reading Area and D Wing Hallway	W1	CMU	Grey	None	0	0.01	Negative
1	2	Lounge between D Wing Large Library Reading Area and D Wing Hallway	W3	CMU	PURPLE	None	0	0	Negative
1	2	Lounge between D Wing Large Library Reading Area and D Wing Hallway	W4	CMU	PINK	None	0	0.02	Negative
1	2	Lounge between D Wing Large Library Reading Area and D Wing Hallway	W2	CMU	PINK	None	0	0.01	Negative
1	2	Lounge between D Wing Large Library Reading Area and D Wing Hallway	DOOR CASING	METAL	PURPLE	None	0	0.02	Negative
1	2	Lounge between D Wing Large Library Reading Area and D Wing Hallway	DOOR CASING	METAL	PURPLE	None	0	0.01	Negative
		Lounge between D Wing Large Library Reading Area and D Wing Hallway	DOOR	WOOD	PINK	None	0	0	Negative
1	2	Lounge between D Wing Large Library Reading Area and D Wing Hallway	DOOR	WOOD	PURPLE	None	0	0.01	Negative
1	2	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Office behind D Wing Stairwell	W1	CMU	PURPLE	None	0	0.01	Negative
1	2	Office behind D Wing Stairwell	W3	CMU	PURPLE	None	0	0	Negative
1	2	Office behind D Wing Stairwell	W4	CMU	PINK	None	0	0.02	Negative
1	2	Office behind D Wing Stairwell	W2	CMU	PINK	None	0	0.01	Negative
1	2	Office behind D Wing Stairwell	DOOR CASING	METAL	PURPLE	None	0	0.02	Negative
1	2	Office behind D Wing Stairwell	DOOR CASING	METAL	PURPLE	None	0	0.01	Negative
1	2	Office behind D Wing Stairwell	DOOR	WOOD	PINK	None	0	0	Negative
1	2	Office behind D Wing Stairwell	DOOR	WOOD	PURPLE	None	0	0.01	Negative
1	2	Office next to D Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Office next to D Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Office next to D Wing Stairwell	DOOR	WOOD	BLUE	None	0	0.02	Negative
1	2	Office next to D Wing Stairwell	W1	CMU	BEIGE	None	0	0	Negative
1	2	Office next to D Wing Stairwell	W2	CMU	BEIGE	None	0	0.02	Negative
1	2	Office next to D Wing Stairwell	W3	CMU	BEIGE	None	0	0	Negative
1	2	Office next to D Wing Stairwell	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Office next to D Wing Stairwell	COLUMN	CONCRETE	BEIGE	None	0	0.02	Negative
1	2	Office across from Classroom D103	W1	CMU	BLUE	None	0	0.01	Negative
1	2	Office across from Classroom D103	W3	CMU	BLUE	None	0	0.01	Negative
1	2	Office across from Classroom D103	W2	CMU	PURPLE	None	0	0.02	Negative
1	2	Office across from Classroom D103	W4	CMU	PURPLE	None	0	0.01	Negative
1	2	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.03	Negative
1	2	Office across from Classroom D103	DOOR	WOOD	BLUE	None	0	0.05	Negative
1	2	Office across from Classroom D103	DOOR	WOOD	BLUE	None	0	0.02	Negative
1	2	Office across from Classroom D103	W1	CMU	WHITE	None	0	0.05	Negative
1	2	Office across from Classroom D103	W1	CMU	BLUE	None	0	0	Negative
1	2	Office across from Classroom D103	W2	CMU	GRAY	None	0	0.02	Negative
1	2	Office across from Classroom D103	W3	CMU	GRAY	None	0	0.01	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Office across from Classroom D103	W3	CMU	BLUE	None	0	0.01	Negative
1	2	Office across from Classroom D103	W3	CMU	WHITE	None	0	0.01	Negative
1	2	Office across from Classroom D103	W4	CMU	WHITE	None	0	0.01	Negative
1	2	Office across from Classroom D103	W4	CMU	GRAY	None	0	0.01	Negative
1	2	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.02	Negative
1	2	Office across from Classroom D103	DOOR	METAL	BLUE	None	0	0	Negative
1	2	Office across from Classroom D103	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.03	Negative
1	2	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.02	Negative
1	2	Office across from Classroom D103	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0	Negative
1	2	D Wing End Storage Room	W1	CMU	BEIGE	None	0	0	Negative
1	2	D Wing End Storage Room	W4	CMU	BEIGE	None	0	0	Negative
1	2	D Wing End Storage Room	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	D Wing End Storage Room	W2	CMU	BEIGE	None	0	0.02	Negative
1	2	D Wing End Storage Room	DOOR CASING	METAL	BLUE	None	0	0.16	Negative
1	2	D Wing End Storage Room	DOOR	WOOD	BLUE	None	0	0.05	Negative
1	2	D Wing Small Storage Room	DOOR	WOOD	BLUE	None	0	0.04	Negative
1	2	D Wing Small Storage Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	D Wing Small Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	D Wing Small Storage Room	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	D Wing Small Storage Room	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	D Wing Small Storage Room	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	D Wing Small Storage Room	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative
1	2	Small Office inside D Wing Large Library Reading Area	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside D Wing Large Library Reading Area	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside D Wing Large Library Reading Area	W2	CMU	BEIGE	None	0	0.03	Negative
1	2	Small Office inside D Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Small Office inside D Wing Large Library Reading Area	DOOR	WOOD	BLUE	None	0	0.01	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	D Wing Storage Room next to HVAC/Mechanical Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	D Wing Storage Room next to HVAC/Mechanical Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	D Wing Storage Room next to HVAC/Mechanical Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	D Wing Storage Room next to HVAC/Mechanical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	D Wing Storage Room next to HVAC/Mechanical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	D Wing Storage Room next to HVAC/Mechanical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room between C and D Wings	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room between C and D Wings	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room between C and D Wings	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room between C and D Wings	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room between C and D Wings	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	HVAC/Mechanical Room between C and D Wings	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Large Library Reading Area in C Wing	W1	CMU	YELLOW	Flaking	28	0.05	Negative
1	2	Large Library Reading Area in C Wing	W1	CMU	WHITE	None	0	0.02	Negative
1	2	Large Library Reading Area in C Wing	W2	DRYWALL	BEIGE	None	0	0	Negative
1	2	Large Library Reading Area in C Wing	W2	CMU	YELLOW	None	0	0.01	Negative
1	2	Large Library Reading Area in C Wing	W3	CMU	YELLOW	None	0	0.01	Negative
1	2	Large Library Reading Area in C Wing	W4	CMU	YELLOW	None	0	0.01	Negative
1	2	Large Library Reading Area in C Wing	COLUMN	Concrete	BEIGE	None	0	0	Negative
1	2	Large Library Reading Area in C Wing	CEILING	PLASTER	BEIGE	None	0	0.01	Negative
1	2	C Wing Large Library Reading Area Stairwell	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	C Wing Large Library Reading Area Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	C Wing Large Library Reading Area Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	C Wing Large Library Reading Area Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	C Wing Large Library Reading Area Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	C Wing Large Library Reading Area Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W1	CMU	PURPLE	None	0	0.01	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W2	CMU	PURPLE	None	0	0	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W3	CMU	PURPLE	None	0	0.03	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W1	CMU	PINK	None	0	0.01	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.05	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.02	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.04	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR	METAL	BLUE	None	0	0	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR	WOOD	BLUE	None	0	-0.09	Negative
1	2	Pipe Chase in 112C Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in 112C Lounge	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in 112C Lounge	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in 112C Lounge	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in 112C Lounge	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Pipe Chase in 112C Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Office behind C Wing Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Office behind C Wing Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Office behind C Wing Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Office behind C Wing Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Office behind C Wing Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Office behind C Wing Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Office next to C Wing Stairwell	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Office next to C Wing Stairwell	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Office next to C Wing Stairwell	W4	CMU	BEIGE	None	0	0.04	Negative
1	2	Office next to C Wing Stairwell	W3	CMU	BEIGE	None	0	0	Negative
1	2	Office next to C Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.02	Negative
1	2	Office next to C Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.13	Negative
1	2	Office next to C Wing Stairwell	DOOR	WOOD	BLUE	None	0	0.04	Negative
1	2	Office across from Classroom C103	W1	CMU	BEIGE	None	0	0	Negative
1	2	Office across from Classroom C103	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Office across from Classroom C103	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Office across from Classroom C103	W3	CMU	BEIGE	None	0	0.02	Negative
1	2	Office across from Classroom C103	DOOR CASING	METAL	BLUE	None	0	0.02	Negative
1	2	Office across from Classroom C103	DOOR	WOOD	BLUE	None	0	0	Negative
1	2	Office across from Classroom C103	DOOR	WOOD	BLUE	None	0	0	Negative
1	2	Office across from Classroom C103	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	C Wing End Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing End Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing End Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing End Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing End Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing End Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	C Wing Small Storage Room	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	C Wing Small Storage Room	DOOR CASING	METAL	BLUE	None	0	0.04	Negative
1	2	C Wing Small Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	C Wing Small Storage Room	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	C Wing Small Storage Room	W3	CMU	BEIGE	None	0	0.04	Negative
1	2	C Wing Small Storage Room	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside C Wing Large Library Reading Area	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside C Wing Large Library Reading Area	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside C Wing Large Library Reading Area	W4	CMU	BEIGE	None	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Small Office inside C Wing Large Library Reading Area	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Small Office inside C Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.02	Negative
1	2	Small Office inside C Wing Large Library Reading Area	DOOR	WOOD	BLUE	None	0	0.05	Negative
1	2	C Wing Storage Room next to HVAC/Mechanical Room 1	DOOR	WOOD	BLUE	None	0	0.04	Negative
1	2	C Wing Storage Room next to HVAC/Mechanical Room 1	DOOR CASING	METAL	BLUE	None	0	0.05	Negative
1	2	C Wing Storage Room next to HVAC/Mechanical Room 1	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	C Wing Storage Room next to HVAC/Mechanical Room 1	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	C Wing Storage Room next to HVAC/Mechanical Room 1	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	C Wing Storage Room next to HVAC/Mechanical Room 1	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	IMC (Library)	W1	CMU	BEIGE	Flaking	15	0.01	Negative
1	2	IMC (Library)	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative
1	2	IMC (Library)	COLUMN	CONCRETE	WHITE	None	0	0.02	Negative
1	2	IMC (Library)	W3	CMU	WHITE	None	0	0.01	Negative
1	2	IMC (Library)	W4	DRYWALL	WHITE	None	0	0	Negative
1	2	IMC (Library)	W4	CMU	BEIGE	None	0	0.04	Negative
1	2	IMC (Library)	W2	CMU	BEIGE	Flaking	25	0.02	Negative
1	2	IMC (Library)	W2	DRYWALL	BEIGE	None	0	0	Negative
1	2	IMC (Library)	SOFFIT	PLASTER	BEIGE	None	0	0.02	Negative
1	2	IMC (Library)	WINDOW CASING	METAL	BROWN	None	0	0.4	Negative
1	2	IMC (Library)	DOOR CASING	METAL	BROWN	None	0	0.4	Negative
1	2	IMC (Library)	DOOR	WOOD	BROWN	None	0	0.03	Negative
1	2	IMC (Library)	DOOR	WOOD	BROWN	None	0	0.01	Negative
1	2	IMC (Library)	DOOR CASING	METAL	BROWN	None	0	0.4	Negative
1	2	IMC Office	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	IMC Office	W2	CMU	BEIGE	None	0	0.02	Negative
1	2	IMC Office	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	IMC Office	W4	CMU	BEIGE	None	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	IMC Office	WINDOW CASING	METAL	BROWN	None	0	0.4	Negative
1	2	IMC Office	WINDOW CASING	METAL	BROWN	None	0	0.23	Negative
1	2	IMC Office	WINDOW CASING	METAL	BROWN	None	0	0.25	Negative
1	2	IMC Office	DOOR CASING	METAL	BROWN	None	0	0.4	Negative
1	2	IMC Office	DOOR	WOOD	BROWN	None	0	0.01	Negative
1	2	IMC Office	DOOR	WOOD	BROWN	None	0	0.01	Negative
1	2	IMC Office	DOOR CASING	METAL	BROWN	None	0	0.25	Negative
1	2	Small office in IMC	DOOR CASING	METAL	BROWN	None	0	0.5	Negative
1	2	Small office in IMC	DOOR CASING	METAL	BROWN	None	0	0.4	Negative
1	2	Small office in IMC	DOOR CASING	WOOD	BROWN	None	0	0.01	Negative
1	2	Small office in IMC	DOOR CASING	WOOD	BROWN	None	0	0	Negative
1	2	Small office in IMC	W1	CMU	BEIGE	None	0	0.01	Negative
1	2	Small office in IMC	W2	CMU	BEIGE	None	0	0.03	Negative
1	2	Small office in IMC	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Small office in IMC	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	IMC Office/Data Room	W1	CMU	BEIGE	None	0	0.03	Negative
1	2	IMC Office/Data Room	W4	CMU	BEIGE	None	0	0.02	Negative
1	2	IMC Office/Data Room	W3	CMU	BEIGE	None	0	0.02	Negative
1	2	IMC Office/Data Room	W2	CMU	BEIGE	None	0	0.04	Negative
1	2	IMC Office/Data Room	DOOR CASING	METAL	BROWN	None	0	0.28	Negative
1	2	IMC Office/Data Room	DOOR	METAL	BROWN	None	0	0.02	Negative
1	2	IMC Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	IMC Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	IMC Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	IMC Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	IMC Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	IMC Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Hallway from D Wing Library Reading Room to Computer Classroom E131	W1	CMU	Beige	None	0	0.1	Negative
1	2	Hallway from D Wing Library Reading Room to Computer Classroom E131	W3	CMU	Beige	None	0	0	Negative
1	2	Hallway from D Wing Library Reading Room to Computer Classroom E131	W4	CMU	Beige	None	0	0.1	Negative
1	2	Hallway from D Wing Library Reading Room to Computer Classroom E131	Door	Wood	Beige	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Hallway from D Wing Library Reading Room to Computer Classroom E131	Door Casing	Metal	Beige	None	0	0.1	Negative
1	2	Hallway from D Wing Library Reading Room to Computer Classroom E131	Soffit	Plaster	Beige	None	0	0.1	Negative
1	2	Hallway between Library and Auditorium	W2	CMU	Purple	None	0	0.1	Negative
1	2	Hallway between Library and Auditorium	W2	CMU	Pink	None	0	0.1	Negative
1	2	Hallway between Library and Auditorium	W2	CMU	Blue	None	0	0.3	Negative
1	2	Hallway between Library and Auditorium	W2	CMU	Green	None	0	0.2	Negative
1	2	Hallway between Library and Auditorium	W2	CMU	Red	None	0	0.1	Negative
1	2	Hallway between Library and Auditorium	W2	CMU	Orange	None	0	0.1	Negative
1	2	Hallway between Library and Auditorium	W4	CMU	Orange	None	0	0	Negative
1	2	Hallway between Library and Auditorium	W4	CMU	Pink	None	0	0.1	Negative
1	2	Hallway between Library and Auditorium	W4	CMU	Purple	None	0	0.1	Negative
1	2	Hallway between Library and Auditorium	W4	CMU	Blue	None	0	0.1	Negative
1	2	Hallway between Library and Auditorium	W4	CMU	Green	None	0	0	Negative
1	2	Hallway between Library and Auditorium	W4	CMU	Red	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	W1	CMU	Yellow	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	W1	CMU	Green	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	W1	CMU	Purple	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	W1	CMU	Blue	None	0	0	Negative
1	2	Hallway from Library to Classroom 126	W1	CMU	Navy	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	W3	CMU	Navy	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	W3	CMU	Blue	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	W3	CMU	Green	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	W3	CMU	Yellow	None	0	0	Negative
1	2	Hallway from Library to Classroom 126	W4	CMU	Beige	None	0	0.2	Negative
1	2	Hallway from Library to Classroom 126	Door Casing	Metal	Beige	None	0	0.1	Negative
1	2	Hallway from Library to Classroom 126	Door Casing	Metal	Beige	None	0	0.3	Negative
1	2	Hallway from Library to Classroom 126	Door	Metal	Beige	None	0	0	Negative
1	2	Hallway from Library to Classroom 126	Door	Metal	Beige	None	0	0	Negative
1	2	Hallway from Library to Classroom 126	Door Casing	Metal	Beige	None	0	0.3	Negative
1	2	Computer Classroom E131	W1	Concrete	White	None	0	0.2	Negative
1	2	Computer Classroom E131	W2	Concrete	White	None	0	0.1	Negative
1	2	Computer Classroom E131	W3	Concrete	White	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Computer Classroom E131	W4	Concrete	White	None	0	0	Negative
1	2	Computer Classroom E131	Column	Concrete	White	None	0	0.2	Negative
1	2	Computer Classroom E131	Ceiling	Concrete	White	None	0	0.2	Negative
1	2	Computer Classroom E131	Duct	Metal	White	None	0	0.1	Negative
1	2	Computer Classroom E131	Closet - Door	Wood	Brown	None	0	0.1	Negative
1	2	Computer Classroom E131	Door Casing	Metal	Brown	None	0	0.5	Negative
1	2	Computer Classroom E131	Column	Concrete	White	None	0	0.2	Negative
1	2	Computer Classroom E131	Window Casing	Metal	Brown	None	0	0	Negative
1	2	Computer Classroom E131	Door	Wood	Brown	None	0	0.1	Negative
1	2	Computer Classroom E131	Door Casing	Metal	Brown	None	0	0	Negative
1	2	Storage Room inside Computer Classroom E131 (former dark room)	W1	Concrete	Black	None	0	0.1	Negative
1	2	Storage Room inside Computer Classroom E131 (former dark room)	W2	Concrete	Black	None	0	0	Negative
1	2	Storage Room inside Computer Classroom E131 (former dark room)	W3	Concrete	Black	None	0	0.1	Negative
1	2	Storage Room inside Computer Classroom E131 (former dark room)	W4	Concrete	Black	None	0	0	Negative
1	2	Office inside Computer Classroom E131	W4	Concrete	White	None	0	0	Negative
1	2	Office inside Computer Classroom E131	W3	Concrete	White	None	0	0.2	Negative
1	2	Office inside Computer Classroom E131	W2	Concrete	White	None	0	0	Negative
1	2	Office inside Computer Classroom E131	W1	Concrete	White	None	0	0.1	Negative
1	2	Office inside Computer Classroom E131	Window Casing	Metal	Brown	None	0	0	Negative
1	2	Storage Room next to Office inside Computer Classroom E131	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room next to Office inside Computer Classroom E131	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room next to Office inside Computer Classroom E131	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room next to Office inside Computer Classroom E131	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room next to Office inside Computer Classroom E131	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Room next to Office inside Computer Classroom E131	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 124	Door Casing	Metal	Blue	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 124	W1	CMU	Beige	None	0	0.1	Negative
1	2	Classroom 124	W4	CMU	Beige	None	0	0.1	Negative
1	2	Classroom 124	W2	Drywall	Beige	None	0	0.2	Negative
1	2	Classroom 124	W3	Drywall	Pink	None	0	0.1	Negative
1	2	Classroom 124	Column	Concrete	Green	None	0	0.1	Negative
1	2	Classroom 124	W1	CMU	Yellow	None	0	0	Negative
1	2	Classroom 124	Door Casing	Metal	Blue	None	0	0.2	Negative
1	2	Classroom 124	Door	Wood	Blue	None	0	0	Negative
1	2	Classroom 124	Column	Concrete	Blue	None	0	0.1	Negative
1	2	Classroom 124	Pipe	Metal	Beige	None	0	0.4	Negative
1	2	Classroom 124	Bookcase	Wood	Purple	None	0	0.1	Negative
1	2	Classroom 125	W1	CMU	BEIGE	None	0	0.02	Negative
1	2	Classroom 125	W2	CMU	BEIGE	None	0	0.01	Negative
1	2	Classroom 125	W3	CMU	BEIGE	None	0	0.01	Negative
1	2	Classroom 125	W4	DRYWALL	BEIGE	None	0	0	Negative
1	2	Classroom 125	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative
1	2	Classroom 125	DOOR CASING	METAL	BLUE	None	0	0	Negative
1	2	Classroom 125	DOOR	WOOD	BLUE	None	0	0.04	Negative
1	2	Classroom 125	DOOR	WOOD	BLUE	None	0	0.03	Negative
1	2	Classroom 125	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Classroom 125	DUCT	METAL	BEIGE	None	0	0.01	Negative
1	2	Classroom 125	PIPE	METAL	BEIGE	None	0	0.16	Negative
1	2	Classroom 125	Door Casing	Metal	Blue	None	0	0.1	Negative
1	2	Classroom 125	W1	CMU	Beige	None	0	0	Negative
1	2	Classroom 125	W2	Drywall	Beige	None	0	0	Negative
1	2	Classroom 125	W4	Drywall	Beige	None	0	0.2	Negative
1	2	Classroom 125	W3	CMU	Beige	None	0	0	Negative
1	2	Classroom 125	Soffit	Plaster	Beige	None	0	0	Negative
1	2	Classroom 125	Column	Concrete	Beige	None	0	0.2	Negative
1	2	Classroom 126	Column	Concrete	Green	None	0	0.1	Negative
1	2	Classroom 126	W1	CMU	Yellow	None	0	0	Negative
1	2	Classroom 126	Door Casing	Metal	Blue	None	0	0.2	Negative
1	2	Classroom 126	Door	Wood	Blue	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 126	Column	Concrete	Blue	None	0	0.1	Negative
1	2	Classroom 126	Pipe	Metal	Beige	None	0	0.4	Negative
1	2	Classroom 126	Bookcase	Wood	Purple	None	0	0.1	Negative
1	2	Classroom 126 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 126 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 126 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 126 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 126 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 126 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairwell next to Classroom 126	Door Casing	Metal	Beige	None	0	0.5	Negative
1	2	Stairwell next to Classroom 126	Door	Metal	Beige	None	0	0	Negative
1	2	Stairwell next to Classroom 126	W1	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell next to Classroom 126	W2	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell next to Classroom 126	W3	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell next to Classroom 126	W4	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell next to Classroom 126	Stairs - Railing	Metal	Beige	None	0	0.3	Negative
1	2	Stairwell next to Classroom 126	Stairs - Stringer	Metal	Beige	None	0	0.6	Negative
1	2	Stairwell next to Classroom 126	Stairs - Riser	Metal	Beige	None	0	0.7	Positive
1	2	Classroom at End of Hall next to Computer Classroom E131, Left Door	W1	DRYWALL	BEIGE	None	0	0	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Left Door	W2	DRYWALL	BEIGE	None	0	0	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Left Door	W3	CMU	BEIGE	None	0	0.02	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Left Door	W4	CMU	BEIGE	None	0	0.01	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Left Door	DUCT	METAL	BEIGE	None	0	0.01	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Left Door	CEILING	CONCRETE	BEIGE	None	0	0.02	Negative
1	2	Large HVAC/Mechanical Room next to Computer Classroom E131	Fan Unit	Metal	Beige	Flaking	20	0.1	Negative
1	2	Large HVAC/Mechanical Room next to Computer Classroom E131	Duct	Metal	Beige	None	0	0.1	Negative
1	2	Large HVAC/Mechanical Room next to Computer Classroom E131	Larger Fan Unit	Metal	Beige	None	0	0	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	W4	CMU	Beige	None	0	0.3	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	W3	CMU	Beige	None	0	0	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	W2	CMU	Beige	None	0	0.1	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	W1	Drywall	Beige	None	0	0.1	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	W4	Drywall	Beige	None	0	0.1	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	Ceiling	Concrete	Beige	None	0	0.2	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	Column	Concrete	Beige	None	0	0.2	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	Duct	Metal	Beige	None	0	0.2	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	Door	Metal	Brown	None	0	0	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	Door Casing	Metal	Brown	None	0	0	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	W4	Drywall	Beige	None	0	0.1	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	Door	Metal	Brown	None	0	0	Negative
1	2	Classroom at End of Hall next to Computer Classroom E131, Right Door	Door Casing	Metal	Brown	None	0	0.5	Negative
1	2	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	W1	CMU	Purple	None	0	0.2	Negative
1	2	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	W2	CMU	Purple	None	0	0.2	Negative
1	2	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	W3	CMU	Purple	None	0	0.1	Negative
1	2	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	W4	CMU	Purple	None	0	0.1	Negative
1	2	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	Pipe	Metal	Purple	None	0	0.3	Negative
1	2	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	Door Casing	Metal	Blue	None	0	0.3	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	Door	Wood	Blue	None	0	0.1	Negative
1	2	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	Univent	Metal	Purple	None	0	0	Negative
1	2	Small HVAC/Mechanical Room outside Computer Classroom E131	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Small HVAC/Mechanical Room outside Computer Classroom E131	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Small HVAC/Mechanical Room outside Computer Classroom E131	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Small HVAC/Mechanical Room outside Computer Classroom E131	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Small HVAC/Mechanical Room outside Computer Classroom E131	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Small HVAC/Mechanical Room outside Computer Classroom E131	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairwell next to Music Classrooms	W1	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell next to Music Classrooms	W4	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell next to Music Classrooms	W2	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell next to Music Classrooms	W3	CMU	Beige	None	0	0.1	Negative
1	2	Stairwell next to Music Classrooms	Stairs - Stringer	Metal	Brown	None	0	0.7	Positive
1	2	Stairwell next to Music Classrooms	Stairs - Riser	Metal	Brown	None	0	1.1	Positive
1	2	Stairwell next to Music Classrooms	Stairs - Railing	Metal	Brown	None	0	0.1	Negative
1	2	Stairwell next to Music Classrooms	Underside of Stair	Metal	Brown	None	0	0.9	Positive
1	2	Stairwell next to Music Classrooms	Door Casing	Metal	Blue	None	0	0.2	Negative
1	2	Stairwell next to Music Classrooms	Door	Wood	Blue	None	0	0.1	Negative
1	2	Music Classroom next to Stairwell	DOOR CASING	METAL	BLUE	None	0	0	Negative
1	2	Music Classroom next to Stairwell	DOOR	WOOD	BLUE	None	0	0.01	Negative
1	2	Music Classroom next to Stairwell	DOOR	WOOD	BLUE	None	0	0.02	Negative
1	2	Music Classroom next to Stairwell	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Music Classroom next to Stairwell	DOOR CASING	METAL	BLUE	None	0	0.01	Negative
1	2	Music Classroom next to Stairwell	DOOR	WOOD	BLUE	None	0	0	Negative
1	2	Music Classroom next to Stairwell	W1	CMU	YELLOW	None	0	0.01	Negative
1	2	Music Classroom next to Stairwell	W4	CMU	YELLOW	None	0	0.02	Negative
1	2	Music Classroom next to Stairwell	W3	CMU	YELLOW	None	0	0.02	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Music Classroom next to Stairwell	COLUMN	CONCRETE	YELLOW	None	0	0.02	Negative
1	2	Music Classroom next to Stairwell	COLUMN	CONCRETE	YELLOW	None	0	0.01	Negative
1	2	Music Classroom next to Stairwell	COLUMN	CONCRETE	YELLOW	None	0	0.04	Negative
1	2	Office inside Music Classroom next to Stairwell	W1	CMU	Yellow	None	0	0.1	Negative
1	2	Office inside Music Classroom next to Stairwell	W2	CMU	Yellow	None	0	0.1	Negative
1	2	Office inside Music Classroom next to Stairwell	W3	CMU	Yellow	None	0	0.1	Negative
1	2	Office inside Music Classroom next to Stairwell	W4	CMU	Yellow	None	0	0.5	Negative
1	2	Office inside Music Classroom next to Stairwell	Door	Wood	Blue	None	0	0	Negative
1	2	Office inside Music Classroom next to Stairwell	Door Casing	Metal	Blue	None	0	0.1	Negative
1	2	Office inside Music Classroom next to Stairwell	Door Casing	Metal	Blue	None	0	0.4	Negative
1	2	Office inside Music Classroom next to Stairwell	Door	Wood	Blue	None	0	0.1	Negative
1	2	Soundproof Room D inside Music Classroom next to Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room D inside Music Classroom next to Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room D inside Music Classroom next to Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room D inside Music Classroom next to Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room D inside Music Classroom next to Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room D inside Music Classroom next to Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room E inside Music Classroom next to Stairwell	W1	CMU	YELLOW	None	0	0.02	Negative
1	2	Soundproof Room E inside Music Classroom next to Stairwell	W2	CMU	YELLOW	None	0	0.01	Negative
1	2	Soundproof Room E inside Music Classroom next to Stairwell	W4	CMU	YELLOW	None	0	0.01	Negative
1	2	Soundproof Room E inside Music Classroom next to Stairwell	W3	CMU	YELLOW	None	0	0.01	Negative
1	2	Soundproof Room F inside Music Classroom next to Stairwell	W1	CMU	Yellow	None	0	0.1	Negative
1	2	Soundproof Room F inside Music Classroom next to Stairwell	W2	CMU	Yellow	None	0	0.1	Negative
1	2	Soundproof Room F inside Music Classroom next to Stairwell	W3	CMU	Yellow	None	0	0.1	Negative

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Soundproof Room F inside Music Classroom next to Stairwell	W4	CMU	Yellow	None	0	0.1	Negative
1	2	Soundproof Room F inside Music Classroom next to Stairwell	Door Casing	Metal	Blue	None	0	0.2	Negative
1	2	Soundproof Room F inside Music Classroom next to Stairwell	Door	Wood	Blue	None	0	0	Negative
1	2	Smaller Music Classroom	W1	CMU	YELLOW	None	0	0.01	Negative
1	2	Smaller Music Classroom	W4	CMU	YELLOW	None	0	0.01	Negative
1	2	Smaller Music Classroom	W3	CMU	YELLOW	None	0	0.01	Negative
1	2	Smaller Music Classroom	W2	CMU	YELLOW	None	0	0.04	Negative
1	2	Smaller Music Classroom	COLUMN 1	CONCRETE	YELLOW	Flaking	15	0.02	Negative
1	2	Smaller Music Classroom	COLUMN 4	CONCRETE	YELLOW	Flaking	10	0.01	Negative
1	2	Office inside Smaller Music Classroom	W1	CMU	YELLOW	None	0	0.01	Negative
1	2	Office inside Smaller Music Classroom	W2	CMU	YELLOW	None	0	0.01	Negative
1	2	Office inside Smaller Music Classroom	W3	CMU	YELLOW	None	0	0.01	Negative
1	2	Office inside Smaller Music Classroom	W4	CMU	YELLOW	None	0	0.01	Negative
1	2	Office inside Smaller Music Classroom	DOOR CASING	METAL	BLUE	None	0	0	Negative
1	2	Office inside Smaller Music Classroom	DOOR	WOOD	BLUE	None	0	0.02	Negative
1	2	Office inside Smaller Music Classroom	DOOR	WOOD	BLUE	None	0	0.06	Negative
1	2	Office inside Smaller Music Classroom	DOOR CASING	METAL	BLUE	None	0	0	Negative
1	2	Soundproof Room A inside Smaller Music Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room A inside Smaller Music Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room A inside Smaller Music Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room A inside Smaller Music Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room A inside Smaller Music Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room A inside Smaller Music Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room B inside Smaller Music Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room B inside Smaller Music Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room B inside Smaller Music Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room B inside Smaller Music Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room B inside Smaller Music Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room B inside Smaller Music Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room C inside Smaller Music Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room C inside Smaller Music Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room C inside Smaller Music Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21, 8/12/21	School District of Philadelphia						
		Name of Inspector: Kristen Masotes	Lead Safe Certification Assessment Report						
		Inspection Company: Acer Associates	E.W. Rhodes ES School						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Soundproof Room C inside Smaller Music Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room C inside Smaller Music Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Soundproof Room C inside Smaller Music Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	AT	Attic - None	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic - None	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic - None	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic - None	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic - None	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	Attic - None	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space Under the Pool	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space Under the Pool	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space Under the Pool	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space Under the Pool	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space Under the Pool	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	Crawl Space Under the Pool	Floor	N/A	N/A	N/A	N/A	N/A	N/A