

Lead Safe Certification																	
			Name of Inspector: Charles Rhodes														
			Inspection Company: Batta Environmental										Inspection Dates: 2/26/20 - 2/27/20				
			On-Site Room Name										ULCS#				
ULCS#	E	Space Type	Student					Primary	Substrate	Color	Description	Primary	XRF Reading	Primary	Additional Component	Substr	
6470	1	Primary	no					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meta	
6470	1	Primary	no					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meta	
6470	1	Stairs	no					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meta	
6470	1	Stairs	no					W1	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Meta	
6470	1	Stairs	no					W3	Plaster	Tan	Chipping	10	0	N/A	N/A	N/A	
6470	1	Stairs	no					W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Meta	
6470	1	Primary	no					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meta	
6470	1	Primary	no					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	no					NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	
6470	1	Primary	no					NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A	
6470	1	Storage	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Storage	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470			yes					W2	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470			yes					Floor	Concrete	Grey	Chipping	10	0.3	N/A	N/A	N/A	
6470	1	Storage	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Storage	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Storage	yes					W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470			yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470			yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470			yes					W2	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470			yes					W3	Concrete	Blue	Cracking	11	0.1	N/A	N/A	N/A	
6470			yes					W4	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Circulation	yes					W1	N/A	N/A	None	N/A	N/A	N/A	Door Frame	Meta	
6470			yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470			yes					W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Administrative	yes					W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W2	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470	1	Administrative	yes					Floor	Concrete	Grey	Chipping	10	0.1	N/A	N/A	N/A	
6470	1	Circulation	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Stairs	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Stairs	yes					W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470	1	Primary	yes					W3	Concrete	Green	Chipping	10	0	N/A	N/A	N/A	
6470			yes					W4	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470	1	Primary	yes					Floor	Concrete	Grey	Chipping	16	0.4	N/A	N/A	N/A	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Primary	yes					W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Teacher	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Circulation	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta	
6470	1	Circulation	yes					W1	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	
6470			yes					W2	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Woo	

		Lead Safe Certification											
		Name of Inspector: Charles Rhodes							Inspection Dates: 2 /26 /20 - 2 /27 /20				
		Inspection Company: Batta Environmental							ULCS#				
ULCS#	E	Space Type	On-Site Room Name	Student	Primary	Substrate	Color	Descriptio	Primary	XRF Reading	Primary	Additional Component	Substr
6470			Classroom 109	yes	W4	Concrete	Blue	Flaking	10	0.2	Negative	N/A	N/A/A
6470			Girl's Restroom across from Classroom 108	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Girl's Restroom across from Classroom 108	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metala
6470			Girl's Restroom across from Classroom 108	yes	W4	Concrete	Blue	Flaking	5	0.2	Negative	N/A	N/A/A
6470			Girl's Restroom across from Classroom 108	yes	W4	Concrete	Tan	Flaking	5	0.2	Negative	N/A	N/A
6470			Girl's Restroom across from Classroom 108	yes	Ceiling	Concrete	Tan	Flaking	10	0.1	Negative	N/A	N/A/A
6470			Girl's Restroom across from Classroom 108	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	DUCT	Metala
6470			Custodial Closet across from Classroom	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Custodial Closet across from Classroom	no	W4	Concrete	White	Flaking	5	0.1	Negative	N/A	N/A/A
6470			Boy's Restroom across from Classroom 109	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Boy's Restroom across from Classroom 109	yes	Ceiling	Concrete	White	Flaking	10	0.2	Negative	N/A	N/A/A
6470			Classroom 110	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Classroom 110	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metala
6470			Classroom 111	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Classroom 112	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Classroom 112	yes	W1	Sheetrock	Blue	Flaking	15	-0.2	Negative	N/A	N/A/A
6470			Classroom 112	yes	W2	Sheetrock	Blue	Flaking	5	0	Negative	N/A	N/A/A
6470			Classroom 112	yes	W4	Sheetrock	Blue	Flaking	10	-0.2	Negative	N/A	N/A/A
6470			Classroom 113	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Classroom 114	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Classroom 114	yes	W1	Sheetrock	White	Flaking	2	-0.2	Negative	N/A	N/A/A
6470			Classroom 114	yes	W4	Sheetrock	Blue	Flaking	5	0.1	Negative	N/A	N/A/A
6470			Classroom 114	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	COAT RACK	Woo
6470			Elevator	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Elevator Mechanical Room adjacent to	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Girl's Restroom near Elevator	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meita
6470			Girl's Restroom near Elevator	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meita
6470			Girl's Restroom near Elevator	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Meita
6470			Girl's Restroom near Elevator	yes	W4	Concrete	White	Flaking	2	0.2	Negative	N/A	N/A/A
6470			Girl's Restroom near Elevator	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	DUCT	Metala
6470			Pipe Chase between Boy's and Girl's	no	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A
6470			Boy's Restroom near Elevator	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Boy's Restroom near Elevator	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metala
6470			Boy's Restroom near Elevator	yes	Ceiling	Concrete	White	Flaking	10	0.1	Negative	N/A	N/A/A
6470			Custodial Closet across from Elevator	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Storage Room across from Classroom 114	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metala
6470			Storage Room across from Classroom 114	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metala
6470			Electrical Room by IMC	no	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A
6470			Men's Restroom near Main Lobby	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meita
6470			Men's Restroom near Main Lobby	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Urinal Divider	Meita
6470			Men's Restroom near Main Lobby Pipe	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meita
6470			Women's Restroom near Main Lobby	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meita
6470			IMC	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meita
6470			IMC	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meita
6470			IMC	yes	W2	Concrete	Blue	Flaking	2	0.1	Negative	N/A	N/A/A
6470			IMC	yes	W2	Sheetrock	Green	Flaking	5	0.1	Negative	N/A	N/A/A

Lead Safe Certification													
		Name of Inspector: Charles Rhodes								Inspection Dates: 2/26/20 - 2/27/20			
		Inspection Company: Batta Environmental								ULCS#			
ULCS#	E	Space Type	On-Site Room Name	Student	Primary	Substrate	Color	Descriptio	Primary	XRF Reading	Primary	Additional Component	Substr
6470			Classroom 205	yes	W3	Concrete	Blue	Cracking	5	-0.3	N/A	N/A	N/A/A
6470			Office 205A	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Classroom 206	yes	W1	Plaster	Pink	Chipping	5	0	N/A	Door Frame	Meta
6470			Classroom 206	yes	W2	Plaster	Pink	Chipping	1	0	N/A	N/A	N/A/A
6470			Classroom 206	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Meta
6470			Classroom 206 Closet	yes	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A
6470			Classroom 207	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meta
6470			Classroom 207	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Men's Restroom across from Classroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meta
6470			Men's Restroom across from Classroom	yes	W3	Concrete	White	Flaking	5	-0.1	N/A	Air Duct	Meta
6470			Mechanical Room behind Men's Restroom	no	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A
6470			Boy's Restroom across from Classroom 208	yes	W1	Concrete	White	Chipping	10	0.3	N/A	Door Frame	Meta
6470			Storage D	no	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A
6470			Storage D Pipe Chase	no	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A
6470			Girl's Restroom across from Classroom 209	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Girl's Restroom across from Classroom 209	yes	W2	Concrete	White	Chipping	5	-0.2	N/A	N/A	N/A/A
6470			Girl's Restroom across from Classroom 209	yes	W3	Concrete	White	Chipping	10	0	N/A	N/A	N/A/A
6470			Classroom 208	yes	W1	Concrete	Blue	Chipping	2	0.2	N/A	Door Frame	Meta
6470			Classroom 208	yes	W3	Concrete	Blue	Chipping	5	0.1	N/A	N/A	N/A/A
6470			Classroom 209	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Classroom 209	yes	W3	Concrete	Green	Chipping	5	-0.1	N/A	N/A	N/A/A
6470			Office 210A	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meta
6470			Office 210A	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Office 210A Mechanical Room	no	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A
6470			Classroom 210	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Meta
6470			Classroom 210	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Classroom 210	yes	W4	Concrete	Blue	Chipping	5	0.2	N/A	N/A	N/A/A
6470			Classroom 211	yes	W1	Concrete	Yellow	Flaking	10	0	N/A	Door Frame	Meta
6470			Classroom 211	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Classroom 211	yes	W2	Concrete	Yellow	Flaking	10	0	N/A	Radiator	Meta
6470			Classroom 211	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Coat Rack	Woo
6470			Classroom 211	yes	W4	Concrete	Yellow	Flaking	20	0.1	N/A	N/A	N/A/A
6470			Classroom 211 Closet	yes	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A
6470			Classroom 212	yes	W1	Plaster	Blue	Flaking	5	-0.2	N/A	Door Frame	Meta
6470			Classroom 212	yes	W2	Plaster	Tan	Flaking	2	0.2	N/A	N/A	N/A/A
6470			Classroom 212	yes	W3	Plaster	Tan	Flaking	5	0.1	N/A	N/A	N/A/A
6470			Classroom 212	yes	W4	Plaster	Blue	Flaking	2	-0.2	N/A	N/A	N/A/A
6470			Office 212A	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Classroom 213	yes	W1	Plaster	Purple	Flaking	10	0.2	N/A	Door Frame	Meta
6470			Classroom 213	yes	W2	Plaster	Purple	Flaking	15	0.2	N/A	N/A	N/A/A
6470			Classroom 213	yes	W4	Plaster	Purple	Flaking	10	0.1	N/A	N/A	N/A/A
6470			Office 213A	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Meta
6470			Office 213A	yes	W3	Concrete	Yellow	Chipping	10	0.2	N/A	N/A	N/A/A
6470			Classroom 214	yes	W1	Plaster	Purple	Flaking	5	0.1	N/A	Door Frame	Meta
6470			Classroom 214	yes	W2	Plaster	Purple	Flaking	5	0.1	N/A	N/A	N/A/A
6470			Classroom 214 Closet	yes	NO DAMAGE	N/A	N/A	None	N/A	N/A	N/A	N/A	N/A/A

