

Report: Lead Safe - Lead-Based Paint Assessment

Site:

**Henry W. Lawton Elementary School
6101 Jackson Street
Philadelphia, PA 19134
ULCS#: 7330**

Prepared For:

**The School District of Philadelphia
Office of Capital Programs
440 North Broad Street, "Portal C" Third Floor
Philadelphia, PA 19130**

Prepared By:

**Mr. Steven A. Vena, CIH
Viva Environmental, Health, & Safety, LLC.
806 Alter Street
Philadelphia, PA 19147**

Date(s) of Project:

August 23 & 24, 2021

Date of Report:

August 27, 2021

Project Number:

210203

TABLE OF CONTENTS

1.0 Executive Summary

2.0 Conclusions

3.0 Recommendations

Attachments

- ◆ XRF Results Spreadsheet
- ◆ Calibration Check Test Results
- ◆ Lead Safe Certificate

1.0 EXECUTIVE SUMMARY

Viva Environmental, Health, & Safety, LLC. (Viva EHS), was requested to perform a Lead-Based Paint Assessment for the purpose of obtaining a Lead Safe Certificate for Henry W. Lawton Elementary School located at 6101 Jackson Street, Philadelphia, PA 19134. The purpose of the inspection was to explore the presence and condition of painted surfaces for lead-based paint. Per the instructions given for this assessment, only surfaces that were found to be damaged were tested for their lead content.

Mr. Lionel Ray Wilson, a PA-licensed Lead Risk Assessor, from Viva EHS, performed the inspection on August 23 and 24, 2021. He was assisted on-site by Lead Technician, Erik Swanson.

Painted surfaces were analyzed for lead using an X-ray Fluorescence Spectrometer (XRF) manufactured by Thermo Scientific-NITON.

The U.S. Department of Housing and Urban Development (HUD) considers 1.0 milligrams of lead per square centimeter of painted surface, or greater, to be lead based paint ($\geq 1.0 \text{ mg/c m}^2$). However, the City of Philadelphia's Department of Public Health document entitled "Regulations Relating to Labeling, Application and Removal of Lead Paint", dated December 26, 1977, states that any paint lacquer or other applied liquid surface coating, and putty or caulking or other sealing compound with a lead content of **0.7 mg/cm² or greater, is considered "lead-based"**.

2.0 CONCLUSIONS

During the inspection, **No** lead-based paint was detected at locations where damaged paint was found throughout the school. (refer to Attachments).

The Environmental Protection Agency's (EPA) Renovation, Repair, and Painting Program Final Rule (40 CFR Part 745) (RRP Rule) mandates that if lead-based paint is disturbed during renovation or painting activity then the work should be completed using lead-safe work practices as defined in the RRP Rule. In addition, the individual disturbing the lead-based paint has to be certified as well as the firm with whom he/she is employed.

3.0 RECOMMENDATIONS

Any painted surface that has **any** concentration of lead should not be sanded, demolished or disturbed without the proper engineering controls and work methods, as spelled out under the OSHA's 29 CFR Part 1926.62 Lead Exposure in Construction, Interim Rule. Improper disturbance of any paint with lead content can cause lead to become airborne. The emphasis on controlling lead dust derives from the conclusion that lead dust appears to be the primary route of exposure to lead, especially of low-level exposure.

It is therefore important that occupants of the building and any contractors be made aware of the presence of the lead-based paint and the potential health risks associated with the ingestion of lead-based paint or the associated dust that results from the damaging of the painted surfaces.

Occupants and/or contractors should also be made aware of the importance of not damaging the painted surfaces and creating loose and flaking paint or the creation of dust. If the painted surfaces are damaged this should be reported to the proper building representative/maintenance personnel to properly correct the problem to prevent an increased exposure potential.

A summary of the locations/components where XRF readings were collected is included in the attached spreadsheet.

Within the spreadsheet, walls are labeled as “A”, “B”, “C”, or “D”. The wall that you enter the room through is labeled as “A” Wall. The walls are then labeled in a clockwise fashion as “B” Wall, “C” Wall, and “D” Wall. For hallways, the front entrance-side of the building is considered the “A” Wall.

ATTACHMENTS

				School District of Philadelphia																	
				Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21								
				LLC.	Lawton Elementary School								ULCS# 7330								
E l e m e n t	F l o o r																				
		Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	101	Classroom 101	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive							
				Yes	W1	Concrete	Blue	Chipping	5	0	Negative			Negative					HID 2612 - Lead Safe Paint Inspection - Viva EHS - RW Actual damage was on concrete wall not CMU walls. Sampled W1, W2, and W3		
1	1	101	Classroom 101																		
				Yes	W2	Concrete	Blue	Chipping	5	0.01	Negative			Negative					HID 2612 - Lead Safe Paint Inspection - Viva EHS - RW Actual damage was on concrete wall not CMU walls. Sampled W1, W2, and W3		
1	1	101	Classroom 101																		
				Yes	W3	Concrete	Blue	Chipping	5	0	Negative			Negative					HID 2612 - Lead Safe Paint Inspection - Viva EHS - RW Actual damage was on concrete wall not CMU walls. Sampled W1, W2, and W3		
1	1	101	Classroom 101																		
1	1	101	Classroom 101	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive							
1	1	101	Classroom 101	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive							
1	1	101	Classroom 101	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	102	Classroom 102	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive							
1	1	102	Classroom 102	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive							
1	1	102	Classroom 102	Yes	W3	Concrete	Blue	None	0	N/A	N/A			Negative							
1	1	102	Classroom 102	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive							
1	1	102	Classroom 102	Yes	Ceiling	Concrete	White	Moisture Damage	20	0	Negative			Positive					HID 2610 - Lead Safe Paint Inspection - Viva EHS - RW		
1	1	102	Classroom 102	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	103	Nurse's Suite	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	103	Nurse's Suite	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	103	Nurse's Suite	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	103	Nurse's Suite	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	103	Nurse's Suite	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive							
1	1	103	Nurse's Suite	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	104	Classroom 104	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	104	Classroom 104	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	104	Classroom 104	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative							
1	1	104	Classroom 104	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	104	Classroom 104	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive							
1	1	104	Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	105	Main Office	Yes	W1	CMU Block Wall	White	Missing	2	0	Negative			Positive					BE said he had to take out piece of CMU wall in order to open up window-Viva EHS		
1	1	105	Main Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	105	Main Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	105	Main Office	Yes	W4	Concrete	White	None	0	N/A	N/A			Negative							
1	1	105	Main Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive							
1	1	105	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	105A	Principal's Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	105A	Principal's Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	105A	Principal's Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	105A	Principal's Office	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	105A	Principal's Office	Yes	Ceiling	Concrete	White	Chipping	1	0	Negative			Positive							
1	1	105A	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	106	Closet accross from Main Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	106	Closet accross from Main Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	106	Closet accross from Main Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	106	Closet accross from Main Office	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive							
1	1	106	Closet accross from Main Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive							

1	1	106	Closet across from Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	101C	Classroom 101 Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
				Yes	W2	CMU Block Wall	White	Water Damage	3	0	Negative			Positive				HID 2613. Lead Safe Paint Inspection - Water damage with black color observed. Sampled 08/24/21 W2-RW
1	1	101C	Classroom 101 Closet															
1	1	101C	Classroom 101 Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	101C	Classroom 101 Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	101C	Classroom 101 Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	101C	Classroom 101 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	101A	Classroom 101 Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	101A	Classroom 101 Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	101A	Classroom 101 Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	101A	Classroom 101 Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	101A	Classroom 101 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	101A	Classroom 101 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102A	Classroom 102 Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102A	Classroom 102 Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102A	Classroom 102 Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102A	Classroom 102 Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102A	Classroom 102 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	102A	Classroom 102 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102B	Classroom 102 Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102B	Classroom 102 Closet	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102B	Classroom 102 Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102B	Classroom 102 Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102B	Classroom 102 Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	102B	Classroom 102 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102C	Stairwell adjacent to Classroom 101	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102C	Stairwell adjacent to Classroom 101	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102C	Stairwell adjacent to Classroom 101	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102C	Stairwell adjacent to Classroom 101	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102C	Stairwell adjacent to Classroom 101	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	102C	Stairwell adjacent to Classroom 101	Yes	Floor	Concrete	Grey	None	0	N/A	N/A							
1	1	H2	Hallway from Classrooms 101 to 113	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	H2	Hallway from Classrooms 101 to 113	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	H2	Hallway from Classrooms 101 to 113	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	H2	Hallway from Classrooms 101 to 113	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	H2	Hallway from Classrooms 101 to 113	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	H2	Hallway from Classrooms 101 to 113	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	H2	Hallway from Classrooms 101 to 113	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	H2	Hallway from Classrooms 101 to 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							

1	1	104A	Classroom 104 Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	104A	Classroom 104 Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	104A	Classroom 104 Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	104A	Classroom 104 Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	104A	Classroom 104 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	104A	Classroom 104 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	104B	Classroom 104 Closet	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	104B	Classroom 104 Closet	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	104B	Classroom 104 Closet	Yes	W3	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	104B	Classroom 104 Closet	Yes	W4	Concrete	Blue	None	0	N/A	N/A			Negative				
1	1	104B	Classroom 104 Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	104B	Classroom 104 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	103B	Nurse's Treatment Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103B	Nurse's Treatment Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103B	Nurse's Treatment Room	Yes	W3	Concrete	White	Chipping	1	0	Negative			Negative				
1	1	103B	Nurse's Treatment Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103B	Nurse's Treatment Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	103B	Nurse's Treatment Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	103D	Nurse's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103D	Nurse's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103D	Nurse's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103D	Nurse's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103D	Nurse's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	103D	Nurse's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	103C	Nurse's Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103C	Nurse's Closet	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103C	Nurse's Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103C	Nurse's Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	103C	Nurse's Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	103C	Nurse's Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	H7	Hallway from Offices 103 to 105	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	H7	Hallway from Offices 103 to 105	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	H7	Hallway from Offices 103 to 105	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	H7	Hallway from Offices 103 to 105	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	H7	Hallway from Offices 103 to 105	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	H7	Hallway from Offices 103 to 105	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	H7	Hallway from Offices 103 to 105	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	H7	Hallway from Offices 103 to 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105F	Principal's Restroom	Yes	W1	CMU Block Wall	Pink	None	0	N/A	N/A			Positive				
1	1	105F	Principal's Restroom	Yes	W2	CMU Block Wall	Pink	None	0	N/A	N/A			Positive				
1	1	105F	Principal's Restroom	Yes	W3	CMU Block Wall	Pink	None	0	N/A	N/A			Positive				
1	1	105F	Principal's Restroom	Yes	W4	CMU Block Wall	Pink	None	0	N/A	N/A			Positive				
1	1	105F	Principal's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	105F	Principal's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105E	Principal's Closet	Yes	W1	CMU Block Wall	Yellow	None	0	N/A	N/A			Positive				

1	1	105E	Principal's Closet	Yes	W2	CMU Block Wall	Yellow	None	0	N/A	N/A			Positive					
1	1	105E	Principal's Closet	Yes	W3	CMU Block Wall	Yellow	None	0	N/A	N/A			Positive					
1	1	105E	Principal's Closet	Yes	W4	CMU Block Wall	Yellow	None	0	N/A	N/A			Positive					
1	1	105E	Principal's Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	105E	Principal's Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106A	Elevator Machinery Room	Yes	W1	CMU Block Wall	Unpainted	None	0	N/A	N/A			Positive					
1	1	106A	Elevator Machinery Room	Yes	W2	CMU Block Wall	Unpainted	None	0	N/A	N/A			Positive					
1	1	106A	Elevator Machinery Room	Yes	W3	CMU Block Wall	Unpainted	None	0	N/A	N/A			Positive					
1	1	106A	Elevator Machinery Room	Yes	W4	CMU Block Wall	Unpainted	None	0	N/A	N/A			Positive					
1	1	106A	Elevator Machinery Room	Yes	Ceiling	Concrete	Unpainted	None	0	N/A	N/A								
1	1	106A	Elevator Machinery Room	Yes	Floor	Concrete	Unpainted	None	0	N/A	N/A								
1	1	106B	Custodial Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	106B	Custodial Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	106B	Custodial Room	Yes	W3	CMU Block Wall	White	Chipping	2	0.02	Negative			Positive					
1	1	106B	Custodial Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	106B	Custodial Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	106B	Custodial Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106B	Custodial Room	Yes	Piping	Metal	White	Chipping	3	0.19	Negative								
1	1	108	Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	108	Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	108	Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	108	Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	108	Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	108	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	108A	Women's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	108A	Women's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	108A	Women's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	108A	Women's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	108A	Women's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	108A	Women's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	110	Boy's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	110	Boy's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	110	Boy's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	110	Boy's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	110	Boy's Restroom	Yes	Ceiling	Concrete	White	Chipping	2	0	Negative			Positive					
1	1	110	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	110	Boy's Restroom	Yes	Duct Work	Metal	White	Chipping	1	0	Negative								
1	1	110A	Men's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	110A	Men's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	110A	Men's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	110A	Men's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	110A	Men's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	110A	Men's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	112G	Electrical Room	Yes	W1	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	112G	Electrical Room	Yes	W2	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	112G	Electrical Room	Yes	W3	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	112G	Electrical Room	Yes	W4	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	112G	Electrical Room	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	112G	Electrical Room	Yes	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	H5	Hallway between Main Office and Classroom 107	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	H5	Hallway between Main Office and Classroom 107	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	H5	Hallway between Main Office and Classroom 107	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	H5	Hallway between Main Office and Classroom 107	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								

1	1	H5	Hallway between Main Office and Classroom 107	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	H5	Hallway between Main Office and Classroom 107	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	H5	Hallway between Main Office and Classroom 107	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	H5	Hallway between Main Office and Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	S12	Stairwell adjacent to Classroom 109	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	S12	Stairwell adjacent to Classroom 109	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	S12	Stairwell adjacent to Classroom 109	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	S12	Stairwell adjacent to Classroom 109	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	S12	Stairwell adjacent to Classroom 109	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	S12	Stairwell adjacent to Classroom 109	Yes	Floor	Concrete	Grey	Chipping	2	0	Negative							
1	1	113	Classroom 109	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	113	Classroom 109	Yes	W2	Concrete	White	Chipping	2	0	Negative			Negative				
1	1	113	Classroom 109	Yes	W3	Concrete	White	Chipping	3	0.01	Negative			Negative				
1	1	113	Classroom 109	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	113	Classroom 109	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	113	Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	111	Classroom 107	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	111	Classroom 107	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	111	Classroom 107	Yes	W3	Concrete	White	Chipping	1	0	Negative			Negative				
1	1	111	Classroom 107	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	111	Classroom 107	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	111	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	111	Classroom 107	Yes	Lockers	Metal	Blue	Chipping	2	0	Negative							
1	1	109	Classroom 105	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	109	Classroom 105	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	109	Classroom 105	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative				
1	1	109	Classroom 105	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	109	Classroom 105	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	109	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	107	Classroom 103	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	107	Classroom 103	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	107	Classroom 103	Yes	W3	Concrete	White	Chipping	5	0	Negative			Negative				
1	1	107	Classroom 103	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	107	Classroom 103	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	107	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105B	School Counselor Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	105B	School Counselor Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	105B	School Counselor Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	105B	School Counselor Office	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	105B	School Counselor Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	105B	School Counselor Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105C	Main Office Mail Room	Yes	W1	CMU Block Wall	Purple	None	0	N/A	N/A			Positive				
1	1	105C	Main Office Mail Room	Yes	W2	CMU Block Wall	Purple	None	0	N/A	N/A			Positive				
1	1	105C	Main Office Mail Room	Yes	W3	CMU Block Wall	Purple	None	0	N/A	N/A			Positive				
1	1	105C	Main Office Mail Room	Yes	W4	CMU Block Wall	Purple	None	0	N/A	N/A			Positive				
1	1	105C	Main Office Mail Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	105C	Main Office Mail Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	105D	Server Room	Yes	W1	CMU Block Wall	Purple	None	0	N/A	N/A			Positive				
1	1	105D	Server Room	Yes	W2	CMU Block Wall	Purple	None	0	N/A	N/A			Positive				
1	1	105D	Server Room	Yes	W3	CMU Block Wall	Purple	None	0	N/A	N/A			Positive				
1	1	105D	Server Room	Yes	W4	CMU Block Wall	Purple	None	0	N/A	N/A			Positive				
1	1	105D	Server Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	105D	Server Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	115	Cafetorium	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	115	Cafetorium	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				

1	1	115	Cafetorium	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115	Cafetorium	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115	Cafetorium	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	115	Cafetorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	115A	Stage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115A	Stage	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115A	Stage	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115A	Stage	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115A	Stage	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	115A	Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	115B	Cafetorium Fan Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115B	Cafetorium Fan Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115B	Cafetorium Fan Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115B	Cafetorium Fan Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115B	Cafetorium Fan Room	Yes	Ceiling	Unpainted	Unpainted	None	N/A	N/A	N/A								
1	1	115B	Cafetorium Fan Room	Yes	Floor	Unpainted	Unpainted	None	N/A	N/A	N/A								
1	1	115B	Cafetorium Fan Room	Yes	Piping	Metal	Black	Chipping	1	0	Negative								
1	1	115C	Kitchen	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115C	Kitchen	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115C	Kitchen	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115C	Kitchen	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115C	Kitchen	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	115C	Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	115D	Kitchen Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115D	Kitchen Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115D	Kitchen Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115D	Kitchen Office	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115D	Kitchen Office	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	115D	Kitchen Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	115E	Kitchen Storage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115E	Kitchen Storage	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115E	Kitchen Storage	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115E	Kitchen Storage	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115E	Kitchen Storage	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	115E	Kitchen Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	1115F	Staff Locker	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	1115F	Staff Locker	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	1115F	Staff Locker	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	1115F	Staff Locker	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	1115F	Staff Locker	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	1115F	Staff Locker	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	115G	Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115G	Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115G	Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115G	Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115G	Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	115G	Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	115H	Food Storage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115H	Food Storage	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115H	Food Storage	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115H	Food Storage	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115H	Food Storage	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	115H	Food Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	115I	Kitchen Loading	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115I	Kitchen Loading	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115I	Kitchen Loading	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115I	Kitchen Loading	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	115I	Kitchen Loading	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	115I	Kitchen Loading	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	112D	Building Engineer's Storage Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	112D	Building Engineer's Storage Room	No	W2	CMU Block Wall	White	Chipping	2	0.03	Negative			Positive					
1	1	112D	Building Engineer's Storage Room	No	W3	CMU Block Wall	White	Chipping	4	0.01	Negative			Positive					

1	1	112D	Building Engineer's Storage Room	No	W4	CMU Block Wall	White	Chipping	4	0.03	Negative			Positive				
1	1	112D	Building Engineer's Storage Room	No	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	112D	Building Engineer's Storage Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112E	Mechanical Room	No	W1	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive				
1	1	112E	Mechanical Room	No	W2	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive				
1	1	112E	Mechanical Room	No	W3	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive				
1	1	112E	Mechanical Room	No	W4	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive				
1	1	112E	Mechanical Room	No	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	112E	Mechanical Room	No	Floor	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	112C	Staff Restroom	No	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112C	Staff Restroom	No	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112C	Staff Restroom	No	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112C	Staff Restroom	No	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112C	Staff Restroom	No	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	112C	Staff Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112B	Building Engineer's Restroom	No	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112B	Building Engineer's Restroom	No	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112B	Building Engineer's Restroom	No	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112B	Building Engineer's Restroom	No	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112B	Building Engineer's Restroom	No	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	112B	Building Engineer's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112A	Staff Locker Room	No	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112A	Staff Locker Room	No	W2	CMU Block Wall	White	Chipping	2	0.03	Negative			Positive				
1	1	112A	Staff Locker Room	No	W3	CMU Block Wall	White	Chipping	2	0.02	Negative			Positive				
1	1	112A	Staff Locker Room	No	W4	CMU Block Wall	White	Chipping	2	0.03	Negative			Positive				
1	1	112A	Staff Locker Room	No	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	112A	Staff Locker Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112	Building Engineer's Office	No	W1	CMU Block Wall	White	Chipping	2	0.01	Negative			Positive				
1	1	112	Building Engineer's Office	No	W2	CMU Block Wall	White	Chipping	2	0.02	Negative			Positive				
1	1	112	Building Engineer's Office	No	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112	Building Engineer's Office	No	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	112	Building Engineer's Office	No	Ceiling	Concrete	White	Efflorescence	2	0.01	Negative	Under pipe run & clean	1	Positive				
1	1	112	Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112	Building Engineer's Office	No	Piping	Metal	White	Chipping	1	0.14	Negative							
1	1	114	Classroom 106	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	114	Classroom 106	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	114	Classroom 106	Yes	W3	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	114	Classroom 106	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	1	114	Classroom 106	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	1	114	Classroom 106	Yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	114	Classroom 114	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	114	Classroom 114	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	114	Classroom 114	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	114	Classroom 114	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	114	Classroom 114	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	114	Classroom 114	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	101	Electrical Room	Yes	W1	Unpainted	N/A	N/A	N/A	N/A	N/A							
1	1	101	Electrical Room	Yes	W2	Unpainted	N/A	N/A	N/A	N/A	N/A							
1	1	101	Electrical Room	Yes	W3	Unpainted	N/A	N/A	N/A	N/A	N/A							
1	1	101	Electrical Room	Yes	W4	Unpainted	N/A	N/A	N/A	N/A	N/A							
1	1	101	Electrical Room	Yes	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A							
1	1	101	Electrical Room	Yes	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A							
1	1	102	Custodial Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102	Custodial Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	1	102	Custodial Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				

1	1	102	Custodial Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	102	Custodial Room	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	102	Custodial Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	112	Classroom 112	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	112	Classroom 112	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	112	Classroom 112	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	112	Classroom 112	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	112	Classroom 112	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	112	Classroom 112	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	123	Classroom 123	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	123	Classroom 123	Yes	W2	CMU Block Wall	White	Chipping	1	0	Negative		Positive					
1	1	123	Classroom 123	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	123	Classroom 123	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	123	Classroom 123	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	123	Classroom 123	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	121	Classroom 121	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	121	Classroom 121	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	121	Classroom 121	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	121	Classroom 121	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	121	Classroom 121	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	121	Classroom 121	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	119	Classroom 119	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	119	Classroom 119	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	119	Classroom 119	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	119	Classroom 119	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	119	Classroom 119	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							Moisture damage on ceiling tile. BE aware of damage-Viva EHS
1	1	119	Classroom 119	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	117	Classroom 117	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	117	Classroom 117	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	117	Classroom 117	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	117	Classroom 117	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	117	Classroom 117	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	117	Classroom 117	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	117	Classroom 117	Yes	Door Casing	Metal	Blue	Chipping	2	0	Negative							
1	1	110	Classroom 110	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	110	Classroom 110	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	110	Classroom 110	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	110	Classroom 110	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	110	Classroom 110	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	110	Classroom 110	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	115	Classroom 115	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	115	Classroom 115	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	115	Classroom 115	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	115	Classroom 115	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	115	Classroom 115	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	115	Classroom 115	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	108	Classroom 108	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	108	Classroom 108	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	108	Classroom 108	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	108	Classroom 108	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	108	Classroom 108	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	108	Classroom 108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	113	Classroom 113	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	113	Classroom 113	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	113	Classroom 113	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	113	Classroom 113	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	113	Classroom 113	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	113	Classroom 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	111	Classroom 111	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	111	Classroom 111	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	111	Classroom 111	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	111	Classroom 111	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	111	Classroom 111	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	111	Classroom 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	1	100	Table Storage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	100	Table Storage	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	100	Table Storage	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	100	Table Storage	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A		Positive					
1	1	100	Table Storage	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	1	100	Table Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							

1	1	104	Boy's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	104	Boy's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	104	Boy's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	104	Boy's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	104	Boy's Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	104	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	105	Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	105	Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	105	Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	105	Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	105	Girl's Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	105	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	114A	Classroom 106 Bathroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	114A	Classroom 106 Bathroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	114A	Classroom 106 Bathroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	114A	Classroom 106 Bathroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	114A	Classroom 106 Bathroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	114A	Classroom 106 Bathroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	S11	Stairwell adjacent to Classroom 106	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	S11	Stairwell adjacent to Classroom 106	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	S11	Stairwell adjacent to Classroom 106	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	S11	Stairwell adjacent to Classroom 106	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	S11	Stairwell adjacent to Classroom 106	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	S11	Stairwell adjacent to Classroom 106	Yes	Floor	Concrete	Grey	Chipping	2	0	Negative								
1	1	H6	Small Hallway adjacent Cafetorium	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	H6	Small Hallway adjacent Cafetorium	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	H6	Small Hallway adjacent Cafetorium	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	H6	Small Hallway adjacent Cafetorium	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	H6	Small Hallway adjacent Cafetorium	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	H6	Small Hallway adjacent Cafetorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	116	Gymnasium	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116	Gymnasium	Yes	W2	Concrete	White	None	0	N/A	N/A			Negative					
1	1	116	Gymnasium	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative					
1	1	116	Gymnasium	Yes	W4	Concrete	White	None	0	N/A	N/A			Negative					
1	1	116	Gymnasium	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	1	116	Gymnasium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	116	Gymnasium	Yes	Piping	Metal	White	Chipping	1	0.2	Negative								
1	1	116	Gymnasium	Yes	Piping	Metal	Black	Chipping	1	0	Negative								
1	1	116F	Closet adjacent to Gymnasium	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116F	Closet adjacent to Gymnasium	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116F	Closet adjacent to Gymnasium	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116F	Closet adjacent to Gymnasium	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116F	Closet adjacent to Gymnasium	Yes	Ceiling	Concrete	White	Chipping	2	0	Negative			Positive					
1	1	116F	Closet adjacent to Gymnasium	Yes	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	116G	Teacher's Lunch Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					

1	1	116G	Teacher's Lunch Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116G	Teacher's Lunch Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116G	Teacher's Lunch Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116G	Teacher's Lunch Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	116G	Teacher's Lunch Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	116E	Boy's Locker Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116E	Boy's Locker Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116E	Boy's Locker Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116E	Boy's Locker Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116E	Boy's Locker Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	116E	Boy's Locker Room	Yes	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	116A	Gym Storage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116A	Gym Storage	Yes	W2	Concrete	White	None	0	N/A	N/A			Negative					
1	1	116A	Gym Storage	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative					
1	1	116A	Gym Storage	Yes	W4	Concrete	White	None	0	N/A	N/A			Negative					
1	1	116A	Gym Storage	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	116A	Gym Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	116B	Coach's Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116B	Coach's Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116B	Coach's Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116B	Coach's Office	Yes	W4	CMU Block Wall	White	Chipping	1	0	Negative			Positive					
1	1	116B	Coach's Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	116B	Coach's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	116C	Coach's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116C	Coach's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116C	Coach's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116C	Coach's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116C	Coach's Restroom	Yes	Ceiling	Concrete	White	Chipping	2	0	Negative			Positive					
1	1	116C	Coach's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	116D	Girl's Locker Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116D	Girl's Locker Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116D	Girl's Locker Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116D	Girl's Locker Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	116D	Girl's Locker Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	116D	Girl's Locker Room	Yes	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	H1	Hallway from Cafetorium to Gymnasium	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	H1	Hallway from Cafetorium to Gymnasium	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	H1	Hallway from Cafetorium to Gymnasium	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	H1	Hallway from Cafetorium to Gymnasium	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	H1	Hallway from Cafetorium to Gymnasium	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	H1	Hallway from Cafetorium to Gymnasium	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	H1	Hallway from Cafetorium to Gymnasium	Yes	Ceiling	Concrete	Unpainted	None	0	N/A	N/A								
1	1	H1	Hallway from Cafetorium to Gymnasium	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A								
1	1	H3	Hallway from IMC to Classroom 216	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	H3	Hallway from IMC to Classroom 216	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	H3	Hallway from IMC to Classroom 216	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	H3	Hallway from IMC to Classroom 216	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	H3	Hallway from IMC to Classroom 216	Yes	Ceiling	Concrete	Unpainted	None	0	N/A	N/A								
1	1	H3	Hallway from IMC to Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	201	Classroom 201	Yes	W1	Wood Partition	Blue	None	0	N/A	N/A								
1	2	201	Classroom 201	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					HID 2614. Lead Safe Paint Inspection - Sampled 08/24/21-RW

1	2	201	Classroom 201	Yes	W3	Concrete	Blue	None	0	N/A	N/A			Negative					HID 2614. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	201	Classroom 201	Yes	W4	Concrete	Blue	None	0	N/A	N/A			Negative					HID 2614. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	201	Classroom 201	Yes	Ceiling	Concrete	White	Chipping	1	0.01	Negative			Positive					
1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	203	Classroom 203	Yes	W1	CMU Block Wall	Blue	Chipping	2	0.05	Negative			Positive					
1	2	203	Classroom 203	Yes	W2	Wood Partition	Blue	None	0	N/A	N/A								
1	2	203	Classroom 203	Yes	W3	Concrete	Blue	Chipping	5	0.01	Negative			Negative					
1	2	203	Classroom 203	Yes	W4	Wood Partition	Blue	None	0	N/A	N/A								
1	2	203	Classroom 203	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	205	Classroom 205	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	205	Classroom 205	Yes	W2	Wood Partition	Blue	None	0	N/A	N/A								
1	2	205	Classroom 205	Yes	W3	Concrete	Blue	None	0	N/A	N/A			Negative					
1	2	205	Classroom 205	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	205	Classroom 205	Yes	Ceiling	Concrete	White	Chipping	4	0.01	Negative			Positive					HID 2611. Lead Safe Paint Inspection - Water damage observed. Sampled 08/24/21-RW
1	2	205	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	205	Classroom 205	Yes	Piping	Metal	Blue	Chipping	1	0.17	Negative								
1	2	207	Science Lab	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	207	Science Lab	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	207	Science Lab	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative					
1	2	207	Science Lab	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	207	Science Lab	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	207	Science Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211	Art Lab	Yes	W1	CMU Block Wall	White	Chipping	1	0.02	Negative			Positive					
1	2	211	Art Lab	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	211	Art Lab	Yes	W3	Concrete	White	Chipping	1	0	Negative			Negative					
1	2	211	Art Lab	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	211	Art Lab	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	211	Art Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	211	Classroom 211	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	211	Classroom 211	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	211	Classroom 211	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	211	Classroom 211	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	211	Classroom 211	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	2	211	Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	213	Computer Lab	Yes	W1	CMU Block Wall	White	Chipping	1	0.02	Negative			Positive					
1	2	213	Computer Lab	Yes	W2	CMU Block Wall	White	Chipping	2	0.06	Negative			Positive					
1	2	213	Computer Lab	Yes	W3	Concrete	White	Chipping	3	0.03	Negative			Negative					
1	2	213	Computer Lab	Yes	W4	Concrete	White	None	0	0	Negative			Negative					
1	2	213	Computer Lab	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	213	Computer Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	213	Classroom 213	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	213	Classroom 213	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	213	Classroom 213	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	213	Classroom 213	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	213	Classroom 213	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A								
1	2	213	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	S22	Stairwell adjacent to Computer Lab	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	S22	Stairwell adjacent to Computer Lab	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	S22	Stairwell adjacent to Computer Lab	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	S22	Stairwell adjacent to Computer Lab	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	S22	Stairwell adjacent to Computer Lab	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	2	S22	Stairwell adjacent to Computer Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	H4	Hallway from Classrooms 201 to 215	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	H4	Hallway from Classrooms 201 to 215	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	H4	Hallway from Classrooms 201 to 215	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	H4	Hallway from Classrooms 201 to 215	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								

1	2	H4	Hallway from Classrooms 201 to 215	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	H4	Hallway from Classrooms 201 to 215	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	2	H4	Hallway from Classrooms 201 to 215	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	H4	Hallway from Classrooms 201 to 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	S23	Stairwell adjacent to Classroom 201	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	S23	Stairwell adjacent to Classroom 201	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	S23	Stairwell adjacent to Classroom 201	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	S23	Stairwell adjacent to Classroom 201	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	S23	Stairwell adjacent to Classroom 201	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	S23	Stairwell adjacent to Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	200	Technical Equipment(Currently psychologist office)	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	200	Technical Equipment(Currently psychologist office)	Yes	W2	CMU Block Wall	White	None	0	0	Negative			Positive				
1	2	200	Technical Equipment(Currently psychologist office)	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	200	Technical Equipment(Currently psychologist office)	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	200	Technical Equipment(Currently psychologist office)	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	2	200	Technical Equipment(Currently psychologist office)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	200A	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	200	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	W2	CMU Block Wall	White	None	0	0	Negative			Positive				
1	2	200	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	200	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	200	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	2	200	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	202	Classroom 202	Yes	W1	Wood Partition	Blue	None	0	N/A	N/A							
1	2	202	Classroom 202	Yes	W2	Concrete	Blue	None	0	N/A	N/A			Negative				HID 2615. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	202	Classroom 202	Yes	W3	Concrete	Blue	None	0	N/A	N/A			Negative				HID 2615. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	202	Classroom 202	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				HID 2615. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	202	Classroom 202	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	204	Classroom 204	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	2	204	Classroom 204	Yes	W2	Wood Partition	Blue	None	0	N/A	N/A							
1	2	204	Classroom 204	Yes	W3	Concrete	Blue	Chipping	3	0	Negative			Negative				
1	2	204	Classroom 204	Yes	W4	Wood Partition	Blue	None	0	N/A	N/A							
1	2	204	Classroom 204	Yes	Ceiling	Concrete	White	Chipping	4	0.01	Negative			Positive				
1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	204	Classroom 204	Yes	Piping	Metal	Blue	Chipping	1	0.18	Negative							
1	2	204	Boy's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	204	Boy's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	204	Boy's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	204	Boy's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				

1	2	204	Boy's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	204	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	205	Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	205	Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	205	Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	205	Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	205	Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	205	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	206	Classroom 206	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	206	Classroom 206	Yes	W2	CMU Block Wall	White	None	0	0	Negative			Positive				
1	2	206	Classroom 206	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative				
1	2	206	Classroom 206	Yes	W4	Wood Partition	Blue	None	0	N/A	N/A							
1	2	206	Classroom 206	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	206	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	207	Classroom 207	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	207	Classroom 207	Yes	W2	CMU Block Wall	White	None	0	0	Negative			Positive				
1	2	207	Classroom 207	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	207	Classroom 207	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	207	Classroom 207	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	2	207	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	208	Classroom 208	Yes	W1	CMU Block Wall	Blue	Chipping	1	0.01	Negative			Positive				
1	2	208	Classroom 208	Yes	W2	CMU Block Wall	Blue	None	0	0	Negative			Positive				
1	2	208	Classroom 208	Yes	W3	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	2	208	Classroom 208	Yes	W3	Concrete	Blue	Chipping	1	0.01	Negative			Negative				
1	2	208	Classroom 208	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive				
1	2	208	Classroom 208	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	208	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	209	Classroom 209	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	209	Classroom 209	Yes	W2	CMU Block Wall	White	Chipping	2	0	Negative			Positive				
1	2	209	Classroom 209	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	209	Classroom 209	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	209	Classroom 209	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A							
1	2	209	Classroom 209	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	210	Closet 210	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	210	Closet 210	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	210	Closet 210	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	210	Closet 210	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	210	Closet 210	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	210	Closet 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	212A	Staff Restroom adjacent Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	212A	Staff Restroom adjacent to Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent to Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent to Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent to Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent to Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	212A	Staff Restroom adjacent to Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							
1	2	216	Office 212	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	216	Office 212	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	216	Office 212	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive				
1	2	216	Office 212	Yes	W4	CMU Block Wall	White	Chipping	2	0	Negative			Positive				
1	2	216	Office 212	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive				
1	2	216	Office 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A							

1	2	216	Office 212	Yes	Piping	Metal	White	Chipping	2	0.07	Negative								
1	2	218	Classroom 214	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	218	Classroom 214	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	218	Classroom 214	Yes	W3	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	218	Classroom 214	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	218	Classroom 214	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	218	Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217A	IMC (Library) Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217A	IMC (Library) Closet	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217A	IMC (Library) Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217A	IMC (Library) Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217A	IMC (Library) Closet	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	2	217A	IMC (Library) Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217B	IMC (Library) Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217B	IMC (Library) Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217B	IMC (Library) Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217B	IMC (Library) Office	Yes	W4	Concrete	White	None	0	N/A	N/A			Negative					
1	2	217B	IMC (Library) Office	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	2	217B	IMC (Library) Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	217	IMC (Library)	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217	IMC (Library)	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217	IMC (Library)	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative					
1	2	217	IMC (Library)	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	217	IMC (Library)	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	2	217	IMC (Library)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	CS	C	Crawlspace- Gym Storage	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit-Viva EHS-RW
1	CS	C	Crawlspace- Gym Storage	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit-Viva EHS-RW
1	CS	C	Crawlspace- Gym Storage	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit-Viva EHS-RW
1	CS	C	Crawlspace- Gym Storage	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit-Viva EHS-RW
1	CS	C	Crawlspace- Gym Storage	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit-Viva EHS-RW
1	CS	C	Crawlspace- Gym Storage	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit-Viva EHS-RW
1	AT	A	Attic	No	W1	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	A	Attic	No	W2	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	A	Attic	No	W3	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	A	Attic	No	W4	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	A	Attic	No	Ceiling	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	A	Attic	No	Floor	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	1	PORTA BLE1	Portable closest to Jackson Street	No	W1	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE1	Portable closest to Jackson Street	No	W2	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE1	Portable closest to Jackson Street	No	W3	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE1	Portable closest to Jackson Street	No	W4	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE1	Portable closest to Jackson Street	No	Ceiling	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE1	Portable closest to Jackson Street	No	Floor	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE2	Portable closest to Ditman Street	No	W1	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE2	Portable closest to Ditman Street	No	W2	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE2	Portable closest to Ditman Street	No	W3	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE2	Portable closest to Ditman Street	No	W4	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE2	Portable closest to Ditman Street	No	Ceiling	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	PORTA BLE2	Portable closest to Ditman Street	No	Floor	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW



EHS

Calibration Check Test Results

Client: SDP

Address: 6101 Jackson St Phila PA 19135

Date: 08/23/21

XRF Serial #: 112574

Project Number: 210203

Inspector: Lionel Ray Wilson

Inspector Signature: Lionel Ray Wilson

Lead Paint Standards Surface Lead mg/cm ²	Start of Job		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	1 st Calibration Check							
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0.00	4	0.00	7	0.00		
1.04 ± 0.06	2	1.00	5	1.10	8	1.10		
0.71 ± 0.08	3	0.79	6	0.69	9	0.79		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	387.9							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



Calibration Check Test Results

Client: SDP
Address: 6101 Jackson St Phila PA 19135
Henry Lawton ES
Date: 08/24/21 XRF Serial #: 112574
Project Number: 210203
Inspector: Lionel Ray Wilson
Inspector Signature: Lionel Ray Wilson

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0.0	4	0.0	7	0.0		
1.04 ± 0.06	2	1.00	5	1.10	8	1.10		
0.71 ± 0.08	3	0.79	6	0.70	9	0.70		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	385.5							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



**Philadelphia Department of Public Health
Certification of School Lead Safe Status**

By signing this certificate, I confirm that I have done a visual inspection of the areas where children have access, including contact surfaces where children store their equipment or materials, and confirm these areas do not have deteriorated lead-based paint. A certified risk assessor or lead dust sampling technician completed verification wipe tests in accordance with the EPA's RRP guidelines and confirms they meet the EPA's cleanliness standard. A certified risk assessor or lead dust sampling technician collected interior dust wipe samples in compliance with EPA regulations in work areas and confirms they did not contain lead contaminated dust in excess of EPA dust lead standards in Pre-K, Kindergarten, and 1st Grade classrooms as well as the restrooms, offices, cafeterias, gymnasiums, and auditoriums these children routinely occupy. This certificate is valid for 4 years from date of verification.

Henry W. Lawton Elementary School, 6101 Jackson Street, Philadelphia, PA 19134, ULCS#: 7330

School Name

Street Address

Viva Environmental, Health, & Safety, LLC.

Lionel Ray Wilson - PA Risk Assessor Lic. # - 006672

Certifying Company (print)

Risk Assessor, Lead Inspector PA Lic. #, EPA Firm Certification or Lead Dust Sampling Technician Certification #

Ray Wilson

08/24/2021

Inspector/Risk Assessor or Dust Wipe Sampling Technician Name (Signature)

Date of Verification

Stephen Link, 215.400.5768, slink@philasd.org

School Official Name, Telephone and E-mail Address

Please note: A visual inspection of the areas listed above has been completed by a certified risk assessor and no damage to Lead Based Painted surfaces was observed. Therefore, no verification wipe samples were completed. This school will be reassessed within 4 years of this certification.