

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	Classroom 101	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 101	Yes	W1	Concrete	Blue	Chipping	5	0	Negative								HID 2612 - Lead Safe Paint Inspection - Viva EHS - RW Actual damage was on concrete wall not CMU walls. Sampled W1, W2, and W3
1	1	Classroom 101	Yes	W2	Concrete	Blue	Chipping	5	0.01	Negative								HID 2612 - Lead Safe Paint Inspection - Viva EHS - RW Actual damage was on concrete wall not CMU walls. Sampled W1, W2, and W3
1	1	Classroom 101	Yes	W3	Concrete	Blue	Chipping	5	0	Negative								HID 2612 - Lead Safe Paint Inspection - Viva EHS - RW Actual damage was on concrete wall not CMU walls. Sampled W1, W2, and W3
1	1	Classroom 101	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 101	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 102	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 102	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 102	Yes	W3	Concrete	Blue	None	0	N/A	N/A								
1	1	Classroom 102	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 102	Yes	Ceiling	Concrete	White	Moisture Damage	20	0	Negative			Positive					HID 2610 - Lead Safe Paint Inspection - Viva EHS - RW
1	1	Classroom 102	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Nurse's Suite	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Suite	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Suite	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Suite	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Suite	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Suite	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 104	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104	Yes	W3	Concrete	White	None	0	N/A	N/A								
1	1	Classroom 104	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Main Office	Yes	W1	CMU Block Wall	White	Missing	2	0	Negative			Positive					BE said he had to take out piece of CMU wall in order to open up window-Viva EHS
1	1	Main Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Main Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Main Office	Yes	W4	Concrete	White	None	0	N/A	N/A								
1	1	Main Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Principal's Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Principal's Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Principal's Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Principal's Office	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Principal's Office	Yes	Ceiling	Concrete	White	Chipping	1	0	Negative			Positive					
1	1	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Closet accross from Main Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Closet accross from Main Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Closet accross from Main Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Closet accross from Main Office	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Closet accross from Main Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Closet accross from Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 101 Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101 Closet	Yes	W2	CMU Block Wall	White	Water Damage	3	0	Negative			Positive					HID 2613. Lead Safe Paint Inspection - Water damage with black color observed. Sampled 08/24/21 W2-RW
1	1	Classroom 101 Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101 Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101 Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 101 Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101 Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101 Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101 Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 101 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	Classroom 101 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 102 Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 102 Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Closet	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 102 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Stairwell adjacent to Classroom 101	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 101	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 101	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 101	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 101	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Stairwell adjacent to Classroom 101	Yes	Floor	Concrete	Grey	None	0	N/A	N/A								
1	1	Hallway from Classrooms 101 to 113	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from Classrooms 101 to 113	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Hallway from Classrooms 101 to 113	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway from Classrooms 101 to 113	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from Classrooms 101 to 113	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Hallway from Classrooms 101 to 113	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway from Classrooms 101 to 113	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Hallway from Classrooms 101 to 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 104 Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 104 Closet	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Closet	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Closet	Yes	W3	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Closet	Yes	W4	Concrete	Blue	None	0	N/A	N/A								
1	1	Classroom 104 Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 104 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Nurse's Treatment Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Treatment Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Treatment Room	Yes	W3	Concrete	White	Chipping	1	0	Negative								
1	1	Nurse's Treatment Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Treatment Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Treatment Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Nurse's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Nurse's Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Closet	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	Nurse's Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Nurse's Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from Offices 103 to 105	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from Offices 103 to 105	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Hallway from Offices 103 to 105	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway from Offices 103 to 105	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from Offices 103 to 105	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Hallway from Offices 103 to 105	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway from Offices 103 to 105	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Hallway from Offices 103 to 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Principal's Restroom	Yes	W1	CMU Block Wall	Pink	None	0	N/A	N/A			Positive					
1	1	Principal's Restroom	Yes	W2	CMU Block Wall	Pink	None	0	N/A	N/A			Positive					
1	1	Principal's Restroom	Yes	W3	CMU Block Wall	Pink	None	0	N/A	N/A			Positive					
1	1	Principal's Restroom	Yes	W4	CMU Block Wall	Pink	None	0	N/A	N/A			Positive					
1	1	Principal's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Principal's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Principal's Closet	Yes	W1	CMU Block Wall	Yellow	None	0	N/A	N/A			Positive					
1	1	Principal's Closet	Yes	W2	CMU Block Wall	Yellow	None	0	N/A	N/A			Positive					
1	1	Principal's Closet	Yes	W3	CMU Block Wall	Yellow	None	0	N/A	N/A			Positive					
1	1	Principal's Closet	Yes	W4	CMU Block Wall	Yellow	None	0	N/A	N/A			Positive					
1	1	Principal's Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Principal's Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Elevator Machinery Room	Yes	W1	CMU Block Wall	Unpainted	None	0	N/A	N/A			Positive					
1	1	Elevator Machinery Room	Yes	W2	CMU Block Wall	Unpainted	None	0	N/A	N/A			Positive					
1	1	Elevator Machinery Room	Yes	W3	CMU Block Wall	Unpainted	None	0	N/A	N/A			Positive					
1	1	Elevator Machinery Room	Yes	W4	CMU Block Wall	Unpainted	None	0	N/A	N/A			Positive					
1	1	Elevator Machinery Room	Yes	Ceiling	Concrete	Unpainted	None	0	N/A	N/A			Positive					
1	1	Elevator Machinery Room	Yes	Floor	Concrete	Unpainted	None	0	N/A	N/A								
1	1	Custodial Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Custodial Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Custodial Room	Yes	W3	CMU Block Wall	White	Chipping	2	0.02	Negative			Positive					
1	1	Custodial Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Custodial Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Custodial Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Custodial Room	Yes	Piping	Metal	White	Chipping	3	0.19	Negative								
1	1	Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Women's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Women's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Women's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Women's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Women's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Women's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Boy's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	Ceiling	Concrete	White	Chipping	2	0	Negative			Positive					
1	1	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Boy's Restroom	Yes	Duct Work	Metal	White	Chipping	1	0	Negative								
1	1	Men's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Men's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Men's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Men's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Men's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	Men's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Electrical Room	Yes	W1	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Electrical Room	Yes	W2	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Electrical Room	Yes	W3	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Electrical Room	Yes	W4	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Electrical Room	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Electrical Room	Yes	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	Hallway between Main Office and Classroom 107	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway between Main Office and Classroom 107	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Hallway between Main Office and Classroom 107	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway between Main Office and Classroom 107	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway between Main Office and Classroom 107	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Hallway between Main Office and Classroom 107	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway between Main Office and Classroom 107	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Hallway between Main Office and Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Stairwell adjacent to Classroom 109	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 109	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 109	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 109	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 109	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 109	Yes	Floor	Concrete	Grey	Chipping	2	0	Negative								
1	1	Classroom 109	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 109	Yes	W2	Concrete	White	Chipping	2	0	Negative								
1	1	Classroom 109	Yes	W3	Concrete	White	Chipping	3	0.01	Negative								
1	1	Classroom 109	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 109	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 107	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 107	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 107	Yes	W3	Concrete	White	Chipping	1	0	Negative								
1	1	Classroom 107	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 107	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 107	Yes	Lockers	Metal	Blue	Chipping	2	0	Negative								
1	1	Classroom 105	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 105	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 105	Yes	W3	Concrete	White	None	0	N/A	N/A								
1	1	Classroom 105	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 105	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 103	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 103	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 103	Yes	W3	Concrete	White	Chipping	5	0	Negative								
1	1	Classroom 103	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 103	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	School Counselor Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	School Counselor Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	School Counselor Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	School Counselor Office	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	School Counselor Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	School Counselor Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Main Office Mail Room	Yes	W1	CMU Block Wall	Purple	None	0	N/A	N/A			Positive					
1	1	Main Office Mail Room	Yes	W2	CMU Block Wall	Purple	None	0	N/A	N/A			Positive					
1	1	Main Office Mail Room	Yes	W3	CMU Block Wall	Purple	None	0	N/A	N/A			Positive					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
		1	1	Main Office Mail Room	Yes	W4	CMU Block Wall	Purple	None	0	N/A	N/A	Positive					
		1	1	Main Office Mail Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	Positive					
		1	1	Main Office Mail Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Server Room	Yes	W1	CMU Block Wall	Purple	None	0	N/A	N/A	Positive					
1	1	1	1	Server Room	Yes	W2	CMU Block Wall	Purple	None	0	N/A	N/A	Positive					
1	1	1	1	Server Room	Yes	W3	CMU Block Wall	Purple	None	0	N/A	N/A	Positive					
1	1	1	1	Server Room	Yes	W4	CMU Block Wall	Purple	None	0	N/A	N/A	Positive					
1	1	1	1	Server Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	Positive					
1	1	1	1	Server Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Cafetorium	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Stage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Stage	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Stage	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Stage	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Stage	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	Positive					
1	1	1	1	Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Cafetorium Fan Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium Fan Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium Fan Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium Fan Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Cafetorium Fan Room	Yes	Ceiling	Unpainted	Unpainted	None	N/A	N/A	N/A	Positive					
1	1	1	1	Cafetorium Fan Room	Yes	Floor	Unpainted	Unpainted	None	N/A	N/A	N/A	Positive					
1	1	1	1	Cafetorium Fan Room	Yes	Piping	Metal	Black	Chipping	1	0	Negative	Positive					
1	1	1	1	Kitchen	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A	Positive					
1	1	1	1	Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Kitchen Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Office	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Office	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A	Positive					
1	1	1	1	Kitchen Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Kitchen Storage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Storage	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Storage	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Storage	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Storage	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A	Positive					
1	1	1	1	Kitchen Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Staff Locker	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Staff Locker	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Staff Locker	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Staff Locker	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Staff Locker	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A	Positive					
1	1	1	1	Staff Locker	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A	Positive					
1	1	1	1	Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Food Storage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Food Storage	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Food Storage	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Food Storage	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Food Storage	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A	Positive					
1	1	1	1	Food Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Positive					
1	1	1	1	Kitchen Loading	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A	Positive					
1	1	1	1	Kitchen Loading	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A	Positive					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	Kitchen Loading	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Kitchen Loading	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Kitchen Loading	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Kitchen Loading	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Building Engineer's Storage Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Building Engineer's Storage Room	No	W2	CMU Block Wall	White	Chipping	2	0.03	Negative			Positive					
1	1	Building Engineer's Storage Room	No	W3	CMU Block Wall	White	Chipping	4	0.01	Negative			Positive					
1	1	Building Engineer's Storage Room	No	W4	CMU Block Wall	White	Chipping	4	0.03	Negative			Positive					
1	1	Building Engineer's Storage Room	No	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Building Engineer's Storage Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Mechanical Room	No	W1	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Mechanical Room	No	W2	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Mechanical Room	No	W3	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Mechanical Room	No	W4	CMU Block Wall	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Mechanical Room	No	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Mechanical Room	No	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	Staff Restroom	No	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Staff Restroom	No	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Staff Restroom	No	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Staff Restroom	No	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Staff Restroom	No	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Staff Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Building Engineer's Restroom	No	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Building Engineer's Restroom	No	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Building Engineer's Restroom	No	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Building Engineer's Restroom	No	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Building Engineer's Restroom	No	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Building Engineer's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Staff Locker Room	No	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Staff Locker Room	No	W2	CMU Block Wall	White	Chipping	2	0.03	Negative			Positive					
1	1	Staff Locker Room	No	W3	CMU Block Wall	White	Chipping	2	0.02	Negative			Positive					
1	1	Staff Locker Room	No	W4	CMU Block Wall	White	Chipping	2	0.03	Negative			Positive					
1	1	Staff Locker Room	No	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Staff Locker Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Building Engineer's Office	No	W1	CMU Block Wall	White	Chipping	2	0.01	Negative			Positive					
1	1	Building Engineer's Office	No	W2	CMU Block Wall	White	Chipping	2	0.02	Negative			Positive					
1	1	Building Engineer's Office	No	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Building Engineer's Office	No	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Building Engineer's Office	No	Ceiling	Concrete	White	Efflorescence	2	0.01	Negative	Under pipe run & riser	1	Positive					
1	1	Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Building Engineer's Office	No	Piping	Metal	White	Chipping	1	0.14	Negative								
1	1	Classroom 106	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 106	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 106	Yes	W3	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 106	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Classroom 106	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 106	Yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 114	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 114	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 114	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 114	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 114	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 114	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Electrical Room	Yes	W1	Unpainted	N/A	N/A	N/A	N/A	N/A								
1	1	Electrical Room	Yes	W2	Unpainted	N/A	N/A	N/A	N/A	N/A								
1	1	Electrical Room	Yes	W3	Unpainted	N/A	N/A	N/A	N/A	N/A								
1	1	Electrical Room	Yes	W4	Unpainted	N/A	N/A	N/A	N/A	N/A								
1	1	Electrical Room	Yes	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A								
1	1	Electrical Room	Yes	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A								
1	1	Custodial Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Custodial Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r																	
		On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	Custodial Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Custodial Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Custodial Room	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Custodial Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 112	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 112	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 112	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 112	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 112	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 112	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 123	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 123	Yes	W2	CMU Block Wall	White	Chipping	1	0	Negative			Positive					
1	1	Classroom 123	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 123	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 123	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 123	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 121	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 121	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 121	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 121	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 121	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 121	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 119	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 119	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 119	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 119	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 119	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					Moisture damage on ceiling tile. BE aware of damage-Viva EHS
1	1	Classroom 119	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 117	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 117	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 117	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 117	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 117	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 117	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 117	Yes	Door Casing	Metal	Blue	Chipping	2	0	Negative								
1	1	Classroom 110	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 110	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 110	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 110	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 110	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 110	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 115	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 115	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 115	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 115	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 115	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 115	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 108	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 108	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 108	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 108	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 108	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 113	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 113	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 113	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 113	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 113	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 111	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 111	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 111	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 111	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 111	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Classroom 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	Table Storage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Table Storage	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Table Storage	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Table Storage	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Table Storage	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Table Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Boy's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Classroom 106 Bathroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 106 Bathroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 106 Bathroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 106 Bathroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Classroom 106 Bathroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Classroom 106 Bathroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Stairwell adjacent to Classroom 106	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 106	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 106	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 106	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 106	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Stairwell adjacent to Classroom 106	Yes	Floor	Concrete	Grey	Chipping	2	0	Negative								
1	1	Small Hallway adjacent Cafetorium	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Small Hallway adjacent Cafetorium	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Small Hallway adjacent Cafetorium	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Small Hallway adjacent Cafetorium	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Small Hallway adjacent Cafetorium	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Small Hallway adjacent Cafetorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Gymnasium	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Gymnasium	Yes	W2	Concrete	White	None	0	N/A	N/A								
1	1	Gymnasium	Yes	W3	Concrete	White	None	0	N/A	N/A								
1	1	Gymnasium	Yes	W4	Concrete	White	None	0	N/A	N/A								
1	1	Gymnasium	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	1	Gymnasium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Gymnasium	Yes	Piping	Metal	White	Chipping	1	0.2	Negative								
1	1	Gymnasium	Yes	Piping	Metal	Black	Chipping	1	0	Negative								
1	1	Closet adjacent to Gymnasium	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Closet adjacent to Gymnasium	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Closet adjacent to Gymnasium	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Closet adjacent to Gymnasium	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Closet adjacent to Gymnasium	Yes	Ceiling	Concrete	White	Chipping	2	0	Negative			Positive					
1	1	Closet adjacent to Gymnasium	Yes	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	Teacher's Lunch Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Teacher's Lunch Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Teacher's Lunch Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Teacher's Lunch Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Teacher's Lunch Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Teacher's Lunch Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	Boy's Locker Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Locker Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Locker Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Locker Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Boy's Locker Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Boy's Locker Room	Yes	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	Gym Storage	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Gym Storage	Yes	W2	Concrete	White	None	0	N/A	N/A								
1	1	Gym Storage	Yes	W3	Concrete	White	None	0	N/A	N/A								
1	1	Gym Storage	Yes	W4	Concrete	White	None	0	N/A	N/A								
1	1	Gym Storage	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	1	Gym Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Coach's Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Coach's Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Coach's Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Coach's Office	Yes	W4	CMU Block Wall	White	Chipping	1	0	Negative			Positive					
1	1	Coach's Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Coach's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Coach's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Coach's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Coach's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Coach's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Coach's Restroom	Yes	Ceiling	Concrete	White	Chipping	2	0	Negative			Positive					
1	1	Coach's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Girl's Locker Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Locker Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Locker Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Locker Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Girl's Locker Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	1	Girl's Locker Room	Yes	Floor	Concrete	Unpainted	None	N/A	N/A	N/A								
1	1	Hallway from Cafetorium to Gymnasium	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from Cafetorium to Gymnasium	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Hallway from Cafetorium to Gymnasium	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway from Cafetorium to Gymnasium	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from Cafetorium to Gymnasium	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	1	Hallway from Cafetorium to Gymnasium	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway from Cafetorium to Gymnasium	Yes	Ceiling	Concrete	Unpainted	None	0	N/A	N/A			Positive					
1	1	Hallway from Cafetorium to Gymnasium	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from IMC to Classroom 216	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from IMC to Classroom 216	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway from IMC to Classroom 216	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	Hallway from IMC to Classroom 216	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	1	Hallway from IMC to Classroom 216	Yes	Ceiling	Concrete	Unpainted	None	0	N/A	N/A			Positive					
1	1	Hallway from IMC to Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 201	Yes	W1	Wood Partition	Blue	None	0	N/A	N/A								
1	2	Classroom 201	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					HID 2614. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	Classroom 201	Yes	W3	Concrete	Blue	None	0	N/A	N/A			Negative					HID 2614. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	Classroom 201	Yes	W4	Concrete	Blue	None	0	N/A	N/A			Negative					HID 2614. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	Classroom 201	Yes	Ceiling	Concrete	White	Chipping	1	0.01	Negative			Positive					
1	2	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 203	Yes	W1	CMU Block Wall	Blue	Chipping	2	0.05	Negative			Positive					
1	2	Classroom 203	Yes	W2	Wood Partition	Blue	None	0	N/A	N/A								
1	2	Classroom 203	Yes	W3	Concrete	Blue	Chipping	5	0.01	Negative			Negative					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	Classroom 203	Yes	W4	Wood Partition	Blue	None	0	N/A	N/A								
1	2	Classroom 203	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 205	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 205	Yes	W2	Wood Partition	Blue	None	0	N/A	N/A								
1	2	Classroom 205	Yes	W3	Concrete	Blue	None	0	N/A	N/A			Negative					
1	2	Classroom 205	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 205	Yes	Ceiling	Concrete	White	Chipping	4	0.01	Negative			Positive					HID 2611. Lead Safe Paint Inspection - Water damage observed. Sampled 08/24/21-RW
1	2	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 205	Yes	Piping	Metal	Blue	Chipping	1	0.17	Negative								
1	2	Science Lab	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Science Lab	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Science Lab	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative					
1	2	Science Lab	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Science Lab	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Science Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Art Lab	Yes	W1	CMU Block Wall	White	Chipping	1	0.02	Negative			Positive					
1	2	Art Lab	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Art Lab	Yes	W3	Concrete	White	Chipping	1	0	Negative			Negative					
1	2	Art Lab	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Art Lab	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Art Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 211	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 211	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 211	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 211	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 211	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	2	Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Computer Lab	Yes	W1	CMU Block Wall	White	Chipping	1	0.02	Negative			Positive					
1	2	Computer Lab	Yes	W2	CMU Block Wall	White	Chipping	2	0.06	Negative			Positive					
1	2	Computer Lab	Yes	W3	Concrete	White	Chipping	3	0.03	Negative			Negative					
1	2	Computer Lab	Yes	W4	Concrete	White	None	0	0	Negative			Negative					
1	2	Computer Lab	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Computer Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 213	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 213	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 213	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 213	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 213	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	2	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Stairwell adjacent to Computer Lab	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Computer Lab	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Computer Lab	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Computer Lab	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Computer Lab	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	2	Stairwell adjacent to Computer Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Hallway from Classrooms 201 to 215	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Hallway from Classrooms 201 to 215	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Hallway from Classrooms 201 to 215	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Hallway from Classrooms 201 to 215	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Hallway from Classrooms 201 to 215	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Hallway from Classrooms 201 to 215	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Hallway from Classrooms 201 to 215	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Hallway from Classrooms 201 to 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	Stairwell adjacent to Classroom 201	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Classroom 201	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Classroom 201	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Classroom 201	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Classroom 201	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Stairwell adjacent to Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Technical Equipment(Currently psychologist office)	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Technical Equipment(Currently psychologist office)	Yes	W2	CMU Block Wall	White	None	0	0	Negative			Positive					
1	2	Technical Equipment(Currently psychologist office)	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Technical Equipment(Currently psychologist office)	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Technical Equipment(Currently psychologist office)	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	2	Technical Equipment(Currently psychologist office)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	W2	CMU Block Wall	White	None	0	0	Negative			Positive					
1	2	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	2	Technical Equipment(Currently psychologist office) Adjacent Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 202	Yes	W1	Wood Partition	Blue	None	0	N/A	N/A								
1	2	Classroom 202	Yes	W2	Concrete	Blue	None	0	N/A	N/A			Negative					HID 2615. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	Classroom 202	Yes	W3	Concrete	Blue	None	0	N/A	N/A			Negative					HID 2615. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	Classroom 202	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					HID 2615. Lead Safe Paint Inspection - Sampled 08/24/21-RW
1	2	Classroom 202	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 204	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 204	Yes	W2	Wood Partition	Blue	None	0	N/A	N/A								
1	2	Classroom 204	Yes	W3	Concrete	Blue	Chipping	3	0	Negative			Negative					
1	2	Classroom 204	Yes	W4	Wood Partition	Blue	None	0	N/A	N/A								
1	2	Classroom 204	Yes	Ceiling	Concrete	White	Chipping	4	0.01	Negative			Positive					
1	2	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 204	Yes	Piping	Metal	Blue	Chipping	1	0.18	Negative								
1	2	Boy's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Boy's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Boy's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Boy's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Boy's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 206	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 206	Yes	W2	CMU Block Wall	White	None	0	0	Negative			Positive					
1	2	Classroom 206	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	Classroom 206	Yes	W4	Wood Partition	Blue	None	0	N/A	N/A								
1	2	Classroom 206	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 207	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 207	Yes	W2	CMU Block Wall	White	None	0	0	Negative			Positive					
1	2	Classroom 207	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 207	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 207	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	2	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 208	Yes	W1	CMU Block Wall	Blue	Chipping	1	0.01	Negative			Positive					
1	2	Classroom 208	Yes	W2	CMU Block Wall	Blue	None	0	0	Negative			Positive					
1	2	Classroom 208	Yes	W3	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 208	Yes	W3	Concrete	Blue	Chipping	1	0.01	Negative			Negative					
1	2	Classroom 208	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 208	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Classroom 209	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 209	Yes	W2	CMU Block Wall	White	Chipping	2	0	Negative			Positive					
1	2	Classroom 209	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 209	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Classroom 209	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
1	2	Classroom 209	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Closet 210	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Closet 210	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Closet 210	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Closet 210	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Closet 210	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Closet 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Staff Restroom adjacent Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Staff Restroom adjacent to Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent to Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent to Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent to Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent to Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Staff Restroom adjacent to Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Staff Restroom adjacent to Boy's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Staff Restroom adjacent to Boy's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Staff Restroom adjacent to Boy's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Staff Restroom adjacent to Boy's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Staff Restroom adjacent to Boy's Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Negative					
2	2	Staff Restroom adjacent to Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Boy's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Boy's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Boy's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Boy's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Boy's Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	2	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Girl's Restroom	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Girl's Restroom	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Girl's Restroom	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Girl's Restroom	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 215	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 215	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 215	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 215	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 215	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Office 212	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Office 212	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Office 212	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	Office 212	Yes	W4	CMU Block Wall	White	Chipping	2	0	Negative			Positive					
1	2	Office 212	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Office 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	Office 212	Yes	Piping	Metal	White	Chipping	2	0.07	Negative								
1	2	Classroom 214	Yes	W1	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 214	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 214	Yes	W3	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 214	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Positive					
1	2	Classroom 214	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Positive					
1	2	Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 218	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 218	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 218	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 218	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 218	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Classroom 218	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 219	Yes	W1	CMU Block Wall	White	Chipping	1	0	Negative			Negative					
2	2	Classroom 219	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 219	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 219	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 219	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Classroom 219	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 220	Yes	W1	CMU Block Wall	White	Chipping	1	0	Negative			Negative					
2	2	Classroom 220	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 220	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 220	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 220	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Classroom 220	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 216	Yes	W1	CMU Block Wall	White	Chipping	2	0.01	Negative			Negative					
2	2	Classroom 216	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 216	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 216	Yes	W4	CMU Block Wall	White	Chipping	2	0.02	Negative			Negative					
2	2	Classroom 216	Yes	Ceiling	Concrete	White	None	0	N/A	N/A			Negative					
2	2	Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 216	Yes	Duct Work	Metal	White	Chipping	2	0.06	Negative			Negative					
2	2	Stairwell adjacent to Classroom 216	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 216	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 216	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 216	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 216	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Hallway from IMC to Classroom 216	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Hallway from IMC to Classroom 216	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	2	Hallway from IMC to Classroom 216	Yes	W2	CMU Block Wall	Blue	None	0	N/A	N/A			Negative					
2	2	Hallway from IMC to Classroom 216	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Hallway from IMC to Classroom 216	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Hallway from IMC to Classroom 216	Yes	W4	CMU Block Wall	Blue	None	0	N/A	N/A			Negative					
2	2	Hallway from IMC to Classroom 216	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Hallway from IMC to Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	IMC (Library) Closet	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library) Closet	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library) Closet	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library) Closet	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library) Closet	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	2	IMC (Library) Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	IMC (Library) Office	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library) Office	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library) Office	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library) Office	Yes	W4	Concrete	White	None	0	N/A	N/A			Negative					
1	2	IMC (Library) Office	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	2	IMC (Library) Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	IMC (Library)	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library)	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library)	Yes	W3	Concrete	White	None	0	N/A	N/A			Negative					
1	2	IMC (Library)	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Positive					
1	2	IMC (Library)	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Positive					
1	2	IMC (Library)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 217	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 217	Yes	W2	CMU Block Wall	White	Moisture Damage	2	0	Negative			Negative					Mold present
2	2	Classroom 217	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 217	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 217	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Classroom 217	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 222	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 222	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 222	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 222	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 222	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Classroom 222	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 224	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 224	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 224	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 224	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 224	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Classroom 224	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Classroom 226	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 226	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 226	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 226	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Classroom 226	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Classroom 226	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Hallway from Classrooms 222 to 226	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Hallway from Classrooms 222 to 226	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Hallway from Classrooms 222 to 226	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Hallway from Classrooms 222 to 226	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Hallway from Classrooms 222 to 226	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Hallway from Classrooms 222 to 226	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Electrical Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Electrical Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Electrical Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Electrical Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					

			School District of Philadelphia															
		Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report								Inspection Dates: 08/23/21-08/24/21							
		Inspection Company: Viva EHS, LLC.	Lawton Elementary School								ULCS# 7330							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	2	Electrical Room	Yes	Ceiling	Concrete	Unpainted	None	N/A	N/A	N/A			Positive					
2	2	Electrical Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Custodial Room	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Custodial Room	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Custodial Room	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Custodial Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Custodial Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Custodial Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	Stairwell adjacent to Classroom 226	Yes	W1	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 226	Yes	W2	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 226	Yes	W3	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 226	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 226	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A			Negative					
2	2	Stairwell adjacent to Classroom 226	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	CS	Crawlspace- Gym Storage	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit- Viva EHS-RW
1	CS	Crawlspace- Gym Storage	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit- Viva EHS-RW
1	CS	Crawlspace- Gym Storage	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit- Viva EHS-RW
1	CS	Crawlspace- Gym Storage	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit- Viva EHS-RW
1	CS	Crawlspace- Gym Storage	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit- Viva EHS-RW
1	CS	Crawlspace- Gym Storage	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Confine Space need supplied air unit- Viva EHS-RW
1	AT	Attic	No	W1	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	Attic	No	W2	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	Attic	No	W3	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	Attic	No	W4	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	Attic	No	Ceiling	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	AT	Attic	No	Floor	X	X	X	X	X	X								No attic exists-Viva EHS-RW
1	1	Portable closest to Jackson Street	No	W1	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Portable closest to Jackson Street	No	W2	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Portable closest to Jackson Street	No	W3	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Portable closest to Jackson Street	No	W4	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Portable closest to Jackson Street	No	Ceiling	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Portable closest to Jackson Street	No	Floor	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Porable closest to Ditman Street	No	W1	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Porable closest to Ditman Street	No	W2	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Porable closest to Ditman Street	No	W3	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Porable closest to Ditman Street	No	W4	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Porable closest to Ditman Street	No	Ceiling	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW
1	1	Porable closest to Ditman Street	No	Floor	X	X	X	X	X	X								B.E. said Portable demolished to make room for Element #3-Viva EHS-RW