

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	2	201	Classroom 201	W1	Concrete	Light Blue	None	0	Negative
1	2	201	Classroom 201	W2	Concrete	Light Blue	None	0	Negative
1	2	201	Classroom 201	W3	Concrete	Light Blue	None	0	Negative
1	2	201	Classroom 201	W4	Concrete	Light Blue	None	0	Negative
1	2	201	Classroom 201	Door Casing	Metal	Blue	Friction	2	Negative
1	2	201	Classroom 201	Door Casing	Metal	Blue	Friction	2	Negative
1	2	201	Classroom 201	Univent	Metal	Blue	Friction	6	Negative
1	2	201	Classroom 201	Univent Top	Wood	Blue	Friction	4	Negative
1	2	201	Classroom 201	Ceiling	Concrete	White	None	0	Negative
1	2	201	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W1	Concrete	Light Blue	None	0	Negative
1	2	202	Classroom 202	W2	Concrete	Light Blue	None	0	Negative
1	2	202	Classroom 202	W3	Concrete	Light Blue	None	0	Negative
1	2	202	Classroom 202	W4	Concrete	Light Blue	None	0	Negative
1	2	202	Classroom 202	Door Casing	Metal	Blue	Friction	3	Negative
1	2	202	Classroom 202	Door Casing	Metal	Blue	Friction	1	Negative
1	2	202	Classroom 202	Univent	Metal	Blue	Friction	3	Negative
1	2	202	Classroom 202	Univent Top	Wood	Blue	Friction	3	Negative
1	2	202	Classroom 202	Ceiling	Concrete	White	None	0	N/A
1	2	202	Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A
1	2	202A	Custodial Closet Next to Classroom 202	W1	Concrete	White	None	0	Negative
1	2	202A	Custodial Closet Next to Classroom 202	W2	Concrete	White	None	0	Negative
1	2	202A	Custodial Closet Next to Classroom 202	W3	Concrete	White	None	0	Negative
1	2	202A	Custodial Closet Next to Classroom 202	W4	Concrete	White	None	0	Negative
1	2	202A	Custodial Closet Next to Classroom 202	Duct	Metal	White	None	0	Negative
1	2	202A	Custodial Closet Next to Classroom 202	Door Casing	Metal	Blue	Friction	2	Negative
1	2	202A	Custodial Closet Next to Classroom 202	Ceiling	Concrete	White	None	0	Negative
1	2	202A	Custodial Closet Next to Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A
1	2	202A	Teacher's Lounge Restroom	W1	Concrete	White	None	0	Negative
1	2	202A	Teacher's Lounge Restroom	W2	Concrete	White	None	0	Negative
1	2	202A	Teacher's Lounge Restroom	W3	Concrete	White	None	0	Negative
1	2	202A	Teacher's Lounge Restroom	W4	Concrete	White	None	0	Negative
1	2	202A	Teacher's Lounge Restroom	Door Casing	Metal	Blue	None	0	Negative
1	2	202A	Teacher's Lounge Restroom	Ceiling	Concrete	White	None	0	Negative
1	2	202A	Teacher's Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report**Inspector Name and Certificate Number:
Christopher Karoly - 006424****John McCloskey School****Inspection Company: Criterion
Laboratories****8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	2	215	Teacher's Lounge next to Classroom 203	W1	Concrete	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	W2	Concrete	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	W3	Concrete	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	W4	Concrete	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Chair Rail 1	Wood	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Chair Rail 2	Wood	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Chair Rail 3	Wood	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Chair Rail 4	Wood	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Door Casing	Metal	Blue	Friction	2	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Door Casing	Metal	Blue	Friction	<1	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Door Casing	Metal	Blue	Friction	3	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Radiator	Metal	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Ceiling	Concrete	White	None	0	Negative
1	2	215	Teacher's Lounge next to Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A
1	2	213	Girl's Restroom next to Classroom 201	W1	Concrete	White	None	0	Negative
1	2	213	Girl's Restroom next to Classroom 201	W2	Concrete	White	None	0	Negative
1	2	213	Girl's Restroom next to Classroom 201	W3	Concrete	White	None	0	Negative
1	2	213	Girl's Restroom next to Classroom 201	W4	Concrete	White	None	0	Negative
1	2	213	Girl's Restroom next to Classroom 201	Door Casing	Metal	Blue	None	2	Negative
1	2	213	Girl's Restroom next to Classroom 201	Radiator	Metal	White	None	0	Negative
1	2	213	Girl's Restroom next to Classroom 201	Ceiling	Concrete	White	None	0	Negative
1	2	213	Girl's Restroom next to Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A
1	2	212	Storage Closet next to Classroom 211	W1	Concrete	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	W2	Concrete	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	W3	Concrete	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	W4	Concrete	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	Duct	Metal	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	Pipechase Door	Metal	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	Electrical Panel	Metal	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	Door Casing	Metal	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	Pipe	Metal	Yellow	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	Ceiling	Concrete	White	None	0	Negative
1	2	212	Storage Closet next to Classroom 211	Floor	N/A	N/A	N/A	N/A	N/A
1	2	212PC	Pipe Chase in Storage Closet	W1	N/A	N/A	N/A	N/A	N/A
1	2	212PC	Pipe Chase in Storage Closet	W2	N/A	N/A	N/A	N/A	N/A

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report**Inspector Name and Certificate Number:
Christopher Karoly - 006424****John McCloskey School****Inspection Company: Criterion
Laboratories****8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	2	212PC	Pipe Chase in Storage Closet	W3	N/A	N/A	N/A	N/A	N/A
1	2	212PC	Pipe Chase in Storage Closet	W4	N/A	N/A	N/A	N/A	N/A
1	2	212PC	Pipe Chase in Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A
1	2	212PC	Pipe Chase in Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	W1	Concrete	Light Blue	None	0	Negative
1	2	211	Classroom 211	W2	Concrete	Light Blue	None	0	Negative
1	2	211	Classroom 211	W3	Concrete	Light Blue	None	0	Negative
1	2	211	Classroom 211	W4	Concrete	Light Blue	None	0	Negative
1	2	211	Classroom 211	Door Casing	Metal	Blue	Friction	2	Negative
1	2	211	Classroom 211	Door Casing	Metal	Blue	Friction	3	Negative
1	2	211	Classroom 211	Univent	Metal	Blue	Friction	5	Negative
1	2	211	Classroom 211	Univent Top	Wood	Blue	Friction	3	Negative
1	2	211	Classroom 211	Ceiling	Concrete	White	None	0	Negative
1	2	211	Classroom 211	Floor	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W1	Concrete	Light Blue	None	0	Negative
1	2	203	Classroom 203	W2	Concrete	Light Blue	None	0	Negative
1	2	203	Classroom 203	W3	Concrete	Light Blue	None	0	Negative
1	2	203	Classroom 203	W4	Concrete	Light Blue	None	0	Negative
1	2	203	Classroom 203	Door Casing	Metal	Blue	Friction	3	Negative
1	2	203	Classroom 203	Door Casing	Metal	Blue	Friction	1	Negative
1	2	203	Classroom 203	Univent	Metal	Blue	Friction	4	Negative
1	2	203	Classroom 203	Univent Top	Wood	Blue	Friction	2	Negative
1	2	203	Classroom 203	Ceiling	Concrete	White	None	0	Negative
1	2	203	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	W1	Concrete	Light Blue	None	0	Negative
1	2	204	Classroom 204	W2	Concrete	Light Blue	None	0	Negative
1	2	204	Classroom 204	W3	Concrete	Light Blue	None	0	Negative
1	2	204	Classroom 204	W4	Concrete	Light Blue	None	0	Negative
1	2	204	Classroom 204	Door Casing	Metal	Blue	Friction	2	Negative
1	2	204	Classroom 204	Door Casing	Metal	Blue	Friction	1	Negative
1	2	204	Classroom 204	Univent	Metal	Blue	Friction	3	Negative
1	2	204	Classroom 204	Univent Top	Wood	Blue	Friction	6	Negative
1	2	204	Classroom 204	Ceiling	Concrete	White	None	0	Negative
1	2	204	Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	W1	Concrete	Light Blue	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment ReportInspector Name and Certificate Number:
Christopher Karoly - 006424**John McCloskey School**Inspection Company: Criterion
Laboratories**8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	2	210	Classroom 210	W2	Concrete	Light Blue	None	0	Negative
1	2	210	Classroom 210	W3	Concrete	Light Blue	None	0	Negative
1	2	210	Classroom 210	W4	Concrete	Light Blue	None	0	Negative
1	2	210	Classroom 210	Door Casing	Metal	Blue	Friction	3	Negative
1	2	210	Classroom 210	Door Casing	Metal	Blue	Friction	2	Negative
1	2	210	Classroom 210	Univent	Metal	Blue	Friction	4	Negative
1	2	210	Classroom 210	Univent Top	Wood	Blue	Friction	7	Negative
1	2	210	Classroom 210	Ceiling	Concrete	White	None	0	Negative
1	2	210	Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	W1	Concrete	Light Blue	None	0	Negative
1	2	205	Classroom 205	W2	Concrete	Light Blue	None	0	Negative
1	2	205	Classroom 205	W3	Concrete	Light Blue	None	0	Negative
1	2	205	Classroom 205	W4	Concrete	Light Blue	None	0	Negative
1	2	205	Classroom 205	Door Casing	Metal	Blue	Friction	3	Negative
1	2	205	Classroom 205	Door Casing	Metal	Blue	Friction	3	Negative
1	2	205	Classroom 205	Univent	Metal	Blue	Friction	4	Negative
1	2	205	Classroom 205	Univent Top	Wood	Blue	Friction	6	Negative
1	2	205	Classroom 205	Ceiling	Concrete	White	None	0	Negative
1	2	205	Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	W1	Concrete	Light Blue	None	0	Negative
1	2	209	Classroom 209	W2	Concrete	Light Blue	None	0	Negative
1	2	209	Classroom 209	W3	Concrete	Light Blue	None	0	Negative
1	2	209	Classroom 209	W4	Concrete	Light Blue	None	0	Negative
1	2	209	Classroom 209	Door Casing	Metal	Blue	Friction	<1	Negative
1	2	209	Classroom 209	Door Casing	Metal	Blue	Friction	2	Negative
1	2	209	Classroom 209	Univent	Metal	Blue	Friction	4	Negative
1	2	209	Classroom 209	Univent Top	Wood	Blue	Friction	3	Negative
1	2	209	Classroom 209	Ceiling	Concrete	White	None	0	Negative
1	2	209	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	W1	Concrete	Light Blue	None	0	Negative
1	2	208	Classroom 208	W2	Concrete	Light Blue	None	0	Negative
1	2	208	Classroom 208	W3	Concrete	Light Blue	None	0	Negative
1	2	208	Classroom 208	W4	Concrete	Light Blue	None	0	Negative
1	2	208	Classroom 208	Door Casing	Metal	Blue	Friction	2	Negative
1	2	208	Classroom 208	Door Casing	Metal	Blue	Friction	2	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report**Inspector Name and Certificate Number:
Christopher Karoly - 006424****John McCloskey School****Inspection Company: Criterion
Laboratories****8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	2	208	Classroom 208	Univent	Metal	Blue	Friction	7	Negative
1	2	208	Classroom 208	Univent Top	Wood	Blue	Friction	3	Negative
1	2	208	Classroom 208	Ceiling	Concrete	White	None	0	Negative
1	2	208	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	W1	Concrete	Light Blue	None	0	Negative
1	2	206	Classroom 206	W2	Concrete	Light Blue	None	0	Negative
1	2	206	Classroom 206	W3	Concrete	Light Blue	None	0	Negative
1	2	206	Classroom 206	W4	Concrete	Light Blue	None	0	Negative
1	2	206	Classroom 206	Door Casing	Metal	Blue	Friction	3	Negative
1	2	206	Classroom 206	Door Casing	Metal	Blue	Friction	2	Negative
1	2	206	Classroom 206	Univent	Metal	Blue	Friction	5	Negative
1	2	206	Classroom 206	Univent Top	Wood	Blue	Friction	3	Negative
1	2	206	Classroom 206	Ceiling	Concrete	White	None	0	Negative
1	2	206	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A
1	2	207	Learning Support Room to Right of Classroom 206	W1	Concrete	White	None	0	Negative
1	2	207	Learning Support Room to Right of Classroom 206	W2	Concrete	White	None	0	Negative
1	2	207	Learning Support Room to Right of Classroom 206	W3	Concrete	White	None	0	Negative
1	2	207	Learning Support Room to Right of Classroom 206	W4	Concrete	White	None	0	Negative
1	2	207	Learning Support Room to Right of Classroom 206	Door Casing	Metal	Blue	Friction	<1	Negative
1	2	207	Learning Support Room to Right of Classroom 206	Door Casing	Metal	Blue	Friction	2	Negative
1	2	207	Learning Support Room to Right of Classroom 206	Univent	Metal	Blue	Friction	3	Negative
1	2	207	Learning Support Room to Right of Classroom 206	Univent Top	Wood	Blue	Friction	2	Negative
1	2	207	Learning Support Room to Right of Classroom 206	Radiator	Metal	Blue	Friction	6	Positive
1	2	207	Learning Support Room to Right of Classroom 206	Ceiling	Concrete	White	None	0	Negative
1	2	207	Learning Support Room to Right of Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A
1	2	218	Boy's Restroom near Classroom 206	W1	Concrete	White	None	0	Negative
1	2	218	Boy's Restroom near Classroom 206	W2	Concrete	White	None	0	Negative
1	2	218	Boy's Restroom near Classroom 206	W3	Concrete	White	None	0	Negative
1	2	218	Boy's Restroom near Classroom 206	W4	Concrete	White	None	0	Negative
1	2	218	Boy's Restroom near Classroom 206	Door Casing	Metal	Blue	Friction	2	Negative
1	2	218	Boy's Restroom near Classroom 206	Radiator	Metal	White	None	0	Negative
1	2	218	Boy's Restroom near Classroom 206	Ceiling	Concrete	White	None	0	Negative
1	2	218	Boy's Restroom near Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A
1	2	217	Storage Closet next to Classroom 208	W1	Concrete	White	None	0	Negative
1	2	217	Storage Closet next to Classroom 208	W2	Concrete	White	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report**Inspector Name and Certificate Number:
Christopher Karoly - 006424****John McCloskey School****Inspection Company: Criterion
Laboratories****8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	2	217	Storage Closet next to Classroom 208	W3	Concrete	White	None	0	Negative
1	2	217	Storage Closet next to Classroom 208	W4	Concrete	White	None	0	Negative
1	2	217	Storage Closet next to Classroom 208	Duct	Metal	Tan	None	0	Negative
1	2	217	Storage Closet next to Classroom 208	Door Casing	Metal	Yellow	None	0	Negative
1	2	217	Storage Closet next to Classroom 208	Pipe	Metal	White	None	0	Negative
1	2	217	Storage Closet next to Classroom 208	Ceiling	Concrete	White	None	0	Negative
1	2	217	Storage Closet next to Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	W1	Concrete	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	W2	Concrete	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	W3	Concrete	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	W4	Concrete	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Chair Rail 1	Wood	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Chair Rail 2	Wood	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Chair Rail 3	Wood	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Chair Rail 4	Wood	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Door Casing	Metal	Blue	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Door Casing	Metal	Blue	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Door Casing	Metal	Blue	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Radiator	Metal	Blue	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Ceiling	Concrete	White	None	0	Negative
1	2	216	Men's Teacher Lounge adjacent to Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A
1	2	216A	Men's Restroom in 2nd Floor Men's Staff Lounge	W1	Concrete	White	None	0	Negative
1	2	216A	Men's Restroom in 2nd Floor Men's Staff Lounge	W2	Concrete	White	None	0	Negative
1	2	216A	Men's Restroom in 2nd Floor Men's Staff Lounge	W3	Concrete	White	None	0	Negative
1	2	216A	Men's Restroom in 2nd Floor Men's Staff Lounge	W4	Concrete	White	None	0	Negative
1	2	216A	Men's Restroom in 2nd Floor Men's Staff Lounge	Duct	Metal	White	None	0	Negative
1	2	216A	Men's Restroom in 2nd Floor Men's Staff Lounge	Door Casing	Metal	Blue	None	0	Negative
1	2	216A	Men's Restroom in 2nd Floor Men's Staff Lounge	Ceiling	Concrete	White	None	0	Negative
1	2	216A	Men's Restroom in 2nd Floor Men's Staff Lounge	Floor	N/A	N/A	N/A	N/A	N/A
1	2	H24	Hallway next to Classrooms 201 through 207	W1	N/A	N/A	N/A	N/A	N/A
1	2	H24	Hallway next to Classrooms 201 through 207	W2	Concrete	White	None	0	Negative
1	2	H24	Hallway next to Classrooms 201 through 207	W3	Concrete	White	None	0	Negative
1	2	H24	Hallway next to Classrooms 201 through 207	W4	Concrete	White	None	0	Negative
1	2	H24	Hallway next to Classrooms 201 through 207	Door	Metal	Blue	None	0	Negative
1	2	H24	Hallway next to Classrooms 201 through 207	Door Casing	Metal	Blue	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report

Inspector Name and Certificate Number:
Christopher Karoly - 006424

John McCloskey School

Inspection Company: Criterion
Laboratories

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	2	H24	Hallway next to Classrooms 201 through 207	Univent 2	Metal	Blue	Friction	4	Positive
1	2	H24	Hallway next to Classrooms 201 through 207	Univent 3	Metal	Blue	Friction	2	Positive
1	2	H24	Hallway next to Classrooms 201 through 207	Univent 4	Metal	Blue	Friction	3	Positive
1	2	H24	Hallway next to Classrooms 201 through 207	Ceiling	Concrete	White	None	0	Negative
1	2	H24	Hallway next to Classrooms 201 through 207	Floor	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell Next to Classroom 201	W1	Concrete	White	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	W2	Concrete	White	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	W3	Concrete	White	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	W4	Concrete	White	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	Stair Post	Metal	Blue	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	Stair Tread	Metal	Blue	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	Stair Stringer	Metal	Blue	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	Univent	Metal	Blue	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	Door 1	Metal	Blue	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	Door Casing 1	Metal	Blue	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	Ceiling	Concrete	White	None	0	Negative
1	2	S21	Stairwell Next to Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A
2	1	109	Classroom 109	W1	Sheetrock	White	None	0	Negative
2	1	109	Classroom 109	W2	Sheetrock	White	None	0	Negative
2	1	109	Classroom 109	W3	Sheetrock	White	None	0	Negative
2	1	109	Classroom 109	W4	Sheetrock	White	None	0	Negative
2	1	109	Classroom 109	Door	Wood	Orange	None	0	Negative
2	1	109	Classroom 109	Door Casing	Metal	Orange	Friction	2	Negative
2	1	109	Classroom 109	Door Casing	Metal	Orange	Friction	2	Negative
2	1	109	Classroom 109	Door Casing	Metal	Orange	Friction	<1	Negative
2	1	109	Classroom 109	Baseboard 1	Wood	Orange	Friction	4	Negative
2	1	109	Classroom 109	Baseboard 2	Wood	Orange	Friction	6	Negative
2	1	109	Classroom 109	Baseboard 3	Wood	Orange	Friction	5	Negative
2	1	109	Classroom 109	Baseboard 4	Wood	Orange	Friction	2	Negative
2	1	109	Classroom 109	Univent	Metal	Orange	Friction	2	Negative
2	1	109	Classroom 109	Radiator	Metal	White	Friction	3	Negative
2	1	109	Classroom 109	Pipe Jacket	Metal	White	None	0	Negative
2	1	109	Classroom 109	Whiteboard trim	Metal	White	None	0	Negative
2	1	109	Classroom 109	Ceiling	Metal	White	None	0	Negative
2	1	109	Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
2	1	109A	Classroom 109 Storage Closet	W1	Metal	White	None	4	Negative
2	1	109A	Classroom 109 Storage Closet	W2	Sheetrock	White	None	0	Negative
2	1	109A	Classroom 109 Storage Closet	W3	Sheetrock	White	None	0	Negative
2	1	109A	Classroom 109 Storage Closet	W4	Sheetrock	White	None	0	Negative
2	1	109A	Classroom 109 Storage Closet	Baseboard 1	Wood	White	None	0	Negative
2	1	109A	Classroom 109 Storage Closet	Baseboard 2	Wood	White	None	0	Negative
2	1	109A	Classroom 109 Storage Closet	Baseboard 3	Wood	White	None	0	Negative
2	1	109A	Classroom 109 Storage Closet	Baseboard 4	Wood	White	None	0	Negative
2	1	109A	Classroom 109 Storage Closet	Box	Metal	White	None	0	Negative
2	1	109A	Classroom 109 Storage Closet	Ceiling	Metal	White	None	0	N/A
2	1	109A	Classroom 109 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A
2	1	114	Classroom 114	W1	Sheetrock	White	None	0	Negative
2	1	114	Classroom 114	W2	Sheetrock	White	None	0	Negative
2	1	114	Classroom 114	W3	Sheetrock	White	None	0	Negative
2	1	114	Classroom 114	W4	Sheetrock	White	None	0	Negative
2	1	114	Classroom 114	Door	Wood	Orange	None	0	Negative
2	1	114	Classroom 114	Door Casing	Metal	Orange	None	0	Negative
2	1	114	Classroom 114	Door Casing	Metal	Orange	None	0	Negative
2	1	114	Classroom 114	Door Casing	Metal	Orange	None	0	Negative
2	1	114	Classroom 114	Baseboard 1	Wood	Orange	None	0	Negative
2	1	114	Classroom 114	Baseboard 2	Wood	Orange	None	0	Negative
2	1	114	Classroom 114	Baseboard 3	Wood	Orange	None	0	Negative
2	1	114	Classroom 114	Baseboard 4	Wood	Orange	None	0	Negative
2	1	114	Classroom 114	Univent	Metal	Orange	None	0	Negative
2	1	114	Classroom 114	Radiator	Metal	White	None	0	Negative
2	1	114	Classroom 114	Pipe Jacket	Metal	White	None	0	Negative
2	1	114	Classroom 114	Whiteboard trim	Metal	White	None	0	Negative
2	1	114	Classroom 114	Ceiling	Metal	White	None	0	Negative
2	1	114	Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A
2	1	114A	Classroom 114 Storage Closet	W1	Metal	White	None	0	Negative
2	1	114A	Classroom 114 Storage Closet	W2	Sheetrock	White	None	0	Negative
2	1	114A	Classroom 114 Storage Closet	W3	Sheetrock	White	None	0	Negative
2	1	114A	Classroom 114 Storage Closet	W4	Sheetrock	White	None	0	Negative
2	1	114A	Classroom 114 Storage Closet	Ceiling	Metal	White	None	0	Negative
2	1	114A	Classroom 114 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment ReportInspector Name and Certificate Number:
Christopher Karoly - 006424**John McCloskey School**Inspection Company: Criterion
Laboratories**8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2	1	113	Classroom 113	W1	Sheetrock	White	None	0	Negative
2	1	113	Classroom 113	W2	Sheetrock	White	None	0	Negative
2	1	113	Classroom 113	W3	Sheetrock	White	None	0	Negative
2	1	113	Classroom 113	W4	Sheetrock	White	None	0	Negative
2	1	113	Classroom 113	Door	Wood	Orange	None	0	Negative
2	1	113	Classroom 113	Door Casing	Metal	Orange	None	0	Negative
2	1	113	Classroom 113	Door Casing	Metal	Orange	None	0	Negative
2	1	113	Classroom 113	Door Casing	Metal	Orange	None	0	Negative
2	1	113	Classroom 113	Baseboard 1	Wood	Orange	None	0	Negative
2	1	113	Classroom 113	Baseboard 2	Wood	Orange	None	0	Negative
2	1	113	Classroom 113	Baseboard 3	Wood	Orange	None	0	Negative
2	1	113	Classroom 113	Baseboard 4	Wood	Orange	None	0	Negative
2	1	113	Classroom 113	Univent	Metal	Orange	None	0	Negative
2	1	113	Classroom 113	Radiator	Metal	White	None	0	Negative
2	1	113	Classroom 113	Pipe Jacket	Metal	White	None	0	Negative
2	1	113	Classroom 113	Whiteboard trim	Metal	White	None	0	Negative
2	1	113	Classroom 113	Ceiling	Metal	White	None	0	Negative
2	1	113	Classroom 113	Floor	N/A	N/A	N/A	N/A	N/A
2	1	113A	Classroom 113 Storage Closet	W1	Metal	White	None	0	Negative
2	1	113A	Classroom 113 Storage Closet	W2	Sheetrock	White	None	0	Negative
2	1	113A	Classroom 113 Storage Closet	W3	Metal	White	None	0	Negative
2	1	113A	Classroom 113 Storage Closet	W4	Sheetrock	White	None	0	Negative
2	1	113A	Classroom 113 Storage Closet	Ceiling	Metal	White	None	0	Negative
2	1	113A	Classroom 113 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A
2	1	110	Classroom 110	W1	Sheetrock	White	None	0	Negative
2	1	110	Classroom 110	W2	Sheetrock	White	None	0	Negative
2	1	110	Classroom 110	W3	Sheetrock	White	None	0	Negative
2	1	110	Classroom 110	W4	Sheetrock	White	None	0	Negative
2	1	110	Classroom 110	Door	Wood	Orange	None	0	Negative
2	1	110	Classroom 110	Door Casing	Metal	Orange	None	0	Negative
2	1	110	Classroom 110	Door Casing	Metal	Orange	None	0	Negative
2	1	110	Classroom 110	Door Casing	Metal	Orange	None	0	Negative
2	1	110	Classroom 110	Baseboard 1	Wood	Orange	None	0	Negative
2	1	110	Classroom 110	Baseboard 2	Wood	Orange	None	0	Negative
2	1	110	Classroom 110	Baseboard 3	Wood	Orange	None	0	Negative

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2	1	110	Classroom 110	Baseboard 4	Wood	Orange	None	0	Negative
2	1	110	Classroom 110	Univent	Metal	Orange	None	0	Negative
2	1	110	Classroom 110	Radiator	Metal	White	None	0	Negative
2	1	110	Classroom 110	Pipe Jacket	Metal	White	None	0	Negative
2	1	110	Classroom 110	Whiteboard trim	Metal	White	None	0	Negative
2	1	110	Classroom 110	Ceiling	Metal	White	None	0	Negative
2	1	110	Classroom 110	Floor	N/A	N/A	N/A	N/A	N/A
2	1	110A	Classroom 110 Storage Closet	W1	Metal	White	Flaking	6	Negative
2	1	110A	Classroom 110 Storage Closet	W2	Sheetrock	White	None	0	Negative
2	1	110A	Classroom 110 Storage Closet	W3	Sheetrock	White	None	0	Negative
2	1	110A	Classroom 110 Storage Closet	W4	Sheetrock	White	None	0	Negative
2	1	110A	Classroom 110 Storage Closet	Duct	Metal	White	None	0	Negative
2	1	110A	Classroom 110 Storage Closet	Ceiling	Metal	White	None	0	Negative
2	1	110A	Classroom 110 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A
2	1	112	Classroom 112	W1	Sheetrock	White	None	0	Negative
2	1	112	Classroom 112	W2	Sheetrock	White	None	0	Negative
2	1	112	Classroom 112	W3	Sheetrock	White	None	0	Negative
2	1	112	Classroom 112	W4	Sheetrock	White	None	0	Negative
2	1	112	Classroom 112	Door	Wood	Orange	None	0	Negative
2	1	112	Classroom 112	Door Casing	Metal	Orange	None	0	Negative
2	1	112	Classroom 112	Door Casing	Metal	Orange	None	0	Negative
2	1	112	Classroom 112	Door Casing	Metal	Orange	None	0	Negative
2	1	112	Classroom 112	Baseboard 1	Wood	Orange	None	0	Negative
2	1	112	Classroom 112	Baseboard 2	Wood	Orange	None	0	Negative
2	1	112	Classroom 112	Baseboard 3	Wood	Orange	None	0	Negative
2	1	112	Classroom 112	Baseboard 4	Wood	Orange	None	0	Negative
2	1	112	Classroom 112	Univent	Metal	Orange	None	0	Negative
2	1	112	Classroom 112	Radiator	Metal	White	None	0	Negative
2	1	112	Classroom 112	Pipe Jacket	Metal	White	None	0	Negative
2	1	112	Classroom 112	Whiteboard trim	Metal	White	None	0	Negative
2	1	112	Classroom 112	Ceiling	Metal	White	None	0	Negative
2	1	112	Classroom 112	Floor	N/A	N/A	N/A	N/A	N/A
2	1	112A	Classroom 112 Storage Closet	W1	Metal	White	Flaking	4	Negative
2	1	112A	Classroom 112 Storage Closet	W2	Sheetrock	White	None	0	Negative
2	1	112A	Classroom 112 Storage Closet	W3	Sheetrock	White	None	0	Negative

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2	1	112A	Classroom 112 Storage Closet	W4	Sheetrock	White	None	0	Negative
2	1	112A	Classroom 112 Storage Closet	Duct	Metal	White	None	0	Negative
2	1	112A	Classroom 112 Storage Closet	Ceiling	Metal	White	None	0	Negative
2	1	112A	Classroom 112 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A
2	1	111	Classroom 111	W1	Sheetrock	White	None	0	Negative
2	1	111	Classroom 111	W2	Sheetrock	White	None	0	Negative
2	1	111	Classroom 111	W3	Sheetrock	White	None	0	Negative
2	1	111	Classroom 111	W4	Sheetrock	White	None	0	Negative
2	1	111	Classroom 111	Door	Wood	Orange	None	0	Negative
2	1	111	Classroom 111	Door Casing	Metal	Orange	None	0	Negative
2	1	111	Classroom 111	Door Casing	Metal	Orange	None	0	Negative
2	1	111	Classroom 111	Door Casing	Metal	Orange	None	0	Negative
2	1	111	Classroom 111	Baseboard 1	Wood	Orange	None	0	Negative
2	1	111	Classroom 111	Baseboard 2	Wood	Orange	None	0	Negative
2	1	111	Classroom 111	Baseboard 3	Wood	Orange	None	0	Negative
2	1	111	Classroom 111	Baseboard 4	Wood	Orange	None	0	Negative
2	1	111	Classroom 111	Univent	Metal	Orange	None	0	Negative
2	1	111	Classroom 111	Radiator	Metal	White	None	0	Negative
2	1	111	Classroom 111	Pipe Jacket	Metal	White	None	0	Negative
2	1	111	Classroom 111	Whiteboard trim	Metal	White	None	0	Negative
2	1	111	Classroom 111	Ceiling	Metal	White	None	0	Negative
2	1	111	Classroom 111	Floor	N/A	N/A	N/A	N/A	N/A
2	1	111A	Classroom 111 Closet	W1	Metal	White	None	0	Negative
2	1	111A	Classroom 111 Closet	W2	Sheetrock	White	None	0	Negative
2	1	111A	Classroom 111 Closet	W3	Sheetrock	White	None	0	Negative
2	1	111A	Classroom 111 Closet	W4	Sheetrock	White	None	0	Negative
2	1	111A	Classroom 111 Closet	Baseboard	Wood	White	None	0	Negative
2	1	111A	Classroom 111 Closet	Duct	Metal	White	None	0	Negative
2	1	111A	Classroom 111 Closet	Ceiling	Metal	White	None	0	Negative
2	1	111A	Classroom 111 Closet	Floor	N/A	N/A	N/A	N/A	N/A
2	1	T101	Women's Restroom in Hall near Classroom 114	W1	Concrete	White	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	W2	Concrete	White	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	W3	Concrete	White	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	W4	Concrete	White	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	Radiator 3	Metal	White	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report**Inspector Name and Certificate Number:
Christopher Karoly - 006424****John McCloskey School****Inspection Company: Criterion
Laboratories****8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2	1	T101	Women's Restroom in Hall near Classroom 114	Radiator 4	Metal	White	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	Pipe Jacket 3	Metal	White	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	Pipe Jacket 4	Metal	White	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	Door Casing 1	Metal	Orange	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	Door Casing 3	Metal	Orange	None	0	Negative
2	1	T101	Women's Restroom in Hall near Classroom 114	Ceiling	Concrete	White	None	0	N/A
2	1	T101	Women's Restroom in Hall near Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	W1	Concrete	Green	None	0	Negative
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	W2	Concrete	Green	None	0	Negative
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	W3	Concrete	Green	None	0	Negative
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	W4	Concrete	Green	None	0	Negative
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	Shelf	Wood	Green	None	0	Negative
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	Pipe	Metal	Green	None	0	Negative
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	Duct	Metal	White	None	0	Negative
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	Ceiling	Concrete	White	None	0	Negative
2	1	T100	Service Closet (with IDF-1) Next to Women's Restroom near Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A
2	1	PC01	Pipe Chase in Service Closet Next to Women's Restroom near Classroom 114	W1	N/A	N/A	N/A	N/A	N/A
2	1	PC01	Pipe Chase in Service Closet Next to Women's Restroom near Classroom 114	W2	N/A	N/A	N/A	N/A	N/A
2	1	PC01	Pipe Chase in Service Closet Next to Women's Restroom near Classroom 114	W3	N/A	N/A	N/A	N/A	N/A
2	1	PC01	Pipe Chase in Service Closet Next to Women's Restroom near Classroom 114	W4	N/A	N/A	N/A	N/A	N/A
2	1	PC01	Pipe Chase in Service Closet Next to Women's Restroom near Classroom 114	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	PC01	Pipe Chase in Service Closet Next to Women's Restroom near Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A
2	1	T102	Boy's Restroom near Classroom 114	W1	Concrete	White	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment ReportInspector Name and Certificate Number:
Christopher Karoly - 006424**John McCloskey School**Inspection Company: Criterion
Laboratories**8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2	1	T102	Boy's Restroom near Classroom 114	W2	Concrete	White	None	0	Negative
2	1	T102	Boy's Restroom near Classroom 114	W3	Concrete	White	None	0	Negative
2	1	T102	Boy's Restroom near Classroom 114	W4	Concrete	White	None	0	Negative
2	1	T102	Boy's Restroom near Classroom 114	Metal Jacket	Metal	White	None	0	Negative
2	1	T102	Boy's Restroom near Classroom 114	Door Casing	Metal	Orange	None	0	Negative
2	1	T102	Boy's Restroom near Classroom 114	Ceiling	Concrete	White	None	0	Negative
2	1	T102	Boy's Restroom near Classroom 114	Floor	Concrete	Grey	None	0	Negative
1	1	120	Boy's Restroom next to Classroom 105	W1	Concrete	Blue	None	0	Negative
1	1	120	Boy's Restroom next to Classroom 105	W2	Concrete	Blue	None	0	Negative
1	1	120	Boy's Restroom next to Classroom 105	W3	Concrete	Blue	None	0	Negative
1	1	120	Boy's Restroom next to Classroom 105	W4	Concrete	Blue	None	0	Negative
1	1	120	Boy's Restroom next to Classroom 105	Door Casing	Metal	Blue	Friction	3	Negative
1	1	120	Boy's Restroom next to Classroom 105	Door	Metal	Brown	None	0	Negative
1	1	120	Boy's Restroom next to Classroom 105	Door Casing	Metal	Brown	Friction	<1	Negative
1	1	120	Boy's Restroom next to Classroom 105	Pipe Jacket	Metal	Brown	None	0	Negative
1	1	120	Boy's Restroom next to Classroom 105	Ceiling	Concrete	White	None	0	Negative
1	1	120	Boy's Restroom next to Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A
1	1	104A	Office 104A	W1	Concrete	Blue	None	0	Negative
1	1	104A	Office 104A	W2	Concrete	Blue	None	0	Negative
1	1	104A	Office 104A	W3	Concrete	Blue	None	0	Negative
1	1	104A	Office 104A	W4	Concrete	Blue	None	0	Negative
1	1	104A	Office 104A	Door Casing	Metal	Blue	None	0	Negative
1	1	104A	Office 104A	Ceiling	Concrete	White	None	0	Negative
1	1	104A	Office 104A	Floor	N/A	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	W1	Concrete	Blue	None	0	Negative
1	1	104	Classroom 104	W2	Concrete	Blue	None	0	Negative
1	1	104	Classroom 104	W3	Concrete	Blue	None	0	Negative
1	1	104	Classroom 104	W4	Concrete	Blue	None	0	Negative
1	1	104	Classroom 104	Univent	Metal	Blue	Friction	8	Negative
1	1	104	Classroom 104	Univent Top	Wood	Blue	Friction	5	Negative
1	1	104	Classroom 104	Door Casing	Metal	Blue	Friction	3	Negative
1	1	104	Classroom 104	Door Casing	Metal	Blue	Friction	3	Negative
1	1	104	Classroom 104	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	104	Classroom 104	Door Casing	Metal	Blue	Friction	1	Negative
1	1	104	Classroom 104	Pipe Jacket	Metal	Blue	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment ReportInspector Name and Certificate Number:
Christopher Karoly - 006424**John McCloskey School**Inspection Company: Criterion
Laboratories**8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	104	Classroom 104	Ceiling	Concrete	White	None	0	Negative
1	1	104	Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A
1	1	104B	Classroom 104 Storage Closet	W1	Concrete	Blue	None	0	Negative
1	1	104B	Classroom 104 Storage Closet	W2	Concrete	Blue	None	0	Negative
1	1	104B	Classroom 104 Storage Closet	W3	Concrete	Blue	None	0	Negative
1	1	104B	Classroom 104 Storage Closet	W4	Concrete	Blue	None	0	Negative
1	1	104B	Classroom 104 Storage Closet	Door Casing	Metal	Blue	Friction	2	Negative
1	1	104B	Classroom 104 Storage Closet	Door Casing	Metal	Blue	Friction	2	Negative
1	1	104B	Classroom 104 Storage Closet	Ceiling	Concrete	White	None	0	Negative
1	1	104B	Classroom 104 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A
1	1	105	Classroom 105	W1	Concrete	Blue	None	0	Negative
1	1	105	Classroom 105	W2	Concrete	Blue	None	0	Negative
1	1	105	Classroom 105	W3	Concrete	Blue	None	0	Negative
1	1	105	Classroom 105	W4	Concrete	Blue	None	0	Negative
1	1	105	Classroom 105	Univent	Metal	Blue	Friction	4	Negative
1	1	105	Classroom 105	Univent Top	Wood	Blue	Friction	8	Negative
1	1	105	Classroom 105	Door Casing	Metal	Blue	Friction	2	Negative
1	1	105	Classroom 105	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	105	Classroom 105	Door Casing	Metal	Blue	Friction	2	Negative
1	1	105	Classroom 105	Door Casing	Metal	Blue	None	0	Negative
1	1	105	Classroom 105	Pipe Jacket	Metal	Blue	None	0	Negative
1	1	105	Classroom 105	Ceiling	Concrete	White	None	0	Negative
1	1	105	Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A
1	1	103	Classroom 103	W1	Concrete	Blue	None	0	Negative
1	1	103	Classroom 103	W2	Concrete	Blue	None	0	Negative
1	1	103	Classroom 103	W3	Concrete	Blue	None	0	Negative
1	1	103	Classroom 103	W4	Concrete	Blue	None	0	Negative
1	1	103	Classroom 103	Univent	Metal	Blue	Friction	5	Negative
1	1	103	Classroom 103	Univent Top	Wood	Blue	Friction	12	Negative
1	1	103	Classroom 103	Door Casing	Metal	Blue	Friction	3	Negative
1	1	103	Classroom 103	Door Casing	Metal	Blue	Friction	3	Negative
1	1	103	Classroom 103	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	103	Classroom 103	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	103	Classroom 103	Pipe Jacket	Metal	Blue	None	0	Negative
1	1	103	Classroom 103	Ceiling	Concrete	White	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment ReportInspector Name and Certificate Number:
Christopher Karoly - 006424**John McCloskey School**Inspection Company: Criterion
Laboratories**8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	103	Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	W1	Concrete	Blue	None	0	Negative
1	1	106	Classroom 106	W2	Concrete	Blue	None	0	Negative
1	1	106	Classroom 106	W3	Concrete	Blue	None	0	Negative
1	1	106	Classroom 106	W4	Concrete	Blue	None	0	Negative
1	1	106	Classroom 106	Univent	Metal	Blue	Friction	6	Negative
1	1	106	Classroom 106	Univent Top	Wood	Blue	Friction	8	Negative
1	1	106	Classroom 106	Door Casing	Metal	Blue	Friction	2	Negative
1	1	106	Classroom 106	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	106	Classroom 106	Door Casing	Metal	Blue	Friction	2	Negative
1	1	106	Classroom 106	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	106	Classroom 106	Pipe Jacket	Metal	Blue	None	0	Negative
1	1	106	Classroom 106	Ceiling	Concrete	White	None	0	Negative
1	1	106	Classroom 106	Floor	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	W1	Concrete	Blue	None	0	Negative
1	1	107	Classroom 107	W2	Concrete	Blue	None	0	Negative
1	1	107	Classroom 107	W3	Concrete	Blue	None	0	Negative
1	1	107	Classroom 107	W4	Concrete	Blue	None	0	Negative
1	1	107	Classroom 107	Univent	Metal	Blue	Friction	6	Negative
1	1	107	Classroom 107	Univent Top	Wood	Blue	Friction	5	Negative
1	1	107	Classroom 107	Door Casing	Metal	Blue	Friction	2	Negative
1	1	107	Classroom 107	Door Casing	Metal	Blue	Friction	2	Negative
1	1	107	Classroom 107	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	107	Classroom 107	Door Casing	Metal	Blue	Friction	2	Negative
1	1	107	Classroom 107	Pipe Jacket	Metal	Blue	None	0	Negative
1	1	107	Classroom 107	Ceiling	Concrete	White	None	0	N/A
1	1	107	Classroom 107	Floor	N/A	N/A	N/A	N/A	N/A
1	1	102	Classroom 102	W1	Concrete	Blue	None	0	Negative
1	1	102	Classroom 102	W2	Concrete	Blue	None	0	Negative
1	1	102	Classroom 102	W3	Concrete	Blue	None	0	Negative
1	1	102	Classroom 102	W4	Concrete	Blue	None	0	Negative
1	1	102	Classroom 102	Univent	Metal	Blue	Friction	6	Negative
1	1	102	Classroom 102	Univent Top	Wood	Blue	Friction	5	Negative
1	1	102	Classroom 102	Door Casing	Metal	Blue	Friction	2	Negative
1	1	102	Classroom 102	Door Casing	Metal	Blue	Friction	2	Negative

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	102	Classroom 102	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	102	Classroom 102	Door Casing	Metal	Blue	Friction	2	Negative
1	1	102	Classroom 102	Pipe Jacket	Metal	Blue	None	0	Negative
1	1	102	Classroom 102	Ceiling	Concrete	White	None	0	Negative
1	1	102	Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A
1	1	101	Classroom 101	W1	Concrete	Blue	None	0	Negative
1	1	101	Classroom 101	W2	Concrete	Blue	None	0	Negative
1	1	101	Classroom 101	W3	Concrete	Blue	None	0	Negative
1	1	101	Classroom 101	W4	Concrete	Blue	None	0	Negative
1	1	101	Classroom 101	Univent	Metal	Blue	Friction	9	Negative
1	1	101	Classroom 101	Univent Top	Wood	Blue	Friction	7	Negative
1	1	101	Classroom 101	Door Casing	Metal	Blue	Friction	3	Negative
1	1	101	Classroom 101	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	101	Classroom 101	Door Casing	Metal	Blue	Friction	2	Negative
1	1	101	Classroom 101	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	101	Classroom 101	Pipe Jacket	Metal	Blue	None	0	Negative
1	1	101	Classroom 101	Ceiling	Concrete	White	None	0	Negative
1	1	101	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	W1	Concrete	Blue	None	0	Negative
1	1	108	Classroom 108	W2	Concrete	Blue	None	0	Negative
1	1	108	Classroom 108	W3	Concrete	Blue	None	0	Negative
1	1	108	Classroom 108	W4	Concrete	Blue	None	0	Negative
1	1	108	Classroom 108	Univent	Metal	Blue	Friction	10	Negative
1	1	108	Classroom 108	Univent Top	Wood	Blue	Friction	8	Negative
1	1	108	Classroom 108	Door Casing	Metal	Blue	Friction	2	Negative
1	1	108	Classroom 108	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	108	Classroom 108	Door Casing	Metal	Blue	Friction	2	Negative
1	1	108	Classroom 108	Door Casing	Metal	Blue	Friction	1	Negative
1	1	108	Classroom 108	Ceiling	Concrete	White	None	0	Negative
1	1	108	Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A
1	1	100	Conference Room next to Classroom 101	W1	Concrete	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	W2	Concrete	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	W3	Concrete	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	W4	Concrete	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	Door Casing	Metal	Blue	Friction	<1	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report**Inspector Name and Certificate Number:
Christopher Karoly - 006424****John McCloskey School****Inspection Company: Criterion
Laboratories****8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	100	Conference Room next to Classroom 101	Radiator	Metal	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	Pipe Jacket	Metal	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	Chair Rail 1	Wood	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	Chair Rail 2	Wood	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	Chair Rail 3	Wood	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	Chair Rail 4	Wood	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	Ceiling	Concrete	White	None	0	Negative
1	1	100	Conference Room next to Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A
1	1	100A	Conference Room/Teacher's Lounge next to Classroom 101 Restroom	W1	Concrete	Blue	None	0	Negative
1	1	100A	Conference Room/Teacher's Lounge next to Classroom 101 Restroom	W2	Concrete	Blue	None	0	Negative
1	1	100A	Conference Room/Teacher's Lounge next to Classroom 101 Restroom	W3	Concrete	Blue	None	0	Negative
1	1	100A	Conference Room/Teacher's Lounge next to Classroom 101 Restroom	W4	Concrete	Blue	None	0	Negative
1	1	100A	Conference Room/Teacher's Lounge next to Classroom 101 Restroom	Duct	Metal	White	None	0	Negative
1	1	100A	Conference Room/Teacher's Lounge next to Classroom 101 Restroom	Door Casing	Metal	Blue	Friction	2	Negative
1	1	100A	Conference Room/Teacher's Lounge next to Classroom 101 Restroom	Ceiling	Concrete	White	None	0	Negative
1	1	100A	Conference Room/Teacher's Lounge next to Classroom 101 Restroom	Floor	N/A	N/A	N/A	N/A	Negative
1	1	115A	Custodial Closet Next to Classroom 108	W1	Concrete	White	None	0	Negative
1	1	115A	Custodial Closet Next to Classroom 108	W2	Concrete	White	None	0	Negative
1	1	115A	Custodial Closet Next to Classroom 108	W3	Concrete	White	None	0	Negative
1	1	115A	Custodial Closet Next to Classroom 108	W4	Concrete	White	None	0	Negative
1	1	115A	Custodial Closet Next to Classroom 108	Ceiling	Concrete	White	None	0	Negative
1	1	115A	Custodial Closet Next to Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A
1	1	115PC	Pipe Chase in Custodial Closet Next to Classroom 108	W1	N/A	N/A	N/A	N/A	N/A
1	1	115PC	Pipe Chase in Custodial Closet Next to Classroom 108	W2	N/A	N/A	N/A	N/A	N/A
1	1	115PC	Pipe Chase in Custodial Closet Next to Classroom 108	W3	N/A	N/A	N/A	N/A	N/A
1	1	115PC	Pipe Chase in Custodial Closet Next to Classroom 108	W4	N/A	N/A	N/A	N/A	N/A
1	1	115PC	Pipe Chase in Custodial Closet Next to Classroom 108	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	115PC	Pipe Chase in Custodial Closet Next to Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report

Inspector Name and Certificate Number:
Christopher Karoly - 006424

John McCloskey School

Inspection Company: Criterion
Laboratories

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	127	Counselor's Office adjacent to Classroom 101	W1	Concrete	Blue	None	0	Negative
1	1	127	Counselor's Office adjacent to Classroom 101	W2	Concrete	Blue	None	0	Negative
1	1	127	Counselor's Office adjacent to Classroom 101	W3	Concrete	Blue	None	0	Negative
1	1	127	Counselor's Office adjacent to Classroom 101	W4	Concrete	Blue	None	0	Negative
1	1	127	Counselor's Office adjacent to Classroom 101	Ceiling	Concrete	White	None	0	Negative
1	1	127	Counselor's Office adjacent to Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A
1	1	115	Girl's Restroom next to Classroom 108	W1	Concrete	Blue	None	0	Negative
1	1	115	Girl's Restroom next to Classroom 108	W2	Concrete	Blue	None	0	Negative
1	1	115	Girl's Restroom next to Classroom 108	W3	Concrete	Blue	None	0	Negative
1	1	115	Girl's Restroom next to Classroom 108	W4	Concrete	Blue	None	0	Negative
1	1	115	Girl's Restroom next to Classroom 108	Door Casing	Metal	Blue	Friction	2	Negative
1	1	115	Girl's Restroom next to Classroom 108	Door	Metal	Brown	None	0	Negative
1	1	115	Girl's Restroom next to Classroom 108	Door Casing	Metal	Brown	Friction	2	Negative
1	1	115	Girl's Restroom next to Classroom 108	Pipe Jacket	Metal	Brown	None	0	Negative
1	1	115	Girl's Restroom next to Classroom 108	Radiator	Metal	Brown	None	0	Negative
1	1	115	Girl's Restroom next to Classroom 108	Ceiling	Concrete	White	None	0	Negative
1	1	115	Girl's Restroom next to Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A
1	1	127A	Storage Closet next to Teacher's Lounge adjacent to Classroom 108	W1	Concrete	Yellow	None	0	Negative
1	1	127A	Storage Closet next to Teacher's Lounge adjacent to Classroom 108	W2	Concrete	Yellow	None	0	Negative
1	1	127A	Storage Closet next to Teacher's Lounge adjacent to Classroom 108	W3	Concrete	Yellow	None	0	Negative
1	1	127A	Storage Closet next to Teacher's Lounge adjacent to Classroom 108	W4	Sheetrock	Tan	None	0	Negative
1	1	127A	Storage Closet next to Teacher's Lounge adjacent to Classroom 108	Door Casing	Metal	Blue	Friction	2	Negative
1	1	127A	Storage Closet next to Teacher's Lounge adjacent to Classroom 108	Ceiling	Concrete	White	None	0	Negative
1	1	127A	Storage Closet next to Teacher's Lounge adjacent to Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A
1	1	116A	Nurse Office Waiting Area	W1	Concrete	Blue	None	0	Negative
1	1	116A	Nurse Office Waiting Area	W2	Concrete	Blue	None	0	Negative
1	1	116A	Nurse Office Waiting Area	W3	Concrete	Blue	None	0	Negative
1	1	116A	Nurse Office Waiting Area	W4	Concrete	Blue	None	0	Negative
1	1	116A	Nurse Office Waiting Area	Door Casing 1	Metal	Blue	Friction	2	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment ReportInspector Name and Certificate Number:
Christopher Karoly - 006424**John McCloskey School**Inspection Company: Criterion
Laboratories**8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	116A	Nurse Office Waiting Area	Door Casing 3	Metal	Blue	Friction	1	Negative
1	1	116A	Nurse Office Waiting Area	Ceiling	Concrete	White	None	0	Negative
1	1	116A	Nurse Office Waiting Area	Floor	N/A	N/A	N/A	N/A	N/A
1	1	116B	Nurse's Office	W1	Concrete	Blue	None	0	Negative
1	1	116B	Nurse's Office	W2	Concrete	Blue	None	0	Negative
1	1	116B	Nurse's Office	W3	Concrete	Blue	None	0	Negative
1	1	116B	Nurse's Office	W4	Concrete	Blue	None	0	Negative
1	1	116B	Nurse's Office	Chair Rail 1	Wood	Blue	None	0	Negative
1	1	116B	Nurse's Office	Chair Rail 2	Wood	Blue	None	0	Negative
1	1	116B	Nurse's Office	Chair Rail 3	Wood	Blue	None	0	Negative
1	1	116B	Nurse's Office	Chair Rail 4	Wood	Blue	None	0	Negative
1	1	116B	Nurse's Office	Door Casing 4	Metal	Blue	Friction	3	Negative
1	1	116B	Nurse's Office	Door Casing 1	Metal	Blue	Friction	<1	Negative
1	1	116B	Nurse's Office	Door Casing 2	Metal	Blue	Friction	3	Negative
1	1	116B	Nurse's Office	Radiator	Metal	Blue	None	0	Negative
1	1	116B	Nurse's Office	Ceiling	Concrete	White	None	0	Negative
1	1	116B	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A
1	1	116	Nurse's Patient Room	W1	Concrete	Blue	None	0	Negative
1	1	116	Nurse's Patient Room	W2	Concrete	Blue	None	0	Negative
1	1	116	Nurse's Patient Room	W3	Concrete	Blue	None	0	Negative
1	1	116	Nurse's Patient Room	W4	Concrete	Blue	None	0	Negative
1	1	116	Nurse's Patient Room	Door Casing	Metal	Blue	Friction	5	Negative
1	1	116	Nurse's Patient Room	Door Casing	Metal	Blue	Friction	3	Negative
1	1	116	Nurse's Patient Room	Door Casing	Metal	Blue	Friction	3	Negative
1	1	116	Nurse's Patient Room	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	116	Nurse's Patient Room	Radiator	Metal	Blue	None	0	Negative
1	1	116	Nurse's Patient Room	Pipe Jacket	Metal	Blue	None	0	Negative
1	1	116	Nurse's Patient Room	Ceiling	Concrete	White	None	0	Negative
1	1	116	Nurse's Patient Room	Floor	N/A	N/A	N/A	N/A	N/A
1	1	116S	Nurse's Office Closet	W1	Concrete	Green	None	0	Negative
1	1	116S	Nurse's Office Closet	W2	Concrete	Green	None	0	Negative
1	1	116S	Nurse's Office Closet	W3	Concrete	Green	None	0	Negative
1	1	116S	Nurse's Office Closet	W4	Concrete	Green	None	0	Negative
1	1	116S	Nurse's Office Closet	Ceiling	Concrete	Green	None	0	Negative
1	1	116S	Nurse's Office Closet	Floor	N/A	N/A	N/A	N/A	N/A

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report

Inspector Name and Certificate Number:
Christopher Karoly - 006424

John McCloskey School

Inspection Company: Criterion
Laboratories

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	116S	Nurse's Office Closet	Duct	Metal	Green	None	0	Negative
1	1	116S	Nurse's Office Closet	Door Casing	Metal	Green	None	0	Negative
1	1	116S	Nurse's Office Closet	Shelf	Wood	Green	None	0	Negative
1	1	116C	Nurse's Office Restroom	W1	Concrete	White	None	0	Negative
1	1	116C	Nurse's Office Restroom	W2	Concrete	White	None	0	Negative
1	1	116C	Nurse's Office Restroom	W3	Concrete	White	None	0	Negative
1	1	116C	Nurse's Office Restroom	W4	Concrete	White	None	0	Negative
1	1	116C	Nurse's Office Restroom	Door Casing	Metal	Grey	None	0	Negative
1	1	116C	Nurse's Office Restroom	Ceiling	Concrete	White	None	0	Negative
1	1	116C	Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A
1	1	L101	Storage in Library	W1	Concrete	Blue/White	None	0	Negative
1	1	L101	Storage in Library	W2	Concrete	Blue/White	None	0	Negative
1	1	L101	Storage in Library	W3	Concrete	Blue/White	None	0	Negative
1	1	L101	Storage in Library	W4	Concrete	Blue/White	None	0	Negative
1	1	L101	Storage in Library	Door Casing 1	Metal	Blue	None	0	Negative
1	1	L101	Storage in Library	Door Casing 4	Metal	Blue	None	0	Negative
1	1	L101	Storage in Library	Radiator	Metal	Blue	None	0	Negative
1	1	L101	Storage in Library	Ceiling	Concrete	White	None	0	Negative
1	1	L101	Storage in Library	Floor	N/A	N/A	N/A	N/A	N/A
1	1	LH	Hallway to Library	W1	Concrete	White	None	0	Negative
1	1	LH	Hallway to Library	W2	Concrete	White	None	0	Negative
1	1	LH	Hallway to Library	W3	Concrete	White	None	0	Negative
1	1	LH	Hallway to Library	W4	Concrete	White	None	0	Negative
1	1	LH	Hallway to Library	Radiator	Metal	White	None	0	Negative
1	1	LH	Hallway to Library	Ceiling	Concrete	White	None	0	Negative
1	1	LH	Hallway to Library	Floor	N/A	N/A	N/A	N/A	N/A
1	1	126	Principal's Office	W1	Concrete	Blue	None	0	Negative
1	1	126	Principal's Office	W2	Concrete	Blue	None	0	Negative
1	1	126	Principal's Office	W3	Concrete	Blue	None	0	Negative
1	1	126	Principal's Office	W4	Concrete	Blue	None	0	Negative
1	1	126	Principal's Office	Chair Rail 1	Wood	Blue	None	0	Negative
1	1	126	Principal's Office	Chair Rail 2	Wood	Blue	None	0	Negative
1	1	126	Principal's Office	Chair Rail 3	Wood	Blue	None	0	Negative
1	1	126	Principal's Office	Chair Rail 4	Wood	Blue	None	0	Negative
1	1	126	Principal's Office	Radiator 3	Metal	Blue	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report

Inspector Name and Certificate Number:
Christopher Karoly - 006424

John McCloskey School

Inspection Company: Criterion
Laboratories

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	126	Principal's Office	Door Casing 1	Metal	Blue	None	0	Negative
1	1	126	Principal's Office	Door Casing 2	Metal	Blue	Friction	<1	Negative
1	1	126	Principal's Office	Door Casing 2	Metal	Blue	Friction	2	Negative
1	1	126	Principal's Office	Door Casing 2	Metal	Blue	Friction	<1	Negative
1	1	126	Principal's Office	Ceiling	Concrete	White	None	0	Negative
1	1	126	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A
1	1	126C	Principal's Office Storage Closet	W1	No Access	No Access	No Access	No Access	No Access
1	1	126C	Principal's Office Storage Closet	W2	No Access	No Access	No Access	No Access	No Access
1	1	126C	Principal's Office Storage Closet	W3	No Access	No Access	No Access	No Access	No Access
1	1	126C	Principal's Office Storage Closet	W4	No Access	No Access	No Access	No Access	No Access
1	1	126C	Principal's Office Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access
1	1	126C	Principal's Office Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access
1	1	126A	Principal's Office Restroom	W1	Concrete	Blue	None	0	Negative
1	1	126A	Principal's Office Restroom	W2	Concrete	Blue	None	0	Negative
1	1	126A	Principal's Office Restroom	W3	Concrete	Blue	None	0	Negative
1	1	126A	Principal's Office Restroom	W4	Concrete	Blue	None	0	Negative
1	1	126A	Principal's Office Restroom	Duct	Metal	White	None	0	Negative
1	1	126A	Principal's Office Restroom	Door Casing	Metal	Blue	Friction	2	Negative
1	1	126A	Principal's Office Restroom	Ceiling	Concrete	White	None	0	Negative
1	1	126A	Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A
1	1	121A	Main Office Storage Closet	W1	Concrete	Yellow	None	0	Negative
1	1	121A	Main Office Storage Closet	W2	Concrete	Yellow	None	0	Negative
1	1	121A	Main Office Storage Closet	W3	Concrete	Yellow	None	0	Negative
1	1	121A	Main Office Storage Closet	W4	Concrete	Yellow	None	0	Negative
1	1	121A	Main Office Storage Closet	Door Casing	Metal	Blue	None	0	Negative
1	1	121A	Main Office Storage Closet	Conduit	Metal	Yellow	None	0	Negative
1	1	121A	Main Office Storage Closet	Ceiling	Concrete	White	None	0	Negative
1	1	121A	Main Office Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A
1	1	121	Main Office	W1	Concrete	Blue	None	0	Negative
1	1	121	Main Office	W2	Concrete	Blue	None	0	Negative
1	1	121	Main Office	W3	Concrete	Blue	None	0	Negative
1	1	121	Main Office	W4	Concrete	Blue	None	0	Negative
1	1	121	Main Office	Chair Rail 1	Wood	Blue	None	0	Negative
1	1	121	Main Office	Chair Rail 2	Wood	Blue	None	0	Negative
1	1	121	Main Office	Chair Rail 3	Wood	Blue	None	0	Negative

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories**Lead Safe Certification Assessment Report****John McCloskey School****8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	121	Main Office	Chair Rail 4	Wood	Blue	None	0	Negative
1	1	121	Main Office	Radiator 2	Metal	Blue	None	0	Negative
1	1	121	Main Office	Radiator 3	Metal	Blue	None	0	Negative
1	1	121	Main Office	Door Casing 1	Metal	Blue	Friction	<1	Negative
1	1	121	Main Office	Door Casing 4	Metal	Blue	Friction	2	Negative
1	1	121	Main Office	Door Casing 4	Metal	Blue	Friction	<1	Negative
1	1	121	Main Office	Ceiling	Concrete	White	None	0	Negative
1	1	121	Main Office	Floor	N/A	N/A	N/A	N/A	N/A
1	1	118	MDF Computer Server Room (across from Main Office)	W1	No Access	No Access	No Access	No Access	No Access
1	1	118	MDF Computer Server Room (across from Main Office)	W2	No Access	No Access	No Access	No Access	No Access
1	1	118	MDF Computer Server Room (across from Main Office)	W3	No Access	No Access	No Access	No Access	No Access
1	1	118	MDF Computer Server Room (across from Main Office)	W4	No Access	No Access	No Access	No Access	No Access
1	1	118	MDF Computer Server Room (across from Main Office)	Ceiling	No Access	No Access	No Access	No Access	No Access
1	1	118	MDF Computer Server Room (across from Main Office)	Floor	No Access	No Access	No Access	No Access	No Access
1	1	118A	Storage Room next to MDF Computer Server Room (across from Main Office)	W1	Concrete	Yellow	None	0	Negative
1	1	118A	Storage Room next to MDF Computer Server Room (across from Main Office)	W2	Concrete	Yellow	None	0	Negative
1	1	118A	Storage Room next to MDF Computer Server Room (across from Main Office)	W3	Concrete	Yellow	None	0	Negative
1	1	118A	Storage Room next to MDF Computer Server Room (across from Main Office)	W4	Concrete	Yellow	None	0	Negative
1	1	118A	Storage Room next to MDF Computer Server Room (across from Main Office)	Door Casing	Metal	Blue	None	0	Negative
1	1	118A	Storage Room next to MDF Computer Server Room (across from Main Office)	Duct	Metal	White	None	0	Negative
1	1	118A	Storage Room next to MDF Computer Server Room (across from Main Office)	Ceiling	Concrete	White	None	0	Negative
1	1	118A	Storage Room next to MDF Computer Server Room (across from Main Office)	Floor	N/A	N/A	N/A	N/A	N/A
1	1	117	Speech and psych office across from auditorium labeled Medical Office	W1	Concrete	Blue	None	0	Negative

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	117	Speech and psych office across from auditorium labeled Medical Office	W2	Concrete	Blue	None	0	Negative
1	1	117	Speech and psych office across from auditorium labeled Medical Office	W3	Concrete	Blue	None	0	Negative
1	1	117	Speech and psych office across from auditorium labeled Medical Office	W4	Concrete	Blue	None	0	Negative
1	1	117	Speech and psych office across from auditorium labeled Medical Office	Ceiling	Concrete	White	None	0	Negative
1	1	117	Speech and psych office across from auditorium labeled Medical Office	Floor	N/A	N/A	N/A	N/A	N/A
1	1	119	Girl's Restroom /Storage Across From Auditorium	W1	Concrete	White	None	0	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	W2	Concrete	White	None	0	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	W3	Concrete	White	None	0	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	W4	Concrete	White	None	0	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	Duct	Metal	White	None	0	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	Radiator	Metal	Grey	None	0	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	Door Casing	Metal	Blue	Friction	2	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	Ceiling	Concrete	White	None	0	Negative
1	1	119	Girl's Restroom /Storage Across From Auditorium	Floor	N/A	N/A	N/A	N/A	N/A
1	1	119PC	Pipe Chase in Girl's Restroom /Storage Across From Auditorium	W1	N/A	N/A	N/A	N/A	N/A
1	1	119PC	Pipe Chase in Girl's Restroom /Storage Across From Auditorium	W2	N/A	N/A	N/A	N/A	N/A
1	1	119PC	Pipe Chase in Girl's Restroom /Storage Across From Auditorium	W3	N/A	N/A	N/A	N/A	N/A
1	1	119PC	Pipe Chase in Girl's Restroom /Storage Across From Auditorium	W4	N/A	N/A	N/A	N/A	N/A
1	1	119PC	Pipe Chase in Girl's Restroom /Storage Across From Auditorium	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	119PC	Pipe Chase in Girl's Restroom /Storage Across From Auditorium	Floor	N/A	N/A	N/A	N/A	N/A
1	1	119A	Fan Room across from Auditorium	W1	No Access	No Access	No Access	No Access	No Access
1	1	119A	Fan Room across from Auditorium	W2	No Access	No Access	No Access	No Access	No Access
1	1	119A	Fan Room across from Auditorium	W3	No Access	No Access	No Access	No Access	No Access
1	1	119A	Fan Room across from Auditorium	W4	No Access	No Access	No Access	No Access	No Access
1	1	119A	Fan Room across from Auditorium	Ceiling	No Access	No Access	No Access	No Access	No Access

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	119A	Fan Room across from Auditorium	Floor	No Access	No Access	No Access	No Access	No Access
1	1	123	Boy's Restroom across from Auditorium	W1	Concrete	White	None	0	Negative
1	1	123	Boy's Restroom across from Auditorium	W2	Concrete	White	None	0	Negative
1	1	123	Boy's Restroom across from Auditorium	W3	Concrete	White	None	0	Negative
1	1	123	Boy's Restroom across from Auditorium	W4	Concrete	White	None	0	Negative
1	1	123	Boy's Restroom across from Auditorium	Duct	Metal	White	None	0	Negative
1	1	123	Boy's Restroom across from Auditorium	Radiator	Metal	Grey	None	0	Negative
1	1	123	Boy's Restroom across from Auditorium	Door Casing	Metal	Blue	Friction	<1	Negative
1	1	123	Boy's Restroom across from Auditorium	Door Casing	Metal	Blue	Friction	2	Negative
1	1	123	Boy's Restroom across from Auditorium	Door Casing	Metal	Brown	Friction	3	Negative
1	1	123	Boy's Restroom across from Auditorium	Door Casing	Metal	Brown	Friction	2	Negative
1	1	123	Boy's Restroom across from Auditorium	Ceiling	Concrete	White	None	0	N/A
1	1	123	Boy's Restroom across from Auditorium	Floor	N/A	N/A	N/A	N/A	N/A
1	1	123PC	Pipe Chase in Boy's Restroom across from Auditorium	W1	No Access	No Access	No Access	No Access	No Access
1	1	123PC	Pipe Chase in Boy's Restroom across from Auditorium	W2	No Access	No Access	No Access	No Access	No Access
1	1	123PC	Pipe Chase in Boy's Restroom across from Auditorium	W3	No Access	No Access	No Access	No Access	No Access
1	1	123PC	Pipe Chase in Boy's Restroom across from Auditorium	W4	No Access	No Access	No Access	No Access	No Access
1	1	123PC	Pipe Chase in Boy's Restroom across from Auditorium	Ceiling	No Access	No Access	No Access	No Access	No Access
1	1	123PC	Pipe Chase in Boy's Restroom across from Auditorium	Floor	No Access	No Access	No Access	No Access	No Access
1	1	122	Food Service Area	W1	N/A	N/A	N/A	N/A	N/A
1	1	122	Food Service Area	W2	N/A	N/A	N/A	N/A	N/A
1	1	122	Food Service Area	W3	N/A	N/A	N/A	N/A	N/A
1	1	122	Food Service Area	W4	N/A	N/A	N/A	N/A	N/A
1	1	122	Food Service Area	Duct	Metal	White	None	0	Negative
1	1	122	Food Service Area	Door Casing	Metal	Grey	None	0	Negative
1	1	122	Food Service Area	Door Casing	Metal	Blue	None	0	Negative
1	1	122	Food Service Area	Gate	Metal	Grey	None	0	Negative
1	1	122	Food Service Area	Ceiling	Concrete	White	None	0	Negative
1	1	122	Food Service Area	Floor	No Access	No Access	No Access	No Access	No Access
1	1	122A	Food Service Area Storage	W1	No Access	No Access	No Access	No Access	No Access
1	1	122A	Food Service Area Storage	W2	No Access	No Access	No Access	No Access	No Access
1	1	122A	Food Service Area Storage	W3	No Access	No Access	No Access	No Access	No Access
1	1	122A	Food Service Area Storage	W4	No Access	No Access	No Access	No Access	No Access
1	1	122A	Food Service Area Storage	Ceiling	No Access	No Access	No Access	No Access	No Access
1	1	122A	Food Service Area Storage	Floor	No Access	No Access	No Access	No Access	No Access

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	124	Gym	W1	Concrete	White	None	0	Negative
1	1	124	Gym	W2	Concrete	White	None	0	Negative
1	1	124	Gym	W3	Concrete	White	None	0	Negative
1	1	124	Gym	W4	Concrete	White	None	0	Negative
1	1	124	Gym	Ceiling	Concrete	White	None	0	No Access
1	1	124	Gym	Floor	N/A	N/A	N/A	N/A	N/A
1	1	124	Gym	Door Casing 1	Metal	Blue	Friction	2	Negative
1	1	124	Gym	Door Casing 1	Metal	Blue	Friction	1	Negative
1	1	124	Gym	Door Casing 4	Metal	Blue	Friction	1	Negative
1	1	124	Gym	Door Casing 2	Metal	Brown	Friction	2	Negative
1	1	124	Gym	Door 2	Metal	Brown	Friction	2	Negative
1	1	124	Gym	Radiator	Metal	Blue	None	0	Negative
1	1	124	Gym	Inlet	Metal	Blue	Flaking	25	Negative
1	1	124	Gym	Backboard	Wood	White	None	0	Negative
1	1	124	Gym	Pipe Behind backboard	Metal	White	None	0	Negative
1	1	124	Gym	Basketball hoop attachment	Wood	Blue/white	Flaking	20	Positive
1	1	124A	Gym Teacher's Office	W1	Concrete	White	None	0	Negative
1	1	124A	Gym Teacher's Office	W2	Concrete	White	None	0	Negative
1	1	124A	Gym Teacher's Office	W3	Concrete	White	None	0	Negative
1	1	124A	Gym Teacher's Office	W4	Concrete	White	None	0	Negative
1	1	124A	Gym Teacher's Office	Radiator	Metal	White	None	0	Negative
1	1	124A	Gym Teacher's Office	Door	Metal	Brown	None	0	Negative
1	1	124A	Gym Teacher's Office	Door Casing	Metal	Brown	None	0	Negative
1	1	124A	Gym Teacher's Office	Door Casing	Metal	Blue	None	0	Negative
1	1	124A	Gym Teacher's Office	Wood Plank	Wood	White	Flaking	1	Positive
1	1	124A	Gym Teacher's Office	Ceiling	Concrete	White	None	0	N/A
1	1	124A	Gym Teacher's Office	Floor	N/A	N/A	N/A	N/A	N/A
1	1	125	Auditorium	W1	Concrete	White	None	0	Negative
1	1	125	Auditorium	W2	Concrete	White	None	0	Negative
1	1	125	Auditorium	W3	Concrete	White	None	0	Negative
1	1	125	Auditorium	W4	Concrete	White	None	0	Negative
1	1	125	Auditorium	Door Casing	Metal	Brown	None	0	Negative
1	1	125	Auditorium	Door Casing	Metal	Brown	None	0	Negative

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	125	Auditorium	Door Casing	Metal	Brown	None	0	Negative
1	1	125	Auditorium	Door	Metal	Brown	None	0	Negative
1	1	125	Auditorium	Radiator	Metal	Brown	None	0	Negative
1	1	125	Auditorium	Ceiling	No Access	No Access	No Access	No Access	No Access
1	1	125	Auditorium	Floor	N/A	N/A	N/A	N/A	N/A
1	1	125A	Auditorium Stage	W1	N/A	N/A	N/A	N/A	N/A
1	1	125A	Auditorium Stage	W2	Concrete	White	None	0	Negative
1	1	125A	Auditorium Stage	W3	Concrete	White	None	0	Negative
1	1	125A	Auditorium Stage	W4	Concrete	White	None	0	Negative
1	1	125A	Auditorium Stage	Door Casing	Metal	Brown	None	0	Negative
1	1	125A	Auditorium Stage	Door Casing	Metal	Brown	None	0	Negative
1	1	125A	Auditorium Stage	Ceiling	No Access	No Access	No Access	No Access	No Access
1	1	125A	Auditorium Stage	Floor	N/A	N/A	N/A	N/A	N/A
1	1	125B	Room between Hallway and Auditorium Stage	W1	Concrete	White	None	0	N/A
1	1	125B	Room between Hallway and Auditorium Stage	W2	Concrete	White	None	0	N/A
1	1	125B	Room between Hallway and Auditorium Stage	W3	Concrete	White	None	0	N/A
1	1	125B	Room between Hallway and Auditorium Stage	W4	Concrete	White	None	0	N/A
1	1	125B	Room between Hallway and Auditorium Stage	Ceiling	Concrete	White	None	0	N/A
1	1	125B	Room between Hallway and Auditorium Stage	Floor	N/A	N/A	N/A	N/A	N/A
1	1	L100	Library	W1	Concrete	Light Blue	None	0	Negative
1	1	L100	Library	W1	Concrete	White	None	0	Negative
1	1	L100	Library	W2	Concrete	Light Blue	None	0	Negative
1	1	L100	Library	W2	Concrete	White	None	0	Negative
1	1	L100	Library	W3	Concrete	Light Blue	None	0	Negative
1	1	L100	Library	W3	Concrete	White	None	0	Negative
1	1	L100	Library	W4	Concrete	Light Blue	None	0	Negative
1	1	L100	Library	W4	Concrete	White	None	0	Negative
1	1	L100	Library	Door Casing 1	Metal	Blue	None	0	Negative
1	1	L100	Library	Door Casing 2	Metal	Blue	None	0	Negative
1	1	L100	Library	Door 1	Metal	Blue	None	0	Negative
1	1	L100	Library	Door Casing 4	Metal	Brown	None	0	Negative
1	1	L100	Library	Door 4	Metal	Brown	None	0	Negative
1	1	L100	Library	Radiator	Metal	Blue	None	0	Negative
1	1	L100	Library	Pipe	Metal	Blue	None	0	Negative
1	1	L100	Library	Window Casing 3	Metal	Blue	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report

Inspector Name and Certificate Number:
Christopher Karoly - 006424

John McCloskey School

Inspection Company: Criterion
Laboratories

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	1	L100	Library	Window Casing 2	Metal	Blue	None	0	Negative
1	1	L100	Library	Ceiling	Concrete	White	None	0	Negative
1	1	L100	Library	Floor	N/A	N/A	N/A	N/A	N/A
1	1	H15	Hallway Next to Main Office Through Office 104A	W1	N/A	N/A	N/A	N/A	N/A
1	1	H15	Hallway Next to Main Office Through Office 104A	W2	Concrete	White	None	0	Negative
1	1	H15	Hallway Next to Main Office Through Office 104A	W3	N/A	N/A	N/A	N/A	N/A
1	1	H15	Hallway Next to Main Office Through Office 104A	W4	Concrete	White	None	0	Negative
1	1	H15	Hallway Next to Main Office Through Office 104A	Univent 2	Metal	Blue	Friction	2	Negative
1	1	H15	Hallway Next to Main Office Through Office 104A	Univent 4	Metal	Blue	Friction	5	Negative
1	1	H15	Hallway Next to Main Office Through Office 104A	Ceiling	Concrete	White	None	0	Negative
1	1	H15	Hallway Next to Main Office Through Office 104A	Floor	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway next to Gym and Auditorium	W1	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway next to Gym and Auditorium	W2	Concrete	White	None	0	Negative
1	1	H13	Hallway next to Gym and Auditorium	W3	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway next to Gym and Auditorium	W4	Concrete	White	None	0	Negative
1	1	H13	Hallway next to Gym and Auditorium	Ceiling	Concrete	White	None	0	Negative
1	1	H13	Hallway next to Gym and Auditorium	Floor	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell Next to Classroom 208	W1	Concrete	White	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	W2	Concrete	White	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	W3	Concrete	White	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	W4	Concrete	White	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Stair Post	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Stair Tread	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Stair Stringer	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Univent	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Pipe Jacket	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Door 1	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Door Casing 1	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Door 3	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Door Casing 3	Metal	Blue	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Ceiling	Concrete	White	None	0	Negative
1	2	S25	Stairwell Next to Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A
1	1	H16	Hallway between Old Building and New building between restrooms	W1	N/A	N/A	N/A	N/A	N/A

4/18/2022 - 5/4/2022

Inspector Name and Certificate Number:
Christopher Karoly - 006424Inspection Company: Criterion
Laboratories

Lead Safe Certification Assessment Report

John McCloskey School

8500 Pickering Avenue, Philadelphia, PA 19150

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	H16	Hallway between Old Building and New building between restrooms	W2	Concrete	White	None	0	N/A
1	1	H16	Hallway between Old Building and New building between restrooms	W3	N/A	N/A	N/A	N/A	N/A
1	1	H16	Hallway between Old Building and New building between restrooms	W4	Concrete	White	None	0	N/A
1	1	H16	Hallway between Old Building and New building between restrooms	Ceiling	Concrete	White	None	0	N/A
1	1	H16	Hallway between Old Building and New building between restrooms	Floor	N/A	N/A	N/A	N/A	N/A
2	1	H11	Hallway near Classrooms 109 through 112	W1	N/A	N/A	N/A	N/A	N/A
2	1	H11	Hallway near Classrooms 109 through 112	W2	Metal	White	Flaking	80	Negative
2	1	H11	Hallway near Classrooms 109 through 112	W3	Sheetrock	White	None	0	Negative
2	1	H11	Hallway near Classrooms 109 through 112	W4	Metal	White	Flaking	120	Negative
2	1	H11	Hallway near Classrooms 109 through 112	Baseboard 2	Wood	Blue	None	0	Negative
2	1	H11	Hallway near Classrooms 109 through 112	Baseboard 4	Wood	Blue	None	0	Negative
2	1	H11	Hallway near Classrooms 109 through 112	Radiator 2	Metal	Blue	Friction	4	Negative
2	1	H11	Hallway near Classrooms 109 through 112	Radiator 4	Metal	Blue	Friction	4	Negative
2	1	H11	Hallway near Classrooms 109 through 112	Pipe Jacket 2	Metal	Blue	None	0	Negative
2	1	H11	Hallway near Classrooms 109 through 112	Pipe Jacket 4	Metal	Blue	None	0	Negative
2	1	H11	Hallway near Classrooms 109 through 112	Ceiling	Metal	White	None	0	N/A
2	1	H11	Hallway near Classrooms 109 through 112	Floor	N/A	N/A	N/A	N/A	N/A
1	B	1	Boiler Room	W1	Concrete	White	Flaking	30	Negative
1	B	1	Boiler Room	W2	Concrete	White	Flaking	40	Negative
1	B	1	Boiler Room	W3	Concrete	White	Flaking	60	Negative
1	B	1	Boiler Room	W4	Concrete	White	Flaking	35	Negative
1	B	1	Boiler Room	Boiler	Metal	Grey	Flaking	100	Negative
1	B	1	Boiler Room	Panel Box	Metal	Grey	None	0	Negative
1	B	1	Boiler Room	Stair Stringer	Metal	Grey	None	0	Negative
1	B	1	Boiler Room	Handrail	Metal	Grey	None	0	Negative
1	B	1	Boiler Room	Stair	Metal	Grey	None	0	Negative
1	B	1	Boiler Room	Ceiling	Concrete	Grey	Flaking	120	Negative
1	B	1	Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A
1	B	1B	Electrical/tank Room next to Boiler Room	W1	N/A	N/A	N/A	N/A	N/A
1	B	1B	Electrical/tank Room next to Boiler Room	W2	N/A	N/A	N/A	N/A	N/A
1	B	1B	Electrical/tank Room next to Boiler Room	W3	N/A	N/A	N/A	N/A	N/A

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment Report**Inspector Name and Certificate Number:
Christopher Karoly - 006424****John McCloskey School****Inspection Company: Criterion
Laboratories****8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	B	1B	Electrical/tank Room next to Boiler Room	W4	N/A	N/A	N/A	N/A	N/A
1	B	1B	Electrical/tank Room next to Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A
1	B	1B	Electrical/tank Room next to Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A
1	B	1A	Building Engineer's Office	W1	Concrete	White	None	0	Negative
1	B	1A	Building Engineer's Office	W2	Concrete	White	None	0	Negative
1	B	1A	Building Engineer's Office	W3	Concrete	White	None	0	Negative
1	B	1A	Building Engineer's Office	W4	Concrete	White	None	0	Negative
1	B	1A	Building Engineer's Office	Door	Metal	Brown	None	0	Negative
1	B	1A	Building Engineer's Office	Door Casing	Metal	Brown	None	0	Negative
1	B	1A	Building Engineer's Office	Door	Metal	Brown	None	0	Negative
1	B	1A	Building Engineer's Office	Door Casing	Metal	Brown	None	0	Negative
1	B	1A	Building Engineer's Office	Duct	Metal	White	None	0	Negative
1	B	1A	Building Engineer's Office	Ceiling	Concrete	White	None	0	Negative
1	B	1A	Building Engineer's Office	Floor	Concrete	Grey	None	0	Negative
1	B	1C	Building Engineer's Office Restroom	W1	Concrete	White	None	0	Negative
1	B	1C	Building Engineer's Office Restroom	W2	Concrete	White	None	0	Negative
1	B	1C	Building Engineer's Office Restroom	W3	Concrete	White	None	0	Negative
1	B	1C	Building Engineer's Office Restroom	W4	Concrete	White	None	0	Negative
1	B	1C	Building Engineer's Office Restroom	Door	Metal	Brown	None	0	Negative
1	B	1C	Building Engineer's Office Restroom	Door Casing	Metal	Brown	None	0	Negative
1	B	1C	Building Engineer's Office Restroom	Ceiling	Concrete	White	None	0	Negative
1	B	1C	Building Engineer's Office Restroom	Floor	Concrete	Grey	None	0	Negative
1	B	1D	Custodial Office	W1	Concrete	White	None	0	Negative
1	B	1D	Custodial Office	W2	Concrete	White	None	0	Negative
1	B	1D	Custodial Office	W3	Concrete	White	None	0	Negative
1	B	1D	Custodial Office	W4	Concrete	White	None	0	Negative
1	B	1D	Custodial Office	Door 1	Metal	Brown	None	2	Negative
1	B	1D	Custodial Office	Door 2	Metal	Brown	None	1	Negative
1	B	1D	Custodial Office	Door Casing 1	Metal	Brown	None	2	Negative
1	B	1D	Custodial Office	Door Casing 2	Metal	Brown	None	2	Negative
1	B	1D	Custodial Office	Pipe	Metal	Green/White	Flaking	5	Negative
1	B	1D	Custodial Office	Duct	Metal	White	None	2	Negative
1	B	1D	Custodial Office	Ceiling	Concrete	White	None	0	Negative
1	B	1D	Custodial Office	Floor	Concrete	Grey	None	0	Negative
1	B	1E	Custodial Office Restroom	W1	Concrete	White	None	0	Negative

4/18/2022 - 5/4/2022

Lead Safe Certification Assessment ReportInspector Name and Certificate Number:
Christopher Karoly - 006424**John McCloskey School**Inspection Company: Criterion
Laboratories**8500 Pickering Avenue, Philadelphia, PA 19150**

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
1	B	1E	Custodial Office Restroom	W2	Concrete	White	None	0	Negative
1	B	1E	Custodial Office Restroom	W3	Concrete	White	None	0	Negative
1	B	1E	Custodial Office Restroom	W4	Concrete	White	None	0	Negative
1	B	1E	Custodial Office Restroom	Duct	Metal	White	None	0	Negative
1	B	1E	Custodial Office Restroom	Ceiling	Concrete	White	None	0	Negative
1	B	1E	Custodial Office Restroom	Floor	Concrete	Grey	None	0	Negative
1	B	1C	Fan Room	W1	Concrete	White	None	0	Negative
1	B	1C	Fan Room	W2	Concrete	White	None	0	Negative
1	B	1C	Fan Room	W3	Concrete	White	None	0	Negative
1	B	1C	Fan Room	W4	Concrete	White	None	0	Negative
1	B	1C	Fan Room	Pipe	Metal	White	Flaking	23	Negative
1	B	1C	Fan Room	Stair Stringer	Metal	Blue	None	0	Negative
1	B	1C	Fan Room	Stair Tread	Metal	Blue	None	0	Negative
1	B	1C	Fan Room	Handrail	Metal	Blue	None	0	Negative
1	B	1C	Fan Room	Ceiling	Concrete	White	None	0	Negative
1	B	1C	Fan Room	Floor	Concrete	Grey	None	0	Negative
1	C	CS	Crawl Space-Boiler Room	W1	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Boiler Room	W2	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Boiler Room	W3	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Boiler Room	W4	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Tank Room	W1	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Tank Room	W2	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Tank Room	W3	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Tank Room	W4	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Tank Room	Ceiling	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space-Tank Room	Floor	N/A	N/A	N/A	N/A	N/A