

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	B	4	Cafeteria (Dining Area)	Cafeteria & Kitchen	yes	W1	Brick	White	Chipping	10	0.04	Negative
1	B	4	Cafeteria (Dining Area)	Cafeteria & Kitchen	yes	W2	Brick	White	None	0	N/A	N/A
1	B	4	Cafeteria (Dining Area)	Cafeteria & Kitchen	yes	W3	Brick	White	Moisture Damage	25	15.2	Positive
1	B	4	Cafeteria (Dining Area)	Cafeteria & Kitchen	yes	W4	Brick	White	Flaking	6	0.3	Negative
	B	4	Cafeteria (Dining Area)	Cafeteria & Kitchen	yes	Duct	Metal	White	Chipping	5	25.5	Positive
1	B	4	Cafeteria (Dining Area)	Cafeteria & Kitchen	yes	Ceiling	Concrete	White	Chipping	15	10	Positive
1	B	4	Cafeteria (Dining Area)	Cafeteria & Kitchen	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	4A	Storage	Cafeteria Storage	yes	W1	Brick	White	N/A	N/A	0.4	Negative
1	B	4A	Storage	Cafeteria Storage	yes	W2	Brick	White	N/A	N/A	0	Negative
1	B	4A	Storage	Cafeteria Storage	yes	W3	Brick	White	N/A	N/A	0.01	Negative
1	B	4A	Storage	Cafeteria Storage	yes	W4	Brick	White	N/A	N/A	0.1	Negative
1	B	4A	Storage	Cafeteria Storage	yes	Ceiling	Concrete	White	N/A	N/A	N/A	N/A
1	B	4A	Storage	Cafeteria Storage	yes	Floor	Concrete	Red	Friction	5	0.03	Negative
1	B	B5	Primary	Classroom B5	yes	W1	Plaster	Pink	Cracking	10	15.6	Positive
1	B	B5	Primary	Classroom B5	yes	W2	Plaster	Pink	Chipping	1	14.3	Positive
1	B	B5	Primary	Classroom B5	yes	W3	Plaster	Pink	Chipping, cracking	10	18.9	Positive
1	B	B5	Primary	Classroom B5	yes	W4	Plaster	Pink	Chipping	5	15.5	Positive
1	B	B5	Primary	Classroom B5	yes	Ceiling	Plaster	White	Flaking, Moisture Damage	50	20.2	Positive
1	B	B5	Primary	Classroom B5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B5	Primary	Classroom B5	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	B5A	Student Restrooms - Male/Female (Classroom)	Classroom B5 Restroom	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	B5A	Student Restrooms - Male/Female (Classroom)	Classroom B5 Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	B5A	Student Restrooms - Male/Female (Classroom)	Classroom B5 Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	B	B5A	Student Restrooms - Male/Female (Classroom)	Classroom B5 Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	B5A	Student Restrooms - Male/Female (Classroom)	Classroom B5 Restroom	yes	Ceiling	Plaster	Tan	Flaking	30	13.1	Positive
1	B	B5A	Student Restrooms - Male/Female (Classroom)	Classroom B5 Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	B5AB	Storage	Classroom B5 Closet	yes	W1	Plaster	White	Chipping	1	0.1	Negative
1	B	B5AB	Storage	Classroom B5 Closet	yes	W2	Plaster	White	Efflorescence, Moisture Damage	20	0	Negative
1	B	B5AB	Storage	Classroom B5 Closet	yes	W3	Plaster	White	Chipping	2	0	Negative
1	B	B5AB	Storage	Classroom B5 Closet	yes	W4	Plaster	White	Flaking	5	0	Negative
1	B	B5AB	Storage	Classroom B5 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	B5AB	Storage	Classroom B5 Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	Ceiling	Plaster	White	Flaking	60	5.6	Positive
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	04B	Storage	Bldg Engineer Restroom and Storage in Stairwell S01	no	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	S01	Stairs	Stairwell near Classroom B5	yes	W1	Plaster	White	Chipping	0	N/A	N/A
1	B	S01	Stairs	Stairwell near Classroom B5	yes	W2	Plaster	White	Chipping	5	14.2	Positive
1	B	S01	Stairs	Stairwell near Classroom B5	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	S01	Stairs	Stairwell near Classroom B5	yes	W4	Plaster	White	Cracking	8	2	Positive
1	B	S01	Stairs	Stairwell near Classroom B5	yes	Ceiling	Concrete	White	Chipping	35	22.9	Positive
1	B	S01	Stairs	Stairwell near Classroom B5	yes	Stair stringer	Concrete	Grey	Chipping	20	0.5	Negative
1	B	S01	Stairs	Stairwell near Classroom B5	yes	Newel post	Metal	Grey	Chipping	2	12.3	Positive
1	B	S01	Stairs	Stairwell near Classroom B5	yes	Baluster	Metal	Grey	Chipping	1	13.5	Positive
	B	S01	Stairs	Stairwell near Classroom B5	yes	Treads and Risers	Concrete	Grey	Chipping	15	0.3	Negative
1	B	S01	Stairs	Stairwell near Classroom B5	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	03A	Service Closets	Custodial Closet between Cafeteria and Boy's Restroom	no	W1	Brick	White/Teal	Chipping	5	0.1	Negative
1	B	03A	Service Closets	Custodial Closet between Cafeteria and Boy's Restroom	no	W2	Brick	White/Teal	Chipping	5	0.21	Negative
1	B	03A	Service Closets	Custodial Closet between Cafeteria and Boy's Restroom	no	W3	Brick	White/Teal	Chipping	5	0.23	Negative
1	B	03A	Service Closets	Custodial Closet between Cafeteria and Boy's Restroom	no	W4	Brick	White/Teal	Chipping	5	0.27	Negative
1	B	03A	Service Closets	Custodial Closet between Cafeteria and Boy's Restroom	no	Ceiling	Plaster	White	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	B	03A	Service Closets	Custodial Closet between Cafeteria and Boy's Restroom	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Concrete	White	Chipping	10	15.2	Positive
1	B	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Concrete	White	Cracking	25	3.5	Positive
1	B	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	B	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	03B	Service Closets	Custodial Storage Room between Boy's and Girl's Restroom	no	W1	Brick	White	Chipping	1	0.2	Negative
1	B	03B	Service Closets	Custodial Storage Room between Boy's and Girl's Restroom	no	W2	Brick	White	None	0	0.2	Negative
1	B	03B	Service Closets	Custodial Storage Room between Boy's and Girl's Restroom	no	W3	Brick	White	Chipping	1	0.2	Negative
1	B	03B	Service Closets	Custodial Storage Room between Boy's and Girl's Restroom	no	W4	Brick	White	Chipping	1	0.2	Negative
1	B	03B	Service Closets	Custodial Storage Room between Boy's and Girl's Restroom	no	Ceiling	Concrete	N/A	Chipping	1	0.4	Negative
1	B	03B	Service Closets	Custodial Storage Room between Boy's and Girl's Restroom	no	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	B	03B	Service Closets	Custodial Storage Room between Boy's and Girl's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01	Circulation (Hallway)	Basement Hallway - Gym to Classroom B5	yes	W1	Sheetrock	White	Cracking	1	0.1	Negative
1	B	H01	Circulation (Hallway)	Basement Hallway - Gym to Classroom B5	yes	W2	Brick	White	Chipping	20	0.09	Negative
1	B	H01	Circulation (Hallway)	Basement Hallway - Gym to Classroom B5	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01	Circulation (Hallway)	Basement Hallway - Gym to Classroom B5	yes	W3	Brick	White	None	0	N/A	N/A
1	B	H01	Circulation (Hallway)	Basement Hallway - Gym to Classroom B5	yes	W4	Brick	White	Chipping	20	0.23	Negative
	B	H01	Circulation (Hallway)	Basement Hallway - Gym to Classroom B5	yes	Duct	Metal	White	Chipping	30	10.2	Positive
1	B	H01	Circulation (Hallway)	Basement Hallway - Gym to Classroom B5	yes	Ceiling	Plaster	White	Flaking	225	12.3	Positive
1	B	H01	Circulation (Hallway)	Basement Hallway - Gym to Classroom B5	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	13A	Circulation (Hallway)	Entrance (Hall) Area to Storage/Pump Room outside Gym	yes	W1	Sheetrock	White	Chipping	2	0.1	Negative

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	B	13A	Circulation (Hallway)	Entrance (Hall) Area to Storage/Pump Room outside Gym	yes	W2	Brick	White	Chipping	10	0	Negative
1	B	13A	Circulation (Hallway)	Entrance (Hall) Area to Storage/Pump Room outside Gym	yes	W3	Brick	White	Chipping	2	0	Negative
1	B	13A	Circulation (Hallway)	Entrance (Hall) Area to Storage/Pump Room outside Gym	yes	W4	Brick	White	Chipping	2	0	Negative
1	B	13A	Circulation (Hallway)	Entrance (Hall) Area to Storage/Pump Room outside Gym	yes	Ceiling	Plaster	White	Flaking	50	25.2	Positive
1	B	13A	Circulation (Hallway)	Entrance (Hall) Area to Storage/Pump Room outside Gym	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	13	Mechanical Room	Storage/Pump Room outside Gym	no	W1	Brick	White	Chipping	2	0.4	Negative
1	B	13	Mechanical Room	Storage/Pump Room outside Gym	no	W2	Brick	White	Chipping	4	0	Negative
1	B	13	Mechanical Room	Storage/Pump Room outside Gym	no	W3	Brick	White	Chipping	3	0.01	Negative
1	B	13	Mechanical Room	Storage/Pump Room outside Gym	no	W4	Brick	White	Chipping	2	0.1	Negative
1	B	13	Mechanical Room	Storage/Pump Room outside Gym	no	Ceiling	Concrete	White	N/A	N/A	0.4	Negative
1	B	13	Mechanical Room	Storage/Pump Room outside Gym	no	Floor	Concrete	None	N/A	N/A	0	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W1	Brick	Red	Chipping	12	0.04	Negative
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W2	Brick	Black	Chipping	150	0.01	Negative

School District of Philadelphia
Lead Safe Certification Assessment Report
Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	S p a c e #	S p a c e T y p e	O n- S i t e R o o m N a m e	S t u d e n t/ T e a c h e r O c c u p i e d (y e s/ n o)	P r i m a r y C o m p o n e n t	S u b s t r a t e M a t e r i a l	C o l o r	D e s c r i p t i o n o f P r i m a r y D a m a g e	P r i m a r y C o m p o n e n t D a m a g e Q u a n t i t y (s f)	X R F R e a d i n g (m g/ c m²)	P r i m a r y C o m p o n e n t X R F (p o s i t i v e/ n e g a t i v e)
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W2	Brick	White	Chipping	10	0	Negative
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W3	Brick	Multi Color	Chipping	50	0.02	Negative
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W4	Brick	White	Chipping	10	0	Negative
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W4	Brick	Multi Color	Chipping	20	0.02	Negative
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	Ceiling	Plaster	White	Flaking, cracking	225	6.7	Positive
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	Floor	Concrete	Blue	Chipping, Cracking	25	0	Negative
1	B	1	Gymnasium - Intermediate Middle	Gym	yes	Floor	Concrete	Yellow	Chipping	10	0.03	Negative
1	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	W1	Plaster	White	None	0	15.3	Positive
1	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	W2	Plaster	White	Cracking	8	10.1	Positive
1	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	W3	Plaster	White	Chipping	1	14.5	Positive
1	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	W4	Plaster	White	Chipping	1	13.3	Positive
	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	W4	CMU	Tan	None	0	0.2	Negative
1	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	Ceiling	Plaster	White	Chipping	20	14.5	Positive
	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	Stair Riser	Concrete	Grey	Chipping	20	0.3	Negative

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	Stair Stringer	Concrete	Grey	Chipping	20	0.2	Negative
1	B	1A	Circulation (Hallway)	Hallway between Gym and Gym Office (includes both sides of steps)	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	15	Administrative Office	Gym Office	yes	W1	Brick	Purple	Chipping	15	0.03	Negative
1	B	15	Administrative Office	Gym Office	yes	W2	Brick	Purple	Chipping	10	0.04	Negative
1	B	15	Administrative Office	Gym Office	yes	W3	Brick	Purple	Chipping	25	0	Negative
1	B	15	Administrative Office	Gym Office	yes	W4	Brick	Purple	Chipping	7	0.01	Negative
1	B	15	Administrative Office	Gym Office	yes	Ceiling	Plaster	White	Flaking	40	15.2	Positive
1	B	15	Administrative Office	Gym Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	15A	Storage	Gym Office Storage Area	yes	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	15A	Storage	Gym Office Storage Area	yes	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	15A	Storage	Gym Office Storage Area	yes	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	15A	Storage	Gym Office Storage Area	yes	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	15A	Storage	Gym Office Storage Area	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	15A	Storage	Gym Office Storage Area	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	14	Weight Room	Gym Storage and Weight Room next to Gym Office	yes	W1	Brick	Yellow	Chipping	25	22.2	Positive
1	B	14	Weight Room	Gym Storage and Weight Room next to Gym Office	yes	W2	Brick	Yellow	Chipping	20	23	Positive
1	B	14	Weight Room	Gym Storage and Weight Room next to Gym Office	yes	W3	Brick	Yellow	Chipping	75	18	Positive
1	B	14	Weight Room	Gym Storage and Weight Room next to Gym Office	yes	W4	Brick	Yellow	Chipping	25	23	Positive
1	B	14	Weight Room	Gym Storage and Weight Room next to Gym Office	yes	Ceiling	Plaster	White	Cracking/Flaking /Efflorescence	150	16.5	Positive
1	B	14	Weight Room	Gym Storage and Weight Room next to Gym Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	14A	Weight Room	Gym Storage and Weight Room next to Gym Office - Rear Storage Area	yes	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	14A	Weight Room	Gym Storage and Weight Room next to Gym Office - Rear Storage Area	yes	W2	Concrete	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia
Lead Safe Certification Assessment Report
Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	B	14A	Weight Room	Gym Storage and Weight Room next to Gym Office - Rear Storage Area	yes	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	14A	Weight Room	Gym Storage and Weight Room next to Gym Office - Rear Storage Area	yes	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	14A	Weight Room	Gym Storage and Weight Room next to Gym Office - Rear Storage Area	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	14A	Weight Room	Gym Storage and Weight Room next to Gym Office - Rear Storage Area	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	W1	Plaster	Tan	Chipping	5	15.9	Positive
1	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	W2	Plaster	Tan	Flaking	12	16.7	Positive
1	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	W3	Plaster	Tan	Falking Paing/Hole	25	16.9	Positive
1	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	W4	Plaster	Tan	Chipping	10	17.4	Positive
1	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	Ceiling	Plaster	Tan	Cracking	25	16.3	Positive
	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	Newel Post	Metal	Grey	Chipping	2	11.3	Positive
	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	Stair Risers	Concrete	Grey	Chipping	10	0.3	Negative
	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	Stair Stringer	Concrete	Grey	Chipping	20	0.3	Negative
1	B	S05	Stairs	Stairwell behind Gym - From Stage Left	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	W1	Plaster	White	Efflorescence	2	1.6	Positive
1	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	W2	Plaster	White	Chipping	2	18.4	Positive
1	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	W3	Plaster	White	Chipping	28	18.4	Positive
1	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	W4	Plaster	White	Chipping	2	17.8	Positive
1	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	Ceiling	Plaster	White	None	0	N/A	N/A
	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	Newel Post	Metal	Grey	Chipping	1	5.7	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	S p a c e #	S p a c e T y p e	O n- S i t e R o o m N a m e	S t u d e n t/ T e a c h e r O c c u p i e d (y e s/ n o)	P r i m a r y C o m p o n e n t	S u b s t r a t e M a t e r i a l	C o l o r	D e s c r i p t i o n o f P r i m a r y D a m a g e	P r i m a r y C o m p o n e n t D a m a g e Q u a n t i t y (s f)	X R F R e a d i n g (m g/ c m ²)	P r i m a r y C o m p o n e n t X R F (p o s i t i v e/ n e g a t i v e)
	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	Stair Risers	Concrete	Grey	Chipping	10	0.4	Negative
	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	Stair Stringer	Concrete	Grey	Chipping	10	0	Negative
1	B	S06	Stairs	Stairwell behind Gym - From Stage Right	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	12	Mechanical Room	Ash Room	no	W1	Concrete	White	None	0	N/A	N/A
1	B	12	Mechanical Room	Ash Room	no	W2	Brick	White	Flaking	40	0.2	Negative
1	B	12	Mechanical Room	Ash Room	no	W3	Brick	White	Flaking	40	0.01	Negative
1	B	12	Mechanical Room	Ash Room	no	W4	Brick	White	Flaking	20	9.6	Positive
1	B	12	Mechanical Room	Ash Room	no	Ceiling	Concrete	White	Cracking	15	15.2	Positive
1	B	12	Mechanical Room	Ash Room	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	B	12A	Circulation (Hallway)	Hallway from Boiler Room to Ash Room	yes	W2	Concrete	White	Flaking	425	10.8	Positive
1	B	12A	Circulation (Hallway)	Hallway from Boiler Room to Ash Room	yes	W4	Concrete	White	Flaking	300	8.8	Positive
1	B	12A	Circulation (Hallway)	Hallway from Boiler Room to Ash Room	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	12A	Circulation (Hallway)	Hallway from Boiler Room to Ash Room	yes	Ceiling	Concrete	White	Flaking	300	23.3	Positive
1	B	12A	Circulation (Hallway)	Hallway from Boiler Room to Ash Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	Boiler Room	no	W1	Concrete	White	Flaking	120	15.3	Positive
1	B	5	Boiler Room	Boiler Room	no	W2	Concrete	White	Flaking	120	13.8	Positive
	B	5	Boiler Room	Boiler Room	no	Stair Risers	Concrete	Grey	Flaking	80	0.2	Positive
	B	5	Boiler Room	Boiler Room	no	Railing	Metal	Grey	Chipping	2	2.8	Positive
1	B	5	Boiler Room	Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Boiler Room	Boiler Room	no	W3	Concrete	White	Flaking	275	7.1	Positive
	B	5	Boiler Room	Boiler Room	no	W3	Brick	White	Flaking	120	0.1	Negative
	B	5	Boiler Room	Boiler Room	no	W4	Brick	White	Flaking	230	0.2	Negative
1	B	5	Boiler Room	Boiler Room	no	W4	Brick	White	Flaking	500	16.5	Positive
	B	5	Boiler Room	Boiler Room	no	Column	Concrete	White	Flaking	450	22	Positive
1	B	5	Boiler Room	Boiler Room	no	Ceiling	Concrete	White	Flaking/Chipping /Moisture	500	20.3	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	S p a c e #	S p a c e T y p e	O n- S i t e R o o m N a m e	S t u d e n t/ T e a c h e r O c c u p i e d (y e s/ n o)	P r i m a r y C o m p o n e n t	S u b s t r a t e M a t e r i a l	C o l o r	D e s c r i p t i o n o f P r i m a r y D a m a g e	P r i m a r y C o m p o n e n t D a m a g e Q u a n t i t y (s f)	X R F R e a d i n g (m g/ c m ²)	P r i m a r y C o m p o n e n t X R F (p o s i t i v e/ n e g a t i v e)
1	B	5	Boiler Room	Boiler Room	no	Floor	Concrete	Grey	Chipping	450	0.1	Negative
1	B	11	Mechanical Room	Coal Room (BE Office and Storage Area)	no	W1	Concrete	White	Chipping	10	21.9	Positive
1	B	11	Mechanical Room	Coal Room (BE Office and Storage Area)	no	W2	Concrete	White	Cracking	15	3.7	Positive
1	B	11	Mechanical Room	Coal Room (BE Office and Storage Area)	no	W3	Concrete	White	Chipping	3	25.6	Positive
1	B	11	Mechanical Room	Coal Room (BE Office and Storage Area)	no	W4	Concrete	White	Chipping, cracking, holes	18	17.7	Positive
1	B	11	Mechanical Room	Coal Room (BE Office and Storage Area)	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	11	Mechanical Room	Coal Room (BE Office and Storage Area)	no	Floor	Concrete	Grey	Friction/Chipping	100	0.1	Negative
1	B	10	Mechanical Room	Fan Room	no	W1	Brick	White	Flaking	150	12.4	Positive
1	B	10	Mechanical Room	Fan Room	no	W2	Brick	White	Chipping/Flaking	75	5.4	Positive
1	B	10	Mechanical Room	Fan Room	no	W3	Concrete	White	Flaking	300	5.5	Positive
1	B	10	Mechanical Room	Fan Room	no	W4	Concrete	White	Flaking	300	5.5	Positive
1	B	10	Mechanical Room	Fan Room	no	Ceiling	Concrete	White	Flaking	500	26.2	Positive
1	B	10	Mechanical Room	Fan Room	no	Floor	Concrete	Grey	Chipping/Flaking	200	0.1	Negative
1	B	10	Mechanical Room	Fan Room	no	Fan Unit	Metal	White	Flaking	200	25.4	Positive
1	B	S03	Stairs	Stairwell near Girl's Restroom	yes	W1	Plaster	Beige	Chipping	3	16.7	Positive
1	B	S03	Stairs	Stairwell near Girl's Restroom	yes	W2	Plaster	Beige	Chipping, cracking	3	19.4	Positive
1	B	S03	Stairs	Stairwell near Girl's Restroom	yes	W3	Plaster	Beige	Chipping	3	13.5	Positive
1	B	S03	Stairs	Stairwell near Girl's Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	B	S03	Stairs	Stairwell near Girl's Restroom	yes	Ceiling	Plaster	White	Chipping	10	15.5	Positive
	B	S03	Stairs	Stairwell near Girl's Restroom	yes	Newel Post	Metal	Grey	Chipping	1	20.1	Positive
	B	S03	Stairs	Stairwell near Girl's Restroom	yes	Stringer	Concrete	Grey	Chipping	20	0.4	Negative
	B	S03	Stairs	Stairwell near Girl's Restroom	yes	Baluster	Metal	Grey	Chipping	2	14.1	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
	B	S03	Stairs	Stairwell near Girl's Restroom	yes	Treads and Risers	Concrete	Grey	Chipping	50	0.1	Negative
1	B	S03	Stairs	Stairwell near Girl's Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	W1	Plaster	Tan	Chipping	3	16.6	Positive
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	W2	Plaster	Tan	Chipping, cracking	5	15.2	Positive
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	W3	Plaster	Tan	Cracking	16	12.3	Positive
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	W4	Plaster	Tan	Chipping	1	17	Positive
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	Ceiling	Plaster	White	Flaking	5	14.9	Positive
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	Floor	Concrete	N/A	None	0	N/A	N/A
	1	S13	Stairs	Stairwell across from Classroom 103	yes	Pipe	Metal	Tan	Chipping	1	3.2	Positive
	1	S13	Stairs	Stairwell across from Classroom 103	yes	Riser	Concrete	Grey	Chipping	35	3	Positive
	1	S13	Stairs	Stairwell across from Classroom 103	yes	Tread	Concrete	Grey	Chipping	35	0.2	Negative
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	Stringer	Concrete	Grey	Chipping	50	2.6	Positive
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	Newel posts	Metal	Grey	Chipping	2	7	Positive
1	1	S13	Stairs	Stairwell across from Classroom 103	yes	Baluster	Metal	Grey	Chipping	4	12.1	Positive
1	1	S17	Stairs	Stairwell outside Main Office	yes	W1	Plaster	Beige	N/A	N/A	N/A	N/A
1	1	S17	Stairs	Stairwell outside Main Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	S17	Stairs	Stairwell outside Main Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	S17	Stairs	Stairwell outside Main Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	S17	Stairs	Stairwell outside Main Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S17	Stairs	Stairwell outside Main Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	S19	Stairs	Stairwell by Stage Right	yes	W1	Plaster	White	Cracking/Chipping/ Holes	10	18.5	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	S19	Stairs	Stairwell by Stage Right	yes	W2	Plaster	White	Cracking/Chipping/ Holes	10	12.9	Positive
1	1	S19	Stairs	Stairwell by Stage Right	yes	W3	Plaster	White	Cracking/Chipping/ Holes	10	23.2	Positive
1	1	S19	Stairs	Stairwell by Stage Right	yes	W4	Plaster	White	Cracking/Chipping/ Holes	10	11.2	Positive
1	1	S19	Stairs	Stairwell by Stage Right	yes	Ceiling	Plaster	White	Efflorescence	60	22.7	Positive
1	1	S19	Stairs	Stairwell by Stage Right	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	S18	Stairs	Stairwell by Stage Left	yes	W1	Plaster	Tan	Cracking	6	15	Positive
1	1	S18	Stairs	Stairwell by Stage Left	yes	W2	Plaster	Tan	Cracking	7	18.5	Positive
1	1	S18	Stairs	Stairwell by Stage Left	yes	W3	Plaster	Tan	Chipping	20	21.1	Positive
1	1	S18	Stairs	Stairwell by Stage Left	yes	W4	Plaster	Tan	Chipping	20	15.9	Positive
1	1	S18	Stairs	Stairwell by Stage Left	yes	Ceiling	Plaster	White	Flaking	25	15.2	Positive
1	1	S18	Stairs	Stairwell by Stage Left	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	109A	Auditorium	Auditorium Stage	yes	W1	Plaster	Black	Chipping	50	0	Negative
1	1	109A	Auditorium	Auditorium Stage	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109A	Auditorium	Auditorium Stage	yes	W2	Plaster	Black	Chipping	46	0.02	Negative
1	1	109A	Auditorium	Auditorium Stage	yes	W3	Plaster	Black	Efflorescence	30	0.08	Negative
1	1	109A	Auditorium	Auditorium Stage	yes	W4	Plaster	Black	Chipping	5	0.1	Negative
1	1	109A	Auditorium	Auditorium Stage	yes	Ceiling	Plaster	Black	Efflorescence	75	No Access	No Access
1	1	109A	Auditorium	Auditorium Stage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	109	Auditorium	Auditorium	yes	W1	Plaster	Tan	Cracking	25	0.02	Negative
1	1	109	Auditorium	Auditorium	yes	W2	Plaster	Tan	Cracking	10	0.15	Negative
1	1	109	Auditorium	Auditorium	yes	W3	Plaster	Tan	Efflorescence	20	0.09	Negative
1	1	109	Auditorium	Auditorium	yes	W4	Plaster	Tan	None	0	0.25	Negative
1	1	109	Auditorium	Auditorium	yes	Ceiling	Plaster	White	Efflorescence/cracking	30	No Access	No Access
1	1	109	Auditorium	Auditorium	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	100	Principal/Directors Office	Principal's Office	yes	W1	Plaster	White/Green	None	0	N/A	N/A
1	1	100	Principal/Directors Office	Principal's Office	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Principal/Directors Office	Principal's Office	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Principal/Directors Office	Principal's Office	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Principal/Directors Office	Principal's Office	yes	W2	Plaster	White/Green	None	0	N/A	N/A
1	1	100	Principal/Directors Office	Principal's Office	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	1	100	Principal/Directors Office	Principal's Office	yes	W3	Plaster	White/Green	Chipping	3	21.8	Positive
1	1	100	Principal/Directors Office	Principal's Office	yes	W4	Plaster	White/Green	None	0	N/A	N/A
1	1	100	Principal/Directors Office	Principal's Office	yes	Ceiling	Plaster	Tan	Alligatoring	200	19.3	Positive
1	1	100	Principal/Directors Office	Principal's Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	100B	Administrative Office	Principal's Office Closet	yes	W1	Plaster	Beige	Cracking	30	10.1	Positive
1	1	100B	Administrative Office	Principal's Office Closet	yes	W2	Plaster	Beige	Cracking	30	10.1	Positive
1	1	100B	Administrative Office	Principal's Office Closet	yes	W3	Plaster	Beige	Cracking	30	10.1	Positive
1	1	100B	Administrative Office	Principal's Office Closet	yes	W4	Plaster	Beige	Cracking	30	10.1	Positive
1	1	100B	Administrative Office	Principal's Office Closet	yes	Ceiling	Plaster	Beige	Cracking	30	10.1	Positive
1	1	100B	Administrative Office	Principal's Office Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	100C	Circulation (Hallway)	Hall Area between Principal Office and its Closet & Restroom	yes	W1	Plaster	White	Holes	1	28.5	Positive
1	1	100C	Circulation (Hallway)	Hall Area between Principal Office and its Closet & Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100C	Circulation (Hallway)	Hall Area between Principal Office and its Closet & Restroom	yes	W2	Plaster	Green/White	None	0	N/A	N/A
1	1	100C	Circulation (Hallway)	Hall Area between Principal Office and its Closet & Restroom	yes	W3	Plaster	Green/White	None	0	N/A	N/A
1	1	100C	Circulation (Hallway)	Hall Area between Principal Office and its Closet & Restroom	yes	W4	Plaster	Green/White	Chipping	5	29.5	Positive
1	1	100C	Circulation (Hallway)	Hall Area between Principal Office and its Closet & Restroom	yes	Ceiling	Plaster	Green/White	Cracking	2	21	Positive
1	1	100C	Circulation (Hallway)	Hall Area between Principal Office and its Closet & Restroom	yes	Floor	Ceramic	Green/White	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	100A	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W1	Ceramic Tile	White/Green	None	0	N/A	N/A
1	1	100A	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100A	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	1	100A	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	1	100A	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	1	100A	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	Ceiling	Plaster	Tan	Alligatoring	50	22.6	Positive
1	1	100A	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	1	101	Administrative Office	Main Office	yes	W1	Plaster	White/Green	Chipping, hole	2	32.8	Positive
1	1	101	Administrative Office	Main Office	yes	W2	Plaster	White/Green	Cracking	3	41.6	Positive
1	1	101	Administrative Office	Main Office	yes	W3	Plaster	White/Green	None	0	31.8	Positive
1	1	101	Administrative Office	Main Office	yes	W4	Plaster	White/Green	None	0	40	Positive
1	1	101	Administrative Office	Main Office	yes	Ceiling	Plaster	Tan	Alligatoring	400	21.5	Positive
1	1	101	Administrative Office	Main Office	yes	Floor	Wood	N/A	None	0	N/a	N/A
1	1	101A	Storage	Main Office Closet	yes	W1	Plaster	White	Cracking	2	15.6	Positive
1	1	101A	Storage	Main Office Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	Storage	Main Office Closet	yes	W2	Plaster	White	hole, cracking	4	10.6	Positive
1	1	101A	Storage	Main Office Closet	yes	W3	Plaster	White	Cracking	5	17.4	Positive
1	1	101A	Storage	Main Office Closet	yes	W4	Plaster	White	Cracking, holes	7	17.9	Positive
1	1	101A	Storage	Main Office Closet	yes	Ceiling	Plaster	White	Chipping	12	20	Positive
1	1	101A	Storage	Main Office Closet	yes	Floor	Concrete	Linolium	Chipping	0	5	Positive
1	1	101B	Storage	Main Office Closet in Hallway	yes	W1	Plaster	Beige	Efflorescence, flaking, cracking	40	11.5	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	101B	Storage	Main Office Closet in Hallway	yes	W2	Plaster	Beige	Efflorescence, cracking	100	9.4	Positive
1	1	101B	Storage	Main Office Closet in Hallway	yes	W3	Plaster	Beige	Cracking	60	9	Positive
1	1	101B	Storage	Main Office Closet in Hallway	yes	W4	Plaster	Beige	Moisture Damage, Flaking, Cracking	80	8.4	Positive
1	1	101B	Storage	Main Office Closet in Hallway	yes	Ceiling	Plaster	Beige	Efflorescence, cracking	60	26.5	Positive
1	1	101B	Storage	Main Office Closet in Hallway	yes	Floor	Wood	N/a	None	0	N/A	N/A
1	1	102	Primary	Classroom 102	yes	W1	Plaster	Pink	Alligatoring, Flaking, Chipping	18	7.8	Positive
1	1	102	Primary	Classroom 102	yes	W2	Varnish	Brown	Staples	20	0.07	Negative
1	1	102	Primary	Classroom 102	yes	W3	Plaster	Pink	Flaking	6	21.6	Positive
1	1	102	Primary	Classroom 102	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Primary	Classroom 102	yes	W4	Plaster	Pink	Chipping	5	18	Positive
1	1	102	Primary	Classroom 102	yes	Ceiling	Plaster	White	Alligatoring	745	15.2	Positive
1	1	102	Primary	Classroom 102	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	102B	Storage	Classroom 102 Sink Closet	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	102B	Storage	Classroom 102 Sink Closet	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	102B	Storage	Classroom 102 Sink Closet	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	102B	Storage	Classroom 102 Sink Closet	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	102B	Storage	Classroom 102 Sink Closet	yes	Ceiling	Plaster	White	Cracking	1	13.6	Positive
1	1	102B	Storage	Classroom 102 Sink Closet	yes	Floor	Ceramic Tile	Grey	None	0	N/A	N/A
1	1	102A	Storage	Classroom 102 Closet	yes	W1	Plaster	Pink	Chipping	3	19.3	Positive
1	1	102A	Storage	Classroom 102 Closet	yes	W2	Plaster	Pink	Chipping	3	10.1	Positive
1	1	102A	Storage	Classroom 102 Closet	yes	W3	Plaster	Pink	Chipping	3	N/A	N/A
1	1	102A	Storage	Classroom 102 Closet	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102A	Storage	Classroom 102 Closet	yes	W4	Plaster	Pink	Chipping	2	9.5	Positive
1	1	102A	Storage	Classroom 102 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	102A	Storage	Classroom 102 Closet	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	108	Primary	Classroom 108	yes	W1	Plaster	Pink	Chipping/Flaking	5	15.4	Positive
1	1	108	Primary	Classroom 108	yes	W2	Plaster	Pink	Chipping	3	19.3	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	1	108	Primary	Classroom 108	yes	W3	Plaster	Pink	Cracking	10	21.4	Positive
1	1	108	Primary	Classroom 108	yes	W4	Plaster	Pink	Alligating	80	8.3	Positive
1	1	108	Primary	Classroom 108	yes	Ceiling	Plaster	Tan	Alligating	745	19.8	Positive
1	1	108	Primary	Classroom 108	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	108C	Storage	Classroom 108 Closet in Rear	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	1	108C	Storage	Classroom 108 Closet in Rear	yes	W2	Plaster	Yellow	Chipping	2	8.6	Positive
1	1	108C	Storage	Classroom 108 Closet in Rear	yes	W3	Plaster	Yellow	Cracking	4	9.2	Positive
1	1	108C	Storage	Classroom 108 Closet in Rear	yes	W4	Plaster	Yellow	Chipping	3	7.6	Positive
1	1	108C	Storage	Classroom 108 Closet in Rear	yes	Ceiling	Plaster	Tan	Chipping	2	6.3	Positive
1	1	108C	Storage	Classroom 108 Closet in Rear	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Ceiling	Plaster	Tan	Flaking	35	15.1	Positive
1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Floor	Ceramic Tile	Grey	None	0	N/A	N/A
1	1	108A	Storage	Classroom 108 Closet	yes	W1	Plaster	Pink	None	0	N/A	N/A
1	1	108A	Storage	Classroom 108 Closet	yes	W2	Plaster	Pink	Chipping	2	7.7	Positive
1	1	108A	Storage	Classroom 108 Closet	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	108A	Storage	Classroom 108 Closet	yes	W3	Sheetrock	Pink	None	0	0	Negative
1	1	108A	Storage	Classroom 108 Closet	yes	W4	Plaster	Pink	None	0	N/a	N/a
1	1	108A	Storage	Classroom 108 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	108A	Storage	Classroom 108 Closet	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	103	Primary	Classroom 103	yes	W1	Plaster	Pink	Chipping/Flaking	10	20.8	Positive
1	1	103	Primary	Classroom 103	yes	W2	Varnish	Brown	Staples	10	0.04	Negative
1	1	103	Primary	Classroom 103	yes	W3	Plaster	Pink	None	6	19.5	Positive
1	1	103	Primary	Classroom 103	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Primary	Classroom 103	yes	W4	Plaster	Pink	Chipping	5	17	Positive
1	1	103	Primary	Classroom 103	yes	Ceiling	Plaster	White	Efflorescence	745	21.2	Positive
1	1	103	Primary	Classroom 103	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	103B	Storage	Classroom 103 Sink Closet	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	103B	Storage	Classroom 103 Sink Closet	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	103B	Storage	Classroom 103 Sink Closet	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	103B	Storage	Classroom 103 Sink Closet	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	103B	Storage	Classroom 103 Sink Closet	yes	Ceiling	Plaster	White	Holes	5	16.4	Positive
1	1	103B	Storage	Classroom 103 Sink Closet	yes	Floor	Ceramic Tile	Grey	None	0	N/A	N/A
1	1	103A	Storage	Classroom 103 Closet	yes	W1	Plaster	Tan	Chipping	3	16.8	Positive
1	1	103A	Storage	Classroom 103 Closet	yes	W2	Plaster	Tan	None	N/A	N/A	N/A
1	1	103A	Storage	Classroom 103 Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103A	Storage	Classroom 103 Closet	yes	W3	Plaster	Tan	Chipping	7	15.1	Positive
1	1	103A	Storage	Classroom 103 Closet	yes	W4	Plaster	Tan	Chipping	3	24.9	Positive
1	1	103A	Storage	Classroom 103 Closet	yes	Ceiling	Plaster	Tan	Flaking	35	12	Positive
1	1	103A	Storage	Classroom 103 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	1	104F	Restrooms, Staff - Female	Women's Restroom	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104F	Restrooms, Staff - Female	Women's Restroom	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104F	Restrooms, Staff - Female	Women's Restroom	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104F	Restrooms, Staff - Female	Women's Restroom	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104F	Restrooms, Staff - Female	Women's Restroom	yes	Ceiling	Plaster	Tan	Flaking	45	16.4	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	1	104F	Restrooms, Staff - Female	Women's Restroom	yes	Floor	Ceramic Tile	Grey	None	0	N/A	N/A
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W1	Plaster	Pink	Cracking	25	18.1	Positive
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W2	Plaster	Pink	Cracking	2	15.1	Positive
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W3	Plaster	Pink	Flaking	15	20	Positive
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	W4	Partition Wall	Varnish	Chipping	30	0.04	Negative
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	Ceiling	Plaster	Tan	Alligatoring	745	18	Positive
1	1	104	Computer - Intermediate Middle	Computer Classroom 104	yes	Floor	Wood	Varnish	Chipping	5	0	Negative
1	1	104E	Storage	Classroom 104 Closet	yes	W1	Plaster	Pink	Holes	1	7	Positive
1	1	104E	Storage	Classroom 104 Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	1	104E	Storage	Classroom 104 Closet	yes	W2	Plaster	Pink	Holes	1	5.2	Positive
1	1	104E	Storage	Classroom 104 Closet	yes	W3	Plaster	Pink	N/A	0	8.7	Positive
1	1	104E	Storage	Classroom 104 Closet	yes	W4	Plaster	Pink	None	0	N/A	N/A
1	1	104E	Storage	Classroom 104 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	104E	Storage	Classroom 104 Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	104D	er - Intermediate	Computer Server Room	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	104D	er - Intermediate	Computer Server Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104D	er - Intermediate	Computer Server Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104D	er - Intermediate	Computer Server Room	yes	W2	Plaster	White	Flaking	6	20.7	Positive
1	1	104D	er - Intermediate	Computer Server Room	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	104D	er - Intermediate	Computer Server Room	yes	W4	Plaster	White	Cracking, Chipping	9	20.7	Positive
1	1	104D	er - Intermediate	Computer Server Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	104D	er - Intermediate	Computer Server Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	106B	Teacher Lounge/Dining	Teacher Office between Rooms 106 & 107	yes	W1	Plaster	White/Blue	Chipping	3	13.8	Positive
1	1	106B	Teacher Lounge/Dining	Teacher Office between Rooms 106 & 107	yes	W2	Plaster	White/Blue	Chipping/Flaking /Holes	3	16.1	Positive
1	1	106B	Teacher Lounge/Dining	Teacher Office between Rooms 106 & 107	yes	W3	Plaster	White/Blue	Chipping	5	16.5	Positive
1	1	106B	Teacher Lounge/Dining	Teacher Office between Rooms 106 & 107	yes	W4	Plaster	White/Blue	Chipping	1	15.5	Positive
1	1	106B	Teacher Lounge/Dining	Teacher Office between Rooms 106 & 107	yes	Ceiling	Plaster	Tan	Alligatoring	150	14.4	Positive
1	1	106B	Teacher Lounge/Dining	Teacher Office between Rooms 106 & 107	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	106C	Storage	Teacher Office Closet with Pay Phone	yes	W1	Plaster	Yellow	Chipping	1	7	Positive
1	1	106C	Storage	Teacher Office Closet with Pay Phone	yes	W2	Plaster	Yellow	Chipping/Cracking	12	13.4	Positive
1	1	106C	Storage	Teacher Office Closet with Pay Phone	yes	W3	Plaster	Yellow	None	0	10.1	Positive
1	1	106C	Storage	Teacher Office Closet with Pay Phone	yes	W4	Plaster	Yellow	None	0	6.5	Positive
1	1	106C	Storage	Teacher Office Closet with Pay Phone	yes	Ceiling	Plaster	Yellow	Chipping	1	7.5	Positive
1	1	106C	Storage	Teacher Office Closet with Pay Phone	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	106D	Student Restrooms - Male (4-12)	Women's Restroom in Teacher Office	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	106D	Student Restrooms - Male (4-12)	Women's Restroom in Teacher Office	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	106D	Student Restrooms - Male (4-12)	Women's Restroom in Teacher Office	yes	W3	Ceramic Tile	Tan	None	N/A	N/A	N/A
1	1	106D	Student Restrooms - Male (4-12)	Women's Restroom in Teacher Office	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	106D	Student Restrooms - Male (4-12)	Women's Restroom in Teacher Office	yes	Ceiling	Plaster	White	holes	2	16.1	Positive
1	1	106D	Student Restrooms - Male (4-12)	Women's Restroom in Teacher Office	yes	Floor	Ceramic Tile	Grey	None	0	N/A	N/A
1	1	107	Primary	Classroom 107	yes	W1	Plaster	Pink	Chipping	4	18.1	Positive
1	1	107	Primary	Classroom 107	yes	W2	Plaster	Pink	Chipping	10	19.8	Positive
1	1	107	Primary	Classroom 107	yes	W3	Plaster	Pink	Flaking, cracking	20	7.7	Positive
1	1	107	Primary	Classroom 107	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Primary	Classroom 107	yes	W4	Plaster	Pink	Cracking	10	21.2	Positive
1	1	107	Primary	Classroom 107	yes	Ceiling	Plaster	Tan	Alligatoring	745	12.6	Positive
1	1	107	Primary	Classroom 107	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	107C	Storage	Classroom 107 Rear Closet	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	107C	Storage	Classroom 107 Rear Closet	yes	W2	Plaster	White	Cracking/Chipping	8	7.2	Positive
1	1	107C	Storage	Classroom 107 Rear Closet	yes	W3	Plaster	White	Cracking	3	10.1	Positive
1	1	107C	Storage	Classroom 107 Rear Closet	yes	W4	Plaster	White	Cracking	5	7.5	Positive
1	1	107C	Storage	Classroom 107 Rear Closet	yes	Ceiling	Plaster	Tan	Alligatoring	35	14	Positive
1	1	107C	Storage	Classroom 107 Rear Closet	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	107A	Storage	Classroom 107 Front Closet	yes	W1	Plaster	Pink	None	0	N/A	N/A
1	1	107A	Storage	Classroom 107 Front Closet	yes	W2	Plaster	Pink	Chipping	4	15.9	Positive
1	1	107A	Storage	Classroom 107 Front Closet	yes	W3	Sheetrock	Pink	Chipping, holes	3	0	Negative
1	1	107A	Storage	Classroom 107 Front Closet	yes	W4	Plaster	Pink	Chipping	2	15.1	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	1	107A	Storage	Classroom 107 Front Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	107A	Storage	Classroom 107 Front Closet	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	Ceiling	Plaster	Tan	Alligatoring	50	17.2	Positive
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	Floor	Ceramic Tile	Grey	None	0	N/A	N/A
1	1	104B	Service Closets	Custodial Closet next to Nurse's Office	no	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104B	Service Closets	Custodial Closet next to Nurse's Office	no	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104B	Service Closets	Custodial Closet next to Nurse's Office	no	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104B	Service Closets	Custodial Closet next to Nurse's Office	no	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104B	Service Closets	Custodial Closet next to Nurse's Office	no	Ceiling	Plaster	White	Chipping/Flaking	12	18.7	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	1	104B	Service Closets	Custodial Closet next to Nurse's Office	no	Floor	Ceramic Tile	Grey	None	0	N/A	N/A
1	1	104A	Health Service Room	Nurse's Office	yes	W1	Plaster	White/Pink	Chipping	1	31	Positive
1	1	104A	Health Service Room	Nurse's Office	yes	W2	Plaster	White/Pink	None	0	27.7	Positive
1	1	104A	Health Service Room	Nurse's Office	yes	W2	Sheetrock	White/Pink	Chipping/Flaking	4	0	Negative
1	1	104A	Health Service Room	Nurse's Office	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104A	Health Service Room	Nurse's Office	yes	W3	Plaster	White/Pink	None	0	30.7	Positive
1	1	104A	Health Service Room	Nurse's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104A	Health Service Room	Nurse's Office	yes	W4	Plaster	White/Pink	Chipping/Flaking	6	30.4	Positive
1	1	104A	Health Service Room	Nurse's Office	yes	Ceiling	Plaster	Tan	Alligatoring	210	27.8	Positive
1	1	104A	Health Service Room	Nurse's Office	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	104A	Health Service Room	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104C	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104C	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104C	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104C	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	104C	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	Ceiling	Plaster	White	holes	3	21.2	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	1	104C	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	Floor	Ceramic Tile	Grey	None	0	N/A	N/A
1	1	106	Primary	Classroom 106	yes	W1	Plaster	Pink	Chipping/Flaking	5	25.6	Positive
1	1	106	Primary	Classroom 106	yes	W2	Plaster	Pink	Chipping/Flaking	20	18.3	Positive
1	1	106	Primary	Classroom 106	yes	W3	Plaster	Pink	Flaking, cracking	12	20.4	Positive
1	1	106	Primary	Classroom 106	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Primary	Classroom 106	yes	W4	Plaster	Pink	Cracking	4	10.5	Positive
1	1	106	Primary	Classroom 106	yes	Ceiling	Plaster	Grey	Alligatoring	934	18.6	Positive
1	1	106	Primary	Classroom 106	yes	Floor	Wood	N/A	None	0	N/A	N/A
1	1	106E	Storage	Classroom 106 Rear Closet	yes	W1	Plaster	White	Chipping/Flaking	10	4.6	Positive
1	1	106E	Storage	Classroom 106 Rear Closet	yes	W2	Plaster	White	Efflorescence/Cracking/Flaking	15	6.3	Positive
1	1	106E	Storage	Classroom 106 Rear Closet	yes	W3	Plaster	White	Cracking	5	8.5	Positive
1	1	106E	Storage	Classroom 106 Rear Closet	yes	W4	Plaster	White	Flaking/Chipping	5	6.7	Positive
1	1	106E	Storage	Classroom 106 Rear Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	106E	Storage	Classroom 106 Rear Closet	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	106F	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	106F	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	106F	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106F	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	106F	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A

School District of Philadelphia
Lead Safe Certification Assessment Report
Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	106F	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	Ceiling	Plaster	Tan	Alligating	50	18.5	Positive
1	1	106F	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	Floor	Ceramic Tile	Brown	None	0	N/A	N/A
1	1	106A	Storage	Classroom 106 Front Closet	yes	W1	Plaster	Pink	N/A	N/A	N/A	N/A
1	1	106A	Storage	Classroom 106 Front Closet	yes	W2	Plaster	Pink	Chipping	10	21.9	Positive
1	1	106A	Storage	Classroom 106 Front Closet	yes	W3	Sheetrock	Pink	None	0	0	Negative
1	1	106A	Storage	Classroom 106 Front Closet	yes	W4	Plaster	Pink	Chipping	10	15.6	Positive
1	1	106A	Storage	Classroom 106 Front Closet	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Storage	Classroom 106 Front Closet	yes	Ceiling	Plaster	White	N/A	N/A	N/A	N/A
1	1	106A	Storage	Classroom 106 Front Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	1	105	Primary	Classroom 105	yes	W1	Plaster	Tan	Chipping	1	17.5	Positive
1	1	105	Primary	Classroom 105	yes	W2	Plaster	Tan	Chipping, Flaking	4	14.3	Positive
1	1	105	Primary	Classroom 105	yes	W3	Plaster	Tan	None	0	14.6	Positive
1	1	105	Primary	Classroom 105	yes	W4	Plaster	Tan	Cracking	1	22.4	Positive
1	1	105	Primary	Classroom 105	yes	Ceiling	Plaster	Tan	Alligating	934	10.9	Positive
1	1	105	Primary	Classroom 105	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom on Right	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom on Right	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom on Right	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom on Right	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom on Right	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom on Right	yes	Ceiling	Plaster	White	Chipping	2	7.5	Positive
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom on Right	yes	Floor	Ceramic Tile	Brown	None	0	N/A	N/A
1	1	105B	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom between other Restroom and Closet	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	105B	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom between other Restroom and Closet	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	105B	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom between other Restroom and Closet	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	105B	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom between other Restroom and Closet	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	1	105B	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom between other Restroom and Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	105B	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom between other Restroom and Closet	yes	Floor	Ceramic Tile	Brown	None	0	N/A	N/A
1	1	105C	Storage	Classroom 105 Closet	yes	W1	Plaster	Pink	Chipping	1	20	Positive
1	1	105C	Storage	Classroom 105 Closet	yes	W2	Plaster	Pink	None	0	14.7	Positive
1	1	105C	Storage	Classroom 105 Closet	yes	W3	Plaster	Pink	Chipping	3	19.8	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	1	105C	Storage	Classroom 105 Closet	yes	W4	Plaster	Pink	None	0	N/A	N/A
1	1	105C	Storage	Classroom 105 Closet	yes	W4	Sheetrock	Pink	Holes	1	0	Negative
1	1	105C	Storage	Classroom 105 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	105C	Storage	Classroom 105 Closet	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	105D	Storage	Classroom 105 Closet in Hallway	yes	W1	Plaster	Yellow	Cracking	8	7.2	Positive
1	1	105D	Storage	Classroom 105 Closet in Hallway	yes	W2	Plaster	Yellow	Chipping	1	7.6	Positive
1	1	105D	Storage	Classroom 105 Closet in Hallway	yes	W3	Plaster	Yellow	None	0	5.2	Positive
1	1	105D	Storage	Classroom 105 Closet in Hallway	yes	W4	Plaster	Yellow	None	0	7.3	Positive
1	1	105D	Storage	Classroom 105 Closet in Hallway	yes	Ceiling	Plaster	Yellow	None	0	N/A	N/A
1	1	105D	Storage	Classroom 105 Closet in Hallway	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	S11	Stairs	Stairwell outside Classroom 106	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	S11	Stairs	Stairwell outside Classroom 106	yes	W2	Plaster	Tan	Cracking	2	17.4	Positive
1	1	S11	Stairs	Stairwell outside Classroom 106	yes	W3	Plaster	Tan	Flaking	5	16.2	Positive
1	1	S11	Stairs	Stairwell outside Classroom 106	yes	W4	Plaster	Tan	Chipping	4	16.7	Positive
	1	S11	Stairs	Stairwell outside Classroom 106	yes	Newel Post	Metal	Grey	Chipping	2	11.7	Positive
	1	S11	Stairs	Stairwell outside Classroom 106	yes	Baluster	Metal	Grey	Chipping	4	10.7	Positive
	1	S11	Stairs	Stairwell outside Classroom 106	yes	Stringer	Concrete	Grey	Chipping	50	2.1	Positive
	1	S11	Stairs	Stairwell outside Classroom 106	yes	Riser	Concrete	Grey	Chipping	35	2.7	Positive
	1	S11	Stairs	Stairwell outside Classroom 106	yes	Tread	Concrete	Grey	Chipping	35	0.3	Negative
1	1	S11	Stairs	Stairwell outside Classroom 106	yes	Ceiling	Plaster	White	Efflorescence	10	12.2	Positive
1	1	S11	Stairs	Stairwell outside Classroom 106	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W1	Plaster	White	Flaking	15	13.5	Positive
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W2	Plaster	White	Cracking	2	14.7	Positive
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W3	Plaster	White	Flaking	3	16.8	Positive
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	Ceiling	Plaster	White	Alligatoring	970	16.3	Positive
1	1	H12	Circulation (Hallway)	1st Floor Hallway	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	2X	Storage	Storage across from Classroom 201	yes	W1	Plaster	Beige	Cracking	20	10.1	Positive
1	2	2X	Storage	Storage across from Classroom 201	yes	W2	Plaster	Beige	Cracking/Holes	50	10.1	Positive
1	2	2X	Storage	Storage across from Classroom 201	yes	W3	Plaster	Beige	Cracking	10	10.1	Positive
1	2	2X	Storage	Storage across from Classroom 201	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	2X	Storage	Storage across from Classroom 201	yes	W4	Plaster	Beige	Cracking/Holes	20	10.1	Positive
1	2	2X	Storage	Storage across from Classroom 201	yes	Ceiling	Plaster	Beige	Cracking/Holes	10	10.1	Positive
1	2	2X	Storage	Storage across from Classroom 201	yes	Floor	Concrete	Brown	Spalling	120	0	Negative
1	2	2X	Storage	Storage across from Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	2X	Storage	Storage across from Classroom 201	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A

School District of Philadelphia
Lead Safe Certification Assessment Report
Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	200	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Plaster	Tan	Flaking	25	18	Positive
1	2	200	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Plaster	White	Cracking	20	21	Positive
1	2	200A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200B	Service Closets	Custodial Closet by Classroom 201	no	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200B	Service Closets	Custodial Closet by Classroom 201	no	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200B	Service Closets	Custodial Closet by Classroom 201	no	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200B	Service Closets	Custodial Closet by Classroom 201	no	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	200B	Service Closets	Custodial Closet by Classroom 201	no	Ceiling	Plaster	White	Moisture Damage/Flaking	20	12	Positive
1	2	200B	Service Closets	Custodial Closet by Classroom 201	no	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	201	Primary	Classroom 201	yes	W1	Plaster	Yellow	Chipping	5	22.4	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	2	201	Primary	Classroom 201	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Primary	Classroom 201	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Primary	Classroom 201	yes	W2	Plaster	Yellow	Chipping	15	22	Positive
1	2	201	Primary	Classroom 201	yes	W3	Plaster	Yellow	Flaking	12	22.6	Positive
1	2	201	Primary	Classroom 201	yes	W4	Plaster	Yellow	Flaking	5	10.1	Positive
1	2	201	Primary	Classroom 201	yes	Ceiling	Plaster	White	Flaking	250	17.6	Positive
1	2	201	Primary	Classroom 201	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W2	Plaster	Yellow	Chipping	8	16	Positive
1	2	201A	Storage	Classroom 201 Closet	yes	W3	Plaster	Yellow	Chipping	2	13	Positive
1	2	201A	Storage	Classroom 201 Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	Ceiling	Plaster	Tan	Cracking	50	19.2	Positive
1	2	201A	Storage	Classroom 201 Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	201B	Storage	Classroom 201 Sink Closet	yes	W1	Ceramic Tile	White/Green	None	0	N/A	N/A
1	2	201B	Storage	Classroom 201 Sink Closet	yes	W2	Ceramic Tile	White/Green	None	0	N/A	N/A
1	2	201B	Storage	Classroom 201 Sink Closet	yes	W3	Ceramic Tile	White/Green	None	0	N/A	N/A
1	2	201B	Storage	Classroom 201 Sink Closet	yes	W4	Ceramic Tile	White/Green	None	0	N/A	N/A
1	2	201B	Storage	Classroom 201 Sink Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	201B	Storage	Classroom 201 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	202	Primary	Classroom 202	yes	W1	Plaster	Yellow	Chipping	5	25.6	Positive
1	2	202	Primary	Classroom 202	yes	W2	Plaster	Yellow	Chipping	2	20	Positive
1	2	202	Primary	Classroom 202	yes	W3	Plaster	Yellow	Chipping	10	14	Positive
1	2	202	Primary	Classroom 202	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Primary	Classroom 202	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Primary	Classroom 202	yes	W4	Plaster	Yellow	Chipping	15	19	Positive
1	2	202	Primary	Classroom 202	yes	Ceiling	Plaster	White	Flaking	50	17.1	Positive
1	2	202	Primary	Classroom 202	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	202A	Storage	Classroom 202 Closet	yes	W1	Plaster	Yellow	Cracking	20	18	Positive
1	2	202A	Storage	Classroom 202 Closet	yes	W2	Plaster	Yellow	Cracking	10	16.4	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	2	202A	Storage	Classroom 202 Closet	yes	W3	Plaster	Yellow	Cracking	35	12	Positive
1	2	202A	Storage	Classroom 202 Closet	yes	W4	Plaster	Yellow	Chipping	3	0.01	Negative
1	2	202A	Storage	Classroom 202 Closet	yes	Ceiling	Plaster	N/A	Flaking	30	20.3	Positive
1	2	202A	Storage	Classroom 202 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	202B	Storage	Classroom 202 Sink Closet	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	2	202B	Storage	Classroom 202 Sink Closet	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	2	202B	Storage	Classroom 202 Sink Closet	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	2	202B	Storage	Classroom 202 Sink Closet	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	2	202B	Storage	Classroom 202 Sink Closet	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202B	Storage	Classroom 202 Sink Closet	yes	Ceiling	Plaster	N/A	Chipping	1	16.6	Positive
1	2	202B	Storage	Classroom 202 Sink Closet	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	2	208	Primary	Classroom 208	yes	W1	Plaster	Yellow	Chipping	10	26.4	Positive
1	2	208	Primary	Classroom 208	yes	W2	Plaster	Yellow	Chipping	6	19	Positive
1	2	208	Primary	Classroom 208	yes	W3	Plaster	Yellow	Chipping	5	22.8	Positive
1	2	208	Primary	Classroom 208	yes	W4	Plaster	Yellow	Chipping	20	20.2	Positive
1	2	208	Primary	Classroom 208	yes	Ceiling	Plaster	Tan	Alligatoring	686	14.9	Positive
1	2	208	Primary	Classroom 208	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	208B	Storage	Classroom 208 Sink Closet	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	208B	Storage	Classroom 208 Sink Closet	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	208B	Storage	Classroom 208 Sink Closet	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	208B	Storage	Classroom 208 Sink Closet	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	208B	Storage	Classroom 208 Sink Closet	yes	Ceiling	Plaster	White	Cracking	1	15.8	Positive
1	2	208B	Storage	Classroom 208 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	208A	Storage	Classroom 208 Closet	yes	W1	Plaster	Yellow	Chipping	5	29.4	Positive
1	2	208A	Storage	Classroom 208 Closet	yes	W2	Plaster	Yellow	N/A	N/A	N/A	N/A
1	2	208A	Storage	Classroom 208 Closet	yes	W3	Plaster	Yellow	Chipping	8	14.5	Positive
1	2	208A	Storage	Classroom 208 Closet	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	208A	Storage	Classroom 208 Closet	yes	Ceiling	Plaster	White	Flaking	20	18.8	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	208A	Storage	Classroom 208 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	203	IMC (Library)	Library 203/204	yes	W1	Plaster	Teal	Chipping	7	18.1	Positive
1	2	203	IMC (Library)	Library 203/204	yes	W2	Plaster	Teal	Chipping	5	0	Negative
1	2	203	IMC (Library)	Library 203/204	yes	W3	Plaster	Teal	Chipping	10	18.6	Positive
1	2	203	IMC (Library)	Library 203/204	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	IMC (Library)	Library 203/204	yes	W4	Plaster	Teal	Flaking	3	13	Positive
1	2	203	IMC (Library)	Library 203/204	yes	Ceiling	Plaster	N/A	Flaking	100	17.2	Positive
1	2	203	IMC (Library)	Library 203/204	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	204A	Storage	Library 204 Closet	yes	W1	Plaster	Teal	Chipping	6	4.4	Positive
1	2	204A	Storage	Library 204 Closet	yes	W2	Plaster	Teal	Chipping	2	10.1	Positive
1	2	204A	Storage	Library 204 Closet	yes	W3	Plaster	Teal	Chipping	4	13.7	Positive
1	2	204A	Storage	Library 204 Closet	yes	W4	Plaster	Teal	Chipping	10	12.4	Positive
1	2	204A	Storage	Library 204 Closet	yes	Ceiling	Plaster	N/A	None	0	N/A	N/A
1	2	204A	Storage	Library 204 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	203A	Storage	Library 203 Closet (near Pipe Shaft)	yes	W1	Plaster	Teal	Chipping	10	8.5	Positive
1	2	203A	Storage	Library 203 Closet (near Pipe Shaft)	yes	W2	Plaster	Teal	Chipping	10	9.9	Positive
1	2	203A	Storage	Library 203 Closet (near Pipe Shaft)	yes	W3	Plaster	Teal	Chipping	10	12	Positive
1	2	203A	Storage	Library 203 Closet (near Pipe Shaft)	yes	W4	Plaster	Teal	Chipping	10	4.9	Positive
1	2	203A	Storage	Library 203 Closet (near Pipe Shaft)	yes	Ceiling	Plaster	Tan	Cracking	35	15.5	Positive
1	2	203A	Storage	Library 203 Closet (near Pipe Shaft)	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	2	207	Music	Music Room 207	yes	W1	Plaster	Yellow	Chipping	3	16.4	Positive
1	2	207	Music	Music Room 207	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Music	Music Room 207	yes	W2	Plaster	Yellow	Chipping	2	13.6	Positive
1	2	207	Music	Music Room 207	yes	W3	Plaster	Yellow	Cracking	1	20.8	Positive
1	2	207	Music	Music Room 207	yes	W4	Plaster	Yellow	Holes	1	22	Positive
1	2	207	Music	Music Room 207	yes	Ceiling	Plaster	Tan	Flaking	200	14.2	Positive
1	2	207	Music	Music Room 207	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	207A	Storage	Music Room 207 Closet	yes	W1	Plaster	Yellow	Chipping	7	13.6	Positive
1	2	207A	Storage	Music Room 207 Closet	yes	W2	Plaster	Yellow	Chipping	4	3.1	Positive
1	2	207A	Storage	Music Room 207 Closet	yes	W3	Plaster	Yellow	Chipping	4	14	Positive
1	2	207A	Storage	Music Room 207 Closet	yes	W4	Plaster	Yellow	Chipping	3	4.1	Positive
1	2	207A	Storage	Music Room 207 Closet	yes	Ceiling	Plaster	Tan	Flaking	20	19.3	Positive
1	2	207A	Storage	Music Room 207 Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	207B	Storage	Music Room 207 Sink Closet	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	207B	Storage	Music Room 207 Sink Closet	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	207B	Storage	Music Room 207 Sink Closet	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	207B	Storage	Music Room 207 Sink Closet	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	207B	Storage	Music Room 207 Sink Closet	yes	Ceiling	Plaster	White	Chipping	1	18.7	Positive
1	2	207B	Storage	Music Room 207 Sink Closet	yes	Floor	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	210	Primary	Classroom 206.5	yes	W1	Plaster	Yellow	Chipping	4	21.6	Positive
1	2	210	Primary	Classroom 206.5	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	Primary	Classroom 206.5	yes	W2	Plaster	Yellow	Flaking	2	15.8	Positive
1	2	210	Primary	Classroom 206.5	yes	W3	Plaster	Yellow	Cracking	15	27.5	Positive
1	2	210	Primary	Classroom 206.5	yes	W4	Plaster	Yellow	Cracking	1	17.8	Positive
1	2	210	Primary	Classroom 206.5	yes	Ceiling	Plaster	Tan	Flaking	75	14.9	Positive
1	2	210	Primary	Classroom 206.5	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	210A	Storage	Classroom 206.5 Closet	yes	W1	Plaster	Beige	Cracking	3	6.1	Positive
1	2	210A	Storage	Classroom 206.5 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	210A	Storage	Classroom 206.5 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	210A	Storage	Classroom 206.5 Closet	yes	W4	Plaster	Beige	Cracking	3	10.1	Positive
1	2	210A	Storage	Classroom 206.5 Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	210A	Storage	Classroom 206.5 Closet	yes	Floor	wood	Varnish	N/A	N/A	N/A	N/A
1	2	210B	Storage	Book Closet between Rooms 206 and 206.5	yes	W1	Plaster	Yellow	Cracking	1	0.75	Positive
1	2	210B	Storage	Book Closet between Rooms 206 and 206.5	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210B	Storage	Book Closet between Rooms 206 and 206.5	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210B	Storage	Book Closet between Rooms 206 and 206.5	yes	W2	Plaster	Beige	Cracking	10	7	Positive
1	2	210B	Storage	Book Closet between Rooms 206 and 206.5	yes	W3	Plaster	Beige	Cracking	3	7	Positive
1	2	210B	Storage	Book Closet between Rooms 206 and 206.5	yes	W4	Plaster	Yellow	Chipping	2	8.3	Positive
1	2	210B	Storage	Book Closet between Rooms 206 and 206.5	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	210B	Storage	Book Closet between Rooms 206 and 206.5	yes	Floor	Wood	Varnish	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	206	Primary	Classroom 206	yes	W1	Plaster	Yellow	Chipping, cracking	10	33.9	Positive
1	2	206	Primary	Classroom 206	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Primary	Classroom 206	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Primary	Classroom 206	yes	W2	Plaster	Yellow	Chipping, cracking	10	9.9	Positive
1	2	206	Primary	Classroom 206	yes	W3	Plaster	Yellow	Chipping, cracking, flaking	39	33.6	Positive
1	2	206	Primary	Classroom 206	yes	W4	Plaster	Yellow	Chipping	1	27.8	Positive
1	2	206	Primary	Classroom 206	yes	Ceiling	Plaster	Tan	Flaking	300	23.7	Positive
1	2	206	Primary	Classroom 206	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	206B	Storage	Classroom 206 Sink Closet	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	206B	Storage	Classroom 206 Sink Closet	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	206B	Storage	Classroom 206 Sink Closet	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	206B	Storage	Classroom 206 Sink Closet	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	206B	Storage	Classroom 206 Sink Closet	yes	Ceiling	Plaster	White	Chipping	1	15.3	Positive
1	2	206B	Storage	Classroom 206 Sink Closet	yes	Floor	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	206A	Storage	Classroom 206 Closet	yes	W1	Plaster	Yellow	Chipping	15	3.8	Positive
1	2	206A	Storage	Classroom 206 Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206A	Storage	Classroom 206 Closet	yes	W2	Plaster	Yellow	Peeling/Cracking	6	3.4	Positive
1	2	206A	Storage	Classroom 206 Closet	yes	W3	Plaster	Yellow	Peeling	1	5.8	Positive
1	2	206A	Storage	Classroom 206 Closet	yes	W4	Plaster	Yellow	Chipping	3	3.3	Positive
1	2	206A	Storage	Classroom 206 Closet	yes	Ceiling	Plaster	Tan	Flaking	30	22	Positive
1	2	206A	Storage	Classroom 206 Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	205	Primary	Classroom 205	yes	W1	Plaster	Yellow	Chipping	8	11.7	Positive
1	2	205	Primary	Classroom 205	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Primary	Classroom 205	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	205	Primary	Classroom 205	yes	W3	Plaster	Yellow	Flaking	30	23.8	Positive
1	2	205	Primary	Classroom 205	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	205	Primary	Classroom 205	yes	Ceiling	Plaster	Tan	Cracking	400	16.6	Positive
1	2	205	Primary	Classroom 205	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	205A	Storage	Classroom 205 Closet	yes	W1	Plaster	Yellow	Cracking	10	2.5	Positive
1	2	205A	Storage	Classroom 205 Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	Storage	Classroom 205 Closet	yes	W2	Plaster	Yellow	Chipping	3	8	Positive
1	2	205A	Storage	Classroom 205 Closet	yes	W3	Plaster	Yellow	Chipping	1	7.7	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	2	205A	Storage	Classroom 205 Closet	yes	W4	Plaster	Yellow	large hole	1	4.9	Positive
1	2	205A	Storage	Classroom 205 Closet	yes	Ceiling	Plaster	Tan	Flaking	25	14.7	Positive
1	2	205A	Storage	Classroom 205 Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	205B	Storage	Classroom 205 Sink Closet	yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	205B	Storage	Classroom 205 Sink Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	Storage	Classroom 205 Sink Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	Storage	Classroom 205 Sink Closet	yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	205B	Storage	Classroom 205 Sink Closet	yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	205B	Storage	Classroom 205 Sink Closet	yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	205B	Storage	Classroom 205 Sink Closet	yes	Ceiling	Plaster	White	Chipping	1	32.5	Positive
1	2	205B	Storage	Classroom 205 Sink Closet	yes	Floor	Ceramic Tile	Tan	None	0	N/A	N/A
1	2	204.5	Administrative Office	Faculty Room	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	204.5	Administrative Office	Faculty Room	yes	W1	Plaster	Tan	Cracking	10	14.3	Positive
1	2	204.5	Administrative Office	Faculty Room	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	2	204.5	Administrative Office	Faculty Room	yes	W2	Plaster	Purple	Cracking	10	16.8	Positive
1	2	204.5	Administrative Office	Faculty Room	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	2	204.5	Administrative Office	Faculty Room	yes	W3	Plaster	Purple	None	0	N/A	N/A
1	2	204.5	Administrative Office	Faculty Room	yes	W4	Plaster	Tan	Cracking	10	17.7	Positive
1	2	204.5	Administrative Office	Faculty Room	yes	W4	Plaster	Purple	Chipping	10	12.4	Positive
1	2	204.5	Administrative Office	Faculty Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204.5	Administrative Office	Faculty Room	yes	Floor	Linoleum	N/A	None	0	N/A	N/A
1	2	204.5	Storage	Faculty Room Closet	yes	W1	Plaster	Tan	N/A	N/A	N/A	N/A
1	2	204.5	Storage	Faculty Room Closet	yes	W2	Plaster	Tan	N/A	N/A	N/A	N/A
1	2	204.5	Storage	Faculty Room Closet	yes	W3	Plaster	Tan	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	2	204.5	Storage	Faculty Room Closet	yes	W4	Plaster	Tan	N/A	N/A	4.4	Positive
1	2	204.5	Storage	Faculty Room Closet	yes	Ceiling	Plaster	White	Flaking	20	12.2	Positive
1	2	204.5	Storage	Faculty Room Closet	yes	Floor	Linoleum	N/A	None	0	N/A	N/A
1	2	205.7	Restrooms, Staff - Male/Female	Faculty Room Restroom	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	205.7	Restrooms, Staff - Male/Female	Faculty Room Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	205.7	Restrooms, Staff - Male/Female	Faculty Room Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	205.7	Restrooms, Staff - Male/Female	Faculty Room Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	205.7	Restrooms, Staff - Male/Female	Faculty Room Restroom	yes	Ceiling	Plaster	White	Chipping	2	13.9	Positive
1	2	205.7	Restrooms, Staff - Male/Female	Faculty Room Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W1	Plaster	Multi Color	None	0	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W2	Plaster	White	Chipping	2	1	Positive
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W3	Plaster	White	Chipping	10	26.2	Positive
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W4	Plaster	White	Chipping	0	2	Positive
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia
Lead Safe Certification Assessment Report
Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	Ceiling	Plaster	White	Cracking	1360	18.5	Positive
1	2	H23	Circulation (Hallway)	2nd Floor Hallway	yes	Floor	Concrete	Brown	Chipping	100	1.4	Positive
1	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	W1	Plaster	Beige	Chipping	5	19.5	Positive
1	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	W2	Plaster	Beige	Chipping	6	24.1	Positive
1	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	W3	Plaster	Beige	chipping, holes	9	21.7	Positive
1	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	Ceiling	Plaster	White	Cracking	16	22.5	Positive
	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	Newel Post	Metal	Grey	Chipping	4	12.2	Positive
	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	Stringer	Concrete	Grey	Chipping	40	3	Positive
	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	Riser	Concrete	Grey	Chipping	75	3.8	Positive
	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	Tread	Concrete	Grey	Chipping	75	0.2	Negative
1	2	S23	Stairs	Stairwell across from Classrooms 202 and 203	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 206	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 206	yes	W2	Plaster	Tan	Chipping	4	19.1	Positive
1	2	S21	Stairs	Stairwell next to Classroom 206	yes	W3	Plaster	Tan	Moisture Damage	12	21	Positive
1	2	S21	Stairs	Stairwell next to Classroom 206	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 206	yes	Ceiling	Plaster	Tan	Chipping	15	19.2	Positive
	2	S21	Stairs	Stairwell next to Classroom 206	yes	Newel Post	Metal	Grey	Chipping	4	20	Positive
	2	S21	Stairs	Stairwell next to Classroom 206	yes	Baluster	Metal	Grey	Chipping	2	13	Positive
	2	S21	Stairs	Stairwell next to Classroom 206	yes	Stringer	Concrete	Grey	Chipping	40	6.7	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
	2	S21	Stairs	Stairwell next to Classroom 206	yes	Tread	Concrete	Grey	Chipping	35	0.2	Negative
	2	S21	Stairs	Stairwell next to Classroom 206	yes	Riser	Concrete	Grey	Chipping	35	2.7	Positive
1	2	S21	Stairs	Stairwell next to Classroom 206	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	252	Storage	Storage above Stage Left	yes	W1	Plaster	Tan	Chipping	2	11.8	Positive
1	2	252	Storage	Storage above Stage Left	yes	W2	Plaster	Tan	Efflorescence	30	15.2	Positive
1	2	252	Storage	Storage above Stage Left	yes	W3	Plaster	Tan	Flaking/Chipping	40	12.3	Positive
1	2	252	Storage	Storage above Stage Left	yes	W4	Plaster	Tan	Cracking	5	14.8	Positive
1	2	252	Storage	Storage above Stage Left	yes	Ceiling	Plaster	White	Cracking	15	17.6	Positive
1	2	252	Storage	Storage above Stage Left	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	252A	Storage	Storage above Stage Left - Rear Closet	yes	W1	Plaster	Beige	N/A	N/A	N/A	N/A
1	2	252A	Storage	Storage above Stage Left - Rear Closet	yes	W2	Plaster	Beige	N/A	N/A	N/A	N/A
1	2	252A	Storage	Storage above Stage Left - Rear Closet	yes	W3	Plaster	Beige	N/A	N/A	N/A	N/A
1	2	252A	Storage	Storage above Stage Left - Rear Closet	yes	W4	Plaster	Beige	N/A	N/A	N/A	N/A
1	2	252A	Storage	Storage above Stage Left - Rear Closet	yes	Ceiling	Plaster	White	N/A	N/A	N/A	N/A
1	2	252A	Storage	Storage above Stage Left - Rear Closet	yes	Floor	No Access	N/A	N/A	N/A	N/A	N/A
1	2	250	Storage	Storage above Stage Right	yes	W1	Plaster	Tan	Cracking	5	17.4	Positive
1	2	250	Storage	Storage above Stage Right	yes	W2	Plaster	Tan	Cracking	5	23.3	Positive
1	2	250	Storage	Storage above Stage Right	yes	W3	Plaster	Tan	Flaking, cracking	18	13.3	Positive
1	2	250	Storage	Storage above Stage Right	yes	W4	Plaster	Tan	Flaking, cracking	15	23.7	Positive
1	2	250	Storage	Storage above Stage Right	yes	Ceiling	Plaster	White	Moisture Damage	15	25.6	Positive
1	2	250	Storage	Storage above Stage Right	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	250A	Storage	Storage above Stage Right - Rear Closet	yes	W1	Plaster	Tan	Cracking	10	16.3	Positive
1	2	250A	Storage	Storage above Stage Right - Rear Closet	yes	W2	Plaster	Tan	Flaking	40	14.3	Positive
1	2	250A	Storage	Storage above Stage Right - Rear Closet	yes	W3	Plaster	Tan	Flaking	40	19.4	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	2	250A	Storage	Storage above Stage Right - Rear Closet	yes	W4	Plaster	Tan	Flaking	20	15.3	Positive
1	2	250A	Storage	Storage above Stage Right - Rear Closet	yes	Ceiling	Plaster	White	Flaking	20	19.2	Positive
1	2	250A	Storage	Storage above Stage Right - Rear Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	309	Art - Elementary	Art Room 309	yes	W1	Plaster	Tan	Chipping	1	16.6	Positive
1	3	309	Art - Elementary	Art Room 309	yes	W2	Plaster	Tan	Cracking	20	12.7	Positive
1	3	309	Art - Elementary	Art Room 309	yes	W3	Plaster	Tan	Cracking	5	16.1	Positive
1	3	309	Art - Elementary	Art Room 309	yes	W4	Plaster	Tan	Chipping	2	20	Positive
1	3	309	Art - Elementary	Art Room 309	yes	Ceiling	Plaster	Tan	Chipping	50	17.7	Positive
1	3	309	Art - Elementary	Art Room 309	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	309A	Storage	Art Room 309 Storage Room	yes	W1	Plaster	Tan	None	0	9.7	Positive
1	3	309A	Storage	Art Room 309 Storage Room	yes	W2	Plaster	Tan	None	0	14.7	Positive
1	3	309A	Storage	Art Room 309 Storage Room	yes	W3	Plaster	Tan	None	0	14.2	Positive
1	3	309A	Storage	Art Room 309 Storage Room	yes	W4	Plaster	Blue	Flaking, holes	8	10.1	Positive
1	3	309A	Storage	Art Room 309 Storage Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	309A	Storage	Art Room 309 Storage Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	309B	Storage	Art Room 309 Closet	yes	W1	Plaster	Tan	Cracking	1	10.1	Positive
1	3	309B	Storage	Art Room 309 Closet	yes	W2	Plaster	Tan	Cracking	1	19.2	Positive
1	3	309B	Storage	Art Room 309 Closet	yes	W3	Plaster	Tan	None	0	29.1	Positive
1	3	309B	Storage	Art Room 309 Closet	yes	W4	Plaster	Tan	Cracking	1	17.3	Positive
1	3	309B	Storage	Art Room 309 Closet	yes	Ceiling	Plaster	Tan	Chipping	15	15.1	Positive
1	3	309B	Storage	Art Room 309 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	300	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	3	300	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Plaster	N/A	Chipping	40	18.1	Positive
1	3	300	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Plaster	White	Moisture/Efflorescence	25	38.8	Positive
1	3	300A	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300B	Service Closets	Custodial Closet next to Classroom 301	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300B	Service Closets	Custodial Closet next to Classroom 301	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300B	Service Closets	Custodial Closet next to Classroom 301	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300B	Service Closets	Custodial Closet next to Classroom 301	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	300B	Service Closets	Custodial Closet next to Classroom 301	yes	Ceiling	Plaster	White	Holes	1	23.9	Positive
1	3	300B	Service Closets	Custodial Closet next to Classroom 301	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	301	Primary	Classroom 301	yes	W1	Plaster	Green	Chipping	5	5	Positive

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	3	301	Primary	Classroom 301	yes	W2	Plaster	Green	Chipping	2	4.9	Positive
1	3	301	Primary	Classroom 301	yes	W3	Plaster	Green	Chipping	7	19.8	Positive
1	3	301	Primary	Classroom 301	yes	W4	Plaster	Green	Chipping	2	16.2	Positive
	3	301	Primary	Classroom 301	yes	W1- Baseboard	Wood	Brown	Chipping	5	0.2	Negative
	3	301	Primary	Classroom 301	yes	W2- Baseboard	Wood	Brown	Chipping	5	0.3	Negative
	3	301	Primary	Classroom 301	yes	W3- Baseboard	Wood	Brown	Chipping	5	0.3	Negative
	3	301	Primary	Classroom 301	yes	W4- Baseboard	Wood	Brown	Chipping	5	0.3	Negative
1	3	301	Primary	Classroom 301	yes	Ceiling	Plaster	Tan	Chipping	350	31	Positive
1	3	301	Primary	Classroom 301	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	W1	Plaster	Green	Cracking	5	5	Positive
1	3	301A	Storage	Classroom 301 Closet	yes	W2	Plaster	Green	Chipping/Cracking	5	14.2	Positive
1	3	301A	Storage	Classroom 301 Closet	yes	W3	Plaster	Green	Cracking	50	9.5	Positive
1	3	301A	Storage	Classroom 301 Closet	yes	W4	Plaster	Green	Cracking	5	9.7	Positive
1	3	301A	Storage	Classroom 301 Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	301B	Storage	Classroom 301 Sink Closet	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	301B	Storage	Classroom 301 Sink Closet	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	301B	Storage	Classroom 301 Sink Closet	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	301B	Storage	Classroom 301 Sink Closet	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	301B	Storage	Classroom 301 Sink Closet	yes	Ceiling	Plaster	White	cracking, holes	3	13.7	Positive
1	3	301B	Storage	Classroom 301 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	310	Service Closets	Custodial Closet across from Classrooms 301 and 302	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	3	310	Service Closets	Custodial Closet across from Classrooms 301 and 302	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	310	Service Closets	Custodial Closet across from Classrooms 301 and 302	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	3	310	Service Closets	Custodial Closet across from Classrooms 301 and 302	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	3	310	Service Closets	Custodial Closet across from Classrooms 301 and 302	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	3	310	Service Closets	Custodial Closet across from Classrooms 301 and 302	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	310	Service Closets	Custodial Closet across from Classrooms 301 and 302	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	310	Service Closets	Custodial Closet across from Classrooms 301 and 302	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	3	308.5	Administrative Office	Faculty Room (309A)	yes	W1	Plaster	Green	Chipping	2	30.4	Positive
1	3	308.5	Administrative Office	Faculty Room (309A)	yes	W2	Plaster	Green	Chipping	4	22.7	Positive
1	3	308.5	Administrative Office	Faculty Room (309A)	yes	W3	Plaster	Green	Chipping	15	12.3	Positive
1	3	308.5	Administrative Office	Faculty Room (309A)	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308.5	Administrative Office	Faculty Room (309A)	yes	W4	Plaster	Green	Chipping	5	24.1	Positive
1	3	308.5	Administrative Office	Faculty Room (309A)	yes	Ceiling	Plaster	N/A	Chipping	25	22.1	Positive
1	3	308.5	Administrative Office	Faculty Room (309A)	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	308.5A	Storage	Faculty Room Closet with Kiln	yes	W1	Plaster	Yellow	Cracking	1	17.8	Positive
1	3	308.5A	Storage	Faculty Room Closet with Kiln	yes	W2	Plaster	Yellow	Cracking	1	20.5	Positive
1	3	308.5A	Storage	Faculty Room Closet with Kiln	yes	W3	Plaster	Yellow	Cracking	6	18.2	Positive
1	3	308.5A	Storage	Faculty Room Closet with Kiln	yes	W4	Plaster	Yellow	Cracking	2	22.6	Positive
1	3	308.5A	Storage	Faculty Room Closet with Kiln	yes	Ceiling	Plaster	White	Cracking	5	16.5	Positive
1	3	308.5A	Storage	Faculty Room Closet with Kiln	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	308.5B	Storage	Faculty Room Rear Closet in Kiln Room	yes	W1	Plaster	Tan	Cracking	40	0	Negative
1	3	308.5B	Storage	Faculty Room Rear Closet in Kiln Room	yes	W2	Plaster	Tan	Cracking	40	0.5	Negative

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	3	308.5B	Storage	Faculty Room Rear Closet in Kiln Room	yes	W3	Plaster	Tan	Cracking	40	0.5	Negative
1	3	308.5B	Storage	Faculty Room Rear Closet in Kiln Room	yes	W4	Plaster	Tan	Cracking	40	0.5	Negative
1	3	308.5B	Storage	Faculty Room Rear Closet in Kiln Room	yes	Ceiling	Plaster	Tan	Cracking	40	0.5	Negative
1	3	308.5B	Storage	Faculty Room Rear Closet in Kiln Room	yes	Floor	Concrete	None	None	N/A	N/A	N/A
1	3	302	Primary	Classroom 302	yes	W1	Plaster	Blue	Chipping	2	16	Positive
1	3	302	Primary	Classroom 302	yes	W2	Sheetrock	Blue	Chipping	2	0.1	Negative
1	3	302	Primary	Classroom 302	yes	W3	Plaster	Blue	Cracking	2	14.9	Positive
1	3	302	Primary	Classroom 302	yes	W4	Plaster	Blue	Chipping	6	13.9	Positive
1	3	302	Primary	Classroom 302	yes	Ceiling	Plaster	Tan	Chipping	125	24.5	N/A
1	3	302	Primary	Classroom 302	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	W1	Plaster	Blue	Cracking	10	10.3	Positive
1	3	302A	Storage	Classroom 302 Closet	yes	W2	Plaster	Blue	Cracking	2	9.4	Positive
1	3	302A	Storage	Classroom 302 Closet	yes	W3	Plaster	Blue	Cracking/Chipping	14	9.6	Positive
1	3	302A	Storage	Classroom 302 Closet	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	W4	Plaster	Blue	Cracking/Chipping	10	8.9	Positive
1	3	302A	Storage	Classroom 302 Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	302B	Storage	Classroom 302 Sink Closet	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	302B	Storage	Classroom 302 Sink Closet	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	302B	Storage	Classroom 302 Sink Closet	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	302B	Storage	Classroom 302 Sink Closet	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	302B	Storage	Classroom 302 Sink Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	302B	Storage	Classroom 302 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	303	Primary	Classroom 303	yes	W1	Plaster	Beige	Chipping	30	8.6	Positive
1	3	303	Primary	Classroom 303	yes	W2	Sheetrock	Beige	Chipping	20	0	Negative
1	3	303	Primary	Classroom 303	yes	W3	Plaster	Beige	Chipping	30	16.4	Positive
1	3	303	Primary	Classroom 303	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Primary	Classroom 303	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Primary	Classroom 303	yes	W4	Sheetrock	Beige	Cracking	5	0.1	Negative

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	3	303	Primary	Classroom 303	yes	Ceiling	Plaster	Tan	Chipping	175	27.1	N/A
1	3	303	Primary	Classroom 303	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	303A	Storage	Classroom 303 Closet	yes	W1	Plaster	Beige	Cracking	10	1	Positive
1	3	303A	Storage	Classroom 303 Closet	yes	W2	Plaster	Beige	Cracking	2	1	Positive
1	3	303A	Storage	Classroom 303 Closet	yes	W3	Plaster	Beige	Cracking	10	1	Positive
1	3	303A	Storage	Classroom 303 Closet	yes	W4	Plaster	Beige	Cracking	10	1	Positive
1	3	303A	Storage	Classroom 303 Closet	yes	Ceiling	Plaster	Beige	Cracking	50	9	Positive
1	3	303A	Storage	Classroom 303 Closet	yes	Floor	Wood	Varnish	None	N/A	N/A	N/A
1	3	303B	Storage	Classroom 303 Sink Closet	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	303B	Storage	Classroom 303 Sink Closet	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	303B	Storage	Classroom 303 Sink Closet	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	303B	Storage	Classroom 303 Sink Closet	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	303B	Storage	Classroom 303 Sink Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	303B	Storage	Classroom 303 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	308	Primary	Classroom 308	yes	W1	Plaster	Green	Chipping	10	21.6	Positive
1	3	308	Primary	Classroom 308	yes	W2	Plaster	Green	Cracking	1	17.3	Positive
1	3	308	Primary	Classroom 308	yes	W3	Plaster	Green	Flaking	50	22.8	Positive
1	3	308	Primary	Classroom 308	yes	W4	Plaster	Green	Chipping	5	19	Positive
1	3	308	Primary	Classroom 308	yes	Ceiling	Plaster	Tan	Chipping	75	13.1	Positive
1	3	308	Primary	Classroom 308	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	308A	Storage	Classroom 308 Closet	yes	W1	Plaster	Green	Cracking/Chipping	10	10.1	Positive
1	3	308A	Storage	Classroom 308 Closet	yes	W2	Plaster	Green	None	0	N/A	N/A
1	3	308A	Storage	Classroom 308 Closet	yes	W3	Plaster	Green	Chipping	25	9.3	Positive
1	3	308A	Storage	Classroom 308 Closet	yes	W4	Plaster	Green	Cracking	25	11.5	Positive
1	3	308A	Storage	Classroom 308 Closet	yes	Ceiling	Plaster	Tan	Flaking	50	9.8	Positive
1	3	308A	Storage	Classroom 308 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	308B	Storage	Classroom 308 Sink Closet	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	308B	Storage	Classroom 308 Sink Closet	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	308B	Storage	Classroom 308 Sink Closet	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	308B	Storage	Classroom 308 Sink Closet	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/ negative)
1	3	308B	Storage	Classroom 308 Sink Closet	yes	Ceiling	Plaster	White	Cracking	1	16.3	Positive
1	3	308B	Storage	Classroom 308 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	304	Primary	Classroom 304	yes	W1	Plaster	White	Chipping	5	19.5	Positive
1	3	304	Primary	Classroom 304	yes	W2	Plaster	Green	Chipping	2	12	Positive
1	3	304	Primary	Classroom 304	yes	W3	Plaster	White	Chipping	30	15.4	Positive
1	3	304	Primary	Classroom 304	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Primary	Classroom 304	yes	W4	Sheetrock	Tan	Chipping	20	0.1	Negative
1	3	304	Primary	Classroom 304	yes	Ceiling	Plaster	Tan	Flaking	150	26.5	N/A
1	3	304	Primary	Classroom 304	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	304A	Storage	Classroom 304 Closet	yes	W1	Plaster	White	Cracking	5	12	Positive
1	3	304A	Storage	Classroom 304 Closet	yes	W2	Plaster	White	Cracking	2	15.2	Positive
1	3	304A	Storage	Classroom 304 Closet	yes	W3	Plaster	White	Efflorescence	5	16.2	Positive
1	3	304A	Storage	Classroom 304 Closet	yes	W4	Plaster	White	Cracking	5	25.3	Positive
1	3	304A	Storage	Classroom 304 Closet	yes	Ceiling	Plaster	Tan	Efflorescence	30	8	Positive
1	3	304A	Storage	Classroom 304 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	304B	Storage	Classroom 304 Sink Closet	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	304B	Storage	Classroom 304 Sink Closet	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	304B	Storage	Classroom 304 Sink Closet	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	304B	Storage	Classroom 304 Sink Closet	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	304B	Storage	Classroom 304 Sink Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	304B	Storage	Classroom 304 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	311	Restrooms, Staff - Female	Women's Restroom between Classrooms 304 and 305	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	311	Restrooms, Staff - Female	Women's Restroom between Classrooms 304 and 305	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	311	Restrooms, Staff - Female	Women's Restroom between Classrooms 304 and 305	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	311	Restrooms, Staff - Female	Women's Restroom between Classrooms 304 and 305	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	S p a c e #	S p a c e T y p e	O n- S i t e R o o m N a m e	S t u d e n t/ T e a c h e r O c c u p i e d (y e s/ n o)	P r i m a r y C o m p o n e n t	S u b s t r a t e M a t e r i a l	C o l o r	D e s c r i p t i o n o f P r i m a r y D a m a g e	P r i m a r y C o m p o n e n t D a m a g e Q u a n t i t y (s f)	X R F R e a d i n g (m g/ c m ²)	P r i m a r y C o m p o n e n t X R F (p o s i t i v e/ n e g a t i v e)
1	3	311	Restrooms, Staff - Female	Women's Restroom between Classrooms 304 and 305	yes	Ceiling	Plaster	White	Cracking	1	15.6	Positive
1	3	311	Restrooms, Staff - Female	Women's Restroom between Classrooms 304 and 305	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	305	Primary	Classroom 305	yes	W1	Plaster	Beige	Chipping	3	14.5	Positive
1	3	305	Primary	Classroom 305	yes	W2	Plaster	Beige	Chipping	3	9.4	Positive
1	3	305	Primary	Classroom 305	yes	W3	Plaster	Beige	Cracking	6	15.6	Positive
1	3	305	Primary	Classroom 305	yes	W4	Plaster	Beige	Chipping	5	18.2	Positive
1	3	305	Primary	Classroom 305	yes	Ceiling	Plaster	Tan	Chipping	350	22	Positive
1	3	305	Primary	Classroom 305	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	305AA	Storage	Classroom 305 Front Closet	yes	W1	Plaster	Beige	Chipping	2	12	Positive
1	3	305AA	Storage	Classroom 305 Front Closet	yes	W2	Plaster	Beige	Chipping	5	16	Positive
1	3	305AA	Storage	Classroom 305 Front Closet	yes	W3	Plaster	Beige	Chipping	10	25.3	Positive
1	3	305AA	Storage	Classroom 305 Front Closet	yes	W4	Plaster	Beige	Chipping	10	25.3	Positive
1	3	305AA	Storage	Classroom 305 Front Closet	yes	Ceiling	Plaster	Tan	Cracking	6	13.6	Positive
1	3	305AA	Storage	Classroom 305 Front Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A
1	3	305A	Storage	Classroom 305 Closet	yes	W1	Plaster	Beige	Chipping	5	56.2	Positive
1	3	305A	Storage	Classroom 305 Closet	yes	W2	Plaster	Beige	Chipping	10	8.9	Positive
1	3	305A	Storage	Classroom 305 Closet	yes	W3	Plaster	Beige	Chipping	5	9.8	Positive
1	3	305A	Storage	Classroom 305 Closet	yes	W4	Plaster	Beige	Chipping	2	9.9	Positive
1	3	305A	Storage	Classroom 305 Closet	yes	Ceiling	Plaster	Tan	Chipping	30	13.9	Positive
1	3	305A	Storage	Classroom 305 Closet	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	305B	Storage	Classroom 305 Sink Closet	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	3	305B	Storage	Classroom 305 Sink Closet	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	3	305B	Storage	Classroom 305 Sink Closet	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	3	305B	Storage	Classroom 305 Sink Closet	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	3	305B	Storage	Classroom 305 Sink Closet	yes	Ceiling	Plaster	White	Holes	2	Not Tested	N/A
1	3	305B	Storage	Classroom 305 Sink Closet	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	3	306	Primary	Classroom 306	yes	W1	Plaster	Green	Chipping	10	20.6	Positive
1	3	306	Primary	Classroom 306	yes	W2	Plaster	Green	Chipping	25	18.4	Positive
1	3	306	Primary	Classroom 306	yes	W3	Plaster	Green	Chipping	50	8.6	Positive
1	3	306	Primary	Classroom 306	yes	W4	Plaster	Green	Chipping	10	9.2	Positive
1	3	306	Primary	Classroom 306	yes	Ceiling	Plaster	Tan	Chipping	175	22.2	Positive
1	3	306	Primary	Classroom 306	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	306B	Storage	Classroom 306 Sink Closet	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	306B	Storage	Classroom 306 Sink Closet	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	306B	Storage	Classroom 306 Sink Closet	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	306B	Storage	Classroom 306 Sink Closet	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	306B	Storage	Classroom 306 Sink Closet	yes	Ceiling	Plaster	White	Chipping	1	15	Positive
1	3	306B	Storage	Classroom 306 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	W1	Plaster	Green	N/A	N/A	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	W2	Plaster	Green	Chipping	15	9.3	Positive
1	3	306A	Storage	Classroom 306 Closet	yes	W3	Plaster	Green	Chipping	5	27.9	Positive
1	3	306A	Storage	Classroom 306 Closet	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	W4	Plaster	Green	N/A	N/A	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	Ceiling	Plaster	White	N/A	N/A	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	312A	Storage	Book Storage adjacent to R-306	yes	W1	Plaster	Tan	Cracking	20	N/A	N/A
1	3	312A	Storage	Book Storage adjacent to R-306	yes	W2	Plaster	Tan	Cracking	2	N/A	N/A
1	3	312A	Storage	Book Storage adjacent to R-306	yes	W3	Plaster	Tan	Cracking	20	N/A	N/A
1	3	312A	Storage	Book Storage adjacent to R-306	yes	W4	Plaster	Tan	Cracking	10	N/A	N/A
1	3	312A	Storage	Book Storage adjacent to R-306	yes	Ceiling	Plaster	White	Cracking	15	N/A	N/A
1	3	312A	Storage	Book Storage adjacent to R-306	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	313	Administrative Office	School Psychologist Office near Classroom 307 (AKA R-306B)	yes	W1	Plaster	Green	Chipping	2	4.6	Positive

School District of Philadelphia
Lead Safe Certification Assessment Report
Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	313	Administrative Office	School Psychologist Office near Classroom 307 (AKA R-306B)	yes	W2	Plaster	Green	chipping/flaking	20	16.5	Positive
1	3	313	Administrative Office	School Psychologist Office near Classroom 307 (AKA R-306B)	yes	W3	Plaster	Blue	Efflorescence	20	11.3	Positive
1	3	313	Administrative Office	School Psychologist Office near Classroom 307 (AKA R-306B)	yes	W4	Plaster	Blue	Chipping	4	15.8	Positive
1	3	313	Administrative Office	School Psychologist Office near Classroom 307 (AKA R-306B)	yes	Ceiling	Plaster	Tan	Cracking	15	17.2	Positive
1	3	313	Administrative Office	School Psychologist Office near Classroom 307 (AKA R-306B)	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	313A	Restrooms, Staff - Female	Restroom in Psychologist Office	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	313A	Restrooms, Staff - Female	Restroom in Psychologist Office	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	313A	Restrooms, Staff - Female	Restroom in Psychologist Office	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	313A	Restrooms, Staff - Female	Restroom in Psychologist Office	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	313A	Restrooms, Staff - Female	Restroom in Psychologist Office	yes	Ceiling	Plaster	White	Cracking	15	10.3	Positive
1	3	313A	Restrooms, Staff - Female	Restroom in Psychologist Office	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	312	Administrative Office	Counselor's Office next to Psychologist Office	yes	W1	Plaster	Purple	chipping/efflorescence	12	19.4	Positive
1	3	312	Administrative Office	Counselor's Office next to Psychologist Office	yes	W2	Plaster	Purple	Flaking	3	8.3	Positive
1	3	312	Administrative Office	Counselor's Office next to Psychologist Office	yes	W3	Plaster	Purple	Cracking	1	0	Negative
1	3	312	Administrative Office	Counselor's Office next to Psychologist Office	yes	W4	Plaster	Purple	None	0	5.6	Positive
1	3	312	Administrative Office	Counselor's Office next to Psychologist Office	yes	Ceiling	plaster	White	Cracking	2	12.2	Positive
1	3	312	Administrative Office	Counselor's Office next to Psychologist Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	312B	Circulation (Hallway)	Hallway Area between Psychologist Office and Counselor Office	yes	W1	Plaster	White	Chipping	1	0.06	Negative

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	3	312B	Circulation (Hallway)	Hallway Area between Psychologist Office and Counselor Office	yes	W2	Plaster	White	none	0	N/A	N/A
1	3	312B	Circulation (Hallway)	Hallway Area between Psychologist Office and Counselor Office	yes	W3	Plaster	White	none	0	N/A	N/A
1	3	312B	Circulation (Hallway)	Hallway Area between Psychologist Office and Counselor Office	yes	W4	Plaster	White	none	0	N/A	N/A
1	3	312B	Circulation (Hallway)	Hallway Area between Psychologist Office and Counselor Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	312B	Circulation (Hallway)	Hallway Area between Psychologist Office and Counselor Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	307	Primary	Classroom 307	yes	W1	Plaster	Green	Chipping	20	11	Positive
1	3	307	Primary	Classroom 307	yes	W2	Plaster	Green	Chipping	20	13	Positive
1	3	307	Primary	Classroom 307	yes	W3	Plaster	Green	Chipping	50	15	Positive
1	3	307	Primary	Classroom 307	yes	W4	Plaster	Green	Chipping	16	11	Positive
1	3	307	Primary	Classroom 307	yes	Ceiling	Plaster	Tan	Chipping	75	29	Positive
1	3	307	Primary	Classroom 307	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	W1	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	W2	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	W3	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1	3	307B	Storage	Classroom 307 Sink Closet	yes	W1	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	307B	Storage	Classroom 307 Sink Closet	yes	W2	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	307B	Storage	Classroom 307 Sink Closet	yes	W3	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	307B	Storage	Classroom 307 Sink Closet	yes	W4	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	307B	Storage	Classroom 307 Sink Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	307B	Storage	Classroom 307 Sink Closet	yes	Floor	Ceramic Tile	N/A	None	0	N/A	N/A
1	3	H34	Circulation (Hallway)	3rd Floor Hallway	yes	W1	Plaster	White	none	0	N/A	N/A

School District of Philadelphia

Lead Safe Certification Assessment Report

Meredith Elementary School

Name of Inspector: Brian Joseph
Inspection Company: Acer

Element	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm ²)	Primary Component XRF (positive/negative)
1	3	H34	Circulation (Hallway)	3rd Floor Hallway	yes	W2	Plaster	Beige	Chipping	6	20.2	Positive
1	3	H34	Circulation (Hallway)	3rd Floor Hallway	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H34	Circulation (Hallway)	3rd Floor Hallway	yes	W4	Plaster	Beige	Cracking	4	18.1	Positive
	3	H34	Circulation (Hallway)	3rd Floor Hallway	yes	Door Casing W3	Metal	Brown	Chipping	1	0.4	Negative
1	3	H34	Circulation (Hallway)	3rd Floor Hallway	yes	Ceiling	Plaster	N/A	Flaking	175	24.1	Positive
1	3	H34	Circulation (Hallway)	3rd Floor Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairs	Stairwell outside Classroom 306	yes	W1	Metal and glass	Brown	Chipping	6	0.12	Negative
1	3	S31	Stairs	Stairwell outside Classroom 306	yes	W2	Plaster	Beige	Cracking	1	18	Positive
1	3	S31	Stairs	Stairwell outside Classroom 306	yes	W3	Plaster	Beige	Cracking	2	18.1	Positive
1	3	S31	Stairs	Stairwell outside Classroom 306	yes	W4	Plaster	Beige	Chipping	1	23.5	Positive
1	3	S31	Stairs	Stairwell outside Classroom 306	yes	Ceiling	Plaster	White	None	0	18.5	Positive
1	3	S31	Stairs	Stairwell outside Classroom 306	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S33	Stairs	Stairwell outside Classroom 308	yes	W1	Plaster	Tan	Cracking	5	27.4	Positive
	3	S33	Stairs	Stairwell outside Classroom 308	yes	W2	Plaster	Tan	Cracking	1	18.1	Positive
1	3	S33	Stairs	Stairwell next to Classroom 308	yes	W3	Plaster	Tan	Cracking	2	19.8	Positive
1	3	S33	Stairs	Stairwell next to Classroom 308	yes	W4	glass and metal door system	Tan	Chipping	1	18.9	Positive
1	3	S33	Stairs	Stairwell next to Classroom 308	yes	Ceiling	Plaster	White	Cracking	15	19.6	Positive
	3	S33	Stairs	Stairwell next to Classroom 308	yes	Newel Post	Metal	Grey	Chipping	2	13.5	Positive
	3	S33	Stairs	Stairwell next to Classroom 308	yes	Baluster	Metal	Grey	Chipping	1	11.7	Positive
	3	S33	Stairs	Stairwell next to Classroom 308	yes	Stringer	Concrete	Grey	Chipping	1	5.2	Positive
1	3	S33	Stairs	Stairwell next to Classroom 308	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A