

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Girl's Restroom next to Classroom 102	yes	W1	Plaster/Ceramic	White	None	0	N/A	N/A
7390	1	1	Girl's Restroom next to Classroom 102	yes	W2	Plaster/Ceramic	White	None	0	N/A	N/A
7390	1	1	Girl's Restroom next to Classroom 102	yes	W3	Plaster/Ceramic	White	None	0	N/A	N/A
7390	1	1	Girl's Restroom next to Classroom 102	yes	W4	Plaster/Ceramic	White	None	0	N/A	N/A
7390	1	1	Girl's Restroom next to Classroom 102	yes	Ceiling	Plaster	White	Cracking	1	17.9	Positive
7390	1	1	Girl's Restroom next to Classroom 102	yes	Floor	Concrete	Grey	Chipping, Contact	2	0	Negative
7390	1	1	Classroom 102	yes	W1	Plaster	Beige	Damaged Plaster	1	28.3	Positive
7390	1	1	Classroom 102	yes	W2	Plaster	Beige	Cracking	5	24.5	Positive
7390	1	1	Classroom 102	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 102	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 102	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1		yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 102	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 102 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 102 Storage	yes	W2	Plaster	Beige	Cracking	2	13.5	Positive
7390	1	1	Classroom 102 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 102 Storage	yes	W4	Plaster	Beige	Cracking	2	24.8	Positive
7390	1	1	Classroom 102 Storage	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 102 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 103	yes	W1	Plaster	Beige	Cracking	6	24.4	Positive
7390	1	1	Classroom 103	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 103	yes	W3	Plaster	Beige	Cracking	2	22.3	Positive
7390	1	1	Classroom 103	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 103	yes	W4	Plaster/Wood	Beige	None	0	N/A	N/A
7390	1	1	Classroom 103	yes	Ceiling	Plaster	Beige	Flaking	1	8.2	Positive
7390	1	1	Classroom 103	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 103 Storage	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Classroom 103 Storage	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Classroom 103 Storage	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Classroom 103 Storage	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Classroom 103 Storage	yes	Ceiling	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Classroom 103 Storage	yes	Floor	Wood	N/A	Partially Inaccessible	N/A	N/A	N/A
7390	1	1	Classroom 103 Storage Foyer	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 103 Storage Foyer	yes	W2	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Classroom 103 Storage Foyer	yes	W3	Plaster	Beige	Cracking	3	25.4	Positive
7390	1	1	Classroom 103 Storage Foyer	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 103 Storage Foyer	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 103 Storage Foyer	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 104	yes	W1	Plaster	Beige	Cracking, Flaking	10	24.8	Positive
7390	1	1	Classroom 104	yes	W2	Plaster	Beige	Cracking, Flaking	25	23.6	Positive
7390	1	1	Classroom 104	yes	W3	Plaster	Beige	Cracking, Flaking	4	26.8	Positive
7390	1	1	Classroom 104	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 104	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 104	yes	Ceiling	Plaster	Beige	Flaking	1	7.7	Positive
7390	1	1	Classroom 104	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 104 Storage	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Classroom 104 Storage	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Classroom 104 Storage	yes	W3	Plaster	Beige	Partially Inaccessible/Cracking	2	33.6	Positive
7390	1	1	Classroom 104 Storage	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Classroom 104 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 104 Storage	yes	Floor	Wood	N/A	Partially Inaccessible	N/A	N/A	N/A
7390	1	1	Main Office	yes	W1	Plaster	Beige	Chipping	1	23.5	Positive
7390	1	1	Main Office	yes	W2	Plaster	Beige/Blue	None	0	N/A	N/A
7390	1	1	Main Office	yes	W3	Plaster	Beige/Blue	None	0	N/A	N/A
7390	1	1	Main Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Main Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Main Office	yes	W4	Plaster	Beige	Flaking	6	25.9	Positive
7390	1	1	Main Office	yes	Ceiling	Plaster	Beige	Efflorescence, Flaking	4	7.9	Positive
7390	1	1	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Principal's Office	yes	W1	Plaster	Beige	Cracking	4	12.2	Positive
7390	1	1	Principal's Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Principal's Office	yes	W3	Plaster	Beige	Cracking	1	24.8	Positive
7390	1	1	Principal's Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Teacher Lounge Foyer	yes	W1	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Teacher Lounge Foyer	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Teacher Lounge Foyer	yes	W3	Sheetrock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Teacher Lounge Foyer	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Teacher Lounge Foyer	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Teacher Lounge Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stationery Closet in Main Office	yes	W1	Plaster	Beige	Cracking/Damaged Plaster	6	21.3	Positive
7390	1	1	Stationery Closet in Main Office	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Stationery Closet in Main Office	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Stationery Closet in Main Office	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	1	Stationery Closet in Main Office	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Stationery Closet in Main Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Teacher's Lounge	yes	W1	Sheetrock	Purple	Chipping	2	0	Negative
7390	1	1	Teacher's Lounge	yes	W2	Plaster	Purple	Cracking	2	26.2	Positive
7390	1	1	Teacher's Lounge	yes	W3	Plaster	Purple	None	0	N/A	N/A
7390	1	1	Teacher's Lounge	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Teacher's Lounge	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Teacher's Lounge	yes	W4	Sheetrock	Purple	None	0	N/A	N/A
7390	1	1	Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Teacher's Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Staff Restroom next to Teacher Lounge	yes	W1	Sheetrock	Beige	Flaking	2	0	Negative
7390	1	1	Staff Restroom next to Teacher Lounge	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Staff Restroom next to Teacher Lounge	yes	W3	Sheetrock	Beige	Flaking	2	0	Negative
7390	1	1	Staff Restroom next to Teacher Lounge	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Staff Restroom next to Teacher Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Staff Restroom next to Teacher Lounge	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	1	1	Principal's Restroom next to Teacher Lounge	yes	W1	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Principal's Restroom next to Teacher Lounge	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Principal's Restroom next to Teacher Lounge	yes	W3	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Principal's Restroom next to Teacher Lounge	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Principal's Restroom next to Teacher Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Principal's Restroom next to Teacher Lounge	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	1	1	Teacher Lounge Kitchen	yes	W1	Sheetrock	Purple	None	0	N/A	N/A
7390	1	1	Teacher Lounge Kitchen	yes	W2	Plaster	Purple	None	0	N/A	N/A
7390	1	1	Teacher Lounge Kitchen	yes	W3	Sheetrock	Purple	None	0	N/A	N/A
7390	1	1	Teacher Lounge Kitchen	yes	W4	Plaster	Purple	None	0	N/A	N/A
7390	1	1	Teacher Lounge Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Teacher Lounge Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 107	yes	W1	Plaster	Beige	Flaking	3	18.9	Positive
7390	1	1	Classroom 107	yes	W2	Plaster	Beige	Cracking	3	25	Positive
7390	1	1	Classroom 107 Coat Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 107	yes	W3	Plaster	Beige	Flaking	32	16.1	Positive
7390	1	1	Classroom 107	yes	W4	Plaster	Beige	flaking	10	27.9	Positive
7390	1	1	Classroom 107	yes	Ceiling	Plaster	Beige	Cracking, Efflorescence	20	8.4	Positive
7390	1	1	Classroom 107	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 107 Coat Room	yes	W1	Plaster	Beige	Cracking, Damaged Plaster	2	23	Positive
7390	1	1	Classroom 107 Coat Room	yes	W2	Plaster	Beige	Cracking	8	25.5	Positive
7390	1	1	Classroom 107 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 107 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 107 Coat Room	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 107 Coat Room	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Boy's Restroom next to Classroom 107	yes	W1	Plaster/Ceramic	Green	None	0	N/A	N/A
7390	1	1	Boy's Restroom next to Classroom 107	yes	W2	Plaster/Ceramic	Green	None	0	N/A	N/A
7390	1	1	Boy's Restroom next to Classroom 107	yes	W3	Plaster/Ceramic	Green	None	0	N/A	N/A
7390	1	1	Boy's Restroom next to Classroom 107	yes	W4	Plaster/Ceramic	Green	None	0	N/A	N/A
7390	1	1	Boy's Restroom next to Classroom 107	yes	Ceiling	Plaster	White	Flaking	4	27.6	Positive
7390	1	1	Boy's Restroom next to Classroom 107	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	1	Classroom 108	yes	W1	Plaster	Beige	Flaking	3	26.5	Positive
7390	1	1	Classroom 108	yes	W2	Plaster	Beige	Flaking	2	19.8	Positive
7390	1	1	Classroom 108	yes	W3	Plaster	Beige	Cracking	20	14.1	Positive
7390	1	1	Classroom 108	yes	W4	Sheetrock	Beige	Flaking	6	0	Negative
7390	1	1	Classroom 108	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 108	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Classroom 108 Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	1	1	Classroom 108 Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	1	1	Classroom 108 Storage	yes	W3	Plaster	Beige	Efflorescence	20	24	Positive
7390	1	1	Classroom 108 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 108 Storage	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Classroom 108 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Auditorium	yes	W1	Plaster	Beige	Cracking, flaking	20	19.2	Positive
7390	1	1	Auditorium	yes	W2	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Auditorium	yes	W3	Plaster	Beige	Crack in Plaster	4	13.9	Positive
7390	1	1	Auditorium	yes	W4	Plaster	Beige	Cracking	25	19.3	Positive
7390	1	1	Auditorium	yes	Ceiling	Plaster	White	Flaking, Cracking	10	No Test	Positive
7390	1	1	Auditorium	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Stage	yes	W2	Plaster	Beige	Crack in Plaster, Hole in Plaster	4	15	Positive
7390	1	1	Stage	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stage	yes	W3	Plaster	Beige	Cracking	20	14.6	Positive
7390	1	1	Stage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Stage	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	1	Stage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Storage to the right of Stage	yes	W1	Plaster	Beige	Flaking	5	19.2	Positive
7390	1	1	Storage to the right of Stage	yes	W2	Plaster	Beige	Flaking	4	20.3	Positive
7390	1	1	Storage to the right of Stage	yes	W3	Plaster	Beige	Flaking	2	24.3	Positive
7390	1	1	Storage to the right of Stage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Storage to the right of Stage	yes	Ceiling	Concrete	White	none	0	N/A	N/A
7390	1	1	Storage to the right of Stage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Philadelphia Police Office	yes	W1	Plaster	White/Orange	None	0	N/A	N/A
7390	1	1	Philadelphia Police Office	yes	W2	Plaster	White/Orange	None	0	N/A	N/A
7390	1	1	Philadelphia Police Office	yes	W3	Plaster	White/Orange	None	0	N/A	N/A
7390	1	1	Philadelphia Police Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Philadelphia Police Office	yes	W4	Plaster	White/Orange	None	0	N/A	N/A
7390	1	1	Philadelphia Police Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	1	Philadelphia Police Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Walkway behind Stage leading to Philadelphia Police Office	yes	W1	Plaster	White/Orange	None	0	N/A	N/A
7390	1	1	Walkway behind Stage leading to Philadelphia Police Office	yes	W2	Plaster	Orange	Cracking	3	19.5	Positive
7390	1	1	Walkway behind Stage leading to Philadelphia Police Office	yes	W3	Plaster	Orange	None	0	N/A	N/A
7390	1	1	Walkway behind Stage leading to Philadelphia Police Office	yes	W4	Plaster	Orange	Cracking	5	19.3	Positive
7390	1	1	Walkway behind Stage leading to Philadelphia Police Office	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Walkway behind Stage leading to Philadelphia Police Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	1	Walkway behind Stage leading to Philadelphia Police Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Left side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	W1	Plaster	Beige	Cracking	1	22.4	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Left side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	W2	Plaster	Beige	Flaking	3	19.3	Positive
7390	1	1	Left side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Left side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	W4	Sheetrock	Beige	None	0	N/A	N/A
7390	1	1	Left side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	1	Left side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Right side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	W1	Plaster	Beige	Cracking	2	21.6	Positive
7390	1	1	Right side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	W2	Sheetrock	Beige	Flaking	1	0	Negative
7390	1	1	Right side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	W3	Plaster	Beige	Crack in Plaster	3	26.7	Positive
7390	1	1	Right side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	W4	Plaster	Beige	Holes in Plaster	3	22.5	Positive
7390	1	1	Right side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	Ceiling	Concrete	Beige	None	0	N/A	N/A
7390	1	1	Right side Electrical Equipment/Storage in the Main Hallway across from Main Office	no	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	MDF Room in the Middle of the two Electrical Equipment/Storage Rooms	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
7390	1	1	MDF Room in the Middle of the two Electrical Equipment/Storage Rooms	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
7390	1	1	MDF Room in the Middle of the two Electrical Equipment/Storage Rooms	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
7390	1	1	MDF Room in the Middle of the two Electrical Equipment/Storage Rooms	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
7390	1	1	MDF Room in the Middle of the two Electrical Equipment/Storage Rooms	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
7390	1	1	MDF Room in the Middle of the two Electrical Equipment/Storage Rooms	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
7390	1	1	Storage in the Main Hallway across from Classroom 104	yes	W1	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Storage in the Main Hallway across from Classroom 104	yes	W2	Plaster	Beige	Partially Inaccessible/Flaking/Damaged Plaster	4	0.06	Negative
7390	1	1	Storage in the Main Hallway across from Classroom 104	yes	W3	Plaster	Beige	Partially Inaccessible/Cracking	6	26.5	Positive
7390	1	1	Storage in the Main Hallway across from Classroom 104	yes	W4	Plaster	Beige	Flaking	3	22	Positive
7390	1	1	Storage in the Main Hallway across from Classroom 104	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	1	Storage in the Main Hallway across from Classroom 104	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stationery Closet next to Stairwell across from Classroom 103	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Stationery Closet next to Stairwell across from Classroom 103	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Stationery Closet next to Stairwell across from Classroom 103	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Stationery Closet next to Stairwell across from Classroom 103	yes	W4	Plaster	Beige	Damaged Plaster	3	8.8	Positive
7390	1	1	Stationery Closet next to Stairwell across from Classroom 103	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	1	Stationery Closet next to Stairwell across from Classroom 103	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Main Hallway at Classrooms 102 to 107	yes	W1	Plaster	White	Flaking	7	25.6	Positive
7390	1	1	Main Hallway at Classrooms 102 to 107	yes	W1	Plaster	Green	Flaking	4	23.5	Positive
7390	1	1	Main Hallway at Classrooms 102 to 107	yes	W2	Plaster	Green	Flaking	2	12.6	Positive
7390	1	1	Main Hallway at Classrooms 102 to 107	yes	W3	Plaster	White/Green	None	0	N/A	N/A
7390	1	1	Main Hallway at Classrooms 102 to 107	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Main Hallway at Classrooms 102 to 107	yes	W4	Plaster	White/Green	None	0	N/A	N/A
7390	1	1	Main Hallway at Classrooms 102 to 107	yes	Ceiling	Plaster	White	Flaking	4	21.7	Positive
7390	1	1	Main Hallway at Classrooms 102 to 107	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	1	Hallway in front of Classroom 108	yes	W1	Plaster	White/Green	None	0	N/A	N/A
7390	1	1	Hallway in front of Classroom 108	yes	W2	Plaster	Green	Chipping	1	1	Positive
7390	1	1	Hallway in front of Classroom 108	yes	W3	Plaster	White/Green	None	0	N/A	N/A
7390	1	1	Hallway in front of Classroom 108	yes	W4	Plaster	White/Green	None	0	N/A	N/A
7390	1	1	Hallway in front of Classroom 108	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Hallway in front of Classroom 108	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	1	Hallway in front of Nurse's Office	yes	W1	Cinderblock	Green	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Hallway in front of Nurse's Office	yes	W2	Cinderblock	Blue	None	0	N/A	N/A
7390	3	1	Hallway in front of Nurse's Office	yes	W3	Cinderblock	Blue	None	0	N/A	N/A
7390	1	1	Hallway in front of Nurse's Office	yes	W4	Plaster	Beige	Cracking	5	18.9	Positive
7390	1	1	Hallway in front of Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Hallway in front of Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stairwell on Girls Restroom side	yes	W1	Plaster	Blue	Scratched	3	18.6	Positive
7390	1	1	Stairwell on Girls Restroom side	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	1	Stairwell on Girls Restroom side	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
7390	1	1	Stairwell on Girls Restroom side	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	1	Stairwell on Girls Restroom side	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stairwell on Girls Restroom side	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stairwell on Girls Restroom side	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	1	Stairwell on Girls Restroom side	yes	Floor	Concrete	Grey	Friction	2	0.2	Negative
7390	1	1	Stairwell on Girls Restroom side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stairwell on Girls Restroom side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	W1	Plaster	White/Yellow	None	0	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	W2	Plaster	Yellow	Efflorescence	6	0.06	Negative
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	W3	Plaster	Yellow	Efflorescence	1	0.07	Negative
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	W4	Plaster	White	Cracking	2	2.4	Positive
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	W4	Plaster	Yellow	Cracking	2	12.6	Positive
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell on Girls Restroom side	yes	Floor	Concrete	Grey	Chipping, Friction	10	0.02	Negative
7390	1	1	Stairwell across from Classroom 108	yes	W1	Plaster	Blue	Chipping	3	18.9	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	1	Stairwell across from Classroom 108	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	1	Stairwell across from Classroom 108	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
7390	1	1	Stairwell across from Classroom 108	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	1	Stairwell across from Classroom 108	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stairwell across from Classroom 108	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	1	Stairwell across from Classroom 108	yes	Floor	Concrete	Grey	Friction	2	0.2	Negative
7390	1	1	Stairwell across from Classroom 108	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Stairwell across from Classroom 108	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell across from Classroom 108	yes	W1	Plaster	White	None	0	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell across from Classroom 108	yes	W2	Plaster	White	None	0	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell across from Classroom 108	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell across from Classroom 108	yes	W3	Plaster	White	None	0	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell across from Classroom 108	yes	W4	Plaster	White	None	0	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell across from Classroom 108	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell across from Classroom 108	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	1	Exit Foyer in Middle Landing at Stairwell across from Classroom 108	yes	Floor	Concrete	Grey	Friction	10	0.1	Negative
7390	1	1	Fire Tower near Classroom 108 at Element #2	yes	W1	Brick	White	Cracking, Efflorescence	20	5	Positive
7390	1	1	Fire Tower near Classroom 108 at Element #2	yes	W2	Brick	White	Cracking	10	3.5	Positive
7390	1	1	Fire Tower near Classroom 108 at Element #2	yes	W3	Brick	White	Cracking, Efflorescence	40	3.1	Positive
7390	1	1	Fire Tower near Classroom 108 at Element #2	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	1	Fire Tower near Classroom 108 at Element #2	yes	W4	Brick	White	Cracking, Efflorescence	20	4.9	Positive
7390	1	1	Fire Tower near Classroom 108 at Element #2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	1	Fire Tower near Classroom 108 at Element #2	yes	Floor	Concrete	Grey	Flaking/Chipping	4	0.11	Negative
7390	1	1	Fire Tower near Classroom 108 at Element #2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 201	yes	W1	Plaster	Beige	Cracking	7	21.7	Positive
7390	1	2	Classroom 201	yes	W2	Plaster	Beige	Flaking, Damaged Plaster	8	17.6	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	2	Classroom 201	yes	W3	Plaster	Beige	Cracking	2	16.1	Positive
7390	1	2	Classroom 201	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 201	yes	W4	Plaster	Beige	Cracking	3	28.2	Positive
7390	1	2	Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 201	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Office 201A next to Classroom 201	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Office 201A next to Classroom 201	yes	W2	Plaster	Beige	Cracking	8	3.2	Positive
7390	1	2	Office 201A next to Classroom 201	yes	W3	Plaster	Beige	Cracking	3	26.3	Positive
7390	1	2	Office 201A next to Classroom 201	yes	W4	Plaster	Beige	Cracking	2	10.1	Positive
7390	1	2	Office 201A next to Classroom 201	yes	Ceiling	Plaster	Beige	Efflorescence, Flaking	4	16.9	Positive
7390	1	2	Office 201A next to Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Girl's Restroom next to Classroom 201	yes	W1	Plaster/Ceramic	White	None	0	N/A	N/A
7390	1	2	Girl's Restroom next to Classroom 201	yes	W2	Plaster/Ceramic	White	None	0	N/A	N/A
7390	1	2	Girl's Restroom next to Classroom 201	yes	W3	Plaster/Ceramic	White	None	0	N/A	N/A
7390	1	2	Girl's Restroom next to Classroom 201	yes	W4	Plaster/Ceramic	White	None	0	N/A	N/A
7390	1	2	Girl's Restroom next to Classroom 201	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	2	Girl's Restroom next to Classroom 201	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Classroom 201 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 201 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 201 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 201 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 201 Storage	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 201 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Restroom inside Office 201A next to Classroom 201	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Restroom inside Office 201A next to Classroom 201	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Restroom inside Office 201A next to Classroom 201	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Restroom inside Office 201A next to Classroom 201	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Restroom inside Office 201A next to Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Restroom inside Office 201A next to Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 202	yes	W1	Plaster	Beige	Cracking, Damaged Plaster	12	22.5	Positive
7390	1	2	Classroom 202	yes	W2	Plaster	Beige	Cracking	10	23.9	Positive
7390	1	2	Classroom 202	yes	W3	Plaster	Beige	Cracking	4	22.1	Positive
7390	1	2	Classroom 202	yes	W4	Plaster	Beige	Cracking	3	25.4	Positive
7390	1	2	Classroom 202	yes	Ceiling	Plaster	Beige	Flaking	2	26.2	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	2	Classroom 202	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 202 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 202 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 202 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 202 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 202 Storage	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 202 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 203	yes	W1	Plaster	Beige	Cracking	1	25.2	Positive
7390	1	2	Classroom 203	yes	W2	Plaster	Beige	Cracking	1	30.1	Positive
7390	1	2	Classroom 203	yes	W3	Plaster	Beige	Cracking	4	21.9	Positive
7390	1	2	Classroom 203	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 203	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Classroom 203	yes	Ceiling	Plaster	Beige	Efflorescence	1	20.6	Positive
7390	1	2	Classroom 203	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 203 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 203 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 203 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 203 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 203 Storage	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 203 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 204	yes	W1	Plaster	Beige	Cracking	10	28.6	Positive
7390	1	2	Classroom 204	yes	W2	Plaster	Beige	Cracking, Damaged Plaster	5	21.6	Positive
7390	1	2	Classroom 204	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 204	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 204	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 204	yes	W4	Plaster	Beige	Cracking	3	8.8	Positive
7390	1	2	Classroom 204	yes	Ceiling	Plaster	Beige	Flaking	1	27.7	Positive
7390	1	2	Classroom 204	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 204 Coat Closet	yes	W1	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Coat Closet	yes	W2	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Coat Closet	yes	W3	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Coat Closet	yes	W4	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Coat Closet	yes	Ceiling	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Coat Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	2	Classroom 204 Front Closet	yes	W1	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Front Closet	yes	W2	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Front Closet	yes	W3	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Front Closet	yes	W4	Plaster	Biege	None	0	N/A	N/A
7390	1	2	Classroom 204 Front Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	2	Classroom 204 Front Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Office 204A	yes	W1	Plaster	Beige	Cracking	3	21.5	Positive
7390	1	2	Office 204A	yes	W2	Plaster	Beige	Cracking	2	26	Positive
7390	1	2	Office 204A	yes	W3	Plaster	Beige	Cracking	2	1.1	Positive
7390	1	2	Office 204A	yes	W4	Plaster	Beige	Cracking	2	20	Positive
7390	1	2	Office 204A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Office 204A	yes	Floor	Wood/Tile	N/A	N/A	N/A	N/A	N/A
7390	1	2	Restroom in Office 204A	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Restroom in Office 204A	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Restroom in Office 204A	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Restroom in Office 204A	yes	W3	Plaster	Beige	Cracking	2	14.6	Positive
7390	1	2	Restroom in Office 204A	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Restroom in Office 204A	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	2	Restroom in Office 204A	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Storage 204B	yes	W1	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204B	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204B	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Storage 204B	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204B	yes	Ceiling	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Storage 204B	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Storage 204C	yes	W1	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204C	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204C	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Storage 204C	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204C	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A
7390	1	2	Storage 204C	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Storage 204E	yes	W1	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204E	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204E	yes	W3	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	2	Storage 204E	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
7390	1	2	Storage 204E	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A
7390	1	2	Storage 204E	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Classroom 205	yes	W1	Plaster	Beige	Cracking, Chipping, Damaged Plaster	12	32.4	Positive
7390	1	2	Classroom 205	yes	W2	Plaster	Beige	Cracking	3	25.7	Positive
7390	1	2	Classroom 205	yes	W3	Plaster	Beige	Cracking	2	31.9	Positive
7390	1	2	Classroom 205	yes	W4	Plaster	Beige	Cracking	4	29.5	Positive
7390	1	2	Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 205	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 205 Storage	yes	W1	Plaster	Beige	Partially Inaccessible/Cracking	2	7	Positive
7390	1	2	Classroom 205 Storage	yes	W2	Plaster	Beige	Partially Inaccessible	N/A	N/A	N/A
7390	1	2	Classroom 205 Storage	yes	W3	Plaster	Beige	Partially Inaccessible/Cracking	3	9.3	Positive
7390	1	2	Classroom 205 Storage	yes	W4	Plaster	Beige	Partially Inaccessible/Efflorescence	3	2.1	Positive
7390	1	2	Classroom 205 Storage	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 205 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 206	yes	W1	Plaster	Beige	Flaking, Damaged Plaster	5	30.5	Positive
7390	1	2	Classroom 206	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 206	yes	W3	Plaster	Beige	Flaking	3	38.5	Positive
7390	1	2	Classroom 206	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 206	yes	Ceiling	Plaster	Beige	Flaking	20	33.8	Positive
7390	1	2	Classroom 206	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 206 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 206 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 206 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 206 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 206 Storage	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	2	Classroom 206 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 207	yes	W1	Plaster	Beige	Cracking	4	31.2	Positive
7390	1	2	Classroom 207	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 207	yes	W2	Plaster	Beige	Spalling, Cracking	15	1.1	Positive
7390	1	2	Classroom 207	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 207	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	2	Classroom 207	yes	W3	Plaster	Beige	Cracking	2	20.7	Positive
7390	1	2	Classroom 207	yes	W4	Plaster/Wood	Beige	Cracking	2	23.4	Positive
7390	1	2	Classroom 207	yes	Ceiling	Plaster	Beige	Efflorescence, Flaking	16	18.2	Positive
7390	1	2	Classroom 207	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Boy's Restroom next to Room 207	yes	W1	Plaster/Ceramic	Blue	None	0	N/A	N/A
7390	1	2	Boy's Restroom next to Room 207	yes	W2	Plaster/Ceramic	Blue	None	0	N/A	N/A
7390	1	2	Boy's Restroom next to Room 207	yes	W3	Plaster/Ceramic	Blue	Flaking	6	1.8	Positive
7390	1	2	Boy's Restroom next to Room 207	yes	W4	Plaster/Ceramic	Blue	Flaking	20	16.9	Positive
7390	1	2	Boy's Restroom next to Room 207	yes	Ceiling	Plaster	Blue	None	0	N/A	N/A
7390	1	2	Boy's Restroom next to Room 207	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Classroom 207 Storage	yes	W1	Plaster	Beige	Damaged Plaster	2	28.4	Positive
7390	1	2	Classroom 207 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 207 Storage	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Classroom 207 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Classroom 207 Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	2	Classroom 207 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 208	yes	W1	Plaster	Blue	Cracking, Chipping	8	30.8	Positive
7390	1	2	Classroom 208	yes	W2	Plaster	Blue	Chipping	2	11.9	Positive
7390	1	2	Classroom 208	yes	W3	Plaster	Blue	Cracking	2	1.2	Positive
7390	1	2	Classroom 208	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 208	yes	W4	Plaster	Blue	Cracking	4	11.8	Positive
7390	1	2	Classroom 208	yes	Ceiling	Plaster	Beige	Flaking	7	26	Positive
7390	1	2	Classroom 208	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Classroom 208 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A
7390	1	2	Classroom 208 Storage	yes	W2	Plaster	Blue	Cracking	4	27.1	Positive
7390	1	2	Classroom 208 Storage	yes	W3	Plaster	Blue	Spalling, Cracking	8	30.4	Positive
7390	1	2	Classroom 208 Storage	yes	W4	Plaster	Blue	Damaged Plaster	4	23.2	Positive
7390	1	2	Classroom 208 Storage	yes	Ceiling	Plaster	Blue	None	0	N/A	N/A
7390	1	2	Classroom 208 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Left side Book Storage Room in the Main Hallway	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Left side Book Storage Room in the Main Hallway	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Left side Book Storage Room in the Main Hallway	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Left side Book Storage Room in the Main Hallway	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Left side Book Storage Room in the Main Hallway	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	2	Left side Book Storage Room in the Main Hallway	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Right side Book Storage Room in the Main Hallway	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Right side Book Storage Room in the Main Hallway	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Right side Book Storage Room in the Main Hallway	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Right side Book Storage Room in the Main Hallway	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	2	Right side Book Storage Room in the Main Hallway	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Right side Book Storage Room in the Main Hallway	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Walkway to Office 212	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Walkway to Office 212	yes	W2	Plaster	Beige	Cracking, Flaking, Damaged Plaster	25	25.3	Positive
7390	1	2	Walkway to Office 212	yes	W3	Plaster	Beige	Cracking	3	26.2	Positive
7390	1	2	Walkway to Office 212	yes	W4	Plaster	Beige	Cracking, Flaking, Damaged Plaster	45	24.7	Positive
7390	1	2	Walkway to Office 212	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Walkway to Office 212	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Office 212	yes	W1	Plaster	Beige	Cracking	3	26.2	Positive
7390	1	2	Office 212	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	2	Office 212	yes	W3	Plaster	Beige	Cracking	1	8.3	Positive
7390	1	2	Office 212	yes	W4	Plaster	Beige	Cracking	2	12.4	Positive
7390	1	2	Office 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Office 212	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	2	Main Hallway at Classrooms 202 to 207	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Main Hallway at Classrooms 202 to 207	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Main Hallway at Classrooms 202 to 207	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Main Hallway at Classrooms 202 to 207	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Main Hallway at Classrooms 202 to 207	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Main Hallway at Classrooms 202 to 207	yes	Ceiling	Plaster	White	Flaking	6	23.5	Positive
7390	1	2	Main Hallway at Classrooms 202 to 207	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 208	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 208	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 208	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 208	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 208	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Hallway in front of Classroom 208	yes	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	2	Hallway in front of Classroom 201	yes	W1	Plaster	Blue/White	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 201	yes	W2	Plaster	Blue/White	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 201	yes	W3	Plaster	Blue/White	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 201	yes	W4	Plaster	Blue/White	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 201	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Hallway in front of Classroom 201	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	2	Hallway in front of Classroom 201	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 201	yes	W1	Plaster	Blue	Cracking	1	1.3	Positive
7390	1	2	Stairwell across from Classroom 201	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 201	yes	W3	Plaster	White	Cracking, contact	6	1.2	Positive
7390	1	2	Stairwell across from Classroom 201	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 201	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Stairwell across from Classroom 201	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 201	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 208	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 208	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 208	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 208	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 208	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	2	Stairwell across from Classroom 208	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	2	Stairwell across from Classroom 208	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	2	Fire Tower near Classroom 208 at Element #2	yes	W1	Brick	White	Cracking, Efflorescence	25	11.7	Positive
7390	1	2	Fire Tower near Classroom 208 at Element #2	yes	W2	Brick	White	Cracking	10	3.6	Positive
7390	1	2	Fire Tower near Classroom 208 at Element #2	yes	W3	Brick	White	Cracking, Efflorescence	80	12.4	Positive
7390	1	2	Fire Tower near Classroom 208 at Element #2	yes	W4	Brick	White	Cracking, Efflorescence	50	6.4	Positive
7390	1	2	Fire Tower near Classroom 208 at Element #2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	2	Fire Tower near Classroom 208 at Element #2	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	3	Classroom 301	yes	W1	Plaster	Beige	Cracking	2	29.1	Positive
7390	1	3	Classroom 301	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 301	yes	W3	Plaster	Beige	Flaking	8	21.4	Positive
7390	1	3	Classroom 301	yes	W3	NA	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 301	yes	W3	NA	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 301	yes	W4	Plaster	Beige	Cracking	7	29.6	Positive
7390	1	3	Classroom 301	yes	Ceiling	Plaster	Beige	Flaking	4	22.9	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	3	Classroom 301	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	3	Office 301A	yes	W1	Cinderblock	Purple	None	0	N/A	N/A
7390	1	3	Office 301A	yes	W2	Plaster	Purple	Cracking	6	15.5	Positive
7390	1	3	Office 301A	yes	W3	Plaster	Purple	Cracking	4	16.4	Positive
7390	1	3	Office 301A	yes	W4	Plaster	Purple	Cracking	10	28.6	Positive
7390	1	3	Office 301A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Office 301A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Girl's Restroom next to Classroom 301	yes	W1	Plaster	Orange	None	0	N/A	N/A
7390	1	3	Girl's Restroom next to Classroom 301	yes	W2	Plaster	Orange	Cracking	2	20.6	Positive
7390	1	3	Girl's Restroom next to Classroom 301	yes	W3	Plaster	Orange	Cracking, Spalling	4	21.5	Positive
7390	1	3	Girl's Restroom next to Classroom 301	yes	W4	Plaster	Orange	None	0	N/A	N/A
7390	1	3	Girl's Restroom next to Classroom 301	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	3	Girl's Restroom next to Classroom 301	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	1	3	Storage 301D	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Storage 301D	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Storage 301D	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Storage 301D	yes	W4	Plaster	Beige	Cracking	2	21.3	Positive
7390	1	3	Storage 301D	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Storage 301D	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 301 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 301 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 301 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 301 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 301 Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 301 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 302	yes	W1	Plaster	Beige	Flaking, Crack in plaster	4	24.7	Positive
7390	1	3	Classroom 302	yes	W2	Sheetrock	Beige	Flaking	5	0	Negative
7390	1	3	Classroom 302	yes	W3	Plaster	Beige	Friction, Crack in Plaster	6	0	Negative
7390	1	3	Classroom 302	yes	W4	Plaster	Beige	Cracking	3	4.8	Positive
7390	1	3	Classroom 302	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 302	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 302 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 302 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 302 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	3	Classroom 302 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 302 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 302 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 303	yes	W1	Plaster	Beige	Cracking, Chipping	4	25.4	Positive
7390	1	3	Classroom 303	yes	W2	Plaster	Beige	Cracking, Chipping	5	17.5	Positive
7390	1	3	Classroom 303	yes	W3	Plaster	Beige	Cracking, Chipping	10	22.3	Positive
7390	1	3	Classroom 303	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 303	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 303	yes	W4	Sheetrock	Beige	Flaking	5	0	Negative
7390	1	3	Classroom 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 303	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 303 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 303 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 303 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 303 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 303 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 303 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	3	Library	yes	W1	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Library	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
7390	1	3	Library	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Library	yes	W4	Plaster	Beige	Chipping	1	0	Negative
7390	1	3	Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Library	yes	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
7390	1	3	Library Office	yes	W1	Sheetrock	Beige	None	0	N/A	N/A
7390	1	3	Library Office	yes	W2	Sheetrock	Beige	None	0	N/A	N/A
7390	1	3	Library Office	yes	W3	Sheetrock	Beige	None	0	N/A	N/A
7390	1	3	Library Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Library Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Library Office	yes	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 307	yes	W1	Plaster	Beige	Cracking	6	16.7	Positive
7390	1	3	Classroom 307	yes	W2	Plaster	Beige	Cracking, Efflorescence	7	4.7	Positive
7390	1	3	Classroom 307	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 307	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 307	yes	W3	Plaster	Beige	Chipping	2	19.2	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	3	Classroom 307	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 307	yes	W4	Plaster/Sheetrock	Beige	None	0	N/A	N/A
7390	1	3	Classroom 307	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 307	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	3	Boy's Restroom next to Classroom 307	yes	W1	Plaster/Ceramic	Orange	None	0	N/A	N/A
7390	1	3	Boy's Restroom next to Classroom 307	yes	W2	Plaster/Ceramic	Orange	None	0	N/A	N/A
7390	1	3	Boy's Restroom next to Classroom 307	yes	W3	Plaster/Ceramic	Orange	None	0	N/A	N/A
7390	1	3	Boy's Restroom next to Classroom 307	yes	W4	Plaster/Ceramic	Orange	None	0	N/A	N/A
7390	1	3	Boy's Restroom next to Classroom 307	yes	Ceiling	Plaster	White	Efflorescence, Spalling, Damaged Plaster	20	0.9	Positive
7390	1	3	Boy's Restroom next to Classroom 307	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	3	Classroom 307 Storage	yes	W1	Plaster	Beige	Efflorescence	2	31.5	Positive
7390	1	3	Classroom 307 Storage	yes	W2	Plaster	Beige	Spalling, Cracking	12	34.8	Positive
7390	1	3	Classroom 307 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 307 Storage	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 307 Storage	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 307 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
7390	1	3	Classroom 307 Storage	yes	Ceiling	Plaster	Beige	Cracking, Damaged Plaster	4	35.9	Positive
7390	1	3	Classroom 307 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 308	yes	W1	Plaster	Beige	Cracking, Chipping	7	31.5	Positive
7390	1	3	Classroom 308	yes	W2	Plaster	Beige	Cracking	5	25.5	Positive
7390	1	3	Classroom 308	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 308	yes	W3	Plaster	Beige	Cracking, Chipping	10	3.8	Positive
7390	1	3	Classroom 308	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 308	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 308	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 308	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Classroom 308	yes	W4	Plaster	Beige	Cracking	2	1.8	Positive
7390	1	3	Classroom 308	yes	Ceiling	Plaster	Beige	Flaking, Efflorescence, Damaged plaster	10	24	Positive
7390	1	3	Classroom 308	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Main Hallway at Classrooms 302 to 307	yes	W1	Plaster	White	Flaking	1	28.2	Positive
7390	1	3	Main Hallway at Classrooms 302 to 307	yes	W1	Plaster	Tan	Flaking	6	20.5	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	3	Main Hallway at Classrooms 302 to 307	yes	W2	Plaster	White/Tan	None	0	N/A	N/A
7390	1	3	Main Hallway at Classrooms 302 to 307	yes	W3	Plaster	Tan	Friction	2	24.1	Positive
7390	1	3	Main Hallway at Classrooms 302 to 307	yes	W4	Plaster	Blue	Damaged plaster	3	21.7	Positive
7390	1	3	Main Hallway at Classrooms 302 to 307	yes	W4	Plaster	Tan	Flaking	1	23	Positive
7390	1	3	Main Hallway at Classrooms 302 to 307	yes	Ceiling	Plaster	Tan	Cracking, Flaking, Efflorescence	20	28.6	Positive
7390	1	3	Main Hallway at Classrooms 302 to 307	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	3	Hallway in front of Classroom 308	yes	W1	No wall	N/A	N/A	N/A	N/A	N/A
7390	1	3	Hallway in front of Classroom 308	yes	W2	Plaster	White	Cracking	6	28.6	Positive
7390	1	3	Hallway in front of Classroom 308	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	1	3	Hallway in front of Classroom 308	yes	W4	Plaster	White	Cracking	2	34.3	Positive
7390	1	3	Hallway in front of Classroom 308	yes	Ceiling	Plaster	Beige	Cracking, Flaking, Efflorescence	4	21.8	Positive
7390	1	3	Hallway in front of Classroom 308	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	3	Hallway in front of Classroom 301	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Hallway in front of Classroom 301	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Hallway in front of Classroom 301	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Hallway in front of Classroom 301	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Hallway in front of Classroom 301	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Hallway in front of Classroom 301	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 301	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 301	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 301	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 301	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 301	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Stairwell across from Classroom 301	yes	Ceiling	Plaster	White	Efflorescence, Spalling, Flaking	25	1.1	Positive
7390	1	3	Stairwell across from Classroom 301	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 308	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 308	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 308	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 308	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 308	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	3	Stairwell across from Classroom 308	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	3	Stairwell across from Classroom 308	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	3	Fire Tower near Classroom 308 at Element #2	yes	W1	Brick	White	Cracking	15	3.7	Positive
7390	1	3	Fire Tower near Classroom 308 at Element #2	yes	W2	Brick	White	Cracking	15	3.6	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	3	Fire Tower near Classroom 308 at Element #2	yes	W3	Brick	White	Cracking, Efflorescence, Flaking	25	2.8	Positive
7390	1	3	Fire Tower near Classroom 308 at Element #2	yes	W4	Brick	White	Cracking, Efflorescence	80	11	Positive
7390	1	3	Fire Tower near Classroom 308 at Element #2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	3	Fire Tower near Classroom 308 at Element #2	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	B	Cafeteria	yes	W1	Brick	Beige	Efflorescence, Flaking	10	2.7	Positive
7390	1	B	Cafeteria	yes	W2	Brick	Green	Craacking	3	1.8	Positive
7390	1	B	Cafeteria	yes	W3	Brick	Beige	Efflorescence	4	3.4	Positive
7390	1	B	Cafeteria	yes	W4	Brick	Beige	Efflorescence	4	2.5	Positive
7390	1	B	Cafeteria	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	B	Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Kitchen	yes	W1	Brick	Beige	Cracking	5	4	Positive
7390	1	B	Kitchen	yes	W1	Brick	Green	Cracking	4	1.4	Positive
7390	1	B	Kitchen	yes	W2	Brick	Beige	Cracking	2	2.3	Positive
7390	1	B	Kitchen	yes	W3	Brick	Beige	None	0	N/A	N/A
7390	1	B	Kitchen	yes	W4	Brick	Beige	Partially Inaccessible	0	N/A	N/A
7390	1	B	Kitchen	yes	Ceiling	Plaster	White	Cracking	100	2.7	Positive
7390	1	B	Kitchen	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom 003	yes	W1	Brick	Beige	Chipping	1	2.3	Positive
7390	1	B	Classroom 003	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom 003	yes	W2	Brick	Beige	None	0	N/A	N/A
7390	1	B	Classroom 003	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	1	B	Classroom 003	yes	W4	Brick	Beige	None	0	N/A	N/A
7390	1	B	Classroom 003	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom 003	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom 003A in Classroom 003	yes	W1	Cinderblock	Green	None	0	N/A	N/A
7390	1	B	Classroom 003A in Classroom 003	yes	W2	Brick	Green	None	0	N/A	N/A
7390	1	B	Classroom 003A in Classroom 003	yes	W3	Brick	Green	Cracking, Flaking	6	10.6	Positive
7390	1	B	Classroom 003A in Classroom 003	yes	W4	Cinderblock	Green	None	0	N/A	N/A
7390	1	B	Classroom 003A in Classroom 003	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom 003A in Classroom 003	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom 003B in Classroom 003	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	1	B	Classroom 003B in Classroom 003	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	1	B	Classroom 003B in Classroom 003	yes	W3	Brick	Beige	Cracking, Flaking	10	2.8	Positive
7390	1	B	Classroom 003B in Classroom 003	yes	W4	Brick	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	B	Classroom 003B in Classroom 003	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom 003B in Classroom 003	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Music Storage	yes	W1	Brick	Beige	None	0	N/A	N/A
7390	1	B	Music Storage	yes	W2	Brick	Beige	None	0	N/A	N/A
7390	1	B	Music Storage	yes	W3	Brick	Beige	None	0	N/A	N/A
7390	1	B	Music Storage	yes	W4	Brick	Beige	None	0	N/A	N/A
7390	1	B	Music Storage	yes	Ceiling	Plaster	Beige	Flaking	5	7.7	Positive
7390	1	B	Music Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	B	Storage across from Student Restrooms	yes	W1	Brick	White	None	0	N/A	N/A
7390	1	B	Storage across from Student Restrooms	yes	W2	Brick	White	None	0	N/A	N/A
7390	1	B	Storage across from Student Restrooms	yes	W3	Brick	White	None	0	N/A	N/A
7390	1	B	Storage across from Student Restrooms	yes	W4	Brick	White	None	0	N/A	N/A
7390	1	B	Storage across from Student Restrooms	yes	Ceiling	Concrete	White	Flaking	4	6.9	Positive
7390	1	B	Storage across from Student Restrooms	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Storage across from Student Restrooms	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	B	Boy's Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	1	B	Boy's Restroom	yes	W2	Brick	Beige	Flaking	12	0	Negative
7390	1	B	Boy's Restroom	yes	W3	Cinderblock	Beige	Flaking, Efflorescence	6	4.1	Positive
7390	1	B	Boy's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	1	B	Boy's Restroom	yes	Ceiling	Sheetrock	Beige	Flaking	6	0	Negative
7390	1	B	Boy's Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	1	B	Girl's Restroom next to Classroom B1	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	1	B	Girl's Restroom next to Classroom B1	yes	W2	Brick	Beige	Cracking	4	5.4	Positive
7390	1	B	Girl's Restroom next to Classroom B1	yes	W3	Brick	Beige	Cracking, Flaking	30	4.7	Positive
7390	1	B	Girl's Restroom next to Classroom B1	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	1	B	Girl's Restroom next to Classroom B1	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A
7390	1	B	Girl's Restroom next to Classroom B1	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom B1	yes	W1	Brick	Green	None	0	N/A	N/A
7390	1	B	Classroom B1	yes	W2	Brick	Green	None	0	N/A	N/A
7390	1	B	Classroom B1	yes	W3	Brick	Orange	None	0	N/A	N/A
7390	1	B	Classroom B1	yes	W4	Brick	Blue	None	0	N/A	N/A
7390	1	B	Classroom B1	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom B1	yes	Ceiling	Concrete	Tan	Flaking	6	1.8	Positive
7390	1	B	Classroom B1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	B	Classroom B1 Office/Storage	yes	W1	Brick	Beige	None	0	N/A	N/A
7390	1	B	Classroom B1 Office/Storage	yes	W2	Brick	Beige	None	0	N/A	N/A
7390	1	B	Classroom B1 Office/Storage	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Classroom B1 Office/Storage	yes	W3	Brick	Beige	Cracking	4	0.21	Negative
7390	1	B	Classroom B1 Office/Storage	yes	W4	Brick	Beige	None	0	N/A	N/A
7390	1	B	Classroom B1 Office/Storage	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	B	Classroom B1 Office/Storage	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	B	Fan Room	no	W1	Brick	White	Flaking, Cracking	70	5.9	Positive
7390	1	B	Fan Room	no	W1	Brick	Grey	Flaking, Cracking	40	12.2	Positive
7390	1	B	Fan Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W2	Brick	White	Flaking, Cracking	50	1.8	Positive
7390	1	B	Fan Room	no	W2	Brick	Grey	Flaking, Cracking	20	3.4	Positive
7390	1	B	Fan Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W3	Brick	White	Flaking, Cracking	15	17.1	Positive
7390	1	B	Fan Room	no	W3	Brick	Grey	Flaking, Cracking	15	10	Positive
7390	1	B	Fan Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W4	Brick	White	Flaking, Cracking	80	12.6	Positive
7390	1	B	Fan Room	no	W4	Brick	Grey	Flaking, Cracking	60	8.8	Positive
7390	1	B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	Ceiling	Concrete	White	Flaking	200	10.4	Positive
7390	1	B	Fan Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	Floor	Concrete	Grey	Chipping	40	1.1	Positive
7390	1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room Storage	no	W1	Brick	White	Flaking, Cracking	50	0	Negative
7390	1	B	Fan Room Storage	no	W2	Metal	White	Flaking	10	0.14	Negative
7390	1	B	Fan Room Storage	no	W3	Brick	White	Flaking, Cracking	40	0.03	Negative
7390	1	B	Fan Room Storage	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room Storage	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room Storage	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Fan Room Storage	no	W4	Brick	White	Flaking, Cracking	50	0.05	Negative
7390	1	B	Fan Room Storage	no	Ceiling	Concrete	Grey	Flaking	40	0.1	Negative
7390	1	B	Fan Room Storage	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W1	Brick	White	Flaking, Cracking	60	0.02	Negative
7390	1	B	Boiler Room	no	W1	Concrete	Grey	Flaking, Cracking	15	21.7	Positive
7390	1	B	Boiler Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W2	Brick	White	Flaking, Cracking	80	0.05	Negative
7390	1	B	Boiler Room	no	W2	Concrete	Grey	Flaking, Cracking	35	18.6	Positive
7390	1	B	Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W3	Brick	White	Flaking, Cracking	100	0.06	Negative
7390	1	B	Boiler Room	no	W3	Concrete	Grey	Flaking, Cracking	70	21.8	Positive
7390	1	B	Boiler Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W4	Brick	White	Flaking, Cracking	120	1.1	Positive
7390	1	B	Boiler Room	no	W4	Concrete	Grey	Flaking, Cracking	80	21	Positive
7390	1	B	Boiler Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	Ceiling	Concrete	White	Flaking	500	0.01	Negative
7390	1	B	Boiler Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	B	Boiler Room	no	Floor	Concrete	Grey	Chipping	20	0.18	Negative
7390	1	B	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Water Main Room	no	W1	Brick	White	Flaking	10	0.03	Negative
7390	1	B	Water Main Room	no	W1	Concrete	Grey	Flaking	5	3.2	Positive
7390	1	B	Water Main Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Water Main Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Water Main Room	no	W2	Brick	White	Flaking	3	10.1	Positive
7390	1	B	Water Main Room	no	W2	Concrete	Grey	Flaking	10	46.2	Positive
7390	1	B	Water Main Room	no	W3	Brick	White	Flaking	10	0.05	Negative
7390	1	B	Water Main Room	no	W3	Concrete	Grey	Flaking	10	18.6	Positive
7390	1	B	Water Main Room	no	W4	Brick	White	Flaking	10	0.04	Negative
7390	1	B	Water Main Room	no	W4	Concrete	Grey	Flaking	12	8.1	Positive
7390	1	B	Water Main Room	no	Ceiling	Concrete	Grey	None	0	N/A	N/A
7390	1	B	Water Main Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room Storage	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room Storage	no	W2	Brick	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room Storage	no	W3	Brick	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room Storage	no	W4	Brick	N/A	N/A	N/A	N/A	N/A
7390	1	B	Boiler Room Storage	no	Ceiling	Concrete	Grey	None	0	N/A	N/A
7390	1	B	Boiler Room Storage	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
7390	1	B	Music Room	Yes	W1	Sheetrock	White	None	0	N/A	N/A
7390	1	B	Music Room	Yes	W2	Sheetrock	White	None	0	N/A	N/A
7390	1	B	Music Room	Yes	W3	Brick	White	Friction	4	4.9	Positive
7390	1	B	Music Room	Yes	W4	Sheetrock	White	None	0	N/A	N/A
7390	1	B	Music Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Music Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Storage room outside Boiler Room	no	W1	Brick	White	Cracking	15	2.6	Positive
7390	1	B	Storage room outside Boiler Room	no	W2	Brick	White	Cracking	12	5.3	Positive
7390	1	B	Storage room outside Boiler Room	no	W3	Brick	White	Cracking	8	3.4	Positive
7390	1	B	Storage room outside Boiler Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Storage room outside Boiler Room	no	W4	Brick	White	Cracking	8	2	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	B	Storage room outside Boiler Room	no	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	B	Storage room outside Boiler Room	no	Floor	Wood	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Music Room 14	yes	W1	Brick	White	None	0	N/A	N/A
7390	1	B	Hallway at Music Room 14	yes	W2	Brick	White	Flaking, Cracking	40	6.8	Positive
7390	1	B	Hallway at Music Room 14	yes	W3	Brick	White	Cracking	12	3.6	Positive
7390	1	B	Hallway at Music Room 14	yes	W4	Brick	White	Flaking, Cracking	40	7.1	Positive
7390	1	B	Hallway at Music Room 14	yes	Ceiling	Plaster	White	Flaking, Damaged Plaster	20	8.3	Positive
7390	1	B	Hallway at Music Room 14	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Music Room 14	yes	Floor	Concrete	Grey	Chipping	8	0.19	Negative
7390	1	B	Hallway at Music Room 14	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Music Room 14	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Music Room 14	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Music Room 14	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Student Restrooms	yes	W1	Brick	Beige	None	0	N/A	N/A
7390	1	B	Hallway at Student Restrooms	yes	W2	Brick	Beige	Cracking	10	6	Positive
7390	1	B	Hallway at Student Restrooms	yes	W3	Brick	Beige	None	0	N/A	N/A
7390	1	B	Hallway at Student Restrooms	yes	W4	Brick	Beige	Cracking	15	4.4	Positive
7390	1	B	Hallway at Student Restrooms	yes	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	B	Hallway at Student Restrooms	yes	Floor	Concrete	Grey	Chipping	10	0.06	Negative
7390	1	B	Hallway at Student Restrooms	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Student Restrooms	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Student Restrooms	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Student Restrooms	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Hallway at Student Restrooms	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Stairwell on Student Restrooms side	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
7390	1	B	Stairwell on Student Restrooms side	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
7390	1	B	Stairwell on Student Restrooms side	yes	W3	Plaster	White	Efflorescence	30	1.3	Positive
7390	1	B	Stairwell on Student Restrooms side	yes	W3	Plaster	Blue	Efflorescence	50	1.1	Positive
7390	1	B	Stairwell on Student Restrooms side	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	B	Stairwell on Student Restrooms side	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	B	Stairwell on Student Restrooms side	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	B	Stairwell on Student Restrooms side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Stairwell on Boiler Room side	yes	W1	Plaster	Blue	Contact	3	15	Positive
7390	1	B	Stairwell on Boiler Room side	yes	W2	Plaster	Blue	Spalling	4	5.4	Positive
7390	1	B	Stairwell on Boiler Room side	yes	W3	Plaster	White	Efflorescence, Flaking, Spalling	10	0	Negative

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	1	B	Stairwell on Boiler Room side	yes	W3	Plaster	Blue	Efflorescence, Flaking, Spalling	20	0	Negative
7390	1	B	Stairwell on Boiler Room side	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Stairwell on Boiler Room side	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
7390	1	B	Stairwell on Boiler Room side	yes	Ceiling	Plaster	White	None	0	N/A	N/A
7390	1	B	Stairwell on Boiler Room side	yes	Floor	Concrete	Grey	Chipping, Contact	3	1	Positive
7390	1	B	Stairwell on Boiler Room side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Stairwell on Boiler Room side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Stairwell on Boiler Room side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Stairwell on Boiler Room side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	1	B	Storage Room in Stairwell on Boiler room side	no	W1	Brick	White	None	0	N/A	N/A
7390	1	B	Storage Room in Stairwell on Boiler room side	no	W2	Brick	White	None	0	N/A	N/A
7390	1	B	Storage Room in Stairwell on Boiler room side	no	W3	Brick	White	Cracking	12	2.7	Positive
7390	1	B	Storage Room in Stairwell on Boiler room side	no	W4	Brick	White	Cracking	10	2.4	Positive
7390	1	B	Storage Room in Stairwell on Boiler room side	no	Ceiling	Concrete	White	Flaking	15	No Test	Positive
7390	1	B	Storage Room in Stairwell on Boiler room side	no	Floor	Concrete	Grey	None	0	N/A	N/A
7390	1	B	Storage Room under the Stairwell on Boiler room side	no	W1	Brick	White	Flaking	2	0.03	Negative
7390	1	B	Storage Room under the Stairwell on Boiler room side	no	W2	Brick	White	None	0	N/A	N/A
7390	1	B	Storage Room under the Stairwell on Boiler room side	no	W3	Concrete	White	None	0	N/A	N/A
7390	1	B	Storage Room under the Stairwell on Boiler room side	no	W4	Concrete	White	None	0	N/A	N/A
7390	1	B	Storage Room under the Stairwell on Boiler room side	no	Ceiling	Concrete	White	None	0	N/A	N/A
7390	1	B	Storage Room under the Stairwell on Boiler room side	no	Floor	Concrete	Grey	None	0	N/A	N/A
7390	2	1	Classroom 109	yes	W1	Cinderblock	Beige	Friction	1	0	Negative
7390	2	1	Classroom 109	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 109	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 109 Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109 Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109 Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109 Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 109 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	1	Classroom 109 Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109 Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109 Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109 Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 109 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	1	Classroom 109 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 110	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 110	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 110	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 110	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 110	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 110 Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 110 Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 110 Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 110 Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 110 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 110 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 111	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 111	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 111 Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111 Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111 Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111 Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 111 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 111 Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111 Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111 Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 111 Restroom	yes	W4	Cinderblock	Beige	Flaking	5	0	Negative

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	1	Classroom 111 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	1	Classroom 111 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 112	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 112	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 112 Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112 Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112 Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112 Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 112 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 112 Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112 Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112 Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112 Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 112 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	1	Classroom 112 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 113	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 113	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 113	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 113	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 113	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 113	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 113 Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 113 Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 113 Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 113 Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 113 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 113 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 114	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 114	yes	W2	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	1	Classroom 114	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 114	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 114	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 114	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 114 Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 114 Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 114 Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 114 Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Classroom 114 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Classroom 114 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Element #2 Hallway	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Hallway	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Hallway	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Hallway	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Element #2 Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Element #2 Foyer	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Foyer	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Foyer	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Foyer	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Foyer	yes	Ceiling	Sheetrock	White	Flaking	4	0	Negative
7390	2	1	Element #2 Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	1	Element #2 Stairwell	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Stairwell	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Stairwell	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Stairwell	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	1	Element #2 Stairwell	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	1	Element #2 Stairwell	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	2	2	Fan Room in the Hallway next to Girl's Restroom	no	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Fan Room in the Hallway next to Girl's Restroom	no	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Fan Room in the Hallway next to Girl's Restroom	no	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Fan Room in the Hallway next to Girl's Restroom	no	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Fan Room in the Hallway next to Girl's Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A
7390	2	2	Fan Room in the Hallway next to Girl's Restroom	no	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	2	Staff Restroom next to Fan Room in Hallway	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Staff Restroom next to Fan Room in Hallway	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Staff Restroom next to Fan Room in Hallway	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Staff Restroom next to Fan Room in Hallway	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Staff Restroom next to Fan Room in Hallway	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	2	Staff Restroom next to Fan Room in Hallway	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 212	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 212	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 212	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 212	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 213	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 213	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 213	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 213	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 213	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 213 Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 213 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 213 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 213 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 213 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 213 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 214	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 214	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 214	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 214	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 214	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Girl's Restroom in the Hallway	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Girl's Restroom in the Hallway	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Girl's Restroom in the Hallway	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Girl's Restroom in the Hallway	yes	W4	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	2	Girl's Restroom in the Hallway	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	2	Girl's Restroom in the Hallway	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 215	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 215	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 215	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 215	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 215	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 215	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 216	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 216	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 216	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 216	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 216	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 216	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 217	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 217	yes	W1	N/A	Beige	N/A	N/A	N/A	N/A
7390	2	2	Classroom 217	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 217	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 217	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 217	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 217	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 217 Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 217 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 217 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 217 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 217 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 217 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 218	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 218	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 218	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 218	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 218	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 218	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 218 Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	2	Classroom 218 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 218 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 218 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Classroom 218 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Classroom 218 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Element#2 Hallway	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Element#2 Hallway	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Element#2 Hallway	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Element#2 Hallway	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Element#2 Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Element#2 Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	2	Element #2 Stairwell	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Element #2 Stairwell	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Element #2 Stairwell	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Element #2 Stairwell	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	2	Element #2 Stairwell	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	2	Element #2 Stairwell	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	2	3	Fan Room in Hallway next to Girl's Restroom	no	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Fan Room in Hallway next to Girl's Restroom	no	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Fan Room in Hallway next to Girl's Restroom	no	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Fan Room in Hallway next to Girl's Restroom	no	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Fan Room in Hallway next to Girl's Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A
7390	2	3	Fan Room in Hallway next to Girl's Restroom	no	Floor	Concrete	Grey	None	0	N/A	N/A
7390	2	3	Staff Restroom next to Fan Room in Hallway	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Staff Restroom next to Fan Room in Hallway	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Staff Restroom next to Fan Room in Hallway	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Staff Restroom next to Fan Room in Hallway	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Staff Restroom next to Fan Room in Hallway	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	3	Staff Restroom next to Fan Room in Hallway	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 312	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 312	yes	W1	N/A	Beige	N/A	N/A	N/A	N/A
7390	2	3	Classroom 312	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 312	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 312	yes	W4	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	3	Classroom 312	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 312	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 312 Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 312 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 312 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 312 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 312 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 312 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 313	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 313	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 313	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 313	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 313	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 313	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 313 Closet	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 313 Closet	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 313 Closet	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 313 Closet	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 313 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 313 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 314	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 314	yes	W1	N/A	Beige	N/A	N/A	N/A	N/A
7390	2	3	Classroom 314	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 314	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 314	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 314	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 314	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Girl's Restroom in the Hallway	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Girl's Restroom in the Hallway	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Girl's Restroom in the Hallway	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Girl's Restroom in the Hallway	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Girl's Restroom in the Hallway	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	3	Girl's Restroom in the Hallway	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 315	yes	W1	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	3	Classroom 315	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 315	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 315 Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 315 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 315 Closet inside storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Closet inside Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Closet inside Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Closet inside storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Closet inside Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 315 Closet inside Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 315 Storage #2	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Storage #2	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Storage #2	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Storage #2	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 315 Storage #2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 315 Storage #2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 316	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 316	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 316	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 316	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Classroom 316	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Classroom 316	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Element #2 Hallway	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Element #2 Hallway	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Element #2 Hallway	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Element #2 Hallway	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Element #2 Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	2	3	Element #2 Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	2	3	Element #2 Stairwell	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Element #2 Stairwell	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Element #2 Stairwell	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Element #2 Stairwell	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	2	3	Element #2 Stairwell	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	2	3	Element #2 Stairwell	yes	Floor	Concrete	Grey	None	0	N/A	N/A
7390	3	1	Gym	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym	yes	W3	N/A	Beige	N/A	N/A	N/A	N/A
7390	3	1	Gym	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym	yes	Ceiling	Metal	N/A	None	0	N/A	N/A
7390	3	1	Gym	yes	Floor	Concrete	Red	None	0	N/A	N/A
7390	3	1	Gym Foyer	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym Foyer	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym Foyer	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym Foyer	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym Foyer	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Gym Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Gym Storage in front of Foyer	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym Storage in front of Foyer	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym Storage in front of Foyer	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym Storage in front of Foyer	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Gym Storage in front of Foyer	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	3	1	Gym Storage in front of Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Restroom in Gym Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Restroom in Gym Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Restroom in Gym Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Restroom in Gym Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Restroom in Gym Storage	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	3	1	Restroom in Gym Storage	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	3	1	First storage on the left in Gym	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	First storage on the left in Gym	yes	W2	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	3	1	First storage on the left in Gym	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	First Storage on the left in Gym	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	First storage on the left in Gym	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	3	1	First Storage on the left in Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	3	1	Middle Storage on the left in Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Last Storage on the left in Gym	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Last Storage on the left in Gym	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Last Storage on the left in Gym	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Last Storage on the left in Gym	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Last Storage on the left in Gym	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	3	1	Last Storage on the left in Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Couselor's Office outside Gym	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Couselor's Office outside Gym	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Couselor's Office outside Gym	yes	W3	Sheetrock	Beige	None	0	N/A	N/A
7390	3	1	Couselor's Office outside Gym	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Couselor's Office outside Gym	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Couselor's Office outside Gym	yes	Ceiling	Sheetrock	White	Flaking	3	0	Negative
7390	3	1	Couselor's Office outside Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Counselor Office Restroom	yes	W1	Cinderblock	White	None	0	N/A	N/A
7390	3	1	Counselor Office Restroom	yes	W2	Cinderblock	White	None	0	N/A	N/A
7390	3	1	Counselor Office Restroom	yes	W3	Cinderblock	White	None	0	N/A	N/A
7390	3	1	Counselor Office Restroom	yes	W4	Cinderblock	White	None	0	N/A	N/A
7390	3	1	Counselor Office Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	3	1	Counselor Office Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
7390	3	1	Nurse's Office outside Gym	yes	W1	Cinderblock/Plaster	Beige	None	0	N/A	N/A
7390	3	1	Nurse's Office outside Gym	yes	W2	Plaster	Beige	None	0	N/A	N/A
7390	3	1	Nurse's Office outside Gym	yes	W3	Plaster	Beige	Cracking	10	19.2	Positive
7390	3	1	Nurse's Office outside Gym	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Nurse's Office outside Gym	yes	Ceiling	Sheetrock	White	Flaking	2	0	Negative

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Andrew Morrison Elementary School											
			Name of Inspector: Ananth K. Vinjamuri								
			Inspection Company: Criterion Labs, Inc.								
ULCS#	E l e m e n t	F l o o r	On Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
7390	3	1	Nurse's Office outside Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
7390	3	1	Nurse's Office Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Nurse's Office Restroom	yes	W2	Plaster	Beige	Crack in Plaster	4	0	Negative
7390	3	1	Nurse's Office Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Nurse's Office Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
7390	3	1	Nurse's Office Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
7390	3	1	Nurse's Office Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
#N/A											