

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	202	Primary	Classroom 301	yes	W1	Plaster	White	Flaking	12	30.9	Positive	N/A	N/A
1	2	202	Primary	Classroom 301	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.6	Positive
1	2	202	Primary	Classroom 301	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.9	Positive
1	2	202	Primary	Classroom 301	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.3	Positive
1	2	202	Primary	Classroom 301	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.5	Positive
1	2	202	Primary	Classroom 301	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.9	Positive
1	2	202	Primary	Classroom 301	yes	W2	Plaster	White	Flaking	20	42.5	Positive	N/A	N/A
1	2	202	Primary	Classroom 301	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.1	Positive
1	2	202	Primary	Classroom 301	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	2.5	Positive
1	2	202	Primary	Classroom 301	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.3	Positive
1	2	202	Primary	Classroom 301	yes	W3	Plaster	White	Flaking	10	39.2	Positive	N/A	N/A
1	2	202	Primary	Classroom 301	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	4	Positive
1	2	202	Primary	Classroom 301	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	2.6	Positive
1	2	202	Primary	Classroom 301	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.5	Positive
1	2	202	Primary	Classroom 301	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.4	Positive
1	2	202	Primary	Classroom 301	yes	W4	Plaster	White	Flaking	18	48.5	Positive	N/A	N/A
1	2	202	Primary	Classroom 301	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	2.1	Positive
1	2	202	Primary	Classroom 301	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.6	Positive
1	2	202	Primary	Classroom 301	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.2	Positive
1	2	202	Primary	Classroom 301	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	0.4	Negative
1	2	202	Primary	Classroom 301	yes	Ceiling	Plaster	White	Cracking	8	42.8	Positive	N/A	N/A
1	2	202	Primary	Classroom 301	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	202	Primary	Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W1	Plaster	White	Flaking	6	46.9	Positive	N/A	N/A
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.8	Positive
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.1	Positive
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	7.9	Positive
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3	Positive
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.4	Positive
1	2	202A	Storage	Classroom 301 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	4.1	Positive
1	2	202A	Storage	Classroom 301 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	202A	Storage	Classroom 301 Storage Closet	yes	Floor	Wood	N/A	None	0	40.5	Positive	N/A	N/A
1	2	202A	Storage	Classroom 301 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	3.2	Positive
1	2	201	Primary	Classroom 302	yes	W1	Plaster	White	Flaking	12	51.2	Positive	N/A	N/A
1	2	201	Primary	Classroom 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.5	Positive
1	2	201	Primary	Classroom 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	4.1	Positive
1	2	201	Primary	Classroom 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.9	Positive
1	2	201	Primary	Classroom 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.4	Positive
1	2	201	Primary	Classroom 302	yes	W2	Plaster	White	Flaking	40	46.5	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
		Name of Inspector: Ryan Hutsell												
		Inspection Company: Synertech												
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	201	Primary	Classroom 302	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3	Positive
1	2	201	Primary	Classroom 302	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.1	Positive
1	2	201	Primary	Classroom 302	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	0.26	Negative
1	2	201	Primary	Classroom 302	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	2.7	Positive
1	2	201	Primary	Classroom 302	yes	W3	Plaster	White	Flaking	20	37.6	Positive	N/A	N/A
1	2	201	Primary	Classroom 302	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.9	Positive
1	2	201	Primary	Classroom 302	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	4.1	Positive
1	2	201	Primary	Classroom 302	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.2	Negative
1	2	201	Primary	Classroom 302	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	2.8	Positive
1	2	201	Primary	Classroom 302	yes	W4	Plaster	White	Cracking	5	35.8	Positive	N/A	N/A
1	2	201	Primary	Classroom 302	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.2	Positive
1	2	201	Primary	Classroom 302	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.1	Positive
1	2	201	Primary	Classroom 302	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.8	Positive
1	2	201	Primary	Classroom 302	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	201	Primary	Classroom 302	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	201	Primary	Classroom 302	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	3.4	Positive
1	2	201C	Storage	Classroom 302 Storage Closet	yes	W1	Plaster	White	Flaking	82	32.8	Positive	N/A	N/A
1	2	201C	Storage	Classroom 302 Storage Closet	yes	W2	Plaster	White	Flaking	60	41.6	Positive	N/A	N/A
1	2	201C	Storage	Classroom 302 Storage Closet	yes	W3	Plaster	White	Flaking	118	43.2	Positive	N/A	N/A
1	2	201C	Storage	Classroom 302 Storage Closet	yes	W4	Plaster	White	Flaking	30	40.8	Positive	N/A	N/A
1	2	201C	Storage	Classroom 302 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	201C	Storage	Classroom 302 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	201C	Storage	Classroom 302 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	3.1	Positive
1	2	201A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 301	yes	W1	Plaster	N/A	Flaking	7	28.6	Positive	N/A	N/A
1	2	201A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 301	yes	W2	Plaster	White	Cracking	6	34.5	Positive	N/A	N/A
1	2	201A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 301	yes	W3	Plaster	White	Chipping	2	39.2	Positive	N/A	N/A
1	2	201A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 301	yes	W4	Plaster	White	Cracking	8	42.8	Positive	N/A	N/A
1	2	201A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 301	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	201A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 301	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	W1	Plaster	White	Chipping	2	46.7	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	0.15	Negative
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	W2	Plaster	White	Flaking	150	40.3	Positive	N/A	N/A
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	W3	Plaster	White	Flaking	80	36.2	Positive	N/A	N/A
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	W4	Plaster	White	Flaking	160	49.6	Positive	N/A	N/A
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	2.5	Positive
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	2.9	Positive
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	3.1	Positive
1	2	S23	Stairs	Stairwell next to Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	4	Positive
1	2	200	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 311	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	200	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 311	yes	W2	Plaster	White	Flaking	6	28.9	Positive	N/A	N/A
1	2	200	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 311	yes	W3	Plaster	White	Flaking	12	35.4	Positive	N/A	N/A
1	2	200	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 311	yes	W4	Plaster	White	Flaking	6	41.8	Positive	N/A	N/A
1	2	200	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 311	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	200	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 311	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	2	200	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 311	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	7.1	Positive
1	2	202A	Primary	Classroom 312	yes	W1	Plaster	White	Flaking	22	41.5	Positive	N/A	N/A
1	2	202A	Primary	Classroom 312	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.5	Positive
1	2	202A	Primary	Classroom 312	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.8	Positive
1	2	202A	Primary	Classroom 312	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	1.9	Positive
1	2	202A	Primary	Classroom 312	yes	W2	Plaster	White	Flaking	20	26.8	Positive	N/A	N/A
1	2	202A	Primary	Classroom 312	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.1	Positive
1	2	202A	Primary	Classroom 312	yes	W3	Plaster	White	Flaking	35	39.6	Positive	N/A	N/A
1	2	202A	Primary	Classroom 312	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	2	202A	Primary	Classroom 312	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.6	Positive
1	2	202A	Primary	Classroom 312	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.2	Positive
1	2	202A	Primary	Classroom 312	yes	W4	Plaster	White	Flaking	15	44.8	Positive	N/A	N/A
1	2	202A	Primary	Classroom 312	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	2.9	Positive
1	2	202A	Primary	Classroom 312	yes	Ceiling	Plaster	White	Cracking	12	43.2	Positive	N/A	N/A
1	2	202A	Primary	Classroom 312	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	202A	Primary	Classroom 312	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	2.5	Positive
1	2	202C	Circulation (Hallway)	Hallway from Classroom 312 to Office	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	202C	Circulation (Hallway)	Hallway from Classroom 312 to Office	yes	W2	Plaster	White	Flaking	16	39.5	Positive	N/A	N/A
1	2	202C	Circulation (Hallway)	Hallway from Classroom 312 to Office	yes	W3	Plaster	White	Flaking	4	28.9	Positive	N/A	N/A
1	2	202C	Circulation (Hallway)	Hallway from Classroom 312 to Office	yes	W4	Plaster	White	Flaking	26	41.4	Positive	N/A	N/A
1	2	202C	Circulation (Hallway)	Hallway from Classroom 312 to Office	yes	Ceiling	Plaster	White	Cracking	4	36.2	Positive	N/A	N/A
1	2	202C	Circulation (Hallway)	Hallway from Classroom 312 to Office	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	202D	Administrative Office	Office next to Classroom 312	yes	W1	Plaster	White	Flaking	96	35.6	Positive	N/A	N/A
1	2	202D	Administrative Office	Office next to Classroom 312	yes	W2	Plaster	White	Cracking	20	38.4	Positive	N/A	N/A
1	2	202D	Administrative Office	Office next to Classroom 312	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	202D	Administrative Office	Office next to Classroom 312	yes	W4	Plaster	White	Cracking	3	40.1	Positive	N/A	N/A
1	2	202D	Administrative Office	Office next to Classroom 312	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	202D	Administrative Office	Office next to Classroom 312	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	W1	Plaster	White	Flaking	220	30.2	Positive	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	W2	Plaster	White	Flaking	10	36.4	Positive	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	2.9	Positive
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.4	Positive
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	W3	Plaster	White	Flaking	855	38.4	Positive	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	W4	Plaster	White	Flaking	26	39.4	Positive	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	2.7	Positive
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 301 - 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	4.1	Positive
1	2	203	Primary	Classroom 303	yes	W1	Plaster	White	Flaking	16	40.5	Positive	N/A	N/A
1	2	203	Primary	Classroom 303	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.8	Positive
1	2	203	Primary	Classroom 303	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.4	Positive
1	2	203	Primary	Classroom 303	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.6	Positive
1	2	203	Primary	Classroom 303	yes	W2	Plaster	White	Chipping	6	51.2	Positive	N/A	N/A
1	2	203	Primary	Classroom 303	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3	Positive
1	2	203	Primary	Classroom 303	yes	W3	Plaster	White	Flaking	8	40.1	Positive	N/A	N/A
1	2	203	Primary	Classroom 303	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.3	Positive
1	2	203	Primary	Classroom 303	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.7	Positive
1	2	203	Primary	Classroom 303	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.5	Positive
1	2	203	Primary	Classroom 303	yes	W4	Plaster	White	Flaking	25	48.7	Positive	N/A	N/A
1	2	203	Primary	Classroom 303	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	1.9	Positive
1	2	203	Primary	Classroom 303	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	203	Primary	Classroom 303	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	203	Primary	Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	3.9	Positive
1	2	203A	Storage	Classroom 303 Storage Closet	yes	W1	Plaster	White	Cracking	4	36.5	Positive	N/A	N/A
1	2	203A	Storage	Classroom 303 Storage Closet	yes	W2	Plaster	White	Flaking	50	42	Positive	N/A	N/A
1	2	203A	Storage	Classroom 303 Storage Closet	yes	W3	Plaster	White	Flaking	25	47.5	Positive	N/A	N/A
1	2	203A	Storage	Classroom 303 Storage Closet	yes	W4	Plaster	White	Flaking	45	30.6	Positive	N/A	N/A
1	2	203A	Storage	Classroom 303 Storage Closet	yes	Ceiling	Plaster	White	Flaking	15	28	Positive	N/A	N/A
1	2	203A	Storage	Classroom 303 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	203D	Administrative Office	Office inside Classroom 303	yes	W1	Plaster	White	Cracking	4	26.6	Positive	N/A	N/A
1	2	203D	Administrative Office	Office inside Classroom 303	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	203D	Administrative Office	Office inside Classroom 303	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	203D	Administrative Office	Office inside Classroom 303	yes	W4	Plaster	White	Flaking	28	40.5	Positive	N/A	N/A
1	2	203D	Administrative Office	Office inside Classroom 303	yes	Ceiling	Plaster	White	Flaking	36	28	Positive	N/A	N/A
1	2	203D	Administrative Office	Office inside Classroom 303	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	211	Primary	Classroom 311	yes	W1	Plaster	White	Flaking	7	39.4	Positive	N/A	N/A
1	2	211	Primary	Classroom 311	yes	W2	Plaster	White	Flaking	125	48.7	Positive	N/A	N/A
1	2	211	Primary	Classroom 311	yes	W3	Plaster	White	Flaking	33	52.1	Positive	N/A	N/A
1	2	211	Primary	Classroom 311	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	1.7	Positive
1	2	211	Primary	Classroom 311	yes	W4	Plaster	White	Flaking	125	45.8	Positive	N/A	N/A
1	2	211	Primary	Classroom 311	yes	Ceiling	Plaster	White	Flaking	23	40.2	Positive	N/A	N/A
1	2	211	Primary	Classroom 311	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	211A	Storage	Classroom 311 Storage Closet	yes	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	211A	Storage	Classroom 311 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	211A	Storage	Classroom 311 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	211A	Storage	Classroom 311 Storage Closet	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	211A	Storage	Classroom 311 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	211A	Storage	Classroom 311 Storage Closet	yes	Floor	Wood	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	S22A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 311	yes	W1	Brick	N/A	None	0	N/A	N/A	N/A	N/A
1	2	S22A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 311	yes	W2	Brick	N/A	None	0	N/A	N/A	N/A	N/A
1	2	S22A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 311	yes	W3	Brick	White	Flaking	24	30.4	Positive	N/A	N/A
1	2	S22A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 311	yes	W4	Brick	N/A	None	0	N/A	N/A	N/A	N/A
1	2	S22A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 311	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	2	S22A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 311	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	2	S22	Stairs	Fire Tower next to Classroom 311	yes	W1	Brick	White	Chipping	5	24.5	Positive	N/A	N/A
1	2	S22	Stairs	Fire Tower next to Classroom 311	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A
1	2	S22	Stairs	Fire Tower next to Classroom 311	yes	W3	Brick	White	Cracking	4	27.3	Positive	N/A	N/A
1	2	S22	Stairs	Fire Tower next to Classroom 311	yes	W4	Brick	White	Flaking	1	33.5	Positive	N/A	N/A
1	2	S22	Stairs	Fire Tower next to Classroom 311	yes	Ceiling	Concrete	White	Flaking	22	29.5	Positive	N/A	N/A
1	2	S22	Stairs	Fire Tower next to Classroom 311	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	2	204	Primary	Classroom 304	yes	W1	Plaster	White	Cracking	6	20.9	Positive	N/A	N/A
1	2	204	Primary	Classroom 304	yes	W2	Plaster	White	Flaking	2	24.2	Positive	N/A	N/A
1	2	204	Primary	Classroom 304	yes	W3	Plaster	White	Flaking	10	19.5	Positive	N/A	N/A
1	2	204	Primary	Classroom 304	yes	W4	Wood	White	None	0	N/A	N/A	N/A	N/A
1	2	204	Primary	Classroom 304	yes	Ceiling	Plaster	White	Flaking	24	27.3	Positive	N/A	N/A
1	2	204	Primary	Classroom 304	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	204A	Storage	Classroom 304 Storage Closet	yes	W1	Plaster	White	Flaking	12	24.8	Positive	N/A	N/A
1	2	204A	Storage	Classroom 304 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	204A	Storage	Classroom 304 Storage Closet	yes	W3	Plaster	White	Flaking	10	20.2	Positive	N/A	N/A
1	2	204A	Storage	Classroom 304 Storage Closet	yes	W4	Plaster	White	Flaking	28	16.5	Positive	N/A	N/A
1	2	204A	Storage	Classroom 304 Storage Closet	yes	Ceiling	Plaster	White	Flaking	20	19.2	Positive	N/A	N/A
1	2	204A	Storage	Classroom 304 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	204B	Storage	Storage Closet outside Classroom 304	yes	W1	Plaster	White	Flaking	6	22.9	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
		Name of Inspector: Ryan Hutsell												
		Inspection Company: Synertech												
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	204B	Storage	Storage Closet outside Classroom 304	yes	W2	Plaster	White	Flaking	4	26.5	Positive	N/A	N/A
1	2	204B	Storage	Storage Closet outside Classroom 304	yes	W3	Plaster	White	Cracking	8	24.3	Positive	N/A	N/A
1	2	204B	Storage	Storage Closet outside Classroom 304	yes	W4	Plaster	White	Flaking	12	23.8	Positive	N/A	N/A
1	2	204B	Storage	Storage Closet outside Classroom 304	yes	Ceiling	Plaster	White	Flaking	16	28.7	Positive	N/A	N/A
1	2	204B	Storage	Storage Closet outside Classroom 304	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	JC1	Service Closets	Custodial Closet outside Classroom 304	no	W1	Plaster	White	Flaking	8	16.4	Positive	N/A	N/A
1	2	JC1	Service Closets	Custodial Closet outside Classroom 304	no	W2	Plaster	White	Flaking	8	28.2	Positive	N/A	N/A
1	2	JC1	Service Closets	Custodial Closet outside Classroom 304	no	W3	Plaster	White	Cracking	6	25.4	Positive	N/A	N/A
1	2	JC1	Service Closets	Custodial Closet outside Classroom 304	no	W4	Plaster	White	Gouges	2	26.8	Positive	N/A	N/A
1	2	JC1	Service Closets	Custodial Closet outside Classroom 304	no	Ceiling	Plaster	White	Cracking	4	22	Positive	N/A	N/A
1	2	JC1	Service Closets	Custodial Closet outside Classroom 304	no	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	205	Primary	Classroom 305	yes	W1	Plaster	White	Flaking	4	25.4	Positive	N/A	N/A
1	2	205	Primary	Classroom 305	yes	W2	Wood	White	None	0	N/A	N/A	N/A	N/A
1	2	205	Primary	Classroom 305	yes	W3	Plaster	White	Flaking	18	23.6	Positive	N/A	N/A
1	2	205	Primary	Classroom 305	yes	W4	Plaster	White	Flaking	6	19.8	Positive	N/A	N/A
1	2	205	Primary	Classroom 305	yes	Ceiling	Plaster	White	Flaking	24	21.7	Positive	N/A	N/A
1	2	205	Primary	Classroom 305	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	205A	Storage	Classroom 305 Storage Closet	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	205A	Storage	Classroom 305 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	205A	Storage	Classroom 305 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	205A	Storage	Classroom 305 Storage Closet	yes	W4	Plaster	White	Flaking	5	26.3	Positive	N/A	N/A
1	2	205A	Storage	Classroom 305 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	205A	Storage	Classroom 305 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	206	Primary	Classroom 306	yes	W1	Plaster	White	Flaking	94	29.4	Positive	N/A	N/A
1	2	206	Primary	Classroom 306	yes	W2	Plaster	White	Flaking	60	20.5	Positive	N/A	N/A
1	2	206	Primary	Classroom 306	yes	W3	Plaster	White	Flaking	12	20.2	Positive	N/A	N/A
1	2	206	Primary	Classroom 306	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.4	Negative
1	2	206	Primary	Classroom 306	yes	W4	Plaster	White	Flaking	18	21.7	Positive	N/A	N/A
1	2	206	Primary	Classroom 306	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	206	Primary	Classroom 306	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	206	Primary	Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	3.7	Positive
1	2	206A	Storage	Classroom 306 Storage Closet	yes	W1	Plaster	White	Chipping	1	24.1	Positive	N/A	N/A
1	2	206A	Storage	Classroom 306 Storage Closet	yes	W2	Plaster	White	Flaking	1	25.6	Positive	N/A	N/A
1	2	206A	Storage	Classroom 306 Storage Closet	yes	W3	Plaster	White	Flaking	4	28.7	Positive	N/A	N/A
1	2	206A	Storage	Classroom 306 Storage Closet	yes	W4	Plaster	White	Cracking	2	21	Positive	N/A	N/A
1	2	206A	Storage	Classroom 306 Storage Closet	yes	Ceiling	Plaster	White	Cracking	6	26.5	Positive	N/A	N/A
1	2	206A	Storage	Classroom 306 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 304 - 306	yes	W1	Plaster	White	Chipping	75	19.2	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 304 - 306	yes	W2	Plaster	White	Chipping	4	22.8	Positive	N/A	N/A
1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 304 - 306	yes	W3	Plaster	White	Flaking	62	26.4	Positive	N/A	N/A
1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 304 - 306	yes	W4	Plaster	White	Flaking	110	19.2	Positive	N/A	N/A
1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 304 - 306	yes	Ceiling	Plaster	White	Flaking	12	20.6	Positive	N/A	N/A
1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 304 - 306	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 306	yes	W1	Plaster	White	Flaking	24	26.2	Positive	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 306	yes	W2	Plaster	White	Flaking	4	19.7	Positive	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 306	yes	W3	Plaster	White	Cracking	6	25.4	Positive	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 306	yes	W4	Plaster	White	Flaking	2	26.9	Positive	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 306	yes	Ceiling	Plaster	White	Cracking	12	N/A	Positive	N/A	N/A
1	2	S21	Stairs	Stairwell next to Classroom 306	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 307 - 310	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 307 - 310	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.7	Positive
1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 307 - 310	yes	W2	Plaster	White	Cracking	10	22.8	Positive	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 307 - 310	yes	W3	Plaster	White	Cracking	4	26.5	Positive	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 307 - 310	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	2.6	Positive
1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 307 - 310	yes	W4	Plaster	White	Flaking	10	21.2	Positive	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 307 - 310	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 307 - 310	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	210B	Storage	Storage Closet outside Classroom 310	yes	W1	Plaster	White	Flaking	4	24.2	Positive	N/A	N/A
1	2	210B	Storage	Storage Closet outside Classroom 310	yes	W2	Plaster	White	Cracking	2	25.1	Positive	N/A	N/A
1	2	210B	Storage	Storage Closet outside Classroom 310	yes	W3	Plaster	White	Flaking	6	29.2	Positive	N/A	N/A
1	2	210B	Storage	Storage Closet outside Classroom 310	yes	W4	Plaster	White	Flaking	3	20	Positive	N/A	N/A
1	2	210B	Storage	Storage Closet outside Classroom 310	yes	Ceiling	Plaster	White	Flaking	12	21.2	Positive	N/A	N/A
1	2	210B	Storage	Storage Closet outside Classroom 310	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	207	Primary	Classroom 307	yes	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	207	Primary	Classroom 307	yes	W2	Plaster	White	Chipping	2	25.6	Positive	N/A	N/A
1	2	207	Primary	Classroom 307	yes	W3	Plaster	White	Flaking	18	28.6	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
		Name of Inspector: Ryan Hutsell												
		Inspection Company: Synertech												
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	207	Primary	Classroom 307	yes	W4	Plaster	White	Flaking	20	21.5	Positive	N/A	N/A
1	2	207	Primary	Classroom 307	yes	Ceiling	Plaster	White	Flaking	6	31.1	Positive	N/A	N/A
1	2	207	Primary	Classroom 307	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	207A	Storage	Classroom 307 Storage Closet	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	207A	Storage	Classroom 306 Storage Closet	yes	W2	Plaster	White	Cracking	3	23.7	Positive	N/A	N/A
1	2	207A	Storage	Classroom 306 Storage Closet	yes	W3	Plaster	White	Flaking	4	21.2	Positive	N/A	N/A
1	2	207A	Storage	Classroom 306 Storage Closet	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	207A	Storage	Classroom 306 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	207A	Storage	Classroom 306 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	CL1	Storage	Storage Closet outside Classroom 306	yes	W1	Plaster	White	Flaking	3	20.6	Positive	N/A	N/A
1	2	CL1	Storage	Storage Closet outside Classroom 306	yes	W2	Plaster	White	Flaking	1	29.9	Positive	N/A	N/A
1	2	CL1	Storage	Storage Closet outside Classroom 306	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	CL1	Storage	Storage Closet outside Classroom 306	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	CL1	Storage	Storage Closet outside Classroom 306	yes	Ceiling	Plaster	White	Flaking	4	21.5	Positive	N/A	N/A
1	2	CL1	Storage	Storage Closet outside Classroom 306	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	208	Primary	Classroom 308	yes	W1	Plaster	White	Cracking	8	22.7	Positive	N/A	N/A
1	2	208	Primary	Classroom 308	yes	W2	Plaster	White	Flaking	38	26.1	Positive	N/A	N/A
1	2	208	Primary	Classroom 308	yes	W3	Plaster	White	Flaking	102	25.9	Positive	N/A	N/A
1	2	208	Primary	Classroom 308	yes	W4	Plaster	White	Flaking	12	32.1	Positive	N/A	N/A
1	2	208	Primary	Classroom 308	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	208	Primary	Classroom 308	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	208A	Storage	Storage Closet outside Classroom 308	yes	W1	Plaster	White	Flaking	11	22.8	Positive	N/A	N/A
1	2	208A	Storage	Storage Closet outside Classroom 308	yes	W2	Plaster	White	Flaking	3	22.1	Positive	N/A	N/A
1	2	208A	Storage	Storage Closet outside Classroom 308	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	208A	Storage	Storage Closet outside Classroom 308	yes	W4	Plaster	White	Flaking	7	24.6	Positive	N/A	N/A
1	2	208A	Storage	Storage Closet outside Classroom 308	yes	Ceiling	Plaster	White	Flaking	5	18.2	Positive	N/A	N/A
1	2	208A	Storage	Storage Closet outside Classroom 308	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	209	Primary	Classroom 309	yes	W1	Plaster	White	Chipping	4	25.9	Positive	N/A	N/A
1	2	209	Primary	Classroom 309	yes	W2	Plaster	White	Flaking	2	26.4	Positive	N/A	N/A
1	2	209	Primary	Classroom 309	yes	W3	Plaster	White	Flaking	49	28.2	Positive	N/A	N/A
1	2	209	Primary	Classroom 309	yes	W4	Plaster	White	Flaking	12	24.9	Positive	N/A	N/A
1	2	209	Primary	Classroom 309	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	209	Primary	Classroom 309	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	209A	Storage	Classroom 309 Storage Closet	yes	W1	Plaster	White	Flaking	72	22.2	Positive	N/A	N/A
1	2	209A	Storage	Classroom 309 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	209A	Storage	Classroom 309 Storage Closet	yes	W3	Plaster	White	Flaking	36	21.5	Positive	N/A	N/A
1	2	209A	Storage	Classroom 309 Storage Closet	yes	W4	Plaster	White	Flaking	264	27.5	Positive	N/A	N/A
1	2	209A	Storage	Classroom 309 Storage Closet	yes	Ceiling	Plaster	White	Flaking	72	25.2	Positive	N/A	N/A
1	2	209A	Storage	Classroom 309 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
		Name of Inspector: Ryan Hutsell												
		Inspection Company: Synertech												
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	210	Primary	Classroom 310	yes	W1	Plaster	White	Chipping	30	20.2	Positive	N/A	N/A
1	2	210	Primary	Classroom 310	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	2	210	Primary	Classroom 310	yes	W3	Plaster	White	Flaking	8	18.7	Positive	N/A	N/A
1	2	210	Primary	Classroom 310	yes	W4	Plaster	White	Flaking	12	23.6	Positive	N/A	N/A
1	2	210	Primary	Classroom 310	yes	Ceiling	Plaster	White	Cracking	15	22.3	Positive	N/A	N/A
1	2	210	Primary	Classroom 310	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	210A	Storage	Classroom 310 Storage Closet	yes	W1	Plaster	White	Flaking	64	28.7	Positive	N/A	N/A
1	2	210A	Storage	Classroom 310 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	210A	Storage	Classroom 310 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	2	210A	Storage	Classroom 310 Storage Closet	yes	W4	Plaster	White	Flaking	1	25.5	Positive	N/A	N/A
1	2	210A	Storage	Classroom 310 Storage Closet	yes	Ceiling	Plaster	White	Flaking	42	21.2	Positive	N/A	N/A
1	2	210A	Storage	Classroom 310 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	2	T3	Restrooms, Staff - Male	Men's Staff Restroom next to Classroom 310	yes	W1	Plaster	White	Flaking	11	20.4	Positive	N/A	N/A
1	2	T3	Restrooms, Staff - Male	Men's Staff Restroom next to Classroom 310	yes	W2	Plaster	White	Flaking	6	28.5	Positive	N/A	N/A
1	2	T3	Restrooms, Staff - Male	Men's Staff Restroom next to Classroom 310	yes	W3	Plaster	White	Flaking	8	23.2	Positive	N/A	N/A
1	2	T3	Restrooms, Staff - Male	Men's Staff Restroom next to Classroom 310	yes	W4	Plaster	White	Cracking	20	26.8	Positive	N/A	N/A
1	2	T3	Restrooms, Staff - Male	Men's Staff Restroom next to Classroom 310	yes	Ceiling	Plaster	White	Flaking	3	20.5	Positive	N/A	N/A
1	2	T3	Restrooms, Staff - Male	Men's Staff Restroom next to Classroom 310	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	2	A1	Stairs	Stairway to Attic next to Classroom 308	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	A1	Stairs	Stairway to Attic next to Classroom 308	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	A1	Stairs	Stairway to Attic next to Classroom 308	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	A1	Stairs	Stairway to Attic next to Classroom 308	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	A1	Stairs	Stairway to Attic next to Classroom 308	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	A1	Stairs	Stairway to Attic next to Classroom 308	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101	Primary	Classroom 201	yes	W1	Plaster	White	Flaking	54	43.8	Positive	N/A	N/A
1	1	101	Primary	Classroom 201	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	1	101	Primary	Classroom 201	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	5.1	Positive
1	1	101	Primary	Classroom 201	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.9	Positive
1	1	101	Primary	Classroom 201	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.1	Positive
1	1	101	Primary	Classroom 201	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	2.8	Positive
1	1	101	Primary	Classroom 201	yes	W2	Plaster	White	Flaking	24	40.9	Positive	N/A	N/A
1	1	101	Primary	Classroom 201	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.5	Positive
1	1	101	Primary	Classroom 201	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.4	Positive
1	1	101	Primary	Classroom 201	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	2.7	Positive

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	101	Primary	Classroom 201	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	4.5	Positive
1	1	101	Primary	Classroom 201	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	2.1	Positive
1	1	101	Primary	Classroom 201	yes	W3	Plaster	White	Flaking	76	49.2	Positive	N/A	N/A
1	1	101	Primary	Classroom 201	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	2.8	Positive
1	1	101	Primary	Classroom 201	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.8	Positive
1	1	101	Primary	Classroom 201	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	2.1	Positive
1	1	101	Primary	Classroom 201	yes	W4	Plaster	White	Flaking	88	46.2	Positive	N/A	N/A
1	1	101	Primary	Classroom 201	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	2.7	Positive
1	1	101	Primary	Classroom 201	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	1	101	Primary	Classroom 201	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.3	Positive
1	1	101	Primary	Classroom 201	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	101	Primary	Classroom 201	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	101	Primary	Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	4.7	Positive
1	1	101A	Storage	Classroom 201 Storage Closet	yes	W1	Plaster	White	Flaking	15	39.8	Positive	N/A	N/A
1	1	101A	Storage	Classroom 201 Storage Closet	yes	W2	Plaster	White	Cracking	9	51.2	Positive	N/A	N/A
1	1	101A	Storage	Classroom 201 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	101A	Storage	Classroom 201 Storage Closet	yes	W4	Plaster	White	Flaking	65	46.5	Positive	N/A	N/A
1	1	101A	Storage	Classroom 201 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	101A	Storage	Classroom 201 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	102	Administrative Office	Principal's Office	yes	W1	Plaster	White	Flaking	104	26.5	Positive	N/A	N/A
1	1	102	Administrative Office	Principal's Office	yes	W2	Plaster	White	Flaking	160	28.9	Positive	N/A	N/A
1	1	102	Administrative Office	Principal's Office	yes	W3	Plaster	White	Flaking	24	24.3	Positive	N/A	N/A
1	1	102	Administrative Office	Principal's Office	yes	W4	Plaster	White	Cracking	7	30.9	Positive	N/A	N/A
1	1	102	Administrative Office	Principal's Office	yes	Ceiling	Plaster	White	Flaking	20	26	Positive	N/A	N/A
1	1	102	Administrative Office	Principal's Office	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	102E	Restrooms, Staff - Male	Principal's Office Restroom	yes	W1	Plaster	White	Flaking	18	25.9	Positive	N/A	N/A
1	1	102E	Restrooms, Staff - Male	Principal's Office Restroom	yes	W2	Plaster	White	Chipping	1	31.2	Positive	N/A	N/A
1	1	102E	Restrooms, Staff - Male	Principal's Office Restroom	yes	W3	Plaster	White	Cracking	8	33.6	Positive	N/A	N/A
1	1	102E	Restrooms, Staff - Male	Principal's Office Restroom	yes	W4	Plaster	White	Flaking	34	26.5	Positive	N/A	N/A
1	1	102E	Restrooms, Staff - Male	Principal's Office Restroom	yes	Ceiling	Plaster	White	Cracking	3	14.2	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	102E	Restrooms, Staff - Male	Principal's Office Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	W1	Plaster	White	Chipping	5	12.9	Positive	N/A	N/A
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	W2	Plaster	White	Flaking	57	32.6	Positive	N/A	N/A
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	W3	Plaster	White	Flaking	72	20.9	Positive	N/A	N/A
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	5.4	Positive
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.8	Positive
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	W4	Plaster	White	Cracking	12	21.2	Positive	N/A	N/A
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	Ceiling	Plaster	White	Flaking	6	18.2	Positive	N/A	N/A
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	102C	Conference Room	Conference Room next to Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	4.6	Positive
1	1	102D	Administrative Office	Counselor's Office next to Principal's Office	yes	W1	Plaster	White	Flaking	40	14.2	Positive	N/A	N/A
1	1	102D	Administrative Office	Counselor's Office next to Principal's Office	yes	W2	Plaster	White	Cracking	13	9.5	Positive	N/A	N/A
1	1	102D	Administrative Office	Counselor's Office next to Principal's Office	yes	W3	Plaster	White	Flaking	19	16.4	Positive	N/A	N/A
1	1	102D	Administrative Office	Counselor's Office next to Principal's Office	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	102D	Administrative Office	Counselor's Office next to Principal's Office	yes	Ceiling	Plaster	White	Cracking	60	10.2	Positive	N/A	N/A
1	1	102D	Administrative Office	Counselor's Office next to Principal's Office	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	W1	Plaster	White	Flaking	16	21.2	Positive	N/A	N/A
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	4	Positive
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	W2	Plaster	White	Flaking	97	30.9	Positive	N/A	N/A
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	W3	Plaster	White	Cracking	20	36.7	Positive	N/A	N/A
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.9	Positive
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	2.7	Positive
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	W4	Plaster	White	Flaking	7	27.4	Positive	N/A	N/A
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	102A	Storage	Storage Room next to Visitor's Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	9.2	Positive

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	S14	Circulation (Hallway)	Visitor's Entrance Vestibule	yes	W1	Plaster	White	Chipping	7	29.8	Positive	N/A	N/A
1	1	S14	Circulation (Hallway)	Visitor's Entrance Vestibule	yes	W2	Plaster	White	Chipping	1	20.6	Positive	N/A	N/A
1	1	S14	Circulation (Hallway)	Visitor's Entrance Vestibule	yes	W3	Plaster	White	Flaking	6	32.1	Positive	N/A	N/A
1	1	S14	Circulation (Hallway)	Visitor's Entrance Vestibule	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.2	Negative
1	1	S14	Circulation (Hallway)	Visitor's Entrance Vestibule	yes	W4	Plaster	White	Chipping	2	14.6	Positive	N/A	N/A
1	1	S14	Circulation (Hallway)	Visitor's Entrance Vestibule	yes	Ceiling	Plaster	White	Flaking	18	9.5	Positive	N/A	N/A
1	1	S14	Circulation (Hallway)	Visitor's Entrance Vestibule	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	S13	Stairs	Stairwell next to Classroom 201	yes	W1	Plaster	White	Flaking	106	31.8	Positive	N/A	N/A
1	1	S13	Stairs	Stairwell next to Classroom 201	yes	W2	Plaster	White	Chipping	6	28.9	Positive	N/A	N/A
1	1	S13	Stairs	Stairwell next to Classroom 201	yes	W3	Plaster	White	Flaking	100	40.2	Positive	N/A	N/A
1	1	S13	Stairs	Stairwell next to Classroom 201	yes	W4	Plaster	White	Flaking	44	35.4	Positive	N/A	N/A
1	1	S13	Stairs	Stairwell next to Classroom 201	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	S13	Stairs	Stairwell next to Classroom 201	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	S13A	Stairs	Entrance Vestibule - Stairwell next to Classroom 201	yes	W1	Plaster	White	Chipping	7	16.5	Positive	N/A	N/A
1	1	S13A	Stairs	Entrance Vestibule - Stairwell next to Classroom 201	yes	W2	Plaster	White	Chipping	1	38.5	Positive	N/A	N/A
1	1	S13A	Stairs	Entrance Vestibule - Stairwell next to Classroom 201	yes	W3	Plaster	White	Flaking	6	33.2	Positive	N/A	N/A
1	1	S13A	Stairs	Entrance Vestibule - Stairwell next to Classroom 201	yes	W4	Plaster	White	Chipping	2	24.9	Positive	N/A	N/A
1	1	S13A	Stairs	Entrance Vestibule - Stairwell next to Classroom 201	yes	Ceiling	Plaster	White	Flaking	18	16.9	Positive	N/A	N/A
1	1	S13A	Stairs	Entrance Vestibule - Stairwell next to Classroom 201	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	W1	Plaster	White	Flaking	6	26.9	Positive	N/A	N/A
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	W2	Plaster	White	Flaking	4	18.2	Positive	N/A	N/A
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.9	Positive
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	5.4	Positive
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	W3	Plaster	White	Flaking	6	35.6	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	W4	Plaster	White	Flaking	10	34.2	Positive	N/A	N/A
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	4.6	Positive
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.5	Positive
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	Ceiling	Plaster	White	Flaking	1	28.4	Positive	N/A	N/A
1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 201 - 203	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	102B	Administrative Office	Main Office	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	102B	Administrative Office	Main Office	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	102B	Administrative Office	Main Office	yes	W3	Plaster	White	Flaking	14	16.5	Positive	N/A	N/A
1	1	102B	Administrative Office	Main Office	yes	W4	Plaster	White	Cracking	15	21.4	Positive	N/A	N/A
1	1	102B	Administrative Office	Main Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	102B	Administrative Office	Main Office	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	102H	Administrative Office	Small Office next to Main Office	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	102H	Administrative Office	Small Office next to Main Office	yes	W2	Plaster	White	Flaking	51	18.5	Positive	N/A	N/A
1	1	102H	Administrative Office	Small Office next to Main Office	yes	W3	Plaster	White	Flaking	6	19.2	Positive	N/A	N/A
1	1	102H	Administrative Office	Small Office next to Main Office	yes	W4	Plaster	White	Flaking	7	20.5	Positive	N/A	N/A
1	1	102H	Administrative Office	Small Office next to Main Office	yes	Ceiling	Plaster	White	Flaking	32	24.3	Positive	N/A	N/A
1	1	102H	Administrative Office	Small Office next to Main Office	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W1	Plaster	White	Flaking	48	29.6	Positive	N/A	N/A
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	5.1	Positive
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	6.3	Positive

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W2	Plaster	White	Flaking	36	31.8	Positive	N/A	N/A
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	5.9	Positive
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W3	Plaster	White	Flaking	28	40.2	Positive	N/A	N/A
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	4.3	Positive
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	2.8	Positive
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W4	Plaster	White	Flaking	35	30.5	Positive	N/A	N/A
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.8	Positive
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	Ceiling	Plaster	White	Flaking	2	14.2	Positive	N/A	N/A
1	1	100	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 211	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	111	Primary	Classroom 211	yes	W1	Plaster	White	Cracking	10	49.5	Positive	N/A	N/A
1	1	111	Primary	Classroom 211	yes	W2	Plaster	White	Flaking	42	38.9	Positive	N/A	N/A
1	1	111	Primary	Classroom 211	yes	W3	Plaster	White	Flaking	8	40.2	Positive	N/A	N/A
1	1	111	Primary	Classroom 211	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.9	Positive
1	1	111	Primary	Classroom 211	yes	W4	Plaster	White	Flaking	36	43.3	Positive	N/A	N/A
1	1	111	Primary	Classroom 211	yes	Ceiling	Plaster	White	Flaking	6	20.6	Positive	N/A	N/A
1	1	111	Primary	Classroom 211	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	111A	Storage	Classroom 211 Storage Closet	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	111A	Storage	Classroom 211 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	111A	Storage	Classroom 211 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	111A	Storage	Classroom 211 Storage Closet	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	111A	Storage	Classroom 211 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	111A	Storage	Classroom 211 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	103	Primary	Classroom 203	yes	W1	Plaster	White	Flaking	29	45.4	Positive	N/A	N/A
1	1	103	Primary	Classroom 203	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	9.8	Positive
1	1	103	Primary	Classroom 203	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	103	Primary	Classroom 203	yes	W3	Plaster	White	Cracking	60	29.2	Positive	N/A	N/A
1	1	103	Primary	Classroom 203	yes	W4	Plaster	White	Cracking	8	36.8	Positive	N/A	N/A
1	1	103	Primary	Classroom 203	yes	Ceiling	Plaster	White	Flaking	16	24.5	Positive	N/A	N/A
1	1	103	Primary	Classroom 203	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	103A	Administrative Office	Office inside Classroom 203	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	103A	Administrative Office	Office inside Classroom 203	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	103A	Administrative Office	Office inside Classroom 203	yes	W3	Plaster	White	Cracking	10	26.2	Positive	N/A	N/A
1	1	103A	Administrative Office	Office inside Classroom 203	yes	W4	Plaster	White	Flaking	18	23.2	Positive	N/A	N/A
1	1	103A	Administrative Office	Office inside Classroom 203	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	103A	Administrative Office	Office inside Classroom 203	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	103C	Administrative Office	Office next to Classroom 203	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	103C	Administrative Office	Office next to Classroom 203	yes	W2	Plaster	White	Flaking	64	16.5	Positive	N/A	N/A
1	1	103C	Administrative Office	Office next to Classroom 203	yes	W3	Plaster	White	Cracking	1	19.2	Positive	N/A	N/A
1	1	103C	Administrative Office	Office next to Classroom 203	yes	W4	Plaster	White	Flaking	12	35	Positive	N/A	N/A
1	1	103C	Administrative Office	Office next to Classroom 203	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	103C	Administrative Office	Office next to Classroom 203	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	S12A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 211	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A
1	1	S12A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 211	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A
1	1	S12A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 211	yes	W3	Brick	White	Flaking	24	26.9	Positive	N/A	N/A
1	1	S12A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 211	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A
1	1	S12A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 211	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	1	S12A	Circulation (Hallway)	Vestibule to Fire Tower next to Classroom 211	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	1	S12	Stairs	Fire Tower next to Classroom 211	yes	W1	Brick	White	Flaking	4	23.2	Positive	N/A	N/A
1	1	S12	Stairs	Fire Tower next to Classroom 211	yes	W2	Brick	White	Flaking	24	19.8	Positive	N/A	N/A
1	1	S12	Stairs	Fire Tower next to Classroom 211	yes	W3	Brick	White	Flaking	10	30.8	Positive	N/A	N/A
1	1	S12	Stairs	Fire Tower next to Classroom 211	yes	W4	Brick	White	Cracking	2	26.7	Positive	N/A	N/A
1	1	S12	Stairs	Fire Tower next to Classroom 211	yes	Ceiling	Concrete	White	Cracking	16	25.5	Positive	N/A	N/A
1	1	S12	Stairs	Fire Tower next to Classroom 211	yes	Floor	Concrete	Grey	Chipping	45	0.28	Negative	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 204 - 206	yes	W1	Plaster	White	Chipping	2	21.6	Positive	N/A	N/A
1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 204 - 206	yes	W2	Plaster	White	Chipping	20	19.8	Positive	N/A	N/A
1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 204 - 206	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 204 - 206	yes	W4	Plaster	White	Flaking	27	24.5	Positive	N/A	N/A
1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 204 - 206	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 204 - 206	yes	Floor	Concrete	N/A	Chipping	0	N/A	N/A	N/A	N/A
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	W1	Plaster	White	Flaking	6	20.9	Positive	N/A	N/A
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	W2	Plaster	White	Flaking	9	19.5	Positive	N/A	N/A
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	W3	Plaster	White	Flaking	12	16.8	Positive	N/A	N/A
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	W4	Plaster	White	Chipping	1	24.3	Positive	N/A	N/A
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	7.9	Positive
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	5.1	Positive
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	7.2	Positive
1	1	S11	Stairs	Stairwell next to Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	5.3	Positive
1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 207 - 208	yes	W1	Plaster	White	Flaking	5	14.8	Positive	N/A	N/A
1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 207 - 208	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 207 - 208	yes	W3	Plaster	White	Cracking	6	23.5	Positive	N/A	N/A
1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 207 - 208	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 207 - 208	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 207 - 208	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	1	104	Primary	Classroom 204	yes	W1	Plaster	White	Flaking	16	20.5	Positive	N/A	N/A
1	1	104	Primary	Classroom 204	yes	W2	Plaster	White	Cracking	8	21.6	Positive	N/A	N/A
1	1	104	Primary	Classroom 204	yes	W3	Plaster	White	Flaking	52	24.3	Positive	N/A	N/A
1	1	104	Primary	Classroom 204	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	104	Primary	Classroom 204	yes	Ceiling	Plaster	White	Flaking	16	19	Positive	N/A	N/A
1	1	104	Primary	Classroom 204	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	104A	Storage	Classroom 204 Storage Closet	yes	W1	Plaster	White	Flaking	15	24.2	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
		Name of Inspector: Ryan Hutsell												
		Inspection Company: Synertech												
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	104A	Storage	Classroom 204 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	104A	Storage	Classroom 204 Storage Closet	yes	W3	Plaster	White	Cracking	8	18.9	Positive	N/A	N/A
1	1	104A	Storage	Classroom 204 Storage Closet	yes	W4	Plaster	White	Flaking	18	19.2	Positive	N/A	N/A
1	1	104A	Storage	Classroom 204 Storage Closet	yes	Ceiling	Plaster	White	Cracking	12	14.9	Positive	N/A	N/A
1	1	104A	Storage	Classroom 204 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	104B	Storage	Storage Closet outside Classroom 204	yes	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	104B	Storage	Storage Closet outside Classroom 204	yes	W2	Plaster	White	Cracking	9	26.3	Positive	N/A	N/A
1	1	104B	Storage	Storage Closet outside Classroom 204	yes	W3	Plaster	White	Cracking	42	21.8	Positive	N/A	N/A
1	1	104B	Storage	Storage Closet outside Classroom 204	yes	W4	Plaster	White	Cracking	21	24.5	Positive	N/A	N/A
1	1	104B	Storage	Storage Closet outside Classroom 204	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	104B	Storage	Storage Closet outside Classroom 204	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	JC2	Service Closets	Custodial Closet outside Classroom 204	no	W1	Plaster	White	Cracking	2	16.2	Positive	N/A	N/A
1	1	JC2	Service Closets	Custodial Closet outside Classroom 204	no	W2	Plaster	White	Flaking	4	34.5	Positive	N/A	N/A
1	1	JC2	Service Closets	Custodial Closet outside Classroom 204	no	W3	Plaster	White	Flaking	12	29.4	Positive	N/A	N/A
1	1	JC2	Service Closets	Custodial Closet outside Classroom 204	no	W4	Plaster	White	Cracking	4	16.8	Positive	N/A	N/A
1	1	JC2	Service Closets	Custodial Closet outside Classroom 204	no	Ceiling	Plaster	White	Flaking	5	10.2	Positive	N/A	N/A
1	1	JC2	Service Closets	Custodial Closet outside Classroom 204	no	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	105	Primary	Classroom 205	yes	W1	Plaster	White	Flaking	5	26.5	Positive	N/A	N/A
1	1	105	Primary	Classroom 205	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	105	Primary	Classroom 205	yes	W3	Plaster	White	Flaking	34	21.4	Positive	N/A	N/A
1	1	105	Primary	Classroom 205	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	105	Primary	Classroom 205	yes	Ceiling	Plaster	White	Flaking	4	20.2	Positive	N/A	N/A
1	1	105	Primary	Classroom 205	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	105A	Storage	Classroom 205 Storage Closet	yes	W1	Plaster	White	Cracking	10	23.1	Positive	N/A	N/A
1	1	105A	Storage	Classroom 205 Storage Closet	yes	W2	Plaster	White	Flaking	30	21.6	Positive	N/A	N/A
1	1	105A	Storage	Classroom 205 Storage Closet	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	105A	Storage	Classroom 205 Storage Closet	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	105A	Storage	Classroom 205 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	105A	Storage	Classroom 205 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	106	Primary	Classroom 206	yes	W1	Plaster	White	Flaking	7	26.4	Positive	N/A	N/A
1	1	106	Primary	Classroom 206	yes	W2	Plaster	White	Chipping	2	27.2	Positive	N/A	N/A
1	1	106	Primary	Classroom 206	yes	W3	Plaster	White	Flaking	40	32.1	Positive	N/A	N/A
1	1	106	Primary	Classroom 206	yes	W4	Plaster	White	Flaking	4	29.5	Positive	N/A	N/A
1	1	106	Primary	Classroom 206	yes	Ceiling	Plaster	White	Flaking	32	21.1	Positive	N/A	N/A
1	1	106	Primary	Classroom 206	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	106A	Storage	Classroom 206 Storage Closet	yes	W1	Plaster	White	Cracking	2	18.7	Positive	N/A	N/A
1	1	106A	Storage	Classroom 206 Storage Closet	yes	W2	Plaster	White	Flaking	8	24.8	Positive	N/A	N/A
1	1	106A	Storage	Classroom 206 Storage Closet	yes	W3	Plaster	White	Flaking	6	20.8	Positive	N/A	N/A
1	1	106A	Storage	Classroom 206 Storage Closet	yes	W4	Plaster	White	Cracking	6	23.2	Positive	N/A	N/A
1	1	106A	Storage	Classroom 206 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
		Name of Inspector: Ryan Hutsell												
		Inspection Company: Synertech												
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	106A	Storage	Classroom 206 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	CL2	Storage	Storage Closet outside Classroom 207	yes	W1	Plaster	White	Cracking	3	23.8	Positive	N/A	N/A
1	1	CL2	Storage	Storage Closet outside Classroom 207	yes	W2	Plaster	White	Cracking	3	19	Positive	N/A	N/A
1	1	CL2	Storage	Storage Closet outside Classroom 207	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	CL2	Storage	Storage Closet outside Classroom 207	yes	W4	Plaster	White	Cracking	2	16.7	Positive	N/A	N/A
1	1	CL2	Storage	Storage Closet outside Classroom 207	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	CL2	Storage	Storage Closet outside Classroom 207	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	CL3	Storage	Storage Closet outside Library Office	yes	W1	Plaster	White	Holes	1	18.2	Positive	N/A	N/A
1	1	CL3	Storage	Storage Closet outside Library Office	yes	W2	Plaster	White	Cracking	1	23.4	Positive	N/A	N/A
1	1	CL3	Storage	Storage Closet outside Library Office	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	CL3	Storage	Storage Closet outside Library Office	yes	W4	Plaster	White	Holes	1	12.6	Positive	N/A	N/A
1	1	CL3	Storage	Storage Closet outside Library Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	CL3	Storage	Storage Closet outside Library Office	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	107	Primary	Classroom 207	yes	W1	Plaster	White	Chipping	4	23.1	Positive	N/A	N/A
1	1	107	Primary	Classroom 207	yes	W2	Plaster	White	Flaking	12	21.3	Positive	N/A	N/A
1	1	107	Primary	Classroom 207	yes	W3	Plaster	White	Flaking	38	19.4	Positive	N/A	N/A
1	1	107	Primary	Classroom 207	yes	W4	Plaster	White	Chipping	3	26.4	Positive	N/A	N/A
1	1	107	Primary	Classroom 207	yes	Ceiling	Plaster	White	Flaking	35	15.4	Positive	N/A	N/A
1	1	107	Primary	Classroom 207	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	107A	Storage	Classroom 207 Storage Closet	yes	W1	Plaster	White	Flaking	5	19.5	Positive	N/A	N/A
1	1	107A	Storage	Classroom 207 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	107A	Storage	Classroom 207 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	107A	Storage	Classroom 207 Storage Closet	yes	W4	Plaster	White	Flaking	60	22.6	Positive	N/A	N/A
1	1	107A	Storage	Classroom 207 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	107A	Storage	Classroom 207 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	108	Primary	Classroom 208	yes	W1	Plaster	White	Cracking	5	25.4	Positive	N/A	N/A
1	1	108	Primary	Classroom 208	yes	W2	Plaster	White	Flaking	6	22.8	Positive	N/A	N/A
1	1	108	Primary	Classroom 208	yes	W3	Plaster	White	Flaking	86	19.2	Positive	N/A	N/A
1	1	108	Primary	Classroom 208	yes	W4	Plaster	White	Cracking	14	23.5	Positive	N/A	N/A
1	1	108	Primary	Classroom 208	yes	Ceiling	Plaster	White	Flaking	27	20.2	Positive	N/A	N/A
1	1	108	Primary	Classroom 208	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	108B	Storage	Classroom 208 Storage Closet	yes	W1	Plaster	White	Cracking	2	16.9	Positive	N/A	N/A
1	1	108B	Storage	Classroom 208 Storage Closet	yes	W2	Plaster	White	Flaking	2	21.3	Positive	N/A	N/A
1	1	108B	Storage	Classroom 208 Storage Closet	yes	W3	Plaster	White	Flaking	2	25.6	Positive	N/A	N/A
1	1	108B	Storage	Classroom 208 Storage Closet	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	108B	Storage	Classroom 208 Storage Closet	yes	Ceiling	Plaster	White	Flaking	50	14.2	Positive	N/A	N/A
1	1	108B	Storage	Classroom 208 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	108A	Student Restrooms - Male/Female (Classroom)	Restroom inside Classroom 208	yes	W1	Plaster	White	Flaking	97	25.1	Positive	N/A	N/A
1	1	108A	Student Restrooms - Male/Female (Classroom)	Restroom inside Classroom 208	yes	W2	Plaster	White	Flaking	24	23.7	Positive	N/A	N/A
1	1	108A	Student Restrooms - Male/Female (Classroom)	Restroom inside Classroom 208	yes	W3	Plaster	White	Flaking	126	21.5	Positive	N/A	N/A
1	1	108A	Student Restrooms - Male/Female (Classroom)	Restroom inside Classroom 208	yes	W4	Plaster	White	Flaking	78	17.1	Positive	N/A	N/A
1	1	108A	Student Restrooms - Male/Female (Classroom)	Restroom inside Classroom 208	yes	Ceiling	Plaster	White	Flaking	60	15.8	Positive	N/A	N/A
1	1	108A	Student Restrooms - Male/Female (Classroom)	Restroom inside Classroom 208	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	1	CL4	Storage	Storage Closet outside Classroom 208	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	CL4	Storage	Storage Closet outside Classroom 208	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	CL4	Storage	Storage Closet outside Classroom 208	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	CL4	Storage	Storage Closet outside Classroom 208	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	CL4	Storage	Storage Closet outside Classroom 208	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	CL4	Storage	Storage Closet outside Classroom 208	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W1	Plaster	White	Chipping	10	20.2	Positive	N/A	N/A
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	4.8	Positive
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	3.5	Positive
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W2	Plaster	White	Flaking	5	23.4	Positive	N/A	N/A
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.4	Positive

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	4.1	Positive
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	2.9	Positive
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W3	Plaster	White	Flaking	16	18.7	Positive	N/A	N/A
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	3.3	Positive
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	5.4	Positive
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.4	Negative
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	5.1	Positive
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	DR1	Health Service Room	Nurses Office next to Classroom 208	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	5.1	Positive
1	1	DR2	Student Restrooms - Male/Female (Classroom)	Nurses Office Restroom	yes	W1	Plaster	White	Flaking	3	17.9	Positive	N/A	N/A
1	1	DR2	Student Restrooms - Male/Female (Classroom)	Nurses Office Restroom	yes	W2	Plaster	White	Flaking	1	23.6	Positive	N/A	N/A
1	1	DR2	Student Restrooms - Male/Female (Classroom)	Nurses Office Restroom	yes	W3	Plaster	White	Flaking	1	21.4	Positive	N/A	N/A
1	1	DR2	Student Restrooms - Male/Female (Classroom)	Nurses Office Restroom	yes	W4	Plaster	White	Flaking	8	17.8	Positive	N/A	N/A
1	1	DR2	Student Restrooms - Male/Female (Classroom)	Nurses Office Restroom	yes	Ceiling	Plaster	White	Cracking	18	22.1	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	DR2	Student Restrooms - Male/Female (Classroom)	Nurses Office Restroom	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	110	IMC (Library)	IMC (Library)	yes	W1	Plaster	White	Flaking	4	19.9	Positive	N/A	N/A
1	1	110	IMC (Library)	IMC (Library)	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	110	IMC (Library)	IMC (Library)	yes	W3	Plaster	White	Flaking	160	24.3	Positive	N/A	N/A
1	1	110	IMC (Library)	IMC (Library)	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	1	110	IMC (Library)	IMC (Library)	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.35	Negative
1	1	110	IMC (Library)	IMC (Library)	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	1	110	IMC (Library)	IMC (Library)	yes	Ceiling	Plaster	White	Flaking	12	16	Positive	N/A	N/A
1	1	110	IMC (Library)	IMC (Library)	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	1	110B	Administrative Office	Library Office	yes	W1	Plaster	White	Cracking	5	16.2	Positive	N/A	N/A
1	1	110B	Administrative Office	Library Office	yes	W2	Plaster	White	Flaking	2	14.9	Positive	N/A	N/A
1	1	110B	Administrative Office	Library Office	yes	W3	Plaster	White	Flaking	38	25.4	Positive	N/A	N/A
1	1	110B	Administrative Office	Library Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	1.9	Positive
1	1	110B	Administrative Office	Library Office	yes	W4	Plaster	White	Chipping	5	13.9	Positive	N/A	N/A
1	1	110B	Administrative Office	Library Office	yes	Ceiling	Plaster	White	Flaking	6	12.6	Positive	N/A	N/A
1	1	110B	Administrative Office	Library Office	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	02B	Boiler Room	Old Boiler Room	no	W1	Brick	Grey	Flaking	384	0.35	Negative	N/A	N/A
1	B	02B	Boiler Room	Old Boiler Room	no	W2	Brick	Grey	Flaking	288	0.32	Negative	N/A	N/A
1	B	02B	Boiler Room	Old Boiler Room	no	W3	Brick	Grey	Flaking	336	0.48	Negative	N/A	N/A
1	B	02B	Boiler Room	Old Boiler Room	no	W4	Brick	Grey	Flaking	225	0.4	Negative	N/A	N/A
1	B	02B	Boiler Room	Old Boiler Room	no	Ceiling	Concrete	White	Flaking	768	0.28	Negative	N/A	N/A
1	B	02B	Boiler Room	Old Boiler Room	no	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	002A	Boiler Room	New Boiler Room	no	W1	Brick	White	Flaking	336	0.2	Negative	N/A	N/A
1	B	002A	Boiler Room	New Boiler Room	no	W2	Brick	White	Flaking	432	0.22	Negative	N/A	N/A
1	B	002A	Boiler Room	New Boiler Room	no	W3	Brick	White	Flaking	336	0.26	Negative	N/A	N/A
1	B	002A	Boiler Room	New Boiler Room	no	W4	Brick	White	Flaking	432	0.31	Negative	N/A	N/A
1	B	002A	Boiler Room	New Boiler Room	no	Ceiling	Concrete	White	Flaking	1152	0.18	Negative	N/A	N/A
1	B	002A	Boiler Room	New Boiler Room	no	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	3	Cafeteria (Dining Area)	Boy's Cafeteria	yes	W1	Concrete	White	Flaking	10	8.7	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	3	Cafeteria (Dining Area)	Boy's Cafeteria	yes	W2	Concrete	White	Chipping	12	14.2	Positive	N/A	N/A
1	B	3	Cafeteria (Dining Area)	Boy's Cafeteria	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	0.25	Negative
1	B	3	Cafeteria (Dining Area)	Boy's Cafeteria	yes	W3	Concrete	White	Flaking	60	6.2	Positive	N/A	N/A
1	B	3	Cafeteria (Dining Area)	Boy's Cafeteria	yes	W4	Concrete	White	Flaking	32	15.9	Positive	N/A	N/A
1	B	3	Cafeteria (Dining Area)	Boy's Cafeteria	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	3.2	Positive
1	B	3	Cafeteria (Dining Area)	Boy's Cafeteria	yes	Ceiling	Plaster	N/A	Flaking	36	19	Positive	N/A	N/A
1	B	3	Cafeteria (Dining Area)	Boy's Cafeteria	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	3A	Storage	Storage Room inside Boy's Cafeteria closest to Entrance	no	W1	Concrete	White	Cracking	2	14.2	Positive	N/A	N/A
1	B	3A	Storage	Storage Room inside Boy's Cafeteria closest to Entrance	no	W2	Concrete	White	Flaking	46	15.7	Positive	N/A	N/A
1	B	3A	Storage	Storage Room inside Boy's Cafeteria closest to Entrance	no	W3	Concrete	White	Flaking	100	12.9	Positive	N/A	N/A
1	B	3A	Storage	Storage Room inside Boy's Cafeteria closest to Entrance	no	W4	Concrete	White	Cracking	2	18.4	Positive	N/A	N/A
1	B	3A	Storage	Storage Room inside Boy's Cafeteria closest to Entrance	no	Ceiling	Plaster	White	Flaking	144	8.9	Positive	N/A	N/A
1	B	3A	Storage	Storage Room inside Boy's Cafeteria closest to Entrance	no	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	3B	Storage	Storage Room inside Boy's Cafeteria - Center	no	W1	Concrete	White	Chipping	4	14.7	Positive	N/A	N/A
1	B	3B	Storage	Storage Room inside Boy's Cafeteria - Center	no	W2	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	3B	Storage	Storage Room inside Boy's Cafeteria - Center	no	W3	Concrete	White	Flaking	28	12.1	Positive	N/A	N/A
1	B	3B	Storage	Storage Room inside Boy's Cafeteria - Center	no	W4	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	3B	Storage	Storage Room inside Boy's Cafeteria - Center	no	Ceiling	Plaster	White	Flaking	8	9.9	Positive	N/A	N/A
1	B	3B	Storage	Storage Room inside Boy's Cafeteria - Center	no	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	3C	Storage	Storage Room inside Boy's Cafeteria - furthest from Entrance	no	W1	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	3C	Storage	Storage Room inside Boy's Cafeteria - furthest from Entrance	no	W2	Concrete	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	3C	Storage	Storage Room inside Boy's Cafeteria - furthest from Entrance	no	W3	Concrete	White	Flaking	80	12.6	Positive	N/A	N/A
1	B	3C	Storage	Storage Room inside Boy's Cafeteria - furthest from Entrance	no	W4	Concrete	White	Flaking	72	14.4	Positive	N/A	N/A
1	B	3C	Storage	Storage Room inside Boy's Cafeteria - furthest from Entrance	no	Ceiling	Plaster	White	Flaking	120	10.8	Positive	N/A	N/A
1	B	3C	Storage	Storage Room inside Boy's Cafeteria - furthest from Entrance	no	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	W1	Plaster	White	Flaking	36	17.5	Positive	N/A	N/A
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	W2	Plaster	White	Flaking	12	16.4	Positive	N/A	N/A
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.6	Positive
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	4.2	Positive
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	3.9	Positive
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	W3	Plaster	White	Partially Inaccessible/Flaking	28	20.9	Positive	N/A	N/A
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	W4	Plaster	White	Partially Inaccessible/Flaking	15	13.8	Positive	N/A	N/A
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	Ceiling	Plaster	White	Flaking	48	20.1	Positive	N/A	N/A
1	B	3D	Kitchen	Kitchen next to Boy's Cafeteria	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	3E	Storage	Storage Room inside Kitchen next to Boy's Cafeteria	yes	W1	Plaster	White	Flaking	43	24.2	Positive	N/A	N/A
1	B	3E	Storage	Storage Room inside Kitchen next to Boy's Cafeteria	yes	W2	Plaster	White	Cracking	6	21.6	Positive	N/A	N/A
1	B	3E	Storage	Storage Room inside Kitchen next to Boy's Cafeteria	yes	W3	Plaster	White	Cracking	64	14.9	Positive	N/A	N/A
1	B	3E	Storage	Storage Room inside Kitchen next to Boy's Cafeteria	yes	W4	Plaster	White	Cracking	64	19.2	Positive	N/A	N/A
1	B	3E	Storage	Storage Room inside Kitchen next to Boy's Cafeteria	yes	Ceiling	Plaster	White	Flaking	7	14.5	Positive	N/A	N/A
1	B	3E	Storage	Storage Room inside Kitchen next to Boy's Cafeteria	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	001A	Primary	Speech Classroom next to Boy's Cafeteria	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	B	001A	Primary	Speech Classroom next to Boy's Cafeteria	yes	W2	Plaster	White	Cracking	30	16.9	Positive	N/A	N/A
1	B	001A	Primary	Speech Classroom next to Boy's Cafeteria	yes	W3	Plaster	White	Cracking	4	24	Positive	N/A	N/A
1	B	001A	Primary	Speech Classroom next to Boy's Cafeteria	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	001A	Primary	Speech Classroom next to Boy's Cafeteria	yes	Ceiling	Plaster	White	Flaking	62	12.4	Positive	N/A	N/A
1	B	001A	Primary	Speech Classroom next to Boy's Cafeteria	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	4	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Brick	White	Cracking	4	12.1	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	4	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	0.2	Negative
1	B	4	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Brick	White	Flaking	12	11.8	Positive	N/A	N/A
1	B	4	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Brick	White	Gouges	1	9.5	Positive	N/A	N/A
1	B	4	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Brick	White	Chipping	8	14.2	Positive	N/A	N/A
1	B	4	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Plaster	White	Flaking	34	10.6	Positive	N/A	N/A
1	B	4	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	0.3	Negative
1	B	4	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Concrete	Grey	Chipping	16	0.2	Negative	N/A	N/A
1	B	S03	Stairs	Stairwell next to Boys' Restroom	yes	W1	Concrete	White	Flaking	6	31.1	Positive	N/A	N/A
1	B	S03	Stairs	Stairwell next to Boys' Restroom	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	B	S03	Stairs	Stairwell next to Boys' Restroom	yes	W3	Concrete	White	Chipping	4	24.2	Positive	N/A	N/A
1	B	S03	Stairs	Stairwell next to Boys' Restroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.5	Negative
1	B	S03	Stairs	Stairwell next to Boys' Restroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.52	Negative
1	B	S03	Stairs	Stairwell next to Boys' Restroom	yes	W4	Concrete	White	Chipping	12	16.5	Positive	N/A	N/A
1	B	S03	Stairs	Stairwell next to Boys' Restroom	yes	Ceiling	Metal	N/A	None	0	N/A	N/A	N/A	N/A
1	B	S03	Stairs	Stairwell next to Boys' Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	S03A	Circulation (Hallway)	Area below Stairwell next to Boys' Restroom	yes	W1	Concrete	White	Flaking	2	14.7	Positive	N/A	N/A
1	B	S03A	Circulation (Hallway)	Area below Stairwell next to Boys' Restroom	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A
1	B	S03A	Circulation (Hallway)	Area below Stairwell next to Boys' Restroom	yes	W3	Concrete	White	Cracking	17	12	Positive	N/A	N/A
1	B	S03A	Circulation (Hallway)	Area below Stairwell next to Boys' Restroom	yes	W4	Concrete	White	Chipping	3	16.2	Positive	N/A	N/A
1	B	S03A	Circulation (Hallway)	Area below Stairwell next to Boys' Restroom	yes	Ceiling	Plaster	White	Chipping	3	5.8	Positive	N/A	N/A
1	B	S03A	Circulation (Hallway)	Area below Stairwell next to Boys' Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway outside of Boy's Cafeteria	yes	W1	Concrete	White	Flaking	4	42.9	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	H03	Circulation (Hallway)	Hallway outside of Boy's Cafeteria	yes	W2	Concrete	White	Flaking	20	27.2	Positive	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway outside of Boy's Cafeteria	yes	W3	Concrete	White	Flaking	9	37.1	Positive	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway outside of Boy's Cafeteria	yes	W4	Concrete	White	Flaking	14	44.5	Positive	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway outside of Boy's Cafeteria	yes	Ceiling	Plaster	White	Flaking	1200	12	Positive	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway outside of Boy's Cafeteria	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	W1	Plaster	White	Flaking	6	19.2	Positive	N/A	N/A
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	0.5	Negative
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	0.42	Negative
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	W2	Plaster	White	Flaking	8	13.5	Positive	N/A	N/A
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	W3	Plaster	White	Flaking	40	16.7	Positive	N/A	N/A
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	1	Positive
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	W4	Plaster	White	Flaking	20	18.8	Positive	N/A	N/A
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	Ceiling	Plaster	White	Flaking	48	4.2	Positive	N/A	N/A
1	B	005B	Restrooms, Staff - Male	Men's Staff Restroom across from Boy's Cafeteria	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	11	Primary	Classroom 111A	yes	W1	Plaster	White	Holes	2	20.2	Positive	N/A	N/A
1	B	11	Primary	Classroom 111A	yes	W2	Sheetrock	White	Chipping	2	18	Positive	N/A	N/A
1	B	11	Primary	Classroom 111A	yes	W3	Plaster	White	Flaking	16	18.5	Positive	N/A	N/A
1	B	11	Primary	Classroom 111A	yes	W4	Plaster	White	Flaking	27	23.1	Positive	N/A	N/A
1	B	11	Primary	Classroom 111A	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	0.2	Negative
1	B	11	Primary	Classroom 111A	yes	Ceiling	Plaster	White	Flaking	6	14.6	Positive	N/A	N/A
1	B	11	Primary	Classroom 111A	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	11A	Primary	Classroom 111B	yes	W1	Sheetrock	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	11A	Primary	Classroom 111B	yes	W2	Plaster	White	Gouges	2	12.1	Positive	N/A	N/A
1	B	11A	Primary	Classroom 111B	yes	W3	Plaster	White	Flaking	38	14.6	Positive	N/A	N/A
1	B	11A	Primary	Classroom 111B	yes	W4	Plaster	White	Flaking	36	19.2	Positive	N/A	N/A
1	B	11A	Primary	Classroom 111B	yes	Ceiling	Plaster	White	Flaking	40	21.8	Positive	N/A	N/A
1	B	11A	Primary	Classroom 111B	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	C3	Administrative Office	Building Engineer's Office	no	W1	Brick	White	None	0	N/A	N/A	N/A	N/A
1	B	C3	Administrative Office	Building Engineer's Office	no	W2	Brick	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	C3	Administrative Office	Building Engineer's Office	no	W3	Brick	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	C3	Administrative Office	Building Engineer's Office	no	W4	Brick	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	C3	Administrative Office	Building Engineer's Office	no	Ceiling	Concrete	White	Flaking	12	16.9	Positive	N/A	N/A
1	B	C3	Administrative Office	Building Engineer's Office	no	Floor	Concrete	N/A	Chipping	16	0.22	Negative	N/A	N/A
1	B	H02	Circulation (Hallway)	Hallway outside Boiler Room	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A
1	B	H02	Circulation (Hallway)	Hallway outside Boiler Room	yes	W2	Brick	White	Flaking	1	24.9	Positive	N/A	N/A
1	B	H02	Circulation (Hallway)	Hallway outside Boiler Room	yes	W3	Brick	White	Chipping	1	23.1	Positive	N/A	N/A
1	B	H02	Circulation (Hallway)	Hallway outside Boiler Room	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A
1	B	H02	Circulation (Hallway)	Hallway outside Boiler Room	yes	Ceiling	Concrete	White	Flaking	8	18.4	Positive	N/A	N/A
1	B	H02	Circulation (Hallway)	Hallway outside Boiler Room	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	S01	Stairs	Stairwell next to Boiler Room	yes	W1	Plaster	White	Chipping	4	23.5	Positive	N/A	N/A
1	B	S01	Stairs	Stairwell next to Boiler Room	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	B	S01	Stairs	Stairwell next to Boiler Room	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	B	S01	Stairs	Stairwell next to Boiler Room	yes	W4	Plaster	White	Flaking	3	19.5	Positive	N/A	N/A
1	B	S01	Stairs	Stairwell next to Boiler Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	B	S01	Stairs	Stairwell next to Boiler Room	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway outside Classrooms 107 - 108	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway outside Classrooms 107 - 108	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway outside Classrooms 107 - 108	yes	W3	Brick	White	Flaking	1	14.9	Positive	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway outside Classrooms 107 - 108	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway outside Classrooms 107 - 108	yes	Ceiling	Concrete	White	Flaking	6	9.7	Positive	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway outside Classrooms 107 - 108	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	7	Primary	Classroom 107	yes	W1	Plaster	White	Flaking	9	12.6	Positive	N/A	N/A
1	B	7	Primary	Classroom 107	yes	W2	Plaster	White	Flaking	10	20.9	Positive	N/A	N/A
1	B	7	Primary	Classroom 107	yes	W3	Plaster	White	Flaking	24	22.3	Positive	N/A	N/A
1	B	7	Primary	Classroom 107	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.32	Negative
1	B	7	Primary	Classroom 107	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	7	Primary	Classroom 107	yes	Ceiling	Concrete	White	Flaking	16	14.7	Positive	N/A	N/A
1	B	7	Primary	Classroom 107	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	7A	Storage	Classroom 107 Storage Closet	yes	W1	Plaster	White	Flaking	5	12.8	Positive	N/A	N/A
1	B	7A	Storage	Classroom 107 Storage Closet	yes	W2	Plaster	White	Cracking	16	17.4	Positive	N/A	N/A
1	B	7A	Storage	Classroom 107 Storage Closet	yes	W3	Plaster	White	Cracking	24	24.1	Positive	N/A	N/A
1	B	7A	Storage	Classroom 107 Storage Closet	yes	W4	Plaster	White	Cracking	16	16.8	Positive	N/A	N/A
1	B	7A	Storage	Classroom 107 Storage Closet	yes	Ceiling	Concrete	White	Cracking	6	13.2	Positive	N/A	N/A
1	B	7A	Storage	Classroom 107 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	7B	Storage	Classroom 107 Coat Closet	yes	W1	Plaster	White	Cracking	2	16.7	Positive	N/A	N/A
1	B	7B	Storage	Classroom 107 Coat Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	7B	Storage	Classroom 107 Coat Closet	yes	W3	Plaster	White	Flaking	40	20.2	Positive	N/A	N/A
1	B	7B	Storage	Classroom 107 Coat Closet	yes	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	7B	Storage	Classroom 107 Coat Closet	yes	Ceiling	Concrete	White	Cracking	5	21.1	Positive	N/A	N/A
1	B	7B	Storage	Classroom 107 Coat Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	8	Primary	Classroom 108	yes	W1	Plaster	White	Flaking	15	14.5	Positive	N/A	N/A
1	B	8	Primary	Classroom 108	yes	W2	Plaster	White	Cracking	9	16.8	Positive	N/A	N/A
1	B	8	Primary	Classroom 108	yes	W3	Plaster	White	Flaking	20	20.7	Positive	N/A	N/A
1	B	8	Primary	Classroom 108	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	0.5	Negative
1	B	8	Primary	Classroom 108	yes	W4	Plaster	White	Flaking	28	22.9	Positive	N/A	N/A
1	B	8	Primary	Classroom 108	yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	8	Primary	Classroom 108	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	8B	Storage	Classroom 108 Storage Closet	yes	W1	Plaster	White	Cracking	14	14.9	Positive	N/A	N/A
1	B	8B	Storage	Classroom 108 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	8B	Storage	Classroom 108 Storage Closet	yes	W3	Plaster	White	Flaking	34	13.2	Positive	N/A	N/A
1	B	8B	Storage	Classroom 108 Storage Closet	yes	W4	Plaster	White	Cracking	6	18	Positive	N/A	N/A
1	B	8B	Storage	Classroom 108 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	B	8B	Storage	Classroom 108 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	008A	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W1	Plaster	White	Flaking	12	14.2	Positive	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	008A	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W2	Plaster	White	Efflorescence	12	21.7	Positive	N/A	N/A
1	B	008A	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W3	Plaster	White	Flaking	26	13.9	Positive	N/A	N/A
1	B	008A	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W4	Plaster	White	Flaking	30	17.4	Positive	N/A	N/A
1	B	008A	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Ceiling	Concrete	White	Flaking	24	10.2	Positive	N/A	N/A
1	B	008A	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	0.5	Negative
1	B	008A	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	6	Cafeteria (Dining Area)	Girl's Cafeteria	yes	W1	Brick	White	Flaking	14	10.9	Positive	N/A	N/A
1	B	6	Cafeteria (Dining Area)	Girl's Cafeteria	yes	W2	Brick	White	Chipping	1	9.5	Positive	N/A	N/A
1	B	6	Cafeteria (Dining Area)	Girl's Cafeteria	yes	W3	Brick	White	Flaking	3	6.7	Positive	N/A	N/A
1	B	6	Cafeteria (Dining Area)	Girl's Cafeteria	yes	W4	Brick	White	Flaking	4	8.2	Positive	N/A	N/A
1	B	6	Cafeteria (Dining Area)	Girl's Cafeteria	yes	Ceiling	Concrete	White	Flaking	90	9.1	Positive	N/A	N/A
1	B	6	Cafeteria (Dining Area)	Girl's Cafeteria	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A
1	B	6A	Storage	IT MDF Closet inside Girl's Cafeteria	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	6A	Storage	IT MDF Closet inside Girl's Cafeteria	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	6A	Storage	IT MDF Closet inside Girl's Cafeteria	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	6A	Storage	IT MDF Closet inside Girl's Cafeteria	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	6A	Storage	IT MDF Closet inside Girl's Cafeteria	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	6A	Storage	IT MDF Closet inside Girl's Cafeteria	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	9	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Brick	White	Flaking	136	8.5	Positive	N/A	N/A
1	B	9	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Brick	White	Flaking	180	15.6	Positive	N/A	N/A
1	B	9	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Brick	White	Flaking	144	12.5	Positive	N/A	N/A
1	B	9	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Brick	White	Flaking	180	17.2	Positive	N/A	N/A
1	B	9	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Plaster	White	Flaking	462	5	Positive	N/A	N/A
1	B	9	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A
1	B	009A	Student Restrooms - Female (4-12)	Girl's Restroom Vestibule	yes	W1	Brick	White	Flaking	64	14.2	Positive	N/A	N/A
1	B	009A	Student Restrooms - Female (4-12)	Girl's Restroom Vestibule	yes	W2	Brick	White	Flaking	32	10.9	Positive	N/A	N/A
1	B	009A	Student Restrooms - Female (4-12)	Girl's Restroom Vestibule	yes	W3	Brick	White	Flaking	50	8.6	Positive	N/A	N/A
1	B	009A	Student Restrooms - Female (4-12)	Girl's Restroom Vestibule	yes	W4	Brick	White	Flaking	26	15.8	Positive	N/A	N/A
1	B	009A	Student Restrooms - Female (4-12)	Girl's Restroom Vestibule	yes	Ceiling	Plaster	White	Flaking	48	9.5	Positive	N/A	N/A
1	B	009A	Student Restrooms - Female (4-12)	Girl's Restroom Vestibule	yes	Floor	Concrete	Grey	Flaking	2	0.12	Negative	N/A	N/A
1	B	1	Primary	Classroom 126	yes	W1	Plaster	White	Flaking	6	18.9	Positive	N/A	N/A
1	B	1	Primary	Classroom 126	yes	W2	Plaster	White	Flaking	16	20.2	Positive	N/A	N/A
1	B	1	Primary	Classroom 126	yes	W3	Plaster	White	Flaking	17	24.1	Positive	N/A	N/A
1	B	1	Primary	Classroom 126	yes	W4	Plaster	White	Flaking	10	13.6	Positive	N/A	N/A
1	B	1	Primary	Classroom 126	yes	Ceiling	Plaster	White	Flaking	8	4.2	Positive	N/A	N/A
1	B	1	Primary	Classroom 126	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	1	Primary	Classroom 126	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	0.3	Negative

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	B	1A	Storage	Classroom 126 Storage Closet	yes	W1	Plaster	White	Flaking	6	14.4	Positive	N/A	N/A
1	B	1A	Storage	Classroom 126 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	1A	Storage	Classroom 126 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	1A	Storage	Classroom 126 Storage Closet	yes	W4	Plaster	White	Flaking	1	15.9	Positive	N/A	N/A
1	B	1A	Storage	Classroom 126 Storage Closet	yes	Ceiling	Plaster	White	Flaking	2	18.6	Positive	N/A	N/A
1	B	1A	Storage	Classroom 126 Storage Closet	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	CL5	Storage	Storage Closet outside Classroom 126	yes	W1	Plaster	White	Flaking	43	25.7	Positive	N/A	N/A
1	B	CL5	Storage	Storage Closet outside Classroom 126	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A
1	B	CL5	Storage	Storage Closet outside Classroom 126	yes	W3	Plaster	White	Efflorescence	3	22.3	Positive	N/A	N/A
1	B	CL5	Storage	Storage Closet outside Classroom 126	yes	W4	Plaster	White	Flaking	12	20.5	Positive	N/A	N/A
1	B	CL5	Storage	Storage Closet outside Classroom 126	yes	Ceiling	Plaster	White	Flaking	32	14	Positive	N/A	N/A
1	B	CL5	Storage	Storage Closet outside Classroom 126	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
1	B	CL6	Storage	Storage Closet across from Building Engineer's Office	no	W1	Plaster	White	Cracking	3	12.1	Positive	N/A	N/A
1	B	CL6	Storage	Storage Closet across from Building Engineer's Office	no	W2	Plaster	White	Flaking	2	15	Positive	N/A	N/A
1	B	CL6	Storage	Storage Closet across from Building Engineer's Office	no	W3	Plaster	White	Cracking	2	14.2	Positive	N/A	N/A
1	B	CL6	Storage	Storage Closet across from Building Engineer's Office	no	W4	Plaster	White	Cracking	8	9.9	Positive	N/A	N/A
1	B	CL6	Storage	Storage Closet across from Building Engineer's Office	no	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
1	B	CL6	Storage	Storage Closet across from Building Engineer's Office	no	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
2	P	TRAILER 1	Trailer / Portable	Portable 1 - Closest to A Street	yes	W1	Wood	N/A	Chipping	18	0.02	Negative	N/A	N/A
2	P	TRAILER 1	Trailer / Portable	Portable 1 - Closest to A Street	yes	W2	Wood	N/A	Cracking	2	0.02	Negative	N/A	N/A
2	P	TRAILER 1	Trailer / Portable	Portable 1 - Closest to A Street	yes	W3	Wood	N/A	None	0	N/A	N/A	N/A	N/A
2	P	TRAILER 1	Trailer / Portable	Portable 1 - Closest to A Street	yes	W4	Wood	N/A	None	0	N/A	N/A	N/A	N/A
2	P	TRAILER 1	Trailer / Portable	Portable 1 - Closest to A Street	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
2	P	TRAILER 1	Trailer / Portable	Portable 1 - Closest to A Street	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
3	P	TRAILER 2	Trailer / Portable	Portable 2 - 2nd from A Street	yes	W1	Wood	N/A	Flaking	14	0.04	Negative	N/A	N/A
3	P	TRAILER 2	Trailer / Portable	Portable 2 - 2nd from A Street	yes	W2	Wood	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A

School District of Philadelphia														
Lead Safe Certification Inspection Report														
Olney Elementary School														
			Name of Inspector: Ryan Hutsell											
			Inspection Company: Synertech											
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
3	P	TRAILER 2	Trailer / Portable	Portable 2 - 2nd from A Street	yes	W3	Wood	N/A	Flaking	28	0.02	Negative	N/A	N/A
3	P	TRAILER 2	Trailer / Portable	Portable 2 - 2nd from A Street	yes	W4	Wood	N/A	None	0	N/A	N/A	N/A	N/A
3	P	TRAILER 2	Trailer / Portable	Portable 2 - 2nd from A Street	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
3	P	TRAILER 2	Trailer / Portable	Portable 2 - 2nd from A Street	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
4	P	TRAILER 3	Trailer / Portable	Portable 3 - 2nd from Water Street	yes	W1	Wood	N/A	None	0	N/A	N/A	N/A	N/A
4	P	TRAILER 3	Trailer / Portable	Portable 3 - 2nd from Water Street	yes	W2	Wood	N/A	None	0	N/A	N/A	N/A	N/A
4	P	TRAILER 3	Trailer / Portable	Portable 3 - 2nd from Water Street	yes	W3	Wood	N/A	None	0	N/A	N/A	N/A	N/A
4	P	TRAILER 3	Trailer / Portable	Portable 3 - 2nd from Water Street	yes	W4	Wood	N/A	None	0	N/A	N/A	N/A	N/A
4	P	TRAILER 3	Trailer / Portable	Portable 3 - 2nd from Water Street	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
4	P	TRAILER 3	Trailer / Portable	Portable 3 - 2nd from Water Street	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A
5	P	TRAILER 4	Trailer / Portable	Portable 4 - Closest to Water Street	yes	W1	Wood	N/A	None	0	N/A	N/A	N/A	N/A
5	P	TRAILER 4	Trailer / Portable	Portable 4 - Closest to Water Street	yes	W2	Wood	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A
5	P	TRAILER 4	Trailer / Portable	Portable 4 - Closest to Water Street	yes	W3	Wood	N/A	Flaking	2	0.02	Negative	N/A	N/A
5	P	TRAILER 4	Trailer / Portable	Portable 4 - Closest to Water Street	yes	W4	Wood	N/A	Cracking	2	0.04	Negative	N/A	N/A
5	P	TRAILER 4	Trailer / Portable	Portable 4 - Closest to Water Street	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A
5	P	TRAILER 4	Trailer / Portable	Portable 4 - Closest to Water Street	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A