

Lead Safe Certification for Overbrook Education Center

Name of Inspector: Charles Rhodes

Inspection Dates: through

Inspection Company: Batta Environmental

ULCS# 4480

ULCS#	On-Site Room Name	Stude	Primary	Substrate	Color	Description	Primary	XRF Reading	Primar	Additional Component	Su
ULCS#	On-Site Room Name	Stude	Primary	Substrate	Color	Description	Primary	XRF Reading	Primar	Additional Component	Su
4480	Hallway outside of the Boiler Room and		No Damage	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	Boiler Room		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	Boiler Room		W3	Concrete	White	Flaking	50 SF	0.1	Negati	N/A	
4480	Boiler Room		W4	Brick	White	Flaking	5 SF	-0.1	Negati	N/A	
4480	Classroom 10		No Damages	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	Classroom 11		W1	Sheetrock	White	Flaking	3 SF	-0.2	Negati	N/A	
4480	Classroom 11		W3	Concrete	White	Flaking	30 SF	-0.4	Negati	N/A	
4480	IT Closet inside Classroom 11		No Damage	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	Restroom inside Classroom 11		W2	Concrete	White	Flaking	5 SF	-0.4	Negati	N/A	
4480	Classroom 12		W3	Sheetrock	Tan	Flaking	2 SF	0	Negati	N/A	
4480	Classroom 12		Ceiling	Plaster	Tan	Flaking	10 SF	0	N/A	N/A	
4480	Hallway between Classroom 12 and		W1	Sheetrock	Tan	Flaking	10 SF	0.1	Negati	N/A	
4480	Hallway between Classroom 12 and		Ceiling	Plaster	Tan	Flaking	10 SF	0.1	Negati	N/A	
4480	N. 67th Street Side Stairwell		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	
4480	N. 67th Street Side Stairwell		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	N. 67th Street Side Stairwell		Floor	Metal	Tan	Flaking	20 SF	0	Negati	N/A	
4480	N. 67th Street Side Stairwell		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	N. 67th Street Side Stairwell		Ceiling	Plaster	Tan	Flaking	2 SF	0.1	Negati	N/A	
4480	Cafeteria		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	
4480	N. 68th Street Side Stairwell		Floor	Metal	Tan	Flaking	20 SF	0	Negati	N/A	
4480	N. 68th Street Side Stairwell		W3	Sheetrock	White	Flaking	2 SF	0.1	Negati	N/A	
4480	N. 68th Street Side Stairwell		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	
4480	N. 68th Street Side Stairwell Entrance		W1	Sheetrock	White	Flaking	2 SF	0	Negati	N/A	
4480	Kitchen		W3	Plaster	White	Flaking	10 SF	-0.4	Negati	N/A	
4480	Kitchen		W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	Office across from Kitchen		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	Office across from Kitchen		W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	Main Open Area		W1	Plaster	White	Cracking	10 SF	0.2	Negati	N/A	
4480	Main Open Area		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	
4480	Main Open Area		W1	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	Main Open Area		W2	Sheetrock	White	Flaking	20 SF	0	Negati	N/A	
4480	Main Open Area		W4	Sheetrock	White	Flaking	20 SF	0	Negati	N/A	
4480	Kindergarten Classroom 1		W1	Sheetrock	White	Flaking	5 SF	-0.1	Negati	N/A	
4480	Kindergarten Classroom 1		W2	Sheetrock	White	Flaking	5 SF	-0.5	Negati	N/A	
4480	Kindergarten Classroom 1		W3	Sheetrock	White	Cracking	10 SF	0.1	Negati	N/A	
4480	Kindergarten Classroom 1		W4	Sheetrock	White	Flaking	20 SF	-0.2	Negati	N/A	
4480	Restroom Closer to Kitchen in		No Damage	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	Restroom along Window Wall in		No Damage	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	Office beside N. 67th Street Side		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	Office beside N. 67th Street Side		W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	N. 67th Street Side Stairwell		W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	N. 67th Street Side Stairwell		Floor	Metal	Tan	Flaking	20 SF	0	Negati	N/A	
4480	N. 67th Street Side Stairwell		Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	
4480	Special Education Classroom 2		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	Special Education Classroom 2		W1	Sheetrock	White	Flaking	20 SF	-0.2	Negati	N/A	

Lead Safe Certification for Overbrook Education Center

Name of Inspector: Charles Rhodes

Inspection Dates: through

Inspection Company: Batta Environmental

ULCS# 4480

ULCS#	On-Site Room Name	Stude	Primary	Substrate	Color	Description	Primary	XRF Reading	Primar	Additional Component	Su
4480	2ND FL: N. 68th Street Side Stairwell		Floor	Metal	Tan	Flaking	20 SF	0	Negati	N/A	
4480	2ND FL: N. 68th Street Side Stairwell		Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	
4480	2ND FL: N. 68th Street Side Stairwell		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	
4480	2nd Floor Hallway		W1	Sheetrock	White	Flaking	10 SF	0.1	Negati	N/A	
4480	2nd Floor Hallway		W3	Sheetrock	White	Flaking	10 SF	0.1	Negati	N/A	
4480	2nd Floor Hallway		W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	
4480	Room 21		W1	Sheetrock	White	Flaking	2 SF	0.1	Negati	N/A	
4480	Room 21		W3	Plaster	White	Flaking	10 SF	-0.4	Negati	N/A	
4480	Room 21		W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	Room 21		W4	Plaster	White	Moisture	10 SF	0	Negati	N/A	
4480	Room 22 & Room 23 (combined)		W1	Sheetrock	White	Flaking	20 SF	0.1	Negati	N/A	
4480	Room 22 & Room 23 (combined)		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	Room 22 & Room 23 (combined)		W2	Plaster	White	Flaking	5 SF	0	Negati	N/A	
4480	Room 22 & Room 23 (combined)		W3	Plaster	White	Flaking	15 SF	-0.3	Negati	N/A	
4480	Room 22 & Room 23 (combined)		W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	Room 22 & Room 23 (combined)		W4	Plaster	White	Flaking	5 SF	0	Negati	N/A	
4480	Janitors Closet across from Room 22		NO DAMAGE	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	Girls Restroom across from Room 22		W3	Sheetrock	White	Flaking	3 SF	0.3	Negati	N/A	
4480	Boys Restroom across from Room 23		NO DAMAGE	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4480	Room 24		W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	2ND FL: N. 67th Street Side Stairwell		Floor	Metal	Tan	Flaking	25 SF	0	Negati	N/A	
4480	2ND FL: N. 67th Street Side Stairwell		Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	
4480	Room 25		W3	Plaster	Blue	Moisture	10 SF	-0.2	Negati	N/A	
4480	Room 25		W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	Room 25		W4	Sheetrock	Blue	Flaking	5 SF	-0.2	Negati	N/A	
4480	Room 25		W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	3RD FL: N. 67th Street Side Stairwell		Floor	Metal	Tan	Flaking	20 SF	0.1	Negati	N/A	
4480	3RD FL: N. 67th Street Side Stairwell		Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	
4480	3RD FL: N. 67th Street Side Stairwell		W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	N. 67th Street Side Stairwell Entrance		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	
4480	3rd Floor Hallway		W1	Sheetrock	White	Flaking	10 SF	0	Negati	N/A	
4480	3rd Floor Hallway		W3	Sheetrock	White	Flaking	10 SF	0.1	Negati	N/A	
4480	Room 31		W1	Sheetrock	White	Flaking	2 SF	-0.1	Negati	N/A	
4480	Room 31		W2	Sheetrock	White	Flaking	2 SF	0.2	Negati	N/A	
4480	Room 31		W3	Plaster	White	Flaking	5 SF	-0.3	Negati	N/A	
4480	Room 31		W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	Room 31		W4	Sheetrock	White	Cracking	10 SF	-0.1	Negati	N/A	
4480	Room 32 & Room 33 (combined)		W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	
4480	Room 32 & Room 33 (combined)		W1	Sheetrock	White	Flaking	10 SF	-0.1	Negati	N/A	
4480	Room 32 & Room 33 (combined)		W3	Plaster	White	Flaking	20 SF	-0.2	Negati	N/A	
4480	Room 32 & Room 33 (combined)		W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	
4480	Janitors Closet across from Room 22		W2	Plaster	White	Flaking	5 SF	0.2	Negati	N/A	
4480	Janitors Closet across from Room 22		W3	Plaster	White	Flaking	10 SF	0.1	Negati	N/A	
4480	Janitors Closet across from Room 22		W4	Plaster	White	Flaking	2 SF	-0.4	Negati	N/A	
4480	Janitors Closet across from Room 22		Ceiling	Plaster	White	Flaking	2 SF	0.2	Negati	N/A	
4480	Girls Restroom across from Room 33		W3	Plaster	White	Cracking	5 SF	0.1	Negati	N/A	

Lead Safe Certification for Overbrook Education Center

Name of Inspector: Charles Rhodes

Inspection Dates: through

Inspection Company: Batta Environmental

ULCS# 4480

ULCS#	On-Site Room Name	Stude	Primary	Substrate	Color	Description	Primary	XRF Reading	Primar	Additional Component	Su
4480	3RD FL: N. 68th Street Side Stairwell		Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	
4480											
4480	Element 1 - Main Building										
4480	Storage Room Adjacent to Engineers										
4480	Hallway adjacent to Basement		W3	Plaster	Yellow=	Chipping	50	0			
4480	Hallway to Cafeteria		W2	Plaster	Blue	Chipping	2	-0.1			
4480			W2	Plaster	Green	Chipping	2	-0.1			
4480	Music Room		W1	Plaster	White	Chipping	2	0.1		Door Frame	
4480	Music Room		W2	Plaster	White	Chipping	10	-0.1			
4480	Music Room		W3	Plaster	White	Chipping	2	-0.2		Door Frame	
4480	Music Room		W4	Plaster	White	Chipping	5	-0.1			
4480	Cafeteria		W1							Door Frame	
4480	Cafeteria		W2	Plaster	Yellow	Chipping	5	0.1		Door Frame	
4480	Cafeteria		W3	Plaster	Yellow	Chipping	5	0.1		Door Frame	
4480	Cafeteria		W3							Door	
4480	Cafeteria		W4	Plaster	Yellow	Chipping	5	0.1		Door Frame	
4480	Cafeteria		W4							Door	
4480	Kitchen		W1							Door Frame	
4480	Stairwell adjacent to Cafeteria (5A)		W1	Plaster	Tan	Chipping	5	17.2			
4480	Stairwell adjacent to Cafeteria (5A)		W4	Plaster	White	Chipping	5	18.9			
4480	Stairwell adjacent to Cafeteria (5A)		Ceiling	Plaster	White	Chipping	20	7.7			
4480	Stairwell adjacent to Cafeteria (5C)		Ceiling	Plaster	White	Chipping	10	7.7			
4480	Stairwell adjacent to Cafeteria (5C)		W2	Plaster	White	Chipping	10	17.2			
4480	Vestibule Outside of Gym Lobby		W1	Plaster	White	Chipping	10	25		Door	
4480	Vestibule Outside of Gym Lobby		W1							Door Frame	
4480	Vestibule Outside of Gym Lobby		W2	Plaster	White	Chipping	5	20			
4480	Lobby adjacent to Gymnasium		W2	Plaster	Multi	Chipping	5	15.9			
4480	Lobby adjacent to Gymnasium		W3	Plaster	Multi	Chipping	5	15.9			
4480	Lobby adjacent to Gymnasium		W4	Plaster	Multi	Chipping	3	15.9			
4480	Custodial Closet in Lobby		W2	Plaster	Tan	Chipping	2	0.1			
4480	Custodial Closet in Lobby		W4	Plaster	Tan	Chipping	2	0.1		Door Frame	
4480	Restroom in Lobby		W1							Door Frame	
4480	Gymnasium		W1	Plaster	Tan	Chipping	35	0			
4480	Gymnasium		W2	Plaster	Tan	Chipping	50	0			
4480	Gymnasium		W3	Plaster	Tan	Chipping	20	0.1		Columns	
4480	Gymnasium		W4	Plaster	Tan	Chipping	20	0.1			
4480	Gymnasium		Ceiling	Plaster	Tan	Chipping	50	0.1			
4480	Stage		W1	Plaster	Black	Chipping	20	-0.3			
4480	Stage		W2	Plaster	Black	Chipping	40	0.1			

Lead Safe Certification for Overbrook Education Center

Name of Inspector: Charles Rhodes

Inspection Dates: through

Inspection Company: Batta Environmental

ULCS# 4480

ULCS#	On-Site Room Name	Stude	Primary	Substrate	Color	Description	Primary	XRF Reading	Primar	Additional Component	Su
4480	Hallway from Nurse to Main Office		W1	Plaster	Yellow	Chipping	5	0		Door Frame	
4480	Nurses Office		W3	Plaster	White	Chipping	2	0			
4480	Exam Room					None					
4480	Nurses Restroom					None					
4480	Conference Room		W2	Plaster	White	Chipping	2	-0.2			
4480	Conference Room		W3	Plaster	White	Chipping	2	-0.2			
4480	Principals Office					None					
4480	Main Office Work Room					None					
4480	Main Office		W3	Plaster	White	Chipping	5	-0.1			
4480	Faculty Lounge - Room 201		W4	Plaster	Tan	Chipping	10	-0.1			
4480	Faculty Lounge - Room 201		W1	Plaster	Tan	Chipping	4	0.2			
4480	Storage at Room 201		W3	Plaster	Yellow	Chipping	2	-0.2			
4480	Hallway at Room 201		W2	Plaster	Tan	Chipping	10	0			
4480	Hallway from 206 to 210		W1	Plaster	Tan	Chipping	74	0		Columns	P
4480	Hallway from 206 to 210		W3	Plaster	Tan	Chipping	40	0		Columns	P
4480	Hallway from 206 to 210		W3							Door	
4480	Room 220		W1	Plaster	Tan	Chipping	18	0.2		Door Frame	
4480	Room 220		W3	Plaster	Tan	Chipping	24	0.1			
4480	Room 220		W4	Plaster	Tan	Chipping	4	0.1			
4480	Room 221		W2	Plaster	Tan	Chipping	4	0.1			
4480	Utility Room		W1							Door Frame	
4480	Data Closet		W3							Door Frame	
4480	Custodial Closet		W2	Plaster	Tan	Chipping	50	0.1			
4480	Custodial Closet		W4	Plaster	Tan	Chipping	10	0.1			
4480	Custodial Closet		W3							Door Frame	
4480	Room 210		W1	Plaster	Tan	Chipping	2	0			
4480	Room 211		W1	Plaster	Tan	Chipping	16	0		Door Frame	
4480	Room 209		W1	Plaster	Tan	Chipping	25	-0.2			
4480	Room 208		W1	Plaster	Tan	Chipping	10	-0.1		Door Frame	
4480	Room 207		W1	Plaster	Tan	Chipping	14	0		Door Frame	
4480	Room 206		W1	Plaster	Tan	Chipping	18	-0.1		Door Frame	
4480	Stairwell adjacent to 301 (5A)		W1	Plaster	Yellow	Chipping	5	12.9			
4480	Stairwell adjacent to 301 (5A)		W2	Plaster	Yellow	Chipping	5	12.9		Hand rails	
4480	Room 301		W2	Plaster	Yellow	Chipping	2	-0.1			
4480	Room 301		W4	Plaster	Yellow	Chipping	2	-0.2			
4480	Office - Room 302					None					
4480	Custodial Closet Outside 301					None					

Lead Safe Certification for Overbrook Education Center

Name of Inspector: Charles Rhodes

Inspection Dates: through

Inspection Company: Batta Environmental

ULCS# 4480

ULCS#	On-Site Room Name	Stude	Primary	Substrate	Color	Description	Primary	XRF Reading	Primar	Additional Component	Su
4480	Room 308		W2	Plaster	White	Chipping	5	0			
4480	Room 309		W1	Plaster	White	Chipping	5	-0.1		Door Frame	
4480	Computer Lab		W1	Plaster	White	Chipping	10	0		Door Frame	
4480	Computer Lab		W2	Plaster	White	Chipping	2	0			
4480	Computer Lab		W3	Plaster	White	Chipping	5	0			
4480	Library		W1							Door Frame	
4480	Library		W3	Plaster	Green	Chipping	5	0.1			
4480	Main Lobby		W1	Plaster	Green	Chipping	5	0		Door Frame	
4480	Main Lobby		W2	Plaster	Green	Chipping	5	0			
4480	Main Lobby		W3	Plaster	Green	Chipping	5	0		Door Frame	
4480	Main Lobby		W4	Plaster	Green	Chipping	5	0			
4480	Gym Office		W1	Plaster	White	Chipping	5	0			
4480	Stage/ Gym Storgae		W2	Plaster	Tan	Chipping	5	-0.2			
4480	Storage adjacent to stage entrance		W2	Plaster	Yellow	Chipping	5	0			
4480	Storage adjacent to stage entrance		Ceiling	Plaster	Yellow	Chipping	15	0.3			